


VORKSHIRE AND THE HANDBER

# Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
Yorkshire and the Humber heritage assets at risk	17
East Riding of Yorkshire (UA) Kingston upon Hull, City of (UA) North East Lincolnshire (UA) North Lincolnshire (UA) North Yorkshire South Yorkshire West Yorkshire York (UA)	18 40 41 42 45 100 113



In its fourth year, the Heritage at Risk Register now includes grade I and II\* listed buildings, listed places of worship, scheduled monuments, registered parks and gardens, registered battlefields, protected wreck sites and conservation areas known to be at risk as a result of neglect, decay or inappropriate development. This year, for the first time, we have published a list of 'priority sites': important heritage at risk sites where we will focus our resources to secure their futures.

We continue to focus on our themes, which we have chosen for their contribution to Yorkshire's distinctive character. Industrial heritage features strongly, chiming in with this year's national initiative. In the last year we have been able to remove 50 sites from the Register and we offered 13 grants totalling £687,000. This year we added 54 places of worship that are known to be in poor or very bad condition, increasing the scope of the Register to give an even fuller picture of the state of our heritage.

Good progress is being made in tackling the Industrial Remains of the Dales. Work is underway to consolidate key features of the lead mines on Grassington Moor. Our next priority is the lead complex at Keld Heads. In current market conditions there is little developer-led investment in the Textile Industry of the West Riding. However, English Heritage has supported repair of the chimney at Shaw Lodge Mills, Halifax. Our current focus is on the precious but fragile First White Cloth Hall, Leeds, revealed last year after demolition of later structures, in time for its 300th birthday in 2011. We are also building on the recent study showing how Haworth could be enhanced to provide a world-class visitor experience.

Two of our themes focus on South Yorkshire. We have been able to support the restoration of Joel's Yard, Sheffield, one of the important **Metal Trades Buildings**, to provide live/work units. But although the market has rescued sites over the last decade, others remain empty and increasingly vulnerable. Our priority is to promote the rescue of Leah's Yard, Cambridge Street, Sheffield, a long-hidden courtyard in the heart of the city centre. The major success with **the Designed Landscapes** has been the transformation of the Georgian parkland of Bretton Hall, home to the Yorkshire

Sculpture Park. Prompted by inclusion on our Register, a project was developed to restore the margins of the ornamental lakes, which are once again the focus of views across the park, reflecting new sculptures, historic bridges and follies.

The North York Moors National Park Authority has made great progress over the past year on the Ancient Landscapes of Wolds and Moors. Thirty barrows, cairns and other sites have been tackled and removed from the Register, through the Monument Management Scheme that we fund. Next year we will be working with the Vivat Trust to secure the restoration of Whorlton Castle. We will also be focusing on the Birdsall Estate, to address its collection of earthwork monuments on the Wolds.

A major success with **Places of Worship** has been the completion of a 3 year project to restore the former church of St Margaret, Leeds, as a place of worship and as the base for 'Left Bank Leeds', an arts and community organisation. Its re-opening was celebrated with a concert by patron Corinne Bailey Rae. We have also helped to establish a Support Officer who will work with Doncaster Minster and our other Greater Parish Churches. Our work on **Battlefields** has concentrated on Towton Moor, although we now have detailed studies for each site and an overarching strategy. Interpretation boards have been installed, public access improved and a code of conduct has been agreed to control metal-detecting. We will continue to work with the Friends and landowner at Towton, developing a model for battlefield management.

Trevor Mitchell, Planning Director YORKSHIRE AND THE HUMBER

#### **BUILDINGS AT RISK**

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In Yorkshire and the Humber this rises to 4.2%, representing 93 sites
- 7 sites have been removed from the 2010 Register, but 2 sites have been added.
- 58% of entries (102 buildings) on the baseline 1999 Register for Yorkshire and the Humber have been removed as their futures have been secured, compared to the national figure of 53% (757 buildings).
- Nationally, £5.2m was offered to 71 sites on the Register during 2010/11. In Yorkshire and the Humber we awarded grants totalling £619k to 9 sites.
- 54 listed places of worship have been added to our Register this year. We estimate the cost of repairing these buildings is £9.3m.

#### SCHEDULED MONUMENTS

- 16.9% (3,339) of England's 19,748 scheduled monuments are at risk, compared to 26.7% (701 sites) in Yorkshire and the Humber:
- In Yorkshire and the Humber, 37 sites have been removed from the 2010 Register, but 5 sites have been added.
- 8.7% of entries (63 sites) on the baseline 2009 Register for Yorkshire and the Humber have been removed due to positive reasons, compared to the national figure of 11.9% (399 sites).
- Arable ploughing and unrestricted plant, scrub or tree growth account for nearly two thirds of sites at risk nationally.
   The proportion is similar in Yorkshire and the Humber.
- Nationally, 82% of scheduled monuments at risk are in private ownership, this rises to 88% in Yorkshire and the Humber.
- Of the £357k offered by English Heritage to owners of at risk scheduled monuments in 2010/11, £68k was to 4 sites in Yorkshire and the Humber.

#### **REGISTERED PARKS AND GARDENS**

- 103 of England's 1,610 registered parks and gardens are at risk, an increase from 6.2% (99) in 2010 to 6.4% this year. In Yorkshire and the Humber, 12 of our 117 sites are at risk (10.3%).
- Nationally, 6 sites have been added and 2 removed from the 2010 Register. In Yorkshire and the Humber, 1 site has been added and 1 removed.

#### REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 2 less than the 2008 baseline.
- Of the 7 registered battlefields in Yorkshire and the Humber, 4 are at risk, this is unchanged since 2008.

#### PROTECTED WRECK SITES

• Of the 46 protected wreck sites off England's coast, 7 are at risk, 3 less than the 2008 baseline. Yorkshire and the Humber's I protected wreck site is not at risk.

#### **CONSERVATION AREAS**

- 288 local planning authorities (86%) have taken part in the national survey of conservation areas, of which 21 are in Yorkshire and the Humber. This is 91% of our local planning authorities.
- We now have information on the condition of 7,841 of England's 9,600 designated conservation areas and 516 (6.6%) are at risk.
- Of the 843 conservation areas surveyed in Yorkshire and the Humber, 52 (6.2%) are at risk.



### CHURCH OF ST MARGARET OF ANTIOCH (LEFT BANK LEEDS)

Corinne Bailey Rae performing at the newly re-opened church, now also used as an arts and community space as well as a place of worship. It was restored through the concerted efforts of the local community, supported by large Repair Grant for Places of Worship. © Barnaby Aldrich

#### IN YORKSHIRE AND THE HUMBER:

50% OF BUILDINGS AT RISK ON THE 1999 REGISTER HAVE BEEN SAVED 267% 267% OF SCHEDULED MONUMENTS ARE AT RISK

910/0 OF OUR LOCAL AUTHORITIES HAVE SURVEYED THEIR CONSERVATION AREAS 667K
IN GRANTS WAS
OFFERED
TO SITES ON THE
2010 REGISTER

#### INDUSTRIAL HERITAGE

Britain was the world's first industrial nation and has a wealth of industrial heritage but many industrial sites have been lost or are at risk due to functional redundancy. Our survey has shown that the percentage of listed industrial buildings at risk is three times greater than the national average for listed buildings at risk.

The conservation of industrial sites can pose considerable challenges. However, industrial sites often have great potential for re-use. Our research shows that the best way of saving industrial buildings is, where possible, to find an adaptive new use. We know this isn't easy, and is not always possible, but we hope those who own or are thinking of developing an industrial building will find our new web pages an invaluable source of information.

Voluntary groups and owners have saved a number of key industrial sites, often sites which contain working machinery. However, research has shown that many of these groups need support to encourage more and younger members to achieve the rescue of the site.

Building preservation trusts can provide the answer for industrial buildings where there is no apparent commercial solution by repairing the site and then selling it, or retaining and letting the space.

#### What we know

- 4% of listed buildings and scheduled monuments are industrial
- Nationally there are proportionally more grade II\* industrial listed buildings than grade II (4.6% compared to 4.4%)
- 10.6% of industrial grade I and II\* listed buildings are at risk, making industrial buildings over three times more likely to be at risk than the national average for grade I and II\* listed buildings
- The average estimated conservation deficit (cost of repair in excess of the end value) of industrial buildings at risk is twice that of non-industrial buildings at risk
- About 10% of industrial buildings at risk are economic to repair, compared to 13% of non-industrial buildings at risk
- Approximately 40% of industrial buildings at risk are capable of beneficial use, compared to 44% of non-industrial buildings at risk
- 10.9% of industrial scheduled monument are at risk, making industrial scheduled monuments less likely to be at risk than the national average for scheduled monuments
- 3% of conservation areas were designated because of their industrial significance
- Industrial conservation areas in the North West and West Midlands are over twice are likely to be at risk than the national average
- In the last 10 years, English Heritage has offered grants totalling £25m to industrial sites



#### SHAW LODGE MILL, HALIFAX

The 67 metre chimney at Shaw Lodge Mills is a prominent feature of the Halifax skyline, whilst not on the Heritage at Risk Register, the structure was in need of repair. We are grant-aiding replacement of the rusting iron bands and re-pointing to ensure the future of the structure. New uses for the chimney are being looked into at the moment; one possible idea is an innovative scheme to use the chimney as a climbing wall which would also provide a sustainable new use for the structure.

#### What are we doing?

- Providing new guidance for owners on maintaining vacant historic buildings.
- Publishing a developers' portal on the English Heritage website where advice for all types of heritage asset including industrial sites can be found.
- Funding a new Industrial Heritage Support Officer, who will build capacity for industrial museums.
- Publishing an industrial themed issue of Conservation Bulletin in October 2011.
- Supporting a new Architectural Heritage Fund grant scheme which aims to encourage local groups to take on industrial buildings.
- Publishing an updated Stopping the Rot: a guide to enforcement action to save historic buildings.
- Using the National Heritage Protection Programme (2011-2015) to shape an industrial designation programme.

If you are a developer, member of a building preservation trust, work in a local authority, own a visitor attraction or have an interest in England's industrial heritage, visit our website for more information:

www.english-heritage.org.uk/industrial-heritage-at-risk


#### **PRIORITY SITES**

- Barden Church, Barden, Yorkshire Dales National Park
- Battle of Towton, Lead / Saxton with Scarthingwell / Towton, Selby, North Yorkshire
- Birdsall Estate (incl. I 6 scheduled monuments at risk), Birdsall Wold, Ryedale, North Yorkshire
- First Leeds White Cloth Hall, 98-101 (consec) Kirkgate, Leeds, West Yorkshire
- Haworth Conservation Area, Bradford, West Yorkshire
- Keld Heads lead smeltmill and mine complex, Wensley, Richmondshire, North Yorkshire
- Kirklees Park Farm buildings (incl. Double aisled barn to north west of Kirklees Priory Gatehouse, Home Farm (Building No. 6), Kirklees Priory Gatehouse, L-shaped Aisled Barn, and the Malthouse) Brighouse, Calderdale, West Yorkshire
- Leah's Yard, 20-22 Cambridge Street, Sheffield, South Yorkshire
- Grassington Moor (multi-period lead mines and processing works and 20th century barytes mill), Grassington, Yorkshire Dales National Park
- Whortlon Castle (gatehouse and ruins of undercroft), Castle Bank, Whorlton, North York Moors National Park

COVER IMAGE:

Keld Heads lead smeltmill and mine complex, Wensley, Richmondshire, Scheduled Monument at Risk and Priority Site

CONTACT: Susan Daniels, Business Manager, English Heritage, Yorkshire and the Humber, Tanner Row, York Y01 6WP. Telephone: 01904 601979 Fax: 01904 601999 Email: susan.daniels@english-heritage.org.uk



For more information on Heritage at Risk visit www.english-heritage.org.uk/risk



If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk



# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our national plan for the protection of England's historic environment (National Heritage Protection Plan 2011-2015). This will be challenging given the number of assets now on the Register and the different kinds of risk they face. Each asset type and individual case will require its own approach and solution.

There are, however, some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential if they are not to become at risk, and to prevent those that are already at risk from decaying further and thereby escalating the cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website www.helm.org.uk.

#### LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society and the Twentieth Century Society.

#### Places of worship at risk

Regular maintenance helps to keep buildings and places of worship in good condition but those that are in poor or very bad condition need help to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing that congregations can do as it stops small problems in the building fabric developing into unnecessary crises. English Heritage supports the Society for the Protection of Ancient Buildings's Faith in Maintenance scheme, giving volunteers practical local training and on-going support. It also encourages the establishment of gutter-clearance projects, enabling congregations to get good quality work done at reasonable prices by reputable contractors.

Where major structural repairs are required, the Repair Grants for Places of Worship scheme helps under resourced buildings in urgent need. The Listed Places of Worship scheme is another source of funding for repairs and maintenance that is available more widely, while local and national charities can offer small grants.

Many congregations wish to adapt and change their places of worship to encourage wider community use alongside worship and faith-focussed events. English Heritage supports the efforts of congregations to keep their places of worship in use wherever possible and welcomes proposals for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character.

English Heritage is aware of the need for practical, hands-on help to be given to individual congregations and is working with partner organisations to enable this. Support Officers are employed by local denominational groups but part-funded by English Heritage. They give advice and encouragement to congregations so that they can achieve repair projects, develop necessary new facilities or re-engage with the wider community, depending on local circumstances and needs.

#### SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value of the dialogue that the initiative has fostered between English Heritage, owners, managers and other partners. More and more owners and managers of scheduled monuments are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Work in the coming years with Defra and Natural England will concentrate upon ensuring that the right options are being used in

the correct way, maximising the conservation benefits whilst at the same time delivering value for money. We will also work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage up to 2015 - the Conservation of Scheduled Monuments in Cultivation project will be rolled out nationally from 2011 onwards. The project, already successfully trialled amongst farmers in the East Midlands, will address what is still the biggest threat by far to monuments – their gradual degradation and loss through arable cultivation. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk shows that unmanaged tree, scrub and bracken growth is the most widespread cause of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. Further work will therefore be needed to better understand how these effects can be minimised.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers is still key to making further progress in ever more challenging circumstances.

#### REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest brings no additional statutory controls, but there is a presumption in favour of the conservation of all designated assets in the planning system. The Government's Planning Policy Statement 5 Planning for the Historic Environment (PPS 5) and its supporting Practice Guide helps planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the proposals for change to the highest graded designed landscapes and where the impact on historic significance is greatest. Our landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We are keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

#### REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in Planning Policy Statement 5.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

#### PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

#### CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners. Looking after them is a responsibility shared by those of us who own homes and businesses in them and those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The conservation area survey provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas are critical in managing change in these areas. This is difficult at a time when local authorities across the country are reducing the number of staff managing changes in conservation areas. There are, of course, opportunities for members of the local community to engage, either individually or through groups such as civic societies or conservation area advisory committees which are proven to help achieve positive action.

Armed with the information provided by the surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk. We will also want to target those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) — a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2011 – national report and summaries for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2011 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Saving Historic Buildings Through Enforcement Action (2011)

The Monuments at Risk initiative 2003–08 (2010)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection.

Details of all nationally designated historic places in England are now available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

## CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010).

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

# THE REGISTER

# Content and criteria

#### **DESIGNATION**

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since I 882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz I 940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some I,610 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

### LISTED BUILDINGS

#### Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

#### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

#### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed only a small proportion of the 14,500 listed places of worship so the number identified so far as 'at risk' and included on this year's Register is small. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence and build up our understanding of the challenges.

#### Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

#### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

# SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,731 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and — often most seriously of all — wholly natural processes such as scrub growth, animal burrowing and erosion.

#### Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

# REGISTERED PARKS AND GARDENS Definition

There are 1,610 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

#### Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

# REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

#### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

# PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

#### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

#### Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with more limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Key to the entries

#### This register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas

#### **ORDER**

Entries are grouped and ordered alphabetically first by County\* or Unitary Authority, and then by Local Planning Authority (Unitary Authority/National Park/District or Borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- · registered parks and gardens
- registered battlefields
- conservation areas

Within each asset type, sites are ordered alphabetically by parish, locality, street/site name.

\*The metropolitan counties of South Yorkshire and West Yorkshire are used to group the data. North Yorkshire is the only two tier planning authority in the Region.

#### **DESIGNATION**

The principal designation is noted for each entry, and includes:

- Listed Building (LB) grade I, II\* or II
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

#### **CONDITION**

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

#### OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- · part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub / tree growth
- · visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### **PRIORITY**

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- **D** Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 Register, the previous category is given in brackets.

#### **TREND**

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

#### CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA' on the Register).

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

CA Conservation Area
EH English Heritage
HLF Heritage Lottery Fund
LA/LPA Local Planning Authority

LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

# Yorkshire and the Humber heritage assets at risk

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
EAST RIDING OF YORKS	SHIRE (UA)						
East Riding of Yorkshire (UA)	11	4	185	2	ı	0	0
KINGSTON UPON HULI	L, CITY OF (U	A)					
Kingston upon Hull, City of (UA)	0	1	0	0	0	0	3
NORTH EAST LINCOLN	SHIRE (UA)						
North East Lincolnshire (UA)	2	0	2	0	0	0	6
NORTH LINCOLNSHIRE	· ,						
North Lincolnshire (UA)	2	3	14	0	0	0	2
NORTH YORKSHIRE							
Craven	1	0	1	0	0	0	0
Hambleton	5	1	29	0	0	0	0
Harrogate	9	0	17	2	I	0	0
North York Moors (NP)	5	0	136	0	0	0	0
Richmondshire	6	0	15	0	0	0	0
Ryedale	11	3	135	2	0	0	0
Scarborough	2		23	0	0	0	1
Selby	4	0	22	0	1	0	0
Yorkshire Dales (NP)	4	2		0	0	0	2
SOUTH YORKSHIRE		_					
Barnsley	6		7	0	0	0	
Doncaster Doncaster (NID)	2		17	0	0	0	7
Peak District (NP) Rotherham	0	0	3	0	0	0	0
Sheffield	6	3 2	15 7	0	0	0	2
WEST YORKSHIRE	6		/	2	0	0	
Bradford	4	6	19		0	0	10
Bradford / Kirklees / Leeds*				1			
Calderdale	0	0 2	0	0	0	0	3
Kirklees	4	8	4	0	0	0	4
Leeds	11	5	10	2	0	0	4
Peak District (NP)	0		0	0	0	0	0
Wakefield	3		6	0	0	0	0
Wakefield / Barnsley / Kirklees*	0		0		0		0
YORK (UA)				'			
York (UA)	0	0	0	0	0	0	3
TOTAL	112	54	684	12	4	0	52

<sup>\*</sup>Sites that cross LPA boundaries

#### EAST RIDING OF YORKSHIRE (UA)



SITE NAME: Gates, gate piers and railings to Norwood House, Norwood, Beverley

DESIGNATION: Listed Building Grade I, CA

Poor CONDITION: OCCUPANCY: N/A D(C)PRIORITY-OWNERTYPE: Company Two pairs of stone gate piers, two pairs of gates and wrought iron railings of circa 1780. Enclosing the forecourt to Norwood House, which has been vacant since 1996. Planning permission has been granted for conversion of the building to offices. The gates and railings are rusting and the stonework has been damaged.

Contact: Keith Miller 01904 601990



Norwood House, SITE NAME: Norwood.

Beverley

Listed Building Grade I, CA DESIGNATION:

CONDITION: Vacant OCCUPANCY: D (C) PRIORITY: OWNERTYPE: Company

Circa 1765-70, probably built for the attorney Jonathan Midgley, twice Mayor of Beverley. Úsed by Beverley Girls' High School until 1996 and vacant since. Planning permission has been granted for office conversion; new proposals for conversion and extension for hotel use are under discussion. Some repairs are underway.

Contact: Keith Miller 01904 601990



Easington Tithe Barn, SITE NAME: High Street, Easington

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION: Occupied PRIORITY C (C) Private OWNER TYPE:

Medieval and post medieval thatched timber-framed aisled barn associated with historic rectory farm. A unique survival for this part of the region. Fallen into disuse and disrepair.

Contact: Tammy Whitaker 01904 601880



Flamborough Castle, SITE NAME:

Tower Street, Flamborough

DESIGNATION: Listed Building Grade II, SM, CA

Poor CONDITION: OCCUPANCY: N/A C (C) PRIORITY-OWNER TYPE: Private Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

Contact: Keith Miller 01904 601990



Elmswell Old Hall. SITE NAME: Elmswell Lane,

Garton

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: OCCUPANCY: Vacant

A(A)OWNER TYPE: Private House, I 634 with later alterations. Once the home of Henry Best, important C17 agricultural diarist. Isolated and abandoned. Urgent works have been carried out but these have not arrested decay. The whole building is roofless. An application to restore the house to a dwelling has been made by the Spitalfield Trust.

Gateway, I 660-70, probably by Robert Hooke, forming the

principal entrance to Londesborough Park. The caps of the

gatepiers are deteriorating and trees are growing from the

Contact: Keith Miller 01904 601990



Gates, gate piers, SITE NAME:

flanking walls and abutments, Londesborough

DESIGNATION: Listed Building Grade I, CA, RPG II\*

CONDITION: Poor N/A OCCUPANCY: PRIORITY: C(C)

OWNERTYPE: Private

joints. The ball finials have fallen.

Contact: Andy Wimble 01904 601986

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS



Paull Holme Tower, SITE NAME: Thorngumbald Road, Paull

DESIGNATION: Listed Building Grade I, SM, CA

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY:

Private

Mid C15 three storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871, roofless since the early C20 and suffering from

long-term neglect.

Contact: Keith Miller 01904 601990



Adlingfleet Medieval Rectory, SITE NAME: Church Lane, Adlingfleet, Twin Rivers

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant A(C)PRIORITY: Private OWNER TYPE:

Part of a C13 dwelling of the wealthy rector and King's councillor, John le Franceys. Re-used as farm buildings in the CI8. A unique survival of a stone-built medieval dwelling in this area.

Contact: Keith Miller 01904 601990

Contact: Keith Miller 01904 601990



Outbuildings to Watton Abbey, SITE NAME: Church Lane. Watton

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant OCCUPANCY: C (D) PRIORITY: OWNERTYPE: Private

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and mainly ruinous. Urgent repairs have been undertaken with the help of an English Heritage grant to stabilise

the leaning gable.



Haltemprice Priory Farmhouse, SITE NAME: Abbey Lane,

Willerby

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant A(A)PRIORITY-Private OWNER TYPE:

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and C16 fabric. In a very advanced state of decay. Proposals for repair and residential re-use are in preparation.

Contact: Tammy Whitaker 01904 601880




Wressle Castle, SITE NAME: Breighton Road, Wressle

DESIGNATION: Listed Building Grade I, SM

CONDITION: Vacant OCCUPANCY: A(A)PRIORITY-OWNERTYPE: Private

Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s.

Contact: Tammy Whitaker 01904 601880



SITE NAME: Church of All Saints, Low Catton, Catton

DESIGNATION: Listed Place of Worship Grade I

CONDITION: C (New entry) PRIORITY:

OWNERTYPE: Religious organisation

Medieval church with prominent Victorian chancel set back from the road in the small village of Low Catton. The roof of the main church is leaded, however the chancel is tiled and there were a large number of slipped tiles particularly to the north.

Contact: Susan Daniels 01904 601979

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

#### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Church of St Andrew, SITE NAME:

Church Lane, Ulrome

Small, largely Victorian, church. Deterioration and structural movement, grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II

Very bad CONDITION: PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Mary, Church Lane. Watton

C16 church, largely brick. Roofs in poor condition,


but grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I

D (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Susan Daniels 01904 601979



Church of St Nicholas, SITE NAME:

Main Street, Wetwang

Medieval church, restored by Hodgson Fowler for Sir Tatton Sykes. Roof coverings renewed, but repairs to tower yet to start.

DESIGNATION: Listed Place of Worship Grade II\*, CA

Poor CONDITION:

F (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Susan Daniels 01904 601979

SITE NAME:	Bewick Hall moated site, Aldbrough		
DESIGNATION:	Scheduled Monument (No. 1007848)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Rectilinear enclosures, Barmby Moor		
DESIGNATION:	Scheduled Monument (No. 1005209)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Barf Hill moated site, Beswick		
DESIGNATION:	Scheduled Monument (No. 1007717)	CONDITION:	Generally satisfactory
	·		but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Beverley sanctuary limit stone, Bishop Burt	on cross, Bishop E	Burton
DESIGNATION:	Scheduled Monument (No. 1012589)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DESIGNATION:	Scheduled Monument (No. 1012589)	CONDITION:	Generally satisfactory but with significant localised prol

#### PRIORITY (FOR BUILDINGS)

PRINCIPAL VULNERABILITY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

OWNER TYPE:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Arable ploughing

Private

Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Scheduled Monument (No. 1007401)

Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Five round barrows 700m north east of Littlewood Lodge, Bishop Burton

### NOTE:

CONTACT:

CONDITION:

TREND:

CONTACT:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

Declining

Keith Miller 01904 601990

Extensive significant problems

Keith Miller 01904 601990

### **ABBREVIATIONS**

Conservation Area CA LB/LBs Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs Unitary Authority World Heritage Site UA WHS

SITE NAME:	Four round barrows 780m north east of Li	ttlewood Lodge, B	Bishop Burton				
DESIGNATION:	Scheduled Monument (No. 1007563)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Round barrow 1000m north east of Littlew	ood Lodge, Bishop	p Burton				
DESIGNATION:	Scheduled Monument (No. 1007572)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
DWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Round barrow 900m north east of Littlewo	ood Lodge, Bishop	Burton				
DESIGNATION:	Scheduled Monument (No. 1007440)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
DWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Three round barrows 800m north east of Littlewood Lodge, Bishop Burton						
DESIGNATION:	Scheduled Monument (No. 1007573)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
DWNERTYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Round barrow 250m east of Wold Farm, B	ishop Wilton Wold	d, Bishop Wilton				
DESIGNATION:	Scheduled Monument (No. 1008320)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
DWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Round barrow 250m south of Callis Wold	Farm, Bishop Wilto					
DESIGNATION:	Scheduled Monument (No. 1008366)	CONDITION:	Extensive significant problems				
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining 16 in National Colons				
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
ITE NAME:	Round barrow 300m south west of Callis V	Vold Farm, Bishop	Wilton				
DESIGNATION:	Scheduled Monument (No. 1008368)	CONDITION:	Extensive significant problems				
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
SITE NAME:	Round barrow 300m south west of Cot Na	ab Farm, Bishop W	/ilton				
DESIGNATION:	Scheduled Monument (No. 1008319)	CONDITION:	Extensive significant problems				
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining				
DWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990				
SITE NAME:	Round barrow 350m west of Cot Nab Fari	m, Bishop Wilton					
	Scheduled Monument (No. 1008314)	CONDITION:	Extensive significant problems				
DESIGNATION:	Arable ploughing	TREND:	Declining				
		COLUTICE	Keith Miller 01904 601990				
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Private	CONTACT:	Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton				
PRINCIPAL VULNERABILITY:	Private		n Wold, Bishop Wilton				
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private  Round barrow 400m north east of Wold Fa		·				
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private	arm, Bishop Wilton	n Wold, Bishop Wilton  Extensive significant problems  Declining				

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS
Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow 850m north of Wold Farm,	Bishop Wilton Wo	old, Bishop Wilton
DESIGNATION:	Scheduled Monument (No. 1008345)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow south east of Cot Nab Farm	n, Bishop Wilton	
DESIGNATION:	Scheduled Monument (No. 1009386)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke on Millingt	on Lings 625m no	orth east of High Callis Wold, Bishop Wilton
DESIGNATION:	Scheduled Monument (No. 1015574)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site of Archbishop's moated palace and fish	ponds, Hall Garth	, Bishop Wilton
DESIGNATION:	Scheduled Monument (No. 1009383)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Settlement site at Boynton Hall, Boynton		
DESIGNATION:	Scheduled Monument (No. 1005207)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British villa at Cockle Pits, near Br	antingham, Branti	ngham
DESIGNATION:	Scheduled Monument (No. 1014736)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
	David barrery 500m and of Division David	Dui din see s	
SITE NAME:	Bowl barrow, 500m south of Buckton Barn,	-	F
DESIGNATION:	Scheduled Monument (No. 1013624)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow, 500m SSW of Buckton Barn,	Bridlington	
DESIGNATION:	Scheduled Monument (No. 1013623)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at North Park Farm, Burstwick	ζ.	
DESIGNATION:	Scheduled Monument (No. 1008047)	CONDITION:	Generally satisfactory
	( 15. 1555)	23.18.1.191	but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
	-		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Iron Age square barrow cemetery on Haist	horpe Moor, 750n	n WNW of Demming Farm, Burton Agne
DESIGNATION:	Scheduled Monument (No. 1013706)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Wharram Hill embankment cross, Burton A	gnes	
DESIGNATION:	Scheduled Monument (No. 1005199)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site revealed by aerial photography north v	vest of Argam Co	tages, Burton Fleming
DESIGNATION:	Scheduled Monument (No. 1005211)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Willy Howe round barrow, Burton Fleming		
DESIGNATION:	Scheduled Monument (No. 1008040)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 200m west of Crest Cottages	s, Carnaby	
DESIGNATION:	Scheduled Monument (No. 1007733)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
	Moated site and two fishponds 80m south	at of Daulchause	Farm Cherry Burton
SITE NAME:	r loated site and two hishponds donn south	west of Farkhouse	a raini, Cherry Barton
	Scheduled Monument (No. 1007842)	CONDITION:	Generally satisfactory
	Scheduled Monument (No. 1007842)		Generally satisfactory but with significant localised problems
designation:	Scheduled Monument (No. 1007842)  Scrub / tree growth		Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007842)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007842)  Scrub / tree growth	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1007842)  Scrub / tree growth  Private	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G	CONDITION:  TREND:  CONTACT:  ardham Farm, Che	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Perry Burton
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726)	CONDITION:  TREND: CONTACT:  ardham Farm, Cho	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G  Scheduled Monument (No. 1007726) Arable ploughing	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Erry Burton Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL YULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL YULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G  Scheduled Monument (No. 1007726) Arable ploughing Other	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Erry Burton Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726) Arable ploughing Other  Round barrow 430m north west of High G	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:  ardham Farm, Che	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton Extensive significant problems Declining Keith Miller 01904 601990  erry Burton
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726) Arable ploughing Other  Round barrow 430m north west of High G Scheduled Monument (No. 1012121)	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:  ardham Farm, Che CONDITION:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Erry Burton Extensive significant problems Declining Keith Miller 01904 601990  Erry Burton Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726) Arable ploughing Other  Round barrow 430m north west of High G Scheduled Monument (No. 1012121) Arable ploughing	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726) Arable ploughing Other  Round barrow 430m north west of High G Scheduled Monument (No. 1012121) Arable ploughing Other	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:	Scheduled Monument (No. 1007842)  Scrub / tree growth Private  Round barrow 300m south west of High G Scheduled Monument (No. 1007726) Arable ploughing Other  Round barrow 430m north west of High G Scheduled Monument (No. 1012121) Arable ploughing Other  Round barrow 430m north west of High G	CONDITION:  TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:  ardham Farm, Che CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems Declining Keith Miller 01904 601990  erry Burton  Extensive significant problems Declining Keith Miller 01904 601990  erry Burton

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

		, ,	
SITE NAME:	Round barrow 700m west of High Gardham	Farm, Cherry Bu	urton
DESIGNATION:	Scheduled Monument (No. 1007728)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Seven round barrows 530m west of High Ga	rdham Farm, Ch	erry Burton
DESIGNATION:	Scheduled Monument (No. 1012187)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two round barrows 600m north west of Hig	h Gardham Farn	n, Cherry Burton
DESIGNATION:	Scheduled Monument (No. 1008785)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Linear earthwork north east of Collingwood	Farm, Cottam	
DESIGNATION:	Scheduled Monument (No. 1007862)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private Proagrams	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 700m north east of Collingwe	ood Farm, Cotta	m
DESIGNATION:	Scheduled Monument (No. 1007861)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Baynard Castle, Cottingham		
DESIGNATION:	Scheduled Monument (No. 1019823)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Money Hill round barrow, Dalton Holme		
DESIGNATION:	Scheduled Monument (No. 1007923)	CONDITION:	Generally satisfactory
	,		·
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	but with significant localised problems  Declining
	Arable clipping Private	TREND: CONTACT:	=
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	•	CONTACT:	Declining Keith Miller 01904 601990
OWNERTYPE: SITE NAME:	Private  Moot Hill motte and bailey castle, and site or	CONTACT:	Declining Keith Miller 01904 601990  ted manor, Driffield
OWNER TYPE: SITE NAME:	Private	CONTACT:	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory
OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Moot Hill motte and bailey castle, and site or	CONTACT:	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory with major localised problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moot Hill motte and bailey castle, and site of Scheduled Monument (No. 1015612)	contact:  a medieval moa	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moot Hill motte and bailey castle, and site of Scheduled Monument (No. 1015612)  Other	contact:  f a medieval moa  condition:  TREND:	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory with major localised problems Declining
OWNER TYPE:	Moot Hill motte and bailey castle, and site of Scheduled Monument (No. 1015612)  Other	contact:  f a medieval moa  condition:  Trend:  contact:	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Moot Hill motte and bailey castle, and site of Scheduled Monument (No. 1015612)  Other Private	contact:  f a medieval moa  condition:  Trend:  contact:	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  ange, Easington  Generally satisfactory
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Moot Hill motte and bailey castle, and site of Scheduled Monument (No. 1015612)  Other Private  World War I acoustic mirror 335m north ea	contact:  a medieval moa  condition:  trend:  contact:  st of Kilnsea Gra	Declining Keith Miller 01904 601990  ted manor, Driffield  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  ange, Easington

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Site of deserted village of Grimston, East G	arton	
DESIGNATION:	Scheduled Monument (No. 1021241)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at Newland Farm, Eastrington		
DESIGNATION:	Scheduled Monument (No. 1015925)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Motte and bailey castle, fishpond and moate	d site north and	east of Aughton church, Ellerton
DESIGNATION:	Scheduled Monument (No. 1007973)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bolton Old Hall moated site, Fangfoss		
DESIGNATION:	Scheduled Monument (No. 1008045)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow I50m NNE of Towthorpe Hig	n Barn, Fimber	
DESIGNATION:	Scheduled Monument (No. 1013702)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow, I 50m south east of Towthorp	e Reservoir, Fimb	er
DESIGNATION:	Scheduled Monument (No. 1013703)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Settlement at Blealands Nook, Fimber		
DESIGNATION:	Scheduled Monument (No. 1005205)	CONDITION:	Extensive significant problems
	, ,		- '
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
OWNER TYPE:			
OWNER TYPE: SITE NAME:	Private		
OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Garton Slack settlement site, Garton	CONTACT:	Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Garton Slack settlement site, Garton  Scheduled Monument (No. 1005235)	CONTACT:	Keith Miller 01904 601990  Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Garton Slack settlement site, Garton Scheduled Monument (No. 1005235) Arable ploughing	CONTACT:  CONDITION: TREND: CONTACT:  Warren Dale	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Garton Slack settlement site, Garton  Scheduled Monument (No. 1005235)  Arable ploughing  Private  Linear earthwork running from the head of towards Sledmere Field Farm and associated	CONTACT:  CONDITION: TREND: CONTACT:  Warren Dale	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Garton Slack settlement site, Garton  Scheduled Monument (No. 1005235)  Arable ploughing  Private  Linear earthwork running from the head of	CONTACT:  CONDITION: TREND: CONTACT:  Warren Dale d settlement site,	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Garton

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow 350m south east of Low Far	m, Garton	
DESIGNATION:	Scheduled Monument (No. 1007852)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 400m south west of Low Fa	rm, Garton	
DESIGNATION:	Scheduled Monument (No. 1007856)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 420m south west of Low Fa	rm, Garton	
DESIGNATION:	Scheduled Monument (No. 1007857)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERTYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 440m south west of Low Fa	rm, Garton	
DESIGNATION:	Scheduled Monument (No. 1007854)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 450m south west of Low Fa	rm, Garton	
DESIGNATION:	Scheduled Monument (No. 1007853)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 500m south east of Low Far	rm, Garton	
DESIGNATION:	Scheduled Monument (No. 1008810)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 500m south of Low Farm, G	arton	
DESIGNATION:	Scheduled Monument (No. 1009394)		
JESIGINATION.	Scheduled Floridifient (140, 1007571)	CONDITION:	Extensive significant problems
	,	CONDITION: TREND:	Extensive significant problems  Declining
PRINCIPAL VULNERABILITY:	Arable ploughing Private		
PRINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing	TREND: CONTACT:	Declining
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Arable ploughing Private	TREND: CONTACT:	Declining
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 700m south of Low Farm, G	TREND: CONTACT:	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850)	TREND: CONTACT:  Garton  CONDITION:	Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Arable ploughing Private  Round barrow 700m south of Low Farm, G  Scheduled Monument (No. 1007850)  Arable ploughing	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:	Arable ploughing Private  Round barrow 700m south of Low Farm, G  Scheduled Monument (No. 1007850)  Arable ploughing Private	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850) Arable ploughing Private  Round barrow 700m south of Low Farm, G	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850) Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007855)	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850) Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007855) Arable ploughing	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DOWNER TYPE:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850) Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007855) Arable ploughing Private  Round barrow 750m south of Low Farm, G	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007850) Arable ploughing Private  Round barrow 700m south of Low Farm, G Scheduled Monument (No. 1007855) Arable ploughing Private	TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Bowl barrow 1000m north east of Goodma	ınham Wold Farm	, Goodmanham			
DESIGNATION:	Scheduled Monument (No. 1008934)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Bowl barrow 230m south west of Enthorpe	e House, Goodma	nham			
DESIGNATION:	Scheduled Monument (No. 1012835)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Bowl barrow 550m north east of Goodma	nham Wold Farm,	Goodmanham			
DESIGNATION:	Scheduled Monument (No. 1008933)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Bowl barrow 550m south west of Enthorpe House, Goodmanham					
DESIGNATION:	Scheduled Monument (No. 1008923)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Bowl barrow 700m south west of Enthorpe	House, Goodma	nham			
DESIGNATION:	Scheduled Monument (No. 1008922)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
	····ate	2011/1/211				
SITE NAME:	Round barrow 730m NNW of Goodmanha	ım Wold Farm, Go	oodmanham			
DESIGNATION:	Scheduled Monument (No. 1007328)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Twelve bowl barrows 800m north of Good	manham Wold Fai	rm, Goodmanham			
DESIGNATION:	Scheduled Monument (No. 1007642)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Romano-British villa east of Sandy Lane, 80	0m north west of	Harpham Grange, Harpham			
DESIGNATION:	Scheduled Monument (No. 1013628)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
SITE NAME:	Park Closes moated lodge, I 30m south wes	st of Park Farm, H	olme upon Spalding Moor			
DESIGNATION:	Scheduled Monument (No. 1015311)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990			
	Hall Garths moated site, immediately south	of St Mary's Chu	rch, Hook			
SITE NAME:	· · · · · · · · · · · · · · · · · · ·					
	·	CONDITION	Generally satisfactory			
SITE NAME: DESIGNATION:	Scheduled Monument (No. 1017823)	CONDITION:	Generally satisfactory but with significant localised problems			
	·	CONDITION:	Generally satisfactory but with significant localised problems Declining			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 230m south west of High Bar	n Farm, Huggate	
DESIGNATION:	Scheduled Monument (No. 1013464)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 400m NNW of East Greenwi	ick Farm, Huggate	
DESIGNATION:	Scheduled Monument (No. 1014727)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 780m north east of Waterma	anhole Reservoir, I	Huggate
DESIGNATION:	Scheduled Monument (No. 1013864)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
	····ate	0011/1/1011	
SITE NAME:	Bowl barrow on Huggate Pasture, 350m no	orth east of Pastur	e Dale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013868)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Pasture, 450m N	NE of Pasture Dal	e Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013867)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Pasture, 500m no	orth of Pasture Da	le Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013866)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 400m NN	W of Watermanho	ole Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No. 1013861)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 460m WN	W of western cor	ner of Horsedale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013858)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 480m nort	h of Watermanho	le Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No. 1013862)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 500m NN\	W of Horsedale Pl	antation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013854)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
o.matti E	····	CONTACT.	1.0.0.1 Filler 01701 001770

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Bowl barrow on Huggate Wold, 580m north	h west of Horsed	ale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013857)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 600m NNV	V of Horsedale Pl	antation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013853)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 600m west	of Horsedale Plan	ntation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013859)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 700m NNV	V of Watermanho	le Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No. 1013863)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 700m nort	h west of Horsed	ale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1013856)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow on Huggate Wold, 840m ENE	of Watermanhole	Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No. 1013860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 240m south west of High Ba	arn Farm, Huggate	
DESIGNATION:	Scheduled Monument (No. 1012491)	CONDITION:	Extensive significant problems
			0 1
	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY: OWNER TYPE:		CONTACT:	Keith Miller 01904 601990
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private  Round barrow 320m south west of High Ba	CONTACT:	Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Private	contact: arn Farm, Huggate	Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Round barrow 320m south west of High Ba	CONTACT:  arn Farm, Huggate  CONDITION:	Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Round barrow 320m south west of High Ba Scheduled Monument (No. 1012479) Arable ploughing	contact:  arn Farm, Huggate  condition:  trend:  contact:	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base Scheduled Monument (No. 1012493)	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate  CONDITION:	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Private  Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate	Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  OWNER TYPE:	Private  Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base Scheduled Monument (No. 1012493) Arable ploughing	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  OWNER TYPE:	Private  Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base Scheduled Monument (No. 1012493) Arable ploughing Private  Round barrow 380m south west of High Base Round barrow 380m south west of High Base	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Cettensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Round barrow 320m south west of High Base Scheduled Monument (No. 1012479) Arable ploughing Private  Round barrow 360m south west of High Base Scheduled Monument (No. 1012493) Arable ploughing Private	CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:  arn Farm, Huggate  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Round barrow 390m south west of High Barn Farm, Huggate		
DESIGNATION:	Scheduled Monument (No. 1012489)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of a single and double linear bound		
	and the junctions of Holm Dale and Harpe		
DESIGNATION:	Scheduled Monument (No. 1015566)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke on Cow Moor, Millington Dale, Huggate		
designation:	Scheduled Monument (No. 1015571)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke south of M	liddleham Plantatio	on and Harper Dale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No. 1015569)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Sections of linear boundary dyke in Cow D	ale Plantation, Ral	obit Dale and Oxland Plantation. Huggat
DESIGNATION:	Scheduled Monument (No. 1015570)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
			redutt inter etter eette
SITE NAME:	Two bowl barrows on Huggate Wold, 600m	north west of H	
SITE NAME: DESIGNATION:		north west of H	
DESIGNATION:	Two bowl barrows on Huggate Wold, 600m Scheduled Monument (No. 1013855) Arable ploughing		orsedale Plantation, Huggate
	Scheduled Monument (No. 1013855)	CONDITION:	orsedale Plantation, Huggate  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013855) Arable ploughing Private	CONDITION: TREND:	orsedale Plantation, Huggate  Extensive significant problems  Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1013855) Arable ploughing Private	CONDITION: TREND:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)	CONDITION: TREND: CONTACT:  CONDITION:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202)	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202) Arable ploughing	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202)	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202) Arable ploughing	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202) Arable ploughing Private  Gallows Hill round barrow, Kilham	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  Le Kelk, Kelk CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013855) Arable ploughing Private  Shaw Fosse moated site, Humbleton Scheduled Monument (No. 1007847)  Scrub / tree growth Private  Nunnery Hill and adjacent earthworks, Litt Scheduled Monument (No. 1005202) Arable ploughing Private	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  Le Kelk, Kelk  CONDITION: TREND:	Extensive significant problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Iron Age barrow cemetery, Kilham			
DESIGNATION:	Scheduled Monument (No. 1005208)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 250m north east of Painsthorpe Wold Cottages, Kirby Underdale			
DESIGNATION:	Scheduled Monument (No. 1008417)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 350m south east of Fordham Farm, Kirby Underdale			
DESIGNATION:	Scheduled Monument (No. 1013165)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 500m south east of Painstho	orpe Wold Cottag	es, Kirby Underdale	
DESIGNATION:	Scheduled Monument (No. 1008347)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 600m north east of Painstho	orpe Wold Cottag	es, Kirby Underdale	
DESIGNATION:	Scheduled Monument (No. 1008408)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 850m north east of Wayrha	m Farm, Kirby Un	nderdale	
DESIGNATION:	Scheduled Monument (No. 1008351)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 900m north east of Wayrham Farm, Kirby Underdale			
DESIGNATION:	Scheduled Monument (No. 1008362)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow south east of South Wold Farm, Kirby Underdale			
DESIGNATION:	Scheduled Monument (No. 1009384)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
	Eastern bowl barrow of a pair at crossroads east of Craike Hill,			
SITE NAME:	Ikm NNW of Eastburn Warren Farm, Kirkb			
SITE NAME:  DESIGNATION:			Extensive significant problems	
	Ikm NNW of Eastburn Warren Farm, Kirkb	ourn	Extensive significant problems Declining	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Western bowl barrow of a pair east of Craike Hill, Ikm NNW of Eastburn Warren Farm, Kirkburn			
DESIGNATION:	Scheduled Monument (No. 1013709)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
ITE NAME:	Moated site at Metham Hall Farm, Laxton			
DESIGNATION:	Scheduled Monument (No. 1007972)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Moated site 100m north of Parkhouse Farm, Leconfield			
DESIGNATION:	Scheduled Monument (No. 1008292)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Moated site 310m north east of Scorborou	igh church, Leconf	îeld	
DESIGNATION:	Scheduled Monument (No. 1015818)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Moated site 550m south east of Scorborou	gh Hall, Leconfield	d	
DESIGNATION:	Scheduled Monument (No. 1016250)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Moated site of Leconfield Castle, Leconfield	d		
DESIGNATION:	Scheduled Monument (No. 1007949)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Hayholme moated site, Leven			
DESIGNATION:	Scheduled Monument (No. 1008043)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Hall Garth motte and bailey, Lockington			
DESIGNATION:	Scheduled Monument (No. 1021289)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Cleaving Hall moated site, Londesborough		
DESIGNATION:	Scheduled Monument (No. 1007817)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
	B II 100 d d (II:1)///	LE M L ()A/	• 1.
SITE NAME:	Bowl barrow 100m north east of High Wold	l Farm, Market VV	_
DESIGNATION:	Scheduled Monument (No. 1013672)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow I I 0m east of High Wold Farm, Market Weighton		
DESIGNATION:	Scheduled Monument (No. 1012091)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 200m south east of High Wold Farm, Market Weighton		
DESIGNATION:	Scheduled Monument (No. 1012092)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 320m north east of High Wol	d Farm, Market W	eighton eighton
DESIGNATION:	Scheduled Monument (No. 1012090)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 400m south of High Wold Far	m, Market Weight	on
DESIGNATION:	Scheduled Monument (No. 1012100)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 450m north east of High Wol	d Farm, Market W	eighton eighton
DESIGNATION:	Scheduled Monument (No. 1014256)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
	Bowl barrow 450m north of High Wold Far	m Market Meich	on
CITE NIAME:	וווטכד שווואט ושטטם ושטטם INVOID Far	iii, i iai ket vveight	.OII
SITE NAME:			E
DESIGNATION:	Scheduled Monument (No. 1012089)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012089) Arable ploughing	CONDITION: TREND:	Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1012089)		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012089) Arable ploughing	TREND: CONTACT:	Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far	TREND: CONTACT: m, Market Weight	Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088)	TREND: CONTACT:  m, Market Weight  CONDITION:	Declining Keith Miller 01904 601990  con  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088) Arable ploughing	TREND: CONTACT:  m, Market Weight  CONDITION: TREND:	Declining Keith Miller 01904 601990  con  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088)	TREND: CONTACT:  m, Market Weight  CONDITION:	Declining Keith Miller 01904 601990  con  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088) Arable ploughing	TREND: CONTACT:  m, Market Weight  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Con Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088) Arable ploughing Private	TREND: CONTACT:  m, Market Weight  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Con  Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1012089) Arable ploughing Private  Bowl barrow 550m north of High Wold Far Scheduled Monument (No. 1012088) Arable ploughing Private  Four bowl barrows 450m south east of High	TREND: CONTACT:  m, Market Weight CONDITION: TREND: CONTACT:  h Wold Farm, Man	Declining Keith Miller 01904 601990  con  Extensive significant problems Declining Keith Miller 01904 601990  cket Weighton

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Nine round barrows south east of Arras C	ottages, Market W	eighton/	
DESIGNATION:	Scheduled Monument (No. 1005228)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Six bowl barrows 300m north east of High	Wold Farm, Mark	et Weighton	
DESIGNATION:	Scheduled Monument (No. 1007501)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Iron Age barrow group north east of Middleton on the Wolds, Middleton			
DESIGNATION:	Scheduled Monument (No. 1003597)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 340m south east of Watermanhole Reservoir, Millington			
DESIGNATION:	Scheduled Monument (No. 1013865)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Dane's Graves, Nafferton			
DESIGNATION:	Scheduled Monument (No. 1005230)	CONDITION:	Generally satisfactory	
	`		but with significant localised problems	
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Five round barrows 750m south east of Ne	ewbald Lodge, Nev	wbald	
DESIGNATION:	Scheduled Monument (No. 1007325)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 400m south west of Newbald Lodge, Newbald			
DESIGNATION:	Scheduled Monument (No. 1011654)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 550m south east of Newbald Lodge, Newbald			
DESIGNATION:	Scheduled Monument (No. 1007320)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 600m south east of Newbal	d Lodge, Newbald	ı	
DESIGNATION:	Scheduled Monument (No. 1007321)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow 620m south east of Newbal	d Lodge, Newbald		
DESIGNATION:	Scheduled Monument (No. 1007323)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Round barrow 700m north east of Littlewo	ood Lodge, Newba	ıld	
DESIGNATION:	Scheduled Monument (No. 1007353)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 600m ESE of Blanch Farm, North Dalton			
DESIGNATION:	Scheduled Monument (No. 1013463)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 610m east of Blanch Farm, N	orth Dalton		
DESIGNATION:	Scheduled Monument (No. 1013460)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 620m ESE of Blanch Farm, No	orth Dalton		
DESIGNATION:	Scheduled Monument (No. 1013461)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Paull Holme moated site and tower, Paull			
DESIGNATION:	Scheduled Monument (No. 1007875)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Paull Point Battery, coastal artillery battery and Submarine Mining Establishment, Paull			
DESIGNATION:	Scheduled Monument (No. 1020425)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Argam dykes, Rudston			
DESIGNATION:	Scheduled Monument (No. 1005234)	CONDITION:	Generally unsatisfactory	
	(,		with major localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Earthwork on the Sheepwalk stretching no	rth from Wold Ga	ate for 530yds (480m), Rudston	
	Calcadulad Manuscant (No. 100E222)	CONDITION	Extensive significant problems	
DESIGNATION:	Scheduled Monument (No. 1005223)	CONDITION:	Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Roman villa site, Rudston			
DESIGNATION:	Scheduled Monument (No. 1005222)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
ITE NAME:	Rudston Beacon and round barrows to east	t, Rudston		
DESIGNATION:	Scheduled Monument (No. 1005231)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Bowl barrow 550m south of High Wold Farm, Sancton			
DESIGNATION:	Scheduled Monument (No. 1012102)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Moated monastic grange 300m south west of Winsetts Farm, Skeffling			
DESIGNATION:	Scheduled Monument (No. 1015309)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Hallgarth medieval hall and moat, Skipsea			
DESIGNATION:	Scheduled Monument (No. 1013705)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Royal Observer Corps underground monito 200m north of Southfield House, Skipsea	oring post and Wo	orld War II visual spotting post,	
DESIGNATION:	Scheduled Monument (No. 1021192)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Skipsea Castle: 11th century motte and bailey castle and inland harbour, Skipsea			
DESIGNATION:	Scheduled Monument (No. 1011212)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	but with significant localised problems  Declining	
	Drainage/dewatering Private	TREND: CONTACT:	Declining Keith Miller 01904 601990	
OWNER TYPE:		CONTACT:	Declining Keith Miller 01904 601990	
OWNER TYPE: SITE NAME:	Private	CONTACT:	Declining Keith Miller 01904 601990	
OWNER TYPE: SITE NAME:	Private  Moated site, fishponds and associated earth	contact: works at Manor H	Declining Keith Miller 01904 601990  House, Skirpenbeck	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Moated site, fishponds and associated earth	contact: works at Manor H	Declining Keith Miller 01904 601990  House, Skirpenbeck Generally satisfactory	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Moated site, fishponds and associated earth Scheduled Monument (No. 1015614)	contact:  works at Manor H	Declining Keith Miller 01904 601990  House, Skirpenbeck Generally satisfactory but with significant localised problems	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Private  Moated site, fishponds and associated earth Scheduled Monument (No. 1015614)  Drainage/dewatering	CONTACT:  works at Manor H  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Moated site, fishponds and associated earth Scheduled Monument (No. 1015614)  Drainage/dewatering Private	CONTACT:  works at Manor H  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Moated site, fishponds and associated earth Scheduled Monument (No. 1015614)  Drainage/dewatering Private  Round barrow I 300m east of Life Hill, Sledn	CONTACT:  works at Manor H  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow I400m east of Life Hill, Sledi	mere	
DESIGNATION:	Scheduled Monument (No. 1007859)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 1650m east of Life Hill, Sledi	mere	
DESIGNATION:	Scheduled Monument (No. 1007860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Kings Manor moated site, 450m south of Li	ttle London, Snait	h and Cowick
DESIGNATION:	Scheduled Monument (No. 1015307)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site at St Lois Farm, Sutton upon D	)erwent	
DESIGNATION:	Scheduled Monument (No. 1007818)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hall Garth moated site, associated drainage	channels and fish	pond, Twin Rivers
DESIGNATION:	Scheduled Monument (No. 1013190)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Ling Howe long barrow, Walkington		
	Ling Howe long barrow, Walkington Scheduled Monument (No. 1015306)	CONDITION:	Extensive significant problems
DESIGNATION:		CONDITION: TREND:	Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015306)		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015306) Arable ploughing	TREND: CONTACT:	Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1015306) Arable ploughing Private	TREND: CONTACT:	Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow I70m north west of Farberry	TREND: CONTACT:  Garth Farm, War	Declining Keith Miller 01904 601990 ter
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471)	TREND: CONTACT:  Garth Farm, War  CONDITION:	Declining Keith Miller 01904 601990  ter  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow I70m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow I70m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private  Bowl barrow 210m south east of Blanch Fa	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:  rm, Warter	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining Keith Miller 01904 601990
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private  Bowl barrow 210m south east of Blanch Fa	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:  rm, Warter  CONDITION:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private  Bowl barrow 210m south east of Blanch Fa Scheduled Monument (No. 1013456) Arable ploughing	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:  rm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private  Bowl barrow 210m south east of Blanch Fa Scheduled Monument (No. 1013456) Arable ploughing Private	TREND: CONTACT:  Garth Farm, War  CONDITION: TREND: CONTACT:  rm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No. 1015306) Arable ploughing Private  Bowl barrow 170m north west of Farberry Scheduled Monument (No. 1013471) Arable ploughing Private  Bowl barrow 210m south east of Blanch Fa Scheduled Monument (No. 1013456) Arable ploughing Private  Bowl barrow 290m south east of Blanch Fa	TREND: CONTACT:  Garth Farm, War CONDITION: TREND: CONTACT:  rm, Warter CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  ter  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Bowl barrow 500m east of Blanch Farm, W	arter	
DESIGNATION:	Scheduled Monument (No. 1013459)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 560m NNW of Farberry Gar	th Farm,Warter	
DECICA IATION I.	Scheduled Monument (No. 1013467)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 720m NNW of Farberry Gar	th Farm,Warter	
DESIGNATION:	Scheduled Monument (No. 1013466)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 760m NNE of Farberry Gartl	n Farm, Warter	
DESIGNATION:	Scheduled Monument (No. 1013465)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
OWNERTHE.	Tillate	CONTROL.	Total Timer 61761 661776
SITE NAME:	Round barrow 100m south west of Cobdalo	e Farm, Warter	
DESIGNATION:	Scheduled Monument (No. 1011895)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round barrow 400m north west of Cobdal	e Farm,Warter	
DESIGNATION:	Scheduled Monument (No. 1012508)	CONDITION:	Extensive significant problems
	Scheduled Monument (No. 1012508) Arable ploughing	CONDITION: TREND:	Extensive significant problems Declining
PRINCIPAL VULNERABILITY:			- '
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing	TREND: CONTACT:	Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Arable ploughing Private  Round barrow 450m north east of Blanch I	TREND: CONTACT:  Farm, Warter	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906)	TREND: CONTACT:  Farm, Warter  CONDITION:	Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 450m north east of Blanch I	TREND: CONTACT:  Farm, Warter	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 450m north east of Blanch I  Scheduled Monument (No. 1011906)  Arable ploughing	TREND: CONTACT:  Farm, Warter  CONDITION: TREND:	Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  Round barrow 450m north east of Blanch I  Scheduled Monument (No. 1011906)  Arable ploughing	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890)	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farm Scheduled Monument (No. 1011890) Arable ploughing	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890)	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  n, Warter  CONDITION:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farm Scheduled Monument (No. 1011890) Arable ploughing	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  n, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  OWNER TYPE:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  n, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  DESIGNATION:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private  Round barrow 915m north east of Dalton	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  n, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private  Round barrow 915m north east of Dalton Scheduled Monument (No. 1011911)	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  CONTACT:  TREND: CONTACT:  Gates Farm, Warter  CONDITION:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  er Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  OWNER TYPE:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private  Round barrow 915m north east of Dalton Scheduled Monument (No. 1011911) Arable ploughing	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  IN, Warter  CONDITION: TREND: CONTACT:  Gates Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  er  Extensive significant problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  OWNER TYPE:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private  Round barrow 915m north east of Dalton Scheduled Monument (No. 1011911) Arable ploughing Private  Round barrow 930m north east of Dalton	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  IN, Warter  CONDITION: TREND: CONTACT:  Gates Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  er Extensive significant problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 450m north east of Blanch I Scheduled Monument (No. 1011906) Arable ploughing Private  Round barrow 520m south of Warren Farr Scheduled Monument (No. 1011890) Arable ploughing Private  Round barrow 915m north east of Dalton Scheduled Monument (No. 1011911) Arable ploughing Private	TREND: CONTACT:  Farm, Warter  CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  Gates Farm, Warter  CONDITION: TREND: CONTACT:  Gates Farm, Warter  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  er  Extensive significant problems Declining Keith Miller 01904 601990  Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

SITE NAME:	Round barrow on Thirty Acres, Warter		
DESIGNATION:	Scheduled Monument (No. 1011908)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Section of linear boundary dyke between Syl north west of Coldwold Farm, Warter	van Dale and Wa	arren Farm,
DESIGNATION:	Scheduled Monument (No. 1016191)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two bowl barrows 300m south east of Blanc	h Farm Warter	
		•	F
DESIGNATION:	Scheduled Monument (No. 1013458)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two bowl barrows 500m north west of Farb	erry Garth Farm	n,Warter
DESIGNATION:	Scheduled Monument (No. 1013470)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Two round barrows 820m north east of Dalt	ton Gates Farm,	Warter
DESIGNATION:	Scheduled Monument (No. 1011912)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Site of Watton Gilbertine priory, two possible	le medieval arch	ery butts and Civil War earthworks, Wattor
DECIGNATION	Scheduled Monument (No. 1007751)	CONDITION:	Generally satisfactory
DESIGNATION:	scriedaled Floridifient (140. 1007751)		but with significant lacelised problems
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
PRINCIPAL VULNERABILITY:		TREND: CONTACT:	-
PRINCIPAL VULNERABILITY: OWNER TYPE:	Deterioration – in need of management	CONTACT:	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Deterioration – in need of management Private	CONTACT:	Declining Keith Miller 01904 601990  Farm, Wawne
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o	CONTACT:  f North Grange	Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o	CONTACT:  f North Grange	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory
PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east of Scheduled Monument (No. 1008039)	CONTACT:  f North Grange  CONDITION:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn	f North Grange  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in	f North Grange  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east of Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn Scheduled Monument (No. 1016068)	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne  CONDITION:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn	f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn Scheduled Monument (No. 1016068)  Scrub / tree growth	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn Scheduled Monument (No. 1016068)  Scrub / tree growth	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east o Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawr Scheduled Monument (No. 1016068)  Scrub / tree growth Private	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Farm, Wawne Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Deterioration – in need of management Private  Medieval moated tile kiln 250m north east of Scheduled Monument (No. 1008039)  Deterioration – in need of management Private  Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn Scheduled Monument (No. 1016068)  Scrub / tree growth Private  Haltemprice Augustinian priory, Willerby	CONTACT:  f North Grange  CONDITION:  TREND:  CONTACT:  n Paradise Woodne  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Farm, Wawne  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Bowl barrow 580m west of High Fordon Fa	arm,Wold Newto	n
DESIGNATION:	Scheduled Monument (No. 1007743)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERTYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Bowl barrow 600m west of High Fordon Fa	arm,Wold Newto	n
DESIGNATION:	Scheduled Monument (No. 1007742)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hall Garth moated site south of Beverley N	1inster, Woodman	sey
DESIGNATION:	Scheduled Monument (No. 1008122)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
	Private	CONTACT:	Keith Miller 01904 601990



SITE NAME:	Thwaite Hall, Cottingham
DESIGNATION:	Registered Park and Garden Grade II, also CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Private, single owner

Grounds of a villa developed mainly in the  $1\,870s$  / 80s, but modified in the mid C20 to provide accommodation for the University College of Hull. Grounds partly developed as a botanical garden. Problems with flood damage in 2007 and drainage problems are affecting mature planting and lawns around the lake.

Contact: Andy Wimble 01904 601970



SITE NAME:	Londesborough Park, Londesborough
DESIGNATION:	Registered Park and Garden Grade II*,
	also part in CA, 5 LBs
CONDITION:	Generally satisfactory
	but with significant localised problems
VULNERABILITY:	High
TREND:	Declining

Gardens laid out in the late C17 wholly or partly by Robert Hooke for the first Lord Burlington, with alterations and additions by the third Lord Burlington in the early to mid C18. Park with avenues of early C18 date with earlier origins. Kitchen garden of 1730-5 with cascades and entrances aligned with parkland avenues. Extensive parkland requiring more detailed study of historic development of the planting design, key avenues and vistas. Structures in walled garden in state of deterioration.

OWNER TYPE: Private, multiple owners Contact: Andy Wimble 01904 601970




SITE NAME:	Battle of Stamford Bridge, Stamford Bridge
DESIGNATION:	Registered Battlefield
CONDITION:	Generally satisfactory
	but with minor localised problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Private

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later C20 and little of the battlefield remains undeveloped.

Contact: Keith Emerick 01904 601988

#### KINGSTON UPON HULL, CITY OF (UA)



St Albans Church, SITE NAME: Hall Road

DESIGNATION: Listed Place of Worship Grade II CONDITION:

C (New entry) PRIORITY: OWNERTYPE: Religious organisation

Parish church dating to 1938, completed 1954. Constructed from orange brick under a pantile roof. Interior has flat concrete arches. Church located in a busy residential area of the town and maintained in use. Tower recently repaired, but aisle roofs in need of recovering.

Contact: Giles Proctor 01904 601981

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

**ABBREVIATIONS** CA LB/LBs

Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs Unitary Authority World Heritage Site UA WHS

SITE NAME:	Beverley Road, Hull		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Philip Hampel (LPA) 01482 612343	NEW ENTRY?:	No
SITE NAME:	Holderness Road (West), Hull		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Philip Hampel (LPA) 01482 612343	NEW ENTRY?:	No
SITE NAME:	St Andrew's Dock, Hull		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Philip Hampel (LPA) 01482 612343	NEW ENTRY?:	No

#### NORTH EAST LINCOLNSHIRE (UA)



The Grimsby Ice Factory,
Gorton Street,
Grimsby

DESIGNATION: Listed Building Grade II\*
CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: A (A)
OWNERTYPE: Company

1900 ice works with extension factory of 1907-8 and later alterations. Closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. Window damage. Roof is now deteriorating rapidly.



SITE NAME: Church of Saint Margaret, Barton Street, Hawerby cum Beesby

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (D)

OWNER TYPE: Private

Former parish church. C12, C13 and C17 with mid C19 restorations. Empty and disused since being made redundant in 1978. Longstanding proposals for conversion to studio / gallery were never implemented. Suffering from neglect, with localised collapses of walling.

Contact: Keith Miller 01904 601990

Contact: Tammy Whitaker 01904 601880

SITE NAME:	Civil War earthwork fort 350m north east	of Walk Farm, Irby	у
DESIGNATION:	Scheduled Monument (No. 1007735)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Premonstratensian priory chapel 170m sout	th west of Priory I	Farm, West Ravendale
DESIGNATION:	Scheduled Monument (No. 1019867)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Central Sea Front, Cleethorpes		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	No

#### PRIORITY (FOR BUILDINGS)


- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Central Area, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	No
SITE NAME:	Great Coates, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	Yes
SITE NAME:	Holme Hill, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	Yes
SITE NAME:	Laceby		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	Yes
SITE NAME:	Waltham		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Tony Sargent (LPA) 01472 324252	NEW ENTRY?:	No

#### NORTH LINCOLNSHIRE (UA)



SITE NAME:

Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow

DESIGNATION: Listed Building Grade II\*, SM

CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY: Private OWNER TYPE:

Contact: Tammy Whitaker 01904 601880



Manor Farmhouse, SITE NAME: East Halton Road, North Killingholme

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant OCCUPANCY:

PRIORITY: B (B)

OWNERTYPE: Private

Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A feasibility study has been completed.

Combined wind and watermill, I 802, by James Middleton

of Hibaldstow. Some repairs undertaken, but further work required to both exterior and interior.

Contact: Keith Miller 01904 601990



Church of St Martin, SITE NAME:

Church Street,

Owston Ferry

Medieval church with early C19 north aisle.

Roofs and drainage in poor condition. Grant offered.

DESIGNATION: Listed Place of Worship Grade I

CONDITION: Poor

PRIORITY: D (New entry)

OWNERTYPE: Religious organisation

Contact: Susan Daniels 01904 601979

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

CA LB/LBs Conservation Area LPA NP RPG SM/SMs UA WHS



Church of St Lawrence, SITE NAME:

Main Street, Thornton Curtis Very fine medieval church with outstanding font. Roofs repaired with grant. Grant offered for repairs

to tower.

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION:

PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Andrew, High Street, Wootton

DESIGNATION: Listed Place of Worship Grade I

Very bad D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

The church dates to the C13; although both in the early English style, the north arcade is thought to be later in date than the south. The west tower is late Perpendicular, the top rebuilt in 1877. The chancel was rebuilt in 1851 when the whole building underwent a restoration and was re-roofed. Grant has been offered for repairs to the tower roof, north and south aisle masonry and stained glass.

Contact: Susan Daniels 01904 601979

SITE NAME:	Heavy Anti-aircraft gunsite 220m east of We	st Marsh Cottag	e, Barrow upon Humber
DESIGNATION:	Scheduled Monument (No. 1020024)	CONDITION:	Generally satisfactory
			but with minor localised problem
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moated site 285m east of Castlethorpe Hou	se, Broughton	
DESIGNATION:	Scheduled Monument (No. 1016429)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Yarborough Camp large univallate hillfort, Co	oxton	
DESIGNATION:	Scheduled Monument (No. 1016427)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British settlement near Staniwells F	arm, Hibaldstow	
DESIGNATION:	Scheduled Monument (No. 1005221)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman settlement, Kirmington		
DESIGNATION:	Scheduled Monument (No. 1005206)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Romano-British villa at Mount Pleasant Farm	, Kirton in Linds	еу
DESIGNATION:	Scheduled Monument (No. 1013627)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Moated site and fishpond 200m south east	of Melton Hall, M	elton Ross
DESIGNATION:	Scheduled Monument (No. 1007747)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	North Garth moated site and associated en	nclosures, North I	Killingholme
DESIGNATION:	Scheduled Monument (No. 1007815)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Money Field Roman site, Dragonby, North	Lincolnshire	
DESIGNATION:	Scheduled Monument (No. 1005224)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Kinaird motte and bailey castle, Owston Fe	rry	
DESIGNATION:	Scheduled Monument (No. 1017556)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Thornton Abbey Augustinian monastery: gatehouse, precinct, medieval road and bridge, moat, fishponds, post-Dissolution college and school, and house, Thornton Curtis		
DESIGNATION:	Scheduled Monument (No. 1011198)	CONDITION:	Generally satisfactory but with significant localised problems
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Private	TREND: CONTACT:	
	·	CONTACT:	Declining
OWNER TYPE: SITE NAME:	Private  Old Winteringham Roman settlement, Winteringham settlement,	contact: teringham	Declining Keith Miller 01904 601990
OWNER TYPE: SITE NAME: DESIGNATION:	Old Winteringham Roman settlement, Winteringham (No. 1005243)	contact: teringham condition:	Declining Keith Miller 01904 601990  Extensive significant problems
OWNER TYPE: SITE NAME:	Private  Old Winteringham Roman settlement, Winteringham settlement,	contact: teringham	Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Old Winteringham Roman settlement, Winteringham Roman (No. 1005243)  Arable ploughing	CONTACT:  teringham  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Extensive significant problems Improving
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Old Winteringham Roman settlement, Winteringham Roman settlement, Winteringham Roman settlement, Wintering Scheduled Monument (No. 1005243)  Arable ploughing  Private	CONTACT:  teringham  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Extensive significant problems Improving
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Old Winteringham Roman settlement, Winteringham Roman settlement, Winteringham Roman settlement, Wintering Scheduled Monument (No. 1005243)  Arable ploughing Private  Howe Hill bowl barrow, Wootton	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Old Winteringham Roman settlement, Winteringham Roman settlement, Winteringham Roman settlement, Wintering Scheduled Monument (No. 1005243)  Arable ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 1009346)	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Old Winteringham Roman settlement, Winteringham Roman settlement, Winteringham Roman settlement, Wintering Scheduled Monument (No. 1005243)  Arable ploughing Private  Howe Hill bowl barrow, Wootton	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Old Winteringham Roman settlement, Winteringham Roman settleme	CONTACT:  teringham  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Old Winteringham Roman settlement, Roma	CONTACT:  teringham  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Old Winteringham Roman settlement, Winteringham Roman settleme	CONTACT:  teringham  CONDITION:  TREND:  CONDITION:  TREND:  CONTACT:  Vorlaby Church, W	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:	Old Winteringham Roman settlement, Winteringham Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 1009346)  Arable clipping Private  Roman site 400yds (370m) north east of Winteringham Scheduled Monument (No. 1005233)	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  Vorlaby Church, W	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Yorlaby Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Old Winteringham Roman settlement, Winteringham Roman site for Winteringham Scheduled Monument (No. 1009346)  Arable clipping Private  Roman site 400yds (370m) north east of Winteringham Scheduled Monument (No. 1005233)  Arable ploughing	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  Vorlaby Church, W  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Yorlaby  Extensive significant problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  DESIGNATION:  OWNER TYPE:	Old Winteringham Roman settlement, Winteringham Roman site ploughing Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 1009346)  Arable clipping Private  Roman site 400yds (370m) north east of Winteringham Scheduled Monument (No. 1005233)  Arable ploughing Private	CONTACT:  teringham  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:  Vorlaby Church, W  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Yorlaby Extensive significant problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:	Old Winteringham Roman settlement, Winteringham Private  Howe Hill bowl barrow, Wootton  Scheduled Monument (No. 1009346)  Arable clipping Private  Roman site 400yds (370m) north east of Winteringham Scheduled Monument (No. 1005233)  Arable ploughing Private  Crowle	CONTACT:  teringham  CONDITION: TREND: CONTACT:  CONDITION:  TREND: CONTACT:  Vorlaby Church, W  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Extensive significant problems Improving Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Corlaby  Extensive significant problems Declining Keith Miller 01904 601990

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Winterton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	lan Goldthorpe (LPA) 01724 297396	NEW ENTRY?:	Yes

### **NORTH YORKSHIRE**

#### **CRAVEN**



Dale End Mills, SITE NAME: Dale End, Lothersdale

DESIGNATION: Listed Building Grade II, SM Poor CONDITION:

Part occupied PRIORITY: C (C) OWNERTYPE: Private

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel is the largest in England and is in poor condition. The mill roofs are deteriorating. The base of the stack is also in need of remedial work. Discussions are underway with the owner to find a

solution to the building repair.

Contact: Giles Proctor 01904 601981

SITE NAME:	Moated site west of Paget Hall, Gargrave		
DESIGNATION:	Scheduled Monument (No. 1004126)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988

#### **HAMBLETON**



The Coach House, SITE NAME: Rounton Grange, East Rounton

DESIGNATION: Listed Building Grade II\* Very bad CONDITION: occupancy: Part occupied A(A)Private OWNER TYPE:

Coach house, built in 1875. Now used as a combined home and workshop. One range is in a fair condition, the rest is in state of collapse.

Contact: Diane Green 01904 601973



SITE NAME: Landmoth Hall, Landmoth cum Catto

designation: Scheduled Monument

CONDITION: Very bad N/A OCCUPANCY: B (B) PRIORITY: Private OWNER TYPE:

Part of the east wing of a medieval manor house. Now in an unstable condition.



Contact: Keith Emerick 01904 601988

Late C18 lodge and entrance gateway. Deteriorating.



#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### **ABBREVIATIONS**

Conservation Area CA LB/LBs Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs Unitary Authority World Heritage Site UA WHS



STE NAME: Snape Castle, Snape with Thorp

DESIGNATION: Listed Building Grade I, SM, CA, RPG II

condition: Very bad occupancy: Part occupied

PRIORITY: B (B)

OWNERTYPE: Private

Castle dated to circa 1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins, including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Keith Emerick 01904 601988



SITE NAME: Stables at

Harlsey Castle Farmhouse,

West Harlsey

DESIGNATION: Listed Building Grade II\*, SM

CONDITION: Poor
OCCUPANCY: Occupied
PRIORITY: D (D)
OWNER TYPE: Private

Remains of medieval castle keep; in use as farm buildings.

Contact: Keith Emerick 01904 601988



SITE NAME:

Church of St Mary, Bolton on Swale Medieval church, heavily restored C19, with interesting murals to chancel. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*, CA

condition: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981

SITE NAME:	Medieval moated grange 160m south east of	The Grange, Bal	k
DESIGNATION:	Scheduled Monument (No. 1015920)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Birkby medieval settlement and associated fi	ield system, moat	ed site and fishponds, Birkby
DESIGNATION:	Scheduled Monument (No. 1016944)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Lime kilns 400m south west of Furlands, Bo	rrowby	
DESIGNATION:	Scheduled Monument (No. 1021190)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow I50m south of Warren Hous	e, Brandsby cum	Stearsby
DESIGNATION:	Scheduled Monument (No. 1013601)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m east of Warren House	, Brandsby cum S	tearsby
DESIGNATION:	Scheduled Monument (No. 1013600)	CONDITION:	Generally satisfactory
	` ,		,

#### PRIORITY (FOR BUILDINGS)

PRINCIPAL VULNERABILITY:

OWNER TYPE:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Plant growth

Private

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

TREND:

CONTACT:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

Declining

#### ABBREVIATIONS

but with significant localised problems

Keith Emerick 01904 601988

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Round barrow 300m west of Quarry Hous	e, Brandsby cum S	itearsby
DESIGNATION:	Scheduled Monument (No. 1013602)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 330yds (300m) south of Bar	house Farm, Bran	dsby cum Stearsby
DESIGNATION:	Scheduled Monument (No. 1003659)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 450m north east of Hagg Fa	rm, Brandsby cum	Stearsby
DESIGNATION:	Scheduled Monument (No. 1013592)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Healam Bridge Roman fort and vicus, Burne	eston	
DESIGNATION:	Scheduled Monument (No. 1021211)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Road construction	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
DESIGNATION:	Scheduled Monument (No. 1020346)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020346)  Gardening  Private	CONDITION:  TREND:  CONTACT:	· · · · · · · · · · · · · · · · · · ·
DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Gardening Private	TREND:	but with minor localised problems Stable
PRINCIPAL VULNERABILITY:	Gardening	TREND:	but with minor localised problems Stable
PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Gardening Private	TREND:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)	TREND: CONTACT:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Gardening Private  Deighton moated site, Deighton Scheduled Monument (No. 1004099)  Drainage/dewatering	TREND: CONTACT:  CONDITION: TREND:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown
PRINCIPAL VULNERABILITY: DWNER TYPE:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)	TREND: CONTACT:  CONDITION:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Gardening Private  Deighton moated site, Deighton Scheduled Monument (No. 1004099)  Drainage/dewatering	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosi	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and burn	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosi	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  cerfield and Thornborough, Generally satisfactory
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and burincluding Centre Hill round barrow, East Tar	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosi	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  terfield and Thornborough,
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and bur including Centre Hill round barrow, East Tail Scheduled Monument (No. 1004912)	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosinfield  CONDITION:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  cerfield and Thornborough, Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and burincluding Centre Hill round barrow, East Tail Scheduled Monument (No. 1004912)  Arable ploughing	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosinfield  CONDITION: TREND: CONTACT:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  cerfield and Thornborough, Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and burincluding Centre Hill round barrow, East Tail Scheduled Monument (No. 1004912)  Arable ploughing Private	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nosinfield  CONDITION: TREND: CONTACT:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  cerfield and Thornborough, Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Gardening Private  Deighton moated site, Deighton  Scheduled Monument (No. 1004099)  Drainage/dewatering Private  Earth circles, cursus, pit alignments and bur including Centre Hill round barrow, East Tar Scheduled Monument (No. 1004912)  Arable ploughing Private  Round barrow 425m north west of Rushwo	TREND: CONTACT:  CONDITION: TREND: CONTACT:  ial sites near Nost nfield  CONDITION: TREND: CONTACT:	but with minor localised problems Stable Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Unknown Keith Emerick 01904 601988  cerfield and Thornborough, Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Medieval moated site, fishponds and associal 125m south of Eldmire Cottage, Eldmire wi		
DESIGNATION:	Scheduled Monument (No. 1015419)	CONDITION:	Generally satisfactory
	1 10 10 10 10 1		but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable Keith Emerick 01904 601988
OWNER TYPE:	Private	CONTACT:	Reith Emerick 01904 601988
SITE NAME:	Medieval settlement of Little Broughton, as: and site of medieval chapel, Great and Little		em
DESIGNATION:	Scheduled Monument (No. 1018921)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow I80m NNE of St Wilfred's C	Church, Kirby Kno	wle
designation:	Scheduled Monument (No. 1010527)	CONDITION:	Generally unsatisfactory
	Amble dissis -		with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 250m north east of Comer	Lodge, Kirklingtor	cum Upsland
DESIGNATION:	Scheduled Monument (No. 1016265)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site known as The Rush, Marton cu	ım Moxby	
DESIGNATION:	Scheduled Monument (No. 1003661)	CONDITION:	Generally satisfactory
525,6, 0 11,6,1	ochodalod violalite (violateosoch)	20112111011	but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of cross ridge dyke and earthworks	s in Roman Planta	tion, Oulston Moor, Oulston
DESIGNATION:	Scheduled Monument (No. 1013438)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	A moated site 100m east of St Mary Magda	lene's Church,Thi	rsk
DESIGNATION:	Scheduled Monument (No. 1008179)	CONDITION:	Generally unsatisfactory
	23.722.727.73.73.73.74	CO. COMON.	with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow known as Gospel Hill, 80m :	south west of Pasi	ture House,Thornton Watlass
	·		
DESIGNATION:	Scheduled Monument (No. 1018922)	CONDITION:	Generally satisfactory
			but with significant localised problems
	Anabla dianing		I la la a una
PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable clipping Private	TREND: CONTACT:	Unknown Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Maiden Bower and Cock Lodge: a motte ar windmill mound and associated linear outw		pated site,
DESIGNATION:	Scheduled Monument (No. 1011612)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Medieval Park Pale, Upsall Estate, Thirsk, Up	osall	
DESIGNATION:	Scheduled Monument (No. 1010804)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three round barrows at Three Hills 500m	north east of Cam	p House, West Tanfield
DESIGNATION:	Scheduled Monument (No. 1015764)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Rabbit Hill, I 20m north o	of High Park Hous	e,Winton, Stank and Hallikeld
DESIGNATION:	Scheduled Monument (No. 1020353)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
THI VOIT IE VOEI VEIV (BIETI I.			0
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	· · · -	CONTACT:	Keith Emerick 01904 601988
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
OWNER TYPE: SITE NAME:	Private  Four round barrows on Yearsley Moor 200	contact: m south west of H	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory
OWNER TYPE:  SITE NAME:  DESIGNATION:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)	m south west of H	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth	CONTACT:  m south west of H  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)  Plant growth Private	CONTACT:  m south west of H  CONDITION:  TREND:  CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  odge, Yearsley  Generally satisfactory
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DITE NAME:  DESIGNATION:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth Private  Round barrow on Yearsley Moor 330m SSV	CONTACT:  m south west of H  CONDITION:  TREND:  CONTACT:  V of High Lions' L	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  odge, Yearsley
DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448)	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)  Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448)  Scrub / tree growth	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)  Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448)  Scrub / tree growth Private	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448) Scrub / tree growth Private  Round barrow on Yearsley Moor 400m sour Scheduled Monument (No. 1013447)	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:  th west of High Li  CONDITION:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory but with significant localised problems  Jeons' Lodge, Yearsley  Generally satisfactory but with significant localised problems
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)  Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448)  Scrub / tree growth Private  Round barrow on Yearsley Moor 400m sou	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448) Scrub / tree growth Private  Round barrow on Yearsley Moor 400m sour Scheduled Monument (No. 1013447) Plant growth	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:  th west of High Li  CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Keith Emerick 01904 601988
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446) Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448) Scrub / tree growth Private  Round barrow on Yearsley Moor 400m sour Scheduled Monument (No. 1013447) Plant growth Private  Two round barrows on Yearsley Moor 550m	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:  th west of High Li  CONDITION:  TREND: CONTACT:	Reith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  High Lions' Lodge, Yearsley
DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Private  Four round barrows on Yearsley Moor 2006 Scheduled Monument (No. 1013446)  Plant growth Private  Round barrow on Yearsley Moor 330m SSV Scheduled Monument (No. 1013448)  Scrub / tree growth Private  Round barrow on Yearsley Moor 400m sour Scheduled Monument (No. 1013447)  Plant growth Private	CONTACT:  m south west of H  CONDITION:  TREND: CONTACT:  V of High Lions' L  CONDITION:  TREND: CONTACT:  th west of High Li  CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  High Lions' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Odge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Hons' Lodge, Yearsley  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### **HARROGATE**



TE NAME:	Chapel of St Mary attached to
	the mansion, Allerton Park,
	Allerton Mauleverer with Hopperton

DESIGNATION: Listed Building Grade II\*, RPG II

OCCUPANCY: Vacant
PRIORITY: D (C)
OWNERTYPE: Trust

Redundant Roman Catholic chapel, circa I 807, attached to the grade I house. The house stands on a promontory in the eastern section of the CI8 park, with mid CI9 terraces to the north. Much of the interior of the chapel has been stripped out for dry rot treatment. English Heritage has funded an up-to-date condition survey and a repair specification has been prepared.

Contact: Giles Proctor 01904 601981



Coach house and bee hives approx
10 metres to north of Nutwith Cote,
Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\*
CONDITION: Poor
OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Private

Coach house with bee hives. Mid C18 and C16. The rear hall of the coach house is settling and the end return of the bee hives is failing. There are structural cracks to the right hand return and rear, and some of the copings are missing from the rear gable. Pointing is failing to cut stone on facades leaving some stone loose.

Contact: Diane Green 01904 601973



Outbuilding approx 20m to north of Nutwith Cote, Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERTYPE: Private

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Diane Green 01904 601973



Temple of Victory
with railed enclosure,
Allerton Park, Flaxby

DESIGNATION: Listed Building Grade II\*, RPG II
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: D (E)
OWNER TYPE: Trust

Summerhouse or view point, 1790, situated on a knoll in the park, to NW of the house. Re-roofed, cornice repaired and building made secure over 10 years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs needed to stonework below cornice level and to steps and railings, and interior needs re-instating. Extensive views from the Temple over the park and surrounding landscape.

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Mary,
Harlow Terrace,
Harrogate

DESIGNATION: Listed Building Grade II\*, CA

PIOCCUPANCY: Vacant F (F)

OWNER TYPE: Company

Redundant church circa 1916 by Sir Walter Tapper. Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. It is now proposed to convert the church into a luxury day spa, with minimal internal subdivision. English Heritage is proposing to support the cost of repairs.

Contact: Giles Proctor 01904 601981



SITE NAME: The Old Hall,
Middleton Quernhow

DESIGNATION: Listed Building Grade II, SM CONDITION: Poor OCCUPANCY: N/A

PRIORITY: C (C)

OWNERTYPE: Private

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable.

Contact: Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified, or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA C LB/LBs Li LPA Lc NP N RPG R SM/SMs Sc UA U WHS W



Orangery with flanking walls. SITE NAME: botheys and pavilion (Ripley Castle), Ripley

DESIGNATION: Listed Building Grade II\*, CA, RPG II

Poor CONDITION: Part occupied OCCUPANCY:

C(C)Private OWNER TYPE:

Classical Orangery in walled garden with flanking pavilions, circa 1785 by William Belwood. One surviving glasshouse circa 1840, now repaired. Botheys, in poor condition, to rear. East Pavilion recently repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Diane Green 01904 601973

offered but not accepted by owner.

Medieval bridge, now crossed by a public footpath.

The structure is overgrown and decaying and there

is danger of structural collapse. English Heritage grant



Butterton Bridge, SITE NAME: Sawley

DESIGNATION: Scheduled Monument Poor CONDITION:

N/A OCCUPANCY: C(C)PRIORITY: OWNERTYPE: Private

Contact: Neil Redfern 01904 601897



Dob Park Lodge, SITE NAME: Dob Park Lane, Weston

DESIGNATION: Listed Building Grade II, SM

Very bad CONDITION: N/A OCCUPANCY: D (C) PRIORITY-OWNERTYPE: Private

Ruins of a C17 park lodge, now roofless structure three storeys high. Scheduled as an Ancient Monument in 1997. Proposal to consolidate most 'at risk' fabric is being grant-aided by English Heritage.

Contact: Giles Proctor 01904 601981

Cairnfield, enclosures, boulder walling, hollow way and carved rocks

towards edge of Snowden Carr centred at 370m south east of Crag House, Askwith

Scheduled Monument (No. 1014304) CONDITION: Generally satisfactory DESIGNATION: but with significant localised problems

Plant growth PRINCIPAL VULNERABILITY: Declining TREND:

Private Keith Emerick 01904 601988 OWNER TYPE CONTACT

SITE NAME Rock with complex carving south west of a wall junction, 265m SSW of Far High Westcliff, Bewerley

Scheduled Monument (No. 1014969) Generally satisfactory CONDITION: DESIGNATION: but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Unknown Private Keith Emerick 01904 601988 OWNER TYPE: CONTACT

Stone alignment west of Boroughbridge known as the Devil's Arrows, SITE NAME

including three standing stones and the setting for a fourth, Boroughbridge

Scheduled Monument (No. 1014705) Generally satisfactory DESIGNATION: CONDITION: but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping **Improving** TREND

Private Keith Emerick 01904 601988 OWNER TYPE: CONTACT

Henge monument 300m north of Nunwick, Hutton Conyers

Scheduled Monument (No. 1012724) Extensive significant problems DESIGNATION: CONDITION: Arable ploughing Declining PRINCIPAL VULNERABILITY: TREND: Keith Emerick 01904 601988 OWNER TYPE: Private CONTACT

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Hutton Hall (site of), Hutton Conyers		
DESIGNATION:	Scheduled Monument (No. 1004074)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow I50m east of Burtree Hill, H	utton Conyers	
DESIGNATION:	Scheduled Monument (No. 1013396)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m WNW of Low Barn, H	lutton Conyers	
DESIGNATION:	Scheduled Monument (No. 1013395)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow at Moor House, Hutton Cor	nyers	
DESIGNATION:	Scheduled Monument (No. 1009784)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow in Harland's Plantation, Hutt	on Conyers	
DESIGNATION:	Scheduled Monument (No. 1009785)	CONDITION:	Generally unsatisfactory
DESIGNATION:		CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	Motte and bailey castle, known as Mowbray	Castle, east of K	irkby Malzeard, Kirkby Malzeard
SITE NAME:			Canavally satisfactory
	Scheduled Monument (No. 1012994)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION:		CONDITION: TREND:	· · · · · · · · · · · · · · · · · · ·
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1012994)  Scrub / tree growth  Private		but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scrub / tree growth	TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scrub / tree growth Private	TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)	TREND: CONTACT: associated fishpo	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and	TREND: CONTACT:  associated fishpo CONDITION:	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately early Scheduled Monument (No. 1018691)	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT: ast of Park House	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  a, Markington with Wallerthwaite Generally unsatisfactory with major localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately ea	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT: ast of Park House	but with significant localised problems Declining Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Indicate the problems Reith Emerick 01904 for the problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately early Scheduled Monument (No. 1018691)	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:  ast of Park House CONDITION:	but with significant localised problems Declining Keith Emerick 01904 601988  nds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  a, Markington with Wallerthwaite Generally unsatisfactory with major localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately ex Scheduled Monument (No. 1018691)  Extensive vehicle damage/erosion	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:  ast of Park House CONDITION: TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Indicate the problems Amarkington with Wallerthwaite Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately early scheduled Monument (No. 1018691)  Extensive vehicle damage/erosion Private	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:  ast of Park House CONDITION: TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Indicate the problems Amarkington with Wallerthwaite Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scrub / tree growth Private  Rougemont Castle ringwork and bailey and Scheduled Monument (No. 1010026)  Moderate animal burrowing Private  Medieval monastic fishponds immediately ear Scheduled Monument (No. 1018691)  Extensive vehicle damage/erosion Private  Henge monument 300m north west of Can	TREND: CONTACT:  associated fishpo CONDITION: TREND: CONTACT:  ast of Park House CONDITION: TREND: CONTACT:	but with significant localised problems Declining Keith Emerick 01904 601988  Inds and outwork, Kirkby Overblow Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  In Markington with Wallerthwaite  In Generally unsatisfactory With major localised problems  In Generally unsatisfactory With Markington with Wallerthwaite  In Generally unsatisfactory With Markington with Wallerthwaite

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Moated site 50m north west of Red House	, Moor Monkton	
DESIGNATION:	Scheduled Monument (No. 1020887)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Green Howe bowl barrow, 280m south of I	Bank House, Nort	h Deighton
DESIGNATION:	Scheduled Monument (No. 1015583)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site 50m north east of North Rigto	on School, North	Rigton
	Moated site 50m north east of North Rigto Scheduled Monument (No. 1017716)	on School, North	Rigton  Generally satisfactory
	<u> </u>		Generally satisfactory
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	<u> </u>		Generally satisfactory
DESIGNATION:	Scheduled Monument (No. 1017716)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1017716)  Moderate stock erosion	CONDITION:  TREND:  CONTACT:  f plantation on We	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1017716)  Moderate stock erosion Private  Cairn 7m in diameter north of track east o	CONDITION:  TREND:  CONTACT:  f plantation on We	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1017716)  Moderate stock erosion Private  Cairn 7m in diameter north of track east o 450m WNW of Weston Moor Cottage, We	CONDITION:  TREND:  CONTACT:  f plantation on Weston	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  eston Moor  Generally unsatisfactory



Allerton Mauleverer with Hopperton DESIGNATION: Registered Park and Garden Grade II, also 19 LBs Generally unsatisfactory CONDITION: with major localised problems vulnerability: Medium Declining Private, multiple owners OWNER TYPE:

Allerton Park,

SITE NAME:

Mid C19 terraced gardens which provide the setting for a country house, surrounded by parkland which was enlarged in the 1720s and reworked in the 1770s. C20 woodland planting has significantly changed the character of the historic landscape and a number of listed structures are in poor condition.



Swinton Castle. SITE NAME: Swinton with Warthermarske DESIGNATION: Registered Park and Garden Grade II\*, also 7 LBs CONDITION: Generally satisfactory but with significant localised problems VULNERABILITY: Medium Declining TREND:

OWNER TYPE: Private, single owner

Gardens and extensive pleasure grounds with grottos, rustic bridges and rockwork laid out from 1796 to c1820 under the direction of Adam Mickle the second and others for Sir William Danby, incorporating lakes and landscaping of c1760. The park probably has C17 or earlier origins. Significant proportion of the tree cover has reached maturity and beyond, some structures in poor condition and water bodies in Quarry Gill woods heavily silted.

Contact: Andy Wimble 01904 601970

Contact: Andy Wimble 01904 601970



Battle of Boroughbridge, SITE NAME: Boroughbridge / Langthorpe / Milby DESIGNATION: Registered Battlefield Generally satisfactory CONDITION: but with significant localised problems VULNERABILITY: Medium Declining TRENID:

Thomas Earl of Lancaster's 1322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north of the river.

Contact: Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNERTYPE: Private

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

#### NORTH YORK MOORS (NP)



SITE NAME: Ruins of Whorlton Castle Undercroft, Castle Bank, Whorlton,

Hambleton

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION: N/A D (D) PRIORITY-OWNERTYPE: Private C14 castle. Parts of two vaulted chambers remain. Conservation plan complete. Options appraisal in progress.

Contact: Keith Emerick 01904 601988



Whorlton Castle Gatehouse, SITE NAME: Castle Bank, Whorlton,

Hambleton

Listed Building Grade I, SM, CA DESIGNATION:

Fair CONDITION: N/A OCCUPANCY: D (D) PRIORITY: OWNERTYPE: Private Shell remains of a late C14 gatehouse, which was altered in the C16. Conservation plan complete. Possible conversion to holiday accommodation being considered.

Contact: Giles Proctor 01904 601981



Ionic Temple, SITE NAME: Duncombe Park Estate, Helmsley, Ryedale

DESIGNATION: Listed Building Grade I, RPG I

Poor CONDITION: N/A D(D)PRIORITY: Private OWNER TYPE:

Decorative temple, circa 1730, attributed to Vanbrugh, situated at the north end of the approximately 800m long, grass East Terrace, approximately 120m east of the house. The column shafts are badly decayed. The trial repair of one column is complete. The possibility of full repair is under discussion.

Contact: Giles Proctor 01904 601981



Tuscan Temple, SITE NAME: Duncombe Park Estate, Helmsley, Ryedale

DESIGNATION: Listed Building Grade I, RPG I Poor CONDITION: OCCUPANCY: N/A

D (C) PRIORITY-OWNER TYPE: Private Decorative temple circa 1730 in the Palladian style situated at the south end of the East Terrace. The column shafts are badly decayed and internal plasterwork falling.

Contact: Giles Proctor 01904 601981



Ayton Castle, SITE NAME:

Castle Rise, West Ayton, Scarborough

DESIGNATION: Listed Building Grade I, SM

Poor CONDITION: OCCUPANCY: N/A C (F)

OWNER TYPE: Local authority

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. The site has been the subject of a detailed condition survey. Conservation plan completed but no further progress.

Contact: Keith Emerick 01904 601988

SITE	NIAME:	

#### Group of round barrows on Bilsdale Moor

1/2 mile (800m) north west of Fangdale Beck, Bilsdale Midcable, Hambleton

Scheduled Monument (No. 1004148) Generally unsatisfactory DESIGNATION CONDITION: with major localised problems PRINCIPAL VULNERABILITY: Other Declining TREND: Private Keith Emerick 01904 601988 OWNER TYPE CONTACT

#### SITE NAME:

#### Urra Moor prehistoric linear boundary on the western edge of Urra Moor, Bilsdale Midcable, Hambleton

DESIGNATION:	Scheduled Monument (No. 1015955)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

#### NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

#### ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Pit alignment forming part of the Cleave D 1000m north west of Dialstone Farm, Boltb	, ,	
DESIGNATION:	Scheduled Monument (No. 1010345)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Pit alignment, part of the Cleave Dyke preband round barrow 450m south east of Hig		
DESIGNATION:	Scheduled Monument (No. 1015576)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Ravensthorpe manor house (site of), Boltby	, Hambleton	
DESIGNATION:	Scheduled Monument (No. 1004083)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 400m south east of Hill For	t Windypit, Boltby	, Hambleton
DESIGNATION:	Scheduled Monument (No. 1010341)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m south east of Hill For	t Windypit, Boltby	; Hambleton
DESIGNATION:	Scheduled Monument (No. 1010342)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 600m north east of South V	Voods, Boltby, Har	nbleton
DESIGNATION:	Scheduled Monument (No. 1013085)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 650m east of South Woods,	Boltby, Hambleto	n
DESIGNATION:	Scheduled Monument (No. 1010343)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining .
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of Cleave Dyke, I.4km long from Si including two pit alignments and round bar		
DESIGNATION:	Scheduled Monument (No. 1012746)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of the Cleave Dyke system known	as Hesketh Dike a	and Silver Hill round barrow, Boltby, Hamble
DESIGNATION:	Scheduled Monument (No. 1015575)	CONDITION:	Generally satisfactory but with significant localised problems
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS IATIONS
Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

but with significant localised problem private	SITE NAME:	Section of the Cleave Dyke system on Ardon including the Steeple Cross boundary stone			
Plant growth Private Consider New Consider N	DESIGNATION:	Scheduled Monument (No. 1010533)	CONDITION:	·	
Two round barrows at Seta Pike, Bolitby, Hambleton  Scheduled Monument (No. 1008580) CORDINAN  Reproductive Marketine  Plant growth Trend  Scheduled Monument (No. 1008856) CORDINAN  Reproductive Marketine  Private CORDINAN  Reproductive Marketine  Private CORDINAN  Reproductive Marketine  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  Scheduled Monument (No. 1012731) CORDINAN  Scheduled Monument (No. 1014564) CORDINAN  Scheduled				but with significant localised problems	
Two round barrows at Seta Pike, Boltby, Hambleton  Scheduled Monument (No. 1006580)  CONDITION  Scheduled Monument (No. 1006580)  CONDITION  Declining  Private  Round barrow 350m west of Green Bank, Carlton, Hambleton  Scheduled Monument (No. 1008856)  CONDITION  Scheduled Monument (No. 1008856)  CONDITION  Scheduled Monument (No. 1008856)  CONDITION  Plant growth  Private  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  Scheduled Monument (No. 1012731)  CONDITION  WARRENTHE  Private  Round barrow 200m south of Green Bank, Great Busby, Hambleton  CONDITION  Scheduled Monument (No. 1012731)  CONDITION  Scheduled Monument (No. 1018854)  CONDITION  Scheduled Monument (No. 1008854)  CONDITION  Scheduled Monument (No. 1014564)  CONDITION  Scheduled Monument (No. 1020347)  CONDITION  Scheduled Monument (No. 1020868)  CONDITION  Scheduled Monument (No. 1020868)  CONDITION  Scheduled Monument (No. 1020868)  CONDITION  Scheduled Monument (	PRINCIPAL VULNERABILITY:	-	TREND:	~	
Scheduled Monument (No. 1008580) continues. Generally satisfactory but with significant localised problem (No. 1008580) contract. Keth Emerick 01904 601988  Round barrow 350m west of Green Bank, Carlton, Hambleton Scheduled Monument (No. 1008856) contract. Keth Emerick 01904 601988  Round barrow 350m west of Green Bank, Carlton, Hambleton Generally satisfactory but with significant localised problem but with significant localised problem (No. 1008656) contract. Keth Emerick 01904 601988  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton Contract. Keth Emerick 01904 601988  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton Generally satisfactory but with significant localised problem (No. 1012731) contract. Keth Emerick 01904 601988  Round barrow 300m south of Green Bank, Great Busby, Hambleton Generally satisfactory but with significant localised problem (No. 1012731) contract. Keith Emerick 01904 601988  RETERMANE  Round barrow 200m south of Green Bank, Great Busby, Hambleton Generally satisfactory but with significant localised problem (No. 1012731) contract. Keith Emerick 01904 601988  RETERMANE  Round barrow 400m south of Green Bank, Great Busby, Hambleton Generally satisfactory but with significant localised problem (No. 1012731) contract. Keith Emerick 01904 601988  RETERMANE  Round barrow 400m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton Generally satisfactory with major localised problems (No. 1014564) contained. Extensive significant problems (No. 1020347) contract. Keith Emerick 01904 601988  RETERMANE  ROUND Banks alum works, Little Ayton, Hambleton Generally unsatisfactory with major localised problems (No. 1020347) contract. Keith Emerick 01904 601988  RETERMANE  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton Generally satisfactory but with significant localised problems (No. 1008868) contained. Generally satisfactory but with significant localised problems (No. 1008864) contained. Generally satisfactory but with	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
Dut with significant localised problem merchanisms (Plant growth Trends Contact)	ITE NAME:	Two round barrows at Seta Pike, Boltby, Ha	ımbleton		
Plant growth TREND Declining  Private CONTACT Keith Emerick 01904 601988  Round barrow 350m west of Green Bank, Carlton, Hambleton  Scheduled Monument (No. 1008856) CONDITION Generally satisfactory but with significant localised problem  RECEIVANCE ROUNDERSEUT:  Plant growth TREND Declining  Private Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  SESCRIMONE Scheduled Monument (No. 1012731) CONDITION Generally satisfactory but with significant localised problem  RECEIVANCE ROUNDERSEUT:  Vandalism TREND Declining  Private CONNACT Keith Emerick 01904 601988  RETEINANCE ROUNDERSEUT:  ROUND Barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854) CONDITION Generally satisfactory but with significant localised problem  RECEIVANCE ROUNDERSEUT:  Private ROUNDERSEUT:  RESCRIMONE Scheduled Monument (No. 1008854) CONDITION Generally satisfactory but with significant localised problem  RECEIVANCE ROUNDERSEUT:  Private CONTROL RECEIVANCE RETEIVANCE ROUNDERSEUT:  RECEIVANCE ROUNDERSEUT:  Private CONTROL RETEIVANCE RECEIVANCE RETEIVANCE  ROUND Barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Scheduled Monument (No. 1014564) CONDITION Extensive significant problems  RECEIVANCE ROUNDERSEUT:  Arable ploughing TREND Declining  Private CONTROL RETEIVANCE RETEIVANCE  ROUNDERSEUT:  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347) CONDITION Generally unsatisfactory with major localised problems  RECEIVANCE ROUNDERSEUT:  Plant growth TREND Declining  RECEIVANCE ROUNDERSEUT:  Private CONTROL Rett Emerick 01904 601988  RECEIVANCE ROUNDERSEUT:  Private ROUNDERSEUT:	DESIGNATION:	Scheduled Monument (No. 1008580)	CONDITION:	Generally satisfactory	
Round barrow 350m west of Green Bank, Carlton, Hambleton  Scheduled Monument (No. 1008856)  CONDITION  SECONDATION:  Plant growth  Private  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  SESCONDITION:  Scheduled Monument (No. 1012731)  CONDITION  SESCONDITION:  Scheduled Monument (No. 1012731)  CONDITION  SESCONDITION:  SCHEDUL VULNERABILITY:  Vandalism  Private  Round barrow 200m south east of Faceby Plantation, Faceby, Hambleton  SESCONDITION:  SCHEDUL VULNERABILITY:  Vandalism  Private  Round barrow 200m south of Green Bank, Great Busby, Hambleton  SESCONDITION:  Scheduled Monument (No. 1008854)  SESCONDITION:  SCHEDUL VULNERABILITY:  Plant growth  TREND:  Declining  SCHEDUL VULNERABILITY:  Plant growth  TREND:  Private  ROUND BARROWSH  Private  ROUND BARROWSH				but with significant localised problems	
Round barrow 350m west of Green Bank, Carlton, Hambleton  Scheduled Monument (No. 1008856)  SCHONLINGER BUILDY  Plant growth  RECONTACT  ROUND Declining  RECONTACT  Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  SCHEDULAUMBRABUTY:  Plant growth  ROUND Barrow 300m south east of Faceby Plantation, Faceby, Hambleton  SCHEDULAUMBRABUTY:  Vandalism  TREND  Declining  SCHEDULAUMBRABUTY:  Vandalism  TREND  Declining  ROUND Declining  ROUND Declining  ROUND Declining  ROUND DECLINING  SCHEDULAUMBRABUTY:  Private  ROUND Barrow 200m south of Green Bank, Great Busby, Hambleton  SCHEDULAUMBRABUTY:  Plant growth  TREND  Declining  ROUND DECLINING  SCHEDULAUMBRABUTY:  Plant growth  TREND  Declining  ROUND DECLINING  RO	PRINCIPAL VULNERABILITY:	-	TREND:		
Scheduled Monument (No. 1008856)  Scheduled Monument (No. 1008856)  Scheduled Monument (No. 1008856)  Scheduled Monument (No. 1012731)  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1012731)  Scheduled Monument (No. 1012731)  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1012731)  Scheduled Monument (No. 1014564)  Scheduled Monument (No. 1020347)  Schedu	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
BANCIPAL VULNERABILITY: Plant growth private contact: Keith Emerick 01904 601988  RESIGNATION: Plant growth private contact: Keith Emerick 01904 601988  RESIGNATION: Scheduled Monument (No. 1012731) contamon. Generally satisfactory but with significant localised problems where the private contact: Keith Emerick 01904 601988  RESIGNATION: Scheduled Monument (No. 1012731) contamon. Generally satisfactory but with significant localised problems where the private contact: Keith Emerick 01904 601988  RESIGNATION: Scheduled Monument (No. 1008854) contation. Generally satisfactory but with significant localised problems where the private contact: Keith Emerick 01904 601988  RESIGNATION: Scheduled Monument (No. 1008854) contact: Keith Emerick 01904 601988  RENAME: Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton seasonation. Scheduled Monument (No. 1014564) contact: Keith Emerick 01904 601988  RENAME: Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton seasonation. Scheduled Monument (No. 1014564) contact: Keith Emerick 01904 601988  RENAME: Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347) contact: Keith Emerick 01904 601988  RESIGNATION: Scheduled Monument (No. 1020347) contact: Keith Emerick 01904 601988  RENAME: Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347) contact: Keith Emerick 01904 601988  RENAME: Rename: Rename of Private contact: Keith Emerick 01904 601988  RENAME: Rename: Rename of Private contact: Keith Emerick 01904 601988  RENAME: Rename: Rename of Private contact: Keith Emerick 01904 601988	ITE NAME:	Round barrow 350m west of Green Bank,	Carlton, Hambleto	on	
Plant growth TREND: Declining  ROWNERTYPE Private CONTACT: Keith Emerick 01904 601988  ROWNERTYPE Private CONTACT: Keith Emerick 01904 601988  ROWNERTYPE ROUND BARROW 300m south east of Faceby Plantation, Faceby, Hambleton  RESIGNATION: Scheduled Monument (No. 1012731) CONDITION: Generally satisfactory but with significant localised problem  RINCIPAL VALNERABILITY: Vandalism TREND: Declining  RINCIPAL VALNERABILITY: Vandalism TREND: Declining  RINCIPAL VALNERABILITY: Reith Emerick 01904 601988  ROUND BARROW 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854) CONDITION: Generally satisfactory but with significant localised problem  RINCIPAL VALNERABILITY: Plant growth TREND: Declining  RINCIPAL VALNERABILITY: Reith Emerick 01904 601988  RETE NAME: ROUND BARROW 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  DESIGNATION: Scheduled Monument (No. 1014564) CONDITION: Extensive significant problems  RINCIPAL VALNERABILITY: Arable ploughing TREND: Declining  DECINING  DEVINATION: Scheduled Monument (No. 1020347) CONDITION: Keith Emerick 01904 601988  RINCIPAL VALNERABILITY: Private  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347) CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1020347) CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1020347) CONDITION: Keith Emerick 01904 601988  RINCIPAL VALNERABILITY: Plant growth TREND: Declining  Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems	DESIGNATION:	Scheduled Monument (No. 1008856)	CONDITION:	Generally satisfactory	
Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  Scheduled Monument (No. 1012731)  CONDITION:  Generally satisfactory but with significant localised problem  RINCIPAL VALABRABILITY:  Vandalism  THEND:  Declining  Private  Round barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854)  CONTACT:  Keith Emerick 01904 601988  RECONTACT:  RECONTACT:  Reconstruct:  Recons				but with significant localised problems	
Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton  Scheduled Monument (No. 1012731)  CONDITION:  Generally satisfactory but with significant localised problem  PRINCIPAL VULNEMABELTY:  Vandalism  Private  CONTACT:  Keith Emerick 01904 601988  RETENANCE  ROUND BARROW 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854)  CONDITION:  Generally satisfactory but with significant localised problem:  Plant growth  TREND:  Declining  Devining  Private  CONTACT:  Keith Emerick 01904 601988  RETENANCE:  ROUND BARROW 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Scheduled Monument (No. 1014564)  CONDITION:  Extensive significant problems  Private  CONTACT:  Keith Emerick 01904 601988  RETENANCE:  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  CONDITION:  Generally unsatisfactory with major localised problems  Private  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  CONDITION:  Generally unsatisfactory with major localised problems  Private  ROUND BARROW VULNERABLTY:  Plant growth  TREND:  Declining  Generally unsatisfactory with major localised problems  CONTACT:  Keith Emerick 01904 601988  RETENANCE:  ROUND BARROW VULNERABLTY:  Plant growth  TREND:  Declining  Generally satisfactory but with significant localised problems  CONTACT:  Keith Emerick 01904 601988  ROUND BARROW VULNERABLTY:  Plant growth  TREND:  Declining  Generally satisfactory but with significant localised problems  Declining  CONTACT:  Keith Emerick 01904 601988	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
Scheduled Monument (No. 1012731)  CONDITION: Generally satisfactory but with significant localised problems where the private contract: Keith Emerick 01904 601988  WE NAME: Round barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854)  CONDITION: Generally satisfactory but with significant localised problems but with significant localised problems with significant localised problems.  Plant growth TREND: Declining  DOWNERTYPE: Private CONTRACT: Keith Emerick 01904 601988  WE NAME: Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Scheduled Monument (No. 1014564)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNERTYPE: Private CONTRACT: Keith Emerick 01904 601988  WE NAME: Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  DOWNERTYPE: Private  ROUND BARY OF PRIVATE  ROUND BARY OF PRIVATE  ROUND BARY OF PRIVATE  ROUND BARY OF PRIVATE  Plant growth TREND: Declining  DOWNERTYPE  Private  ROUND BARY OF PRI	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
But with significant localised problems  TREND: Declining  Deventyre: Private Contact: Keith Emerick 01904 601988  TRENAME: Round barrow 200m south of Green Bank, Great Busby, Hambleton  Sesignation: Scheduled Monument (No. 1008854) Condition: Generally satisfactory but with significant localised problems  RINGIPLE VALUERABILITY: Plant growth TREND: Declining  Devining  Devining  Devining  Devining  Devining  TREND: Reith Emerick 01904 601988  TREND: Declining  Devining  TREND: Declining  Devining  TREND: Declining  Devining  Devi	ITE NAME:	Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton			
RINCIPAL VULNERABILITY: Vandalism TREND: Declining  WINDERTYPE: Private CONTACT: Keith Emerick 01904 601988  ROUND barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854) CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth TREND: Declining  WINDERTYPE: Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  SESGNATION: Scheduled Monument (No. 1014564) CONDITION: Extensive significant problems  RINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  WINDERTYPE: Private CONTACT: Keith Emerick 01904 601988  WITE NAME: Ayton Banks alum works, Little Ayton, Hambleton  SESGNATION: Scheduled Monument (No. 1020347) CONDITION: Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: Plant growth TREND: Declining  WINDERTYPE: Private CONTACT: Keith Emerick 01904 601988  WITE NAME: Ayton Banks alum works, Little Ayton, Hambleton  SCHEDULE AYTON BANKS ALUM WORKS AND CONDITION: Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: Plant growth TREND: Declining  SCHEDULE AVENCE ROUND BANKS AND CONDITION: Generally satisfactory but with significant localised problems  PRIVATE: ROUND BANKS AND CONDITION: Generally satisfactory but with significant localised problems  PRIVATE: ROUND BANKS AND CONDITION: Generally satisfactory but with significant localised problems  PRIVATE ROUND BANKS AND CONDITION: Generally satisfactory but with significant localised problems	DESIGNATION:	Scheduled Monument (No. 1012731)	CONDITION:	Generally satisfactory	
Round barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1018564)  Scheduled Monument (No. 1014564)  Scheduled Monument (No. 1020347)  Scheduled M				but with significant localised problems	
Round barrow 200m south of Green Bank, Great Busby, Hambleton  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1008854)  Scheduled Monument (No. 1008854)  Firence  Ringrantione  Ringrantione  Ringrantione  Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Scheduled Monument (No. 1014564)  Scheduled Monument (No. 1014564)  Scheduled Monument (No. 1014564)  Scheduled Monument (No. 1014564)  Firence  Ringrantione  Arable ploughing  Trence  Contact:  Keith Emerick 01904 601988  Firence  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  Scheduled Monument (No. 1020347)  Scheduled Monument (No. 1020347)  Scheduled Monument (No. 1020347)  Firence  Ringrantione  Ringrantione  Ringrantione  Ringrantione  Ringrantione  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868)  Conditione  Generally satisfactory  with major localised problems  Contact:  Keith Emerick 01904 601988  Firence  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868)  Conditione  Generally satisfactory  but with significant localised problems  Declining	RINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining	
Scheduled Monument (No. 1008854)  CONDITION: Generally satisfactory but with significant localised problems. Plant growth  TREND: Declining  Private  Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Sesignation: Scheduled Monument (No. 1014564)  CONDITION: Extensive significant problems. Private  Rincipal vulnerability: Arable ploughing  TREND: Declining  Declining  TREND: Declining  TREND: Declining  TREND: Declining  TREND: Generally unsatisfactory with major localised problems. Private  Ayton Banks alum works, Little Ayton, Hambleton  Sesignation: Scheduled Monument (No. 1020347)  CONDITION: Generally unsatisfactory with major localised problems. Private  Rincipal vulnerability: Plant growth  TREND: Declining  CONTACT: Keith Emerick 01904 601988  TREND: Declining  Swith major localised problems. Private  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Sesignation: Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory but with significant localised problems. Private  Round Barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Sesignation: Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory but with significant localised problems. Plant growth  TREND: Declining	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
But with significant localised problems  Plant growth TREND: Declining	SITE NAME:	Round barrow 200m south of Green Bank,	Great Busby, Han	nbleton	
But with significant localised problems  Plant growth TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1008854)	CONDITION:	Generally satisfactory	
Plant growth TREND: Declining DevinerType Private CONTACT: Keith Emerick 01904 601988  Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Designation: Scheduled Monument (No. 1014564) CONDITION: Extensive significant problems  RINCIPAL WUNDERABILITY: Arable ploughing TREND: Declining		,			
Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton  Scheduled Monument (No. 1014564)  CONTACT: Keith Emerick 01904 601988  RINCIPAL VILINERABILITY: Arable ploughing  TREND: Declining  Declining  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  CONDITION: Generally unsatisfactory  with major localised problems  RINCIPAL VILINERABILITY: Plant growth  TREND: Declining  Declining  RINCIPAL VILINERABILITY: Reith Emerick 01904 601988  RINCIPAL VILINERABILITY: Plant growth  TREND: Declining  ROWNER TYPE: Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  DESIGNATION: Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory  but with significant localised problems.  Plant growth  TREND: Declining	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	-	
Scheduled Monument (No. 1014564)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  CONDITION: Generally unsatisfactory  with major localised problems  Plant growth  TREND: Declining  Declining  Deviner Type: Private  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory  but with significant localised problems  CONDITION: Generally satisfactory  but with significant localised problems  Plant growth  TREND: Declining	OWNER TYPE:	-	CONTACT:		
Arable ploughing TREND: Declining DWNERTYPE: Private CONTACT: Keith Emerick 01904 601988  Ayton Banks alum works, Little Ayton, Hambleton  DESIGNATION: Scheduled Monument (No. 1020347) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  DWNERTYPE: Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Plant growth TREND: Declining  DECLINING  DESIGNATION: Generally satisfactory but with significant localised problems  DESIGNATION: Plant growth TREND: Declining	SITE NAME:	Round barrow 480m east of Yorkshire Glid	ing Club, Kilburn	High and Low, Hambleton	
Arable ploughing TREND: Declining DWNERTYPE: Private CONTACT: Keith Emerick 01904 601988  Ayton Banks alum works, Little Ayton, Hambleton  DESIGNATION: Scheduled Monument (No. 1020347) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  DWNERTYPE: Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Plant growth TREND: Declining  DECLINING  DESIGNATION: Generally satisfactory but with significant localised problems  DESIGNATION: Plant growth TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1014564)	CONDITION:	Extensive significant problems	
Ayton Banks alum works, Little Ayton, Hambleton  Scheduled Monument (No. 1020347)  Plant growth  Private  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868)  Round Banks alum works, Little Ayton, Hambleton  CONDITION: Generally unsatisfactory with major localised problems  Plant growth  TREND: Declining  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory but with significant localised problems  Plant growth  TREND: Declining	PRINCIPAL VULNERABILITY:				
Scheduled Monument (No. 1020347)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  CONTACT: Keith Emerick 01904 601988  ROUND Barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  DESIGNATION: Scheduled Monument (No. 1008868)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining	DWNER TYPE:	·	CONTACT:	9	
with major localised problems  Plant growth  Private  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Designation:  Scheduled Monument (No. 1008868)  CONDITION:  Generally satisfactory but with significant localised problems  Private  Trend:  Declining  Trend:  Declining  Trend:  Declining	SITE NAME:	Ayton Banks alum works, Little Ayton, Hambleton			
with major localised problems  Plant growth  Private  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Designation:  Scheduled Monument (No. 1008868)  CONDITION:  Generally satisfactory but with significant localised problems  Private  Trend:  Declining  Trend:  Declining  Trend:  Declining	DESIGNATION:	Scheduled Monument (No. 1020347)	CONDITION:	Generally unsatisfactory	
Plant growth TREND: Declining  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton Declining Declining Declining Declining Declining Declining		, , , , , , , , , , , , , , , , , , , ,			
Private CONTACT: Keith Emerick 01904 601988  Round barrow 200m north east of Priests' Spar Quarry, Osmotherley, Hambleton  Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	,	
DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems: Plant growth TREND: Declining	OWNER TYPE:	-			
DESIGNATION: Scheduled Monument (No. 1008868) CONDITION: Generally satisfactory but with significant localised problems: Plant growth TREND: Declining	SITE NAME:	Round barrow 200m north east of Priests'	Spar Quarry, Osn	notherley, Hambleton	
but with significant localised problems but with significant localised problems.  Plant growth Trend: Declining	DECICALATION I			·	
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining	DESIGNATION:	Screduled Monument (140, 1000000)	CONDITION:		
	DDINICIDAL VILLA IED A DU TO (	Plant growth	TRENIE		
DWNERTIFE: CONTACT: REITH EMERICK UT 704 601788		-		<u> </u>	
	OVVINER LYPE:	rivate	CONTACT:	KEILII EITIELICK UT704 601788	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow 450m north west of Garbutt Farm, Sutton-under-Whitestonecliffe, Hambleton				
DESIGNATION:	Scheduled Monument (No. 1010344)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 600m north west of Garbut	t Farm, Sutton-un	der-Whitestonecliffe, Hambleton		
DESIGNATION:	Scheduled Monument (No. 1018550)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 200m north west of Scarth	Nick,Whorlton, H	Hambleton		
DESIGNATION:	Scheduled Monument (No. 1008862)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 500m west of Red Way Head, Whorlton, Hambleton				
DESIGNATION:	Scheduled Monument (No. 1012728)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow at northern edge of Snotter	dale Plantation,W	horlton, Hambleton		
DESIGNATION:	Scheduled Monument (No. 1012736)	CONDITION:	Generally satisfactory		
	,		but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Two round barrows 275m south of Scarth Wood, Whorlton, Hambleton				
DESIGNATION:	Scheduled Monument (No. 1011917)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Oxmoor and Givendale Dikes: prehistoric l	inear boundaries	and associated features, Allerston, Ryeda		
DESIGNATION:	Scheduled Monument (No. 1020834)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Two round barrows on Low Common, App	leton-le-Moors, R	yedale		
DESIGNATION:	Scheduled Monument (No. 1003660)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow on Beadlam Rigg, 490m west of Stone Ruckles round barrow, Beadlam, Ryedale				
DESIGNATION:	Scheduled Monument (No. 1019516)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Cockan Cross wayside cross 600m west of	Fox Hole Crag, B	ransdale, Ryedale		
DESIGNATION:	Scheduled Monument (No. 1011747)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow at Crook Staff Hill, Bransdal	e, Ryedale			
DESIGNATION:	Scheduled Monument (No. 1009360)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 410m south of Keldy Banks, Cropton, Ryedale				
DESIGNATION:	Scheduled Monument (No. 1017832)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow at Blanket Head, 350m nort	h west of Broad H	Head Farm, Ebberston and Yedingham, Rye		
	Round barrow at Blanket Head, 350m nort Scheduled Monument (No. 1020698)	h west of Broad F	Head Farm, Ebberston and Yedingham, Rye Generally unsatisfactory with major localised problems		
designation:			Generally unsatisfactory with major localised problems Declining		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020698)	CONDITION:	Generally unsatisfactory with major localised problems		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth	CONDITION:  TREND:  CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1020698)  Plant growth  Government or Agency	CONDITION:  TREND:  CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco Generally satisfactory but with significant localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping	CONDITION:  TREND:  CONTACT:  ries and associated  CONDITION:  TREND:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco Generally satisfactory but with significant localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco Generally satisfactory but with significant localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryed Generally satisfactory but with significant localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco Generally satisfactory but with significant localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, 1	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:  TREND: CONTACT:  Ryedale	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryed Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, Scheduled Monument (No. 1018983)	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:  TREND: CONTACT:  Ryedale  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeco Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, Scheduled Monument (No. 1018983)  Extensive visitor erosion	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  Ryedale  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryed Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, Scheduled Monument (No. 1018983)  Extensive visitor erosion Private	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  Ryedale  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryed Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, 1 Scheduled Monument (No. 1018983)  Extensive visitor erosion Private  Pike Howe round cairn, Farndale East, Ryed	CONDITION:  TREND: CONTACT:  ries and associated  CONDITION:  TREND: CONTACT:  Ryedale  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeo Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory with major localised problems Declining Keith Emerick 01904 601988		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  OWNER TYPE:  OWNER TYPE:	Scheduled Monument (No. 1020698)  Plant growth Government or Agency  Scamridge Dikes: prehistoric linear boundar Scheduled Monument (No. 1020835)  Arable clipping Private  Blakey Howe round barrow, Farndale East, I Scheduled Monument (No. 1018983)  Extensive visitor erosion Private  Pike Howe round cairn, Farndale East, Ryed Scheduled Monument (No. 1018986)	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  CONTACT:  Ryedale  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  d features, Ebberston and Yedingham, Ryeo Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ITE NAME:	Unenclosed hut circle settlement, field syst north west of Harland Beck House, Farnda		rn cemetery on Harland Moor		
DESIGNATION:	Scheduled Monument (No. 1019600)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Shunner Howe round barrow, Hartoft, Rye	dale			
DESIGNATION:	Scheduled Monument (No. 1018763)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Cairnfield 200m east of Hazelshaw House,	Hawnby, Ryedale			
DESIGNATION:	Scheduled Monument (No. 1008860)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Cairnfield 500m north east of Bumper Castle, Hawnby, Ryedale				
DESIGNATION:	Scheduled Monument (No. 1009358)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow I50m north east of Silver H	ill Farm, Hawnby, I	Ryedale		
DESIGNATION:	Scheduled Monument (No. 1016052)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 500m east of Silver Hill Farr	n, Hawnby, Ryedal	e		
DESIGNATION:	Scheduled Monument (No. 1016066)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 500m north west of Lower	Locker Farm, Hav	vnby, Ryedale		
DESIGNATION:	Scheduled Monument (No. 1009371)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
THE VOLUME TO A VEH	Private	CONTACT:	Keith Emerick 01904 601988		
OWNER TYPE:		Round barrow 550m south east of High Cote Farm, Hawnby, Ryedale			
	Round barrow 550m south east of High Co	ote Farm, Hawnby	, Ryedale		
OWNER TYPE:	Round barrow 550m south east of High Co Scheduled Monument (No. 1013223)	ote Farm, Hawnby.	Generally satisfactory		
OWNER TYPE: SITE NAME:	-	,	·		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Two round barrows at Sour Milk Hills, Haw	nby, Ryedale	
DESIGNATION:	Scheduled Monument (No. 1008442)	CONDITION:	Generally satisfactory but with minor localised problems
RINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Douthwaite pillow mounds, Hutton-le-Hole	, Ryedale	
DESIGNATION:	Scheduled Monument (No. 1016024)	CONDITION:	Generally unsatisfactory
	Plant grounth	TOTALD	with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Declining Keith Emerick 01904 601988
OWNER TYPE:	rrivate	CONTACT:	Reitil Efficience 01704 601700
SITE NAME:	Four round barrows one 400m and three 5	40m east of Grou	se Hall, Hutton-le-Hole, Ryedale
DESIGNATION:	Scheduled Monument (No. 1016023)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
ITE NAME:	Two round barrows, 245m and 340m north	west of Barmoor	· Lodge, Hutton-le-Hole, Ryedale
DESIGNATION:	Scheduled Monument (No. 1016022)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three medieval pillow mounds 900m north	of Grove House,	Levisham, Ryedale
DESIGNATION:	Scheduled Monument (No. 1020685)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cross dyke centred 480m south of Fox and	Rabbit Farm, Loc	kton, Ryedale
SITE NAME: DESIGNATION:	Cross dyke centred 480m south of Fox and Scheduled Monument (No. 1021170)		Generally satisfactory
designation:	•		Generally satisfactory
	Scheduled Monument (No. 1021170)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021170)  Arable clipping	CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1021170)  Arable clipping  Private	CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)	CONDITION:  TREND: CONTACT:  Moor, Ikm NNE CONDITION:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High	CONDITION:  TREND:  CONTACT:  Moor, Ikm NNE	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority	CONDITION:  TREND: CONTACT:  Moor, Ikm NNE CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Local	CONDITION:  TREND: CONTACT:  Moor, Ikm NNE CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Le Scheduled Monument (No. 1020117)	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONTACT:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Local Scheduled Monument (No. 1020117)  Extensive visitor erosion	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONTACT:  CONTACT:  TREND: TREND: TREND: TREND: TREND: TREND: TREND:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DITE NAME:  DESIGNATION:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Le Scheduled Monument (No. 1020117)	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONTACT:  CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Local Scheduled Monument (No. 1020117)  Extensive visitor erosion	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Le Scheduled Monument (No. 1020117)  Extensive visitor erosion Local Authority	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scheduled Monument (No. 1021170)  Arable clipping Private  Field system and cairnfield on Lockton High Scheduled Monument (No. 1021234)  Plant growth Local Authority  Prehistoric dyke known as Horcum Dike, Le Scheduled Monument (No. 1020117)  Extensive visitor erosion Local Authority  Round barrow 400m north east of Low Pase	CONDITION:  TREND: CONTACT:  Moor, I km NNE CONDITION:  TREND: CONTACT:  CONTACT:  TREND: CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  of Needle Point, Lockton, Ryedale Generally satisfactory but with significant localised problems Unknown Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  on, Ryedale

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow 430m north west of Crossd	ale Head, Locktor	n, Ryedale	
DESIGNATION:	Scheduled Monument (No. 1021098)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Potato Nab round barrow 1020m south we	st of Penny Holm	e, Nawton, Ryedale	
DESIGNATION:	Scheduled Monument (No. 1019592)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Rawcliffe Howe round barrow, Newton, Rye	edale		
DESIGNATION:	Scheduled Monument (No. 1019776)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable	
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 350m south of Long Plain Fa	arm, Old Byland a	nd Scawton, Ryedale	
DESIGNATION:	Scheduled Monument (No. 1009793)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
	Round barrow on Scawton Moor, 620m north west of High Lodge, Old Byland and Scawton, Ryedale			
SITE NAME:	Round barrow on Scawton Moor, 620m no	rth west of High I	odge, Old Byland and Scawton, Ryedale	
SITE NAME:  DESIGNATION:	Round barrow on Scawton Moor, 620m nor Scheduled Monument (No. 1019824)	rth west of High I		
		-	Lodge, Old Byland and Scawton, Ryedale Extensive significant problems Declining	
DESIGNATION:	Scheduled Monument (No. 1019824)	CONDITION:	Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H	CONDITION: TREND: CONTACT:  ligh Blansby, Picke  CONDITION:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:  Farm, Pickering, F	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:  Farm, Pickering, F CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other  Two round barrows 400m south west of W	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:  Farm, Pickering, F CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other	CONDITION: TREND: CONTACT:  ligh Blansby, Picke CONDITION: TREND: CONTACT:  Farm, Pickering, F CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: DESIGNATION:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other  Two round barrows 400m south west of W Scheduled Monument (No. 1020819)	CONDITION: TREND: CONTACT:  ligh Blansby, Picke  CONDITION: TREND: CONTACT:  Farm, Pickering, F  CONDITION: TREND: CONTACT:  /est Farm, Pickerin	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  rig, Ryedale Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other  Two round barrows 400m south west of W Scheduled Monument (No. 1020819) Arable ploughing	CONDITION: TREND: CONTACT:  ligh Blansby, Picke  CONDITION:  TREND: CONTACT:  Farm, Pickering, F  CONDITION:  TREND: CONTACT:  /est Farm, Pickerin  CONDITION:  TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ng, Ryedale Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other  Two round barrows 400m south west of W Scheduled Monument (No. 1020819) Arable ploughing Other	CONDITION: TREND: CONTACT:  ligh Blansby, Picke  CONDITION:  TREND: CONTACT:  Farm, Pickering, F  CONDITION:  TREND: CONTACT:  /est Farm, Pickerin  CONDITION:  TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ng, Ryedale Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019824) Arable ploughing Private  Four round barrows 875m north west of H Scheduled Monument (No. 1020818)  Arable clipping Other  Round barrow 440m north of Blansby Park Scheduled Monument (No. 1020817)  Arable clipping Other  Two round barrows 400m south west of W Scheduled Monument (No. 1020819) Arable ploughing Other  Two sections of Roman road on Flamborous	CONDITION: TREND: CONTACT:  ligh Blansby, Picke  CONDITION: TREND: CONTACT:  Farm, Pickering, F  CONDITION: TREND: CONTACT:  /est Farm, Pickerin  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  ring, Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Ryedale Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ring, Ryedale Extensive significant problems Declining Keith Emerick 01904 601988  Ryedale Extensive significant problems Declining Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Cairn cemetery north east of Birk Nab Far	m, Pockley, Ryedal	e
DESIGNATION:	Scheduled Monument (No. 1004088)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Linear boundary earthwork 370m east of C	Oscar Park Farm, F	Rievaulx, Ryedale
DESIGNATION:	Scheduled Monument (No. 1019340)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Linear dyke known as Double Dikes, in War	terloo Plantation,	Sproxton, Ryedale
DECIGNATION.	Scheduled Monument (No. 1019346)		
DESIGNATION:	Scrieduled Fioriament (No. 1017346)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Pry Rigg round barrows, Sproxton, Ryedale		
DESIGNATION:	Scheduled Monument (No. 1004086)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Rabbit type 570m south east of Pexton Mo	or Farm,Thornton	·
DESIGNATION:	Scheduled Monument (No. 1020675)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 460m north west of the Add	der Stone,Thornto	on le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No. 1020434)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 520m north west of St Hilds	a's Church, Ellerbu	ırn,Thornton le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No. 1020693)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 650m north west of St Hilds	a's Church, Ellerbu	ırn,Thornton le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No. 1020694)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Warrening enclosure 975m north east of H	ligh Paper Mill Far	m,Thornton le Dale. Ryedale
	-		·
DESIGNATION:	Scheduled Monument (No. 1020680)	CONDITION:	Generally satisfactory but with significant localised problems
	Dland man de	TRENID	Declining
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Decilining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Standing stone 470m north east of High Fa	rm, known as Wa	de's Stone, Barnby, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1016542)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Late prehistoric enclosed settlement and fi 360m south of Moor House Farm, Borrowl		rrowby Moor,		
DESIGNATION:	Scheduled Monument (No. 1016957)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Northern section of prehistoric linear boundary with intersecting hollow ways, known as Rise Dikes, in Wykeham Forest, Brompton, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1019368)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow in Wykeham Forest, 440m e	ast of Jenny Thrus	sh Spring, Brompton, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1019356)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
	Round barrow on Troutsdale Brow, 165m south east of Jenny Thrush Spring, Brompton, Scarborough				
SITE NAME:	Round barrow on Troutsdale Brow, 165m s	outh east of Jenny	rThrush Spring, Brompton, Scarborough		
	Round barrow on Troutsdale Brow, 165m s Scheduled Monument (No. 1019354)	outh east of Jenny	Thrush Spring, Brompton, Scarborough Generally unsatisfactory with major localised problems		
			Generally unsatisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019354)	CONDITION:	Generally unsatisfactory with major localised problems		
DESIGNATION:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc	CONDITION:  TREND:  CONTACT:  losure in Wykehai	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019354)  Plant growth  Government or Agency	CONDITION:  TREND:  CONTACT:  losure in Wykehai	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		
DESIGNATION: PRINCIPAL YULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto	CONDITION:  TREND:  CONTACT:  losure in Wykehai	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  m Forest, Generally satisfactory		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)	CONDITION:  TREND: CONTACT:  CONTACT:  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Forest, Generally satisfactory but with significant localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth	CONDITION:  TREND: CONTACT:  losure in Wykehar n, Scarborough CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  m Forest, Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m	CONDITION:  TREND: CONTACT:  losure in Wykehar n, Scarborough CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Forest, Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  east of Gowland Farm, Generally satisfactory		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)	CONDITION:  TREND: CONTACT:  losure in Wykehar on, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  The Forest,  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  The east of Gowland Farm,  Generally satisfactory but with significant localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)  Plant growth	CONDITION:  TREND: CONTACT:  losure in Wykehar In, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:  TREND:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Forest,  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  east of Gowland Farm,  Generally satisfactory but with significant localised problems Declining		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)	CONDITION:  TREND: CONTACT:  losure in Wykehar on, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  The Forest,  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  The east of Gowland Farm,  Generally satisfactory but with significant localised problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)  Plant growth	CONDITION:  TREND: CONTACT:  losure in Wykehar on, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Forest,  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  east of Gowland Farm,  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:  SITE NAME:  SITE NAME:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)  Plant growth Other  Round barrow I 50m south of Thirley Beck Scheduled Monument (No. 1019774)	CONDITION:  TREND: CONTACT:  losure in Wykehar on, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  The Forest,  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  The east of Gowland Farm,  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  The same of Gowland Farm,  Scarborough Extensive significant problems		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019354)  Plant growth Government or Agency  Round barrow, lime kiln and warrening enc. 540m east of Jenny Thrush Spring, Brompto Scheduled Monument (No. 1019355)  Plant growth Private  Cross dyke in Cloughton Plantations, 550m Cloughton, Scarborough Scheduled Monument (No. 1019772)  Plant growth Other  Round barrow I50m south of Thirley Beck	CONDITION:  TREND: CONTACT:  losure in Wykehar on, Scarborough CONDITION:  TREND: CONTACT:  and 890m north  CONDITION:  TREND: CONTACT:  Farm, Cloughton,	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Forest, Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  east of Gowland Farm, Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow known as Hunter Howe, Cloughton, Scarborough					
DESIGNATION:	Scheduled Monument (No. 1019770)	CONDITION:	Generally unsatisfactory with major localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Other	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Cross dyke 900m west of Backleys Farm, Darncombe cum Langdale End, Scarborough					
DESIGNATION:	Scheduled Monument (No. 1020534)	CONDITION:	Generally satisfactory but with significant localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Round barrow on Maw Rigg, I.6km south west of High Langdale End, Darncombe cum Langdale End, Scarborough					
DESIGNATION:	Scheduled Monument (No. 1019970)	CONDITION:	Generally satisfactory but with significant localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving			
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988			
CITE NAME.	Round barrow 520m north west of Keeper	s Cottago Fact A	uton Scarborough			
SITE NAME:	·	s Collage, East A)	•			
DESIGNATION:	Scheduled Monument (No. 1008482)	CONDITION:	Generally unsatisfactory with major localised problems			
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown			
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Round barrow in Raincliffe Woods, 420m no	orth of Osborne I	Lodge, East Ayton, Scarborough			
DESIGNATION:	Scheduled Monument (No. 1021235)	CONDITION:	Generally satisfactory but with significant localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Skell Dikes: a prehistoric linear boundary w and an adjoining pit alignment, East Ayton, S	rith two associated	d round barrows			
DESIGNATION:	Scheduled Monument (No. 1021238)	CONDITION:	Generally unsatisfactory			
			with major localised problems			
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Enclosure on In Moor, Struntry Carr, Egton	, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1004185)	CONDITION:	Generally satisfactory but with significant localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Round cairn on Skivick Crag, 380m south v	vest of Wheeldale	Lodge, Egton, Scarborough			
DESIGNATION:	Scheduled Monument (No. 1021258)	CONDITION:	Generally unsatisfactory with major localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Other	CONTACT:	Keith Emerick 01904 601988			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Two round barrows east of Coopers Quarries, Egton, Scarborough				
neduled Monument (No. 1004158)	CONDITION:	Generally unsatisfactory with major localised problems		
nt growth	TREND:	Stable		
vate	CONTACT:	Keith Emerick 01904 601988		
und barrow in Newton Mulgrave Woods	, 740m south of N	lewton Brow, Ellerby, Scarborough		
neduled Monument (No. 1016571)	CONDITION:	Generally satisfactory but with significant localised problems		
restry	TREND:	Declining		
vate	CONTACT:	Keith Emerick 01904 601988		
neduled Monument (No. 1004891)	CONDITION:	Generally unsatisfactory with major localised problems		
nt growth	TREND:	Declining		
_	CONTACT:	Keith Emerick 01904 601988		
gh Bride Stones, Eskdaleside cum Uggleba	arnby, Scarborougl	1		
peduled Monument (No. 1004892)	CONDITION	Extensive significant problems		
` ,		Declining		
~	CONTACT:	Keith Emerick 01904 601988		
	m south of the St	anding Stones on Standing Stones Rigg,		
neduled Monument (No. 1011965)	CONDITION:	Extensive significant problems		
able ploughing	TREND:	Declining		
vate	CONTACT:	Keith Emerick 01904 601988		
irnfield, field system and ring cairn 610m	south east of Fou	ılsike Farm, Fylingdales, Scarborough		
neduled Monument (No. 1019725)				
reduced Fiorialment (No. 1017/23)	CONDITION:	Generally unsatisfactory with major localised problems		
nt growth	CONDITION: TREND:			
, ,		with major localised problems		
nt growth	TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988		
nt growth vate	TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  gh Generally unsatisfactory		
nt growth vate ing medieval deer park wall section, Fylin	TREND: CONTACT: ngdales, Scarborou	with major localised problems  Declining  Keith Emerick 01904 601988		
nt growth vate  ing medieval deer park wall section, Fylin neduled Monument (No. 1015542)	TREND: CONTACT:  ngdales, Scarborou  CONDITION:	with major localised problems Declining Keith Emerick 01904 601988  gh Generally unsatisfactory with major localised problems		
nt growth vate  ing medieval deer park wall section, Fylin neduled Monument (No. 1015542)	TREND: CONTACT:  agdales, Scarborou CONDITION:  TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  gh Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		
nt growth vate  ing medieval deer park wall section, Fylin neduled Monument (No. 1015542)  illapse vate  ear earthwork south east of the junction	TREND: CONTACT:  agdales, Scarborou CONDITION:  TREND: CONTACT:	with major localised problems Declining Keith Emerick 01904 601988  gh Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory		
ing medieval deer park wall section, Fylin meduled Monument (No. 1015542)  Illapse wate  dear earthwork south east of the junction of the road leading to Fylingthorpe, Fyling.	TREND: CONTACT:  Ingelales, Scarborough CONDITION: TREND: CONTACT:  In of the A171 dales, Scarborough	with major localised problems Declining Keith Emerick 01904 601988  gh Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988		
, i	restry vate  oup of seventeen tumuli to the north of the east side of Sleights Moor, Eskdalesia neduled Monument (No. 1004891)  Int growth vate  gh Bride Stones, Eskdaleside cum Uggleba neduled Monument (No. 1004892) tensive vehicle damage/erosion vate  will barrow in north corner of a field 205 ingdales, Scarborough neduled Monument (No. 1011965) able ploughing vate	restry vate  contact:  coup of seventeen tumuli to the north of Greenlands Howe the east side of Sleights Moor, Eskdaleside cum Ugglebarn neduled Monument (No. 1004891)  condition:  restry  restry		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Linear earthwork to the north west of the and the road leading to Fylingthorpe, Fyling	•	
DESIGNATION:	Scheduled Monument (No. 1011961)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Medieval dyke known as Green Dike, Fyling	dales, Scarboroug	h
DESIGNATION:	Scheduled Monument (No. 1020116)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 510m north east of Cook H	ouse, Fylingdales,	Scarborough
DESIGNATION:	Scheduled Monument (No. 1019698)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 720m north east of Cook H	ouse, Fylingdales,	Scarborough
DESIGNATION:	Scheduled Monument (No. 1019699)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Site of Stoupe Brow alum works, 210m sou	th east of Stoupe	Bank Farm, Fylingdales, Scarborough
DESIGNATION:	Scheduled Monument (No. 1018145)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	The Latter Gate Hills tumuli; the northern of the two, 200m ESE from the junction of the A171 and the road leading to Fylingthorpe, Fylingdales, Scarborou		
SITE NAME:	· · · · · · · · · · · · · · · · · · ·	,	g to Fylingthorpe, Fylingdales, Scarborough
	· · · · · · · · · · · · · · · · · · ·	,	Generally unsatisfactory
DESIGNATION:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)	d the road leadin	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	200m ESE from the junction of the A171 an	d the road leadin	Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth	d the road leadin  CONDITION:  TREND:  CONTACT:  TREST and prehistori	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair	d the road leadin  CONDITION:  TREND:  CONTACT:  TREST and prehistori	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  JITE NAME: DESIGNATION:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair immediately south of Morton Close, Goath	d the road leadin  CONDITION:  TREND:  CONTACT:  This and prehistoriand, Scarborough	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,  Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair immediately south of Morton Close, Goathly Scheduled Monument (No. 1021301)	d the road leadin  CONDITION:  TREND:  CONTACT:  This and prehistoriand, Scarborough  CONDITION:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair immediately south of Morton Close, Goathly Scheduled Monument (No. 1021301)  Plant growth	d the road leadin  CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair immediately south of Morton Close, Goathly Scheduled Monument (No. 1021301)  Plant growth Other  Simon Howe: a round cairn on Goathland No.	d the road leadin  CONDITION:  TREND: CONTACT:  TREND: CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	200m ESE from the junction of the A171 and Scheduled Monument (No. 1011973)  Plant growth Private  Allan Tofts cairnfield, field system, burial cair immediately south of Morton Close, Goathly Scheduled Monument (No. 1021301)  Plant growth Other  Simon Howe: a round cairn on Goathland Na standing stone and a stone alignment, Goathland Na standing stone and a stone alignment stone and a stone a	d the road leadin  CONDITION:  TREND: CONTACT:  Trens and prehistoriand, Scarborough CONDITION:  TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  c rock art,  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  ted round barrows, ugh Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Two Howes: two round barrows on Goathland Moor, Goathland, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1021296)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining		
OWNER TYPE:	Other	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow in Springwood Heights Plant 220m north west of Springwood Cottage, I		Ough		
DESIGNATION:	Scheduled Monument (No. 1019620)	CONDITION:	Generally satisfactory		
BESIGN WICH.	Scheduled Floridinent (140. For 7020)	CONDITION.	but with significant localised problems		
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow in Harwood Dale Forest kno	own as Penny Hov	we, Harwood Dale, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1019678)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining		
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round cairn on Cowgate Rigg, 790m south	west of Teydale F	arm, Harwood Dale, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1020226)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving		
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round cairn on Cowgate Rigg, 870m north	of Brooklands Fa	rm, Harwood Dale, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1019769)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving		
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Moated site at Low Laithes Farm, Whitby L	aithes, Hawsker cı	um Stainsacre, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1020402)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Saltwick Nab alum quarries, Hawsker cum S	Stainsacre, Scarbo	rough		
DESIGNATION:	Scheduled Monument (No. 1017779)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow and 20th century Royal Obs	server Corps post	on Beacon Hill,		
	known as the site of Hinderwell Beacon, Hi		ough		
DESIGNATION:	Scheduled Monument (No. 1016956)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
	Private	CONTACT:	Keith Emerick 01904 601988		
OWNER TYPE:	11114416	2011,7,61.	Reidit Emerick 01701 001700		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow immediately south of California	rnia Belt, I 90m ea	st of Fox Head, Hutton Buscel, Scarborou	
DESIGNATION:	Scheduled Monument (No. 1017158)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
TITE NAME:	Round barrow in School Belt, 1050m north	west of Jenny Spr	ring, Hutton Buscel, Scarborough	
DESIGNATION:	Scheduled Monument (No. 1017167)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Shortgate Hill, 500m south east of Coomb Slack Farm, Hutton Buscel, Scarborough			
DESIGNATION:	Scheduled Monument (No. 1019277)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving	
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988	
DITE NAME:	The Moor Dikes and Craddlegrip Dike pread and other prehistoric remains in Wykeham			
DESIGNATION:	Scheduled Monument (No. 1017164)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Three square barrows in Wykeham Forest,	590m south east	of Mount Misery, Hutton Buscel, Scarboro	
designation:	Scheduled Monument (No. 1017107)	CONDITION:	Generally satisfactory	
	Plant grouth	T05.15	but with significant localised problems	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988	
SITE NAME:	Cairnfield, including a standing stone, rounc	l barrow, round ca	irn, enclosed field and part of	
	Cucket medieval deer park boundary, 360m			
DESIGNATION:	Scheduled Monument (No. 1016962)	CONDITION:	Generally satisfactory	
	,			
	,		but with significant localised problems	
'RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
		trend: contact:	-	
OWNER TYPE:	Plant growth	CONTACT:	Declining Keith Emerick 01904 601988	
OWNER TYPE: SITE NAME:	Plant growth Private	CONTACT:	Declining Keith Emerick 01904 601988	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Plant growth Private  Round barrow at Lady Cross, 730m south	CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 1019076)	CONTACT:  west of Dun Bogs  CONDITION:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough  Generally satisfactory but with significant localised problems	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 1019076)  Arable clipping	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 1019076)  Arable clipping Private	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 1019076)  Arable clipping Private  Round barrow 1200m north west of Beaco	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:  n Farm, Irton, Scal	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Phorough	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Plant growth Private  Round barrow at Lady Cross, 730m south Scheduled Monument (No. 1019076)  Arable clipping Private  Round barrow I 200m north west of Beaco Scheduled Monument (No. 1008501)	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:  n Farm, Irton, Scal	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  -borough Extensive significant problems	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No. 1019076)  Arable clipping Private  Round barrow I 200m north west of Beaco Scheduled Monument (No. 1008501) Arable ploughing	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:  n Farm, Irton, Scal  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Phorough Extensive significant problems Unknown Keith Emerick 01904 601988	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No. 1019076)  Arable clipping Private  Round barrow I 200m north west of Beaco Scheduled Monument (No. 1008501) Arable ploughing Local Authority	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:  n Farm, Irton, Scal  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Phorough Extensive significant problems Unknown Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No. 1019076)  Arable clipping Private  Round barrow I 200m north west of Beaco Scheduled Monument (No. 1008501) Arable ploughing Local Authority  Round barrow I 350m north west of Beaco	CONTACT:  west of Dun Bogs  CONDITION:  TREND:  CONTACT:  n Farm, Irton, Scal  CONDITION:  TREND:  CONTACT:	Declining Keith Emerick 01904 601988  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Phorough Extensive significant problems Unknown Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Alum works at Kettleness, Lythe, Scarborou	ıgh		
DESIGNATION:	Scheduled Monument (No. 1018144)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Brockrigg, 400m east of	Brockrigg Farm, Ly	rthe, Scarborough	
DESIGNATION:	Scheduled Monument (No. 1016539)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough			
DESIGNATION:	Scheduled Monument (No. 1016538)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Dunsley Moor, I 60m wes	t of Skelder Cott	age, Newholm cum Dunsley, Scarborougl	
DESIGNATION:	Scheduled Monument (No. 1016534)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Newton Mulgrave medieval settlement, Nev	wton Mulgrave, Sc	arborough	
DESIGNATION:	Scheduled Monument (No. 1016958)	CONDITION:	Generally unsatisfactory	
	,		with major localised problems	
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 330m south west of Newton Brow, Newton Mulgrave, Scarborough			
DESIGNATION:	Scheduled Monument (No. 1016961)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow 920m south west of Silpho I	Brow Farm, Silpho	, Scarborough	
DESIGNATION:	Scheduled Monument (No. 1019626)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	The Thieves' Dikes: prehistoric linear bound	daries and associa	ted features, Silpho, Scarborough	
	The Thieves' Dikes: prehistoric linear bound Scheduled Monument (No. 1019627)	daries and associate condition:	ded features, Silpho, Scarborough  Generally satisfactory but with significant localised problems	
designation:	·		Generally satisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019627)	CONDITION:	Generally satisfactory but with significant localised problems	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1019627)  Arable clipping	CONDITION:  TREND:  CONTACT:  features including	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  a medieval monastic grange,	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019627)  Arable clipping Government or Agency  Prehistoric linear boundary and associated	CONDITION:  TREND:  CONTACT:  features including	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  a medieval monastic grange,	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019627)  Arable clipping Government or Agency  Prehistoric linear boundary and associated north, east and south east of Moorsome Fa	CONDITION:  TREND:  CONTACT:  features including rm, Snainton, Scar	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  a medieval monastic grange, borough Generally satisfactory	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS

SITE NAME:	Round barrow 100m north of Church Road Farm, Stainton Dale, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1020110)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 370m south east of Rudda Cottages, Stainton Dale, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1020106)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow on Ugthorpe Moor known as Loose Howe, 130m south west of Day Well House, Ugthorpe, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1016543)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Prehistoric linear boundary in Craddlegrip Wood, 900m north west of High Yedmandale, West Ayton, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1017165)	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow on Coverdale Moor, 530m south of North Stile Cottage, West Ayton, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1017156)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow at North Moor, I 20m south	east of Forest Lo	dge, Wykeham, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1017021)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow in Wykeham Forest, 550m south east of the Three Tremblers, Wykeham, Scarborough				
DESIGNATION:	Scheduled Monument (No. 1017024)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow on East Moor, 640m north o	of East Moor Farn	n, Wykeham, Scarborough		
DESIGNATION:	Scheduled Monument (No. 1019371)	CONDITION:	Extensive significant problems		
			<u> </u>		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

#### RICHMONDSHIRE



The Old Gatehouse, SITE NAME: Jervaulx Park,

. East Witton Out Parish

DESIGNATION: Listed Building Grade I, SM

Very bad CONDITION: Part occupied OCCUPANCY:

C(C)PRIORITY-Private OWNER TYPE:

The house and gardens known as the Old Gatehouse is probably re-used medieval masonry (probably in the C19) on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair.

Contact: Keith Emerick 01904 601988



Ravensworth Castle and park wall, SITE NAME: The Green. Ravensworth

Listed Building Grade I, SM, CA DESIGNATION: CONDITION: N/A OCCUPANCY:

A(A)PRIORITY: OWNERTYPE: Private Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower, are now at risk. A detailed record of the standing fabric has been completed.

Contact: Neil Redfern 01904 601897



SITE NAME: Cobscar Lead smelt mill, Redmire

Scheduled Monument DESIGNATION:

Poor CONDITION: N/A D (E) PRIORITY: Private OWNER TYPE:

The monument includes the standing, earthwork and buried remains of an ore hearth lead smelt mill, fuel store, and associated buildings, with the remains of a flue system leading to an intact chimney. Natural England will be taking forward repair programme.

Contact: Neil Redfern 01904 601897



Old Grandstand, SITE NAME: Richmond

DESIGNATION: Listed Building Grade II\*, CA Poor CONDITION: OCCUPANCY: N/A C (C) PRIORITY-OWNERTYPE: Company

A rare example of an C18 racecourse grandstand. The racecourse was closed in the late C19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

Contact: Neil Redfern 01904 601897



St Martins Priory Ruins, SITE NAME: A6136,

St Martins

DESIGNATION: Listed Building Grade I, SM, CA

Poor CONDITION: OCCUPANCY: N/A A(A)OWNERTYPE: Private

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.





Keld Heads lead smeltmill SITE NAME and mine complex, Preston-under-Scar, Wensley

**DESIGNATION: Scheduled Monument** CONDITION: Poor N/A OCCUPANCY:

PRIORITY: D (D) OWNERTYPE: Private

The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 and C19. Scrub clearance was undertaken by North Yorkshire County Council volunteers in 2005 to assist with the preparation of survey documents. Condition survey and options appraisal in progress.

Contact: Neil Redfern 01904 601897

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA LB/LBs LPA NP

UA WHS

SITE NAME:	Section of Scots Dyke linear boundary 600m south east of Park House, Aldbrough			
DESIGNATION:	Scheduled Monument (No. 1013305)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Stanwick Late Iron Age oppidum, Iron Age and medieval settlement, early Christian church and sculpture and post-medieval emparkment, Aldbrough			
DESIGNATION:	Scheduled Monument (No. 1016199)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Section of Scots Dyke linear boundary I 50m ENE of Olliver, Aske			
DESIGNATION:	Scheduled Monument (No. 1013780)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Cataractonium Roman forts and town, Brompton-on-Swale			
DESIGNATION:	Scheduled Monument (No. 1021181)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	St Giles medieval hospital, post-medieval farmstead and Iron Age occupation site immediately north of St Giles Farm, Brough with St Giles			
SHE IVALIE.				
DESIGNATION:			Generally satisfactory	
DESIGNATION:	immediately north of St Giles Farm, Brough	with St Giles	· · · · · · · · · · · · · · · · · · ·	
	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)	with St Giles  CONDITION:	Generally satisfactory but with significant localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210) Extensive natural erosion	with St Giles  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private	with St Giles  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)	with St Giles  CONDITION:  TREND:  CONTACT:  and associated field	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees an	with St Giles  CONDITION:  TREND:  CONTACT:  and associated field  CONDITION:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  system, Dalton-on-Tees Generally satisfactory but with significant localised problems	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development	with St Giles  CONDITION:  TREND:  CONTACT:  and associated field  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private	with St Giles  CONDITION:  TREND:  CONTACT:  and associated field  CONDITION:  TREND:  CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East Generally satisfactory	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private  Section of Scots Dyke linear boundary and	with St Giles  CONDITION:  TREND: CONTACT:  Ind associated field CONDITION:  TREND: CONTACT:  portion of field sy	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private  Section of Scots Dyke linear boundary and Scheduled Monument (No. 1013777)	with St Giles  CONDITION:  TREND: CONTACT:  and associated field  CONDITION:  TREND: CONTACT:  portion of field sy  CONDITION:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East Generally satisfactory but with significant localised problems	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private  Section of Scots Dyke linear boundary and Scheduled Monument (No. 1013777)  Permitted development	with St Giles  CONDITION:  TREND: CONTACT:  Ind associated field CONDITION:  TREND: CONTACT:  Portion of field sy CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private  Section of Scots Dyke linear boundary and Scheduled Monument (No. 1013777)  Permitted development Private  Roman fort and prehistoric enclosed settle	with St Giles  CONDITION:  TREND: CONTACT:  Ind associated field CONDITION:  TREND: CONTACT:  Portion of field sy CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  of Carkin Moor Farm, East Layton	
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:	immediately north of St Giles Farm, Brough Scheduled Monument (No. 1021210)  Extensive natural erosion Private  Medieval settlement of Dalton upon Tees and Scheduled Monument (No. 1019724)  Permitted development Private  Section of Scots Dyke linear boundary and Scheduled Monument (No. 1013777)  Permitted development Private	with St Giles  CONDITION:  TREND: CONTACT:  Ind associated field CONDITION:  TREND: CONTACT:  Portion of field sy CONDITION:  TREND: CONTACT:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  I system, Dalton-on-Tees Generally satisfactory but with significant localised problems Stable Keith Emerick 01904 601988  ystem 100m east of Whitefields Farm, East Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Two moated sites, the site of a dovecote ar 120m north west and 180m north of The C		
DESIGNATION:	Scheduled Monument (No. 1021039)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Medieval village of Hunton and field system	, Hunton	
DESIGNATION:	Scheduled Monument (No. 1018380)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of Scots Dike linear boundary nort	h west of High M	errybent, Melsonby
DESIGNATION:	Scheduled Monument (No. 1014799)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of Scots Dyke linear boundary east	of Langdale Rush	, Melsonby
DESIGNATION:	Scheduled Monument (No. 1014240)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	William's Hill, Middleham		
DESIGNATION:	Scheduled Monument (No. 1004907)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of the Scots Dyke linear boundary	225m south of St	Martin's Priory, St Martin's
DESIGNATION:	Scheduled Monument (No. 1018143)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Roman fort at Wensley, Wensley		
DESIGNATION:	Scheduled Monument (No. 1012004)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

#### **RYEDALE**



SITE NAME: Lime Kilns. A170.

Allerston

DESIGNATION: Listed Building Grade II, SM, CA

Poor CONDITION: N/A D (D) PRIORITY-OWNERTYPE: Private Bank of four lime kilns circa 1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair. Some parts are starting to collapse. Section 17 Management Agreement works to remove damaging trees completed.

Contact: Keith Emerick 01904 601988



Yedingham Priory, SITE NAME: Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, SM

CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY: Private OWNER TYPE:

Redundant priory, C12-C13. Little standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging in places.

Contact: Keith Emerick 01904 601988



SITE NAME: Wall of cascade approximately 100 metres north of Ebberston Hall, A170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

Poor CONDITION: N/A OCCUPANCY:

C(C)PRIORITY: Private OWNER TYPE:

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale approximately 50m to the north of the Hall by Colen Campbell. Forms the lowest cascade of the two in the water garden.





Wall of cascade approximately SITE NAME: 50 metres north of Ebberston Hall, A170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

CONDITION: Poor OCCUPANCY: N/A C (C) PRIORITY-

OWNER TYPE:

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale circa 50m to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Andy Wimble 01904 601986



SITE NAME: The Stray, Castle Howard, Henderskelfe

Private

DESIGNATION: Listed Building Grade I, RPG

Poor CONDITION: N/A OCCUPANCY: D (D) OWNERTYPE: Private interval towers stretching for one mile to either side of the main drive, immediately south of the pyramid gate. Built to the designs of Sir John Vanbrugh c 1723 as a landscape feature. With English Heritage support and advice the Estate has secured Natural England grant of £1 million to help fund repairs. Eastern half repairs completed.

Castellated walls, 4 metres high, with square and round

Contact: Giles Proctor 01904 601981



The Mausoleum and bastion wall SITE NAME with gates and railings, Kirk Hill, Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I CONDITION: Poor N/A OCCUPANCY:

Mausoleum by Hawksmoor, 1729-42, modelled on the tomb of Metella. Situated on a bluff c1.2km E of the mansion and visible from the Temple Terrace and the Temple of the Four Winds (1724-28 by Vanbrugh), both SE of the mansion. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.

Contact: Neil Redfern 01904 601897

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

C(C)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

Conservation Area CA LB/LBs Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs UA WHS Unitary Authority World Heritage Site



The Pyramid, St Annes Hill, SITE NAME: Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I

Poor CONDITION: N/A OCCUPANCY:

C (C) OWNERTYPE: Private

Commemorative monument of 1728 by Hawksmoor, situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone pyramid suffering from cramp damage. Five of the eight piers at the corners have been repaired with the support of a grant. Set in late C17/early C18 park, one of the most historically significant landscapes in the country.

Contact: Neil Redfern 01904 601897



SITE NAME: Walls to walled garden with gates and corner piers, Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I

Very bad CONDITION: N/A C(C)PRIORITY: Private

OWNER TYPE:

Walls to the walled garden, early C18 by Sir John Vanburgh. The brick walls are in fair condition but the limestone piers are decaying and destabilising, partly collapsed due to lack of maintenance and repair.

Contact: Neil Redfern 01904 601897



Screen wall, SITE NAME:

north west of Malton Lodge, Old Maltongate, Malton

DESIGNATION: Listed Building Grade II\*, CA

Very bad CONDITION: N/A OCCUPANCY: PRIORITY: A(A)OWNERTYPE: Private

Courtyard wall circa I 604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Neil Redfern 01904 601897



Sheriff Hutton Castle, SITE NAME:

Main Street, Sheriff Hutton

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION: N/A C(C)PRIORITY-Private OWNER TYPE:

Ruinous castle begun in 1382 by John, Lord Neville, with C15 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Emergency works to south west tower are complete.

Contact: Neil Redfern 01904 601897



Slingsby Castle, SITE NAME: Slingsby

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad N/A OCCUPANCY:

C (C) PRIORITY-OWNERTYPE: Private C16 Great House built on the site of a medieval castle. Ruinous but surviving up to the eaves in height. In need of urgent consolidation; site is deteriorating as a result of natural erosion and some vandalism.

Contact: Keith Emerick 01904 601988



SITE NAME:

Church of St Michael, Town Green, Crambe

Small medieval church. Roofs and pointing in poor order, but grant-aided repairs on site.

DESIGNATION: Listed Place of Worship Grade I

CONDITION:

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site



Church of All Saints, SITE NAME:

Church Lane, Slingsby

Largely Victorian village church. Serious deterioration of tower parapet due to rusting cramps. Grant-aided repairs to tower underway.

DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION:

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation Contact: Giles Proctor 01904 601981



Church of St Mary, SITE NAME: Main Street. Thixendale

Fine village church by GE Street. Repairs underway to roofs, with grant support.

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION:

F (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Giles Proctor 01904 601981

SITE NAME:	Acklam Wold barrow group: a bowl barrow 220m north west of Acklam Wold House,		
DESIGNATION:	Scheduled Monument (No. 1011543)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a bowl barrow	300m north wes	t of Acklam Wold House, Acklam
DESIGNATION:	Scheduled Monument (No. 1011541)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam		
DESIGNATION:	Scheduled Monument (No. 1011570)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam		
DESIGNATION:	Scheduled Monument (No. 1009928)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a bowl barrow	450m south of A	acklam Wold House, Acklam
DESIGNATION:	Scheduled Monument (No. 1011574)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: a bowl barrow	450m south wes	t of Acklam Wold House, Acklam
DESIGNATION:	Scheduled Monument (No. 1011573)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
OVVINERTITE.	Acklam Wold barrow group: a bowl barrow on Wooing Nab, Acklam		
SITE NAME:	Acklam Wold barrow group: a bowl barrow	on Wooing Nab,	Acklam
	Acklam Wold barrow group: a bowl barrow Scheduled Monument (No. 1011539)	on Wooing Nab,	Acklam  Extensive significant problems
SITE NAME:	<u> </u>		

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### **ABBREVIATIONS**

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site

SITE NAME:	Acklam Wold barrow group: a pair of bell b 200m south west of Acklam Wold House, A		l barrow
DESIGNATION:	Scheduled Monument (No. 1011547)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Acklam Wold barrow group: two bowl barr	ows on Wooing N	lab, Acklam
DESIGNATION:	Scheduled Monument (No. 1011537)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Aldro earthworks: a linear boundary, two c	ross-dykes and nir	ne round barrows on Birdsall Wold, Acklan
DESIGNATION:	Scheduled Monument (No. 1007500)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 530m north of Keeper's Cotta	age. Allerston	
		-	Canarally satisfactory
DESIGNATION:	Scheduled Monument (No. 1020330)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 630m north west of Scamridg	e Farm Allerston	
DESIGNATION:	Scheduled Monument (No. 1020832)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
	6		17 11 5 11 01004 701000
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	Private  Prehistoric linear boundary on Stonygate M		
SITE NAME:			of Warren House Farm, Allerston  Generally satisfactory
site name: Designation:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)	loor, 550m west o	of Warren House Farm, Allerston  Generally satisfactory  but with significant localised problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Prehistoric linear boundary on Stonygate M	loor, 550m west o	of Warren House Farm, Allerston  Generally satisfactory
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695) Arable clipping	loor, 550m west of condition:  TREND:  CONTACT:	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems  Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695) Arable clipping Private	loor, 550m west of condition:  TREND:  CONTACT:	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems  Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Cor Scheduled Monument (No. 1020331)	loor, 550m west of CONDITION:  TREND:  CONTACT:  ttage, Allerston	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth	loor, 550m west of CONDITION:  TREND:  CONTACT:  ttage, Allerston	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Cor Scheduled Monument (No. 1020331)	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:  TREND: CONTACT:	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth Government or Agency	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:  TREND: CONTACT:	of Warren House Farm, Allerston  Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Fair Scheduled Monument (No. 1020831)	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Fair	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Fair Scheduled Monument (No. 1020831)	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Cor Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Far Scheduled Monument (No. 1020831)  Arable clipping	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston CONDITION:  TREND: CONTACT:  rm, Allerston  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Cor Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Far Scheduled Monument (No. 1020831)  Arable clipping Government or Agency	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston CONDITION:  TREND: CONTACT:  rm, Allerston  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Prehistoric linear boundary on Stonygate M Scheduled Monument (No. 1020695)  Arable clipping Private  Round barrow 470m north of Keeper's Co Scheduled Monument (No. 1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Far Scheduled Monument (No. 1020831)  Arable clipping Government or Agency  Round barrow 250m NNE of Easthorpe Co	loor, 550m west of CONDITION:  TREND: CONTACT:  ttage, Allerston  CONDITION:  TREND: CONTACT:  rm, Allerston  CONDITION:  TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988  Generally satisfactory but with significant localised problems Improving Keith Emerick 01904 601988  Generally satisfactory but with minor localised problems Improving Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE:

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

### ABBREVIATIONS

SITE NAME:	Round barrow 310m NNE of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No. 1014565)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 330m north of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No. 1014567)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 360m north of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No. 1014568)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 380m NNW of Easthorpe L	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No. 1014569)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Iron Age settlement, Barton-le-Street		
DESIGNATION:	Scheduled Monument (No. 1003666)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	Pockley Gates round barrow 600m west of	f Beadlam Grange.	Beadlam
SITE NAME:	rocker dates round barrow down west of		
SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1019341)	CONDITION:	Extensive significant problems
DESIGNATION:	,	-	Extensive significant problems Declining
	Scheduled Monument (No. 1019341)	CONDITION:	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019341) Arable ploughing	CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor	CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571)	CONDITION: TREND: CONTACT:  Tth west of Vessey  CONDITION:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor	CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing	CONDITION: TREND: CONTACT:  Th west of Vessey  CONDITION: TREND:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou Scheduled Monument (No. 1007569)	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou Scheduled Monument (No. 1007569) Arable ploughing	CONDITION: TREND: CONTACT:  Th west of Vessey  CONDITION: TREND: CONTACT:  The east of Vessey	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou Scheduled Monument (No. 1007569)	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:  The east of Vessey  CONDITION:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou Scheduled Monument (No. 1007569) Arable ploughing	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  CONTACT:  THE east of Vessey  CONDITION: TREND: CONTACT:  CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou Scheduled Monument (No. 1007569) Arable ploughing Private	CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  CONTACT:  THE east of Vessey  CONDITION: TREND: CONTACT:  CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sour Scheduled Monument (No. 1007569) Arable ploughing Private  A bowl barrow on Birdsall Wold, 300m nor Scheduled Monument (No. 1007569) Arable ploughing Private	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:  The east of Vessey  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sour Scheduled Monument (No. 1007569) Arable ploughing Private  A bowl barrow on Birdsall Wold, 300m nor Scheduled Monument (No. 1007570)	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:  The east of Vessey  CONDITION: TREND: CONTACT:  The east of Vessey  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sour Scheduled Monument (No. 1007569) Arable ploughing Private  A bowl barrow on Birdsall Wold, 300m nor Scheduled Monument (No. 1007570) Arable ploughing	CONDITION: TREND: CONTACT:  CONTACT:  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL YULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL YULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sour Scheduled Monument (No. 1007569) Arable ploughing Private  A bowl barrow on Birdsall Wold, 300m nor Scheduled Monument (No. 1007570) Arable ploughing Private  A bowl barrow on Birdsall Wold, 425m eas	CONDITION: TREND: CONTACT:  The west of Vessey  CONDITION: TREND: CONTACT:  THE east of Vessey  CONDITION: TREND: CONTACT:  TREND: CONTACT:  TREND: CONTACT:  THE east of Vessey  CONDITION: TREND: CONTACT:  TREND:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Fasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1019341) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No. 1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sour Scheduled Monument (No. 1007569) Arable ploughing Private  A bowl barrow on Birdsall Wold, 300m nor Scheduled Monument (No. 1007570) Arable ploughing Private	CONDITION: TREND: CONTACT:  CONTACT:  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

# ABBREVIATIONS

	A bowl barrow on Birdsall Wold, 475m noi incorporating part of a linear boundary, Bir	•	Pasture Farm,	
DESIGNATION:	Scheduled Monument (No. 1007575)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
ITE NAME:	A bowl barrow on Birdsall Wold, 580m eas	et of Aldro Farm, B	irdsall	
DESIGNATION:	Scheduled Monument (No. 1007514)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	A bowl barrow on Birdsall Wold, 750m east of Aldro Farm, Birdsall			
DESIGNATION:	Scheduled Monument (No. 1007468)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and \	essey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No. 1007443)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and \	/essey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No. 1007442)	CONDITION:	Generally satisfactory	
	,		but with minor localised problem	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and \	essey Pasture Dale, Birdsall	
			E	
DESIGNATION:	Scheduled Monument (No. 1007439)	CONDITION:	Extensive significant problems	
	Scheduled Monument (No. 1007439) Arable ploughing	CONDITION: TREND:	Declining Declining	
PRINCIPAL VULNERABILITY:	,			
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing	TREND: CONTACT:	Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Arable ploughing Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400	TREND: CONTACT: m north west of V	Declining Keith Emerick 01904 601988  Vessey Pasture Farm, Birdsall	
PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574)	TREND: CONTACT:  m north west of V  CONDITION:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988	
RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private  Two bowl barrows on Birdsall Wold, 850m	TREND: CONTACT:  m north west of V CONDITION: TREND: CONTACT:  east of Aldro Farm	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  m, Birdsall	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private  Two bowl barrows on Birdsall Wold, 850m Scheduled Monument (No. 1007403)	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:  east of Aldro Farr CONDITION:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  m, Birdsall Extensive significant problems	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private  Two bowl barrows on Birdsall Wold, 850m Scheduled Monument (No. 1007403) Arable ploughing	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:  east of Aldro Farr  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  m, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private  Two bowl barrows on Birdsall Wold, 850m Scheduled Monument (No. 1007403) Arable ploughing Private	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:  east of Aldro Farr  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  m, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  OWNER TYPE:	Arable ploughing Private  Three bowl barrows on Birdsall Wold, 400 Scheduled Monument (No. 1007574) Arable ploughing Private  Two bowl barrows on Birdsall Wold, 850m Scheduled Monument (No. 1007403) Arable ploughing Private  Two bowl barrows on Birdsall Wold, between	TREND: CONTACT:  m north west of V  CONDITION: TREND: CONTACT:  east of Aldro Farr CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Sessey Pasture Farm, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988  m, Birdsall Extensive significant problems Declining Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Hedon Howe tumulus, Burythorpe		
DESIGNATION:	Scheduled Monument (No. 1005487)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Roman site south west of Kennythorpe, Bu	rythorpe	
DESIGNATION:	Scheduled Monument (No. 1004070)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bossall Hall: a quadrangular castle, Buttercr	ambe with Bossall	
DESIGNATION:	Scheduled Monument (No. 1008016)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Cawthorne medieval settlement remains 15	0m north east of	West Cawthorne, Cropton
DESIGNATION:	Scheduled Monument (No. 1018951)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 350m north west of Hen Fla	atts, Cropton	
DESIGNATION:	Scheduled Monument (No. 1018408)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 550m north of High Nova F	arm, Cropton	
DESIGNATION:	Scheduled Monument (No. 1015440)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Foston medieval settlement and moated me	onastic grange, Fo	ston
DESIGNATION:	Scheduled Monument (No. 1019388)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Boythorpe settlement site, Foxholes		
DESIGNATION:	Scheduled Monument (No. 1004059)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Romano-British settlement, Foxholes		
DESIGNATION:	Scheduled Monument (No. 1004046)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004046)  Arable ploughing	CONDITION: TREND:	Extensive significant problems  Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE:

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

### ABBREVIATIONS

SITE NAME:	Settlement site at Butterwick, Foxholes		
DESIGNATION:	Scheduled Monument (No. 1004047)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 250m ENE of High Baxtonh	owe, Fryton	
DESIGNATION:	Scheduled Monument (No. 1013682)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 700yds (640m) north east o	of Brompton Wold	Farm, Ganton
DESIGNATION:	Scheduled Monument (No. 1003688)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three round barrows north east of Ganton	n Wold Farm, Gan	ton
DESIGNATION:	Scheduled Monument (No. 1003687)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 450m south west of Coney	Hill Farm, Gilling	East
DESIGNATION:	Scheduled Monument (No. 1014082)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 500m SSW of Coney Hill Fa	ırm, Gilling East	
DESIGNATION:	Scheduled Monument (No. 1014083)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 530m NNW of Maidenswor	th Farm, Grimsto	ne
DESIGNATION:	Scheduled Monument (No. 1013599)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Grimston Moor 350m n	orth east of Black	Gill Plantation, Grimstone
DESIGNATION:	Scheduled Monument (No. 1013444)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 300m north of Rye House F	arm, Helmsley	
DESIGNATION:	Scheduled Monument (No. 1019596)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1019596)  Arable ploughing	CONDITION: TREND:	Extensive significant problems  Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 420m north of Rye House F	arm, Helmsley			
DESIGNATION:	Scheduled Monument (No. 1019595)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a bowl	barrow I.Ikm eas	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 1011578)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining		
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a bowl barrow I.3km east of Manor Wold Farm, Heslerton				
DESIGNATION:	Scheduled Monument (No. 1011579)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a bowl	barrow 750m eas	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 1011580)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	East Heslerton Brow barrow group: a long	barrow 1000m ea	st of Manor Wold Farm, Heslerton		
DESIGNATION:	Scheduled Monument (No. 1011516)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
ITE NAME:	Heslerton Brow barrow group: a bowl barr	ow 230m north e	ast of Wold Barn, Heslerton		
DESIGNATION:	Scheduled Monument (No. 1011585)	CONDITION:	Extensive significant problems		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Heslerton Brow barrow group: a bowl barr	ow 250m north v	vest of Wold Barn. Heslerton		
	- ·		Extensive significant problems		
DESIGNATION:	Scheduled Monument (No. 1011582)  Arable ploughing	CONDITION:	Declining		
PRINCIPAL VULNERABILITY:  DWNER TYPE:	Private	TREND: CONTACT:	Keith Emerick 01904 601988		
	Heslerton Brow barrow group: three bowl	barrows 300m no			
SITE NAME:					
	Scheduled Monument (No. 1011586)	CONDITION:	Extensive significant problems		
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DESIGNATION: PRINCIPAL VULNERABILITY:	,		• .		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing	TREND: CONTACT:	Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: ITE NAME:	Arable ploughing Private	TREND: CONTACT:	Declining		
DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:	Arable ploughing Private  New Bield round barrow and ringwork, He	TREND: CONTACT:	Declining Keith Emerick 01904 601988		
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  New Bield round barrow and ringwork, He Scheduled Monument (No. 1004105)	TREND: CONTACT:  slerton  CONDITION:	Declining Keith Emerick 01904 601988  Extensive significant problems		
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  New Bield round barrow and ringwork, He Scheduled Monument (No. 1004105) Arable ploughing	TREND: CONTACT:  slerton  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988		
DESIGNATION: PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  DWNER TYPE:	Arable ploughing Private  New Bield round barrow and ringwork, He Scheduled Monument (No. 1004105) Arable ploughing Private	TREND: CONTACT:  slerton  CONDITION: TREND: CONTACT:	Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988  Ingham Generally unsatisfactory		
DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private  New Bield round barrow and ringwork, He Scheduled Monument (No. 1004105) Arable ploughing Private  Round barrow 100m north west of Moor H	TREND: CONTACT:  slerton  CONDITION: TREND: CONTACT:  House Farm, Hovin	Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

Scheduled Monument (No. 1013552)  Forestry Private  Round barrow 350m south west of Moor H Scheduled Monument (No. 1013545) Arable ploughing	CONDITION:  TREND:  CONTACT:  House Farm, Hovi	Generally satisfactory but with significant localised problems Declining Keith Emerick 01904 601988		
Private  Round barrow 350m south west of Moor F Scheduled Monument (No. 1013545)	CONTACT:	Declining		
Private  Round barrow 350m south west of Moor F Scheduled Monument (No. 1013545)		Keith Emerick 01904 601988		
Scheduled Monument (No. 1013545)	House Farm, Hovi			
,		ngham		
,	CONDITION:	Extensive significant problems		
	TREND:	Declining		
Private	CONTACT:	Keith Emerick 01904 601988		
Round barrow 400m ESE of Theaker Waster's Spring, Hovingham				
Scheduled Monument (No. 1013553)	CONDITION:	Generally satisfactory but with significant localised problems		
Forestry	TREND:	Declining		
Private	CONTACT:	Keith Emerick 01904 601988		
Round harrow 500m NNW of Moor House	Farm Hovingha	m		
	-			
scheduled Monument (No. 101354/)	CONDITION:	Generally satisfactory		
Egypetry		but with significant localised problems		
•		Declining Keith Emerick 01904 601988		
rrivate	CONTACT:	Keith Emerick 01904 601988		
Round barrow 700m north of Moor House	Farm, Hovinghan	n		
Scheduled Monument (No. 1013546)	CONDITION:	Generally satisfactory but with significant localised problems		
Forestry	TREND:	Declining		
Private	CONTACT:	Keith Emerick 01904 601988		
Medieval moated site 150m south east of Lo	ow Hutton Post C	Office, Huttons Ambo		
Scheduled Monument (No. 1014384)	CONDITION	Generally satisfactory		
Scheduled Floridinent (Fig. 1011501)	CONDITION.	but with minor localised problems		
Moderate stock erosion	TREND:	Improving		
Private	CONTACT:	Keith Emerick 01904 601988		
Two round barrows I/2 mile (800m) north	east of Duggleby	High Barn, Kirby Grindalythe		
, ,		Extensive significant problems		
,		Declining		
		Keith Emerick 01904 601988		
Tivate	CONTACT:	Rolat Efficient 01701 001700		
Moated site known as Vivers Hill Castle, 30	0m north east of	the parish church, Kirkbymoorside		
Scheduled Monument (No. 1015811)	CONDITION:	Generally satisfactory but with significant localised problems		
Moderate stock erosion	TREND:	Declining		
Private	CONTACT:	Keith Emerick 01904 601988		
Starfits round barrow, 450m north east of S	Starfits House, Kir	rkbymoorside		
Scheduled Monument (No. 1015810)	CONDITION:	Extensive significant problems		
Arable ploughing	TREND:	Declining		
		Keith Emerick 01904 601988		
	Forestry Private  Round barrow 500m NNW of Moor House Scheduled Monument (No. 1013547)  Forestry Private  Round barrow 700m north of Moor House Scheduled Monument (No. 1013546)  Forestry Private  Medieval moated site I50m south east of Lo Scheduled Monument (No. 1014384)  Moderate stock erosion Private  Two round barrows I/2 mile (800m) north Scheduled Monument (No. 1004165) Arable ploughing Private  Moated site known as Vivers Hill Castle, 300 Scheduled Monument (No. 1015811)  Moderate stock erosion Private  Starfits round barrow, 450m north east of Scheduled Monument (No. 1015810)	Forestry Private  Round barrow 500m NNW of Moor House Farm, Hovingham Scheduled Monument (No. 1013547)  Forestry Private  Round barrow 700m north of Moor House Farm, Hovingham Scheduled Monument (No. 1013546)  Condition:  Round barrow 700m north of Moor House Farm, Hovingham Scheduled Monument (No. 1013546)  Forestry Private  Contact:  Medieval moated site 150m south east of Low Hutton Post Of Scheduled Monument (No. 1014384)  Moderate stock erosion Private  Two round barrows 1/2 mile (800m) north east of Duggleby Scheduled Monument (No. 1004165)  Arable ploughing Private  Contact:  Moated site known as Vivers Hill Castle, 300m north east of Scheduled Monument (No. 1015811)  Moderate stock erosion Private  Contact:  Starfits round barrow, 450m north east of Starfits House, Kin Scheduled Monument (No. 1015810)  Condition:		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Roman villa, Langton		
DESIGNATION:	Scheduled Monument (No. 1004884)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Esh's round barrow: a long barrow and late	r bowl barrow 40	0m north of Cross Thorns Barn, Lutton
DESIGNATION:	Scheduled Monument (No. 1011576)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Long barrow 650m south east of Cross The	orns Barn, Luttons	
DESIGNATION:	Scheduled Monument (No. 1011575)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private		Keith Emerick 01904 601988
OWNER TYPE:	FIIVate	CONTACT:	Reful Efferick 01704 601700
SITE NAME:	Round barrow I/4 mile (400m) north west	of Broom House,	Luttons
DESIGNATION:	Scheduled Monument (No. 1004114)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Three bowl barrows 200m west of Belle Vu	e Farm, Luttons	
DESIGNATION:	Scheduled Monument (No. 1011514)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	D. C.M.		
SITE NAME:	Roman fort, Malton		
DESIGNATION:	Scheduled Monument (No. 1004885)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND.	Declining
	Private	TREND:	Keith Emerick 01904 601988
OWNER TYPE:	FTIVALE	CONTACT:	Reful Efficience 01704 601700
SITE NAME:	Middleton Heights round barrow, Middleton	า	
DESIGNATION:	Scheduled Monument (No. 1003258)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Black Howe round barrow, Newton		
DESIGNATION:	Scheduled Monument (No. 1019777)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Beacon Hill ringwork siege castle and Roya	l Observer Corps	post, Pickering
DESIGNATION:	Scheduled Monument (No. 1019091)	CONDITION:	Generally unsatisfactory
	36.1000.00 1.311diffolio (1.30.1017071)	CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Emerick 01904 601988
	5 4.0	COIVIACI.	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

ABBREVIATIONS IATIONS
Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site

SITE NAME:	Round barrow 140m west of Haugh Rigg, Pi	ckering	
DESIGNATION:	Scheduled Monument (No. 1020230)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 280m south west of Haugh	Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No. 1019781)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 400m north east of Haugh F	Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No. 1019778)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 570m south of Saintoft Grai	nge, Pickering	
DESIGNATION:	Scheduled Monument (No. 1020115)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 600m SSW of Saintoft Gran	ge, Pickering	
DESIGNATION:	Scheduled Monument (No. 1020114)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Iron Age barrow cemetery, East Field, Rilling	gton	
DESIGNATION:	Scheduled Monument (No. 1004072)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Moated site and ridge and furrow cultivation	n 230m south eas	et of Manor Farm, Scackleton
DESIGNATION:	Scheduled Monument (No. 1015491)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
	D d b	on	
SITE NAME:	Round barrow on Knapton Brow, Scampsto		
	Scheduled Monument (No. 1004109)	CONDITION:	Extensive significant problems
DESIGNATION:	· ·	CONDITION: TREND:	Extensive significant problems Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No. 1004109)		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1004109) Arable ploughing Private  Part of Leppington medieval village,	TREND: CONTACT:	Declining Keith Emerick 01904 601988
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1004109) Arable ploughing Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988  en, Scrayingham Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1004109) Arable ploughing Private  Part of Leppington medieval village, a moated site and site of the former parish	TREND: CONTACT:  church of St Hele	Declining Keith Emerick 01904 601988 en, Scrayingham

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### ABBREVIATIONS

	Round barrow I/2 mile (800m) NNE of Set	ttrington House, S	ettrington	
DESIGNATION:	Scheduled Monument (No. 1004159)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow I/4 mile (400m) south west	of Many Thorns F	arm, Settrington	
DESIGNATION:	Scheduled Monument (No. 1004160)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow north east of Lawson's Wold Barn, Sherburn			
DESIGNATION:	Scheduled Monument (No. 1003140)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Three round barrows south of Prodham's \	Nold Farm. Sherbu	ırn	
DECICALATION	Scheduled Monument (No. 1004089)	,	Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	CONDITION: TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
OWNER TIPE.	Tilvace	CONTACT.	Return Emerick 01701 001700	
SITE NAME:	Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th		n Birdsall Wold,	
DESIGNATION:	Scheduled Monument (No. 1007483)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Aldro earthworks: a bowl barrow on Birds	all Wold, 500m no	rth west of Brown Moor Farm,Thixenda	
SITE NAME: DESIGNATION:		all Wold, 500m no		
	Scheduled Monument (No. 1007484)		rth west of Brown Moor Farm, Thixenda Extensive significant problems Declining	
DESIGNATION:		CONDITION:	Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang	CONDITION: TREND: CONTACT:  ing Grimston Wole	Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T	CONDITION: TREND: CONTACT:  ing Grimston Wole	Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496)	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale	Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale CONDITION:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing	CONDITION: TREND: CONTACT:  ing Grimston Woldenberg Condition: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall	CONDITION: TREND: CONTACT:  ing Grimston Woldenberg Condition: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale CONDITION: TREND: CONTACT:  Wold, 200m west	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale CONDITION: TREND: CONTACT:  Wold, 200m west	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale Generally unsatisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall Scheduled Monument (No. 1007485)	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale CONDITION: TREND: CONTACT:  Wold, 200m west CONDITION:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall Scheduled Monument (No. 1007485)  Scrub / tree growth	CONDITION: TREND: CONTACT:  ing Grimston Wolk hixendale  CONDITION: TREND: CONTACT:  Wold, 200m west  CONDITION: TREND:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale Generally unsatisfactory with major localised problems Declining	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall Scheduled Monument (No. 1007485)  Scrub / tree growth Private  Barrow near Middle Plantation, Thixendale	CONDITION: TREND: CONTACT:  ing Grimston Wolk hixendale  CONDITION: TREND: CONTACT:  Wold, 200m west  CONDITION: TREND:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1007484) Arable ploughing Private  Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm, T Scheduled Monument (No. 1007496) Arable ploughing Private  Aldro earthworks: a cross-dyke on Birdsall Scheduled Monument (No. 1007485)  Scrub / tree growth Private	CONDITION: TREND: CONTACT:  ing Grimston Woldhixendale CONDITION: TREND: CONTACT:  Wold, 200m west CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  d  Extensive significant problems Declining Keith Emerick 01904 601988  of Brown Moor Farm, Thixendale Generally unsatisfactory with major localised problems Declining	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Barrow west of Bradeham Farm, Thixendale	•	
DESIGNATION:	Scheduled Monument (No. 1004170)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl ba	rrow 200m west	of Wold Farm,Thixendale
DESIGNATION:	Scheduled Monument (No. 1007920)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl ba	rrow 300m east o	of Stone Sleights Farm, Thixendale
designation:	Scheduled Monument (No. 1007906)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl ba	rrow 400m south	west of Wold Farm, Thixendale
DESIGNATION:	Scheduled Monument (No. 1007985)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private Producting Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl ba	rrow 450m north	east of Wold Farm, Thixendale
DESIGNATION:	Scheduled Monument (No. 1007982)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Hanging Grimston barrow group: a bowl ba	rrow 650m south	west of Thixendale Grange, Thixendale
DESIGNATION:	Scheduled Monument (No. 1008481)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
TNINCII AL VOLINLIVABILITI.	Private	CONTACT:	Keith Emerick 01904 601988
	rrivate		
OWNER TYPE:	Hanging Grimston barrow group: a long ba		
OWNER TYPE:	Hanging Grimston barrow group: a long bai		e
OWNER TYPE: SITE NAME:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear bo Scheduled Monument (No. 1007922)		e Extensive significant problems
OWNER TYPE: SITE NAME: DESIGNATION:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922)  Arable ploughing	oundary,Thixendal	e Extensive significant problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear bo Scheduled Monument (No. 1007922)	oundary, Thixendal	e Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL YULNERABILITY:  OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922)  Arable ploughing	coundary, Thixendal  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendale	coundary, Thixendal  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922)  Arable ploughing  Private  Hanging Grimston barrow group: four bowh 600m SSW of Thixendale Grange, Thixendale Scheduled Monument (No. 1008484)	coundary, Thixendal  condition:  TREND:  CONTACT:  I barrows and parile	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendale	condary, Thixendal  condition:  TREND:  CONTACT:  I barrows and parile  CONDITION:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922)  Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484)  Arable ploughing Private	condary, Thixendal  condition:  TREND:  CONTACT:  I barrows and par le  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendale Scheduled Monument (No. 1008484) Arable ploughing Private	condary, Thixendal CONDITION: TREND: CONTACT:  I barrows and parele CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: DESIGNATION:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484) Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474)	condary, Thixendal  CONDITION:  TREND:  CONTACT:  I barrows and parele  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  eby Stoop, Thixendale Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  DESIGNATION: PRINCIPAL VULNERABILITY:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922)  Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484)  Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474)  Arable ploughing	condary, Thixendal  CONDITION:  TREND:  CONTACT:  I barrows and parele  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  Seby Stoop, Thixendale Extensive significant problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  DESIGNATION: PRINCIPAL VULNERABILITY:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484) Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474)	condary, Thixendal  CONDITION:  TREND:  CONTACT:  I barrows and parele  CONDITION:  TREND:  CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  eby Stoop, Thixendale Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both scheduled Monument (No. 1007922)  Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484)  Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474)  Arable ploughing	condary, Thixendal CONDITION: TREND: CONTACT:  I barrows and parele  CONDITION: TREND: CONTACT:  I barrows on Uncl CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  leby Stoop, Thixendale Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  SITE NAME:  OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484) Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474) Arable ploughing Private	condary, Thixendal CONDITION: TREND: CONTACT:  I barrows and parele  CONDITION: TREND: CONTACT:  I barrows on Uncl CONDITION: TREND: CONTACT:	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  leby Stoop, Thixendale Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Hanging Grimston barrow group: a long bar incorporating part of a prehistoric linear both Scheduled Monument (No. 1007922) Arable ploughing Private  Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixendal Scheduled Monument (No. 1008484) Arable ploughing Private  Hanging Grimston barrow group: four bow Scheduled Monument (No. 1008474) Arable ploughing Private  Hanging Grimston barrow group: three boy	condary, Thixendal CONDITION: TREND: CONTACT:  I barrows and parele  CONDITION: TREND: CONTACT:  I barrows on Uncl CONDITION: TREND: CONTACT:  VI barrows 350m	Extensive significant problems Declining Keith Emerick 01904 601988  t of a cross dyke  Extensive significant problems Declining Keith Emerick 01904 601988  eby Stoop, Thixendale Extensive significant problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

Arable ploughing movements Private Round barrow north of manor house, Thixendale Scheduled Monument (No. 1004128) CONDICE BERNALE ROUND BARROWS South east of Gill's Farm, Thixendale CONDICE	SITE NAME:	Hanging Grimston barrow group: three boy	vl barrows 600m	south west of Thixendale Grange, Thixe
Description  Private  Round barrow north of manor house, Thixendale  DESCANDON  Scheduled Monument (No. 1004128)  Description  Recombination	DESIGNATION:	Scheduled Monument (No. 1008483)	CONDITION:	Extensive significant problems
Round barrow north of manor house, Thixendale  Scheduled Monument (No. 1004128)  Thixensensensensensensensensensensensensense	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Scheduled Monument (No. 1004128) control Extensive significant problems prescrive with major localised problems ownstrine.  Private Control Keith Emerick 01904 601988  Set NAME Round barrow south east of Gill's Farm. Thizendale  Scheduled Monument (No. 1004537) control Extensive significant problems prescrive vulnerature.  Arable ploughing revolution of Gill's Farm. Thizendale  Scheduled Monument (No. 1004149) control Generally satisfactory but with significant localised problems provide with significant localised problems.  Scheduled Monument (No. 1004149) control Generally satisfactory but with significant localised problems.  Scheduled Monument (No. 1004149) control Keith Emerick 01904 601988  Streams Round barrows south west of Riggs Farm, Thizendale  Streams Round barrows south west of Riggs Farm, Thizendale  Scheduled Monument (No. 1004554) control Extensive significant problems.  Scheduled Monument (No. 1004554) control Extensive significant problems.  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thizendale  Scheduled Monument (No. 1007919) control Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thizendale  Scheduled Monument (No. 1007919) control Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thizendale  Scheduled Monument (No. 1007919) control Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thizendale  Scheduled Monument (No. 100498) report of control Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thizendale  Scheduled Monument (No. 100498) report of control Keith Emerick 01904 601988  Scheduled Monument (No. 100498) report of control Keith Emerick 01904 601988  Scheduled Monument (No. 1003141) control Keith Emerick 01904 601988  Scheduled Monument (No. 1003141) control Keith Emerick 01904 601988  Scheduled Monument (No. 1003141) control Keith Emerick 01904 601988  Scheduled Monument (No. 1003141) control Keith Emerick 0190	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
Arable ploughing Private Declining Contract: Keth Emerick 01904 601988  Arable ploughing Private Private Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable dipping TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable ploughing TREND: Declining Contract: Keth Emerick 01904 601988  Arable Declining Contract: Keth Emerick 01904 601988  Arable Declining Contract: Keth Emerick 01904 601988	SITE NAME:	Round barrow north of manor house, Thix	endale	
OWNERTIFE Private CORPACT: Keith Emerick 01904 601988  STET NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION Scheduled Monument (No. 1004537) CONDITION: Extensive significant problems  PRIVATE CONTROL Keith Emerick 01904 601988  WIS NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION Scheduled Monument (No. 1004149) CONDITION: Generally satisfactory but with significant localised problems  PRIVATE CONTROL VALIBRABILITY Analyse ploughing TIBND Declining  CONDITION: Keith Emerick 01904 601988  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1004554) CONDITION: Keith Emerick 01904 601988  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1004554) CONDITION: Keith Emerick 01904 601988  STE NAME: DESIGNATION: Arable ploughing TIBND. Declining  CONDITION: Keith Emerick 01904 601988  STE NAME: The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1007919) CONDITION: Generally unsatisfactory with major localised problems  PRIVATE CONTROL: Keith Emerick 01904 601988  STE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Keith Emerick 01904 601988  STE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRIVATE CONTROL: Keith Emerick 01904 601988  STE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRIVATE CONTROL: Keith Emerick 01904 601988  STE NAME: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRIVATE CONTROL: Keith Emerick 01904 601988  STE NAME: Scheduled Monument (No. 1003141) CONDITION: Generally unsatisfactory with major localised problems  Declining  DECLINION: CONDITION: Generally unsatisfactory with major localised problems  DESIG	DESIGNATION:	Scheduled Monument (No. 1004128)	CONDITION:	Extensive significant problems
Round barrow south east of Gill's Farm, Thixendale  BISCONDITION  Scheduled Monument (No. 1004537)  CONDITION  Arable ploughing  TREND:  Declining  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  Scheduled Monument (No. 1004149)  CONDITION:  Scheduled Monument (No. 1004149)  CONDITION:  Scheduled Monument (No. 1004149)  CONDITION:  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  Arable ploughing  TREND:  Declining  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  ROUND Barrows south west of Riggs Farm, Thixendale  DESCONDITION:  ROUND BARROWS  BISCONDITION:  CONTEXT:  Reith Emerick 01904 601988  BISCONDITION:  CONTEXT:  Reith Emerick 01904 601988  BISCONDITION:  CONTEXT:  FRECENAL NATIONALITY  Arable ploughing  TREND:  Declining  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  CONTEXT:  Reith Emerick 01904 601988  BISCONDITION:  THEND:  Declining  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  THEND:  Declining  CONTEXT:  Keith Emerick 01904 601988  BISCONDITION:  TRENDITION OF TRENDI	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Scheduled Monument (No. 1004537)  CONDIDENT  REVENDANCE  Round barrows south of Gill's Farm, Thixendale  DESCRIPTION  Scheduled Monument (No. 1004149)  CONDIDENT  Revendance  Round barrows south of Gill's Farm, Thixendale  DESCRIPTION  Scheduled Monument (No. 1004149)  CONDIDENT  Revendance  Revendance  Round barrows south west of Riggs Farm, Thixendale  Description  Revendance  Round barrows south west of Riggs Farm, Thixendale  Scheduled Monument (No. 1004554)  CONDIDENT  Revendance  Round barrows south west of Riggs Farm, Thixendale  Description  Scheduled Monument (No. 1004554)  CONDIDENT  Revendance  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESCRIPTION  Scheduled Monument (No. 1007919)  CONDIDENT  Revendance  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESCRIPTION  Scheduled Monument (No. 1007919)  CONDIDENT  Revendance  Revenda	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
PRINCE VALUERABULTY: Arable ploughing Private CONTACT Keth Emerick 01904 601988  STEINAME ROUND BATTOWN SOUTH OF GILL'S FARM, Thixendale  SCHEDULAR MARITY: Arable ploughing TIRRED Declining  CONTACT: Keth Emerick 01904 601988  STEINAME: ROUND BATTOWN SOUTH WEST OF RIGGS FARM, Thixendale  DESIGNATION SCHEDULAR MARITY: Arable ploughing TIRRED Declining  CONTACT: Keith Emerick 01904 601988  STEINAME: ROUND BATTOWN SOUTH WEST OF RIGGS FARM, Thixendale  DESIGNATION SCHEDULAR MARITY: Arable ploughing TIRRED Declining  CONTACT: Keith Emerick 01904 601988  THEND DECLINING  CONTACT: Keith E	SITE NAME:	Round barrow south east of Gill's Farm,Th	ixendale	
PRINCE VALUE PROBLEM Private CONTROL Private CONTROL Private Reith Emerick 01904 601988  STEINAME ROUND BATTOWN SOUTH OF GILLS FARM, Thisendale  SCHEDULE MATERIAL PROBLEM PRIVATE ROUND BATTOWN SOUTH OF GILLS FARM, THISEND DECIDING CONTROL STEINAME ROUND BATTOWN SOUTH WEST OF RIGGS FARM, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE PRIVATE  THE DO DECIDING CONTROL REITH FRENCH VALUE PRIVATE PRIVATE  DESIGNATION SCHEDULE PRIVATE PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE  PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE  PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE  PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  DESIGNATION SCHEDULE PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  THE QUEEN DIRE: part of a cross-dyke 600m east of Wold Farm, Thisendale  DESIGNATION SCHEDULE PRIVATE  THE QUEEN DIRECT PRIVATE  THE DO CONTROL  Reith Emerick 01904 601988  THE NO. CONTROL  REITH PRIVATE  REITH PRIV	DESIGNATION:	Scheduled Monument (No. 1004537)	CONDITION:	Extensive significant problems
Round barrows south of Gill's Farm, Thixendale  DESCNATION:  Scheduled Monument (No. 1004149)  CONDITION  Generally satisfactory but with significant localised problems  Declining  Private  CONTECT  Keith Emerick 01904 601988  STEINAME  ROUND Barrows south west of Riggs Farm, Thixendale  DESCNATION:  Scheduled Monument (No. 1004554)  CONDITION  Arable ploughing  TREND  Declining  Development  Private  CONTECT  Keith Emerick 01904 601988  STEINAME  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESCNATION:  Scheduled Monument (No. 1007919)  CONDITION  Generally unsatisfactory with major localised problems  Private  Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1004098)  GENERALLY  Arable ploughing  TREND  Declining  OWNERTIPE:  Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1004098)  CONDITION  Extensive significant problems  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1003141)  CONDITION  Extensive significant problems  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1003141)  CONDITION  Extensive significant problems  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1003141)  CONDITION  Extensive significant problems  Private  CONTECT:  Keith Emerick 01904 601988  Stensive significant problems  Private  CONTECT:  Keith Emerick 01904 601988  Declining  OWNERTIPE:  Round barrow north west of Mount Spaniel, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1003141)  CONDITION  Extensive significant problems  Private  CONTECT:  Keith Emerick 01904 601988  Declining  OWNERTIPE:  Round Barrow north west of Mount Spaniel, Weaverthorpe  DESCNATION:  Scheduled Monument (No. 1003141)  CONDITION  Extensive Significant problems  Private  CONTECT:  Keith Emerick 01904 601988  Declining  OWNERTIPE:  Declining  OWNERTIPE:  Declining  OWNERTIPE:  Dec	PRINCIPAL VULNERABILITY:		TREND:	- '
Scheduled Monument (No. 1004149)  Scheduled Monument (No. 1004149)  Scheduled Monument (No. 1004149)  Scheduled Monument (No. 1004149)  Scheduled Monument (No. 1004594)  Scheduled Monument (No. 1007919)  Scheduled Monument (No. 1004098)  Scheduled Monument (No. 1003141)  Schedu	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
Dut with significant localised problems PRINCIPAL VALINERABILITY: Arable ploughing TREND: Declining CONNERTYPE: Private CONTACT: Keith Emerick 01904 601988  STEINAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1004554) CONTACT: Keith Emerick 01904 601988  TREND: Declining CONTACT: Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1007919) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VALUERABILITY: Arable clipping TREND: Declining CONTACT: Keith Emerick 01904 601988  STEINAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems  PRINCIPAL VALUERABILITY: Arable ploughing TREND: Declining CONNERTYPE: Private CONTACT: Keith Emerick 01904 601988  STEINAME: Round barrow morth west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRINCIPAL VALUERABILITY: Arable ploughing TREND: Declining  CONTACT: Keith Emerick 01904 601988  STEINAME: Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRINCIPAL VALUERABILITY: Arable ploughing TREND: Declining  CONNERTYPE: Private  Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRINCIPAL VALUERABILITY: Arable ploughing TREND: Declining  CONNERTYPE: Private  Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VALUERABILITY: Arable clipping TREND: Declining  DECLINITION: With major localised problems	SITE NAME:	Round barrows south of Gill's Farm, Thixen	dale	
Arable ploughing TREND: Declining OWNERTPRE: Private  Round barrows south west of Riggs Farm, Thixendale DESIGNATION: Scheduled Monument (No. 1004554) CONDITION: Extensive significant problems PRINCIPAL Arable ploughing TREND: Declining OWNERTPRE: Private  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument (No. 1007919) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL Arable clipping TREND: Declining OWNERTPRE: Private  Round barrow east of Weaverthorpe Ling, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Keith Emerick 01904 601988  STE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems PRINCIPAL VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Private  Round barrow north west of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Round barrow north west of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Private  Scection of linear earthwork in Pasture Plantation, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1007864)  SCHEDULAR VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Scheduled Monument (No. 1007864)  SCHEDULAR VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Scheduled Monument (No. 1007864)  SCHEDULAR VILLIERABILITY: Arable ploughing TREND: Declining OWNERTPRE: Scheduled Monument (No. 1007864)  DESIGNATION: Arable clipping TREND: Declining OWNERTPRE: Scheduled Monument (No. 1007864)  DECLIDING OWNERTPRE: Scheduled Monument (No. 1007864)  DECLIDING OWNERTPRE: Scheduled Monument (No. 1007864)  DECLIDING OWNERTPRE: Decliping	DESIGNATION:	Scheduled Monument (No. 1004149)	CONDITION:	, , , , , , , , , , , , , , , , , , , ,
ROUND BATTOPHE ROUND BATTOWN SOUTH WEST OF Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1004554) CONDITION: Extensive significant problems PRINCER VALNERABLITY: Arable ploughing TEND: Declining CONNERT PRINCE Private  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument (No. 1007919) CONDITION: Generally unsatisfactory with major localised problems PRINCEPAL VALNERABLITY: Arable clipping TREND: Declining CONNERT PRIVE  ROUND BATTOWN East of Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) STEINAME: ROUND BATTOWN East of Weaverthorpe Ling, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems PRINCEPAL VALNERABLITY: Arable ploughing TREND: Declining CONNERT PRIVE  ROUND BATTOWN East of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCEPAL VALNERABLITY: Arable ploughing TREND: Declining CONNERT PRIVE  ROUND BATTOWN NOTH WEST Of MOUNT Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCEPAL VALNERABLITY: Arable ploughing TREND: Declining CONNERT PRIVE  Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCEPAL VALNERABLITY: Arable ploughing TREND: Declining CONNERT PRIVE  Section of linear earthwork in Pasture Plantation, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems PRINCEPAL VALNERABLITY: Arable clipping TREND: Declining	PRINICIPAL VI II NIERARII ITY:	Arable plaughing	TRENID:	
Round barrows south west of Riggs Farm, Thixendale  DESCRIATION:  Scheduled Monument (No. 1004554)  CONDITION:  Arable ploughing  TREND: Declining  OWNERTYPE:  Private  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESCRIATION: Scheduled Monument (No. 1007919)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VALIABRABILITY: Arable clipping  TREND: Declining  OWNERTYPE:  Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESCRIATION: Scheduled Monument (No. 1004098)  CONDITION: Extensive significant problems  PRINCIPAL VALIABRABILITY: Arable ploughing  TREND: Declining  OWNERTYPE: Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESCRIATION: DESCRIATION: DESCRIATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  PRIVATE: CONTACT: Keith Emerick 01904 601988  STIE NAME: ROUND barrow north west of Mount Spaniel, Weaverthorpe  DESCRIATION: DESCRIATION: DESCRIATION: DESCRIATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRIVATE: CONTACT: Keith Emerick 01904 601988  STIE NAME: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRIVATE: CONTACT: Keith Emerick 01904 601988  STIE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESCRIATION: DESCRIATION: Scheduled Monument (No. 1007864) CONDITION: With major localised problems  PRIVATE: Arable clipping TREND: Declining  TREND: DEClining		·		9
Scheduled Monument (No. 1004554)  Scheduled Monument (No. 1004554)  Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  THE Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument (No. 1007919)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABUTY: Arable clipping  TREND: Declining  CONTACT: Keith Emerick 01904 601988	OVVINER I IFE:	Tivate	CONTACT:	Retur Linerick 0170 F 001700
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Keith Emerick 01904 601988  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument (No. 1007919) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining OWNER TYPE Private CONTACT: Keith Emerick 01904 601988  STE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Keith Emerick 01904 601988  STE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Keith Emerick 01904 601988  STE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	SITE NAME:	Round barrows south west of Riggs Farm, 7	<sup>-</sup> hixendale	
Private  The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESIGNATION:  Scheduled Monument (No. 1007919)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  TREND: Declining  OWNERTYPE  Private  Round barrow east of Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1004098)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTYPE  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  CONTACT: Keith Emerick 01904 601988  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTYPE  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTYPE  Private  Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: DESIGNATION: Scheduled Monument (No. 1007864)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1004554)	CONDITION:	Extensive significant problems
The Queen Dike: part of a cross-dyke 600m east of Wold Farm, Thixendale  DESIGNATION:  Scheduled Monument (No. 1007919)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  TREND: Declining  OWNERTIYPE  Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1004098)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTIYPE  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTIYPE  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTIYPE  Private  Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DESIGNATION:  Scheduled Monument (No. 1007919)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  TREND: Declining  CONTACT: Keith Emerick 01904 601988  SITE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1004098)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  SITE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: DESIGNATION: Scheduled Monument (No. 1007864)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  TREND: Declining	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Round barrow east of Weaverthorpe Ling, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNER TYPE DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	SITE NAME:	The Queen Dike: part of a cross-dyke 600r	n east of Wold Fa	rm,Thixendale
Round barrow east of Weaverthorpe Ling, Weaverthorpe  Scheduled Monument (No. 1004098)  STE NAME:  Round barrow east of Weaverthorpe Ling, Weaverthorpe  Scheduled Monument (No. 1004098)  CONDITION:  Extensive significant problems  Declining  OWNER TYPE  Private  CONTACT:  Keith Emerick 01904 601988  STE NAME:  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION:  Scheduled Monument (No. 1003141)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Keith Emerick 01904 601988  STE NAME:  Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION:  Scheduled Monument (No. 1007864)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  TREND:  Declining	DESIGNATION:	Scheduled Monument (No. 1007919)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
SITE NAME:  Round barrow east of Weaverthorpe Ling, Weaverthorpe  DESIGNATION:  Scheduled Monument (No. 1004098)  CONDITION:  Arable ploughing  OWNERTYPE:  Private  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION:  Scheduled Monument (No. 1003141)  DESIGNATION:  Scheduled Monument (No. 1003141)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNERTYPE:  Private  Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION:  Scheduled Monument (No. 1007864)  STE NAME:  Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION:  Arable clipping  TREND:  Declining  TREND:  Declining  Declining  TREND:  Declining  TREND:  Declining	PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DESIGNATION: Scheduled Monument (No. 1004098) CONDITION: Extensive significant problems PRINCIPAL VULNERABLITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABLITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABLITY: Arable clipping TREND: Declining	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	SITE NAME:	Round barrow east of Weaverthorpe Ling,	Weaverthorpe	
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	designation:	Scheduled Monument (No. 1004098)	CONDITION:	Extensive significant problems
Round barrow north west of Mount Spaniel, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1003141) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DESIGNATION: Scheduled Monument (No. 1003141) condition: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private contact: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) condition: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	SITE NAME:	Round barrow north west of Mount Spanie	l,Weaverthorpe	
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Keith Emerick 01904 601988  SITE NAME: Section of linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1003141)	CONDITION:	Extensive significant problems
OWNER TYPE: Private CONTACT: Keith Emerick 01904 601988  SECTION OF linear earthwork in Pasture Plantation, Weaverthorpe  DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	PRINCIPAL VULNERABILITY:		TREND:	
DESIGNATION: Scheduled Monument (No. 1007864) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	OWNER TYPE:		CONTACT:	Keith Emerick 01904 601988
with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	SITE NAME:	Section of linear earthwork in Pasture Plan	tation,Weavertho	rpe
PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1007864)	CONDITION:	•
	PRINCIPAL VULNERABII ITY:	Arable clipping	TREND:	
		· · · · · · · · · · · · · · · · · ·		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Two round barrows on Weaverthorpe Pasture, Weaverthorpe					
DESIGNATION:	Scheduled Monument (No. 1004097)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Two round barrows south east of Pasture I	arm, Weaverthor	pe			
DESIGNATION:	Scheduled Monument (No. 1004166) condition: Extensive significant problem					
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Round barrows on Wharram Percy Wold, V	Vharram				
DESIGNATION:	Scheduled Monument (No. 1004127)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Bowl barrow I I 00m west of High Fordon I	arm, Willerby				
DESIGNATION:	Scheduled Monument (No. 1007745)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Bowl barrow 700m north west of High For	don Farm, Willert	ру			
DESIGNIATION!	Scheduled Monument (No. 1007746)	CONDITION:	Extensive significant problems			
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Bowl barrow 800m west of High Fordon Fa	arm,Willerby				
DESIGNATION:	Scheduled Monument (No. 1007744)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
TE NAME:	Prior Moor round barrow, Willerby					
DESIGNATION:	Scheduled Monument (No. 1004106)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
ITE NAME:	Round barrow south east of Willerby Wold	l House,Willerby				
DESIGNATION:	Scheduled Monument (No. 1004112)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Round barrow west of Willerby Wold House, Willerby					
DESIGNATION:	Scheduled Monument (No. 1004107)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988			
SITE NAME:	Two round barrows north east of Ganton	Dale,Willerby				
	Scheduled Monument (No. 1004111)	CONDITION:	Extensive significant problems			
DESIGNATION:	Scrieduled Floridifient (140, 100 1111)	CONDINON				
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Two round barrows, Staxton Brow, Willerby				
DESIGNATION:	Scheduled Monument (No. 1004090)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Wilton Hall moated site 250m south of Ma	nor Farm,Wilton			
DESIGNATION:	Scheduled Monument (No. 1021269)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow I/4 mile (400m) south east of	of Newton South	Wold Farm, Wintringham		
DESIGNATION:	Scheduled Monument (No. 1003136)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow 330yds (300m) NNW of Lac	dyhills, Wintringha	m		
DESIGNATION:	Scheduled Monument (No. 1003135)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow north east of Wintringham	South Wold Farm	,Wintringham		
DESIGNATION:	Scheduled Monument (No. 1004163)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Round barrow west of Newlands Lane, Wir	ntringham			
DESIGNATION:	Scheduled Monument (No. 1004538)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Three round barrows on West Heslerton V	Vold, Wintringhan	1		
DESIGNATION:	Scheduled Monument (No. 1004110)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
L. F. St.	SITE NAME: Ebberston Hall, Ebberston and Yedingham	design of E	ith water features c1718 integral to bberston Hall and views of the wide		



DESIGNATION: Registered Park and Garden Grade II\*, also 5 LBs, 2 SMs Generally satisfactory CONDITION:

but with significant localised problems

vulnerability: Low Declining OWNER TYPE: Private, single owner landscape from it. Stepped cascade water features (listed grade II\*) in need of consolidation and repair, trees in parkland to south over-mature.

Contact: Andy Wimble 01904 601970

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site



Castle Howard, Henderskelfe SITE NAME:

DESIGNATION: Registered Park and Garden Grade I,

also 65 LBs, 2 SMs

Generally satisfactory CONDITION:

but with significant localised problems

vulnerability: Low Declining

OWNERTYPE: Private, single owner

Gardens, pleasure grounds and park with a mixture of geometric and less formal features developed c1698-1738 by Charles Howard, third Earl of Carlisle and Sir John Vanbrugh (1664-1726) possibly with some advice from Stephen Switzer (1682-1745). Key buildings and structures in the landscape are in need of consolidation and repair; sections of the grand approach avenues have over-mature trees in need of replacement.

Contact: Andy Wimble 01904 601970

Dovecote, probably C17. Believed to be the only

example in the country of a circular tiered dovecote. Building suffered partial collapse following heavy snowfall.

C12 Cistercian priory. Little remains of the priory except

a transplanted moorland cross. It is situated in the private

some sections of walling, part of the old parish church and

#### **SCARBOROUGH**



Dovecote at Cloughton Hall, SITE NAME:

High Street, Cloughton

DESIGNATION: Listed Building Grade II, SM, CA

Very bad CONDITION:


N/A OCCUPANCY: PRIORITY:

B (New entry) OWNER TYPE: Private

Contact: Keith Emerick 01904 601988

grounds of a large country house.

Contact: Neil Redfern 01904 601897



Wykeham Priory, SITE NAME:

Back Lane, Wykeham

Listed Building Grade II, SM DESIGNATION:

CONDITION: Poor N/A OCCUPANCY: D (D) PRIORITY: Private OWNER TYPE:




Church of St Martin. SITE NAME:

Main Street,

Seamer

Substantial C12 church with later medieval alterations. Nave roof poor and severe deterioration of south

walls. Grant offered for repair.



OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St John the Evangelist,

Baxtergate, Whitby

Early Victorian church with three parallel roofs. Slating in poor condition. Grant aided-repairs about to start.

DESIGNATION: Listed Place of Worship Grade II, CA

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981

### SITE NAME

#### Bowl barrow 700m north of Betton Farm, East Ayton

DESIGNATION:	Scheduled Monument (No. 1008128)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988

#### SITE NAME

### Bowl barrow 920m north of Betton Farm, East Ayton

DESIGNATION:	Scheduled Monument (No. 1008129)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

### ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS

SITE NAME:	Bowl barrow 950m north of Betton Farm, Ea	ast Ayton	
DESIGNATION:	Scheduled Monument (No. 1008130)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Roman signal station, Carr Naze, Filey		
DESIGNIATIONI	Scheduled Monument (No. 1004187)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Elf Howe round barrow, Folkton		
	,		F
DESIGNATION:	Scheduled Monument (No. 1004091)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Flixton Wold, Folkton		
DESIGNATION:	Scheduled Monument (No. 1004113)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow on Flotmanby Brow, Folkton		
DESIGNATION:	Scheduled Monument (No. 1004096)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
		001171011	Note: Emerica 97, 97, 997, 99
SITE NAME:	Round barrow on Flotmanby Wold, Folkton		
DESIGNATION:	Scheduled Monument (No. 1004095)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow south of Long Plantation, Folk	cton	
DESIGNATION:	Scheduled Monument (No. 1004539)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Sharpe Howes, round barrows, Folkton		
DESIGNATION:	Scheduled Monument (No. 1004182)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Two round barrows north west of Danebury	Manor, Folkton	
DESIGNATION:	Scheduled Monument (No. 1004092)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Group of circular and rectangular enclosures	s, near Cansdale	Whin, Hunmanby
	Scheduled Monument (No. 1004065)	CONDITION:	Extensive significant problems
DESIGNATION:	(1001000)	20.12111014	p
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Arable ploughing Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Round barrow south of Grange Farm, Hunr	manby	
DESIGNATION:	Scheduled Monument (No. 1004093)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 60m west of Beacon Farm, I	rton	
DESIGNATION:	Scheduled Monument (No. 1008476)	CONDITION:	Generally satisfactory
DESIGNATION.	scheduled Floridinent (140, 1000 170)	CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 450m north east of Moor Ho	use Farm, Scarboi	rough
DESIGNATION:	Scheduled Monument (No. 1008139)	CONDITION:	Generally unsatisfactory
	(		with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 600m north of Moor House F	Farm, Scarborough	1
DESIGNATION:	Scheduled Monument (No. 1008138)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Round barrow 460m south of Oliver's Mou	nt Farm, Scarboro	ough
DESIGNATION:	Scheduled Monument (No. 1021233)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Section of linear earthwork on Seamer Mod	or Hill, Scarborou	gh
DESIGNATION:	Scheduled Monument (No. 1008135)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	Government or Agency	CONTACT:	Keith Emerick 01904 601988
	Government or Agency	CONTACT:	Keith Emerick 01904 601988
OWNER TYPE:	Three barrows at Seamer Beacon and the r		ert's Tower, Scarborough
OWNER TYPE: SITE NAME:	<u> </u>		ert's Tower, Scarborough  Generally satisfactory
OWNER TYPE: SITE NAME:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)	ruins of Baron Alb	ert's Tower, Scarborough  Generally satisfactory  but with minor localised problems
OWNER TYPE:  SITE NAME:  DESIGNATION:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)	ruins of Baron Alb	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)	ruins of Baron Alb	ert's Tower, Scarborough  Generally satisfactory  but with minor localised problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)	condition:  TREND:  CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)  Plant growth Local Authority	condition:  TREND:  CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)  Plant growth Local Authority  Bowl barrow I50m north of Moor House F	condition:  TREND: CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three barrows at Seamer Beacon and the rescheduled Monument (No. 1008486)  Plant growth Local Authority  Bowl barrow I50m north of Moor House Feather Scheduled Monument (No. 1008133)	condition:  TREND: CONTACT:  carm, Seamer CONDITION:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining Keith Emerick 01904 601988  Extensive significant problems
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Three barrows at Seamer Beacon and the rescheduled Monument (No. 1008486)  Plant growth Local Authority  Bowl barrow I50m north of Moor House Feedbaled Monument (No. 1008133)  Arable ploughing	condition:  TREND: CONTACT:  Farm, Seamer  CONDITION: TREND: CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Three barrows at Seamer Beacon and the rescheduled Monument (No. 1008486)  Plant growth Local Authority  Bowl barrow I50m north of Moor House Feedballed Monument (No. 1008133)  Arable ploughing Private  Bowl barrow 450m north west of Moor House Feedballed Monument (No. 1008133)	condition:  TREND: CONTACT:  CONTACT:  CONDITION: TREND: CONTACT:  CONTACT:  CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Three barrows at Seamer Beacon and the r Scheduled Monument (No. 1008486)  Plant growth Local Authority  Bowl barrow I50m north of Moor House F Scheduled Monument (No. 1008133) Arable ploughing Private	condition:  TREND: CONTACT:  Farm, Seamer  CONDITION: TREND: CONTACT:	ert's Tower, Scarborough  Generally satisfactory but with minor localised problems Declining Keith Emerick 01904 601988  Extensive significant problems Declining Keith Emerick 01904 601988

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

SITE NAME:	Bowl barrow 550m NNW of Moor House	Farm, Seamer	
DESIGNATION:	Scheduled Monument (No. 1008136)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Bowl barrow 800m north west of Moor H	ouse Farm, Seamer	•
DESIGNATION:	Scheduled Monument (No. 1008137)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988
SITE NAME:	Dean Road / Manor Road Cemetery		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving significantly
CONTACT:	Chris Hall (LPA) 01723 232481	NEW ENTRY?:	Yes

#### **SELBY**



Chapel to Huddleston Hall (now barn), SITE NAME: west of house, Laith Staid Lane, Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\* Poor CONDITION: OCCUPANCY: Vacant C (C) PRIORITY: Private OWNER TYPE:

Redundant chapel with CI5 origins, CI6 rebuilding to the east and later alterations. The building is disused and the roof coverings are in poor repair, resulting in water ingress to the interior.

Contact: Giles Proctor 01904 601981



Huddleston Hall, SITE NAME: Laith Staid Lane,

Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\* Poor CONDITION:

Part occupied

C (C) PRIORITY-OWNER TYPE: Private

OCCUPANCY:

Late C16 manor house, now used as a farmhouse. The roofs are in poor condition resulting in water ingress to the interior, and there is some decaying stonework. A full repairs programme planned but work has not yet been carried out.

Contact: Giles Proctor 01904 601981



Stables to Huddleston Hall, SITE NAME: south east of house, Laith Staid Lane,

Huddleston with Newthorpe DESIGNATION: Listed Building Grade II\*

Fair CONDITION: Part occupied

PRIORITY: C (C) OWNERTYPE: Private

Stables of the late C16 with C19 additions and alterations. The roof coverings have some missing tiles.

Contact: Giles Proctor 01904 601981



Abbot's Staith Buildings, SITE NAME:

> Water Lane, Selby

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION:

Part occupied OCCUPANCY:

PRIORITY C (C) OWNER TYPE: Company

C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesium limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating.

Contact: Keith Emerick 01904 601988

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### **ABBREVIATIONS**

Conservation Area CA LB/LBs Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s LPA NP RPG SM/SMs Unitary Authority World Heritage Site UA WHS

SITE NAME:	St Andrew's College and moat, 440m north east of College Farm, Acaster Selby				
DESIGNATION:	Scheduled Monument (No. 1017457)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable		
OWNER TYPE:	Private	CONTACT: Keith Emerick 01904 601988			
SITE NAME:	Brocket Hall moated site, Appleton Roebuc	ck			
DESIGNATION:	Scheduled Monument (No. 1008228)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining		
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Mote Hill: a moated site, two fishponds and 500m west of Nun Appleton Hall, Appleton		nt field system		
DESIGNATION:	Scheduled Monument (No. 1008229)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Parkshaw moated site, 170m north west of	Wood Farm, Baln	e		
DESIGNATION:	Scheduled Monument (No. 1016025)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Catterton Hall moated site and adjacent bu	uilding platform, C	atterton		
DESIGNATION:	Scheduled Monument (No. 1017456)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Castle Hill moated site, 350m south of St P	eter and St Paul's	Church, Drax		
DESIGNATION:	Scheduled Monument (No. 1017455)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Scurff Hall moated site, Drax				
DESIGNATION:	Scheduled Monument (No. 1017485)	CONDITION:	Generally satisfactory but with minor localised problems		
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
	Kelfield moated site and fishpond, 180m no	rth of Kelfield Ch	urch, Kelfield		
SITE NAME:					
	Scheduled Monument (No. 1017459)	CONDITION:	Generally satisfactory but with minor localised problems		
DESIGNATION:	Scheduled Monument (No. 1017459)  Drainage/dewatering	CONDITION: TREND:	but with minor localised problems Stable		
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	, ,		but with minor localised problems		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS

SITE NAME:	Toulston medieval village, manor house site and early garden earthworks, Newton Kyme cum Toulston				
DESIGNATION:	Scheduled Monument (No. 1017922)	CONDITION:	Generally satisfactory		
			but with minor localised problems		
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Two Roman forts, two Roman camps, vicus				
	Bronze Age barrows and Neolithic henge n		, ,		
DESIGNATION:	Scheduled Monument (No. 1017693)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Danes Hills square barrow cemetery, 300m	south of Adamso	n Farm, Riccall		
DESIGNATION:	Scheduled Monument (No. 1018603)	CONDITION:	Generally unsatisfactory		
	Dland man th		with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable  Keith Freewick 01904 (01999)		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	York prebendary manor moated site, 300m	north west of Ha	wthorn Farm, Riccall		
DESIGNATION:	Scheduled Monument (No. 1018212)	CONDITION:	Generally satisfactory		
	D : //		but with minor localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Paradise Lodge moated site and grange of t	he Prior of Bolto	n, Ryther cum Ossendyke		
DESIGNATION:	Scheduled Monument (No. 1008225)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining		
OWNER TYPE:	Local Authority	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Thorpe Hall moated monastic grange, Selby	,			
DESIGNATION:	Scheduled Monument (No. 1017460)	CONDITION:	Generally satisfactory		
	Duning golden vatering		but with minor localised problems Unknown		
PRINCIPAL VULNERABILITY:	Drainage/dewatering Private	TREND:	Keith Emerick 01904 601988		
OWNER TYPE:	Tivate	CONTACT:	Reitif Efficience 01704 001700		
SITE NAME:	Danes Hills square barrow cemetery on Cr	ook Moor, Skipwi	th		
DESIGNATION:	Scheduled Monument (No. 1016619)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
SITE NAME:	Moated site and fishpond I 40m south of St	Helen's Church, S	Skipwith		
DESIGNATION:	Scheduled Monument (No. 1015543)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Improving		
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988		
OTTIVITE.	. 117460	COIVIACI.	. Column Elitication Color Color Color		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith				
DESIGNATION:	Scheduled	Monument (No. 1018604)	CONDITION:	Generally unsatisfactory	
				with major localised problems	
PRINCIPAL VULNERABILITY:	Plant grow	th	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith				
DESIGNATION:	Scheduled	Monument (No. 1018601)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth		TREND:	Declining	
DWNER TYPE:	Private		CONTACT:	Keith Emerick 01904 601988	
OWNER THE	TTIVACC		CONTROL.	Notal Emerick 91701 991799	
ITE NAME:	Round bar	row on Skipwith Common, 830m	south east of Ad	amson Farm, Skipwith	
DESIGNATION:	Scheduled	Monument (No. 1018605)	CONDITION:	Generally unsatisfactory	
				with major localised problems	
RINCIPAL VULNERABILITY:	Plant grow	th	TREND:	Declining	
DWNER TYPE:	Private		CONTACT:	Keith Emerick 01904 601988	
ITE NAME:	Steeton Hall medieval magnate's residence and manorial centre, South Milford				
DESIGNATION:	Scheduled	Monument (No. 1015504)	CONDITION:	Generally satisfactory	
				but with significant localised problems	
RINCIPAL VULNERABILITY:		development	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Steeton m	edieval village, moated site and fis	shponds, Steeton		
DESIGNATION:	Scheduled	Monument (No. 1017555)	CONDITION:	Generally satisfactory	
DESIGNATION:	ocheduled	1 Ionament (140. 1017333)	CONDITION:	but with significant localised problems	
RINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	Declining	
DWNERTYPE:	Private	ugning	CONTACT:	Keith Emerick 01904 601988	
OVVINER TIPE.	TTIVALC		CONTACT.	Nettr Effect 01701 001700	
ITE NAME:	Whitley T	horpe moated Templar grange site	e, 600m north we	st of Fulham House,Whitley	
DESIGNATION:	Scheduled	Monument (No. 1017458)	CONDITION:	Generally satisfactory	
				but with minor localised problems	
RINCIPAL VULNERABILITY:	Drainage/o	dewatering	TREND:	Stable	
OWNER TYPE:	Private		CONTACT:	Keith Emerick 01904 601988	
	SITE NAME:	Battle of Towton, Lead / Saxton with Scarthingwell / Towt	t <b>on</b> a ten-hour	arable land near Tadcaster was the scene of battle in March I 461 during the Wars of the 00 were said to have been killed. Still actively	
	DESIGNATION: Registered Battlefield		farmed and	I under the plough, the below-ground battlefic	
	DESIGNATION:			y – artefacts and arrowheads from the battle	
200 B	DESIGNATION: CONDITION:	Generally unsatisfactory			
ma.		· ·	has been co	onsistently targeted by metal detectorists, son	
		Generally unsatisfactory with major localised problems	has been co unauthorise archaeologi	onsistently targeted by metal detectorists, somed and working independently of any agreed ical survey. At least one episode of deep	
	CONDITION:	Generally unsatisfactory with major localised problems	has been co unauthorise archaeologi	onsistently targeted by metal detectorists, som	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### YORKSHIRE DALES (NP)



Barden Church, B6160, Barden,

Craven

DESIGNATION: Listed Building Grade I

Fair CONDITION: Vacant C(C)PRIORITY-

OWNERTYPE: Private

Redundant C16 chapel. The interior is derelict and there is some water penetration and damage. The chapel roof has been repaired but it remains vacant. An options appraisal has been undertaken with the Estate and Yorkshire Dales National Park Authority and is due for completion in June 2011.

Contact: Diane Green 01904 601973



Lead cupola, flue and chimney, SITE NAME:

Grassington, Craven

Scheduled Monument DESIGNATION:

CONDITION: N/A OCCUPANCY: D (D) PRIORITY: OWNERTYPE: Private Smelt mills, flues and chimney of a lead processing complex. Built in 1792. Some consolidation has been undertaken but the flue system is still in urgent need of repair. Grant-aided solution agreed and works to take place in Summer 2011.

Contact: Neil Redfern 01904 601897



Lodge Hall, Ingman Lodge Road, SITE NAME: Selside, Horton in Ribblesdale,

DESIGNATION: Listed Building Grade II\*

C (C)

Poor CONDITION: Occupied

Private OWNER TYPE:

PRIORITY

Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof reported to leak badly with attendant decay. Integral part of a working farm.



Nappa Hall, SITE NAME: Askrigg,

Richmondshire

DESIGNATION: Listed Building Grade CONDITION:

OCCUPANCY: Part occupied PRIORITY

F (F) OWNER TYPE: Private A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. There has recently been a change in ownership and some repairs have been carried out. However, the floors in the west tower are still in a rotten and dangerous state and the roof coverings over the great hall and the south east wing are in very poor condition.

Contact: Neil Redfern 01904 601897

Contact: Diane Green 01904 601973



Church of St Mary the Virgin, SITE NAME:

Arkengarthdale, Richmondshire

Early C19 church. Masonry now in good order. Grant-aided urgent window repair underway. Third phase of grant for re-roofing offered.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION:

PRIORITY: F (New entry)

Religious organisation OWNER TYPE:

Contact: Giles Proctor 01904 601981



SITE NAME:

Church of St Margaret, Gruel Street, Hawes, Richmondshire

1851 church with fine later furnishings. Roofs in poor condition, extensive repointing required, glazing poor.

DESIGNATION: Listed Place of Worship Grade II

Very bad CONDITION: PRIORITY C (New entry)

Religious organisation

Contact: Giles Proctor 01904 601981

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site

SITE NAME:	Large univallate hillfort on Ingleborough Hill, Clapham cum Newby, Craven			
DESIGNATION:	Scheduled Monument (No. 1008876)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining	
OWNER TYPE:	Private Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Kinsey Cave, Giggleswick Scar, Giggleswick, Craven			
DESIGNATION:	Scheduled Monument (No. 1010295)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
ITE NAME:	Multi-period lead mines and processing works and 20th century barytes mill on Grassington Moor, Grassington, Craven			
DESIGNATION:	Scheduled Monument (No. 1018333)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
ITE NAME:	Meal Bank Quarry Hoffmann kiln, quarry ar	nd lime works, Ing	leton, Craven	
	· · ·	-		
DESIGNATION:	Scheduled Monument (No. 1020889)	CONDITION:	Generally unsatisfactory with major localised problems	
DDINICIDAL VI II NED ADII ITV.	Collapse	TDENID:	Declining	
PRINCIPAL VULNERABILITY:  DWNER TYPE:	Local Authority	TREND: CONTACT:	Keith Emerick 01904 601988	
OVVINER TIFE.	Local / Additionity	CONTACT.	Reful Effected 01701 001700	
SITE NAME:	Victoria Cave, Langcliffe Scar, Langcliffe, Cra	ven		
DESIGNATION:	Scheduled Monument (No. 1010290)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
OWNER TYPE:	Government or Agency	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Bolton Parks Lead Mine and ore works, Castle Bolton with East and West Bolton, Richmondshire			
DESIGNATION:	Scheduled Monument (No. 1018712)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
	Extensive animal burrowing Private	TREND: CONTACT:	Declining Keith Emerick 01904 601988	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:		CONTACT:	Keith Emerick 01904 601988	
OWNER TYPE: SITE NAME:	Private  Sargill ore hearth lead smelt mill, on North	CONTACT:	Keith Emerick 01904 601988  ondshire  Generally unsatisfactory	
OWNER TYPE: ITE NAME:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)	CONTACT: Rigg, Abbotside, Richme	Keith Emerick 01904 601988  ondshire  Generally unsatisfactory  with major localised problems	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)  Collapse	CONTACT: Rigg, Abbotside, Richme	Neith Emerick 01904 601988  Condshire  Generally unsatisfactory  with major localised problems  Declining	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)	CONTACT:  Rigg, Abbotside, Richmo	Keith Emerick 01904 601988  ondshire  Generally unsatisfactory  with major localised problems	
OWNER TYPE:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)  Collapse	CONTACT:  Rigg, Abbotside, Richmo CONDITION:  TREND: CONTACT:	Neith Emerick 01904 601988  Condshire  Generally unsatisfactory  with major localised problems  Declining	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)  Collapse Private	CONTACT:  Rigg, Abbotside, Richmo CONDITION:  TREND: CONTACT:	Keith Emerick 01904 601988  condshire  Generally unsatisfactory with major localised problems Declining Keith Emerick 01904 601988  Generally satisfactory	
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Sargill ore hearth lead smelt mill, on North 340m south east of Sargill Lead Mine, High Scheduled Monument (No. 1018338)  Collapse Private  Marrick ore hearth lead smeltmill, Marrick,	Rigg, Abbotside, Richmo CONDITION: TREND: CONTACT: Richmondshire	Keith Emerick 01904 601988  Condshire  Generally unsatisfactory  with major localised problems  Declining  Keith Emerick 01904 601988	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Gunnerside Gill lead mines and ore works, Melbecks, Richmondshire			
DESIGNATION:	Scheduled Monument (No. 1015830)	CONDITION:	Generally unsatisfactory	
	Callagae		with major localised problems	
PRINCIPAL VULNERABILITY:	Collapse Private	TREND:	Declining Keith Emerick 01904 601988	
OWNER TYPE:	rrivate	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	Beldi Hill Low Level lead mine and ore works, Muker, Richmondshire			
DESIGNATION:	Scheduled Monument (No. 1015408)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Emerick 01904 601988	
SITE NAME:	West Stonesdale lead mine and ore works,	Muker, Richmond	shire	
DESIGNATION:	Scheduled Monument (No. 1015407)	CONDITION:	Extensive significant problems	
	0 "	TOTALD	Declining	
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Decilining	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Collapse Private	CONTACT:	Keith Emerick 01904 601988	
	•		8	
OWNERTYPE: SITE NAME:	Private		8	
OWNER TYPE:	Private Farfield Mill (Sedbergh)	CONTACT:	Keith Emerick 01904 601988	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Farfield Mill (Sedbergh)  Conservation Area	CONTACT:	Keith Emerick 01904 601988  Very bad	
OWNER TYPE:  SITE NAME:  DESIGNATION:  VULNERABILITY:	Private  Farfield Mill (Sedbergh)  Conservation Area Low	CONTACT:  CONDITION: TREND: NEW ENTRY?:	Keith Emerick 01904 601988  Very bad Deteriorating	
OWNER TYPE:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	Private  Farfield Mill (Sedbergh)  Conservation Area Low  Robert White (LPA) 01969 652360	CONTACT:  CONDITION: TREND: NEW ENTRY?:	Keith Emerick 01904 601988  Very bad Deteriorating	
OWNER TYPE:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:	Private  Farfield Mill (Sedbergh)  Conservation Area Low Robert White (LPA) 01969 652360  Swaledale and Arkengarthdale barns and wa	CONTACT:  CONDITION: TREND: NEW ENTRY?:	Keith Emerick 01904 601988  Very bad  Deteriorating  Yes	

# SOUTH YORKSHIRE BARNSLEY



SITE NAME: Grimethorpe Hall, Brierley Road,

Brierley

DESIGNATION: Listed Building Grade II\*

OCCUPANCY: Vacant
PRIORITY: C (C)
OWNER TYPE: Company

House, circa 1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is residential. The setting has been eroded by construction of housing to the west. Consent was granted for conversion to a restaurant in 2005, but the scheme has failed.

Contact: Tammy Whitaker 01904 601880



SITE NAME: Conservatory and linking bridge at north west corner of Wentworth Castle, Stainborough

DESIGNATION: Listed Building Grade II\*, CA, RPG I
CONDITION: Very bad
OCCUPANCY: Vacant

PRIORITY: D (D)

OWNER TYPE: Trust

Conservatory built in 1877, probably by Crompton and Fawkes, located immediately west of the house. The conservatory is situated in the early C18 formal gardens on the west side of the house. A support scaffold has been erected to prevent collapse. English Heritage grant has been offered towards the full repair of the conservatory.

Contact: Susan Daniels 01904 601979



SITE NAME: Gun Room,
Wentworth Castle,
Stainborough

DESIGNATION: Listed Building Grade II\*, CA, RPG I CONDITION: Fair

occupancy: Vacant priority: E (E) owner type: Trust Probably built as a banqueting house or a bath-house, it was used as a gun room in the C19. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006-07, but a further phase of conservation is required to the interior which is in very poor condition.

Contact: Tammy Whitaker 01904 601880

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site



Pillared barn approx SITE NAME: 20m south of Steeple Lodge, Stainborough

DESIGNATION: Listed Building Grade II\*, CA, RPG

CONDITION: Poor N/A OCCUPANCY:

B (New entry) PRIORITY:

Trust OWNER TYPE:

Dutch barn c1775, early of its type and of very unusual plan. A timber purlin has snapped, with consequent stressing of the roof structure. An English Heritage grant has been offered and works are due to be carried out in 2011.

Contact: Susan Daniels 01904 601979



Dovecote at Glebe Farm, SITE NAME: **Tankersley** 

DESIGNATION: Listed Building Grade II, SM

Very bad CONDITION: Vacant A(A)PRIORITY: Private

OWNER TYPE:

of the Glebe Farm for Richard Goodwin, Rector 1715-52. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes. In a state of serious disrepair with a temporary roof structure in place. Potential for low key use, ancillary to residential.

Stone built dovecote and cart shed, built in 1735 as part

Contact: Keith Miller 01904 601990



Low Forge, SITE NAME: Wortley

designation: Scheduled Monument

CONDITION: N/A OCCUPANCY: C(C)PRIORITY-Private OWNER TYPE:

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair.

Contact: Keith Miller 01904 601990



Church of St Peter SITE NAME:

including attached wall and gateway to south west, Brinckman Street


DESIGNATION: Listed Place of Worship Grade II\*

Poor CONDITION:

C (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Church and attached wall and gateway, 1893-1910 by Temple Moore. In generally good order; nave seems to have been re-slated. Slates to chancel roof look poor and there is salting brickwork to the Lady Chapel.





SITE NAME:

Church of St Peter, Harshaw Lane, Hoyland Nether

Church dating to 1830 from dressed limestone with a slate roof. Orientated northeast-southwest. Grant-aided repairs underway to spire and pinnacles.

DESIGNATION: Listed Place of Worship Grade II

CONDITION:

F (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Susan Daniels 01904 601979



SITE NAME:

Bull House Chapel, Manchester Road, Penistone

DESIGNATION: Listed Place of Worship Grade II

CONDITION:

D (New entry) PRIORITY:

OWNERTYPE: Religious organisation

Non-conformist chapel, previously Presbyterian and Methodist, dated to 1692. Simple, single-storey rectangular plan and constructed from coursed stone with a stone slate roof. The chapel lies in an isolated position outside the town, adjacent to the manor. The roof and ceiling

are in poor condition. Grant offered.

Contact: Susan Daniels 01904 601979

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site



Church of St John the Baptist, SITE NAME:

Church Street, Royston

DESIGNATION: Listed Place of Worship Grade I

CONDITION:

PRIORITY: F (New entry)

Religious organisation OWNER TYPE:

On the 4 April 1234, Archbishop Walter Gray appropriated the Church of Royston to the monks of Monk Bretton Priory. Alterations were made in the C14 and C15 with extensive alterations in the C19. Grant-aided repairs are underway to the tower, oriel and masonry.

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Helen, High Street,

Thurnscoe

Victorian church with Georgian Tower, rest rebuilt in 1887. Clay tiled roofs to nave and south east corner are in poor condition, although regularly repaired. Eroded stonework to porch.

DESIGNATION: Listed Place of Worship Grade II

PRIORITY: C (New entry)

Religious organisation OWNER TYPE:

Contact: Susan Daniels 01904 601979

SITE NAME:	East Gawber Hall colliery fanhouse, 800m north east of Croft Farm, Barnsley		
DESIGNATION:	Scheduled Monument (No. 1017748)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Elsecar Colliery Newcomen engine, Barnsle	у	
DESIGNATION:	Scheduled Monument (No. 1004790)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Heavy Anti-aircraft gunsite 330m south east of Lowfield Farm, Barnsley		
DESIGNATION:	Scheduled Monument (No. 1019872)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Monk Bretton standing cross, Barnsley		
SITE NAME:  DESIGNATION:	Monk Bretton standing cross, Barnsley Scheduled Monument (No. 1013765)	CONDITION:	Extensive significant problems
	· · · · · · · · · · · · · · · · · · ·	CONDITION: TREND:	Extensive significant problems Declining
DESIGNATION:	Scheduled Monument (No. 1013765)		· ·
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion	TREND:	Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion	TREND:	Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority	TREND:	Declining Keith Miller 01904 601990  Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)	TREND: CONTACT:  CONDITION:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf	TREND: CONTACT:	Declining Keith Miller 01904 601990  Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)  Flooding	TREND: CONTACT:  CONDITION: TREND:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)  Flooding	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)  Flooding Private	TREND: CONTACT:  CONDITION:  TREND: CONTACT:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)  Flooding Private  Romano-British settlements at Finkle Street	TREND: CONTACT:  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No. 1013765) Extensive vehicle damage/erosion Local Authority  Wortley Top Forge, Hunshelf Scheduled Monument (No. 1018262)  Flooding Private  Romano-British settlements at Finkle Street Scheduled Monument (No. 1004801)	TREND: CONTACT:  CONDITION: TREND: CONTACT:	Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### **ABBREVIATIONS**

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site

	Flance		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
DESIGNATION:	Scheduled Monument (No. 1020626)	CONDITION:	Extensive significant problems
SITE NAME:	Water powered bloomery, iron forge and rolling mill at Low Forge, Wortley		

SHE NAME.	Lisecai		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Tony Wiles (LPA) 01226 772 576	NEW ENTRY?:	No

### **DONCASTER**



Moat Hall ruins, SITE NAME: **Braithwell** 

Ruins of medieval monastic grange and post-medieval dwelling, consisting of arched doorway and low walls, in poor repair.

DESIGNATION: Scheduled Monument Very bad OCCUPANCY: N/A A(A)PRIORITY: OWNERTYPE: Private

Contact: Keith Miller 01904 601990



Stable to Hickleton Hall including the SITE NAME: Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton

DESIGNATION: Listed Building Grade II\*, CA, RPG II Fair CONDITION: Vacant OCCUPANCY: E (E) OWNERTYPE: Charity

Mid C18 stable block, now store and house with attached walls and gatepiers. Possibly by James Paine, who designed Hickleton Hall, 1745-48, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. Repairs have recently been carried out to the roofs and the building is now in fair condition, but disused.

Contact: Kathryn Gibson 01904 601939



Christ Church, SITE NAME: Thorne Road

A gothic style church dating to 1827/9. It is constructed from limestone ashlar with a slate roof and copper spire. It has a four stage south tower. The building fell into disrepair and was bought for a very small sum a few years ago.

DESIGNATION: Listed Place of Worship Grade II\*, CA CONDITION: C (New entry) PRIORITY: OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986



Church of St Peter. SITE NAME: Warmsworth Road Known as 'The White Church'. Consecrated in 1942 and mentioned in a wartime broadcast from Berlin by the notorious 'Lord Haw Haw'. Windows in poor condition.

DESIGNATION: Listed Place of Worship Grade II Poor CONDITION: C (New entry) PRIORITY: OWNER TYPE: Religious organisation

Contact: Susan Daniels 01904 601979



Church of St Lawrence, SITE NAME: Station Road.

Hatfield

Norman church. C12 origin, C13 arcades, rest mostly C15. Tower in poor condition.

DESIGNATION: Listed Place of Worship Grade I, CA CONDITION: PRIORITY: C (New entry)

OWNERTYPE: Religious organisation

Contact: Richard Jaques 01904 601986

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS CA LB/LBs LPA NP

Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s RPG SM/SMs UA WHS Unitary Authority World Heritage Site



Church of St Luke, SITE NAME: The Circle,

Rossington

Early C20 church, roofs in poor repair. Grant offered for re-roofing.

DESIGNATION: Listed Place of Worship Grade II

Poor CONDITION:

PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Mary, Main Street. Sprotbrough

Medieval church, significant decay to medieval

oak roofs. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I, CA

Very bad

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986

SITE NAME:	Site of St Helen's Chapel, Barnburgh and Harlin	gton	
DESIGNATION:	Scheduled Monument (No. 1004799)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Manor Holt moated site, Bawtry		
DESIGNATION:	Scheduled Monument (No. 1012453)	CONDITION:	Generally unsatisfactory
	` '		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moat Hall moated site and site of external anci	llary buildings	, Braithwell
DESIGNATION:	Scheduled Monument (No. 1012461)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge, Roman road, north west of Dono	aster, Brodsw	vorth
DESIGNATION:	Scheduled Monument (No. 1003672)	CONDITION:	Generally satisfactory
BESIGN (HOIN.	Scheduled Fishlament (Fvo. 1003072)	CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
	·		
SITE NAME:	Roman fort at Robin Hood's Well, Burghwallis		
DESIGNATION:	Scheduled Monument (No. 1002930)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman potteries 300yds (270m) north east of	Rossington Br	ridge, Cantley
DESIGNATION:	Scheduled Monument (No. 1004787)	CONDITION:	Generally satisfactory
	` ,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

### **ABBREVIATIONS**

SITE NAME:	Castle Hills motte and bailey castle, Langthwai	ite, Adwick le S	treet, Doncaster
DESIGNATION:	Scheduled Monument (No. 1013654)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moat Hills moated site, Bentley, Doncaster		
DESIGNATION:	Scheduled Monument (No. 1013655)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Edlington Wood Roman settlement, Edlington		
DESIGNATION:	Scheduled Monument (No. 1004824)	CONDITION:	Generally satisfactory
JESIGNATION.	Scheduled Floridinent (146, 166 1621)	CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Moat Hill moated site, Fenwick		
DESIGNATION:	Scheduled Monument (No. 1011920)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Castle Hill, Hampole		
DESIGNATION:	Scheduled Monument (No. 1004794)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Icehouse 720m south east of Bath House Farr	n, High Melton	
DESIGNATION:	Scheduled Monument (No. 1020715)	CONDITION:	Generally unsatisfactory
	Van dellere		with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism Private	TREND: CONTACT:	
PRINCIPAL VULNERABILITY: DWNER TYPE:			Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Private		Declining Keith Miller 01904 601990  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Earthworks on Sutton Common, Norton	CONTACT:	Declining Keith Miller 01904 601990  Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Private  Earthworks on Sutton Common, Norton  Scheduled Monument (No. 1004816)	CONTACT:  CONDITION:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816) Drainage/dewatering	CONTACT:  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816)  Drainage/dewatering Private	CONTACT:  CONDITION:  TREND:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816)  Drainage/dewatering Private  Rossington Roman fort, Rossington	CONTACT:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816)  Drainage/dewatering Private  Rossington Roman fort, Rossington Scheduled Monument (No. 1004823)	CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Earthworks on Sutton Common, Norton  Scheduled Monument (No. 1004816)  Drainage/dewatering Private  Rossington Roman fort, Rossington  Scheduled Monument (No. 1004823)  Arable ploughing	CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816)  Drainage/dewatering Private  Rossington Roman fort, Rossington Scheduled Monument (No. 1004823) Arable ploughing Private	CONTACT:  CONDITION:  TREND:  CONTACT:  CONDITION:  TREND:  CONTACT:	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Balne Generally satisfactory
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Earthworks on Sutton Common, Norton Scheduled Monument (No. 1004816)  Drainage/dewatering Private  Rossington Roman fort, Rossington Scheduled Monument (No. 1004823) Arable ploughing Private  Thorpe in Balne moated site, chapel and fishpone	CONTACT:  CONDITION: TREND: CONTACT:  CONTACT:  CONTACT:  Ond, Thorpe in	Declining Keith Miller 01904 601990  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Extensive significant problems Declining Keith Miller 01904 601990  Balne

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS

SITE NAME:	Stancil Roman villa, Tickhill		
DESIGNATION:	Scheduled Monument (No. 1004789)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Tickhill Castle, Tickhill		
DESIGNATION:	Scheduled Monument (No. 1004828)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Hatfield High Street		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Marr		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	Yes
SITE NAME:	Mexborough		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	St George's, Doncaster		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Thorne Central		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Thorne Road, Doncaster		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Woodlands		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
			1
VULNERABILITY:	High	TREND:	Deteriorating

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

The transfer of the transfer o				
PEAK DISTRICT (NP)				
SITE NAME:	Bailey Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield			
DESIGNATION:	Scheduled Monument (No. 1013217)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Castle Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield			
DESIGNATION:	Scheduled Monument (No. 1017612)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining	
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Cowell Flat prehistoric field system, 350m south east of Mortimer House, Bradfield, Sheffield			
DESIGNATION:	Scheduled Monument (No. 1017833)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990	

### **ROTHERHAM**



25 and 27 High Street, SITE NAME: Rotherham

Known as The Three Cranes. Late medieval house. Signs of structural decay, faulty rainwater goods.

DESIGNATION: Listed Building Grade II\*, CA Poor CONDITION: Vacant C (C) PRIORITY: OWNERTYPE: Private

Contact: Susan Daniels 01904 601979



Keppels Column, SITE NAME: Admirals Crest, Thorpe Common, Rotherham

DESIGNATION: Listed Building Grade II\* CONDITION: Poor N/A OCCUPANCY: PRIORITY: C (C) OWNER TYPE: Local authority

Monumental column built 1773-80. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. The internal staircase is unsafe.

Contact: Susan Daniels 01904 601979



Thorpe Salvin Old Hall (Ruins of), SITE NAME: Ladyfield Road, Thorpe Salvin

DESIGNATION: Listed Building Grade II\*, SM, CA Poor CONDITION: N/A OCCUPANCY: C (C) PRIORITY:

Gatehouse and imposing 3 storey south facade of mid C16 stone-built mansion built by Henry Sanford (died 1582) standing in an open courtyard. Grant has been offered for a condition survey.

Contact: Tammy Whitaker 01904 601880



Stable Block and Riding School, SITE NAME: Wentworth Woodhouse, Wentworth

DESIGNATION: Listed Building Grade I, RPG II\*

Fair CONDITION: Vacant OCCUPANCY: E (E) PRIORITY: OWNERTYPE: Private

OWNERTYPE: Private

Stable block and riding school, 1760s, situated approx 300 metres north-west of the house. Vacant and vulnerable due to under-maintenance and vandalism. English Heritage supporting possible office conversion scheme.

Contact: Kathryn Gibson 01904 601939

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

CA LB/LBs LPA NP RPG SM/SMs UA WHS

ABBREVIATIONS Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site



SITE NAME: Church of St Michael and All Angels,

Church Street, Great Houghton C17 chapel, severe stone decay and poor roofs. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*

condition: Very bad PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Leonard,
Doncaster Road,
Thrybergh

Medieval church with fine monuments. Roofs poor. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Very bad

PRIORITY: D (New entry)

OWNERTYPE: Religious organisation

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Peter and St Paul,

Todwick

Medieval church with CII nave, CI4 chancel and CI5 tower with CI8 and CI9 alterations. Tower parapets and pinnacles in poor condition.

 ${\scriptsize \mbox{\tt DESIGNATION:}} \ \, \mbox{\tt Listed Place of Worship Grade II*, CA}$ 

condition: Poor

PRIORITY:

C (New entry)

owner type: Religious organisation

Contact: Richard Jaques 01904 601986

SITE NAME:	Roman Ridge (Roman road): section 135yds	s (120m) long, eas	t of Hoober House, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. 1004830)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge (Roman road): section south	of Hoober House	e, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. 1004831)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 300yds (270m) long of	on Birchcliff Bank,	Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. 1004809)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 400yds (370m) long :	south of Abdy Far	m, Brampton Bierlow
DESIGNATION:	Scheduled Monument (No. 1004810)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

### ABBREVIATIONS CA Conserv

CA LB/LBs LPA NP RPG SM/SMs UA WHS

Conservation Area
s Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
s Scheduled Monument/s
Unitary Authority
World Heritage Site

Dut with significant localised problems  PRINCIPAL VULNERABILITY: Arable clipping Private Declining CONTACT: Keith Miller 01904 601990  STE NAME: Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION: Scheduled Monument (No. 1004808) CONDITION: Generally satisfactory  But with significant localised problems  PRINCIPAL VULNERABILITY: Moderate visitor erosion TREND: Declining  OWNERT TIPE: Local Authority CONTACT: Keith Miller 01904 601990  STE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No. 1004811) CONDITION: Generally satisfactory  But with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining  CONTACT: Keith Miller 01904 601990  STE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION: Scheduled Monument (No. 1004807) CONDITION: Generally satisfactory  But with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining  CONNERT TIPE: Scheduled Monument (No. 1004807) CONDITION: Generally satisfactory  But with significant localised problems  Declining  CONDITION: Generally unsatisfactory  With Miller 01904 601990  STE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory  With major localised problems  Declining  Generally unsatisfactory  With major localised problems  Declining: Contact: Keith Miller 01904 601990	SITE NAME:	Dead Man's Cave, Anston, North and South	Anston	
PRINCIPAL MALERAGETTE  Vanidation  COMPRETITIE  Kimberworth motte and bailey castle, Rotherham  Scheduled Monument (No. 1013469)  COMBRETITIE  COMBR	DESIGNATION:	Scheduled Monument (No. 1013468)	CONDITION:	·
Covernment or Agency Covernment or Agency Covernment Co	PRINCIPAL VULNERABILITY:	Vandalism	TREND:	,
Scheduled Monument (No. 1013469)  Sensitive Margin localised problems  Sensitive Private  Scheduled Monument (No. 1004815)  Scheduled Monument (No. 1004835)  Scheduled Monument (No. 1004837)  Scheduled Monument (No. 1004837)  Scheduled Monument (No. 1004838)  Scheduled Monument (No. 1004839)  Scheduled Monument	OWNER TYPE:	Government or Agency	CONTACT:	
with major localised problems Declining CONNECTIVE Private  Roman Ridge: section I I Oyds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherhal CONNECTIVE Reich Miller 01904 601990  Scheduled Monument (No. 1004835)  CONDINO Scheduled Monument (No. 1004813)  CONDINO Scheduled Monument (No. 1004808)  CONDINO Scheduled Monument (No. 1004801)  CONDINO Scheduled Monument (No. 1004807)  CONDINO Sch	SITE NAME:	Kimberworth motte and bailey castle, Rothe	rham	
Roman Ridge; section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherhan BESGNATION:  Scheduled Monument (No. 1004835) CONDITION:  Generally satisfactory but with minor localised problems Private  Scrub / tree growth IRRAD Declining CONTROLL:  Keith Miller 01904 601990  STENAME:  Roman Ridge; section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhan BESGNATION:  Scheduled Monument (No. 1004813) CONDITION:  Generally satisfactory but with significant localised problems Declining CONTROLL:  READ Declining CONTROLL:  Read Monument (No. 1004813) CONTROLL:  Read Declining CONTROLL:  Read Monument (No. 1004813) CONTROLL:  Read Declining CONTROLL:  Read Monument (No. 1004813) CONTROLL:  Read Declining CONTROLL:  Read Declining CONTROLL:  Read Monument (No. 1004808) CONTROLL:  Read Declining CONTROLL:  Read Monument (No. 1004808) CONTROLL:  Read Declining CONTROLL:  Read Monument (No. 1004808) CONTROLL:  Read Monument (No. 1004807) CONTRO	DESIGNATION:	Scheduled Monument (No. 1013469)	CONDITION:	
Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherhand Education  Scheduled Monument (No. 1004835)  CONDITION:  Generally satisfactory but with minor localised problems  Perivate  Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhand Dissonantion  Scheduled Monument (No. 1004813)  CONDITION:  Generally satisfactory but with significant localised problems  Perivate  Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhand Dissonantion  Scheduled Monument (No. 1004813)  CONDITION  Arable clipping  TREND:  CONDITION  CONDITION  CONDITION  CONDITION  CONDITION  Generally satisfactory but with significant localised problems  Perivate  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherhand Dissonantion  Scheduled Monument (No. 1004808)  CONDITION  CONDITION  Generally satisfactory but with significant localised problems  PRENDIA VALDEMABLET:  Moderate visitor erosion  TREND:  Declining  CONTECT  Keith Miller 01904 601990   STITE NAME:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESCNATION  Scheduled Monument (No. 1004811)  CONDITION  Generally satisfactory but with significant localised problems  DESCNATION  Scheduled Monument (No. 1004801)  CONDITION  Generally satisfactory but with significant localised problems  DESCNATION  CONDITION  Generally satisfactory but with significant localised problems  DESCNATION  CONDITION  CO	PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
Scheduled Monument (No. 1004835)  Scheduled Monument (No. 1004835)  Scheduled Monument (No. 1004835)  Scheduled Monument (No. 1004813)  Scheduled Monument (No. 100480)  Scheduled Monument (No. 1004808)  Scheduled Monument (No. 1004807)  Schedul	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
Dut with minor localised problems PRINCIPM VALUERFABILITY: Private  Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhan DESCNATION: Scheduled Monument (No. 1004813) CONDITION: Generally satisfactory but with significant localised problems Private  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherhan DESCNATION: Scheduled Monument (No. 1004808) Desclining DESCNATION: Scheduled Monument (No. 1004811) DESCNATION: Scheduled Monument (No. 1004811) DESCNATION: DESCNATION: Descnation: Descining Descnation: Desclining Descnation: Descining Descnation: Desclining Descnation: Desclining Desclining Descnation: Desclining Desclining Descnation: Descnation: Descnation: Desclining Descnation: Descnatio	SITE NAME:	Roman Ridge: section 110yds (100m) long, 4	50yds (410m) NI	NE of Kimberworth Park Farm, Rotherhar
Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherham DESCRIATION:  Scheduled Monument (No. 1004813)  Scheduled Monument (No. 1004813)  CONDITION:  Arable clipping  TREND  Declining  OWNERTHYPE:  Private  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham DESCRIATION:  Scheduled Monument (No. 1004808)  Scheduled Monument (No. 1004808)  Scheduled Monument (No. 1004808)  SCHEDINGE  With Hiller 01904 601990  ROMARTHYPE:  ROMAN RIDGE: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham DESCRIATION:  Scheduled Monument (No. 1004808)  SCHEDINGE  ROMAN RIDGE: section 400yds (370m) long in Wath Wood, Rotherham DESCRIATION:  STERNAME:  ROMAN RIDGE: section 400yds (370m) long in Wath Wood, Rotherham DESCRIATION:  SCHEDULE AUTHORITY:  Moderate vehicle damage/erosion  TREND  Declining  Whoderate vehicle damage/erosion  TREND  DESCRIATION:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESCRIATION:  SCHEDULARIABILITY:  Deterioration — in need of management  TREND:  Declining  Whoderate National Problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESCRIATION:  Whoderate natural erosion  TREND:  Declining  Whoderate natural erosion  TREND:  Declining  ONDITION:  Whoderate natural erosion  TREND:  Declining  ONDITION:  Reith Miller 01904 601990	DESIGNATION:	Scheduled Monument (No. 1004835)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhand Designation:  Scheduled Monument (No. 1004813)  Scheduled Monument (No. 1004813)  CONDITION:  Arable clipping  TRIND:  Declining  OWNERTIFE:  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherhand Designation:  Scheduled Monument (No. 1004808)  Stephanish Moderate visitor erosion  TRIND:  Declining  Scheduled Monument (No. 1004811)  Scheduled Monument (No. 1004811)  Scheduled Monument (No. 1004811)  Scheduled Monument (No. 1004811)  Scheduled Monument (No. 1004808)  Scheduled Monument (No. 1004808)  Scheduled Monument (No. 1004807)  Stephanish Moderate vehicle damage/erosion  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother Designation:  Scheduled Monument (No. 1004807)  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhal Designation:  Scheduled Monument (No. 1020067)  With major localised problems  Moderate natural erosion  Residuations  Bellining	PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DESIGNATION:  Scheduled Monument (No. 1004813)  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VALINERABILITY: DATE NAME: ROMAN Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham DESIGNATION: Scheduled Monument (No. 1004808)  SCHEDULED LOCAL Authority  CONTRACT:  Keith Miller 01904 601990  STE NAME: ROMAN Ridge: section 400yds (370m) long in Wath Wood, Rotherham DESIGNATION: SCHEDULED LOCAL Authority  CONTRACT:  Keith Miller 01904 601990  STE NAME: ROMAN Ridge: section 400yds (370m) long in Wath Wood, Rotherham DESIGNATION: SCHEDULED LOCAL Authority  CONTRACT:  Moderate vehicle damage/erosion  TREND: DESIGNATION: DESIGNATION: SCHEDULED LOCAL Authority  CONTRACT: Keith Miller 01904 601990  STE NAME: ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESIGNATION: DESIGNATION: SCHEDULED LOCAL Authority  CONTRACT:  Keith Miller 01904 601990  STE NAME: ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESIGNATION: SCHEDULED LOCAL Authority  CONDITION: Generally satisfactory but with significant localised problems DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: SWINTON POTTERY (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhan DESIGNATION: Moderate natural erosion  TREND: DESIGNATION: DESIGNATION: DESIGNATION: Moderate natural erosion  TREND: DESIGNATION: Moderate natural erosion  TREND: DESIGNATION: DESIGNATION: Moderate natural erosion  TREND: DESIGNATION: DESIGNAT	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
Dut with significant localised problems Declining Declin	SITE NAME:	Roman Ridge: section 300yds (270m) long n	orth of Birchwoo	od (east of Chemical Cottages), Rotherhar
ROMARR TYPE  ROMAN Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION.  Scheduled Monument (No. 1004808)  CONDITION.  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate visitor erosion  TREND:  Local Authority  CONTACT:  Keith Miller 01904 601990  STIE NAME:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION:  Scheduled Monument (No. 1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate vehicle damage/erosion  TREND:  Declining  OWNER TYPE:  Local Authority  CONTACT:  Keith Miller 01904 601990  STIE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION:  Scheduled Monument (No. 1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNER TYPE:  Local Authority  CONTACT:  Keith Miller 01904 601990  STIE NAME:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  Declining  Moderate natural erosion  TREND:  Declining	DESIGNATION:	Scheduled Monument (No. 1004813)	CONDITION:	·
Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION:  Scheduled Monument (No. 1004808)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate visitor erosion  TREND: Declining  CONTACT: Keith Miller 01904 601990  ROMAN Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No. 1004811)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion  TREND: Declining  CONTACT: Keith Miller 01904 601990  ROMAN RIdge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION: Scheduled Monument (No. 1004807)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining  CONTACT: Keith Miller 01904 601990  STEENAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Declining  CONTACT: Keith Miller 01904 601990  STEENAME  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining  CONTACT: Keith Miller 01904 601990	PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
DESIGNATION: Scheduled Monument (No. 1004808)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate visitor erosion  TREND: Declining  OWNERTYPE  Local Authority  CONTACT: Keith Miller 01904 601990  SITE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No. 1004811)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion  TREND: Declining  OWNERTYPE  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother Condition: Scheduled Monument (No. 1004807)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management  TREND: Declining  OWNERTYPE  Local Authority  CONTACT: Keith Miller 01904 601990  SITE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Moderate natural erosion  TREND: Declining	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
But with significant localised problems Declining OWNERTYPE Local Authority CONTACT: Keith Miller 01904 601990  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No. 1004811) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion REND: Declining OWNERTYPE Local Authority CONTACT: Keith Miller 01904 601990  SITE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESIGNATION: Scheduled Monument (No. 1004807) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management REND: Declining OWNERTYPE Local Authority CONTACT: Keith Miller 01904 601990  SITE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhad DESIGNATION: Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining	SITE NAME:	Roman Ridge: section 400yds (370m) long fr	om Hill Top Lane	e to Little Common Lane, Rotherham
OWNERTYPE  Local Authority  CONTACT: Keith Miller 01904 601990  STE NAME:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION:  Scheduled Monument (No. 1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate vehicle damage/erosion  TREND:  Declining  OWNER TYPE  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION:  Scheduled Monument (No. 1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNER TYPE  Local Authority  TREND:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhal DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Moderate natural erosion  TREND:  Declining  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Moderate natural erosion  TREND:  Declining	DESIGNATION:	Scheduled Monument (No. 1004808)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION:  Scheduled Monument (No. 1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate vehicle damage/erosion  TREND:  Declining  OWNER TYPE:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION:  Scheduled Monument (No. 1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNER TYPE:  Local Authority  CONTACT:  Keith Miller 01904 601990  STIE NAME:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhan DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Moderate natural erosion  TREND:  Declining  CONTACT:  Keith Miller 01904 601990	PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
DESIGNATION:  Scheduled Monument (No. 1004811)  CONDITION:  Generally satisfactory but with significant localised problems  Moderate vehicle damage/erosion  TREND:  Declining  OWNERTYPE:  Local Authority  CONTACT:  Keith Miller 01904 601990  STE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION:  Scheduled Monument (No. 1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNERTYPE:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Moderate natural erosion  TREND:  Declining  CONDITION:  Generally unsatisfactory  with major localised problems  Declining  Declining  Declining  CONDITION:  Generally unsatisfactory  With major localised problems  Declining  Declining  Declining  CONDITION:  CONDITION:  Declining  CONDITION:  Declining  CONDITION:  Declining  CONDITION:  CONDITION:  Declining  CONDITION:  CONDITION	OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
but with significant localised problems  Moderate vehicle damage/erosion  TREND: Declining  OWNERTYPE  Local Authority  CONTACT: Keith Miller 01904 601990  SITE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION:  Scheduled Monument (No. 1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  CONTACT:  Keith Miller 01904 601990  STIE NAME:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhal  DESIGNATION:  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  Moderate natural erosion  TREND:  Declining  CONTACT:  TREND:  Declining  CONTACT:  CONDITION:  Declining  CONTACT:  CONDITION:  Declining  CONTACT:  CONDITION:  Declining  CONTACT:  CONDITION:  Declining  CONTACT:	SITE NAME:	Roman Ridge: section 400yds (370m) long ir	ı Wath Wood, Ro	otherham
PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining  CONTACT: Keith Miller 01904 601990  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother  DESIGNATION: Scheduled Monument (No. 1004807) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining  CONTACT: Keith Miller 01904 601990  SITE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion TREND: Declining  CONDITION: Generally unsatisfactory with major localised problems  Declining	DESIGNATION:	Scheduled Monument (No. 1004811)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother Designation:  Scheduled Monument (No. 1004807)  Deterioration — in need of management  Deterioration — in need of management  TREND:  Declining  Local Authority  TREND:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham Designation:  Scheduled Monument (No. 1020067)  Scheduled Monument (No. 1020067)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Moderate natural erosion  TREND:  Declining  Scheduled Monument (No. 1020067)  TREND:  Declining  Declining  Declining  CONDITION:  Generally unsatisfactory with major localised problems  Declining  Declining  CONDITION:  CONDITION:  Declining  CONDITION:  CONDITION:  CONDITION:  Declining  CONDITION:  CONDITI	PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	
DESIGNATION: Scheduled Monument (No. 1004807)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management  TREND: Declining  CONTACT: Keith Miller 01904 601990  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherham  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining	OWNER TYPE:	-	CONTACT:	Keith Miller 01904 601990
but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management  TREND: Declining  CONTACT: Keith Miller 01904 601990  SITE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherha  DESIGNATION: Scheduled Monument (No. 1020067)  CONDITION: Generally unsatisfactory  with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining	SITE NAME:	Roman Ridge: south east of Hill Top (section	700yds (660m)	long, Meadowhall Road to Hill Top), Rothe
PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND: Declining  CONTACT: Keith Miller 01904 601990  SITE NAME:  Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherha  DESIGNATION:  Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion  TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1004807)	CONDITION:	,
STIE NAME: Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage, Rotherhad Designation: Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion TREND: Declining	PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	_
DESIGNATION: Scheduled Monument (No. 1020067) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion TREND: Declining	OWNER TYPE:	-	CONTACT:	Keith Miller 01904 601990
with major localised problems  PRINCIPAL VULNERABILITY: Moderate natural erosion TREND: Declining  With major localised problems  Declining	SITE NAME:	Swinton Pottery (The Rockingham Works),	310m and 120m i	north west of Keeper's Cottage, Rotherha
PRINCIPAL VULNERABILITY: Moderate natural erosion TREND: Declining	DESIGNATION:	Scheduled Monument (No. 1020067)	CONDITION:	·
D ' 4	PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	•
	OWNER TYPE:	Private	CONTACT:	

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Hood Hill shaft mounds, 480m east of Hoo	d Hill Farm, Went	worth
DESIGNATION:	Scheduled Monument (No. 1017747)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 330yds (300m) long,	south of Dog Ken	nnel Pond, Wentworth Park, Wentworth
DESIGNATION:	Scheduled Monument (No. 1004833)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 500yds (460m) long,	north of Dog Ken	nnel Pond, Wentworth Park, Wentworth
DESIGNATION:	Scheduled Monument (No. 1004832)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Doncaster Road, Rotherham Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Jonathan Bell (LPA) 01709 823811	NEW ENTRY?:	No
SITE NAME:	Greasborough, Rotherham Urban		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jonathan Bell (LPA) 01709 823811	NEW ENTRY?:	No
SITE NAME:	Rotherham Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jonathan Bell (LPA) 01709 823811	NEW ENTRY?:	No
SITE NAME:	Wales, Rotherham South		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating

## **SHEFFIELD**



SITE NAME: Loxley United Reformed Church, Loxley Road,

Bradfield

DESIGNATION: Listed Building Grade II\* Poor CONDITION:

Vacant OCCUPANCY: PRIORITY: C(C)

OWNERTYPE: Private

Redundant church, 1787. Closed in 1994. Recently suffered from further vandalism, condition deteriorating.

Contact: Giles Proctor 01904 601981

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS



Leah's Yard, SITE NAME:

20-22 Cambridge Street,

Sheffield

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION: Vacant OCCUPANCY: D(D)

Mid C19 cutlery / silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food / drink agreed and included in "New Retail Quarter" proposals. Some patch repairs to the roof have been carried out.

Contact: Tammy Whitaker 01904 601880



SITE NAME: Nonconformist Chapel,

General Cemetery, Cemetery Road,

DESIGNATION: Listed Building Grade II\*, CA, RPG II\*

Poor CONDITION: Vacant A(A)PRIORITY: Trust OWNER TYPE:

Cemetery chapel built in circa 1836. Lead has been stolen from the roof and not reinstated, risking further structural deterioration.

Contact: Tammy Whitaker 01904 601880



Wicker Arch and adjoining viaduct, SITE NAME: The Wicker,

Sheffield

Listed Building Grade II\* DESIGNATION:

Fair CONDITION:

Part occupied OCCUPANCY: C (C) PRIORITY:

OWNER TYPE: Company

Railway viaduct, I 848. Main arch listed grade II\* has been cleared and overhauled but the remaining arches are suffering from stone theft (parapets) and general lack of maintenance. Many of the adjacent (grade II listed) viaduct arches are in use for workshops but remain in poor repair.

Contact: Susan Daniels 01904 601979



SITE NAME: Workshop ranges and crucible furnace, attached to No. 35,

Well Meadow Street, Sheffield

DESIGNATION: Listed Building Grade II\*

Fair CONDITION: Vacant F (F) PRIORITY-Private

OWNER TYPE:

Workshops and a crucible furnace, circa 1840. The buildings are suffering from general decay. The gutters are failing in places and some slates have slipped. Site is generally secure and weathertight. Consents are in place and some repair underway. English Heritage is supporting the cost of completion of the repairs.

Contact: Giles Proctor 01904 601981




Gateway and adjoining walls at SITE NAME: garden entrance to Oakes Park, Norton, Sheffield

DESIGNATION: Listed Building Grade II\*, CA, RPG I

CONDITION: Poor OCCUPANCY: N/A C (C) PRIORITY-OWNERTYPE: Private Early C18 and early C19 gateway with ornamental iron gates leading to C18 gardens. The gates are rusty and the gate piers are in poor condition. The park is also at risk.

Victorian chapel, now Seventh Day Adventist Church.





Seventh Day Adventist Church SITE NAME: adjoining school and boundary wall, Andover Street

Roofs and rainwater goods in poor condition.

DESIGNATION: Listed Place of Worship Grade II, CA CONDITION:

PRIORITY: C (New entry)

OWNERTYPE: Religious organisation

Contact: Susan Daniels 01904 601979

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable)
  end use or user identified;
  functionally redundant buildings
  with new use agreed but not yet implemented

### NOTE:

If the priority category has changed since the 2010 register, the previous category given in brackets

## ABBREVIATIONS

Conservation Area CA LB/LBs LPA NP RPG SM/SMs UA WHS



Church of the Sacred Heart, SITE NAME: Forbes Road

1930s Roman Catholic church. In good repair, except for deterioration of mortar to the tower and deterioration of internal mosaic. Grant-aided repairs underway to tower and mosaic.

DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION:

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Contact: Susan Daniels 01904 601979

SITE NAME:	Handlands Romano-British settlement, 460	n south west of V	Voodseats Farm, Ecclesfield
DESIGNATION:	Scheduled Monument (No. 1017835)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Willow Garth moated site and fishpond, Ec	clesfield, Ecclesfie	ld
DESIGNATION:	Scheduled Monument (No. 1012477)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Former Sanderson's Darnall Steelworks (ex in south corner and south east side) and D		
DESIGNATION:	Scheduled Monument (No. 1021424)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Mousehole Forge, Malin Bridge, Sheffield		
DESIGNATION:	Scheduled Monument (No. 1004804)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Roman Ridge: section 600yds (550m) long I	oetween Jenkin La	ne (now Road) and Tylers Street, Sheffield
DESIGNATION:	Scheduled Monument (No. 1004806)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	The Shepherd Wheel, Sheffield		
DESIGNATION:	Scheduled Monument (No. 1002931)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Iron Age and Roman quern workings on W	harncliffe Rocks, S	Stocksbridge
	Scheduled Monument (No. 1004802)	CONDITION:	Generally unsatisfactory
DESIGNATION:			with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Plant growth	TREND:	with major localised problems  Declining

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS



Oakes Park, SITE NAME:

Sheffield

DESIGNATION: Registered Park and Garden Grade II,

also CA, 9 LBs

Extensive significant problems CONDITION:

VULNERABILITY: High Declining

OWNER TYPE: Mixed, multiple owners

Gardens and pleasure grounds with early to mid C18 origins, an early C19 terrace and parkland probably of early C19 date. Park and gardens compromised by multiple use, condition of park is poor and listed structures in very poor condition.

Contact: Andy Wimble 01904 601970



SITE NAME: Sheffield General Cemetery, Sheffield

DESIGNATION: Registered Park and Garden Grade II\*,

also CA. 9 LBs

Generally unsatisfactory CONDITION:

with major localised problems

VULNERABILITY: High Declining TRENID:

OWNER TYPE: Local Authority, multiple owners

General Cemetery

Cemetery of 1836 designed by Sheffield architect Samuel Worth (fl. 1830) with a chapel, catacombs and a cemetery office, and a layout which makes dramatic use of a quarried hillside site. An extension of 1846 for Anglican burials, laid out by Robert Marnock (1800-89). The cemetery retains both its Anglican and Non-Conformist Chapels (listed grade II\*) the latter a building at risk. Site managed by The Friends of Sheffield General Cemetery.

Contact: Andy Wimble 01904 601970

No

NEW ENTRY?

ITE NAME:	Sheffield
ITE INAME:	Sileilleid

DESIGNATION: Conservation Area CONDITION Very bad VULNERABILITY: Deteriorating TREND: Craig Broadwith (LPA) 0114 273 4223


Well Meadow SITE NAME:

Conservation Area Very bad DESIGNATION: CONDITION: Deteriorating VULNERABILITY

Craig Broadwith (LPA) 0114 273 4223 No CONTACT: NEW ENTRY?:

## **WEST YORKSHIRE**

CONTACT



Manningham Mill, SITE NAME:

> Heaton Street, Heaton, **Bradford**

DESIGNATION: Listed Building Grade II\*, CA

Fair CONDITION:

OCCUPANCY: Part occupied

Company OWNER TYPE:

Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion agreed. Conversion of warehouse completed. Works to mill block underway.

Contact: Kathryn Gibson 01904 601939



Leventhorpe Hall, SITE NAME:

1289 and 1291 Thornton Road, Lower Grange, Bradford

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant D (D) PRIORITY: OWNERTYPE: Private Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. Residential scheme has consent for the whole site, but work has stalled.

Contact: Tammy Whitaker 01904 601880



SITE NAME:

Mill Building at Low Mills, Low Mill Lane,

Keighley

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: D (D)

OWNER TYPE: Company

Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use but little progress on site as yet.

Contact: Kathryn Gibson 01904 601939

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS



Waterloo Mill, SITE NAME: Howden Road,

Silsden

DESIGNATION: Listed Building Grade II\*, CA

Fair CONDITION:

Part occupied OCCUPANCY:

F (F) Company OWNER TYPE:

Main four storey spinning mill block, parts of roof deteriorating and allowing water ingress although extensive repairs to windows and roof covering recently completed. The middle section, which contains the engine, is deteriorating. Part converted to residential use. The Chimney was extensively repaired in 2005.

Contact: Kathryn Gibson 01904 601939



Church of St Clement, SITE NAME: Barkerend Road

Church dating to 1894 of dressed limestone with slate roof. Its principle feature of interest is the interior designed by Morris and Co. Grant-aided repairs are underway to the nave and north aisle roofs.

DESIGNATION: Listed Place of Worship Grade II\*, CA CONDITION: F (New entry) PRIORITY: Religious organisation OWNER TYPE:

Contact: Richard Jaques 01904 601986



Church of All Saints, SITE NAME: Little Horton Lane

All Saint's Church was built in the C19 when the area became a densely populated urban district. Grant-aided repairs are underway to the tower and spire.

DESIGNATION: Listed Place of Worship Grade II\*, CA Poor CONDITION: F (New entry) PRIORITY:

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Chad, St Chad's Road

OWNER TYPE: Religious organisation

1916 Arts and Crafts church. Poor roofs to east apses and Lady Chapel. Grant offered for roof repairs.



Contact: Giles Proctor 01904 601981



Church of St Paul, SITE NAME: St Paul's Avenue

Small gothic church dating to 1838 and constructed from sandstone with ashlar dressings. Grant offered for repairs to the tower, spire and rainwater goods.

DESIGNATION: Listed Place of Worship Grade II, CA CONDITION: D (New entry) PRIORITY:

OWNER TYPE: Religious organisation Contact: Richard Jaques 01904 601986



SITE NAME: St Michael and All Angels, Church Street,

Haworth, Keighley

Large Victorian church with C16 tower. Roof coverings in poor condition and deterioration of mural paintings. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION:

PRIORITY: D (New entry)

OWNERTYPE: Religious organisation

Contact: Giles Proctor 01904 601981

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.



SITE NAME:

Church of St James, Thornton Road, Thornton

Large Victorian church with Morris glass. Slate roofs in poor condition. Grant offered.

DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION:

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981

SITE NAME:	Late prehistoric enclosed settlement knows	n as Round Dykes	Camp on Addingham Low Moor, Addingham
DESIGNATION:	Scheduled Monument (No. 1018259)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cup and ring marked rock north of Pennyt	horn Hill, Baildon	
DESIGNATION:	Scheduled Monument (No. 1012684)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cup-marked rock on slight bank north east	of Glovershaw q	uarry, Baildon
DESIGNATION:	Scheduled Monument (No. 1009724)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Enclosed settlement known as 'Soldier's Tre	nch' including a c	up-marked rock, Baildon
DESIGNATION:	Scheduled Monument (No. 1009718)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Northernmost of two cairns east of Glover	rshaw quarry, inclu	uding adjacent cup-marked rock, Baildon
DESIGNATION:	Scheduled Monument (No. 1013408)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round cairn and curving bank on Pennytho	rn Hill, Baildon	
DESIGNATION:	Scheduled Monument (No. 1012683)	CONDITION:	Generally unsatisfactory
	,		with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Round cairn on east flank of Baildon Hill, B	aildon	
DESIGNATION:	Scheduled Monument (No. 1012676)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
	,		

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

ABBREVIATIONS Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Small cup-marked rock 30m east of Glover	shaw quarry, Baild	on
DESIGNATION:	Scheduled Monument (No. 1009722)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Southernmost of two cairns east of Glover	shaw quarry, Baild	on
DESIGNATION:	Scheduled Monument (No. 1009725)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Cairn 330m north of Woodhead on Harde	n Moor, Bradford	
DESIGNATION:	Scheduled Monument (No. 1018239)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
	Turkin Assetler street similar Dunkin Massel	Dl	
SITE NAME:	Twelve Apostles stone circle, Burley Moor, I	,	
DESIGNATION:	Scheduled Monument (No. 1011763)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
OWNER TYPE: SITE NAME:	Private  Late prehistoric enclosed settlement known		
			Ring, Cullingworth  Generally satisfactory
SITE NAME:	Late prehistoric enclosed settlement know	n as Castle Stead	Ring, Cullingworth  Generally satisfactory  but with significant localised problems  Declining
site name: Designation:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)	n as Castle Stead	Ring, Cullingworth  Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing	n as Castle Stead  CONDITION:  TREND:  CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private	n as Castle Stead  CONDITION:  TREND:  CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  ng on Catstones Hill, Cullingworth Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known	condition:  TREND: CONTACT:  n as Catstones Rin	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  ng on Catstones Hill, Cullingworth Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rig	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rii  CONDITION:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rii  CONDITION:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  The gon Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillangement and properties of the control of the co	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillar Scheduled Monument (No. 1013472)	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  The generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillar Scheduled Monument (No. 1013472)  Extensive visitor erosion Local Authority	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:  CONTACT:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillar Scheduled Monument (No. 1013472)  Extensive visitor erosion Local Authority  Cairnfield, carved rocks and associated currat north west end of Green Crag Slack, eas	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:  CONTACT:  TREND: CONTACT:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Servoir, Ilkley
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillar Scheduled Monument (No. 1013472)  Extensive visitor erosion Local Authority  Cairnfield, carved rocks and associated curv	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:  CONTACT:  TREND: CONTACT:  TREND: CONTACT:	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DWNER TYPE:	Late prehistoric enclosed settlement known Scheduled Monument (No. 1018258)  Arable ploughing Private  Late prehistoric enclosed settlement known Scheduled Monument (No. 1018240)  Plant growth Private  Cairn at Rombalds Moor triangulation pillar Scheduled Monument (No. 1013472)  Extensive visitor erosion Local Authority  Cairnfield, carved rocks and associated currat north west end of Green Crag Slack, eas	n as Castle Stead  CONDITION:  TREND: CONTACT:  n as Catstones Rin  CONDITION:  TREND: CONTACT:  CONTACT:  TREND: CONTACT:  TREND: CONTACT:  ved bank it of Gill Head Res	Ring, Cullingworth  Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Ing on Catstones Hill, Cullingworth Generally satisfactory but with significant localised problems Declining Keith Miller 01904 601990  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Servoir, Ilkley Generally unsatisfactory

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Cup and Ring marked rock known as the Hanging Stone Rock, llkley				
DESIGNATION:	Scheduled Monument (No. 1012008)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Enclosure with carved rocks and disturbed cairn known as Green Crag Enclosure, llkley				
DESIGNATION:	Scheduled Monument (No. 1012840)	CONDITION:	Generally satisfactory		
	,		but with significant localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Two cup marked rocks in path south east of qu	arry at Cow	and Calf Rocks, llkley		
DESIGNATION:	Scheduled Monument (No. 1012838)	CONDITION:	Generally unsatisfactory		
	,		with major localised problems		
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TRENE	Declining		
I ININCIPAL VOLINEIVABILITI:	EXTENSIVE VISITOL ELOSION	TREND:			
OWNER TYPE:  SITE NAME:	Local Authority  Late prehistoric enclosed settlement 150m north	CONTACT:	Keith Miller 01904 601990		
OWNER TYPE:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)	CONTACT:	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems		
OWNER TYPE:  SITE NAME:	Local Authority  Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping	contact:	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining		
OWNER TYPE:  SITE NAME:  DESIGNATION:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)	contact:  h of Shaygate  condition:	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Local Authority  Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping	contact:  th of Shaygate condition:  TREND: contact:  Gardens ar	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  and pleasure grounds partly laid out c1897 with		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Local Authority  Late prehistoric enclosed settlement 150m nort Scheduled Monument (No. 1018241)  Dumping Private	contact:  th of Shaygate  condition:  trend:  contact:  Gardens ar  additional f 1912 to 193 by TH Maw	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with ormal landscaping and features dating from 38, with some design work in the latter period wson and Son. Formerly owned by Bradford Ciri		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley DESIGNATION: Registered Park and Garden Grade II,	contact:  th of Shaygate  condition:  trend:  contact:  Gardens ar additional f 1912 to 19, by TH Maw Council, no	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period wson and Son. Formerly owned by Bradford Circle win private ownership and lay vacant for a		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley DESIGNATION: Registered Park and Garden Grade II, also 3 LBs	contact:  th of Shaygate  condition:  TREND:  contact:  Gardens ar  additional f 1912 to 193 by TH Maw  Council, no  number of	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period vson and Son. Formerly owned by Bradford Cirow in private ownership and lay vacant for a years suffering decay and vandalism. New		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley DESIGNATION: Registered Park and Garden Grade II, also 3 LBs CONDITION: Generally satisfactory	contact:  th of Shaygate  condition:  TREND:  contact:  Gardens ar  additional f 1912 to 193 by TH Maw  Council, no  number of	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period wson and Son. Formerly owned by Bradford Circle win private ownership and lay vacant for a		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley  DESIGNATION: Registered Park and Garden Grade II, also 3 LBs  CONDITION: Generally satisfactory but with minor localised problems  VULNERABILITY: LOW  TREND: Unknown	CONTACT:  th of Shaygate  CONDITION:  TREND:  CONTACT:  Gardens ar additional f 1912 to 19, by TH Maw Council, no number of owners in 1912 to	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period yson and Son. Formerly owned by Bradford Circle win private ownership and lay vacant for a years suffering decay and vandalism. New process of repairing house and grounds.		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley  DESIGNATION: Registered Park and Garden Grade II, also 3 LBs  CONDITION: Generally satisfactory but with minor localised problems  VULNERABILITY: LOW	CONTACT:  th of Shaygate  CONDITION:  TREND:  CONTACT:  Gardens ar additional f 1912 to 19, by TH Maw Council, no number of owners in 1912 to	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period vson and Son. Formerly owned by Bradford Citsw in private ownership and lay vacant for a years suffering decay and vandalism. New		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley  DESIGNATION: Registered Park and Garden Grade II, also 3 LBs  CONDITION: Generally satisfactory but with minor localised problems  VULNERABILITY: LOW  TREND: Unknown	CONTACT:  th of Shaygate  CONDITION:  TREND:  CONTACT:  Gardens ar additional f 1912 to 19, by TH Maw Council, no number of owners in 1912 to	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period vson and Son. Formerly owned by Bradford Citow in private ownership and lay vacant for a years suffering decay and vandalism. New process of repairing house and grounds.		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley  DESIGNATION: Registered Park and Garden Grade II, also 3 LBs  CONDITION: Generally satisfactory but with minor localised problems  VULNERABILITY: LOW  TREND: Unknown  OWNER TYPE: Private, single owner	CONTACT:  th of Shaygate  CONDITION:  TREND:  CONTACT:  Gardens ar additional f 1912 to 19, by TH Maw Council, no number of owners in 1912 to	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  And pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period vson and Son. Formerly owned by Bradford Citow in private ownership and lay vacant for a years suffering decay and vandalism. New process of repairing house and grounds.		
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Late prehistoric enclosed settlement 150m north Scheduled Monument (No. 1018241)  Dumping Private  SITE NAME: Whinburn, Keighley DESIGNATION: Registered Park and Garden Grade II, also 3 LBs CONDITION: Generally satisfactory but with minor localised problems  VULNERABILITY: LOW TREND: Unknown OWNER TYPE: Private, single owner  Apsley Crescent, Manningham, Bradford	contact:  th of Shaygate  condition:  TREND:  contact:  Gardens ar  additional f 1912 to 19; by TH Maw  Council, no  number of  owners in    Contact: Ar	Keith Miller 01904 601990  Farm, Wilsden  Generally unsatisfactory with major localised problems Declining Keith Miller 01904 601990  Ind pleasure grounds partly laid out c1897 with formal landscaping and features dating from 38, with some design work in the latter period with youngened by Bradford Citow in private ownership and lay vacant for a years suffering decay and vandalism. New process of repairing house and grounds.  Indy Wimble 01904 601970		

SITE NAME:	Apsley Crescent, Manningham, Bradford			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Low	TREND:	Deteriorating	
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	Yes	
SITE NAME:	Devonshire Park and Cliffe Castle, Keighley	,		
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Low	TREND:	Deteriorating	
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No	
SITE NAME:	Great Horton			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	Low	TREND:	Deteriorating	
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No	

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:
If the priority category
has changed since the 2010
register, the previous category
is given in brackets.

## ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

SITE NAME:	Haworth, Keighley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	Idle and The Green		
			\/
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	Keighley Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	North Park Road		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	St Paul		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	Yes
SITE NAME:	The Goitside, Bradford		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	Yes
SITE NAME:	Thornton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
	John 188 8/8 (E. F.) 012/11/133/32	. 4044 (1411(1))	

## BRADFORD / KIRKLEES / LEEDS



SITE NAME:	Battle of Adwalton Moor, Drighlington
DESIGNATION:	Registered Battlefield
CONDITION:	Generally satisfactory
	but with significant localised problems
VULNERABILITY	: Medium
TREND:	Declining
OWNER TYPE:	Private

The I 643 battle during the English Civil War on moorland outside Bradford in which some I 4,000 men fought, gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

Contact: Keith Emerick 01904 601988

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

#### **CALDERDALE**



SITE NAME: Double aisled barn to north west of Kirklees Priory Gatehouse,

Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade I

Fair OCCUPANCY: Part occupied

C (C) PRIORITY-Private OWNER TYPE

CONDITION:

Aisled barn. One of the farm buildings of the Priory (now gone), with a CI5 timber frame, which was later stone-clad. Whole complex continuing to decay. North east corner of stables and north threshing porch appear unstable. A report on development options is under consideration by the owners.

Early C17 cowhouse, two cell house, possibly slaughter

house. Gable wall partially collapsed and unstable.

Contact: Richard Jaques 01904 601986



Home Farm Building No. 6, SITE NAME:

Kirklees Park, **Brighouse** 

Listed Building Grade II\* DESIGNATION:

CONDITION: Very bad Vacant OCCUPANCY: A(A)PRIORITY: OWNERTYPE: Private

Contact: Richard Jaques 01904 601986



SITE NAME: Kirklees Priory Gatehouse,

Kirklees Park, **Brighouse** 

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)Private OWNER TYPE:

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs in place, but beginning to fail. Feasibility and consent for office or dwelling recently obtained. Timber decay ongoing, so that work is becoming urgently necessary.

Contact: Richard Jaques 01904 601986



L-shaped Aisled Barn, SITE NAME:

> Kirklees Park, **Brighouse**

DESIGNATION: Listed Building Grade II\*

CONDITION: OCCUPANCY: Vacant C (C) PRIORITY-Private

OWNER TYPE:

Aisled barn, early C16, encased in stone during the early to mid C17. Part of a little used farm complex. Area of roof missing to north and some timber decay to frame.

Contact: Richard Jaques 01904 601986

Contact: Richard Jaques 01904 601986



Malthouse, SITE NAME:

Kirklees Park, **Brighouse** 

DESIGNATION: Listed Building Grade I

Fair CONDITION: Vacant OCCUPANCY: C (C) OWNERTYPE: Private Malthouse, late C17. It forms part of a little used farm complex. Building appears to be in a stable condition.



SITE NAME:

Scout Hall, Lee Lane, Halifax

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant PRIORITY: B (B)

OWNERTYPE: Private

Late C17 house. Part repaired with English Heritage grant, part derelict. Repair and reuse under discussion with . Conservation Officer at Calderdale.

Contact: Tammy Whitaker 01904 601880

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS



Former lock-up. SITE NAME:

121 Keighley Road, Illingworth, Halifax

DESIGNATION: Listed Building Grade II\* Very bad CONDITION:

Vacant OCCUPANCY: A(A)PRIORITY:

Local authority OWNER TYPE:

Located on the north side of the A629 Halifax -Keighley Road, the lock-up is a small two storey building of coursed sandstone walls and stone slate roof dated 1823. The building is vacant. The roof covering and roof drainage is in very poor condition.

Contact: Richard Jaques 01904 601986



Broad Bottom Old Hall, SITE NAME: Mytholmroyd.

Hebden Royd DESIGNATION: Listed Building Grade II\*

Fair CONDITION: Vacant

C(C)

Private OWNER TYPE:

PRIORITY:

Late medieval timber-framed open hall encased in stone in the mid C16. Watertight but vacant for some years. Vulnerable to decay without a sustaining use.

Contact: Tammy Whitaker 01904 601880



Barn to north west of SITE NAME: Greenwood Lee, Widdop Road,

Heptonstall

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Private

Late C16 aisled barn. Major failure of roof structure and loss of roof covering. Residential conversion of the barn and nearby outbuildings has been approved.

Contact: Tammy Whitaker 01904 601880



SITE NAME: Wainsgate Baptist Church, Wainsgate Lane, Hebden Bridge,

Wadsworth

DESIGNATION: Listed Building Grade II\*


Fair CONDITION:

Part occupied

E (E) PRIORITY-Trust OWNER TYPE:

Redundant chapel with attached Sunday School and former Minister's house dating from 1859. The Chapel is in poor condition: the school is currently used as a workshop and the former Minister's house is used as a store.

Contact: Richard Jaques 01904 601986



Church of St Mary, SITE NAME: Church Street,

Elland

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION:

F (New entry) PRIORITY:

OWNER TYPE: Religious organisation

St Mary's dates from 1180 and was most probably built by the masons who built Kirkstall Abbey. Alterations have continued over the centuries. One phase of grant-aided work has been completed and masonry repairs are now underway on the east, south and west elevations.

Contact: Richard Jaques 01904 601986

Contact: Richard Jaques 01904 601986



Hope Baptist Church, SITE NAME:

New Road. Hebden Bridge, Hebden Royd

DESIGNATION: Listed Place of Worship Grade II, CA

Very bad CONDITION: PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Chapel dating from 1858. Grant-aided repairs

to roofs are underway.

Camp at Kirklees Park, Calderdale SITE NAME:

Scheduled Monument (No. 1005806) Generally unsatisfactory DESIGNATION: CONDITION: with major localised problems PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining Private Keith Miller 01904 601990 OWNER TYPE: CONTACT:

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

CA LB/LBs LPA NP RPG SM/SMs UA WHS

with major localised problems OWNERTHE Private Declining OWNERTHE Private DESIGNATION Scheduled Monument (No. 1017655) CONDINCE Scheduled Monument (No. 1017655) CONDINCE Scheduled Monument (No. 1017655) CONDINCE DESIGNATION Scheduled Monument (No. 1017655) CONDINCE DESIGNATION COLLEGE DESIGNATION COLLEGE DESIGNATION CONDINCT Private  CONDINCT Declining OWNERTHE Private  Blackstone Edge Roman road, Ripponden DESIGNATION Scheduled Monument (No. 1005819) CONDINCE DESIGNATION Scheduled Monument (No. 1005819) CONDINCE DESIGNATION Scheduled Monument (No. 1005819) CONDINCE DESIGNATION Scheduled Monument (No. 1018560) CONDINCE DESIGNATION Scheduled Monument (No. 1005803) CONDINCE DESIGNATION Scheduled Monument (No. 1005803) CONDINCE DESIGNATION Scheduled Monument (No. 1005803) CONDINCE DECIDING DESIGNATION Scheduled Monument (No. 1005803) CONDINCE DECIDING DESIGNATION Scheduled Monument (No. 1005803) CONDINCE DECIDING DECIDI	SITE NAME:	Mill gas plant, Shaw Lodge Mills, Calderdale		
PRINCE LYBRIGHT CONTROL Scheduled Monument (No. 1017655)  Scheduled Monument (No. 1017655)  CONDITION Scheduled Monument (No. 1017655)  CONDITION Scheduled Monument (No. 1017655)  CONDITION Generally unsatisfactory with major localised problems but major localised problems (Scheduled Monument (No. 1005819)  Blackstone Edge Roman road, Ripponden  Blackstone Edge Roman road, Ripponden  Brinische Blackstone Edge Roman road, Ripponden  Brinische Blackstone Edge Roman road, Ripponden  Brinische Utility Control (No. 1005819)  CONTROL (With Miller 01904 601990)  CONTROL	DESIGNATION:	Scheduled Monument (No. 1005783)	CONDITION:	Generally unsatisfactory
OWNERTOPE  Ventilation chimney and furnace house 260m south of Park Farm, Calderdale  Designation  Scheduled Monument (No. 1017655)  CERBITION  CORRECTION  COLLABOR  THERED  CONTRIBUTION  COLLABOR  Private  COLLABOR  CENTRICIT  Reith Miller 01904 601990  CENTRICIT  CENTRI				with major localised problems
STEINAME  Ventilation chimney and furnace house 260m south of Park Farm, Calderdale  DESIGNATION  Scheduled Monument (No. 1017655)  CONDITION  COILapse  Private  COILapse  Private  COILapse  Declining  CONNECT:  Keith Miller 01904 601990  STEINAME  Blackstone Edge Roman road, Ripponden  DESIGNATION  Scheduled Monument (No. 1005819)  CONDITION  CONDIT	PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
Scheduled Monument (No. 1017655)  CONDITIONS  CONDITIO	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
with major localised problems  Private  Contract:  Reith Miller 01904 601990  Selecting  Contract:  Reith Miller 01904 601990  Contract:  Reith Miller	SITE NAME:	Ventilation chimney and furnace house 260	n south of Park F	arm, Calderdale
PRINCENDAL VOLUMENABLETY:  CONTROLL PROJECT PRIVATE  CONTROLL PROJECT PRIVATE  CONTROLL PROJECT PRIVATE  CONTROLL PROJECT PRIVATE  Blackstone Edge Roman road, Ripponden  Scheduled Monument (No. 1005819)  CONDITION  Scheduled Monument (No. 1005819)  CONDITION  FRINCIPAL VOLUMENABLETY:  CONTROLL  CONTROLL  CONTROLL  CONTROLL  Keith Miller 01904 601990  CONTROLL  Keith Miller 01904 601990  CONTROLL  Keith Miller 01904 601990  CONTROLL	DESIGNATION:	Scheduled Monument (No. 1017655)	CONDITION:	Generally unsatisfactory
Blackstone Edge Roman road, Ripponden  Scheduled Monument (No. 1005819)  CONDITION  Scheduled Monument (No. 1005819)  CONDITION  CON				with major localised problems
Blackstone Edge Roman road, Ripponden  DESCHARION: Scheduled Monument (No. 1005819) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPLA VALUERABULTY: Detensive vehicle damage/erosion THEND: Declining  CONTRACT: Keith Miller 01904 601990  STET NAME: Cairnfield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden  DESCHARION: Scheduled Monument (No. 1018560) CONDITION: With major localised problems  PRINCIPLA VALUERABULTY: Arable ploughing TREND: Declining  CONTRACT: Keith Miller 01904 601990  STET NAME: Oxygrains packhorse bridge, Rishworth, Ripponden  DESCHARION: Scheduled Monument (No. 1005803) CONDITION: Generally unsatisfactory with major localised problems  DESCHARION: Scheduled Monument (No. 1005803) CONDITION: Generally unsatisfactory with major localised problems  DESCHARION: Declining  CONTRACT: Keith Miller 01904 601990  STET NAME: OXYGRAINS PRINCIPLA VIOLENCE CONTRACT: Keith Miller 01904 601990  STET NAME: Akroydon  DESCHARION: CONTRACT: Keith Miller 01904 601990  STET NAME: Akroydon  DESCHARION: CONSERVATION PREND: Deteriorating  DESCHARION: CONSERVATION PREND: Deteriorating  DESCHARION: Very bad  DESCHARION: CONSERVATION PREND: NOW BRITTON NEW BRITTON NOW	PRINCIPAL VULNERABILITY:	Collapse	TREND:	
Scheduled Monument (No. 1005819)  Scheduled Monument (No. 1005819)  Extensive vehicle damage/erosion  TREND  Declining  OWNERTIFIE  Utility  Cairrifield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden  DESIGNATION:  Scheduled Monument (No. 1018560)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  OWNERTIFIE  Private  Oxygrains packhorse bridge, Rishworth, Ripponden  DESIGNATION:  Scheduled Monument (No. 1005803)  STENAME:  Oxygrains packhorse bridge, Rishworth, Ripponden  DESIGNATION:  Scheduled Monument (No. 1005803)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  DESIGNATION:  Scheduled Monument (No. 1005803)  CONDITION:  Generally unsatisfactory with major localised problems  DESIGNATION:  DEClining  OWNERTIFIE  Akroydon  DESIGNATION:  CONTACT:  Keith Miller 01904 601990  TREND:  Deteriorating  TREND:  Deteriorating  TREND:  Deteriorating  TREND:  Deteriorating  Deteriorating  TREND:  Deteriorating  Deteriorating  TREND:  DETERIORATION:  Kate Peach (LPA) 01422 392267  NEW BNITEM:  No  STENAME:  Todmorden  DESIGNATION:  CONTACT:  Kate Peach (LPA) 01422 392267  NEW BNITEM:  No  Deteriorating  DETERIORATION:  CONTACT:  Kate Peach (LPA) 01422 392267  NEW BNITEM:  No  DETERIORATION:  CONTACT:  No  TREND:  Deteriorating  DETERIORATION:  CONTACT:  Kate Peach (LPA) 01422 392267  NEW BNITEM:  No  DETERIORATION:  CONTACT:  No  TREND:  Deteriorating  DETERIORATION:  CONTACT:  DETERIORATION:  DETERIORATION:  CONTACT:  DETER	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
Scheduled Monument (No. 1005819)  Scheduled Monument (No. 1005819)  Extensive vehicle damage/erosion  TREND  Declining  CONTACT:  Keith Miller 01904 601990  CONTACT:  Contact Miller 01904 601990  Contact Miller 0190				
Dut with significant localised problems Declining Devinentive Utility Declining Devinentive Utility Declining Declin	SITE NAME:			
PRINCIPAL VULNERABILITY: Extensive vehicle damage/erosion TRIND: Declining OWNERTHYPE: Utility CONTACT: Keith Miller 01904 601990  STEINAME: Cairnfield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden Designation: Scheduled Monument (No. 1018560) CONDITION: Generally unsatisfactory with major localised problems Private Private CONTACT: Keith Miller 01904 601990  STEINAME: Oxygrains packhorse bridge, Rishworth, Ripponden Designation: Scheduled Monument (No. 1005803) CONDITION: Generally unsatisfactory with major localised problems Private Utility CONTACT: Keith Miller 01904 601990  STEINAME: Oxygrains packhorse bridge, Rishworth, Ripponden Designation: Extensive visitor erosion TRIND: Declining With major localised problems Private Utility CONTACT: Keith Miller 01904 601990  STEINAME: Akroydon  DESIGNATION: Conservation Area CONDITION: Poor WULNERABILITY: Medium TRIND: Deteriorating New BITRY: Yes  STEINAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  DESIGNATION: Conservation Area CONDITION: Very bad  DESIGNATION: Conservation Area CONDITION: Very bad  DESIGNATION: Conservation Area CONDITION: New BITRY: No  STEINAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Very bad  DESIGNATION: Conservation Area CONDITION: New BITRY: No	DESIGNATION:	Scheduled Monument (No. 1005819)	CONDITION:	
CAITREE Utility CONTACT: Keith Miller 01904 601990  STEENAME: Cairnfield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden  DESIGNATION: Scheduled Monument (No. 1018560) CONDITION: Generally unsatisfactory with major localised problems  PRINCERNAL VALNERABILITY: A rable ploughing THEND: Declining  OWNER TYPE: Oxygrains packhorse bridge, Rishworth, Ripponden  DESIGNATION: Scheduled Monument (No. 1005803) CONDITION: Generally unsatisfactory with major localised problems  PRINCEL VALNERABILITY: Extensive visitor erosion TREND: Declining  OWNER TYPE: Utility CONTACT: Keith Miller 01904 601990  STEENAME: Akroydon  DESIGNATION: Conservation Area CONDITION: Poor  VALNERABILITY: Medium TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW BYTEM: Yes  STEENAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  VALNERABILITY: No  STEENAME: Kate Peach (LPA) 01422 392267  NEW BYTEM: No  STEENAME: Todmorden  STEENAME: Todmorden  STEENAME: Todmorden  STEENAME: Todmorden  STEENAME: Todmorden  STEENAME: Todmorden  DESIGNATION: Conservation Area CONDITION: No  STEENAME: Todmorden  STEENAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Poor  NEW BYTEM: No  STEENAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Poor  NEW BYTEM: No  STEENAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Poor  NEW BYTEM: Deteriorating  DESIGNATION: Conservation Area CONDITION: Poor  NEW BYTEM: Deteriorating  DESIGNATION: Conservation Area CONDITION: Poor		Francisco vehicle de la		9 ,
STEINAME Cairnfield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden  DESIGNATION: Scheduled Monument (No. 1018560) condition: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABUTY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Keith Miller 01904 601990  STEINAME Oxygrains packhorse bridge, Rishworth, Ripponden  DESIGNATION: Scheduled Monument (No. 1005803) condition: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABUTY: Extensive visitor erosion TREND: Declining  OWNIRTYPE: Utility contact: Keith Miller 01904 601990  STEINAME: Akroydon  DESIGNATION: Conservation Area condition: Poor  VULNERABUTY: Medium TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267 NEW BITTEY: Yes  STEINAME: Elland  DESIGNATION: Conservation Area condition: Very bad  VULNERABUTY: Low TREND: Deteriorating  Kate Peach (LPA) 01422 392267 NEW BITTEY: No  STEINAME: Todmorden  STEINAME: Todmorden  DESIGNATION: Conservation Area condition: Poor  Very bad  VULNERABUTY: No  STEINAME: Todmorden  DESIGNATION: Conservation Area condition: Poor  Very bad  VULNERABUTY: No  STEINAME: Todmorden  DESIGNATION: Conservation Area condition: Poor  Very bad  Very bad	PRINCIPAL VULNERABILITY:	-		<u> </u>
Scheduled Monument (No. 1018560)  STREND:  Declining  CONTACT:  Keith Miller 01904 601990  STREND:  DESIGNATION:  Scheduled Monument (No. 1005803)  SCHEDULER MONUMER TYPE  Extensive visitor erosion  TREND:  Declining  CONTACT:  Keith Miller 01904 601990  STREND:  Declining  CONTACT:  Keith M	OWNER TYPE:	Otility	CONTACT:	Keith Miller 01904 601990
With major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing Private  Oxygrains packhorse bridge, Rishworth, Ripponden  STE NAME: Oxygrains packhorse bridge, Rishworth, Ripponden  Scheduled Monument (No. 1005803) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Extensive visitor erosion  TREND: Declining OWNERTYPE: Utility  CONTACT: Keith Miller 01904 601990  STE NAME: Akroydon  DESIGNATION: Conservation Area  CONDITION: Poor  VULNERABILITY: Medium  TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY: Yes  STE NAME: Elland  DESIGNATION: Conservation Area  CONDITION: Very bad  Very bad	SITE NAME:	Cairnfield on Ringstone Edge Moor, 240m s	outh west of Clay	House, Ripponden
Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Keith Miller 01904 601990  SITE NAME: Oxygrains packhorse bridge, Rishworth, Ripponden  DESIGNATION: Scheduled Monument (No. 1005803) CONDTION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Extensive visitor erosion TREND: Declining OWNERTYPE Utility CONTACT: Keith Miller 01904 601990  SITE NAME: Akroydon  DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: Medium TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: Yes  SITE NAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: Low TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: No  SITE NAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: No  TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: No  SITE NAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Poor  VULNERABILITY: No  DESIGNATION: CONSERVATION Area CONDITION: Poor  VULNERABILITY: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor  VULNERABILITY: DESIGNATION: CONSERVATION Area CONDITION: Poor  VULNERABILITY: DESIGNATION: DETERMINENTION: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor  VULNERABILITY: DESIGNATION: DETERMINENTION: DETERMINE	DESIGNATION:	Scheduled Monument (No. 1018560)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
OXYGRATYPE  OXYGRAINS packhorse bridge, Rishworth, Ripponder  DESIGNATION:  Scheduled Monument (No. 1005803)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Extensive visitor erosion  TREND:  Declining  OWNERTYPE  Utility  CONTACT:  Keith Miller 01904 601990   Akroydon  UNINERABILITY:  CONSERVATION:  CONSERVATION:  CONSERVATION:  Medium  TREND:  Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  Yes  SITE NAME:  Elland  DESIGNATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  NO  TREND:  Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  NO  TREND:  Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  NO  TREND:  Deteriorating  CONDITION:  POOF  UNINERABILITY:  NO  TREND:  Deteriorating  CONDITION:  POOF  UNINERABILITY:  DESIGNATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  CONSERVATION:  DESIGNATION:  CONSERVATION:  CONDITION:  POOF  UNINERABILITY:  DESIGNATION:  CONSERVATION:  CONDITION:  DESIGNATION:  CONDITION:  DESIGNATION:  CONDITION:  DESIGNATION:  CONDITION:  DESIGNATION:  DESIG	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
DESIGNATION:  Scheduled Monument (No. 1005803)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Extensive visitor erosion  TREND: Declining  OWNER TYPE:  Utility  CONTACT:  Keith Miller 01904 601990   STE NAME:  Akroydon  DESIGNATION: Conservation Area  CONDITION: Poor  VULNERABILITY: Medium TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY: Yes  STE NAME:  Elland  DESIGNATION: VULNERABILITY: LOW TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY: No  STE NAME: Todmorden  DESIGNATION: CONSERVATION: CONSERVATION: CONTACT: CONSERVATION: CONSERVATION: CONSERVATION: CONDITION: CONDIT	OWNER TYPE:		CONTACT:	Keith Miller 01904 601990
PRINCIPAL VULNERABILITY: Extensive visitor erosion TREND: Declining OWNERTYPE: Utility CONTACT: Keith Miller 01904 601990  SITE NAME: Akroydon  SITE NAME: CONSERVATION Area CONDITION: POOR VULNERABILITY: Medium TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: Yes  SITE NAME: Elland  DESIGNATION: CONSERVATION Area CONDITION: Very bad  VULNERABILITY: LOW TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: NO  SITE NAME: Todmorden  SITE NAME: CONSERVATION Area CONDITION: Poor VULNERABILITY: NO  SITE NAME: Todmorden  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: Deteriorating CONTACT: NEW ENTRY: NO  SITE NAME: Todmorden  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating	SITE NAME:	Oxygrains packhorse bridge, Rishworth, Rip	pponden	
PRINCIPAL VULNERABILITY: Extensive visitor erosion TREND: Declining OWNERTYPE: Utility CONTACT: Keith Miller 01904 601990  SITE NAME: Akroydon  SITE NAME: CONSERVATION Area CONDITION: POOR VULNERABILITY: Medium TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: Yes  SITE NAME: Elland  DESIGNATION: CONSERVATION Area CONDITION: Very bad  VULNERABILITY: LOW TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: NO  SITE NAME: Todmorden  SITE NAME: CONSERVATION Area CONDITION: Poor VULNERABILITY: NO  SITE NAME: Todmorden  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: Deteriorating CONTACT: NEW ENTRY: NO  SITE NAME: Todmorden  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: LOW TREND: Deteriorating	DESIGNATION:	Scheduled Monument (No. 1005803)	CONDITION:	Generally unsatisfactory
PRINCIPAL VULNERABILITY: Extensive visitor erosion TREND: Declining OWNER TYPE: Utility CONTACT: Keith Miller 01904 601990  SITE NAME: Akroydon  DESIGNATION: COnservation Area CONDITION: Poor VULNERABILITY: Medium TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: Yes  SITE NAME: Elland  DESIGNATION: COnservation Area CONDITION: Very bad VULNERABILITY: Low TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY: No  SITE NAME: Todmorden  SITE NAME: Todmorden  DESIGNATION: COnservation Area CONDITION: Poor VULNERABILITY: Low CONSERVATION: Poor VULNERABILITY: Low CONSERVATION: Deteriorating  SITE NAME: Todmorden  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: Low CONSERVATION: Deteriorating  DESIGNATION: CONSERVATION Area CONDITION: Poor VULNERABILITY: Low Deteriorating				·
OWNERTYPE:  Utility  CONTACT: Keith Miller 01904 601990  SITE NAME:  Akroydon  DESIGNATION:  CONDITION:  Medium  TREND:  Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  Yes  SITE NAME:  Elland  DESIGNATION:  CONSERVATION Area  CONDITION:  Very bad  VULNERABILITY:  LOW  TREND:  Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY:  NO  SITE NAME:  Todmorden  DESIGNATION:  CONSERVATION:  CONSERVATION:  CONDITION:  FOOR  VULNERABILITY:  LOW  TREND:  Deteriorating  CONDITION:  Poor  VULNERABILITY:  LOW  TREND:  DETERIORATION:  VULNERABILITY:  DESIGNATION:  VULNERABILITY:  LOW  TREND:  Deteriorating	PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	
DESIGNATION: Conservation Area CONDITION: Poor  VULNERABILITY: Medium TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  SITE NAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: Low TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY?: No  SITE NAME: Todmorden  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: Low TREND: Deteriorating  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: Low TREND: Deteriorating	OWNER TYPE:		CONTACT:	
DESIGNATION: Conservation Area CONDITION: Poor  VULNERABILITY: Medium TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  SITE NAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: Low TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY?: No  SITE NAME: Todmorden  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: Low TREND: Deteriorating  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: Low TREND: Deteriorating				
WULNERABILITY: Medium  Kate Peach (LPA) 01422 392267  NEW ENTRY?: Yes  SITE NAME: Elland  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: Low  TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY?: No  SITE NAME: Todmorden  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: Low  TREND: Deteriorating  DESIGNATION: CONSERVATION Area  DESIGNATION: CONSERVATION Area  Low  TREND: Deteriorating	SITE NAME:	·		
CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY: Yes  SITE NAME:  Elland  Conservation Area  CONDITION: Very bad  VULNERABILITY: Low TREND: Deteriorating CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY: No  SITE NAME: Todmorden  DESIGNATION: COnservation Area  CONDITION: Poor  VULNERABILITY: Low TREND: Deteriorating  CONDITION: Deteriorating  CONDITION: Deteriorating  CONDITION: Deteriorating	DESIGNATION:			
Elland  DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: LOW TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267 NEW ENTRY?: NO  SITE NAME: Todmorden  DESIGNATION: CONSErvation Area CONDITION: Poor  VULNERABILITY: LOW TREND: Deteriorating	VULNERABILITY:		TREND:	
DESIGNATION: Conservation Area CONDITION: Very bad  VULNERABILITY: LOW TREND: Deteriorating  CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY?: No  SITE NAME: Todmorden  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: LOW TREND: Deteriorating	CONTACT:	Kate Peach (LPA) 01422 39226/	NEW ENTRY?:	Yes
VULNERABILITY:  LOW TREND: Deteriorating  CONTACT:  Kate Peach (LPA) 01422 392267  NEW ENTRY: No  SITE NAME:  Todmorden  DESIGNATION: COnservation Area CONDITION: Poor  VULNERABILITY: LOW TREND: Deteriorating	SITE NAME:	Elland		
CONTACT: Kate Peach (LPA) 01422 392267  NEW ENTRY?: NO  SITE NAME:  Todmorden  DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: Low TREND: Deteriorating	DESIGNATION:	Conservation Area	CONDITION:	Very bad
SITE NAME: Todmorden  DESIGNATION: Conservation Area CONDITION: Poor VULNERABILITY: Low TREND: Deteriorating	VULNERABILITY:	Low	TREND:	Deteriorating
DESIGNATION: Conservation Area CONDITION: Poor vulnerability: Low Trend: Deteriorating	CONTACT:	Kate Peach (LPA) 01422 392267	NEW ENTRY?:	No
VULNERABILITY: Low TREND: Deteriorating	SITE NAME:	Todmorden		
•	DESIGNATION:	Conservation Area	CONDITION:	Poor
•	VULNERABILITY:	Low	TREND:	Deteriorating
	CONTACT:	Kate Peach (LPA) 01422 392267	NEW ENTRY?:	-


## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREVIATIONS IATIONS
Conservation Area
Listed Building/s
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument/s
Unitary Authority
World Heritage Site CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

### **KIRKLEES**



SITE NAME: Milnsbridge House, 2-6 Dowker Street,

Huddersfield

DESIGNATION: Listed Building Grade II\*, CA

Fair CONDITION:

OCCUPANCY: Part occupied

PRIORITY: E (E) Private OWNER TYPE

Mid C18 house now in engineering use. Pediments conceal modern flat roof. Scheme approved for residential conversion but works not yet commenced.

Contact: Tammy Whitaker 01904 601880



18-20 St George's Square, SITE NAME: Huddersfield

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Vacant OCCUPANCY: F (C) PRIORITY:

OWNERTYPE: Company

Part of Tite's Building Built as offices and warehousing (Sir William Tite, 1852). Planning permission and listed building consent granted for conversion to student accommodation. Work currently in progress and due to be completed September 2011.

Contact: Kathryn Gibson 01904 601939



SITE NAME: Westwood Mills,

Lowestwood Lane, Linthwaite,

Huddersfield

Listed Building Grade II\*, CA DESIGNATION:

Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)Company OWNER TYPE:

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering. Consents for conversion to residential use and new build residential development approved October 2005.

Redundant church and attached school buildings to rear

dated 1829. Largely unaltered and retaining box pews in

the body of the church and original windows throughout. Water penetration has resulted in patches of timber

decay and a falling roof truss. English Heritage supporting

Contact: Tammy Whitaker 01904 601880



Hopton Congregational Church, SITE NAME:

Calder Road, Mirfield

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant

C (C) PRIORITY Private OWNER TYPE:

Contact: Kathryn Gibson 01904 601939



Church of the Holy Spirit, SITE NAME:

> Bath Road, Heckmondwicke, Batley and Liversdege

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION:

PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Roman Catholic church, 1914-15, with minor late C20 alterations. Byzantine revival style. Grant offered for roof and window repairs.

residential conversion.



Parish Church of St Peter, SITE NAME:

> Kirkgate, Birstall,

Batley and Liversedge

Listed Place of Worship Grade II\*, CA DESIGNATION:

Poor CONDITION:

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

One of the earliest churches to occupy the present site of St Peter's was built circa 1100. The present church was essentially rebuilt in the 1860s. Grant aid has been offered for roof and masonry repairs.

Contact: Richard Jaques 01904 601986

Contact: Richard Jaques 01904 601986

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS



SITE NAME: Church of St Aidan, Radcliffe Street, Skelmanthorpe, Denby Dale

and chimney. Further roof repairs will be required in the future.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: POC

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986

St Aidan's was opened on September 28 1895.

Urgent repairs have been carried out to the bell-cote



SITE NAME: Christ Church,
Staincliffe Road,
Dewsbury

On April 13 1866 the foundation stone of the new church of Christ Church, Staincliffe, was laid and the church consecrated one and a half years later. The Lady Chapel was re-ordered by Sir Charles Nicholson and dedicated on 9 November 1919 as the parish War Memorial. Grant-aided repairs are underway to the tower roofs and masonry

DESIGNATION: Listed Place of Worship Grade II, CA repairs are underway to the tower roofs and masonry.

CONDITION: Poor

PRIORITY: F (New entry)

OWNERTYPE: Religious organisation

Contact: Richard Jaques 01904 601986

Small mid-C19 Apostolic Church constructed from

ashlar to facade, with rock-cut stone elsewhere and rusticated quoins. Simple rectangular plan with four



SITE NAME: The Apostolic Church, Mountjoy Road, Huddersfield

bay facade. In poor condition.

DESIGNATION: Listed Place of Worship Grade II, CA

condition: Poor

PRIORITY: C (New entry)

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Cuthbert, Grimscar Avenue, Huddersfield Local fundraising provided the money to build the church in the 1920s. The west end was finally completed in 1956. Grant-aided repairs are underway to roofs and parapets.

DESIGNATION: Listed Place of Worship Grade II, CA

condition: Poor

PRIORITY: F (New entry)

OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St John, St John's Road, Huddersfield St John's was built in 1852/3. Four high quality memorial stained glass windows were added in 1923. Grant aid was declined and the future of the church is uncertain.

DESIGNATION: Listed Place of Worship Grade II\*, CA

condition: Very bad

PRIORITY: A (New entry)

OWNER TYPE: Religious organisation

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Peter, Kirkgate, Huddersfield The present building is the third church to have stood on the site and was built in 1836. Grant-aided repairs are underway to the plaster ceilings and a grant has been offered towards masonry repairs and vestry roofs.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Poor

PRIORITY: F (New entry)

OWNERTYPE: Religious organisation

Contact: Richard Jaques 01904 601986

## SITE NAME:

## Late prehistoric enclosed settlement on Castle Hill, 550m north of Broadstone Lodge, Denby Dale

DESIGNATION:	Scheduled Monument (No. 1018554)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS

CA Conservation Area
LB/LBs Listed Building/s
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM/SMs Scheduled Monument/s
UA Unitary Authority
WHS WOrld Heritage Site

SITE NAME:	Thornhill Hall moat and sites of formal gardens and bowling green, and remnant of pre-seventeenth century open-field system, Kirklees			
DESIGNATION:	Scheduled Monument (No. 1009930)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining	
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Crosland Lower Hall moated site, Meltham			
DESIGNATION:	Scheduled Monument (No. 1013896)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Castle Hall Hill motte and bailey castle, Mirfie	ld		
DESIGNATION:	Scheduled Monument (No. 1009929)	CONDITION:	Generally unsatisfactory	
	,		with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990	
SITE NAME:	Birkby, Huddersfield			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	High	TREND:	Deteriorating	
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No	
SITE NAME:	Dewsbury			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No	
SITE NAME:	Edgerton, Huddersfield			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No	
SITE NAME:	Holmfirth			
DECIGNATION	Conservation Area	CONDITION:	Poor	
DESIGNATION:				
DESIGNATION: VULNERABILITY:	High	TREND:	No significant change	

## **LEEDS**



Stank Hall quasi-manorial site, SITE NAME: Dewsbury Road,

Beeston

DESIGNATION: Listed Building Grade II\*, SM, CA

Very bad CONDITION: OCCUPANCY: Vacant A (A) PRIORITY:

OWNERTYPE: Local authority

Remains of a major yeoman farm of sub-manorial type, with surviving barn of C15 of eight bays. Southern-most bays rebuilt in stone mid C17. Roof slates missing.

Contact: Richard Jaques 01904 601986

## PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## **ABBREVIATIONS**

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS



Temple Works gate lodge, SITE NAME: Marshall Street, Holbeck

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY: OWNERTYPE: Company Small derelict gate lodge to spinning, water, steam and flax mill of 1836-40 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

Contact: Kathryn Gibson 01904 601939



Ledston Hall, SITE NAME: Hall Lane. Ledston

DESIGNATION: Listed Building Grade I, RPG II

Fair CONDITION:

Part occupied OCCUPANCY:

E (E) PRIORITY: Private OWNER TYPE:

Country house now partly subdivided into flats, situated in late C17/C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. Long term future under consideration through preparation of a conservation plan and feasibility study.

Contact: Tammy Whitaker 01904 601880

Townscape Heritage Initiative programme.

Cloth hall built in 1711. Derelict and deteriorating.

An exceptionally rare example of an early C18 arcaded

which is being proposed for the Heritage Lottery Fund

cloth hall. Part of generally dilapidated block along Kirkgate,



First Leeds White Cloth Hall, SITE NAME: 98-101 (consec) Kirkgate, Leeds

DESIGNATION: Listed Building Grade II\*, CA

Very bad CONDITION: Vacant OCCUPANCY: PRIORITY-C(C)OWNER TYPE: Company

Contact: Kathryn Gibson 01904 601939



Temple Mill, SITE NAME: Marshall Street, Holbeck,

Leeds

DESIGNATION: Listed Building Grade I, CA

CONDITION: Very bad Vacant F (F) PRIORITY-OWNERTYPE: Company

Brick-vaulted former spinning shed by Bonomi, Egyptian facade, 1836-40. Brick-vaulted roof with circular rooflights. Failure of tie bar has caused collapse of two front bays. Other bays vulnerable to similar failure. Remedial scheme agreed and underway.

Contact: Giles Proctor 01904 601981

Flax mill of 1838 with later infill in south block.

A permanent roof has recently been erected.

Housing development agreed, but not yet underway.



Hunslet Mill, SITE NAME:

Goodman Street, Hunslet, Leeds

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor Vacant OCCUPANCY: D (D) PRIORITY OWNER TYPE: Company

Contact: Kathryn Gibson 01904 601939



St Marys Convent Church SITE NAME: (Mount Saint Mary), Church Road, Richmond Hill, Leeds

DESIGNATION: Listed Building Grade II

Poor CONDITION: Vacant PRIORITY: D (D) OWNER TYPE: Company

Redundant Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing, the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development has received consent.

Contact: Tammy Whitaker 01904 601880

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS



SITE NAME:	Memorial to Queen Victoria,
	Woodhouse Lane, Woodhouse Moor,
	Leeds

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Poor N/A OCCUPANCY: C (C)

OWNER TYPE: Local authority

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Tammy Whitaker 01904 601880



Rothwell Castle, SITE NAME: Church Street (off), Rothwell

DESIGNATION: Scheduled Monument, CA

Poor CONDITION: N/A C(C)PRIORITY: OWNERTYPE: Private

Ruined chapel to medieval manor complex. C14. Masonry needs to be consolidated. The site is part of an active Local Heritage Initiative scheme to investigate its surroundings.

Contact: Richard Jaques 01904 601986



Gazebo north of Clumpcliffe SITE NAME: Farmhouse, Methley Lane, Methley, Rothwell

Listed Building Grade II\* DESIGNATION:

Very bad CONDITION: Vacant OCCUPANCY: B (B) PRIORITY: Private OWNER TYPE:

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs has failed. Residential conversion agreed. Work still not implemented other than removal of debris. Site fenced.

Contact: Tammy Whitaker 01904 601880



Thorpe Hall, SITE NAME: Middleton Lane, Thorpe on the Hill

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant A(A)PRIORITY: Private OWNER TYPE:

Former farmhouse, 1735. Unitary Development Plan proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling collapsed in one room. Roof holed.

Contact: Tammy Whitaker 01904 601880



Church of the Epiphany, SITE NAME: Beech Lane

Superb 1930s Art Deco church. Roofs and windows in poor condition. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I

CONDITION:

D (New entry) PRIORITY:

OWNER TYPE:

Religious organisation Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Mary, Church Street

Spire and tower repairs grant-aided. Further work required.

DESIGNATION: Listed Place of Worship Grade II CONDITION: D (New entry) PRIORITY:

OWNERTYPE: Religious organisation

Contact: Richard Jaques 01904 601986

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.



Church of St Stephen, SITE NAME: Morris Lane

Original church dates from 1829 but a new spire was erected in the 1830s after a lightening strike. Grant aid has been offered for chancel roof repairs.

DESIGNATION: Listed Place of Worship Grade II

Very bad CONDITION: D (New entry) PRIORITY: Religious organisation OWNER TYPE:

Contact: Richard Jaques 01904 601986



SITE NAME: Church of St Mark, St Mark's Road

Commissioners' Church, in very poor condition, taken over by independent evangelical group. Grant offered.

DESIGNATION: Listed Place of Worship Grade II

Very bad D (New entry) PRIORITY:

Contact: Richard Jaques 01904 601986 Religious organisation OWNER TYPE:



Church of St Wilfrid, SITE NAME:

Significant 1930s Expressionist style church. Roofs in very poor structural condition. Major grant offered for repair. Selby Road

DESIGNATION: Listed Place of Worship Grade II\*

Very bad CONDITION: D (New entry) PRIORITY:

OWNER TYPE: Religious organisation Contact: Richard Jaques 01904 601986

STE NAME:	between Aberford and a quarry 590m north of		, ,
DESIGNATION:	Scheduled Monument (No. 1016951)	CONDITION:	Generally satisfactory

but with significant localised problems

Declining PRINCIPAL VULNERABILITY: Scrub / tree growth TREND:

Keith Miller 01904 601990 Private OWNER TYPE: CONTACT

SITE NAME:	Linear earthwork, part of the Aberford Dyke system,
	extending 770m east from Humphrey Dale Cottage, Aberford

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Keith Miller 01904 601990	DESIGNATION:	Scheduled Monument (No. 1016953)	CONDITION:	Extensive significant problems
OWNER TYPE Private CONTACT: Keith Miller 01904 601990	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

#### Dalton Parlours Roman villa and Iron Age settlement, Bramham cum Oglethorpe SITE NAME:

DESIGNATION:	Scheduled Monument (No. 1017560)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990

#### Cairn west of Craven Hall Hill, Leeds SITE NAME

DESIGNATION:	Scheduled Monument (No. 1010355)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990

#### Medieval farmstead in Ireland Wood, I50m north east of Cookridge Hospital, Leeds SITE NAME:

DESIGNATION:	Scheduled Monument (No. 1018553)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Keith Miller 01904 601990

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE:

If the priority category has changed since the 2010 register, the previous category is given in brackets.

## **ABBREVIATIONS**

SITE NAME:	Stone hut circle settlement in Clayton Woo	od on the south w	est side of Iveson Drive, Leeds
DESIGNATION:	Scheduled Monument (No. 1018814)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Stone hut circle settlement in Iveson Wood	l, Leeds	
DESIGNATION:	Scheduled Monument (No. 1018815)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Linear earthworks known as Woodhouse Moor Rein and South Dyke, part of the Aberford Dyke system, Lotherton cum Aberford		
DESIGNATION:	Scheduled Monument (No. 1016954)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Howley Hall: a 16th century country house	and gardens, Mor	ley
DESIGNATION:	Scheduled Monument (No. 1016323)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990
SITE NAME:	Settlement site revealed by aerial photography near Moat House, Walton		
DESIGNATION:	Scheduled Monument (No. 1003801)	CONDITION:	Extensive significant problems
	A 11 1 12		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining



SITE NAME: High Royds Hospital, Aireborough DESIGNATION: Registered Park and Garden Grade II, also I LB Extensive significant problems CONDITION: VULNERABILITY: High Declining TREND: OWNER TYPE: Mixed, multiple owners

The grounds of an echelon-style psychiatric hospital, opened in 1888, including airing courts, sports grounds, woodland and parkland. Hospital under conversion to residential use including extensive new build within the grounds. Historic landscape now significantly compromised and peripheral areas neglected.



Oulton Hall SITE NAME DESIGNATION: Registered Park and Garden Grade II, also CA, 2 LBs Generally satisfactory CONDITION: but with significant localised problems vulnerability: Low

Park and pleasure grounds laid out in 1809-10 in part to designs by Humphry Repton, with mid C19 additions by WA Nesfield. Chequered C20 history and now split as a hotel and golf course. De Vere hotel group restored the main building. The garden layout survives in part but golf course and new development predominate.

Contact: Andy Wimble 01904 601970

Contact: Andy Wimble 01904 601970

Buslingthorpe,	Leeds
	Buslingthorpe,

DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Richard Taylor (LPA) 0113 247 8145	NEW ENTRY?:	No

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Unknown

Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

**ABBREVIATIONS** CA LB/LBs LPA NP RPG SM/SMs Conservation Area Conservation Area Listed Building/s Local Planning Authority National Park Registered Park and Garden Scheduled Monument/s Unitary Authority World Heritage Site UA WHS

SITE NAME:	Chapeltown, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Richard Taylor (LPA) 0113 247 8145	NEW ENTRY?:	No
SITE NAME:	Holbeck, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Richard Taylor (LPA) 0113 247 8145	NEW ENTRY?:	No
SITE NAME:	Stank Hall, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Richard Taylor (LPA) 0113 247 8145	NEW ENTRY?:	No



#### Malt House approx 15 metres south SITE NAME: west of Blacker Hall Farmhouse, Crigglestone Branch Road, Chevet

Listed Building Grade II\* DESIGNATION: Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY: Private OWNER TYPE:

Rare early-mid C17 malt-house located approx 15m south west of Blacker Hall Farmhouse. Impressive group value. Recent partial collapse of front wall, roof covering missing, roof timbers collapsing. Imminent danger of total collapse. Local Authority working closely with owner to find a sustainable future use.



#### Pontefract Castle, SITE NAME: **Pontefract**

DESIGNATION: Scheduled Monument Poor CONDITION: OCCUPANCY: N/A B (B) PRIORITY OWNER TYPE: Local authority

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey has been prepared. Grant has been awarded for the first two phases of repair which are currently underway.

Contact: Richard Jaques 01904 601986

Contact: Richard Jaques 01904 601986



Dovecote approximately SITE NAME: 100 metres south of Sharlston Hall, The Green, Sharlston

DESIGNATION: Listed Building Grade II, SM Poor CONDITION: OCCUPANCY: N/A

Stone dovecote with pyramidal roof of uncertain date. Grant has recently been awarded for repairs which have commenced. The roof has been completed and is now in good order.

F (B) OWNERTYPE: Private Contact: Richard Jaques 01904 601986



Quaker Meeting House, SITE NAME: Pontefract Road, Ackworth

A two storey building in classical style constructed in 1847 from sandstone ashlar with a slate roof. It is currently in use as part of a school. Low level stonework is badly eroding. Two windows are broken. Roof in poor repair.

DESIGNATION: Listed Place of Worship Grade II\*, CA Poor CONDITION: PRIORITY: C (New entry)

Religious organisation

Contact: Richard Jaques 01904 601986

## PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: If the priority category has changed since the 2010 register, the previous category is given in brackets.

## ABBREVIATIONS



Church St Peter, SITE NAME: Church Lane. South Hiendley

Medieval village church, roofs in poor condition. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION:

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Giles Proctor 01904 601981

SITE NAME:	Newland Preceptory, Newland with Woodhouse Moor				
DESIGNATION:	Scheduled Monument (No. 1012153)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Sharlston Common coal and ironstone workings, Sharlston				
DESIGNATION:	Scheduled Monument (No. 1018399)	CONDITION:	Generally satisfactory		
			but with significant localised problems		
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Site of post-medieval tannery, Felkirk, South	n Hiendley			
DESIGNATION:	Scheduled Monument (No. 1005775)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990		
	Date to the second of		C d Will IM d		
SITE NAME:	Prehistoric enclosed settlement known as S	South Kirkby Cam	· · · · · · · · · · · · · · · · · · ·		
DESIGNATION:	Scheduled Monument (No. 1018818)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Earthwork west of Ferrybridge, Knottingley, Wakefield				
DESIGNATION:	Scheduled Monument (No. 1005789)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Keith Miller 01904 601990		
SITE NAME:	Ferrybridge near Knottingley, Wakefield				
DESIGNATION:	Scheduled Monument (No. 1005799)	CONDITION:	Generally satisfactory		
	,		but with significant localised problems		
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining		
OWNER TYPE:	Local Authority	CONTACT:	Keith Miller 01904 601990		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA
LB/LBs
LPA
NP
RPG
SM/SMs
UA
WHS

TREND:

## WAKEFIELD / BARNSLEY / KIRKLEES



Bretton Hall, West Bretton SITE NAME: DESIGNATION: Registered Park and Garden Grade II, also CA, 23 LBs Generally satisfactory CONDITION: but with significant localised problems VULNERABILITY: Medium

**Improving** 

OWNER TYPE: Mixed, multiple owners

Pleasure grounds of late C18 and early C19, parkland of C18 with earlier origins. Associations with Richard Woods and Robert Marnock. Part of parkland accommodates Yorkshire Sculpture Park, part country park. Hall is owned by Wakefield Council who are negotiating with potential purchaser of the Hall for hotel use. A Conservation Management Plan for the whole landscape has now been completed. Significant conservation and repair works are well under way including the restoration of dramatic views across the lakes.

YORK (UA)					
SITE NAME:	Strensall, York				
DESIGNATION:	Conservation Area	CONDITION:	At risk		
VULNERABILITY:	Unknown	TREND:	No significant change		
CONTACT:	Leigh Weston (LPA) 01904 551329	NEW ENTRY?:	No		
SITE NAME:	The Racecourse and Terry's Factory, York				
DESIGNATION:	Conservation Area	CONDITION:	At risk		
VULNERABILITY:	Unknown	TREND:	Improving		
CONTACT:	Leigh Weston (LPA) 01904 551329	NEW ENTRY?:	No		
SITE NAME:	Towthorpe, York				
DESIGNATION:	Conservation Area	CONDITION:	At risk		
VULNERABILITY:	Unknown	TREND:	No significant change		
CONTACT:	Leigh Weston (LPA) 01904 551329	NEW ENTRY?:	No		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2011 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST