


# E Plade A

EAST OF ENGLAND

# Contents

Heritage at Risk	III	Norfolk Broads (NP) North Norfolk	48 48
The Register	VII	Norwich South Norfolk	54 56
Content and criteria	VII	Peterborough, City of (UA)	59
Criteria for inclusion on the Register	VIII	Southend-on-Sea (UA)	63
Reducing the risks	X	Suffolk	64
Key statistics	XIII	Babergh	64
Publications and guidance	XIV	Forest Heath	65
Key to the entries	XVI	lpswich Mid Suffolk	66 66
Entries on the Register by local planning authority	XVIII	St Edmundsbury Suffolk Coastal	68 71
Bedford (UA)	I	Waveney Thurnock (LIA)	75 76
Cambridgeshire	2	Thurrock (UA)	76
Cambridge East Cambridgeshire Fenland Huntingdonshire South Cambridgeshire Central Bedfordshire (UA)	2 3 6 7 10		
Essex	17		
Braintree Brentwood Chelmsford Colchester Epping Forest Harlow Maldon Tendring Uttlesford	17 18 19 20 21 23 23 24 27		
Hertfordshire	28		
Broxbourne Dacorum East Hertfordshire North Hertfordshire St Albans Stevenage Three Rivers Watford Welwyn Hatfield	28 29 29 30 33 33 33 33 34		
Luton (UA)	34		
Norfolk	35		
Breckland Broadland Great Yarmouth King's Lynn and West Norfolk	35 40 42 44		

II





Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results.

Over the past year we have focused much of our effort on assessing listed Places of Worship, and visiting those considered to be in poor or very bad condition as a result of local reports.

We now know that of the 14,775 listed places of worship in England, 6% (887) are at risk and as such are included on this year's Register. These additions mean the overall number of sites on the Register has increased to 5,753. However, 575 sites have been removed from the 2013 Register, which includes one of our biggest achievements this year, Clophill Old St Mary's Church.

Greg Luton, Planning and Conservation Director, East of England

Over the last year 16 buildings or structures, 27 places of worship, 12 conservation areas, 9 archaeological entries and 1 park and garden have been saved and removed from the Register.

We have also visited and assessed over 350 places of worship to help target advice and support towards those most at risk; as well as providing expert technical advice to the Heritage Lottery Fund under the Grants for Places of Worship Scheme which has helped remove 27 listed places of worship from the East of England Register this year.

Positive progress has been made on 9 of our top ten priority sites over the last year; with 3 of them, Langham Trainer Dome, Clophill Old Church and Pentney Priory Gatehouse removed from the Register this year. Many buildings and structures have been rescued following successful partnerships with private owners, trusts and other funding bodies including Natural England, the Heritage Lottery Fund and WREN (landfill tax distributor), with £1.7m of English Heritage grant spent assisting 21 heritage sites in the East. Grants have also been offered to 4 new urgent cases needing repair this year including Sibton Abbey, Drinkstone Mill, Barnham nuclear bomb store, Suffolk and Hopton on Sea old church, Norfolk. We have also funded repairs being undertaken to ruined parts of St Osyth's Priory, Essex.

Wisbech, known as the Capital of the Fens and a particularly fine and historic Georgian Market town and port, has been subject to close partnership working with the District Council and local community to address a number of key architectural buildings at risk. We also helped support an application to the Heritage Lottery Fund

for a Townscape Heritage bid to help address some of these problem buildings as well as with regenerating the wider townscape newly identified as a conservation area at risk.

There are other challenges for the years ahead including Stow Maries airfield, Essex a uniquely well preserved WWI aerodrome, which was purchased for the nation with grants from English Heritage, the National Heritage Memorial Fund and local authority loans last year. Following assessment 10 of the 24 grade II\* listed buildings have been added to the Register and we are working closely with a new trust and their volunteers, local authorities and other stakeholders to conserve and repair the site.

Close co-operation with Natural England has been vital to help with our shared objectives for historic features and sites under agri-environment schemes with 10 sites on the Register removed this year including Euston Park, Suffolk, following works to de-silt and restore the lakes and water bodies. A challenge this year will be to help with targeting the New Environment Land Management Scheme which replaces the Stewardship Scheme in 2015.

John Ette,

Principal Adviser, Heritage at Risk

#### FRISTON POST MILL, FRISTON, SUFFOLK

Friston Post Mill, the tallest surviving post mill in Britain, has been on the Heritage at Risk Register since 2006. It is one of just four post mills of the tall east Suffolk type to survive, and generally acknowledged as the most intact and tallest. The owner is working with English Heritage to formulate a repair strategy and is developing a community-led bid to the Heritage Lottery Fund. This would see the completed conservation and restoration of the whole site, and develop a community learning centre focused on mills and milling, and conservation workshops open to the public.

# 2014 EAST OF ENGLAND

65 SITES REMOVED FROM THE 2013 REGISTER

£1.7<sub>M</sub>



#### WHAT'S ON THE HERITAGE AT RISK REGISTER?



39 CONSERVATION AREAS (4.4%) NATIONAL AVERAGE EAST OF ENGLAND IN THE EAST OF ENGLAND THERE ARE... 95 BUILDINGS & STRUCTURES **4**0/0 2.8% 115 PLACES OF WORSHIP 60/n 4.9% 207 SCHEDULED MONUMENTS 15.2º/o 11.9% PARKS & GARDENS 191



# REMAINS OF AUGUSTINIAN PRIORY GATEHOUSE, PENTNEY, NORFOLK

#### **BACKGROUND AND HISTORY**

The Augustinian Priory at Pentney, dedicated to the Holy Trinity, St Mary and St Mary Magdalen, was founded around 1130 by Robert de Vaux and endowed with various properties including the manor of Pentney. It was one of at least seven monastic foundations situated in or adjacent to the Nar valley. Two others, including the associated Wormegay Priory, were of the Augustinian order. Being among the larger religious foundations in Norfolk, these were moderately wealthy. After the Dissolution of the Monasteries the site of the priory, with a water mill and the manor of Pentney, was granted to Sir Thomas Mildmay sometime after 1537.

In late November 2011 the building was roofless, and

the first floor structure and vault over the carriageway and the upper parts of the two internal supporting walls had collapsed. As a result, the outer walls had lost structural integrity. Parapets and upper masonry were all in precarious condition, with strong likelihood of further collapse. Some internal scaffolding had previously been erected in an attempt to brace the external walls, but the central gate passage was buried in places by up to 2 metres of collapsed material.

...ON THE REGISTER

2.8%

#### IS IT AT RISK?

5.7%

Pentney Priory Gatehouse was on the Buildings at Risk Register from 1998. It was removed this year following a significant scheme and two phases of repair. In January 2012, a Project Development grant was offered from English Heritage. Work began immediately, project managed by the owner, on the erection of internal and external scaffolding, and a temporary roof. At the same time, an archaeological brief was agreed and the excavation of collapsed stonework began under close archaeological supervision.

#### WHAT'S THE CURRENT SITUATION?

Phase 2 repair works were confined to imperative external and internal structural repairs, high and low level masonry, and the provision of a roof. This has restored structural integrity to the upper sections of the medieval stonework, ensured adequate rainwater disposal and prevented further loss of internal surfaces and finishes. The owners undertook further works in order to bring the building back into use as an events or wedding venue. All works were completed by December 2013.

#### **HELP HISTORIC BUILDINGS**

Historic buildings are irreplaceable; they give us our sense of place and contribute to our quality of life. These precious buildings need to be looked after for future generations, but how do we know what needs our help the most? English Heritage is encouraging community groups, volunteers, building owners and local authorities across the country to come together to record the condition of grade II listed buildings in their area. Volunteers will visit a selection of grade II buildings local to them and answer questions, in the form of a survey, about the condition of the building. This information will be collected together and shared with local planning authorities to help identify those grade II buildings most at risk. Visit www.english-heritage.org.uk/helphistoricbuildings to find out more.

# FOR MORE INFORMATION CONTACT:

John Ette
English Heritage
East of England
Brooklands
24 Brooklands Avenue
Cambridge
CB2 8BU

Telephone: 01223 582 700

Email: eastofengland@ english-heritage.org.uk



#### LANGHAM AIRFIELD DOME TRAINER, LANGHAM, NORFOLK

#### **BACKGROUND AND HISTORY**

The intriguing structure of Langham Dome has a diameter of 40 feet and a height of 25 feet. The concrete is 4.5 inches thick, over a steel framework and supported by a steel lattice set within the concrete. Externally, it was only protected by a light render, and the interior was plastered.

Inside, a white lined interior formed a screen onto which moving pictures of aircraft were projected. A mock gun, with a yellow beam and realistic sound effects was used by the trainee to aim at and shoot the targets. The trainee, who wore yellow tinted goggles, could not see the beam,

but the trainer could, in order to judge how well the trainee was performing.

The dome was only in use for the second half of the second world war and has deteriorated steadily since the closure of the airfield. The concrete had carbonated and no longer gave protection to the main reinforcing steelwork, which had begun to rust and expand, thereby breaking the concrete and allowing further water penetration. This led to extensive rusting internally and the failing of the plasterwork. All services and equipment were missing.

The dome was gifted to the North Norfolk Historic Buildings Trust in 2008. The Friends of Langham Dome was established in 2010. The two groups proceeded to work in partnership towards the restoration of the dome.

#### IS IT AT RISK?

No. Langham Dome was on the Heritage at Risk Register from 1998 to 2013. The conservation and restoration works have been completed and the dome has been removed from the Register this year. The repair and preservation of rusting ferro-concrete structures is a highly technical and specialist business, but it has been successfully achieved at Langham Dome to an exemplary standard.

#### WHAT'S THE CURRENT SITUATION?

The Trust applied to English Heritage and the Heritage Lottery Fund for grants. A development phase grant was awarded by HLF in 2011 and a delivery phase grant was awarded in 2013 for £446,000. £200,000 was awarded from English Heritage and £46,000 in partnership funding from The Coastal Sustainability Fund, North Norfolk District Council, Norfolk County Council, Architectural Heritage Fund and the Paul Bassham Trust. Thanks to the partnership funding, this complex and unusual project was completed. Langham Dome is now open as an educational and memorial centre, focusing on the history of the airfield and the Dome and in memory of the men and women who were stationed there.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# THE REGISTER Content and criteria

# DESIGNATION Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets (http://list.english-heritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s planning acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a neverending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

#### LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are almost 376,000 listed entries on the statutory list of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

#### SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,833 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

#### REGISTERED PARKS AND GARDENS

There are 1,628 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls,

but there is a clear presumption in favour of upholding their significance in government planning guidance. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

#### REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the *Register of Historic Battlefields* for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy.

#### PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

#### **CONSERVATION AREAS**

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,848 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

# Criteria for inclusion on the Register

#### RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

#### **BUILDINGS AND STRUCTURES**

Buildings or structures (not in use as public places of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from very bad to poor, fair and (occasionally) good reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

#### PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in very bad or poor condition it is added to the Register.

English Heritage has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

#### **ARCHAEOLOGY**

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

#### PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

#### **BATTLEFIELDS**

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure - for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of factors can be enough to raise the risk of a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

#### WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

#### **CONSERVATION AREAS**

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, are defined as being at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

## Reducing the risks

English Heritage is working to secure a reduction in the number of heritage sites at risk as part of our contribution to the National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Despite the challenge, given the number of entries on the Register and the different kinds of risk they face, excellent progress is being made.

The published Heritage at Risk National Strategy (www.english-heritage.org.uk/publications/eh-har-strategy-2011-15) sets out how this will be delivered through our dedicated Heritage at Risk teams in each local office. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Resolving cases requires working in close partnership with owners, local planning authorities and a wide variety of other relevant organisations. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including: new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk. Key publications and guidance are listed on pages XIV-XV.

Historic Environment Records and local heritage at risk registers, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

#### **BUILDINGS AND STRUCTURES**

Our nine local teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. We can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. Our own principal grant stream for buildings and structures is the Historic Buildings, Monuments and Designed Landscapes (HBMDL) grant but Section 17 Management Agreements can also be used to tackle risk to scheduled monuments. More information on funding can be found at www.english-heritage.org.uk/professional/funding.

We know from our own Register how useful it is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities and voluntary groups to enable them to compile local heritage at risk registers and develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers. Our Heritage at Risk Legal Adviser can support local authorities considering enforcement action and we have published guidance at www.englishheritage.org.uk/publications/stoppingtherot. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the Architectural Heritage Fund and fund their regional support officers to work across the county. They help BPTs and other not-for-profit organisations access funding, carry out feasibility studies and develop solutions for buildings at risk. For more information on support officers and BPTs visit www.ahfund.org.uk and www.ukapt.org.uk. Guidance and case studies can be found at www.englishheritage.org.uk/publications/pillars-of-the-community.

English Heritage also funds an Industrial Heritage Support Officer to work with groups running industrial heritage sites. For more information please visit www.industrialheritagesupport.wordpress.com.

#### PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the new Grants for Places of Worship scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

#### **ARCHAEOLOGY**

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites. The large majority (84%) of the 19,832 scheduled

monuments in England (in 2013) are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This will be especially important with the New Environmental Land Management Scheme (NELMS) which commences in 2015. Natural England now shares our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. Reporting in late 2013, however, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for 1587 sites on the Register, and features bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in a significant number of removals from the 2013 Register.

Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

#### PARKS AND GARDENS

Although a statutory list, the *Register of Historic Parks Gardens of Special Historic Interest in England* in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's *National Planning Policy Framework* (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the *Register of Historic Parks and Gardens of Special Historic Interest* and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens.

#### **BATTLEFIELDS**

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II\* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' understanding of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

#### **WRECK SITES**

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require

significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from www.helm.org.uk

#### CONSERVATION AREAS

The risks to conservation areas are difficult to address as these designated areas can constitute large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage them or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improve-your-neighbourhood.

## Key statistics

#### **BUILDINGS AND STRUCTURES**

- Nationally, 4.0% of grade I and II\* listed buildings (excluding places of worship) are on the Register. In the East of England the percentage is 2.8% (95 listed secular buildings).
- 16 building or structure entries have been removed from the 2013 East of England Register because their futures have been secured, and 6 have been added.
- 59.3% of buildings or structures (64) on the East of England baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 59.4%.

#### PLACES OF WORSHIP

- Nationally, 6.0% of listed places of worship are on the Register. In the East of England, 4.9% (115) are on the Register.
- 27 places of worship have been removed from the East of England Register following repair work, and 57 have been added.

#### **ARCHAEOLOGY**

- 3,012 (15.2%) of England's 19,833 scheduled monuments are on the Register. 207 (11.9%) of the East of England's 1,734 scheduled monuments are on the Register.
- 9 archaeology entries have been removed from the 2013 East of England Register for positive reasons, and 3 have been added.
- 29.1% of archaeology entries (59) on the East of England baseline 2009 Register have been removed for positive reasons, compared with the national figure of 29.2%.

 Nationally, damage from arable cultivation is the greatest cause of risk affecting 43% of archaeological entries on the Register. In the East of England the proportion is 74%.

#### PARKS AND GARDENS

- 93 (5.7%) of England's 1,628 registered parks and gardens are on the Register. Of the 211 registered parks and gardens in the East of England, 6 (2.8%) are on the Register.
- I park and garden entry was removed from the 2013 East of England Register for a positive reason.

#### BATTLEFIELDS

 Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. The only registered battlefield in the East of England is not on the Register.

#### WRECK SITES

 Of the 49 protected wreck sites around England's coast, 4 (8.2%) are on the Register. The East of England's single protected wreck site is not on the Register.

#### **CONSERVATION AREAS**

- 8,206 of England's 9,848 conservation areas have been surveyed by local authorities and 497(6.1%) are on the Register. Of the 1,210 conservation areas in the East of England, 895 have been surveyed and 39 (4.4%) are on the Register.
- 12 conservation areas have been removed from the 2013 East of England Register for positive reasons, and 8 have been added.

#### **ENGLISH HERITAGE FUNDING**

• £1.7 million in grant was spent on 21 entries on the East of England Register during 2013/14.

Risk assessments of heritage assets are based on the nature of the site. Building and structure assessments include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – English Heritage Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

English Heritage's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2014 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2014 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database:

#### www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/professional/protection.

### CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications and www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation — revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012—2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

## Key to the entries

This Register includes the following risk assessment types:

- Building or structure
   (grade I and II\* listed buildings and structural scheduled monuments)
- Place of worship (grade I, II\* and II listed buildings)
- Archaeology

   (scheduled monuments earthworks and buried archaeology)
- Park and garden
   (Registered parks and gardens)
- Conservation area (Conservation areas)

#### **ORDER**

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

#### DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II\*
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

#### CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

#### PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2013 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

#### **TRFND**

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

#### CONTACT

This is the member of the English Heritage local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

CA Conservation Area
EH English Heritage
HLF Heritage Lottery Fund

LB Listed Building

LPA Local Planning Authority

NP National Park

RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority

WHS World Heritage Site

# Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
BEDFORD (UA)							
Bedford (UA)	1	I	8	0	0	0	1
CAMBRIDGESHIRE							
Cambridge	0	2	0	0	0	0	0
East Cambridgeshire	3	I	16	0	0	0	0
Fenland	0	I	9	0	0	0	1
Huntingdonshire	3	5	6	0	0	0	0
South Cambridgeshire	3	4	24	0	0	0	5
CENTRAL BEDFORDSHIRE	(UA)						
Central Bedfordshire (UA)	I	3	7	ı	0	0	0
ESSEX							
Basildon	0	0	0	0	0	0	0
Braintree	0	2	4	0	0	0	2
Brentwood	2	ı	0	0	0	0	0
Castle Point	0	0	0	0	0	0	0
Chelmsford	0	I	2	0		0	3
Colchester	2	2	3	0		0	
Epping Forest	5	3	2	0		0	
Harlow	0	0	1	0		0	
Maldon	2	ı	2	0		0	0
Rochford	0	0	0	0	0	0	0
Tendring	6	2	2	0		0	
Uttlesford	2	2	5	1	0	0	
HERTFORDSHIRE			<u> </u>	ı	0	0	0
Broxbourne	0	0	0	0	0	0	2
			0	0			
Dacorum	0	0	1	1	0	0	
East Hertfordshire	2	2	4	0		0	
Hertsmere	0	0	0	0		0	
North Hertfordshire	5	I	7	0		0	
St Albans	0	0	2	0		0	
Stevenage	l	0	0	0		0	
Three Rivers		0	0	0	0	0	0
Watford	2	l	0	0	0	0	0
Welwyn Hatfield		0	0	0	0	0	0
LUTON (UA)	_		_	l .			
Luton (UA)	0	0	0	0	0	0	2
NORFOLK		l		l e	l		
Breckland	8	16	5	0		0	
Broadland	3	5	2			0	
Great Yarmouth	4	5	0	0	0	0	0
King's Lynn and West	7	7	7	0	0	0	0
Norfolk	1	0	0	0	0	0	
Norfolk Broads (NP)	0		0	0		0	
North Norfolk	8	13	4	1	0	0	
Norwich	6	l l	0	0		0	
South Norfolk	(114)	15	4	0	0	0	0
PETERBOROUGH, CITY OF							
Peterborough, City of (UA)	4	0	25	0	0	0	0
SOUTHEND-ON-SEA (UA)							
Southend-on-Sea (UA)		I	0	0	0	0	0
SUFFOLK							
Babergh	3	l	4	0		0	
Forest Heath	0	0	4	0		0	
lpswich	2	0	0			0	
Mid Suffolk	4	5	I	l l	0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
Norfolk Broads (NP)	0	0	0	0	0	0	0
St Edmundsbury	5	2	6	0	0	0	2
Suffolk Coastal	7	8	6	I	0	0	1
Waveney	2	I	1	0	0	0	0
THURROCK (UA)							
Thurrock (UA)	2	0	2	0	0	0	1
TOTAL	110	115	176	6	0	0	39

#### BEDFORD (UA)



© English Heritage

© English Heritage

SITE NAME: Cardington No. I Shed at RAF Cardington, High Road,

Eastcotts

DESIGNATION: Listed Building grade II\*

CONDITION:

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: F (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1114165

The colossal Number 1 Shed is the only airship hangar from the period up to 1918 to survive in situ in Europe (the similar Number 2 Shed was re-sited from Norfolk). Repairs to the roof and gable ends have been completed and repairs to the side are programmed for the coming

Contact: Clare Campbell 01223 582738



SITE NAME: Church of All Saints, Church Lane, Little Staughton DESIGNATION: Listed Place of Worship grade I CONDITION: Fair PRIORITY CATEGORY: F (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1114812

Parish church. C15 with C13 and C14 details remaining. Coursed limestone rubble and brown cobbles, with ashlar dressings. Chancel, nave, south aisle, south porch, west tower. Chancel, rebuilt C15, retains C14 south door. C15 chancel arch. Three bay nave, with buttresses up to parapet of north wall. Three windows each side to C15 clerestory. C13 north doorway. C14 south arcade. Chancel roof structure and covering in very poor condition. Repair Grant for Places of Worship grant offered in 2011. Repair programme due to be completed late 2014.

Contact: Robert Parkinson 01223 582733

SITE NAME:	Remains of the George Inn		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004674
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Manor Farm Iron Age univallate hillfort and mediev	al moated enclosur	re, Bolnhurst and Keysoe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1012066
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement site north of Chapel End Farm, Carding	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005390
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Site discovered by aerial photography south of villa	ge, Cardington	

#### PRIORITY CATEGORIES

DESIGNATION:

CONDITION:

OWNER TYPE:

PRINCIPAL VULNERABILITY:

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Scheduled Monument

Arable ploughing

Private

Extensive significant problems

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

LIST ENTRY NUMBER:

TREND:

NEW ENTRY?:

CONTACT:

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

1005413

Declining

Nο

#### **ABBREVIATIONS**

David Kenny 01223 582700

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bury Hill Camp: a motte and bailey castle with thre	ee fishponds, Thurle	eigh
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1009155
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Yarl's Wood hermitage and moated site, Milton Er	nest	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Palaceyard Wood medieval moated enclosure and earthworks, Wyboston, Chawston and Colesden /		es, woodland bank and cultivation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010948
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Wold Farm moated enclosure, Odell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012490
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bedford		
DESIGNATION:	Conservation Area, 100 LBs, RPG grade II, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	lan Johnson (LPA) 01234 221953

#### **CAMBRIDGESHIRE**

#### **CAMBRIDGE**



© English Heritag	ge
-------------------	----

SITE NAME:	Church of St Clement, Bridge Street, Cambridge
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1126262

The exterior of this church is dominated by the early C19 tower in a thin, Commissioners' Gothic style. The nave and aisles are externally entirely early C16, and the brick chancel is distinctively C18. There is a distinctive mix of building materials and blocked openings in the pre-C19 work. Church shared by Anglican and Greek Orthodox congregations. South aisle roof in particularly poor condition with significant water penetration. No long term solution agreed.

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Church of St Andrew the Less, Newmarket Road, Cambridge
DESIGNATION:	Listed Place of Worship grade II, CA

CONDITION: Very bad

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1126143

Abbey church of early C13 date consisting of chancel and nave. Rubble with some dressed stone. Built by Barnwell Priory on original Augustinian site. The church was restored 1854-6, the vestry and organ-chamber added in the late C19. Walls, roof and churchyard in very poor condition. Long term solution yet to be agreed.

Contact: Robert Parkinson 01223 582733

#### EAST CAMBRIDGESHIRE



© English Heritage

SITE NAME:	Dovecote to St John's Farm, St Johns Road, Ely
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1331739

LIST ENTRY NUMBER:

Part of medieval hospital of C13 date, later used as a dovecote. The roof is in urgent need of repairs. A grant offer was made in 2013, and a scheme of works agreed. This is currently being progressed, and works are due to be complete by the end of 2014.

Contact: Will Fletcher 01223 582710



© English Heritage

SITE NAME:	Downfield Windmill, Fordham Road, Soham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1331761

rebuilt following storm in 1889. Machinery substantially complete, but condition deteriorating. In need of general repairs, and reinstatement of sails and other missing parts of the structure. A schedule of works has been prepared with English Heritage grant aid. Repair work started on site in June 2013. Completion estimated end of summer 2014.

Windmill originally built in 1726, raised in 1860, largely

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Northfield Windmill, The Shades, Soham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1124419

Originally C18 drainage mill for the neighbouring Fen, relocated during 1830s to present position and converted to a corn mill. Six-sided timber-framed smock mill. Has machinery but the cap is deformed, leaking; and will not turn to wind. Some temporary repairs completed 2009 to attend to leaks. Since 2012 and a change of ownership, repairs have been undertaken and condition has improved. Plans remain to repair cap, curb and sails, and to make the mill mechanically sound. Some emergency works have been recently complete. This mill is part of the 'East Anglian Mills Society (TEAMS) grouping.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of St Peter, Church Lane, Stetchworth
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1331821

The chancel is CI5 on an earlier site, the nave CI4 and the tower CI5. The church is suffering from severe settlement, especially the north aisle wall is pulling horizontally away from the aisle at floor level. Signs of stress in nave arcades at tie beam/truss positions, and at each end in masonry of the south aisle. Attention also needed to roofs and rainwater goods and drainage. A Repair Grant for Places of Worship was offered 2012, towards structural issues due to clay subsoil and poor drainage. Project development phase now underway with urgent repairs due to be . completed autumn 2014.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

	All Saints' Church, remains of, Ashley		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006898
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Romano-British settlement site west of Allington	Hill, Bottisham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006901
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 450m east of Shelford Farm, Hadde	enham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020398
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Long barrow at Foulmire Fen, 140m north west	of the junction of Bac	k and Small Fen Drove, Haddenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019983
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Oval barrow and round barrow at Small Fen, 250m north of the junction of Back and Small Fen Drove, Haddenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019984
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
	Round barrow at Small Fen, 220m east of the jun	ction of Back and Sm	all Fen Drove, Haddenham
SITE NAME:			all Tell Drove, Fladdelliaili
	Scheduled Monument	LIST ENTRY NUMBER:	1019986
SITE NAME:  DESIGNATION:  CONDITION:	·		
designation: Condition:	Scheduled Monument	LIST ENTRY NUMBER:	1019986
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER:	1019986 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No David Kenny 01223 582700
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company Three bowl barrows 450m and 570m east of Ne	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No David Kenny 01223 582700
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company  Three bowl barrows 450m and 570m east of Nethaddenham	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: w England, part of the	1019986  Declining  No  David Kenny 01223 582700  Haddenham round barrow cemeter
DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company  Three bowl barrows 450m and 570m east of Nethaddenham Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  W England, part of the	1019986 Declining No David Kenny 01223 582700 Haddenham round barrow cemeter 1019982

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay: no solution agreed.

  D Slow decay; solution agreed but F not yet implemented.
  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial uses) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Two bowl barrows 370m and 505m south of No Haddenham	ew England, part of the	e Haddenham round barrow cemete	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019985	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Roman settlement, Lode			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006793	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700	
ITE NAME:	Roman site near Old Fordey Farm, Barway, Soh	am		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006885	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Settlement site south of Tiled House Farm, Stre	tham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006795	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Long barrow at South Fen, 90m south west of the west end of Rymanmoor Long Turning, Sutton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019988	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Long barrow at South Fen, 180m south east of E	Long barrow at South Fen, 180m south east of Between Ditches Drove, Sutton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009994	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Round barrow 690m SSW of Stocking Drove Fa	rm, Sutton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019987	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Long barrow 650m NNW of Lythel's Farm, Swa	ffham Bulbeck		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020843	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700	

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Long barrow 410m south east of Partridge Hall Farm, Swaffham Prior		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020842
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700

#### **FENLAND**



SITE NAME: Church of St Wendreda, Church Street, March

DESIGNATION: Listed Place of Worship grade I

CONDITION: Very bad

PRIORITY CATEGORY: B (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1287740

Parish church, mainly mid C14 to late C15. Restored 1874. Rubblestone with Barnack limestone dressings and flint and brick to late C15 clerestory. West tower, nave, north and south aisles. South porch and chancel. Four stage west tower and spire, 1350-1400, embattled with five stage buttressing. South aisle parapet loose in places. Heritage Lottery Fund repair grant offered. Work expected to start late 2014.

Contact: Robert Parkinson 01223 582733

#### © English Heritage

SITE NAME:	Bowl barrow 200m south east of Horseley Fen	arm, Chatteris	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011723
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 250m south of Honey Farm, Chatteris		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020393
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 580m east of Mount Pleasant Bridge, Chatteris		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020394
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 600m west of Honey Hill Farm, Chatteris		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011718
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582700
SITE NAME:	Neolithic enclosures at Grey's Farm, Horseley Fen, Chatteris		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009993
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

TIENTAGE AT NISK 20147 EAS	TOT ENGLAND / FENLAND / HONTINGDONSHIKE		
SITE NAME:	Bowl barrow 500m south of Bunting's Farm, Whit	ttlesey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020847
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Ring ditch and settlement site north of Eastrea, Whittlesey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006853
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Suet Hills round barrow cemetery, Whittlesey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Romano-British settlement near Honeybridge, Wimblington / Chatteris		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006906
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Wisbech		
DESIGNATION:	Conservation Area, 229 LBs, RPG grade I	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Nicola Duncan-Finn (LPA) 01354 622321

#### **HUNTINGDONSHIRE**



SITE NAME:	Great Gransden Windmill, Great Gransden
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Local authority

Constructed c1612, Great Gransden is the oldest remaining mill in England. Building contains a flour dressing machine with the inscription 'IL 1774 RW'. A comprehensive survey shows that the mill is in very poor condition. Consent for emergency repairs was granted, including dismantling of sails for safety reasons, in late 2013. Emergency works to be completed summer 2014. Discussions are continuing regarding the creation of a local trust to manage the building.

© English Heritage LIST ENTRY NUMBER: 1006820 Contact: Deborah Priddy 01223 582720



SITE NAME:	Park wall of Hinchingbrooke House, Hinchingbrooke, Huntingdon
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (state sector)

1128652

C17 and C18 wall. The south portion of the park boundary wall is of coursed stone and brick with ball finials. This section of the wall is in a bad condition and some parts have collapsed. Other parts are beginning to lean significantly, and plant growth is a problem. The bank also suffers from significant, but localised animal burrowing. Discussions have been opened with the site manager, but no strategy agreed as of May 2014.

Contact: Claire Fidler 01223 582735

#### PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

© English Heritage

SITE NAME:	St Andrew's Church, Church End, Wood Walton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1130123

Former church with C13 south arcade of nave, C14-C15 west tower, C14 chancel, C16 north arcade much rebuilt 1856-9. Coursed limestone rubble, limestone dressings, plain tile roof. Very isolated. May 2013: high level repairs completed to tower, following a fall of stonework; roofs repaired; copings repointed. Building still thought to be moving and currently undergoing structural monitoring.

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of All Saints, Buckworth
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1130189

Parish church noted for its early C14 tower and broach spire. C13, C14 and C15 additions, with further works in 1884 and 1925; tower repaired in 1908. Walls of limestone rubble with limestone dressings and ashlar tower. High level masonry in poor condition. Grant for Places of Worship offered in 2012. Work started in May 2014, with completion expected summer 2014.

Contact: Robert Parkinson 01223 582733

	N.	*	
Service Services			
		la n	

	N.	4
1		
10 PE	10 11	and the

SITE NAME:	St Marys Parish Church, Broadway, Farcet
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215281

Parish church. C12 nave, west tower c1180-90, C13 chancel and south chapel. South aisle rebuilt with wider east bay 1270-80. South porch C14. Church restored in 1852 and north aisle and arcade added with original C12 north door resited. Tower restored 1894-97. Walls of limestone rubble with Barnack dressings. Serious structural problems associated with ground conditions and drainage difficulties. Grant for Places of Worship offered 2013. Repairs commenced spring 2014 with anticipated completion late 2014.

Contact: Robert Parkinson 01223 582733

© English Heritage

© English Heritage

SITE NAME:	Parish Church of St Nicholas, Church Road, Glatton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	F (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1215294

Parish church. Nave arcades C12 with late C13 north transept, early C14 chancel and south aisle. Chancel partly rebuilt and lengthened in early C15. Early C16 vaulted north vestry, rood loft and staircase. Restoration undertaken in 1869. Chancel roof leaking and in need of replacement; west end of south aisle roof in similar condition. Parish received Heritage Lottery Fund grant in July 2014. Development phase due to commence late 2014.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of All Saints, Church Road, Grafham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288615

Medieval church with classic limestone-belt stone steeple on tower. Church dates from C12; chancel C13; south chapel early C14; tower and spire C14. Porch rebuilt in 1657. Serious deformations in the arcade walls due to settlement, and increasingly urgent need for re-roofing chancel north slope and aisle south slope. Drainage also needs attention. A Repair Grants for Places of Worship grant was offered in June 2013. Investigation work is underway and repairs expected to be completed by end of

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG

Unitary Authority World Heritage Site



SITE NAME:	Church of St Thomas, Herne Road, Ramsey
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1330457

Parish church built in 1869 by subscription. Nave with polygonal east end, north west bell turret. Gault brick, slate roof. Early English fenestration. High level general mortar failure in brickwork and around windows with some cracking visible. No action/strategy identified or agreed.

Contact: Claire Fidler 01223 582735

#### © English Heritage

	Deserted village at Wintringham, Abbotsley		
	N: Scheduled Monument	ENTRY NUMBER: 1006815	
	Extensive significant problems	ND: Declining	
	ULNERABILITY: Arable ploughing	VENTRY?: No	
	Mixed, multiple owners	David Kenny 01223 582700	
	Roman site, Rushey Farm, Great Staughton		
	ON: Scheduled Monument	ENTRY NUMBER: 1006866	
	Generally unsatisfactory with major localised problems	ND: Declining	
	ULNERABILITY: Arable ploughing	/ ENTRY?: No	
	Commercial company	David Kenny 01223 582700	
Wood	Monk's Hole barrow, 630m NNE of Monk's Wood	ı, Sawtry	
	Scheduled Monument	ENTRY NUMBER: 1015007	
	Extensive significant problems	ND: Declining	
	ULNERABILITY: Arable ploughing	VENTRY?: No	
	Mixed, multiple owners	David Kenny 01223 582700	
s Woo	Site of Sawtry Judith village adjoining Archers Woo	vtry	
	N: Scheduled Monument	ENTRY NUMBER: 1006816	
	Generally unsatisfactory with major localised problems	ND: Declining	
	ULNERABILITY: Arable ploughing	VENTRY?: No	
	Mixed, multiple owners	David Kenny 01223 582700	
east of	Moated site in Prestley Wood, 800m north east o	wright's Farm, The Stukeleys	
	ON: Scheduled Monument	ENTRY NUMBER: 1017843	
ılised	Generally satisfactory but with significant localised problems	ND: Stable	
	ULNERABILITY: Scrub/tree growth	/ ENTRY?: No	
	PE: Private	David Kenny 01223 582700	
	Moated site in Toseland Wood, Toseland		
	Scheduled Monument	ENTRY NUMBER:   1017881	
ılised	Generally satisfactory but with significant localised problems	ND: Stable	
	ULNERABILITY: Metal detecting - unlicensed	/ ENTRY?: No	
	Commercial company	David Kenny 01223 582700	
alised	Scheduled Monument  Generally satisfactory but with significant localised problems  WLNERABILITY: Metal detecting - unlicensed	ND: Stable VENTRY?: No	582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:

#### **SOUTH CAMBRIDGESHIRE**



© English Heritage

SITE NAME:	Little Chishill Mill, Barley Road, Great and Little Chishill
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Charity (heritage)

1330927

Post mill. Possibly rebuilt 1819 (Wailes), scratching on stud 1712, main post renewed 1868 and dated underneath mill. Patent sails c1912-16 replacing former canvas covered sails. Timber-framed, weather boarded and painted with brick piers. The main structure extends to the rear housing the bolter; restored fantail on ladder. The mill was last used in 1951, and was renovated by Thompsons of Alford, Lincs. in 1966. The buck (sail housing) is leaking and requires new weatherboarding. The owner is carrying out some holding

Medieval church restored in 1874 by William Butterfield, now closed. Owners have completed external repairs (except east window) with the help of an English Heritage grant. The Local Authority has been in discussion with a trust as a potential user but no solution agreed. Nave floor repairs and east window reinstatement still required before building can be reused. Charitable trust currently liaising with Local Planning Authority over future of building.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of St Denis, East Hatley, Hatley
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1128153

Contact: Trudi Hughes 01223 582739



© English Heritage

STETO WIE.	Hutchins and Harding Ltd, High Street (east side), Sawston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Commercial company LIST ENTRY NUMBER: 1127985 Contact: Sheila Stones 01223 582716

Large tannery building at

C19 timber-framed skin drying shed with adjustable timber louvered walls. Redundant and in immediate risk of further deterioration or loss of fabric. No solution agreed.



© English Heritage

SITE NAME:	Parish Church of St Nicolas, Great and Little Chishill
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1162491

Parish Church. C12 chancel, extended in C13 or early C14. Late C14 tower with C16 belfry windows. Late C14 nave. Late C14 south porch. C19 restoration included replacement of C15 nave windows and building of pyramidal tower roof structure. Memorial glass by Kempe 1916, in east window. Batten failure on nave roof; tiles slipping. Long term solution yet to be agreed.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of St Mary, High Street, Great Eversden
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1127621

Parish church. Rebuilt after a fire in 1466. Restorations of 1864 and 1920. Fieldstone, clunch rubble and dressings of clunch and limestone. Tiled roof. Plan of west tower, nave and chancel. West tower of three stages on plinth with three stage diagonal buttressing and newel staircase at north east angle. Serious structural movement. Repair Grant for Places of Worship awarded in 2011. Repair works have commenced and estimated completion is 2015.

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



The second second	Research Land
Property of	
© English Heritage	

SITE NAME:	Church of St Andrew, Burgoynes Road, Impington
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1178832

Early C13 nave and tower, upper stages rebuilt C14, and rood stair. South porch C15, chancel rebuilt during restoration of 1878, dated rainwater heads. Walls of Barnack limestone with limestone and pebble rubble. Timber framed porch. Plain tile roofs with gable parapets to nave and chancel with cross finials. South elevation: tower of three stages with Barnack limestone quoins. Severe cracks in tower and nave monitored 1999-2012. Movement stabilised after removal of trees pre-2009. Long term solution to be agreed.

Contact: Robert Parkinson 01223 582733



SITE NAME: Church of St Giles, Potton Road, Tadlow DESIGNATION: Listed Place of Worship grade II\* CONDITION: PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1317879

Parish church. C13 nave and chancel and C14 west tower. Restored c1860 under supervision of W Butterfield. Fieldstone, clunch rubble with limestone and clunch dressing. Plain tiled roof. West tower of three stages. Crack to second stage of tower on east face. Some displacement/cracking to buttress on north wall adjacent to infilled north door. Further crack to north side of east gable. Cracking to stonework and extensive ivy growth reported April 2014. Deterioration continues but no solution agreed.

Contact: David Grech 01223 582717

© English Heritage	

SITE NAME:	John O'Gaunt's House: a motte castle and moate Kneesworth	ed site 300m north ea	st of Haygate Farm, Bassingbourn cur
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010865
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Sites revealed by air photography, Bassingbourn	cum Kneesworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006881
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement site west of Town's End Farm, Comb	perton / Barton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006879
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement site by Caudle Corner Farm, Fulbour	'n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006878
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Site revealed by aerial photography west of Whi	te Hill Farm, Great Sh	nelford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006891
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Coursewood analogues 900m wast of Great Wilher	aham pawish skuust	Groot Wilhusham
	Causewayed enclosure 900m west of Great Wilbra	aham parish church  LIST ENTRY NUMBER:	, Great Wilbraham
DESIGNATION:  CONDITION:	Scheduled Monument	TREND:	
PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing	NEW ENTRY?:	Declining No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
OWNER THE.	Commercial Company	CONTACT.	David Refilly 01223 362700
SITE NAME:	Henge 220m ESE of Herring's House, Great Wilbra	aham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011716
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 550m north east of Slip End Farm, G	uilden Morden	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017328
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa 1000yds (910m) north east of Ashwell	village, Guilden Mo	orden
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006876
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement complex north east of Haslingfield, Has	lingfield / Grantche	ster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa site south of Rose Villa, Ickleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006872
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 205m SSE of Lodge Cottage, Melbour	rn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011720
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow, known as Grinnel Hill, 260m SSE of	Lodge Cottage, Me	lbourn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011719
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
	•		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Extensive significant problems IMM3. Declining PROPRIETY Commercial company Arable ploughing NOVIDITATE No Commercial Company Extensive significant problems Extensive significant problems Mixed, multiple owners CONTACT: David Kenny 01223 582700 D	SITE NAME:	Causewayed enclosure and two ring ditches 140	m south east of New	Farm, Melbourn
Remoderal Augustrabuth?  Arable ploughing  Square barrow 170m north east of Summer House Farm, Melbourn  Scheduled Monument  Extensive significant problems  Remoderal Augustrabuth?  Arable ploughing  Remoderal Augustrabuth?  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Enclosures and linear trackways south east of Newton, Newton  Contract  Enclosures and linear trackways south east of Newton, Newton  Contract  Enclosures and linear trackways south east of Newton, Newton  Contract  Enclosures and linear trackways south east of Newton, Newton  Contract  Enclosures  Enclosures and linear trackways south east of Newton, Newton  Contract  Enclosures  Enclosures and linear trackways south east of Newton, Newton  Enclosures  Enclosures  Enclosures  Enclosures  Five bowl barrows 790m north west of Chain House, part of the Over round barrow cemetery, Over  Extensive significant problems  Extensi	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009237
Commercial company COMMACT:  Square barrow 170m north east of Summer House Farm, Melbourn COMMACT:  Scheduled Monument Extensive significant problems Extensive significant problems COMMACT:  David Kenny 01223 582700  Declining COMMACT: David	CONDITION:	Extensive significant problems	TREND:	Declining
Square barrow 170m north east of Summer House Farm, Melbourn Scheduled Monument Scheduled	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument ust ENTER NUMBER 1020397  CONDITIONS Extensive significant problems TRANS: Declining  Mixed, multiple owners CONTACT: David Kenny 01223 582700  DAVID REPORT TYPE: David Kenny 01223 5	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
Extensive significant problems IRND: Declining  Arable ploughing NAW NOTITE: No  Mixed, multiple owners CONTACT: David Kenny 01223 582700  Art NAME: Enclosures and linear trackways south east of Newton, Newton  PREMIABING: Scheduled Monument IRI SHINKTIALIBRES: 1006806  CONTACT: David Kenny 01223 582700  Generally unsatisfactory with major localised problems  Generally unsatisfactory with major localised problems  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  DECONDITION  Extensive significant problems  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  DECONDITION  Extensive significant problems  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining  RINGHILL OWNERSHIPM: No  CONTACT: David Kenny 01223 582700  Declining	SITE NAME:	Square barrow 170m north east of Summer Hou	ise Farm, Melbourn	
Mixed, multiple owners CONTACT: David Kenny 01223 582700  DETERMINE Mixed, multiple owners CONTACT: David Kenny 01223 582700  DETERMINE Mixed, multiple owners CONTACT: David Kenny 01223 582700  DETERMINE Scheduled Monument US FINIST NUMBER: 1006806  DESCRIPTION OF THE DAVID MIXED M	designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020397
David Kenny 01223 582700  Selection Mixed, multiple owners  Enclosures and linear trackways south east of Newton, Newton Designation, Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Metal detecting - unilicensed  New Interview Commercial company  Contract:  David Kenny 01223 582700  Declining  New Entersive Significant problems  David Kenny 01223 582700  David Kenny 01223 5	CONDITION:	Extensive significant problems	TREND:	Declining
Enclosures and linear trackways south east of Newton, Newton  Scheduled Monument  Sche	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument UST ENTRY NUMBER: 1006806  CONDITION: Generally unsatisfactory with major localised TREND: Declining  PRENCIPAL VULNETABILITY: Metal detecting - unlicensed NEW ENTRY: No  DOWNER TYPE: Commercial company CONTACT: David Kenny 01223 582700  STE NAME: Five bowl barrows 790m north west of Chain House, part of the Over round barrow cemetery, Over 1005804347001: Scheduled Monument LIST ENTRY NUMBER: 1019874  Extensive significant problems TREND: Declining  PRENCIPAL VULNETABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over 1000000000000000000000000000000000000	OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
Generally unsatisfactory with major localised problems  PRINCIPAL VILINERABILITY: Metal detecting - unlicensed  NEW ENTRYP: No  David Kenny 01223 582700  David Kenny 01223 58	SITE NAME:	Enclosures and linear trackways south east of No	ewton, Newton	
problems problems problems Prescript. Vulnisharabiliti: Metal detecting - unlicensed New Entrity: No David Kenny 01223 582700  Declining Prescript. Vulnisharabiliti: No Declining Prescript. Vulnisharabiliti: No Declining Prescript. Vulnisharabiliti: No Declining Prescript. Vulnisharabiliti: No David Kenny 01223 582700  Declining Prescript. Vulnisharabiliti: No David Kenny 01223 582700  Declining Prescript. Vulnisharabiliti: No David Kenny 01223 582700  Declining Prescript. Vulnisharabiliti: David Kenny 01223 582700  Declining Prescript. Vulnisharabiliti: No Declining Prescript. Vulnisharabiliti: Arable ploughing Declining Prescript. Vulnisharabiliti: No Declining Prescript.	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006806
Commercial company  CONTACT:  David Kenny 01223 582700  Five bowl barrows 790m north west of Chain House, part of the Over round barrow cemetery, Over Scheduled Monument  Extensive significant problems  RINAD: CONDITION: Extensive significant problems  RINAD: CONTACT: David Kenny 01223 582700  STERNAME:  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over Contact:  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over Contact:  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over Cover Cove	CONDITION:		TREND:	Declining
Five bowl barrows 790m north west of Chain House, part of the Over round barrow cemetery, Over DESIGNATION:  Scheduled Monument  Extensive significant problems  TREND:  CONTACT:  David Kenny 01223 582700  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery. Over  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery. Over  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery. Over  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery. Over  Scheduled Monument  UST ENTRY NUMBER:  Declining  FRENCE Declining  FRENCE Declining  FRENCE No  COMMERT TYPE  Commercial company, multiple owners  CONTACT:  David Kenny 01223 582700  STR NAME:  Borough Hill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  Dough Fill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  Dough Fill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  Dough Fill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  Dough Fill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  Dough Fill: a large multivallate hillfort, Sawston  Scheduled Monument  UST ENTRY NUMBER:  No  CONTACT:  David Kenny 01223 582700  STR NAME:  Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  No  Declining  RENDED:  Declining  PRENCIPAL VULNERABILITY:  Arable ploughing  New ENTRY:  No  Downer TYPE:  Mixed, multiple owners  CONTACT:  David Kenny 01223 582700  David Kenny 0	PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER: 1019874  CONDITION: Extensive significant problems TREND: Declining  NIEWINTRY: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  STEENAME: Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over  CONDITION: Extensive significant problems TREND: Declining  RENDERANTION: Extensive significant problems TREND: Declining  RENDERANTION: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  STEENAME: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  STEENAME: Roman site north of Brown Spinney, Shepreth / Foxton  STEENAME: Roman site north of Brown Spinney, Shepreth / Foxton  STEENAME: Roman site north of Brown Spinney, Shepreth / Foxton  STEENAME: Roman site north of Brown Spinney, Shepreth / Foxton  STEENAME: Arable ploughing NEWENTRY: No  DOWNER TYPE: David Kenny 01223 582700  STEENAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  STEENAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  STEENAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  Scheduled Monument UST ENTRY NUMBER: 1006874  Generally unsatisfactory with major localised problems  RENDERANTON: Arable ploughing  NEWENTRY: No	OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
Extensive significant problems  TREND: Declining  No OWNIR TYPE: No OWNIR TYPE: Commercial company, multiple owners  CONTACT: David Kenny 01223 582700  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over Over  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019130  Extensive significant problems  TREND: Declining  NEWENTRY: No OWNER TYPE: Commercial company, multiple owners  CONTACT: David Kenny 01223 582700  STENAME  Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1009396  Extensive significant problems  TREND: Declining  NEW ENTRY: No  DECIDITION: Extensive significant problems  TREND: Declining  NEW ENTRY: No  DEVENTRY: NUMBER: 1006873  TREND: Declining  REND: Declining  REND: Declining  REND: Declining  REND: Declining  REND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006873  DEVENTRY: No  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: No  DECLINING  REND: David Kenny 01223 582700  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006874  Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006874  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006874  DECLINING  DECLINING  DECLINING  REND: Declining	SITE NAME:	Five bowl barrows 790m north west of Chain H	ouse, part of the Ove	r round barrow cemetery, Over
Arable ploughing NEW ENTRYP: No David Kenny 01223 582700  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019130  EXTENSIVE Significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SITENAME Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009396  EXTENSIVE Significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SITENAME ROMAN site north of Brown Spinney, Shepreth / Foxton  SITENAME ROMAN site north of Brown Spinney, Shepreth / Foxton  SESSIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006873  EXTENSIVE Scheduled Monument UST ENTRY NUMBER: 1006873  EXENCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006873  EXTENSIVE Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITENAME Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006874  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006874  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DESIGNATION: Scheduled Monument UST ENTRY: NUMBER: 1006874  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019874
CONTACT: David Kenny 01223 582700  Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over  Scheduled Monument  LIST ENTRY NUMBER: 1019130  SCHODITION: Extensive significant problems  FRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYT: No  David Kenny 01223 582700  STE NAME: Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1009396  STE NAME: Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1009396  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DOWNER TYPE: Commercial company, multiple owners  CONTACT: David Kenny 01223 582700  STE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  EXTENSIVE: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  EXTENSIVE: David Kenny 01223 582700  STE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  EXTENSIVE: No  DOWNER TYPE: No  DOWNER TYPE: No  DOWNER TYPE: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  EXTENSIVE: No  DAVID REMINISTRY: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006874  Arable ploughing  NEW ENTRY: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006874  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1006874  DESIGNATION: Scheduled Monument  LIS	CONDITION:	Extensive significant problems	TREND:	Declining
Three bowl barrows 380m south of Brownshill Staunch House, part of the Over round barrow cemetery, Over  Scheduled Monument  LIST ENTRY NUMBER: 1019130  CONDITION: Extensive significant problems  TREND: Declining  NEW ENTRY! No  DAVID Kenny 01223 582700  SITE NAME: Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009396  CONDITION: Extensive significant problems TREND: Declining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY! No  DOWNER TYPE: Commercial company, multiple owners  CONTACT: David Kenny 01223 582700  SITE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  REINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  DEVENTRY: No  DOWNER TYPE: Mixed, multiple owners  CONTACT: David Kenny 01223 582700  SITE NAME: ROMAN Site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  DEVENTRY: No  DOWNER TYPE: Mixed, multiple owners  CONTACT: David Kenny 01223 582700  SITE NAME: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Mixed, multiple owners  CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  DESIGNATION: DESIGNATION: DECLINING  SCHEDULE WENTRY: No  Declining  NEW ENTRY: No  Declining  NEW ENTRY: No  Declining  NEW ENTRY: No  Declining  NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Over    Control   Control	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019130  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1009396  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SETENAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SETENAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  SETENAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006874  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	SITE NAME:		Staunch House, part c	of the Over round barrow cemetery,
PRINCIPAL VULNERABILITY: Arable ploughing  Arable ploughing  NEW ENTRYP: No  CONTACT: David Kenny 01223 582700  Bowner type:  Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1009396  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  CONTACT: David Kenny 01223 582700  BITE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  DOWNER TYPE: No  DOWNER TYPE: No  DOWNER TYPE: No  DOWNER TYPE: No  DESIGNATION: CONTACT: David Kenny 01223 582700  BITE NAME: Arable ploughing  NEW ENTRYP: No  DOWNER TYPE: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006873  CONTACT: David Kenny 01223 582700  BITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019130
Commercial company, multiple owners  CONTACT:  David Kenny 01223 582700  SITE NAME:  Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  Docclining  PRINCIPAL VULNERABILITY:  Arable ploughing  CONTACT:  David Kenny 01223 582700  Declining  NEW ENTRY):  No  COMMER TYPE:  Commercial company, multiple owners  CONTACT:  David Kenny 01223 582700  Declining  REMINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY):  No  CONTACT:  David Kenny 01223 582700  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY):  No  CONTACT:  David Kenny 01223 582700  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY):  No  CONTACT:  David Kenny 01223 582700  Declining  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  1006874  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY):  No	CONDITION:	Extensive significant problems	TREND:	Declining
Borough Hill: a large multivallate hillfort, Sawston  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009396  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  Declining  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument List entry Number: 1009396  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  COMMERTYPE: Commercial company, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DOWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
Extensive significant problems  Frencipal Vulnerability:  Arable ploughing  Commercial company, multiple owners  Contact:  David Kenny 01223 582700  SITE NAME:  Roman site north of Brown Spinney, Shepreth / Foxton  Designation:  Scheduled Monument  Extensive significant problems  Frencipal Vulnerability:  Arable ploughing  New Entry?:  No  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  Mixed, multiple owners  Contact:  David Kenny 01223 582700  Designation:  Scheduled Monument  Designation:  Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  New Entry?:  No	SITE NAME:	Paraugh Hills a large multivallate hillfort Square	_	
PRINCIPAL VULNERABILITY: Arable ploughing New Entry?: No David Kenny 01223 582700  SITE NAME: Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DAVID Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  NEW ENTRY: Declining  PRINCIPAL VULNERABILITY: No  NEW ENTRY: No		Boi ough mill. a large multivaliate milliort, Sawston	1	
CONTACT: David Kenny 01223 582700  Roman site north of Brown Spinney, Shepreth / Foxton  Designation: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DOWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  NO  NEW ENTRY: No  Declining  NEW ENTRY: No  No	DESIGNATION:			1009396
Roman site north of Brown Spinney, Shepreth / Foxton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Scheduled Monument	LIST ENTRY NUMBER:	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006873  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER:	Declining
Extensive significant problems  TREND: Declining  NEW ENTRYP: No  Declining  No  Declining  No  Declining  No  Declining  No  Declining  Declining  No  Declining	CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument  Extensive significant problems  Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700  SITE NAME: Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument  Extensive significant problems  Arable ploughing  Commercial company, multiple owners	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No
Mixed, multiple owners  CONTACT:  David Kenny 01223 582700  Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  CONTACT:  David Kenny 01223 582700  Declining  NEW ENTRY?  No	CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners Roman site north of Brown Spinney, Shepreth /	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Foxton	Declining No David Kenny 01223 582700
Arrington Bridge Romano-British site, Shingay cum Wendy / Whaddon  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006874  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument  Extensive significant problems  Arable ploughing  Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Foxton LIST ENTRY NUMBER:	Declining No David Kenny 01223 582700
DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1006874  CONDITION:  Generally unsatisfactory with major localised problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Foxton LIST ENTRY NUMBER: TREND:	Declining No David Kenny 01223 582700  1006873 Declining
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  NEW ENTRY?:  No	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Scheduled Monument  Extensive significant problems  Arable ploughing  Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument  Extensive significant problems  Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Foxton LIST ENTRY NUMBER: TREND: NEW ENTRY?:	Declining No David Kenny 01223 582700  1006873 Declining No
problems  problems  Arable ploughing  New entry?:  No	CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument Extensive significant problems Arable ploughing Mixed, multiple owners	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Foxton LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No David Kenny 01223 582700  1006873 Declining No David Kenny 01223 582700
· · · · ·	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument Extensive significant problems Arable ploughing Mixed, multiple owners  Arrington Bridge Romano-British site, Shingay co	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  FOXTON LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  IIM Wendy / Whaddo	Declining No David Kenny 01223 582700  1006873 Declining No David Kenny 01223 582700
OWNER TYPE: Mixed, multiple owners CONTACT: David Kenny 01223 582700	CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument Extensive significant problems Arable ploughing Mixed, multiple owners  Arrington Bridge Romano-British site, Shingay cu Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  FOXTON LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Im Wendy / Whaddo LIST ENTRY NUMBER:	Declining No David Kenny 01223 582700  1006873 Declining No David Kenny 01223 582700  n 1006874
	DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  CONDITION:  PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive significant problems Arable ploughing Commercial company, multiple owners  Roman site north of Brown Spinney, Shepreth / Scheduled Monument Extensive significant problems Arable ploughing Mixed, multiple owners  Arrington Bridge Romano-British site, Shingay cu Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  FOXTON LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  IM Wendy / Whaddo LIST ENTRY NUMBER: TREND:	Declining No David Kenny 01223 582700  1006873 Declining No David Kenny 01223 582700  n 1006874 Declining

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

TERITAGE AT RISK 2014 / EAST	OF ENGLAND / SOUTH CAMBRIDGESHIRE		
SITE NAME:	Wandlebury Camp: a multivallate hillfort, earlier ur formal garden remains, Stapleford	nivallate hillfort, Iro	n Age cemetery and 17th century
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1009395
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bell barrow 500m south of Morden Grange Plantat	ion, Steeple Morde	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011714
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman settlement south of Chronicle Hills, Whittle	esford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006794
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Duxford Airfield, Duxford/Whittlesford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jane Green (LPA) 01954 713164
SITE NAME:	Gamlingay		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jane Green (LPA) 01954 713164
SITE NAME:	Papworth Everard		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Jane Green (LPA) 01954 713164
SITE NAME:	Papworth Everard - village		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
vulnerability:	Medium	CONTACT:	Jane Green (LPA) 01954 713164
YULNERABILITY: SITE NAME:	Medium Sawston	CONTACT:	Jane Green (LPA) 01954 713164
SITE NAME:		CONTACT:  NEW ENTRY:	Jane Green (LPA) 01954 713164  No
	Sawston		

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:

#### **CENTRAL BEDFORDSHIRE (UA)**



© English Heritage

The Grotto, Woburn Park, SITE NAME Woburn Listed Building grade II\*, RPG DESIGNATION: grade I CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: D (D) OWNER TYPE: Commercial company

1114010

Grotto, 1839, situated approximately 200 metres to the north east of Woburn Abbey, on the northern edge of the C18 and early C19 Pleasure Grounds. Repair works have been completed. However, the grotto work lining has delaminated in places. Discussions are ongoing.

Contact: Clare Campbell 01223 582738



© English Heritage

© English Heritage

SITE NAME:	Church of St Peter and All Saints, Battlesden
DESIGNATION:	Listed Place of Worship grade I, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311979

Medieval church of C13 origins. Little restored. Rubble walls with later brick to both C18 tower and parapets (modern). Tower cracked and stonework much decayed. Discussions with parish ongoing.

Contact: John Neale 01223 582719



SITE NAME:	Church of St Mary, Church Street, Dunton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1114060

Parish church C14 and C15, reworked 1981 by E Browning. Coursed ironstone rubble and cobbles, with ashlar dressings. Tower completely of ashlar. Stonework in poor condition, including decayed tracery to south aisle windows adjacent to porch and south aisle wall; decayed windows to north aisle; decayed clunch to tower stair; internal delamination at base of piers due to damp; decay to south side chancel, sedilia and low level plaster and high level paint delamination to chancel. Solution to be agreed.

Contact: Clare Campbell 01223 582738

1			
		D	
消费	nul	nm kma	
		1	
計畫    學		N. IT	Cite III

© English Heritage

SITE NAME:	Church of St Mary the Virgin, Church Road, Meppershall
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1312589

Parish church dating to C12 half rebuilt 1875-6 by Sir Arthur Blomfield. Stonework of coursed ironstone with ashlar dressings and clay tile roofs. Chancel, central tower, north and south transepts, nave, north and south aisles. Decayed clunch corner stones and tracery to the south aisle chapel and vestry. Tower in need of repointing. Longterm repair strategy yet to be agreed.

Contact: John Ette 01223 582711

SITE NAME:	A ringwork and bailey castle, ring ditch and enclo	sures east of Brookl	and Farm, Biggleswade
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010115
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

3 582700
3 582700
3 582700
3 582700
3 582700
3 582700 - otternhoe

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Old Warden Park (including the Swiss Garden), Old Warden / Southill
DESIGNATION:	Registered Park and Garden grade II*, 28 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)

1000474

A mid to late C19 country house surrounded by an early C19 landscape park, with unique picturesque Swiss Garden c1820. Institutional use has resulted in some compromise to the historic parkland. Completion of conservation works (including repairs to the buildings and structures within the Swiss Garden and surroundings), supported by the Heritage Lottery Fund, are anticipated in July 2014.

Contact: Clare Campbell 01223 582738

#### **ESSEX**

#### **BRAINTREE**



SITE NAME: Parish Church (dedication unknown), Hall Road, Borley DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1169675

Grade I listed church on an early manorial site, with Saxon fabric surviving in the nave. The interior has several monuments, and wall paintings are believed to be present below later limewash. The plain tiled roofs are deteriorating; many have slipped, fractured and delaminated, especially on the north side. Daylight is visible from inside through the chancel roof. Repair strategy still to be agreed.

Contact: Trudi Hughes 01223 582739

© English Heritage



SITE NAME: Parish Church of All Saints, The Street, Stisted Listed Place of Worship grade I, DESIGNATION: CA CONDITION: Very bad PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation

Parish church of C12 origins, with C13 and C14 additions. Some C19 restoration. A very unusual plan; the tower abutting the south side of the nave, leaving the west end as an uninterrupted symmetrical composition. Cedar shingles to the tower are in poor condition with daylight visible from inside. Masonry of tower buttresses poor, as is the nave roof, with visible decay in the rafter feet and wallplate. A Heritage Lottery Fund grant for repairs was accepted February 2014.

LIST ENTRY NUMBER: 1123870 Contact: Malcolm Starr 01223 582723 © English Heritage

SITE NAME:	Circular cropmark at Ferriers Farm, 190m south w	est of Hill Farm, Bu	ıres Hamlet
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010501
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Anglo-Saxon cemetery 150m east of Easterford Mil	l, Feering	
SITE NAME:  DESIGNATION:	Anglo-Saxon cemetery 150m east of Easterford Mil	I, Feering  LIST ENTRY NUMBER:	1013515
	· ·		1013515 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Long mortuary enclosure and round barrow 160m south west of Frame Farm, Feering			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017230	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Roman villa 480m south east of Hill Farm, Gestingthorpe / Wickham St. Paul			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011806	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	Yes	
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Sible Hedingham South (Swan Street), Sible Hed	Sible Hedingham South (Swan Street), Sible Hedingham		
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	No significant change	
VULNERABILITY:	High	CONTACT:	Emma Goodings (LPA) 01376 552525	
SITE NAME:	Silver End			
DESIGNATION:	Conservation Area, 22 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	No significant change	
VULNERABILITY:	High	CONTACT:	Emma Goodings (LPA) 01376 552525	

### **BRENTWOOD**



(C)	English	Heritage

SITE NAME:	Chantry Chapel and Mausoleum, Thorndon Park
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1293260

Contact: Malcolm Starr 01223 582723

commence summer 2014.



© English Heritage Archive

SITE NAME:	Thoby Priory ruins, Thoby Lane, Mountnessing
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005560 and 1293183

Ruined remains of Augustinian Priory, founded circa 1150, comprising south wall of presbytery and south nave arcade. The Priory site was subject to an archaeological evaluation in 2002-3. In June 2014 the local authority and English Heritage engaged in pre-application discussions regarding development in the vicinity of the monument which may provide opportunities for improved monument management.

Mid C19 private Roman Catholic chapel and mausoleum of the Petre family, no longer used for worship. Designed by William Wardell and located south west of Thorndon Hall (now flats). The chapel has a leaking roof and suffers from extensive stone decay. An English Heritage grant was accepted by the trust in 2010 and project development work has now been completed. The repair phase is due to

Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Paul, Mores Lane, Brentwood	
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1207545	

Parish church 1878, by EC Lee. Flint walls with stone dressings. Leaking iron gutters on stone string courses starting to cause failure in stone. Evidence of active leakage. Much Bath stone in evidence, some of which appears to be of poor quality and particularly susceptible to decay due to excess moisture. Long term strategy to be agreed.

Contact: Trudi Hughes 01223 582739

© English Heritage

### **CHELMSFORD**



SITE NAME: Church of St Michael, The Street, Roxwell Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

Roxwell is a medieval church probable C14 date, but much restored in the C19. Flint rubble with stone dressings, tiled roofs, timber porch and bell turret, shingled spire. The tiling of the roofs has loosened and tiles are slipping.

© English Heritage

LIST ENTRY NUMBER: Contact: John Neale 01223 582719 1235784

SITE NAME:	Settlement site at Ash Tree Corner, Little Walth:	am	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002140
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa 450m west of Bury Farm, Pleshey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011808
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Baddow Road		
DESIGNATION:	Conservation Area, 10 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739
SITE NAME:	Moulsham Street		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739
SITE NAME:	West End		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Michael Hurst (LPA) 01245 606739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

-- - - - - -

### COLCHESTER



© English Heritage

SITE NAME: Ruins of Church of St Mary, North of Birch Hall, Birch Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1002144 and 1110898

Contact: David Kenny 01223 582700

scheme has been agreed.

identified or agreed.

Small Norman church, no longer used for worship, C12.

Roofless ruin with some structural problems. Principally, the unconsolidated flint rubble walling is at risk. There is

Monumental water tower, C19, decommissioned in the 1980s. Redundant building and local landmark. Following the refusal of a further radical scheme to repair and alter the tower it has been sold to a new owner who is committed to its conversion if possible. No action/strategy

C15 church, re-modelled C17 and with C19 alterations. Stone rubble with brick west tower of 1758, the upper two stages of which have rusticated quoins. The high level stonework is in fair condition, but the overall condition is poor as the roofs have a substantial number of slipped slates and the interior has large areas of damp at both low and high levels, particularly in the north aisle and there is water ingress through windows. Long term solution to be

currently no public access to the site. Conservation

Management Plan has been completed, but no repair

F &	(H)	-14
The state of	200000000	
iov-an-	71111111	
uir I		

© Essex County Council

SITE NAME:	Municipal Water Tower "Jumbo", Balkerne Passage, Colchester
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1123669 Contact: John Neale 01223 582719



ര	English	Heritage

SITE NAME:	Church of St Peter, North Hill, Colchester
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1123570

Contact: Sheila Stones 01223 582716

agreed.



© English Heritage

	Botolph's Street, Colchester
DESIGNATION:	Listed Place of Worship grade II, SM, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1123508

Church of St Botolph, St

Church of Neo-Norman design in white brick with slate roofs by William Mason of Ipswich, which takes its cue from the priory ruins to the north. Dating from 1835-37, it has a four-stage gabled west portal between a pair of turrets with pyramidal cappings. Stonework is in poor condition with abundant vegetation in joints. The roofs are in poor condition with a substantial number of slipped slates. Gutters and drainpipes are in fair condition. The overall condition is poor. No action/strategy identified or agreed.

Contact: Sheila Stones 01223 582716

SITE NAME:	Small multivallate hillfort known as Pitchbury Ramparts, Great Horkesley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019959
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

TIENTAGE AT NISK 20147 EAS	I OF ENGLAND / COLCHESTER / EFFING FOREST		
SITE NAME:	Roman villa 450m south of Warren's Farm, Grea	at Tey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Remains of St Mary the Virgin's Church, Virley		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582700
SITE NAME:	Birch		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374
SITE NAME:	Distillery Pond		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374
SITE NAME:	Hythe		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Libby Kirkby-Taylor (LPA) 01206 506374

### **EPPING FOREST**



SITE NAME: Latton Priory, London Road, North Weald Bassett Scheduled Monument and Listed DESIGNATION: Building grade II\*, LB grade II CONDITION: OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A (New entry) OWNER TYPE: Private

Remains of C12 Augustinian monastery. Although doors missing; in use as barn and for occasional church services. Almost all of roofs leak; gaps in weatherboard cladding to walls all of which is putting at risk interior timber framing and in particular, important C13 carved stonework. Owner trying to source funding for scheme of major repairs.

© English Heritage LIST ENTRY NUMBER: 1017386 and 1111392 Contact: Deborah Priddy 01223 582720

© English Heritage

Essex Redoubt at Ongar Radio SITE NAME: Station, North Weald Bassett / **Bobbingworth** DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE: Commercial company

1018456

Late C19 redoubt consisting of early concrete structures and associated earthworks. Buildings at risk from failure of concrete and vandalism. Discussions with the owners and local authority currently centre on proposals to commission a Conservation Management Plan for beneficial re-use; discussions with owners regarding proposals are ongoing.

Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Littlebury Farmhouse, Romford Road, Stanford Rivers
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1306771

Timber-framed house of c1540 and earlier. A lean-to roof over the single storey is not weather proof and is in poor condition. The timber frame is currently protected by ply sheeting. The building remains unoccupied and its condition slowly deteriorating. No action/strategy identified or agreed.

Contact: Sheila Stones 01223 582716



© English Heritage

SITE NAME:	Grand Magazine, Waltham Abbey Royal Gunpowder Mills, Waltham Abbey
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Charity (heritage)

1016618

A rectangular, barrel-vaulted brick structure with a smaller barrel-vaulted west "transept". Masonry has collapsed and there is extensive vegetation growth. Cracking is evident throughout the structure, with flattening to the head of the vault and extensive moisture ingress. English Heritage is in discussion with owners over funding and maintenance of the whole site.

Contact: Deborah Priddy 01223 582720



© English Heritage

SITE NAME:	Quinan Stove, Waltham Abbey Royal Gunpowder Mills, Waltham Abbey
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

A technologically innovative building of 1935, 18 bays in length with steel hooped frames and longitudinal purlins. There is extensive evidence of steelwork corrosion and the roof and windows are deteriorating. English Heritage is in continuing discussion with the owner over the site.

SITE NAME:

OWNER TYPE:

LIST ENTRY NUMBER:

Charity (heritage) 1016618 Church of St Nicholas, Willingale Road, Fyfield

C12 church, central tower incorporating re-used Roman materials, but displaying problems with eroded quoins and open joints. Solution to be agreed.

DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1337250

Contact: Malcolm Starr 01223 582723

Contact: Deborah Priddy 01223 582720

© English Heritage



© English Heritage

SITE NAME:	Church of St Mary the Virgin, The Street, High Ongar
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1111302

A largely mid-C19 church with some medieval features surviving internally. Nave and chancel roofs show signs of batten failure and ongoing tile losses. Patching has been completed using concrete plain tiles to rear of tower, on chancel verge and elsewhere. Probable batten and tile fixing failure resulting in continuing losses of tiles. Nave and chancel require re-roofing. Condition is being monitored.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME: Parish Church of St Christopher Willingale Doe, Village Street, Willingale DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation

1111257

C14 and C15 church with south aisle added and general restoration in C19, which included extensive cementitious repointing. This has accelerated the erosion of the medieval windows, tower quoins and even some of the C19 limestone replacements. There is a risk of local collapse if the tower quoins are not repaired. Grant for Places of Worship offered in 2013 and project development is in progress as of June 2014.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Roman villa 300m south of Long Shaw, Loughton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008896
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700

SITE NAME:	A London mobilisation centre known as the Nor	th Weald Redoubt, N	North Weald Bassett / Bobbingworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018456
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Deborah Priddy 01223 582720

### **HARLOW**

SITE NAME:	Roman villa 500m north east of Harlowbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014738
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700

### **MALDON**

© English Heritage



SITE NAME: Creeksea Place, Ferry Road, Creeksea, Burnham-on-Crouch DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private

Elizabethan mansion, completed 1569 with several alterations; south range demolished in 1740. Although the house suffers from major structural problems, in recent years the owners have stabilised the building and brought parts into use. Modest repairs continue to be made but comprehensive repair is still required. In the meantime, the condition of the garden walls is of concern.

LIST ENTRY NUMBER: Contact: John Neale 01223 582719 1123776



© English Heritage

Former Stow Maries Airfield. SITE NAME: Flambirds Farm, Stow Maries, Cold Norton DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A (New entry) OWNER TYPE: Private LIST ENTRY NUMBER: 1406155

Listed at grade II\*, the site comprises of 24 operations buildings of a former World War One Royal Flying Corps airfield; the largest known surviving group of this kind. The individual buildings are rare survivors in themselves. The site has been acquired on behalf of the nation with funds from National Heritage Memorial Fund, English Heritage and Local Authorities.

Contact: John Ette 01223 582711

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of All Saints, Braxted Park Road, Great Braxted
designation:	Listed Place of Worship grade II*, RPG grade II*
CONDITION:	Very bad

PRIORITY CATEGORY: B (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1165777

The only building surviving from the original village of Great Braxted after the site was emparked. The church dates from the C12. Early surviving fabric, some of this period, includes reused Roman tiles, unusually large medieval tiles on part of the nave roof and a crown post roof. Later features are the unusual tiered pews in the nave, and the broach spire, the shingles of which are beginning to deteriorate. There are open joints and erosion in the stonework of the tower and elsewhere, including areas of very early fabric. Heritage Lottery Fund grant awarded June 2014.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Mill Mound: a bowl barrow 300m south west of Beckingham Hall, Tolleshunt Major		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009449
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Woodham Walter Hall: an early C16 house and its associated garden earthworks, Woodham Walter		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021442
DESIGNATION:  CONDITION:	Scheduled Monument, LB grade II  Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND:	1021442 Declining
	Generally unsatisfactory with major localised		

### **TENDRING**



© English Heritage

	metres south-south-west of Clubhouse, Clacton Golf Course, Clacton on Sea
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1016553 and 1111524

Martello Tower "D", 450

One of 29 original Martello towers built along the east coast, against the threat of French invasion. Built between 1808-12. Sold in 1904 and absorbed into a new golf course. The forward battery has been lost in 1980s during construction of new sea defences. Suffers from water ingress and loss of render. No action/strategy identified or agreed.

Contact: Deborah Priddy 01223 582720



© English Heritage

SITE NAME:	Martello Tower "E", 300 metres south west of junction of Marine Parade West and Wash Lane, Clacton on Sea
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1016554 and 1337150

One of 29 original Martello towers along the east coast built between 1808-12, against the threat of French invasion. The forward battery was destroyed in 1819 and it contains a large water tank, inserted after 1935 when it became part of Butlins holiday camp. Now sealed up with only access by ladder to first floor. Suffers from water ingress and loss of render. Discussions with Tendring District Council on repair scheme are ongoing.

Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:



© English Heritage

SITE NAME:	Spring Valley Mill, Spring Valley Lane, Ardleigh
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1112053

Contact: John Neale 01223 582719

Martello tower, C19. Some internal alteration and problems arising from water ingress. Pre-applications discussions for domestic conversion commenced May

now scaffolded.

C18 watermill, white weatherboarded over painted brick base. Beam engine circa 1873 now gone. Mill disused since 1930s. Machinery complete. Road elevation and lucam



© English Heritage

SITE NAME:	Martello Tower "K", Kirby Road, Walton on the Naze, Frinton and Walton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Private

1016787 and 1111504

Contact: Deborah Priddy 01223 582720

Contact: Deborah Priddy 01223 582720



© English Heritage Archive

SITE NAME:	Beacon Hill Fort, Harwich
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners

1018958

Ruined coastal artillery fortification of late C19; refortified during the two World Wars. Fabric at risk from failure of concrete, water ingress and vandalism. Monument is in split ownership. English Heritage continue to liaise with the Local Authority, private owners and interested third parties over potential new uses.



© English Heritage

SITE NAME:	St Osyth's Priory, St. Osyth
DESIGNATION:	Scheduled Monument and Listed Buildings - 7 grade I; 2 grade II*; 6 grade II, 3 LBs, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)

| 1002193 and 1111495; | 1308972; 1337158; 1146545; | 1166377; 1337159; 1337160; | 1166310; 1111465; 1111468; | 1111496; 1111460; 1111462;

1111466; 1111467

Private

Remains of an Augustinian priory founded before 1127 and post-Dissolution mansion incorporating monastic remains. The site comprises a number of buildings including the main house, a gatehouse, Darcy Tower and various other buildings and standing remains, all in need of consolidation. The Darcy Tower (pictured) is scaffolded. Discussions concerning grant aided repairs and enabling development are ongoing. English Heritage is grant aiding repairs to the ruined range and this will be completed in 2014.

Contact: John Neale 01223 582719

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Church of St Michael, The Street, Frinton and Walton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1111500

A substantial late medieval church of flint and stone rubble, much restored in the C19. The building suffers from subsidence at the east end of the chancel, where recent repairs have failed, resulting in substantial cracks reappearing in the walls and at the junction of the chancel roof and the east gable. Structural movement continues at the east end of the church, with previously repaired areas cracking again. Long-term solution to be agreed.

Contact: Malcolm Starr 01223 582723

	100	
- 373	個問	mr. A
A		
Ai		

SITE NAME: Church of St George, Badley Hall Road, Great Bromley DESIGNATION: Listed Place of Worship grade I CONDITION: Very bad PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1337189

Parish church, dating from the C14 and C15, featuring double hammerbeam nave roof with surviving original medieval polychrome decoration. Nave clerestory flushwork and windows repaired in 2012 with an English Heritage/Heritage Lottery Fund grant. New Heritage Lottery Fund application in 2014 and subsequent site visit by English Heritage confirmed the south porch masonry and roof to be in urgent need of repairs.

Contact: Malcolm Starr 01223 582723

0	Eng	lish	Н	ler	itag	ge
---	-----	------	---	-----	------	----

SITE NAME:	Crop mark site south of Ardleigh, Ardleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002146
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Beacon Hill Fort: a late 19th and 20th century co	pastal artillery fortifica	tion, Harwich
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1018958
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Deborah Priddy 01223 582720
SITE NAME:	Clacton Seafront, Clacton-on-Sea		
DESIGNATION:	Conservation Area, 4 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Philip Hornby (LPA) 01255 686170
SITE NAME:	Dovercourt, Harwich		
SITE NAME:  DESIGNATION:	Dovercourt, Harwich  Conservation Area, 6 LBs, part in SM	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Deteriorating significantly
DESIGNATION:	Conservation Area, 6 LBs, part in SM		
DESIGNATION: CONDITION:	Conservation Area, 6 LBs, part in SM Very bad	TREND:	Deteriorating significantly
DESIGNATION:  CONDITION:  VULNERABILITY:	Conservation Area, 6 LBs, part in SM Very bad Low	TREND:	Deteriorating significantly
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:	Conservation Area, 6 LBs, part in SM Very bad Low St Osyth, St. Osyth	TREND: CONTACT:	Deteriorating significantly Philip Hornby (LPA) 01255 686170
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:	Conservation Area, 6 LBs, part in SM  Very bad  Low  St Osyth, St. Osyth  Conservation Area, 62 LBs, RPG grade I, SM	TREND:  CONTACT:  NEW ENTRY?:	Deteriorating significantly Philip Hornby (LPA) 01255 686170 No
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:  CONDITION:	Conservation Area, 6 LBs, part in SM  Very bad  Low  St Osyth, St. Osyth  Conservation Area, 62 LBs, RPG grade I, SM  Poor	TREND: CONTACT:  NEW ENTRY?: TREND: CONTACT:	Deteriorating significantly Philip Hornby (LPA) 01255 686170  No Deteriorating
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:  CONDITION:  VULNERABILITY:	Conservation Area, 6 LBs, part in SM  Very bad  Low  St Osyth, St. Osyth  Conservation Area, 62 LBs, RPG grade I, SM  Poor  Low	TREND: CONTACT:  NEW ENTRY?: TREND: CONTACT:	Deteriorating significantly Philip Hornby (LPA) 01255 686170  No Deteriorating
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:	Conservation Area, 6 LBs, part in SM  Very bad  Low  St Osyth, St. Osyth  Conservation Area, 62 LBs, RPG grade I, SM  Poor  Low  Thorpe-le-Soken Station and Maltings, Thorpe-le-	TREND: CONTACT:  NEW ENTRY?: TREND: CONTACT:	Deteriorating significantly Philip Hornby (LPA) 01255 686170  No Deteriorating Philip Hornby (LPA) 01255 686170
DESIGNATION:  CONDITION:  VULNERABILITY:  SITE NAME:  DESIGNATION:  VULNERABILITY:  SITE NAME:  DESIGNATION:	Conservation Area, 6 LBs, part in SM  Very bad  Low  St Osyth, St. Osyth  Conservation Area, 62 LBs, RPG grade I, SM  Poor  Low  Thorpe-le-Soken Station and Maltings, Thorpe-le  Conservation Area, LB grade II	TREND: CONTACT:  NEW ENTRY?: TREND: CONTACT:  2-Soken NEW ENTRY?:	Deteriorating significantly Philip Hornby (LPA) 01255 686170  No Deteriorating Philip Hornby (LPA) 01255 686170  No

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

### **UTTLESFORD**



© English Heritage

SITE NAME: Barn at Little Canfield Hall,
Little Canfield

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: F(D)OWNER TYPE: Private

LIST ENTRY NUMBER: 1054762

LIST ENTRY NUMBER:

SITE NAME:

A substantial aisled barn dating from the late C14. The barn is redundant and requires structural repairs and re-roofing. Listed Building Consent for the conversion of the barn to a single residential dwelling was approved in January 2013 and building works commenced on site in April 2014.

Contact: Sheila Stones 01223 582716

Contact: Malcolm Starr 01223 582723



SITE NAME: Tilty Mill, Tilty

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (C)

OWNER TYPE: Private

Watermill, early C18. Machinery intact. Evidence of defective roof tiles and some structural failure. In need of maintenance and repair, but no action/strategy identified or agreed.

© English Heritage



© English Heritage

SITE NAME:

Church of St Mary the Virgin, Hatfield Broad Oak

DESIGNATION:

Listed Place of Worship grade I, CA

CONDITION:

Very bad

PRIORITY CATEGORY:

B (B)

OWNER TYPE:

Religious organisation

1186272

1112221

Grade I parish church, part of former Benedictine priory. C12, with late C14 clerestory, but much of the exterior is C15. Restored in 1845 by RC Carpenter. Walls of pebble rubble with limestone dressings. Part of roofing suffered from heritage crime in 2010/11. Now temporarily protected, but water ingress remains a problem. Requires permanent solution which has been provisionally agreed, but works are yet to commence.

Contact: Trudi Hughes 01223 582739



0	English	Heritage

	The Street, Manuden
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1233999

Church of St Mary the Virgin,

Church with probable C12 origins. C15 nave. Largely demolished and rebuilt in the 1860s. Constructed from flint rubble with stone dressings and a tile roof. The church forms the focal point of the village. Shingled spire showing signs of loss and curling of shingles; north transept (vestry) roof tiles are slipping. The latter are over a C15 roof structure with plastered ceiling and there is mould growth on the western part of the ceiling which is indicative of moisture ingress. Other tiles slipping elsewhere. Long term solution to be agreed.

Contact: Trudi Hughes 01223 582739

SITE NAME:	Roman fort, Roman town, Roman and Anglo-Saxon cemeteries at Great Chesterford, Great Chesterford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1013484
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Romano-Celtic temple 400m south of Dell's Farm, 0	Great Chesterford	
SITE NAME: DESIGNATION:	Romano-Celtic temple 400m south of Dell's Farm, of Scheduled Monument	Great Chesterford  LIST ENTRY NUMBER:	1017453
	·		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017453

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ADDREVIATIONS		
CA	Conservation Area	
LB	Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garden	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	

A DDDE\/IATIONIC

SITE NAME:	Square and circular barrows 260m south east of Pa	ırsonage Farm, Gre	at Dunmow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017231
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Stansted Castle: a ringwork and associated bailey I	00m north of Elms	Farm, Stansted Mountfitchet
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1009311
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes
OWNER TYPE:	Commercial company	CONTACT:	Deborah Priddy 01223 582720
SITE NAME:	Site of Waltham Hall, Takeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002161
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700



© English Heritage

SITE NAME:	Easton Lodge, Little Easton
DESIGNATION:	Registered Park and Garden grade II, 3 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1001484

Edwardian gardens designed by Harold Peto c1902, incorporating a late C17/early C18 grove. The house was fire damaged and finally demolished in 1950. Converted service buildings and infill development remain. Built structures within the garden have deteriorated, particularly the Italian Garden but planting improving. Ownership split between private owners of house and an investment company. Garden continues to open to public in a limited manner under the direction of the charity, The Gardens of Easton Lodge Preservation Trust.

Contact: Deborah Priddy 01223 582720

### **HERTFORDSHIRE BROXBOURNE** SITE NAME: Churchgate DESIGNATION: NEW ENTRY?: Conservation Area, 23 LBs Νo CONDITION: TREND: No significant change Poor Colin Haigh (LPA) 01992 785555 ext: VUI NERABII ITY High CONTACT: SITE NAME: Wormley DESIGNATION: NEW ENTRY?: Conservation Area, 12 LBs Nο CONDITION: Very bad TREND: No significant change Colin Haigh (LPA) 01992 785555 ext: VULNERABILITY: High CONTACT:

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

### DACORUM SITE NAME Roman settlement at the Cow Roast Inn, Wigginton / Northchurch DESIGNATION LIST ENTRY NUMBER: Scheduled Monument 1005254 Generally satisfactory but with significant localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY?: Arable ploughing No OWNER TYPE: CONTACT: David Kenny 01223 582700 Mixed, multiple owners



© English Heritage

SITE NAME:	Hemel Water Gardens
DESIGNATION:	Registered Park and Garden grade II
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001710

The Water Gardens were registered in 2010 and are the subject of a Heritage Lottery Fund bid in February 2014 by Dacorum Borough Council. The gardens are well-used but the original concrete structures are in need of urgent repair. Little original planting survives and improved maintenance resources are required. There is a significant problem with geese. The design legibility of the canal and basin has been eroded by recent and invasive planting and the creation of two islands circa 1980. Discussions with the Environment Agency over weirs have taken place under the Water Framework Directive.

Contact: John Neale 01223 582719

### **EAST HERTFORDSHIRE**



© English Heritage

SITE NAME:	Remains of old church tower of St Mary and All Saints Church, Thundridge
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LICT ENITON AU IMPED	1077050

Ruinous CI5 west tower belonging to the CII-CI2 church of St Mary and All Saints. Flint rubble with some dressings; a Romanesque doorway has been reset within the blocking of the chancel arch. The church was demolished in 1853, and only the three stage tower remains substantially above ground. The building is suffering from architectural decay and is threatened by vandalism and anti social behaviour. English Heritage grant-aided repairs were completed at the end of 2010 but long term management remains a problem.

LIST ENTRY NUMBER: 1077953 Contact: Deborah Priddy 01223 582720



© English Heritage Archive

SITE NAME:	Remains of St Mary and All Saints, Old Church Lane, Thundridge
DESIGNATION:	Scheduled Monument, LB grade II*, part in RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Religious organisation LIST ENTRY NUMBER: 1012268

The church was demolished in 1853, only the separately listed three stage tower (see separate entry for remains of old church tower) remains substantially above ground within the scheduled churchyard and adjacent manorial moated site. The rest of the church (demolished to foundation level) and the churchyard wall are scheduled and considered to be structurally at risk. Buried archaeological remains are also considered to be at risk from vandalism and anti-social behaviour. Long term management remains a problem to avoid repetition of vandalism.

Contact: Deborah Priddy 01223 582720



© English Heritage

SITE NAME:	Parish Church of All Saints, Church Lane, Little Munden
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1102260

Parish church dating from the C12. Construction is in flint rubble, with tower and "spike" characteristic of the county. The condition of the tiled roofs to the north east chapel, chancel and south slope of the nave are all poor. Solution yet to be agreed.

Contact: John Neale 01223 582719

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



	PRIORITY CATEGORY:	
	OWNER TYPE:	
© English Heritage	LIST ENTRY NUMBER:	

SITE NAME: Walkern and Sandon United Reformed Church, High Street, Walkern Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Poor PRIORITY CATEGORY: F (A) NER TYPE: Religious organisation

1308152

Non-conformist chapel of 1811, comprising a single hall with small vestry attached. Timber-framed, brick infill with ashlared stucco, fluted doorcase, cast iron windows, and Welsh slate roof. Internally, the original dado panels and pulpit survive. Extensive structural failure in the walls and footings resulting from substandard construction exacerbated by adjacent tree growth. Repair Grant for Places of Worship offered 2012 and repairs underway. Due for completion late 2014.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Roman site near railway station, Braughing / Stando	on	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005249
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement site north east of Letty Green, Herting	fordbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005240
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Thundridgebury moated enclosure and associated Church and graveyard, Thundridge	remains of Thundri	dgebury House, St Mary and All Saints'
DESIGNATION:	Scheduled Monument, LB grade II*, part in RPG grade II*	LIST ENTRY NUMBER:	1012268
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Deborah Priddy 01223 582720
SITE NAME:	Roman site 440yds (400m) east of Backlane Wood	l, Watton-at-Stone	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005255
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700

### **NORTH HERTFORDSHIRE**



© English Heritage Archive

.=	
SITE NAME:	Ruins of Church of St Etheldreda, Chesfield, Graveley
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Former C14 church of St Etheldreda, part demolished 1750; now roofless ruin. Unconsolidated flint rubble. Wall facing is being lost.

LIST ENTRY NUMBER: 1003542 and 1102564 Contact: Deborah Priddy 01223 582720

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME: Knebworth House, Knebworth

DESIGNATION: Listed Building grade II\*, RPG
grade II\*, CA

CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C)

Charity (heritage)

1102767

Knebworth House comprises one wing of a C16 courtyard house remodelled in lavish neo-Tudor style in the mid C19. This later external work was in very poor condition for many years, and despite a major campaign of work some years ago much remains to be repaired. A further phase of English Heritage grant-aided work is expected to early next year.

Ruined remains of a small C14 two-cell church with bellcote. Built of flint rubble with stone dressings, plastered externally. Probably a ruin by end of C17. Church was dedicated to St Nicholas. Inspection showed loss of

Contact: John Neale 01223 582719



© English Heritage

SITE NAME:	Minsden Chapel, Whitwell Road, Langley
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

voussoirs from openings and general erosion of fabric which requires consolidation. Discussions with Parochial Church Council and diocese regarding repairs took place in 2013.

OWNER TYPE: Religious organisation
LIST ENTRY NUMBER: 1003543 and 1347462

Contact: Deborah Priddy 01223 582720

Contact: Malcolm Starr 01223 582723



© English Heritage

	Lodge (the Cloisters), Barrington Road, Letchworth Garden City
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1102019

North Hertfordshire Masonic

Built 1906-7, originally a residential school for psychology based on Arts and Crafts ethics. Patron Miss A Lawrence, Architect WH Cowlishaw, a follower of William Morris. Highly idiosyncratic design incorporating a philosophical approach to materials with traditional and progressive themes, but now costly to maintain. Currently the North Hertfordshire Masonic Lodge. Problems of rainwater entry and architectural deterioration. No action/strategy identified or agreed.

© English Heritage

SITE NAME:	West Barn at Rectory Farm, Shillington Road, Pirton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

Tithe barn built late C15 or early C16. The building is now vacant and in need of major repairs. Other buildings on site have been converted into houses. Sympathetic proposals for repair and partial conversion have been agreed but have yet to be implemented.

LIST ENTRY NUMBER: 1175545 Contact: John Neale 01223 582719



© English Heritage

SITE NAME:	Church of St Faith, Barton Road, Hexton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1347066

A grade II\* church largely dating from the C13 and later, but incorporating earlier fabric of 1108-1114. The exterior was rendered in 1824. In 1947, two sides of the west tower collapsed. Extensive grant-aided repairs to the tower, roofs and rendered walls commenced in 2013. Although these are largely completed, additional costs have forced some work to be deferred, leaving parts of the chancel and vestry damp and at risk of further deterioration. The parish is currently considering options to complete the outstanding repairs.

Contact: Malcolm Starr 01223 582723

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental and first a good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Romano-British small town and late Iron Age settle	ement at Baldock	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016305
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Two bowl barrows at Bygrave, 650m east of Park \	Wood, Bygrave	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009821
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Hinxworth Roman fortlet, Hinxworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015852
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Slight univallate hillfort on Wilbury Hill, Letchwort	h Garden City / Ick	leford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016410
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Ring ditch and enclosure, Newnham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003596
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Triple ditches at Galley Hill, Sandon / Kelshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003550
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Wymondley Priory, barn, moat, associated earthwo Wymondley	orks, enclosures, pl	atforms, hollow-way and conduit head
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER:	1013338
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

ST ALBANS			
SITE NAME:	The Aubreys camp, Redbourn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
OUT NAME			
SITE NAME:	Wheathampstead earthwork incorporating Devils I	Dyke and the Slad, '	Wheathampstead / Sandridge
DESIGNATION:	Wheathampstead earthwork incorporating Devils I Scheduled Monument	Dyke and the Slad, ' LIST ENTRY NUMBER:	Wheathampstead / Sandridge 1003521
		,	·
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1003521

### **STEVENAGE**



© Stevenage Borough Council

SITE NAME:	Old malt houses and kiln at Alleyne's School, High Street, Old Stevenage
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)

LIST ENTRY NUMBER: 1005259 and 1101202

Local authority, multiple owners

Long range comprising former malt house and kiln, C17 or earlier. Two storey, red brick with timber upper storey with brick infill panels. Germinating floor missing. Leaning markedly; now propped. Scheme of structural repairs agreed with Hertfordshire County Council's consultant conservation engineer in April 2014. It is envisaged that repairs are completed before December 2014, by which time structural integrity will have been reinstated. School use proposed by charitable trust.

Contact: Deborah Priddy 01223 582720

### THREE RIVERS



© English Heritage

SITE NAME:	Langleybury House, Langleybury, Abbots Langley
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
	1172157

LIST ENTRY NUMBER: 1173157

OWNER TYPE:

Country house c1725. Formerly in use as part of a school, but vacant since 1996, Proposals for the repair of the house have yet to be implemented, and while use of the buildings for filming helps ensure their protection, the implementation of a comprehensive scheme is desirable.

Contact: John Neale 01223 582719

### WATFORD



© English Heritage

SITE NAME:	stable block, Hempstead Road, Watford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority

1175392

Late C17 house built as dower house to Cassiobury. Last occupied as offices, the building has been empty for many years. Various repairs have been carried out over this period. The future of the building remains unclear, but the recently established Friends of Little Cassiobury are working on an imaginative scheme for the building's reuse.

Contact: John Neale 01223 582719

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

### I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

Frogmore House, High Street (north east side), Watford

DESIGNATION: Listed Building grade II\*

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: | 175515

A fine house built in 1716, Frogmore House was last used as flats. The house was repaired some years ago but remained vacant due to the uncertainty surrounding the future use of adjacent land. Discussions about an imaginative re-use of the building continue in connection with proposals to develop the adjacent site, but have yet to be finalised.

Contact: John Neale 01223 582719



Church of All Saints, Horseshoe Lane, Leavesden, Watford

DESIGNATION: Listed Place of Worship grade II

CONDITION: Fair

PRIORITY CATEGORY: F (B)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1175616

A grade II listed church dating from 1853, designed by Sir George Gilbert Scott, and little changed. Retains good historic fittings and details internally, including stained glass. The roofs have courses of ornate scalloped plain tiles, probably original. Many are now delaminating and slipping; leakage is reported. A Repair Grants for Places of Worship grant was offered for repairs in 2011. Repairs to the nave and chancel roofs are in progress and due for completion late 2014.

Contact: Malcolm Starr 01223 582723

### WELWYN HATFIELD

© English Heritage



© Priest Restoration Ltd

Paine Bridge at Brocket Hall, Marford Road, Lemsford, Hatfield

DESIGNATION: Listed Building grade II\*, RPG grade II

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1173560 Contact: John Neale 01223 582719

Very fine classical bridge, built of stone, to designs of James Paine. Stonework is decaying progressively.

LUTON (UA)			
SITE NAME:	High Town Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Gemma Pike (LPA) 01582 546317
VULNERABILITY:	Low	CONTACT:	Gemma Pike (LPA) 01582 546317
VULNERABILITY:  SITE NAME:	Plaiters Lea, Town Centre	CONTACT:	Gemma Pike (LPA) 01582 546317
		NEW ENTRY?:	Gemma Pike (LPA) 01582 546317  No
SITE NAME:	Plaiters Lea, Town Centre		· /

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental and first a good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

### **NORFOLK**

### **BRECKLAND**



© English Heritage

SITE NAME Shadwell Court and clock tower, Brettenham

Listed Building grade I, RPG DESIGNATION: grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1076940

Country house circa 1720 with substantial C19 additions set in the centre of C18 park. Mid C19 formal gardens to the west, now much simplified. The building has been unoccupied for many years and affected by severe dry rot outbreaks set off by leaks in the roof. Extensive roof repairs have been undertaken and the main building is now stabilising. Part of the attached stable yard is in use and maintained, but part is deteriorating.

Contact: David Eve 01223 582721



@ Andrew Gayton

Dereham Maltings (Crisp SITE NAME: Malting), Norwich Road, East Dereham, Dereham

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE:

Private LIST ENTRY NUMBER: 1246348

Large complex of C19 maltings, disused and vacant. Proposal to build houses on part of land and repair and reuse of maltings has been discussed in principle, but no yet

Contact: David Eve 01223 582721



© English Heritage

SITE NAME: Guntons Farmhouse, Reymerston Road, Garvestone DESIGNATION: Listed Building grade II\* CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY F (F) OWNER TYPE: Private

LIST ENTRY NUMBER: 1342566

Timber-framed manor house, late C16. General neglect; lack of repairs leading to decay of windows and exterior brickwork. Some repairs have been carried out, but longterm solution still to be agreed and implemented.





© English Heritage

SITE NAME: Church of St Mary, West Tofts, Lynford DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1077249

C13 foundation, with later medieval additions, greatly altered C19 by A. W. N. Pugin, with much of the significance of the building deriving from this latter stage of works. Problems identified with rainwater goods causing internal environmental conditions leading to problems for decorative work. English Heritage funded investigative work and repairs between 2008 and 2012. Further repair work funded by English Heritage is currently underway. This is now entering its final phase and is due to be completed by the end of 2014.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of All Saints, Stanford
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172174

C12 and later medieval church now redundant, now owned by the Ministry of Defence. Chancel arch in danger of collapse and masonry is falling from the tower. English Heritage has offered grant aid towards repair works to secure the failing chancel arch, and to consolidate the top of the tower. Diocese and military discussing way forward and will advise English Heritage once outcome known.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category shown in brackets, otherwis

'New entry' is noted.

	ADDK	EVIATIONS
is e	CA LB LPA NP RPG SM UA WHS	Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

A DDDE\/IATIONIC

The same of the sa	t		A STATE OF THE STA
	DA.		
			T ME
*		M75.01	
	Trans.	MANAGEMENT CO.	

© English Heritage

SITE NAME:	Church of St Mary the Less, Bury Road, Thetford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1297899

Former church, CII foundation, fabric mainly late CI4. West tower CI5, chancel rebuilt CI9. Redundant and has suffered from decay and vandalism. A scheme for residential conversion was granted consent but has not been implemented. Some repairs to the roof have been carried out but the church remains in a poor condition and with an uncertain future.

Late medieval Abbey outbuilding, converted to farm building and latterly workshop. Previously neglected. Currently weathertight. Permission for conversion to residential use granted but not implemented.

Contact: David Eve 01223 582721

© English Heritage

SITE NAME:	Abbey Farm Barn, Monksgate, Thetford
DESIGNATION:	Listed Building grade I, SM, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1297897

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: David Eve 01223 582721

Contact: David Eve 01223 582721



© English Heritage

SITE NAME:	Abbey Farm Cottage, Thetford
DESIGNATION:	Listed Building grade I, SM, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1207935

Late medieval Abbey outbuilding, converted to farm building, incorporating accommodation. Previously neglected. Currently weathertight. Permission for conversion to residential use granted but not implemented.



© English Heritage

SITE NAME:	Church of St Andrew, Brettenham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER:	1074025

This grade I church is of Norman origins, but of particular interest for the extensive work undertaken by Teulon in 1852, including a highly decorative octagonal vestry, internal ironwork screens, a fretwork reredos, alabaster panels, a polychrome scheme of decoration (now largely painted over) and a set of pews. Extensive outbreak of dry rot affecting the entire interior (pews and flooring). Repair Grants for Places of Worship grant offered in 2012, with works due for completion summer 2014.

Contact: Malcolm Starr 01223 582723



© English Heritage

SITE NAME:	Church of St Peter and St Paul, Church Road, Griston
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172332

Parish church dating from C14/C15 comprising west tower, nave, chancel and north porch. Roofs in nave, porch and chancel date from the 1884 restoration by JB Pearce. Constructed in flint rubble with limestone dressings. Parapet at top of tower contains some loose and weathered flint flushwork panels. Loose flints have fallen on adjacent roofs. Tower roof is leaking. A grant application has been submitted to the Heritage Lottery Fund.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

M Scheduled Monument
A Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Michael, Hockering
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077354

A parish church of medieval origin, with C13 three-bay north arcade and later additions of CI5 and CI9 date. Flint with ashlar and some brick dressings. Concern over structural condition of chancel roof. Repair Grants for Places of Worship grant offered in 2012. Repairs to chancel roof underway in May 2014.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

SITE NAME:	Church of Holy Trinity, Hockham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077572

C14 church, possibly incorporating earlier fabric. Distinctive features include the unusual C19 octagonal bell tower, a large C15 wall painting on the chancel arch, C15 pews and benches, and the C15 plaster barrel-vaulted chancel ceiling. Other wall paintings may survive in the chancel under later plaster. The chancel roof leaks badly and puts the interior at risk. There are cracks running through the chancel arch wall painting. Repair Grants for Places of Worship grant offered. Project development is underway.

Contact: Malcolm Starr 01223 582723



© English Heritage

© English Heritage

© English Heritage

SITE NAME:	Church of St Andrew, Holme Hale
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Good
PRIORITY CATEGORY:	E (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1152077

Medieval and later church. Flint with ashlar and some brick dressings. Slate and pantiled roofs. West tower; nave with north aisle and north porch; chancel. C14 and C15 west tower with angle buttresses. The condition of the tower roof is deteriorating. Repair grant offered in 2010 and work is now complete. Exceptionally, the number of bats using the nave remains an issue and impacts on the usability of the building. Long-term solution to this issue currently being discussed.

Contact: Trudi Hughes 01223 582739



SITE NAME: Church of St Andrew, Lexh	am
DESIGNATION: Listed Place of Worship gra	de I
CONDITION: Very bad	
PRIORITY CATEGORY: A (New entry)	
OWNER TYPE: Religious organisation	
LIST ENTRY NUMBER:   342495	

Situated on an elevated circular site, indicative of an early foundation, this church comprises Saxon round tower, largely in-tact; Nave and chancel in-line and largely rendered; with evidence of long and short work at quoins. S porch. N and S doorways ca 1200. Perpendicular east window. Fine C14 piscina. Restoration of 1837 which provided the roofs to the nave and chancel. E window glass by Clayton & Bell. The round tower is surmounted by an octagonal parapet which does not fit the geometry of the walling below, which has led to excess water ingress into late Saxon walling. Roof leaks.

Contact: Trudi Hughes 01223 582739



© Ruth & Peter Blackman

SITE NAME:	Street, Litcham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169244

C14 and C15 church in flint rubble masonry plus rebuilt tower all in brick, 1699. Chancel roof tiles slipping and gutters failed/moving. Drains ineffective. English Heritage grant offered December 2011. North aisle roof material is currently felt but can only be veiwed as an interim solution. Repair work began in July 2013, completion expected in summer 2014.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS** I PA

Conservation Area Listed Building Local Planning Authority National Park ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of St Andrew, Fairstead Lane, Little Cressingham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation

1077227

Parish church. The C15 tower is partially demolished and the two western most bays of the nave and south aisle are roofless. The two most western north aisle bays have been demolished except for the west wall. The present entrance is to the west in the brick wall dividing the roofed church in use from the ruin. A corrugated roof covers the south aisle, while the nave is roofed in plain tile. Roof is leaking with damp penetration in aisles. Vegetation growth is also an issue. No action/strategy as yet identified or agreed.


Contact: Janine Dykes 01223 582724



SITE NAME: Church of St Margaret, Lyng Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: F (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1169125

A grade II\* listed church dating from the C13 with interesting later alterations, especially the "Dutch" gable added to the south porch in the C18 and the unusually narrow, offset chancel of 1912. The nave has Westmorland slates, many of which are fractured and slipped. A Repair Grant for Places of Worship was offered in 2011. Works are due to be completed late 2014.

Contact: Malcolm Starr 01223 582723



© English Heritage

© English Heritage

SITE NAME:	Church of St Martin, Church Street, New Buckenham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation

1077529

Parish church, randomly knapped flint with ashlar dressings. Lead nave and aisle roofs, with machine-made clay plain tiled chancel. C16 west tower. C15 Nave and aisles, restored 1879. C13 chancel but rebuilt 1895. Nave roof covering no longer watertight. North nave clerestory windows' saddle bars rusting and require replacement. Similar issues with two windows in the north aisle where glass and surrounding stonework is cracking. South aisle floor rotted and requires extensive repair/replacement. Heritage Lottery Fund grant offered 2014.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of All Saints, Church Lane, Old Buckenham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342465

Church with C12 origins and round tower partly rebuilt in C14 and restored in 1858. Widespread loss of pointing to brickwork of tower upper stage and some fall of flint rubble from stage below. North slope of thatched nave roof shows thinning and some sagging plus quite shallow oversailing detail at eaves. Repair Grant for Places of Worship has been offered for the tower. Project development currently in progress with a view to completing urgent repairs by autumn 2014.

Contact: Malcolm Starr 01223 582723



© English Heritage

SITE NAME:	Church of St Peter, Church Road, Shropham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077578

Mid C13 nave, north aisle and chancel; remodelled in C15. C15 W tower; restored 1867. Flint with ashlar dressings and slated roofs. North nave roof heavily tingled (a form of temporary repair) and may require replacement in near future. Slow decline, no overall solution agreed, but monitoring is ongoing.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Botolph, Stow Bedon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077585

Parish church with C12 origins, re-modelled in the C14, C15 and C19. Constructed with flint with ashlar dressings and slate roof replaced following second world war bomb damage. There is evidence for two phases of structural ties in the south elevation, but they do not appear to be working. The interior has recently been re-plastered, but structural movement and a damp problem persists. Heritage Lottery Fund grant under Grants for Places of Worship Scheme offered July 2014. Contact: Robert Parkinson 01223 582733

© English Heritage

	A	4	
	high		
Sim.			EEL
- 100			3 40

SITE NAME:	Church of St Peter and St Paul, Church Lane, Swaffham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1269628

Parish church dating from C14, with C18 and C19 alterations and restorations. Flint, Barnack stone construction with some brick. Gutters, roof, windows and interior in poor condition. Heritage Lottery Fund grant accepted late 2013. Investigations on extent of repairs required is currently ongoing.

© English Heritage



SITE NAME:	Church of St Andrew, Tottington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342814

Parish church dated to 1360, restored 1885-6 by EP Willins. Rendered flint with ashlar quoins and tiled and pantiled roofs. West tower, nave, aisles and chancel. Tower of four stages. Angle buttresses to east and west becoming diagonal. Arched and moulded west door below 2-light window. High level stonework on tower an issue; chancel ceiling at risk of collapse. No action/strategy identified or agreed.

Contact: Trudi Hughes 01223 582739

Contact: Robert Parkinson 01223 582733

(C)	Eng	lish	He	ritage



SITE NAME:	Church of St Mary, Church Road, Whinburgh and Westfield
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1152030

An architecturally and historically important church, as its grade I listing indicates, dating from at least the CI2, with CI3 tower, the latter unusual in that it is attached to the south side of the nave. The present chancel may incorporate an earlier Norman structure. Its roofs are in poor condition, as is the ground drainage system generally. The church suffers from leakage and damp penetration from the ground, which is putting the plaster and its early decoration at risk. A Repair Grant for Places of Worship was offered in 2011. Repair works expected to be completed by late 2014.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Roman enclosure 3/4 mile (1210m) north east of Pa	nworth Hall, Ashil	I / Holme Hale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003965
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Tumulus west of Leader's Spinney, Banham		
SITE NAME: DESIGNATION:	Tumulus west of Leader's Spinney, Banham Scheduled Monument	LIST ENTRY NUMBER:	1003161
		LIST ENTRY NUMBER: TREND:	1003161 Declining
DESIGNATION:	Scheduled Monument		

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

I PA ΝP RPG

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	OF ENGLAND / BRECKLAIND / BROADLAIND		
SITE NAME:	A Roman roadside settlement 150m south west of	Billingford Hall, Bill	ingford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021458
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa west of Woodrising Wood, Cranwort	h	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003930
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Leylands Farm Romano-British site, Hockwold, We	eeting-with-Broomh	ill / Hockwold cum Wilton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Dereham, Dereham / Scarning		
DESIGNATION:	Conservation Area, 97 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Andrew Gayton (LPA) 01362 656257
SITE NAME:	Thetford		
DESIGNATION:	Conservation Area, 170 LBs, 9 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Andrew Gayton (LPA) 01362 656257

### **BROADLAND**



SITE NAME-Drayton Lodge, Drayton High Road, Drayton Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(C)

Ruinous lodge, constructed early C15. In need of structural repairs including wall capping and repointing. English Heritage has provided advice to the Local Authority conservation officer on repair techniques who are liaising with the owner regarding repairs. Discussions to agree a suitable repair strategy are ongoing.

© English Heritage

OWNER TYPE: Commercial company 1003999 and 1306023 LIST ENTRY NUMBER:

Contact: Will Fletcher 01223 582710



Stockhouse at Manor Farm, The SITE NAME: Green, Freethorpe DESIGNATION: Listed Building grade II\* CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

Farm building, 1828. Built for the Walpole family who owned Freethorpe in the C19. This is the most complete example of probably no more than six surviving stock houses of this type. In very bad condition with structural cracking to west gable end, serious erosion to east gable, brick copings missing and thatch slipping. As of June 2014, works are not yet completed on the conversion of the complex to mixed use.

1152503 Contact: David Eve 01223 582721

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

### LPA ΝP RPG

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Panxworth Church Tower, Panxworth, Woodbastwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1372709

Medieval church tower. The nave, although rebuilt in 1847, was demolished, along with the chancel, in 1981. The tower, which is covered in ivy, requires stabilisation and the roof and internal floor have collapsed but not fully fallen through to ground level. The tower was struck by lightning and parapet damaged in 2007. Panxworth Parochial Church Council and local interest group have agreed schedule of repair to the building with English Heritage grant aid. Repairs are expected to be completed by end of summer 2014.

Contact: Trudi Hughes 01223 582739



© English Heritage

© English Heritage

© David Lemon

SITE NAME:	Parish Church of St Agnes, Church Lane, Cawston
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1263465

Large medieval church built on wealth of iron trade. Tower paid for by the Earl of Suffolk in C15. Hammerbeam roof and painted screen. Stonework decay to base of south porch. Some vegetation in tower, signs of plaster movement and water ingress. No action/strategy identified or agreed.

Contact: Malcolm Starr 01223 582723



SITE NAME:	Church of St Margaret, School Road, Drayton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1306000

Parish church, with medieval fabric, though mainly rebuilt in C19. Built of flint with stone dressings. Nave roof thatch. West tower, north aisle, north vestry, south porch, nave, north chancel chapel and chancel. Square tower, with two light west window, lancet sound holes and single light bell openings. Battlemented parapet. C20 brick and flint vestry. Nave roof in poor condition with clear water ingress. Vestry floor has potential for structural failure and drains not working. Repair Grant for Places of Worship offered and project development ongoing

Contact: Trudi Hughes 01223 582739



SITE NAME:	Church of St Peter and St Paul, Church Lane, Oulton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1372723

Parish church, comprising nave, chancel, south porch and tower with embattled parapets. The building is of flint rubble, with limestone dressings. The tower has loose masonry at parapet level and possibly below. An application for a Grant for Places of Worship has been made. Site visit confirmed that tower parapet has loose masonry and there are other high level structural defects to the tower which require urgent attention.

Contact: Trudi Hughes 01223 582739

CONTRACTOR OF CO
The second secon

© Nicholas Warns Architects

SITE NAME:	Church of St Andrew, Reepham Road, Wood Dalling
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172116

Parish church. C13, C14 and C15. Flint construction with limestone dressings. Extensive repairs completed in recent past to north and south aisles and to the nave. However, the chancel appears to be suffering from roof spread where the roof structure shows visible signs of sagging. Monitoring is underway, although no long term solution currently agreed.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Helen, The Street, Woodbastwick
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1154645

C15 church noted for its painted screens. The building is generally in fair to good condition with the exception of the nave roof which is poor and needs replacing. A Repair Grant for Places of Worship has been offered by the Heritage Lottery Fund and works are underway.

Contact: Trudi Hughes 01223 582739

© English Heritage

SITE NAME:	Roman settlement at Brampton, Brampton / Bux	ton with Lammas	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003698
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman camp and settlement site west of Horster	ad, Horstead with Sta	ınninghall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003928
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	RAF Coltishall, Coltishall / Buxton with Lammas		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Barbara Hornbrook (LPA) 01603 431133

### **GREAT YARMOUTH**



town walls, 2-3, Dene Street, Great Yarmouth Scheduled Monument, 4 LBs, 3 DESIGNATION: CAs CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Tower on Great Yarmouth

Derelict tower on Great Yarmouth town walls in very poor

© English Heritage

© English Heritage

LIST ENTRY NUMBER: 1003782 Medieval vaults under, 50-56, SITE NAME: Howard Street South, Great Yarmouth DESIGNATION:

Scheduled Monument, CA Poor N/A PRIORITY CATEGORY: D(D) Private, multiple owners

LIST ENTRY NUMBER: 1003935

CONDITION:

OCCUPANCY:

OWNER TYPE:

C12 and C14 vaulted undercroft of possible medieval merchant's house. Water penetration, condensation and the poor condition of existing timber shores mean that the structure is at risk of structural failure. Owners considering a scheme of structural propping.

Contact: Will Fletcher 01223 582710

Contact: David Kenny 01223 582700

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP

RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	The Winter Gardens, Marine Parade, Great Yarmouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Cast iron seaside winter gardens, situated on the seafront within the conservation area. Cruciform plan, with lantern over crossing. Cast iron components corroding due to excess moisture leaking into structure. Owner looking at possibility of reinstating winter gardens function. Currently the owner is discussing options which may result in bid for Heritage Lottery Fund funding.

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME:	Old St Margaret's Church, Coast Road, Hopton-on-Sea
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (D)

Religious organisation

1271608

Ruins of C12 to C14 church partly destroyed by fire in the C19. A local building preservation society is working with the community to develop a program of repair for the ruins. Removal of vegetation and survey work already largely complete. Grant offered by English Heritage towards major repairs in March 2014 and repairs due to commence summer 2014.

1050970 Contact: Malcolm Starr 01223 582723



SITE NAME: Church of St Peter and St Paul, Church Road, Burgh Castle DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: F (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1051008

Parish church. Late CII west tower and CI3 nave and chancel re-modelled in C15. North aisle 1847. Flint construction with ashlar dressings and some brick. Slate roofs. Repair Grant for Places of Worship grant offered in 2013. Repairs now underway to address structural failure in north aisle and failure at the chancel north east corner as well as the subsidence at the foot of the chancel east gable.

Contact: Trudi Hughes 01223 582739

ila sa	8
. 罚 世	

© Nicholas Warns Architects

100 110	Manage St.
7 4	
CONTRACTOR	
16 图	
ALCOHOL:	

©	English	Heritage

SITE NAME:	Church of All Saints, Church Lane, Filby
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1287564

A church of C13 origins or earlier, with C14 and C15 alterations, and some C19 restoration, but the lower panels of the medieval rood survive with their original polychrome decoration and depictions of saints. PCC applied for a Heritage Lottery Fund grant and in May 2014, English Heritage produced a report confirming that rainwater goods, tower masonry, and chancel roof are in poor condition.

Contact: Malcolm Starr 01223 582723



© English Heritage

SITE NAME:	Church of St Nicholas, Church Plain, Great Yarmouth
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1096813

Parish church founded in 1101 in association with adiacent Benedictine priory. Considered by Pevsner to be the largest parish church in England. Base of tower early C12; remainder C13; restored in C19. Extensively fire damaged in World War II. First phase of urgent repairs completed July 2013. However, further urgent repairs are needed including stonework repairs to central tower; tower north east turret repairs; high level flashing repairs; repairs to north transept buttress stonework; various other high level stonework repairs required. Solution to be agreed.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of St John, York Road, Great Yarmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1271806

Parish Church, 1857 by JH Hakewill with later alterations. Flint with red brick and ashlar dressings. Slate roofs. Comprising a nave, apsed chancel and south porch. 1859 south aisle added by AW Morant, nave extended west 1866, north aisle, transept and north chancel aisle 1878. Restored 1989. Roofs, gutters and high level stonework in poor condition. Repair Grants for Places of Worship grant was offered in 2010, with investigation work completed in 2012. However, the repair stage of the grant has not been offered. Discussions to inform solution are ongoing.

Contact: Trudi Hughes 01223 582739

1	4	W.	1
4	الماء		1
Miles			
1	EL IN	7111	
	- Laborator		

SITE NAME: Church of St Edmund, Church Road, Thurne DESIGNATION: Listed Place of Worship grade II\* CONDITION: Very bad PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1304567

Church featuring early C14 tower with later top with brick triple-stepped battlements. Nave and chancel early C14; rest is Perpendicular. Restored in 1853. Chancel roof showing signs of serious structural decay; ceiling panels fallen. Grant application to the Heritage Lottery Fund in 2014 was successful and development phase is underway.

Contact: Robert Parkinson 01223 582733

© English Heritage

### KING'S LYNN AND WEST NORFOLK

SITE NAME:



3.1.2.1.0.1.1.E.	Hall, Ely Road, Denver
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

Gatehouse north of Denver

Gatehouse circa 1570 in private garden. In need of repair due to lack of maintenance. English Heritage in discussion with owner.

© English Heritage Archive

OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1077847

Contact: David Eve 01223 582721



© English Heritage

SITE NAME:	Denver Mill, Sluice Road, Denver
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1077850

Grade II\* listed mill built in 1835 ceased working in 1941 after being struck by lightning. Repairs undertaken in the late 1990s but the render has failed and sails removed for health and safety purposes in 2011, when one of the steel stocks broke. A further programme of conservation is required to the make the building safe and put the mill into working order for demonstration purposes. The owner is in discussion with the WREN Heritage Fund, Heritage Lottery Fund and English Heritage for assistance with the repair costs.

Contact: John Ette 01223 582711



© Norfolk County Council

SITE NAME:	Ruins of St Mary's Church, Appleton, Flitcham with Appleton
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1020768

Ruined church (Sandringham stone, carstone, conglomerate, limestone and flints) showing evidence of original C11 construction. Heavy vegetation cover has been for the most part removed, through a management agreement with Norfolk County Council funded by English Heritage. Rough racking to wall tops is needed, especially to north and south nave walls, and repairs to C14 arcade on the south side. Urgent conservation work to walls under discussion.

Contact: John Ette 01223 582711

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS** I PA

Conservation Area Listed Building Local Planning Authority National Park ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Detached porch in courtyard, Hunstanton Hall, Old Hunstanton
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)

Private

1077922

Freestanding porch built in 1618, in the centre of the courtyard of the Hall. Porch was retained in 1853 after the wing to which it was attached was demolished. The front piece and short return walls remain, but with no roof. Repair and consolidation needed.

Former chapel, C13 and C14. Roofless and overgrown; in need of consolidation, repair and control of burrowing animals. English Heritage is working with local partners to develop a strategy for repair. Condition continuing to deteriorate in June 2014. Actions cannot be implemented

Contact: David Eve 01223 582721

until ownership issues are resolved.

		ib.
_		
		9
A SHEET AND A SHEE	and the same	

© English Heritage Archive

SITE NAME:	Chapel of St Andrew, Barret Ringstead, Old Hunstanton
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Religious organisation LIST ENTRY NUMBER: 1003986 and 1077919 Contact: Will Fletcher 01223 582710



© English Heritage Archive

SITE NAME:	Ruins of Church of St Edmund, Egmere Road, Egmere, Walsingham / South Creake
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1018173 and 1039409

Ruined church, C12 and C14. The only above-ground remains of the deserted medieval village. The building is a ruin with no possibility of economically beneficial use. It is in need of consolidation due to loose flints.



© Norfolk County Council

SITE NAME:	West Acre Priory, West Acre
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*; 3 grade II, 3 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)

B (B) Private

1008352 and 1077660; 1077661; 1342410; 1171741; 1077662

Large Augustinian priory (building began circa 1135). A large lump of flint and stonework fell in early 2005 from what appears to be the ruins of the east range of the cloister. As the lump fell it damaged further smaller areas of flintwork. More corework has been exposed and is now vulnerable to further loss.

Contact: David Kenny 01223 582700

Contact: David Kenny 01223 582700

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of All Saints, Bircham Newton, Bircham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077805

Late C13 church in flint rubble, reordered 1854. Chancel roof plain tiles in serious condition with battens faded. Drains and rainwater goods need repair. Repair Grant for Places of Worship offered, with repair work commencing in July 2013. Due for completion at end of 2014.

Contact: Trudi Hughes 01223 582739

© English Heritage



SITE NAME:	Church of St Mary, Great Bircham, Bircham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077807

Flint rubble church of C13 and C14 plus evidence of Norman work. Lofty nave arcades, great C14 west window. All windows in severe condition, bowed, buckled, holes, broken panes, high risk of loss. Repair Grants for Places of Worship grant offered in December 2011. Project development phase completed and repair works are underway. Estimated completion is summer 2014.

Contact: Trudi Hughes 01223 582739

© Ruth & Peter Blackman



SITE NAME:	Church of St Clement, Burnham Overy
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1239094

Parish church of medieval origins comprising a nave, south aisle, south porch, central tower, south vestry and chancel. The central, massive, squat tower is possibly Saxon in origin. The tower is surmounted by a pyramidal roof with a timber lantern. Church rebuilt in C13 although there is evidence of an earlier north aisle. Constructed for the most part, in random flintwork with limestone dressings. Moisture ingress is evident at junction of nave and south aisle roof. Roof sheets splitting and admitting water. Parish offered a Heritage Lottery Fund grant in May 2014.

Contact: Trudi Hughes 01223 582739

© English Heritage



SITE NAME:	Church of All Saints, Church Lane, East Winch
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1342382

Parish church of C14 and C15 date with restorations in 1878 by Sir George Gilbert Scott. Constructed from rubblestone, carstone and part rendered. Slate roofs. Masonry of the tower, south aisle, and chancel deteriorating badly. Ineffective ground drainage is making the interior damp and places the historic pews at risk. A grant application for all these repairs has been successful. Work is expected to begin in 2014 or 2015.

Contact: Malcolm Starr 01223 582723

© English Heritage



© English Heritage

SITE NAME:	Church of All Saints, Church Road, Hilgay
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077719

Parish church. Brick west tower of 1794, remainder of carstone with ashlar dressings. Late C14 south aisle, nave and chancel. Slate roofs. Two stage tower supported by angle buttresses to first stage where belfry is set back at string course. 3-light timber west window. Roundels to north end south. Arched belfry windows with timber trellis screen. Water and damp penetration with vegetation growing on fabric of roofs indicating building has lost weather integrity. Solution to be agreed.

Contact: John Ette 01223 582711

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBR	eviations
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



100		
♠ English	Llawieana	

SITE NAME:	Church of St Mary The Virgin, Church Lane, Sedgeford
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172064

roofs. Urgent roof repairs needed to the south transept, south porch high level roof and rainwater goods to the south side of the church. Further repairs required to nave clerestories, south aisle parapets and south transept buttresses. Consolidation of loose internal plaster is required where the stability of the wall paintings is at risk. Heritage Lottery Fund grant awarded July 2014. Development phase due to commence. Contact: Robert Parkinson 01223 582733

		3		
000	N. II		1	I
				X

SITE NAME:	Church of St Germans, Wiggenhall St. Germans
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077892

Grade I listed church built between C13 and C16. Carved pew ends c1500 are of great historical importance. The church contains font donated in 1851 and also the font from the nearby ruined Wiggenhall St Peter's church. Stonework, render, roofs and rainwater goods are in very poor condition. Has suffered from crime (vandalism). No action/strategy identified or agreed.

Medieval church. Flint with stone dressings, clunch rubble and stone dressings to chancel, slated nave and porch

Contact: Janine Dykes 01223 582724

©	Eng	lish	Н	erit	age
---	-----	------	---	------	-----

SITE NAME:	Roman fort (Branodunum), Brancaster		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003983
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Moated site and associated earthwork enclosure	s 190m south east of	Denver Hall, Denver
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016486
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Remains of St Andrew's Church, East Walton		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019836
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
OWNER TYPE:  SITE NAME:	Private  Romano-British villa 400m west of White House		David Kenny 01223 582700
			David Kenny 01223 582700
SITE NAME:	Romano-British villa 400m west of White House	, Fring	·
SITE NAME: DESIGNATION:	Romano-British villa 400m west of White House Scheduled Monument	, Fring  LIST ENTRY NUMBER:	1020861

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Well Hall Roman settlement, Grimston / Gayton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003168
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Remains of tower on Lodge Hill, Snettisham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003912
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Moated site of Wormegay Priory, fishponds and ass	ociated enclosures	, Wormegay
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009987
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No

### NORFOLK BROADS (NP)



Burgh Mill, The Street, Burgh and Tuttington, North Norfolk

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: B (C)

OWNER TYPE: Private

Three storey C18 watermill on the River Bure. Milling has ceased and the vacant building is in disrepair. Condition survey and feasibility report undertaken. Owner is funding a scheme of re-roofing and emergency structural propping. Close liaison with Local Authority Heritage at Risk Officer.

© English Heritage LIST ENTRY NUMBER: 1250712 Contact: David Eve 01223 582721

Halvergate Marshes, Halvergate / Mautby / Norton Subcourse / Reedham / Stokesby with Herringby /
Thurlton / West Caister / Acle / Belton with Browston / Burgh Castle / Fleggburgh / Freethorpe / Fritton and
St. Olaves / Haddiscoe, Broadland

DESIGNATION:	Conservation Area, 28 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Ben Hogg (LPA) 01603 756074

### **NORTH NORFOLK**



© English Heritage Archive

SITE NAME:	Ruins of Broomholm Priory, Abbey Street, Bacton
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, part in CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (C)
OWNER TYPE:	Private

Priory remains, primarily C12-C13 in date. The general condition of the site has been stabilised though the introduction of a Section 17 management agreement. Stabilisation of the ruins is urgently needed and a strategy for implementation in 2014-15 is currently being developed.

LIST ENTRY NUMBER: 1003974 and 1373815; 1049146 Contact: Will Fletcher 01223 582710

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:



© English Heritage

SITE NAME:	Church of All Saints, Cockthorpe, Binham
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1373671

Medieval church, now in the care of the Norfolk Churches Trust. English Heritage offered grant towards collapsing tower. Works started late summer 2011 on reduced scope of works. New application and grant offer enabled contract to continue on site and completed late 2012. Further urgent structural repairs to the nave roof required. Heritage Lottery Fund has awarded a grant for repairs and increased access and interpretation. The project development for this work is now underway.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

SITE NAME:	Church of St Peter, Corpusty and Saxthorpe
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

1049202

Medieval former church, taken on by the Norfolk Churches Trust who have completed an extensive scheme of external fabric repairs. Building now in need of reroofing. Talks still ongoing with village as to whether they are able to take on building, and if so: potential use(s).

Contact: Trudi Hughes 01223 582739



© Fakenham Town Gas Works Museum Trust

SITE NAME:	Fakenham gas works, Hempton Road, Fakenham
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Charity (heritage)

1003908

The gasworks produced town gas from 1825 until 1965 and is now the only remaining town gas works of its kind in England. Acquired in 1983 and repaired, it was opened as a museum in 1989. Damp and ground movement are causing structural weakness to key industrial buildings and machinery. Corrosion of metalwork and metal components. Major issues surround the retort housing and its ashpit.

Contact: Nick Carter 01223 582751

Contact: David Eve 01223 582721



© English Heritage

	Constable Park, Melton Constable
DESIGNATION:	Listed Building grade I, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1153044

Melton Constable Hall, Melton

Country house, 1664-1670, enlarged to east, 1810. Service and stable range to north. South and west of Hall are formal C19 terraces, now grassed over. The Hall is on slightly elevated ground overlooking parkland and a lake to the south. The Hall is presently not used and is in need of repair, although some work has been undertaken to the east wing.



© English Heritage

SITE NAME:	Enclosing wall and gatehouse to Waxham Hall, Waxham, Sea Palling
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

C16 wall and gatehouse. Major structural repair necessary due to lack of maintenance. Some flint facing falling away. Destructive ivy growth. Several damaged copings. Solution to be agreed with owner.

Contact: David Eve 01223 582721 LIST ENTRY NUMBER: 1172520

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Conservation Area Listed Building Last year's priority category is shown in brackets, otherwise Local Planning Authority National Park I PA ΝP 'New entry' is noted. Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

**ABBREVIATIONS** 



© English Heritage

SITE NAME:	Sutton Mill, New Road, Sutton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1049326

Tower mill of 1789. Restored in 1976-85 and part of a museum. Since then there has been a lack of maintenance and the museum has closed. The mill's cap is not watertight and repairs are now about to be implemented. Discussion of possible redevelopment of the site ongoing.

Contact: David Eve 01223 582721

~~	A	M.,	
TO THE	n	1	

© English Heritage Archive

SITE NAME:	Remains of St Mary's Friary, Fakenham Road, Little Walsingham, Walsingham
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (C)

OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1003162 and 1373991

Extensive remains of Franciscan house founded in 1347. Deterioration of structural elements leading to collapse of Chapter House wall in 2010. Major scheme of repairs ongoing.

Contact: David Kenny 01223 582700



SITE NAME:	Church of St Ethelbert, Church Road, Alby with Thwaite
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049885

Parish church. Medieval. Flint with stone and brick dressings. Pantile roof. West tower, nave, south porch, chancel, vestry. Roof, rainwater goods and high level masonry all in very poor condition. Heritage Lottery Fund grant offered in 2013. Development stage underway.

Contact: Robert Parkinson 01223 582733



© English Heritage

© English Heritage

SITE NAME:	Church of St Mary, Church Lane, Holt, Baconsthorpe
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049847

Chancel dates from 1260 and most of church to C14. Fine interiors, important monument to William Heydon dated 1593. Tower rebuilt 1740 after collapse. North side very damp. Repair Grant for Places of Worship offered in December 2011. Repairs now underway.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of All Saints, Hempstead
DESIGNATION:	Listed Place of Worship grade II*, 2 CAs
CONDITION:	Fair
PRIORITY CATEGORY:	F (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049211

Parish church dated to C14. C18 north-west and former south aisle now nave. C14 south doorway. Windows renewed in C18. Repair Grant for Places of Worship aided repairs underway to tower, nave drainage and high level masonry. Repairs anticipated for completion by the end of 2014.

Contact: Trudi Hughes 01223 582739


### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of Holy Trinity, Mill Road, Ingham
DESIGNATION:	Listed Place of Worship grade CA
CONDITION:	Poor

PRIORITY CATEGORY: F (F)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1049353

Parish church, mid-C14 with later additions. Chancel circa 1340-44. Flint with ashlar dressings and slate roofs. Restored in 1875-78 by JP Seddon and Ewan Christian. Chancel roof in very poor condition. Repair Grants for Places of Worship grant offered 2011. Repairs are underway and due for completion in early 2015.

Contact: Robert Parkinson 01223 582733



© English Heritage

SITE NAME:	Church of St Peter and St Paul, The Street, Knapton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1306264

Parish church. Early C14 north-west tower and chancel, nave re-modelled C15 when chancel altered. Restored 1882 by Sir GG Scott. Flint with ashlar dressings, the chancel rendered. South nave roof very poor and failing. Previous serious water ingress, with potential damage to important roof carvings. Rainwater goods all poor and in need of replacement. Cracks in chancel arch. Very significant stonework problems in tower. Rusting of ferrous beams supporting bell frame probably responsible. Grants for Places of Worship grant offered July 2014.

Contact: Robert Parkinson 01223 582733



© Ruth & Peter Blackman

SITE NAME:	Church of St Andrew, Church Lane, Hempstead-next-the-Sea, Lessingham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373720

Medieval church with chancel dating from C13; nave, porch and tower C15. Nave and chancel thatched; unusually wide nave at 26ft. C14 screen. Thatch seriously defective and leaking; tower high level masonry needs repointing, stone falling. English Heritage offered grant under the Repair Grant for Places of Worship scheme in December 2011. Repair work is due to be completed in February 2015.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

SITE NAME:	Church of St Nicholas, North Walsham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1039527

Parish church, mainly C14 with remains of pre-conquest west tower. Tower is part ruinous, and in need of urgent structural repair and conservation. Repair Grant for Places of Worship-funded repair work to commence June 2014.

Contact: Robert Parkinson 01223 582733



© English Heritage

n
I

1373419

C14 parish church; restored 1601, 1843 and 1869. Flint construction with ashlar dressings, thatched nave and slated chancel. Three-stage west tower. Associated with Paston family, the church contains C17 Paston family funerary monuments. Repair Grant for Places of Worship funded repairs underway, which include external stonework repairs, new drainage, conservation of Paston family monuments. Completion expected by end of

summer 2014.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



(C)	Fng	lish	Her	itage

© English Heritage

© English Heritage

SITE NAME:	Church of All Saints, Stibbard
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER: 1049230

Parish church featuring west tower containing early C12 flintwork. Belfry openings with C14 Y-tracery windows. Chancel C13. Nave with C14 features. Restored in 1742 when buttresses added to tower and again in 1861-2 by Butterfield, including works to roofs and the porch. Constructed from flint rubble with brick quoins to postreformation buttresses, otherwise, limestone dressings. Bulging facework on tower identified as well as deterioration to brick and flint buttresses. Tower roof requires replacement. Heritage Lottery Fund grant awarded July 2014.

Contact: Malcolm Starr 01223 582723

1		
R		
MA A	10 10	
1	HILL III	

SITE NAME: Church of St Giles, Church Road, Swafield DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1306217

Parish church CI4 with west tower of late CI5. Flint with ashlar quoins and slate roofs. Nave and chancel. Nave aisles removed and church partly rebuilt 1786. Four-stage tower with string courses between floors. Serious problems with water penetration in tower and nave stonework poor. Solution to be agreed.

Contact: Robert Parkinson 01223 582733



Church of St Nicholas, Trunch SITE NAME: Road, Swafield DESIGNATION: Listed Place of Worship grade II\* CONDITION: PRIORITY CATEGORY: F (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1306194

Late C14 tower, C15 nave and chancel. Water ingress at head of chancel and above chancel arch; major cracks above tower arch; internal leaks; algal growth and blown plaster. Failure of earlier repairs and tell-tales suggests recent structural movement. Thatched nave roof, masonry, and two windows in need of repair, failed guttering and downpipes on slated chancel roof, possible water ingress at flashing to nave gable wall head. Widespread problems requiring substantial repair work as a matter of urgency. Project development complete, with works underway.

Contact: Malcolm Starr 01223 582723



© Nicholas Warns Architects

SITE NAME:	Church of All Saints, The Green, Upper Sheringham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1049800

Parish church early C14 and mid C15. Restored 1849 and 1872. Galleted, coursed and knapped flintwork with stone dressings, slate roof, pantiles to south nave. Repair Grant for Places of Worship offered towards reroofing of aisle, repair and replacement of copings and replacement of rainwater goods. Slates on vestry roof need renewing; tower roof spout needs effective drainage at ground level. Structural repairs needed to wall of mausoleum. Repair work to commence September 2014.

Contact: Trudi Hughes 01223 582739



© Nicholas Warns Architects

SITE NAME:	Church of All Saints, Kirkgate, Wighton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1171738

A largely C15 church, comprising tower, south porch, north and south aisles, nave and chancel. Church suffering from damp due to inadequate below-ground drainage system. South aisle roof slates laid at too slack a pitch and letting in water. Nave roof north side is slated with fixings failing. Internally the tower east wall cement render loose and in places at imminent risk of falling. Heritage Lottery Fund development phase grant offered early in 2014. Repair specification currently being developed.

Contact: Trudi Hughes 01223 582739

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ΝP

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2014 / EAST C					
SITE NAME:	Gatehouse at manor house, East Barsham, Barsham				
DESIGNATION:	Scheduled Monument, LB grade I, CA		LIST ENTRY NUMBER:	1003997	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	David Kenny 01223 582700	
SITE NAME:	Cross in St Giles' churchyard, Colby				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1018300	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No	
OWNER TYPE:	Religious organisation		CONTACT:	David Kenny 01223 582700	
SITE NAME:	RAF Neatishead Type 84 radar modulator building and four radar plinths, Neatishead				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1021408	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple o	owners	CONTACT:	David Kenny 01223 582700	
SITE NAME:	Remains of a medieval ringwork castle known as Crabb's Castle, 680m north east of Crabb's Castle Farm, Wighton				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1018175	
CONDITION:	Extensive significant problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Commercial company		CONTACT:	David Kenny 01223 582700	
	SITE NAME:	Wolterton Hall, Wickmere / Erpingham / Itteringham	Early C18 park and woodland designed as a collaboration between Thomas Ripley, Charles Bridgeman and Horatio Walpole, surrounding an early C18 Palladian mansion with mid C19 gardens laid out by William Sawrey Gilpin. The park is a Country Park with a focus on wildlife management, some fields arable others pasture. Loss of definition of lake margins. Some replanting of clumps to west and avenue to north of house. Built structures in verpoor condition, Peach House in kitchen garden particularly vulnerable.		
	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, SM, CA			
	CONDITION:	Generally unsatisfactory with major localised problems			
	VULNERABILITY:	High			
	TREND:	Stable			
© English Heritage	NEW ENTRY?:	No			
	OWNER TYPE:	Private	Contact: David Eve 01223 582721		
	LIST ENTRY NUMBER:	1001022			
SITE NAME:	Cromer 77 LPs		NIE/A/ ENITEV?	V	
DESIGNATION:	Conservation Area, 77 LBs		NEW ENTRY?:	Yes	
CONDITION:  VULNERABILITY:	Poor Low		TREND:  CONTACT:	Deteriorating Paul Rhymes (LPA) 01263 516367	
SITE NAME:	Fakenham				
DESIGNATION:	Conservation Area, 84 LBs, part in SM		NEW ENTRY?:	Yes	
CONDITION:	Very bad		TREND:	Deteriorating	
	,				

### PRIORITY CATEGORIES

VULNERABILITY:

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D

Medium

- Slow decay; solution agreed but F not yet implemented.
  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

CONTACT:

### **ABBREVIATIONS**

Paul Rhymes (LPA) 01263 516367

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Former RAF Coltishall (also in Broadland), Scottow		
DESIGNATION:	Conservation Area, SM	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Rhymes (LPA) 01263 516367
SITE NAME:	Happisburgh		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade I	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Paul Rhymes (LPA) 01263 516367
SITE NAME:	Melton Constable Park, Melton Constable / Swanton Novers / Hindolveston		
DESIGNATION:	Conservation Area, 19 LBs, part in RPG grade II*	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Paul Rhymes (LPA) 01263 516367

#### **NORWICH**



SITE NAME:

St Peter Hungate Museum, Prince Street

DESIGNATION:

Listed Building grade I, CA

CONDITION:

Very bad

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

A (New entry)

OWNER TYPE:

Charity (heritage)

Grade I former parish church now museum. Building largely C13 and after. The building is held on long lease by Norwich Historic Churches Trust and sub-let to the Hungate Medieval Arts Trust who use the building as a medieval arts museum and exhibition space. Batten and fixing failure to chancel roof tiles which means that reroofing is a high priority. Trust applying for Heritage Lottery Fund grant.

© English Heritage

LIST ENTRY NUMBER: 1220104

LIST ENTRY NUMBER:

Contact: Trudi Hughes 01223 582739

Contact: Will Fletcher 01223 582710



© Norwich City Council

SITE NAME:	Bishop Salmon's Porch, Norwich
DESIGNATION:	Scheduled Monument and Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (B)
OWNER TYPE:	Religious organisation

Early C14 porch to former hall. Two storeys with two ground floor open bays. Window reveals and mullions, capitals, shafts and other areas of carved stonework are badly decayed. The roof upper chamber vault and windows are suffering from water ingress, and the raised ground to north and south is allowing damp to penetrate the structure. A programme of repairs is being progressed.



© Norwich City Council

SITE NAME:	Bethel Hospital, Bethel Street, Norwich
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1051362

1004030 and 1051329

Former hospital of C17/early C18, partly converted to residential use with new uses agreed for other parts but not fully implemented. The C19 wing is in poor condition needing substantial repairs. The gable end of the C18 boardroom also in poor condition and in need of structural reinforcement.

Contact: David Eve 01223 582721

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental for the good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### ABBREVIATIONS



© English Heritage

SITE NAME:	Briton's Arms, 9, Elm Hill, Norwich
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

Late medieval building, originally a religious house, and unique survivor of the 1507 fire. Thatched roof is in very poor condition with roof structure showing deterioration. Major scheme of English Heritage grant-aided repairs underway and due to be fully completed autumn 2014.

Contact: Trudi Hughes 01223 582739

Contact: David Eve 01223 582721

A CONTRACTOR OF THE PARTY OF TH
TEXANDER MAINTENANCE PROPERTY OF THE PROPERTY
<b>等据了原则</b>
THE RESERVE THE PARTY OF THE PA
新一个方式是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
一种 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

SITE NAME: Howard's House, 97, King Street, Norwich DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

1372804

Long term vacant building, former house, converted to offices, now vacant. C17 with C18 and C20 alterations. Damaged by vandals. Planning consent granted for redevelopment of the area including new use for the house but not implemented. Deterioration of the building arrested through temporary measures and new use of building is under discussion.

LIST ENTRY NUMBER: 1372824 © English Heritage

© Norwich City Council

SITE NAME: St Mary the Less, Queen Street, Norwich DESIGNATION: Listed Building grade I, CA CONDITION: Fair OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private 1051918

Former parish church with C13 origins, currently used as an historical studies centre. The building is in need of repair, especially the roof. No action/strategy has been identified or agreed.

LIST ENTRY NUMBER:

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of St George, Tombland, Norwich
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1051809

Parish church of the C15. Constructed from flint with a brick clerestory and stone dressings. General wear and tear throughout, with clerestory masonry in very poor condition. Repair Grant for Places of Worship grant offered in 2011 and works completed 2014. New phase of Heritage Lottery Fund-funded repairs about to begin.

Contact: Robert Parkinson 01223 582733

SITE NAME:	Mile Cross		
DESIGNATION:	Conservation Area, RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Chris Bennett (LPA) 01603 212513

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

LIST ENTRY NUMBER:

#### SOUTH NORFOLK



© English Heritage

SITE NAME:	Remains of Church of St Mary, Market Lane, Great Melton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation

1050732

A roofless church tower, built of flintwork with some brick and stone detailing. The tower may date from CII and is the only remnant of St Mary's Church, which was left to become a ruin in 1882 when the decision was taken to use the adjacent All Saints Church as the main place of worship for the parish. At risk of partial collapse due to eroding fabric, an English Heritage grant was accepted in 2012. The repair project is underway and is expected to be completed by late 2014.

Contact: Malcolm Starr 01223 582723

		<u> </u>
	1	
A)		

© English Heritage

	SITE NAME:	Church of St Nicholas, Whip's Lane, Ashwellthorpe and Fundenhall
	DESIGNATION:	Listed Place of Worship grade I
	CONDITION:	Poor
	PRIORITY CATEGORY:	B (New entry)
	OWNER TYPE:	Religious organisation
	LIST ENTRY NUMBER:	1306126

C12 central tower with original small window openings. Norman south portal; Early English north portal. Heavily restored in 1869. C15 rood screen; only coving supporting rood loft remains. Parish have been awarded a Grant for Places of Worship to undertake investigative works in order to ascertain extent of repairs required. These are likely to include structural repairs to chancel east gable and other areas, refurbishment and renewal of gutters; renewal of rotted pew platforms, and dealing with excess salt migration internally.

Contact: Trudi Hughes 01223 582739



© English Heritage

SITE NAME:	Church of St Wandregelius, Bixley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1050487

Parish church. Early C14 tower, remainder dates from 1868. C16 memorial in chancel, removed for safe storage. Church in occasional use prior to fire which destroyed roof and interior. However, church is not formally closed. Repair scheme under discussion but not agreed or implemented.

Contact: David Eve 01223 582721



0	English	Heritage

SITE NAME:	Church of St Mary, Diss Road, Burston and Shimpling
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

C15 church. Nave with large replacement Perpendicular windows. Chancel rebuilt with south vestry. South porch with arch-braced roof. Tower collapsed in 1753 and west wall of nave supported by large red brick buttress. Roofs in very poor condition. Heritage Lottery Fund Grant for Places of Worship grant offered 2014.

LIST ENTRY NUMBER: 1305672

Contact: Robert Parkinson 01223 582733



© English Heritage

SITE NAME:	Church of St Peter, Church Road, Forncett
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1152619

Parish church of C13 origins, possibly earlier. Formerly closed and in very poor condition, but recently brought back into use by the PCC and Friends Group. Some repairs have been completed but more are needed to the masonry, windows, rainwater goods and drainage. Potential problems in chancel roof/arch and walls need to be investigated. PCC are in discussion with Heritage Lottery Fund regarding possible grant assistance.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

#### I PA ΝP RPG



© English Heritage

SITE NAME:	Church of St Mary, Low Road, Forncett
DESIGNATION:	Listed Place of Worship grade I

CA

CONDITION: Poor

PRIORITY CATEGORY: F (New entry - re-assessed)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1304627

C13 church with chancel dating 1869. A major scheme of repairs part funded by a Repair Grant for Places of Worship grant is currently in progress. A programme of educational and community use is being implemented while retaining the church as a place of worship.

Contact: Malcolm Starr 01223 582723



© English Heritage

SITE NAME:	Church of St Mary, Lower Street, Gissing
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1152891

The west tower and nave of this church date from the CII. Characteristic Norman windows of that period survive, but the nave roof was replaced in the CI5 with a double hammerbeam roof, all the more remarkable for its small scale and good state of survival. Repairs are needed to the masonry and roofs of the tower, north porch and chancel. Grant's for Places of Worship application has been applied for and discussions are ongoing.

Contact: Malcolm Starr 01223 582723



SITE NAME:	Church of All Saints, Market Lane, Great Melton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1050731

Church of CII origins, with fabric surviving of that period (long and short quoins, and reused Roman tiles). The extent of C19 rebuilding or restoration is less extensive than once believed, hence its recent upgrading to II\*. Areas of flintwork in poor condition, especially on the tower. Repair Grants for Places of Worship grant offered in 2010. Repairs are underway and due for completion autumn

Contact: Malcolm Starr 01223 582723



© English Heritage

© English Heritage

SITE NAME:	Church of St Mary, Church Lane, Haddiscoe
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169126

Parish church. CII with CI3 and CI5 re-modelling. Round west tower, probably late CII, divided into stages by three stone bands. North west bay of chancel has CI5 2-light window flanked by blocked circular openings. North aisle has two 2-light CÍ3 'Y' tracery windows and, at north west corner, north doorway with billet hood mould and shaft, scallop and roll-moulded arches. Widespread damage from damp caused by inadequate disposal of rainwater is leading to deterioration of internal fabric and structural problems in external walls. Repair strategy yet to be agreed and implemented.

Contact: David Eve 01223 582721



© English Heritage

SITE NAME:	Church of St Remigius, Norwich Road, Hethersett
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation

1373115

Largely C14 church with windows and clerestory replaced in C19, and internal polychrome decoration of the latter period. Slate fixings on the nave are corroded, causing loss and impact damage on the aisle roofs. Leakage poses a threat to the decorative interior. A Repair Grants for Places of Worship grant was offered in 2012. Project development phase is currently in progress.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS**

LIST ENTRY NUMBER



© English Heritage

© English Heritage

SITE NAME:	Church of St Mary, Barnham Broom Road, Carleton Forehoe, Kimberley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation

1172547

Grade II\* listed church, with surviving Norman tower. Adjacent to the church are indications of either a deserted medieval village or manorial site. The tower roof is in poor condition and leaks. Repair Grants for Places of Worship grant offered 2011. Repair works underway and due to complete 2014.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Church of St Botolph, Chapel Lane, Morley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373064

Parish church dating to the C15, restored and re-roofed in the 1960s. Constructed from flint with ashlar and brick dressings. Pantile roof. Although re-roofed in the 1960s, there are a number of slipped tiles on the south slope and heavy moss to the north, alongside blocked gutters. The rainwater goods are in a poor condition throughout. Pigeons in the tower may also be causing damage. Solution yet to be agreed.

Contact: David Eve 01223 582721



Church of All Saints, Church Lane, Runhall

DESIGNATION: Listed Place of Worship grade II\*

CONDITION: Poor

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1304940

Parish church dating from C12. The C12 round tower has a C19 brick corbel course and conical roof. There is a C15 porch with blind spandrel tracery to entrance. The tower is in a poor condition with large cracks at high level and slates falling from the roof. The tower is currently cordoned off with danger signs. Solution not yet agreed.

© English Heritage

	1		b.	
			1	1
105				
1	4	n.		ed.
		8	陽	

SITE NAME:	Church of All Saints, Church Road, Shelfanger
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1373360

Early C14 church. Tower with diagonal buttresses, embattled parapet with chequer flushwork and pyramidal tiled roof. Early C14 chancel with east window with intersecting tracery. Cl4 nave with C15 Perpendicular windows, and one Decorated north window. Mural fragments in east end of chancel. Wall painting in chancel vulnerable to dampness in walls. Repair to roof needed to prevent water ingress and dampness in chancel, threatening an important medieval wall painting. Parish is considering

Contact: David Eve 01223 582721

applying for Heritage Lottery Fund grant aid.

Contact: Janine Dykes 01223 582724

		MA
-211		ű
	N. Allen and	

© English Heritage

© English Heritage

SITE NAME:	Church of St Peter, Swainsthorpe
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation

1169726

C12 west tower with C14 top stage. Remainder C14 but restored in C19. Porch 1885. Tower roof collapsing due to inadequate perimeter gutters and undersized rainwater outlets. Supporting beams fractured. No safe access on to tower roof for purposes of inspection and repair. Repair Grant for Places of Worship offered 2010. Repairs complete 2014, with exception of re-roofing chancel (batten failure) which was postponed due to lack of funds. Long-term solution being discussed.

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Mary, Church Road, Yelverton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1050639

Parish church predominantly dating from C14 with C12 fragments, with the tower dated to C17. The masonry to part of the tower is in poor condition with detaching flints. The PCC applied for a grant from the Heritage Lottery Fund in June 2014 towards the cost of repairs. Outcome awaited.

Contact: Clare Campbell 01223 582738

© English Heritage

SITE NAME:	Arminghall, sites discovered by air photographs, Biz	cley / Trowse with	Newton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003620
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Sites discovered by air photography at Markshall, C	Caistor St. Edmund	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002887
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Long barrow and round barrows on Broome Heatl	n, Ditchingham / Br	oome
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004002
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Romano-Celtic temple 590m south east of St James	s's Church, Wickley	boow
DESIGNATION:	Romano-Celtic temple 590m south east of St James Scheduled Monument	s's Church, Wickley LIST ENTRY NUMBER:	wood 1020862
	•		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020862

#### PETERBOROUGH, CITY OF (UA)



© Dr Jackie Hill, Cathedral Archaeologist
---

SITE NAME:	Peterborough Cathedral precinct wall, Peterborough
DESIGNATION:	Scheduled Monument and Listed Buildings - 10 grade I, 5 LBs, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)

OWNER TYPE: Religious organisation

1003264 and 1126932; 1331514; 1126930; 1126937; 1161429; 1161668; 1331517; LIST ENTRY NUMBER:

1331494; 1126939; 1161737

Various sections of the Cathedral precinct wall, of medieval (and some places, perhaps, Saxon) origin with later stone and brick refacing, are in very poor condition and need significant amounts of repointing and recapping. Two sections of fallen wall and one propped section have been rebuilt. The walls are vulnerable to water penetration which has led to stone decay. Some repairs completed.

Contact: Deborah Priddy 01223 582720

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



© English Heritage

SITE NAME: Laurel Court, 22, Precincts, Peterborough

Listed Building grade I, RPG DESIGNATION: grade II, CA

CONDITION:

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1310019 An early C18 house adjacent to the remains of the cloister at Peterborough Cathedral. The building is suffering from structural problems and failure of its modern flat roof. Proposals for repair and reuse are being discussed.

Contact: John Neale 01223 582719



© English Heritage

SITE NAME: Barn at Wothorpe Farmhouse near Wothorpe Towers,

Wothorpe

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1127451

C17 stables. Major repairs to the building are underway, and it is expected that it will be re-roofed this year. Part of barn associated with the stable range has been converted and is occupied.

C17 farmhouse. Repairs are underway and it is expected

necessary) will be completed this year, leaving the building

that the renewal of dormers and chimneys (where

Contact: John Neale 01223 582719

wind and weather-tight.



SITE NAME: Wothorpe Farmhouse near Wothorpe Towers, Wothorpe

DESIGNATION: Listed Building grade II\*

1265974

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: F (F)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: © English Heritage

Contact: John Neale 01223 582719

SITE NAME:	Fletton churchyard cross		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006839
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa south west of Castor station, Ailsworth	ı	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006862
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	David Kenny 01223 582700
SITE NAME:	Site of Roman villa north east of Sibson Hollow, Ails	sworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006863
CONDITION:	Extensive significant problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems  Digging	TREND: NEW ENTRY?:	Declining No

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG

Unitary Authority World Heritage Site

SITE NAME:	Settlement site east of Uffington and Barnack Sta	tion, Barnack / Uffing	ton / Bainton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006792
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Four bowl barrows 690m and 550m ESE of The	Willows, Borough Fe	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021314
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman house north of Castor Mills, Castor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004673
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman site in Normangate Field, Castor / Ailswo	orth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006864
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 550m south east of Hill Farm, Eye		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021304
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 570m north east of Slipe Farm, Eye	2	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa north of Oxey Wood, Helpston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006832
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Site revealed by aerial photography east of Lolha	m Hall, Maxey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006827
CONDITION:	Extensive significant problems	TREND:	Declining
DDIN ICIDAL VII II NIED A DII ITV	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	7 (lable ploughing		· · · -

#### PRIORITY CATEGORIES

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial specified). use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Three bowl barrows 390m north west of The F	irs, Newborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021317
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
ITE NAME:	Three bowl barrows and a ring ditch 590m and	500m north west of T	he Four Winds, Newborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021318
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
ITE NAME:	Sutton Heath, Romano-British site, Sutton / Sou	ithorpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006880
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	A Bronze Age post alignment and timber platfor systems and settlement to either side of the No	rm at Flag Fen and asso orthey Road, Thorney	ociated Bronze Age and later field
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1406460
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Will Fletcher 01223 582710
ITE NAME:	Bowl barrow 225m north east of Prior's Fen Fa	rm, Thorney	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
TE NAME:	Bowl barrow 430m north east of Prior's Fen Fa	rm, Thorney	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021310
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
ITE NAME:	Bowl barrow 490m west of Gores Farm, Thorn	еу	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021307
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow 620m north east of East Wryde C	Cottages, Thorney	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021306
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Private	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

01223 582700
01223 582700
01223 582700
01223 582700
01223 582700
01223 582700
01223 582700
01223 582700
01223 582700 01223 582700

#### SOUTHEND-ON-SEA (UA)



9	
SITE NAME:	Manor House, Suttons Road, South Shoebury
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1306855

House, 1681. Currently vacant, last used as residential quarters. Re-use of the building is complicated by its location within a military site. A serious dry rot problem was treated 1998-2003, but has caused considerable damage to the interior. Building has been vacant for many years. Rigid application of 3-year break clause in all long leases granted by Ministry of Defence has seriously worsened potential for reuse by charitable trusts.

Contact: Sheila Stones 01223 582716

#### PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets, otherwise

# 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument

UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Church of the Holy Trinity, Southchurch Boulevard, Southend on Sea
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	F (New entry)
OWNER TYPE:	Religious organisation

1112723

A church of CII origins with substantial fabric of that period surviving. A new nave added parallel to the old one by Comper in 1906, and a new chancel added to this in 1931-2 by Eden (influenced by Comper). Some elegant windows of this later period. The old part of the church has bell tower with cedar shingles, which are in very poor condition with daylight visible from inside. Heritage Lottery Fund application for repairs accepted and development phase due to commence summer 2014.

Contact: Malcolm Starr 01223 582723

#### **SUFFOLK**

#### **BABERGH**



SITE NAME:	Barn north east of Bentley Hall Bentley Hall Road, Bentley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1351965

Built C15, timber-framed and brick nogging. It is redundant and is only suitable for a very low-key use. It is structurally unstable and water is penetrating the walls in places, accelerating decay of its structure. English Heritage and the Local Authority are involved in ongoing discussions with the owner to secure the conservation of the barn.

© English Heritage

LIST ENTRY NUMBER:

LIST ENTRY NUMBER

Contact: Robert Parkinson 01223 582733

Contact: Robert Parkinson 01223 582733



SITE NAME:	Kersey Mill, Kersey
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Large timber framed and weatherboarded watermill of three storeys, with attics under slate roof. Early C19 front range, rear range 1830s. Small paned sash and centre pivot windows. Fine iron waterwheel and important range of milling machinery. English Heritage in discussion with new owners over conservation and repair needs.

© English Heritage

EST ENTITY NOT IDEA.	1100310
SITE NAME:	Lawshall Hall, The Street, Lawshall
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor

1180340

House, C16 and C19. Unoccupied since the 1960s. A scheme has been approved for repair, refurbishment and extension of the building for use as a residential dwelling. Repair works are progressing on site as of June 2014.



SITE TO WIE.	Lawshall	
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1036593	

© English Heritage

LIST ENTRY NUMBER:

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME:	Church of St Mary, The Street, Arwarton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1286145

'Arwarton"). Historic fabric of church datable from Cl4. Some interesting repairs of 1838 in the Georgian tradition, which add to the architectural character. Serious erosion of the tower facework and quoins, posing a risk of partial collapse. A Repair Grants for Places of Worship grant was offered in 2011. Repairs commenced in 2014.

Parish church located in the small hamlet of Erwarton (or

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### I PA ΝP RPG

SITE NAME:	Enclosure east of Nether Hall, Harkstead		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005981
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa north east of Rodbridge House, Lor	g Melford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005969
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Wissington ring ditch cluster, Nayland-with-Wis	sington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003758
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Wood Hall moated site, Sudbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005997
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	David Kenny 01223 582700
FOREST HEATH			
SITE NAME:	Bowl barrow 990m south west of Cranhouse Fa	rm, Eriswell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018100
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Three bowl barrows 750m south west of Pin Fa	rm, Gazeley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018103
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Two bowl barrows 150m south east of Warren	nill Farm, Herringswel	I
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018674
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Mildenhall Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006037
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
		001171.07	D
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:	Newmarket, Newmarket / Snailwell		
DESIGNATION:	Conservation Area, 106 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Boyd Nicholas (LPA) 01638 719248

#### **IPSWICH**



© Ipswich Borough council

SITE NAME:	Gateway to Wolsey's College of St Mary, College Street
DESIGNATION:	Listed Building grade I, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1206515

of Brick gateway adjoining St Peter's Church Yard is all that remains of the college founded by Cardinal Wolsey for Secular Cannons in 1528 and suppressed in 1530. 4-centred moulded brick archway with square hood moulding surmounted by the very decayed arms of Henry VIII carved in stone. Walltops and upper masonry admitting water. Evidence of vehicle impacts and casual vandalism. Recent phase of conservation by Borough Council involved repairs to adjoining walltips. Discussions underway between Ipswich Borough Council and English Heritage working towards conservation of monument.

Contact: Robert Parkinson 01223 582733



© English Heritage

SITE NAME:	St Mary at Quay, Quay Street, Ipswich
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1037707

Poor

C (C)

Private

1231085

Former church dated to 1448. Featuring nave, north and south aisles, west tower and hammerbeam roof. Now owned by the Churches Conservation Trust. Currently in a poor condition with major drainage issues with severe water penetration of masonry at low level. English Heritage and Heritage Lottery Fund grants have now been accepted and urgent repair works are expected to commence in summer 2014.

Contact: Robert Parkinson 01223 582733

SITE NAME:	Stoke		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Gail Broome (LPA) 01473 432934

Badley Hall barn 100 metres

Listed Building grade II\*, SM

Vacant/not in use

south east of Badley Hall, Badley

#### MID SUFFOLK

© English Heritage



DESIGNATION:
CONDITION:
OCCUPANCY:
PRIORITY CATEGORY:
OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:

A very well built and unusually complete C15 or early C16 timber-framed barn on a flint rubble plinth. Timber frame in need of repairs.

Contact: Malcolm Starr 01223 582723



SITE NAME:

Badley Hall dovecote 60 metres east of Badley Hall, Badley

DESIGNATION:

Listed Building grade II\*

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

F (F)

OWNER TYPE:

Private

1231084

A rare example of a near-complete C16 timber-framed dovecote. Some nesting boxes remain. First phase of repair programme carried out and further work anticipated for 2014.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

© English Heritage

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area is LB Listed Building ie LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© English Heritage

SITE NAME:	Drinkstone Post Mill, Woolpit Road, Drinkstone
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (A)

Other not for profit group 1032625 Contact: Robert Parkinson 01223 582733

SITE NAME:	Barn 200 metres west of Hall's Farmhouse, Halls Lane, Norton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1352406

Contact: Malcolm Starr 01223 582723

alternative uses.



© English Heritage

© English Heritage

SITE NAME:	Church of St Lawrence, Church Lane, Brundish
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1352203

A church of Norman origins with C12 tower. C14 and C15 alterations. Very fine internal features include a window niche with surviving Medieval polychrome decoration. A C15 pulpit and a collection of pews typifying their development from Medieval to C18. The C18 pews incorporate the Medieval benches and their poppyhead ends. Very poor rain and ground water disposal arrangements have resulted in extensive internal damp and initial stages of decay in the pews. Wiring is also affected and could become dangerous. Repair Grant for Places of Worship accepted and in development phase.

Timber-framed and weatherboarded barn, mid C16. High quality timber frame with some rare features. Soleplates rotted and whole barn leaning sideways. Although propped, permanent repairs now required to secure the structure. Roof was wind and weathertight on date of last visit. Discussions continue regarding repairs and potential

C16/C17 post mill, part of the Drinkstone Mills conservation area containing circa 1790 smock mill and other buildings associated with nearly 400 years of milling activity. The buck has been repaired but the round house and other elements are in need of attention as the roof to the round house leaks and the walls require consolidation. English Heritage grant accepted and works about to begin.

Contact: Malcolm Starr 01223 582723



77	
14	DESI
	CON
CHICAT A C	PRIC
-	OW
el some	LIST

SITE NAME:	Church of St Mary, The Street, Horham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032540

Medieval parish church. Core of the nave probably dates from C12. The nave contains C12 doorways. The chancel was largely rebuilt 1879-8. Beneath all the belfry lights are square flushwork. The nave seating includes C15 benches with poppyhead ends enriched with buttressing and fleurons. Principal issue of damp, particularly on external walls of the nave. Slow decay continues but solution to be identified and agreed.

Contact: Janine Dykes 01223 582724

© English Heritage

© English Heritage

SITE NAME:	Church of All Saints, The Street, Laxfield
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1180967

Church of C14 origins, but earlier fabric may survive. Good collection of pews from the Medieval period onwards, and traces of Medieval polychrome decoration surviving on the font. The very fine flushwork tower has suffered from erosion and weather ingress at high level. South and west faces have been repaired, but work is now needed urgently to the east and north before fabric is lost. Leakage at the abutment of the CI9 chancel roof to the nave. Repair Grants for Places of Worship grant offered and project development is in progress.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

**ABBREVIATIONS** 

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



♠ English	Haritago

SITE NAME:	Church of St Peter, Palgrave
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032776

Parish church. C14 origins, C15 nave and south porch, early C18 chancel, restored 1861 with addition of north aisle. Flint rubble, largely knapped, some squared, with flushwork in south porch. North nave roof in very poor condition and leaking. The north aisle roof is in tile and at a very lean slope which is leaking. Flushwork on south porch is falling. Reroofing of nave and north aisle proposed together with porch flushwork repairs. Grant offered in 2011 under the Repair Grants for Places of Worship scheme. Works underway with estimated completion late

Contact: Robert Parkinson 01223 582733

) Town
The state of
THE

SITE NAME: Church of St Margaret, Little Green, Thrandeston DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1032763

Medieval parish church dating from the C15 apart from the C13 chancel which was re-fenestrated in C15. The church was fully restored c1870-80. Short gabled north porch has a C19 outer arch. There is damp throughout the interior of the church which is particularly bad around the pews at low level. Slow decay, no solution yet agreed but discussions are ongoing.

Contact: Janine Dykes 01223 582724

©	Eng	lish	Hei	ritage
---	-----	------	-----	--------

SITE NAME:	Baylham Roman site, Coddenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006033
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700



© English Heritage

SITE NAME:	Shrubland Hall, Coddenham / Hemingstone / Barham
DESIGNATION:	Registered Park and Garden grade I, 22 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000155

Extensive mid C19 Italianate garden by Charles Barry set in C17 park, for which Humphry Repton prepared a Red Book in 1789 and William Woods in 1808. Many proposals have been implemented in the expanded park. The site is in divided ownership following sale in 2009 and boundary fence erected. Management of Old Hall landscape is improving but the built garden features and planting are significantly decayed. Improved management strategies for the park as a whole need to be developed to safeguard its future.

Contact: Clare Campbell 01223 582738

#### ST EDMUNDSBURY



© English Heritage

SITE NAME:	Atomic bomb store on Thetford Heath, Barnham
DESIGNATION:	Scheduled Monument, 5 LBs
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F(E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020781

Former Ministry of Defence strategic defence site, built 1953-1955. Purchased and in use as an industrial estate since 1965. Non-beneficial historic elements are scheduled and English Heritage grant was offered towards selective 'pilot projects' in 2009. Elements at risk due to short term anticipated lifespan. Successive English Heritage grant aided phases of work undertaken between 2011-2014 as well as privately funded works by the owner. These are greatly improving the condition of the site. Fifth phase of repairs commenced and owner is working up grant application to Heritage Lottery Fund.

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



© English Heritage

SITE NAME:	Moreton Hall, Bury St. Edmunds
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)

1022597

Contact: Clare Campbell 01223 582738

the exterior are needed.

4.7	SI
	D
	C
	С
-	Pl
	_

LIST ENTRY NUMBER

ITE NAME: Cupola House, 7, The Traverse, Bury St. Edmunds DESIGNATION: Listed Building grade I, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use RIORITY CATEGORY: B (B) OWNER TYPE: Commercial company

Timber framed-house built in 1693, remodelled on an earlier two-storey house, named after its roof-top Cupola. Repaired in 2001-2002 and used as a restaurant, suffered devastating fire in June 2012. Damage is to the rear of the building, which has collapsed in places, and parts of the roof structure. The façade and historic timber frame have survived. Consent has been granted for repair, reconstruction and new work with some repairs now being undertaken. Discussions to seek long-term solution ongoing.

Robert Adam House of 1773. Urgent high level works to

© English Heritage

LIST ENTRY NUMBER: 1038264 Contact: Clare Campbell 01223 582738

Contact: Clare Campbell 01223 582738



SITE NAME: Stoke College, Stoke-by-Clare DESIGNATION: Listed Building grade II\*, CA CONDITION: OCCUPANCY: Occupied/in use PRIORITY CATEGORY: D (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1265211

Originally a Benedictine Convent, converted to a college and then a mansion after the dissolution. Repairs required to the roof and other areas of building.

© English Heritage

Immini		
人	W.	66.
		様を
		2

© English Heritage

SITE NAME:	The Umbrello, Great Saxham Hall, Chevington Road, Great Saxham, The Saxhams
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Private

1031410

Early C19 Coade stone folly. Very poor condition: roof missing, ingress of water is rusting iron core. The proposal to dismantle it and re-erect in a new location had been granted listed building consent, but was not implemented. A programme of photographic recording and building analysis was undertaken by English Heritage in 2012. No progress has been made since this date.

© English Heritage

SITE NAME:	Church of St Nicholas, Church Road, Bradfield Combust with Stanningfield
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1229767

A grade II\* listed church dating from the C12 with a C13 chancel, flint rubble with limestone dressings, plain tiled roofs with parapet gables, the tiles of which are in poor condition and leaking. A Repair Grant for Places of Worship was offered in 2011, with works underway and due to complete by late 2014.

Contact: Malcolm Starr 01223 582723

Contact: Clare Campbell 01223 582738

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG



SITE NAME:	Church of St Mary, Cavendish
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1031774

Church dating from the C14, prominently situated in the Cavendish Conservation Area at the east end of the green. Unusual features include the vaulted parvise and external arched timber bell cage and flagpole combined which sits on the tower parapet. There is some deterioration of masonry on the tower. The flagpole has begun to lean, possibly because the plated joint at low level is becoming ineffective. This needs to be investigated to confirm its condition. PCC have applied to Heritage Lottery Fund for grant assistance.

Contact: Malcolm Starr 01223 582723

0	English	Heritage
---	---------	----------

SITE NAME:	Round barrows, Risby Poor's Heath East, Flempt	on / Risby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006038
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Sites north west and south east of Fornham All S	Saints, Fornham All Sa	ints / Hengrave
DESIGNATION:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1006018
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Interrupted ditch system west of Hall Farm, Ked	ington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005959
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman villa south east of Lidgate, Lidgate		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002971
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	Roman settlement south of Ixworth, Pakenham		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006019
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	David Kenny 01223 582700
SITE NAME:	East Low Hill tumulus, Rushbrooke with Rougha	m	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

SITE NAME:	Haverhill Hamlet Road, Haverhill		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Johnson (LPA) 01284 757339
SITE NAME:	Haverhill Queen Street, Haverhill		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Johnson (LPA) 01284 757339

#### SUFFOLK COASTAL



© English Heritage

Martello Tower "Z", south east of Buckanay Farm, Alderton SITE NAME: Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: B (B)

Private LIST ENTRY NUMBER: 1006014 and 1030773 Martello Tower Z forms part of a chain of martello towers along the south and east coast of England dating from the early C19. The tower has been unused since the Second World War. Whilst generally robust and structurally sound a recent condition survey undertaken as part of a Heritage Lottery Funded Landscape Heritage Initiative has indicated the need for repairs to prevent water ingress. Further discussions with the owner are needed to consider any urgent conservation works to the tower.

Contact: John Ette 01223 582711



© English Heritage

SITE NAME: Transmitter Block, Bawdsey Manor, Bawdsey Listed Building grade II\*, RPG DESIGNATION: grade II CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private LIST ENTRY NUMBER: 1245307

Concrete transmitter block built in 1937. Site of pioneering radar development. Featured in BBC "Restoration" TV programme. Some repair and refurbishment works undertaken. Bawdsey Radar Group have commissioned an options appraisal. A Conservation Management Plan has been produced for the estate and discussions with the Trust are ongoing. Heritage Lottery Fund grant offered 2013 and development works in progress.

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME: Martello tower at western end of sea front, Felixstowe Scheduled Monument, LB grade DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (New entry) OWNER TYPE: Local authority

Martello Tower 'P'. Water penetration through roof. Problems of damp exacerbated by walls being of impermeable render and brickwork. Major redevelopment taking place around site partly in historic curtilage. Preliminary conservation works underway summer 2014.

LIST ENTRY NUMBER: 1006013

Contact: Robert Parkinson 01223 582733



© English Heritage

SITE NAME: Martello tower on golf course adjoining Woodbridge Haven, Felixstowe Scheduled Monument, LB grade DESIGNATION: CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

1006036

Martello Tower T on Felixstowe Golf Course. Built c1810-1812 as part of defences against Napoleonic invasion. Roof and walls in very poor condition with water penetration. English Heritage in discussion with the owners over repairs and interpretation.

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



© English Heritage

SITE NAME:	Friston Post Mill, Mill Road, Friston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1215741

One of the finest, and possibly tallest, post mills in the United Kingdom. Built in 1812 and operational until 1956. Restored in 1976; temporary supports added 2004; post out of alignment and trestle fractured and now in need of urgent and permanent repair. Repair scheme agreed but work has not yet commenced, with the owners now working on securing a Heritage Lottery Fund grant for repairs, access and interpretation

Contact: Trudi Hughes 01223 582739

1000	***
M ALL	

© English Heritage

SITE NAME:	Glevering Hall Orangery, Easton Road, Hacheston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1377281

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Orangery built in classical style circa 1835. Architect Decimus Burton. Glass missing, especially from the dome, and rusting iron cramps are forcing apart the stonework. Discussions regarding repair works ongoing. English Heritage has offered grant aid towards a condition survey, repair schedule and Conservation Management Plan together with feasibility study. Owners accepted grant at end of March 2014 and discussions about details of work are in progress.

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME:	Remains of Sibton Abbey, Sibton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Other not for profit group

1018327 and 1377160

Remains of Cistercian abbey built in 1150. Damaging vegetation. Occasional trespass and vandalism. Building currently suffering ongoing decay. The building is a ruin with no possibility of economical beneficial use. Condition survey undertaken. Trees removed. Repair scheme and grant application under discussion.



© English Heritage

SITE NAME:	Church of St Andrew, The Street, Alderton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1377186

Parish church with ruinous west tower. Chancel rebuilt in 1862 and nave restored in 1864. Drainage for guttering unclear and significant low level damp in interior. Ruinous tower overgrown by trees and shrubs and blocked off from nave. Significant high level damp in interior. Slow decay continues, no solution yet agreed.

Contact: Natalie Gates 01223 582747

Contact: John Ette 01223 582711



© English Heritage

SITE NAME:	All Saints Church, The Street, Darsham
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1198791

A church with C12 origins, much of which survives, incorporating some re-used Roman tiles and possibly some reused Saxon quoins. Good later Medieval work including C15 pews and (possibly original) ceiled chancel. Chancel roof and rainwater goods poor, putting the ceiling at risk. Grant for Places of Worship for repairs offered 2012. Project development completed 2013 and repairs to commence late 2014.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Church of St James, Leet Hill, Dunwich
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation

1283930

Church with nave, chancel, west tower, south porch. 1837-42 by Robert Appleton; considerably altered 1881, probably by EF Bishop: chancel added, nave cased in flint and given new windows, tower rebuilt and interior re-cast. Brick core with random flint and stone facing. Water penetration to roof. Heritage Lottery Grant offered, work expected to start late 2014.

Contact: Robert Parkinson 01223 582733

Contact: Clare Campbell 01223 582738

11 -	THE PERSON	
150		THINK
( ESI		THE
SAME.		THE REAL PROPERTY.
144		188.1
143		11.00
- A		
- 3	The Real Property lies	-
<b>医皮部</b>	CONTROL IN LABOR.	
145	4411	1

SITE NAME: Church of St Andrew, St Andrews Road, Felixstowe DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: A (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1377388

LIST ENTRY NUMBER:

Church built c 1929-31 and is an interpretation of a late C15 East Anglian church constructed using concrete. The concrete is now in poor condition and the parish is exploring options for repair.

© English Heritage

SITE NAME:	Church of All Saints, The Street, Hacheston
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1199742

Medieval parish church restored mid C19. Fabric dating from C12, with C15 hammerbeam roof. The church requires urgent roof repairs to halt water ingress. Consent has been granted for repair works which are expected to commence summer 2014.

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME:	Church of St Andrew, Church Road, Little Glemham	
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Very bad	
PRIORITY CATEGORY:	F (B)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1230821	

Church with Norman origins, with some fabric of that period surviving (north nave doorway and areas of coursed "herringbone" flintwork). Major remodelling in C15. The major features are the neoclassical mausoleum added in 1830, and the remarkable collection of C18 and C19 monuments. Serious rainwater leakage through the mausoleum roof has de-stabilised the interior plasterwork, causing areas to fall off and threatening further loss. Repair Grants for Places of Worship grant offered 2013. Repairs now in progress.

Contact: Malcolm Starr 01223 582723



© English Heritage

SITE NAME:	Church of All Saints, Church Road, Ramsholt
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1030735

Parish church, unchanged since the early C19, with box pews, a double-decker pulpit on the south side of the nave, and no electricity: services being held by candlelight. The round tower is at least of Norman origin but is allegedly Saxon, serving as a watchtower for Viking raids. The tower roof and masonry are in very poor condition. An application to the Heritage Lottery Fund for grant assistance was successful and project development is expected to commence in 2014.

Contact: Malcolm Starr 01223 582723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**



© English Heritage

SITE NAME:	Church of St Margaret, Church Lane, Shottisham
DESIGNATION:	Listed Place of Worship grade I

CONDITION: Very bad

PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1030736

The church is believed to be of C14 origins, but incorporates re-used Roman tiles and possibly Saxon or early Norman quoins. The masonry of the tower and east gable of the nave are in poor condition. A grant application to the Heritage Lottery Fund for this work has been successful and the development of the repair project is in progress.

Contact: Malcolm Starr 01223 582723

SITE NAME:	Settlement site east of the Cedars, Alderton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement site around St Botolph's Church, Bur	gh / Clopton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006035
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Settlement sites 330yds (300m) north west of V	Valnut Tree Farm, Ho	llesley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006002
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Rectilinear enclosures 1km south west of Boyto	n Hall Farm, Hollesley	/ Boyton
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006005
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Henge and associated barrow cemetery south o	f Home Whin Farm, S	hottisham / Sutton
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700
SITE NAME:	Bowl barrow on Waldringfield Heath, 150m south of Heath Farm, Waldringfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008506
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	David Kenny 01223 582700

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:



© English Heritage

SITE NAME:	Bawdsey Manor, Bawdsey
DESIGNATION:	Registered Park and Garden grade II, 8 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001465

Gardens laid out between 1885 and 1909 on advice from Alfred Parsons. The garden contains an extensive Pulhamite cliff garden, complete with seats and alcoves, built in the 1890s by Pulham & Co. Site is improving with house no longer at risk following English heritage grant aided works which were completed in 2012. Informed work to some garden structures now being undertaken. Pulhamite and planting are in poor condition and in need of strategic management. Despite plans to manage coastal defences, coastal erosion and climate change remain major concerns.

Contact: Clare Campbell 01223 582738

SITE NAME:	Felixstowe South, Felixstowe		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Robert Scrimgeour (LPA) 01394 444616

#### WAVENEY



Moat Farmhouse, Shadingfield, **Beccles** DESIGNATION: Listed Building grade II\*, SM CONDITION: OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

C16 farmhouse with C19 alterations and brick wing to rear. Good quality timber frame, finely moulded beams and joists internally. Scheduled moated site. Under tarpaulin and scaffolded.

Medieval Castle built by Roger Bigod. Problems with the southern C13 tower to the gatehouse have been addressed and urgent repairs completed, discussions ongoing over further repairs and conservation work to the keep, northern gatehouse tower, and curtain and bailey walls. Conservation statement and condition survey currently being prepared to inform next steps.

© Waveney District Council

LIST ENTRY NUMBER: 1032132

LIST ENTRY NUMBER:

Contact: Clare Campbell 01223 582738



© English Heritage

SITE NAME:	Bungay Castle, Bungay
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1006060 and 1034404 Contact: John Ette 01223 582711



© English Heritage

SITE NAME:	Church of St Margaret, Stoven, Brampton with Stoven
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1032100

Parish church. C12 doorways, the lower portion of the tower possibly medieval; remainder entirely rebuilt 1849-50 in neo-Norman style, with crude detailing. The tower is of flint rubble, the bell-chamber stage faced with knapped flint; the nave and chancel are plastered; stone dressings. Slated roofs with courses of fish-scale slates. Poor construction in C19 has resulted in serious structural failures in masonry, particularly the south nave wall, and water penetration. Roof poor; interior fair; rainwater goods satisfactory. No action/strategy identified or agreed.

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Two moated sites adjoining All Saints' Church, All Saints and St. Nicholas, South Elmham			
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017633	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700	

#### THURROCK (UA)



SITE NAME: State Cinema, George Street, Grays DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

The State Cinema is one of the best preserved of the 'super cinemas' of the late 1930s. It was constructed in 1938 by F G M Chancellor for Frederick's Electric Theatres. The building has suffered from heritage crime and the roof, rainwater goods and interior are in poor condition. The reuse of this vast cinema poses complex problems, as confirmed by a feasibility study some years ago, but ways to achieve this as part of the regeneration of Grays are being explored. No action/strategy has yet been agreed.

© Essex County Council

LIST ENTRY NUMBER: 1111543 Contact: John Neale 01223 582719

Contact: Deborah Priddy 01223 582720



SITE NAME: Coalhouse Fort, Tilbury DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1013943

Ruined C19 armoured casemate fort on site of earlier battery; refortified since the two World Wars. Problem of water ingress to casemates; barrack block in severe disrepair. English Heritage grant-aided repair work to the gatehouse barrack block was completed in 2011. Further phased repairs anticipated. Heritage Lottery Fund scheme for conversion of generator house to cafe has been approved. Storm damage to roof of north caponier has now been repaired.

© English Heritage Archive

SITE NAME:	Causewayed enclosure and Anglo-Saxon ce	Causewayed enclosure and Anglo-Saxon cemetery 500m ENE of Heath Place			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009286		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	David Kenny 01223 582700		
SITE NAME:	Crop mark complex, Orsett				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002134		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	David Kenny 01223 582700		
SITE NAME:	East Tilbury				
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	Yes		
CONDITION:	Very bad	TREND:	No significant change		
VULNERABILITY:	Medium	CONTACT:	Planning Dept (LPA) 01375 652275		

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2014 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST