# Heritage at **Risk**



East of England Register 2015

# Contents

| Heritage at Risk  |  |
|---|--|
| The Register  | VII  |
| Content and criteria  | VII  |
| Criteria for inclusion on the Register  | IX   |
| Reducing the risks  | XI   |
| Key statistics  | XIV  |
| Publications and guidance   | XV   |
| Key to the entries  | XVII   |
| Entries on the Register by local planning authority   | XIX  |
| Bedford (UA)  | I  |
| Cambridgeshire  | 2  |
| Cambridge<br>East Cambridgeshire<br>Fenland<br>Huntingdonshire<br>South Cambridgeshire<br>Central Bedfordshire (UA)   | 2<br>3<br>5<br>7<br>9  |
| Essex   | 15   |
| Braintree<br>Brentwood<br>Chelmsford<br>Colchester<br>Epping Forest<br>Harlow<br>Maldon<br>Tendring<br>Uttlesford<br><i>Hertfordshire</i><br>Broxbourne<br>Dacorum  | 15<br>16<br>17<br>19<br>21<br>21<br>22<br>25<br>26<br>26<br>27                   |
| East Hertfordshire<br>North Hertfordshire<br>St Albans<br>Three Rivers<br>Watford<br>Welwyn Hatfield<br>Luton (UA)<br><i>Norfolk</i><br>Breckland<br>Broadland<br>Great Yarmouth<br>King's Lynn and West Norfolk<br>Norfolk Broads (NP) | 27<br>28<br>30<br>31<br>31<br>32<br>32<br>32<br>32<br>32<br>38<br>40<br>42<br>46 |


| North Norfolk<br>Norwich<br>South Norfolk<br>Peterborough, City of (UA) | 46<br>51<br>53<br>57 |
|---|----------------------|
| Southend-on-Sea (UA)  | 60                   |
| Suffolk   | 61                   |
| Babergh   | 61                   |
| Forest Heath  | 62                   |
| lpswich   | 63                   |
| Mid Suffolk   | 63                   |
| St Edmundsbury  | 65                   |
| Suffolk Coastal   | 68                   |
| Waveney   | 72                   |
| Thurrock (UA)   | 72                   |

# Heritage at Risk





East of England Summary 2015



or the first time, we've compared all sites on the Heritage at Risk Register – from houses to hillforts – to help us better understand which types of site are most commonly at risk. There are things that make each region special and, once lost, will mean a sense of our region's character is lost too. Comparing the East of England to the national Register shows that 40.7% of all mills and 15.5% of all enclosures are in our region. There are 421 entries on the East of England 2015 Heritage at Risk Register, making up 7.7% of the national total of 5,478 entries. The Register provides an annual snapshot of historic sites known to be at risk from neglect, decay or inappropriate development. Our local HAR team, led by John Ette, continues to work with owners, funders and other stakeholders to find the right solutions for sites on the Register.

### **Greg Luton** Planning Director, East of England



In the East of England we have removed 108 (33%) of entries from the 2010 Register against the national target to remove 25% over the 5 year period. Over the last year, this significant progress has included removing 10 buildings and

structures, 29 places of worship, 2 conservation areas, 19 archaeological entries and 1 park and garden from the 2014 Register.

To achieve this we rely on successful relationships with owners and partners. The expert technical advice we provide to the Heritage Lottery Fund (HLF) under the Grants for Places of Worship Scheme has helped with the removal of places of worship from the 2014 Register; however 21 have been added as part of the team's assessment process.


We have worked closely with Natural England exceeding by 13% a shared target to remove scheduled monuments from the Register and to identify goals for the new Countryside Stewardship scheme. We are pleased that the historic environment remains a priority. This will allow us to continue to reduce risk to rural heritage sites, including our many prehistoric barrows. A developing partnership with Landfill Tax distributor WREN, has resulted in awards amounting to 50% of the national grants made this year to 5 sites including the ruins at St Andrews Church, Walberswick, Suffolk.

Cardington Airship Shed 1 has been restored. Positive progress has also been made on all other priority sites over the last year including Friston Mill, Suffolk where a project development grant has been awarded to the private owner. Wisbech, a key town for engagement in Cambridgeshire, also achieved a successful HLF award to help regenerate the High Street and secure the future of neglected buildings. The Naze Tower in Essex represents an on-going challenge. Complex structural issues arising from its military use as a radar station are currently being addressed.

The Heritage at Risk team has identified our wind and water mills at risk as a challenge for the year ahead; although positive action is in progress on 10 of those 11 mill buildings. We are also advising on a HLF Landscape Partnership scheme for part of the Broads National Park which would result in the conservation of a number of windmills and wind pumps. To help provide a strategic overview of this important site type, we intend to commission a survey of all the mills in the region.

### **John Ette** Principal Adviser, Heritage at Risk

**Cover image:** The remaining built elements of the **Latton Priory**, a 12th century Augustinian monastic house, now a scheduled monument surviving within a series of timber-framed barn structures. Roof tile fixings have rusted, and tiles have been lost over recent years. Water ingress is leading to decay of important 14th century fine ashlar stone. There is concern about the progressively worsening condition of the fabric. Historic England has provided £114,000 towards the cost of repairs with completion due by March 2016.



# St Mary's Friary Walsingham, Norfolk



# Background and history

The remains of St Mary's Friary, founded in 1347, comprise the most complete surviving example of a medieval Franciscan monastic house in the country. The friars would have ministered to and drawn income from pilgrims who flocked

to Walsingham, one of the pre-eminent pilgrimages in England at the time.

The friary was suppressed in 1538 during the Reformation and the church demolished soon after. The little cloister and the guest house were converted into dwellings by various tenants and owners before the whole site was acquired by the Walsingham Estate in the 18th century. Little of the church or great cloister now survives, but the domestic buildings, the little cloister, guest house, chapterhouse, dorter and kitchen survive as ruins.

### Is it at risk?

The site has long standing problems and has been on the Heritage at Risk Register since 2008. Works funded by Natural England, the Walsingham Estate and Historic England since 2010 have seen the little cloister, the guest house and chapter house repaired and consolidated. These works have been a model of cooperation between statutory agencies, grant awarding bodies, conservation professionals including skilled masons, and private owners. The prioritised works have been completed to a very high standard and the site was removed from the Register in 2015.

### What's the current situation?

The site is now open to visitors on one day a week and it is hoped that some low level, discreet interpretation can be provided.

# Hemel Water Gardens Hemel Hempstead, Hertfordshire

### **Background and history**

Architect and Town Planner, Geoffrey Jellicoe (1900-1996) was commissioned in 1947 to devise a master plan for the new town of Hemel Hempstead. A key component of the plan was the Water Gardens (designed 1957-59).

The Water Gardens is one of Jellicoe's earlier schemes and showcases many of his design characteristics including canals, bridges, viewing platforms and planting by Jellicoe's wife, Susan.

Over the years the gardens have been well used but the original concrete structures now need urgent repair. Comprehensive refurbishment is proposed, including structural repairs to bridges, balconies and other key elements. The planting scheme will be renewed in keeping with the original design and the impact of later additions will be reduced.

### Is it at risk?

The registered Water Gardens were placed on the Heritage at Risk Register in 2013.



### What's the current situation?

Dacorum Borough Council achieved a successful Heritage Lottery Fund bid and works are due to commence in 2015. Historic England offered extensive pre-application advice and an appraisal of a detailed master plan. Historic England also advised on the setting of the gardens in relation to the wider townscape redevelopment.

# Historic England Angel Awards

The Historic England Angel Awards were founded in 2011, co-funded by the Andrew Lloyd Webber Foundation. They celebrate local people's extraordinary efforts to save historic buildings and places. Over the past five years, the Angel Awards have showcased inspirational friends groups, communities, worshippers, owners and craftspeople.

From 2016, we'll be looking for projects that champion the historic environment in many ways. These could include:

- community action projects
- heritage research, survey or education projects
- heritage professionals
- lifetime achievements
- and of course, rescues of heritage sites

Shortlisted Angels will continue to be put to the vote in the ever-popular People's Favourite Award.

Look out for news at www.HistoricEngland.org.uk/ AngelAwards

### For more information contact:

John Ette, Historic England East of England Brooklands, 24 Brooklands Avenue, Cambridge, CB2 8BU Telephone: 01223 582 749 Email: eastofengland@HistoricEngland.org.uk Twitter: @HE\_E0E For a different format of this document contact our customer services department on:

Telephone: 0370 333 0608 Textphone: 0800 015 0516 Email: customers@HistoricEngland.org.uk Product code: 51988

Find out what's at risk by searching or downloading the online Heritage at Risk Register at: HistoricEngland.org.uk/har

# THE REGISTER Content and criteria

# DESIGNATION Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the <u>National</u> <u>Heritage List for England</u> (NHLE), an online searchable database of designated assets. Since I 882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

# LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Culture Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly

important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are over 376,000 listed entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

# SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,850 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not designated. Instead, they are managed through the planning system and other regimes.

# REGISTERED PARKS AND GARDENS

There are 1,635 designed landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II\*, and the Gardens Trust on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

# **REGISTERED BATTLEFIELDS**

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

# PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

# CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For almost 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,853 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

# Criteria for inclusion on the Register

### **RISK ASSESSMENTS**

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of designation. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

## **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be:

- designated and included on the National Heritage List for England
- a grade I or II\* listed building
- a grade II listed building in London
- a structural scheduled monument with upstanding remains
- in secular (non-worship) use

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

# PLACES OF WORSHIP

To be considered for inclusion on the Register places of worship must be designated and listed grade I, II\* or II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

# ARCHAEOLOGY

To be considered for inclusion on the Register archaeological sites must be designated as scheduled monuments and included on the National Heritage List for England. Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it ranging from 'extensive significant problems', to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

# PARKS AND GARDENS

To be considered for inclusion on the Register parks and gardens must be designated as grade I, II\* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

# BATTLEFIELDS

To be considered for inclusion on the Register battlefields must be designated and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings
- pressures of particular use within the site e.g. arable cultivation
- damage e.g. unregulated metal detecting

Battlefields are removed from the Register either when damaging activities cease, are managed, or when threats recede due to effective planning.

## WRECK SITES

To be considered for inclusion on the Register wrecks must be designated and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# **CONSERVATION AREAS**

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Reducing the risks

One of the primary aims of the Historic England Corporate Plan 2015-2018 is reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grants to help remove heritage from the Register

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website,

www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

# **BUILDINGS AND STRUCTURES**

Our nine regional teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. Historic England can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk for all asset types and Section 17 Management Agreements which are smaller grants for scheduled monuments. More information on funding can be found on the <u>Historic England</u> website.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with Civic Voice and voluntary groups to enable the compilation of local heritage at risk registers. We are also working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our Heritage at Risk Solicitor can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and fund their regional support officers to work across the country. They help BPTs and other not-for-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The <u>United Kingdom Association of Preservation Trusts</u> also provides information about support officers and BPTs. Guidance and case studies are available on the <u>Historic England</u> website.

# PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Cooperatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the <u>Grants for Places</u> of <u>Worship</u> scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. Historic England's architects and surveyors, based in our regional Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants. The Government's Listed Places of Worship Roof Repair Fund offers grants to help make listed places of worship weathertight, safe and open for use.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. <u>New Work in Historic Places of Worship</u> helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part funded by Historic England, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

# ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,832 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This is especially important under the New Environmental Land Management Scheme (NELMS) which commenced in 2015. Natural England shared our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015, which was achieved with 35% being removed. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project will provide updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in over 130 entries being removed from the 2014 Register.

Analysis of entries on the Register shows that prehistoric barrows are one of the most 'at risk' types of archaeological site on the Register. Unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

# PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

# BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II\*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

## WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems. In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival.

Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from <u>Historic England</u>.

## CONSERVATION AREAS

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management. Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them as well as those of us whose job it is to manage them or make decisions about their future.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

# Key statistics

# BUILDINGS AND STRUCTURES

- Nationally, 3.9% of grade I and II\* listed buildings (excluding places of worship) are on the Register. In the East of England the percentage is 2.6% (89 listed secular buildings).
- 10 building or structure entries have been removed from the 2014 East of England Register because their futures have been secured, and 11 have been added.
- 61.1% of buildings or structures (66) on the East of England baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 60.8%.

# PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In the East of England, 4.6% (107) are on the Register.
- 29 places of worship have been removed from the East of England Register following repair work, and 21 have been added.

# ARCHAEOLOGY

- 2,701 (13.6%) of England's 19,850 scheduled monuments are on the Register. 193 (11.1%) of the East of England's 1,735 scheduled monuments are on the Register.
- 19 archaeology entries have been removed from the 2014 East of England Register for positive reasons, and 3 have been added.
- 38.4% of archaeology entries (78) on the East of England baseline 2009 Register have been removed for positive reasons, compared with the national figure of 38.6%.

• Nationally, damage from arable cultivation is the greatest cause of risk affecting 39% of archaeological entries on the Register. In the East of England the proportion is 73%.

# PARKS AND GARDENS

- 94 (5.8%) of England's 1,633 registered parks and gardens are on the Register. Of the 212 registered parks and gardens in the East of England, 5 (2.4%) are on the Register.
- I park and garden entry has been removed from the 2014 East of England Register for a positive reason, and none have been added.

# BATTLEFIELDS

• Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. The only registered battlefield in the East of England is not on the Register.

# WRECK SITES

• Of the 49 protected wreck sites around England's coast, 4 (8.2%) are on the Register. The East of England's single protected wreck site is not on the Register.

# CONSERVATION AREAS

- 8,298 of England's 9,853 conservation areas have been surveyed by local authorities and 505 (6.1%) are on the Register. Of the 1,211 conservation areas in the East of England, 896 have been surveyed and 40 (4.5%) are on the Register.
- 2 conservation areas have been removed from the 2014 East of England Register for positive reasons, and 4 have been added.

# HISTORIC ENGLAND FUNDING

• £560,000 in grant was spent on 18 entries on the East of England Register during 2014/15.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – Historic England Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

Historic England's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2015 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2015 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.HistoricEngland.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit

http://www.HistoricEngland.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally. Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.HistoricEngland.org.uk .

Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address: http://list.HistoricEngland.org.uk.

# CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: <u>http://www.historicengland.org.uk/publications</u>

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological Sites on Arable Land (2004) Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Repair Grants for Heritage at Risk (2015)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2007)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

# Key to the entries

This Register includes the following risk assessment types

- Building or structure (grade I and II\* listed buildings and structural scheduled monuments)
- Place of worship (grade I, II\* and II listed buildings)
- Archaeology (scheduled monuments – earthworks and buried archaeology)
- Park and garden (Registered parks and gardens)
- Conservation area
  (Conservation areas)

# ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

# DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II\*
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

# CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

# OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

# VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- detenioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

# PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

2014 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

# TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

# OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

# CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- HE Historic England
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

# Entries on the Register by local planning authority

| Local planning authority                           | Building and structure entries | Place of<br>worship<br>entries | Archaeology<br>entries | Park and<br>garden<br>entries | Battlefield<br>entries | Wreck site<br>entries | Conservation<br>area entries |
|--|--------------------------------|--------------------------------|------------------------|-------------------------------|------------------------|-----------------------|------------------------------|
| BEDFORD (UA)                                       |                                |                                |                        |                               |                        |                       |                              |
| Bedford (UA)                                       | 0                              | 2                              | 7                      | 0                             | 0                      | 0                     |                              |
| CAMBRIDGESHIRE                                     |                                | 1                              |                        | 1                             | 1                      |                       |                              |
| Cambridge  | 0                              | 2                              |                        | 0                             | 0                      | 0                     | 0                            |
| East Cambridgeshire                                | 2                              | 1                              | 15                     | 0                             | 0                      | 0                     | 0                            |
| Fenland  | 0                              | 0                              | 8                      | 0                             | 0                      | 0                     | 5                            |
| Huntingdonshire                                    | 3                              | 2                              | 5                      | 0                             | 0                      | 0                     | 0                            |
| South Cambridgeshire                               | 2                              | 5                              | 22                     | 0                             | 0                      | 0                     | 5                            |
| CENTRAL BEDFORDSHIRE                               | (UA)                           | 1                              |                        | 1                             |                        |                       |                              |
| Central Bedfordshire (UA)                          | I                              | 3                              | 6                      | 0                             | 0                      | 0                     | 0                            |
| ESSEX  |                                | 1                              |                        | 1                             |                        |                       |                              |
| Basildon   | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Braintree  | 0                              | 2                              | 3                      | 0                             | 0                      | 0                     | 2                            |
| Brentwood  | 2                              | I                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Castle Point                                       | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Chelmsford   | 0                              | I                              | 1                      | 0                             | 0                      | 0                     | 3                            |
| Colchester   | 2                              | 2                              | 3                      | 0                             | 0                      | 0                     | 3                            |
| Epping Forest                                      | 5                              | 3                              | 2                      | 0                             | 0                      | 0                     | 0                            |
| Harlow   |                                | 0                              | 1                      | 0                             | 0                      | 0                     | 0                            |
| Maldon   | 2                              | 0                              | 2                      | 0                             | 0                      | 0                     | 0                            |
| Rochford   | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Tendring   | 7                              | 2                              | 2                      | 0                             | 0                      | 0                     | 4                            |
| Uttlesford   | 3                              | I                              | 4                      | I                             | 0                      | 0                     | 0                            |
| HERTFORDSHIRE                                      |                                |                                |                        |                               |                        |                       |                              |
| Broxbourne   | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 2                            |
| Dacorum  | 0                              | 0                              | 0                      | I                             | 0                      | 0                     | 0                            |
| East Hertfordshire                                 | 2                              | 2                              | 3                      | 0                             | 0                      | 0                     | 0                            |
| Hertsmere  | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| North Hertfordshire                                | 5                              | 2                              | 6                      | 0                             | 0                      | 0                     | 0                            |
| St Albans  |                                | 0                              | 2                      | 0                             | 0                      | 0                     | 0                            |
| Stevenage  | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Three Rivers                                       | I                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Watford  | 2                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Welwyn Hatfield                                    | I                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| LUTON (UA)   |                                |                                |                        |                               | •                      |                       |                              |
| Luton (UA)   | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 2                            |
| NORFOLK  |                                |                                |                        | ·                             |                        |                       |                              |
| Breckland  | 9                              | 15                             | 5                      | 0                             | 0                      | 0                     | 2                            |
| Broadland  | 2                              | 6                              | 3                      | 0                             | 0                      | 0                     | 0                            |
| Great Yarmouth                                     | 5                              | 7                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| King's Lynn and West<br>Norfolk                    | 8                              | 5                              | 7                      | 0                             | 0                      | 0                     | 0                            |
| Norfolk Broads (NP)                                | I                              | 0                              | 0                      | 0                             | 0                      | 0                     | 1                            |
| North Norfolk                                      | 7                              | 11                             | 4                      | I                             | 0                      | 0                     | 4                            |
| Norwich  | 5                              | 0                              | 0                      | 0                             | 0                      | 0                     | I                            |
| South Norfolk                                      | 0                              | 16                             | 5                      | 0                             | 0                      | 0                     | 0                            |
| PETERBOROUGH, CITY OF                              | (UA)                           |                                |                        | ·                             |                        |                       |                              |
| Peterborough, City of (UA)<br>SOUTHEND-ON-SEA (UA) | 4                              | 0                              | 21                     | 0                             | 0                      | 0                     | 0                            |
| Southend-on-Sea (UA)                               |                                | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| SUFFOLK  |                                | 0                              | 0                      | 0                             | 0                      | 0                     | 0                            |
| Babergh  | 3                              |                                | 4                      | 0                             | 0                      | 0                     | 0                            |
| Forest Heath                                       | 0                              |                                |                        |                               | 0                      |                       | 0                            |
|  |                                | 0                              |                        |                               |                        |                       |                              |
| Ipswich  | <br>                           |                                |                        |                               |                        |                       |                              |
| Mid Suffolk  | 3                              | 5                              |                        |                               | 0                      | 0                     | 0                            |

| Local planning authority | Building and structure entries | Place of<br>worship<br>entries | Archaeology<br>entries | Park and<br>garden<br>entries | Battlefield<br>entries | Wreck site<br>entries | Conservation area entries |
|--------------------------|--------------------------------|--------------------------------|------------------------|-------------------------------|------------------------|-----------------------|---------------------------|
| Norfolk Broads (NP)      | 0                              | 0                              | 0                      | 0                             | 0                      | 0                     | 0                         |
| St Edmundsbury           | 7                              | 2                              | 6                      | 0                             | 0                      | 0                     | 2                         |
| Suffolk Coastal          | 8                              | 7                              | 5                      |                               | 0                      | 0                     | 1                         |
| Waveney                  | 2                              |                                |                        | 0                             | 0                      | 0                     | 0                         |
| THURROCK (UA)            |                                |                                |                        |                               |                        |                       |                           |
| Thurrock (UA)            | 2                              | 0                              |                        | 0                             | 0                      | 0                     | 1                         |
|                          |                                |                                |                        |                               |                        |                       |                           |
| TOTAL                    | 110                            | 107                            | 159                    | 5                             | 0                      | 0                     | 40                        |

SITE NAME:

LIST ENTRY NUMBER:

1146376

#### **BEDFORD (UA)**



Congregational chapel, created c1806 in Cottage Ornee style. Plastered walls and thatched roofs. Thatch moss-Congregational Chapel, High Street, Roxton covered and deteriorating. Possibility that re-thatching required on some slopes. Church Elders applied unsuccessfully for a Listed Places of Worship Roof Repair Listed Place of Worship grade DESIGNATION: II\*, CA grant in 2015. CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation

© Bernard Hooker



| SITE NAME:         | Parish Church of All Saints,<br>High Street, Turvey | Medieval parish church with additions and alterations 185<br>1854 by Sir George Gilbert Scott. "The finest mid-Victoria<br>ecclesistical ensemble in Bedfordshire" (McHardy), Nave |
|--------------------|---|--|
| DESIGNATION:       | Listed Place of Worship grade I,<br>CA              | ecclesiastical ensemble in Bedfordshire" (McHardy). Nave,<br>chancel, west tower, north and south aisles and south<br>porch. West part of the nave and the base of the tower       |
| CONDITION:         | Poor  | has remains of Saxon work. The nave is mainly C13 with the north arcade added early C14 and the nave extended.   |
| PRIORITY CATEGORY: | A (New entry)                                       | Most of the windows were reworked by Scott. CI5  |
| OWNER TYPE:        | Religious organisation                              | clerestory and fine angel roof. South aisle roof leaking badly over early C14 wall painting of the crucifixion.  |
| LIST ENTRY NUMBER: | 1039598   | Contact: Robert Parkinson 01223 582733   |

Contact: Trudi Hughes 01223 582739

© Historic England

| SITE NAME:               | Manor Farm Iron Age univallate hillfort and med        | eval moated enclosur  | re, Bolnhurst and Keysoe |
|--------------------------|--|-----------------------|--------------------------|
| DESIGNATION:             | Scheduled Monument, LB grade II                        | LIST ENTRY NUMBER:    | 1012066                  |
| CONDITION:               | Generally unsatisfactory with major localised problems | TREND:                | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                       | NEW ENTRY?:           | No                       |
| OWNER TYPE:              | Private  | CONTACT:              | David Kenny 01223 582760 |
| SITE NAME:               | Settlement site north of Chapel End Farm, Cardi        | ngton                 |                          |
| DESIGNATION:             | Scheduled Monument                                     | LIST ENTRY NUMBER:    | 1005390                  |
| CONDITION:               | Extensive significant problems                         | TREND:                | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                       | NEW ENTRY?:           | No                       |
| OWNER TYPE:              | Private  | CONTACT:              | David Kenny 01223 582760 |
| SITE NAME:               | Site discovered by aerial photography south of v       | llage, Cardington     |                          |
| DESIGNATION:             | Scheduled Monument                                     | LIST ENTRY NUMBER:    | 1005413                  |
| CONDITION:               | Extensive significant problems                         | TREND:                | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                       | NEW ENTRY?:           | No                       |
| OWNER TYPE:              | Private  | CONTACT:              | David Kenny 01223 582760 |
| SITE NAME:               | Bury Hill Camp: a motte and bailey castle with th      | ree fishponds, Thurle | eigh                     |
| DESIGNATION:             | Scheduled Monument, LB grade II, part in CA            | LIST ENTRY NUMBER:    | 1009155                  |
| CONDITION:               | Extensive significant problems                         | TREND:                | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                       | NEW ENTRY?:           | No                       |
| OWNER TYPE:              | Private  | CONTACT:              | David Kenny 01223 582760 |
|                          |  |                       |                          |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BEDFORD (UA) / CAMBRIDGE

| SITE NAME:               | Palaceyard Wood medieval moated enclosure and earthworks, Wyboston, Chawston and Colesden / | associated enclosu<br>Great Barford | res, woodland bank and cultivation |
|--------------------------|---|-------------------------------------|------------------------------------|
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER:                  | 1010948                            |
| CONDITION:               | Generally satisfactory but with significant localised problems                              | TREND:                              | Stable                             |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth   | NEW ENTRY ?:                        | No                                 |
| OWNER TYPE:              | Private   | CONTACT:                            | Claire Fidler 01223 582735         |
| SITE NAME:               | Yarl's Wood hermitage and moated site, Milton Er  | nest                                |                                    |
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER:                  | 1012057                            |
| CONDITION:               | Generally unsatisfactory with major localised problems                                      | TREND:                              | Declining                          |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth   | NEW ENTRY?:                         | No                                 |
| OWNER TYPE:              | Private   | CONTACT:                            | David Kenny 01223 582760           |
| SITE NAME:               | Wold Farm moated enclosure, Odell   |                                     |                                    |
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER:                  | 1012490                            |
| CONDITION:               | Generally unsatisfactory with major localised problems                                      | TREND:                              | Declining                          |
| PRINCIPAL VULNERABILITY: | Dumping   | NEW ENTRY ?:                        | No                                 |
| OWNER TYPE:              | Private   | CONTACT:                            | David Kenny 01223 582760           |
| site name:               | Bedford   |                                     |                                    |
| DESIGNATION:             | Conservation Area, 100 LBs, RPG grade II, 4 SMs   | NEW ENTRY?:                         | No                                 |
| CONDITION:               | Very bad  | TREND:                              | Improving                          |
| VULNERABILITY:           | Low   | CONTACT:                            | lan Johnson (LPA) 01234 221953     |
|                          |   |                                     |                                    |

#### CAMBRIDGESHIRE

#### CAMBRIDGE

| e E Enderd | SITE NAME:         | Church of St Clement, Bridge<br>Street, Cambridge | The exterior of this church is dominated by the early C19 tower in a thin, Commissioners' Gothic style. The nave and   |
|------------|--------------------|---|--|
|            | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA          | aisles are externally entirely early C16, and the brick<br>chancel is distinctively C18. There is a distinctive mix of<br>building materials and blocked openings in the pre-C19 |
|            | CONDITION:         | Poor  | work. Church shared by Anglican and Greek Orthodox congregations. South aisle roof in particularly poor  |
|            | PRIORITY CATEGORY: | A (A)   | condition with significant water penetration. No long term   |
|            | OWNER TYPE:        | Religious organisation                            | solution agreed.   |
|            | LIST ENTRY NUMBER: | 1126262   | Contact: Robert Parkinson 01223 582733   |

© Historic England



|        | SITE NAME:         | Church of St Andrew the Less,<br>Newmarket Road, Cambridge | Abbey church of early C13 date consisting of chancel and<br>nave. Rubble with some dressed stone. Built by Barnwell  |
|--------|--------------------|--|--|
|        | DESIGNATION:       | Listed Place of Worship grade II,<br>CA                    | Priory on original Augustinian site. The church was<br>restored 1854-6, the vestry and organ-chamber added in<br>the late C19. Walls, roof and churchyard in very poor |
|        | CONDITION:         | Very bad   | condition. Long term solution yet to be agreed.  |
| ta bab | PRIORITY CATEGORY: | A (A)  |  |
|        | OWNER TYPE:        | Religious organisation                                     |  |
|        | LIST ENTRY NUMBER: | 1126143  | Contact: Robert Parkinson 01223 582733   |

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

2

#### EAST CAMBRIDGESHIRE

|                    | SITE NAME:         | Downfield Windmill, Fordham<br>Road, Soham | Windmill originally built in 1726, raised in 1860, largely rebuilt following storm damage in 1889. Machinery          |
|--------------------|--------------------|--|---|
|                    | DESIGNATION:       | Listed Building grade II*                  | substantially complete, but condition deteriorating. In need of general repairs, and reinstatement of sails and other |
|                    | CONDITION:         | Poor                                       | missing parts of the structure. A schedule of works has been prepared with Historic England grant aid. Repair         |
|                    | OCCUPANCY:         | N/A  | work started in June 2013. Completion estimated end of 2015.  |
|                    | PRIORITY CATEGORY: | F (F)                                      | 2013.   |
|                    | OWNER TYPE:        | Private                                    |   |
| © Historic England | LIST ENTRY NUMBER: | 1331761                                    | Contact: Trudi Hughes 01223 582739  |
|                    |                    |  |   |



|      | SITE NAME:         | Northfield Windmill, The<br>Shades, Soham | Originally C18 drainage mill for the neighbouring Fen,<br>relocated during 1830s to present position and converted          |
|------|--------------------|---|---|
| × 34 | DESIGNATION:       | Listed Building grade II*                 | to a corn mill. Six-sided timber-framed smock mill. Has machinery but the cap is deformed, leaking and will not             |
|      | CONDITION:         | Poor                                      | turn to wind. Some temporary repairs completed 2009 to attend to leaks. Since 2012 and a change of ownership,               |
|      | OCCUPANCY:         | N/A                                       | repairs have been undertaken and condition has improved.  |
|      | PRIORITY CATEGORY: | D (C)                                     | Plans remain to repair cap, curb and sails, and to make the mill mechanically sound. Sails are being repaired. This mill is |
|      | OWNER TYPE:        | Private                                   | part of the 'East Anglian Mills Society' (TEAMS) grouping.  |
|      | LIST ENTRY NUMBER: | 1126418                                   | Contact: Trudi Hughes 01223 582739  |

© Historic England

|                    | SITE NAME:         | Church of St Peter, Church<br>Lane, Stetchworth | Parish church dated to C14 and the tower C15. The church is suffering from severe settlement, especially the                   |
|--------------------|--------------------|---|--|
|                    | DESIGNATION:       | Listed Place of Worship grade II*               | north aisle wall is pulling horizontally away from the aisle at floor level. Signs of stress in nave arcades at tie beam/truss |
|                    | CONDITION:         | Poor  | positions, and at each end in masonry of the south aisle.<br>Attention also needed to roofs and rainwater goods and            |
|                    | PRIORITY CATEGORY: | F (F)   | drainage. A Repair Grant for Places of Worship was   |
|                    | OWNER TYPE:        | Religious organisation                          | offered in 2012, towards structural issues due to clay<br>subsoil and poor drainage. Project development phase now             |
|                    | LIST ENTRY NUMBER: | 33 82   | underway with urgent repairs due to be completed autumn 2015.  |
| © Historic England | _                  |   | Contact: Malcolm Starr 01223 582723  |

Contact: Malcolm Starr 01223 582723

| SITE NAME:               | All Saints' Church, remains of, Ashley                     |                          |                          |  |  |
|--------------------------|--|--------------------------|--------------------------|--|--|
| DESIGNATION:             | Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1006898 |                          |                          |  |  |
| CONDITION:               | Generally unsatisfactory with major localised problems     | TREND:                   | Declining                |  |  |
| PRINCIPAL VULNERABILITY: | Vandalism  | Vandalism NEW ENTRY?: No |                          |  |  |
| OWNER TYPE:              | Mixed, multiple owners                                     | CONTACT:                 | David Kenny 01223 582760 |  |  |
| SITE NAME:               | Bowl barrow 450m east of Shelford Farm, Haddenham          |                          |                          |  |  |
| DESIGNATION:             | Scheduled Monument LIST ENTRY NUMBER: 1020398              |                          | 1020398                  |  |  |
| CONDITION                |  |                          |                          |  |  |

| CONDITION:               | Extensive significant problems                  | TREND:              | Declining                        |
|--------------------------|---|---------------------|----------------------------------|
| PRINCIPAL VULNERABILITY: | Arable ploughing                                | NEW ENTRY?:         | No                               |
| OWNER TYPE:              | Commercial company                              | CONTACT:            | David Kenny 01223 582760         |
| SITE NAME:               | Long barrow at Foulmire Fen, 140m north west of | the junction of Bac | k and Small Fen Drove, Haddenham |
| DESIGNATION:             | Scheduled Monument                              | LIST ENTRY NUMBER:  | 1019983                          |
| CONDITION:               | Extensive significant problems                  | TREND:              | Declining                        |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                | NEW ENTRY?:         | No                               |
| OWNER TYPE:              | Commercial company                              | CONTACT:            | David Kenny 01223 582760         |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- LB Listed Building LPA Local Planning Autho NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / EAST CAMBRIDGESHIRE

| SITE NAME:               | Oval barrow and round barrow at Small Fen, 25<br>Haddenham | 0m north of the junct  | tion of Back and Small Fen Drove, |  |
|--------------------------|--|------------------------|-----------------------------------|--|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1019984                           |  |
| CONDITION:               | Generally unsatisfactory with major localised problems     | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
| SITE NAME:               | Round barrow at Small Fen, 220m east of the ju             | nction of Back and Sm  | nall Fen Drove, Haddenham         |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1019986                           |  |
| CONDITION:               | Extensive significant problems                             | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
| SITE NAME:               | Three bowl barrows 450m and 570m east of Ne<br>Haddenham   | w England, part of th  | e Haddenham round barrow cemete   |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1019982                           |  |
| CONDITION:               | Extensive significant problems                             | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
| ITE NAME:                | Two bowl barrows 370m and 505m south of Ne<br>Haddenham    | ew England, part of th | e Haddenham round barrow cemete   |  |
| DESIGNATION:             | Scheduled Monument LIST ENTRY NUMBER: 1019                 |                        | 1019985                           |  |
| CONDITION:               | Extensive significant problems                             | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
| SITE NAME:               | Roman settlement, Lode                                     |                        |                                   |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006793                           |  |
| CONDITION:               | Generally unsatisfactory with major localised problems     | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                |  |
| OWNER TYPE:              | Mixed, multiple owners                                     | CONTACT:               | David Kenny 01223 582760          |  |
| ITE NAME:                | Roman site near Old Fordey Farm, Barway, Soh               | am                     |                                   |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006885                           |  |
| CONDITION:               | Extensive significant problems                             | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:            | No                                |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
| ITE NAME:                | Settlement site south of Tiled House Farm, Stre            | tham                   |                                   |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006795                           |  |
| CONDITION:               | Generally unsatisfactory with major localised problems     | TREND:                 | Declining                         |  |
| PRINCIPAL VULNERABILITY: | •  |                        |                                   |  |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760          |  |
|                          |  |                        |                                   |  |

#### PRIORITY CATEGORIES

# А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
  C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but F Under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / EAST CAMBRIDGESHIRE / FENLAND

| SITE NAME:                                     | Long barrow at South Fen, 90m south west of | the west end of Ryman   | moor Long Turning, Sutton |  |  |
|--|---|-------------------------|---------------------------|--|--|
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1019988                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing NEW ENTRY: No              |                         |                           |  |  |
| DWNER TYPE: Private CONTACT: David Kenny 01223 |   |                         |                           |  |  |
| SITE NAME:                                     | Long barrow at South Fen, 180m south east o | f Between Ditches Drov  | ve, Sutton                |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1009994                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing                            | NEW ENTRY ?:            | No                        |  |  |
| OWNER TYPE:                                    | Private                                     | CONTACT:                | David Kenny 01223 582760  |  |  |
| SITE NAME:                                     | Round barrow 690m SSW of Stocking Drove     | Farm, Sutton            |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1019987                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing                            | NEW ENTRY?:             | No                        |  |  |
| OWNER TYPE:                                    | Commercial company                          | CONTACT:                | David Kenny 01223 582760  |  |  |
| SITE NAME:                                     | Long barrow 650m NNW of Lythel's Farm, Sv   | waffham Bulbeck         |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1020843                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       |   |                         | No                        |  |  |
| OWNER TYPE:                                    | David Kenny 01223 582760                    |                         |                           |  |  |
| SITE NAME:                                     | Long barrow 410m south east of Partridge Ha | II Farm, Swaffham Prior |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument LIST ENTRY NUMBER: [(    |                         | 1020842                   |  |  |
| CONDITION:                                     | Extensive significant problems TREND:       |                         | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing NEW ENTRY?: No             |                         | No                        |  |  |
| OWNER TYPE:                                    | Commercial company, multiple owners         | CONTACT:                | David Kenny 01223 582760  |  |  |
| ENLAND   |   |                         |                           |  |  |
| SITE NAME:                                     | Bowl barrow 200m south east of Horseley Fe  | n Farm, Chatteris       |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1011723                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing                            | NEW ENTRY?:             | No                        |  |  |
| OWNER TYPE:                                    | Commercial company                          | CONTACT:                | David Kenny 01223 582760  |  |  |
| SITE NAME:                                     | Bowl barrow 250m south of Honey Farm, Ch    | atteris                 |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1020393                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing                            | NEW ENTRY?:             | No                        |  |  |
| OWNER TYPE:                                    | Mixed, multiple owners                      | CONTACT:                | David Kenny 01223 582760  |  |  |
| SITE NAME:                                     | Bowl barrow 580m east of Mount Pleasant Br  | idge, Chatteris         |                           |  |  |
| DESIGNATION:                                   | Scheduled Monument                          | LIST ENTRY NUMBER:      | 1020394                   |  |  |
| CONDITION:                                     | Extensive significant problems              | TREND:                  | Declining                 |  |  |
| PRINCIPAL VULNERABILITY:                       | Arable ploughing                            | NEW ENTRY ?:            | No                        |  |  |
| OWNER TYPE:                                    | Religious organisation                      |                         | David Kenny 01223 582760  |  |  |

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / FENLAND

| SITE NAME:                 | Bowl barrow 600m west of Honey Hill Farm, Ch                        | natteris                                      |  |  |  |
|----------------------------|---|---|--|--|--|
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                            | 1011718                                  |  |  |
| CONDITION:                 | Extensive significant problems                                      | TREND: Declining                              |  |  |  |
| PRINCIPAL VULNERABILITY:   | Arable ploughing  | NEW ENTRY?: No                                |  |  |  |
| OWNER TYPE:                | Religious organisation CONTACT: David Kenny 01223 5827              |   |  |  |  |
| SITE NAME:                 | Neolithic enclosures at Grey's Farm, Horseley F                     | en, Chatteris                                 |  |  |  |
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                            | 1009993                                  |  |  |
| CONDITION:                 | Generally unsatisfactory with major localised problems              | Generally unsatisfactory with major localised |  |  |  |
| PRINCIPAL VULNERABILITY:   | Arable ploughing  | NEW ENTRY?:                                   | No                                       |  |  |
| OWNER TYPE:                | Mixed, multiple owners  | CONTACT:                                      | David Kenny 01223 582760                 |  |  |
| SITE NAME:                 | Bowl barrow 500m south of Bunting's Farm, Wh                        | nittlesey                                     |  |  |  |
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                            | 1020847                                  |  |  |
| CONDITION:                 | Extensive significant problems                                      | TREND:  | Declining                                |  |  |
| PRINCIPAL VULNERABILITY:   | Arable ploughing  | NEW ENTRY?:                                   | No                                       |  |  |
| OWNER TYPE:                | Commercial company  | CONTACT:                                      | David Kenny 01223 582760                 |  |  |
| SITE NAME:                 | Suet Hills round barrow cemetery, Whittlesey                        |   |  |  |  |
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                            | 1020844                                  |  |  |
| CONDITION:                 | Extensive significant problems                                      | TREND: Declining                              |  |  |  |
| PRINCIPAL VULNERABILITY:   | TY: Arable ploughing NEW ENTRY?: No                                 |   | No                                       |  |  |
| OWNER TYPE:                | NER TYPE: Commercial company CONTACT: David Kenny                   |   |  |  |  |
| SITE NAME:                 | Romano-British settlement near Honeybridge, Wimblington / Chatteris |   |  |  |  |
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                            | 1006906                                  |  |  |
| CONDITION:                 | Generally unsatisfactory with major localised problems              | TREND:  | Declining                                |  |  |
| PRINCIPAL VULNERABILITY:   | Arable ploughing  | NEW ENTRY?:                                   | No                                       |  |  |
| OWNER TYPE:                | Commercial company  | CONTACT:                                      | David Kenny 01223 582760                 |  |  |
| SITE NAME:                 | Bowthorpe, Wisbech  |   |  |  |  |
| DESIGNATION:               | Conservation Area, 5 LBs  | NEW ENTRY?:                                   | Yes                                      |  |  |
| CONDITION:                 | Poor  | TREND:  | Deteriorating                            |  |  |
| VULNERABILITY:             | Nicola Duncan-Fir   |   | Nicola Duncan-Finn (LPA) 01354<br>622321 |  |  |
| SITE NAME:                 | Chatteris   |   |  |  |  |
| DESIGNATION:               | Conservation Area, 100 LBs  | NEW ENTRY?:                                   | Yes                                      |  |  |
| CONDITION:                 | Very bad  | TREND:  | Improving                                |  |  |
| VULNERABILITY:             | Low CONTACT: Nicola Duncan-Finn<br>622321                           |   |  |  |  |
| SITE NAME:                 | March   |   |  |  |  |
|                            | Conservation Area, 27 LBs   | NEW ENTRY ?:                                  | Yes                                      |  |  |
| DESIGNATION:               | ·   |   |  |  |  |
| designation:<br>condition: | Poor  | TREND:  | Deteriorating                            |  |  |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / FENLAND / HUNTINGDONSHIRE

| SITE NAME:     | Whittlesey                              |             |  |
|----------------|---|-------------|--|
| DESIGNATION:   | Conservation Area, 63 LBs, SM           | NEW ENTRY?: | Yes                                      |
| CONDITION:     | Poor                                    | TREND:      | Deteriorating                            |
| VULNERABILITY: | Low                                     | CONTACT:    | Nicola Duncan-Finn (LPA) 01354<br>622321 |
| SITE NAME:     | Wisbech                                 |             |  |
| DESIGNATION:   | Conservation Area, 229 LBs, RPG grade I | NEW ENTRY?: | No                                       |
| CONDITION:     | Very bad                                | TREND:      | Deteriorating                            |
| VULNERABILITY: | Low                                     | CONTACT:    | Nicola Duncan-Finn (LPA) 01354<br>622321 |

#### HUNTINGDONSHIRE



| E  |                    |  |  |
|----|--------------------|--|--|
|    | SITE NAME:         | Great Gransden Windmill,<br>Great Gransden | Constructed c1612, Great Gransden is allegedly, the oldest remaining mill in England. Building contains a flour dressing                               |
| 6  | DESIGNATION:       | Scheduled Monument, LB grade<br>II*        | machine with the inscription 'IL 1774 RW'. A comprehensive survey shows that the mill is in poor condition. Consent for emergency repairs was granted, |
| 38 | CONDITION:         | Poor                                       | including dismantling of sails for safety reasons, in late 2013.<br>Some emergency works completed in 2014. Discussions                                |
|    | OCCUPANCY:         | Vacant/not in use                          | are continuing regarding the creation of a local trust to take   |
| ++ | PRIORITY CATEGORY: | C (D)                                      | on the repairs and manage the building.  |
| 1  | OWNER TYPE:        | Local authority                            |  |
|    | LIST ENTRY NUMBER: | 1006820                                    | Contact: Deborah Priddy 01223 582720   |

© Historic England



| SITE NAME:         | Park wall of Hinchingbrooke<br>House, Hinchingbrooke,<br>Huntingdon | C17 and C18 wall. The south portion of the park boundary wall is of coursed stone and brick with ball finials. This section of the wall is in a bad condition and some parts |
|--------------------|---|--|
| DESIGNATION:       | Listed Building grade II*, CA                                       | have collapsed. Other parts are beginning to lean significantly, and plant growth is a problem. The bank, and  |
| CONDITION:         | Very bad  | steps leading up to the terrace below the wall, also suffer from significant, but localised animal burrowing.  |
| OCCUPANCY:         | N/A   | Discussions have been opened with the site manager, and  |
| PRIORITY CATEGORY: | C (C)   | an application for a development and repair project has<br>been submitted.   |
| OWNER TYPE:        | Educational (state sector)  |  |
| LIST ENTRY NUMBER: | 1128652   | Contact: Claire Fidler 01223 582735  |

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

| SITE NAME:         | St Andrew's Church, Church<br>End, Wood Walton | Former church with CI3 south arcade of nave, CI4-CI5 west tower, CI4 chancel, CI6 north arcade much rebuilt    |
|--------------------|--|--|
| DESIGNATION:       | Listed Building grade II*                      | 1856-9. Coursed limestone rubble, limestone dressings, plain tile roof. Very isolated. High level repairs were |
| CONDITION:         | Poor   | completed to tower and roofs in 2013. Building still thought to be moving and currently undergoing structural  |
| OCCUPANCY:         | N/A  | monitoring.  |
| PRIORITY CATEGORY: | C (C)  |  |
| OWNER TYPE:        | Charity (heritage)                             |  |
| LIST ENTRY NUMBER: | 1130123  | Contact: Trudi Hughes 01223 582739   |

St Marys Parish Church, Broadway, Farcet

Religious organisation

Listed Place of Worship grade II\*

© Historic England



© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Fair

F (F)

1215281

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Robert Parkinson 01223 582733

with completion late 2015.

Parish church. CI2 nave, west tower cI180-90, CI3

difficulties. Heritage Lottery Fund Grant for Places of

chancel and south chapel. South aisle rebuilt with wider east bay 1270-80. South porch C14. Church restored in

1852 and north aisle and arcade added with original C12 north door re-sited. Tower restored 1894-97. Walls of

Worship offered 2013. Repairs commenced spring 2014

limestone rubble with Barnack dressings. Serious structural problems associated with ground conditions and drainage

#### ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UÁ WHS

Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / HUNTINGDONSHIRE



| Church of St Thomas, Herne<br>Road, Ramsey |
|--|
| Listed Place of Worship grade              |
| Poor                                       |
| C (C)                                      |
| Religious organisation                     |
| 1330457                                    |
|  |

Parish church built in 1869 by subscription. Nave with polygonal east end, north west bell turret. Gault brick, slate roof. Early English fenestration. High level general mortar failure in brickwork and around windows with some cracking visible. Plant growth taking hold in porch and rainwater goods. No action/strategy identified or agreed.

Contact: Claire Fidler 01223 582735

Ш

© Historic England

| SITE NAME:  | Roman site, Rushey Farm, Great Staughton  |                          |                          |  |
|---|---|--------------------------|--------------------------|--|
| DESIGNATION:  | Scheduled Monument  | 1006866                  |                          |  |
| CONDITION:  | Generally unsatisfactory with major localised TREND: Declining problems           |                          |                          |  |
| PRINCIPAL VULNERABILITY:                                      | Arable ploughing  | NEW ENTRY ?:             | No                       |  |
| OWNER TYPE:   | Commercial company  | David Kenny 01223 582760 |                          |  |
| SITE NAME:  | Monk's Hole barrow, 630m NNE of Monk's Wood                                       | l Farm, Sawtry           |                          |  |
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:       | 1015007                  |  |
| CONDITION:  | Extensive significant problems  | TREND:                   | Declining                |  |
| PRINCIPAL VULNERABILITY:                                      | Arable ploughing  | NEW ENTRY?:              | No                       |  |
| OWNER TYPE:   | Mixed, multiple owners  | CONTACT:                 | David Kenny 01223 582760 |  |
| SITE NAME:  | Site of Sawtry Judith village adjoining Archers Woo                               | od, Sawtry               |                          |  |
| DESIGNATION:  | TION: Scheduled Monument LIST ENTRY NUMBER  |                          | 1006816                  |  |
| CONDITION:  | Generally unsatisfactory with major localised TREN problems                       |                          | Declining                |  |
| PRINCIPAL VULNERABILITY:                                      | Arable ploughing NEW ENTRY?: No   |                          | No                       |  |
| OWNER TYPE:   | RTYPE: Mixed, multiple owners CONTACT:  |                          | David Kenny 01223 582760 |  |
| SITE NAME:  | Moated site in Prestley Wood, 800m north east of Cartwright's Farm, The Stukeleys |                          | , The Stukeleys          |  |
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:       | 1017843                  |  |
| CONDITION:  | Generally satisfactory but with significant localised problems                    | TREND:                   | Stable                   |  |
| PRINCIPAL VULNERABILITY:                                      | Scrub/tree growth   | NEW ENTRY ?:             | No                       |  |
| OWNER TYPE:   | Private   | CONTACT:                 | David Kenny 01223 582760 |  |
| site name:  | Moated site in Toseland Wood, Toseland  |                          |                          |  |
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:       | 1017881                  |  |
| CONDITION:  | Generally satisfactory but with significant localised problems                    | TREND:                   | Declining                |  |
| PRINCIPAL VULNERABILITY:                                      | Animal burrowing - moderate   | NEW ENTRY?:              | No                       |  |
| OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582 |   |                          |                          |  |
|   |   |                          |                          |  |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP RPG
  - Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

| SOUTH CAMBRIDGESHI | RE                 |  |   |
|--------------------|--------------------|--|---|
|                    | SITE NAME:         | Little Chishill Mill, Barley Road,<br>Great and Little Chishill                            | Post mill. Possibly rebuilt 1819 (Wailes), scratching on stud 1712, main post renewed 1868 and dated underneath mill.   |
|                    | DESIGNATION:       | Listed Building grade II*  | Patent sails c1912-16 replacing former canvas covered sails.<br>Timber-framed, weather boarded and painted with brick   |
|                    | CONDITION:         | Poor   | piers. The main structure extends to the rear housing the bolter; restored fantail on ladder. The mill was last used in   |
| Charles Battle     | OCCUPANCY:         | Vacant/not in use  | 1951, and was renovated by Thompsons of Alford, Lincs.  |
|                    | PRIORITY CATEGORY: | C (C)  | in 1966. The buck (sail housing) is leaking and requires new weatherboarding. Mill transferred to the Great Chishill  |
| line -             | OWNER TYPE:        | Charity (heritage)   | Windmill Trust who are preparing to carry out external repairs to the buck.   |
| © Historic England | LIST ENTRY NUMBER: | 1330927  | Contact: Trudi Hughes 01223 582739  |
|                    | SITE NAME:         | Large tannery building at<br>Hutchins and Harding Ltd, High<br>Street (east side), Sawston | C19 timber-framed skin drying shed with adjustable timber<br>louvered walls. Major areas of roof and south and west<br>walls exposed and admitting rain. Internal boarded floors in |
|                    | DESIGNATION:       | Listed Building grade II*  | very bad condition and partly collapsed. Redundant and at immediate risk of further deterioration or loss of fabric.  |
|                    | CONDITION:         | Very bad   | Historic England has advised Local Planning Authority that<br>Urgent Works Notice should be served.   |
|                    | OCCUPANCY:         | Vacant/not in use  | orgent works notice should be served.   |
|                    | PRIORITY CATEGORY: | A (A)  |   |
|                    | OWNER TYPE:        | Commercial company   |   |
| © Historic England | LIST ENTRY NUMBER: | 1127985  | Contact: Robert Parkinson 01223 582733  |
|                    | SITE NAME:         | Parish Church of St Nicolas,<br>Great and Little Chishill                                  | Parish church. C12 chancel, extended in C13 or early C14.<br>Late C14 tower with C16 belfry windows. Late C14 nave  |
|                    | DESIGNATION:       | Listed Place of Worship grade II*  | and south porch. C19 restoration included replacement of C15 nave windows and building of pyramidal tower roof  |
|                    | CONDITION:         | Poor   | structure. Memorial glass by Kempe 1916, in east window.<br>Batten failure on nave roof; tiles slipping. Parish architect   |
| THE HALL AND AND   | PRIORITY CATEGORY: | C (C)  | and builder carried out detailed inspection and application   |
| A T T T            | OWNER TYPE:        | Religious organisation   | for grant aid anticipated.  |
|                    | LIST ENTRY NUMBER: | 6249   | Contact: Trudi Hughes 01223 582739  |
| © Historic England |                    |  |   |

C13 nave and chancel. Late C14 south aisle. C15 tower. SITE NAME: Parish Church of St Swithun, Tower collapsed in 1892; rebuilt 1897, at which time the Barley Road, Great and Little nave and aisles were restored by F E Penrose. Early C20 Chishill vestry and organ chamber. Repairs including stabilising DESIGNATION: Listed Place of Worship grade II\* south porch and part renewal of drainage completed 2014. However, water ingress and possible on-going movement CONDITION: Fair over tower arch is causing on-going decay to stonework internally, with cracking in other parts of church. Discussion PRIORITY CATEGORY: A (New entry) ongoing. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1128142 Contact: Trudi Hughes 01223 582739

© Historic England

© Historic England



|  | SITE NAME:         | Church of St Mary, High Street,<br>Great Eversden | Parish church rebuilt after a fire in 1466, with further restorations in 1864 and 1920. Construction materials        |
|--|--------------------|---|---|
|  | DESIGNATION:       | Listed Place of Worship grade II*                 | consist of Fieldstone, clunch rubble and dressings of clunch<br>and limestone with a tiled roof. West tower, nave and |
|  | CONDITION:         | Very bad  | chancel. Serious structural movements. Historic<br>England/Heritage Lottery Fund Repair Grant for Places of           |
|  | PRIORITY CATEGORY: | F (F)   | Worship awarded in 2011. Repair works to foundations  |
|  | OWNER TYPE:        | Religious organisation                            | and low level masonry, estimated completion 2015. HLF<br>Grant for Places of Worship offered 2015 for repairs to      |
|  | LIST ENTRY NUMBER: | 2762  | north slopes of chancel and nave roofs, high level masonry<br>and north porch. Repair works underway.                 |
|  |                    |   | and nor ar por ch. repair works underway.   |

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park CA LB
- LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH CAMBRIDGESHIRE



| ITE NAME:         | Church of St Andrew,<br>Burgoynes Road, Impington | Early C13 nave and tower, upper stages rebuilt C14, and rood stair. South porch C15, chancel rebuilt during        |
|-------------------|---|--|
| DESIGNATION:      | Listed Place of Worship grade I                   | restoration of 1878, dated rainwater heads. Walls of<br>Barnack limestone with limestone and pebble rubble.        |
| CONDITION:        | Very bad  | Timber framed porch. Plain tile roofs with gable parapets to nave and chancel with cross finials. South elevation: |
| RIORITY CATEGORY: | A (A)   | tower of three stages with Barnack limestone quoins.   |
| OWNER TYPE:       | Religious organisation                            | Severe cracks in tower and nave monitored 1999-2012.<br>Movement stabilised after removal of trees pre-2009. Long  |
| IST ENTRY NUMBER: | 1178832   | term solution to be agreed.  |
|                   |   | Contact: Robert Parkinson 01223 582733   |

© Historic England



|       | SITE NAME:         | Church of St Giles, Potton<br>Road, Tadlow | Parish church. C13 nave and chancel and C14 west tower.<br>Restored c1860 under supervision of W Butterfield. |
|-------|--------------------|--|---|
|       | DESIGNATION:       | Listed Place of Worship grade II*          | Fieldstone, clunch rubble with limestone and clunch dressing. Plain tiled roof. West tower of three stages.   |
| T     | CONDITION:         | Fair                                       | Crack to second stage of tower on east face. Some displacement/cracking to buttress on north wall adjacent    |
|       | PRIORITY CATEGORY: | A (A)                                      | to infilled north door. Further crack to north side of east   |
| 1 200 | OWNER TYPE:        | Religious organisation                     | gable. Cracking to stonework and extensive ivy growth reported April 2014. Deterioration continues but no     |
| 1     | LIST ENTRY NUMBER: | 1317879                                    | solution agreed.  |
|       |                    |  | Contact: David Grech 01223 582717   |

© Historic England

| SITE NAME:               | John O'Gaunt's House: a motte castle and moate<br>Kneesworth | ed site 300m north ea  | ist of Haygate Farm, Bassingbourn cun |
|--------------------------|--|------------------------|---------------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1010865                               |
| CONDITION:               | Extensive significant problems                               | TREND:                 | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:            | No                                    |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760              |
| SITE NAME:               | Sites revealed by air photography, Bassingbourn              | cum Kneesworth         |                                       |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006881                               |
| CONDITION:               | Extensive significant problems                               | TREND:                 | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                    |
| OWNER TYPE:              | Commercial company, multiple owners                          | CONTACT:               | David Kenny 01223 582760              |
| SITE NAME:               | Settlement site west of Town's End Farm, Comb                | oerton / Barton        |                                       |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006879                               |
| CONDITION:               | Generally unsatisfactory with major localised problems       | TREND:                 | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:           | No                                    |
| OWNER TYPE:              | Commercial company, multiple owners                          | CONTACT:               | David Kenny 01223 582760              |
| SITE NAME:               | Settlement site by Caudle Corner Farm, Fulbour               | 'n                     |                                       |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006878                               |
| CONDITION:               | Extensive significant problems                               | TREND:                 | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable clipping  | NEW ENTRY?:            | No                                    |
| OWNER TYPE:              | Commercial company   | CONTACT:               | David Kenny 01223 582760              |
| SITE NAME:               | Site revealed by aerial photography west of Whi              | te Hill Farm, Great Sh | nelford                               |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:     | 1006891                               |
| CONDITION:               | Extensive significant problems                               | TREND:                 | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:            | No                                    |
| OWNER TYPE:              | Mixed, multiple owners                                       | CONTACT:               | David Kenny 01223 582760              |
|                          |  |                        |                                       |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH CAMBRIDGESHIRE

| SITE NAME: Causewayed enclosure 900m west of Great Wilbraham parish church, Great Wilbraham |  |                      | , Great Wilbraham        |
|---|--|----------------------|--------------------------|
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1009103                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY?:          | No                       |
| OWNER TYPE:   | Commercial company   | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Henge 220m ESE of Herring's House, Great Wilbra                | aham                 |                          |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1011716                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY?:          | No                       |
| OWNER TYPE:   | Commercial company, multiple owners                            | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Bowl barrow 550m north east of Slip End Farm, Gu               | uilden Morden        |                          |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1017328                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY?:          | No                       |
| OWNER TYPE:   | Commercial company   | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Roman villa 1000yds (910m) north east of Ashwell               | village, Guilden Mo  | rden                     |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1006876                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY?:          | No                       |
| OWNER TYPE:   | Private, multiple owners                                       | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Settlement complex north east of Haslingfield, Has             | lingfield / Grantche | ster                     |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1006867                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY ?:         | No                       |
| OWNER TYPE:   | Commercial company   | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Roman villa site south of Rose Villa, Ickleton                 |                      |                          |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1006872                  |
| CONDITION:  | Generally satisfactory but with significant localised problems | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY ?:         | No                       |
| OWNER TYPE:   | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Bowl barrow 205m SSE of Lodge Cottage, Melbour                 | rn                   |                          |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1011720                  |
| CONDITION:  | Extensive significant problems                                 | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Arable ploughing   | NEW ENTRY?:          | No                       |
| OWNER TYPE:   | Private  | CONTACT:             | David Kenny 01223 582760 |
| SITE NAME:  | Bowl barrow, known as Grinnel Hill, 260m SSE of                | Lodge Cottage, Mel   | bourn                    |
| DESIGNATION:  | Scheduled Monument   | LIST ENTRY NUMBER:   | 1011719                  |
| CONDITION:  | Generally satisfactory but with significant localised problems | TREND:               | Declining                |
| PRINCIPAL VULNERABILITY:  | Animal burrowing - extensive                                   | NEW ENTRY?:          | No                       |
|   | -  |                      | David Kenny 01223 582760 |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH CAMBRIDGESHIRE

| SITE NAME:               | Square barrow 170m north east of Summer House  | e Farm, Melbourn        |                                    |
|--------------------------|--|-------------------------|------------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1020397                            |
| CONDITION:               | Extensive significant problems   | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Five bowl barrows 790m north west of Chain Hou   | ise, part of the Ove    | r round barrow cemetery, Over      |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1019874                            |
| CONDITION:               | Extensive significant problems   | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Commercial company, multiple owners  | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Three bowl barrows 380m south of Brownshill Sta<br>Over                                | unch House, part c      | of the Over round barrow cemetery, |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1019130                            |
| CONDITION:               | Extensive significant problems   | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Commercial company, multiple owners  | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Borough Hill: a large multivallate hillfort, Sawston                                   |                         |                                    |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1009396                            |
| CONDITION:               | Extensive significant problems   | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Commercial company, multiple owners  | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Roman site north of Brown Spinney, Shepreth / Fo                                       | xton                    |                                    |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1006873                            |
| CONDITION:               | Extensive significant problems   | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Arrington Bridge Romano-British site, Shingay cum                                      | wendy / Whaddo          | n                                  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:      | 1006874                            |
| CONDITION:               | Generally unsatisfactory with major localised problems                                 | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:                | David Kenny 01223 582760           |
| SITE NAME:               | Wandlebury Camp: a multivallate hillfort, earlier un formal garden remains, Stapleford | nivallate hillfort, Iro | n Age cemetery and 17th century    |
| DESIGNATION:             | Scheduled Monument, 3 LBs  | LIST ENTRY NUMBER:      | 1009395                            |
| CONDITION:               | Generally satisfactory but with significant localised problems                         | TREND:                  | Declining                          |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth  | NEW ENTRY?:             | No                                 |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:                | David Kenny 01223 582760           |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH CAMBRIDGESHIRE / CENTRAL BEDFORDSHIRE (UA)

| SITE NAME:               | Bell barrow 500m south of Morden Grange Plantat                | ion, Steeple Morde | n                             |
|--------------------------|--|--------------------|-------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1011714                       |
| CONDITION:               | Extensive significant problems                                 | TREND:             | Declining                     |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                            |
| OWNER TYPE:              | Commercial company   | CONTACT:           | David Kenny 01223 582760      |
| SITE NAME:               | Roman settlement south of Chronicle Hills, Whittl              | esford             |                               |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1006794                       |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:             | Declining                     |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                            |
| OWNER TYPE:              | Commercial company   | CONTACT:           | David Kenny 01223 582760      |
| SITE NAME:               | Duxford Airfield, Duxford/Whittlesford                         |                    |                               |
| DESIGNATION:             | Conservation Area  | NEW ENTRY?:        | No                            |
| CONDITION:               | Very bad   | TREND:             | Deteriorating                 |
| VULNERABILITY:           | Medium   | CONTACT:           | Jane Green (LPA) 01954 713164 |
| SITE NAME:               | Gamlingay  |                    |                               |
| DESIGNATION:             | Conservation Area  | NEW ENTRY?:        | No                            |
| CONDITION:               | Poor   | TREND:             | Deteriorating                 |
| VULNERABILITY:           | Medium   | CONTACT:           | Jane Green (LPA) 01954 713164 |
| SITE NAME:               | Papworth Everard   |                    |                               |
| DESIGNATION:             | Conservation Area  | NEW ENTRY?:        | No                            |
| CONDITION:               | Poor   | TREND:             | Deteriorating significantly   |
| VULNERABILITY:           | Medium   | CONTACT:           | Jane Green (LPA) 01954 713164 |
| SITE NAME:               | Papworth Everard - village                                     |                    |                               |
| DESIGNATION:             | Conservation Area  | NEW ENTRY?:        | No                            |
| CONDITION:               | Very bad   | TREND:             | Deteriorating significantly   |
| VULNERABILITY:           | Medium   | CONTACT:           | Jane Green (LPA) 01954 713164 |
| SITE NAME:               | Sawston  |                    |                               |
| DESIGNATION:             | Conservation Area  | NEW ENTRY?:        | No                            |
| CONDITION:               | Very bad   | TREND:             | Deteriorating                 |
| VULNERABILITY:           | Low  | CONTACT:           | Jane Green (LPA) 01954 713164 |

#### **CENTRAL BEDFORDSHIRE (UA)**

| 1       | Res                                    | A     |
|---------|--|-------|
| in the  |  |       |
| E       | a star                                 |       |
|         |  |       |
| STREET, | ······································ |       |
| - TRACE |  | Alter |

| SITE NAME:The Grotto, Woburn Park,<br>WoburnGrotto, 1839, situated approxima<br>north east of Woburn Abbey, on<br>OC18 and early C19 pleasure group<br>been completed. However, the gr<br>delaminated in places. DiscussionsCONDITION:FairOCCUPANCY:N/APRIORITY CATEGORY:C (D)OWNER TYPE:Commercial companyLIST ENTRY NUMBER:III4010 |  |                    |                    |                                 |
|--|--|--------------------|--------------------|---------------------------------|
| DESIGNATION:    Listed Building grade II*, RPG grade I    been completed. However, the gradelaminated in places. Discussions      CONDITION:    Fair      OCCUPANCY:    N/A      PRIORITY CATEGORY:    C (D)      OWNER TYPE:    Commercial company  |  | SITE NAME:         |                    | north east of Woburn Abbey, on  |
| CONDITION:FairOCCUPANCY:N/APRIORITY CATEGORY:C (D)OWNER TYPE:Commercial company  |  | DESIGNATION:       |                    | been completed. However, the g  |
| PRIORITY CATEGORY: C (D)<br>OWNER TYPE: Commercial company   |  | CONDITION:         | Fair               |                                 |
| OWNER TYPE: Commercial company   |  | OCCUPANCY:         | N/A                |                                 |
| Commercial company   |  | PRIORITY CATEGORY: | C (D)              |                                 |
| LIST ENTRY NUMBER: 1114010 Contact: Clare Campbell 01223 5   |  | OWNER TYPE:        | Commercial company |                                 |
|  |  | LIST ENTRY NUMBER: | 1114010            | Contact: Clare Campbell 01223 5 |

nately 200 metres to the n the northern edge of the unds. Repair works have grotto work lining has ns are ongoing.

© Historic England

#### 582738

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / CENTRAL BEDFORDSHIRE (UA)

|                    | SITE NAME:         | Church of St Peter and All<br>Saints, Battlesden | Medieval church of CI3 origins. Little restored. Rubble walls with later brick to both CI8 tower and parapets |
|--------------------|--------------------|--|---|
|                    | DESIGNATION:       | Listed Place of Worship grade I,<br>RPG grade II | (modern). Tower cracked and stonework much decayed.<br>No solution currently agreed.                          |
|                    | CONDITION:         | Poor   |   |
|                    | PRIORITY CATEGORY: | C (C)  |   |
|                    | OWNER TYPE:        | Religious organisation                           |   |
|                    | LIST ENTRY NUMBER: | 1311979  | Contact: John Neale 01223 582719  |
| © Historic England |                    |  |   |

|   | SITE NAME:         | Church of St Mary, Church<br>Street, Dunton | Parish church C14 and C15, reworked 1891 by E<br>Browning. Coursed ironstone rubble and cobbles, with                     |
|---|--------------------|---|---|
| 1 | DESIGNATION:       | Listed Place of Worship grade II*           | ashlar dressings. Tower completely of ashlar. Stonework in poor condition, including decayed tracery to south aisle       |
|   | CONDITION:         | Poor  | windows adjacent to porch and south aisle wall; decayed windows to north aisle; decayed clunch to tower stair;            |
|   | PRIORITY CATEGORY: | C (C)                                       | internal delamination at base of piers due to damp; decay   |
|   | OWNER TYPE:        | Religious organisation                      | to south side chancel, sedilia and low level plaster and high level paint delamination to chancel. Solution to be agreed. |
|   | LIST ENTRY NUMBER: | 4060  | Contact: Clare Campbell 01223 582738  |

© Historic England

|                  | SITE NAME:         | Church of St Mary the Virgin,<br>Church Road, Meppershall | Parish church dating to C12 half rebuilt 1875-6 by Sir<br>Arthur Blomfield. Stonework of coursed ironstone with  |
|------------------|--------------------|---|--|
|                  | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA                  | ashlar dressings and clay tile roofs. Chancel, central tower,<br>north and south transepts, nave, north and south aisles.<br>Decayed clunch corner stones and tracery to the south |
|                  | CONDITION:         | Very bad  | aisle chapel and vestry. Tower in need of repointing. Long-<br>term repair strategy yet to be agreed.  |
|                  | PRIORITY CATEGORY: | A (A)   |  |
|                  | OWNER TYPE:        | Religious organisation                                    |  |
|                  | LIST ENTRY NUMBER: | 1312589   | Contact: John Ette 01223 582711  |
| listoric England |                    |   |  |

© Historic England

| STE NAME:  A ringwork and bailey castle, ring ditch and enclosures east of Brookland Farm, Biggleswade    DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1010115    CONDITION:  Generally unsatisfactory with major localised<br>problems  TREND:  Declining    PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No    OWNER TYPE:  Commercial company  CONTACT:  David Kenny 01223 582760    STE NAME:  Moated site at Ivy Hall, Cranfield  ISTE NAME:  1009592    CONDITION:  Scheduled Monument  LIST ENTRY NUMBER:  1009592    CONDITION:  Generally unsatisfactory with major localised<br>problems  TREND:  Declining    PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No    OWNER TYPE:  Private  CONTACT:  David Kenny 01223 582760    STE NAME:  Dunstable Priory, Dunstable  CONTACT:  David Kenny 01223 582760    STE NAME:  Dunstable Priory, Dunstable  IST ENTRY NUMBER:  1004676    CONDITION:  Generally statisfactory but with significant localised<br>problems  TREND:  Declining    STE NAME:  Dunstable Priory, Dut with significant localised<br>problems  TREND:  Declining    ONTION:  Generally statisfactory but with significant localised<br>problems  TREND:  Declini |   |                                    |                    |                          |  |
|--|---|------------------------------------|--------------------|--------------------------|--|
| CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site at Ivy Hall, CranfieldUST ENTRY NUMBER:1009592Designation:Scheduled MonumentUST ENTRY NUMBER:1009592CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableCONTACT:DecliningOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableUST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningSITE NAME:CollapseNEW ENTRY NUMBER:1004676  | A ringwork and bailey castle, ring ditch and enclosures east of Brookland Farm, Biggleswade |                                    |                    |                          |  |
| CONDITION:problemsProvide and an analysisIndextDecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site at Ivy Hall, CranfieldUST ENTRY NUMBER:1009592Designation:Scheduled MonumentUST ENTRY NUMBER:1009592CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Dunstable Priory, DunstableCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableScheduled Monument, CALIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY:No  | DESIGNATION:  | TION: Scheduled Monument           |                    | 1010115                  |  |
| OWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site at Ivy Hall, CranfieldDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1009592CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Dunstable Priory, DunstableCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableIST ENTRY NUMBER:1004676DESIGNATION:Scheduled Monument, CAIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No  | CONDITION:  |                                    | TREND:             | Declining                |  |
| SITE NAME:Moated site at lvy Hall, CranfieldDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1009592CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableIST ENTRY NUMBER:1004676DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No   | PRINCIPAL VULNERABILITY:  | Arable ploughing                   | NEW ENTRY?:        | No                       |  |
| DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1009592CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableUST ENTRY NUMBER:1004676DESIGNATION:Scheduled Monument, CAUST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No   | OWNER TYPE:   | Commercial company                 | CONTACT:           | David Kenny 01223 582760 |  |
| CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableUST ENTRY NUMBER:1004676DESIGNATION:Scheduled Monument, CAUST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No  | SITE NAME:  | Moated site at Ivy Hall, Cranfield |                    |                          |  |
| CONDITION:problemsIncludeDecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableIST ENTRY NUMBER:1004676DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No  | DESIGNATION:  | Scheduled Monument                 | LIST ENTRY NUMBER: | 1009592                  |  |
| OWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Dunstable Priory, DunstableDESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:PRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No   |   |                                    | TREND:             | Declining                |  |
| SITE NAME:    Dunstable Priory, Dunstable      DESIGNATION:    Scheduled Monument, CA    LIST ENTRY NUMBER:    1004676      CONDITION:    Generally satisfactory but with significant localised problems    TREND:    Declining      PRINCIPAL VULNERABILITY:    Collapse    NEW ENTRY?:    No   | PRINCIPAL VULNERABILITY:  | Arable ploughing                   |                    | No                       |  |
| DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1004676CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:No   | OWNER TYPE: Private   |                                    | CONTACT:           | David Kenny 01223 582760 |  |
| CONDITION:  Generally satisfactory but with significant localised problems  TREND:  Declining    PRINCIPAL VULNERABILITY:  Collapse  NEW ENTRY?:  No   | SITE NAME:  | Dunstable Priory, Dunstable        |                    |                          |  |
| PRINCIPAL VULNERABILITY:  Collapse  NEW ENTRY?:  No  | DESIGNATION:  | Scheduled Monument, CA             | LIST ENTRY NUMBER: | 1004676                  |  |
|  | CONDITION:  |                                    | TREND:             | Declining                |  |
| OWNER TYPE: Local authority CONTACT: David Kenny 01223 582760  | PRINCIPAL VULNERABILITY:  | LITY: Collapse                     |                    | No                       |  |
|  | OWNER TYPE: Local authority CC  |                                    | CONTACT:           | David Kenny 01223 582760 |  |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / CENTRAL BEDFORDSHIRE (UA) / BRAINTREE

| SITE NAME:               | Apsley Bury moated site and fishpond, south of Apsley End, Shillington                                    |                    |                          |  |
|--------------------------|---|--------------------|--------------------------|--|
| DESIGNATION:             | Scheduled Monument, LB grade II   | LIST ENTRY NUMBER: | 1010927                  |  |
| CONDITION:               | Generally satisfactory but with significant localised problems  | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable clipping   | NEW ENTRY?:        | No                       |  |
| OWNER TYPE:              | Private   | CONTACT:           | David Kenny 01223 582760 |  |
| SITE NAME:               | Bowl barrow in Tingley Field Plantation, near Pegs  | don, Shillington   |                          |  |
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER: | 1010369                  |  |
| CONDITION:               | Generally unsatisfactory with major localised problems  | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth   | NEW ENTRY?:        | No                       |  |
| OWNER TYPE:              | Private   | CONTACT:           | David Kenny 01223 582760 |  |
| SITE NAME:               | MME: Totternhoe Castle: a motte and bailey castle, medieval quarries and cultivation terraces, Totternhoe |                    |                          |  |
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER: | 1020772                  |  |
| CONDITION:               | Generally satisfactory but with significant localised problems  | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive   | NEW ENTRY ?:       | No                       |  |
| OWNER TYPE:              | Local authority   | CONTACT:           | David Kenny 01223 582760 |  |
|                          |   |                    |                          |  |

ESSEX

BRAINTREE

|         | SITE NAME:         | Parish Church (dedication<br>unknown), Hall Road, Borley | Grade I listed church on an early manorial site, with Saxon fabric surviving in the nave. The interior has several      |
|---------|--------------------|--|---|
|         | DESIGNATION:       | Listed Place of Worship grade I                          | monuments, and wall paintings are believed to be present below later limewash. The plain tiled roofs are                |
| 1 m     | CONDITION:         | Very bad   | deteriorating; many have slipped, fractured and delaminated, especially on the north side. Daylight is visible          |
|         | PRIORITY CATEGORY: | F (C)  | from inside through the chancel roof. The congregation  |
|         | OWNER TYPE:        | Religious organisation                                   | have received an Heritage Lottery Fund Grant for Places of<br>Worship to re-roof the nave and chancel. The repair stage |
| and the | LIST ENTRY NUMBER: | 1169675  | is now underway.  |
|         |                    |  | Contact: Trudi Hughes 01223 582739  |

© Historic England

|         | SITE NAME:         | Parish Church of All Saints, The<br>Street, Stisted | Parish church of C12 origins, with C13 and C14 additions.<br>Some C19 restoration. A very unusual plan; the tower  |
|---------|--------------------|---|--|
|         | DESIGNATION:       | Listed Place of Worship grade I,<br>CA              | abutting the south side of the nave, leaving the west end<br>an uninterrupted symmetrical composition. Cedar shing<br>to the tower are in poor condition with daylight visible<br>from inside. Masonry of tower buttresses poor, as is the<br>nave roof, with visible decay in the rafter feet and wallpla |
|         | CONDITION:         | Very bad  |  |
|         | PRIORITY CATEGORY: | F (B)   | A Heritage Lottery Fund grant for repairs was accepted   |
|         | OWNER TYPE:        | Religious organisation                              | February 2014. Project in development /delivery stage  |
| England | LIST ENTRY NUMBER: | 1123870   | Contact: Malcolm Starr 01223 582723  |
|         |                    |   |  |

© Historic England

| SITE NAME:               | Circular cropmark at Ferriers Farm, 190m south west of Hill Farm, Bures Hamlet |             |                          |
|--------------------------|--|-------------|--------------------------|
| DESIGNATION:             | Scheduled Monument LIST ENTRY NUMBER: 1010501                                  |             |                          |
| CONDITION:               | Extensive significant problems   | TREND:      | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?: | No                       |
| OWNER TYPE:              | Private, multiple owners   | CONTACT:    | David Kenny 01223 582760 |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BRAINTREE / BRENTWOOD

| SITE NAME:               | Long mortuary enclosure and round barrow 160m south west of Frame Farm, Feering |                     |                                  |  |
|--------------------------|---|---------------------|----------------------------------|--|
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER:  | 1017230                          |  |
| CONDITION:               | Extensive significant problems  | TREND:              | Declining                        |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing  | NEW ENTRY?:         | No                               |  |
| OWNER TYPE:              | Commercial company  | CONTACT:            | David Kenny 01223 582760         |  |
| SITE NAME:               | Roman villa 480m south east of Hill Farm, Gestin                                | gthorpe / Wickham S | St. Paul                         |  |
| DESIGNATION:             | Scheduled Monument  | LIST ENTRY NUMBER:  | 1011806                          |  |
| CONDITION:               | Generally unsatisfactory with major localised problems                          | TREND:              | Declining                        |  |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed  | NEW ENTRY?:         | No                               |  |
| OWNER TYPE:              | Commercial company CONTACT:   |                     | David Kenny 01223 582760         |  |
| SITE NAME:               | Sible Hedingham South (Swan Street), Sible Hedingham                            |                     |                                  |  |
| DESIGNATION:             | Conservation Area, 46 LBs NEW ENTRY?: No  |                     | No                               |  |
| CONDITION:               | Poor TREND: No significan   |                     | No significant change            |  |
| VULNERABILITY:           | High CONTACT: Emma Goodings (LPA  |                     | Emma Goodings (LPA) 01376 552525 |  |
| SITE NAME:               | Silver End  |                     |                                  |  |
| DESIGNATION:             | Conservation Area, 22 LBs NEW ENTRY?: No  |                     | No                               |  |
| CONDITION:               | Poor TREND: No significant change   |                     | No significant change            |  |
| VULNERABILITY:           | High  | CONTACT:            | Emma Goodings (LPA) 01376 552525 |  |
|                          |   |                     |                                  |  |

#### BRENTWOOD

© Historic England

|  | SITE NAME:         | Chantry Chapel and<br>Mausoleum, Thorndon Park  | Mid C19 private Roman Catholic chapel and mausoleum of<br>the Petre family, no longer used for worship. Designed by   |
|--|--------------------|---|---|
|  | DESIGNATION:       | Listed Building grade II*, RPG<br>grade II*, CA | William Wardell and located south west of Thorndon Hall<br>(now flats). The chapel has a leaking roof and suffers from<br>extensive stone decay. A grant aided programme of project |
|  | CONDITION:         | Poor  | development, investigation and subsequent repair work i nearing completion.   |
|  | OCCUPANCY:         | Vacant/not in use                               | hearing completion.   |
|  | PRIORITY CATEGORY: | F (F)   |   |
|  | OWNER TYPE:        | Private   |   |
|  | LIST ENTRY NUMBER: | 1293260   | Contact: Malcolm Starr 01223 582723   |



© Historic England Archive

| SITE | NAME:           | Thoby Priory ruins, Thoby Lane,<br>Mountnessing    | Ruined remains of Augustinian Priory, founded circa I comprising south wall of presbytery and south nave ar   |  |  |
|------|-----------------|--|---|--|--|
| DESI | IGNATION:       | Scheduled Monument and Listed<br>Building grade II | The Priory site was subject to an archaeological evaluation<br>in 2002-3. In June 2014 the local authority and Historic<br>England engaged in pre-application discussions regarding |  |  |
| CON  | NDITION:        | Poor   | development in the vicinity of the monument which ma<br>provide opportunities for improved monument   |  |  |
| 000  | CUPANCY:        | Part occupied/part in use                          | management, via a Section 106 agreement. These  |  |  |
| PRIC | ORITY CATEGORY: | A (A)  | discussions are continuing.   |  |  |
| ow   | NER TYPE:       | Private  |   |  |  |
| LIST | ENTRY NUMBER:   | 1005560 and 1293183                                | Contact: Deborah Priddy 01223 582720  |  |  |

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BRENTWOOD / CHELMSFORD / COLCHESTER

|  | SITE NAME:         | Church of St Paul, Mores Lane,<br>Brentwood | Parish church 1878, by EC Lee. Flint walls with stone dressings. Leaking iron gutters on stone string courses               |
|--|--------------------|---|---|
|  | DESIGNATION:       | Listed Place of Worship grade II            | starting to cause failure in stone. Evidence of active leakage.<br>Much Bath stone in evidence, some of which appears to be |
|  | CONDITION:         | Poor  | of poor quality and particularly susceptible to decay due to excess moisture. Long term strategy to be agreed.              |
|  | PRIORITY CATEGORY: | C (C)                                       |   |
|  | OWNER TYPE:        | Religious organisation                      |   |
|  | LIST ENTRY NUMBER: | 1207545                                     | Contact: Trudi Hughes 01223 582739  |
|  |                    |   |   |

© Historic England

#### CHELMSFORD Church of St Michael, The SITE NAME: Street, Roxwell Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1235784

St Michael's Roxwell is a medieval church of probable C14 date, but much restored in the C19. Flint rubble with stone dressings, tiled roofs, timber porch and bell turret, shingled spire. The tiling of the roofs has loosened and tiles are slipping. Solution yet to be agreed.

Contact: John Neale 01223 582719

© Historic England

| SITE NAME:               | Settlement site at Ash Tree Corner, Little Waltham |                    |                                  |  |  |
|--------------------------|--|--------------------|----------------------------------|--|--|
| DESIGNATION:             | Scheduled Monument                                 | LIST ENTRY NUMBER: | 1002140                          |  |  |
| CONDITION:               | Extensive significant problems                     | TREND:             | Declining                        |  |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                   | NEW ENTRY?:        | No                               |  |  |
| OWNER TYPE:              | Commercial company                                 | CONTACT:           | David Kenny 01223 582760         |  |  |
| SITE NAME:               | Baddow Road  |                    |                                  |  |  |
| DESIGNATION:             | Conservation Area, 10 LBs, SM                      | NEW ENTRY?:        | No                               |  |  |
| CONDITION:               | Very bad   | TREND:             | No significant change            |  |  |
| VULNERABILITY:           | Low  | CONTACT:           | Michael Hurst (LPA) 01245 606739 |  |  |
| SITE NAME:               | Moulsham Street                                    |                    |                                  |  |  |
| DESIGNATION:             | Conservation Area, 16 LBs                          | NEW ENTRY?:        | No                               |  |  |
| CONDITION:               | Very bad   | TREND:             | Improving                        |  |  |
| VULNERABILITY:           | Low  | CONTACT:           | Michael Hurst (LPA) 01245 606739 |  |  |
| SITE NAME:               | West End   |                    |                                  |  |  |
| DESIGNATION:             | Conservation Area, 3 LBs                           | NEW ENTRY?:        | No                               |  |  |
| CONDITION:               | Very bad   | TREND:             | Unknown                          |  |  |
| VULNERABILITY:           | Low  | CONTACT:           | Michael Hurst (LPA) 01245 606739 |  |  |
|                          |  |                    |                                  |  |  |

## COLCHESTER

|            | A MARINE |    |  |
|------------|----------|----|--|
| <b>F</b> h | TR       |    |  |
|            |          | ha |  |

| EC       |                    |   |   |  |  |
|----------|--------------------|---|---|--|--|
|          | LIST ENTRY NUMBER: | 1002144 and 1110898                                       | Contact: David Kenny 01223 582760   |  |  |
| ti kakad | OWNER TYPE:        | Private   |   |  |  |
| Phone    | PRIORITY CATEGORY: | C (C)   |   |  |  |
| 161      | OCCUPANCY:         | N/A   |   |  |  |
|          | CONDITION:         | Very bad  | scheme has been agreed.   |  |  |
|          | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II*       | the unconsolidated flint rubble walling is at risk. There is<br>currently no public access to the site. Conservation<br>Management Plan has been completed, but no repair |  |  |
| ha       | SITE NAME:         | Ruins of Church of St Mary,<br>North of Birch Hall, Birch | Small Norman church, no longer used for worship, C12<br>Roofless ruin with some structural problems. Principally  |  |  |
|          |                    |   |   |  |  |

## PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / COLCHESTER

| CONDITION              | SITE NAME:         | Municipal Water Tower<br>"Jumbo", Balkerne Passage,<br>Colchester | Monumental water tower, C19, decommissioned in the 1980s. Redundant building and local landmark. No action/strategy identified or agreed for full repair but |
|------------------------|--------------------|---|--|
|                        | DESIGNATION:       | Listed Building grade II*, CA                                     | discussions about urgent works are ongoing.  |
|                        | CONDITION:         | Poor  |  |
|                        | OCCUPANCY:         | Vacant/not in use   |  |
| Contraction of the     | PRIORITY CATEGORY: | C (C)   |  |
|                        | OWNER TYPE:        | Commercial company  |  |
| © Essex County Council | LIST ENTRY NUMBER: | 1123669   | Contact: John Neale 01223 582719   |





|  | SITE NAME:         | Church of St Botolph, St<br>Botolph's Street, Colchester | Church of neo-Norman design in white brick with slate<br>roofs by William Mason of Ipswich, which takes its cue  |
|--|--------------------|--|--|
|  | DESIGNATION:       | Listed Place of Worship grade II,<br>SM, CA              | from the priory ruins to the north. Dating from 1835-37. It<br>has a four-stage gabled west portal between a pair of<br>turrets with pyramidal cappings. High level stonework on   |
|  | CONDITION:         | Poor   | the tower is in poor condition with vegetation in joints.<br>The aisle roofs are in poor condition with a substantial<br>number of slipped slates. Gutters and drainpipes are in   |
|  | PRIORITY CATEGORY: | C (C)  |  |
|  | OWNER TYPE:        | Religious organisation                                   | condition. The overall condition is poor. No a state of |
|  | LIST ENTRY NUMBER: | 1123508  | Contact: Sheila Stones 01223 582716  |
|  |                    |  |  |

© Historic England

| SITE NAME:                                | Small multivallate hillfort known as Pitchbury Ramparts, Great Horkesley   |                         |                                |
|---|--|-------------------------|--------------------------------|
| DESIGNATION:                              | Scheduled Monument   | LIST ENTRY NUMBER:      | 1019959                        |
| CONDITION:                                | Extensive significant problems   | TREND:                  | Declining                      |
| PRINCIPAL VULNERABILITY:                  | Arable ploughing   | NEW ENTRY?:             | No                             |
| OWNER TYPE: Private, multiple owners      |  | CONTACT:                | David Kenny 01223 582760       |
| SITE NAME:                                | Roman villa 450m south of Warren's Farm, Great T   | ey                      |                                |
| DESIGNATION:                              | Scheduled Monument   | LIST ENTRY NUMBER:      | 1013516                        |
| CONDITION:                                | Extensive significant problems   | TREND:                  | Declining                      |
|   |  |                         |                                |
| PRINCIPAL VULNERABILITY:                  | Arable ploughing   | NEW ENTRY?:             | No                             |
| PRINCIPAL VULNERABILITY:                  | Arable ploughing<br>Commercial company   | NEW ENTRY?:<br>CONTACT: | No<br>David Kenny 01223 582760 |
|   | 1 0 0  |                         |                                |
| OWNER TYPE:                               | Commercial company   |                         |                                |
| OWNER TYPE:                               | Commercial company<br>Remains of St Mary the Virgin's Church, Virley   | CONTACT:                | David Kenny 01223 582760       |
| OWNER TYPE:<br>SITE NAME:<br>DESIGNATION: | Commercial company<br>Remains of St Mary the Virgin's Church, Virley<br>Scheduled Monument, LB grade II<br>Generally unsatisfactory with major localised | CONTACT:                | David Kenny 01223 582760       |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

## HERITAGE AT RISK 2015 / EAST OF ENGLAND / COLCHESTER / EPPING FOREST

| SITE NAME:     | Birch                          |              |   |
|----------------|--------------------------------|--------------|---|
| DESIGNATION:   | Conservation Area, 6 LBs       | NEW ENTRY?:  | No  |
| CONDITION:     | Very bad                       | TREND:       | Unknown                                   |
| VULNERABILITY: | Medium                         | CONTACT:     | Libby Kirkby-Taylor (LPA) 01206<br>506374 |
| SITE NAME:     | Distillery Pond                |              |   |
| DESIGNATION:   | Conservation Area, LB grade II | NEW ENTRY ?: | No  |
| CONDITION:     | Very bad                       | TREND:       | No significant change                     |
| VULNERABILITY: | Medium                         | CONTACT:     | Libby Kirkby-Taylor (LPA) 01206<br>506374 |
|                |                                |              |   |
| SITE NAME:     | Hythe                          |              |   |
| DESIGNATION:   | Conservation Area, 15 LBs      | NEW ENTRY?:  | No  |
| CONDITION:     | Very bad                       | TREND:       | Deteriorating                             |
| VULNERABILITY: | Medium                         | CONTACT:     | Libby Kirkby-Taylor (LPA) 01206<br>506374 |
|                |                                |              |   |

## EPPING FOREST

© Histor

|   | SITE NAME:   | Latton Priory, London Road,<br>North Weald Bassett   | Remains of C12 Augustinian monastery. Although doors missing; the barn is in use and for occasional church |
|---|--|--|--|
|   | DESIGNATION: Scheduled Monument and Listed<br>Building grade II*, LB grade II timber framing and in pa | services. Almost all of roofs leak; gaps in weatherboard<br>cladding to walls all of which is putting at risk interior<br>timber framing and in particular, important C13 carved |  |
| CONDITION:  Poor    OCCUPANCY:  Part occupied/part in use | CONDITION:   | Poor   | stonework. Repair work commenced Summer 2015.  |
|   |  |  |  |
|   | PRIORITY CATEGORY:   | F (A)  |  |
|   | OWNER TYPE:  | Private  |  |
| oric England  | LIST ENTRY NUMBER:   | 1017386 and 1111392  | Contact: Trudi Hughes 01223 582739   |

|   | SITE NAME:         | Essex Redoubt at Ongar Radio<br>Station, North Weald Bassett /<br>Bobbingworth | Late C19 redoubt consisting of early concrete structures<br>and associated earthworks. Buildings at risk from failure of<br>concrete and vandalism. Discussions with the owners and |
|---|--------------------|--|---|
| A STATE OF  | DESIGNATION:       | Scheduled Monument   | local authority currently centre on proposals to commission a Conservation Management Plan for beneficial   |
| A REALIZED AND AND AND AND AND AND AND AND AND AN | CONDITION:         | Poor   | re-use of the site as an outdoor activity centre in the context of local development proposals. The discussions   |
|   | OCCUPANCY:         | Vacant/not in use  | have not agreed a scheme.   |
|   | PRIORITY CATEGORY: | C (C)  |   |
|   | OWNER TYPE:        | Commercial company   |   |
| © Historic England                                | LIST ENTRY NUMBER: | 1018456  | Contact: Deborah Priddy 01223 582720  |
|   |                    |  |   |



|        |                    | 1010150  | Contact. Deboran mudy 01225 302720  |
|--------|--------------------|--|---|
|        | SITE NAME:         | Littlebury Farmhouse, Romford<br>Road, Stanford Rivers | Timber-framed house of c1540 and earlier. A lean-to roof over the single storey is not watertight and is in poor      |
| -      | DESIGNATION:       | Listed Building grade II*                              | condition. The timber frame is currently protected by ply sheeting. The building remains unoccupied and its condition |
| -      | CONDITION:         | Poor   | slowly deteriorating. Discussions with owner ongoing. No action/strategy identified or agreed.                        |
|        | OCCUPANCY:         | Vacant/not in use                                      |   |
|        | PRIORITY CATEGORY: | C (C)  |   |
| No. Ca | OWNER TYPE:        | Private  |   |
|        | LIST ENTRY NUMBER: | 1306771  | Contact: Sheila Stones 01223 582716   |

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / EPPING FOREST

| SITE NAME:         | Grand Magazine, Waltham<br>Abbey Royal Gunpowder Mills,<br>Waltham Abbey      | A rectangular, barrel-vaulted brick structure with a smaller<br>barrel-vaulted west "transept". Masonry has collapsed and<br>there is extensive vegetation growth. Cracking is evident |
|--------------------|---|--|
| DESIGNATION:       | IGNATION: Scheduled Monument, 2 LBs, vault and extensive moisture in          | throughout the structure, with flattening to the head of the<br>vault and extensive moisture ingress. Historic England is in<br>discussion with owners over funding and maintenance of |
| CONDITION:         | Poor  | the whole site and a programme of tree clearance around the structure has been completed.  |
| OCCUPANCY:         | Vacant/not in use   | the structure has been completed.  |
| PRIORITY CATEGORY: | E (C)   |  |
| OWNER TYPE:        | Charity (heritage)  |  |
| LIST ENTRY NUMBER: | 1016618   | Contact: Deborah Priddy 01223 582720   |
|                    | DESIGNATION:<br>CONDITION:<br>OCCUPANCY:<br>PRIORITY CATEGORY:<br>OWNER TYPE: | Abbey Royal Gunpowder Mills,<br>Waltham AbbeyDESIGNATION:Scheduled Monument, 2 LBs,<br>CACONDITION:PoorOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:E (C)OWNER TYPE:Charity (heritage) |



© Histo

|     | SITE NAME:         | Quinan Stove, Waltham Abbey<br>Royal Gunpowder Mills,<br>Waltham Abbey | A technologically innovative building of 1935, 18 bays in<br>length with steel hooped frames and longitudinal purlins.<br>There is extensive evidence of steelwork corrosion and the |
|-----|--------------------|--|--|
|     | DESIGNATION:       | Scheduled Monument, 2 LBs,<br>CA                                       | roof and windows are deteriorating. A programme of tree<br>clearance around the building has been agreed to prevent<br>damage. Historic England grant-aided repair works will        |
|     | CONDITION:         | Poor   | commence in summer 2015.   |
| 1-2 | OCCUPANCY:         | Vacant/not in use  |  |
|     | PRIORITY CATEGORY: | D (C)  |  |
|     | OWNER TYPE:        | Charity (heritage)   |  |
|     | LIST ENTRY NUMBER: | 1016618  | Contact: Deborah Priddy 01223 582720   |
|     |                    |  |  |



|  | SITE NAME:         | Church of St Nicholas,<br>Willingale Road, Fyfield | C12 church, central tower incorporating re-used Roman materials, but displaying problems with eroded quoins and |
|--|--------------------|--|---|
|  | DESIGNATION:       | Listed Place of Worship grade II*                  | open joints. Solution to be agreed.   |
|  | CONDITION:         | Poor   |   |
|  | PRIORITY CATEGORY: | A (A)  |   |
|  | OWNER TYPE:        | Religious organisation                             |   |
|  | LIST ENTRY NUMBER: | 1337250  | Contact: Malcolm Starr 01223 582723   |
|  |                    |  |   |

© Historic England

© Historic England



| SITE NAME:         | Church of St Mary the Virgin,<br>The Street, High Ongar | A largely mid-C19 church with some medieval features surviving internally. Nave and chancel roofs show signs of   |
|--------------------|---|---|
| DESIGNATION:       | Listed Place of Worship grade I,<br>CA                  | batten failure and ongoing tile losses. Patching has been<br>completed using concrete plain tiles to rear of tower, on<br>chancel verge and elsewhere. Probable batten and tile |
| CONDITION:         | Poor  | fixing failure resulting in continuing losses of tiles. Nave and<br>chancel require re-roofing. Church has received a Listed  |
| PRIORITY CATEGORY: | B (A)   | Places of Worship Roof Repair grant to re-roof the nave   |
| OWNER TYPE:        | Religious organisation                                  | and chancel and works are expected to commence summer 2015.   |
| LIST ENTRY NUMBER: | 302   | Contact: Trudi Hughes 01223 582739  |
|                    |   | -   |

© Historic England

|     | SITE NAME:         | Parish Church of St Christopher<br>Willingale Doe, Village Street,<br>Willingale | C14 and C15 church with south aisle added and general restoration in C19, which included extensive cementitious repointing. This has accelerated the erosion of the |
|-----|--------------------|--|---|
|     | DESIGNATION:       | Listed Place of Worship grade II*  | medieval windows, tower quoins and even some of the C19 limestone replacements. There is a risk of local  |
|     | CONDITION:         | Poor   | collapse if the tower quoins are not repaired. Grant for<br>Places of Worship offered in 2013 and repair project  |
| ,11 | PRIORITY CATEGORY: | F (B)  | underway. Listed Places of Worship Roof Repair Fund   |
|     | OWNER TYPE:        | Religious organisation   | grant confirmed March 2015. All repair works scheduled for completion by spring 2016.   |
|     | LIST ENTRY NUMBER: | 1111257  | Contact: Malcolm Starr 01223 582723   |

© Historic England

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / EPPING FOREST / HARLOW / MALDON

| SITE NAME:                 | A London mobilisation centre known as the North  | Weald Redoubt, N   | North Weald Bassett / Bobbingworth |
|----------------------------|--|--------------------|------------------------------------|
| DESIGNATION:               | Scheduled Monument   | LIST ENTRY NUMBER: | 1018456                            |
| CONDITION:                 | Extensive significant problems   | TREND:             | Declining                          |
| PRINCIPAL VULNERABILITY:   | Vandalism  | NEW ENTRY?:        | No                                 |
| OWNER TYPE:                | Commercial company, multiple owners  | CONTACT:           | Deborah Priddy 01223 582720        |
|                            |  |                    |                                    |
| SITE NAME:                 | Waltham Abbey Royal Gunpowder Factory, Walth   | am Abbey           |                                    |
| SITE NAME:<br>DESIGNATION: | Waltham Abbey Royal Gunpowder Factory, Walth<br>Scheduled Monument, 2 LBs, CA          | am Abbey           | 1016618                            |
|                            |  | ,                  | 1016618<br>Declining               |
| DESIGNATION:               | Scheduled Monument, 2 LBs, CA<br>Generally satisfactory but with significant localised | LIST ENTRY NUMBER: |                                    |

## HARLOW



|   | SITE NAME:         | Kingsmoor House, Paringdon<br>Road | This stuccoed<br>C18 house. It    |
|---|--------------------|------------------------------------|-----------------------------------|
|   | DESIGNATION:       | Listed Building grade II*          | window and a elegant red br       |
|   | CONDITION:         | Very bad                           | undergoing co<br>change of owr    |
|   | OCCUPANCY:         | Vacant/not in use                  | problems resu                     |
|   | PRIORITY CATEGORY: | A (New entry)                      | ventilation tha<br>ceased subject |
|   | OWNER TYPE:        | Private                            | authority.                        |
| - | LIST ENTRY NUMBER: | 1337043                            | Contact: Sheil                    |

d two storey building is a late C19 rebuild of a has a parapet extending round a compassed a peg-tiled roof surmounted by two tall rick chimneys. The building is currently onversion to apartments under a recent nership. It suffers from serious chronic ulting from water penetration and inadequate at led to dry rot. Conversion works have ct to enforcement action from local planning

Contact: Sheila Stones 01223 582716

| SITE NAME:               | Roman villa 500m north east of Harlowbury |                    |                          |
|--------------------------|---|--------------------|--------------------------|
| DESIGNATION:             | Scheduled Monument                        | LIST ENTRY NUMBER: | 1014738                  |
| CONDITION:               | Extensive significant problems            | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                          | NEW ENTRY?:        | No                       |
| OWNER TYPE:              | Mixed, multiple owners                    | CONTACT:           | David Kenny 01223 582760 |

## MALDON

© Historic England

| A A | SITE NAME:         | Creeksea Place, Ferry Road,<br>Creeksea, Burnham-on-Crouch | Former Elizabethan courtyard house completed in 1569,<br>but the south range was demolished in 1740 and the east     |
|-----|--------------------|--|--|
|     | DESIGNATION:       | Listed Building grade II*                                  | range rebuilt in the C19. The house suffers from major structural problems and is extensively propped internally.    |
|     | CONDITION:         | Very bad   | In recent years the owners have stabilised the building,<br>brought parts into use and carried out some repairs, but |
|     | OCCUPANCY:         | Part occupied/part in use                                  | comprehensive works are still required. The condition of   |
|     | PRIORITY CATEGORY: | C (C)  | the garden walls and the main roofs are of particular concern. Historic England has offered a grant towards          |
|     | OWNER TYPE:        | Private  | project development; consultants now appointed and working on a scheme.  |
|     | LIST ENTRY NUMBER: | 1123776  | Contact: Malcolm Starr 01223 582723  |

© Historic England



| SITE NAME:         | Former Stow Maries Airfield,<br>Flambirds Farm, Stow Maries,<br>Cold Norton | L<br>E<br>a |
|--------------------|---|-------------|
| DESIGNATION:       | Listed Building grade II*, CA   | i<br>s      |
| CONDITION:         | Very bad  | f           |
| OCCUPANCY:         | Part occupied/part in use   | N           |
| PRIORITY CATEGORY: | B (A)   | a<br>f      |
| OWNER TYPE:        | Private   |             |
| LIST ENTRY NUMBER: | 1406155   | (           |
|                    |   |             |

Listed at grade II\*, the site comprises of 24 operations buildings of a former World War One Royal Flying Corps airfield; the largest known surviving group of this kind. The individual buildings are rare survivors in themselves. The site has been acquired on behalf of the nation with funds from National Heritage Memorial Fund, Historic England and Local Authorities. Awards have also been made by WREN and Historic England to repair four of the buildings at risk and a large additional award has also been secured from the Government to further safeguard the site.

Contact: John Ette 01223 582711

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / MALDON / TENDRING

| SITE NAME:                 | Mill Mound: a bowl barrow 300m south west of E   | Beckingham Hall, Tol                        | leshunt Major                         |
|----------------------------|--|---|---------------------------------------|
| DESIGNATION:               | Scheduled Monument   | LIST ENTRY NUMBER:                          | 1009449                               |
| CONDITION:                 | Generally satisfactory but with minor localised problems                                     | TREND:                                      | Declining                             |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY?:                                 | No                                    |
| OWNER TYPE:                | Mixed, multiple owners   | CONTACT:                                    | David Kenny 01223 582760              |
|                            |  |   |                                       |
| SITE NAME:                 | Woodham Walter Hall: an early C16 house and i  | its associated garden                       | earthworks, Woodham Walter            |
| SITE NAME:<br>DESIGNATION: | Woodham Walter Hall: an early C16 house and i<br>Scheduled Monument, LB grade II             | its associated garden<br>LIST ENTRY NUMBER: | earthworks, Woodham Walter<br>1021442 |
|                            | ,  |   |                                       |
| DESIGNATION:               | Scheduled Monument, LB grade II<br>Generally unsatisfactory with major localised             | LIST ENTRY NUMBER:                          | 1021442                               |
| DESIGNATION:<br>CONDITION: | Scheduled Monument, LB grade II<br>Generally unsatisfactory with major localised<br>problems | LIST ENTRY NUMBER:                          | 1021442<br>Declining                  |

#### ... TEND

© Histor

| IDRING        |                    |  |   |
|---------------|--------------------|--|---|
|               | SITE NAME:         | Martello Tower "D", 450<br>metres south-south-west of<br>Clubhouse, Clacton Golf<br>Course, Clacton on Sea         | One of 29 original Martello towers built along the east<br>coast, against the threat of French invasion. Built between<br>1808-12. Sold in 1904 and absorbed into a new golf<br>course. The forward battery has been lost in 1980s during |
|               | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II   | construction of new sea defences. Suffers from water<br>ingress and loss of render. No action/strategy identified or<br>agreed.   |
| MATHINE T     | CONDITION:         | Poor   | -   |
|               | OCCUPANCY:         | Vacant/not in use  |   |
| oric England  | PRIORITY CATEGORY: | C (C)  |   |
| Sine England  | OWNER TYPE:        | Private  |   |
|               | LIST ENTRY NUMBER: | 1016553 and 1111524  | Contact: Deborah Priddy 01223 582720  |
| a may         | SITE NAME:         | Martello Tower "E", 300 metres<br>south west of junction of<br>Marine Parade West and Wash<br>Lane, Clacton on Sea | One of 29 original Martello towers along the east coast<br>built between 1808-12, against the threat of French<br>invasion. The forward battery was destroyed in 1819 and it<br>contains a large water tank, inserted after 1935 when it  |
| in the second | DESIGNATION:       | Scheduled Monument and Listed  | became part of Butlins holiday camp. Now sealed up with only access by ladder to first floor. Suffers from water  |

© Historic England

|  | SITE NAME:         | Martello Tower "E", 300 metres<br>south west of junction of<br>Marine Parade West and Wash<br>Lane, Clacton on Sea | One of 29 original Martello towers along the east coast<br>built between 1808-12, against the threat of French<br>invasion. The forward battery was destroyed in 1819 and it<br>contains a large water tank, inserted after 1935 when it |
|--|--------------------|--|--|
|  | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II   | became part of Butlins holiday camp. Now sealed up with<br>only access by ladder to first floor. Suffers from water<br>ingress and loss of render. Discussions with Tendring   |
|  | CONDITION:         | Poor   | District Council on a repair scheme in 2014 but there has been no further recent development.  |
|  | OCCUPANCY:         | Vacant/not in use  |  |
|  | PRIORITY CATEGORY: | C (C)  |  |
|  | OWNER TYPE:        | Local authority  |  |
|  | LIST ENTRY NUMBER: | 1016554 and 1337150  | Contact: Deborah Priddy 01223 582720   |



SITE NAME: Spring Valley Mill, Spring Valley C18 watermill, white weatherboarded over painted brick base. Beam engine circa 1873 now gone. Mill disused since Lane, Ardleigh 1930s. Machinery complete. Road elevation and lucam DESIGNATION: Listed Building grade II\* remain scaffolded. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1112053 Contact: Sheila Stones 01223 582716

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument

- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / TENDRING

|     | SITE NAME:         | Naze Tower, the Naze, Frinton and Walton | Built in 1720, this 86ft navigational tower was re-pointed in sand and cement during the 1970s. This resulted in      |
|-----|--------------------|--|---|
|     | DESIGNATION:       | Listed Building grade II*                | excessive damp problems internally, putting its continued use as an art gallery at risk. The roof structure, also     |
|     | CONDITION:         | Poor                                     | insufficient for the number of visitors to the viewing platform, is cracking significantly, and allowing considerable |
| •   | OCCUPANCY:         | Occupied/in use                          | water ingress. Severe structural cracking is also apparent  |
|     | PRIORITY CATEGORY: | F (New entry)                            | where opening up was carried out to install radar<br>equipment during WW2, and subsequently filled in with            |
|     | OWNER TYPE:        | Private                                  | brick and sand and cement mortar. Historic England grant aided repairs are underway.                                  |
| ind | LIST ENTRY NUMBER: | 1165846                                  | Contact: Claire Fidler 01223 582735   |



© Historic England

© Historic England

|         | SITE NAME:         | Martello Tower "K", Kirby<br>Road, Walton on the Naze,<br>Frinton and Walton | Martello tower, C19. Some internal alteration and problems arising from water ingress. Pre-applications discussions for domestic conversion commenced May |
|---------|--------------------|--|---|
|         | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II                           | 2014. Structural investigations have been undertaken and<br>the principles of proposed domestic conversion have been<br>agreed with Historic England.     |
|         | CONDITION:         | Poor   | -   |
| Citra C | OCCUPANCY:         | Vacant/not in use  |   |
|         | PRIORITY CATEGORY: | D (C)  |   |
|         | OWNER TYPE:        | Private  |   |
|         | LIST ENTRY NUMBER: | 1016787 and 1111504  | Contact: Deborah Priddy 01223 582720  |



© Historic England Archive



© Historic England

|  | SITE NAME:         | Beacon Hill Fort, Harwich      |
|--|--------------------|--------------------------------|
|  | DESIGNATION:       | Scheduled Monument, part in CA |
|  | CONDITION:         | Poor                           |
|  | OCCUPANCY:         | N/A                            |
|  | PRIORITY CATEGORY: | C (C)                          |
|  | OWNER TYPE:        | Mixed, multiple owners         |
|  |                    |                                |

LIST ENTRY NUMBER: 1018958

SITE NAME: Remains of an Augustinian priory founded before 1127 and St Osyth's Priory, St. Osyth post-Dissolution mansion incorporating monastic remains. Scheduled Monument and Listed The site comprises a number of buildings including the main Buildings - 7 grade I; 2 grade II\*; 6 grade II, 3 LBs, part in RPG house, a gatehouse, Darcy Tower and various other DESIGNATION: buildings and standing remains, most in need of major grade II, CA repairs. The Darcy Tower (pictured) remains scaffolded. The "ruined range" was repaired by Historic England in CONDITION: Poor 2013-2015. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private 1002193 and 1111495; Contact: John Neale 01223 582719 1308972; 1337158; 1146545;

over potential new uses.

Contact: Deborah Priddy 01223 582720

LIST ENTRY NUMBER:

## ||||496; ||||460; ||||462; 1111466; 1111467

1166377; 1337159; 1337160;

||663|0; |||1465; |||1468;

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but  $\ \ F$  not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

Ruined coastal artillery fortification of late C19; refortified

concrete, water ingress and vandalism. Monument is in split ownership. Historic England continues to liaise with the Local Authority, private owners and interested third parties

during the two World Wars. Fabric at risk from failure of

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG SM
- ÍΙΑ
- Unitary Authority World Heritage Site WHS

## HERITAGE AT RISK 2015 / EAST OF ENGLAND / TENDRING

|         | SITE NAME:         | Church of St Michael, The<br>Street, Frinton and Walton | A substantial late medieval church of flint and stone rubble,<br>much restored in the C19. The building suffers from   |
|---------|--------------------|---|--|
|         | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA                | subsidence at the east end of the chancel, where recent<br>repairs have failed, resulting in substantial cracks re-<br>appearing in the walls and at the junction of the chancel |
|         | CONDITION:         | Poor  | roof and the east gable. Structural movement continues at the east end of the church, with previously repaired areas   |
|         | PRIORITY CATEGORY: | A (A)   | cracking again. Long-term solution to be agreed.   |
|         | OWNER TYPE:        | Religious organisation                                  |  |
|         | LIST ENTRY NUMBER: | 500   | Contact: Malcolm Starr 01223 582723  |
| England |                    |   |  |

© Historic Er



|            | SITE NAME:         | Church of St George, Badley<br>Hall Road, Great Bromley | Parish church, dating from the C14 and C15, featuring double hammerbeam nave roof with surviving original     |  |  |
|------------|--------------------|---|---|--|--|
| 4          | DESIGNATION:       | Listed Place of Worship grade I                         | medieval polychrome decoration. Nave clerestory flushwork and windows repaired in 2012 with a Historic        |  |  |
| A          | CONDITION:         | Very bad  | England/Heritage Lottery Fund grant. A further Heritage<br>Lottery Fund Grant for Places of Worship grant was |  |  |
|            | PRIORITY CATEGORY: | B (A)   | offered in 2014. Development stage successfully completed   |  |  |
|            | OWNER TYPE:        | Religious organisation                                  | with repair phase due to comence summer 2015.   |  |  |
| Companys ( | LIST ENTRY NUMBER: | 1337189   | Contact: Malcolm Starr 01223 582723   |  |  |

© Historic England

| SITE NAME:               | Crop mark site south of Ardleigh, Ardleigh        |                            |                                  |
|--------------------------|---|----------------------------|----------------------------------|
| DESIGNATION:             | Scheduled Monument                                | LIST ENTRY NUMBER:         | 1002146                          |
| CONDITION:               | Extensive significant problems                    | TREND:                     | Declining                        |
| PRINCIPAL VULNERABILITY: | Arable ploughing                                  | NEW ENTRY ?:               | No                               |
| OWNER TYPE:              | Mixed, multiple owners                            | CONTACT:                   | David Kenny 01223 582760         |
| SITE NAME:               | Beacon Hill Fort: a late 19th and 20th century co | oastal artillery fortifica | ation, Harwich                   |
| DESIGNATION:             | Scheduled Monument, part in CA                    | LIST ENTRY NUMBER:         | 1018958                          |
| CONDITION:               | Extensive significant problems                    | TREND:                     | Declining                        |
| PRINCIPAL VULNERABILITY: | Deterioration - in need of management             | NEW ENTRY ?:               | No                               |
| OWNER TYPE:              | Mixed, multiple owners                            | CONTACT:                   | Deborah Priddy 01223 582720      |
| SITE NAME:               | Clacton Seafront, Clacton-on-Sea                  |                            |                                  |
| DESIGNATION:             | Conservation Area, 4 LBs, RPG grade II, SM        | NEW ENTRY?:                | No                               |
| CONDITION:               | Very bad  | TREND:                     | Improving                        |
| VULNERABILITY:           | Low   | CONTACT:                   | Philip Hornby (LPA) 01255 686170 |
| SITE NAME:               | Dovercourt, Harwich                               |                            |                                  |
| DESIGNATION:             | Conservation Area, 6 LBs, part in SM              | NEW ENTRY?:                | No                               |
| CONDITION:               | Very bad  | TREND:                     | Deteriorating significantly      |
| VULNERABILITY:           | Low   | CONTACT:                   | Philip Hornby (LPA) 01255 686170 |
| site name:               | St Osyth, St. Osyth                               |                            |                                  |
| DESIGNATION:             | Conservation Area, 62 LBs, RPG grade I, SM        | NEW ENTRY?:                | No                               |
| CONDITION:               | Poor  | TREND:                     | Deteriorating                    |
| VULNERABILITY:           | Low   | CONTACT:                   | Philip Hornby (LPA) 01255 686170 |
| SITE NAME:               | Thorpe-le-Soken Station and Maltings, Thorpe-le   | e-Soken                    |                                  |
| DESIGNATION:             | Conservation Area, LB grade II                    | NEW ENTRY?:                | No                               |
| CONDITION:               | Very bad  | TREND:                     | Deteriorating significantly      |
| VULNERABILITY:           | Medium  | CONTACT:                   | Philip Hornby (LPA) 01255 686170 |

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

24

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / UTTLESFORD

| UTTLESFORD   |                    |  |  |
|--|--------------------|--|--|
| all to   | SITE NAME:         | Barn at Little Canfield Hall,<br>Little Canfield | A substantial aisled barn dating from the late C14. The barn<br>is redundant and requires structural repairs and re-roofing. |
|  | DESIGNATION:       | Listed Building grade II*                        | Listed Building Consent for the conversion of the barn to a single residential dwelling was approved in January 2013         |
|  | CONDITION:         | Poor   | and building works commenced on site in April 2014. Roof tiles removed leading to subsequent partial roof collapse in        |
|  | OCCUPANCY:         | Vacant/not in use                                | early 2015. Roof repaired but other work on site has   |
| and a state of the | PRIORITY CATEGORY: | B (F)  | ceased due to enforcement action by the Local Planning<br>Authority. The building is currently not weatherproof.             |
| 10/00/2018   | OWNER TYPE:        | Private  |  |
| © Historic England   | LIST ENTRY NUMBER: | 1054762  | Contact: Sheila Stones 01223 582716  |

| 2                    | SITE NAME:         | Bury Hill, Castle Lane, Saffron<br>Walden                    | Norman castle remains consisting of roofless ruins of the keep. Unconsolidated flint rubble. Two phases of urgent   |
|----------------------|--------------------|--|---|
| - have               | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade I, 3 LBs, CA | repairs undertaken in 2013-14 and proposals for high level<br>repairs to wall tops are being prepared for further repairs<br>in 2015. Fabric at ground level on interior faces subject to |
|                      | CONDITION:         | Poor   | vandalism.  |
| 1 - 13 4 - P - P     | OCCUPANCY:         | N/A  |   |
|                      | PRIORITY CATEGORY: | B (New entry)  |   |
|                      | OWNER TYPE:        | Local authority  |   |
| oric England Archive | LIST ENTRY NUMBER: | 1009307 and 1297737  | Contact: Deborah Priddy 01223 582720  |
|                      |                    |  |   |

| AN COMPANY  | SITE NAME:         | Tilty Mill, Tilty         | Watermill, early C18. Machinery intact. Evidence of   |
|---|--------------------|---------------------------|---|
| and the second se | DESIGNATION:       | Listed Building grade II* | defective roof tiles and some structural failure. In need of<br>urgent structural repairs and repair work to make it wind |
| r tû  | CONDITION:         | Very bad                  | and weathertight. Historic England liaising with owner and Local Authority over a variety of options to save the mill.    |
| 1 1   | OCCUPANCY:         | Vacant/not in use         | Local Autionity over a variety of options to save the mill.   |
|   | PRIORITY CATEGORY: | A (A)                     |   |
| Married West  | OWNER TYPE:        | Private                   |   |
| and the second  | LIST ENTRY NUMBER: | 222                       | Contact: Trudi Hughes 01223 582739  |
| © Historic England  |                    |                           |   |

Church with probable C12 origins. Largely demolished and SITE NAME: Church of St Mary the Virgin, rebuilt in the 1860s. Constructed from flint rubble with The Street, Manuden stone dressings and a tile roof. Shingled spire showing signs Listed Place of Worship grade of loss and curling of shingles; north transept (vestry) roof tiles are slipping. The latter are over a C15 roof structure DESIGNATION: II\*, CA with plastered ceiling and there is mould growth on the CONDITION: Poor western part of the ceiling which is indicative of moisture ingress. Other tiles slipping elsewhere. Congregation has PRIORITY CATEGORY: B (A) applied for a grant under the Listed Places of Worship Roof OWNER TYPE: Religious organisation Repair grant scheme. LIST ENTRY NUMBER: 1233999 Contact: Trudi Hughes 01223 582739

© Historic England

© Histor

| SITE NAME:               | Roman fort, Roman town, Roman and Anglo-Saxon | cemeteries at Gre  | eat Chesterford, Great Chesterford |
|--------------------------|---|--------------------|------------------------------------|
| DESIGNATION:             | Scheduled Monument, part in CA                | LIST ENTRY NUMBER: | 1013484                            |
| CONDITION:               | Extensive significant problems                | TREND:             | Declining                          |
| PRINCIPAL VULNERABILITY: | Arable ploughing                              | NEW ENTRY ?:       | No                                 |
| OWNER TYPE:              | Mixed, multiple owners                        | CONTACT:           | David Kenny 01223 582760           |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / UTTLESFORD / BROXBOURNE

| SITE NAME:               | Romano-Celtic temple 400m south of Dell's Farm, 0              | Great Chesterford  |                             |
|--------------------------|--|--------------------|-----------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1017453                     |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:             | Declining                   |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                          |
| OWNER TYPE:              | Commercial company   | CONTACT:           | David Kenny 01223 582760    |
| SITE NAME:               | Stansted Castle: a ringwork and associated bailey 10           | 00m north of Elms  | Farm, Stansted Mountfitchet |
| DESIGNATION:             | Scheduled Monument, LB grade II, part in CA                    | LIST ENTRY NUMBER: | 1009311                     |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:             | Stable                      |
| PRINCIPAL VULNERABILITY: | Collapse   | NEW ENTRY?:        | No                          |
| OWNER TYPE:              | Commercial company   | CONTACT:           | Deborah Priddy 01223 582720 |
| SITE NAME:               | Site of Waltham Hall, Takeley                                  |                    |                             |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1002161                     |
| CONDITION:               | Extensive significant problems                                 | TREND:             | Declining                   |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                          |
| OWNER TYPE:              | Commercial company   | CONTACT:           | David Kenny 01223 582760    |



Edwardian gardens designed by Harold Peto c1902, SITE NAME: Easton Lodge, Little Easton incorporating a late CI7/early CI8 grove. The house was Registered Park and Garden fire damaged and finally demolished in 1950. Converted DESIGNATION: grade II, 3 LBs service buildings and infill development remain. Built structures within the garden have deteriorated, particularly Generally satisfactory but with CONDITION: the Italian Garden but planting improving. Ownership split significant localised problems between private owners of house and an investment VULNERABILITY: company. Garden continues to open to public in a limited High manner under the direction of the charity, The Gardens of TREND: Stable Easton Lodge Preservation Trust. NEW ENTRY ?: No OWNER TYPE: Private, multiple owners LIST ENTRY NUMBER: 1001484 Contact: Deborah Priddy 01223 582720

## HERTFORDSHIRE

© Historic England

| BROXBOURNE                 |                                      |                       |   |
|----------------------------|--------------------------------------|-----------------------|---|
| SITE NAME:                 | Churchgate                           |                       |   |
| DESIGNATION:               | Conservation Area, 23 LBs            | NEW ENTRY?:           | No  |
| CONDITION:                 | Poor                                 | TREND:                | No significant change                       |
| VULNERABILITY:             | High                                 | CONTACT:              | Colin Haigh (LPA) 01992 785555 ext:<br>5951 |
| SITE NAME:                 |                                      |                       |   |
|                            | Wormley                              |                       |   |
| DESIGNATION:               | Wormley<br>Conservation Area, 12 LBs | NEW ENTRY?:           | No  |
| DESIGNATION:<br>CONDITION: | ,                                    | NEW ENTRY?:<br>TREND: | No<br>No significant change                 |
|                            | Conservation Area, 12 LBs            |                       |   |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / DACORUM / EAST HERTFORDSHIRE

SITE NAME:

#### DACORUM

|                    | SITE NAME:<br>DESIGNATION: | Hemel Water Gardens<br>Registered Park and Garden<br>grade II | The Water Gardens were registered in 2010 and were the<br>subject of a successful Heritage Lottery Fund bid in<br>February 2014 by Dacorum Borough Council.<br>Comprehensive refurbishment of the whole gardens |
|--------------------|----------------------------|---|---|
|                    | CONDITION:                 | Generally unsatisfactory with major localised problems        | proposed, including structural repairs to bridges and<br>renewed planting scheme. Alterations to car parking and<br>play areas included. Works due to commence in 2015.   |
| MCM LINE AND CO    | VULNERABILITY:             | High  |   |
|                    | TREND:                     | Declining   |   |
|                    | NEW ENTRY ?:               | No  |   |
| © Historic England | OWNER TYPE:                | Local authority   |   |
|                    | LIST ENTRY NUMBER:         | 1001710   | Contact: Stuart Taylor 01223 582754   |

## EAST HERTFORDSHIRE



© Historic England



© Historic England Archive



© Historic England

PRIORITY CATEGORIES

implemented.

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet

C Slow decay; no solution agreed.

А

В

|                |   | St Mary and All Saints Church,<br>Thundridge                         | of St Mary and All Saints. Flint rubble with some dressings;<br>a Romanesque doorway has been reset within the blocking   |  |  |  |  |
|----------------|---|--|---|--|--|--|--|
|                | DESIGNATION:  | Listed Building grade II*, SM  | of the chancel arch. The church was demolished in 1853,<br>and only the three-stage tower remains substantially above   |  |  |  |  |
|                | CONDITION:  | Poor   | ground. The building is suffering from architectural decay and is threatened by vandalism and anti-social behaviour.  |  |  |  |  |
|                | OCCUPANCY:  | N/A  | During 2015 numerous works to prevent access to the   |  |  |  |  |
|                | PRIORITY CATEGORY:  | C (C)  | interior of the tower have resulted in increasingly serious damage and vandalism.   |  |  |  |  |
|                | OWNER TYPE:   | Religious organisation   |   |  |  |  |  |
|                | LIST ENTRY NUMBER:  | 1077953  | Contact: Deborah Priddy 01223 582720  |  |  |  |  |
| Ka             | SITE NAME:  | Remains of St Mary and All<br>Saints, Old Church Lane,<br>Thundridge | The church was demolished in 1853, only the separately<br>listed three-stage tower (see separate entry for remains of<br>old church tower) remains substantially above ground             |  |  |  |  |
|                | DESIGNATION: Scheduled Monument, LB grade<br>II*, part in RPG grade II* |  | within the scheduled churchyard and adjacent manorial<br>moated site. The rest of the church (demolished to<br>foundation level) and the churchyard wall are scheduled                    |  |  |  |  |
|                | CONDITION:  | Very bad   | and considered to be structurally at risk. Buried archaeological remains are also considered to be at risk  |  |  |  |  |
|                | OCCUPANCY:  | N/A  | from vandalism and anti-social behaviour. Long term   |  |  |  |  |
| N.             | PRIORITY CATEGORY:  | C (C)  | management remains a problem to avoid repetition of vandalism.  |  |  |  |  |
|                | OWNER TYPE:   | Religious organisation   |   |  |  |  |  |
|                | LIST ENTRY NUMBER:  | 1012268  | Contact: Deborah Priddy 01223 582720  |  |  |  |  |
|                | SITE NAME:  | Church of St Andrew, St<br>Andrew Street, Hertford                   | High Victorian Gothic church 1869-70, incorporating C15<br>doorway from earlier church, steeple 1875-6. Flint with  |  |  |  |  |
|                | DESIGNATION:  | Listed Place of Worship grade II,<br>CA                              | grey limestone dressings and bands, fine yellow sandstone<br>windows. Welsh slated roofs with red ridge tiles. A scheme<br>for conservation of the historic fabric will be the subject of |  |  |  |  |
|                | CONDITION:  | Very bad   | a grant application to the Heritage Lottery Fund.   |  |  |  |  |
|                | PRIORITY CATEGORY:  | A (New entry)  |   |  |  |  |  |
| and the second | OWNER TYPE:   | Religious organisation   |   |  |  |  |  |
| A DEC          | LIST ENTRY NUMBER:  | 1268748  | Contact: Robert Parkinson 01223 582733  |  |  |  |  |
|                |   |  |   |  |  |  |  |

Remains of old church tower of Ruinous CI5 west tower belonging to the CII-CI2 church

## ABBREVIATIONS

- CA LB
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

- Immediate risk of further rapid deterioration or loss of fabric; no
- D Slow decay: solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted). LPA NP RPG SM

27

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / EAST HERTFORDSHIRE / NORTH HERTFORDSHIRE



| TE NAME:          | Parish Church of All Saints,<br>Church Lane, Little Munden |
|-------------------|--|
| ESIGNATION:       | Listed Place of Worship grade I                            |
| ONDITION:         | Poor   |
| RIORITY CATEGORY: | C (C)  |
| WNER TYPE:        | Religious organisation                                     |
| ST ENTRY NUMBER:  | 1102260  |
|                   |  |

Parish church dating from the C12. Construction is in flint rubble, with tower and "spike" characteristic of the county. The condition of the tiled roofs to the north east chapel, chancel and south slope of the nave is poor. Solution yet to be agreed.

Contact: John Neale 01223 582719

© Historic England

| SITE NAME:               | Roman site near railway station, Braughing / Stando                                | on                 |  |
|--------------------------|--|--------------------|--|
| DESIGNATION:             | Scheduled Monument, part in CA   | LIST ENTRY NUMBER: | 1005249                                |
| CONDITION:               | Extensive significant problems   | TREND:             | Declining                              |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                                     |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:           | David Kenny 01223 582760               |
| SITE NAME:               | Settlement site north east of Letty Green, Herting                                 | fordbury           |  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1005240                                |
| CONDITION:               | Extensive significant problems   | TREND:             | Declining                              |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                                     |
| OWNER TYPE:              | Commercial company   | CONTACT:           | David Kenny 01223 582760               |
| SITE NAME:               | Thundridgebury moated enclosure and associated<br>Church and graveyard, Thundridge | remains of Thundri | dgebury House, St Mary and All Saints' |
| DESIGNATION:             | Scheduled Monument, LB grade II*, part in RPG grade II*                            | LIST ENTRY NUMBER: | 1012268                                |
| CONDITION:               | Generally satisfactory but with significant localised problems                     | TREND:             | Declining                              |
| PRINCIPAL VULNERABILITY: | Deterioration - in need of management  | NEW ENTRY?:        | No                                     |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:           | Deborah Priddy 01223 582720            |

## NORTH HERTFORDSHIRE

| ~                          | SITE NAME:         | Ruins of Church of St<br>Etheldreda, Chesfield, Graveley | Former C14 church of St Etheldreda, part demolished<br>1750; now roofless ruin. Unconsolidated flint rubble. Wall |
|----------------------------|--------------------|--|---|
| CA 14                      | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II*      | facing is being lost.   |
| ALLA TON                   | CONDITION:         | Poor   |   |
|                            | OCCUPANCY:         | N/A  |   |
|                            | PRIORITY CATEGORY: | C (C)  |   |
| No. 146 August State State | OWNER TYPE:        | Private  |   |
| © Historic England Archive | LIST ENTRY NUMBER: | 1003542 and 1102564                                      | Contact: Deborah Priddy 01223 582720  |

| 12                 | SITE NAME:         | Knebworth House, Knebworth                      | Knebworth House comprises one wing of a C16 courtyard  |
|--------------------|--------------------|---|--|
|                    | DESIGNATION:       | Listed Building grade II*, RPG<br>grade II*, CA | house remodelled in lavish neo-Tudor style in the mid C19.<br>This later external work was in very poor condition for<br>many years, and despite a major campaign of work some |
|                    | CONDITION:         | Poor  | years ago much remains to be repaired. A further phase of Historic England grant-aided work has commenced, and   |
| III Frank          | OCCUPANCY:         | Occupied/in use                                 | work is on site.   |
| J.M. ALE           | PRIORITY CATEGORY: | F (C)   |  |
|                    | OWNER TYPE:        | Charity (heritage)                              |  |
| © Historic England | LIST ENTRY NUMBER: | 1102767   | Contact: John Neale 01223 582719   |

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / NORTH HERTFORDSHIRE

|                           | SITE NAME:  | Minsden Chapel, Whitwell<br>Road, Langley  | Ruined remains of a small C14 two-cell church with<br>bellcote. Built of flint rubble with stone dressings, plastered  |
|---------------------------|---|--|--|
| A State B                 | DESIGNATION:  | Scheduled Monument and Listed<br>Building grade II   | externally. Probably a ruin by end of C17. Church was<br>dedicated to St Nicholas. Inspection showed loss of<br>voussoirs from openings and general erosion of fabric  |
| 140 × 1                   | CONDITION:  | Poor   | which requires consolidation. Discussions with Parochial<br>Church Council and diocese regarding repairs took place in   |
| 10000 2 2 2               | OCCUPANCY:  | N/A  | 2013.  |
|                           | PRIORITY CATEGORY:  | C (C)  |  |
|                           | OWNER TYPE:   | Religious organisation   |  |
| D Historic England        | LIST ENTRY NUMBER:  | 1003543 and 1347462  | Contact: Deborah Priddy 01223 582720   |
|                           | SITE NAME:  | North Hertfordshire Masonic<br>Lodge (the Cloisters),<br>Barrington Road, Letchworth<br>Garden City  | Built 1906-7, originally a residential school for psychology<br>based on Arts and Crafts ethics. Patron Miss A Lawrence,<br>Architect WH Cowlishaw, a follower of William Morris.<br>Highly idiosyncratic design incorporating a philosophical   |
|                           | DESIGNATION:  | Listed Building grade II*, CA  | approach to materials with traditional and progressive<br>themes, but now costly to maintain. Currently the North  |
|                           | CONDITION:  | Very bad   | Hertfordshire Masonic Lodge. Problems of rainwater entry   |
|                           | OCCUPANCY:  | ,<br>Occupied/in use   | and architectural deterioration. No action/strategy identified or agreed.  |
|                           | PRIORITY CATEGORY:  | A (A)  | 5  |
| D Historic England        | OWNER TYPE:   | Private  |  |
|                           | LIST ENTRY NUMBER:  | 1102019  | Contact: Malcolm Starr 01223 582723  |
|                           |   |  |  |
|                           | SITE NAME:  | West Barn at Rectory Farm,<br>Shillington Road, Pirton   | Tithe barn built late C15 or early C16. The building is now vacant and in need of major repairs. Other buildings on site   |
|                           | DESIGNATION:  | Listed Building grade II*, CA  | have been converted into houses. Sympathetic proposals for repair and partial conversion have been agreed but  |
|                           | CONDITION:  | Poor   | have yet to be implemented.  |
|                           | OCCUPANCY:  | Vacant/not in use  |  |
|                           | PRIORITY CATEGORY:  | D (D)  |  |
|                           | OWNER TYPE:   | Commercial company   |  |
| D Historic England        | LIST ENTRY NUMBER:  | 1175545  | Contact: John Neale 01223 582719   |
|                           | SITE NAME:  | Church of St Mary, Church  | Prominently sited parish church, dating from the C13, with   |
|                           |   | Street, Baldock  | CI4 and CI5 alterations and additions. Some CI9  |
|                           | DESIGNATION:  | Street, Baldock<br>Listed Place of Worship grade I,<br>CA  | restoration. Tower spire C19. Plan: tower, with nave and chancel; north and south aisles and porches. Nave and   |
|                           | designation:  | Listed Place of Worship grade I,   | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle   |
|                           |   | Listed Place of Worship grade I,<br>CA   | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in  |
|                           | CONDITION:  | Listed Place of Worship grade I,<br>CA<br>Very bad   | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant   |
|                           | CONDITION:<br>PRIORITY CATEGORY:  | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)  | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in  |
| D Barker & Associates LLP | Condition:<br>Priority category:<br>Owner type:   | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation  | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.  |
| Barker & Associates LLP   | Condition:<br>Priority category:<br>Owner type:   | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation  | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.<br>Contact: Malcolm Starr 01223 582723<br>Parish church largely dating from the C13 and later but<br>incorporating earlier fabric of 1108-1114. The exterior was   |
| Barker & Associates LLP   | CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE:<br>LIST ENTRY NUMBER:   | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation<br>1347611<br>Church of St Faith, Barton   | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.<br>Contact: Malcolm Starr 01223 582723<br>Parish church largely dating from the C13 and later but<br>incorporating earlier fabric of 1108-1114. The exterior was<br>rendered in 1824. In 1947, two sides of the west tower<br>collapsed. Extensive grant-aided repairs to the tower, roof<br>and rendered walls commenced in 2013. Although these  |
| Dearker & Associates LLP  | CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE:<br>LIST ENTRY NUMBER:<br>SITE NAME:                               | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation<br>1347611<br>Church of St Faith, Barton<br>Road, Hexton<br>Listed Place of Worship grade            | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.<br>Contact: Malcolm Starr 01223 582723<br>Parish church largely dating from the C13 and later but<br>incorporating earlier fabric of 1108-1114. The exterior was<br>rendered in 1824. In 1947, two sides of the west tower<br>collapsed. Extensive grant-aided repairs to the tower, roof<br>and rendered walls commenced in 2013. Although these<br>are largely completed, additional costs have forced some  |
| Parker & Associates LLP   | CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE:<br>LIST ENTRY NUMBER:<br>SITE NAME:<br>DESIGNATION:               | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation<br>1347611<br>Church of St Faith, Barton<br>Road, Hexton<br>Listed Place of Worship grade<br>II*, CA | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.<br>Contact: Malcolm Starr 01223 582723<br>Parish church largely dating from the C13 and later but<br>incorporating earlier fabric of 1108-1114. The exterior wa<br>rendered in 1824. In 1947, two sides of the west tower<br>collapsed. Extensive grant-aided repairs to the tower, roof<br>and rendered walls commenced in 2013. Although these<br>are largely completed, additional costs have forced some<br>work to be deferred, leaving parts of the chancel and<br>vestry damp and at risk of further deterioration. The |
| Derker & Associates LLP   | CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE:<br>LIST ENTRY NUMBER:<br>SITE NAME:<br>DESIGNATION:<br>CONDITION: | Listed Place of Worship grade I,<br>CA<br>Very bad<br>D (New entry)<br>Religious organisation<br>1347611<br>Church of St Faith, Barton<br>Road, Hexton<br>Listed Place of Worship grade<br>II*, CA | restoration. Tower spire C19. Plan: tower, with nave and<br>chancel; north and south aisles and porches. Nave and<br>south aisle roofs suffering from severe underside lead<br>corrosion; leaking. Some of flint facework on south aisle<br>and to south porch is loose. Heritage Lottery Fund Grant<br>for Places of Worship awarded in 2014; project now in<br>development stage.<br>Contact: Malcolm Starr 01223 582723<br>Parish church largely dating from the C13 and later but<br>incorporating earlier fabric of 1108-1114. The exterior wa<br>rendered in 1824. In 1947, two sides of the west tower<br>collapsed. Extensive grant-aided repairs to the tower, roof<br>and rendered walls commenced in 2013. Although these<br>are largely completed, additional costs have forced some<br>work to be deferred, leaving parts of the chancel and  |

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

## HERITAGE AT RISK 2015 / EAST OF ENGLAND / NORTH HERTFORDSHIRE / ST ALBANS

| HERITAGE AT RISK 2015 / EAST ( | OF ENGLAND / NORTH HERTFORDSHIRE / ST ALBANS                   |                      |  |
|--------------------------------|--|----------------------|--|
| SITE NAME:                     | Romano-British small town and late Iron Age settle             | ement at Baldock     |  |
| DESIGNATION:                   | Scheduled Monument   | LIST ENTRY NUMBER:   | 1016305                                |
| CONDITION:                     | Generally unsatisfactory with major localised problems         | TREND:               | Declining                              |
| PRINCIPAL VULNERABILITY:       | Arable ploughing   | NEW ENTRY?:          | No                                     |
| OWNER TYPE:                    | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760               |
| SITE NAME:                     | Two bowl barrows at Bygrave, 650m east of Park                 | Wood, Bygrave        |  |
| DESIGNATION:                   | Scheduled Monument   | LIST ENTRY NUMBER:   | 1009821                                |
| CONDITION:                     | Extensive significant problems                                 | TREND:               | Declining                              |
| PRINCIPAL VULNERABILITY:       | Arable ploughing   | NEW ENTRY ?:         | No                                     |
| OWNER TYPE:                    | Commercial company   | CONTACT:             | David Kenny 01223 582760               |
| SITE NAME:                     | Slight univallate hillfort on Wilbury Hill, Letchwort          | h Garden City / Ick  | leford                                 |
| DESIGNATION:                   | Scheduled Monument   | LIST ENTRY NUMBER:   | 1016410                                |
| CONDITION:                     | Generally satisfactory but with significant localised problems | TREND:               | Stable                                 |
| PRINCIPAL VULNERABILITY:       | Vandalism  | NEW ENTRY ?:         | No                                     |
| DWNER TYPE:                    | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760               |
| SITE NAME:                     | Ring ditch and enclosure, Newnham                              |                      |  |
| DESIGNATION:                   | Scheduled Monument, part in CA                                 | LIST ENTRY NUMBER:   | 1003596                                |
| CONDITION:                     | Extensive significant problems                                 | TREND:               | Declining                              |
| PRINCIPAL VULNERABILITY:       | Arable ploughing   | NEW ENTRY?:          | No                                     |
| OWNER TYPE:                    | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760               |
| ITE NAME:                      | Triple ditches at Galley Hill, Sandon / Kelshall               |                      |  |
| DESIGNATION:                   | Scheduled Monument   | LIST ENTRY NUMBER:   | 1003550                                |
| CONDITION:                     | Extensive significant problems                                 | TREND:               | Declining                              |
| PRINCIPAL VULNERABILITY:       | Arable ploughing   | NEW ENTRY?:          | No                                     |
| OWNER TYPE:                    | Commercial company   | CONTACT:             | David Kenny 01223 582760               |
| DITE NAME:                     | Wymondley Priory, barn, moat, associated earthwo<br>Wymondley  | orks, enclosures, pl | atforms, hollow-way and conduit head   |
| DESIGNATION:                   | Scheduled Monument, 5 LBs                                      | LIST ENTRY NUMBER:   | 1013338                                |
| CONDITION:                     | Generally satisfactory but with significant localised problems | TREND:               | Stable                                 |
| PRINCIPAL VULNERABILITY:       | Development requiring planning permission                      | NEW ENTRY?:          | No                                     |
| OWNER TYPE:                    | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760               |
| ST ALBANS                      |  |                      |  |
| he share                       | SITE NAME: The Benedictine Priory of St                        | Well preserved       | post-dissolution remains of Benedictin |



| IS            |   |   |   |
|---------------|---|---|---|
| -             | SITE NAME:  | The Benedictine Priory of St<br>Mary (Sopwell Priory) and the<br>post-medieval mansions known<br>as Sopwell House or Lee Hall | Well preserved post-dissolution remains of Benedictine<br>Priory. Building requires repairs to wall tops and areas of<br>lost walling and window openings, where cracking and<br>decay is causing loss of fabric and risk to the structure. |
|               | DESIGNATION: Scheduled Monument, LB grade<br>II, CA |   | Discussions with the owners continue about additional grant aid which may be needed to complete a full repair programme of works to the ruins. Garden walls also in   |
| and the state | CONDITION:  | Poor  | need of urgent repairs.   |
|               | OCCUPANCY:  | N/A   |   |
| 4             | PRIORITY CATEGORY:                                  | A (New entry)   |   |
|               | OWNER TYPE:   | Government or agency  |   |
|               | LIST ENTRY NUMBER:                                  | 1019137   | Contact: John Ette 01223 582711   |

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / ST ALBANS / THREE RIVERS / WATFORD

| SITE NAME:                 | The Aubreys camp, Redbourn  |   |                                       |
|----------------------------|---|---|---------------------------------------|
| DESIGNATION:               | Scheduled Monument  | LIST ENTRY NUMBER:                              | 1003520                               |
| CONDITION:                 | Generally unsatisfactory with major localised problems                          | TREND:  | Declining                             |
| PRINCIPAL VULNERABILITY:   | Scrub/tree growth   | NEW ENTRY?:                                     | No                                    |
| OWNER TYPE:                | Mixed, multiple owners  | CONTACT:  | David Kenny 01223 582760              |
|                            |   |   |                                       |
| SITE NAME:                 | Wheathampstead earthwork incorporating Devils                                   | Dyke and the Slad,                              | Wheathampstead / Sandridge            |
| SITE NAME:<br>DESIGNATION: | Wheathampstead earthwork incorporating Devils I<br>Scheduled Monument           | <b>Dyke and the Slad,</b><br>LIST ENTRY NUMBER: | Wheathampstead / Sandridge<br>1003521 |
|                            |   |   |                                       |
| DESIGNATION:               | Scheduled Monument<br>Generally unsatisfactory with major localised             | LIST ENTRY NUMBER:                              | 1003521                               |
| DESIGNATION:<br>CONDITION: | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems | LIST ENTRY NUMBER:                              | 1003521<br>Declining                  |

## THREE RIVERS

|       | SITE NAME:         | Langleybury House,<br>Langleybury, Abbots Langley | Country house c1725. Formerly in use as part of a school, but vacant since 1996. Proposals for the repair of the |
|-------|--------------------|---|--|
|       | DESIGNATION:       | Listed Building grade II*                         | house have yet to be implemented, and while use of the buildings for filming helps ensure their protection, the  |
|       | CONDITION:         | Fair  | implementation of a comprehensive scheme remains desirable.  |
|       | OCCUPANCY:         | Part occupied/part in use                         |  |
|       | PRIORITY CATEGORY: | C (C)   |  |
|       | OWNER TYPE:        | Commercial company                                |  |
| gland | LIST ENTRY NUMBER: | 1173157   | Contact: John Neale 01223 582719   |

© Historic Engla

© His

## WATFORD

| ATFORD         |                    |  |
|----------------|--------------------|--|
|                | SITE NAME:         | Little Cassiobury and former<br>stable block, Hempstead Road,<br>Watford |
|                | DESIGNATION:       | Listed Building grade II*, CA  |
|                | CONDITION:         | Fair   |
|                | OCCUPANCY:         | Vacant/not in use  |
|                | PRIORITY CATEGORY: | C (E)  |
|                | OWNER TYPE:        | Local authority  |
| storic England | LIST ENTRY NUMBER: | 1175392  |

Cassiobury continue to work on an imaginative scheme for the building's reuse.

Late C17 house built as dower house to Cassiobury. Last

occupied as offices, the building has been empty for many

years. Various repairs have been carried out over this period. The Borough Council and the Friends of Little

Contact: John Neale 01223 582719



A fine house built in 1716, Frogmore House was last used SITE NAME: Frogmore House, High Street (north east side), Watford as flats. The house was repaired some years ago but unding the re-use of the ls to develop

© Historic England

| X.32 |                    | (nor the case side), wattor d |  |
|------|--------------------|-------------------------------|--|
|      | DESIGNATION:       | Listed Building grade II*     | remained vacant due to the uncertainty surro future use of adjacent land. Discussions about      |
|      | CONDITION:         | Fair                          | building continue in connection with proposals<br>the adjacent site, but have yet to bear fruit. |
|      | OCCUPANCY:         | Vacant/not in use             | the adjacent site, but have yet to bear mut.   |
|      | PRIORITY CATEGORY: | E (E)                         |  |
|      | OWNER TYPE:        | Commercial company            |  |
|      | LIST ENTRY NUMBER: | 1175515                       | Contact: John Neale 01223 582719   |
|      |                    |                               |  |

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
  - Unitary Authority World Heritage Site

#### WELWYN HATFIELD



SITE NAME: Paine Bridge at Brocket Hall, Marford Road, Lemsford, Hatfield Listed Building grade II\*, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1173560

Very fine classical bridge, built of stone to designs of James Paine in 1772. Stonework has decayed on all four bridge abutments requiring conservation repair.

Contact: John Ette 01223 582711

© Priest Restoration Ltd

## LUTON (UA)

| SITE NAME:     | High Town Road            |              |                                 |
|----------------|---------------------------|--------------|---------------------------------|
| DESIGNATION:   | Conservation Area, 4 LBs  | NEW ENTRY ?: | No                              |
| CONDITION:     | Very bad                  | TREND:       | Improving significantly         |
| VULNERABILITY: | Low                       | CONTACT:     | Gemma Davies (LPA) 01582 546548 |
|                |                           |              |                                 |
| SITE NAME:     | Plaiters Lea, Town Centre |              |                                 |
| DESIGNATION:   | Conservation Area, 9 LBs  | NEW ENTRY?:  | No                              |
| CONDITION:     | Very bad                  | TREND:       | Improving significantly         |
|                |                           |              |                                 |
| VULNERABILITY: | Medium                    | CONTACT:     | Gemma Davies (LPA) 01582 546548 |

NORFOLK

© Historic England

© Andrew Gayton

## BRECKLAND



Country house circa 1720 with substantial C19 additions Shadwell Court and clock SITE NAME: set in the centre of C18 park. Mid C19 formal gardens to tower, Brettenham the west, now much simplified. The building has been Listed Building grade I, RPG unoccupied for many years and affected by severe dry rot DESIGNATION: grade II outbreaks set off by leaks in the roof. Extensive roof repairs have been undertaken and the main building is now CONDITION: Poor stabilising. Part of the attached stable yard is in use and OCCUPANCY: maintained, but part is deteriorating. Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1076940 Contact: David Eve 01223 582721



| L | SITE NAME:         | Dereham Maltings (Crisp<br>Malting), Norwich Road, East<br>Dereham, Dereham | Large complex of C19 maltings, disused and vacant.<br>Proposal to build houses on part of land and repair and<br>reuse of maltings has been discussed in principle, but not |
|---|--------------------|---|---|
|   | DESIGNATION:       | Listed Building grade II* yet agreed.                                       |   |
|   | CONDITION:         | Poor  |   |
|   | OCCUPANCY:         | Vacant/not in use   |   |
|   | PRIORITY CATEGORY: | C (C)   |   |
|   | OWNER TYPE:        | Private   |   |
|   | LIST ENTRY NUMBER: | 1246348   | Contact: David Eve 01223 582721   |

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

© Historic Englan

© Historic Eng

|     | SITE NAME:         | Guntons Farmhouse,<br>Reymerston Road, Garvestone | Timber-framed manor house, late C16. General lack of repairs leading to areas of decay, particularly long-standing |
|-----|--------------------|---|--|
|     | DESIGNATION:       | Listed Building grade II*                         | decay in rear stair tower. Long-term solution still to be agreed and implemented.                                  |
|     | CONDITION:         | Poor  |  |
|     | OCCUPANCY:         | Occupied/in use                                   |  |
|     | PRIORITY CATEGORY: | C (F)   |  |
|     | OWNER TYPE:        | Private   |  |
| and | LIST ENTRY NUMBER: | 1342566   | Contact: David Eve 01223 582721  |
|     |                    |   |  |

|        | SITE NAME:         | Church of St Mary, West Tofts,<br>Lynford | C13 foundation, with later medieval additions, greatly altered C19 by AWN Pugin, with much of the significance         |
|--------|--------------------|---|--|
|        | DESIGNATION:       | Listed Building grade I                   | of the building deriving from this latter stage of works.<br>Problems identified with rainwater goods causing internal |
|        | CONDITION:         | Poor                                      | environmental conditions leading to problems for decorative work. Historic England funded investigative                |
|        | OCCUPANCY:         | Vacant/not in use                         | work and repairs between 2008 and 2012. Further repair   |
|        | PRIORITY CATEGORY: | E (E)                                     | work funded by Historic England is currently underway.<br>This is now entering its final phase and is due to be        |
|        | OWNER TYPE:        | Religious organisation                    | completed by the third quarter of 2015.  |
| ngland | LIST ENTRY NUMBER: | 1077249                                   | Contact: Trudi Hughes 01223 582739   |
|        |                    |   |  |

The ruinous church remains form a significant monument in Ruins of St Andrew's Church, SITE NAME: Roudham and Larling the local landscape but are in a dangerous condition and cordoned off. Negotiations are progressing and it is hoped Scheduled Monument, LB grade that repairs and consolidation works will be carried out in DESIGNATION: Ш 2015/16. CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation © Historic England LIST ENTRY NUMBER: 1004012 Contact: David Kenny 01223 582760

|        | SITE NAME:         | Church of All Saints, Stanford | C12 and later medieval church now closed and owned by  |
|--------|--------------------|--------------------------------|--|
|        | DESIGNATION:       | Listed Building grade I        | the Ministry of Defence. Chancel arch in danger of collapse<br>and masonry is falling from the tower. Chancel arch |
|        | CONDITION:         | Very bad                       | propped by structural scaffold. Diocese and military discussing way forward and will discuss with Historic         |
|        | OCCUPANCY:         | Vacant/not in use              | England once a final way forward has been agreed.  |
| ACTION | PRIORITY CATEGORY: | A (A)                          |  |
| - A    | OWNER TYPE:        | Religious organisation         |  |
|        | LIST ENTRY NUMBER: | 1172174                        | Contact: Trudi Hughes 01223 582739   |

© Historic England



|  | SITE NAME:         | Church of St Mary the Less,<br>Bury Road, Thetford | Former church, C11 foundation, fabric mainly late C14.<br>West tower C15, chancel rebuilt C19. Closed for worship |
|--|--------------------|--|---|
|  | DESIGNATION:       | Listed Building grade II*, CA                      | and has suffered from decay and vandalism. A scheme for residential conversion was granted consent but has not    |
|  | CONDITION:         | Poor   | been implemented. Some repairs to the roof have been carried out and a fresh proposal for a residential use is    |
|  | OCCUPANCY:         | Vacant/not in use                                  | under discussion.   |
|  | PRIORITY CATEGORY: | D (B)  |   |
|  | OWNER TYPE:        | Religious organisation                             |   |
|  | LIST ENTRY NUMBER: | 1297899  | Contact: David Eve 01223 582721   |

© Historic England

| PRIORITY CATEGO | ORIES |
|-----------------|-------|
|-----------------|-------|

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

|                    | SITE NAME:         | Abbey Farm Barn, Monksgate,<br>Thetford | Late medieval abbey outbuilding, converted to farm building and latterly workshop. Previously neglected. |
|--------------------|--------------------|---|--|
|                    | DESIGNATION:       | Listed Building grade I, SM, CA         | Currently weathertight. Permission for conversion to residential use now being implemented.              |
| C                  | CONDITION:         | Fair                                    |  |
|                    | OCCUPANCY:         | Vacant/not in use                       |  |
| La alta da da da   | PRIORITY CATEGORY: | F (D)                                   |  |
|                    | OWNER TYPE:        | Commercial company                      |  |
| © Historic England | LIST ENTRY NUMBER: | 1297897                                 | Contact: David Eve 01223 582721  |
|                    |                    |   |  |

|  | SITE NAME:         | Abbey Farm Cottage, Thetford    | Late medieval abbey outbuilding, converted to farm  |  |
|--|--------------------|---------------------------------|---|--|
|  | DESIGNATION:       | Listed Building grade I, SM, CA | building, incorporating accommodation. Previously neglected. Currently weathertight. Permission for |  |
|  | CONDITION:         | Fair                            | conversion to residential use now being implemented.  |  |
|  | OCCUPANCY:         | Vacant/not in use               |   |  |
|  | PRIORITY CATEGORY: | F (D)                           |   |  |
|  | OWNER TYPE:        | Commercial company              |   |  |
|  | LIST ENTRY NUMBER: | 1207935                         | Contact: David Eve 01223 582721   |  |
|  |                    |                                 |   |  |

© Historic England



© Ruth & Peter Blackman

|  | SITE NAME:         | Church of All Saints, Norwich<br>Road, East Tuddenham | Parish church. Medieval and later. Flint with ashlar and some brick dressings. Black pantiled roofs. Off-centre west   |
|--|--------------------|---|--|
|  | DESIGNATION:       | Listed Place of Worship grade I                       | tower, exceptionally wide aisle- less nave with south porch<br>and chancel with vestry to north. Tower of c I 300 with   |
|  | CONDITION:         | Poor  | diagonal buttresses. Fine C15 porch with flushwork<br>inscription above entrance GLORIA TIBI TR. Tiling on n<br>and chancel north slopes in poor condition; Historic |
|  | PRIORITY CATEGORY: | F (New entry)   |  |
|  | OWNER TYPE:        | Religious organisation                                | England grant aided repairs in progress and due for completion in autumn 2015.   |
|  | LIST ENTRY NUMBER: | 1077352   | Contact: Trudi Hughes 01223 582739   |

© Historic England



| SITE NAME:         | Church of St Mary, Church<br>Road, Elsing | Parish church. B<br>and 1347 replac  |
|--------------------|---|--------------------------------------|
| DESIGNATION:       | Listed Place of Worship grade I           | fragment of walli<br>ashlar and some |
| CONDITION:         | Poor                                      | exceptionally wi<br>porches. High le |
| PRIORITY CATEGORY: | D (New entry)                             | failing. Repair Gr                   |
| OWNER TYPE:        | Religious organisation                    | south side comp<br>windows and the   |
| LIST ENTRY NUMBER: | 1342548                                   | threaten the imp                     |

© Historic England

Built by Sir Hugh Hastings between 1330 cing an earlier church of which a small lling survives in west wall of nave. Flint with e brick dressings. Pantile roofs. West tower, vide aisleless nave with north and south evel masonry, roofs and rainwater goods Frant for Places of Worship for work to pleted 2014. Outstanding items include ne internal environmental conditions which portant rood screen, a solution to which is yet to be agreed.

Contact: Robert Parkinson 01223 582733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

|            | SITE NAME:         | Church of St Peter and St Paul,<br>Church Road, Griston | Parish church dating from C14 comprising west tower, nave, chancel and north porch. Roofs in nave, porch and  |
|------------|--------------------|---|---|
|            | DESIGNATION:       | Listed Place of Worship grade I                         | chancel date from the 1884 restoration by JB Pearce.<br>Constructed in flint rubble with limestone dressings. |
| and the la | CONDITION:         | Very bad  | Parapet at top of tower contains some loose and weathered flint flushwork panels. Loose flints have fallen on |
|            | PRIORITY CATEGORY: | D (A)   | adiacent roofs. Tower roof is leaking. Heritage Lottery   |
|            | OWNER TYPE:        | Religious organisation                                  | Fund has offered a grant under Grants for Places of Worship. Development work to start on site at end of July |
|            | LIST ENTRY NUMBER: | 1172332   | 2015.   |
|            |                    |   | Contact: Trudi Hughes 01223 582739  |

© Historic England



© Historic England

© Historic England

| SITE NAME:         | Church of St Andrew, Holme<br>Hale | Medieval and later church. Flint with ashlar and some brick dressings. Slate and pantiled roofs. West tower; nave with   |
|--------------------|------------------------------------|--|
| DESIGNATION:       | Listed Place of Worship grade I    | north aisle and north porch; chancel. CI4 and CI5 west tower with angle buttresses. Condition of the tower roof is   |
| <br>CONDITION:     | Poor                               | deteriorating. Repair grant offered in 2010 and work is no<br>complete. Exceptionally, the number of bats using the nav<br>remains an issue and impacts on the usability of the<br>building. Natural England supported grant in place to<br>resolve issues of bats and users. Buttresses on south side |
| PRIORITY CATEGORY: | C (E)                              |  |
| OWNER TYPE:        | Religious organisation             |  |
| LIST ENTRY NUMBER: | 1152077                            | nave full of vegetation; suspect faulty drainage; some loose flints.   |
|                    |                                    | inites.  |

Church of St Mary, Church

Listed Place of Worship grade I,

Street, Kenninghall

CA

Poor

B (New entry)

1168685

Religious organisation

Contact: Trudi Hughes 01223 582739

Medieval parish church of CII origins. Nave, north aisle and chancel C14; C15 west tower. Continual roof leaks and dampness along northern side. Nave roof is in need of recovering and there are various areas of stonework repairs largely to weathering. Heritage Lottery Fund Grant for Places of Worship offered in summer 2015.

Contact: Trudi Hughes 01223 582739

© Ruth & Peter Blackman

Parish church featuring a Saxon round tower, largely intact; SITE NAME: Church of St Andrew, Lexham nave and chancel in line and largely rendered, with DESIGNATION: Listed Place of Worship grade I evidence of long and short work at quoins. 1837 restoration provided the roofs to the nave and chancel. CONDITION: Very bad The round tower is surmounted by an octagonal parapet PRIORITY CATEGORY: which does not fit the geometry of the walling below, B (A) which has led to excess water ingress into late Saxon OWNER TYPE: Religious organisation walling. Roof leaks. Heritage Lottery Fund has offered a Grant for Places of Worship which is currently in the LIST ENTRY NUMBER: 1342495 development stage.

Contact: Trudi Hughes 01223 582739

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

|   | 1 |   | Ĭ |   |
|---|---|---|---|---|
|   |   |   |   |   |
| - | Y | 1 |   |   |
|   |   | ~ |   | T |

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England

|      | SITE NAME:         | Church of St Andrew, Fairstead<br>Lane, Little Cressingham | Parish church. The CI5 tower is partially demolished and the two western most bays of the nave and south aisle are             |
|------|--------------------|--|--|
| - n  | DESIGNATION:       | Listed Place of Worship grade I                            | roofless. The two most western north aisle bays have been demolished except for the west wall. The present entrance            |
|      | CONDITION:         | Poor   | is to the west in the brick wall dividing the roofed church in<br>use from the ruin. A corrugated roof covers the south aisle, |
| ATTA | PRIORITY CATEGORY: | A (A)  | while the nave is roofed in plain tile. Roof is leaking with   |
|      | OWNER TYPE:        | Religious organisation                                     | damp penetration in aisles. Vegetation growth is also an issue. No action/strategy as yet identified or agreed.                |
|      | LIST ENTRY NUMBER: | 1077227  | Contact: Janine Dykes 01223 582724   |

© Historic England

|  | SITE NAME:         | Church of St John Evangelist,<br>Church Street, Ovington | Parish church dated to C12 and restored 1867.<br>Rubblestone construction with ashlar quoins and white        |
|--|--------------------|--|---|
|  | DESIGNATION:       | Listed Place of Worship grade II*                        | pantiles. Square west tower and continuous nave and chancel. Hipped slate roof. South door C12. Serious       |
|  | CONDITION:         | Very bad   | structural cracks in tower and nave walls. Roofs leaking with associated water penetration problems. Heritage |
|  | PRIORITY CATEGORY: | A (New entry)  | Lottery Fund grant application made June 2015.  |
|  | OWNER TYPE:        | Religious organisation                                   |   |
|  | LIST ENTRY NUMBER: | 1076798  | Contact: Robert Parkinson 01223 582733  |
|  |                    |  |   |

© Historic England

|                | SITE NAME:         | Church of St Peter, Church<br>Road, Shropham | Mid C13 nave, north aisle and chancel; remodelled in C15.<br>C15 west tower restored 1867. Flint with ashlar dressings |
|----------------|--------------------|--|--|
| 1 3            | DESIGNATION:       | Listed Place of Worship grade I              | and slated roofs. North nave roof heavily tingled (a form of temporary repair) and may require replacement in near     |
|                | CONDITION:         | Poor   | future. Slów decline, no overall solution agreed, but<br>monitoring is ongoing.  |
|                | PRIORITY CATEGORY: | C (C)  |  |
|                | OWNER TYPE:        | Religious organisation                       |  |
| and the second | LIST ENTRY NUMBER: | 1077578                                      | Contact: Trudi Hughes 01223 582739   |

© Historic England

|  | SITE NAME:         | Church of St Botolph, Stow<br>Bedon | Parish church with C12 origins, re-modelled in the C14,<br>C15 and C19. Constructed with flint with ashlar dressings   |
|--|--------------------|-------------------------------------|--|
|  | DESIGNATION:       | Listed Place of Worship grade II*   | and slate roof replaced following second world war bomb<br>damage. There is evidence for two phases of structural ties   |
|  | CONDITION:         | Poor                                | in the south elevation but they do not appear to be<br>working. The interior has recently been re-plastered, but<br>structural movement and a damp problem persists. |
|  | PRIORITY CATEGORY: | B (B)                               |  |
|  | OWNER TYPE:        | Religious organisation              | Heritage Lottery Fund grant under Grants for Places of<br>Worship Scheme offered July 2014 and development   |
|  | LIST ENTRY NUMBER: | 1077585                             | works due to commence summer 2015.   |
|  |                    |                                     | Contact: Robert Parkinson 01223 582733   |

© Historic England



| SITE NAME:         | Church of St Peter and St Paul,<br>Church Lane, Swaffham | Parish church dating from C14, with C18 and C19 alterations and restorations. Flint, Barnack stone  |
|--------------------|--|---|
| DESIGNATION:       | Listed Place of Worship grade I,<br>CA                   | construction with some brick. Gutters, roof, windows and<br>interior in poor condition. Heritage Lottery Fund grant<br>accepted late 2013 and repairs underway. |
| CONDITION:         | Good   |   |
| PRIORITY CATEGORY: | F (B)  |   |
| OWNER TYPE:        | Religious organisation                                   |   |
| LIST ENTRY NUMBER: | 1269628  | Contact: Robert Parkinson 01223 582733  |

© Historic England

| PRIORITY | CATEGORIES |
|----------|------------|
|          |            |

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

|                   | SITE NAME:         | Church of St Andrew,<br>Tottington | Parish church dated to 1360, restored 1885-6 by EP<br>Willins. Rendered flint with ashlar quoins and tiled and   |
|-------------------|--------------------|------------------------------------|--|
|                   | DESIGNATION:       | Listed Place of Worship grade II*  | pantiled roofs. West tower, nave, aisles and chancel.<br>Tower of four stages. Angle buttresses to east and west |
| TA                | CONDITION:         | Fair                               | becoming diagonal. Arched and moulded west door below<br>2-light window. High level stonework on tower an issue; |
| Danne (De la come | PRIORITY CATEGORY: | A (A)                              | chancel ceiling at risk of collapse. No action/strategy  |
|                   | OWNER TYPE:        | Religious organisation             | confirmed.   |
|                   | LIST ENTRY NUMBER: | 1342814                            | Contact: Trudi Hughes 01223 582739   |

© Historic England

|            | SITE NAME:         | Church of St Mary, Church<br>Road, Whinburgh, Whinburgh<br>and Westfield | An architecturally and historically important church, as its grade I listing indicates, dating from at least the CI2, with CI3 tower, the latter unusual in that it is attached to the |
|------------|--------------------|--|--|
| 20010      | DESIGNATION:       | Listed Place of Worship grade I  | south side of the nave. The present chancel may<br>incorporate an earlier Norman structure. Its roofs are in   |
|            | CONDITION:         | Poor   | poor condition, as is the ground drainage system generally.<br>The church suffers from leakage and damp penetration  |
|            | PRIORITY CATEGORY: | F (F)  | from the ground, which is putting the plaster and its early<br>decoration at risk. Repair Grant for Places of Worship was  |
|            | OWNER TYPE:        | Religious organisation   | offered in 2011. Repair works expected to be completed   |
|            | LIST ENTRY NUMBER: | 1152030  | by late 2015.  |
| ic England |                    |  | Contact: Malcolm Starr 01223 582723  |

© Historic Eng

| SITE NAME:  | Roman enclosure 3/4 mile (1210m) north east of Panworth Hall, Ashill / Holme Hale   |   |   |  |  |
|---|---|---|---|--|--|
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:  | 1003965   |  |  |
| CONDITION:  | Generally satisfactory but with significant localised problems  | TREND:  | Declining   |  |  |
| PRINCIPAL VULNERABILITY:  | Arable ploughing  | NEW ENTRY?:   | No  |  |  |
| OWNER TYPE:   | Mixed, multiple owners  | CONTACT:  | David Kenny 01223 582760                            |  |  |
| SITE NAME:  | Tumulus west of Leader's Spinney, Banham  |   |   |  |  |
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:  | 1003161   |  |  |
| CONDITION:  | Extensive significant problems  | TREND:  | Declining   |  |  |
| PRINCIPAL VULNERABILITY:  | Arable ploughing  | NEW ENTRY?:   | No  |  |  |
| OWNER TYPE:   | Commercial company  | CONTACT:  | David Kenny 01223 582760                            |  |  |
|   |   |   |   |  |  |
| SITE NAME:  | A Roman roadside settlement 150m south west of  | Billingford Hall, Bil   | lingford  |  |  |
| SITE NAME:<br>DESIGNATION:  | A Roman roadside settlement 150m south west of<br>Scheduled Monument  | Billingford Hall, Bil   | lingford<br>1021458                                 |  |  |
|   |   | -   | -   |  |  |
| DESIGNATION:  | Scheduled Monument<br>Generally unsatisfactory with major localised   | LIST ENTRY NUMBER:  | 1021458   |  |  |
| DESIGNATION:<br>CONDITION:  | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems   | LIST ENTRY NUMBER:<br>TREND:  | 1021458<br>Stable                                   |  |  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:  | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems<br>Metal detecting - unlicensed   | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:                       | 1021458<br>Stable<br>No                             |  |  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:                               | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems<br>Metal detecting - unlicensed<br>Commercial company   | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:                       | 1021458<br>Stable<br>No                             |  |  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:<br>SITE NAME:                 | Scheduled Monument      Generally unsatisfactory with major localised problems      Metal detecting - unlicensed      Commercial company      Roman villa west of Woodrising Wood, Cranworth  | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:                       | 1021458<br>Stable<br>No<br>David Kenny 01223 582760 |  |  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:<br>SITE NAME:<br>DESIGNATION: | Scheduled Monument      Generally unsatisfactory with major localised problems      Metal detecting - unlicensed      Commercial company      Roman villa west of Woodrising Wood, Cranworth      Scheduled Monument      Generally satisfactory but with significant localised | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:<br>LIST ENTRY NUMBER: | 1021458<br>Stable<br>No<br>David Kenny 01223 582760 |  |  |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

37

| SITE NAME:               | Leylands Farm Romano-British site, Hockwold, Wo                | eeting-with-Brooml | nill / Hockwold cum Wilton       |
|--------------------------|--|--------------------|----------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1003621                          |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:             | Declining                        |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:       | No                               |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:           | David Kenny 01223 582760         |
| SITE NAME:               | Dereham, Dereham / Scarning                                    |                    |                                  |
| DESIGNATION:             | Conservation Area, 97 LBs                                      | NEW ENTRY?:        | No                               |
| CONDITION:               | Poor   | TREND:             | Deteriorating                    |
| VULNERABILITY:           | Medium   | CONTACT:           | Andrew Gayton (LPA) 01362 656257 |
| SITE NAME:               | Thetford   |                    |                                  |
| DESIGNATION:             | Conservation Area, 170 LBs, 9 SMs                              | NEW ENTRY?:        | No                               |
| CONDITION:               | Poor   | TREND:             | Deteriorating significantly      |
| VULNERABILITY:           | Low  | CONTACT:           | Andrew Gayton (LPA) 01362 656257 |
|                          |  |                    |                                  |

## BROADLAND

|                                       | SITE NAME:         | Drayton Lodge, Drayton High<br>Road, Drayton        | Ruinous lodge constructed early C15. In need of structural repairs including wall capping and repointing. Historic  |
|---------------------------------------|--------------------|---|---|
|                                       | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II* | England has provided advice to the Local Authority<br>conservation officer on repair techniques who is liaising<br>with the owner regarding repairs. Historic England offered |
|                                       | CONDITION:         | Poor  | a grant December 2014 towards repairs and repairs now underway. Scheme expected to be completed by the end  |
|                                       | OCCUPANCY:         | N/A   | of March 2016.  |
|                                       | PRIORITY CATEGORY: | F (A)   |   |
| · · · · · · · · · · · · · · · · · · · | OWNER TYPE:        | Commercial company                                  |   |
| © Historic England                    | LIST ENTRY NUMBER: | 1003999 and 1306023                                 | Contact: Trudi Hughes 01223 582739  |

|                    | SITE NAME:         | Stockhouse at Manor Farm, The<br>Green, Freethorpe | Farm building, 1828. Built for the Walpole family who owned Freethorpe in the C19. This is the most complete |
|--------------------|--------------------|--|--|
|                    | DESIGNATION:       | Listed Building grade II*                          | example of probably no more than six surviving stock houses of this type. Repair works and converison        |
|                    | CONDITION:         | Fair   | underway but not yet completed.  |
|                    | OCCUPANCY:         | Vacant/not in use                                  |  |
|                    | PRIORITY CATEGORY: | F (F)  |  |
|                    | OWNER TYPE:        | Private  |  |
| © Historic England | LIST ENTRY NUMBER: | 1152503  | Contact: David Eve 01223 582721  |
|                    |                    |  |  |



|     |                    | 1132303  | Contact. David Eve 01225 502721  |
|-----|--------------------|--|--|
|     | SITE NAME:         | Parish Church of St Agnes,<br>Church Lane, Cawston | Large medieval church built on wealth of iron trade. Tower paid for by the Earl of Suffolk in C15. Hammerbeam roof   |
|     | DESIGNATION:       | Listed Place of Worship grade I,<br>CA             | and painted screen. Stonework decay to base of south<br>porch. Some vegetation in tower and signs of plaster<br>movement and water ingress. Suspected faulty drainage. |
|     | CONDITION:         | Poor   | No action/strategy identified or agreed.   |
|     | PRIORITY CATEGORY: | C (C)  |  |
| a a | OWNER TYPE:        | Religious organisation                             |  |
|     | LIST ENTRY NUMBER: | 1263465  | Contact: Trudi Hughes 01223 582739   |
|     |                    |  |  |

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

|       | SITE NAME:         | Church of St Margaret, School<br>Road, Drayton | Parish church with medieval fabric, though mainly rebuilt in C19. Built of flint with stone dressings. Nave roof thatch.    |
|-------|--------------------|--|---|
|       | DESIGNATION:       | Listed Place of Worship grade II*              | Square tower, with two light west window, lancet sound holes and single light bell openings. Battlemented parapet.          |
|       | CONDITION:         | Poor   | C20 brick and flint vestry. Nave roof in poor condition with clear water ingress. Vestry floor has potential for structural |
|       | PRIORITY CATEGORY: | F (B)  | failure and drains not working. Heritage Lottery Fund   |
|       | OWNER TYPE:        | Religious organisation                         | Grant for Places of Worship offered with work to commence August 2015; completion estimated January                         |
|       | LIST ENTRY NUMBER: | 1306000  | 2016.   |
| -land |                    |  | Contact: Trudi Hughes 01223 582739  |

© Historic England

| 1        | SITE NAME:         | Church of St Peter and St Paul,<br>Church Lane, Oulton | Parish church, comprising nave, chancel, south porch and tower with embattled parapets. The building is of flint       |
|----------|--------------------|--|--|
| A MANNIN | DESIGNATION:       | Listed Place of Worship grade II*                      | rubble, with limestone dressings. The tower has loose masonry at parapet level and possibly below. Site visit          |
| R R H    | CONDITION:         | Very bad   | confirmed that tower parapet has loose masonry and there<br>are other high level structural defects to the tower which |
|          | PRIORITY CATEGORY: | B (A)  | require urgent attention. Heritage Lottery Fund Grant for  |
|          | OWNER TYPE:        | Religious organisation                                 | Places of Worship offered. Project development work underway.  |
|          | LIST ENTRY NUMBER: | 1372723  | Contact: Trudi Hughes 01223 582739   |

© David Lemon

| Arbitrar | SITE NAME:         | Church of St Mary, Church Hill,<br>Reepham | Three churches in a shared churchyard; St Michael (now a community centre), St Mary Reepham and the upstanding  |
|----------|--------------------|--|---|
|          | DESIGNATION:       | Listed Place of Worship grade I,<br>CA     | ruins of All Saints Hackford (destroyed in the 1540s).<br>Tower underwent a programme of repairs in the 1950s<br>which included renewal of roof (now failing) and heavy |
|          | CONDITION:         | Poor                                       | cementitious repairs to tower, as a result of which, pieces of masonry periodically fall onto the surrounding area.   |
|          | PRIORITY CATEGORY: | F (New entry)                              | Heritage Lottery Fund Grant for Places of Worship   |
|          | OWNER TYPE:        | Religious organisation                     | offered. Project now underway.  |
|          | LIST ENTRY NUMBER: | 1076872                                    | Contact: Trudi Hughes 01223 582739  |
|          |                    |  |   |

© Nicholas Warns Architects

|  | SITE NAME:         | Church of St Andrew, Reepham<br>Road, Wood Dalling | Parish church. C13, C14 and C15. Flint construction with limestone dressings. Extensive repairs completed in recent    |
|--|--------------------|--|--|
|  | DESIGNATION:       | Listed Place of Worship grade I                    | past to north and south aisles and to the nave. However,<br>the chancel appears to be suffering from roof spread where |
|  | CONDITION:         | Poor   | the roof structure shows visible signs of sagging. Monitoring is underway, although no long term solution currently    |
|  | PRIORITY CATEGORY: | C (C)  | agreed.  |
|  | OWNER TYPE:        | Religious organisation                             |  |
|  | LIST ENTRY NUMBER: | 72  6  | Contact: Trudi Hughes 01223 582739   |
|  |                    |  |  |

© Nicholas Warns Architects



|  | SITE NAME:         | Church of St Helen, The Street,<br>Woodbastwick | C15 church noted for its painted screens. The building is generally in fair to good condition with the exception of the |
|--|--------------------|---|---|
|  | DESIGNATION:       | Listed Place of Worship grade I                 | nave roof which is poor and needs replacing. A Repair<br>Grant for Places of Worship has been offered by the            |
|  | CONDITION:         | Poor  | Heritage Lottery Fund and works are underway; due to complete by end of July 2015.                                      |
|  | PRIORITY CATEGORY: | F (F)   |   |
|  | OWNER TYPE:        | Religious organisation                          |   |
|  | LIST ENTRY NUMBER: | 1154645   | Contact: Trudi Hughes 01223 582739  |

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

39

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BROADLAND / GREAT YARMOUTH

| SITE NAME: Roman settlement at Brampton, Brampton / Buxton with Lammas |  |                    |                          |  |
|--|--|--------------------|--------------------------|--|
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER: | 1003698                  |  |
| CONDITION:   | Extensive significant problems                                 | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY ?:       | No                       |  |
| OWNER TYPE:  |  |                    | David Kenny 01223 582760 |  |
| SITE NAME:   | Wayside cross 160m north west of Stump Cross Fa                | arm, Haveringland  |                          |  |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER: | 1018301                  |  |
| CONDITION:   | Generally satisfactory but with significant localised problems | TREND:             | Stable                   |  |
| PRINCIPAL VULNERABILITY:   | Vandalism  | NEW ENTRY ?:       | Yes                      |  |
| OWNER TYPE:  | Local authority  | CONTACT:           | David Kenny 01223 582760 |  |
| SITE NAME:   | Roman camp and settlement site west of Horstead,               | Horstead with Sta  | anninghall               |  |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER: | 1003928                  |  |
| CONDITION:   | Generally satisfactory but with minor localised problems       | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY:   | Dumping  | NEW ENTRY ?:       | No                       |  |
| OWNER TYPE:  | Mixed, multiple owners   | CONTACT:           | David Kenny 01223 582760 |  |

## GREAT YARMOUTH

|   | SITE NAME:         | Greyfriars Franciscan friary          | Medieval and later wall of friary is suffering from extensive<br>mortar decay requiring an extensive re-pointing<br>conservation project. Discussions ongoing with the owner<br>regarding grant aid for conservation repairs. |
|---|--------------------|---------------------------------------|---|
|   | DESIGNATION:       | Scheduled Monument, LB grade<br>I, CA |   |
|   | CONDITION:         | Poor                                  |   |
|   | OCCUPANCY: N/A     |                                       |   |
|   | PRIORITY CATEGORY: | A (New entry)                         |   |
|   | OWNER TYPE:        | Private                               |   |
| d | LIST ENTRY NUMBER: | 1017910                               | Contact: John Ette 01223 582711   |
|   |                    |                                       |   |

© Historic England



|        | SITE NAME:         | Tower on Great Yarmouth<br>town walls, 2-3, Dene Street,<br>Great Yarmouth | Derelict tower on medieval town walls dating to 1261.<br>Structure in very poor condition and urgent conservation<br>and repairs to the stonework is required. Discussions are |
|--------|--------------------|--|--|
|        | DESIGNATION:       | Scheduled Monument, 4 LBs, 3<br>CAs  | ongoing with owner to agree a suitable repair strategy.  |
|        | CONDITION:         | Very bad   |  |
| 100000 | OCCUPANCY:         | Vacant/not in use  |  |
|        | PRIORITY CATEGORY: | C (C)  |  |
|        | OWNER TYPE:        | Private  |  |
|        | LIST ENTRY NUMBER: | 1003782  | Contact: John Ette 01223 582711  |

© Historic England



|  | SITE NAME:         | Medieval vaults under, 50-56,<br>Howard Street South, Great<br>Yarmouth | C12 and C14 vaulted undercroft of possible medieval<br>merchant's house. Water penetration, condensation and<br>the poor condition of existing timber shores mean that the |  |
|--|--------------------|---|--|--|
|  | DESIGNATION:       | Scheduled Monument, CA  | structure is at risk of structural failure. Owners considering a scheme of structural propping.  |  |
|  | CONDITION:         | Poor  |  |  |
|  | OCCUPANCY:         | N/A   |  |  |
|  | PRIORITY CATEGORY: | C (D)   |  |  |
|  | OWNER TYPE:        | Private, multiple owners  |  |  |
|  | LIST ENTRY NUMBER: | 1003935   | Contact: Will Fletcher 01223 582710  |  |
|  |                    |   |  |  |

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / GREAT YARMOUTH

OWNER TYPE:

LIST ENTRY NUMBER:

|                     | SITE NAME:         | The Winter Gardens, Marine<br>Parade, Great Yarmouth   | Cast iron seaside winter gardens, situated on the seafront within the conservation area. Cruciform plan, with lantern        |
|---------------------|--------------------|--|--|
| A REAL MARKED AND A | DESIGNATION:       | Listed Building grade II*, CA                          | over crossing. Cast iron components corroding due to excess moisture leaking into structure. Owner looking at                |
|                     | CONDITION:         | Poor   | possibility of reinstating winter gardens function. Currently<br>the owner is discussing options which may result in bid for |
|                     | OCCUPANCY:         | Vacant/not in use                                      | Heritage Lottery Fund funding.   |
|                     | PRIORITY CATEGORY: | C (C)  |  |
|                     | OWNER TYPE:        | Local authority  |  |
| © Historic England  | LIST ENTRY NUMBER: | 1271608  | Contact: Clare Campbell 01223 582738   |
|                     |                    |  |  |
|                     | SITE NAME:         | Old St Margaret's Church,<br>Coast Road, Hopton-on-Sea | Ruins of C12 to C14 church partly destroyed by fire in the C19. A local building preservation society is working with        |
| 5.9                 | DESIGNATION:       | Listed Building grade II*                              | the community to develop a programme of repair for the ruins. Removal of vegetation and survey work already                  |
|                     | CONDITION:         | Poor   | largely complete. Grant offered by Historic England towards major repairs in March 2014 and repairs nearly                   |
|                     | OCCUPANCY:         | Vacant/not in use                                      | complete.  |
|                     | PRIORITY CATEGORY: | F (B)  |  |
|                     |                    |  |  |

Religious organisation

1050970

© Historic England

|  | SITE NAME:         | Church of St Peter and St Paul,<br>Church Road, Burgh Castle | Parish church. Late CI I west tower and CI3 nave and chancel re-modelled in CI5. North aisle 1847. Flint                    |
|--|--------------------|--|---|
|  | DESIGNATION:       | Listed Place of Worship grade II*                            | construction with ashlar dressings and some brick. Slate roofs. Heritage Lottery Fund Grant for Places of Worship           |
|  | CONDITION:         | Poor   | grant offered in 2013. Repairs to address structural failure in north aisle and failure at the chancel north east corner as |
|  | PRIORITY CATEGORY: | C (F)  | well as the subsidence at the foot of the chancel east gable  |
|  | OWNER TYPE:        | Religious organisation                                       | now complete. However, there appears to be active movement in the chancel south wall which requires                         |
|  | LIST ENTRY NUMBER: | 1051008  | addressing before removal from the Register can be considered.  |
|  |                    |  | considered.   |

Contact: Malcolm Starr 01223 582723

Contact: Trudi Hughes 01223 582739

© Nicholas Warns Architects

|  | SITE NAME:  | Church of All Saints, Church<br>Lane, Filby | Parish church of C13 origin or earlier, with C14 and C15<br>alterations, and some C19 restoration, but the lower<br>panels of the medieval rood survive with their original<br>polychrome decoration and depictions of saints. In May |
|--|---|---|---|
|  | DESIGNATION:Listed Place of Worship grade IICONDITION:Very badPRIORITY CATEGORY:A (A) | Listed Place of Worship grade II*           |   |
|  |   | Very bad                                    | 2014, Historic England produced a report confirming that rainwater goods, tower masonry, and chancel roof are in  |
|  |   | A (A)                                       | poor condition. Discussions ongoing regarding next steps.   |
|  | OWNER TYPE:   | Religious organisation                      |   |
|  | LIST ENTRY NUMBER:  | 1287564                                     | Contact: Malcolm Starr 01223 582723   |

© Historic England

|        | SITE NAME:         | Church of St Nicholas, Church<br>Plain, Great Yarmouth | Parish church founded in 1101 in association with adjacent<br>Benedictine priory. Considered by Pevsner to be the  |
|--------|--------------------|--|--|
|        | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA               | largest parish church in England. Base of tower early C12;<br>remainder C13; restored in C19. Extensively fire damaged<br>in World War II. First phase of urgent repairs completed |
|        | CONDITION:         | Poor   | July 2013. However, further urgent repairs are needed including stonework repairs to central tower; tower north  |
|        | PRIORITY CATEGORY: | A (A)  | east turret repairs; high level flashing repairs; repairs to   |
| 000000 | OWNER TYPE:        | Religious organisation                                 | north transept buttress stonework; various other high level stonework repairs required. Solution to be agreed.   |
|        | LIST ENTRY NUMBER: | 1096813  | Contact: Trudi Hughes 01223 582739   |

© Historic England

| PR | IOR | ITY | C | ATE | GOR | IES |  |
|----|-----|-----|---|-----|-----|-----|--|
|    |     |     |   |     |     |     |  |

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 / EAST OF ENGLAND / GREAT YARMOUTH / KING'S LYNN AND WEST NORFOLK

| - Martin                    | SITE NAME:         | Church of St Mary including<br>church rooms and surrounding<br>wall, Regent Road, Great<br>Yarmouth | Roman Catholic Church, Perpendicular style with late<br>Decorated features, built 1848-1850 by JJ Scoles for the<br>Society of Jesus. Built of knapped flint with limestone ashlar<br>dressings, C20 concrete tiles to the roof. Chancel to the |
|-----------------------------|--------------------|---|---|
|                             | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA  | east end and a tower to the west, nave and side aisles.<br>Urgent and wide-scale structural and weathering proble<br>Repair Grant for Places of Worship offered 2011 to   |
|                             | CONDITION:         | Poor  | stabilise west end and re-roof presbytery link. Now   |
|                             | PRIORITY CATEGORY: | C (New entry)   | complete, but other urgent and wide-scale structural and weathering problems remain. Discussions ongoing.   |
| © Nicholas Warns Architects | OWNER TYPE:        | Religious organisation  |   |
| 9 Nicholas Warns Architects | LIST ENTRY NUMBER: | 1245910   | Contact: Trudi Hughes 01223 582739  |
|                             |                    |   |   |
|                             | SITE NAME:         | Church of St John, York Road,<br>Great Yarmouth   | Parish church, 1857 by JH Hakewill with later alterations.<br>Flint with red brick and ashlar dressings. Slate roofs.   |
| 011-0                       | DESIGNATION:       | Listed Place of Worship grade II,<br>CA   | Comprising a nave, apsidal chancel and south porch. I<br>south aisle added by AW Morant, nave extended wes<br>1866, north aisle, transept and north chancel aisle 187   |
|                             | CONDITION:         | Very bad  | Restored 1989. Roofs, gutters and high level stonework in poor condition. Repair Grant for Places of Worship was  |
|                             | PRIORITY CATEGORY: | A (A)   | offered in 2010, with investigation work completed in   |
|                             | OWNER TYPE:        | Religious organisation  | 2012. However, the repair stage of the grant has not beer offered. Discussions to inform solution are ongoing.  |
| - C - A                     | LIST ENTRY NUMBER: | 1271806   | Contact: Trudi Hughes 01223 582739  |
| © Historic England          |                    |   | -   |
|                             | SITE NAME:         | Church of St Margaret, Main<br>Road, Fleggburgh   | Nave and west tower Perpendicular and ruinous. Chancel<br>of C15 origins but substantially of 1872. Flint with ashlar   |
|                             | DESIGNATION:       | Listed Place of Worship grade II*   | dressings. Rethatching of chancel and nave roofs needed together with installation of rainwater goods and drainage  |
| in the second               | CONDITION:         | Poor  | and localised internal repairs.   |
|                             | PRIORITY CATEGORY: | B (New entry)   |   |
|                             | OWNER TYPE:        | Religious organisation  |   |
| A CAT AND A                 | LIST ENTRY NUMBER: | 1372907   | Contact: Robert Parkinson 01223 582733  |
|                             |                    |   |   |

© Historic England

| - In   | SITE NAME:         | Church of St Edmund, Church<br>Road, Thurne | Church featuring early C14 tower with later top with brick triple-stepped battlements. Nave and chancel early C14; |
|--|--------------------|---|--|
| 2 Mar 194  | DESIGNATION:       | Listed Place of Worship grade II*           | rest is Perpendicular. Restored in 1853. Chancel roof showing signs of serious structural decay; ceiling panels    |
| ALL CAR  | CONDITION:         | Very bad                                    | fallen. Grant application to the Heritage Lottery Fund in 2014 was successful and development phase due to         |
|  | PRIORITY CATEGORY: | B (B)                                       | commence summer 2015.  |
| and the second sec | OWNER TYPE:        | Religious organisation                      |  |
| and the second se  | LIST ENTRY NUMBER: | 1304567                                     | Contact: Robert Parkinson 01223 582733   |

© Historic England

## KING'S LYNN AND WEST NORFOLK

| 0 211 11 7 11 20 11 20 |                    |                               |  |
|------------------------|--------------------|-------------------------------|--|
|                        | SITE NAME:         | Denver Hall, Ely Road, Denver | House with original and unusual C16 features, some C18   |
|                        | DESIGNATION:       | Listed Building grade II*     | and C20 alterations. In need of repair and improvement.<br>Roof is in very poor condition. Historic England liaising |
|                        | CONDITION:         | Poor                          | with owners to discuss next steps.   |
|                        | OCCUPANCY:         | Occupied/in use               |  |
|                        | PRIORITY CATEGORY: | A (New entry)                 |  |
|                        | OWNER TYPE:        | Private                       |  |
|                        | LIST ENTRY NUMBER: | 1342309                       | Contact: Claire Fidler 01223 582735  |

© Historic England

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / KING'S LYNN AND WEST NORFOLK

SITE NAME:

DESIGNATION:

CONDITION

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

|  | SITE NAME:         | Gatehouse north of Denver<br>Hall, Ely Road, Denver | Gatehouse circa 1570 in private garden. In need of repair<br>due to lack of maintenance. Historic England has been in |  |  |
|--|--------------------|---|---|--|--|
|  | DESIGNATION:       | Listed Building grade II*                           | discussion with the owner and an application for Historic<br>England grant aid has been received (July 2015).         |  |  |
|  | CONDITION:         | Poor  |   |  |  |
|  | OCCUPANCY:         | Vacant/not in use                                   |   |  |  |
|  | PRIORITY CATEGORY: | D (D)   |   |  |  |
|  | OWNER TYPE:        | Private   |   |  |  |
|  | LIST ENTRY NUMBER: | 1077847   | Contact: Claire Fidler 01223 582735   |  |  |
|  |                    |   |   |  |  |

© Historic England



|  | SITE NAME:         | Denver Mill, Sluice Road,<br>Denver | Grade II* listed mill built in 1835 ceased working in 1941 after being struck by lightning. Repairs undertaken in the   |
|--|--------------------|-------------------------------------|---|
|  | DESIGNATION:       | Listed Building grade II*           | late 1990s but the render has failed and sails removed for<br>health and safety purposes in 2011, when one of the steel |
|  | CONDITION:         | Very bad                            | stocks broke. A further programme of conservation is required to the make the building safe and put the mill into       |
|  | OCCUPANCY:         | Part occupied/part in use           | working order for demonstration purposes. After   |
|  | PRIORITY CATEGORY: | B (A)                               | discussions with the owner to agree a suitable strategy, the WREN Heritage Fund and Historic England offered grant in   |
|  | OWNER TYPE:        | Charity (heritage)                  | 2015. Discussions are ongoing.  |
|  | LIST ENTRY NUMBER: | 1077850                             | Contact: John Ette 01223 582711   |

Ruins of St Mary's Church,

Appleton, Flitcham with

Scheduled Monument

Religious organisation

Hunstanton Hall, Old

Detached porch in courtyard,

Listed Building grade I, RPG

Appleton

Very bad

1020768

Hunstanton

grade II

N/A

A (A)

Private

1077922

Very bad

N/A

B (C)

Ruined church (Sandringham stone, carstone,

regarding next steps.

Contact: John Ette 01223 582711

Repair and consolidation needed.

Contact: David Eve 01223 582721

conglomerate, limestone and flints) showing evidence of

original CII construction. Heavy vegetation cover has been for the most part removed, through a management

especially to north and south nave walls, and repairs to

Freestanding porch built in 1618, in the centre of the

piece and short return walls remain, but with no roof.

courtyard of the Hall. Porch was retained in 1853 after the

wing to which it was attached was demolished. The front

CI4 arcade on the south side. Historic England offered a grant in December 2014 and discussions are ongoing

agreement with Norfolk County Council funded by Historic England. Rough racking to wall tops is needed,

© Historic England



© Norfolk County Council



© Historic England



|             | SITE NAME:         | Chapel of St Andrew, Barret<br>Ringstead, Old Hunstanton | Former chapel, C13 and C14. Roofless and overgrown; in need of consolidation, repair and control of burrowing  |
|-------------|--------------------|--|--|
| No. Changes | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II*      | animals. Historic England is working with local partners to develop a strategy for repair. Condition continuing to deteriorate in June 2015. Actions cannot be implemented |
|             | CONDITION:         | Poor   | until ownership issues are resolved.   |
|             | OCCUPANCY:         | Vacant/not in use  |  |
|             | PRIORITY CATEGORY: | C (C)  |  |
|             | OWNER TYPE:        | Religious organisation                                   |  |
|             | LIST ENTRY NUMBER: | 1003986 and 1077919                                      | Contact: Will Fletcher 01223 582710  |

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UÁ Unitary Authority World Heritage Site WHS
- 43

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / KING'S LYNN AND WEST NORFOLK

| 112                                      | SITE NAME:                         | Ruins of Church of St Edmund,<br>Egmere Road, Egmere,<br>Walsingham / South Creake                          | Ruined church, C12 and C14. The only above-ground<br>remains of the deserted medieval village. The building is a<br>ruin with no possibility of economically beneficial use. It is  |
|--|------------------------------------|---|---|
|  | DESIGNATION:                       | Scheduled Monument and Listed<br>Building grade II*   | in need of consolidation due to loose flints.   |
| 1  | CONDITION:                         | Poor  |   |
| I ho                                     | OCCUPANCY:                         | N/A   |   |
|  | PRIORITY CATEGORY:                 | C (D)   |   |
| Historic England Archive                 | OWNER TYPE:                        | Private   |   |
|  | LIST ENTRY NUMBER:                 | 1018173 and 1039409   | Contact: David Kenny 01223 582760   |
|  | SITE NAME:                         | West Acre Priory, West Acre   | Large Augustinian priory (building began circa 1135). A   |
|  | DESIGNATION:                       | Scheduled Monument and Listed<br>Buildings - I grade I; I grade II*;<br>3 grade II, 3 LBs                   | large lump of flint and stonework fell in early 2005 from<br>what appears to be the ruins of the east range of the<br>cloister. As the lump fell it damaged further smaller areas<br>flintwork. More corework has been exposed and is now |
|  | CONDITION:                         | Very bad  | vulnerable to further loss. Discussions with owner are  |
| the state of the                         | OCCUPANCY:                         | N/A   | ongoing.  |
|  | PRIORITY CATEGORY:                 | A (B)   |   |
| 10 10 10 10 10 10 10 10 10 10 10 10 10 1 | OWNER TYPE:                        | Private   |   |
| Norfolk County Council                   | LIST ENTRY NUMBER:                 | 1008352 and 1077660;<br>1077661; 1342410; 1171741;<br>1077662   | Contact: David Kenny 01223 582760   |
|  | SITE NAME:                         | Church of St Clement, Burnham<br>Overy  | Parish church of medieval origins comprising a nave, south aisle, south porch, central tower, south vestry and chance   |
| 4  | DESIGNATION:                       | Listed Place of Worship grade I   | The central tower is possibly Saxon in origin. The tower is surmounted by a pyramidal roof with a timber lantern.   |
| the second second                        | CONDITION:                         | Poor  | Largely constructed in random flintwork with limestone  |
| A. R. L. W. A. W.                        | PRIORITY CATEGORY:                 | B (B)   | dressings. Moisture ingress is evident at junction of nave<br>and south aisle roof. Roof sheets splitting and admitting   |
|  | OWNER TYPE:                        | Religious organisation  | water. Congregation was offered a Listed Places of Worship Roof Repair grant (March 2015). Works  |
| Rent Contract                            | LIST ENTRY NUMBER:                 | 1239094   | expected to start summer 2015.  |
| Historic England                         |                                    |   | Contact: Trudi Hughes 01223 582739  |
| Citrad .                                 | SITE NAME:                         | Church of All Saints, Church<br>Lane, East Winch  | Parish church of C14 and C15 date with restorations in 1878 by Sir George Gilbert Scott. Constructed from   |
|  | DESIGNATION:                       | Listed Place of Worship grade II*   | rubblestone, carstone and part rendered. Slate roofs.<br>Masonry of the tower, south aisle, and chancel   |
|  | CONDITION:                         | Very bad  | deteriorating badly. Ineffective ground drainage is making<br>the interior damp and places the historic pews at risk. A   |
|  | PRIORITY CATEGORY:                 | B (B)   | Heritage Lottery Fund Grant for Places of Worship has   |
|  | OWNER TYPE:                        | Religious organisation  | been offered for all these repairs. Work is expected to begin summer 2015.  |
|  | LIST ENTRY NUMBER:                 | 1342382   | Contact: Malcolm Starr 01223 582723   |
| Historic England                         |                                    |   |   |
| head                                     | SITE NAME:                         | Church of All Saints, Church<br>Road, Hilgay  | Parish church. Brick west tower of 1794, remainder of carstone with ashlar dressings. Late C14 south aisle, nave  |
| 10                                       | DESIGNATION:                       | Listed Place of Worship grade II*   | and chancel. Slate roofs. Two stage tower supported by angle buttresses to first stage where belfry is set back at  |
| 1  | CONDITION:                         | Poor  | string course. 3-light timber west window. Roundels to  |
| A D. O A                                 | north end south. Arched belfry wir | north end south. Arched belfry windows with timber trell screen. Water and damp penetration with vegetation |   |
|  |                                    | (-)   | growing on fabric of roofs indicating building has lost   |

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

OWNER TYPE:

LIST ENTRY NUMBER:

- D Slow decay: solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Religious organisation

1077719

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

growing on fabric of roofs indicating building has lost

weather integrity. Solution to be agreed.

Contact: John Ette 01223 582711

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 / EAST OF ENGLAND / KING'S LYNN AND WEST NORFOLK

| SITE NAME:         | Church of St Mary The Virgin,<br>Church Lane, Sedgeford | Medieval church. Flint with stone dressings, clunch rubble<br>and stone dressings to chancel, slated nave and porch |
|--------------------|---|---|
| DESIGNATION:       | Listed Place of Worship grade I                         | roofs. Urgent roof repairs needed to the south transept, south porch high level roof and rainwater goods to the     |
| CONDITION:         | Poor  | south side of the church. Further repairs required to nave clerestories, south aisle parapets and south transept    |
| PRIORITY CATEGORY: | B (B)   | buttresses. Consolidation of loose internal plaster is  |
| OWNER TYPE:        | Religious organisation                                  | required where the stability of the wall paintings is at risk.<br>Heritage Lottery Fund grant awarded July 2014.    |
| LIST ENTRY NUMBER: | 1172064   | Development phase due to commence.  |
|                    |   | Contact: Robert Parkinson 01223 582733  |

© Historic England

|      | SITE NAME:         | Church of St Germans,<br>Wiggenhall St. Germans | Grade I listed church built between C13 and C16. Carved pew ends c1500 are of great historical importance. The     |
|------|--------------------|---|--|
| 1    | DESIGNATION:       | Listed Place of Worship grade I                 | church contains font donated in 1851 and also the font from the nearby ruined Wiggenhall St Peter's church.        |
|      | CONDITION:         | Very bad  | Stonework, render, roofs and rainwater goods are in very   |
|      | PRIORITY CATEGORY: | C (C)   | poor condition. The building has also been the subject of heritage crime. No action/strategy identified or agreed. |
| , II | OWNER TYPE:        | Religious organisation                          |  |
| 00   | LIST ENTRY NUMBER: | 1077892   | Contact: Janine Dykes 01223 582724   |
|      |                    |   |  |

© Historic England

| SITE NAME:               | Roman fort (Branodunum), Brancaster                            |                    |                          |
|--------------------------|--|--------------------|--------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1003983                  |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:             | Stable                   |
| PRINCIPAL VULNERABILITY: | Flooding   | NEW ENTRY?:        | No                       |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:           | David Kenny 01223 582760 |
| SITE NAME:               | Moated site and associated earthwork enclosures                | 190m south east of | Denver Hall, Denver      |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1016486                  |
| CONDITION:               | Generally unsatisfactory with major localised problems         | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Development requiring planning permission                      | NEW ENTRY ?:       | No                       |
| OWNER TYPE:              | Private  | CONTACT:           | David Kenny 01223 582760 |
| SITE NAME:               | Remains of St Andrew's Church, East Walton                     |                    |                          |
| DESIGNATION:             | Scheduled Monument, LB grade II                                | LIST ENTRY NUMBER: | 1019836                  |
| CONDITION:               | Generally unsatisfactory with major localised problems         | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Collapse   | NEW ENTRY?:        | No                       |
| OWNER TYPE:              | Private  | CONTACT:           | David Kenny 01223 582760 |
| SITE NAME:               | Romano-British villa 400m west of White House, I               | Fring              |                          |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER: | 1020861                  |
| CONDITION:               | Extensive significant problems                                 | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:       | No                       |
| OWNER TYPE:              | Private  | CONTACT:           | David Kenny 01223 582760 |
|                          |  |                    |                          |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2015 / EAST OF ENGLAND / KING'S LYNN AND WEST NORFOLK / NORFOLK BROADS (NP) / NORTH NORFOLK

| SITE NAME:Well Hall Roman settlement, Grimston / GaytonDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1003168CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Remains of tower on Lodge Hill, SnettishamUST ENTRY NUMBER:1003912DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1003912CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Visitor erosion - moderateNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site of Wormegay Priory, fishponds and as-Jourge Statisfactory but with significant localised<br>problemsID09987DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1009987ONTACT:Dovid Kenny 01223 582760Statisfactory but with significant localised<br>problemsID09987 |                          |   | . ,                |                          |
|---|--------------------------|---|--------------------|--------------------------|
| CONDITION:Generally satisfactory but with significant localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Remains of tower on Lodge Hill, SnettishamUST ENTRY NUMBER:1003912DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1003912CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:DecliningPRINCIPAL VULNERABILITY:Visitor erosion - moderateNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site of Wormegay Priory, fishponds and associated enclosures, WormegayDesignation:Scheduled MonumentUST ENTRY NUMBER:1009987CONDITION:Scheduled MonumentUST ENTRY NUMBER:1009987CONDITION:Generally satisfactory but with significant localised<br>TREND:TREND:Declining   | SITE NAME:               | Well Hall Roman settlement, Grimston / Gayton     |                    |                          |
| CONDITION:  problems  Private  Declining    PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No    OWNER TYPE:  Private  CONTACT:  David Kenny 01223 582760    SITE NAME:  Remains of tower on Lodge Hill, Snettisham  Declining    DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1003912    CONDITION:  Generally unsatisfactory with major localised problems  TREND:  Declining    PRINCIPAL VULNERABILITY:  Visitor erosion - moderate  NEW ENTRY?:  No    OWNER TYPE:  Commercial company  CONTACT:  David Kenny 01223 582760    SITE NAME:  Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay    DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1009987    CONDITION:  Generally satisfactory but with significant localised  TREND:  Declining  | DESIGNATION:             | Scheduled Monument                                | LIST ENTRY NUMBER: | 1003168                  |
| OWNER TYPE:PrivateCONTACT:David Kenny 01223 582760SITE NAME:Remains of tower on Lodge Hill, SnettishamDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003912CONDITION:Generally unsatisfactory with major localised<br>problemsTREND:PRINCIPAL VULNERABILITY:Visitor erosion - moderateNEW ENTRY?:OWNER TYPE:Commercial companyCONTACT:David Kenny 01223 582760SITE NAME:Moated site of Wormegay Priory, fishponds and assciated enclosures.WormegayDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1009987CONDITION:Generally satisfactory but with significant localised<br>Generally satisfactory but with significant localisedTREND:Declining   | CONDITION:               |   | TREND:             | Declining                |
| SITE NAME:    Remains of tower on Lodge Hill, Snettisham      DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1003912      CONDITION:    Generally unsatisfactory with major localised problems    TREND:    Declining      PRINCIPAL VULNERABILITY:    Visitor erosion - moderate    NEW ENTRY?:    No      OWNER TYPE:    Commercial company    CONTACT:    David Kenny 01223 582760      SITE NAME:    Moated site of Wormegay Priory, fishponds and assciated enclosures.    Wormegay      DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1009987      CONDITION:    Generally satisfactory but with significant localised    TBEND:    Declining  | PRINCIPAL VULNERABILITY: | Arable ploughing                                  | NEW ENTRY?:        | No                       |
| DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1003912      CONDITION:    Generally unsatisfactory with major localised problems    TREND:    Declining      PRINCIPAL VULNERABILITY:    Visitor erosion - moderate    NEW ENTRY?:    No      OWNER TYPE:    Commercial company    CONTACT:    David Kenny 01223 582760      SITE NAME:    Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay      DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1009987      CONDITION:    Generally satisfactory but with significant localised    TREND:    Declining  | OWNER TYPE:              | Private   | CONTACT:           | David Kenny 01223 582760 |
| CONDITION:    Generally unsatisfactory with major localised problems    TREND:    Declining      PRINCIPAL VULNERABILITY:    Visitor erosion - moderate    NEW ENTRY?:    No      OWNER TYPE:    Commercial company    CONTACT:    David Kenny 01223 582760      SITE NAME:    Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay      DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1009987      CONDITION:    Generally satisfactory but with significant localised    TREND:    Declining   | SITE NAME:               | Remains of tower on Lodge Hill, Snettisham        |                    |                          |
| CONDITION:  problems  Principal vullerability:  Visitor erosion - moderate  NEW ENTRY?:  No    OWNER TYPE:  Commercial company  CONTACT:  David Kenny 01223 582760    SITE NAME:  Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay    DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1009987    CONDITION:  Generally satisfactory but with significant localised  TREND:  Declining  | DESIGNATION:             | Scheduled Monument                                | LIST ENTRY NUMBER: | 1003912                  |
| OWNER TYPE:    Commercial company    CONTACT:    David Kenny 01223 582760      SITE NAME:    Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay      DESIGNATION:    Scheduled Monument    LIST ENTRY NUMBER:    1009987      CONDITION:    Generally satisfactory but with significant localised    TREND:    Declining   | CONDITION:               |   | TREND:             | Declining                |
| SITE NAME:    Moated site of Wormegay Priory, fishponds and associated enclosures, Wormegay      DESIGNATION:    Scheduled Monument      LIST ENTRY NUMBER:    1009987      CONDITION:    Generally satisfactory but with significant localised   | PRINCIPAL VULNERABILITY: | Visitor erosion - moderate                        | NEW ENTRY?:        | No                       |
| DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1009987    CONDITION:  Generally satisfactory but with significant localised  TREND:  Declining   | OWNER TYPE:              | Commercial company                                | CONTACT:           | David Kenny 01223 582760 |
| CONDITION: Generally satisfactory but with significant localised TREND: Declining   | SITE NAME:               | Moated site of Wormegay Priory, fishponds and ass | ociated enclosures | , Wormegay               |
|   | DESIGNATION:             | Scheduled Monument                                | LIST ENTRY NUMBER: | 1009987                  |
|   | CONDITION:               |   | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: Stock erosion - extensive NEW ENTRY?: No   | PRINCIPAL VULNERABILITY: | Stock erosion - extensive                         | NEW ENTRY?:        | No                       |
| OWNER TYPE: Commercial company CONTACT: David Kenny 01223 582760  | OWNER TYPE:              | Commercial company                                | CONTACT:           | David Kenny 01223 582760 |

## NORFOLK BROADS (NP)



© Historic England

|  | SITE NAME:         | Burgh Mill, The Street, Burgh<br>and Tuttington, North Norfolk | Three storey C18 watermill on the River Bure. Milling has ceased and the vacant building is in disrepair. Condition    |
|--|--------------------|--|--|
|  | DESIGNATION:       | Listed Building grade II*, CA                                  | survey and feasibility report undertaken. Owner has completed first phase of repairs to weatherboarding,               |
|  | CONDITION:         | Very bad   | temporary repairs to rainwater disposal. Internal structural propping still in place. Owner considering a second phase |
|  | OCCUPANCY:         | N/A  | of work.   |
|  | PRIORITY CATEGORY: | B (B)  |  |
|  | OWNER TYPE:        | Private  |  |
|  | LIST ENTRY NUMBER: | 1250712  | Contact: David Eve 01223 582721  |

| DESIGNATION:  Conservation Area, 28 LBs, SM  NEW ENTRY?:  No    CONDITION:  Very bad  TREND:  No significant change    VULNERABILITY:  Medium  CONTACT:  Ben Hogg (LPA) 01603 756074 | SITE NAME:     | Halvergate Marshes, Halvergate, Halvergate / Mauth<br>Herringby / Thurlton / West Caister / Acle / Beltor<br>Fritton and St. Olaves / Haddiscoe, Broadland | by / Norton Subco<br>with Browston / | urse / Reedham / Stokesby with<br>Burgh Castle / Fleggburgh / Freethorpe / |
|--|----------------|--|--------------------------------------|--|
| ,  | DESIGNATION:   | Conservation Area, 28 LBs, SM  | NEW ENTRY?:                          | No   |
| VULNERABILITY: Medium CONTACT: Ben Hogg (LPA) 01603 756074   | CONDITION:     | Very bad   | TREND:                               | No significant change  |
|  | VULNERABILITY: | Medium   | CONTACT:                             | Ben Hogg (LPA) 01603 756074  |

## NORTH NORFOLK



| Î | SITE NAME:         | Ruins of Broomholm Priory,<br>Abbey Street, Bacton                                 | Priory remains, primarily C12-C13 in date. The general condition of the site has been stabilised though the   |  |
|---|--------------------|--|---|--|
|   | DESIGNATION:       | Scheduled Monument and Listed<br>Buildings - I grade I; I grade II*,<br>part in CA | introduction of a Section 17 management agreement<br>offered by Historic England. Stabilisation of the ruins is<br>urgently needed and a strategy for implementation in<br>16 is currently being developed. |  |
|   | CONDITION:         | Poor   | , 2 .   |  |
|   | OCCUPANCY:         | Part occupied/part in use  |   |  |
|   | PRIORITY CATEGORY: | B (B)  |   |  |
|   | OWNER TYPE:        | Private  |   |  |
|   | LIST ENTRY NUMBER: | 1003974 and 1373815; 1049146   | Contact: Will Fletcher 01223 582710   |  |

## PRIORITY CATEGORIES

© Historic England Archive

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park

  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

|          | SITE NAME: Church of All Saints,<br>Cockthorpe, Binham |                         | Medieval former church, now in the care of the Norfolk<br>Churches Trust. Heritage Lottery Fund has awarded a       |
|----------|--|-------------------------|---|
|          | DESIGNATION:   | Listed Building grade I | grant for repairs and increased access and interpretation.<br>The project development for this work is now complete |
|          | CONDITION:   | Very bad                | and repairs commenced in summer 2015.   |
|          | OCCUPANCY:   | Vacant/not in use       |   |
| a martin | PRIORITY CATEGORY:                                     | F(C)                    |   |
| A        | OWNER TYPE:  | Charity (heritage)      |   |
| land     | LIST ENTRY NUMBER:                                     | 1373671                 | Contact: Scilla Latham 01379 677272   |
|          |  |                         |   |

© Historic Englar



© Nicholas Warns Architects

| C<br>C<br>P | SITE NAME:         | Church of St Peter, Corpusty and Saxthorpe | Medieval former church, taken on by the Norfolk<br>Churches Trust who have completed an extensive scheme                    |
|-------------|--------------------|--|---|
|             | DESIGNATION:       | Listed Building grade II*                  | of external fabric repairs. Building now in need of re-<br>roofing. Talks still on-going with village as to whether they    |
|             | CONDITION:         | Poor                                       | are able to take on building, and if so: potential use(s). The<br>Trust secured a Listed Places of Worship Roof Repair Fund |
|             | OCCUPANCY:         | Vacant/not in use                          | grant in March 2015 towards the cost of re-roofing.   |
|             | PRIORITY CATEGORY: | B (A)                                      | Works expected to start summer 2015.  |
|             | OWNER TYPE:        | Charity (heritage)                         |   |
| _           | LIST ENTRY NUMBER: | 1049202                                    | Contact: Trudi Hughes 01223 582739  |

The gasworks produced town gas from 1825 until 1965 SITE NAME: Fakenham gas works, Hempton Road, Fakenham and is now the only remaining town gas works of its kind in England. Acquired in 1983 and repaired, it was opened as a Scheduled Monument, part in museum in 1989. Damp and ground movement are causing DESIGNATION: CA structural weakness to key industrial buildings and machinery. Corrosion of metalwork and metal CONDITION: Poor components. Major issues surround the retort housing and OCCUPANCY: Occupied/in use its ashpit. PRIORITY CATEGORY: A (A) OWNER TYPE: Charity (heritage) © Historic England LIST ENTRY NUMBER: Contact: Nick Carter 01223 582751 1003908

|                    | SITE NAME:         | Melton Constable Hall, Melton<br>Constable Park, Melton<br>Constable | Country house 1664-1670, enlarged to east in 1810.<br>Service and stable range to north. South and west of Hall<br>are formal C19 terraces, now grassed over. The Hall is on        |
|--------------------|--------------------|--|---|
|                    | DESIGNATION:       | Listed Building grade I, RPG<br>grade II*, CA                        | slightly elevated ground overlooking parkland and a lake to<br>the south. The Hall is presently not used and is in need of<br>repair, although some work has been undertaken to the |
|                    | CONDITION:         | Poor   | east wing.  |
|                    | OCCUPANCY:         | Part occupied/part in use  |   |
|                    | PRIORITY CATEGORY: | C (C)  |   |
| © Historic England | OWNER TYPE:        | Private  |   |
|                    | LIST ENTRY NUMBER: | 1153044  | Contact: David Eve 01223 582721   |
|                    |                    |  |   |

|                 | SITE NAME:         | Site of Manorial Complex, Hall<br>Farm, Waxham, Sea Palling | C16 wall and gatehouse. Major structural repair necessary due to lack of maintenance. Some flint facing falling away. |
|-----------------|--------------------|---|---|
|                 | DESIGNATION:       | Scheduled Monument, 3 LBs                                   | Destructive ivy growth. Several damaged copings. Solution to be agreed with owner.                                    |
|                 | CONDITION:         | Very bad  | -   |
|                 | OCCUPANCY:         | N/A   |   |
|                 | PRIORITY CATEGORY: | A (New entry)   |   |
| Sol Sol         | OWNER TYPE:        | Private   |   |
| istoric England | LIST ENTRY NUMBER: | 1013418   | Contact: Will Fletcher 01223 582710   |

PRIORITY CATEGORIES

© Hist

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

| /          | SITE NAME:         | Sutton Mill, New Road, Sutton | Tower mill of 1789. Restored in 1976-85 and part of a   |
|------------|--------------------|-------------------------------|---|
|            | DESIGNATION:       | Listed Building grade II*     | museum. Since then there has been a lack of maintenance<br>and the museum has closed. The mill's cap became |
|            | CONDITION:         | Poor                          | unstable and has been removed for repair. Discussion about possible redevelopment of the site ongoing.      |
|            | OCCUPANCY:         | Vacant/not in use             | about possible redevelopment of the site of going.  |
|            | PRIORITY CATEGORY: | C (C)                         |   |
|            | OWNER TYPE:        | Private                       |   |
| ALC: MARKE | LIST ENTRY NUMBER: | 1049326                       | Contact: David Eve 01223 582721   |
|            |                    |                               |   |

© Historic England

| A REAL    | SITE NAME:         | Church of St Ethelbert, Church<br>Road, Alby with Thwaite | Parish church of medieval origin. Constructed of flint with stone and brick dressings. Pantile roof. West tower, nave,   |
|-----------|--------------------|---|--|
|           | DESIGNATION:       | Listed Place of Worship grade II*                         | south porch, chancel, vestry. Roof, rainwater goods and<br>high level masonry all in very poor condition. Heritage<br>Lottery Fund grant offered in 2013. Development stage<br>underway. |
|           | CONDITION:         | Very bad  |  |
| Res 1 Car | PRIORITY CATEGORY: | B (B)   |  |
|           | OWNER TYPE:        | Religious organisation                                    |  |
|           | LIST ENTRY NUMBER: | 1049885   | Contact: Robert Parkinson 01223 582733   |
|           |                    |   |  |

© Historic England

| -                  | SITE NAME:         | Church of St Mary, Church<br>Lane, Holt, Baconsthorpe | Parish church dating to 1260. Fine interiors, important monument to William Heydon dated 1593. Tower rebuilt   |
|--------------------|--------------------|---|--|
| 1 1                | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA              | 1740 after collapse. North side very damp. Historic<br>England/Heritage Lottery Fund Repair Grant for Places of<br>Worship offered in December 2011 for repairs to chancel<br>roof, north vestry and surrounding drains complete, but<br>excess dampness affects the building through inadequately<br>weathering copings on south aisle putting at risk a fine C16<br>monument; gutters to nave and aisles leak and the below<br>ground drainage is ineffective. Remains at risk and further |
|                    | CONDITION:         | Fair  |  |
|                    | PRIORITY CATEGORY: | A (F)   |  |
| C LUG              | OWNER TYPE:        | Religious organisation                                |  |
|                    | LIST ENTRY NUMBER: | 1049847   | discussions ongoing.   |
| © Historic England |                    |   | Contact: Trudi Hughes 01223 582739   |

| DESIGNATION:      Listed Place of Worship grade I      chapel 1440- 45. Restored 1890 and 1934. Flint with ash dressings and slate roofs. Three-stage tower supported flushwork diagonal buttresses on flushwork plinth. Significant problems with structural stability water penetration and the roof.              |                   |  |   |       |
|--|-------------------|--|---|-------|
| DESIGNATION:    Listed Place of Worship grade I    dressings and slate roofs. Three-stage tower supported I      CONDITION:    Poor    flushwork diagonal buttresses on flushwork plinth.      PRIORITY CATEGORY:    A (New entry)    Significant problems with structural stability water penetration and the roof. |                   |  | tower. Aisles and chancel remodelled 1494, South chancel<br>chapel 1440- 45. Restored 1890 and 1934. Flint with ashlar<br>dressings and slate roofs. Three-stage tower supported by<br>flushwork diagonal buttresses on flushwork plinth.<br>Significant problems with structural stability water | ancel |
| PRIORITY CATEGORY: A (New entry) Significant problems with structural stability water penetration and the roof.  | 1                 | DESIGNATION: Listed Place of Worship grade I |   |       |
| PRIORITY CATEGORY: A (New entry) penetration and the roof.   | and the second    | CONDITION: Poor                              |   |       |
|  |                   | PRIORITY CATEGORY: A (New entry)             |   |       |
| OWNER TYPE: Religious organisation   | and the second    | OWNER TYPE: Religious organisation           |   |       |
| LIST ENTRY NUMBER: 1049931 Contact: Robert Parkinson 01223 582733  | Wind Stores Rates | LIST ENTRY NUMBER: 1049931                   | Contact: Robert Parkinson 01223 582733  |       |

© Historic England



| SITE NAME:         | Church of All Saints,<br>Hempstead          | Parish church dated to CI4. CI8 north-west and former south aisle now nave. CI4 south doorway. Windows   |
|--------------------|---|--|
| DESIGNATION:       | Listed Place of Worship grade<br>II*, 2 CAs | renewed in C18. Historic England/Heritage Lottery Fund<br>Repair Grant for Places of Worship offered and repairs<br>underway to tower, nave drainage and high level masonry. |
| CONDITION:         | Fair  | Repairs anticipated for completion by end of 2015.   |
| PRIORITY CATEGORY: | F (F)                                       |  |
| OWNER TYPE:        | Religious organisation                      |  |
| LIST ENTRY NUMBER: | 1049211                                     | Contact: Trudi Hughes 01223 582739   |

© Historic England

| PRIORITY | CATEGORIES |
|----------|------------|
|          |            |

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 48

| 4   | SITE NAME:         | Church of St Peter and St Paul,<br>Long Lane, Honing | Parish church dating to the C15, heavily restored in 1795.<br>Constructed from knapped flint with ashlar dressings and a  |
|-----|--------------------|--|---|
|     | DESIGNATION:       | Listed Place of Worship grade II*                    | slate roof. Maintained in regular use, but roof in poor<br>condition and interior suffering from water ingress. In June<br>2015 the congregation received an offer of a Heritage<br>Lottery Fund Grant for Places of Worship for re-roofing |
|     | CONDITION:         | Poor   |   |
| 1 m | PRIORITY CATEGORY: | B (New entry)  | nave and chancel; new drainage and for tower repairs.   |
|     | OWNER TYPE:        | Religious organisation                               | Development work underway.  |
|     | LIST ENTRY NUMBER: | 1169952  | Contact: Trudi Hughes 01223 582739  |

© Historic England

© Historic Engla

|         | SITE NAME:         | Church of St Peter and St Paul,<br>The Street, Knapton | Parish church. Early C14 north-west tower and chancel,<br>nave re-modelled C15 when chancel altered. Restored |
|---------|--------------------|--|---|
|         | DESIGNATION:       | Listed Place of Worship grade I                        | 1882 by Sir George Gilbert Scott. South nave roof very poor and failing. Previous serious water ingress, with |
|         | CONDITION:         | Poor   | potential damage to important roof carvings. Rainwate<br>goods all poor and in need of replacement. Cracks in |
| 10410 - | PRIORITY CATEGORY: | B (B)  | chancel arch. Very significant stonework problems in  |
|         | OWNER TYPE:        | Religious organisation                                 | tower. Rusting of ferrous beams supporting bell frame probably responsible. Heritage Lottery Fund Grant for   |
|         | LIST ENTRY NUMBER: | 1306264  | Places of Worship grant offered July 2014 and development works due to commence summer 2015.                  |
| land    |                    |  | Contact: Robert Parkinson 01223 582733  |
|         |                    |  |   |

| d |                    |  | development works due to commence summer 2015.  |
|---|--------------------|--|---|
|   |                    |  | Contact: Robert Parkinson 01223 582733  |
|   | SITE NAME:         | Church of St Andrew, Church<br>Lane, Hempstead-next-the-Sea,<br>Lessingham | Medieval church with chancel dating from C13; nave, porch<br>and tower C15. Nave and chancel thatched; unusually wide<br>nave at 26ft. C14 screen. Thatch seriously defective and |
|   | DESIGNATION:       | Listed Place of Worship grade II*  | leaking; tower high level masonry needs repointing, stone falling. Historic England/Heritage Lottery Fund Repair  |
|   | CONDITION:         | Fair   | Grant for Places of Worship scheme offered in December 2011. Repair work is due to be completed in third quarter  |
|   | PRIORITY CATEGORY: | F (F)  | of 2015.  |
|   | OWNER TYPE:        | Religious organisation   |   |
|   | LIST ENTRY NUMBER: | 1373720  | Contact: Trudi Hughes 01223 582739  |

© Ruth & Peter Blackman

|  | SITE NAME:         | Church of St Mary Barningham<br>Winter, Matlask    | Parish church in grounds of Barningham Hall. Flint with some iron conglomerate, plain tiles. West tower, nave and  |
|--|--------------------|--|--|
|  | DESIGNATION:       | Listed Place of Worship grade<br>II*, RPG grade II | south porch in ruins. Chancel in use with west addition of<br>1830. Chancel of uncoursed flint with diagonal buttresses.<br>Crow stepped gables in red brick, embattled parapet in |
|  | CONDITION:         | Poor   | gault brick; small blocked opening in west wall with brick<br>dressings. Addition of 1830 within nave of knapped and   |
|  | PRIORITY CATEGORY: | B (New entry)                                      | galletted flint with plain tiles to roof; crow stepped gables  |
|  | OWNER TYPE:        | Religious organisation                             | with medieval pierced stone quatrefoil and embattled parapet. Heritage Lottery Fund grant offered in 2013.   |
|  | LIST ENTRY NUMBER: | 1049180  | Development stage underway.  |
|  |                    |  | Contact: Robert Parkinson 01223 582733   |

© Historic England



© Historic England

Parish church featuring west tower containing early C12  $\,$ Church of All Saints, Stibbard flintwork. Belfry openings with C14 Y-tracery windows. Listed Place of Worship grade II\* Chancel C13. Nave with C14 features. Restored in 1742 when buttresses added to tower and again in 1861-2 by Poor Butterfield, including works to roofs and the porch. PRIORITY CATEGORY: B (B) Constructed from flint rubble with brick quoins to postreformation buttresses, otherwise, limestone dressings. Religious organisation Bulging facework on tower identified as well as deterioration to brick and flint buttresses. Tower roof LIST ENTRY NUMBER: 1049230 requires replacement. Heritage Lottery Fund grant awarded July 2014 and development underway.

Contact: Malcolm Starr 01223 582723

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

|        | SITE NAME:         | Church of St Giles, Church<br>Road, Swafield | Parish church C14 with west tower of late C15. Flint with ashlar quoins and slate roofs. Nave and chancel. Nave |
|--------|--------------------|--|---|
| 1000   | DESIGNATION:       | Listed Place of Worship grade II*            | aisles removed and church partly rebuilt 1786. Four-stage tower with string courses between floors. Serious     |
| to the | CONDITION:         | Poor   | problems with water penetration in tower and nave stonework poor. Solution to be agreed.                        |
|        | PRIORITY CATEGORY: | A (A)  |   |
| No.    | OWNER TYPE:        | Religious organisation                       |   |
|        | LIST ENTRY NUMBER: | 1306217                                      | Contact: Robert Parkinson 01223 582733  |
|        |                    |  |   |

© Historic England

1

| 1                      | SITE NAME:         | Church of All Saints, Kirkgate,<br>Wighton | A largely C15 church, comprising tower, south porch, north and south aisles, nave and chancel. Building suffering   |
|------------------------|--------------------|--|---|
|                        | DESIGNATION:       | Listed Place of Worship grade I,<br>CA     | from damp due to inadequate below-ground drainage<br>system. South aisle roof slates laid at too slack a pitch and<br>letting in water. Nave roof north side is slated with fixings |
| a lar                  | CONDITION:         | Very bad                                   | failing. Internally the tower east wall cement render loose<br>and in places at imminent risk of falling. Heritage Lottery  |
|                        | PRIORITY CATEGORY: | F (B)                                      | Fund development phase grant offered early in 2014. Work  |
| Mar Star               | OWNER TYPE:        | Religious organisation                     | due for completion summer 2015.   |
| holas Warns Architects | LIST ENTRY NUMBER: | 1171738                                    | Contact: Trudi Hughes 01223 582739  |
|                        |                    |  |   |

© Nicholas Warns Architects

| SITE NAME:  | Gatehouse at manor house, East Barsham, Barsh   | am  |   |
|---|---|---|---|
| DESIGNATION:  | Scheduled Monument, LB grade I, CA  | LIST ENTRY NUMBER:  | 1003997   |
| CONDITION:  | Generally unsatisfactory with major localised problems  | TREND:  | Declining   |
| PRINCIPAL VULNERABILITY:  | Deterioration - in need of management   | NEW ENTRY?:   | No  |
| OWNER TYPE:   | Private   | CONTACT:  | David Kenny 01223 582760  |
| SITE NAME:  | Cross in St Giles' churchyard, Colby  |   |   |
| DESIGNATION:  | Scheduled Monument  | LIST ENTRY NUMBER:  | 1018300   |
| CONDITION:  | Generally unsatisfactory with major localised problems  | TREND:  | Declining   |
| PRINCIPAL VULNERABILITY:  | Deterioration - in need of management   | NEW ENTRY?:   | No  |
| OWNER TYPE:   | Religious organisation  | CONTACT:  | David Kenny 01223 582760  |
|   |   |   |   |
| SITE NAME:  | RAF Neatishead Type 84 radar modulator buildir  | ng and four radar plin  | ths, Neatishead   |
| SITE NAME:<br>DESIGNATION:  | RAF Neatishead Type 84 radar modulator buildir<br>Scheduled Monument  | ng and four radar plin  | ths, Neatishead<br>1021408  |
| DESIGNATION:  |   |   |   |
| DESIGNATION:<br>CONDITION:  | Scheduled Monument<br>Generally unsatisfactory with major localised   | LIST ENTRY NUMBER:  | 1021408   |
| DESIGNATION:<br>CONDITION:  | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems   | LIST ENTRY NUMBER:  | 1021408<br>Declining  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:                               | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems<br>Deterioration - in need of management  | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:   | 1021408<br>Declining<br>No<br>David Kenny 01223 582760  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:<br>SITE NAME:                 | Scheduled Monument<br>Generally unsatisfactory with major localised<br>problems<br>Deterioration - in need of management<br>Mixed, multiple owners<br>Remains of a medieval ringwork castle known as                                      | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:   | 1021408<br>Declining<br>No<br>David Kenny 01223 582760  |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:<br>SITE NAME:                 | Scheduled Monument      Generally unsatisfactory with major localised problems      Deterioration - in need of management      Mixed, multiple owners      Remains of a medieval ringwork castle known as Wighton                         | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:<br>Crabb's Castle, 680m                       | 1021408<br>Declining<br>No<br>David Kenny 01223 582760<br>north east of Crabb's Castle Farm,            |
| DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY:<br>OWNER TYPE:<br>SITE NAME:<br>DESIGNATION: | Scheduled Monument      Generally unsatisfactory with major localised problems      Deterioration - in need of management      Mixed, multiple owners      Remains of a medieval ringwork castle known as Wighton      Scheduled Monument | LIST ENTRY NUMBER:<br>TREND:<br>NEW ENTRY?:<br>CONTACT:<br>Crabb's Castle, 680n<br>LIST ENTRY NUMBER: | 1021408<br>Declining<br>No<br>David Kenny 01223 582760<br>north east of Crabb's Castle Farm,<br>1018175 |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / NORTH NOREOLK / NORWICH

Very bad

Medium

| A CONTRACTOR                 | SITE NAME:                            | Wolterton Hall, Wickmere /<br>Erpingham / Itteringham   | Early C18 park and woodland designed as a collaboration<br>between Thomas Ripley, Charles Bridgeman and Horatio<br>Walpole, surrounding an early C18 Palladian mansion with<br>mid C19 gardens laid out by William Sawrey Gilpin. The<br>park is a Country Park with a focus on wildlife<br>management, some fields arable others pasture. Loss of<br>definition of lake margins. Some replanting of clumps to<br>west and avenue to north of house. Built structures in ver |  |  |
|------------------------------|---------------------------------------|---|--|--|--|
| Sectore 1                    | DESIGNATION:                          | Registered Park and Garden<br>grade II*, 13 LBs, SM, CA |  |  |  |
|                              | CONDITION:                            | Generally unsatisfactory with major localised problems  |  |  |  |
| A La La                      | VULNERABILITY:                        | High  | poor condition   | poor condition, Peach House in kitchen garden particular |  |
|                              | TREND:                                | Stable  | vulnerable.  |  |  |
| © Historic England           | NEW ENTRY?:                           | No  |  |  |  |
|                              | OWNER TYPE:                           | Private   |  |  |  |
|                              | LIST ENTRY NUMBER:                    | 1001022   | Contact: David Eve 01223 582721  |  |  |
|                              |                                       |   |  |  |  |
| SITE NAME:                   | Cromer                                |   |  |  |  |
| DESIGNATION:                 | Conservation Are                      | ea, 77 LBs  | NEW ENTRY?:  | No   |  |
| CONDITION:                   | Poor                                  |   | TREND:   | Deteriorating  |  |
| VULNERABILITY:               | Low                                   |   | CONTACT:   | Paul Rhymes (LPA) 01263 516367                           |  |
| SITE NAME:                   | Fakenham                              |   |  |  |  |
| DESIGNATION:                 | Conservation Area, 84 LBs, part in SM |   | NEW ENTRY?:  | No   |  |
| CONDITION:                   | Very bad                              |   | TREND:   | Deteriorating  |  |
| VULNERABILITY:               | Medium                                |   | CONTACT:   | Paul Rhymes (LPA) 01263 516367                           |  |
| SITE NAME:                   | Happisburgh                           |   |  |  |  |
| DESIGNATION:                 | Conservation Ar                       | Conservation Area, 9 LBs, RPG grade I                   |  | No   |  |
| CONDITION:                   | Very bad                              |   | TREND:   | Deteriorating  |  |
|                              |                                       |   | CONTACT:   |  |  |
| VULNERABILITY:               | Medium                                |   | CONTACT:   | Paul Rhymes (LPA) 01263 516367                           |  |
| VULNERABILITY:<br>SITE NAME: |                                       | e Park, Melton Constable / Swant                        |  |  |  |

## NORWICH

VULNERABILITY:

CONDITION:

|    | SITE NAME:         | St Peter Hungate Museum,<br>Prince Street | Grade I former parish church now museum. Building largely C13 and after. The building is held on long lease by  |
|----|--------------------|---|---|
| 7/ | DESIGNATION:       | Listed Building grade I, CA               | Norwich Historic Churches Trust and sub-let to the<br>Hungate Medieval Arts Trust who use the building as a     |
|    | CONDITION:         | Very bad                                  | medieval arts museum and exhibition space. Batten and fixing failure to chancel roof tiles which means that re- |
|    | OCCUPANCY:         | Part occupied/part in use                 | roofing is a high priority. Historic England grant offered  |
|    | PRIORITY CATEGORY: | F (A)                                     | June 2015 and project development work underway with the aim being to complete the re-roofing by the end of     |
|    | OWNER TYPE:        | Charity (heritage)                        | March 2016.   |
|    | LIST ENTRY NUMBER: | 1220104                                   | Contact: Trudi Hughes 01223 582739  |

TREND:

CONTACT:

No significant change

Paul Rhymes (LPA) 01263 516367

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / NORWICH

|                        | SITE NAME:         | Bishop Salmon's Porch,<br>Norwich                       | Early C14 porch to former hall. Two storeys with two ground floor open bays. Window reveals and mullions,   |
|------------------------|--------------------|---|---|
| © Norwich City Council | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II*, CA | capitals, shafts and other areas of carved stonework are<br>badly decayed. The roof upper chamber vault and windows<br>are suffering from water ingress, and the raised ground to |
|                        | CONDITION:         | Poor  | north and south is allowing damp to penetrate the structure. A programme of repairs is being progressed,  |
|                        | OCCUPANCY:         | N/A   | including a scheme for placing a roof over the structure  |
|                        | PRIORITY CATEGORY: | E (E)   | make it wind and weathertight in the longer term.<br>Discussions on going.  |
|                        | OWNER TYPE:        | Religious organisation                                  |   |
|                        | LIST ENTRY NUMBER: | 1004030 and 1051329                                     | Contact: Will Fletcher 01223 582710   |

|                 | SITE NAME:         | Bethel Hospital, Bethel Street,<br>Norwich | Former hospital of C17/early C18, partly converted to residential use with new uses agreed for other parts but |
|-----------------|--------------------|--|--|
|                 | DESIGNATION:       | Listed Building grade II*, CA              | not fully implemented. The C19 wing is in poor condition needing substantial repairs. The gable end of the C18 |
|                 | CONDITION:         | Poor                                       | boardroom also in poor condition and in need of structural reinforcement.                                      |
|                 | OCCUPANCY:         | Part occupied/part in use                  |  |
|                 | PRIORITY CATEGORY: | C (C)                                      |  |
|                 | OWNER TYPE:        | Commercial company                         |  |
| ch City Council | LIST ENTRY NUMBER: | 1051362                                    | Contact: David Eve 01223 582721  |
|                 |                    |  |  |



| 1.1.1                  | SITE NAME:         | St Mary the Less, Queen Street,<br>Norwich | Former parish church with C13 origins, currently used as<br>an historical studies centre. The building is in need of |
|------------------------|--------------------|--|--|
| © Norwich City Council | DESIGNATION:       | Listed Building grade I, CA                | repair, especially the roof. Tower masonry viewed from adjoining building and appeared to be in reasonable order.    |
|                        | CONDITION:         | Fair                                       | No action/strategy has been identified or agreed.  |
|                        | OCCUPANCY:         | Occupied/in use                            |  |
|                        | PRIORITY CATEGORY: | C (C)                                      |  |
|                        | OWNER TYPE:        | Private                                    |  |
|                        | LIST ENTRY NUMBER: | 1051918                                    | Contact: Trudi Hughes 01223 582739   |

| SITE NAME:     | Mile Cross                      |              |                                  |
|----------------|---------------------------------|--------------|----------------------------------|
| DESIGNATION:   | Conservation Area, RPG grade II | NEW ENTRY ?: | No                               |
| CONDITION:     | Poor                            | TREND:       | Deteriorating                    |
| VULNERABILITY: | Low                             | CONTACT:     | Chris Bennett (LPA) 01603 212513 |

## PRIORITY CATEGORIES

© Norwich

© Historic England

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

## SOUTH NORFOLK



|  | SITE NAME:         | Church of St Nicholas, Whip's<br>Lane, Ashwellthorpe and<br>Fundenhall | Parish church dating to C12 featuring Norman south<br>portal. C15 rood screen; only coving supporting rood loft<br>remains. Parish have been awarded a Heritage Lottery |
|--|--------------------|--|---|
|  | DESIGNATION:       | Listed Place of Worship grade I  | Fund Grant for Places of Worship to undertake investigative works in order to ascertain extent of repairs   |
|  | CONDITION:         | Poor   | required, which included structural repairs to chancel east<br>gable and other areas, refurbishment and renewal of  |
|  | PRIORITY CATEGORY: | F (B)  | gutters; renewal of rotted pew platforms. Repair work to  |
|  | OWNER TYPE:        | Religious organisation   | be complete by end of December 2015.  |
|  | LIST ENTRY NUMBER: | 1306126  | Contact: Trudi Hughes 01223 582739  |

© Historic England

Parish church. Early CI4 tower, remainder dates from SITE NAME: Church of St Wandregelius, 1868. The church was badly damaged by a fire in 2004 Bixley which destroyed the roof and interior. C16 memorial in DESIGNATION: Listed Place of Worship grade II\* chancel has been removed for safe storage. A repair scheme is under discussion but not agreed or CONDITION: Very bad implemented. The church is not formally closed. PRIORITY CATEGORY: B (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1050487 Contact: David Eve 01223 582721

© Historic England

|                      | SITE NAME:         | Church of St John the Baptist,<br>Diss Road, Bressingham | Late C15/early C16 church with late C13 chancel and C14<br>fabric. Possible water ingress above chancel arch and<br>blown plaster at high level around eastern- and<br>westernmost clerestory windows. Damp discolouration of<br>plaster in north aisle. Evidence of moisture at junction of<br>aisle roofs with arcades. Loss of render inside porch and<br>west wall externally. Some rainwater goods missing or<br>failed. Sand cement render and pointing on parts of<br>exterior masonry. Damage from water ingress and in need |
|----------------------|--------------------|--|--|
|                      | DESIGNATION:       | Listed Place of Worship grade I                          |  |
| and and a            | CONDITION:         | Poor   |  |
|                      | PRIORITY CATEGORY: | C (New entry)  |  |
|                      | OWNER TYPE:        | Religious organisation                                   |  |
|                      | LIST ENTRY NUMBER: | 1373587  | of urgent attention. Solution not yet agreed.  |
| Sectored Letters (14 | -                  |  | Contact: David Eve 01223 582721  |

© Historic England

| -       | SITE NAME:         | Church of St Mary, Diss Road,<br>Burston and Shimpling | C15 church. Nave with large replacement Perpendicular<br>windows. Chancel rebuilt with south vestry. South porch<br>with arch-braced roof. Tower collapsed in 1753 and west<br>wall of nave supported by large red brick buttress. Roofs<br>very poor condition. Heritage Lottery Fund Grant for<br>Places of Worship grant offered 2014 and development<br>phase due to commence summer 2015. |
|---------|--------------------|--|--|
|         | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA               |  |
|         | CONDITION:         | Poor   |  |
| - Care  | PRIORITY CATEGORY: | D (D)  |  |
|         | OWNER TYPE:        | Religious organisation                                 |  |
| England | LIST ENTRY NUMBER: | 1305672  | Contact: Robert Parkinson 01223 582733   |
|         |                    |  |  |

© Historic England



D

Е

| SITE NAME:         | Church of St Edmund, The<br>Street, Costessey | The church sits on high ground at the northern end of the village of Old Costessey. Mainly CI4 (Decorated), with        |
|--------------------|---|---|
| DESIGNATION:       | Listed Place of Worship grade I               | C15 porch. The upper section of the tower is in brick and much later, as is the bell turret. Links with the Jerninghams |
| CONDITION:         | Very bad                                      | of Costessey Park, a prominent Catholic recusant family.<br>The church suffers from dampness caused by deteriorating    |
| PRIORITY CATEGORY: | F (New entry)                                 | slate roofing over the nave and chancel. Both roofs have  |
| OWNER TYPE:        | Religious organisation                        | rusting fixings, and the Delabole slates are crumbling.<br>Repairs funded by Heritage Lottery Fund Grant for Places     |
| LIST ENTRY NUMBER: | 1305980                                       | of Worship now underway.  |
|                    |   | Contact: Trudi Hughes 01223 582739  |

© Mr D Collen

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

53

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH NORFOLK

|                           | SITE NAME:         | Church of St Mary, Earsham<br>Road, Denton | Flint built with stone dressings and slate roofs. Late C13 chancel. North and south chancel windows with Y-tracery.  |
|---------------------------|--------------------|--|--|
| E III                     | DESIGNATION:       | Listed Place of Worship grade I            | Perpendicular north and south aisles with Decorated east<br>and west windows. Aisle roofs leaking; drainage and high<br>level repairs required. Discussions ongoing. |
|                           | CONDITION:         | Very bad                                   |  |
|                           | PRIORITY CATEGORY: | B (New entry)                              |  |
| Contraction of the second | OWNER TYPE:        | Religious organisation                     |  |
|                           | LIST ENTRY NUMBER: | 1373626                                    | Contact: Trudi Hughes 01223 582739   |
|                           |                    |  |  |

© Historic England



|  | SITE NAME:         | Church of St Peter, Church<br>Road, Forncett | Parish church of C13 origins, possibly earlier. Formerly closed and in very poor condition, but recently brought   |  |
|--|--------------------|--|--|--|
|  | DESIGNATION:       | Listed Place of Worship grade I,<br>CA       | back into use by the PCC and Friends Group. Some repa<br>have been completed but more are needed to the<br>masonry, windows, rainwater goods and drainage. Ongo<br>discussions about possible grant applications to fund<br>necessary works. |  |
|  | CONDITION:         | Poor   |  |  |
|  | PRIORITY CATEGORY: | A (A)  |  |  |
|  | OWNER TYPE:        | Religious organisation                       |  |  |
|  | LIST ENTRY NUMBER: | 1152619                                      | Contact: Malcolm Starr 01223 582723  |  |
|  |                    |  |  |  |

© Historic England

|                  | SITE NAME:         | Church of St Mary, Low Road,<br>Forncett | C13 church with chancel dating 1869. A major scheme of repairs part funded by a Heritage Lottery Fund Grant for  |
|------------------|--------------------|--|--|
|                  | DESIGNATION:       | Listed Place of Worship grade I,<br>CA   | Places of Worship grant is currently in progress. A<br>programme of educational and community use is being<br>implemented while retaining the church as a place of<br>worship. |
| TAL STALL        | CONDITION:         | Poor                                     |  |
| Jer Miller       | PRIORITY CATEGORY: | F (F)                                    |  |
|                  | OWNER TYPE:        | Religious organisation                   |  |
| All and a second | LIST ENTRY NUMBER: | 1304627                                  | Contact: Malcolm Starr 01223 582723  |
| age .            |                    |  |  |

© English Heritage

| - J            | SITE NAME:         | Church of St Mary, Lower<br>Street, Gissing | The west tower and nave of this church date from the CII. Characteristic Norman windows of that period   |
|----------------|--------------------|---|--|
|                | DESIGNATION:       | Listed Place of Worship grade I,<br>CA      | survive, but the nave roof was replaced in the C15 with a<br>double hammerbeam roof, all the more remarkable for its<br>small scale and good state of survival. Repairs are needed |
|                | CONDITION:         | Poor  | to the masonry and roofs of the tower, north porch an<br>chancel. Heritage Lottery Fund Grant for Places of  |
| AX R           | PRIORITY CATEGORY: | B (A)                                       | Worship grant offered 2015 and project now in  |
| and the second | OWNER TYPE:        | Religious organisation                      | development.   |
|                | LIST ENTRY NUMBER: | 5289  | Contact: Malcolm Starr 01223 582723  |
|                |                    |   |  |

© Historic England



| SITE NAME:         | Church of All Saints, Market<br>Lane, Great Melton | Church of CI I origins, with fabric surviving of that period<br>(long and short quoins, and reused Roman tiles). The      |
|--------------------|--|---|
| DESIGNATION:       | Listed Place of Worship grade II*                  | extent of C19 rebuilding or restoration is less extensive<br>than once believed, hence its recent upgrading to II*. Areas |
| CONDITION:         | Fair   | of flintwork in poor condition, especially on the tower.<br>Historic England/Heritage Lottery Fund Repair Grant for       |
| PRIORITY CATEGORY: | F (F)  | Places of Worship grant offered in 2010. Repairs are  |
| OWNER TYPE:        | Religious organisation                             | underway and due for completion spring 2016. Listed<br>Places of Worship Roof Repair grant offered March 2015             |
| LIST ENTRY NUMBER: | 1050731  | and work underway.  |
|                    |  | Contact: Malcolm Starr 01223 582723   |

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH NORFOLK

| Å       | SITE NAME:         | Church of St Mary, Church<br>Lane, Haddiscoe | Parish church. CII with CI3 and CI5 re-modelling. Round west tower, probably late CII, divided into stages by three  |
|---------|--------------------|--|--|
|         | DESIGNATION:       | Listed Place of Worship grade I              | stone bands. North west bay of chancel has C15 2-light<br>window flanked by blocked circular openings. North aisle<br>has two 2-light C13 'Y' tracery windows and, at north west<br>corner, north doorway with billet hood mould and shaft,<br>scallop and roll-moulded arches. Widespread damage from<br>damp caused by inadequate disposal of rainwater is leadin<br>to deterioration of internal fabric and structural problems |
|         | CONDITION:         | Poor   |  |
| n.      | PRIORITY CATEGORY: | C (C)  |  |
| A THE W | OWNER TYPE:        | Religious organisation                       |  |
|         | LIST ENTRY NUMBER: | 1169126                                      | in external walls. Repair strategy yet to be agreed and implemented.   |
|         |                    |  | implemented.   |

© Historic England



| P    | SITE NAME:         | Church of St Botolph, Chapel<br>Lane, Morley | Parish church dating to the CI5, restored and re-roofed in the 1960s. Constructed from flint with ashlar and brick      |
|------|--------------------|--|---|
|      | DESIGNATION:       | Listed Place of Worship grade II*            | dressings. Pantile roof. Although re-roofed in the 1960s,<br>there are a number of slipped tiles on the south slope and |
|      | CONDITION:         | Poor   | heavy moss to the north, alongside blocked gutters. The rainwater goods are in a poor condition throughout.             |
| 12.4 | PRIORITY CATEGORY: | C (C)  | Pigeons in the tower may also be causing damage. Solution   |
|      | OWNER TYPE:        | Religious organisation                       | yet to be agreed.   |
| 1    | LIST ENTRY NUMBER: | 1373064                                      | Contact: David Eve 01223 582721   |

Contact: David Eve 01223 582721

© Historic England

| A   | SITE NAME:         | Church of All Saints, Church<br>Lane, Runhall | Parish church dating from C12. The C12 round tower has a C19 brick corbel course and conical roof. There is a C15          |
|-----|--------------------|---|--|
| *** | DESIGNATION:       | Listed Place of Worship grade II*             | porch with blind spandrel tracery to entrance. The tower is in a poor condition with large cracks at high level and slates |
|     | CONDITION:         | Poor  | falling from the roof. The tower is currently cordoned off with danger signs. Solution not yet agreed.                     |
|     | PRIORITY CATEGORY: | C (C)   | with danger signs. Solution not yet agreed.  |
|     | OWNER TYPE:        | Religious organisation                        |  |
|     | LIST ENTRY NUMBER: | 1304940                                       | Contact: Janine Dykes 01223 582724   |

© Historic England

|  | SITE NAME:         | Church of All Saints, Church<br>Road, Shelfanger | Early C14 church. Tower with diagonal buttresses,<br>embattled parapet with chequer flushwork and pyramidal        |
|--|--------------------|--|--|
|  | DESIGNATION:       | Listed Place of Worship grade I                  | tiled roof. Early CI4 chancel with east window with intersecting tracery. CI4 nave with CI5 Perpendicular          |
|  | CONDITION:         | Poor   | windows, and one Decorated north window. Mural fragments in east end of chancel. Wall painting in chancel          |
|  | PRIORITY CATEGORY: | C (C)  | vulnerable to dampness in walls. Repair to roof needed to  |
|  | OWNER TYPE:        | Religious organisation                           | prevent water ingress and dampness in chancel, threatening<br>an important medieval wall painting. Congregation is |
|  | LIST ENTRY NUMBER: | 1373360  | considering applying for Heritage Lottery Fund grant aid, although no solution formally agreed.                    |
|  |                    |  | although no solution formally agreed.  |

© Historic England



| SITE NAME:         | Church of St Peter,<br>Swainsthorpe | Parish church with C12 west tower with C14 top stage.<br>Remainder C14 but restored in C19. Tower roof collapsing |
|--------------------|-------------------------------------|---|
| DESIGNATION:       | Listed Place of Worship grade II*   | due to inadequate perimeter gutters and undersized rainwater outlets. Supporting beams fractured. No safe         |
| CONDITION:         | Poor                                | access on to tower roof for purposes of inspection and repair. Historic England/Heritage Lottery Fund Repair      |
| PRIORITY CATEGORY: | F (C)                               | Grant for Places of Worship offered 2010. Repairs   |
| OWNER TYPE:        | Religious organisation              | complete 2014, with exception of re-roofing chancel (batten failure) which was postponed due to lack of funds.    |
| LIST ENTRY NUMBER: | 1169726                             | Listed Places of Worship Roof Repair grant offered in March 2015. Works now underway.                             |
|                    |                                     |   |

© Historic England

Contact: Trudi Hughes 01223 582739

Contact: David Eve 01223 582721

## PRIORITY CATEGORIES

## Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SOUTH NORFOLK



| TE NAME:         | Church of St Mary, Church<br>Road, Yelverton | Paris<br>fragr |  |
|------------------|--|----------------|--|
| SIGNATION:       | Listed Place of Worship grade I              | part<br>The    |  |
| ONDITION:        | Poor   |                |  |
| IORITY CATEGORY: | B (A)  | deve           |  |
| WNER TYPE:       | Religious organisation                       |                |  |
| ST ENTRY NUMBER: | 1050639                                      | Con            |  |
|                  |  |                |  |

sh church predominantly dating from C14 with C12 ments, with the tower dated to C17. The masonry to of the tower is in poor condition with detaching flints. congregation has received a Heritage Lottery Fund nt for Places of Worship and the project is in its elopment phase.

ntact: Malcolm Starr 01223 582723

© Historic England

| SITE NAME:               | Arminghall, sites discovered by air photographs, Bi            | xley / Trowse with   | Newton                                |
|--------------------------|--|----------------------|---------------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:   | 1003620                               |
| CONDITION:               | Extensive significant problems                                 | TREND:               | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:          | No                                    |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760              |
| SITE NAME:               | Sites discovered by air photography at Markshall, (            | Caistor St. Edmund   |                                       |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:   | 1002887                               |
| CONDITION:               | Extensive significant problems                                 | TREND:               | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:         | No                                    |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760              |
| SITE NAME:               | Langley Cross 360m north of Park Farm, Chedgrav                | ve / Langley with Ha | ardley / Thurton / Carleton St. Peter |
| DESIGNATION:             | Scheduled Monument, LB grade II, RPG grade II                  | LIST ENTRY NUMBER:   | 1020060                               |
| CONDITION:               | Extensive significant problems                                 | TREND:               | Declining                             |
| PRINCIPAL VULNERABILITY: | Rain entry   | NEW ENTRY ?:         | Yes                                   |
| OWNER TYPE:              | Private  | CONTACT:             | Will Fletcher 01223 582710            |
| SITE NAME:               | Long barrow and round barrows on Broome Heat                   | h, Ditchingham / Bı  | roome                                 |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:   | 1004002                               |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:               | Declining                             |
| PRINCIPAL VULNERABILITY: | Levelling  | NEW ENTRY?:          | No                                    |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:             | David Kenny 01223 582760              |
| SITE NAME:               | Romano-Celtic temple 590m south east of St Jame                | es's Church, Wickle  | wood                                  |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:   | 1020862                               |
| CONDITION:               | Extensive significant problems                                 | TREND:               | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:          | No                                    |
| OWNER TYPE:              | Commercial company   | CONTACT:             | David Kenny 01223 582760              |
|                          |  |                      |                                       |

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

# PETERBOROUGH, CITY OF (UA)

| PETERBOROUGH, CITY   | OF (UA)            |   |  |  |
|--|--------------------|---|--|--|
| & VIA  | SITE NAME:         | Peterborough Cathedral<br>precinct wall, Peterborough   | Various sections of the Cathedral precinct wall, of medieval (and some places, perhaps, Saxon) origin with later stone   |  |
|  | DESIGNATION:       | Scheduled Monument and Listed<br>Buildings - 10 grade I, 5 LBs, part<br>in RPG grade II, CA                   | and brick refacing, are in very poor condition and need<br>significant amounts of repointing and recapping. Two<br>sections of fallen wall and one propped section have been<br>rebuilt. The walls are vulnerable to water penetration |  |
| T I WALLEY   | CONDITION:         | Poor  | which has led to stone decay. Some repairs completed, discussions ongoing for further phase of repairs.  |  |
|  | OCCUPANCY:         | N/A   | discussions ongoing for fulltier phase of repairs.   |  |
|  | PRIORITY CATEGORY: | A (F)   |  |  |
| © Dr Jackie Hill, Cathedral Archaeologist  | OWNER TYPE:        | Religious organisation  |  |  |
|  | LIST ENTRY NUMBER: | 1003264 and 1126932;<br>1331514; 1126930; 1126937;<br>1161429; 1161668; 1331517;<br>1331494; 1126939; 1161737 | Contact: Deborah Priddy 01223 582720   |  |
| and a second second  | SITE NAME:         | Laurel Court, 22, Precincts,<br>Peterborough  | An early C18 house adjacent to the remains of the cloister at Peterborough Cathedral. The building is suffering from   |  |
|  | DESIGNATION:       | Listed Building grade I, RPG<br>grade II, CA  | structural problems and failure of its modern flat roof<br>covering. Although there are no proposals for full scale<br>repair the building is occupied and maintained.   |  |
|  | CONDITION:         | Poor  |  |  |
|  | OCCUPANCY:         | Part occupied/part in use   |  |  |
|  | PRIORITY CATEGORY: | C (C)   |  |  |
| The subscription of the second se | OWNER TYPE:        | Religious organisation  |  |  |
| © Historic England   | LIST ENTRY NUMBER: | 1310019   | Contact: John Neale 01223 582719   |  |
| A 4  | SITE NAME:         | Barn at Wothorpe Farmhouse<br>near Wothorpe Towers,<br>Wothorpe   | C17 stables. Repairs are underway: dormer on the south face will be reinstated this year and the reinstatement of the Collyweston stone slate roof will follow. The adjoining  |  |
|  | DESIGNATION:       | Listed Building grade II*   | barn and granary have been repaired and are occupied.  |  |
|  | CONDITION:         | Poor  |  |  |
|  | OCCUPANCY:         | Part occupied/part in use   |  |  |
| E Contraction of the second  | PRIORITY CATEGORY: | F (F)   |  |  |
|  | OWNER TYPE:        | Charity (heritage)  |  |  |
| © Historic England   | LIST ENTRY NUMBER: | 2745  | Contact: John Neale 01223 582719   |  |
|  | SITE NAME:         | Wothorpe Farmhouse near<br>Wothorpe Towers, Wothorpe  | C17 farmhouse. Repairs are underway three dormers on<br>east face will be reinstated this year, followed by the  |  |
|  |                    |   | reinstatement of the Collyweston roof slate.   |  |



|      | SITE NAME:         | Wothorpe Farmhouse near<br>Wothorpe Towers, Wothorpe | east face will be reinstated this year, followed by |  |
|------|--------------------|--|---|--|
|      | DESIGNATION:       | Listed Building grade II*                            | reinstatement of the Collyweston roof slate.        |  |
|      | CONDITION:         | Poor   |   |  |
| 120. | OCCUPANCY:         | Vacant/not in use                                    |   |  |
| -    | PRIORITY CATEGORY: | F (F)  |   |  |
|      | OWNER TYPE:        | Private  |   |  |
|      | LIST ENTRY NUMBER: | 1265974  | Contact: John Neale 01223 582719                    |  |
|      |                    |  |   |  |

© Historic England

| PR | TY C | ATE | GOR | IES |  |
|----|------|-----|-----|-----|--|
|    |      |     |     |     |  |

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

## HERITAGE AT RISK 2015 / EAST OF ENGLAND / PETERBOROUGH, CITY OF (UA)

| SITE NAME:                 | Fletton churchyard cross                               |                        |                          |
|----------------------------|--|------------------------|--------------------------|
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1006839                  |
| CONDITION:                 | Generally unsatisfactory with major localised problems | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Natural erosion - moderate                             | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Religious organisation                                 | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Settlement site east of Uffington and Barnack Sta      | tion, Barnack / Uffing | ton / Bainton            |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1006792                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Mixed, multiple owners                                 | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Four bowl barrows 690m and 550m ESE of The             | Willows, Borough Fe    | n                        |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1021314                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Local authority, multiple owners                       | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Roman house north of Castor Mills, Castor              |                        |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1004673                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Other not for profit group                             | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Roman site in Normangate Field, Castor / Ailswo        | orth                   |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1006864                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Other not for profit group                             | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Bowl barrow 550m south east of Hill Farm, Eye          |                        |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1021304                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Private  | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Bowl barrow 570m north east of Slipe Farm, Eye         |                        |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1021303                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Private  | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Roman villa north of Oxey Wood, Helpston               |                        |                          |
|                            | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1006832                  |
| DESIGNATION:               | Generally unsatisfactory with major localised          | TREND:                 | Declining                |
| designation:<br>Condition: | problems   | TREIND:                | Declining                |
|                            |  | NEW ENTRY?:            | No                       |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / PETERBOROUGH, CITY OF (UA)

| SITE NAME:   | Site revealed by aerial photography east of Lolh   | am Hall, Maxey                                 |                                    |
|--|--|--|------------------------------------|
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1006827                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY ?:                                   | No                                 |
| OWNER TYPE:  | Mixed, multiple owners   | CONTACT:                                       | David Kenny 01223 582760           |
| SITE NAME:   | Three bowl barrows 390m north west of The F  | irs, Newborough                                |                                    |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1021317                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY ?:                                   | No                                 |
| OWNER TYPE:  | Private  | CONTACT:                                       | David Kenny 01223 582760           |
| ITE NAME:  | Three bowl barrows and a ring ditch 590m and   | 500m north west of T                           | he Four Winds, Newborough          |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1021318                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY?:                                    | No                                 |
| OWNER TYPE:  | Private  | CONTACT:                                       | David Kenny 01223 582760           |
| SITE NAME:   | Sutton Heath, Romano-British site, Sutton / Sou  | thorpe   |                                    |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1006880                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY?:                                    | No                                 |
| OWNER TYPE:  | Commercial company, multiple owners  | CONTACT:                                       | David Kenny 01223 582760           |
| SITE NAME:   | A Bronze Age post alignment and timber platfor systems and settlement to either side of the No | rm at Flag Fen and asso<br>rthey Road, Thorney | ociated Bronze Age and later field |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1406460                            |
| CONDITION:   | Generally unsatisfactory with major localised problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Drainage/dewatering  | NEW ENTRY ?:                                   | No                                 |
| OWNER TYPE:  | Mixed, multiple owners CONTACT   |  | Deborah Priddy 01223 582720        |
| SITE NAME:   | Bowl barrow 225m north east of Prior's Fen Fa  | rm, Thorney                                    |                                    |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1021311                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY?:                                    | No                                 |
| OWNER TYPE:  | Commercial company   | CONTACT:                                       | David Kenny 01223 582760           |
| SITE NAME:   | Bowl barrow 430m north east of Prior's Fen Fa  | rm, Thorney                                    |                                    |
| DESIGNATION:   | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1021310                            |
| CONDITION:   | Extensive significant problems   | TREND:   | Declining                          |
| PRINCIPAL VULNERABILITY:   | Arable ploughing   | NEW ENTRY?:                                    | No                                 |
| OWNER TYPE:  | Commercial company   | CONTACT:                                       | David Kenny 01223 582760           |
|  | Bowl barrow 490m west of Gores Farm, Thorn   | ev   |                                    |
| SITE NAME:   | Bowl ballow 47011 west of Goles Falli, Hioff   | -/   |                                    |
|  | Scheduled Monument   | LIST ENTRY NUMBER:                             | 1021307                            |
| DESIGNATION:   |  | •  | 1021307<br>Declining               |
| SITE NAME:<br>DESIGNATION:<br>CONDITION:<br>PRINCIPAL VULNERABILITY: | Scheduled Monument   | LIST ENTRY NUMBER:                             |                                    |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2015 / EAST OF ENGLAND / PETERBOROUGH, CITY OF (UA) / SOUTHEND-ON-SEA (UA)

| SITE NAME:               | Bowl barrow 620m north east of East Wi  | ryde Cottages, Thorney                          |                          |  |
|--------------------------|---|---|--------------------------|--|
| DESIGNATION:             | Scheduled Monument                      | LIST ENTRY NUMBER:                              | 1021306                  |  |
| CONDITION:               | Extensive significant problems          | TREND:  | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                        | NEW ENTRY?:                                     | No                       |  |
| OWNER TYPE:              | Private                                 | CONTACT:  | David Kenny 01223 582760 |  |
| SITE NAME:               | Bowl barrow 730m WSW of Gores Farm      | , Thorney                                       |                          |  |
| DESIGNATION:             | Scheduled Monument                      | LIST ENTRY NUMBER:                              | 1021308                  |  |
| CONDITION:               | Extensive significant problems          | Extensive significant problems TREND: Declining |                          |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                        | NEW ENTRY ?:                                    | No                       |  |
| OWNER TYPE:              | Commercial company                      | CONTACT:  | David Kenny 01223 582760 |  |
| SITE NAME:               | Bowl barrow 780m east of Bar Pasture Fa | ırm, Thorney                                    |                          |  |
| DESIGNATION:             | Scheduled Monument                      | LIST ENTRY NUMBER:                              | 1021309                  |  |
| CONDITION:               | Extensive significant problems          | TREND:  | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                        | NEW ENTRY?:                                     | No                       |  |
| OWNER TYPE:              | Commercial company                      | CONTACT:  | David Kenny 01223 582760 |  |
| SITE NAME:               | Bowl barrow 880m south west of Singleco | ote Cottage, Thorney                            |                          |  |
| DESIGNATION:             | Scheduled Monument                      | LIST ENTRY NUMBER:                              | 1021312                  |  |
| CONDITION:               | Extensive significant problems          | TREND:  | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                        | NEW ENTRY ?:                                    | No                       |  |
| OWNER TYPE:              | Private                                 | CONTACT:  | David Kenny 01223 582760 |  |
| SITE NAME:               | Two bowl barrows 940m south east of Ba  | ar Pasture Farm, Thorney                        |                          |  |
| DESIGNATION:             | Scheduled Monument                      | LIST ENTRY NUMBER:                              | 1021313                  |  |
| CONDITION:               | Extensive significant problems          | TREND:  | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing                        | NEW ENTRY ?:                                    | No                       |  |
| OWNER TYPE:              | Private                                 | CONTACT:  | David Kenny 01223 582760 |  |

# SOUTHEND-ON-SEA (UA)

|                    | SITE NAME:         | Manor House, Suttons Road,<br>South Shoebury | House, 1681. Currently vacant, last used as residential quarters. Re-use of the building is complicated by its           |
|--------------------|--------------------|--|--|
|                    | DESIGNATION:       | Listed Building grade II*                    | location within a military site. Ā serious dry rot problem was treated 1998-2003, but has caused considerable            |
|                    | CONDITION:         | Poor   | damage to the interior. Building has been vacant for many<br>years. Rigid application of 3-year break clause in all long |
|                    | OCCUPANCY:         | Vacant/not in use                            | leases granted by Ministry of Defence has seriously  |
|                    | PRIORITY CATEGORY: | C (C)  | worsened potential for reuse by charitable trusts. No change for 2015.   |
|                    | OWNER TYPE:        | Government or agency                         |  |
| © Historic England | LIST ENTRY NUMBER: | 1306855                                      | Contact: Sheila Stones 01223 582716  |

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BABERGH

#### **SUFFOLK**

#### BABERGH

| 1  |                    |  |   |
|----|--------------------|--|---|
|    | SITE NAME:         | Barn north east of Bentley Hall,<br>Bentley Hall Road, Bentley | Built C15, timber-framed and brick nogging. It is redundant and is only suitable for a very low-key use. It is structurally |
|    | DESIGNATION:       | Listed Building grade II*                                      | unstable and water is penetrating the walls in places, accelerating decay of its structure. Historic England and the        |
|    | CONDITION:         | Very bad   | Local Authority are involved in ongoing discussions with the owner to secure the conservation of the barn.                  |
|    | OCCUPANCY:         | Vacant/not in use  |   |
|    | PRIORITY CATEGORY: | A (B)  |   |
|    | OWNER TYPE:        | Private  |   |
| nd | LIST ENTRY NUMBER: | 1351965  | Contact: Robert Parkinson 01223 582733  |
|    |                    |  |   |

© Historic England

|          | SITE NAME:         | Kersey Mill, Kersey       | Large timber framed and weatherboarded watermill of  |
|----------|--------------------|---------------------------|--|
|          | DESIGNATION:       | Listed Building grade II* | three storeys, with attics under slate roof. Early C19 front<br>range, rear range 1830s. Small paned sash and centre pivot |
|          | CONDITION:         | Very bad                  | windows. Fine iron waterwheel and important range of milling machinery. Owner has applied for Historic England             |
| 1        | OCCUPANCY:         | Vacant/not in use         | grant (July 2015) to repair two principal posts and axial<br>beam and associated structural work, all of which is          |
|          | PRIORITY CATEGORY: | B (C)                     | beam and associated structural work, all of which is essential to restore structural integrity.                            |
|          | OWNER TYPE:        | Private                   |  |
| Stores . | LIST ENTRY NUMBER: | 80340                     | Contact: Trudi Hughes 01223 582739   |
|          |                    |                           |  |

Lawshall Hall, The Street,

Listed Building grade II\*

Vacant/not in use

Lawshall

Poor

C (F)

LIST ENTRY NUMBER:

Private

1036593

© Historic England



© Historic England



|                    | 1000070                                    |  |
|--------------------|--|--|
|                    |  |  |
| SITE NAME:         | Church of St Mary, The Street,<br>Arwarton | Parish church located in the small hamlet of Erwarton (or<br>"Arwarton"). Historic fabric of church datable from C14.    |
| DESIGNATION:       | Listed Place of Worship grade I            | Some interesting repairs of 1838 in the Georgian tradition, which add to the architectural character. Serious erosion of |
| CONDITION:         | Very bad                                   | the tower facework and quoins, posing a risk of partial collapse. Heritage Lottery Fund Repair Grants for Places of      |
| PRIORITY CATEGORY: | F (F)                                      | Worship grant was offered in 2011. Repairs commenced in  |
| OWNER TYPE:        | Religious organisation                     | 2014 and due to complete autumn 2015.  |
| LIST ENTRY NUMBER: | 1286145                                    | Contact: Malcolm Starr 01223 582723  |

House, C16 and C19. Unoccupied since the 1960s. A

Contact: Clare Campbell 01223 582738

scheme has been approved for repair, refurbishment and

extension of the building for use as a residential dwelling.

Some repair and conservation works were undertaken June 2014 and discussions are ongoing regarding further repairs.

© Historic England

| SITE NAME:               | Enclosure east of Nether Hall, Harkstead |                    |                          |
|--------------------------|--|--------------------|--------------------------|
| DESIGNATION:             | Scheduled Monument                       | LIST ENTRY NUMBER: | 1005981                  |
| CONDITION:               | Extensive significant problems           | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Arable ploughing                         | NEW ENTRY ?:       | No                       |
| OWNER TYPE:              | Private                                  | CONTACT:           | David Kenny 01223 582760 |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / BABERGH / FOREST HEATH

|                            | I OF ENGLAND / BABERGH / FOREST HEATH                  |                        |                          |
|----------------------------|--|------------------------|--------------------------|
| SITE NAME:                 | Roman villa north east of Rodbridge House, Lon         | g Melford              |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1005969                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Commercial company                                     | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Wissington ring ditch cluster, Nayland-with-Wis        | sington                |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1003758                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Commercial company                                     | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Wood Hall moated site, Sudbury                         |                        |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1005997                  |
| CONDITION:                 | Generally unsatisfactory with major localised problems | TREND:                 | Improving                |
| PRINCIPAL VULNERABILITY:   | Scrub/tree growth                                      | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Local authority  | CONTACT:               | David Kenny 01223 582760 |
| OREST HEATH                |  |                        |                          |
| SITE NAME:                 | Bowl barrow 990m south west of Cranhouse Fa            | rm, Eriswell           |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1018100                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY ?:           | No                       |
| OWNER TYPE:                | Commercial company                                     | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Three bowl barrows 750m south west of Pin Far          | rm, Gazeley            |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1018103                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Commercial company                                     | CONTACT:               | David Kenny 01223 582760 |
| ITE NAME:                  | Two bowl barrows 150m south east of Warren             | nill Farm, Herringswel | I                        |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1018674                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Commercial company                                     | CONTACT:               | David Kenny 01223 582760 |
| ITE NAME:                  | Mildenhall Roman site, Mildenhall                      |                        |                          |
| DESIGNATION:               | Scheduled Monument                                     | LIST ENTRY NUMBER:     | 1006037                  |
| CONDITION:                 | Extensive significant problems                         | TREND:                 | Declining                |
| PRINCIPAL VULNERABILITY:   | Arable ploughing                                       | NEW ENTRY?:            | No                       |
| OWNER TYPE:                | Mixed, multiple owners                                 | CONTACT:               | David Kenny 01223 582760 |
| SITE NAME:                 | Newmarket, Newmarket / Snailwell                       |                        |                          |
|                            |  |                        |                          |
| DESIGNATION:               | Conservation Area, 106 LBs                             | NEW ENTRY?:            | No                       |
| designation:<br>condition: | Conservation Area, 106 LBs<br>Very bad                 | NEW EN IRY?:<br>TREND: | No<br>Improving          |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / IPSWICH / MID SUFFOLK

#### **IPSWICH**

|                    | SITE NAME:         | St Mary at Quay, Quay Street,<br>Ipswich | A former church, dating from 1448, now owned by the<br>Churches Conservation Trust. In general, the building is in  |
|--------------------|--------------------|--|---|
|                    | DESIGNATION:       | Listed Building grade II*, CA            | a poor condition with major drainage issues with severe water penetration of masonry at low level. Historic England |
| C ale ale ale ale  | CONDITION:         | Very bad                                 | and Heritage Lottery Fund grants have enabled urgent repair works to commence in summer 2014 and will               |
|                    | OCCUPANCY:         | Vacant/not in use                        | continue in 2015-16.  |
|                    | PRIORITY CATEGORY: | F (B)                                    |   |
|                    | OWNER TYPE:        | Charity (heritage)                       |   |
| © Historic England | LIST ENTRY NUMBER: | 1037707                                  | Contact: Robert Parkinson 01223 582733  |

# MID SUFFOLK

| Casto /              | SITE NAME:         | Badley Hall barn 100 metres south east of Badley Hall, Badley | A very well built and unusually complete C15 or early C16<br>timber-framed barn on a flint rubble plinth. Timber frame |
|----------------------|--------------------|---|--|
| Activity             | DESIGNATION:       | Listed Building grade II*, SM                                 | in need of repair.   |
|                      | CONDITION:         | Poor  |  |
|                      | OCCUPANCY:         | Vacant/not in use   |  |
|                      | PRIORITY CATEGORY: | C (C)   |  |
| white and the second | OWNER TYPE:        | Private   |  |
| © Historic England   | LIST ENTRY NUMBER: | 1231085   | Contact: Clare Campbell 01223 582738   |



© Historic England



1231084 Barn 200 metres west of Hall's Farmhouse, Halls Lane, Norton SITE NAME: DESIGNATION: Listed Building grade II\* CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1352406

© Historic England



| SITE NAME:<br>DESIGNATION | SITE NAME:         | Church of St Lawrence, Church<br>Lane, Brundish | Parish church of Norman origins with C12 tower. C14 and C15 alterations. Very fine internal features include a        |
|---------------------------|--------------------|---|---|
|                           | DESIGNATION:       | Listed Place of Worship grade I                 | window niche with surviving medieval polychrome decoration. A CI5 pulpit and a collection of pews typifying           |
|                           | CONDITION:         | Very bad  | their development from medieval to C18. Very poor rain<br>and ground water disposal arrangements have resulted in     |
| PRIOR                     | PRIORITY CATEGORY: | F (B)   | extensive internal damp and initial stages of decay in the  |
|                           | OWNER TYPE:        | Religious organisation                          | pews. This is also affecting the electrical wiring. Heritage<br>Lottery Fund Grant for Places of Worship accepted and |
|                           | LIST ENTRY NUMBER: | 1352203   | repair works ongoing. Due for completion autumn 2015.   |
|                           |                    |   | Contact: Malcolm Starr 01223 582723   |

alternative uses.

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

A rare example of a near-complete C16 timber-framed

programme carried out in 2013 and repairs ongoing.

Contact: Malcolm Starr 01223 582723

Contact: Malcolm Starr 01223 582723

dovecote. Some nesting boxes remain. First phase of repair

Timber-framed and weatherboarded barn, mid C16. High

quality timber frame with some rare features. Soleplates rotted and whole barn leaning sideways. Although

propped, permanent repairs now required to secure the structure. Roof was wind and weathertight on date of last

visit. Discussions continue regarding repairs and potential

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
  - Unitary Authority World Heritage Site

## HERITAGE AT RISK 2015 / EAST OF ENGLAND / MID SUFFOLK

|            | SITE NAME:         | Church of St Mary, The Street,<br>Horham | Medieval parish church. Core of the nave probably dates<br>from C12. The nave contains C12 doorways. The chancel      |
|------------|--------------------|--|---|
| Lester of  | DESIGNATION:       | Listed Place of Worship grade II*        | was largely rebuilt 1879-8. Beneath all the belfry lights are square flushwork. The nave seating includes C15 benches |
| 11 - 11    | CONDITION:         | Poor                                     | with poppyhead ends enriched with buttressing and fleurons. Principal issue of damp, particularly on external         |
|            | PRIORITY CATEGORY: | C (C)                                    | walls of the nave. Slow decay continues but solution to be  |
| AL HORE OF | OWNER TYPE:        | Religious organisation                   | identified and agreed.  |
|            | LIST ENTRY NUMBER: | 1032540                                  | Contact: Janine Dykes 01223 582724  |

© Historic England

| SITE NAME:         | Church of All Saints, The Street,<br>Laxfield                   | Church of C14 origins, but earlier fabric may survive. Good collection of pews from the medieval period onwards, and                              |
|--------------------|---|---|
| DESIGNATION:       | Listed Place of Worship grade I                                 | traces of medieval polychrome decoration surviving on the font. The very fine flushwork tower has suffered from                                   |
| CONDITION:         | Poor  | erosion and weather ingress at high level. South and west faces have been repaired, but work is now needed urgently                               |
| PRIORITY CATEGORY: | F (B)   | to the east and north before fabric is lost. Leakage at the   |
| OWNER TYPE:        | Religious organisation  | abutment of the C19 chancel roof to the nave. Heritage<br>Lottery Fund Grant for Places of Worship grant offered                                  |
| LIST ENTRY NUMBER: | 80967   | and project is in progress.   |
|                    |   | Contact: Malcolm Starr 01223 582723   |
|                    | DESIGNATION:<br>CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE: | Laxfield    DESIGNATION:  Listed Place of Worship grade I    CONDITION:  Poor    PRIORITY CATEGORY:  F (B)    OWNER TYPE:  Religious organisation |

© Historic England

|           | SITE NAME:         | Church of St Andrew, Church<br>Road, Redlingfield | Parich church dating to C14. Chancel rebuilt c.1800. C14<br>nave of flint rubble (formerly plastered) with stone |
|-----------|--------------------|---|--|
| A SOMALTA | DESIGNATION:       | Listed Place of Worship grade II*                 | dressings; the walls were later heightened in red brick.<br>Tower stump is of red brick with diaperwork in dark  |
|           | CONDITION:         | Very bad  | headers; above is a timber framed and plastered belfry, probably of C16 date, with a gabled pantiled roof. Red   |
| 1 Imar    | PRIORITY CATEGORY: | A (New entry)                                     | brick chancel. Nave has plain tiled roof; chancel has glaz   |
|           | OWNER TYPE:        | Religious organisation                            | black pantiles. Signs of masonry collapse and water penetration. Solution yet to be agreed.                      |
|           | LIST ENTRY NUMBER: | 1032497   | Contact: John Ette 01223 582711  |

© Historic England

| the The | SITE NAME:         | Church of St Margaret, Little<br>Green, Thrandeston | Medieval parish church dating from the C15 apart from the C13 chancel which was re-fenestrated in C15. The church    |
|---------|--------------------|---|--|
| 9       | DESIGNATION:       | Listed Place of Worship grade I                     | was fully restored c1870-80. Short gabled north porch has a C19 outer arch. There is damp throughout the interior of |
|         | CONDITION:         | Poor  | the church which is particularly bad around the pews at<br>low level. Slow decay, no solution yet agreed but         |
|         | PRIORITY CATEGORY: | C (C)   | discussions are ongoing.   |
|         | OWNER TYPE:        | Religious organisation                              |  |
| TAT     | LIST ENTRY NUMBER: | 1032763   | Contact: Janine Dykes 01223 582724   |

© Historic England

| SITE NAME:               | Baylham Roman site, Coddenham  |                    |                          |
|--------------------------|--------------------------------|--------------------|--------------------------|
| DESIGNATION:             | Scheduled Monument             | LIST ENTRY NUMBER: | 1006033                  |
| CONDITION:               | Extensive significant problems | TREND:             | Declining                |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed   | NEW ENTRY?:        | No                       |
| OWNER TYPE:              | Private, multiple owners       | CONTACT:           | David Kenny 01223 582760 |

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / MID SUFFOLK / ST EDMUNDSBURY

SITE NAME:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

D

Е

|                | SITE NAME:         | Shrubland Hall, Coddenham /<br>Hemingstone / Barham            | Extensive mid C19 Italianate garden by Charles Barry set in<br>C17 park, for which Humphry Repton prepared a Red  |
|----------------|--------------------|--|---|
|                | DESIGNATION:       | Registered Park and Garden<br>grade I, 22 LBs                  | Book in 1789 and William Woods in 1808. Many proposals<br>have been implemented in the expanded park. The site is in<br>divided ownership following sale in 2009 and boundary |
|                | CONDITION:         | Generally satisfactory but with significant localised problems | fence erected. Management of Old Hall landscape is<br>improving but the built garden features and planting are<br>significantly decayed. Improved management strategies for   |
|                | VULNERABILITY:     | High   | the park as a whole need to be developed to safeguard its   |
|                | TREND:             | Declining  | future.   |
| storic England | NEW ENTRY?:        | No   |   |
|                | OWNER TYPE:        | Private, multiple owners                                       |   |
|                | LIST ENTRY NUMBER: | 1000155  | Contact: Clare Campbell 01223 582738  |
|                |                    |  |   |

# ST EDMUNDSBURY

© Hist

| -                  | SITE NAME:         | Atomic bomb store on<br>Thetford Heath, Barnham | Former Ministry of Defence strategic defence site, built<br>1953-1955. Purchased and in use as an industrial estate  |
|--------------------|--------------------|---|--|
|                    | DESIGNATION:       | Scheduled Monument, 5 LBs                       | since 1965. Elements at risk due to short term anticipated lifespan. Successive grant aided phases of work undertaken  |
|                    | CONDITION:         | Poor  | between 2011-2015 with privately funded works by the owner, have greatly improved the condition of the site.   |
|                    | OCCUPANCY:         | Part occupied/part in use                       | Fifth phase of repairs nearing completion. Owner has<br>applied (July 2015) to Historic England to fund urgent<br>repairs to gantries in front of buildings 60 & 61. |
|                    | PRIORITY CATEGORY: | F (F)   |  |
|                    | OWNER TYPE:        | Private   |  |
| © Historic England | LIST ENTRY NUMBER: | 1020781   | Contact: Trudi Hughes 01223 582739   |

The Guildhall and attached

Educational (independent)

St. Edmunds

C (C)

1022597

Railings, Guildhall Street, Bury



© Historic England



|  | DESIGNATION:               | Listed Building grade I, CA       | the court room on the left, which has a rare mid CI4  |  |
|--|----------------------------|-----------------------------------|---|--|
|  | CONDITION:                 | Poor                              | timber framed roof including both king-and queen posts,<br>with arched braced roof resting on corbels visible. Roof |  |
|  | OCCUPANCY:                 | Part occupied/part in use         | above leaks. To the right, is the mid-C18 banqueting room.  |  |
|  | PRIORITY CATEGORY:         | F (New entry)                     | Roof over ops room leaking badly and structural movement evident in roof structure. Reroofing scheme to             |  |
|  | OWNER TYPE:                | Charity (heritage)                | complete Jan 2016.  |  |
|  | LIST ENTRY NUMBER:         | 1363726                           | Contact: Trudi Hughes 01223 582739  |  |
|  |                            |                                   |   |  |
|  | SITE NAME:                 | Moreton Hall, Bury St. Edmunds    | Robert Adam House of 1773. Urgent high level works to   |  |
|  |                            |                                   | the exterior are needed.  |  |
|  | DESIGNATION:               | Listed Building grade II*         |   |  |
|  | DESIGNATION:<br>CONDITION: | Listed Building grade II*<br>Poor |   |  |

© Historic England



| SITE NAME:         | Cupola House, 7, The Traverse,<br>Bury St. Edmunds | Timber framed-house built in 1693, remodelled on an earlier two-storey house, named after its roof-top Cupola.       |
|--------------------|--|--|
| DESIGNATION:       | Listed Building grade I, CA                        | Repaired in 2001-2002 and used as a restaurant, suffered devastating fire in June 2012. Damage is to the rear of the |
| CONDITION:         | Very bad   | building, which has collapsed in places, and parts of the roof structure. The façade and historic timber frame have  |
| OCCUPANCY:         | Vacant/not in use                                  | survived. Consent has been granted for repair,   |
| PRIORITY CATEGORY: | A (B)  | reconstruction and new work with some repairs now being undertaken. Discussions to seek long-term solution           |
| OWNER TYPE:        | Commercial company                                 | ongoing.   |
| LIST ENTRY NUMBER: | 1038264  | Contact: Clare Campbell 01223 582738   |

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Clare Campbell 01223 582738

## ABBREVIATIONS

Guildhall: CI3; CI5 with CI7, CI8 and CI9 adaptations.

The front elevation dates from the early C19, but older fabric lies behind, including the two principal public rooms:

Predominantly of flint and brick, with tiled and slated roofs.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA WHS
- Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / ST EDMUNDSBURY



|   | SITE NAME:         | Moated site at Denham Hall,<br>Denham | Remains of brick banqueting house and associated revetting<br>on northern corner of moat island. North-east wall and   |
|---|--------------------|---------------------------------------|--|
|   | DESIGNATION:       | Scheduled Monument, LB grade<br>II    | part of the underlying revetment have recently collapsed<br>into the moat, resulting in loss of historic fabric and<br>instability to other parts of the structure. Issues include |
|   | CONDITION:         | Very bad                              | erosion around the base, unstable ground formations behind the collapsed brickwork, a large vertical fracture in   |
|   | OCCUPANCY:         | Vacant/not in use                     | the corner of the north-west wall and lintel failures and loss   |
| 5 | PRIORITY CATEGORY: | A (New entry)                         | of brick work around the doorway and window. Part of grade II listed garden wall also collapsed.   |
|   | OWNER TYPE:        | Private, multiple owners              |  |
|   | LIST ENTRY NUMBER: | 1019803                               | Contact: Nick Carter 01223 582751  |

© Historic England



|      | SITE NAME:         | Stoke College, Stoke-by-Clare | Originally a Benedictine Convent, converted to a college  |
|------|--------------------|-------------------------------|---|
|      | DESIGNATION:       | Listed Building grade II*, CA | and then a mansion after the dissolution. Repairs required to the roof and other areas of building. |
|      | CONDITION:         | Fair                          |   |
|      | OCCUPANCY:         | Occupied/in use               |   |
|      | PRIORITY CATEGORY: | C (D)                         |   |
|      | OWNER TYPE:        | Private                       |   |
| Sec. | LIST ENTRY NUMBER: | 1265211                       | Contact: Clare Campbell 01223 582738  |
|      |                    |                               |   |

© Historic England



OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: © Historic England

Early C19 Coade stone folly. Very poor condition: roof SITE NAME: The Umbrello, Great Saxham Hall, Chevington Road, Great missing, ingress of water is rusting iron core. The proposal Saxham, The Saxhams to dismantle it and re-erect in a new location had been granted listed building consent, but was not implemented. DESIGNATION: Listed Building grade II\* A programme of photographic recording and building analysis was undertaken by Historic England in 2012. No CONDITION: Very bad progress has been made since this date. N/A A (A) Private LIST ENTRY NUMBER: 1031410 Contact: Clare Campbell 01223 582738

| <b>F</b>         | SITE NAME:         | Church of St Nicholas, Church<br>Road, Bradfield Combust with<br>Stanningfield | A grade II* listed church dating from the C12 with a C13<br>chancel, flint rubble with limestone dressings, plain tiled<br>roofs with parapet gables, the tiles of which are in poor |
|------------------|--------------------|--|--|
|                  | DESIGNATION:       | Listed Place of Worship grade I  | condition and leaking. Historic England/Heritage Lottery<br>Fund Repair Grant for Places of Worship offered in 2011.   |
|                  | CONDITION:         | Poor   | Works underway and due to complete autumn 2015.  |
|                  | PRIORITY CATEGORY: | F (B)  |  |
|                  | OWNER TYPE:        | Religious organisation   |  |
|                  | LIST ENTRY NUMBER: | 1229767  | Contact: Malcolm Starr 01223 582723  |
| listoric England |                    |  |  |

© Historic England

|           | SITE NAME:         | Church of St Mary, Cavendish           | Church dating from the CI4, prominently situated in the   |
|-----------|--------------------|--|---|
| All and   | DESIGNATION:       | Listed Place of Worship grade I,<br>CA | Cavendish Conservation Area at the east end of the gre<br>Unusual features include the vaulted parvise and externa<br>arched timber bell cage and flagpole combined which sit |
|           | CONDITION:         | Poor                                   | on the tower parapet. There is some deterioration of masonry on the tower. The flagpole has begun to lean,  |
|           | PRIORITY CATEGORY: | C (C)                                  | possibly because the plated joint at low level is becoming  |
|           | OWNER TYPE:        | Religious organisation                 | ineffective. Congregation has applied to Heritage Lottery<br>Fund for grant assistance.   |
| A PARA LA | LIST ENTRY NUMBER: | 1031774                                | Contact: Malcolm Starr 01223 582723   |

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / ST EDMUNDSBURY

| SITE NAME:               | Round barrows, Risby Poor's Heath East, Flemptor               | n / Risby           |                                   |
|--------------------------|--|---------------------|-----------------------------------|
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:  | 1006038                           |
| CONDITION:               | Generally unsatisfactory with major localised problems         | TREND:              | Declining                         |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:         | No                                |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | Sites north west and south east of Fornham All Sai             | nts, Fornham All Sa | ints / Hengrave                   |
| DESIGNATION:             | Scheduled Monument, 2 CAs                                      | LIST ENTRY NUMBER:  | 1006018                           |
| CONDITION:               | Extensive significant problems                                 | TREND:              | Declining                         |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY ?:        | No                                |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | Interrupted ditch system west of Hall Farm, Keding             | gton                |                                   |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:  | 1005959                           |
| CONDITION:               | Extensive significant problems                                 | TREND:              | Declining                         |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:         | No                                |
| OWNER TYPE:              | Private  | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | Roman villa south east of Lidgate, Lidgate                     |                     |                                   |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:  | 1002971                           |
| CONDITION:               | Generally satisfactory but with significant localised problems | TREND:              | Declining                         |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:         | No                                |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | Roman settlement south of Ixworth, Pakenham                    |                     |                                   |
| DESIGNATION:             | Scheduled Monument, CA   | LIST ENTRY NUMBER:  | 1006019                           |
| CONDITION:               | Extensive significant problems                                 | TREND:              | Declining                         |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed                                   | NEW ENTRY?:         | No                                |
| OWNER TYPE:              | Private, multiple owners                                       | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | East Low Hill tumulus, Rushbrooke with Rougham                 |                     |                                   |
| DESIGNATION:             | Scheduled Monument   | LIST ENTRY NUMBER:  | 1002974                           |
| CONDITION:               | Generally unsatisfactory with major localised problems         | TREND:              | Stable                            |
| PRINCIPAL VULNERABILITY: | Subsidence   | NEW ENTRY?:         | No                                |
| OWNER TYPE:              | Private  | CONTACT:            | David Kenny 01223 582760          |
| SITE NAME:               | Haverhill Hamlet Road, Haverhill                               |                     |                                   |
| DESIGNATION:             | Conservation Area, 12 LBs                                      | NEW ENTRY?:         | No                                |
| CONDITION:               | Poor   | TREND:              | Deteriorating                     |
| VULNERABILITY:           | Medium   | CONTACT:            | Claire Johnson (LPA) 01284 757339 |
| SITE NAME:               | Haverhill Queen Street, Haverhill                              |                     |                                   |
| DESIGNATION:             | Conservation Area, 9 LBs                                       | NEW ENTRY?:         | No                                |
| CONDITION:               | Fair   | TREND:              | Deteriorating                     |
| VULNERABILITY:           | Medium   | CONTACT:            | Claire Johnson (LPA) 01284 757339 |

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

LIST ENTRY NUMBER:

## SUFFOLK COASTAL



Martello Tower "Z", south east Martello Tower Z forms part of a chain of Martello towers SITE NAME: of Buckanay Farm, Alderton along the south and east coast of England dating from the early C19. The tower has been unused since the Second Scheduled Monument and Listed World War. Whilst generally robust and structurally sound a recent condition survey undertaken as part of a Heritage DESIGNATION: Building grade II Lottery Fund Landscape Heritage Initiative has indicated CONDITION: Poor the need for repairs to prevent water ingress. Further OCCUPANCY: discussions with the owner are needed to consider any N/A urgent conservation works to the tower. PRIORITY CATEGORY: B (B) OWNER TYPE: Private

1006014 and 1030773

© Historic England



|                | SITE NAME:         | Transmitter Block, Bawdsey<br>Manor, Bawdsey | Concrete transmitter block built in 1937. Site of pioneering radar development. Featured in BBC "Restoration" TV  |
|----------------|--------------------|--|---|
|                | DESIGNATION:       | Listed Building grade II*, RPG<br>grade II   | programme. Some repair and refurbishment works<br>undertaken. Bawdsey Radar Group have commissioned an<br>options appraisal. A Conservation Management Plan has |
| A A            | CONDITION:         | Fair   | been produced for the estate. A grant from Historic<br>England has assisted in developing the project. The  |
| TO S           | OCCUPANCY:         | Part occupied/part in use                    | Heritage Lottery Fund offered a grant 2013 and further  |
|                | PRIORITY CATEGORY: | D (C)  | development works are now in progress.  |
| and the second | OWNER TYPE:        | Private                                      |   |
|                | LIST ENTRY NUMBER: | 1245307                                      | Contact: Clare Campbell 01223 582738  |

Contact: John Ette 01223 582711

© Historic England



SITE NAME: Martello Tower 'P'. Water penetration through roof. Martello tower at western end Problems of damp exacerbated by walls being of of sea front, Felixstowe impermeable render and brickwork. Major redevelopment Scheduled Monument, LB grade taking place around site partly in historic curtilage. DESIGNATION: Ш Preliminary conservation works began in autumn 2014 and will continue in 2015-16. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (B) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1006013 Contact: Robert Parkinson 01223 582733

© Historic England



| SITE NAME:         | Martello tower on golf course<br>adjoining Woodbridge Haven,<br>Felixstowe | Martello Tower T on Felixstowe Golf Course. Built c1810-<br>1812 as part of defences against Napoleonic invasion. Roof<br>and walls in very poor condition with water penetration. |
|--------------------|--|--|
| DESIGNATION:       | Scheduled Monument, LB grade<br>II   | Historic England in discussion with the owners over repairs and interpretation.  |
| CONDITION:         | Poor   |  |
| OCCUPANCY:         | Part occupied/part in use  |  |
| PRIORITY CATEGORY: | D (C)  |  |
| OWNER TYPE:        | Commercial company   |  |
| LIST ENTRY NUMBER: | 1006036  | Contact: Robert Parkinson 01223 582733   |

© Historic England



|   | SITE NAME:         | Friston Post Mill, Mill Road,<br>Friston | One of the finest, and possibly tallest, post mills in the United Kingdom. Built in 1812 and operational until 1956. |
|---|--------------------|--|--|
| 5 | DESIGNATION:       | Listed Building grade II*                | Restored in 1976; temporary supports added 2004; post<br>out of alignment and trestle fractured and now in need of   |
| b | CONDITION:         | Very bad                                 | urgent and permanent repair. Owner has applied to<br>Historic England (July 2015) for a development grant,           |
|   | OCCUPANCY:         | N/A                                      | covering survey, costings; specifications and schedules of   |
|   | PRIORITY CATEGORY: | A (B)                                    | repair works needed to inform future repair phases.  |
|   | OWNER TYPE:        | Private                                  |  |
|   | LIST ENTRY NUMBER: | 1215741                                  | Contact: Claire Fidler 01223 582735  |

## PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
- Unitary Authority World Heritage Site ŴĤS

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SUFFOLK COASTAL



|      | SITE NAME:         | Glevering Hall Orangery, Easton<br>Road, Hacheston | Orangery built in classical style circa 1835. Architect<br>Decimus Burton. Glass missing, especially from the dome,  |
|------|--------------------|--|--|
|      | DESIGNATION:       | Listed Building grade II*                          | and rusting iron cramps are forcing apart the stonework.<br>Discussions regarding repair works ongoing. Historic     |
|      | CONDITION:         | Very bad   | England has offered grant aid towards a condition survey, repair schedule and Conservation Management Plan           |
|      | OCCUPANCY:         | N/A  | together with feasibility study. Owners accepted grant at<br>end of March 2014 and discussions about details of work |
|      | PRIORITY CATEGORY: | A (A)  | end of March 2014 and discussions about details of work are ongoing.   |
| - 34 | OWNER TYPE:        | Private  |  |
|      | LIST ENTRY NUMBER: | 1377281  | Contact: Clare Campbell 01223 582738   |

© Historic England

© Historic England




|  | SITE NAME:         | Remains of Sibton Abbey,<br>Sibton                 | Remains of Cistercian abbey built in 1150. Damaging vegetation. Occasional trespass and vandalism. Building   |
|--|--------------------|--|---|
|  | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade II | currently suffering ongoing decay. The building is a ruin<br>with no possibility of economical beneficial use. Condition<br>survey undertaken. Trees removed. A conservation repair |
|  | CONDITION:         | Poor   | scheme has been offered grant aid by Historic England.  |
|  | OCCUPANCY:         | N/A  |   |
|  | PRIORITY CATEGORY: | D (D)  |   |
|  | OWNER TYPE:        | Other not for profit group                         |   |
|  | LIST ENTRY NUMBER: | 1018327 and 1377160                                | Contact: John Ette 01223 582711   |

| Alle    | SITE NAME:         | St Andrew's Church, the Street,<br>Walberswick | The medieval ruins of a much larger church are at risk due<br>to structural failure and unconsolidated walling. Some   |
|---------|--------------------|--|--|
|         | DESIGNATION:       | Listed Building grade I, CA                    | active areas of loose stonework are apparent where flint cobbles and brick are eroding out of the wall surfaces.   |
| HALK N  | CONDITION:         | Poor   | Discussions are on-going with the Parochial Church<br>Council and their advisors to develop a programme of<br>repairs to conserve the ruins. The Church of St Andrews, |
| OUS !!  | OCCUPANCY:         | N/A  |  |
|         | PRIORITY CATEGORY: | A (New entry)                                  | which is regularly used for worship, is not at risk.   |
|         | OWNER TYPE:        | Religious organisation                         |  |
| England | LIST ENTRY NUMBER: | 1283823  | Contact: John Ette 01223 582711  |

| 1.4 M    | SITE NAME:         | Church of St Andrew, The<br>Street, Alderton | Parish church with ruinous west tower. Chancel rebuilt in 1862 and nave restored in 1864. The condition of the          |
|----------|--------------------|--|---|
| - La P   | DESIGNATION:       | Listed Place of Worship grade II             | drainage and guttering is unclear. However, there is significant evidence of damp in interior of the church.            |
| A Martin | CONDITION:         | Poor   | Blocked off from the nave, the ruinous tower is overgrown<br>by trees and shrubs. Slow decay continues, no solution yet |
|          | PRIORITY CATEGORY: | C (C)  | agreed for either the church, or the ruinous tower.   |
| 1        | OWNER TYPE:        | Religious organisation                       |   |
|          | LIST ENTRY NUMBER: | 1377186                                      | Contact: Natalie Gates 01223 582747   |

© Historic England

© Historic Er



© Historic England

| ۲ | RIORI | IΥ | CAI | EGC | RIES |
|---|-------|----|-----|-----|------|
|   |       |    |     |     |      |

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SUFFOLK COASTAL

| discussion of the local discus | SITE NAME:                       | Church of St Andrew, St<br>Andrews Road, Felixstowe | Church built c1929-31 and is an interpretation of a late<br>C15 East Anglian church constructed using concrete. The<br>concrete is now in poor condition and the congregation is<br>exploring options for repair. |
|--|----------------------------------|---|---|
|  | DESIGNATION:                     | Listed Place of Worship grade II*                   |   |
| THE REAL   | CONDITION:<br>PRIORITY CATEGORY: | Poor  |   |
|  |                                  | A (A)   |   |
|  | OWNER TYPE:                      | Religious organisation                              |   |
| -  | LIST ENTRY NUMBER:               | 1377388   | Contact: Clare Campbell 01223 582738  |
|  |                                  |   |   |

© Historic England

| SITE NAME:         | Church of All Saints, The Street,<br>Hacheston                  | Medieval parish church restored mid C19. Fabric dating from C12, with C15 hammerbeam roof. The church                          |
|--------------------|---|--|
| DESIGNATION:       | Listed Place of Worship grade I                                 | requires urgent roof repairs to halt water ingress. Consent has been granted for repair works which are expected to            |
| CONDITION:         | Very bad  | commence summer 2015.  |
| PRIORITY CATEGORY: | B (B)   |  |
| OWNER TYPE:        | Religious organisation  |  |
| LIST ENTRY NUMBER: | 1199742   | Contact: Clare Campbell 01223 582738   |
|                    | DESIGNATION:<br>CONDITION:<br>PRIORITY CATEGORY:<br>OWNER TYPE: | HachestonDESIGNATION:Listed Place of Worship grade ICONDITION:Very badPRIORITY CATEGORY:B (B)OWNER TYPE:Religious organisation |

© Historic England

| 13        | SITE NAME:         | Church of All Saints, Church<br>Road, Ramsholt | Parish church, unchanged since the early C19, with box<br>pews, a double-decker pulpit on the south side of the r     |
|-----------|--------------------|--|---|
|           | DESIGNATION:       | Listed Place of Worship grade II*              | and no electricity: services being held by candlelight. The round tower is at least of Norman origin but is allegedly |
|           | CONDITION:         | Very bad                                       | Saxon, serving as a watchtower for Viking raids. The tower roof and masonry are in very poor condition. Heritage      |
|           | PRIORITY CATEGORY: | F (B)  | Lottery Fund Grant for Places of Worship offered 2013   |
|           | OWNER TYPE:        | Religious organisation                         | and repairs underway.   |
| L. Marine | LIST ENTRY NUMBER: | 1030735  | Contact: Malcolm Starr 01223 582723   |

© Historic England

|     | SITE NAME:         | Church of St John Baptist,<br>Church Street, Saxmundham | Parish church dated to C14 with significant C19 alterations.<br>South aisle roof leaks; gutters undersized and rot on roof  |
|-----|--------------------|---|---|
|     | DESIGNATION:       | Listed Place of Worship grade<br>II*, CA                | boarding. Nave and chancel roofs south side: many tingle<br>indicative of rusting ferrous slate fixings. Fine C15 hamme<br>beam roof below nave roof slating. Heritage Lottery Fund<br>Grant for Places of Worship offered in summer 2015 for<br>repairs. |
| C A | CONDITION:         | Very bad  |   |
|     | PRIORITY CATEGORY: | B (New entry)   |   |
|     | OWNER TYPE:        | Religious organisation                                  |   |
|     | LIST ENTRY NUMBER: | 1268184   | Contact: Trudi Hughes 01223 582739  |
|     |                    |   |   |

© Historic England



5

| SITE NAME:         | Church of St Margaret, Church<br>Lane, Shottisham | The church is believed to be of C14 origins, but incorporates re-used Roman tiles and possibly Saxon or   |
|--------------------|---|---|
| DESIGNATION:       | Listed Place of Worship grade II,<br>CA           | early Norman quoins. The masonry of the tower and east<br>gable of the nave are in poor condition. A grant application<br>to the Heritage Lottery Fund for this work has been |
| CONDITION:         | Very bad  | successful and the development phase is now in progress.  |
| PRIORITY CATEGORY: | B (B)   |   |
| OWNER TYPE:        | Religious organisation                            |   |
| LIST ENTRY NUMBER: | 1030736   | Contact: Malcolm Starr 01223 582723   |

© Historic England

| PRIORITY | CATEGORIES |
|----------|------------|
|          |            |

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2015 / EAST OF ENGLAND / SUFFOLK COASTAL

| SITE NAME:               | Settlement site e   | east of the Cedars, Alderton                                   |  |                                       |
|--------------------------|---------------------|--|--|---------------------------------------|
| DESIGNATION:             | Scheduled Monu      | ment   | LIST ENTRY NUMBER:   | 1005977                               |
| CONDITION:               | Extensive significa | ant problems   | TREND:   | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing    |  | NEW ENTRY?:  | No                                    |
| OWNER TYPE:              | Commercial corr     | ipany  | CONTACT:   | David Kenny 01223 582760              |
| SITE NAME:               | Settlement sites    | 330yds (300m) north west of Wal                                | nut Tree Farm, Ho  | llesley                               |
| DESIGNATION:             | Scheduled Monument  |  | LIST ENTRY NUMBER:   | 1006002                               |
| CONDITION:               | Extensive significa | Extensive significant problems                                 |  | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing    |  | NEW ENTRY?:  | No                                    |
| OWNER TYPE:              | Commercial corr     | ipany  | CONTACT:   | David Kenny 01223 582760              |
| SITE NAME:               | Rectilinear enclo   | osures 1km south west of Boyton H                              | Hall Farm, Hollesley   | / Boyton                              |
| DESIGNATION:             | Scheduled Monu      | ment   | LIST ENTRY NUMBER:   | 1006005                               |
| CONDITION:               | Extensive significa | ant problems   | TREND:   | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing    |  | NEW ENTRY?:  | No                                    |
| OWNER TYPE:              | Commercial company  |  | CONTACT:   | David Kenny 01223 582760              |
| SITE NAME:               | Henge and assoc     | iated barrow cemetery south of H                               | lome Whin Farm, S  | Shottisham / Sutton                   |
| DESIGNATION:             | Scheduled Monu      | Scheduled Monument   |  | 1017632                               |
| CONDITION:               | Extensive significa | Extensive significant problems                                 |  | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing    | Arable ploughing   |  | No                                    |
| OWNER TYPE:              | Commercial corr     | Commercial company   |  | David Kenny 01223 582760              |
| SITE NAME:               | Bowl barrow on      | Waldringfield Heath, 150m south                                | of Heath Farm, Wa  | aldringfield                          |
| DESIGNATION:             | Scheduled Monu      | ment   | LIST ENTRY NUMBER:   | 1008506                               |
| CONDITION:               | Extensive significa | ant problems   | TREND:   | Declining                             |
| PRINCIPAL VULNERABILITY: | Arable ploughing    |  | NEW ENTRY?:  | No                                    |
| OWNER TYPE:              | Private             |  | CONTACT:   | David Kenny 01223 582760              |
|                          | SITE NAME:          | Bawdsey Manor, Bawdsey   |  | between 1885 and 1909 on advice from  |
|                          | DESIGNATION:        | Registered Park and Garden<br>grade II, 8 LBs                  | Alfred Parsons. The garden contains an extensive<br>Pulhamite cliff garden, complete with seats and alco<br>built in the 1890s by Pulham & Co. Site is improving<br>house no longer at risk following Historic England g<br>aided works which were completed in 2012. Inform<br>work to some garden structures now being underta |                                       |
|                          | CONDITION:          | Generally satisfactory but with significant localised problems |  |                                       |
|                          | VULNERABILITY:      | High   | Pulhamite cliff ga   | rden in poor condition and in need of |
|                          | TREND:              | Stable   | strategic management; scrub clearance underway.<br>erosion remains a major concern.  |                                       |
| ) Historic England       | NEW ENTRY?:         | No   |  |                                       |
| I IISTOLIC EUSIGUU       | OWNER TYPE:         | Mixed, multiple owners   |  |                                       |
|                          | LIST ENTRY NUMBER:  | 1001465  | Contact: Clare C   | Campbell 01223 582738                 |

| SITE NAME:     | Felixstowe South, Felixstowe   |             |   |
|----------------|--------------------------------|-------------|---|
| DESIGNATION:   | Conservation Area, LB grade II | NEW ENTRY?: | No                                      |
| CONDITION:     | Very bad                       | TREND:      | No significant change                   |
| VULNERABILITY: | Medium                         | CONTACT:    | Robert Scrimgeour (LPA) 01394<br>444616 |

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
  C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / WAVENEY / THURROCK (UA)

#### WAVENEY




| SITE NAME:         | Moat Farmhouse, Shadingfield,<br>Beccles | C16 farmhouse with C19 alterations and brick wing to rear. Good quality timber frame, finely moulded beams and |
|--------------------|--|--|
| DESIGNATION:       | Listed Building grade II*, SM            | joists internally. Scheduled moated site. Under tarpaulin and scaffolded.                                      |
| CONDITION:         | Poor                                     |  |
| OCCUPANCY:         | Part occupied/part in use                |  |
| PRIORITY CATEGORY: | C (C)                                    |  |
| OWNER TYPE:        | Private                                  |  |
| LIST ENTRY NUMBER: | 1032132                                  | Contact: Clare Campbell 01223 582738   |

© Waveney District Council



| A state | SITE NAME:         | Bungay Castle, Bungay                                 | Medieval castle built by Roger Bigod. Problems with the   |
|---------|--------------------|---|---|
|         | DESIGNATION:       | Scheduled Monument and Listed<br>Building grade I, CA | southern C13 tower to the gatehouse have been<br>addressed and urgent repairs completed, discussions<br>ongoing over further repairs and conservation work to the |
|         | CONDITION:         | Fair  | keep, northern gatehouse tower, and curtain and bailey walls. Conservation statement and condition survey   |
|         | OCCUPANCY:         | N/A   | currently being prepared to inform next steps.  |
|         | PRIORITY CATEGORY: | B (B)   |   |
|         | OWNER TYPE:        | Charity (heritage)                                    |   |
|         | LIST ENTRY NUMBER: | 1006060 and 1034404                                   | Contact: John Ette 01223 582711   |

© Historic England



Parish church. C12 doorways, the lower portion of the tower possibly medieval; remainder entirely rebuilt 1849-50 in neo-Norman style. The tower is of flint rubble, the bell-chamber stage faced with knapped flint; the nave and chancel are plastered; stone dressings. Slated roofs with courses of fish-scale slates. Poor construction in C19 has resulted in serious structural failures in masonry, particularly the south nave wall, and water penetration. Roof poor; interior fair; rainwater goods satisfactory. No action/strategy identified or agreed. Contact: Robert Parkinson 01223 582733

© Historic England

| SITE NAME:               | Two moated sites adjoining All Saints' Church, All Saints and St. Nicholas, South Elmham |                    |                          |  |
|--------------------------|--|--------------------|--------------------------|--|
| DESIGNATION:             | Scheduled Monument, 2 LBs  | LIST ENTRY NUMBER: | 1017633                  |  |
| CONDITION:               | Generally unsatisfactory with major localised problems                                   | TREND:             | Declining                |  |
| PRINCIPAL VULNERABILITY: | Arable ploughing   | NEW ENTRY?:        | No                       |  |
| OWNER TYPE:              | Mixed, multiple owners   | CONTACT:           | David Kenny 01223 582760 |  |

# THURROCK (UA)



D

Е

| SITE NAME:         | State Cinema, George Street,<br>Grays |
|--------------------|---------------------------------------|
| DESIGNATION:       | Listed Building grade II*             |
| CONDITION:         | Poor                                  |
| OCCUPANCY:         | Vacant/not in use                     |
| PRIORITY CATEGORY: | C (C)                                 |
| OWNER TYPE:        | Commercial company                    |
| LIST ENTRY NUMBER: | 1111543                               |

The State Cinema is one of the best preserved of the 'super cinemas' of the late 1930s. It was constructed in 1938 by F G M Chancellor for Frederick's Electric Theatres. The building has suffered from heritage crime and the roof, rainwater goods and interior are in poor condition. The reuse of this vast cinema poses complex problems, as confirmed by a feasibility study some years ago, but ways to achieve this as part of the regeneration of Grays are being explored. No action/strategy has yet been agreed. Regular inspections are carried out and the building is now watertight and weatherproof.

Contact: Sheila Stones 01223 582716

# PRIORITY CATEGORIES

© Essex County Council

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

NOTE

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ÍΙΑ WHS
  - Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / EAST OF ENGLAND / THURROCK (UA)

| - A - C - C - C - C - C - C - C - C - C | SITE NAME:         | Coalhouse Fort, Tilbury   | Ruined C19 armoured casemate fort on site of earlier   |
|---|--------------------|---------------------------|--|
| Alere .                                 | DESIGNATION:       | Scheduled Monument        | battery; refortified since the two World Wars. Problem of water ingress to casemates; barrack block in severe      |
|   | CONDITION:         | Poor                      | disrepair. Repair work to the gatehouse barrack block was completed in 2011 with grant aid. Further phased repairs |
|   | OCCUPANCY:         | Part occupied/part in use | anticipated. Heritage Lottery Fund scheme for conversion   |
|   | PRIORITY CATEGORY: | C (C)                     | of generator house to cafe is underway. Storm damage to roof of north caponier has now been repaired. Discussions  |
|   | OWNER TYPE:        | Local authority           | to remedy water ingress to casemates are on-going.   |
| 1.1.0                                   | LIST ENTRY NUMBER: | 1013943                   | Contact: Deborah Priddy 01223 582720   |

© Historic England Archive

| SITE NAME:               | Crop mark complex, Orsett      |                    |                                  |
|--------------------------|--------------------------------|--------------------|----------------------------------|
| DESIGNATION:             | Scheduled Monument             | LIST ENTRY NUMBER: | 1002134                          |
| CONDITION:               | Extensive significant problems | TREND:             | Declining                        |
| PRINCIPAL VULNERABILITY: | Arable ploughing               | NEW ENTRY?:        | No                               |
| OWNER TYPE:              | Mixed, multiple owners         | CONTACT:           | David Kenny 01223 582760         |
| SITE NAME:               | East Tilbury                   |                    |                                  |
| DESIGNATION:             | Conservation Area, 11 LBs      | NEW ENTRY?:        | No                               |
| CONDITION:               | Very bad                       | TREND:             | No significant change            |
| VULNERABILITY:           | Medium                         | CONTACT:           | Planning Dept (LPA) 01375 652275 |
|                          |                                |                    |                                  |

# PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
  C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

This document is one in a series of publications produced as part of Historic England's national **Heritage at Risk** programme. More information about **Heritage at Risk** and other titles in the series can be found at **HistoricEngland.org.uk/har** 

Heritage at Risk Published October 2015 1 Waterhouse Square 138–142 Holborn London EC1N 2ST © Copyright Historic England 2015 Product code: 51989



East of England Register 2015