





# Contents



LP

// -----

# LONBON



Despite the challenges of recession, the number of sites on the Heritage at Risk Register continues to fall. Excluding listed places of worship, for which the survey is still incomplete, 1,150 assets have been removed for positive reasons since the Register was launched in 2008. The sites that remain at risk tend to be the more intractable ones where solutions are taking longer to implement.

While the overall number of buildings at risk has fallen, the average conservation deficit for each property has increased from £260k (1999)

to  $\pounds$ 370k (2012). We are also seeing a steady increase in the proportion of buildings that are capable of beneficial re-use – those that have become redundant not because of any fundamental lack of potential, but simply as the temporary victims of the current economic climate.

London is basking in the afterglow of the very successful Olympic and Paralympic games, events that showcased the wealth of its historic environment to viewers and visitors across the world. The choice of Greenwich for the equestrian events provided the final stimulus for the successful restoration of the fire-damaged, grade I listed Cutty Sark in time for the games.

The Cutty Sark was perhaps the most high profile asset to come off the London Register in the last year, but was only one of 49 buildings, two scheduled monuments and two registered parks and gardens in London that were successfully secured for the future. Despite the very challenging times through which we are living, the percentage of grade I and II\* buildings at risk in London continues to reduce slightly, down to 3.8% from 4.2% last year.

Progress on the priority Heritage at Risk sites in London has also been maintained with the most notable success being at Gunnersbury in the London Borough of Hounslow. Heritage Lottery Fund support has been secured to enable the repair and restoration of a series of listed buildings and a registered landscape as part of a long-term 'Gunnersbury 2026' project.

English Heritage itself has recently acquired the medieval Great Barn at Harmondsworth, once dubbed by Sir John Betjeman as the 'Cathedral of Middlesex', and is now preparing to carry out urgently needed repairs. We are also in discussion with partners to try and progress a solution for the important but neglected Abney Park Cemetery in Stoke Newington. Meanwhile, Clissold House and the Granary at Kings Cross have been re-invigorated, meaning that both sites now have bright futures. The biggest challenge for London remains the condition of its burial grounds and cemeteries, several of which are also important registered landscapes. In the last year a comprehensive survey of their condition has resulted in more than 70 new entries onto the Register. The first step in tackling heritage at risk is to establish the scale of the problem and in the case of cemeteries we now have a much clearer understanding of the challenge ahead.

The second largest category of new entries on the Register this year is buildings. Approximately 30 examples, in both private and public ownership and capable of use, have had to be added because of their neglected condition. Many were last in residential use and could once again provide good homes for the population of the capital.

Despite the difficult economic context, we believe that a combination of perseverance, determination and creative partnership will allow us to increase the number of positive outcomes and thus further reduce the percentage of London's irreplaceable heritage assets at risk.



**Nigel Barker** Head of Partnerships, London

#### GUNNERSBURY PARK, LONDON BOROUGH OF HOUNSLOW

This Georgian house is one of a number of buildings at risk within the grade II\* registered Gunnersbury Park that was purchased for the nation from the Rothschild family in 1925. The Heritage Lottery Fund has awarded Stage I grants for restoration and reinstatement of the park and refurbishment of the Large Mansion, which has been used since 1929 as a local history museum for the London Boroughs of Ealing and Hounslow. In parallel, a grant from English Heritage has allowed urgent repair work to begin on other buildings at risk in the park. © English Heritage

#### **BUILDINGS AT RISK**

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In London this rises to 3.8% (75 buildings).
- 2.7% (449) of London's grade II listed buildings are at risk.
- 49 buildings at risk were removed from the 2011 London Register because their futures have been secured. 115 have been added, the majority as a result of a survey of listed structures in cemeteries and churchyards.

#### PLACES OF WORSHIP AT RISK

• Of the 195 listed places of worship surveyed in London, 37 are at risk. I I have been added this year.

#### SCHEDULED MONUMENTS

- 3,286 (16.6%) of England's 19,759 scheduled monuments are at risk, of which 35 are in London.
- In London, 2 scheduled monuments have been removed from the 2011 Register for positive reasons, and 2 have been added.
- 27% of scheduled monuments (10) on London's baseline 2009 Register have been removed for positive reasons, compared to the national figure of 15.8%.
- Nationally, damage from arable cultivation is the greatest risk factor for scheduled monuments, accounting for 44% of those at risk. In London the proportion is 9%. The greatest threat for 31% of scheduled monuments in London is from unrestricted scrub and tree growth.

#### REGISTERED PARKS AND GARDENS

- 99 (6.1%) of England's 1,617 registered parks and gardens are at risk, a decrease from 103 (6.4%) in 2011. In London, 12 (8%) of our 150 sites are at risk.
- Nationally, 5 sites were removed from the 2011 Register and I has been added. Of the registered parks and gardens removed, 2 are in London.

#### **REGISTERED BATTLEFIELDS**

- Of the 43 registered battlefields in England, 6 are at risk, 2 fewer than the 2008 baseline. London's single registered battlefield is not at risk.
- London's single registered battlefield is not at risk.

#### PROTECTED WRECK SITES

- Of the 46 protected wreck sites off England's coast, 4 are at risk. Of the 10 sites on the 2008 baseline, 9 have been removed. London has no protected wreck sites.
- London has no protected wreck sites at risk.

#### CONSERVATION AREAS

- We now have information on the condition of 7,976 of England's 9,770 conservation areas; 524 (6.6%) are at risk. Of the 949 conservation areas surveyed in London, 65 (6.8%) are at risk.
- 3 conservation areas were removed from the 2011 London Register for positive reasons, but 8 have been added.



#### CLISSOLD HOUSE, LONDON BOROUGH OF HACKNEY

Following an £8.9m programme of Lottery-funded repair, the London Borough of Hackney's magnificent grade II\* mansion has at last been removed from the Heritage at Risk Register. It was reopened to the public in Spring 2012 and now provides a café, restored function rooms and smaller meeting rooms. © Hackney Council



#### PRIORITY HAR SITES

- Abney Park Cemetery, Hackney
- Crossways, 134 Church Road, Hanwell, Ealing
- Finsbury Health Centre, Pine Street, Islington
- Gunnersbury Park (including the west and east stables, the large and small mansions and other structures), Hounslow
- Hanwell flight of locks and brick boundary wall of St Bernard's Hospital, Ealing
- Kensal Green (All Souls) Cemetery (including the Anglican Chapel, a number of monuments and other structures), Kensington and Chelsea
- Manor Farm barn, High Street, Harmondsworth, Hillingdon
- Tide Mill (known as the House Mill), Three Mill Lane, Newham
- Whitechapel High Street and Stepney Green Conservation Areas (High Street 2012), Tower Hamlets
- 94 Piccadilly, Westminster

#### GRADE II PILOT PROJECTS

English Heritage is looking for people to take part in pilot projects that will explore options for expanding the Heritage at Risk programme to include all grade II listed buildings.


A maximum of I 5 pilot projects are required to explore, cost and test various options for undertaking surveys of grade II listed buildings.

For more information and details on how to apply visit:

www.english-heritage. org.uk/risk

#### FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser, English Heritage London, 1 Waterhouse Square, 138 - 142 Holborn, London, EC1N 2ST. Telephone: 0207 973 3000 Email: **Iondon@english-heritage.org.uk** 



Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. This will be challenging given the number of assets on the Register and the different kinds of risk they face.

To help address this challenge we have published our National Heritage at Risk Strategy which will be supported by nine local strategies. Key objectives of the strategy are to understand why assets are at risk and what most influences their removal from the Register and to find solutions for heritage at risk through partnership, stimulating economic regeneration and growth and maximising the benefit of our expertise and resources.

Whilst each asset type and individual site will require its own approach and solution, there are some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential to prevent them becoming at risk, and those that are already at risk from decaying further and the cost of their repair and consolidation from escalating. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing*).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website, **www.helm.org.uk** 

#### LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society, The Twentieth Century Society, the Council for British Archaeology and the Ancient Monuments Society. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk officers to help not-for-profit organisations take building at risk projects forward.

#### Places of worship at risk

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. It also means volunteers do not take unnecessary risks balancing on ladders.

The Repair Grants for Places of Worship scheme helped under-resourced congregations do urgent works to make buildings wind and watertight. From 2013 the Heritage Lottery Fund will fund a new scheme for places of worship. The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports the congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

#### SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Continuing partnership with Defra and Natural England over the last year has seen the introduction of much more effective information sharing so that resources whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. Over the next year we will also work more closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Continued progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage for the period 2011 to 2015 – the Conservation of Scheduled Monuments in Cultivation project has begun across England. The project, which started with a questionnaire to all farmers and landowners with a scheduled monument that is being cultivated, will look at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk still shows that unmanaged tree, scrub and bracken growth is one of the most widespread causes of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers will remain the key to making further progress in ever more challenging circumstances.

#### REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest confers no additional statutory controls but the Government's new National Planning Policy Framework stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. Registered parks and gardens carry the same weight as listed buildings in the National Planning Policy Framework and substantial harm or loss can only be justified in exceptional cases. English Heritage's landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We encourage the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/ advice-by-topic/parks-and-gardens

#### REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the *National Planning Policy Framework*.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

#### PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

#### CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after them is a responsibility shared by those of us who own homes and businesses in them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. However, this is extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/getinvolved/improving-your-neighbourhood

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2012 – national report and summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2012 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

#### CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Works: the use of Historic Buildings in Regeneration (2006)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

# THE REGISTER Content and criteria

#### DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,617 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

#### LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

#### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

#### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed a proportion of the 14,500 listed places of worship. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence which will help us build upon our understanding of the challenges.

#### Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

#### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

# SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,759 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

#### Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

# REGISTERED PARKS AND GARDENS Definition

There are 1,617 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

#### Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

#### REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

#### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

# PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

#### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,700 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

#### Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Key to the entries

### This Register includes the following heritage assets at risk:

- grade I, II\* and II listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (if applicable)
- protected wreck sites (if applicable)
- conservation areas

#### ORDER

Entries are ordered alphabetically by London Borough. Within each Borough, assets are grouped in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- conservation areas

Within each asset type, sites are ordered alphabetically by street and site name. Conservation areas are ordered by site name only. Registered parks and gardens are integrated by locality.

#### DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) Grade I, II\* or II
- Listed Place of Worship Grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) Grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

#### CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

#### TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

#### CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas and grade II listed buildings, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LPA	Local Planning Authority
LB	Listed Building
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

# Heritage at risk entries by local planning authority

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
GREATER LONDON							
Barking and Dagenham	5			0	0	0	
Barnet	10	0		0	0	0	
Bexley	2	0	0		0	0	0
Brent	3	0	0	0	0	0	0
Bromley	24	0	4		0	0	
Camden	39	4	0	0	0	0	0
City of London		2	4	0	0	0	0
Croydon	7		3	0	0	0	
Ealing	8	2	4	0	0	0	9
Enfield			0	2	0	0	2
Greenwich	21			0	0	0	0
Hackney	28	3	0		0	0	2
Hammersmith and Fulham	11	2	0	0	0	0	I
Haringey	16	2	0	0	0	0	5
Harrow	10	0	5		0	0	0
Havering	12	0		0	0	0	
Hillingdon	22	0	2	0	0	0	10
Hounslow	23	0	3		0	0	2
Islington	18	3	0	0	0	0	
Kensington and Chelsea	41	2	0	2	0	0	
Kingston upon Thames	3	0	0	0	0	0	0
Lambeth	38		0		0	0	0
Lewisham	7	0	0	0	0	0	
Merton		0	2	0	0	0	
Newham	23	0	0	0	0	0	2
Redbridge	3	0	0		0	0	2
Richmond upon Thames	10	0	0	0	0	0	
Southwark	31		2		0	0	
Sutton	2		I	0	0	0	0
Tower Hamlets	28	5		0	0	0	9
Waltham Forest	9	0	0	0	0	0	0
Wandsworth	16	0	0	0	0	0	0
Westminster, City of	22	5	0	0	0	0	0
TOTAL	525	37	35	12	0	0	65

GREATER LONDON			
BARKING AND DAGE	NHAM		
Í	SITE NAME:	The Old Vicarage, Crown Street, Dagenham	House, dated 1665, remodelled in C19. The building is currently part occupied and at risk of vandalism. Interest has been expressed in developing the site and a planning application is under consideration
		Listed Building Grade II, CA	for residential conversion.
	CONDITION:	Poor	
	PRIORITY:	Part occupied C (C)	
	OWNER TYPE:		Contact: Francesca Cliff (LPA) 020 8227 3910
	SITE NAME:	Magistrates Court, East Street, Barking	Built 1893 in the manner of the Flemish Renaissance. The building was in use as a Magistrates Court but has now been empty for nearly a year. There are no future plans for the building.
		Listed Building Grade II, CA Good	
	CONDITION:		
	PRIORITY:	E (New entry)	
		Government	Contact: Francesca Cliff (LPA) 020 8227 3910
			× •
	SITE NAME:	The Marks Stones, Whalebone Lane North, Chadwell Heath	Boundary marker of the Liberty of Havering-atte-Bower, originally set up in 1642. Two stones: one 12 inches high inscribed 'Marks Stone', one 30 inches high inscribed 'Marks Stone Sont 1642' One stone is below and is
A Card	DESIGNATION:	Listed Building Grade II	'Marks Stone Sept I 642'. One stone is broken and is in safekeeping, the other remains in its original position.
	CONDITION:	Very bad	To be repaired when the land levels in the quarry have been restored and the restoration of the area is complete.
	OCCUPANCY:		been restored and the restoration of the area is complete.
	PRIORITY: OWNER TYPE:	D (D)	Contact: Francesca Cliff (LPA) 020 8227 3910
	OVVINER I TPE:	Clowin	Contact. Trancesca Cini (ErA) 020 0227 5710
•••	SITE NAME:	The Warren Stone, Whalebone Lane North, Chadwell Heath	Boundary stone erected in 1642. The stone marked the boundary of Hainault Forest, along with the Marks Stones and the Forest Bounds Stone. The stone is in storage
	DESIGNATION:	Listed Building Grade II	at Warren Farm during ongoing quarrying operations. The intention is to reinstate the stone in its original
	CONDITION:	Poor	position when the quarrying is finished. To be repaired
	OCCUPANCY:		when the land levels in the quarry have been restored.
a lander to the state	PRIORITY:	D (D)	
	OWNER TYPE:	Crown	Contact: Francesca Cliff (LPA) 020 8227 3910
	SITE NAME:	Chadwell Heath anti-aircraft gun site, Whalebone Lane North (off), Chadwell Heath	battery with pits for eight guns in two groups of four and associated structures. The buildings are subject to
Carly water falls and a	DESIGNATION:	Listed Building Grade II, CA	vandalism and are in an isolated spot, surrounded by a quarry, increasing their chances of further deterioration.
	CONDITION:	Poor	Work has now started on filling in the quarry. The future
	OCCUPANCY:		of the site is being discussed with English Heritage and the local community.
and the second	PRIORITY:	C (C)	,
	OWNER TYPE:	Crown	Contact: Francesca Cliff (LPA) 020 8227 3910
	SITE NAME:	Church of St Peter and St Paul, Crown Street, Dagenham	Church of medieval origins, rebuilt with red brick Gothic tower 1800. Nave part ashlar and random rubble, and rendered chancel. Slipped and missing tiles on chancel and blocked rainwater hoppers.
	DESIGNATION:	Listed Place of Worship Grade II*, CA	
	CONDITION:	Poor	
	PRIORITY:	C (C)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / BARKING AND DAGENHAM / BARNET

SITE NAME:	Barking Abb	ey, Barking and Dagenham				
DESIGNATION:	Scheduled M	onument (No.1003581)	CONDITION:	Extensive significant problems		
RINCIPAL VULNERABILITY:	Vandalism		TREND:	Declining		
DWNER TYPE:	Local author	ity	CONTACT:	Principal Heritage at Risk Adviser		
				020 7973 3000		
SITE NAME:	Chadwell He	eath Anti-Aircraft Gun Site, Marks	Gate			
DESIGNATION:	Conservatio	Area	CONDITION:	Very bad		
/ULNERABILITY:	Medium		TREND:	Deteriorating		
CONTACT:	Francesca Cl	iff (LPA) 020 8227 3910	NEW ENTRY?:	No		
BARNET						
	C	omb of John Jones, Church End, St Mary's Churchyarc Iendon NW4	. dating from	al over base with carved fielded panels, early C18. Panels have now been exposing damaged brickwork.		
	designation:	isted Building Grade II, CA				
		'ery bad				
- ARE NO.	OCCUPANCY:	/				
		(New entry)				
the fully a straight		ocal authority	Contact: Jor	nathan Hardy (LPA) 020 8359 4655		
		,	,			
1 Alexandre	C	omb of Susannah Frye, Church End, St Mary's Churchyarc Iendon NW4		o with inset angle balusters, a curved carvings of funerary and heraldic imagery. end panel.		
	designation: L	isted Building Grade II, CA				
Sand and the sand the sand	CONDITION: F	oor				
	occupancy: N	J/A				
	PRIORITY:	C (New entry)				
	OWNER TYPE: L	ocal authority	Contact: Jor	Contact: Jonathan Hardy (LPA) 020 8359 4655		
	A	Colindale Hospital Administration Block, Colindale Avenue NW9	Consent gr	Iministration block dated 1899. Baroque style. anted for conversion of the building and site Works are ongoing.		
	designation: L	isted Building Grade II, CA				
	condition: F	oor				
	occupancy: $\vee$	'acant				
	priority: F	(F)				
	OWNER TYPE:	Company	Contact: Jor	nathan Hardy (LPA) 020 8359 4655		
	E	he Bothy, ast End Road, inchley N3	comprising storage. Co	mpound in the grounds of Avenue House, summer house, living accommodation and ompleted in 1882. Building is vacant and optior		
		isted Building Grade II, CA	for future u	ise are being considered by the Trust.		
		air				
	OCCUPANCY: V	'acant				
	PRIORITY:	C (C)				
he had	OWNER TYPE: 7	rust	Contact: Jor	nathan Hardy (LPA) 020 8359 4655		
	E	The Water Tower, ast End Road, inchley N3	The structuis overgrow	er, circa 1800, built of massed concrete. Ire has been neglected for many years and In with ivy which is likely to be contributing		
- AND -	designation: L	isted Building Grade II, CA	to the large	e cracks in the concrete. There are currently als for future use.		
P P		ery bad				
	occupancy: V	'acant				
	PRIORITY: A	м (А)				
a for	OWNER TYPE: 7	rust	Contact: Jor	nathan Hardy (LPA) 020 8359 4655		

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

		College Farm – main building, Fitzalan Road N3	Frederick C	shop and dairy, built 1883 to the design of Chancellor in a picturesque style. Model dairy
1 And				Express Dairy Company Acquired by the m Trust who are developing plans for the
		Listed Building Grade II, CA		ency repairs undertaken.
	CONDITION:	Fair		
		Occupied		
Mar I and the	PRIORITY:	C (C) Truct	Contact: lor	nathan Hardy (LPA) 020 8359 4655
	OWNER I TPE:	ii ust	Contact. joi	
	SITE NAME:	College Farm Dairy, Fitzalan Road N3	with ornate	1883 to the design of Frederick Chancellor, timber lantern roof and decorative tilework Condition of building is deteriorating. See also
	DESIGNATION:	Listed Building Grade II, CA	entry for C	ollege Farm main building.
ALLENGT	CONDITION:	Fair		
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:		Contact: Jor	nathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Silo, Fitzalan Road, College Farm N3	of the Expr Condition o	83 to the design of Frederick Chancellor as pa ess Dairy Company's pioneering model farm. of building is deteriorating. See entry for Colleg
	DESIGNATION:	Listed Building Grade II, CA	Farm main	building.
	CONDITION:	Fair		
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
14	OWNER TYPE:	Trust	Contact: Jor	nathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Monument to Major John Cartwright St Mary at Finchley Churchyard, Hendon Lane N3	by public su tapering ob	erected in 1835 to Major John Cartwright Joscription. Yellow oolitic limestone. Square Jelisk with armorial and portrait roundels.
	DESIGNATION:	Listed Building Grade II, CA		dismantled due to dangerous condition.
	CONDITION:	Poor	Restoration	under discussion.
	OCCUPANCY:			
	PRIORITY:	A (A)		
		Local authority	Contact: Jor	nathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Physic Well,	Timber-fran	ned cruciform cover to well circa 1937.
	SHE NULL.	Well Approach EN5	Beneath is t chamber: O	the original C17 barrel-vaulted brick well Ince a fashionable rendezvous for Londoners
	DESIGNATION:	Listed Building Grade II		dicinal qualities of the mineral waters. or refurbishment being discussed.
	CONDITION:	Poor	i i op obaio ii	
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
	OWNER TYPE:	Local authority	Contact: Jor	nathan Hardy (LPA) 020 8359 4655
CITE NIAME.	Brockley	Hill Romano-British pottery and settler	ment Barnet	
SITE NAME:	-			Extensive significant problems
DESIGNATION:		Monument (No.1018006)	CONDITION:	Extensive significant problems Unknown
PRINCIPAL VULNERABILITY:	Arable plo Private		TREND:	Principal Heritage at Risk Adviser
OWNER TYPE:	Frivale		CONTACT:	020 7973 3000
SITE NAME:	College Fa	ırm, Finchley		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	Medium		TREND:	Deteriorating
CONTACT:		Hardy (LPA) 020 8359 4598	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### HERITAGE AT RISK 2012 / LONDON / BEXLEY / BRENT

#### BEXLEY

BLALLI			
	SITE NAME:	Crossness Pumping Station, Belvedere Road	Opened 4 April 1865. Engineer: Joseph Bazalgette. Retains important cast-iron interior fittings and four colossal beam engines by James Watt and Co. The Crossness Engines Trust, with Heritage Lottery Funding and English Heritage
	DESIGNATION:	Listed Building Grade I, CA	grant, is restoring the building, and is expected to be
ulles land - The	CONDITION:	Good	completed 2013. When complete it is envisaged the complex will be removed from the Register.
	OCCUPANCY:	Occupied	complex will be removed if one the fiscal
	PRIORITY:	F (F)	
The second second	OWNER TYPE:	Irust	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	site name:	Chapel House, 497 Blackfen Road, Sidcup	An eye-catcher as part of the layout of Danson Park – circa 1761 attributed to Lancelot 'Capability' Brown. Now separated from park by A2 trunk road and modern houses. Some render repairs have been carried out.
		Listed Building Grade II	A dialogue continues between the Local Authority
	CONDITION:	Fair	and the owner occupiers to find a sustainable use and future for the building.
		Part occupied	and lotor of the building.
	PRIORITY:	C (C)	Contact Condon Empon (LRA) 020 2045 5780
	OWNER TYPE:	Company	Contact: Gordon Fraser (LPA) 020 3045 5789
	SITE NAME:	Lamorbey Park	An C18 landscape park with early C19 pleasure grounds and C20 gardens. The park was partially converted to a golf course in the early C20 and
MR. S. Salin	DESIGNATION:	Registered Park and Garden Grade II,	further subdivided by the construction of three
		also part in CA, 4 LBs	schools. Part of the gardens are managed by Bexley as a public park. The gardens and pleasure grounds
	CONDITION:	Extensive significant problems	are in need of repair, and management of the historic
	VULNERABILITY	· · · · · · · · · · · · · · · · · · ·	landscape is disjointed due to the separate ownerships.
	TREND:	Declining	
	OWNER TYPE:	Mixed, multiple owners	Contact: Principal Heritage at Risk Adviser 020 7973 3000
BRENT			
	SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6	Built 1863 as St James's Episcopal Chapel. Prefabricated structure of corrugated iron with boarded roof covered in corrugated asbestos. The Hall is within the South Kilburn New Deal for Communities area and is the subject of a
	DESIGNATION:	Listed Building Grade II, CA	conservation study and assessment. The Local Authority
	CONDITION:	Poor	is exploring possible uses.
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
	OWNER TYPE:	Housing Association	Contact: Mark Smith (LPA) 020 8937 5267
20.			
In	SITE NAME:	Old Oxgate Farm, Coles Green Road, Cricklewood NW2	C16 and C17 timber-frame building; possibly the oldest surviving house in the Borough. Suffering from subsidence to brick plinth and structural failure of beam ends to ground floor due to damp penetration. Local authority
	DESIGNATION:	Listed Building Grade II*	are discussing possible options with the owners.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied	
	PRIORITY:	C (C)	Constants Duis single Lawits and at Dist. A divisory 020 7072 2000
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	St Andrew's Old Church, Old Church Lane, Kingsbury NW2	C12 to C13 former church. Repairs completed. To be vested in the Churches Conservation Trust. Confirmation is awaited of future use.
	DESIGNATION:	Listed Building Grade I, CA	
	CONDITION:	Good	
	OCCUPANCY:		
	PRIORITY:	F (F)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

BROMLEY			
	SITE NAME: DESIGNATION:	Crystal Palace Low Level Station, Crystal Palace Listed Building Grade II, CA	Mid C19 station, built for visitors to the Crystal Palace. Extensive repairs and restoration works completed in November 2001. The building is partially occupied. Works to refurbish the former booking hall and demolish modern extension to south commenced April 2012.
	CONDITION:	Fair	
		Part occupied	
	PRIORITY:	F (F)	
		Company	Contact: Kevin Munnelly (LPA) 020 8313 4582
		1 /	
	SITE NAME:	Pedestrian subway under Crystal Palace Parade, Crystal Palace	Pedestrian subway circa 1854. Included in the 2008 master plan application for the regeneration of the park as site of a proposed new museum. Holding repairs currently being considered.
666	DESIGNATION:	Listed Building Grade II	currently being considered.
	CONDITION:	Poor	
	OCCUPANCY:		
and the Alexander	PRIORITY:	C (C)	
and the second s	OWNER TYPE:	Local authority	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Upper and Lower Terraces, Crystal Palace Park	Terraces designed by Sir Joseph Paxton and situated to the east of the site of Crystal Palace (re-erected here in 1852-4 and burnt down in 1936), on the west of Crystal Palace Park. In a ruinous condition and
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	suffering from erosion.
1 - 3.9.9 - 11 Int when	CONDITION:	Poor	5
	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Crystal Palace Park	C19 pleasure grounds designed by Sir Joseph Paxton as a
- State -	DESIGNATION:	Registered Park and Garden Grade II*, also CA, 6 LBs	setting for the Crystal Palace (re-erected here 1852-4 and burnt down in 1936). Park is in deteriorating condition and the grade II listed terraces, pedestrian subway and railings
A AMARA	CONDITION:	Generally unsatisfactory with major localised problems	are also at risk. English Heritage supported a master plan for repair and regeneration of the park and discussions will
	VULNERABILITY		be held throughout 2012 with the Heritage Lottery Fund to test the feasibility of an application through the Parks
	TREND:	Declining	for People programme.
		Local authority, single owner	Contact: Principal Heritage at Risk Adviser 020 7973 3000
-	SITE NAME:	The Studio, 28 Beckenham Road, Beckenham	Technical Institute, later arts centre. Built in Dutch style in I 898 for Beckenham Urban District Council. Vacant. Applications for planning and listed building consent have been granted for community use.
	DESIGNATION:	Listed Building Grade II	Work is yet to commence.
	CONDITION:	Fair	,
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	Local authority	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Derwent House, 68 Camden Park Road, Chislehurst	Substantial house (1899) by Ernest Newton. Latterly used as a nursing home. Permission granted for conversion to flats and scheme recently permitted for single residential use. Work has commenced.
	DESIGNATION:	Listed Building Grade II, CA	ase, work has commenced.
		Fair	
	OCCUPANCY:		
	PRIORITY:	E (E)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### HERITAGE AT RISK 2012 / LONDON / BROMLEY

	SITE NAME:	North and south railings, Crystal Palace Parade, Crystal Palace	Decorative cast iron railings on gault brick plinths with stone copings. Formed the main pedestrian entrance to the Crystal Palace (demolished following a major
	DESIGNATION:	Listed Building Grade II, RPG II*	fire in 1936) from Crystal Palace Parade.
	CONDITION:	Poor	
A CONTRACTOR OF THE OWNER	OCCUPANCY:	N/A	
- CE STARD	PRIORITY:	C (New entry)	
THE MAN THE SAME	OWNER TYPE:	Local authority	Contact: Kevin Munnelly (LPA) 020 8313 4582
		,	
And	SITE NAME:	Downe Court Manor, Cudham Road, Downe	Modest red brick house of 1690. Starting to show the effects of long term neglect. Roof and joinery repairs have been undertaken to arrest the decline of the building. House this work, which included
111	DESIGNATION:	Listed Building Grade II	of the building. However, this work, which included alterations, is subject to enforcement action.
	CONDITION:	Poor	,,,,,
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Frontage building to Richard Klinger Factory, Edgington Way, Sidcup	Offices, cutting shop, tool room and storage factory. Completed in 1937 to the designs of Wallis Gilbert and Partners for Richard Klinger Ltd, founded in Austria
THE PROPERTY OF	DESIGNATION:	Listed Building Grade II	in 1893. The building has been vacant for many years. Crittal window frames intact, interior dilapidated.
The second se	CONDITION:	Poor	Previous planning application for IKEA store withdrawn.
KLINGER BILL	OCCUPANCY:	Vacant	Future use uncertain.
	PRIORITY:	С (С)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
1 N 1	SITE NAME:	20-22 Hamlet Road,	Pair of mid C19 stuccoed houses suffering from
		Crystal Palace	structural problems.
FREE	DESIGNATION:	-	structural problems.
	DESIGNATION: CONDITION:	Crystal Palace Listed Building Grade II, CA Poor	structural problems.
	CONDITION:	Listed Building Grade II, CA Poor	structural problems.
	CONDITION:	Listed Building Grade II, CA Poor Occupied	structural problems.
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Occupied C (C)	structural problems.
	CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Occupied C (C)	structural problems.
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Occupied C (C)	structural problems.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E)	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E)	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E) Private 318 High Street, St Mary Cray	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up. Contact: Kevin Munnelly (LPA) 020 8313 4582
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E) Private 318 High Street, St Mary Cray	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up. Contact: Kevin Munnelly (LPA) 020 8313 4582
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E) Private 318 High Street, St Mary Cray	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up. Contact: Kevin Munnelly (LPA) 020 8313 4582
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E) Private 318 High Street, St Mary Cray Listed Building Grade II, CA Poor Vacant	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up. Contact: Kevin Munnelly (LPA) 020 8313 4582
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Occupied C (C) Private The Royal Bell Hotel, 173-177 High Street, Bromley Listed Building Grade II, CA Fair Vacant E (E) Private 318 High Street, St Mary Cray Listed Building Grade II, CA Poor Vacant C (C)	structural problems. Contact: Kevin Munnelly (LPA) 020 8313 4582 This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is currently vacant and boarded up. Contact: Kevin Munnelly (LPA) 020 8313 4582



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS



	site name:	91 High Street, St Mary Cray	CI6 dwelling with crown post roof. In poor condition, currently being recorded by local archaeological society. Potential listed building consent application to be
	DESIGNATION:	Listed Building Grade II, CA	submitted for use as dwelling. At risk of collapse.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Former Officers Mess, RAF Biggin Hill, Main Road, Biggin Hill	Officers' mess, circa 1935. Partially occupied but suffering neglect due to cost of repairs and maintenance. Planning permission and listed building
1 1 1 7	DESIGNATION:	Listed Building Grade II, CA	consent have been granted for conversion to a hotel.
	CONDITION:	Poor	
		Part occupied	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	· · · · ·	Contact: Robert Buckley (LPA) 020 8461 7532
	SITE NAME:	Building IO (Junior Ranks Mess), West Camp, Main Road, A233 (east side), Biggin Hill	Airmen's Institute and recreation centre, with dining room. Circa 1926 design, built 1930.Vacant since Royal Air Force withdrew from Biggin Hill in 1993. No new use has been identified.
Committee Constant	DESIGNATION:	Listed Building Grade II, CA	use has been identified.
	CONDITION:	Poor	
TERMINATERE ENTER	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Building I2 (Candidate's Club, Former Sergeant's Mess), West Camp, Main Road, A233 (east side), Biggin Hill	Sergeant's mess, 1932. By the Air Ministry's Directorate of Works and Buildings.Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
Martin Contraction of the	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Building I 5, Hawkinge Block, West Camp, Main Road, A233 (east side), Biggin Hill	Barrack block. Dated 1934. By the Air Ministry's Directorate of Works and Buildings.Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.
		Lists of Dudidius - Cus de II. C.A	
	DESIGNATION:	Listed Building Grade II, CA	
	DESIGNATION:	Poor	
		Poor	
	CONDITION:	Poor	
	CONDITION: OCCUPANCY:	Poor Vacant C (C)	Contact: Kevin Munnelly (LPA) 020 8313 4582
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Vacant C (C) Private Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill	Contact: Kevin Munnelly (LPA) 020 8313 4582 Office block, formerly station headquarters building. Dated 1931.Vacant since RAF withdrew from Biggin Hill in 1993. No new use has been secured.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Vacant C (C) Private Building 33 (Station HQ), West Camp, Main Road,	Office block, formerly station headquarters building. Dated 1931.Vacant since RAF withdrew from Biggin Hill
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Vacant C (C) Private Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill	Office block, formerly station headquarters building. Dated 1931.Vacant since RAF withdrew from Biggin Hill
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Poor Vacant C (C) Private Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill Listed Building Grade II, CA Poor	Office block, formerly station headquarters building. Dated 1931.Vacant since RAF withdrew from Biggin Hill
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Poor Vacant C (C) Private Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill Listed Building Grade II, CA Poor	Office block, formerly station headquarters building. Dated 1931.Vacant since RAF withdrew from Biggin Hill

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / BROMLEY

	SITE NAME:	Buildings I-5 (Airmen's barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill	Group of five airmen's barracks blocks, 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill in 1993. They have generally been kept in good order but
	DESIGNATION:	Listed Building Grade II, CA	no new use has been identified.
		Poor	
	OCCUPANCY:	Vacant	
as the second second	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	lce house to Sundridge Park, Plaistow Lane, Bromley	Ice house circa 1800, in the south-west corner of late C18 landscape park designed by Humphry Repton, now a golf course. Ice house subject to continuous vandalism
	DESIGNATION:	Listed Building Grade II, RPG II	despite strenuous efforts by owners to prevent access.
TOTAL TOTAL		Very bad	Negotiations about its future have so far failed to find a suitable solution.
State	OCCUPANCY:	,	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	The Convent of the Holy Trinity, Plaistow Lane, Bromley	House built by John Hulls about 1708 and since 1888 used as a convent and school. Now vacant. Badly damaged by vandalism and water ingress.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	lce house to Old Palace, Stockwell Close, Bromley Palace Park	Ice house to Bromley Old Palace. Located in the gardens of the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter possible used as a stopping off point when
		Stockwell Close,	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when
	DESIGNATION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation
	DESIGNATION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C)	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C)	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter; possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close,	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter; possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C)	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A	the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite waterfall, Stockwell Close, Bromley Palace Park	<ul> <li>the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite waterfall, Stockwell Close, Bromley Palace Park Listed Building Grade II	<ul> <li>the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite waterfall, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor	<ul> <li>the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite waterfall, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A	<ul> <li>the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor N/A C (C) Local authority Pulhamite waterfall, Stockwell Close, Bromley Palace Park Listed Building Grade II Poor	<ul> <li>the Palace at the southern end of the ornamental lake, near the waterfall. Probably late C18, remodelled in early C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. In poor condition and in need of conservation and repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> <li>Contact: Kevin Munnelly (LPA) 020 8313 4582</li> <li>Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal merchant. The Fernery is at the northern end of the ornamental lake. In need of repair.</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME: Old Town Hall, Tweedy Road, Bromley	premises of	vn Hall building built in 1906. Had been used as f Bromley College until 2006/07.The building is artially vacant and awaiting a suitable use.
	designation: Listed Building Grade II, CA		
	condition: Fair		
	occupancy: Part occupied		
	PRIORITY: E (E)		
	OWNERTYPE: Local authority	Contact: Ke	evin Munnelly (LPA) 020 8313 4582
SITE NAME:	Camp on Keston Common, Bromley		
DESIGNATION:	Scheduled Monument (No.1002022)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	High Elms ice house I 30m south of Flint L	.odge, Bromley	
DESIGNATION:	Scheduled Monument (No.1018959)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Iron Age settlement and Roman villa at W	′arbank, Keston, Bro	omley
DESIGNATION:	Scheduled Monument (No.1002024)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
	Private	CONTACT:	Principal Heritage at Risk Adviser
OVVINER I I FE:			020 7973 3000
	Romano-British masonry building and Sax	on cemetery, Fordc	
SITE NAME:	Romano-British masonry building and Sax Scheduled Monument (No.1001973)	on cemetery, Fordc	
ITE NAME:	, -	•	roft, Orpington, Bromley
ite name: Designation:	, -	•	roft, Orpington, Bromley Generally unsatisfactory
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1001973)	CONDITION:	Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE:	Scheduled Monument (No.1001973) Vandalism	CONDITION: TREND:	Froft, Orpington, Bromley Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWINER TYPE: SITE NAME:	Scheduled Monument (No.1001973) Vandalism Local authority	CONDITION: TREND:	roft, Orpington, Bromley Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Monument (No.1001973) Vandalism Local authority Biggin Hill RAF	CONDITION: TREND: CONTACT:	Froft, Orpington, Bromley Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser

#### CAMDEN



#### 9 Calthorpe Street WCI SITE NAME:

designation:	Listed Building Grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	E (E)
OWNER TYPE:	Local authority

One of a terrace of 21 houses dating from 1821-26, constructed in yellow stock brick over four storeys plus basement. The property remains vacant but has been squatted intermittently. Repairs have been undertaken to the roof to ensure building is watertight. Application being considered for refurbishment and subdivision (spring 2012).

Contact: Joanna Ecclestone (LPA) 020 7974 2078

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE-2011 priority categories are given in brackets.

### ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	44 Chalcot Crescent, Primrose Hill NWI	Built as part of a terrace of I2 houses circa I855. Stucco with rusticated ground floor and canted bay window, also slated roof, three storeys and basement. Roof structure
	DESIGNATION:	Listed Building Grade II, CA	removed and most rooms have lost original detailing.
MARK MARK MENT	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (New entry)	
A CONTRACTOR OF THE OWNER	OWNER TYPE:	Private	Contact: Catherine Bond (LPA) 020 7974 2669
	SITE NAME:	Cattle trough to south east of the Roundhouse, Chalk Farm Road NWI	Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist
	DESIGNATION:	Listed Building Grade II, CA	Charles Kingsley. Some repairs carried out but investigation needed into the security of the trough
	CONDITION:	Poor	on the plinth. Vulnerable from being situated adjacent
	OCCUPANCY:	N/A	to the bus lane and bus stop.
	PRIORITY:	C (C)	
The second second	OWNER TYPE:	Local authority	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NW1	Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but remains
	DESIGNATION:	Listed Building Grade II, CA	prone to littering and damage.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Unknown	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	Stanley Sidings: stables (inc. stables A, B, C, D), Chalk Farm Road NWI	Important complex of industrial stabling built 1883-1895 for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment
		stables (inc. stables A, B, C, D),	for the Camden Goods Yard of the London and North
		stables (inc. stables A, B, C, D), Chalk Farm Road NWI	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment
	DESIGNATION:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment
	DESIGNATION:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied D (D) Company	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry)	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	stables (inc. stables A, B, C, D), Chalk Farm Road NWI Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry)	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals for mixed use scheme included in Kings Cross Central
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation Stanley Buildings South, Flats 21-30, Clarence Passage,	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation Stanley Buildings South, Flats 21-30, Clarence Passage, Kings Cross NW1	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals for mixed use scheme included in Kings Cross Central
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation Stanley Buildings South, Flats 21-30, Clarence Passage, Kings Cross NW1 Listed Building Grade II, CA Poor Vacant	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals for mixed use scheme included in Kings Cross Central
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation Stanley Buildings South, Flats 21-30, Clarence Passage, Kings Cross NW1 Listed Building Grade II, CA Poor Vacant C (C)	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals for mixed use scheme included in Kings Cross Central planning application.
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	stables (inc. stables A, B, C, D), Chalk Farm Road NW1 Listed Building Grade II, CA Fair Part occupied D (D) Company Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3 Listed Building Grade II, CA Fair N/A A (New entry) Religious organisation Stanley Buildings South, Flats 21-30, Clarence Passage, Kings Cross NW1 Listed Building Grade II, CA Poor Vacant C (C)	for the Camden Goods Yard of the London and North Western Railway. Scheme approved for refurbishment of stables with new development for arts/retail use. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Stone stele from mid C19 with flanking angels holding a cross and an inscription. Leaning heavily. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Philanthropic flats built in 1865 to design by Matthew Allen under guidance of Sydney Waterlow. Proposals for mixed use scheme included in Kings Cross Central

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

H II	SITE NAME:	Former Strand Union Workhouse (Middlesex Hospital Annex), 44 Cleveland Street	Former Strand Union workhouse, 1778 austere symmetrical brick building facing Cleveland Street behind later high brick walls. Vacated by University College London Hospital
	DESIGNATION:	Listed Building Grade II, CA	and in temporary occupation by live-in guardians in listed buildings, and by site staff in adjoining unlisted buildings.
	CONDITION:	Fair	Buildings currently weathertight and secure.
	OCCUPANCY:	Part occupied	
	PRIORITY:	E (New entry)	
	OWNER TYPE:	Health Authority	Contact: Joanna Ecclestone (LPA) 020 7974 2078
		,	
iii ii	SITE NAME:	26 Denmark Street WC2	Early C18 terraced house; windows altered in C20. Bar on ground floor. Windows, parapets and gutters still in poor condition.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
TZ BAR CAT	PRIORITY:	С (С)	
	OWNER TYPE:		Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	9 Downshire Hill NW3	Early C19 villa. The property is in a very poor condition. Partial demolition of the roof, rear wall and rear wing has been undertaken in order to stabilise the majority
	DESIGNATION:	Listed Building Grade II, CA	of the building. Extensively scaffolded and propped pending redevelopment.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	B (A)	
	OWNER TYPE:		Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	The Elms (formerly Elm Lodge), Fitzroy Park N6	Detached house built 1838-40 to the design of George Basevi. Under refurbishment for residential use with new development but progress slow with extensive works
	DESIGNATION:	Listed Building Grade II, CA	yet to be completed.
	CONDITION:	Poor	
ISI ITAT THE TIL	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNER TYPE:	Company	Contact: Catherine Bond (LPA) 020 7974 2669
	SITE NAME:	43 Fitzroy Street WI	One of a terrace of four houses, dating from the late C18, constructed from darkened multi-coloured stock
			brick with some stucco dressings. Comprising four storeys
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a
	CONDITION:	Poor Part occupied	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a
	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (A)	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition.
	CONDITION: OCCUPANCY:	Poor Part occupied C (A)	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a
	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (A)	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NW I	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NW I Listed Building Grade II, CA	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Gasholders, 1864-1880. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NW I Listed Building Grade II, CA Fair	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Gasholders, 1864-1880. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NW I Listed Building Grade II, CA Fair N/A	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Gasholders, 1864-1880. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NWI Listed Building Grade II, CA Fair N/A F (D)	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Gasholders, 1864-1880. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central. Dismantled and offsite for repair; to be re-erected on site.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (A) Private Three linked Gasholders, Goods Way NW I Listed Building Grade II, CA Fair N/A	brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied in a deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Gasholders, 1864-1880. Relocation and reuse proposed as part of ongoing redevelopment for Kings Cross Central.



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

H	SITE NAME:	Gasholder No. 8, Goods Way, Kings Cross NWI	Single gasholder erected in 1883 for the Imperial Gas Light and Coke Company. Relocated and reuse proposed as part of the ongoing redevelopment of King's Cross
	DESIGNATION:	Listed Building Grade II, CA	Central. Dismantled and offsite for repairs, to be re-erected on site as part of redevelopment.
	CONDITION:	Fair	re-crected on site as part of redevelopment.
	OCCUPANCY:	N/A	
	PRIORITY:	F (D)	
	OWNER TYPE:	Company	Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	39 Great James Street WCI	One of a terrace of I4 houses, dating from I720-24, comprising four storeys and basement, constructed from brown brick. The property is currently empty.
	DESIGNATION:	Listed Building Grade II*	Listed building consent and planning permission granted in 2011 for refurbishment and rear extension, works
	CONDITION:	Fair	due to start in the summer of 2012.
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Ladies and gentlemen's public conveniences, Guilford Place WC1	Disused late C19 public lavatory sited on a traffic island. Enriched railings and gates with overthrows and lanterns. No current proposals.
AND THE REAL PROPERTY AND	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Educational Body	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	66 Guilford Street WCI	One of a terrace of six houses built circa 1793-99 by James Burton. No solution or scheme agreed to date.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:		Contact: Charlie Rose (LPA) 020 7974 1971
	SITE NAME:	67 Guilford Street WCI	Part of a terrace of three houses built circa 1793-99 by James Burton. No solution or scheme agreed to date.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Charlie Rose (LPA) 020 7974 1971
	SITE NAME:	70-72 (consecutive) Guilford Street WCI	Terrace of three houses built circa I793-99 by James Burton. The grand elevation with giant Doric half columns was designed to close the vista from Queen Square. Consent granted for structural repairs at Nos. 70 and 72.
	DESIGNATION:	0	Consent granted for suldetural repairs at Nos. 70 and 72.
In Indiana State of the state	CONDITION:	Fair	
CAR DIFE	OCCUPANCY:	Occupied	
	PRIORITY:	E (E)	
	OWNER TYPE:	Private	Contact: Charlie Rose (LPA) 020 7974 1971



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	77-82 (consecutive) Guilford Street WC1	Terrace built circa 1793-99 by James Burton. Various degrees of deterioration and condition. Interest shown in several of the properties on a pre-application basis within
	DESIGNATION:	Listed Building Grade II, CA	the last year but no solution or scheme agreed to date.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
and a stand and the	PRIORITY:	C (C)	
	OWNER TYPE:		Contact: Charlie Rose (LPA) 020 7974 1971
	SITE NAME:	Railings to water reservoir, Upper Terrace, Hampstead Grove, Hampstead NW3	Railings surrounding reservoir of 1856. Cast iron, with urn finials and secondary lower rails. Larger finials at each seventeenth upright. Moulded kerb of cast iron above brick
	DESIGNATION:	Listed Building Grade II, CA	plinth.The railings are at risk due to lack of maintenance which is causing damage to the plinth and ironwork.
	CONDITION:	Poor	Repairs/reinstatement scheme granted LBC May 2011
	OCCUPANCY:	N/A	but no works commenced as of March 2012.
CONTRACTOR OF CONTRACT	PRIORITY:	D (C)	
	OWNER TYPE:	Company	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	I Hawley Road NWI	Early C19 detached villa. Has been used as an office and also for storage. External works on site at the end of 2011, render and joinery repairs.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	B (B)	
	OWNER TYPE:	Private	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	Fountain and pond in the Italianate Garden,Witanhurst, Highgate West Hill N6	Fountain set in circular pond forming a central feature of the Italianate Garden, built circa 1913, probably to design of Harold Peto for Sir Arthur Crosfield. Site is in new
A STATE OF A STATE	DESIGNATION:	Listed Building Grade II, CA	ownership and works on the house have commenced.
TEST	CONDITION:	Very bad	
AND	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
Pure ALE	OWNER TYPE:	Private	Contact: Catherine Bond (LPA) 020 7974 2669
	SITE NAME:	Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6	Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. Two are now missing; the remaining two are in storage. Property is in
HEAT I BE WAR	DESIGNATION:		new ownership and works to the house have commenced.
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	D (D)	
	OWNER TYPE:	DI	Contact: Hannah Walker (LPA) 020 7974 5786
	SITE NAME:	Garden steps and retaining wall in grounds of Witanhurst, Highgate West Hill N6	Garden steps and retaining wall, circa 1913 by Harold Peto as part of his design for Sir Arthur Crosfield's garden. Property is in new ownership and works to the house have commenced.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
Distance in the second s	PRIORITY:	D (D)	
	OWNER TYPE:		Contact: Hannah Walker (LPA) 020 7974 5786



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Italianate Garden in grounds of Witanhurst, Highgate West Hill N6	Italianate Garden comprising walls, steps, gateway, sunken pond and pergola. Built circa 1913, probably designed by Harold Peto for Sir Arthur Crosfield. Property is in new
Times a Times	DESIGNATION:	Listed Building Grade II, CA	ownership and works to the house have commenced.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Hannah Walker (LPA) 020 7974 5786
mamania	SITE NAME:	Tennis pavilion in the grounds of Witanhurst, Highgate West Hill N6	Tennis Pavilion, 1913. Designed by Harold Peto as part of his design for Sir Arthur Crosfield's garden. Urgent works have been carried out to make the building wind and weather tight. Property is in new ownership and works
	DESIGNATION:	Listed Building Grade II, CA	to the house have commenced.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Hannah Walker (LPA) 020 7974 5786
	SITE NAME:	Witanhurst, 41 Highgate West Hill N6	Substantial detached house, 1913-20 by George Hubbard for Sir Arthur Crosfield. Incorporating early C18 house 'Parkfield' enlarged in 1881.Vacant for many years, now in new ownership. Listed building consent granted in 2009 for full repairs to roof.
Time a	DESIGNATION:	Listed Building Grade II*, CA	Consented repair works undertaken. Planning and listed
	CONDITION:	Fair	building consent granted for full repair and refurbishment
	OCCUPANCY:		for use as a dwelling house. Works are underway.
	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	I and 2 Lincoln's Inn Fields WC2	Two early C18 terraced houses, converted to one in C19.
			The building has been vacant for some time and is at risk of deterioration.
	DESIGNATION:		The building has been vacant for some time and is at risk
	DESIGNATION: CONDITION:	Listed Building Grade II, CA Fair	The building has been vacant for some time and is at risk
		Listed Building Grade II, CA Fair	The building has been vacant for some time and is at risk
	CONDITION:	Listed Building Grade II, CA Fair	The building has been vacant for some time and is at risk
	CONDITION: OCCUPANCY:	Listed Building Grade II, CA Fair Vacant E (New entry)	The building has been vacant for some time and is at risk
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Fair Vacant E (New entry)	The building has been vacant for some time and is at risk of deterioration.
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Fair Vacant E (New entry)	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Fair Vacant E (New entry) Private	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA Poor	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA Poor Occupied C (C)	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA Poor Occupied C (C)	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA Poor Occupied C (C) Private The 'Lighthouse' block, 295-297 (odd) Pentonville Road NI	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NWI Listed Building Grade II, CA Poor Occupied C (C) Private The 'Lighthouse' block, 295-297 (odd) Pentonville Road NI Listed Building Grade II, CA	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville Road. A tall lead-clad tower at the apex gives it its 'lighthouse' identity. Scheme approved for refurbishment
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NW1 Listed Building Grade II, CA Poor Occupied C (C) Private The 'Lighthouse' block, 295-297 (odd) Pentonville Road NI Listed Building Grade II, CA	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville Road. A tall lead-clad tower at the apex gives it its
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NW1 Listed Building Grade II, CA Poor Occupied C (C) Private The 'Lighthouse' block, 295-297 (odd) Pentonville Road NI Listed Building Grade II, CA Very bad	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville Road. A tall lead-clad tower at the apex gives it its 'lighthouse' identity. Scheme approved for refurbishment
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: CONDITION:	Listed Building Grade II, CA Fair Vacant E (New entry) Private 25 Mornington Crescent NW1 Listed Building Grade II, CA Poor Occupied C (C) Private The 'Lighthouse' block, 295-297 (odd) Pentonville Road NI Listed Building Grade II, CA	The building has been vacant for some time and is at risk of deterioration. Contact: Joanna Ecclestone (LPA) 020 7974 2078 House forming part of a crescent, built circa 1821-23 by I Bryant for the Southampton Estate. In use as a house of multiple occupation and in a poor and deteriorating condition. Contact: Joanna Ecclestone (LPA) 020 7974 2078 Also includes 378-380 (even) Gray's Inn Road. 'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and Pentonville Road. A tall lead-clad tower at the apex gives it its 'lighthouse' identity. Scheme approved for refurbishment

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

	SITE NAME:	Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3	Brick and stone boundary wall along Hampstead Green, 1869. Repairs complete to wall and piers in location of entrances, but other areas on Rosslyn Hill and francting Lieparatead Graph and many to store
	DESIGNATION:	Listed Building Grade II, CA	and fronting Hampstead Green need repairs to stone copings and repointing.
- Shere	CONDITION:	Poor	
A DECEMBER OF	OCCUPANCY:	N/A	
The second second	PRIORITY:	F (F)	
The state of the	OWNER TYPE:	Trust	Contact: Catherine Bond (LPA) 020 7974 2669
	SITE NAME:	Kingsway Tram Subway (northern section), Southampton Row WCI	Tram subway built 1904-6 by the London County Council. Repairs undertaken in 2011, reinstatement of lamp standards and associated works expected to
	DESIGNATION:	Listed Building Grade II, CA	complete in 2012. Site due to be leased to Crossrail for five years from 2012.
	CONDITION:	Good	
	OCCUPANCY:	N/A	
	PRIORITY:	F (F)	
88 2 J	OWNER TYPE:	Local authority	Contact: Joanna Ecclestone (LPA) 020 7974 2078
	SITE NAME:	Baptist Church House, 2-6 (even) Southampton Row WCI	Former Baptist Chapel, offices and shop built 1901-3 to the design of Arthur Keen, architect for the Baptist Union of Great Britain and Ireland. Wrenaissance style
	DESIGNATION:	Listed Building Grade II*, CA	with Flemish-inspired shaped gables and eclectic baroque and Arts and Crafts details. Planning and listed building
	CONDITION:	Fair	consent granted for restoration and conversion to a
	OCCUPANCY:	Part occupied	hotel, but not yet implemented.
	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Toll Gate House,	Late C18 toll house restored 1967, marking the spot
		Spaniards Road, Highgate NW3	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has
	DESIGNATION:	Spaniards Road, Highgate NW3	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard
		Spaniards Road, Highgate NW3	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property
	DESIGNATION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic.
	DESIGNATION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E)	where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C)	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C)	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C)	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and listed building consents granted in 2011. Enforcement</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1 Listed Building Grade II, CA	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1 Listed Building Grade II, CA Very bad	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and listed building consents granted in 2011. Enforcement notice served. Some refurbishment work now being</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1 Listed Building Grade II, CA Very bad Vacant	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and listed building consents granted in 2011. Enforcement notice served. Some refurbishment work now being</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1 Listed Building Grade II, CA Very bad Vacant A (A)	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and listed building consents granted in 2011. Enforcement notice served. Some refurbishment work now being undertaken (May 2012).</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Spaniards Road, Highgate NW3 Listed Building Grade II Good Vacant E (E) Local authority 108 St Pancras Way, Kentish Town NW1 Listed Building Grade II, CA Very bad Vacant B (C) Private 16 Swinton Street WC1 Listed Building Grade II, CA Very bad Vacant A (A)	<ul> <li>where the road entered the Bishop of London's estate. It stands at a traffic bottleneck on a busy road and has suffered impact damage from heavy vehicles. Bollard erected late 2008 to provide protection from traffic. Roof and guttering repair works undertaken and property now in good condition but remains unoccupied.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>End of terrace house dating from the mid 1820s, with early C19 shop front. Consent has been granted for the repair, refurbishment and alteration of the building, but the approved works have not commenced. Building has been squatted intermittently, very poor condition. Temporary roof repairs carried out in early 2012.</li> <li>Contact: Joanna Ecclestone (LPA) 020 7974 2078</li> <li>One of 12 early to mid C19 terrace houses, yellow stock brick with rusticated stucco ground floor. Planning and listed building consents granted in 2011. Enforcement notice served. Some refurbishment work now being</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

32

HEEE	SITE NAME:	65 Swinton Street WCI	Terraced house circa 1775, with late C19 shop front. Unoccupied and deteriorating. Building is in poor condition, interior removed. Planning application
	DESIGNATION:	Listed Building Grade II, CA	for hotel use being negotiated.
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:		Contact: Alan Wito (LPA) 020 7974 6392
5465	SITE NAME:	Eastern coal drops at Kings Cross Goods Yard, York Way NWI	Coal drops built in 1851-2 probably to design of Lewis Cubitt, to carry high-level track for transport of coal into storage bins. Part of a system of distributing coal from the North East and Yorkshire to the London market. Proposals
	DESIGNATION:	Listed Building Grade II, CA	for mixed-use scheme included in the Kings Cross Central
	CONDITION:	Fair	planning application. Currently vacant.
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Alan Wito (LPA) 020 7974 6392
		1 /	
THE HE	SITE NAME:	Church of the HolyTrinity with St Barnabus, Clarence Way NWI	Built 1849-50 in a C14 Gothic style to design of Thomas H Wyatt and David Brandon. Bomb damaged during World War II; now suffering from structural movement. Phase I repairs to roof complete with English Heritage/Heritage Lottery Fund grant aid. Phase II grant offered for stonework
	DESIGNATION:	Listed Place of Worship Grade II	repairs to tower and underpinning, but this was not taken up.
AL ALAN	CONDITION:	Poor	
	PRIORITY:	C (C)	
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 020 7973 3000
	OWNERTHE.		
	SITE NAME:	St George's Cathedral (formerly Christ Church), Albany Street, Camden Town NWI	Early Victorian church with later alterations. Grey stock brick with stucco and stone dressings. Several vertical cracks were identified on the eastern section of the principal façade. Penetrating damp and vegetation growth was prominent in the spire and pediment on central
	DESIGNATION:	Listed Place of Worship Grade II*, CA	projecting bay of principal façade. Plaster work and
	CONDITION:	Poor	stonework to spire also highly worn in places.
	PRIORITY:	A (A)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	OWNER TIPE:	Religious of gallisation	Contact. Thirdpartientage at hisk Adviser 020 7775 5000
	SITE NAME:	Church of St Martin, Vicars Road, Hampstead NW5	1864-6 by EB Lamb for JD Allcroft. Later chapel by EB Lamb Jnr. Eclectic Gothic style with rubbled Kentish ragstone walls and stone dressing, tiled, gabled fishtail pattern roof, missing pinnacles. Interior incorporates elaborate hammerbeam roof and fine internal fittings.
	DESIGNATION:	Listed Place of Worship Grade I	Urgent high level repairs needed including, roof,
	CONDITION:	Poor	stonework and rainwater goods.
	PRIORITY:	A (New entry)	5
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	OWNER TIPE:		Contact. Thirdpar Hentage at this Adviser 020 7775 5000
	SITE NAME:	Christ Apostolic Church (formerly Church of St John), Highgate Road, Kentish Town, Hampstead NW5	Formerly St John's Church. Chapel built on site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. Now occupied by religious group. English Heritage/Heritage Lottery Fund grant-aided high
m 1	DESIGNATION:	Listed Place of Worship Grade II	level repairs to west end roof completed, but further
	CONDITION:	Poor	works required to roofs, high level stonework, boundary
	PRIORITY:	C (C)	wall and gates.
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	GAMENTIFE		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

ADDILL 1	ATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site
	0

33

CITY OF LONDON				
The second	SITE NAME:	St Mary Somerset Tower, Upper Thames Street EC4	Body of chi granted for	church built between 1686-94 by Wren. urch destroyed in 1871. Permission has been renovations and extension in connection rsion to residential use.
	DESIGNATION:	Listed Building Grade I	with conver	sion to residential use.
	CONDITION:	Fair		
THERE A. CO. CO.	OCCUPANCY:	Vacant		
	PRIORITY:	E (E)		
ARRINE TO THE REAL PROPERTY.	OWNER TYPE:	Local authority	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Church of St Bride, Fleet Street, City of London EC4	medieval cr Tallest of al of high leve	rch of I67I-8 on site of earlier church, the rypts of which were excavated after WWII. I Wren spires and unique in form, condition I stone is poor, including rusting iron cramps, ining, and risk of falling stone.
	DESIGNATION:	Listed Place of Worship Grade I	crosion, sta	
	CONDITION:	Poor		
	PRIORITY:	C (New entry)		
A SUN MATHEMAN	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Church of St Giles Without Cripplegate, Fore Street, City of London EC2	extensively Much of th repairs. Join	nurch incorporating earlier tower. Building was refaced in C19 in Kentish ragstone to the tower. e ragstone is now failing due to poor quality t English Heritage/Heritage Lottery Fund grant
	DESIGNATION:	Listed Place of Worship Grade I	is underway	vards stonework repair and development phase
	CONDITION:	Very bad	is ander way	··
	PRIORITY:	D (D)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:		/all: remains of Roman and medieval v c end of All Hallows Church to 38 Ca		;, City of London
DESIGNATION:	Scheduled	Monument (No.1002050)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deteriorat	tion – in need of management	TREND:	Declining
OWNER TYPE:	Local auth	ority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:		/all: section of Roman and Medieval w ting remains of St Alphage's Church, G		
DESIGNATION:	Scheduled	Monument (No.1018886)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deteriorat	tion – in need of management	TREND:	Declining
OWNER TYPE:	Local auth	-	CONTACT:	Principal Heritage at Risk Adviser
				020 7973 3000
SITE NAME:		/all: the west gate of Cripplegate Fort Wall underground car park, adjacent		
DESIGNATION:	Scheduled	Monument (No.1018889)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Rain entry	,	TREND:	
OWNER TYPE:	Local auth		CONTACT:	Principal Heritage at Risk Adviser
				020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

SITE NAME:	Roman wa	all in basement of 90 Gracechurch Str	eet, City of L	ondon
DESIGNATION:	Scheduled	Monument (No.1002035)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deteriorat	tion – in need of management	TREND:	Declining
OWNER TYPE:	Local auth		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
CROYDON				
	SITE NAME:	lce house, Geoffrey Harris House, Coombe Road	House. Dis	use to Coombe House, now Geoffrey Harris used and partly overgrown, some loose and deterioration of pointing.
	DESIGNATION:	Listed Building Grade II		
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
		Health Authority	Contact: Sa	urah Freeman (LPA) 020 8726 6000
	of the the		Contaction	
	SITE NAME:	Former Kennedys Butchers, 18a High Street, South Norwood	butchers, n of being cc	6 for Kennedys, a chain of South London ow closed.The upper floors are in the process inverted to flats and it is hoped that the ground
IS KENNEDY 18	DESIGNATION:	Listed Building Grade II, CA	floor shop	will be bought back into use in the near future. with the local authority are ongoing.
	CONDITION:	Poor	Discussions	with the local authority are ongoing.
	OCCUPANCY:	Vacant		
	PRIORITY:	В (В)		
	OWNER TYPE:		Contact: Sa	urah Freeman (LPA) 020 8726 6000
MAN	SITE NAME:	Lesley Arms public house, 62 Lower Addiscombe Road, Addiscombe	many years has been la	se circa 1900 in Arts and Crafts style. Vacant for A Section 215 notice was served in 2009 and urgely implemented. Upper floors have now bee
	DESIGNATION:	Listed Building Grade II		to flats. Discussions with the local authority he ground floor use, repair and renovation
	CONDITION:	Poor		red, but not come to any definitive conclusions
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Company	Contact: Sa	urah Freeman (LPA) 020 8726 6000
	SITE NAME:	Segas Offices, 32 Park Lane, Croydon	Moderne's the emergi	ny showroom and office, built 1939-41 in tyle. In sound condition but vacant. As part of ng Mid Croydon Masterplan, the local authority
	DESIGNATION:		is currently	seeking potential new uses for the building.
	CONDITION:	Fair		
A summer of the	OCCUPANCY:			
	PRIORITY:	C (C)		
	OWNER TYPE:		Contact: Sa	urah Freeman (LPA) 020 8726 6000
	SITE NAME:	Lion Lodge, including gate piers, 2 Spout Hill,Addington	east entran Robert My	air of single-storey lodges at the former ice to Addington Palace. Built 1773-78 by Ine.Vacant for several years. Building work
	DESIGNATION:	Listed Building Grade II, CA, RPG II	return to n	egun on the works to repair, extend and esidential use. Gates in local authority
AND THE REAL OF	CONDITION:	Poor	ownership.	Planning permission and listed building
	OCCUPANCY:	Vacant	consent giv	en and gates due to be replaced in 2012,
			tollowing th	ne completion of works to the lodge.
	PRIORITY:	D(C)		
	PRIORITY: OWNER TYPE:	D (C) Company	Contact: Sa	urah Freeman (LPA) 020 8726 6000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

35

	CONDITION: OCCUPANCY:	Listed Building Grade II, CA		erworks Yard have recently been completed.
	OCCUPANCY:	Fair	FUSILIVE NEW	v uses for the Pumping Station under consideration
		I QII	πιοΝ: Fair Improved walking and cycling routes planned thro	
	PRIO PUTO (	DCCUPANCY: Vacant in 2013 should improve		uld improve access.
	PRIORITY:	C (C)		
	OWNER TYPE:	Private		
	SITE NAME:	2 Woodside Green, South Norwood	Early C18 two storey weatherboarded house. The house is unoccupied and in very poor condition internally and externally following extensive fire damage in 1991. The condition of the building is being monitored by the local authority and discussions are ongoing, also involving English Heritage. A structural report has recently been submitted for consideration. Contact: Sarah Freeman (LPA) 020 8726 6000	
	DESIGNATION:	Listed Building Grade II		
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
	OWNER TYPE:	Private		
	SITE NAME:	Church of St Andrew, Southbridge Road, Croydon	Church dating from 1857 by Benjamin Ferrey. Unusual bellcote feature, which has recently been dismantled due to its poor structural condition. English Heritage grant offered in 2010 towards general repairs to the church.	
	DESIGNATION:	Listed Place of Worship Grade II		
	CONDITION:	Poor		
	PRIORITY:	D (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
ITE NAME:	Group of	our World War II fighter pens at th	e former airfiel	d of RAF Kenley, Croydon
DESIGNATION:	Scheduled	Monument (No.1021242)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deteriorat	ion – in need of management	TREND:	Declining
OWNER TYPE:	Local autho	prity	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
ITE NAME:	Group of s	seven World War II fighter pens at t	he former airfie	eld of RAF Kenley, Croydon
DESIGNATION:	Scheduled	Monument (No.1021243)	CONDITION:	Generally satisfactory
				but with significant localised problems
RINCIPAL VULNERABILITY:	Deterioration – in need of management		TREND:	Declining
DWNER TYPE:	Local authority		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
ITE NAME:	Surrey Iron Railway embankment, approximately I 30m south west of Lion Green Road, Coulsdon, Croydon			
DESIGNATION:	Scheduled Monument (No.1021441)		CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Scrub/tree growth		TREND:	Declining
DWNER TYPE:	Local authority		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Wellesley	Road North, Croydon		
DESIGNATION:	Conservation Area		CONDITION:	Very bad
	High		TREND:	Improving
	Sarah Freeman (LPA) 020 8726 6000		NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

EALING			
		Stable Diade at Duant Lader Daule	
	SITE NAME:	Stable Block at Brent Lodge Park, Church Road, Hanwell W7	Late C19, yellow stock brick, two storey building. The slate hipped roof had been in a very poor condition causing water ingress and subsequent structural faults.
	DESIGNATION:	Listed Building Grade II, CA	Urgent works to control water ingress and underpinning completed. Plans for future use being prepared for
	CONDITION:	Good	consultation. Statement of significance and condition
	OCCUPANCY:		survey completed 2010.
	PRIORITY:	E (E)	
	OWNER TYPE:	Local authority	Contact: Rosemarie Wakelin (LPA) 020 8825 6600
	SITE NAME:	Crossways, 134 Church Road, Hanwell W7	C18 or earlier house. In a very bad condition, vacant and has been deteriorating for some time. Some site clearance has been carried out. Urgent works carried out in 2011.
	DESIGNATION:	Listed Building Grade II, CA	Now shored up with scaffolding supporting tin roof. Local authority continuing to seek a resolution to the building,
A REALLING	CONDITION:	Very bad	including use of statutory powers.
THE	OCCUPANCY:		5 / T
	PRIORITY:	A (A)	
and Amoral State Constant	OWNER TYPE:		Contact: Rosemarie Wakelin (LPA) 020 8825 6600
	SITE NAME:	Hanwell Community Centre, Cuckoo Avenue, Hanwell W7	Administration block of former London District Schools, 1856. The Council have raised over $\pounds$ 3m for the Community Centre and for local regeneration.
0000000	DESIGNATION:	Listed Building Grade II, CA	Repair and repointing undertaken, building now in good condition. Conservation Management Plan completed and
	CONDITION:	Good	Ealing Council addressing ongoing management issues with
	OCCUPANCY:	Part occupied	efforts being made to negotiate long-term business plan.
	PRIORITY:	E (E)	
	OWNER TYPE:	Local authority	Contact: Rosemarie Wakelin (LPA) 020 8825 6600
	SITE NAME:	Norwood Hall, Norwood Green Road, Southall	Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled
THILL	DESIGNATION:	Listed Building Grade II, CA	garden. Most recently used as a horticultural college and is now used as community centre by the present owner.
KILL IN THE	CONDITION:	Fair	Works are ongoing.
	OCCUPANCY:	Part occupied	
	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Rosemarie Wakelin (LPA) 020 8825 6600
TESUSTEET			
	SITE NAME:	and down side island platform, Station Road, Hanwell W7	Circa 1875-77. Important station canopies and ironwork especially on central platform. The least altered example remaining of the general station rebuilding of the 1870s when the track numbers were quadrupled. The timber
		Listed Building Grade II	platform structures have been repaired, however, the
	CONDITION:	Poor	buildings remain in a poor condition. Drainage issues are causing further deterioration to the fabric.
	OCCUPANCY:		
	PRIORITY:	A (A)	
a far and the	OWNER TYPE:	Company	Contact: Rosemarie Wakelin (LPA) 020 8825 6600
	SITE NAME:	Southall Manor House, The Green, Southall	Substantial timber-framed manor house of 1587, with later extensions and alterations. Recently cleared to make way for urgent and much needed maintenance. Following a
	DESIGNATION:	Listed Building Grade II*	survey a programme of repairs and refurbishment has been drawn up and is now underway. Ongoing negotiations
	CONDITION:	Fair	regarding long-term management.
	OCCUPANCY:	Part occupied	
	PRIORITY:	E (E)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

at is the	SITE NAME:	Twyford Abbey, Twyford Abbey Road NW10	Last used a substantial	s a nursing home. E enabling developme	307-9 by William Atkinson. Discussions are ongoing for ent in the grounds to pay
	DESIGNATION:	Listed Building Grade II	for the rep	air and maintenance	e of the historic building taken alongside marketing
	CONDITION:	Very bad	of the site.	uigent work under	laken alongside mai keling
ALL DESCRIPTION	OCCUPANCY:	Vacant			
	PRIORITY:	A (C)			
A second states of the	OWNER TYPE:	Company	Contact: Ro	osemarie Wakelin (l	_PA) 020 8825 6600
	SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall	extended   restored fo	854-57. Part of the r continuing healthd	by William Alderson; original complex has been care use. Site now partially
	DESIGNATION:	Listed Building Grade II	still vacant	, but chapel, ballroo with no agreed use	m and remaining wards are , and a rolling programme
	CONDITION:	Fair	of repairs a	igreed. Further appl	lications pending for
	OCCUPANCY:	Part occupied	residential/	new build.	
Alter N	PRIORITY:	C (C)			
	OWNER TYPE:	Health Authority	Contact: Ro	osemarie Wakelin (l	_PA) 020 8825 6600
AL.	SITE NAME:	Church of St Peter, Mount Park Road W5	dating from has issues v Heritage/He	1889 to 1892. Gene vith high level stonev eritage Lottery Fund	D Sedding and H Wilson erally well maintained but work decay. Joint English I grant offered towards high velopment phase is underway
	DESIGNATION:	Listed Place of Worship Grade II*, C	A	vork repairs and dev	velopi neni priase is unuer way
	CONDITION:	Poor			
	PRIORITY:	B (B)			
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at R	isk Adviser 020 7973 3000
P	SITE NAME:	Church of St Mary, Brentmead Gardens, Twyford, Park Royal, Ealing NW10	built in the on the faça southern fa	grounds of Twyford de was noted and so çade to repair windo	chemaille-Day extension Abbey. Some salt damage caffolding was erected on the ows. Access to the rear of the
	DESIGNATION:	Listed Place of Worship Grade II			ruction fencing. At the time c restoration. Services are
	CONDITION:	Fair		being held in a neig	
	PRIORITY:	F (E)			
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at R	isk Adviser 020 7973 3000
SITE NAME:	Hanwell fl	ight of locks and brick boundary wa	II of St Bernarc	l's Hospital, Ealing	
DESIGNATION:	Scheduled	Monument (No.1001963)	CONDITION:	Generally satisfac but with significa	ctory nt localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree	e growth	TREND:	Improving	
OWNER TYPE:	Utility		CONTACT:	Principal Heritag 020 7973 3000	e at Risk Adviser
SITE NAME:	Moated si	te at Down Barns Farm, Ealing			
DESIGNATION:	Scheduled	Monument (No.1005552)	CONDITION:	Generally satisfac but with significa	ctory nt localised problems
PRINCIPAL VULNERABILITY:	Drainage/o	dewatering	TREND:	Stable	
OWNER TYPE:	Private		CONTACT:	Principal Heritag	e at Risk Adviser
				020 7973 3000	
SITE NAME:	Moated si	te at Sudbury golf course, Wembley,	Ealing		
DESIGNATION:	Scheduled	Monument (No.1001971)	CONDITION:	Generally satisfac	,
	Design /	dowataring		•	nt localised problems
PRINCIPAL VULNERABILITY:	Drainage/o Private	dewatering	TREND:	Unknown Principal Heritag	e at Rick Advisor
OWNER TYPE:	Trivale		CONTACT:	Principal Heritag 020 7973 3000	C at INSK AUVISEI
PRIORITY (FOR BUILDINGS)     A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.     Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.     Slow decay; no solution agreed.	E Under rep repair, but under thr obvious n	y; solution agreed t implemented. bair or in fair to good no user identified; or eat of vacancy with no wuser (applicable only ts capable of beneficial use). F Repair scheme in pro and (where applicable end use or user iden functionally redundar with new use agreed yet implemented.	e) 2011 tified; are g at buildings	E: priority categories ven in brackets.	ABBREVIATIONS           CA         Conservation Area           LB         Listed Building           LPA         Local Planning Authority           NP         National Park           RPG         Registered Park and Gard           SM         Scheduled Monument           UA         Unitary Authority           WHS         World Heritage Site

## HERITAGE AT RISK 2012 / LONDON / EALING

SITE NAME:	Windmill Bridge, Ealing		
DESIGNATION:	Scheduled Monument (No.1002020)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser
			020 7973 3000
SITE NAME:	Acton Town Centre, Acton		
	Conservation Area		De ere
DESIGNATION:	Low	CONDITION:	Poor
VULNERABILITY: CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	TREND: NEW ENTRY?:	Deteriorating No
CONTACT:		INEVV EINTRE:	INU
SITE NAME:	Cuckoo Estate, Hanwell		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Ealing Town Centre, Ealing		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Hanwell Clock Tower, Hanwell		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Hanwell Village Green, Hanwell		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Haven Green, Ealing		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
SITE NAME:	Northolt Village Green, Northolt		
DESIGNATION:	Conservation Area	CONDITION:	Poor
/ULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No
CONTACT.			
	Norwood Green, Southall		
SITE NAME: DESIGNATION:	Norwood Green, Southall Conservation Area	CONDITION:	Very bad
SITE NAME:		CONDITION: TREND:	Very bad Deteriorating significantly

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

## HERITAGE AT RISK 2012 / LONDON / EALING / ENFIELD

SITE NAME:	St Mark's Church and Canal, Hanwell		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600	NEW ENTRY?:	No

ENFIELD			
- <b>X</b>	SITE NAME:	Statue of Hercules and Autaeus, Bramley Road, Trent Park	Statue of circa 1700 by Nost after da Bologna, brought from Stowe Park, Buckinghamshire in the 1920s by Sir Philip Sassoon. Being repaired off site (April 2012).
	DESIGNATION:	Listed Building Grade II, CA, RPG II	
and a second	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	E (B)	
	OWNER TYPE:	Educational Body	Contact: Christine White (LPA) 020 8379 3852
	SITE NAME:	Statue of Samson defeating a Philistine, Bramley Road, Trent Park	Statue of circa 1700 by Nost after da Bologna, brought from Stowe Park, Bucks, in the 1920s by Sir Philip Sassoon. Off site and under repair (April 2012).
	DESIGNATION:	Listed Building Grade II, CA, RPG II	
	CONDITION:	Very bad	
the set of states	OCCUPANCY:		
- A REAL PROPERTY AND A RE	PRIORITY:	E (B)	
	OWNER TYPE:	Educational Body	Contact: Christine White (LPA) 020 8379 3852
	SITE NAME:	Trent Park House terrace, Cockfosters Road, Trent Park	Brick and stone terrace reconstructed in the 1920s. The terrace is in poor condition and needs repair and repaving.
	DESIGNATION:	Listed Building Grade II, CA, RPG II	
	CONDITION:	Very bad	
7712	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Educational Body	Contact: Christine White (LPA) 020 8379 3852
	SITE NAME:	Trent Park	Late CI8 landscape park further developed early C20
		Registered Park and Garden Grade II,	by Sir Philip Sassoon. The central mansion house, gardens
Sere Shall	DESIGNATION.	also CA, 19 LBs, 1 SM	and pleasure grounds are occupied by Middlesex University and the surrounding parkland is managed by Enfield as a
	CONDITION:	Generally satisfactory	country park. The mansion house's terrace and a number
		but with significant localised problems	of statues are at risk. Two garden sculptures have been restored and discussions are ongoing to place replicas
	VULNERABILITY		in National Trust Gardens.
- MERCE	TREND:	Declining	
	OWNER TYPE:	Mixed, multiple owners	Contact: Principal Heritage at Risk Adviser 020 7973 3000
XHATCHNAKI		Broomfield House,	CI6 house with late CI8 additions, situated in public
	SITE NAME:	Broomfield Park, Broomfield Lane	park. Severely fire damaged although significant parts of the interior are in safe storage. Recent proposals to convert to mixed use including flats and community
	DESIGNATION:	Listed Building Grade II*, RPG II	spaces have fallen through due to cuts in housing grants.
1 Pl - Pl - Pl	CONDITION:	Very bad	Options being reappraised.
1 - Longerord	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

### HERITAGE AT RISK 2012 / LONDON / ENFIELD

DESIGNATION:       Listed Building Grade II*, RPG II         CONDITION:       Poor         OCCURANCE:       Vacant         PRORTY:       C (C)         CONDITION:       Poor         OCCURANCE:       Vacant         PRORTY:       C (C)         Conditional authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Conditional authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Conditional authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Conditional authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Conditional authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Conditional authority       Bife Name: Conditional authority         Image: Conditional authority       Contact: Christine White (LPA) 020 8379 3852         Image: Conditional authority       Single storey building, central arched doorway to the strate ads ash window to either side, externally above doorwa is a statuet of a female pupil. The building is used by community groups. Condition of the building is used by community groups. Condition of the building is used by community groups. Condition of the building is used by community groups. Condition of the building is used by community groups. Condition of the building in 2012.         Import:       C (C)         Import:       C (C)
CONDITION:       Poor         OCCUPANCY:       Vacant         PRORTY:       C (C)         OWNERTYPE:       Local authority         Contact:       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact:         Contact:       Contact:         Contact:       Contact:         Principal Heritage: Control       Contact:         Contact:       Contact:
PRIORITY:       C (C) OWNER TYPE       Cocla authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contract Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Stre NAME:       Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact:       Contact: Christine White (LPA) 020 8379 3852       Contact: Christine White (LPA) 020 8379 3852         Image: Contact:       Single storey building, central arched doorway to the stread stah window to either side, externally above doorway Control Rine:       Single storey building, central arched doorway to the stread stah window to either side, externally above doorway Control Rine:         Image: Control Rine:       Former Edmonton Girl's Charity School, Church Street, Edmonton       Single storey building, central arched doorway to the str and sash window to either side, externally above doorway Control Rine:         Image: Control Rine:       Fair       Contact: Christine White (LPA) 020 8379 3852         Image: Contact:       Contact: Christine White (LPA) 020 8379 3852
OWNERTIFE       Local authority       Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Principal Heritage at Risk Adviser 020 7973 30         Image: Contact: Contact: Contact: Contact: Contact: Contact: Contact: Christine White (LPA) 020 8379 3852       Image: Contact: Christine White (LPA) 020 8379 3852         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Christine White (LPA) 020 8379 3852         Image: Contact: Principal Heritage at Risk Adviser 020 7973 30       Image: Contact: Christine White (LPA) 020 8379 3852         Image: Contact: Christine White (LPA) 020 8379 3852       Image: Contact: Christine White (LPA) 020 8379 3852         Image: Contact: Christine White (LPA) 020 8379 3852       Image: Contact: Christine White (LPA) 020 8379 3852
SITE NAME       Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road       I870-1 Gothic Revival cemetery chapel. In need of an appropriate use. In poor condition.         Designation       Listed Building Grade II CONDITION:       Poor       Occureance: Vacant PRORITY:       C (C)         OWNER TYPE       Local authority       Contact: Christine White (LPA) 020 8379 3852         Single storey building, central arched doorway to the str and sash window to either side, externally above doorw is a statuette of a female pupil. The building is used by Community groups. Condition of the building is used by Community groups. Condition of the building is slowly detriorating and the current use is unable to provide adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         WIRE TYPE       C (C) OWNER TYPE       Contact: Christine White (LPA) 020 8379 3852
Lavender Hill Cemetery, Cedar Road       of an appropriate use. In poor condition.         Designation:       Listed Building Grade II         CONDITION:       Poor         OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNER TYPE:       Local authority         Stre NAME:       Former Edmonton Girl's Charity School, Church Street, Edmonton         Designation:       Listed Building Grade II, CA         Condition:       Fair         OCCUPANCY:       Part occupied         PRIORITY:       C (C)         OWNER TYPE:       Condition Girl's Charity School, Church Street, Edmonton         Designation:       Listed Building Grade II, CA         CONDITION:       Fair         OCCUPANCY:       Part occupied         PRIORITY:       C (C)         OWNER TYPE:       Charity
CONDITION:       Poor         OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE:       Local authority         STEE NAME:       Former Edmonton Girl's Charity School, Church Street, Edmonton       Single storey building, central arched doorway to the str and sash window to either side, externally above doorwa is a statuette of a female pupil. The building is used by condition of the building is slowly deteriorating and the current use is unable to provide adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         PRIORITY:       C (C)         OWNERTYPE:       Charity
Image: Streen Priority in the priority of the the p
Image: PRIORITY:       C (C)         OWNERTYPE       Local authority         Contact: Christine White (LPA) 020 8379 3852         Image: PRIORITY:       C (C)         OWNERTYPE       Local authority         Ste NAME:       Former Edmonton Girl's Charity School, Church Street, Edmonton         Designation:       Listed Building Grade II, CA         CONDITION:       Fair         OCCUPANCY:       Part occupied         PRIORITY:       C (C)         OWNERTYPE       Charity
OWNERTYPE       Local authority       Contact: Christine White (LPA) 020 8379 3852         Image: Step Name:       Former Edmonton Girl's Charity School, Church Street, Edmonton       Single storey building, central arched doorway to the str and sash window to either side, externally above doorw is a statuette of a female pupil. The building is used by community groups. Condition of the building is slowly deteriorating and the current use is unable to provide adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         Image: Market Street
SITE NAME:       Former Edmonton Girl's Charity School, Church Street, Edmonton       Single storey building, central arched doorway to the str and sash window to either side, externally above doorw is a statuette of a female pupil. The building is used by community groups. Condition of the building is slowly deteriorating and the current use is unable to provide adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         PRIORITY:       C (C) OWNERTYPE:       Charity
Girl's Charity School, Church Street, Edmonton DESIGNATION: Listed Building Grade II, CA CONDITION: Fair OCCUPANCY: Part occupied PRIORITY: C (C) OWNERTYPE: Charity Charity Charity Contact: Christine White (LPA) 020 8379 3852
Design Anton:       Easted building Grade in, CA       deteriorating and the current use is unable to provide adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         PRIORITY:       C (C)         OWNERTYPE:       Charity
CONDITION:       Fair       adequate income for its upkeep. English Heritage are to grant aid a feasibility study for the building in 2012.         PRIORITY:       C (C)         OWNERTYPE:       Charity    Conduct: Christine White (LPA) 020 8379 3852
PRIORITY: C (C) OWNERTYPE: Charity Contact: Christine White (LPA) 020 8379 3852
OWNER TYPE: Charity Contact: Christine White (LPA) 020 8379 3852
SITE NAME: 24 Church Street, Edmonton Former teacher's accommodation to the Charity School adjoining, C18 cottage of red brick with renewed pantile roof. Two storeys, two windows, those on the first floor modern casements; ground floor windows are sash with
designation: Listed building Grade II, CA glazing bars in box frames. Doorways with architrave, cu
CONDITION: Poor brackets, frieze and dentilled cornice hood. Building is
occupancy: Occupied slowly deteriorating with worthwhile but financially unviable usage.
PRIORITY: C (C)
OWNERTYPE Charity Contact: Christine White (LPA) 020 8379 3852
SITE NAME: Truro House and stable block, 176 Green Lanes Early to mid C19 detached villa with C19 stable block. Enfield have written to owners with a suggested schedu for repair works, awaiting timetable. A residential scheme
DESIGNATION: Listed Building Grade II was agreed in 2009 and the legal agreement remains to be concluded.
De concluded.
condition: Poor
CONDITION: POOR OCCUPANCY: Vacant
OCCUPANCY: Vacant
OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE       Company         Contact:       Christine White (LPA) 020 8379 3852         SITE NAME:       Enfield Electricity Works, 20 Ladysmith Road, Enfield         Enfield       Enfield         Enfield       Enfield         OWNERTYPE:       Company
OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE:       Company         SITE NAME:       Enfield Electricity Works, 20 Ladysmith Road,    Former Enfield Electricity Works 1906, architect unknown. Partially occupied. Future operational
OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNER TYPE:       Company         Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       SITE NAME:         Enfield       Electricity Works, 20 Ladysmith Road, Enfield         Image: Contact:       Contact:         Image: Contact:       Contact: <t< td=""></t<>
OCCLUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE       Company         Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       Contact:         Image: Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       Contact:         Image: Conta
OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNER TYPE:       Company         Contact:       Christine White (LPA) 020 8379 3852         Image: Contact:       SITE NAME:         Enfield       Electricity Works, 20 Ladysmith Road, Enfield         Image: Contact:       Contact:         Image: Contact:       Contact: <t< td=""></t<>

PR	IORITY (FOR BUILDINGS)
А	Immediate risk of further rapid

- А
- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

	SITE NAME:	Barn at Whitewebbs Farm, Whitewebbs Road EN2	The barn ha Enfield to ur	er-framed barn probably dating from later CI s partly collapsed, the owner has agreed with idertake urgent repair works to protect it fror pse. These are scheduled for early 2012.
	DESIGNATION:	Listed Building Grade II	iui titei colla	pse. These are scheduled for early 2012.
The second second	CONDITION:	Very bad		
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
	OWNER TYPE:	Company	Contact: Chi	ristine White (LPA) 020 8379 3852
5 . St.	SITE NAME:	Grovelands Park	Late CI8 lar	ndscape park and lake by Humphry Repton,
	DESIGNATION:	Registered Park and Garden Grade II*, also 4 LBs	in early C20	the mid C19, and laid out as a public park by Thomas Mawson. The mansion is now a ital. The management is fragmented due to
	CONDITION:	Generally satisfactory but with significant localised problems	the separate produced a	e ownerships. Enfield Borough Council has historic environment assessment which sets
Stalos Margarell	VULNERABILITY		out priorities	s for repair and restoration of the park.
		Declining		
A CONTRACTOR AND A	TREND:	Mixed, multiple owners	Contact: Prir	acipal Horitago at Rick Advisor 020 7973 3000
Grovelands Park, Southger	OWNER TYPE:	Trixed, multiple owners	Contact. Fhi	ncipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	All Saints Church, Church Street N9	and 1889 by V Lamb and Wi Victorian wall	Nurch. Restored in 1855 and 1871 by Ewan Christia W Gilbee Scott. There are monuments to Charles illiam Cowper. The east end has a spectacular painting of angels and saints. Following a very
	DESIGNATION:	Listed Place of Worship Grade II*, CA		e tower stonework and roofs are now in a poor glish Heritage/Heritage Lottery Fund have awarded
	CONDITION:	Very bad	a grant for to	wer repairs and development phase is underway.
	PRIORITY:	B (B)	Photo copyrig	ght: Colin Kerr (Architect).
	OWNER TYPE:	Religious organisation	Contact: Princ	cipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Church St	reet, Edmonton		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	No significant change
CONTACT:	Christine V	White (LPA) 020 8379 3852	NEW ENTRY?:	No
SITE NAME:	Fore Stree	et, Edmonton		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	Improving
CONTACT:	Christine V	White (LPA) 020 8379 3852	NEW ENTRY?:	No
GREENWICH	Christine V	White (LPA) 020 8379 3852	NEW ENTRY!:	
	Christine V	White (LPA) 020 8379 3852 Royal Military Academy, Academy Road, Woolwich SE18	Military colle Site sold and	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are
		Royal Military Academy, Academy Road, Woolwich SE18	Military colle Site sold and conversion. \	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are
	SITE NAME:	Royal Military Academy, Academy Road, Woolwich SE18	Military colle Site sold and conversion. \	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are
	SITE NAME: DESIGNATION:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA	Military colle Site sold and conversion. \	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are
	SITE NAME: DESIGNATION: CONDITION:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair	Military colle Site sold and conversion. \	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F)	Military colle Site sold and conversion. \ continuing in	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are n phases.
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F)	Military colle Site sold and conversion. V continuing in Contact: Prin Large conset by a figure o previously su	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are n phases. hcipal Heritage at Risk Adviser 020 7973 3000 rvatory with domed glass roofs, surmounted of Mercury. Built in 1889 in a classical style uffering from long term neglect and major
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F) Private Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Military colle Site sold and conversion. continuing in Contact: Prin Large conset by a figure o previously su deterioration	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are h phases. hcipal Heritage at Risk Adviser 020 7973 3000 rvatory with domed glass roofs, surmounted of Mercury. Built in 1889 in a classical style uffering from long term neglect and major n of the fabric. Access to some parts was
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F) Private Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Military colle Site sold and conversion. \ continuing in Contact: Prin Large conset by a figure o previously su deterioration restricted or	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are h phases. hcipal Heritage at Risk Adviser 020 7973 3000 rvatory with domed glass roofs, surmounted of Mercury. Built in 1889 in a classical style uffering from long term neglect and major n of the fabric. Access to some parts was h health and safety grounds. Listed building
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F) Private Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9 Listed Building Grade II Fair	Military colle Site sold and conversion. V continuing in Contact: Prin Large conset by a figure o previously su deterioratior restricted or consent app repairs and n	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are n phases. heripal Heritage at Risk Adviser 020 7973 3000 rvatory with domed glass roofs, surmounted of Mercury. Built in 1889 in a classical style uffering from long term neglect and major n of the fabric. Access to some parts was n health and safety grounds. Listed building roved in 2009 for comprehensive internal renovations. Restoration of the East House
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Royal Military Academy, Academy Road, Woolwich SE18 Listed Building Grade II*, CA Fair Vacant F (F) Private Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9 Listed Building Grade II Fair	Military colle Site sold and conversion. \ continuing in Contact: Prin Large conset by a figure o previously su deterioration restricted or consent app	No ege built 1805 to the designs of James Wyatt. d planning permission granted for residential Works on site began Spring 2008, and are n phases. heripal Heritage at Risk Adviser 020 7973 3000 rvatory with domed glass roofs, surmounted of Mercury. Built in 1889 in a classical style uffering from long term neglect and major n of the fabric. Access to some parts was n health and safety grounds. Listed building roved in 2009 for comprehensive internal renovations. Restoration of the East House

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

	SITE NAME:	Lock and Swing Bridge, Broadwater Estate SE28	The canal was built 1812-14 to bring supplies into the Arsenal.The swing bridge was built circa 1876 to carry railway tracks across the canal. Some work was done to
	DESIGNATION:	Listed Building Grade II	the bridge in the early 1980s but since then the lock and
	CONDITION:	Poor	bridge have both lain derelict.
A A A	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
N. Comment	OWNER TYPE:	Company	Contact: Rebecca Duncan (LPA) 020 8921 5355
	SITE NAME:	Garden House to north west of Charlton House, Charlton Road, Charlton SE7	Small red brick garden house with undercroft. High pyramidal swept roof. Mid to late C17 and attributed to Inigo Jones. Previously used as a public lavatory, now
	DESIGNATION:	Listed Building Grade I, CA	vacant. In need of repair, maintenance and beneficial use.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Enderby House, 100 Christchurch Way, Greenwich SE10	Early-mid C19 wharf-side building of Samuel Enderby, largest whalers and sealers in Britain and pioneers of Atlantic exploration. Unusual octagonal room giving onto
	DESIGNATION:	Listed Building Grade II	projecting bay, allowing views of approaching vessels. Scheme agreed in principle, subject to a Section 106
	CONDITION:	Poor	agreement, but currently unresolved.
	OCCUPANCY:	Vacant	
	PRIORITY:	D (B)	
	OWNER TYPE:	Company	Contact: Rebecca Duncan (LPA) 020 8921 5355
<b>AND</b>	SITE NAME:	Old brick wall between gardens in front of Nos. 34 and 36, Court Yard, Eltham SE9	Brick wall with sloped coping of C16 appearance. In poor structural condition and suffering from vandalism.
		in front of Nos. 34 and 36,	Brick wall with sloped coping of CI6 appearance. In poor structural condition and suffering from vandalism.
		in front of Nos. 34 and 36, Court Yard, Eltham SE9	Brick wall with sloped coping of CI6 appearance. In poor structural condition and suffering from vandalism.
	DESIGNATION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A	Brick wall with sloped coping of C16 appearance. In poor structural condition and suffering from vandalism.
	DESIGNATION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C)	In poor structural condition and suffering from vandalism.
	DESIGNATION: CONDITION: OCCUPANCY:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C)	Brick wall with sloped coping of C16 appearance. In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C)	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C)	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C)	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C)	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C) Private Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and converted to an office in 2003. A scheme for reuse and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private <b>95A Eltham High Street,</b> Eltham SE9 Listed Building Grade II Fair Part occupied C (C) Private Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C) Private Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9 Listed Building Grade II* Fair	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and converted to an office in 2003. A scheme for reuse and redevelopment to west of the Orangery approved in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private 95A Eltham High Street, Eltham SE9 Listed Building Grade II Fair Part occupied C (C) Private Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9 Listed Building Grade II* Fair	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and converted to an office in 2003. A scheme for reuse and redevelopment to west of the Orangery approved in
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	in front of Nos. 34 and 36, Court Yard, Eltham SE9 Listed Building Grade II*, CA Poor N/A C (C) Private <b>95A Eltham High Street,</b> Eltham SE9 Listed Building Grade II Fair Part occupied C (C) Private Orangery to former Eltham House, Eltham High Street (north side), Eltham SE9 Listed Building Grade II* Fair Vacant	In poor structural condition and suffering from vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000 C17 or earlier stable building with three diagonal chimney shafts. Although it has been made weathertight, it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, most appropriate future uses would be commercial/office use. Currently in residential use and subject to enforcement action. Contact: Rebecca Duncan (LPA) 020 8921 5355 Orangery, 1717-25, to Eltham House (demolished in the 1920s). A fine example of a Baroque garden building. A long running building at risk case. It was repaired and converted to an office in 2003. A scheme for reuse and redevelopment to west of the Orangery approved in



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Forecourt railings and gates to Red Barracks, and Gate Lodge, Frances Street, Woolwich SE18	Railings and entrance gateway to the former Red Barracks (1858-60 but now demolished). The railings, piers and gate piers generally in good condition. Repairs to Watch Room
	DESIGNATION:	Listed Building Grade II	in hand. Now derelict gate lodge to rear of south end of boundary wall probably in need of major repair behind
	CONDITION:	Poor	the retained gable to the street.
	OCCUPANCY:	Vacant	
and the second second	PRIORITY:	E(C)	
	OWNER TYPE:	Local authority	Contact: Rebecca Duncan (LPA) 020 8921 5355
	SITE NAME:	91 Genesta Road, Woolwich SE18	Berthold Lubetkin 1933-4. Reinforced concrete construction with flat roof. Original Crittall metal windows. The only completed terrace in England built in the modern idiom during the 1920s Lack of maintenance and packet have
States - The states	DESIGNATION:	Listed Building Grade II*	during the 1930s. Lack of maintenance and neglect have resulted in severe external deterioration with concrete
	CONDITION:	Very bad	cracking and spalling. Internally damp and water penetration
	OCCUPANCY:	Vacant	is causing extensive damage to original features.
Stan Quanta and	PRIORITY:	A (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Garrison Church of St George, Grand Depot Road, Royal Artillery Barracks, Woolwich SE18	Former Italianate church of 1863, a roofless ruin after bomb damage in 1944. Temporary scaffolding now in place to protect mosaics, including one commemorating members of the Royal Artillery awarded the Victoria Cross. Scheme to stabilise and protect ruined structure with
	DESIGNATION:	Listed Building Grade II	grant form Heritage Lottery Fund and English Heritage
	CONDITION:	Poor	not yet implemented.
	OCCUPANCY:	N/A	
a dia dia	PRIORITY:	D (D)	
	OWNER TYPE:	Trust	Contact: Rebecca Duncan (LPA) 020 8921 5355
1 × 1	SITE NAME:	The Rotunda, Greenhill, Woolwich Common, Woolwich SE18	24-side polygon, single storey building designed by John Nash. Concave conoid lead-covered roof; first erected in grounds of Carlton House in 1814 for (premature) celebration of Allied
2.FIL	DESIGNATION:	Listed Building Grade II*	victory in Napoleonic wars. Housed the reserve collection of 'Firepower' museum but now vacant. Lead-sheet roof covering
-	CONDITION:	Fair	is failing. Currently in use as the garrison boxing centre.
	OCCUPANCY:	Vacant	
and the state	PRIORITY:	С (С)	
	OWNER TYPE:	Government	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	I Greenwich South Street, Woolwich SE10	End terrace to an early C18 group, three storeys and attic with mansard roof. Upper floors unoccupied for a number of years and building fabric, especially
	DESIGNATION:	Listed Building Grade II, CA	windows, deteriorating.
	CONDITION:	Poor	
142	OCCUPANCY:	Part occupied	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	-	Contact: Rebecca Duncan (LPA) 020 8921 5355
	SITE NAME:	Riverside Guard Rooms, Royal Arsenal, Plumstead Road, Woolwich SE18	Royal Arsenal's guardrooms, 1814. The Royal Arsenal site is owned by Berkeley Homes who are progressing repairs. Planning permission has been given for Arsenal master plan Shall repairs have been carried out.
	DESIGNATION:	Listed Building Grade II, CA	plan. Shell repairs have been carried out.
	CONDITION:	Fair	
	CONDITION:		
	OCCUPANCY:	Vacant	
		Vacant E (E)	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / LONDON / GREENWICH

	SITE NAME:	Royal Laboratory to Royal Arsenal, Plumstead Road, Woolwich SE18	Royal Arsenal's laboratory, two buildings originally built in 1696, reconstructed 1802 after fire. Both buildings secured and within the area covered by the Arsenal master plan.
THE REAL ASIA	DESIGNATION:	Listed Building Grade II, CA	Scheme for restoration and conversion to residential use approved but not yet implemented.
	CONDITION:	Very bad	
	OCCUPANCY: PRIORITY:	Vacant D (C)	
		Company	Contact: Rebecca Duncan (LPA) 020 8921 5355
- delaber	SITE NAME:	70-84 River Way SE10	Row of eight cottages, according to date-stone built in 1801 and known as Ceylon Place. Constructed for workers at adjacent tidal mill and chemical works and a rare survival of late Georgian artisans' housing. Partially vacant and, due
	DESIGNATION:	Listed Building Grade II	to isolated location, vulnerable to vandalism.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
ALCONT B	OWNER TYPE:	Quango	Contact: Rebecca Duncan (LPA) 020 8921 5355
	SITE NAME:	24 Royal Hill SE10	Early C18 small urban house of central chimneystack plan, smallest known example of the 1703 Moxon Plan. Vacant for some years and in poor condition. Scheme for
BL PACK BIL	DESIGNATION:	Listed Building Grade II, CA	restoration and conversion recently agreed but not yet implemented.
DUN	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
annie ante dange stall anna sussis de elle	OWNER TYPE:	Private	Contact: Rebecca Duncan (LPA) 020 8921 5355
	SITE NAME:	Officers Quarters, Royal Arsenal (building 11), Seymour Street, Woolwich SE18	Officers block for Royal Military Academy 1717-20. The Royal Arsenal site is owned by the London Development Agency which is progressing repairs.
			A master plan for the whole site has been approved
	DESIGNATION:	Listed Building Grade II	A master plan for the whole site has been approved by the Local Authority. Proposals for shell repairs have
	DESIGNATION: CONDITION:		by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold
		Listed Building Grade II Poor Vacant	by the Local Authority. Proposals for shell repairs have
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II Poor Vacant C (C)	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.
	CONDITION: OCCUPANCY:	Listed Building Grade II Poor Vacant C (C)	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle,	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: STE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D)	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: STE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant	by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior. Contact: Rebecca Duncan (LPA) 020 8921 5355 Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English
	CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D) Local authority Coronet Cinema, Well Hall Road, Eltham SE9	<ul> <li>by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.</li> <li>Contact: Rebecca Duncan (LPA) 020 8921 5355</li> <li>Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.</li> <li>Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D) Local authority Coronet Cinema, Well Hall Road,	<ul> <li>by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.</li> <li>Contact: Rebecca Duncan (LPA) 020 8921 5355</li> <li>Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and auditorium. Closed in 1999 and subject to vandalism. Now in new ownership. Planning permission and</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D) Local authority Coronet Cinema, Well Hall Road, Eltham SE9	<ul> <li>by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.</li> <li>Contact: Rebecca Duncan (LPA) 020 8921 5355</li> <li>Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and auditorium. Closed in 1999 and subject to vandalism. Now in new ownership. Planning permission and listed building consent granted in 2008; redevelopment</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D) Local authority Coronet Cinema, Well Hall Road, Eltham SE9 Listed Building Grade II Poor Vacant	<ul> <li>by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.</li> <li>Contact: Rebecca Duncan (LPA) 020 8921 5355</li> <li>Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and auditorium. Closed in 1999 and subject to vandalism. Now in new ownership. Planning permission and</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: CONDITION: CONDITION: OCCUPANCY: PRIORITY: CONDITION: CONDITION: CONDITION: CONDITION:	Listed Building Grade II Poor Vacant C (C) Quango Severndroog Castle, Shooters Hill SE18 Listed Building Grade II* Fair Vacant D (D) Local authority Coronet Cinema, Well Hall Road, Eltham SE9 Listed Building Grade II Poor	<ul> <li>by the Local Authority. Proposals for shell repairs have been submitted. Currently protected by sheeted scaffold and temporary roof, but much timber decay in interior.</li> <li>Contact: Rebecca Duncan (LPA) 020 8921 5355</li> <li>Gothick tower built in 1784 to commemorate the conquest of the Malabar Coast by Sir William James in 1755. Stands in woodlands and suffers from vandalism. The Severndroog Castle Building Preservation Trust have secured Heritage Lottery funding for repairs and alterations, with English Heritage grant. Works are expected to commence in 2013.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Former Odeon cinema built 1936 to the design of Andrew Mather and Horace Ward. Faience cladding to front. Good internal features in foyers, stairs and auditorium. Closed in 1999 and subject to vandalism. Now in new ownership. Planning permission and listed building consent granted in 2008; redevelopment</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

## HERITAGE AT RISK 2012 / LONDON / GREENWICH / HACKNEY

HERITAGE AT RISK 2012 / LONI				
	SITE NAME:	Government House, Woolwich New Road, Woolwich SE18	isolated site attacks of v	a 1800, set in fairly extensive grounds in 2. Severe internal damage caused by periodic andalism. Built originally as private dwelling, it y the military from 1841-1937. Urgent works
ATT BURNESS	DESIGNATION:	Listed Building Grade II		early 2010 to enhance security as part of a
	CONDITION:	Poor	revised sch	eme for restoration, conversion and enabling
	OCCUPANCY:	Vacant	developme	nt agreed in 2011 but not implemented.
	PRIORITY:	D (D)	Site current	lly for sale.
	OWNER TYPE:	Private	Contact: Re	ebecca Duncan (LPA) 020 8921 5355
0	SITE NAME:	Church of St Mary Magdalene, Church Hill, Woolwich SE18	stone dress been a rece leaks from investigatior	ower built 1732-8 in stock brick with Portland ing. East end added by Scott in 1894. There has ent serious outbreak of dry rot following roof defects in valley gutters and flashing. Emergency is underway to determine scope of works to
		Listed Place of Worship Grade II*	prevent fur	ther deterioration. An application for grant aid d. Photo copyright: Revd Jesse van der Valk.
	CONDITION:	Poor	is anticipate	ed. Thoto copyright. Neve jesse van der vaik.
	PRIORITY:	A (A)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Linear Tra	ining Fortification, Royal Military Repo	ository, Green	wich
DESIGNATION:	Scheduled	Monument (No.1021456)	CONDITION:	Generally satisfactory
				but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Declining
OWNER TYPE:		ent or Agency	CONTACT:	Principal Heritage at Risk Adviser
Owner Hite	Coverning		contract.	020 7973 3000
HACKNEY				
E 1	SITE NAME:	Cleeve Workshops,	Row of wo	rkshops, built 1895-8 to the design of Reginald
an taken		Calvert Avenue E2	the Bounda	or of the London County Council as part of ary Estate. Some are in use but all require repair: s have had pre-application discussions with the
	DESIGNATION		the Bounda	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the
	DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor	the Bounda The owner	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the
	CONDITION:	Listed Building Grade II, CA Poor	the Bounda The owner	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the
	CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Part occupied	the Bounda The owner	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the
	CONDITION:	Listed Building Grade II, CA Poor Part occupied C (C)	the Bounda The owner local author	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity.
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied C (C)	the Bounda The owner local author	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the
	CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied C (C)	the Bounda The owner local author Contact: Ro Early C19 t action take	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Part occupied C (C) Private	the Bounda The owner local author Contact: Ro Early C19 t action take	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5	the Bounda The owner local author Contact: Ro Early C19 t action take	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5 Listed Building Grade II, CA Poor	the Bounda The owner local author Contact: Ro Early C19 t action take	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5 Listed Building Grade II, CA Poor	the Bounda The owner local author Contact: Ro Early C19 t action take	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5 Listed Building Grade II, CA Poor Part occupied D (D)	the Bounda The owner local author Contact: Ro Early C19 t action taker in a poor st	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5 Listed Building Grade II, CA Poor Part occupied D (D)	the Bounda The owner local author Contact: Ro Early C19 t action taker in a poor st	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. odney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair:
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square E5 Listed Building Grade II, CA Poor Part occupied D (D)	the Bounda The owner local author Contact: Ro Early C19 t action taker in a poor st	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square ES Listed Building Grade II, CA Poor Part occupied D (D) Private 55 and 59 Clapton Terrace N16	the Bounda The owner local author Contact: Ro Early C19 t action take in a poor st Contact: Ro Terraced ho	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	<ul> <li>Listed Building Grade II, CA</li> <li>Poor</li> <li>Part occupied</li> <li>C (C)</li> <li>Private</li> </ul> 7 Clapton Square E5 Listed Building Grade II, CA Poor Part occupied D (D) Private	the Bounda The owner local author Contact: Ro Early C19 t action take in a poor st Contact: Ro Terraced ho	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square ES Listed Building Grade II, CA Poor Part occupied D (D) Private 55 and 59 Clapton Terrace N16 Listed Building Grade II Poor	the Bounda The owner local author Contact: Ro Early C19 t action take in a poor st Contact: Ro Terraced ho	ary Estate. Some are in use but all require repair: s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square ES Listed Building Grade II, CA Poor Part occupied D (D) Private 55 and 59 Clapton Terrace N16 Listed Building Grade II Poor Part occupied	the Bounda The owner local author Contact: Ro Early C19 t action take in a poor st Contact: Ro Terraced ho	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY:	Listed Building Grade II, CA Poor Part occupied C (C) Private 7 Clapton Square ES Listed Building Grade II, CA Poor Part occupied D (D) Private 55 and 59 Clapton Terrace N16 Listed Building Grade II Poor Part occupied C (C)	the Bounda The owner local author Contact: Ro Early C19 t action taken in a poor st Contact: Ro Terraced ho and under the	ary Estate. Some are in use but all require repair. s have had pre-application discussions with the rity. bodney Keg (LPA) 020 8356 7739 rerraced house. Local authority enforcement n against unauthorised works. Property remains tate of repair. bodney Keg (LPA) 020 8356 7739 bouses, mid to late C18. Suffering from disrepair



A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expediate functions and fabrics and

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	Marlow House, 160 Dalston Lane E8	Early-mid C18 house. Listed building consent granted for conversion to residential in 2011. Works yet to take place.
		Too Daiston Lane Lo	
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	St Columba's Vicarage	Gothic Revival vicarage built 1873-4 to design of James
		and link to church,	Brooks. Lantern joinery and leadwork repaired in 2011
		Kingsland Road E2	and localised reslating carried out.
	DESIGNATION:	Listed Building Grade I, CA	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
and the second second second	SITE NAME:	320 Kingsland Road E8	Early C19 terraced house suffering from
			under use and lack of maintenance.
	DESIGNATION	Listed Building Grade II, CA	
	CONDITION:	Fair	
		Part occupied	
	PRIORITY:	C (C)	
		Company	Contact: Rodney Keg (LPA) 020 8356 7739
	CITE NIAME.	592 Kingsland Boad E8	C18 terraced house. Shop on ground floor Lipper floors
	SITE NAME:	592 Kingsland Road E8	C18 terraced house. Shop on ground floor. Upper floors disused. Listed building consent granted in 2008 for
	SITE NAME:	592 Kingsland Road E8	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall
		<b>592 Kingsland Road E8</b> Listed Building Grade II, CA	disused. Listed building consent granted in 2008 for
		-	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall
GRANADA - BASH	DESIGNATION:	Listed Building Grade II, CA	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall
GRANADA BASH	DESIGNATION:	Listed Building Grade II, CA Poor	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.
GRANADA = BASH	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Part occupied D (D)	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall
GRANADA BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied D (D)	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.
GRANADA = BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin,	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa I 889. Suffering from lack of maintenance.
CRANADA T BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Part occupied D (D) Private	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs
CRANADA® BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction
GRANADA BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa I 889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction
CRUNADA I BASH	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa I 889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C)	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C)	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private	disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems. Contact: Rodney Keg (LPA) 020 8356 7739 Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel. Contact: Rodney Keg (LPA) 020 8356 7739
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir,	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir, Lordship Road,	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in deteriorating condition. Feasibility work underway</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir, Lordship Road, Stoke Newington N16	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir, Lordship Road, Stoke Newington N16 Listed Building Grade II, CA Poor	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in deteriorating condition. Feasibility work underway by local group to repair the building and use as a</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir, Lordship Road, Stoke Newington N16 Listed Building Grade II, CA Poor	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in deteriorating condition. Feasibility work underway by local group to repair the building and use as a</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Listed Building Grade II, CA Poor Part occupied D (D) Private The Griffin, Leonard Street EC2 Listed Building Grade II, CA Poor Occupied C (C) Private Gas House to west of reservoir, Lordship Road, Stoke Newington N16 Listed Building Grade II, CA Poor Vacant	<ul> <li>disused. Listed building consent granted in 2008 for rebuilding the upper parts of the north and east wall following structural problems.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Public house circa 1889. Suffering from lack of maintenance. Listed building consent application submitted for repairs and conversion of upper floors to residential in conjunction with proposals for adjoining site for hotel.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Single storey, 4 bay, stock brick building with moulded brick cornice and parapet. No longer has operational use in connection with reservoir, is vacant and in deteriorating condition. Feasibility work underway by local group to repair the building and use as a</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

#### HERITAGE AT RISK 2012 / LONDON / HACKNEY

HENHAGE AT NISK 2012 / LOINE			
	SITE NAME:	Forecourt wall to Pond House, 162 Lower Clapton Road E5	Forecourt wall, early C19. In need of extensive repair. See entry for Pond House.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	,	
	PRIORITY:	C (C)	
		Company	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	Pond House, 162 Lower Clapton Road E5	Villa circa 1800. In need of repair and full beneficial use. Repair works and conversion to residential given consent in May 2011. Works yet to take place.
	DESIGNATION:	Listed Building Grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
		Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	Official and a		
	SITE NAME:	Stables to north of Pond House, 162 Lower Clapton Road E5	Early C19 stable block. In need of repair and full beneficial use. Repair works and conversion to residential given consent in May 2011. Works yet to take place.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	New Lansdowne Club, 195 Mare Street E8	Substantial detached house, 1715. Front elevation repaired in 2010. Property has been marketed for sale.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
C ON A STORE STORE		. ,	1 0
	SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5	Disinfecting station. Built 1900. Site used as an animal warden's base and as the Council's cleansing depot. Proposals underway to make building watertight
AA	DESIGNATION:	Listed Building Grade II	pending feasibility study for new uses.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	Court House and Police Station, Old Street ECI	Former magistrates' court and police station. Planning permission and listed building consent granted in 2010 for conversion to hotel but work not yet started on site.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	· · ·	Contact: Rodney Keg (LPA) 020 8356 7739

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

ATTA	SITE NAME:	Air Raid Precaution Centre, Rossendale Street (east side) E5	Air raid shelter. Built in 1938. Suffered from flooding and in poor condition. Potential uses very limited.
			"Adopted" as a monument by local school, Horizon School in Stoke Newington. Planning permission and
	DESIGNATION:	Listed Building Grade II	listed building consent granted in 2004 for retention
	CONDITION:	Poor	of air raid shelter as a museum and construction of
TTEX T	OCCUPANCY:		flats above. Works nearing completion.
	PRIORITY:	D (D)	
	OWNER TYPE:	Local authority	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	Walls and gates to Bishopsgate Goods Station,	Late CI9 walls to demolished goods station. Gates have been repaired off site. Future use of structure currently being discussed as part of the redevelopment of the
		Shoreditch High Street El	Goods Yard.
		Listed Building Grade II	
and and a	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	D (D)	Contact: Podpay Kag (LPA) 020 9254 7729
	OWNER TYPE:	Company	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	187 Shoreditch High Street EI	Early C18 terraced house with altered facade. Vacant and in deteriorating condition. Temporary metal covering to roof to provide protection against water ingress.
	DESIGNATION:	Listed Building Grade II	
anner (a blage fammers at	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	196 Shoreditch High Street EI	Early C18 building. Stabilisation and repair works now complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.
		196 Shoreditch High Street E1 Listed Building Grade II	complete and upper floors occupied. External rendering
		-	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to
	DESIGNATION:	Listed Building Grade II Good Part occupied	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to
	DESIGNATION:	Listed Building Grade II Good	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.
	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II Good Part occupied F (F)	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly. Contact: Rodney Keg (LPA) 020 8356 7739 The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard,	complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly. Contact: Rodney Keg (LPA) 020 8356 7739 The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor N/A	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor N/A C (C)	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor N/A C (C)	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor N/A C (C)	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI Listed Building Grade II, CA Poor N/A C (C) Local authority Shrubland Road Evangelical Church, Shrubland Road EVangelical Church,	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>A rare and complete example of a temporary iron</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street E1 Listed Building Grade II, CA Poor N/A C (C) Local authority Shrubland Road Evangelical Church,	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>A rare and complete example of a temporary iron</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street E1 Listed Building Grade II, CA Poor N/A C (C) Local authority Shrubland Road Evangelical Church, Shrubland Road E8	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>A rare and complete example of a temporary iron</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street E1 Listed Building Grade II, CA Poor N/A C (C) Local authority Shrubland Road Evangelical Church, Shrubland Road Evangelical Church,	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>A rare and complete example of a temporary iron</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II Good Part occupied F (F) Quango Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street E1 Listed Building Grade II, CA Poor N/A C (C) Local authority Shrubland Road Evangelical Church, Shrubland Road Evangelical Church, Shrubland Road E8	<ul> <li>complete and upper floors occupied. External rendering to ground floor to mitigate damp ingress. Works to commence shortly.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate pointing and damaged stone coping. Railings and gates around forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. The churchyard is maintained by the local authority. Further repair works needed.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>A rare and complete example of a temporary iron</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

	SITE NAME:	White Lodge,	Early/mid C19 villa. Café on ground floor. Listed building
A BASE		Springfield Park E5	consent application for repair and for use of the upper floor for community uses approved in November 2011.
	DESIGNATION:	Listed Building Grade II, RPG II	Works yet to start.
	CONDITION:	Fair	
TTIII	OCCUPANCY:	Part occupied	
	PRIORITY:	D (C)	
	OWNER TYPE:	Local authority	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	91 Stoke Newington Church Street N16	Mid C18 house of three storeys with pedimented front. Although at least partially occupied, the building is falling into disrepair.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
	OWNER TYPE:	Private	Contact: Rodney Keg (LPA) 020 8356 7739
	SITE NAME:	Monument to Joanna Vassa,	A four-sided stone pedestal with lotus bud cornice
		Stoke Newington High Street,	surmounted by urn commemorating the death of the daughter of black abolitionist, Olaudah Equiano in 1857.
		Abney Park Cemetery NI6	Failure of previous repairs and widespread erosion.
	DESIGNATION:	Listed Building Grade II, RPG II Poor	
	CONDITION: OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Unknown	Contact: Rodney Keg (LPA) 020 8356 7739
	OWNERTHE.	CHRIOWIT	
ZEAL AN	SITE NAME:	Monument to John Swan,	A white marble draped urn over pedestal from around
A CARLEN AND		Stoke Newington High Street,	1869. Hidden behind overgrown vegetation, fallen trees
		Stoke Newington High Street, Abney Park Cemetery N16	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion,
	DESIGNATION:	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent
	CONDITION:	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Poor	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion,
		Stoke Newington High Street, Abney Park Cemetery N16Listed Building Grade II, CA, RPG II PoorN/A	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion,
	CONDITION: OCCUPANCY:	Stoke Newington High Street, Abney Park Cemetery N16Listed Building Grade II, CA, RPG IIPoorN/AA (New entry)	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.
	CONDITION: OCCUPANCY: PRIORITY:	Stoke Newington High Street, Abney Park Cemetery N16Listed Building Grade II, CA, RPG IIPoorN/AA (New entry)	1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion,
	CONDITION: OCCUPANCY: PRIORITY:	Stoke Newington High Street, Abney Park Cemetery N16Listed Building Grade II, CA, RPG IIPoorN/AA (New entry)UnknownMortuary Chapel, Stoke Newington High Street,	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Stoke Newington High Street, Abney Park Cemetery N16Listed Building Grade II, CA, RPG IIPoorN/AA (New entry)UnknownMortuary Chapel, Stoke Newington High Street,	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad         Vacant         A (A)	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad         Vacant         A (A)	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad         Vacant         A (A)	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad         Vacant         A (A)         Trust	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early CI9 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME:	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Poor N/A A (New entry) Unknown Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Very bad Vacant Vacant A (A) Trust Abney Park Cemetery Registered Park and Garden Grade II, also CA, 16 LBs	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the chapel is in very bad condition. Stakeholder meetings are</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Poor N/A A (New entry) Unknown Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Very bad Vacant A (A) Trust Abney Park Cemetery Abney Park Cemetery Registered Park and Garden Grade II, also CA, 16 LBs Extensive significant problems	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early CI9 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Poor         N/A         A (New entry)         Unknown         Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16         Listed Building Grade II, CA, RPG II         Very bad         Vacant         A (A)         Trust         Abney Park Cemetery         Abney Park Cemetery         Stoke Newington High Street, Abney Cemetery         Vacant         A (A)         Trust         Abney Park Cemetery         Listed Building Grade II, CA, RPG II         Vacant         A (A)         Trust         Listed Suiding Grade II, CA, RPG II         Vacant         A (A)         Trust         Listed Suiding Grade II, CA, RPG II         Listed Building Grade II, CA, RPG II         Stoke Action II         A (A)         Trust         Listed Suiding Grade II, CA, IG LBS         Extensive significant problems	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the chapel is in very bad condition. Stakeholder meetings are planned throughout 2012 to discuss and agree a future</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Poor N/A A (New entry) Unknown Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Very bad Vacant A (A) Trust Abney Park Cemetery Abney Park Cemetery Registered Park and Garden Grade II, also CA, 16 LBs Extensive significant problems High Declining	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the chapel is in very bad condition. Stakeholder meetings are planned throughout 2012 to discuss and agree a future strategy for repairs and improvements.</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY	Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Poor N/A A (New entry) Unknown Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16 Listed Building Grade II, CA, RPG II Very bad Vacant A (A) Trust Abney Park Cemetery Abney Park Cemetery Registered Park and Garden Grade II, also CA, 16 LBs Extensive significant problems High Declining	<ul> <li>1869. Hidden behind overgrown vegetation, fallen trees and other structures, this monument leans upon adjacent pedestal and its surface is badly damaged by erosion, dirt and organic growth.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Gothic Revival cemetery chapel, 1839, now ruinous. Situated in the centre of the early C19 cemetery and a feature of views along the main avenues. See entry for Abney Park Cemetery. Condition survey recently commissioned by local authority.</li> <li>Contact: Rodney Keg (LPA) 020 8356 7739</li> <li>Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. One of London's most important Nonconformist cemeteries. The landscape, many tombs and monuments are in poor condition; the chapel is in very bad condition. Stakeholder meetings are planned throughout 2012 to discuss and agree a future</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### HERITAGE AT RISK 2012 / LONDON / HACKNEY

JAN IL	SITE NAME:	Premises of Testi and Sons Millwrights, Waterworks Lane E5	Currently va but new use	dor style building, probably originally a school. acant. Surrounding redevelopment completed e required for this building. Repairs required stonework. Heritage Lottery Fund bid being
	DESIGNATION:	Listed Building Grade II, CA	made by lo	cal amenity group to bring the building into
	CONDITION:	Poor	use as herit	age and educational facility.
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Company	Contact: Ro	odney Keg (LPA) 020 8356 7739
	SITE NAME:	Haggerston Baths, Whiston Road E2	in disrepair.	s and swimming pool, 1904. Now vacant and Pre-application discussions took place during urther progress.
	DESIGNATION:	Listed Building Grade II		
	CONDITION:	Poor		
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Local authority	Contact: Ro	odney Keg (LPA) 020 8356 7739
	SITE NAME:	Church of St Mary of Eton with St Augustine, East Way E9	Garner: A for roof slating the 2010 Q its replacem	an brick with stone dressings by Bodley and ormer mission church of Eton College. The nave appears to be in serviceable condition althoug Quinquennial Inspection report recommends nent in the foreseeable future. The church has
	DESIGNATION:	Listed Place of Worship Grade II*	suffered dar	mage in the past from water penetration at
	CONDITION:	Poor		ters and gable flashings and it is reported ontinue to occur.
	PRIORITY:	C (C)	ulat icans co	ontinue to occui.
	OWNER TYPE:	Religious organisation	Contact: Pri	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Church of St John of Jerusalem, Lauriston Road E9	style. Crucif limestone d of high leve	EC Hakewill of I 845-8 in the early English form with west tower in Kentish ragstone with Iressings and slate roofs. There is deterioration I stonework with an anticipated programme Heritage/Heritage Lottery Fund grant-aided
	DESIGNATION:	Listed Place of Worship Grade II*, CA	repairs bein	ig worked up.
	CONDITION:	Poor	1	0
	PRIORITY:	D (D)		
	OWNER TYPE:	Religious organisation	Contact: Pri	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Church of St Leonard, Shoreditch High Street EI	George Dai a joint Heri repair of ro	t between 1736 and 1740 to the design of nce the Elder. The church recently received tage Lottery Fund/English Heritage grant for ofs at south west and north west corners are underway. Recent investigation work
	DESIGNATION:	Listed Place of Worship Grade I, CA		d issues with high level stonework which
	CONDITION:	Poor	needs repai	r.
	PRIORITY:	С (С)		
	OWNER TYPE:	Religious organisation	Contact: Pri	incipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Dalston La	ane West		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	Unknown
CONTACT:		eg (LPA) 020 8356 7739	NEW ENTRY?:	No
SITE NAME:	Sun Street	:		
	Conservat			Very bad
	Conservat	IOII AI ed	CONDITION:	Very bad
DESIGNATION:				
	Medium	eg (LPA) 020 8356 7739	TREND: NEW ENTRY?:	Deteriorating significantly No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

## HAMMERSMITH AND FULHAM

HAMMERSMITH AND	FULHAM		
	SITE NAME:	34 Black Lion Lane, St Peter's Square W6	Cottage, early/mid C19. Stuccoed and painted brick. Listed building consent for restoration approved 2005, and local planning authority has been proactive in seeking implementation. Works halted on site. New listed building
	DESIGNATION:	Listed Building Grade II, CA	consent application approved due to need for extra
	CONDITION:	Very bad	demolition works in 2011. Conditions on approval
	OCCUPANCY:	,	being discharged. Negotiations with owner ongoing.
-	PRIORITY:	В (А)	
6 6 2	OWNER TYPE:	Private	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Mortuary Chapel of Conde De Bayona Marques De Misa, Harrow Road, St Mary's Roman Catholic Cemetery NW10	Late C19 Gothic mausoleum with tiled forecourt, railings and gate. Broken stained glass, loss of gutters and rooftiles, corrosion of ironwork with missing finials.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Vault of Campbell Family, Harrow Road, St Mary's Roman Catholic Cemetery NW10	Mausoleum by CHB Quennell in Byzantine style, erected in 1904. Severe damage to brickwork bands and internal marble cladding. Vegetation growing through roof. Evidence of anti-social activity.
	DESIGNATION:	Listed Building Grade II, CA	Evidence of anti-social activity.
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Former Wormholt Library and Infant Welfare Centre, Hemlock Road W12	Former public library and infant welfare centre, 1930, partly occupied. Copper stolen from dome in 2009. Urn finials have been placed in storage. Listed building
	DESIGNATION:	Listed Building Grade II, CA	consent approved for the refurbishment of the building for a new Free School. Works to library part of the
	CONDITION:	Fair	building completed in 2011. Copper roof reinstated.
	OCCUPANCY:	Part occupied	Awaiting restoration of urn finials and former welfare centre.
	PRIORITY:	F (A)	
	OWNER TYPE:	Local authority	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Kent House including front boundary railings and gate, 10 Lower Mall W6	House circa 1762, but the wrought iron railings and gate are thought to be earlier. The gate has an overthrow illustrated in the Survey of London. Works commenced on
	DESIGNATION:	Listed Building Grade II, CA	site and significant restoration including the reinstatement of the railings has been undertaken. Listed building consent
	CONDITION:	•	and planning permission granted for refurbishment and
HIH CHARTER AND A	OCCUPANCY:	Vacant	conversion to single dwelling.
	PRIORITY:	E (E)	
	OWNER TYPE:	Private	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Tomb of Frederick Harold Young, Margravine Road, Hammersmith Cemetery W6	Mausoleum dating from 1884. Missing coping stone to west elevation, some broken or missing glass. Lead flashing stolen 2012. Interior not inspected.
2 2000000000 L	DESIGNATION:	Listed Building Grade II, CA	
Dependence!	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Unknown	Contact: Adam O'Neill (LPA) 020 8753 3318

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### HERITAGE AT RISK 2012 / LONDON / HAMMERSMITH AND FULHAM

SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	F (F) Private Tomb of Samuel Jones,	Court House, 1908. Red brick in early English baroque style. Vacant since closure. Broken into and vandalised in 2009. Listed building consent and planning permission for refurbishment and conversion to office and residential use approved in 2010. Works completed in 2012 and awaiting occupation. Contact: Adam O'Neill (LPA) 020 8753 3318 Table tomb over brick and stone plinth dating from end
DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Very bad	of C18. Evidence of severe mechanical damage, erosion and rusting of remaining railings. Invasive vegetation. Contact: Adam O'Neill (LPA) 020 8753 3318
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Hospital Nurses' Home, Ravenscourt Gardens W6 Listed Building Grade II, CA Fair	Nurses' home, 1938 by Burnet, Tait and Lorne. Vacant since cessation of unauthorised budget hotel use in 2009. Resolution to approve planning permission and listed building consent for conversion to residential use subject to completion of Section 106 agreement. Contact: Adam O'Neill (LPA) 020 8753 3318
STE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Fair	Hospital, 1933 by Thomas Tait, funded by the freemasons. Vacant since closure of NHS facility in 2006. Listed building consent approved in 2008 for refurbishment in connection with a cancer treatment hospital proposal. Some works, including dismantling of the garden walls and sundial, have been undertaken, but conversion work has stalled. Parapet repairs underway in 2011/12. Contact: Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor Vacant B (B)	Formerly a cinema built in 1923 by Frank Verity, then a bingo hall, now vacant. Listed building consent and planning permission for a new hotel scheme approved in 2010 and Section 106 Agreement completed. Conditions on those approvals currently being discharged. Contact: Adam O'Neill (LPA) 020 8753 3318
SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Poor D (D)	Church built in 1827, designed by George Ledwell Taylor. Reordered in 1980s creating upper and lower halls at the west end retaining a worship area in the east end. Ancillary spaces now in use by a nursery. Grant offered towards high level tower works and aisle roofs which are due to commence shortly. Contact: Principal Heritage at Risk Adviser 020 7973 3000

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Parish Church of All Saints, Putney Bridge Approach, Fulham SW6	late C19.Th Arthur Blom	n CI4 and CI5 origins, heavily restored in the le rest of the church was rebuilt in 1880-1 by Si nfield. Main issue is due to movement within the sh Heritage grant offered in 2011 towards ower.
1 State		Listed Place of Worship Grade II*		
	CONDITION:			
A A A A A A A A A A A A A A A A A A A	PRIORITY:	D (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Prir	ncipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	St Mary's,	Kensal Green		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	Deteriorating significantly
CONTACT:	Adam O'N	Neill (LPA) 020 8753 3318	NEW ENTRY?:	No
HARINGEY				
	SITE NAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N22	hall and thea 1935.The Tri	ent complex including exhibition hall, music atre, built 1868-73. First ever television centre, ust are exploring orbits for expanding uses.
	DESIGNATION:	Listed Building Grade II, CA, RPG II		tage has offered funding towards investigative urgent repairs.
	CONDITION:	Poor		
B almer Com	OCCUPANCY:	Part occupied		
TO AN INC. IN COMPANY	PRIORITY:	С (С)		
EAN	OWNER TYPE:		Contact: Mo	ortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	Hornsey Town Hall, Broadway N8	on Dudock's important ir	to the design of RH Uren. Modelled s seminal town hall at Hilversum and an nfluence in subsequent British town hall design.
	DESIGNATION:	Listed Building Grade II*, CA	Well preserv	ved interior. Part occupied for Council use. or the repair, conversion and future use of the
	CONDITION:	Poor	listed buildin	ng, as well as the enabling development at the
	OCCUPANCY:	Part occupied		site, have been approved by the Council.
	PRIORITY:	D (D)		
	OWNER TYPE:	Local authority	Contact: Prir	ncipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Public toilets, Bruce Grove, Tottenham N17	and deterior of a partner	circa 1920, with fine external ironwork. Empty rating. The ironwork has been restored as part rship scheme between the local authority and tage and a feasibility study/future use fabric
	DESIGNATION:	Listed Building Grade II, CA	survey has b	been undertaken, but no future use identified.
	CONDITION:	Poor	,	
	OCCUPANCY:	N/A		
Contraction of the local division of the loc	PRIORITY:	C (C)		
	OWNER TYPE:	Local authority	Contact: Mo	ortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	7 Bruce Grove, Tottenham N17	vacant and h An urgent w	air of early C19 houses.The building is has suffered substantial internal collapse. vorks notice has been served and urgent
	DESIGNATION:	Listed Building Grade II, CA		been undertaken. A scheme of refurbishment sion to flats is under consideration.
		Very bad		
	OCCUPANCY:			
	PRIORITY:	A (A)		
	OWNER TYPE:	Private	Contact: Mo	ortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17	In urgent ne deteriorating	ck boundary wall to Bruce Castle Park. eed of essential repairs as brickwork is g. An initial programme of repairs has taken, but further works are needed.
1 states have	DESIGNATION:	Listed Building Grade II, CA	been under	taken, but fullther works are needed.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	B (B)		
	OWNER TYPE:	Local authority	Contact: Mo	ortimer MacSweeney (LPA) 020 8489 2841
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution	but not ye E Under rep	y; solution agreed t implemented. bair or in fair to good no user identified; or with new use agreed t	ied; are give buildings	ABBREVIATIONS CA Conservation Area Driority categories LB Listed Building en in brackets. LPA Local Planning Authority NP National Park RPG Registered Park and Garde

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

with new use agreed but not yet implemented.

ABBREVIATIONS				
ABBREV	IATIONS			
CA	Conservation Area			
LB	Listed Building			
LPA	Local Planning Authority			
NP	National Park			
RPG	Registered Park and Garden			
SM	Scheduled Monument			
UA	Unitary Authority			
WHS	World Heritage Site			

	SITE NAME:	639 High Road, Tottenham N17	Former gas showroom built 1901 and 1914 in attractive neo Jacobean style, red brick with terracotta dressing and
	DECIDINATION	Listed Ruilding Crade II CA	stone decoration. Elaborate gables and turrets at either end. Large showroom windows. Damaged during 2011
ARC		Listed Building Grade II, CA Poor	riots whilst in use as Council offices.
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
		Local authority	Contact: Mortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	662 High Road, Tottenham N17	Early C18 building of three storeys, in stock brick with stone coped parapet, lower than neighbouring properties with which it has group value. Badly damaged by fire during 2014 rists Owners are calking to protom the building and
	DESIGNATION:	Listed Building Grade II, CA	2011 riots. Owners are seeking to restore the building and listed building consent proceeding.
	CONDITION:	Very bad	5 1 5
No. In.	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Company	Contact: Mortimer MacSweeney (LPA) 020 8489 2841
<b>1</b> .	SITE NAME:	Warmington House, 744 High Road, Tottenham N17	Early C19 house last used as offices. Partly in use for storage. The building is to be restored as part of the proposed Tottenham Hotspur FC stadium
	DESIGNATION:	Listed Building Grade II, CA	redevelopment proposal.
		Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: Mortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	Percy House, 796 High Road, Tottenham N17	Mid C18 house with late C17 forecourt walls and railings. The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of
		796 High Road, Tottenham NI7	Mid C18 house with late C17 forecourt walls and railings. The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals.
		<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of
	DESIGNATION:	<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA Fair	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of
	DESIGNATION:	<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA Fair	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA Fair Vacant	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA Fair Vacant C (C)	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	<b>796 High Road,</b> <b>Tottenham N17</b> Listed Building Grade II*, CA Fair Vacant C (C)	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road,	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company B10 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C)	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company B10 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C)	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company Drinking fountain and cattle trough, High Road,	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Contact: Principal Heritage at Risk Adviser 020 7973 3000 Cattle trough and drinking fountain, 1901. Elaborate Roman baroque style stone fountain head. Grey granite trough.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	796 High Road, Tottenham N17         Listed Building Grade II*, CA         Fair         Vacant         C (C)         Company         810 High Road, Tottenham N17         Listed Building Grade II*, CA         Fair         Vacant         C (C)         Company         Drinking fountain and cattle trough, High Road, Wood Green N22	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company Drinking fountain and cattle trough, High Road, Wood Green N22 Listed Building Grade II Poor N/A	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company Drinking fountain and cattle trough, High Road, Wood Green N22 Listed Building Grade II Poor N/A C (C)	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Contact: Principal Heritage at Risk Adviser 020 7973 3000 Cattle trough and drinking fountain, 1901. Elaborate Roman baroque style stone fountain head. Grey granite trough. Neglected but some repair works carried out last year, but further works are still required.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	796 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company 810 High Road, Tottenham N17 Listed Building Grade II*, CA Fair Vacant C (C) Company Drinking fountain and cattle trough, High Road, Wood Green N22 Listed Building Grade II Poor N/A	The council have been liaising with Tottenham Hotspur FC to secure the repair and reuse of Percy House as part of the stadium redevelopment proposals. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The Council and Trust have been seeking to secure the internal refurbishment and the reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / LONDON / HARINGEY

	site name:	Poor N/A C (C) Local authority South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17 Listed Building Grade II, CA	Retaining wall along Highgate Hill between the street pavement and higher paved walk. Early C19 wall in need of repair: Some repairs carried out in 2010/11 but further repairs are required. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Probably early C17 tall red brick wall in Flemish bond. Tall sloped coping and plinth. Wall ramped gently up at intervals towards the west. Now seriously deteriorating with open decayed pointing, loose and unstable brickwork, previous re-pointing damage also extensive ivy/creeper
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor N/A A (A) Local authority	and frost damage. Programme of urgent repairs undertaken, but further repairs required. Contact: Mortimer MacSweeney (LPA) 020 8489 2841
	SITE NAME:	62 Monument Way, Tottenham NI7	Late C18 three storey detached house, also known as 62 High Cross Road. Seriously affected by water penetration into the structure and interior. The Council is seeking repair and refurbishment proposals.
	DESIGNATION:	Listed Building Grade II	and relarbishment proposals.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (B)	
	OWNER TYPE:	Private	Contact: Mortimer MacSweeney (LPA) 020 8489 2841
<b>A</b>	SITE NAME:	Porters and Walters Almshouses,	Circa 1904. Four two-storey almshouses which form
		St Leonard's Almshouses, Nightingale Road, Wood Green N22	a group with a commemorative stone and front railings. The buildings have suffered from lack of proper maintenance over a number of years and are in
	DESIGNATION:	Nightingale Road,Wood Green N22 Listed Building Grade II, CA	
	CONDITION:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor	The buildings have suffered from lack of proper maintenance over a number of years and are in
	CONDITION: OCCUPANCY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied	The buildings have suffered from lack of proper maintenance over a number of years and are in
	CONDITION: OCCUPANCY: PRIORITY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay.
	CONDITION: OCCUPANCY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C)	The buildings have suffered from lack of proper maintenance over a number of years and are in
	CONDITION: OCCUPANCY: PRIORITY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hill, Highgate N6	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: STTE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hill, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A) Company The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A) Company The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is currently occupied by a church group but is suffering from water ingress which is causing significant damage to both the structure and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hill, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A) Company The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17 Listed Place of Worship Grade II, CA	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is currently occupied by a church group but is suffering from water ingress which is causing significant damage to both the structure and
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A) Company The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17 Listed Place of Worship Grade II, CA Poor C (C)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is currently occupied by a church group but is suffering from water ingress which is causing significant damage to both the structure and interior plaster work.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Nightingale Road, Wood Green N22 Listed Building Grade II, CA Poor Occupied C (C) Charity St George's House, 6 North Hilll, Highgate N6 Listed Building Grade II, CA Poor Vacant B (A) Company The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17 Listed Place of Worship Grade II, CA Poor C (C)	The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 Early C19, three storeys and basement, stucco fronted, with side extensions. Used as a nursing home in the 1930s and afterwards as a hostel. Subsequently squatted and vandalised. Now vacant and in a state of dilapidation, with water penetration damage. Proposals for listed building consent and planning permission secured and programme of works to be undertaken shortly. Contact: Mortimer MacSweeney (LPA) 020 8489 2841 The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is currently occupied by a church group but is suffering from water ingress which is causing significant damage to both the structure and

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

## HERITAGE AT RISK 2012 / LONDON / HARINGEY / HARROW

SITE NAME:	Former Gaumont Palace cinema, Broadway, Wood Green N22	Cinema built 1934, later a bingo hall, with fine original Art Deco interiors. Church group uses part of the building for worship. A scheme of high level roof and stonework repairs and internal refurbishment is underway and will complete in 2012.
DESIGNATION:	Listed Place of Worship Grade II*	
CONDITION:	Fair	
PRIORITY:	F (D)	
OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000

SITE NAME:	Bruce Grove		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	Yes
SITE NAME:	Clyde Circus		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No
SITE NAME:	Noel Park		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No
SITE NAME:	North Tottenham High Road		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	Yes
SITE NAME:	Scotland Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Mortimer MacSweeney (LPA) 020 8489 2841	NEW ENTRY?:	No

## HARROW

SITE NAME:	Brick Kiln to south-east of The Kiln, Common Road, Stanmore	Lower part of a C18 brick kiln conical chimney of which the upper part no longer exists. In urgent need of structural stabilisation and repair:
DESIGNATION:	Listed Building Grade II	
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY:	A (C)	
OWNER TYPE:	Private	Contact: Lucy Haile (LPA) 020 8736 6101
SITE NAME:	Cannons Farm Barn, Hereford Gardens, Pinner	C17 barn with three bays and narrow central bay. An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has
	Hereford Gardens,	An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has approved the change of use of the building and its repair
	Hereford Gardens, Pinner	An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has
DESIGNATION:	Hereford Gardens, Pinner Listed Building Grade II Fair	An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has approved the change of use of the building and its repair
DESIGNATION:	Hereford Gardens, Pinner Listed Building Grade II Fair	An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has approved the change of use of the building and its repair
DESIGNATION: CONDITION: OCCUPANCY:	Hereford Gardens, Pinner Listed Building Grade II Fair Vacant D (C)	An Urgent Works Notice was served on the owners in 2008. Some repair works are required. The Council has approved the change of use of the building and its repair

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	The Hermitage, 776 Kenton Lane	The building is a partially timber-framed, rendered, two-storey range of two bays that probably dates to the C16. The building is in a state of disrepair with cracks
	DESIGNATION:	Listed Building Grade II	in walls, holes in ceilings, broken roof tiles and damp
	CONDITION:	Very bad	problems. A proposal for enabling development to secure the repair and future upkeep of the building
	OCCUPANCY:	Vacant	approved with conditions, awaiting implementation.
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Garden wall to Bernays Gardens, Old Church Lane, Stanmore	C19 wall with buttresses. High number of bricks significantly decayed. In need of repointing. Local authority is seeking funding and has commissioned conservation specialists to
	DESIGNATION:	Listed Building Grade II, CA	prepare a draft listed building consent application for the restoration of the wall.
A DECEMBER OF A	CONDITION:	Poor	restoration of the wall.
Real and the second	OCCUPANCY:	N/A	
The second second	PRIORITY:	C (New entry)	
	OWNER TYPE:	Local authority	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Headstone Manor, Pinner View, Harrow	Manor House dating from C14 with C16, C17 and C18 fabric. Believed to be the earliest surviving timber-framed building in Middlesex. The building is occasionally open for
m m 📃 🗖	DESIGNATION:	Listed Building Grade I, SM	tours and the local authority is exploring funding for repairs and usage.
	CONDITION:	Poor	5
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Harrow Magistrates Court, Rosslyn Crescent, Wealdstone	The building has been empty and on the market for over six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building
		Rosslyn Crescent,	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use
		Rosslyn Crescent, Wealdstone	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building
	DESIGNATION:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local
	DESIGNATION:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local
	DESIGNATION: CONDITION: OCCUPANCY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry)	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128,	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C)	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012).
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C)	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C)	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C) Private Boundary wall fronting road (Hill House), 173 Stanmore Hill	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C) Private Boundary wall fronting road (Hill House), 173 Stanmore Hill (East Side), Stanmore	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C) Private Boundary wall fronting road (Hill House), 173 Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Rosslyn Crescent, Wealdstone Listed Building Grade II Fair Vacant C (New entry) Charity Boundary wall fronting road from Nos I 18-128, Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor N/A C (C) Private Boundary wall fronting road (Hill House), 173 Stanmore Hill (East Side), Stanmore Listed Building Grade II, CA Poor	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered
	DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Rosslyn Crescent,         Wealdstone         Listed Building Grade II         Fair         Vacant         C (New entry)         Charity         Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore         Listed Building Grade II, CA         Poor         N/A         C (C)         Private         Boundary wall fronting road (Hill House), 173 Stanmore Hill (East Side), Stanmore         Listed Building Grade II, CA         Poor         N/A         C (C)         Private	six months. Some of the lead and roof tiles have been removed. The Jasper Foundation have acquired the building with the intention of carrying out repairs and a new use and are seeking pre-application advice from the local authority (April 2012). Contact: Lucy Haile (LPA) 020 8736 6101 C18 brick wall with buttresses with chamfered bases. Many bricks at base have weathered away and parts require re-pointing. Harrow Council are discussing repairs with the owners (March 2012). Contact: Lucy Haile (LPA) 020 8736 6101 This brick wall originates from the C18 or early C19. It is 10 foot high red brick with chamfered pilaster buttresses. Many sections of the wall have weathered



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

	CONDITION: OCCUPANCY: PRIORITY:	Bentley Priory – central entrance block, The Common, Stanmore Listed Building Grade II*, RPG II Fair Part occupied F (C)	its association played in ho use as the h building is co it into a mu development	B the property has a rich history ranging from on with the architect Sir John Soane, the role it osting political figures in the 1800s through to it home of fighter command in WWII. Part of the currently occupied and there are plans to turn useum, but this is dependent on enabling nt which is now underway.
	OWNER TYPE:	Company	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Bentley Priory	A CI6 esta	te enlarged and improved in the late CI8. Price and William Gilpin influenced the
	DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs	design in th occupied th	ne early C19. Royal Air Force Fighter Commanc The mansion from 1936 and it played a central
	CONDITION:	Generally unsatisfactory with major localised problems	Conversion	WWII. They withdrew from the site in 2008. In to a museum and new housing in the house is is underway with related restoration of the
	VULNERABILITY	-	Italian Gard	
	TREND:	Improving		
	OWNER TYPE:	Mixed, multiple owners	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	The Rayners public house, 23 Village Way East	internal plan been empty	unaltered 1930s public house retaining its n form and original fittings.The building has y since 2006. Listed building consent was
All and a state of the state of	DESIGNATION:	Listed Building Grade II	recently app	proved for the repair, renovation and reuse ling and outline planning permission approved
	CONDITION:	Fair		ding development that would help secure
	OCCUPANCY:	Vacant		for its future.
a line	PRIORITY:	E (E)		
	OWNER TYPE:	Private	Contact: Lu	acy Haile (LPA) 020 8736 6101
SITE NAME:	Grim's Dit	ch: four linear sections between Uxbr	idge Road an	d Oxhey Lane, Harrow
SITE NAME: DESIGNATION:		ch: four linear sections between Uxbr Monument (No.1003530)	idge Road an	d Oxhey Lane, Harrow Generally satisfactory
			-	-
	Scheduled Deteriorat	Monument (No.1003530) ion – in need of management	-	Generally satisfactory but with significant localised problems Declining
DESIGNATION:	Scheduled	Monument (No.1003530) ion – in need of management	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Deteriorat Local auth	Monument (No.1003530) ion – in need of management ority	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Deteriorat Local auth	Monument (No.1003530) ion – in need of management ority sch: section extending 1500yds (1370m	CONDITION: TREND: CONTACT: ) north east	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Deteriorat Local auth	Monument (No.1003530) ion – in need of management ority	CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Deteriorat Local auth Grim's Dit Scheduled	Monument (No.1003530) ion – in need of management ority <b>:ch: section extending 1500yds (1370m</b> Monument (No.1002044)	CONDITION: TREND: CONTACT: ) north east CONDITION:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Deteriorat Local auth	Monument (No.1003530) ion – in need of management ority <b>:ch: section extending 1500yds (1370m</b> Monument (No.1002044) growth	CONDITION: TREND: CONTACT: ) north east	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth	Monument (No.1003530) ion – in need of management ority <b>cch: section extending 1500yds (1370m</b> Monument (No.1002044) growth ority	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Grim's Dit	Monument (No.1003530) ion – in need of management ority <b>:ch: section extending 1500yds (1370m</b> Monument (No.1002044) growth ority <b>:ch: section north of Blythwood House</b>	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Grim's Dit	Monument (No.1003530) ion – in need of management ority <b>cch: section extending 1500yds (1370m</b> Monument (No.1002044) growth ority	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth	Monument (No.1003530) ion – in need of management ority cch: section extending 1500yds (1370m Monument (No.1002044) growth ority cch: section north of Blythwood House Monument (No.1002007)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Grim's Dit	Monument (No.1003530) ion – in need of management ority cch: section extending 1500yds (1370m Monument (No.1002044) growth ority cch: section north of Blythwood House Monument (No.1002007) growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Scheduled Scrub/tree Local auth	Monument (No.1003530) ion – in need of management ority cch: section extending 1500yds (1370m Monument (No.1002044) growth ority cch: section north of Blythwood House Monument (No.1002007) growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Scheduled	Monument (No.1003530) ion – in need of management ority cch: section extending 1500yds (1370m Monument (No.1002044) growth ority cch: section north of Blythwood House Monument (No.1002007) growth ority	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: CONDITION: CONDITION:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 from Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERA	Scheduled Deteriorat Local auth Grim's Dit Scheduled Scrub/tree Local auth Scheduled	Monument (No.1003530) ion – in need of management ority cch: section extending 1500yds (1370m Monument (No.1002044) growth ority cch: section north of Blythwood House Monument (No.1002007) growth ority thworks in Pear Wood, west of Watlin Monument (No.1001996)	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONDITION: CONDITION: TREND: CONTACT: CONTACT:	Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 From Oxhey Lane, Harrow Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000 Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 020 7973 3000

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## HERITAGE AT RISK 2012 / LONDON / HARROW / HAVERING

SITE NAME:	Pinner de	er park, Pinner Park Farm, Harrow		
designation:	Scheduled	Monument (No.1019135)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Declining
OWNER TYPE:	Local auth	ority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
HAVERING				
	SITE NAME:	Garden walls to former North Ockendon Hall, Church Lane, North Ockendon RM14	CI6 and lat (now demo	er garden walls to Ockendon Hall lished). Slowly deteriorating.
the States allowed	DESIGNATION:	Listed Building Grade II, CA		
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
and the second	PRIORITY:	С (С)		
and a start of the start	OWNER TYPE:		Contact: Ka	tie Dickson (LPA) 01708 432606
MA	SITE NAME:	Bridge in Parklands Park, Corbets Tey Road, Upminster RM14	landscaped now a publi	, attributed to James Paine; in the former park to Gaynes House (demolished), and c park. Listed building consent has been
CONTRACTOR OF STREET	DESIGNATION:	Listed Building Grade II, CA	granted for	repairs; but the project is still awaiting enable the full restoration.
	CONDITION:	Fair	iunuing to e	enable the full restoration.
	OCCUPANCY:	N/A		
	PRIORITY:	D (D)		
	OWNER TYPE:	Local authority	Contact: Ka	tie Dickson (LPA) 01708 432606
		96-102 North Street.	Late CI7 ti	mber-framed building consisting of two parall
	SITE NAME:	Romford RMI	ranges. The repairs. Woi	building is occupied, but in need of extensive rks have recently been completed to repair the chimney stack.
	DESIGNATION:	Listed Building Grade II	and restore	the childhey stack.
BMST	CONDITION:	Poor		
	OCCUPANCY:	Occupied		
	PRIORITY:	С (С)		
	OWNER TYPE:	Company	Contact: Ka	tie Dickson (LPA) 01708 432606
OT I	SITE NAME:	High House Farmhouse, Ockendon Road RM14	with older t	y house of brick and timber frame c1700 imber frame wing. Timber frame to three on under stress, porch propped by scaffold,
AL-	DESIGNATION:	Listed Building Grade II*, CA		vater damage from roof. Many rooms
N.C. Statement of the second s		Very bad	unnnaditadi	le.Vegetation growth.
	CONDITION.			
		,		
		Part occupied		
	OCCUPANCY:	Part occupied A (A)	Contact: Pri	ncipal Heritage at Risk Adviser 020 7973 300
	OCCUPANCY: PRIORITY:	Part occupied A (A) Trust		
	OCCUPANCY: PRIORITY:	Part occupied A (A)	CI6 garden	ncipal Heritage at Risk Adviser 020 7973 300 walls to Brettons House. extensive repairs.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Part occupied A (A) Trust Garden walls to south of Brettons House,	CI6 garden	walls to Brettons House.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Part occupied A (A) Trust Garden walls to south of Brettons House, Rainham Road, Hornchurch RM13	CI6 garden	walls to Brettons House.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Part occupied A (A) Trust Garden walls to south of Brettons House, Rainham Road, Hornchurch RMI3 Listed Building Grade II Very bad	CI6 garden	walls to Brettons House.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Part occupied A (A) Trust Garden walls to south of Brettons House, Rainham Road, Hornchurch RMI3 Listed Building Grade II Very bad	CI6 garden	ncipal Heritage at Risk Adviser 020 7973 300 walls to Brettons House. extensive repairs.



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Upminster Old Chapel, St Mary's Lane, Upminster RM14	Chapel built in 1800, and no longer used as a place of worship. A Heritage Lottery Fund grant has been secured for the repair and refurbishment of the building to create
	DESIGNATION:	Listed Building Grade II	a performance and community space. Works are currently being undertaken.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (C)	
	OWNER TYPE:	Educational Body	Contact: Katie Dickson (LPA) 01708 432606
A	SITE NAME:	Upminster Windmill, St Mary's Lane, Upminster RM14	Smock mill 1803, retaining original machinery. The building preservation trust (Friends of Upminster Windmill) are putting together a Heritage Lottery Fund bid for further restoration of the mill and to rebuild the miller's cottage to
the state of the state	DESIGNATION:	Listed Building Grade II*	provide a workshop and visitor centre. Regular public access.
the ALL AND	CONDITION:	Fair	р
	OCCUPANCY:	Occupied	
	PRIORITY:	D (D)	Contact: Principal Heritage at Risk Adviser 020 7973 3000
A REAL PROPERTY AND	OWNER TYPE:	Local authority	
	SITE NAME:	Stable block, Rainham Hall, The Broadway, Rainham RM13	Stables and coach house dating to C18. Used for some storage but in need of repair. A feasibility study for the entire Rainham Hall site has been prepared and proposals for the future use of the building are being prepared.
	DESIGNATION:	Listed Building Grade II*, CA	Work is underway to restore the accompanying gardens
	CONDITION:	Poor	as a visitor attraction to open in 2012.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Garden walls at Cranham Hall,	CI6 walls to earlier house on site of Cranham Hall.
	SHE NAHE.	The Chase, Cranham RM14	In need of extensive repairs.
		The Chase,	
		The Chase, Cranham RM14	
	DESIGNATION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor	
	DESIGNATION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor	
	DESIGNATION: CONDITION: OCCUPANCY:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C)	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C)	In need of extensive repairs.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C)	In need of extensive repairs.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C)	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C)	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C)	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Structural repairs have been carried out but the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C) Private Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: STE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE STTE NAME:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C) Private Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Structural repairs have been carried out but the project is still awaiting funding to complete the restoration
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C) Private Footbridge to rear of Nos. 52 and 54, The Grove, Upminster Listed Building Grade II Fair	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Structural repairs have been carried out but the project is still awaiting funding to complete the restoration
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C) Private Footbridge to rear of Nos. 52 and 54, The Grove, Upminster Listed Building Grade II Fair	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Structural repairs have been carried out but the project is still awaiting funding to complete the restoration
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OWNERTYPE: SITE NAME: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	The Chase, Cranham RM14 Listed Building Grade II, CA Poor N/A C (C) Private Mill Cottage, The Dell, High Street, Hornchurch RM12 Listed Building Grade II Poor Occupied C (C) Private Footbridge to rear of Nos. 52 and 54, The Grove, Upminster Listed Building Grade II Fair N/A	In need of extensive repairs. Contact: Katie Dickson (LPA) 01708 432606 Single storey timber-framed range, C17. Now one dwelling. In poor condition and continuing to deteriorate. Contact: Katie Dickson (LPA) 01708 432606 Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s for Sir James Esdaile, Lord Mayor of London 1777-78. Structural repairs have been carried out but the project is still awaiting funding to complete the restoration

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / LONDON / HAVERING / HILLINGDON


	SITE NAME:	Barn to south west of Great Tomkyns, Tomkyns Lane, Upminster RM14	Listed building consent has been granted for the full repair and refurbishment of
	DESIGNATION:	Listed Building Grade II*	the barn in 2011; awaiting implementation.
No. 1	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
and the second second	PRIORITY:	D (C)	
and the second s	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000


SITE NAME:	Dagnam Park Farm moated site, Noak Hill,	, Romford, Havering	g
DESIGNATION:	Scheduled Monument (No.1001988)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Romford		
DESIGNATION:	Conservation Area	CONDITION:	Very bad


DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Katie Dickson (LPA) 01708 432606	NEW ENTRY?:	No

## HILLINGDON

	SITE NAME:	Barn to the west of Weekly House, Bath Road, Harmondswoth	Late CI7 or early CI8 weatherboarded barn with tiled roof. Queen post truss at west end. Weekly House, the boundary wall and the barn form a group. Dilapidated state. Listed building and planning consent granted for
100	DESIGNATION:	Listed Building Grade II, CA	conversion to use as a children's nursery.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	В (А)	
	OWNER TYPE:	Private	Contact: Sarah Harper (LPA) 01895 556000







PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets.

ABBREV	(IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

HUANDA	SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield	C17 red brick garden walls in need of extensive repairs.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:	DI	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Cinema, RAF Uxbridge, Grays Road, Uxbridge	Designed in 1918, it has a large auditorium used historically as lecture hall/cinema or concert hall and was converted to a gymnasium in the 1960s. The building is vacant and
The local is a	DESIGNATION:	Listed Building Grade II	in very poor condition. RAF Uxbridge has been sold by the MoD to a private-sector consortium on a long lease.
	CONDITION:	Very bad	Developers and local authority are working together to
	OCCUPANCY:	Vacant	find a suitable new use. Minor repairs carried out in
	PRIORITY:	A (A)	February 2010.
	OWNER TYPE:	Company	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Former stables to Eastcote House, High Road, Eastcote, Pinner	Early C17 timber-framed building with alterations. Two storeys, three windows blocked. A Conservation Management Plan jointly funded by Hillingdon and English Heritage has been produced and a Stage I bid for funding
	DESIGNATION:	Listed Building Grade II, CA	from the HLF has been successful for works to repair and
	CONDITION:	Poor	reuse all the listed structures on site. Interim holding
	OCCUPANCY:		repairs are scheduled for spring/summer 2012.
	PRIORITY:	D (C)	
	OWNER TYPE:	Local authority	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Dovecote and garden walls to Eastcote House, High Road, Eastcote, Pinner	Square red brick building of C18 appearance with pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible
	SITE NAME: DESIGNATION:	to Eastcote House, High Road, Eastcote, Pinner	pyramidal tiled roof and central louvred turret. Wall is
		to Eastcote House, High Road, Eastcote, Pinner	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible
	DESIGNATION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible
	DESIGNATION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible
	DESIGNATION: CONDITION: OCCUPANCY:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C)	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road,	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C)	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C)	pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains. Contact: Sarah Harper (LPA) 01895 556000 CI7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C)	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed and it has been removed from the Register. Repairs to the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Front garden wall, The Beeches, High Street, Cowley	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Front garden wall, The Beeches, High Street, Cowley	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed and it has been removed from the Register. Repairs to the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Front garden wall, The Beeches, High Street, Cowley Listed Building Grade II Poor	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed and it has been removed from the Register. Repairs to the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: SITE NAME: CONDITION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Front garden wall, The Beeches, High Street, Cowley Listed Building Grade II Poor	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed and it has been removed from the Register. Repairs to the</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Garden walls to former stables to Eastcote House, High Road, Eastcote, Pinner Listed Building Grade II, CA Poor N/A C (C) Local authority Front garden wall, The Beeches, High Street, Cowley Listed Building Grade II Poor N/A A (A)	<ul> <li>pyramidal tiled roof and central louvred turret. Wall is to west of dovecote. Inside, the roof structure is visible and part of the wooden potence remains.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl7 red brick walls surrounding an inner and an outer garden. North west wall has large square brick piers at intervals and a flat stone coping. The north east wall has been much lowered and repaired. Elsewhere wall has been breached and made good in two places.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Cl8 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed and it has been removed from the Register. Repairs to the</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / LONDON / HILLINGDON

	CITE 1111-	The Dower House.	Two storay house with C10 briefs front to alder
	SITE NAME:	393 High Street,	Two storey house with C18 brick front to older timber-framed structure. Four windows wide, brown brick with red brick quoins and window dressings.
C / TA		Harlington Listed Building Grade II	High pitched roof hipped at right and renewed in
In the second se	CONDITION:	Very bad	machine tile. Rebuilt large C16 chimney. The building suffered severe fire damage in May 2011.
	OCCUPANCY:		suffered severe fire damage in ray 2011.
	PRIORITY:	A (A)	
C. C	OWNER TYPE:		Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Manor Farm Barn, High Street, Harmondsworth	Medieval timber-framed, aisled barn of 12 bays, one of the finest buildings of its type. Urgent works undertaken by English Heritage in January 2010 to repair roof covering and areas of weatherboarding. Acquired by English Heritage
	DESIGNATION:	Listed Building Grade I, CA	in 2011 and now open to the public from April-October.
	CONDITION:	Fair	Phased programme of repairs under consideration but not
	OCCUPANCY:		yet implemented.
SALAN DI MAN	PRIORITY:	D (A)	
	OWNER TYPE:	English Heritage	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	The Cedars, 66 High Street, Uxbridge	C18 town house with later additions. Three storeys, central doorway with Doric pilasters, entablature and open pediment. Red brick facade, with bands at first and
	DESIGNATION:	Listed Building Grade II, CA	second floors, dentil and cyma recta cornice with plain tiled roof. Distinctive Dutch gables to side elevation.
	CONDITION:	Fair	Development proposals including the site to the rear
	OCCUPANCY:		have been discussed with the Local Authority.
	PRIORITY:	C (C)	
	OWNER TYPE:	Trust.	Contact: Sarah Harper (LPA) 01895 556000
1	SITE NAME:	Harefield Park	Site comprises main building and two flanking
	SHE NAME:	(annexe to Harefield Hospital), Hill End Road, Harefield	stable buildings of early C18 date. Hospital may close. House vacant, no use identified, south facade
	DESIGNATION:	Listed Building Grade II*, CA	propped and roof in poor condition.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Health Authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000
THE AND	SITE NAME:	The stable block, north east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	Site comprises one of two stable buildings of early C18 date. Hospital may close. In the interim, the stable building will continue to be used for clinical storage. A long-term use needs to be identified.
I III	DESIGNATION:	Listed Building Grade II, CA	
A CONTRACTOR OF A CONTRACTOR O	CONDITION:	Poor	
T PPLO	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Health Authority	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	The stable block, south east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	Site comprises one of two stable buildings of early C18 date. Hospital may close. In the interim the stable building will continue to be used for clinical storage. A long-term use needs to be identified.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Health Authority	Contact: Sarah Harper (LPA) 01895 556000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

TE III	SITE NAME:	Harefield Grove, Rickmansworth Road, Harefield	Probably early C19 country house of three storeys, five windows. Stucco with stone cornice and parapet concealing fairly low pitched hipped slate roof. Extension two storey modern courtyard wing for office use with
	DESIGNATION:	Listed Building Grade II	atrium link. The building has been vacant for a number
	CONDITION:	Good	of years and is deteriorating.
	OCCUPANCY:		
and the second second	PRIORITY:	E (E)	
All and the second second second	OWNER TYPE:	Private	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Cellars of former Cranford House, Roseville Road, Cranford	Brick vaulted cellars to Cranford House circa 1722 (demolished). Of archaeological interest, but potential for use limited due to likely very high costs involved. Suffering from circuit una walkopies and condition detariorating
	DESIGNATION:	Listed Building Grade II, CA	from structural weakening and condition deteriorating.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Cranford House Stables, Roseville Road, Cranford	Stables to Cranford House circa I 720 (demolished). Jointly managed by the London Boroughs of Hillingdon and Hounslow. In reasonable condition following repairs,
	DESIGNATION:	Listed Building Grade II, CA	but in need of a long-term, possibly residential, use.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
and the second	OWNER TYPE:	Local authority	Contact: Sarah Harper (LPA) 01895 556000
		,	
	SITE NAME:	Benlow Works, Silverdale Road, Hayes	Orchestrelle Factory of 1909-11. Reinforced concrete frame; brick exterior, four storeys with 19 bay elevation. Entrance bay has semi-circular stepped brick architrave to
		Listed Building Grade II	doorway and segimental-arched metal casements flanked by rusticated pilasters slightly set forward and breaking
	DESIGNATION.		
	CONDITION:	Very bad	parapet. The roof is letting water in and windows are
	CONDITION:	Very bad Part occupied	parapet. The roof is letting water in and windows are broken. No current proposals.
	CONDITION:	,	parapet. The roof is letting water in and windows are
	CONDITION: OCCUPANCY:	Part occupied	parapet. The roof is letting water in and windows are
	CONDITION: OCCUPANCY: PRIORITY:	Part occupied A (A)	parapet. The roof is letting water in and windows are broken. No current proposals.
	CONDITION: OCCUPANCY: PRIORITY:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road	parapet. The roof is letting water in and windows are broken. No current proposals. Contact: Sarah Harper (LPA) 01895 556000 Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road	parapet. The roof is letting water in and windows are broken. No current proposals. Contact: Sarah Harper (LPA) 01895 556000 Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road	Diract: Sarah Harper (LPA) 01895 556000 Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant	Diract: Sarah Harper (LPA) 01895 556000 Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C)	Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant	Diract: Sarah Harper (LPA) 01895 556000 Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating
	CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority	parapet. The roof is letting water in and windows are broken. No current proposals.         Contact: Sarah Harper (LPA) 01895 556000         Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.         Contact: Sarah Harper (LPA) 01895 556000         Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the
	CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed building consent granted in 2008 for conversion to four</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge Listed Building Grade II	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed building consent granted in 2008 for conversion to four flats and rebuilding of extension and granary following unauthorised demolition. New scheme in discussion,</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge Listed Building Grade II Very bad Vacant	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed building consent granted in 2008 for conversion to four flats and rebuilding of extension and granary following</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Part occupied A (A) Unknown Gatehouse at Hillingdon-Uxbridge Cemetery, Uxbridge Road Listed Building Grade II Poor Vacant C (C) Local authority Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge Listed Building Grade II Very bad Vacant A (A)	<ul> <li>parapet. The roof is letting water in and windows are broken. No current proposals.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. Gatehouse constructed of rubble with stone dressings, tiled roof, five bays with wide central entrance under arch. In deteriorating condition and vacant; wall partially collapsed.</li> <li>Contact: Sarah Harper (LPA) 01895 556000</li> <li>Large, probably late C16, five bay barn with original east aisle. Queen strut roof trusses, lower timbers original except for some added arch braces to the tie beams. Extremely bad condition. Planning and listed building consent granted in 2008 for conversion to four flats and rebuilding of extension and granary following unauthorised demolition. New scheme in discussion,</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## HERITAGE AT RISK 2012 / LONDON / HILLINGDON

SITE NAME:	Manor Farm moat, Ickenham, Hillingdon		
DESIGNATION:	Scheduled Monument (No.1002006)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Moated site, west bank of River Pinn, near Ick	xenham (1/2 mil	e (800m) north west of church), Hillingdon
DESIGNATION:	Scheduled Monument (No.1002001)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Black Jacks Lock and Copper Mill Lock, Hare	field	
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	Yes
site name:	Botwell (Thorn/EMI), Hayes		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	Harmondsworth Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	Hayes Village		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
	Nairita Chakraborty (LPA) 01895 558390		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### HERITAGE AT RISK 2012 / LONDON / HILLINGDON / HOUNSLOW

SITE NAME:	Morford Way, Eastcote, Ruislip		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
site name:	Ruislip Manor Way, Ruislip		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Nairita Chakraborty (LPA) 01895 558390	NEW ENTRY?:	No

## HOUNSLOW

	SITE NAME:	Hardinge Block, Hounslow Barracks, Beavers Lane TW4	Standard-pattern barrack block of the 1870s Cardwell Forces Localisation Programme, unoccupied since c1997. Listed building consent granted in May 2011 for re-use as barracks accommodation. Works currently underway
	DESIGNATION:	Listed Building Grade II	on site.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (D)	
and the second	OWNER TYPE:	Government	Contact: Maggie Urquhart (LPA) 020 8583 4941
	SITE NAME:	Boston Manor House, Boston Manor Road, Boston Manor Park TW8	Built 1623 for Lady Mary Reade. Stabilising action to south and west elevations undertaken. English Heritage grant awarded towards options appraisal for future uses.
	DESIGNATION:	Listed Building Grade I, CA	Repairs to south west corner substantially completed. Reinstatement of finishes awaited. Options appraisal
a statistic for	CONDITION:	Fair	almost ready for public consultation.
	OCCUPANCY:	Vacant	

Contact: Principal Heritage at Risk Adviser 020 7973 3000

Red brick boundary wall of considerable height, C17 and later. Partly shored and in need of repair. A scheme has been agreed to reduce the amount of loss of material to the head of the wall. English Heritage has awarded a grant towards the repairs and works are due to commence in spring 2012.

Contact: Principal Heritage at Risk Adviser 020 7973 3000



	SITE NAME:	Brentford Baths, Clifden Road, Brentford TW8	Public baths and swimming pool 1895-96. Closed 1990. Sold by London Borough of Hounslow in November 1998. Interiors in reasonable condition. Planning permission
	DESIGNATION:	Listed Building Grade II, CA	and listed building consent were granted on appeal in July 2011 for change of use to live-work units.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
16 Mar Car	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Maggie Urquhart (LPA) 020 8583 4941

PRIORITY	(FOR BUILDING	S)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Eventsee and the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E (E)

Boundary wall

DESIGNATION: Listed Building Grade II, SM, CA

to Tudor House and Parr Court,

Castle Way, Hanworth Park TW13

OWNER TYPE: Local authority

Poor

N/A

D (D)

PRIORITY:

SITE NAME:

CONDITION

OCCUPANCY: PRIORITY:

OWNERTYPE: Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site

	SITE NAME:	Archway near east entrance lodge, Gunnersbury Avenue, Gunnersbury Park W3	Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park, a public park since 1925. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in
		Listed Building Grade II, CA, RPG II*	November 2011, which includes works of repair to
	CONDITION:	Very bad	the arch. EH has awarded a grant towards urgent repairs in order to secure the structural stability
	OCCUPANCY:		of the arch, which are due to commence May 2012.
	PRIORITY:	B (A)	
9- T	OWNER TYPE:	Local authority	Contact: Maggie Urquhart (LPA) 020 8583 4941
	SITE NAME:	Boundary wall at Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Part of boundary wall of the garden of the original Gunnersbury House, built I 658-63 by John Webb for Sir John Maynard. Wall runs north-south from arch to south east of Princess Amelia's Bath House. A major
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	'Parks for People' bid was submitted to the Heritage
Les weather the second second	CONDITION:	Fair	Lottery Fund in November 2011, which includes priority
	OCCUPANCY:		works of repair to the wall.
一、"自己"的"自己"的第三人称单数	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Maggie Urquhart (LPA) 020 8583 4941
	SITE NAME:	East lodge to Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Entrance lodge circa 1837. All that remains are small sections of the south and west elevations. 'A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes works
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	of repair to the East Lodge. EH has awarded a grant
	CONDITION:	Very bad	towards urgent repairs in order to secure the structural
	OCCUPANCY:	N/A	stability of the remaining elements of the lodge, which are due to commence in May 2012.
the second second	PRIORITY:	B (C)	are due to commence in may 2012.
	OWNER TYPE:	Local authority	Contact: Maggie Urquhart (LPA) 020 8583 4941
**			
	SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Stable block 1835, on the eastern edge of Gunnersbury Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage.
	SITE NAME: DESIGNATION:	Gunnersbury Avenue, Gunnersbury Park W3	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities
		Gunnersbury Avenue, Gunnersbury Park W3	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage.
	DESIGNATION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities
	DESIGNATION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue,	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People'
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II*	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People'
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A)	Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II*	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor N/A	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor N/A A (A)	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Very bad Vacant A (A) Local authority Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad N/A A (A) Local authority Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor N/A	<ul> <li>Park to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Emergency works have been undertaken, partly funded by English Heritage. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the boathouse.</li> <li>Contact: Maggie Urquhart (LPA) 020 8583 4941</li> <li>Sham Gothic ruins, on the east side of Gunnersbury Park. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

STE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	North Lodge, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor Vacant F (New entry) Local authority	Early C19 lodge building in classical style with Doric portico. A major 'Parks for People' bid was submitted to the Heritage Lottery Fund in November 2011, which includes priority works of repair to the lodge. English Heritage has awarded a grant towards urgent repairs, which are due to commence in May 2012. It is anticipated that the lodge will be used by local community groups. Contact: Maggie Urquhart (LPA) 020 8583 4941
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	The Large Mansion, Gunnersbury Park House, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II*, CA, RPG II* Poor Occupied C (C) Local authority	Country house 1801-28 by and for Alexander Copland; remodelled 1836 by Sydney Smirke for Nathan Rothschild. Good interiors, houses local history museum and education centre for the Boroughs of Hounslow and Ealing. A major 'Heritage Grant' bid has been submitted to the Heritage Lottery Fund, which includes repair and restoration of the building for continued use as a local history museum. Contact: Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	The Small Mansion, Gunnersbury House, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor Vacant C (C) Local authority	Built circa 1810, the smaller of the two houses on the site of Gunnersbury House demolished circa 1801. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. English Heritage has awarded a grant towards urgent repairs to the roof, which are due to commence in May 2012. Contact: Maggie Urquhart (LPA) 020 8583 4941
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	West Lodge, Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Poor Part occupied C (New entry) Local authority	Lodge building dating from 1875 in manner of gate house, partly in use for residential purposes. English Heritage has awarded a grant towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway, which are due to commence in May 2012.
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Gunnersbury Avenue, Gunnersbury Park W3 Listed Building Grade II, CA, RPG II* Very bad Vacant A (A)	Early C19 stables situated within Gunnersbury Park. Emergency works have been undertaken, partly funded by English Heritage. Discussions are continuing with local planning authorities in order to secure repair and reuse of the building. Contact: Maggie Urquhart (LPA) 020 8583 4941
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY TREND: OWNER TYPE:	also part in CA, 22 LBs Generally satisfactory but with significant localised problems	A landscape park developed in the C18 by Princess Amelia and in C19 by Baron Lionel de Rothschild. Became a public park in 1925. Landscape in variable condition. London Borough of Ealing submitted a Parks for People Pre-application for Heritage Lottery funding for restoration of the landscape in the heritage core area and recreation of the west side of the horseshoe lake. A decision on the application is expected in summer 2012. A community horticulture and training scheme is proposed for the walled garden. Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

CONDITION: OCCUPANCY: PRIORITY:	St Lawrence's Church (former), High Street, Brentford TW8Listed Building Grade II*, CAPoorVacantC (C)Company	Former C15 church tower, nave 1764 by Thomas Hardwick. Victorian additions. Empty since 1960s and stripped of fittings. Urgent repairs to the medieval tower were carried out; building since neglected but weathertight. Proposals for waterside development, including the church, have stalled. Condition of the building is deteriorating. Contact: Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	A (A)	Bridge, 1780, by Robert Adam. Rusticated stone-faced with one segmental arch. Flanking pairs of rusticated Doric half columns. Severed from the historic park by the M4. Straddles the borough boundary between Ealing and Hounslow. In need of repair and consolidation; suffers from sporadic vandalism. Contact: Principal Heritage at Risk Adviser 020 7973 3000
CONDITION: OCCUPANCY: PRIORITY:	Kew Bridge Railway Station, Kew Bridge Road, Brentford TW8 Listed Building Grade II, CA Fair Part occupied C (C) Company	Railway station built 1850 by Sir William Tite for the London and South Western Railway. Largely unoccupied, boarded up and deterioration increasing. Externally weathertight. No longer required for railway use and is likely to be sold. Nearby development site now under construction may help as a catalyst for combined action by English Heritage, the Local Authority and others. Contact: Maggie Urquhart (LPA) 020 8583 4941
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	В (В)	C18 Coaching Inn with watching bay at first floor: Characterful and deliberatively attractive elevations. Public House on ground floor: Following a long period of lack of maintenance and water ingress, listed building consent has been granted for conversion to small hotel. Contact: Maggie Urquhart (LPA) 020 8583 4941
CONDITION: OCCUPANCY: PRIORITY:	Ornamental bridge in Syon Park, Park Road, Isleworth TW7 Listed Building Grade II, CA, RPG II Poor N/A F (D) Company	Wrought iron bridge, 1827-30 over west lake on the north west boundary of Park. The owners have carried out a structural survey and works of repair currently underway on site. Contact: Maggie Urquhart (LPA) 020 8583 4941
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	С (С)	Early C19 classical villa style house, symmetrical front. Has been extended and used as a school. Discrete areas have suffered former dry rot following water ingress. Repairs to halt deterioration have been carried out. Current application for change of use to school being considered. Contact: Maggie Urquhart (LPA) 020 8583 4941

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

L	SITE NAME:	The Hermitage, 17 Upper Sutton Lane, Heston TW5	Badly dama further det	mber-framed house with later additions. Iged by fire in 2003. The building has suffered erioration following theft of the temporary
THE REAL PROPERTY	DESIGNATION:	Listed Building Grade II	protective i	roof. Owner seeking enabling development but are considered excessive. Discussions ongoing.
	CONDITION:	Very bad	proposais a	re considered excessive. Discussions ongoing.
	OCCUPANCY:	,		
	PRIORITY:	A (A)		
	OWNER TYPE:	· · ·	Contact: M	aggie Urquhart (LPA) 020 8583 4941
	SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth TW13	c1860. Úrg has suffered	ouse built after 1828 with extension ent works carried out 2002 but building d vandalism and further deterioration.
	DESIGNATION:	Listed Building Grade II		rks undertaken to stem dry rot outbreaks the building but will need renewal. Lack of
	CONDITION:	Poor		s on land swap for enabling development
HALLET THE DEC	OCCUPANCY:	Vacant	have stalled	progress.
	PRIORITY:	A (A)		
	OWNER TYPE:	Company	Contact: M	aggie Urquhart (LPA) 020 8583 4941
SITE NAME:	18th centu	ury garden feature at Hanworth Pa	rk. Hounslow	
		Monument (No.1002008)		Generally unsatisfactory
DESIGNATION:	Junequied		CONDITION:	with major localised problems
	Dotoriorat	tion – in need of management	70010	
PRINCIPAL VULNERABILITY:		uon – in need of management	TREND:	0
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
				020 7973 3000
SITE NAME:	Double di	tched enclosure beside A30 road 5	600yds (460m) w	est of East Bedfont parish church, Hounslow
SITE NAME: DESIGNATION:		tched enclosure beside A30 road 5 Monument (No.1002043)	00yds (460m) w	est of East Bedfont parish church, Hounslow Extensive significant problems
		Monument (No.1002043)		
DESIGNATION:	Scheduled	Monument (No.1002043)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Arable plc	Monument (No.1002043)	CONDITION: TREND:	Extensive significant problems Unknown
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Arable plc Private	Monument (No.1002043)	CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Arable plc Private Romano-B	Monument (No.1002043) pughing	CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Arable plo Private Romano-E Scheduled	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042)	CONDITION: TREND: CONTACT: East Bedfont pa	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Arable plc Private Romano-B	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042)	CONDITION: TREND: CONTACT: East Bedfont pa CONDITION:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Arable plo Private Romano-E Scheduled Arable plo	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042)	CONDITION: TREND: CONTACT: East Bedfont pa CONDITION: TREND:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Arable plo Private Romano-E Scheduled Arable plo	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing	CONDITION: TREND: CONTACT: East Bedfont pa CONDITION: TREND:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Arable plo Private Romano-E Scheduled Arable plo Private	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park	CONDITION: TREND: CONTACT: East Bedfont pa CONDITION: TREND:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Arable plo Private Romano-R Scheduled Arable plo Private Gunnersb	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Arable plo Private Romano-E Scheduled Arable plo Private Gunnersb Conservat Low	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park	East Bedfont pa CONDITION: CONTACT: CONDITION: TREND: CONTACT:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 Very bad
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY:	Scheduled Arable plo Private Romano-E Scheduled Arable plo Private Gunnersb Conservat Low Maggie Ur	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park ion Area	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 Very bad Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Scheduled Arable plo Private Romano-E Scheduled Arable plo Private Gunnersb Conservat Low Maggie Ur	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park tion Area rquhart (LPA) 020 8583 4941 Church, Heston East	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONDITION: CONDITION: TREND:	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 Very bad Unknown
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Scheduled Arable plo Private Romano-R Scheduled Arable plo Private Gunnersb Conservat Low Maggie Ur St Pauls C	Monument (No.1002043) bughing British site 1000yds (910m) west of Monument (No.1002042) bughing ury Park tion Area rquhart (LPA) 020 8583 4941 Church, Heston East	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT: CONTACT: CONTACT: CONTACT: CONDITION: TREND: NEW ENTRY?	Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 rish church, Hounslow Extensive significant problems Unknown Principal Heritage at Risk Adviser 020 7973 3000 Very bad Unknown No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

ADDICENATIONS		
CA	Conservation Area	
LB	Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garden	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	
	0	

## HERITAGE AT RISK 2012 / LONDON / ISLINGTON

ISLINGTON			
	SITE NAME:	Stables to rear of No. 55, Balfe Street NI	Stables built circa 1895 for the London General Omnibus Company. Forms part of the P&O development site. Scheme approved for repair and regeneration of this whole block, including the stables. Permission has been
int	DESIGNATION:	Listed Building Grade II, CA	granted for conversion into office use, and currently
	CONDITION:	Fair	under construction (March 2012).
	OCCUPANCY:	Vacant	
	PRIORITY:	F (D)	
	OWNER TYPE:	Company	Contact: Kristian Kaminski (LPA) 020 7527 2524
	SITE NAME:	Former Milford Haven public house, 214 Caledonian Road NI	Mid C19 public house. In poor condition and substantial decay to the original timber pub front.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Private	Contact: Kristian Kaminski (LPA) 020 7527 2524
	SITE NAME:	Flying Scotsman public house, 2-4 Caledonian Road, King's Cross NI	1900-01. Ground floor in use as a public house, upper floors are vacant and in poor condition (roof leaking).
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
	OWNER TYPE:	Company	Contact: Luciana Grave (LPA) 020 7527 2389
	SITE NAME:	Gates and railings around New Church Hawe and gates on south side of the square, Charterhouse Square EC1	C19 cast iron carriage gates, the piers of clustered columns surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers.
		New Church Hawe and gates on south side of the square, Charterhouse Square EC1	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact
	DESIGNATION:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact
	DESIGNATION:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA Poor	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact
	DESIGNATION: CONDITION: OCCUPANCY:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA Poor N/A	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA Poor N/A A (New entry)	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA Poor N/A	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates on south side of the square, Charterhouse Square ECI Listed Building Grade II, CA Poor N/A A (New entry)	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk,	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates         on south side of the square,         Charterhouse Square ECI         Listed Building Grade II, CA         Poor         N/A         A (New entry)         Unknown         K2 telephone kiosk,         Compton Terrace NI         Listed Building Grade II, CA         Poor         N/A	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry)	Surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry)	Surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry) Company Bevin Court,	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered to be Lubetkin's "most idiosyncratic post-war achievement".
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry) Company Bevin Court, Cruickshank Street WC1	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered to be Lubetkin's 'most idiosyncratic post-war achievement''. Mural damaged by water ingress. Grant funding to be sought for repairs to the mural. Redecoration to common areas
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: OWINER TYPE: SITE NAME: SITE NAME:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry) Company Bevin Court, Cruickshank Street WC1 Listed Building Grade II*, CA	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered to be Lubetkin's 'most idiosyncratic post-war achievement''. Mural damaged by water ingress. Grant funding to be sought
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: OWINER TYPE: SITE NAME: SITE NAME:	New Church Hawe and gates         on south side of the square,         Charterhouse Square EC1         Listed Building Grade II, CA         Poor         N/A         A (New entry)         Unknown         K2 telephone kiosk,         Compton Terrace N1         Listed Building Grade II, CA         Poor         N/A         A (New entry)         Company         Bevin Court,         Cruickshank Street WC1         Listed Building Grade II*, CA         Poor	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered to be Lubetkin's 'most idiosyncratic post-war achievement''. Mural damaged by water ingress. Grant funding to be sought for repairs to the mural. Redecoration to common areas
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	New Church Hawe and gates on south side of the square, Charterhouse Square EC1 Listed Building Grade II, CA Poor N/A A (New entry) Unknown K2 telephone kiosk, Compton Terrace N1 Listed Building Grade II, CA Poor N/A A (New entry) Company Bevin Court, Cruickshank Street WC1 Listed Building Grade II*, CA Poor Occupied	surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. Severe vehicle impact damage to one of the piers. Contact: Kristian Kaminski (LPA) 020 7527 2524 Cast iron, square telephone kiosk with domed roof. 1927. Designed by Giles Gilbert Scott. Poor general condition and door hanging off its hinges. Contact: Kristian Kaminski (LPA) 020 7527 2524 Block of 130 flats designed by Skinner, Bailey and Lubetkin, built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase considered to be Lubetkin's 'most idiosyncratic post-war achievement''. Mural damaged by water ingress. Grant funding to be sought for repairs to the mural. Redecoration to common areas

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

	SITE NAME:	Mecca Bingo Hall, 161-169 Essex Road NI	Built as the Carlton Cinema in 1930 by George Coles, now a bingo hall. Black, white and coloured faience to the Essex Road front, the rest of yellow brick; constant.
	DESIGNATION:	Listed Building Grade II*, CA	The facade to Essex Road is in Egyptian style. Currently vacant but scheme for repair being progressed. A planning
	CONDITION:	Poor	appeal for roof and basement extension to the hall was
The second se	OCCUPANCY:	Vacant	dismissed by the Planning Inspectorate. Future unknown.
	PRIORITY:	С (С)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Odeon Cinema, Holloway Road N7	Cinema, built as the Gaumont 1937-8, architect C Howard Crane of Chicago. Poor general condition, cracking and damage to faience. Inappropriate modern shop fronts in poor condition undermine the design aesthetic.
	DESIGNATION:	Listed Building Grade II	poor condition under nine the design aesthetic.
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Company	Contact: Kristian Kaminski (LPA) 020 7527 2524
5	SITE NAME:	Studio (former Chapel), Lloyd Baker Street, Thornhill WC1	Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. Stock brick with tracery windows in stone, slate roof, late Decorated Gothic style. Permission granted to convert
	DESIGNATION:	Listed Building Grade II, CA	building to residential use, but works not started, and
	CONDITION:	Fair	property is for sale (April 2012).
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
and the second second	OWNER TYPE:	Private	Contact: Andy Rayner (LPA) 020 7527 4087
	SITE NAME:	Islington War Memorial Arch, Manor Gardens N7	Listed war memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed Benairs carried out including works to the
			part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the
		Manor Gardens N7	part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress
	DESIGNATION:	Manor Gardens N7 Listed Building Grade II Fair N/A	part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair
	DESIGNATION: CONDITION:	Manor Gardens N7 Listed Building Grade II Fair	part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A	part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C)	part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C)	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park,	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C)	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C)	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C)	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C) Local authority Finsbury Health Centre,	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage. Some urgent work carried out. Health use to remain,</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C) Local authority Finsbury Health Centre, Pine Street ECI	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C) Local authority Finsbury Health Centre, Pine Street ECI Listed Building Grade I	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage. Some urgent work carried out. Health use to remain,</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C) Local authority Finsbury Health Centre, Pine Street ECI Listed Building Grade I Poor	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage. Some urgent work carried out. Health use to remain,</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: COCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	Manor Gardens N7 Listed Building Grade II Fair N/A D (C) Company Railings, walls, gate piers and gates to Caledonian Park, Market Road N7 Listed Building Grade II Poor N/A C (C) Local authority Finsbury Health Centre, Pine Street ECI Listed Building Grade I Poor Occupied	<ul> <li>part of the Royal Northern Hospital. The memorial is the archway around which the new building has been constructed. Repairs carried out including works to the lettering and stonework and the arch remains in a fair condition. Investigative works complete on water ingress to stonework, solution agreed. Grant funding to be sought.</li> <li>Contact: Kate Graham (LPA) 020 7527 2380</li> <li>Railings, walls and gates to Caledonian Market built 1854 (market demolished). Some repairs carried out with help of English Heritage grant, but extensive further works required. Redevelopment of housing on adjacent site underway. Section of railings repaired as part of this but no scheme for complete repair as yet.</li> <li>Contact: Luciana Grave (LPA) 020 7527 2389</li> <li>Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Conservation plan and management guidelines grant-aided by English Heritage. Some urgent work carried out. Health use to remain,</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Finsbury Town Hall, Rosebery Avenue ECI Listed Building Grade II*, CA	Town hall, built 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style. Magnificent public hall on first floor with elaborate plasterwork in Belle Epoque manner. Now in use as dance studios with
		Fair	main halls available for public use. External fabric of
	CONDITION:		building still not repaired.
	PRIORITY:	F (F)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	The Vaults to the House of Detention (part of former), Sans Walk EC1	Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. In stable condition and works for conversion to office space for a part of
	DESIGNATION:	Listed Building Grade II, CA	the structure approved. Water infiltration from the car park above. Consent for conversion to office granted,
	CONDITION:	Fair	yet to be implemented.
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Luciana Grave (LPA) 020 7527 2389
	SITE NAME:	St Paul's Church, St Paul's Road NI	Former church, built 1826-28 to design of Sir Charles Barry in early Gothic Revival style. Occupied by the Steiner Foundation and in use as school. English Heritage grant for
VAL 1-11 NAVAR	DESIGNATION:	Listed Building Grade II*, CA	repairs to former vestry roof and associated works should be carried out in 2012.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	F (F)	
	OWNER TYPE:	Charity	Contact: Principal Heritage at Risk Adviser 020 7973 3000
144 431 223			
2 Juli	SITE NAME:	49 Thornhill Road NI	House, I 868/9 of stock brick with hipped slate roof and end stock. Two storeys, three window range of two light casements and central 6 over 6 sash. Moulded
	DESIGNATION:	Listed Building Grade II, CA	shouldered architraves. Central porch with ionic columns and entablature. The single storey side extension is derelict.
The second second	CONDITION:	Poor	Permission granted in 2011 for residential use, but not yet
	OCCUPANCY:	Part occupied	commenced (March 2012).
	PRIORITY:	D (D)	
	OWNER TYPE:		Contact: Kristian Kaminski (LPA) 020 7527 2524
	SITE NAME:	Railings, Thornhill Square NI	Some repairs to railings completed in 2010, part-funded by English Heritage. Islington Borough Council is proposing to apply to the Heritage Lottery Fund for further repairs and londersing funding.
	DESIGNATION:	Listed Building Grade II, CA	landscaping funding.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
Same and	PRIORITY:	D (D)	
and the second se	OWNER TYPE:	Local authority	Contact: Andy Rayner (LPA) 020 7527 4087
	SITE NAME:	Railings, Wilmington Square WCI	Cast iron railings of 1819-1841. Urgent works carried out, but currently no funding for full repair programme.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS



	SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Celestial Church of Christ, Cloudesley Square NI Listed Place of Worship Grade II*, CA Very bad C (C) Religious organisation	Although ur stonework I Heritage Lo very poor c also the ceil roof trusses	to the design of Sir Charles Barry. rgent repairs to the roof and high level have been carried out with English Heritage/ ittery Fund funding, the west turrets are in a condition and the finials remain clad in netting, ling has been badly affected by decayed to ncipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Union Chapel, Compton Terrace NI Listed Place of Worship Grade I, CA Very bad F (F) Religious organisation	the upper p Cubbit, on t Anglican/no have major carry out. Jc grant award funding fron	onal chapel and related buildings of 1876-7, wart of the tower completed in 1889, by James the site of the chapel of 1806 built for a joint n conformist congregation. The Union Chapel tower/roof renewal and high level work to oint English Heritage/Heritage Lottery Fund led in December 2008 and 2009, also major n Islington Council in 2010. ncipal Heritage at Risk Adviser 020 7973 3000
	SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Church of St Joseph, Highgate Hill N19 Listed Place of Worship Grade II* Poor A (New entry) Religious organisation	and chapel. T the existing built in 1887 Elements of including var goods of thi: have been le and ceiling p copyright: Jin	ists acquired the site in 1858 and built a monastery Fhe monastery remains and is wrapped around church to its eastern end. The existing church was -9 by Albert Vicars in a Neo-Romanesque style. the previous church built by EW Pugin remain, ious fixtures and fittings. The roof and rainwater is fine church are in a very poor condition – they eaking for some years, damaging the very fine wall baintings within the nave and chancel. Photo n Linwood. hcipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Bunhill Fie	lds, Finsbury Square		
		ion Area		Fair
DESIGNATION: VULNERABILITY:	Conservat Medium	ion Area	CONDITION: TREND:	Fair Deteriorating
	Conservat Medium	ion Area rave (LPA) 020 7527 3000		Fair Deteriorating No
VULNERABILITY:	Conservat Medium	rave (LPA) 020 7527 3000	TREND:	Deteriorating
VULNERABILITY: CONTACT:	Conservat Medium Luciana Gr	rave (LPA) 020 7527 3000 arket	TREND:	Deteriorating
VULNERABILITY: CONTACT: SITE NAME:	Conservat Medium Luciana Gr Chapel Ma	rave (LPA) 020 7527 3000 arket	TREND: NEW ENTRY?:	Deteriorating No
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Conservat Medium Luciana Gr Chapel Ma Conservat Medium	rave (LPA) 020 7527 3000 arket	TREND: NEW ENTRY?: CONDITION:	Deteriorating No Very bad
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY:	Conservat Medium Luciana Gr Chapel Ma Conservat Medium	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000	TREND: NEW ENTRY?: CONDITION: TREND:	Deteriorating No Very bad Improving significantly
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Conservat Medium Luciana Gr Chapel Ma Conservat Medium Luciana Gr	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet	TREND: NEW ENTRY?: CONDITION: TREND:	Deteriorating No Very bad Improving significantly
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Conservat Medium Luciana Gr Chapel Ma Conservat Medium Luciana Gr Chiswell S	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet	TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?:	Deteriorating No Very bad Improving significantly No
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Conservat Medium Luciana Ge Chapel Ma Conservat Medium Luciana Ge Chiswell S Conservat Medium	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet	TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?: CONDITION:	Deteriorating No Very bad Improving significantly No Fair
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY:	Conservat Medium Luciana Ge Chapel Ma Conservat Medium Luciana Ge Chiswell S Conservat Medium	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000	TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Deteriorating No Very bad Improving significantly No Fair Deteriorating
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Conservat Medium Luciana Gi Chapel Ma Conservat Medium Luciana Gi Conservat Medium Luciana Gi	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell	TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND:	Deteriorating No Very bad Improving significantly No Fair Deteriorating
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: SITE NAME:	Conservat Medium Luciana Gr Chapel Ma Conservat Medium Luciana Gr Chiswell S Conservat Medium Luciana Gr	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell	TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?: CONDITION: TREND: NEW ENTRY?:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: DESIGNATION:	Conservat Medium Luciana Gi Chapel Ma Conservat Medium Luciana Gi Chiswell S Conservat Medium Luciana Gi	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell	TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: NEW ENTRY: NEW ENTRY:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes Fair
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY:	Conservat Medium Luciana Gi Chapel Ma Conservat Medium Luciana Gi Chiswell S Conservat Medium Luciana Gi	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell ion Area rave (LPA) 020 7527 3000	TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes Fair
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: CONTACT:	Conservat Medium Luciana Gi Chapel Ma Conservat Medium Luciana Gi Chiswell S Conservat Medium Luciana Gi	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell ion Area rave (LPA) 020 7527 3000 ell arave (LPA) 020 7527 3000	TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes Fair
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT:	Conservat Medium Luciana Ga Chapel Ma Conservat Medium Luciana Ga Chiswell S Conservat Medium Luciana Ga Clerkenwa Conservat Medium	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell ion Area rave (LPA) 020 7527 3000 ell arave (LPA) 020 7527 3000	TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes Fair
VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION: CONTACT: SITE NAME: DESIGNATION: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT: CONTACT:	Conservat Medium Luciana Gi Chapel Ma Conservat Medium Luciana Gi Chiswell S Conservat Medium Luciana Gi Clerkenwe Conservat Medium Luciana Gi	rave (LPA) 020 7527 3000 arket ion Area rave (LPA) 020 7527 3000 itreet ion Area rave (LPA) 020 7527 3000 ell ion Area rave (LPA) 020 7527 3000 ell arave (LPA) 020 7527 3000	TREND: NEW ENTRY: CONDITION: TREND: NEW ENTRY: CONDITION: NEW ENTRY: CONDITION: TREND: NEW ENTRY: NEW ENTRY: NEW ENTRY:	Deteriorating No Very bad Improving significantly No Fair Deteriorating Yes Fair Deteriorating Yes

#### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

SITE NAME:	Mercers Road/Tavistock Terrace		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY ?:	No
SITE NAME:	Moorfields		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	Yes
SITE NAME:	St John's Grove		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No
SITE NAME:	St Mary Magdalene		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY ?:	No
SITE NAME:	Stroud Green		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY ?:	No
SITE NAME:	Tollington Park		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Luciana Grave (LPA) 020 7527 3000	NEW ENTRY?:	No

#### KENSINGTON AND CHELSEA

SITE NAME:	31, Brompton Square, South Kensington SW3	House I 824-39, part of Brompton Square layout. A series of planning and listed building consents have been granted for internal alterations and rear extensions. Works to implement the consents came to a halt in
DESIGNATION:	Listed Building Grade II, CA	December 2008. An urgent works notice to make the
CONDITION:	Poor	building weathertight was served and complied with in December 2009.
OCCUPANCY:	Vacant	IT December 2007.
PRIORITY:	С (С)	
OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
SITE NAME:	Campden Hill, I Campden Hill W8	Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country



	I Campden Hill W8
DESIGNATION:	Listed Building Grade II, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNER TYPE:	Private

house in an urban setting. Permission was granted for internal alterations and extensions in July 2008. Works have stalled on site and the building is now showing the initial signs of neglect with lack of general maintenance.

Contact: Mark Butler (LPA) 020 7361 2465

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ADDILL 1	ATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site
	0

AA	SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10	High brick boundary wall to Harrow Road, a 100m section (approx.) of which collapsed in 2006. Proposals have been formulated for the rebuilding and strengthening
	DESIGNATION:	Listed Building Grade II, CA, RPG I	works. English Heritage have awarded a grant towards the first phase of rebuilding the collapsed section. Works of
and there at the life of		Very bad	rebuilding are due to commence in autumn 2012.
and the factor of the second sec	OCCUPANCY:	,	
	PRIORITY:	В (Е)	
	OWNER TYPE:	Company	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Blumberg Mausoleum, Harrow Road, Kensal Green Cemetery W10	Large mausoleum from mid C19 with rich use of Carrara marble, grey granite and bronze. In very bad condition with extensive vegetation growth, collapsed in parts and showing widesamed delogination
	DESIGNATION:	Listed Building Grade II, CA, RPG I	widespread delamination.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
- Salara	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
1 Sector	SITE NAME:	Mausoleum of Andrew Ducrow, Harrow Road, Kensal Green Cemetery W10	Flamboyant mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson. Later embellished following Ducrow's own
1 STELL KONK		Listed Building Grade II*, CA, RPG I	interment. Considered one of the outstanding monuments
	CONDITION:	-	of the cemetery, it draws its inspiration from Egyptian symbolism and from Ducrow's career as an equestrian
	OCCUPANCY:		circus performer. Loss of sculptural elements and
	PRIORITY:	C (New entry)	ironwork, overgrown vegetation and general erosion.
		Unknown	Contact: Principal Heritage at Risk Adviser 020 7973 3000
N	SITE NAME:	Mausoleum of Isabella Gregory, Harrow Road, Kensal Green Cemetery W10	Mausoleum circa 1830. Part of a group. Hidden behind overgrown vegetation.
		Harrow Road, Kensal Green Cemetery W10	
		Harrow Road,	
	DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad	
	DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry)	Hidden behind overgrown vegetation.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry)	Hidden behind overgrown vegetation.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road,	Hidden behind overgrown vegetation. Contact: Mark Butler (LPA) 020 7361 2465 Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Hidden behind overgrown vegetation. Contact: Mark Butler (LPA) 020 7361 2465 Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A	Hidden behind overgrown vegetation. Contact: Mark Butler (LPA) 020 7361 2465 Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Hidden behind overgrown vegetation. Contact: Mark Butler (LPA) 020 7361 2465 Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A	Hidden behind overgrown vegetation. Contact: Mark Butler (LPA) 020 7361 2465 Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry)	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and there is damage to some windows which may have been</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and there is damage to some windows which may have been</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and there is damage to some windows which may have been</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A	<ul> <li>Hidden behind overgrown vegetation.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Large mausoleum designed by Robert Shout in the first half of C19. Part of the pediment has collapsed and there are cracks on the rear elevation. Corroded ironwork.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and there is damage to some windows which may have been</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Harrow Road, Kensal Green Cemetery W10	Tall monument on plinth dedicated to Frederick Albert Winsor, a pioneer of gas-street lighting, dating from circa 1830. Severe erosion of the plinth threatens the structural stability of the monument.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Monument to Joseph Allmond Cropper, Harrow Road, Kensal Green Cemetery W10	Circa 1870 tall composite monument in Portland stone and pink Peterhead granite shafts. Significant lean and damage to figure, canopy and ironwork.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Monument to Julia Slater, Harrow Road, Kensal Green Cemetery W10	Triangular monument with relief of an allegorical female figure on each side on a circular plinth. Circa 1840. Significant lean and collapse of panels. Encroaching mature vegetation.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
USU	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10	1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco. Central chapel of a Greek Doric tetrastyle, flanked by three-bay colonades, with nine-bay returns to north and south, terminating
TIM		Listed Building Grade I, CA, RPG I	in (now roofless) pavilions containing marble memorial
	CONDITION:	Poor	sculpture. No longer in use, it is suffering from water ingress. A detailed condition survey is now underway
	OCCUPANCY:		with English Heritage grant.
	PRIORITY:	C (C)	0 0 0
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10	Built by John Griffith in 1833 to display tablets and monuments, with a brick vaulted catacomb underneath. In poor condition. English Heritage have recently offered
	DESIGNATION:	Listed Building Grade II, CA, RPG I	a grant towards restoration of a sample bay within the colonnade.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
	OWNER TYPE:	Company	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Admiral Henry Collins Deacon, Harrow Road, Kensal Green Cemetery W10	Mid C19 sculptural monument in Portland stone reproducing a cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the monument on its base and a significant lean.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
MARIA -	CONDITION:	Poor	
21/2 × 000	OCCUPANCY:	N/A	
THE MAN AND AND AND AND AND AND AND AND AND A	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

78

+	SITE NAME:	Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery W10	White marble memorial with sculpture of an anchor and a cross on tall pedestal, dating from mid C19. Significant lean to the south.
the second and a second second	DESIGNATION:	Listed Building Grade II, CA, RPG I	
THE PARTY AND AND AND	CONDITION:	Poor	
	OCCUPANCY:	N/A	
and stands	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10	Two-stage monument dating from 1850 consisting of a rectangular pedestal upon a tomb chest with relief of mourning women in a tropical landscape. A deep
	DESIGNATION:	Listed Building Grade II, CA, RPG I	undercut at its base had led to exposure and erosion of vault and foundations and a slight lean of the monument.
	CONDITION:	Very bad	Chains are missing and posts around it are collapsing.
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
		Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Alfred Cooke, Harrow Road, Kensal Green Cemetery W10	A limestone tomb by Thomas Milnes from mid C19 with statue of horse and infant over pedestal. The sculpture is badly damaged. Railings are missing.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
and the second s	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
State of the survey of	OWNER TYPE:		Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Harrow Road,	Elaborate military monument dating from 1841. Evidence of erosion at foundation level.
		Harrow Road, Kensal Green Cemetery W10	Elaborate military monument dating from 1841. Evidence of erosion at foundation level.
	DESIGNATION:	Harrow Road,	Elaborate military monument dating from 1841. Evidence of erosion at foundation level.
	DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair	Elaborate military monument dating from 1841. Evidence of erosion at foundation level.
	DESIGNATION: CONDITION: OCCUPANCY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A	Elaborate military monument dating from 1841. Evidence of erosion at foundation level.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry)	Evidence of erosion at foundation level.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A	Elaborate military monument dating from 1841. Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road,	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry)	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry)	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Daboda Dewanjee, Harrow Road,	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Indian memorial of red sandstone from mid C19.
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Indian memorial of red sandstone from mid C19.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Indian memorial of red sandstone from mid C19.
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Indian memorial of red sandstone from mid C19.
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A C (New entry) Unknown Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A	Evidence of erosion at foundation level. Contact: Mark Butler (LPA) 020 7361 2465 Monument to Royal Navy Commander Charles Spencer Rickets designed by William Burgess in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In poor condition with damages inflicted by anti-social behaviour, invasive vegetation and general weathering. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Indian memorial of red sandstone from mid C19.



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

	SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10	Portland stone mausoleum dating from mid C19. Erosion at foundation level and encroaching vegetation. Evidence of anti-social activity in the past.
		Listed Building Grade II, CA, RPG I	
	CONDITION:	Fair	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:		Contact: Mark Butler (LPA) 020 7361 2465
	OWNERTHE		
	SITE NAME:	Tomb of Frederick Tillson, Harrow Road, Kensal Green Cemetery W10	Elaborate Gothic Revival monument dating from circa 1870, consisting of a canopied tomb of Portland stone, marble and sandstone over raised, moulded base.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	The monument is in poor condition with subsidence on the north elevation, deterioration of stonework,
	CONDITION:	Poor	widening of joints, corrosion of iron and loss of finials.
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:		Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10	Portland stone sarcophagus with effigy of sleeping child in Carrara marble from around 1840. Slight lean to north-east, erosion of foundations and invasive vegetation
A REAL PROPERTY OF	DESIGNATION	Listed Building Grade II, CA, RPG I	growth. The effigy of the child has been removed and laid
THE REAL PROPERTY OF		-	on the side for safekeeping.
	CONDITION:	Very bad N/A	
	OCCUPANCY:		
	PRIORITY:	A (New entry) Unknown	Contacts Mark Putton (LPA) 020 7261 2465
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
A TABLE A CONTRACT AND A DOCUMENT			
	SITE NAME:	Tomb of General James Perry and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10	Large Mausoleum from the end of C19. In very bad condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner.
	SITE NAME: DESIGNATION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10	condition with widespread erosion, harmful plant growth
		and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I	condition with widespread erosion, harmful plant growth
	DESIGNATION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad	condition with widespread erosion, harmful plant growth
	DESIGNATION: CONDITION: OCCUPANCY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A	condition with widespread erosion, harmful plant growth
	DESIGNATION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry)	condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry)	condition with widespread erosion, harmful plant growth
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry)	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road,	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner. Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry)	Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry)	Condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner: Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations. Contact: Mark Butler (LPA) 020 7361 2465 A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10	Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations. Contact: Mark Butler (LPA) 020 7361 2465 A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger framed by Minton tiles and looked over by an angel
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10	Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations. Contact: Mark Butler (LPA) 020 7361 2465 A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger framed by Minton tiles and looked over by an angel sculpture. Failure of metal supports behind sculpture,
<image/>	DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	<ul> <li>condition with widespread erosion, harmful plant growth and extensive damage to the roof and north-west corner.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger framed by Minton tiles and looked over by an angel</li> </ul>
<image/>	DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor Listed Building Grade II, CA, RPG I Poor	Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations. Contact: Mark Butler (LPA) 020 7361 2465 A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger framed by Minton tiles and looked over by an angel sculpture. Failure of metal supports behind sculpture,
<image/>	DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Very bad N/A A (New entry) Unknown Tomb of George and Mary Waugh, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	Contact: Mark Butler (LPA) 020 7361 2465 Marble figure of a mourning woman with urn and bowl over an inscribed plinth. The monument dates from the end of the C19. The base has been repaired with blocks from other monuments and there is concern about possible collapse of foundations. Contact: Mark Butler (LPA) 020 7361 2465 A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large sexafoil headstone with masonic symbols over raised ledger framed by Minton tiles and looked over by an angel sculpture. Failure of metal supports behind sculpture,



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

		Tomb of James Pasta	Slate chart temb from mid C10 The manual title i
	SITE NAME:	Tomb of James Poole, Harrow Road, Kensal Green Cemetery W10	Slate chest tomb from mid C18. The monument is leaning and delamination is visible on the elevations and on the ledger slab. Loss of decorative features.
	DESIGNATION:	Listed Building Grade II, CA, RPG I	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
CARD ANT ANT		Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of James Ward,	Tall upright with a relief of Muse of Painting dating
		Harrow Road,	from circa I 859. The stone now lies flat and broken in two pieces.
		Kensal Green Cemetery W10	
		Listed Building Grade II, CA, RPG I	
	CONDITION: OCCUPANCY:	Very bad	
		A (New entry)	
	PRIORITY:	Unknown	Contact: Mark Putler (LPA) 020 7261 2465
	OVVINER TYPE:	UTIKI IUWI I	Contact: Mark Butler (LPA) 020 7361 2465
A Part A	SITE NAME:	Tomb of John Gibson,	Tomb of architect John Gibson, designed by the architect
1414		Harrow Road,	himself, circa 1890. Severe erosion of the upper registers
		Kensal Green Cemetery W10	and widening of joints.
1 H Contraction	DESIGNATION:	Listed Building Grade II, CA, RPG I	
K BOBLIT	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Unknown	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of John Lucas.	Tall grey Cornish granite obelisk with Carrara marble
with the second second	SITE NAME:	Tomb of John Lucas, Harrow Road,	Tall grey Cornish granite obelisk with Carrara marble bas-relief dating from end C19. The landing stone is
	SITE NAME:		bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument
* Li		Harrow Road,	bas-relief dating from end C19. The landing stone is
*	DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument
	DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry)	bas-relief dating from end C19.The landing stone is broken and sinking into the vault and the monument is leaning significantly.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry)	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson,	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road,	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown	bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly. Contact: Mark Butler (LPA) 020 7361 2465 Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions. Contact: Principal Heritage at Risk Adviser 020 7973 3000
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry)	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith,	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion of ironwork and heavy overgrowth. Railings are missing</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith, Harrow Road,	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion of ironwork and heavy overgrowth. Railings are missing</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion of ironwork and heavy overgrowth. Railings are missing</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion of ironwork and heavy overgrowth. Railings are missing</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Fair N/A A (New entry) Unknown Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II*, CA, RPG I Poor N/A A (New entry) Unknown Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10 Listed Building Grade II, CA, RPG I Poor Listed Building Grade II, CA, RPG I	<ul> <li>bas-relief dating from end C19. The landing stone is broken and sinking into the vault and the monument is leaning significantly.</li> <li>Contact: Mark Butler (LPA) 020 7361 2465</li> <li>Monumental tomb from 1856 comprising carved, coped coffin under open aedicule with twelve Corinthian columns surmounted by four angels formerly holding a wreath. Loss of structural and sculptural elements, sinking on west side, widespread erosion and dirt accretions.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Portland stone altar tomb on stepped granite base, from circa 1830. Erosion and loss of detailing, corrosion of ironwork and heavy overgrowth. Railings are missing</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Tomb of Sir Charles Newton, Harrow Road, Kensal Green Cemetery W10	Now laid fla	tyle headstone dating from at and more vulnerable to a ne erosion and cracking.	
12.3 53	DESIGNATION:	Listed Building Grade II, CA, RPG I			
	CONDITION:	Very bad			
	OCCUPANCY:	N/A			
	PRIORITY:	A (New entry)			
	OWNER TYPE:	Unknown	Contact: Ma	ark Butler (LPA) 020 7361	2465
	SITE NAME:	Tomb of the Earl of Galloway, Harrow Road, Kensal Green Cemetery W10	from 1838.	lassical chest tomb by JB Pa Damage to kerb stone, wid nt growth. Some collapse o	ening of joints,
	DESIGNATION:	Listed Building Grade II, CA, RPG I			
	CONDITION:	Poor			
The state of the s	OCCUPANCY:	N/A			
The second second	PRIORITY:	A (New entry)			
	OWNER TYPE:	Unknown	Contact: Ma	ark Butler (LPA) 020 7361	2465
	SITE NAME:	Tomb of Thomas Fenwick, Harrow Road, Kensal Green Cemetery W10	in the ceme vegetation i	from 1834, one of the earl etery. Several elements have s infiltrating through mason s and chains have been lost	e collapsed and ry. Door is rusted
		Listed Building Grade II, CA, RPG I			
	CONDITION:	Very bad			
	OCCUPANCY:				
and the second	PRIORITY:	A (New entry)	Carata at M		
	OWNER TYPE:	Unknown	Contact: Ma	ark Butler (LPA) 020 7361	2465
AN BELOW	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery W10	urn. Relief c Erosion of c	arrara marble pedestal surn of dog at base. The monum arving, deterioration of ins	ent dates from 187 cription and heavy
I TEAM	DESIGNATION:	Listed Building Grade II, CA, RPG I	lean of mor	nument towards west. Encre	oaching vegetation.
Fight The Store in	CONDITION:	Fair			
<b>这一些一个的</b> 时代	OCCUPANCY:	N/A			
	PRIORITY:	A (New entry)			
	OWNER TYPE:	Unknown	Contact: Ma	ark Butler (LPA) 020 7361	2465
	SITE NAME:	Tomb of William Price Lewis, Harrow Road, Kensal Green Cemetery W10		one obelisk with armorial a 19. Corrosion of iron cram	
XIIIII	DESIGNATION:	Listed Building Grade II, CA, RPG I			
the well the stand	CONDITION:	Poor			
CI. of the Participant	OCCUPANCY:	N 174			
	PRIORITY:	C (New entry)			
The second se	OWNER TYPE:	Unknown	Contact: Ma	ark Butler (LPA) 020 7361	2465
				· · · ·	
The second	SITE NAME:	Kensal Green (All Souls) Cemetery		st metropolitan cemetery b John William Griffith. Cont	
	DESIGNATION:	Registered Park and Garden Grade I, also CA, I 39 LBs	of listed mo Chapel and	numents and structures at the North Colonnade are	risk.The Anglican buildings at risk an
	CONDITION:	Generally unsatisfactory with major localised problems	Managemer	ry wall has partially collapse It Plan is in place to guide f	ed. A Conservation future work to
the second second	VULNERABILITY	, ,	the cemete	ry.	
	TREND:	Declining			
a stand	OWNER TYPE:	Corporate, single owner	Contact: Pr	ncipal Heritage at Risk Adv	viser 020 7973 3000
SITE NAME:	Kensal Gr	een Cemetery			
	Conservat		CONDITION:	Very bad	
VULNERABILITY:	Low		TREND:	Improving	
CONTACT:		er (LPA) 020 7361 2465	NEW ENTRY?:	No	
NORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	D Slow deca but not ye	y; solution agreed F Repair scheme in progra and (where applicable) end use or user identifie		ABBREVI/ CA priority categories LB LPA	ATIONS Conservation Area Listed Building Local Planning Authority

- deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets.

LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

Image: Section of the section of th	X+X A			
Image: State Building Grade IP, CA, NGU II counters Fair counters Fair	N A	SITE NAME:		Matthew, Johnson-Marshall and Partners is one of the most important public buildings in Britain of the late 1950s.
concords       Fair         concords       Fair         concords       Fair         concords       Concords         concords       Concords         concords       Concords         concords       Concords         concords       Registered Park and Carden Grade II.         abs CA LIB       Concords         concords       Extensive significant problems         vacatures       High         concords       Extensive significant problems         vacatures       Accade forming circle and versue.         concords       Extensive significant problems         vacatures       Accade forming circle and versue.         concords       Extensive significant problems         vacatures       Accade forming circle and versue.         concords       Extend building Grade II (PRG III		DESIGNATION:	Listed Building Grade II*, CA, RPG II	Vacant since 1995. Mixed use scheme granted permission.
Image: Market House Waant Waa	1 Aler Aler	CONDITION:	-	year, subject to completion of Section 106 Agreement
Action       D (1)         ownerme       Company       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Commonwealth Institute       The works       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Commonwealth Institute       The works       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Common Wealth Institute       The works significant problems       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Declining       The works       Declining       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Contact: Principal Heritage at Risk Adviser 020 7973 3000       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkerme       Arcade forming circle and avenue, Encorpter Comports Common Read SVI 0       Arcade Risg 40, situated in centre of southern half of Risk contenter y designed by Renjamin Blaud. A magnifient torm the circle on the southern at forming content.         contact: Principal Heritage at Risk Adviser 020 7973 3000       Winkersee         winkersee       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkersee       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkersee       Contact: Principal Heritage at Risk Adviser 020 7973 3000         winkersee       Contact: Mark Butler (IPA) 020 7361 2465 <td< td=""><td></td><td>OCCUPANCY:</td><td>Vacant</td><td>and discharge of conditions.</td></td<>		OCCUPANCY:	Vacant	and discharge of conditions.
Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Proveneme Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Proveneme Commony         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Company         Proveneme Commany         Contact: Principal Heritage at Risk Adviser 020 7973 3000           Image: Seveneme Commony	States and an and an and a state of the stat	PRIORITY:	D (D)	
Image: Segment of the second segment segment segment of the second segment of the second segment of t		OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 020 7973 3000
Image: Segment of the second segment segment segment of the second segment of the second segment of t				
Image: Segment of the second segment segment segment of the second segment of the second segment of t		SITE NAME:	Commonwealth Institute	Garden for the Commonwealth Institute (1960-2).
also CA, 118       Concreate Extensive significant problems         also CA, 118       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Also Cancer       Provement         Contact: Principal Heritage at Risk Adviser 020 7973 3000         Also Cancer       Provement         Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Provement       Contact: Principal Heritage at R	PARTY AND AND AND		Registered Park and Garden Grade II	Outline design by architects Robert Matthew and
Concrease       Extensive significant problems wavewarm High wavewarm E       and a designed fandscape. The institute has been yearnt since 1995. Thure use as the Design Museum has been granted planning consent.         Image: State Stat	et allege and	DEDICITO MICITA	•	Johnson Marshall refined and detailed by Dame Sylvia Crowe showing a strong unity between architecture
MULERVALUTY: High       Tread:       Declining         MARKET ME       Corporate, single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Corporate, Single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000<		CONDITION:		and a designed landscape. The Institute has been vacant
Image: Declining OWERTIME       Declining OWERTIME       Corporate, single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Declining OWERTIME       Arcade forming circle and avenue, Brompton Cemetery, OWERTIME       Arcade forming circle and avenue, Brompton Cemetery, OWERTIME       Arcade, 1839-40, stuated in centre of southern half of 1830s cemetery designed by Benjamin Baud. A magnificent united composition comprising the four quadratist which or act scorecter it not circle and the avenue. The structure is suffering gradual decay owing to the later addition of a cast concrete it at confinence of the avenue. The structure is suffering gradual decay owing to the later addition of a cast concrete it not oncessitating (temporary) propping in parts. Some stone and brick cleaning was carried out in 2008.         Image: Structure Decomposition comprision cast concrete it not oncessitating (temporary) propping in parts. Some stone and brick cleaning was carried out in 2008.         Image: Structure Decomposition comprision compris comprision comprision comprision compris comp				
OWNERTING       Corporate, single owner       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: State Stat			0	granted planning consent.
STE NAME       Arcade forming circle and avenue, Brompton Cometery, Old Brompton Road SW 10       Arcade, 1839-40, situated in centre of southern half of 330s cernetery designed by Benjamin Baud. A magnificent united composition compring the four quadrants which or quadrants which or accument.         STE NAME       Listed Building Grade IIP, RPG IIP COLUMNET:       Arcade, 1839-40, situated in centre of southern half of gradual decay owing to the later addition of a cast concrete flat nor necessitaing (femporary) proping in parts. Some stone and brick cleaning was carried out in 2008.         STE NAME       Listed Building Grade III, CA contence:       Contact: Principal Heritage at Risk Adviser 020 7973 3000         STE NAME       Listed Building Grade III, CA contence:       Two mid C19 Permission granted in june 2009 for charge of use back to residential with rear extension and basement. Works have not yet commended on site and the buildings are now showing signs of neglect.         COLUMNET       Private       Contact: Mark Butler (LPA) 020 7361 2465         STE NAME       Isted Building Grade II. CA contence:       Mid C19 terrace house with attached mews arch. Planning and listed building comment were granted in june 2009 for internal aterractions. The works were part implemented and then came to a that and the proper application discussions with application was submitted in Marc 2010. Works have gain commented on site.         OCOLUMNET       Vacant moent:       Finale       Contact: Mark Butler (LPA) 020 7361 2465         Ster NAME       Current of St Augustine, Queen's Gate SW7       Mid C19 terrace house with attached mews arch. Planning and		OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 020 7973 3000
Brompton Cemetery, Old Brompton Road SW10       Bi30s cemetery designed by Benjamin Baud. A magnificent form the circle and the avenue. The structure is suffering adual decay owing to the later addition of a cast concrete flat roof necessitating (temporary) propping in parts. Some stone and brick cleaning was carried out in 2008.         Image: Concenter Wi/A moorn: C (C) concenter Wi/A moorn: C (C) concenter Wi/A moorn: C (C) concenter C (C) concenter Vi/A moorn: C (C) concenter (C) concenter (C) concenter C (C) concenter C (C) conce				
Image: Second construction of the second constructing (the port of the second construction of the	and the	SITE NAME:	Brompton Cemetery,	1830s cemetery designed by Benjamin Baud. A magnificent united composition comprising the four quadrants which
CONDITION:       Poor         CONDITION:       CONDITION:         CONDITION:       C (C)         CONDITION:       Listed Building Grade II, CA         CONDITION:       Fair         CONDITION:       Contact: Mark Butler (LPA) 020 7361 2465         CONDITION:       Poor         CONDITION:       Contact: Mark Butler (LPA) 020 7361 2465         CONDITION:       Poor         CONDITION:       Poor         CONDITION:       Poor         CONDITION	THE REPAIR OF MOUTH	DESIGNATION:	Listed Building Grade II*, RPG II*	form the circle and the avenue. The structure is suffering
Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried out in 2008.         Image: Some stone and brick cleaning was carried in 100000000000000000000000000000000000		CONDITION:	-	flat roof necessitating (temporary) propping in parts.
OWNERTIFIE       Government       Contact: Principal Heritage at Risk Adviser 020 7973 3000         Image: Strand St		OCCUPANCY:	N/A	Some stone and brick cleaning was carried out in 2008.
STE NAME:       25-26 Pembridge Square W2       Two mid C19 stucco houses in florid classical style now joined together to form a hotel. Permission granted in june 2009 for change of use back to residential with rear extension and basement. Works have not yet commenced on site and the buildings are now showing signs of neglect.         Image: State Augustion of the state of the stat	- Standard	PRIORITY:	С (С)	
Image: State of the state		OWNER TYPE:	Government	Contact: Principal Heritage at Risk Adviser 020 7973 3000
Image: State of the state				
Designations:       Listed Duilding Grade II, CA       on site and the buildings are now showing signs of neglect.         CONDITION:       Fair       CCUUPANCY:       Part occupied         PUORTY:       D (B)       Contact: Mark Butler (LPA) 020 7361 2465         Image: Condition in the state of the		SITE NAME:	25-26 Pembridge Square W2	joined together to form a hotel. Permission granted in June 2009 for change of use back to residential with rear
CONDITION:       Fair         OCCUPANCY:       Part occupied         PROBINI:       D (B)         OWNERT/PE       Private         CONDITION:       Fair occupied         PROBIN:       D (B)         OWNERT/PE       Private         CONDITION:       Fair         OCEUPANCY:       D (B)         OWNERT/PE       Private         Contact: Mark Butler (LPA) 020 7361 2465         Image: Control of the property sold After pre-application         DESIGNATION:       Listed Building Grade II, CA         CONDITION:       POOR         OCCUPANCY:       Vacant         PRORTY:       F (C)         OCCUPANCY:       Vacant         PRORTY:       F (C)         OWNERT/PE       Private         Contact: Mark Butler (LPA) 020 7361 2465            Image: Contact: Mark Butler (LPA) 020 7361 2465 <td></td> <td>DESIGNATION:</td> <td>Listed Building Grade II, CA</td> <td></td>		DESIGNATION:	Listed Building Grade II, CA	
Image: PRIORITY:       D (B) WINERTIPE       Contact: Mark Butler (LPA) 020 7361 2465         Image: PRIORITY:       D (B) WINERTIPE       Contact: Mark Butler (LPA) 020 7361 2465         Image: PRIORITY:       B, Queen's Gate Place SW7       Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in lune 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image:			Fair	of site and the buildings are now showing signs of neglect.
Image: PRIORITY:       D (B) WINERTIPE       Contact: Mark Butler (LPA) 020 7361 2465         Image: PRIORITY:       D (B) WINERTIPE       Contact: Mark Butler (LPA) 020 7361 2465         Image: PRIORITY:       B, Queen's Gate Place SW7       Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in lune 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Private       Contact: Mark Butler (LPA) 020 7361 2465         Image:		CONDITION:	i ali	
SITE NAME       I8, Queen's Gate Place SW7         Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application occupancy: Vacant         DESIGNATION:       Listed Building Grade II, CA CONDITION:       Poor         OCCUPANCY:       Vacant       Vacant         PRORITY:       F (C)       OWNER TYPE         OWNER TYPE       Private       Contact: Mark Butler (LPA) 020 7361 2465         STE NAME:       Listed Place of Worship Grade II*, CA CONDITION:       Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond facade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.				
Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner; an application was submitted in March 2010. Works have again commenced on site.         PRORITY:       F (C)         OWNERTYPE       Private         STE NAME:       Church of St Augustine, Queen's Gate SW7         Designation:       Listed Place of Worship Grade II*, CA         Designation:       Extended place of Worship Grade II*, CA         Middle version:       Designation:         Designation:       Listed Place of Worship Grade II*, CA         Middle version:       Poor         Output:       Pice Private	<b>MITTER</b>	OCCUPANCY:	Part occupied	
Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner; an application was submitted in March 2010. Works have again commenced on site.         PRORITY:       F (C)         OWNERTYPE       Private         STE NAME:       Church of St Augustine, Queen's Gate SW7         Designation:       Listed Place of Worship Grade II*, CA         Designation:       Extended place of Worship Grade II*, CA         Middle version:       Designation:         Designation:       Listed Place of Worship Grade II*, CA         Middle version:       Poor         Output:       Pice Private		OCCUPANCY: PRIORITY:	Part occupied D (B)	Contact: Mark Butler (LPA) 020 7361 2465
Designation:       Listed building Grade II, CA       a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.         PRORITY:       F (C)         OWNER TYPE       Private         Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond facade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.		OCCUPANCY: PRIORITY:	Part occupied D (B)	Contact: Mark Butler (LPA) 020 7361 2465
CONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY:       F (C)         OWNER TYPE       Private         SITE NAME:       Church of St Augustine, Queen's Gate SW7         SITE NAME:       Listed Place of Worship Grade II*, CA CONDITION:         DESIGNATION:       Listed Place of Worship Grade II*, CA CONDITION:         PRORITY:       F (F)		OCCUPANCY: PRIORITY: OWNER TYPE:	Part occupied D (B) Private	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions.
PRIORITY:       F (C)         OWNER TYPE       Private         Contact: Mark Butler (LPA) 020 7361 2465         Image: Stell NAME       Church of St Augustine, Queen's Gate SW7         Image: Stell NAME       Church of St Augustine, Queen's Gate SW7         Image: Stell NAME       Church of St Augustine, Queen's Gate SW7         Image: Stell NAME       Listed Place of Worship Grade II*, CA CONDITION:         Image: Designation:       Listed Place of Worship Grade II*, CA CONDITION:         Image: Private       Priorition:         PRIORITY:       F (F)		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME:	Part occupied D (B) Private I8, Queen's Gate Place SW7	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to
OWNERTYPE       Private       Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image: Contact: Mark Butler (LPA) 020 7361 2465       Image: Contact: Mark Butler (LPA) 020 7361 2465         Image:		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted
SITE NAME:       Church of St Augustine, Queen's Gate SW7       Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted
Queen's Gate SW7       style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.         DESIGNATION:       Listed Place of Worship Grade II*, CA         No.       PRIORITY:         F (F)		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C)	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.
Queen's Gate SW7       style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.         DESIGNATION:       Listed Place of Worship Grade II*, CA         No.       PRIORITY:         F (F)		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C)	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.
DESIGNATION:       Listed Place of Worship Grade II*, CA       window. Large derelict site adjacent to north. Ongoing grant aid towards high level works.         CONDITION:       Poor       grant aid towards high level works.		OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C)	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site.
PRIORITY: F (F)		OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C) Private Church of St Augustine,	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site. Contact: Mark Butler (LPA) 020 7361 2465 Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General
		OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C) Private Church of St Augustine, Queen's Gate SW7	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site. Contact: Mark Butler (LPA) 020 7361 2465 Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing
OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 020 7973 3000		OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C) Private Church of St Augustine, Queen's Gate SW7 Listed Place of Worship Grade II*, CA	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site. Contact: Mark Butler (LPA) 020 7361 2465 Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing
		OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Part occupied D (B) Private I8, Queen's Gate Place SW7 Listed Building Grade II, CA Poor Vacant F (C) Private Church of St Augustine, Queen's Gate SW7 Listed Place of Worship Grade II*, CA Poor F (F)	Mid C19 terrace house with attached mews arch. Planning and listed building consent were granted in June 2008 for internal alterations and rear extensions. The works were part implemented and then came to a halt and the property sold. After pre-application discussions with new owner, an application was submitted in March 2010. Works have again commenced on site. Contact: Mark Butler (LPA) 020 7361 2465 Large church designed by W Butterfield in the Gothic style. Constructed from yellow brick with black and red and stone bands. Rich polychrome brick decoration throughout. Part of the building used as offices. General wear and tear beyond façade with partly boarded east window. Large derelict site adjacent to north. Ongoing



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

83

#### HERITAGE AT RISK 2012 / LONDON / KENSINGTON AND CHELSEA / KINGSTON UPON THAMES / LAMBETH

	SITE NAME:	Church of St John the Baptist, Holland Road, Kensington, W14	Church dating from 1874-1911 by J Brooks and JS Adkins architects. Early English Style with large rose window at west end and highly decorated baptistry. English Heritage grant offered for extensive repairs to roofs, high level masonry and rainwater goods. Works yet to start on site.
	DESIGNATION:	Listed Place of Worship Grade II*	
South A MAR	CONDITION:	Poor	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
KINGSTON UPON TH	AMES		
	SITE NAME:	Kingston Telephone Exchange, Ashdown Road, Kingston upon Thames	Purpose built telephone exchange. Built in 1907 and opened in 1908. Arts and Crafts style in asymmetrical plan. Works to make the building secure and weathertight
	DESIGNATION	Listed Building Grade II	completed in 2008/2009. Building located within an area identified for comprehensive redevelopment as set out in
	CONDITION:	Fair	the K+20 Area Action Plan.
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: Andrew Lynch (LPA) 020 8547 5376
Alex	SITE NAME:	Former Head Post Office, 42 Eden Street, Kingsten waar Thamas	Post office built in 1875. Three storeys in red brick with stone dressings. Works for internal improvements and weather proofing were carried out in 2008/2009 in
LA IN		Kingston upon Thames	preparation for leasing out. However, the reuse of the
		Listed Building Grade II	building has been delayed due to wider considerations
	CONDITION:	Fair	relating to the Council's aspirations for town centre renewal as set out in the K+20 Area Action Plan.
I DORO DORONO	OCCUPANCY:		renewal as set out in the K+20 Area Action Fian.
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Andrew Lynch (LPA) 020 8547 5376
	SITE NAME:	Lambeth uncovered coal store including tower and attached tunnels, Portsmouth Road, Surbiton	Uncovered coal store with tower and attached underground tunnels. Built 1851-1852 to the design of James Simpson in a Romanesque style for the
	DESIGNATION:	Listed Building Grade II, CA	Lambeth Waterworks.Vacant for many years. No works have been carried out recently.
222201	CONDITION:	Poor	Local Authority to instigate negotiations with owner.
	OCCUPANCY:	Vacant	, 5 5
and a second	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Andrew Lynch (LPA) 020 8547 5376
LAMBETH			
	SITE NAME:	Beaufoy Institute,	Educational building of 1907 (architect FA Powell).
TT TT		39 Black Prince Road, Vauxhall SEI	Brick and terracotta facade with free Baroque motifs. 1930 laboratory wing to the side and assembly hall at the rear.Vacated by Lilian Baylis Secondary School in
	DESIGNATION:	Listed Building Grade II, CA	1999. Sold by London Borough of Lambeth, subject
	CONDITION:	Fair	to acceptable planning proposals.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	PRIORITY:	C (C) Local authority	Contact: Elizabeth Martin (LPA) 020 7926 1213
	PRIORITY: OWNER TYPE:	Local authority	
	PRIORITY: OWNER TYPE: SITE NAME:	Local authority 136 and 138 Brixton Hill SW2	Contact: Elizabeth Martin (LPA) 020 7926 1213 Early-mid C19. Unoccupied, windows boarded up and scaffolding has been erected.
	PRIORITY: OWNER TYPE: SITE NAME:	Local authority	Early-mid C19. Unoccupied, windows boarded
	PRIORITY: OWNER TYPE: SITE NAME:	Local authority 136 and 138 Brixton Hill SW2	Early-mid C19. Unoccupied, windows boarded
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Local authority 136 and 138 Brixton Hill SW2 Listed Building Grade II, CA Poor	Early-mid C19. Unoccupied, windows boarded
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Local authority 136 and 138 Brixton Hill SW2 Listed Building Grade II, CA Poor	Early-mid C19. Unoccupied, windows boarded
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Local authority I 36 and I 38 Brixton Hill SW2 Listed Building Grade II, CA Poor Vacant	Early-mid C19. Unoccupied, windows boarded

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

TER	SITE NAME:	124 and 134 Camberwell New Road SE5	Two terrace houses part of an early-mid C19 terrace. Sold by the local planning authority to a private buyer at auction in March 2011. Enforcement action pending
	DESIGNATION:	Listed Building Grade II, CA	for unauthorised internal works and paving over of front garden/removal of railings. Works on site but building
	CONDITION:	Fair	still vacant.
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Private	Contact: Elizabeth Martin (LPA) 020 7926 1213
STORE A	SITE NAME:	Shelter, Denmark Hill, Ruskin Park SE5	Late C18 screen and flanking walls of house that stood on the site. Funding is being sought by the Local Authority for future refurbishment and through access.
	DESIGNATION:	Listed Building Grade II, RPG II	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	B (B)	
	OWNER TYPE:	Local authority	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Raleigh Hall, I and 3 Effra Road SW2	Substantial pair of villas built 1824. Black Cultural Archives have started the restoration of the building as a national black heritage centre with grant from the Heritage Lottery
	DESIGNATION:	Listed Building Grade II, CA	Fund.The centre is expected to open in 2013.
	CONDITION:	Very bad	
TAAMAA.	OCCUPANCY:	Vacant	
	PRIORITY:	E (A)	
	OWNER TYPE:	Local authority	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Dorchester Court, Herne Hill SE24	Eight blocks with 96 flats around a central landscaped courtyard. 1933-4 by Leslie H Kemp and Frederick E Tasker. Structural problems with balconies and general external
	DESIGNATION:	Listed Building Grade II	deterioration. Discussions are ongoing regarding a comprehensive programme of refurbishment.
THE DRY AND IN THE AVE	CONDITION:	Poor	
	OCCUPANCY:	I I I I I I I I I I I I I I I I I I I	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Private	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Gentlemen's public convenience, Kennington Cross SEI I	Underground gentlemen's public lavatory with ornate railings enclosing stairway. Listing includes elegant flue ventilator pipe and adjacent C19 bollards and horse
	DESIGNATION:	Listed Building Grade II, CA	trough. Lavatories unused since the 1980s. Some repairs
TOLETE CLOSED	CONDITION:	Fair	A local group is considering use options.
Chan Shan	OCCUPANCY:	N/A	
The second	PRIORITY:	С (С)	
	OWNER TYPE:		Contact: Elizabeth Martin (LPA) 020 7926 1213
FUR SALE	SITE NAME:	Off licence attached to the Old Red Lion public house, 44 Kennington Park Road SEI I	Tudorbethan style off-licence, built circa I 929. Vacant. Damage including broken window pane. Planning permission for redevelopment with facade retention granted in 2004 but has expired.
KINGSBURY 020 7103 2529	DESIGNATION:	Listed Building Grade II	The building is for sale.
	CONDITION:	Poor	~
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Elizabeth Martin (LPA) 020 7926 1213

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

And a second sec			
	SITE NAME:	Walls, railings and gates to Church of St Mary, Lambeth Road SEI	Mid C19 ragstone walls and ironwork. In a partial state of collapse. Urgent action needed to secure repair and restoration. English Heritage are in
	DESIGNATION:	Listed Building Grade II, CA	discussions with the owner.
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:		Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Lilian Baylis School, Lollard Street SEI I	Comprehensive school. Designed 1960 and built by the Architects' Co-Partnership for the London County Council. Sold by London Borough of Lambeth. Planning application for part of the site is being considered.
	DESIGNATION:	Listed Building Grade II	application for part of the site is being considered.
RECEPTION	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Old Fire Station (South London Theatre), 2A Norwood High Street SE27	Former fire station in use as South London Theatre for many years, leased from London Borough of Lambeth. There has been internal water damage and significant roof maging an maging funding is currently being purged.
	DESIGNATION:	Listed Building Grade II, CA	repairs are required. Funding is currently being pursued by the theatre for internal reconfiguration and repairs.
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:	Local authority	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Catacombs beneath the	Catacombs circa 1837; cemetery laid out circa 1837 by
		Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored.
	DESIGNATION	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before
	DESIGNATION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II*	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored.
	DESIGNATION: CONDITION: OCCUPANCY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored.
MERSE MARKEN	CONDITION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored.
NUMBER OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER O	CONDITION: OCCUPANCY: PRIORITY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B)	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011.
	CONDITION: OCCUPANCY: PRIORITY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored.
	CONDITION: OCCUPANCY: PRIORITY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B)	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department.
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: STTE NAME: STTE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: STTE NAME: STTE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry)	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Comb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred. Plans for restoration are
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Local authority Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II*, CA, RPG II* Very bad	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred. Plans for restoration are
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Comb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II*, CA, RPG II* Very bad	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred. Plans for restoration are
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II*, CA, RPG II* Very bad N/A B (A)	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred. Plans for restoration are
<image/>	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Very bad N/A B (B) Local authority West Norwood fire station, 445 Norwood Road, Norwood SE27 Listed Building Grade II Good Vacant E (New entry) Local authority Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II*, CA, RPG II* Very bad N/A B (A)	Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs and funding options are being explored. Application to retain temporary roof granted 2011. Contact: Elizabeth Martin (LPA) 020 7926 1213 Fire station with flats above. Built 1914-15 by London County Council Architects' Department. Planning permission granted for new station elsewhere in the borough. Future use is uncertain. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. The roof is broken, door missing, slabs of granite broken and water ingress has occurred. Plans for restoration are advanced, and it is hoped works will start during 2012.

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

86

	SITE NAME:	Tomb of C Auffrey and E O'Gorman, Norwood Road, West Norwood Memorial Park SE27	Pedestal tomb dating from 1893 with carved wreaths, faces and anchor. Leaning significantly.
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:		Contact: Elizabeth Martin (LPA) 020 7926 1213
AND A STATE OF A			
	SITE NAME:	Tomb of Captain John Wimble, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1851 with finely carved reliefs showing ships at sea. The stone ship surmounting the tomb is subject to movement.
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Fair	
A CONTRACTOR OF A CONTRACTOR OFTA CONT	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Tomb of Christopher Gabriel, Norwood Road,	Chest tomb in Portland stone dating from 1873 with carvings by Kelsey. Cracking to stone panels on side
		West Norwood Memorial Park SE27	of tomb.
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
A DESCRIPTION OF THE	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Tomb of Elizabeth King, Norwood Road, West Norwood Memorial Park SE27	Statue of an angel mounted against a rough headstone over rough base, dating from 1922. In the style of the 1878 Oneto Monument by Giulio Monteverge in Genoa.
Statement and a statement of the stateme		Listed Building Grade II, CA, RPG II*	Statue and headstone are leaning significantly.
	DESIGNATION:		
	DESIGNATION: CONDITION:	Fair	
		Fair	
	CONDITION:	Fair	
	CONDITION: OCCUPANCY:	Fair N/A A (New entry)	Contact: Elizabeth Martin (LPA) 020 7926 1213
	CONDITION: OCCUPANCY: PRIORITY:	Fair N/A A (New entry)	Contact: Elizabeth Martin (LPA) 020 7926 1213
	CONDITION: OCCUPANCY: PRIORITY:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II*	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry)	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry)	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage.
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pedestal monument above a vault in the Egyptian Revival style, circa 1842. Overgrown with vegetation, plinth broken
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pedestal monument above a vault in the Egyptian Revival style, circa 1842. Overgrown with vegetation, plinth broken
	CONDITION: PRIORITY: OWNERTYPE: OWNERTYPE: SITE NAME: CONDITION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pedestal monument above a vault in the Egyptian Revival style, circa 1842. Overgrown with vegetation, plinth broken
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor Listed Building Grade II, CA, RPG II*	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pedestal monument above a vault in the Egyptian Revival style, circa 1842. Overgrown with vegetation, plinth broken
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION:	Fair N/A A (New entry) Unknown Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A Listed Building Grade II, CA, RPG II*	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles missing and cementitious repairs causing further damage. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pedestal monument above a vault in the Egyptian Revival style, circa 1842. Overgrown with vegetation, plinth broken

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

CONDITION: OCCUPANCY: PRIORITY:	Tomb of James Baldwin Brown, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A A (New entry) Unknown	Celtic cross on pedestal faced in terracotta in Romanesque/Gothic style, dating from 1885. Leaning heavily and with side tablet disengaged and pinnacle tip missing. Contact: Elizabeth Martin (LPA) 020 7926 1213
CONDITION: OCCUPANCY: PRIORITY:	Tomb of James Kershaw, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A C (New entry) Unknown	Chest tomb dating from 1864 in Gothic style with elaborate carving. Designed by Alfred Waterhouse commemorating the MP James Kershaw. Structural ironwork corroding, causing splitting of stone. Railings affected by movement to plinth. Contact: Elizabeth Martin (LPA) 020 7926 1213
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	and family, Norwood Road, West Norwood Memorial Park SE27 Listed Building Grade II, CA, RPG II* Poor N/A C (New entry)	Tomb in the style of a small Greek temple, dating from 1904. Movement evident to columns and base. Contact: Elizabeth Martin (LPA) 020 7926 1213
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Fair N/A A (New entry)	Monument dating from 1908 within the Greek Burial Ground. Comprises stepped granite base with sarcophagus surmounted by white marble female figure with flowing robes and veiled head. Figure is subject to movement and is now close to edge of sarcophagus. Contact: Elizabeth Martin (LPA) 020 7926 1213
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Fair N/A A (New entry)	Obelisk monument dating from 1861 by Anderson and McKenzie of Aberdeen with incised fret pattern. Leaning significantly. Contact: Elizabeth Martin (LPA) 020 7926 1213
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Poor N/A C (New entry)	Pink granite table tomb dating from circa 1899 within the Greek Burial Ground. Invasive vegetation is causing damage to the stepped base and the pillars surrounding the central pedestal. Contact: Elizabeth Martin (LPA) 020 7926 1213

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Tomb of Mrs Alice Moffatt, Norwood Road, West Norwood Memorial Park SE27	An arcaded chest tomb, circa I 847. The columns and top slab have been lost, leaving the structural rods exposed.
	DESIGNIATION	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Very bad	
	OCCUPANCY:	,	
	PRIORITY:	A (A)	
		Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
a data	SITE NAME:	Tomb of Thomas De La Garde Grissell, Norwood Road, West Norwood Memorial Park SE27	Chest tomb, circa 1847. Cast iron, stucco and pink granite. Plinth broken, and parts exposed.
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Tomb of William Grane, Norwood Road, West Norwood Memorial Park SE27	Tomb dating from 1856, noted in listing description as having pink granite cross with foliated arms and vine trails to stem. This cross is missing and there is clear evidence of movement to the base of monument.
	DESIGNATION:	Listed Building Grade II, CA, RPG II*	of movement to the base of monument.
A water and	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Tomb of XE Balli Family, Norwood Road, West Norwood Memorial Park SE27	lonic temple mausoleum dating from late C19 within the Greek Burial Ground. Evidence of movement to entablature and collapse of steps.
101	DESIGNATION:	Listed Building Grade II, CA, RPG II*	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Water tower to former Lambeth Workhouse, Renfrew Road SELL	1877 water tower built in Venetian Gothic style. Vacant. Application for conversion to a residential dwelling plus extension has been granted.
	DESIGNATION:	Listed Building Grade II, CA	Works are due to start.
TITI	CONDITION:	Poor	
A CONTRACT OF	OCCUPANCY:		
II	PRIORITY:	D (C)	
	OWNER TYPE:	D	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	St Michael's Convent (Formerly Park Hill)	A rare example of a C19 villa garden in south London. Designed by JB Papworth for William Leaf in the mid C19 and improved by Robert Marnock for Sir Henry Tate in the
	DESIGNATION:	also CA, 10 LBs	late C19. The garden is deteriorating in parts. Clearance work was undertaken to the lake and surrounding trees in winter 2010-2011 and restoration of the terrace wall is
	CONDITION:	Generally satisfactory but with significant localised problems	planned.The Pulhamite grotto (grade II listed building) has been repaired and was removed from the Heritage at Risk
	VULNERABILITY		Register in 2011.
	TREND:		
	OWNER TYPE:	Private, multiple owners	Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	SITE NAME:	ABC Cinema, Streatham High Road, Streatham SW16	Art Deco style cinema built in 1938 to the design of WR Glen. Facade and double height foyer are of notable quality. Repair work completed, awaiting new use.
A TOTAL DATE OF	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Good	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Monument to George Abell, St Leonard's churchyard, Streatham High Road, Streatham SW16	Chest tomb of circa I 826 commemorating George and Elizabeth Abell. Slab of Portland limestone with curved-edged top, has broken and the plinth is in a bad condition.
2900 -	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Very bad	
Real Property in the second seco	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Unknown	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Monument to Joseph Hay, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, dated 1808 in Coade Stone by Coade and Sealy. Railings are broken and in poor state of repair.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:		Contact: Elizabeth Martin (LPA) 020 7926 1213
State Man 110 Balling and Income			
	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa 1808 by Coade and Sealy.The Coade Stone is in an advanced state of decay.
		St Leonards churchyard, Streatham High Road, Streatham SW16	
		St Leonards churchyard, Streatham High Road,	
	DESIGNATION:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor	
	DESIGNATION:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A)	Sealy.The Coade Stone is in an advanced state of decay.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A)	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: DESIGNATION:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8 Listed Building Grade II, CA Fair	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8 Listed Building Grade II, CA Fair	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8 Listed Building Grade II, CA Fair Vacant C (C)	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8 Listed Building Grade II, CA Fair Vacant C (C)	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012).
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	St Leonards churchyard, Streatham High Road, Streatham SW16 Listed Building Grade II Poor N/A A (A) Unknown 335-337 Wandsworth Road SW8 Listed Building Grade II, CA Fair Vacant C (C) Private Wall on the south side of St John with All Saints' churchyard,	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012). Contact: Elizabeth Martin (LPA) 020 7926 1213 Early C19 stock brick walls, spalled and cracked
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	St Leonards churchyard,   Streatham High Road,   Streatham SW16   Listed Building Grade II   Poor   N/A   A (A)   Unknown   335-337 Wandsworth Road SW8   Listed Building Grade II, CA   Fair   Vacant   C (C)   Private   Wall on the south side of St John with All Saints' churchyard, Waterloo Road SE1	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012). Contact: Elizabeth Martin (LPA) 020 7926 1213 Early C19 stock brick walls, spalled and cracked
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	St Leonards churchyard,         Streatham High Road,         Streatham SW16         Listed Building Grade II         Poor         N/A         A (A)         Unknown         335-337 Wandsworth Road SW8         Listed Building Grade II, CA         Fair         Vacant         C (C)         Private         Wall on the south side of St John with All Saints' churchyard, Waterloo Road SE1         Listed Building Grade II, CA         Poor	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor: Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012). Contact: Elizabeth Martin (LPA) 020 7926 1213 Early C19 stock brick walls, spalled and cracked
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: OWNER TYPE: SITE NAME: CONDITION:	St Leonards churchyard,         Streatham High Road,         Streatham SW16         Listed Building Grade II         Poor         N/A         A (A)         Unknown         335-337 Wandsworth Road SW8         Listed Building Grade II, CA         Fair         Vacant         C (C)         Private         Wall on the south side of St John with All Saints' churchyard, Waterloo Road SE1         Listed Building Grade II, CA         Poor	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012). Contact: Elizabeth Martin (LPA) 020 7926 1213 Early C19 stock brick walls, spalled and cracked
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: SITE NAME: CONDITION: CONDITION: CONDITION: CONDITION:	St Leonards churchyard,         Streatham High Road,         Streatham SW16         Listed Building Grade II         Poor         N/A         A (A)         Unknown         335-337 Wandsworth Road SW8         Listed Building Grade II, CA         Fair         Vacant         C (C)         Private         Wall on the south side of St John with All Saints' churchyard, Waterloo Road SE1         Listed Building Grade II, CA         Poor	Sealy. The Coade Stone is in an advanced state of decay. Contact: Elizabeth Martin (LPA) 020 7926 1213 Pair of Regency houses, formerly undertaker's premises. Boarded up at ground floor. Building vulnerable and at risk. Approval for conversion granted but poorly implemented, enforcement case by the Local Authority is pending. Building is for sale (spring 2012). Contact: Elizabeth Martin (LPA) 020 7926 1213 Early C19 stock brick walls, spalled and cracked

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

	CONDITION: OCCUPANCY: PRIORITY:	The Clapham Orangery, Worsopp Drive SW4 Listed Building Grade II Fair N/A C (C) Local authority	Orangery built in 1793 to the design of William Burgh, in a Palladian style. It stood in the grounds of Thornton House, demolished in the 1940s. Now standing in the middle of a housing estate. Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Trinity Congregational Church, St Matthews Road, Brixton SW2 Listed Place of Worship Grade II Poor C (C) Religious organisation	Classical Chapel built 1828 of stock brick with stucco entablature with original pews. There are structural problems with the front elevation. Contact: Principal Heritage at Risk Adviser 020 7973 3000
LEWISHAM			
	SITE NAME: DESIGNATION: CONDITION:	Louise House, Dartmouth Road, Lewisham SE23 Listed Building Grade II Fair	Former Girls' Industrial Home, built in 1891, and surviving former laundry block to rear. Some essential repairs have been carried out and the building is being used temporarily as offices while a new owner is sought.
	PRIORITY:	Occupied E (E) Local authority	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Ramp at Deptford Railway Station, Deptford High Street SE8 Listed Building Grade II, CA Poor N/A D (D)	Built 1856 to the design of engineer Colonel Lordmann. A dog-leg ramp formed by a series of brick arches rising up from Deptford High Street to the level of the tracks. Listed building consent and planning permission granted for redevelopment of enclosed square, repair of ramp and occupation of arches. Anticipated start of work on site in 2012/13.
		Company	Contact: Regina Jaszinski (LPA) 020 8314 9112
	CONDITION: OCCUPANCY:		House, shop and bakehouse built 1791-2 for Thomas Palmer, baker. Further modifications made 1801-2 and 1822-3. C19 shop front in disrepair. Bake house demolished. Some repairs have been carried out to make the building wind and weather-tight, and internally it has remained gutted and unoccupied. The owner is currently seeking listed building consent for internal repairs and refurbishment.
	PRIORITY: OWNER TYPE:	C (A) Private	Contact: Regina Jaszinski (LPA) 020 8314 9112
	OWNER TTPE:	- Trivate	Contact regina jaszinski (LLA) 020 0317 /112
	SITE NAME: DESIGNATION:	Beckenham Place, Foxgrove Road, Beckenham Place Park BR3 Listed Building Grade II*, CA Fair	Mansion built circa 1773, situated within former park land, now golf course. The local authority is actively seeking new owners and uses that could secure the long-term future of the building. Some emergency repairs were carried out in 2012 with grant from English Heritage.

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### HERITAGE AT RISK 2012 / LONDON / LEWISHAM

	SITE NAME:	Stable block and garden walls to Beckenham Place, Beckenham Hill Road SE26	Late C18 stable block. Severely damaged by fire in 2011. Remaining structure has been stabilised and protected, while necessary consents and funding
	DESIGNATION:	Listed Building Grade II	are sought for reconstruction.
	CONDITION:	Very bad	
	OCCUPANCY:		
Danne (	PRIORITY:	A (C)	
and the second	OWNER TYPE:	Local authority	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Old Swimming Baths, Ladywell Road SEI3	Public baths, consisting of first and second class swimming pools constructed in 1884. Designed in the Gothic style by Wilson and Son and Thomas Aldwinkle. Unused and deteriorating condition. A conservation management plan
	DESIGNATION:	Listed Building Grade II, CA	has recently been completed, essential repair works are
	CONDITION:	Poor	being commissioned, and negotiations are taking place
	OCCUPANCY:	Vacant	with a potential new owner.
	PRIORITY:	D (D)	
	OWNER TYPE:	Local authority	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old Churchyard SE3	A stone chest tomb from the middle of the C18 commemorates Captain Limeburner of the Royal Navy and his wife The south side has lost its central panel
ľ	DESIGNATION:	Listed Building Grade II, CA	and the angle balusters are displaced.
	CONDITION:	Very bad	
Chille Property	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard SE3	An elaborate Rococo tomb from 1769 in Portland stone and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
		Lee Terrace, St Margaret's Old Churchyard SE3	and marble. Despite previous repairs, the monument is in
		Lee Terrace,	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry)	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry)	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace,	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: SITE NAME: CONDITION: CONDITION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A A (New entry)	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II*, CAVery badN/AA (New entry)Religious organisationTomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II, CAPoorN/AA (New entry)	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II*, CAVery badN/AA (New entry)Religious organisationTomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II, CAPoorN/AA (New entry)	and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A A (New entry) Religious organisation Tomb of John Crutchley, Lee Terrace,	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.</li> <li>Contact: Regina Jaszinski (LPA) 020 8314 9112</li> <li>Raised ledger stone from 1727. Ground subsidence has caused some sinking and some movement to the ledger</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II*, CAVery badN/AA (New entry)Religious organisationTomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3Listed Building Grade II, CAPoorN/AA (New entry)Religious organisationTomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.</li> <li>Contact: Regina Jaszinski (LPA) 020 8314 9112</li> <li>Raised ledger stone from 1727. Ground subsidence has caused some sinking and some movement to the ledger</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A A (New entry) Religious organisation Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.</li> <li>Contact: Regina Jaszinski (LPA) 020 8314 9112</li> <li>Raised ledger stone from 1727. Ground subsidence has caused some sinking and some movement to the ledger</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: SITE NAME: CONDITION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A A (New entry) Religious organisation Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.</li> <li>Contact: Regina Jaszinski (LPA) 020 8314 9112</li> <li>Raised ledger stone from 1727. Ground subsidence has caused some sinking and some movement to the ledger</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: CONDITION: CONDITION: CONDITION:	Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II*, CA Very bad N/A A (New entry) Religious organisation Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A A (New entry) Religious organisation Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor Listed Building Grade II, CA Poor N/A	<ul> <li>and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from where vegetation grows and some collapse.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The monument has lost its railings, back plates and inscription panels and vegetation growth is further damaging its condition.</li> <li>Contact: Regina Jaszinski (LPA) 020 8314 9112</li> <li>Raised ledger stone from 1727. Ground subsidence has caused some sinking and some movement to the ledger</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / LEWISHAM

IN AS	SITE NAME:	Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SE3	Stone chest tomb erected in 1767. Badly damaged by vegetation through open joints.
	DESIGNATION:	Listed Building Grade II, CA	
Contractor	CONDITION:	Poor	
	OCCUPANCY:	N/A	
Call and the second second	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Lord Dacre, Lee Terrace, St Margaret's Old Churchyard SE3	This composite urn monument to Lord Dacre dates from 1794. All elements now lie disassembled on the ground. The monument needs urgent attention to avoid further damage or loss of its components.
1-57 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	DESIGNATION:	Listed Building Grade II, CA	damage or loss of its components.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Rev.Thomas Negus, Lee Terrace, St Margaret's Old Churchyard SE3	Chest tomb from 1765, badly damaged from vegetation which has infiltrated through open joints and cracked ledger slab. One angle baluster has been lost and there
	DESIGNATION:	Listed Building Grade II, CA	is a risk of further collapse.
	CONDITION:	Very bad	
Carlos 1 1 1	OCCUPANCY:	N/A	
and the second	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Thomas Butler, Lee Terrace, St Margaret's Old Churchyard SE3	Chest tomb from 1733. The panels on both sides and on one end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration.
	DESIGNATION:	Listed Building Grade II, CA	
P GEAL	CONDITION:	Very bad	
		N/A	
A DANA	OCCUPANCY:		
ARE	OCCUPANCY: PRIORITY:	A (New entry)	
	PRIORITY:	A (New entry) Religious organisation	Contact: Regina Jaszinski (LPA) 020 8314 9112
	PRIORITY:	Religious organisation Tomb of Tredway, Lee Terrace,	Contact: Regina Jaszinski (LPA) 020 8314 9112 A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken.
	PRIORITY: OWNER TYPE: SITE NAME:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus.
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus.
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus.
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus.
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus.
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A C (New entry)	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken. Contact: Regina Jaszinski (LPA) 020 8314 9112 Coade stone chest tomb from late C18.The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. In need of
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A C (New entry) Religious organisation Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE3	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken. Contact: Regina Jaszinski (LPA) 020 8314 9112 Coade stone chest tomb from late C18.The loss of the ledger slab has allowed a tree to take root inside
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Religious organisation Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A C (New entry) Religious organisation Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE3	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken. Contact: Regina Jaszinski (LPA) 020 8314 9112 Coade stone chest tomb from late C18.The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. In need of
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Religious organisation  Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A C (New entry) Religious organisation  Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Fair	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken. Contact: Regina Jaszinski (LPA) 020 8314 9112 Coade stone chest tomb from late C18.The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. In need of
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Religious organisation  Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Poor N/A C (New entry) Religious organisation  Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE3 Listed Building Grade II, CA Fair	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. End panel of the upper part is broken. Contact: Regina Jaszinski (LPA) 020 8314 9112 Coade stone chest tomb from late C18.The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. In need of

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

T	SITE NAME:	25 Tanners Hill, Deptford SE8	workshop.Th currently sta	use, until recently used as a cycle shop ne business closed in 2009 and the buil- nds empty. The building has suffered fro	ding m
		Listed Building Grade II, CA	ingress. Planr	ck of maintenance, under-use and water ning and listed building consent applicati	ions
AND THAT	CONDITION:	Poor	have now be	en approved for residential conversion.	
The de la	OCCUPANCY:				
FL	PRIORITY:	D (C)	Contact: Dog	ing lagringhi (LRA) 020 8214 8112	
	OWNER TYPE:	Private	Contact: Reg	jina Jaszinski (LPA) 020 8314 9112	
ITE NAME:	Deptford	High Street			
esignation:	Conservat	ion Area	CONDITION:	Very bad	
ULNERABILITY:	Medium		TREND:	Improving	
ONTACT:	Philip Asht	ford (LPA) 020 8314 8533	NEW ENTRY?:	No	
MERTON					
	SITE NAME:	Garden wall enclosing		CI6 to CI7 and later. Some sections a	
		four sides of playing field,	eroded, mair	ily in areas subjected to inappropriate p	bast
		Church Lane, Merton Park		wall has fallen into further disrepair and been demolished for safety reasons with	
	DESIGNATION:	Listed Building Grade II, CA	intention tha	t it will be rebuilt. Damaging vegetation	has
	CONDITION:	Fair		ed and a comprehensive survey and	
	OCCUPANCY:	N/A	specification	for repairs is being carried out.	
	PRIORITY:	B (C)			
	OWNER TYPE:	Local authority	Contact: Jill T	yndale (LPA) 0208 545 3839	
THE ALL DE ALL	SITE NAME:	Tomb of Thomas Stanley,	Table tomb (	over large podium erected in the early	
I COLUMN I	SITE INALIE.	Church Road, Mitcham,		severely damaged by vegetation.	
La Linder and La		St Peter and St Paul's Churchyard			
	DESIGNATION:	Listed Building Grade II, CA			
Contraction of the second	CONDITION:	Poor			
Same and	OCCUPANCY:	N/A			
A STALLER	PRIORITY:	A (New entry)			
AND PERMIT	OWNER TYPE:	Religious organisation	Contact: Jill T	yndale (LPA) 0208 545 3839	
	SITE NAME:	Motor House, 2 Highbury Road, Wimbledon	built motor H listed dwellin	RJ Thomas and AG Pomeroy. Unique p nouse listed in its own right adjacent to g, Good Hope. The glazed washing por	grade ch ha
Martin Falls	DESIGNATION:	Listed Building Grade II, CA		dismantled and the glass has been remo	oved.
	CONDITION:	Poor		nted in 2011 for conversion to living tion in association with adjacent house	
THE REAL PROPERTY OF		Occupied		that the washing porch was restored.	
	PRIORITY:	D (C)		work has yet to start.	
	OWNER TYPE:		Contact: lill T	yndale (LPA) 0208 545 3839	
	OWNER ITPE:	Trivate	Contact. Jin 1	yndale (El X) 0200 5 15 5057	
	SITE NAME:	Dovecote adjacent to pond to south east of The Canons, Madeira Road, Mitcham	in Merton. It	e was built in 1511, being the oldest bu is a square structure with a hipped roc es on the inside of the walls. It is constr	of. Ö
	DESIGNATION	Listed Building Grade II		ks and red brick quoins with a tiled roc	
	CONDITION:	Fair		all and roof carried out following dama remains very vulnerable to vandalism.	.ge
A Standard Read	OCCUPANCY:				
	PRIORITY:	E (New entry)			
		Local authority	Contact: Jill T	yndale (LPA) 0208 545 3839	
	SITE NAME:	Ravensbury Mill (North Wing),	CI8 and CI	9 snuff mill powered by water.The Nor	
I I I	SHE NAME:	245 Morden Road, Morden	Wing is subjection towards reso	ect to a Section 106 agreement. Slow p olving outstanding planning obligations, e	rogre enablii
Hard Hinds -	DESIGNATION:	Listed Building Grade II, CA	a lease for th	ne occupation of the North Wing by W Iseum. Discussions ongoing to resolve	andle
	CONDITION:	Fair	outstanding i		
	OCCUPANCY:	Part occupied			
	PRIORITY:	C (C)			
- June -	OWNER TYPE:	Charity	Contact: Jill T	yndale (LPA) 0208 545 3839	
DRITY (FOR BUILDINGS)	D Slow deer	v solution arreed <b>F</b> Papping schame in arrest		ABBREVIATIONS	
mmediate risk of further rapid deterioration or loss of fabric; no solution agreed. mmediate risk of further rapid deterioration or loss of fabric; solution	but not ye E Under rep repair, but	y; solution agreed F Repair scheme in prog and (where applicable end use or user identified; or at of vacancy with no with new use agreed yet implemented. yet implemented.	) 2011 pr fied; are give : buildings	iority categories n in brackets. RPG Registered Park a SM Scheduled Monur	uthority

deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

	SITE NAME:	Mausoleum of Sir Joseph William Bazalgette, St Mary's Road, St Mary's Churchyard, Wimbledon	Portland stone mausoleum from the end of C19. Ironwork in very poor condition, gates missing and evidence of anti-social activity.
	DESIGNATION:	Listed Building Grade II*, CA	
A right	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Tomb of Bankes, St Mary's Road, Wimbledon, St Mary's Churchyard	Table tomb from mid C18 with inset panels and baluster profiled corners. Continued waste dump activity.
A Med M	DESIGNATION:	Listed Building Grade II, CA	
AND	CONDITION:	Poor	
	OCCUPANCY:	N/A	
the second s	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Jill Tyndale (LPA) 0208 545 3839
	SITE NAME:	Tomb of Elizabeth Johnson, St Mary's Road, Wimbledon, St Mary's Churchyard	Table tomb, tapered to base, erected around 1800. Side panels have collapsed and vegetation has rooted in the monument and on its pedestal.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Jill Tyndale (LPA) 0208 545 3839
	SITE NAME:	Tomb of John Lawson, St Mary's Road, Wimbledon, St Mary's Churchyard	Table tomb on stepped podium, dating from circa 1704. Evidence of joints widening and plinth collapsing.
	DESIGNATION:	Listed Building Grade II, CA	
and a service of the	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A CARDON CONTRACTOR	PRIORITY:	C (New entry	
	OWNER TYPE:	Religious organisation	Contact: Jill Tyndale (LPA) 0208 545 3839
	SITE NAME:	Base of windmill at Mill House, Windmill Road	Brick with timber framing comprising base of hollow-post windmill. Located within the car park of Windmill Public House with its timber superstructure exposed to the
	DESIGNATION:	Listed Building Grade II	elements. The new owners have undertaken preservation work on the timbers which have now been reinstated.
	CONDITION:	Fair	The structure remains at risk without a protective cover.
	OCCUPANCY:	N/A	
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Jill Tyndale (LPA) 0208 545 3839
	SITE NAME:	Wall to rear of flats, 27-33 (consecutive) Windsor Avenue, Colliers Wood	rubble stone, it is being damaged by vegetation growing
	DESIGNATION:	Listed Building Grade II, CA	out of the wall structure.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
and the second second	PRIORITY:	A (A)	
	OWNER TYPE:	D	Contact: Jill Tyndale (LPA) 0208 545 3839

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

#### HERITAGE AT RISK 2012 / LONDON / MERTON / NEWHAM

SITE NAME:	Merton Pr	riory (site of), Merton		
DESIGNATION:	Scheduled Monument (No.1001976)		CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission		TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Morden P	ark Mound, Merton		
DESIGNATION:	Scheduled	Monument (No.1002011)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local auth	ority	CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Bathgate F	Road		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Medium		TREND:	Deteriorating
CONTACT:		Cearey (LPA) 020 8545 3055	NEW ENTRY?:	No
NEWHAM				
	SITE NAME:	Abbey Mills Pumping Station (Station C) with associated Valve House, Abbey Lane E15	and moulde deep below	ation 1910-14, white stock brick with terracotta ed stone dressings. Internal pumping floor sunk / ground level. Heritage Lottery Fund Townscap tiative bid, involving conversion to Building Craf
	DESIGNATION:	Listed Building Grade II, CA	Centre faile	d. No current long-term proposals for reuse o
<b>Della</b>	CONDITION:	Poor	the building	at this stage.
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Former utility	Contact: Be	n Hull (LPA) 020 3373 9574
	SITE NAME:	Bases of pair of chimneystacks at Abbey Mills Pumping Station, Abbey Lane E15	Two chimney bases built 1865 by Bazalgette. Elaborate pedimented porches to battered brick plinths crowned by stone bases of octagonal stacks	
	DESIGNATION:	Listed Building Grade II, CA		d).Thames Water considering options to works to structure.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
they are a second	PRIORITY:	С (С)		
	OWNER TYPE:	Former utility	Contact: Be	n Hull (LPA) 020 3373 9574
	SITE NAME:	Gate lodge at Abbey Mills Pumping Station, Abbey Lane E15		umping station, built circa 1865. m proposals for reuse at this stage.
	DESIGNATION:			
	CONDITION:	Fair		
	OCCUPANCY:	Vacant		
A COMPANY OF A SAME	PRIORITY:	E (C)		
	OWNER TYPE:	Former utility	Contact: Be	n Hull (LPA) 020 3373 9574
	SITE NAME:	Offices (former Superintendent's House) at Abbey Mills Pumping Station, Abbey Lane E15	built 1865 b with stone o consent grad	perintendent's House to pumping station, by Bazalgette. Two storeys in yellow brick dressings. Part used as offices. Listed building inted for external repair and restoration work ete. No long-term proposals for reuse.
	DESIGNATION:	Listed Building Grade II, CA	now compi	eter to long term proposals for reuse.
	CONDITION:	Fair		
	OCCUPANCY:	Vacant		
	PRIORITY:	E (E)		
	OWNER TYPE:	Former utility	Contact: Be	n Hull (LPA) 020 3373 9574
RIORITY (FOR BUILDINGS)				ABBREVIATIONS
<ul> <li>Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>Immediate risk of further rapid</li> </ul>	but not ye E Under rep	y; solution agreed F Repair scheme in progres at implemented. sair or in fair to good no user identified: or no user identified: or	2011 p are giv	E: CA Conservation Area priority categories LB Listed Building LPA Local Planning Authority NP National Park

- detenoration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ABBREV	'IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site
	0

#### HERITAGE AT RISK 2012 / LONDON / NEWHAM

HENHAGE AT MISK 2012 / LONE			
	SITE NAME:	Stores Building at Abbey Mills Pumping Station, Abbey Lane E15	Storage building circa 1865 by Sir Joseph Bazalgette. Vacant. Significant structural movement. Damage due to water ingress. Thames Water considering options
	DESIGNATION:	Listed Building Grade II, CA	for repair.
The second second	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (A)	
Contraction of the owner owne	OWNER TYPE:	Former utility	Contact: Ben Hull (LPA) 020 3373 9574
		,	
	SITE NAME:	Ancillary Pump House at Abbey Mills Pumping Station (Station B), Abbey Road E15	Pump house circa 1868, probably by Bazalgette and Cooper, built in similar style to main pumping station. Temporary use as storage facility.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
and the second second	OWNER TYPE:	Former utility	Contact: Ben Hull (LPA) 020 3373 9574
		,	
	SITE NAME:	West Ham Pumping Station Engine House, Abbey Road E15	Engine house, 1897. Contains original Lilleshall Company beam engines. In use as training facility. Extensive unauthorised works to interior.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
	PRIORITY:	D (E)	
A la desta la seconda de la	OWNER TYPE:	Former utility	Contact: Ben Hull (LPA) 020 3373 9574
		,	
	SITE NAME:	Technical College, Barking Road, East Ham E6	Technical College 1903-04: by Cheers and Smith. Red brick with terracotta dressings. Slated roof. Good circulation spaces and impressive main hall
	DESIGNATION:	Listed Building Grade II, CA	with large painted glass roof light. Building currently empty. Damage to elaborate plasterwork within main
	CONDITION:	Fair	hall caused by water ingress. Permission received for
	OCCUPANCY:	Vacant	conversion as part of overall 'Civic Campus' proposal.
	PRIORITY:	D (New entry)	
	OWNER TYPE:	Local authority	Contact: Ben Hull (LPA) 020 3373 9574
		,	
	SITE NAME:	Dukes Head public house, 593 Barking Road, East Ham E6	Impressive corner public house 1900. Damaged by fire. Restoration complete. Ground floor and first floor in use but upper floor flats remain unoccupied.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied	
The Island	PRIORITY:	F (B)	
ANS AND	OWNER TYPE:	Private	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Gallions Hotel, Gallions Road, Royal Albert Dock E16	Hotel built 1881-3 to the design of Vigers and Wagstaffe. Conversion and restoration works appear to be complete, but building still vacant.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Good	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (E)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
		. ,	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / NEWHAM

	SITE NAME:	Coach and Horses public house, 100 High Street, Plaistow E13	Three storey C18 public house, yellow brick with red brick arches and reveals. Extensive damage to 1930s interior. Urgent repairs have been carried out following threat
	DESIGNATION:	Listed Building Grade II	of section 54 notice. Recent pre-application discussions. Application expected for reuse and restoration.
	CONDITION:	Poor	Application expected for reduce and restoration.
	OCCUPANCY:	Vacant	
A VAL SHE REAR IN A HOMES A	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	The Log Cabin (formerly known as The Yorkshire Grey), 335-337 High Street, Stratford E15	Three storey, C18 coaching inn. Permission granted for conversion to hotel. Damaged by fire in March 2009. Listed building consent subsequently granted for restoration works. Now nearing completion. Hotel due to open
	DESIGNATION:	Listed Building Grade II	July 2012.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNER TYPE:	Private	Contact: Ben Hull (LPA) 020 3373 9574
I	site name:	Chimney to Beckton Sewage Works, Jenkins Lane, Beckton IGII	Chimney 1887/89, designed by Joseph Bazalgette, as part of the improvements to the northern outfall of the London drainage network. Listed building consent granted for
	DESIGNATION:	Listed Building Grade II	works to facilitate Lee Tunnel and Beckton extension works. Chimney dismantled and in storage, pending
-	CONDITION:	Poor	re-erection following completion of tunnelling works.
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Ben Hull (LPA) 020 3373 9574
-	SITE NAME:	Duke of Fife public house, 350 Katherine Road, Forest Gate E7	Impressive public house circa 1895. The building has been vacant since closing as a public house in 2011. The building is showing signs of neglect. Current proposals to convert
	DESIGNATION:	Listed Building Grade II	the upper floors into residential with commercial use on
	CONDITION:	Fair	the ground floor.
	OCCUPANCY:	Vacant	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	D I I I	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Earl of Derby public house, London Road, West Ham E13	Public House, circa I 880, two storey with stucco dressings and slate roof. The building is currently unoccupied. Application approved for residential
	DESIGNATION:	Listed Building Grade II	use and repair/restoration. Works ongoing.
AND A DECK	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F(C)	
	OWNER TYPE:	Private	Contact: Ben Hull (LPA) 020 3373 9574
in the second se	SITE NAME:	Silo D, North Woolwich Road, Canning Town E16	Grain silo, 1920. Reinforced concrete. Building appears neglected. Vegetation growing from various areas of the structure. Broken windows in many places.
A Street A			
Alter Sal	DESIGNATION:	Listed Building Grade II	
	DESIGNATION: CONDITION:	Listed Building Grade II Fair	
		Fair	
	CONDITION:	Fair	
	CONDITION: OCCUPANCY:	Fair N/A C (C)	Contact: Ben Hull (LPA) 020 3373 9574

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

98

	SITE NAME:	North Woolwich Station including turntable and platform lamp standards, Pier Road, North Woolwich E16	Former railway station, 1847. Broken windows on first floor front elevation. Vegetation growing from the stonework and brickwork. Platform overgrown. Site unsecured.
an an anna an	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER	OWNER TYPE:	Company	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Earl of Essex public house, 616 Romford Road, Newham E12	Impressive Edwardian public house from 1902, on prominent corner site by Henry Poston and WE Trent. Empty and boarded up, no future use identified.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Fair	
	OCCUPANCY:		
AND	PRIORITY:	C (New entry)	
	OWNER TYPE:	Private	Contact: Ben Hull (LPA) 020 3373 9574
A	SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16	Restaurant, built 1883 to the design of Vigers and Wagstaff in a free classical style. Repaired and 'mothballed' by the London Docklands Development Corporation. Ownership now with London Development Agency
	DESIGNATION:	Listed Building Grade II	and part of the Royals Business Park. Security has been
	CONDITION:	Good	improved. Some emergency repairs have been undertaken.
	OCCUPANCY:		No current plans for the building.
In the second se	PRIORITY:	E (E)	
And the second second second	OWNER TYPE:	Quango	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Central offices at Custom House, Royal Albert Dock E16	Offices, built 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation.
			in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part
		Royal Albert Dock E16	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken.
	DESIGNATION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E)	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building.
	DESIGNATION: CONDITION: OCCUPANCY:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E)	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill),	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E)	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E)	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E) Trust Spotted Dog public house, 212 Upton Lane E7	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Weatherboarded C16 timber-framed public house. Local authority have carried out works to secure property and make it weathertight following non compliance with
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E) Trust Spotted Dog public house, 212 Upton Lane E7	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Weatherboarded C16 timber-framed public house. Local authority have carried out works to secure property and make it weathertight following non compliance with Urgent Works Notice part funded by English Heritage. Repairs Notice served and urgent repairs carried out.
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E) Trust Spotted Dog public house, 212 Upton Lane E7 Listed Building Grade II Very bad	in the manner of Norman Shaw. Repaired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Weatherboarded C16 timber-framed public house. Local authority have carried out works to secure property and make it weathertight following non compliance with Urgent Works Notice part funded by English Heritage. Repairs Notice served and urgent repairs carried out. Pre-application scheme submitted by administrators
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: COCUPANCY: SITE NAME: SITE NAME: CONDITION: CONDITION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied Fair Part occupied E (E) Trust Spotted Dog public house, 212 Upton Lane E7 Listed Building Grade II Very bad Vacant	in the manner of Norman Shāw. Repāired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Weatherboarded C16 timber-framed public house. Local authority have carried out works to secure property and make it weathertight following non compliance with Urgent Works Notice part funded by English Heritage. Repairs Notice served and urgent repairs carried out.
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION:	Royal Albert Dock E16 Listed Building Grade II Good Vacant E (E) Quango Tide Mill (known as the House Mill), Three Mill Lane E3 Listed Building Grade I, CA Fair Part occupied E (E) Trust Spotted Dog public house, 212 Upton Lane E7 Listed Building Grade II Very bad Vacant A (A)	in the manner of Norman Shāw. Repāired and 'mothballed' by the London Docklands Development Corporation. Now owned by London Development Agency and part of Royals Business Park. Security has been improved. Some emergency repairs have been undertaken. No current plans for the building. Contact: Ben Hull (LPA) 020 3373 9574 Tide Mill 1776, last used in 1941. Four undershot water wheels in very poor condition. Much machinery remains, though dismantled. The owners, the Waterways Trust, and other partners including British Waterways, English Heritage and London Thames Gateway Development Corporation commissioned an options appraisal. An HLF development grant has been secured and fully developed proposals to be submitted. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Weatherboarded C16 timber-framed public house. Local authority have carried out works to secure property and make it weathertight following non compliance with Urgent Works Notice part funded by English Heritage. Repairs Notice served and urgent repairs carried out. Pre-application scheme submitted by administrators but currently unacceptable and further development

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

99

#### HERITAGE AT RISK 2012 / LONDON / NEWHAM / REDBRIDGE

TITEE	SITE NAME:	West Ham Court House, West Ham Lane EI5	Urgent wor Newham Co	e built 1884 to the design of Lewis Angell. ks carried out to prevent water ingress. ouncil have prepared a conservation plan
1 1 0 1 61 61	DESIGNATION:	Listed Building Grade II, CA	and are con	sidering options.
	CONDITION:	Very bad		
Em a CHEL C A	OCCUPANCY:	Vacant		
	PRIORITY:	C (C)		
	OWNER TYPE:	Local authority	Contact: Ber	n Hull (LPA) 020 3373 9574
SITE NAME:	Sugar Hou	ise Lane		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Medium		TREND:	No significant change
CONTACT:	Ben Hull (	LPA) 020 3373 9574	NEW ENTRY?:	No
SITE NAME:	Three Mill	s		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Low		TREND:	Improving significantly

RE			
K FI	лы	к п.	1 9 F

CONTACT:

	SITE NAME:	Dr Johnson public house, Longwood Gardens, Ilford	Moderne-style public house 1937-8 by H Reginald Ross. Built to serve the large new estates in Barkingside. The building has been vacant and boarded up since 2010, and is on the market. The roof is in a poor state and in
	DESIGNATION:	Listed Building Grade II	2011 the interior was seriously damaged following flooding.
H GROAD THE CONSTRUME	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (C)	
and the second	OWNER TYPE:	Company	Contact: Simon Algar (LPA) 020 8708 2747

		Garden Temple in garden of Temple House, 14 The Avenue, Wanstead	Garden temple, 1730-40, with lonic pedimented portico. Roof repairs completed with English Heritage grant aid. English Heritage funded development grant for repairs
	DESIGNATION:	Listed Building Grade II*, CA	to the portico.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000



	SITE NAME:	The High Stone, Woodford Road, Leytonstone	Obelisk milestone. C19. Portland stone. Condition deteriorating due to lack of long-term maintenance. Local authority currently preparing restoration proposals.	
	DESIGNATION:	Listed Building Grade II		
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	A (New entry)		
	OWNER TYPE:	Local authority	Contact: Simon Algar (LPA) 020 8708 2747	
	SITE NAME:	Wanstead Park	Remains of an important landscape dating from the late C17 to early C19, developed late C19 by the City of London as a public park. Central area converted to	
DESIGNATION:		Registered Park and Garden Grade II*,	a private golf course in the early C20. Some historic	
		also part in CA, 6 LBS	features are undergoing restoration but others are in	

	late C17 to early C19, developed late C19 by the City of London as a public park. Central area converted to
Registered Park and Garden Grade II	*, a private golf course in the early C20. Some historic
also part in CA, 6 LBS	features are undergoing restoration but others are in poor condition. The City of London has deferred
Extensive significant problems	making a decision on submission of a Heritage
r: High	Lottery Fund bid.
Declining	

No

NEW ENTRY?:

Declining OWNER TYPE: Mixed, multiple owners

Ben Hull (LPA) 020 3373 9574

Contact: Principal Heritage at Risk Adviser 020 7973 3000

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

CONDITION:

TREND:

 $\mathsf{vulnerability}: \mathsf{High}$ 

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREV	(IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

#### HERITAGE AT RISK 2012 / LONDON / REDBRIDGE / RICHMOND UPON THAMES

SITE NAME:	Wanstead Park		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Simon Algar (LPA) 020 8708 2747	NEW ENTRY ?:	No
SITE NAME:	Woodford Bridge, Bridge		
SITE NAME: DESIGNATION:	Woodford Bridge, Bridge Conservation Area	CONDITION:	Very bad
		CONDITION: TREND:	Very bad Deteriorating

### DIGUNOND UDON TUANE

RICHMOND UPON TI	HAMES		
THE REAL PROPERTY AND INCOME.	SITE NAME:	Loggia and grotto in grounds of Thames Eyot, Cross Deep, Twickenham	Probably C18. Stone loggia of nine Doric columns and shellwork grotto. Situated in grounds of 1930s flats on the bank of the Thames. Roof has suffered partial collapse and structural movement causing distortion to colonnade.
	DESIGNATION:	Listed Building Grade II, CA	An options appraisal completed in 2011, but no further
	CONDITION:	Very bad	progress due to lack of resources. Ongoing monitoring.
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Nicolette Duckham (LPA) 020 8891 7335
	SITE NAME:	Pope's Grotto in grounds of St James Independent School for Boys, Cross Deep (east side), Twickenham	Grotto with rusticated arched entrance facing the river. Long passage with two 'chapels', one on either side of entrance. Seen as the 'locus classicus' of English C18 gam
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	history. Basic structural condition appears sound, but much of the decorative lining is loose or missing. Owners are
	CONDITION:	Fair	working with Environment Trust, Popes Grotto Preservation
	OCCUPANCY:	N/A	Trust and English Heritage to try to achieve a solution.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Stanhope Grotto in grounds of St James' Independent School for Boys, Cross Deep (east side),Twickenham	owned. The end leading from Pope's Gardens was known
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	as "Stanhope Caves". Grotto entrance overgrown and partially obscured by other decaying vegetation.
	CONDITION:	Poor	
Sherry Mary	OCCUPANCY:	N/A	
	PRIORITY:	C (D)	

Contact: Principal Heritage at Risk Adviser 020 7973 3000

		Normansfield Hospital	Former private sanatorium established by Dr. Langdon Down
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	PRIORITY:	F (B)	
	CONDITION: Fair	Vacant	
		Fair	plumbing and electrics.
	DESIGNATION:	Listed Building Grade I, CA	completed March 2012 in accordance with listed building consent. First phase of internal works underway, comprising
-	SITE NAME:	Garrick's Villa, Hampton Court Road, Hampton	Villa by Robert Adam built in 1756 and remodelled in 1773. Converted into nine apartments in the 1960s and severely damaged by fire in 2008. All external reinstatement works

Former private sanatorium established by Dr Langdon-Down. Normansfield Hospital, SITE NAME: Central portion 1866 incorporating original house. Original Kingston Road, fine interiors vandalised or removed and theft of roof tiles Teddington and lead have led to serious water penetration and severe DESIGNATION: Listed Building Grade II\* deterioration. Listed building consent has been granted to CONDITION: Fair refurbish and convert the main building into flats. Conversion works due for completion in July 2012. OCCUPANCY: Vacant F (B) PRIORITY: Contact: Principal Heritage at Risk Adviser 020 7973 3000 OWNER TYPE: Company

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the function of the solution of the solution

2 Sandarter

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

OWNERTYPE: Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE 2011 priority categories are given in brackets.

#### HERITAGE AT RISK 2012 / LONDON / RICHMOND UPON THAMES

	SITE NAME:	Boat house No. 5 (easternmost I 3 bays), Platts Eyot, Hampton	Timber-framed boathouse built 1917 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build torpedo boats for the Admiralty. A full measured
	DESIGNATION:	Listed Building Grade II, CA	survey of the remaining structure has been completed. Ongoing monitoring.
	CONDITION:	Very bad	
	OCCUPANCY:	Part occupied	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Nicolette Duckham (LPA) 020 8891 7335
	SITE NAME:	The Gallery at Doughty House, 142 Richmond Hill, Richmond upon Thames	Gallery built in 1880 for Sir Francis Cook, extended in 1915 by Brewer Smith. Eleven bays. Giant lonic order with balustrade, the lower order containing door and window
	DESIGNATION:	Listed Building Grade II, CA	openings between Doric pilasters. Works required to roof,
	CONDITION:	Poor	balustrade and especially rainwater goods. Application for renewal of consent for conversion of gallery to offices
		Part occupied	approved. A feasibility study to consider other uses has
	PRIORITY:	D (D)	been completed.
	OWNER TYPE:		Contact: Nicolette Duckham (LPA) 020 8891 7335
		Towns average Marian	Pagun in 1940 by Desingus Durston and not completed until
	SITE NAME:	Temperate House, Royal Botanical Gardens, Kew	Begun in 1860 by Decimus Burton and not completed until 1897-9. Three communicating glasshouses in iron, glass and stucco. Completion of previous restoration in 1984 and
CALCULATING TRANSPORTATION A LEADER MANAGEMENT	DESIGNATION:	Listed Building Grade I, CA, RPG I	now once again in need of major repair. Heritage Lottery Fund Stage I pass received for comprehensive repair and
III III (JUJUU ADARTITI	CONDITION:	Poor	refurbishment; Stage 2 to be delivered by October 2012.
	OCCUPANCY:	Occupied	, ,
	PRIORITY:	D (New entry)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Air Raid Shelter, St Leonard's Court, St Leonard's Road, East Sheen	Air raid shelter, probably built in 1938 to serve St Leonard's Court which was built in 1934-38 by local builder Mr FG Fox. Designed to hold forty eight people, at the time there
LADIES LADIES	DESIGNATION:	Listed Building Grade II	were eighty three flats. Richmond Environment Trust have
	CONDITION:	Poor	commissioned a structural survey and funding is being sought for repairs and use as an educational resource.
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
	OWNER TYPE:		Contact: Nicolette Duckham (LPA) 020 8891 7335
		The Kilmen Merrelever	Managara dation from 1054 by Llange Kandall insign
	SITE NAME:	The Kilmorey Mausoleum, including enclosure wall, railings and gate, St Margaret's Road, Isleworth	Mausoleum dating from 1854 by Henry Kendall junior for Francis Needham, 2nd Earl of Kilmorey, brought to its present location in 1868. The mausoleum is subject to water ingress at roof level and the surrounding railings are in a poor condition.
	DESIGNATION:	Listed Building Grade II, CA	rainings are in a poor condition.
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	C (New entry)	
		Local authority	Contact: Nicolette Duckham (LPA) 020 8891 7335

DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Nicolette Duckham (LPA) 020 8891 7335	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

#### HERITAGE AT RISK 2012 / LONDON / SOUTHWARK

SOUTHWARK			
	SITE NAME:	Licensed Victuallers Almshouses: Chapel, Asylum Road SEI5	Former almshouse chapel, 1827-31. In stable condition, but in need of extensive repairs. Let by the London Borough of Southwark to a local artists' group.
autoul	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
Contraction of the second	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	Chest tomb, Bermondsey Street, St Mary Magdalene Churchyard SEI	Chest tomb from 1815 with original railings. Overgrowth has caused damage to stone and ironwork. Repairs to surrounding churchyard
	DESIGNATION:	Listed Building Grade II, CA	monuments and landscape are in progress.
<b>德诺美国教育 新闻 新</b> 有	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	Table tomb, Bermondsey Street, St Mary Magdalene Churchyard SEI	Unusual C18 table tomb under stone canopy with tapered, fluted columns. Some deterioration to stone elements and railings. Repairs to churchyard monuments and landscape
	DESIGNATION:	Listed Building Grade II, CA	are in progress.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
111日 不能要	PRIORITY:	D (New entry)	
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	Tomb of John Sargeant, Bermondsey Street, St Mary Magdalene Churchyard SEI	C18 stone chest tomb. Damaged by erosion and cementitious repairs in the past. Repairs to churchyard monuments and landscape are in progress.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
Charles and the state	PRIORITY:	D (New entry)	
and the second sec	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	Presbyterian Chapel, 109 Borough Road SEI	Former Presbyterian chapel, 1846. Consent approved for facade retention (2006) and conditions discharged but works ceased. The building has been made weather-proof
	DESIGNATION:	Listed Building Grade II, CA	and 'mothballed' while South Bank University reviews options
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	B (B)	
	OWNER TYPE:	Educational Body	Contact: David Lane (LPA) 0207 525 5449
		113-119 Borough Road SEI	Terrace of three storey late Georgian brick
	SITE NAME:		houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University.
		Listed Building Grade II, CA	houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight
		-	houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University.
	DESIGNATION:	Listed Building Grade II, CA Poor	houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University exploring options to
	DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor	houses with shops on the ground floor. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University exploring options to

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / SOUTHWARK

	SITE NAME:	Lodge, Camberwell New Cemetery, Brenchley Gardens, Honor Oak SE23	Former cemetery lodge (1928-29) designed by Sir Aston Webb. Building is vacant and condition is deteriorating. The London Borough of Southwark is exploring options
ana	DESIGNATION:	Listed Building Grade II	to bring the building back into use.
	CONDITION:		
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
		Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	Gate piers and railings to the churchyard of the former Church of St John, Fair Street, London SEI	Early to mid C19 railings, gates and gate piers. Wrought iron railings and Portland stone piers and plinth.They are a good example of late Georgian ironwork but have started to corrode.
	DESIGNATION:	Listed Building Grade II, CA	The local authority is exploring repair options.
	CONDITION:	Poor	, , , , , , , , , , , , , , , , , , , ,
	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	38 Glengall Road, Peckham SE17	Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. Ionic entrance porch is in poor condition. Discussions have been
	DESIGNATION:	Listed Building Grade II, CA	held on the repair of the building.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:		Contact: David Lane (LPA) 0207 525 5449
	SITE NAME:	143 Kennington Park Road, Kennington SEI1	Part of late C18 terrace. The building has been vacant for sometime and was sold to a new owner in February 2011. Consent was granted to refurbish the building in June 2011
	DESIGNATION:	Listed Building Grade II, CA	Works are currently in progress.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	F(C)	
		Company	Contact: David Lane (LPA) 0207 525 5449
	OWNERTHE	Company	Contacti David Lane (Livi) 0207 020 0117
	SITE NAME:	133 Kennington Park Road, Walworth SEI1	A late C18 terrace house. Conditional planning and listed building consents for conversion to four flats granted May 2008, but not implemented.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:		
	PRIORITY:	D (D)	
	OWNER TYPE:		Contact: David Lane (LPA) 0207 525 5449
	OWNERTIFE		
	SITE NAME:	East Lodge to Nunhead Cemetery, Linden Grove SE15	One of a pair of gate lodges, 1840, by James Bunstone Bunning, adjacent to the main entrance gates. In ruinous condition, but stabilised. English Heritage awarded a
	DESIGNATION:	Listed Building Grade II, CA, RPG II	development grant. Friends of Nunhead Cemetery exploring matched funding and Building Preservation
	CONDITION:	Very bad	Trusts to repair building.
	OCCUPANCY:		
	PRIORITY:	A (A)	
	PRIORITY: OWNER TYPE:	A (A) Local authority	Contact: David Lane (LPA) 0207 525 5449

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

CONDITION: VULNERABILITY TREND:	Nunhead Cemetery (All Saints) Registered Park and Garden Grade II*, also CA, 15 LBs Generally unsatisfactory with major localised problems High Declining Local authority, single owner	An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the cemetery skilfully exploits the undulating topography to create picturesque effects and vistas. Despite Heritage Lottery Fund funded repair of some elements in 1998, many tombs remain in poor condition and the East Lodge is a building at risk. Contact: Principal Heritage at Risk Adviser 020 7973 3000
CONDITION: OCCUPANCY: PRIORITY:		Visually prominent monument from 1872 in pink and grey granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure presents a praying figure carried on a tall column and plinth and an angel statue at its base. Missing railings. Due to ground subsidence nearby there is concern over its structural stability. Contact: David Lane (LPA) 0207 525 5449
CONDITION: OCCUPANCY: PRIORITY:		Terrace of three and four storey late Georgian houses with shops on the ground floors. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University exploring options to bring the terrace back into use. Contact: David Lane (LPA) 0207 525 5449
CONDITION: OCCUPANCY: PRIORITY:		Part of the formal composition of St George's Circus on the approach to Blackfriars Bridge. Four storey late Georgian brick and stucco composition with later C19 pub front. Formed part of a larger site assembled by South Bank University. Stabilisation programme completed. Buildings weathertight and drying. South Bank University exploring options to bring the building back into use. Contact: David Lane (LPA) 0207 525 5449
SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant D (D)	House built in 1873 by Charles Drake of the Patent Concrete Building Company. Serious structural problems. Compulsory Purchase Order confirmed. Building preservation trust has consent for conversion to five flats and work to start 2012. Contact: David Lane (LPA) 0207 525 5449
CONDITION: OCCUPANCY: PRIORITY:		Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is suffering from structural movement and lack of maintenance. The Dulwich Society are planning a proposal for repair of the hall. Contact: David Lane (LPA) 0207 525 5449

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / SOUTHWARK

HERITAGE AT RISK 2012 / LOIND	011 / <b>3001</b>		
	CONDITION: OCCUPANCY: PRIORITY:		Former Ada Lewis women's hostel, built in 1913 as first women's hostel, and renamed Driscoll House when the hostel was run by Terrance Driscoll from late 1960s. Consent has been granted for refurbishment works and to bring the building back into use. Works are currently underway. Contact: David Lane (LPA) 0207 525 5449
	CONDITION: OCCUPANCY: PRIORITY:	Fire station (former), 306-312 (even) Old Kent Road SEI Listed Building Grade II Poor Part occupied C (C) Company	Fire station built between 1903-4 by the London County Council Architects Department. Red brick with Portland stone dressings. Roof has recently been repaired. Unauthorised installation of shop fronts.
	CONDITION: OCCUPANCY: PRIORITY:	The Kentish Drovers public house, 720 Old Kent Road, Peckham SEI5 Listed Building Grade II Poor Occupied C (C) Company	Mid C19 public house. The mural over painting has been removed. Enforcement pending on unauthorised alterations to fabric and UPVC windows and investigation of further breaches. Contact: David Lane (LPA) 0207 525 5449
	CONDITION:	<b>38 Peckham Hill Street SE15</b> Listed Building Grade II, CA Poor Occupied C (C) Private	One of a terrace of four houses. Built circa 1840. Building damaged by fire in 2009. Sold to new owner in February 2011. Unauthorised works carried out to mitigate fire damage. Contact: David Lane (LPA) 0207 525 5449
	CONDITION:	Occupied C (C)	One of a group of four pairs of early C19 houses. No proposals for reuse. Repairs have been carried out using unsuitable materials. Grant application made under the East Peckham Renewal Scheme and currently investigating adaptations to make the building disability accessible with London Borough of Southwark housing. Contact: David Lane (LPA) 0207 525 5449
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant C (C)	Early C19 terraced building. Extensive unauthorised works. In a poor condition. Contact: David Lane (LPA) 0207 525 5449

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

	SITE NAME:	Former Clare College Mission Church, Southwark Park SE16	Former church. The Bermondsey Artists' Group was awarded a Big Lottery grant under the Community Assets Programme (2008) to refurbish the building	
	DESIGNATION:	Listed Building Grade II	as an art gallery space. English Heritage and Southwark Council have funded roof repairs completed in 2010.	
	CONDITION:	Poor	Further repairs are required to the walls.	
	OCCUPANCY:	Occupied		
	PRIORITY:	D (D)		
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449	
	SITE NAME:	Southwark Park School, Southwark Park Road, Southwark SEI6	London Board School, by ER Robson, of 1873 with extensions of 1899. Major redevelopment scheme began 2010 but abandoned. Retained fabric is protected from the weather. The local authority is exploring options	
	DESIGNATION:	Listed Building Grade II	to bring the school back into use.	
	CONDITION:	Poor	0	
	OCCUPANCY:	Vacant		
	PRIORITY:	C (C)		
	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449	
	SITE NAME:	St Giles Hospital, St Giles Road, London SE5	Hospital administration block with attached ward block, 1904 by ET Hall. Brick in Flemish bond with stone dressings. Hipped roofs of slate. Building vacant	
	DESIGNATION:	Listed Building Grade II	since the Trust moved in 2008. Windows currently blocked up. Proposals to convert the building to 12 flats were	
	CONDITION:	Fair	agreed in March 2010, subject to a legal agreement.	
	OCCUPANCY:	Vacant		
	PRIORITY:	D (D)		
	OWNER TYPE:	Company	Contact: David Lane (LPA) 0207 525 5449	
	SITE NAME:	Peckham Rye Station, Station Way, Peckham SE15	The station is an H-shaped building. 1864-65 by Charles Henry Driver for the London, Brighton and South East Coast Railway. It is in a Continental Renaissance style and	
	DESIGNATION:	Listed Building Grade II, CA	is built with stock brick and stone dressings. The northern wing is not in use and suffering from wet and dry rot.	
	CONDITION:	Poor	The ceiling in the southern wing has partially collapsed	
	OCCUPANCY:	Part occupied	and the stone stair with cast iron balustrade has fallen	
510	PRIORITY:	C (New entry)	into disrepair.	
and the second second	OWNER TYPE:	-	Contact: David Lane (LPA) 0207 525 5449	
A RECENCIC				
	SITE NAME:	Beltwood House, 41 Sydenham Hill, Camberwell SE26	Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. House remodelled in the neo-classical style in circa 1895. Building contains fine	
	DESIGNATION:	Listed Building Grade II, CA	interiors, but currently vacant and suffering effects of water ingress. The curtilage buildings (stables, lodge, two	
	CONDITION:	Fair	cottages and animal store) are in a poor state of repair.	
	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNER TYPE:	Private	Contact: David Lane (LPA) 0207 525 5449	
	SITE NAME:	Drinking fountain, Tanner Street Park, Bermondsey SEI	Originally a turret and the capping to the tower of the former Church of St Olave, Tooley Street. 1738-9, re-sited 1929. Now a drinking fountain. In poor condition. Consultant commissioned	
	DESIGNATION:	Listed Building Grade II, CA	for schedule of repairs.	
	CONDITION:	Poor	,	
	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
State - Alter -	OWNER TYPE:	Local authority	Contact: David Lane (LPA) 0207 525 5449	



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
UA	Unitary Authority
WHS	World Heritage Site

	SITE NAME: 62 and 64 Union Street SEI		Pair of terraced houses built circa I 835. Network Rail has carried out works to make the property weatherproof an structurally secure. Phase II to bring houses into beneficial			
	DESIGNATION:	Listed Building Grade II, CA	use being e	explored.		
	CONDITION:	Fair				
	OCCUPANCY:					
	PRIORITY:	E (E)				
	OWNER TYPE: Company		Contact: Da	Contact: David Lane (LPA) 0207 525 5449		
305 KENNEDY. 305)	SITE NAME:	Kennedys Sausages shop,Former Kennedy sausages shop, circa 1923.305 Walworth Road,A well-preserved example of a 1920s shop.Walworth SE17Vacant and in a deteriorating condition.				
	DESIGNATION:	Listed Building Grade II				
	CONDITION:	Poor				
	OCCUPANCY:	Vacant				
	PRIORITY:	C (C)				
	OWNER TYPE:	Company	Contact: David Lane (LPA) 0207 525 5449			
	SITE NAME:	Church of St Augustine, Honor Oak Park, Camberwell SE23 Listed Place of Worship Grade II	Constructed between 1872-73 by William Oakley in Kentish ragstone with ashlar details and slate roof. Rainwater goods have experienced extensive rusting, numerous stone dressings have weathered and structural cracks are visible above the northern transept. English Haritage grant effer for programme of high lavel program			
	CONDITION:			Heritage grant offer for programme of high level repairs has been made.		
	PRIORITY:	D (D)				
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 020 7973 3000			
SITE NAME:	Roman bo	pat at New Guy's House, Bermondsey,	Southwark			
DESIGNATION:	Scheduled	Monument (No.1001979)	CONDITION:	Generally satisfactory		
				but with significant localised problems		
PRINCIPAL VULNERABILITY:	-	dewatering	TREND:	Declining		
OWNER TYPE:	Other		CONTACT:	Principal Heritage at Risk Adviser 020 7973 3000		
SITE NAME:	The Rose	Theatre, Rose Court, Southwark				
DESIGNATION:		Monument (No.1012707) dewatering	CONDITION:	Extensive significant problems Unknown		
PRINCIPAL VULNERABILITY: OWNER TYPE:	Other	Jewatering	TREND: CONTACT:	Principal Heritage at Risk Adviser		
Owner IIFE.	Other		CONTACT.	020 7973 3000		
SITE NAME:	St George	s's Circus				
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad		
VULNERABILITY:	Low		TREND:	Improving significantly		
CONTACT:		oukaris (LPA) 020 8299 6078	NEW ENTRY?:	No		
SUTTON						
	SITE NAME:	Orangery wall to Beddington Place, Church Road, Beddington	Orangery wall of circa 1720. Subject to severe vandalism. The Local Authority have completed a restoration strategy document.			
	DESIGNATION: Listed Building Grade II, CA					
The second second	condition: Poor					
	OCCUPANCY:	N/A				
A Contraction of the second se	priority: A (A)					
	OWNER TYPE:	OWNERTYPE: Local authority		Contact: Sally Blomfield (LPA) 020 8770 6253		
RIORITY (FOR BUILDINGS)				ABBREVIATIONS		

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

#### HERITAGE AT RISK 2012 / LONDON / SUTTON / TOWER HAMIETS

HERITAGE AT RISK 2012 / LONE	don / sutto	ON / TOWER HAMLETS		
	SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton	grotto has s gradually to	grotto in Carshalton Park. The exterior of the symmetrical curved walls of brick, ramped up a central peak. The grotto is extremely to vandalism and graffiti.
	DESIGNATION:	Listed Building Grade II, CA	Valitici abie i	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
and the second second	PRIORITY:	A (A)		
2101-10-10-10-10-10-10-10-10-10-10-10-10-	OWNER TYPE:	Local authority	Contact: Sa	lly Blomfield (LPA) 020 8770 6253
inne.	SITE NAME:	Christ Church, Christchurch Park, Sutton	Jacques. Lar Notable ch of the bapt	nmenced I 880s designed by Newman and ge and imposing red brick with stone dressings. ancel screen and Arts and Crafts treatment istry. Grant offered towards high level works. rright: Catherine Keen.
	DESIGNATION:	Listed Place of Worship Grade II		0
A Construction and	CONDITION:	Poor		
L. mat	PRIORITY:	D (D)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 020 7973 3000
SITE NAME:	Roman vil	lla east of Beddington Park, Sutton		
DESIGNATION:	Scheduled	I Monument (No.1001990)	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Unknown
OWNER TYPE:	Utility	5,5,7,7,7	CONTACT:	Principal Heritage at Risk Adviser
OWNERTHE.	Clinty		contract.	020 7973 3000
TOWER HAMLETS				
TO WER TIATIELTS				
	SITE NAME:	Well and Bucket public house, 143 Bethnal Green Road E2	shops which Heritage pa	blic house; part of mid to late C19 terrace of h is subject to current Tower Hamlets/English artnership scheme. Planning application for d external works agreed.
	DESIGNATION:	Listed Building Grade II		
	CONDITION:	Fair		
	OCCUPANCY:	Part occupied		
	PRIORITY:	D (D)		
LEATHERITEX	OWNER TYPE:		Contact: Ma	ark Hutton (LPA) 020 7364 5372
	SITE NAME:	Front wall, gate piers and gates at St Clements Hospital, Bow Road, Bow E3	redundant S	gates and railings forming front boundary to St Clements Hospital. Homes and Community owners and the Local Authority are actively
	DESIGNATION:	Listed Building Grade II, CA	SEEKING HEV	v use.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	C (C)		
Timisin	OWNER TYPE:	Government	Contact: Ma	ark Hutton (LPA) 020 7364 5372
	SITE NAME:	St Clements Hospital, Bow Road, Bow E3	Impressive   Vacant. Hor	hospital, formerly City of London infirmary. Italianate main block fronting Bow Road. nes and Community Agency are owners
	DESIGNATION	Listed Building Grade II, CA	and the Loo	cal Authority are actively seeking new use.
E THE ME	CONDITION:	Poor		
	OCCUPANCY:			
	PRIORITY:	C (C)		
		Government	Contact: M	ark Hutton (LPA) 020 7364 5372
	OWNER ITPE:	Government	Contact. Pla	



PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	2 Bollards (Between statue of Gladstone and St Mary's churchyard entrance), Bow Road, Bromley-By-Bow E3	Two C19 bollards which formed a group along with St Mary's Church, its gates and railings and the statue of WE Gladstone. One of the bollards has been removed.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
and the second	OCCUPANCY:	N/A	
in the second	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: Mark Hutton (LPA) 020 7364 5372
11	SITE NAME:	Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3	Underground gentlemen's public convenience, constructed by the Board of Works and opened in 1899. Curved entrance steps designed to fit around
	DESIGNATION:	Listed Building Grade II, CA	statue of WE Gladstone. Decorative iron gates recently damaged. Decorative interior finishes including russet
	CONDITION:	Very bad	marble urinals. Disused for many years. Interior subject
The second states of the second states	OCCUPANCY:	N/A	to vandalism. Tower Hamlets Council is aiming to work
	PRIORITY:	A (A)	with strategic partners to find a way forward.
	OWNER TYPE:	Unknown	Contact: Mark Hutton (LPA) 020 7364 5372
	SITE NAME:	How Memorial Gateway, Bromley High Street E3	Circa 1893. Gabled stone Gothic arch style with double buttresses at each side. Formerly an entrance to St Mary's Churchyard. Suffering from stonework decay.
	DESIGNATION:	Listed Building Grade II	
	CONDITION:	Poor	
T termine the series	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Unknown	Contact: Mark Hutton (LPA) 020 7364 5372
	SITE NAME:	The British Prince public house, 49 Bromley Street El	Early C19, but facade partly rebuilt, probably as a result of war damage. Permission granted for change to residential. Work currently underway.
AFILI		49 Bromley Street El	war damage. Permission granted for change to residential.
DESELUCIONE			war damage. Permission granted for change to residential.
TE BUILTON OF	DESIGNATION:	<b>49 Bromley Street EI</b> Listed Building Grade II, CA Poor	war damage. Permission granted for change to residential.
	DESIGNATION:	<b>49 Bromley Street EI</b> Listed Building Grade II, CA Poor Vacant	war damage. Permission granted for change to residential.
	DESIGNATION: CONDITION: OCCUPANCY:	<b>49 Bromley Street EI</b> Listed Building Grade II, CA Poor Vacant F (A)	war damage. Permission granted for change to residential.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	<b>49 Bromley Street EI</b> Listed Building Grade II, CA Poor Vacant F (A)	war damage. Permission granted for change to residential. Work currently underway. Contact: Mark Hutton (LPA) 020 7364 5372
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14	war damage. Permission granted for change to residential. Work currently underway. Contact: Mark Hutton (LPA) 020 7364 5372 Built 1879-81 as Limehouse Vestry Hall, designed by A & C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor	war damage. Permission granted for change to residential. Work currently underway. Contact: Mark Hutton (LPA) 020 7364 5372 Built 1879-81 as Limehouse Vestry Hall, designed by A & C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied	war damage. Permission granted for change to residential. Work currently underway. Contact: Mark Hutton (LPA) 020 7364 5372 Built 1879-81 as Limehouse Vestry Hall, designed by A & C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied F (D)	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied F (D)	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied F (D) Local authority George Tavern public house, 373 Commercial Road E1	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road E14 Listed Building Grade II, CA Poor Occupied F (D) Local authority George Tavern public house, 373 Commercial Road E1	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road EI4 Listed Building Grade II, CA Poor Occupied F (D) Local authority George Tavern public house, 373 Commercial Road EI Listed Building Grade II, CA Poor	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	49 Bromley Street EI         Listed Building Grade II, CA         Poor         Vacant         F (A)         Private         Limehouse Town Hall, Commercial Road E14         Listed Building Grade II, CA         Poor         Occupied         F (D)         Local authority         George Tavern public house, 373 Commercial Road E1         Listed Building Grade II, CA         Poor	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	49 Bromley Street EI Listed Building Grade II, CA Poor Vacant F (A) Private Limehouse Town Hall, Commercial Road EI4 Listed Building Grade II, CA Poor Occupied F (D) Local authority George Tavern public house, 373 Commercial Road EI Listed Building Grade II, CA Poor Occupied F (C)	<ul> <li>war damage. Permission granted for change to residential. Work currently underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Built 1879-81 as Limehouse Vestry Hall, designed by A &amp; C Harston. Leased to the Limehouse Town Hall Consortium for arts, educational and community projects. Roof repairs partly grant-aided by English Heritage are underway.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Prominent public house c1820-25. Remodelled 1862 and interior in 1891. Water ingress from roof; slow deterioration of building fabric. Some grant assistance</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	Former Caird & Rayner Ltd Warehouse, 777-783 Commercial Road E14	Former sail-makers and ship-chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. Fire damaged with loss of roof
ANAL	DESIGNATION:	Listed Building Grade II, CA	covering. Urgent works completed April 2010.
	CONDITION:	Very bad	
	OCCUPANCY:		
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Mark Hutton (LPA) 020 7364 5372
	site name:	Limehouse District Library, Commercial Road, Limehouse E14	Former Passmore Edwards Library. Built 1900 by Messrs Clarkson Architects. Library closed, building vacant and boarded up.
THE PARTY AND THE	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (New entry)	
	OWNER TYPE:		Contact: Mark Hutton (LPA) 020 7364 5372
	site name:	689 Commercial Road, Limehouse E14	Early C19 terraced house, three storeys and basement. Severely damaged by fire 2012.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Very bad	
De T	OCCUPANCY:	Vacant	
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Private	Contact: Mark Hutton (LPA) 020 7364 5372
AL TO	SITE NAME:	Poplar Baths, East India Dock Road E14	Former public baths, with slipper and vapour baths. Built 1932-4 for Poplar Borough Council to the designs of Harley Heckford, Borough Engineer and RW Stanton, Chief Assistant. Vacant and in poor condition. Local
	DESIGNATION:	Listed Building Grade II	authority are considering re-opening as a swimming
	CONDITION:	Poor	pool and sports centre.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Mark Hutton (LPA) 020 7364 5372
	OWNER TYPE:	Local authority Dowgate Wharf warehouses, 22-23 Gillender Street E14	Contact: Mark Hutton (LPA) 020 7364 5372 Mid C19 brick warehouses, with heavy corbelled cornice and blocking course.
		Dowgate Wharf warehouses, 22-23 Gillender Street E14	Mid C19 brick warehouses, with heavy corbelled
	SITE NAME:	Dowgate Wharf warehouses, 22-23 Gillender Street E14	Mid C19 brick warehouses, with heavy corbelled
	SITE NAME: DESIGNATION:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor	Mid C19 brick warehouses, with heavy corbelled
	SITE NAME: DESIGNATION: CONDITION:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant	Mid C19 brick warehouses, with heavy corbelled
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor	Mid C19 brick warehouses, with heavy corbelled
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A)	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course.
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A)	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course. Contact: Mark Hutton (LPA) 020 7364 5372 Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. Substantial grant
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A) Company Wiltons Music Hall, Graces Alley E1	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course. Contact: Mark Hutton (LPA) 020 7364 5372 Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. Substantial grant for repair and restoration received with work to
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A) Company Wiltons Music Hall, Graces Alley E1	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course. Contact: Mark Hutton (LPA) 020 7364 5372 Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. Substantial grant
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A) Company Wiltons Music Hall, Graces Alley E1 Listed Building Grade II*, CA	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course. Contact: Mark Hutton (LPA) 020 7364 5372 Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. Substantial grant for repair and restoration received with work to
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Dowgate Wharf warehouses, 22-23 Gillender Street E14 Listed Building Grade II Poor Vacant A (A) Company Wiltons Music Hall, Graces Alley E1 Listed Building Grade II*, CA Fair	Mid C19 brick warehouses, with heavy corbelled cornice and blocking course. Contact: Mark Hutton (LPA) 020 7364 5372 Former music hall with fine ornamental interior built 1858. Leased to opera company and now in regular use. Some repair and restoration required. Substantial grant for repair and restoration received with work to



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

||||

Constant and a second and	SITE NAME:	Tablet in the North Wall of the Portuguese Jewish Burial Ground, Mile End Road E1	An inscribed stone tablet, formerly in a glazed case with side scrolls, moulded cornice and pediment recording laying of first stone in the burial ground in
	DESIGNATION:	Listed Building Grade II, CA	1684. The top of the wall including moulded cornice and pediment has collapsed, leaving the stone open
	CONDITION:	Poor	to the elements.
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Religious organisation	Contact: Mark Hutton (LPA) 020 7364 5372
	SITE NAME:	Drinking fountain (on pavement outside 31-74 Mile End Road), Mile End Road, Stepney E1	Late C19 polished granite drinking fountain, short column on plinth with inscription commemorating erection by Metropolitan Cattle Trough and Drinking Fountain Association. Bowl removed. Restoration
annet 2	DESIGNATION:	Listed Building Grade II	proposed as part of the High Street 2012 initiative,
	CONDITION:	Very bad	subject to available funding.
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
The state of the s	OWNER TYPE:	Local authority	Contact: Mark Hutton (LPA) 020 7364 5372
		,	
	SITE NAME:	Drinking fountain (on pavement outside 99 Mile End Road), Mile End Road, Stepney El	C19 small granite polished drinking fountain with dog trough. Upper part of structure removed. Restoration works expected to begin as part of the High Street
The second secon	DESIGNATION:	Listed Building Grade II, CA	2012 initiative.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Mark Hutton (LPA) 020 7364 5372
	SITE NAME:	St Saviours Church, Northumbria Street, Poplar E14	Former church dating from 1873-4 to design by Frederick J and Horace Francis. The building was severely damaged by fire in May 2007 and is currently propped by scaffolding.
	DESIGNATION:	Listed Building Grade II	The Local Authority has been approached by developers but no application has been submitted.
			but no application has been submitted.
	CONDITION:	Very bad	
	CONDITION: OCCUPANCY:	Very bad Vacant	
		,	
	OCCUPANCY:	Vacant	Contact: Mark Hutton (LPA) 020 7364 5372
	OCCUPANCY: PRIORITY:	Vacant A (A)	Contact: Mark Hutton (LPA) 020 7364 5372
	OCCUPANCY: PRIORITY:	Vacant A (A)	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock,	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street E1 Listed Building Grade I	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some
	OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street E1 Listed Building Grade I Fair	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street E1 Listed Building Grade I Fair Vacant E (E)	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El Listed Building Grade I Fair Vacant E (E)	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El Listed Building Grade I Fair Vacant E (E) Company I9 Princelet Street, Spitalfields El	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street E1 Listed Building Grade I Fair Vacant E (E) Company 19 Princelet Street,	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El Listed Building Grade I Fair Vacant E (E) Company I9 Princelet Street, Spitalfields El	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and rare surviving small synagogue.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El Listed Building Grade I Fair Vacant E (E) Company I9 Princelet Street, Spitalfields El Listed Building Grade II*, CA	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and rare surviving small synagogue.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street El Listed Building Grade I Fair Vacant E (E) Company I9 Princelet Street, Spitalfields El Listed Building Grade II*, CA Poor	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and rare surviving small synagogue.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Vacant A (A) Religious organisation Tobacco Dock, Pennington Street E1 Listed Building Grade I Fair Vacant E (E) Company U I9 Princelet Street, Spitalfields E1 Listed Building Grade II*, CA Poor Part occupied C (C)	Warehouse building of 1811-13, converted to form a shopping complex in the early 1990s. This was not successful and the building has been vacant for some time, although occasionally used as an events venue. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. Combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and rare surviving small synagogue.

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	II3 Redchurch Street, Tower Hamlets E2	Weavers' tenement house. Built c1735 by William Farmer, a local builder. Of interest as a rare and early survival of a
			building type that once dominated Spitalfields. The building is derelict and has structural problems. The facade is braced
		Listed Building Grade II, CA	to prevent further movement. Pre-application planning
	CONDITION:	Very bad	discussions have taken place. Local authority considering enforcement options.
	OCCUPANCY:		
Estate Agents Ltd.	PRIORITY: OWNER TYPE:	A (A) Privato	Contact: Mark Hutton (LPA) 020 7364 5372
	OWNER TIPE.	Thrate	
	SITE NAME:	Tomb of Joseph Wrestwood, Southern Grove, Tower Hamlets Cemetery E3	One of the most prominent monuments of the cemetery for design and location, this stone cross dates from circa 1883. It is in poor condition due
ALL ALL ALLAN	DESIGNATION:	Listed Building Grade II, CA	a general decay and the loss of parts of its low railings, tiles, finials and other detailing.
A UA A	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Local authority	Contact: Mark Hutton (LPA) 020 7364 5372
	SITE NAME:	10-12 Stroudley Walk, Bromley-by-Bow E3	Late C18, early C19, three storeys, stock brick with shop on ground floor. Attached to the Rose and Crown Public House. Application for conversion to residential use
	DESIGNATION:	Listed Building Grade II	refused. Negotiations with local authority continuing.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Mark Hutton (LPA) 020 7364 5372
Margaret Margaret			
K	SITE NAME:	Braithwaite Viaduct, Bishopsgate Goods Yard, Wheler Street/Brick Lane EI	Early railway viaduct built 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003.
K		Bishopsgate Goods Yard,	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other
		Bishopsgate Goods Yard, Wheler Street/Brick Lane EI	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003.
	DESIGNATION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C)	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C)	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard,	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative,
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A	the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required. Contact: Mark Hutton (LPA) 020 7364 5372 Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative,
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Royal London Hospital – front block, Whitechapel Road,	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Royal London Hospital – front block, Whitechapel EI	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Fine C18 yellow brick hospital building fronting Whitechapel Road. The building has become redundant following development of new facilities</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Royal London Hospital – front block, Whitechapel EI Listed Building Grade II, CA	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Boyal London Hospital – front block, Whitechapel EI Listed Building Grade II, CA Fair	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Fine C18 yellow brick hospital building fronting Whitechapel Road. The building has become redundant following development of new facilities</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Coreant Royal London Hospital – front block, Whitechapel EI Listed Building Grade II, CA Fair Part occupied	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Fine C18 yellow brick hospital building fronting Whitechapel Road. The building has become redundant following development of new facilities</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Bishopsgate Goods Yard, Wheler Street/Brick Lane EI Listed Building Grade II Poor N/A C (C) Company Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI Listed Building Grade II Poor N/A D (D) Local authority Boyal London Hospital – front block, Whitechapel EI Listed Building Grade II, CA Fair	<ul> <li>the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished 2003. Master plan completed. Condition survey and other works to vaults required.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected 1860 but moved to present position 1879. The Local Authority has carried out cleaning, but repairs outstanding. Further restoration proposed as part of the High Street 2012 initiative, subject to available funding.</li> <li>Contact: Mark Hutton (LPA) 020 7364 5372</li> <li>Fine C18 yellow brick hospital building fronting Whitechapel Road. The building has become redundant following development of new facilities</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	2 Wilkes Street El	Early C18 terraced house. Three storeys with basement and attic in painted brick. Some repair works undertaken. Local authority to consider enforcement action.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	E (C)	
	OWNER TYPE:		Contact: Mark Hutton (LPA) 020 7364 5372
	OWNERTHE.	- Trivate	
	SITE NAME:	Church of St John on Bethnal Green, Cambridge Heath Road, Bethnal Green E2	Parish church of 1824 by Sir John Soane. Heavily restored and extended in C19 by William Munday and GF Bodley. Stock brick with artificial stone dressings and western portico. Phased programme of English Heritage/Heritage Lottery Fund grant-aided repairs underway to high level
A A A A A A	DESIGNATION:	Listed Place of Worship Grade I, CA	stonework and render.
	CONDITION:	Poor	
	PRIORITY:	F (F)	
THE REAL PROPERTY OF	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	London stock brick with stone dressings designed by G Austin and built 1836-9. Repairs to roofs and stonework have been undertaken. The church is being used with a marquee in the nave.
自制有三世口	DESIGNATION:	Listed Place of Worship Grade II, CA	
	CONDITION:	Fair	
	PRIORITY:	C (C)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
		5 5	1 0
	SITE NAME:	Sandy's Row Synagogue, Sandys Row, Bethnal Green El	Former Huguenot chapel which was altered mid-C19 as a synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered These will ultimately need
		Sandys Row,	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an
		Sandys Row, Bethnal Green El	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of
	DESIGNATION:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an
	DESIGNATION: CONDITION: PRIORITY:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000
	DESIGNATION: CONDITION: PRIORITY:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F)	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C)	synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C)	<ul> <li>synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Church built in 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate-faced concrete is exposing reinforcement which requires repair. A new</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C) Religious organisation Former Trinity Methodist Church (including attached hall and Church rooms),	<ul> <li>synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Church built in 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate-faced concrete is</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C) Religious organisation C (C) Religious organisation	<ul> <li>synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Church built in 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate-faced concrete is exposing reinforcement which requires repair. A new</li> </ul>
<image/>	DESIGNATION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C) Religious organisation Former Trinity Methodist Church (including attached hall and Church rooms), East India Dock Road, Poplar E14 Listed Place of Worship Grade II, CA	<ul> <li>synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Church built in 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate-faced concrete is exposing reinforcement which requires repair. A new</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Sandys Row, Bethnal Green EI Listed Place of Worship Grade II, CA Poor D (F) Religious organisation Gurdwara Sikh Sanghat, Harley Grove, Bow E3 Listed Place of Worship Grade II, CA Very bad C (C) Religious organisation Former Trinity Methodist Church (including attached hall and Church rooms), East India Dock Road, Poplar E14 Listed Place of Worship Grade II, CA Poor	<ul> <li>synagogue. Major re-roofing and high level brick repairs were completed in 2011 through the Repair Grants for Places of Worship scheme. Whilst scaffolding on the front elevation was in place for this work, bowing of the brickwork to the narrow piers between each of the arched windows to the first and second floors was discovered. These will ultimately need rebuilding. Meanwhile English Heritage has awarded an emergency grant towards the cost of temporary restraining of brickwork until permanent repair and funding can be resolved.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Stuccoed mid C19 classical building. Built as a chapel, converted to a synagogue in 1927 and re-opened as a Sikh Temple in 1979. Part of the rear is in use as the former Sunday School. The entire building was severely damaged by fire in 2009 and is currently propped by scaffolding.</li> <li>Contact: Principal Heritage at Risk Adviser 020 7973 3000</li> <li>Church built in 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. Spalling of aggregate-faced concrete is exposing reinforcement which requires repair. A new</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Priory and Hospital of St Mary Spital, Tower	Hamlets	
DESIGNATION:	Scheduled Monument (No.1001982)	CONDITION:	Generally unsatisfactory
	Public utilities		with major localised problems
PRINCIPAL VULNERABILITY:	Public utilities Private	TREND:	Declining Principal Heritage at Risk Adviser
OWNER TYPE:	rnvate	CONTACT:	020 7973 3000
SITE NAME:	Balfron Tower		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	London Hospital, Stepney		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
site name:	Redchurch Street, Bethnal Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	St Anne's Church		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	Stepney Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	Tower Hamlets Cemetery, Bow		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	Wentworth Street, Bethnal Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
SITE NAME:	Whitechapel High Street, Bethnal Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

#### HERITAGE AT RISK 2012 / LONDON / TOWER HAMLETS / WALTHAM FOREST

SITE NAME:	Wilton's Music Hall		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Mark Hutton (LPA) 0207 364 5372	NEW ENTRY?:	No
WALTHAM FOREST			

<b>N</b>	SITE NAME:	Wall to south east of St Mary's Churchyard, Church End EI7	C de	l 8 walls, formerly belonging molished, on the adjacent s	to a ho ite. In ne	use, now eed of repair:
A SALE AND A SALE OF	DESIGNATION:	Listed Building Grade II, CA				
	CONDITION:	Poor				
	OCCUPANCY:	N/A				
	PRIORITY:	A (A)				
	OWNER TYPE:	Private	Co	ontact: Ron Presswell (LPA)	020 849	96 6736
	SITE NAME:	698a High Road Leytonstone Leytonstone EII	Ge Br	obably late CI8. One of a s eorgian houses, for many ye itish Legion branch, Largely	ars the l vacant a	nome of the local nd up for sale.
	DESIGNATION:	Listed Building Grade II	Pla	anning application for conve	rsion to	flats currently
	CONDITION:	Poor	De	eing considered.		
	OCCUPANCY:	Part occupied				
	PRIORITY:	С (С)				
	OWNER TYPE:		Co	ontact: Ron Presswell (LPA)	020 849	96 6736
	SITE NAME:	Granada Cinema.	Bı	uilt 1929-30 as the Granada	Cinema	to the design of Cec
A BA	SITE INAME:	186 Hoe Street, Walthamstow E17	M: Tł	asey with fine Art Deco and neodore Komisarjevsky. Repa	d Mooris airs carri	h style interiors by ed out to the Hoe
CHERE C	DESIGNATION:	Listed Building Grade II*	St	reet frontage and canopy M	larch 20	2. Planning Inquiry
A RADIE	CONDITION:	Poor	CO	to refusal of application's for mmunity uses November 2	a place $0 2$ .	or worship and
	OCCUPANCY:	Part occupied				
	PRIORITY:	A (A)				
		Religious organisation	Co	ontact: Principal Heritage at	Risk Adv	viser 020 7973 3000
		5 5				
	SITE NAME:	Pimp Hall dovecote, King's Road, Chingford E4	str an	16 / C17 timber framed do ructure from the historic Ch d Buckerells. Currently in a eterioration of the timber from the timber from the tim	ningford poor co	Manor of Gowers ndition as a result of
	DESIGNATION:	Listed Building Grade II	ue			repeated varidalism.
	CONDITION:	Poor				
	OCCUPANCY:	N/A				
	PRIORITY:	С (С)				
	OWNER TYPE:	Local authority	Co	ontact: Ron Presswell (LPA)	020 849	96 6736
	SITE NAME:	Chapel to south of main hospital block, Langthorne Road EII	18	osed chapel to hospital (for 40. Roof tiles slipped and bi d water-tight.		
	DESIGNATION:	Listed Building Grade II				
	CONDITION:	Poor				
	OCCUPANCY:	Vacant				
	PRIORITY:	С (Е)				
	OWNER TYPE:	Health Authority	Са	ontact: Ron Presswell (LPA)	020 849	96 6736
	SITE NAME:	Lodge south of main hospital Langthorne Road EI I	Be	40 lodge to hospital (forme ing maintained; long-term u part of hospital site.	erly a wo ise to be	rkhouse). determined
	DESIGNATION:	Listed Building Grade II				
	CONDITION:	Poor				
	OCCUPANCY:	Vacant				
and the second sec	PRIORITY:	C (C)				
	OWNER TYPE:		Co	ontact: Ron Presswell (LPA)	020 849	96 6736
IDRITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	E Under rep repair, but under thre obvious ne	y solution agreed F Repair sche t implemented. and (where air or in fair to good en user idmutificat ar so users idmutificat ar	eme in progress : applicable) user identified; redundant building se agreed but not	NOTE: 2011 priority categories are given in brackets.	ABBREV CA LB LPA NP RPG SM UA	

#### HERITAGE AT RISK 2012 / LONDON / WALTHAM FOREST / WANDSWORTH

	SITE NAME:	Chingford Mill Pumping Station, Lower Hall Lane E4	Pumping station built 1895 for East London Water Works, in a variant of the style popularised by Norman Shaw. Planning permission and listed building consent for
	DESIGNATION:	Listed Building Grade II	residential use granted in 2007 subject to a Section 106 agreement. Currently the subject of enforcement action
	CONDITION:	Poor	for unauthorised works.
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built 1895 for East London Water Works. Planning permission and listed building consent for residential use granted in 2007 subject to a Section 106 agreement. Currently the subject of
	DESIGNATION:	Listed Building Grade II	enforcement action for unauthorised works.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
A A A	OWNER TYPE:	Private	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	133 Whipps Cross Road, Leytonstone EI1	One of six survivors from an original terrace of 12 'middle-class' three storey houses called Assembly Row. Built in 1767 on the high ground at the edge of the forest
	DESIGNATION:	Listed Building Grade II, CA	land, and within Leytonstone Conservation Area. Planning consent and listed building consent for conversion into
	CONDITION:	Poor	flats refused in 2005 and upheld on appeal. Occupied but
	OCCUPANCY:	Occupied	in deteriorating condition.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Ron Presswell (LPA) 020 8496 6736
WANDSWORTH			
	SITE NAME:	Battersea Park Station, Battersea Park Road SW8	Italianate style railway station built circa 1865 for the London, Brighton and South Coast Railway. Applications for alterations, repairs and refurbishment to station building and discharge conditions regarding redecoration, approved.
	DESIGNATION:	Listed Building Grade II, CA	Works commenced 2011 and expected completion by
	CONDITION:	Fair	late 2012.
	OCCUPANCY:	Part occupied	
	PRIORITY:	F (D)	
	OWNER TYPE:	Company	Contact: Barry Sellers (LPA) 020 8871 6631
	SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII	Church School of I 866-67 designed by Benjamin Ferrey. The building is now vacant. Report on structural condition commissioned by owners found the building wind and
			The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association
		Battersea Rise SWII	The building is now vacant. Report on structural condition commissioned by owners found the building wind and
E H	DESIGNATION:	Battersea Rise SWI I Listed Building Grade II, CA Poor	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association
	DESIGNATION:	Battersea Rise SWI I Listed Building Grade II, CA Poor	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association
	DESIGNATION: CONDITION: OCCUPANCY:	Battersea Rise SWI I Listed Building Grade II, CA Poor Vacant	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Battersea Rise SW11 Listed Building Grade II, CA Poor Vacant A (A) Religious organisation Ice house in the grounds of Burntwood Secondary School, Beechcroft Road, Tooting SW17	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association with Parish. Feasibility appraisal to be carried out. Contact: Barry Sellers (LPA) 020 8871 6631 Circular domical icehouse in brown and yellow brick covered by earth mound with retaining walls to approach. Probably C18. Poor but stable condition. Linked with
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE:	Battersea Rise SW11 Listed Building Grade II, CA Poor Vacant A (A) Religious organisation Ice house in the grounds of Burntwood Secondary School, Beechcroft Road, Tooting SW17	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association with Parish. Feasibility appraisal to be carried out. Contact: Barry Sellers (LPA) 020 8871 6631 Circular domical icehouse in brown and yellow brick covered by earth mound with retaining walls to approach. Probably C18. Poor but stable condition. Linked with Springfield Hospital redevelopment which is awaiting
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Battersea Rise SW11 Listed Building Grade II, CA Poor Vacant A (A) Religious organisation Ice house in the grounds of Burntwood Secondary School, Beechcroft Road, Tooting SW17	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association with Parish. Feasibility appraisal to be carried out. Contact: Barry Sellers (LPA) 020 8871 6631 Circular domical icehouse in brown and yellow brick covered by earth mound with retaining walls to approach. Probably C18. Poor but stable condition. Linked with
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Battersea Rise SW11 Listed Building Grade II, CA Poor Vacant A (A) Religious organisation Listed Building Grade II Poor N/A	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association with Parish. Feasibility appraisal to be carried out. Contact: Barry Sellers (LPA) 020 8871 6631 Circular domical icehouse in brown and yellow brick covered by earth mound with retaining walls to approach. Probably C18. Poor but stable condition. Linked with Springfield Hospital redevelopment which is awaiting outcome of appeal. Funding set out in draft Section
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: STEE NAME: STEE NAME: CONDITION: CONDITION: CONDITION: PRIORITY:	Battersea Rise SW11         Listed Building Grade II, CA         Poor         Vacant         A (A)         Religious organisation         Ice house in the grounds of Burntwood Secondary School, Beechcroft Road, Tooting SW17         Listed Building Grade II         Poor	The building is now vacant. Report on structural condition commissioned by owners found the building wind and weathertight. Owners discussing potential use in association with Parish. Feasibility appraisal to be carried out. Contact: Barry Sellers (LPA) 020 8871 6631 Circular domical icehouse in brown and yellow brick covered by earth mound with retaining walls to approach. Probably C18. Poor but stable condition. Linked with Springfield Hospital redevelopment which is awaiting outcome of appeal. Funding set out in draft Section

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

1	SITE NAME:	Battersea Power Station, Cringle Street SW8	Power station built 1932 onwards. Closed and vacated in 1983. Planning and listed building applications approved 2011, subject to legal agreement, for restoration, extension
	DESIGNATION:	Listed Building Grade II*	and conversion of Power Station to provide mixed use
	CONDITION:	Very bad	facilities, but current owners placed in receivership. Expressions of interest to be submitted to Official
	OCCUPANCY:		Receivers by summer 2012.
	PRIORITY:	D (D)	
*	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Battersea Pumping Station, Cringle Street SW8	Water pumping station, circa I 846. Linked to development of Battersea Power Station. Separate demolition of boiler house agreed in 2002 in advance of works to engine house. Archaeological report and building recording
	DESIGNATION:	Listed Building Grade II	completed. Application to demolish approved August 2011.
	CONDITION:	Very bad	Current owners placed in receivership and Official Receiver
h c a c	OCCUPANCY:		requested details of expressions of interest summer 2012.
	PRIORITY:	D (D)	
Carlo and a second	OWNER TYPE:	Company	Contact: John Webb (LPA) 020 8871 6645
	SITE NAME:	Springfield Hospital (main building), Glenburnie Road SW17	Former Psychiatric hospital built 1840 in Tudor Gothic style as the Surrey County Asylum. Revised planning application for the redevelopment of site and demolition of curtilage listed buildings refused in December 2010. Public enquiry
	DESIGNATION:	Listed Building Grade II, RPG II	held in October 2011. Inspector's decision due spring 2012.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	С (С)	
and the second sec	OWNER TYPE:	Health Authority	Contact: Barry Sellers (LPA) 020 8871 6631
A CONTRACTOR OF	SITE NAME:	Tomb of Cotterell and Allen, Huguenot Place, Huguenot Burial Ground SW18	Table tomb from 1843. The moulded top slab is cracked in the middle and vegetation is growing through it.
	SITE NAME: DESIGNATION:	Huguenot Place, Huguenot Burial Ground SW18	
		Huguenot Place, Huguenot Burial Ground SW18	
	DESIGNATION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor	
	DESIGNATION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor	
	DESIGNATION: CONDITION: OCCUPANCY:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry)	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry)	in the middle and vegetation is growing through it.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry)	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street,	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F)	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F)	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F)	in the middle and vegetation is growing through it. Contact: Barry Sellers (LPA) 020 8871 6631 C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F)	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012.</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F) Company Temple in the grounds of Mount Clare, Minstead Gardens SW15	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012. Long-term strategy for Temple awaited following</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Huguenot Place, Huguenot Burial Ground SW18	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012.</li> </ul>
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F) Company Temple in the grounds of Mount Clare, Minstead Gardens SW15 Listed Building Grade II*, CA Poor	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012. Long-term strategy for Temple awaited following</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F) Company Temple in the grounds of Mount Clare, Minstead Gardens SW15 Listed Building Grade II*, CA Poor	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012. Long-term strategy for Temple awaited following</li> </ul>
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Huguenot Place, Huguenot Burial Ground SW18 Listed Building Grade II, CA Poor N/A A (New entry) Unknown The Montague Arms, 3 Medfield Street, Roehampton Village SW15 Listed Building Grade II, CA Fair Vacant F (F) Company Temple in the grounds of Mount Clare, Minstead Gardens SW15 Listed Building Grade II*, CA Poor N/A	<ul> <li>in the middle and vegetation is growing through it.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>C17 house converted into a public house in the 1860s. Vacant. Applications for change of use from public house to retail or office uses on ground floor with residential above approved in June 2010. Works to flats substantially complete with ground floor commercial to follow.</li> <li>Contact: Barry Sellers (LPA) 020 8871 6631</li> <li>Temple 1762-69. Some damage caused by vandalism following unauthorised access. Site has been re-secured, minor works of repair to the roof undertaken 2012. Long-term strategy for Temple awaited following</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

DESIGNATION:       Listed Building Grade II         CONDITION:       Poor         OCCUPANCE:       Part occupied         PRIORITY:       D (D)         OWNERTIFYE       Religious organisation         STE INAME:       Queenstown Road Station, Queenstown Road SW8         STE INAME:       Queenstown Road SW8         Station built in 1877. Repairs needed to doors, windows and floors of disused areas of this unattended station. Former station ticket office re-used for cafe and redecoration to lobby area completed 2010. Owners report funding in place for repair works 2012-13. Listed building consent application expected 2012.         OCUPANCE:       Part occupied PRIORITY:       D (D)         OWNERTIFYE       Company       Contact: Barry Sellers (LPA) 020 8871 6631
CONDITION       Poor         OCCUPANCY:       Part occupied         PRORITY:       D (D)         OWNERTYPE       Religious organisation         Construction       Queenstown Road Station, Queenstown Road Stw8         STE NAME:       Queenstown Road Station, Queenstown Road SW8         DESIGNATION:       Listed Building Grade II, CA         CONDITION:       Poor         OCCUPANCY:       Part occupied         PRORITY:       D (D)         OWNERTYPE:       Condect II, CA         CONDITION:       Poor         OCCUPANCY:       Part occupied         PRORITY:       D (D)         OWNERTYPE:       Condect II, CA         CONDITION:       Poor         CONDITION:       Poor         OCCUPANCY:       Part occupied         PRORITY:       D (D)         OWNERTYPE:       Company         Contact:       Barry Sellers (LPA) 020 8871 6631          STE NAME:       King's Head public house, I Roehampton High Street SW15
PRIORITY:       D (D)         OWNERTYPE       Religious organisation         Contact: John Webb (LPA) 020 8871 6645         STE NAME:       Queenstown Road Station, Queenstown Road Styv8         STE NAME:       Queenstown Road Station, Queenstown Road SW8         DESIGNATION:       Listed Building Grade II, CA         CONDITION:       Poor         OCCUPANCY:       Part occupied         PRIORITY:       D (D)         WWNERTYPE:       Company         Contact: Barry Sellers (LPA) 020 8871 6631         STE NAME:       King's Head public house, I Roehampton High Street SW15         C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
OWNERTYPE       Religious organisation       Contact: John Webb (LPA) 020 8871 6645         Image: Strephone Station of the strephone Station Station Station Station of the strephone Station Statis and strephone Station Station Statis and station Sta
STE NAME:       Queenstown Road Station, Queenstown Road SW8       Station built in 1877. Repairs needed to doors, windows and floors of disused areas of this unattended station. Former station ticket office re-used for cafe and redecoration to lobby area completed 2010. Owners report funding in place for repair works 2012-13. Listed building consent application expected 2012.         OCCUPANCY:       Part occupied PRIORITY:       D (D) OWNER TYPE         OWNER TYPE       Company         STE NAME:       King's Head public house, I Roehampton High Street SW15         C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
Queenstown Road SW8       and floors of disused areas of this unattended station. Former station ticket office re-used for cafe and redecoration to lobby area completed 2010. Owners report funding in place for repair works 2012-13. Listed building consent application expected 2012.         OCLUPANCY:       Part occupied PRIORITY:       D (D)         OWNERTYPE       Company         SITE NAME:       King's Head public house, I Roehampton High Street SW15       C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
Queenstown Road SW8       and floors of disused areas of this unattended station. Former station ticket office re-used for cafe and redecoration to lobby area completed 2010. Owners report funding in place for repair works 2012-13. Listed building consent application expected 2012.         OCLUPANCY:       Part occupied PRIORITY:       D (D)         OWNERTYPE       Company         SITE NAME:       King's Head public house, I Roehampton High Street SW15       C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
DESIGNATION:       Listed Building Grade II, CA       report funding in place for repair works 2012-13.         CONDITION:       Poor       Designation:       Designation:         OCCUPANCY:       Part occupied       PRORITY:       D (D)         WINER TYPE       Company       Contact: Barry Sellers (LPA) 020 8871 6631         SITE NAME:       King's Head public house, I Roehampton High Street SW15       C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
Image: State of the number
PRIORITY:       D (D)         OWNERTYPE       Company         Contact: Barry Sellers (LPA) 020 8871 6631         SITE NAME:       King's Head public house, I Roehampton High Street SW15         C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
OWNERTYPE       Company       Contact: Barry Sellers (LPA) 020 8871 6631         Image: Stre NAME:       King's Head public house, I Roehampton High Street SW15       C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
SITE NAME: King's Head public house, I Roehampton High Street SW15 C17 public house. Vacant but in fair condition. Planning and listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
I Roehampton High Street SW15 listed building consent applications approved October 2010 for alterations and creation of two 2 flats in stable block in
DESIGNATION: Listed Building Grade II, CA conjunction with re-use as a public house. Works being tendered with a view to being carried out 2012-13.
CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: F(D)
OWNERTYPE: Company Contact: John Webb (LPA) 020 8871 6645
STE NAME STE NAME The Watchers, behind Downshire House, Roehampton Lane, STE NAME STE NAME Sculpture of 1960 by Lynn Chadwick and installed in 1963 by the London County Council. The sculpture has been temporarily removed following vandalism
Roehampton SW15 and carefully stored. Further discussions held in 2011 with owners about reinstatement
Roehampton SW15       and carefully stored. Further discussions held in 2011 with owners about reinstatement.         DESIGNATION: Listed Building Grade II, CA       and carefully stored. Further discussions held in 2011
with owners about reinstatement.
With owners about reinstatement.
DESIGNATION:       Listed Building Grade II, CA         CONDITION:       Poor
Image: Construction of the construc
Image: Stream provide and stream provid
International procession of the second se
Image: Strema bill (Strema bill)       Image: Strema bill (Strema bil
International procession of the second se
International procession of the second se
International procession of the second se
International period of the
View of the second processing of the second procesing of the second processing of the second processing of the seco
Initial period of the listed Building Grade II, CA       with owners about reinstatement.         Designations       Educational Body         CONDITION:       POOR         OCCUPANCY:       N/A         PRORITY:       C (C)         OWNERTYPE       Educational Body         STE NAME       Former Gala Bingo Hall (Granada), 58 St John's Hill SW1 I         Ste St John's Hill SW1 I       Contact: Barry Sellers (LPA) 020 8871 6631         Designation:       Listed Building Grade II*         CONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY:       F (F)         ONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY:       F (F)         ONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY:       F (F)         ONNERTYPE       Company         Contact: Principal Heritage at Risk Adviser 020 7973 3000         STE NAME:       100 Tooting Bec Road SW17         Early C19 stucco lodge.Vacant and in need of repair:         Planing and listed building consent applications for extension and refurbishment and two additional dwellings in rear earcher areached Divide add Upicelings in rear earcher areached Divide add Upicelings in rear earcher areached Discuered Discuering and Discuering and Discuering and Discuering a
With owners about reinstatement.         Designation:       Listed Building Grade II, CA         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY::       C (C)         OWNERTYPE:       Educational Body         STE NAME:       Former Gala Bingo Hall (Granada), 58 St John's Hill SW I         STE NAME:       Former Gala Bingo Hall (Granada), 58 St John's Hill SW I         Designation:       Listed Building Grade II*         CONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY::       F (F)         ONDERTON:       Listed Building Grade II*         CONDITION:       Poor         OCCUPANCY:       Vacant         PRORITY::       F (F)         ONNERTYPE:       Company         STE NAME:       100 Tooting Bec Road SW17         STE NAME:       100 Tooting Bec Road SW17
International development and international internaterational international international interna
International internatinterational international international intern
Instrumption of the procession of the procesion of the procession of the procession of th

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

HERITAGE AT RISK 2012 / LONE	on / wane	DSWORTH / WESTMINSTER, CITY OF	
	SITE NAME:	Former Bolingbroke Hospital, Wakehurst Road SW11	Hospital built in 1901-1936 by Young and Hall Vacant following redundancy. Planning and listed building consent applications approved October 2011 for use of building as
	DESIGNATION:	Listed Building Grade II, CA	a free school (Bolingbroke Academy). Works underway with completion expected September 2012.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F(D)	
	OWNER TYPE:	Local authority	Contact: Barry Sellers (LPA) 020 8871 6631
WESTMINSTER, CITY	OF		
	SITE NAME:	Crockers public house, 23-24 Aberdeen Place NW8	Public house circa 1900. Formerly known as "The Crown". Has been closed since autumn 2004. Temporary works have been undertaken to secure the building and to make weathertight. Planning permission and listed building
	DESIGNATION:	Listed Building Grade II*, CA	consent were granted in November 2011 to allow use of
	CONDITION:	Fair	upper floors as residential flats. Work has yet to commence on implementing this scheme.
	OCCUPANCY:	Part occupied	on implementing this scheme.
	PRIORITY:	D (C)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	Bow Street Magistrates' Court and Police Station, Bow Street WC2	Court and Police Station. 1879-80. Greco Roman style with Vanbrughian details. Some repair works have been undertaken to ensure the building is weathertight and secure. An application has been submitted which seeks
	DESIGNATION:	Listed Building Grade II, CA	an extension of time to a 2008 permission for works of
	CONDITION:	Fair	conversion to a hotel, museum and interpretive centre,
	OCCUPANCY:	Vacant	including a substantial rear extension.
	PRIORITY:	D (D)	
and the second s	OWNER TYPE:	Company	Contact: Lucy Metcalfe (LPA) 020 7641 2169
	SITE NAME:	21 Charles Street WI	Terraced town house circa 1750-53. Some unauthorised works have taken place. Planning permission and listed building consent granted in July 2008 for various works
	DESIGNATION:	Listed Building Grade II, CA	including demolition and rebuilding of the mews building to the rear. Street elevation has been cleaned and repaired
	CONDITION:	Poor	in 2011-12.
	OCCUPANCY:	Vacant	
- In Reason and the second	PRIORITY:	D (D)	
	OWNER TYPE:	Unknown	Contact: Robert Ayton (LPA) 020 7641 2978
	SITE NAME:	39 Charles Street, Mayfair WI	Main house dates from 1750s and includes mews buildings at rear. The main house is currently suffering from severe structural problems. Consent was granted
	DESIGNATION:	Listed Building Grade II*, CA	in June 2011 for temporary structural bracing to the rear, which has been implemented. The condition of the building
	CONDITION:	Poor	is now being monitored. Permission was granted in January
	OCCUPANCY:	Vacant	2009 for works of conversion and extension, but has yet
	PRIORITY:	B (D)	to be implemented.
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	76 Dean Street, Soho WI	Terraced town house dating from 1730s. The property was seriously damaged by fire in 2009. Permission was granted in August 2011 for various works of demolition
	DESIGNATION:	Listed Building Grade II*, CA	and reconstruction associated with an office use. However, the ownership of the building has since
	CONDITION:	Very bad	changed and the Council are currently engaged in
	OCCUPANCY:	Vacant	new pre-application discussions.
	PRIORITY:	B (A)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.


E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

	SITE NAME:	112 Eaton Square SWI	Grand terrace house, circa 1825. Building is suffering from neglect, water ingress and a serious outbreak of dry rot.
			Works to improve the building are underway on site.
Carle and the		Listed Building Grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:		
	PRIORITY:	E (B)	Contact Drin size I I I with an at Did. Addison 020 7072 2000
	OWNER TYPE:	Frivate	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	46 and 52 Gloucester Place WI	Terraced houses built 1790-1800 for the Portman Estate. Permission and consent has been granted in May 2011 for various works of alteration at No. 46, including renewal of
	DESIGNATION:	Listed Building Grade II, CA	roof coverings. Works have yet to commence. Works of refurbishment are underway at No. 52.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNER TYPE:	Company	Contact: Lucy Metcalfe (LPA) 020 7641 2169
		. ,	
	SITE NAME:	94 and 100 Gloucester Place WI	Terraced houses built circa I 800 for the Portman Estate. Mainly vacant. Listed building consent was granted in July 2009 for the internal refurbishment and alterations to
HALL BE B	DESIGNATION:	Listed Building Grade II, CA	No. 100. Works have yet to be implemented.
	CONDITION:	Poor	
and the second s	OCCUPANCY:	Part occupied	
	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Robert Ayton (LPA) 020 7641 2978
	SITE NAME:	2-5 (consecutive) Hertford Street WI	Part of a block of terraced houses, some with shops. Mid to late C18. Linked to scheme for 35 Shepherd Market, 20 Shepherd Street, and numbers 2, 2A, 4-8 (aug) Techeol, Street, learning but still upper surgiced
			(even) Trebeck Street. Largely repaired but still unoccupied.
	DESIGNATION:	Listed Building Grade II, CA	Consent granted in 2010 for further alterations and use of
	DESIGNATION: CONDITION:	Listed Building Grade II, CA Fair	Consent granted in 2010 for further alterations and use of
		Fair	Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.
	CONDITION:	Fair Vacant	Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and
	CONDITION: OCCUPANCY: PRIORITY:	Fair Vacant F (F)	Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.
	CONDITION: OCCUPANCY: PRIORITY:	Fair Vacant	Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and
	CONDITION: OCCUPANCY: PRIORITY:	Fair Vacant F (F)	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Fair Vacant F (F) Company	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions,</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Fair Vacant F (F) Company <b>41 Lancaster Gate W2</b>	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions,</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions,</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D)	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions,</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D)	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D)	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D) Company Middlesex Hospital Chapel, Mortimer street, East Marylebone W1	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for the surrounding site has been agreed subject to legal</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D) Company Middlesex Hospital Chapel, Mortimer street, East Marylebone W1	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNERTYPE SITE NAME: SITE NAME:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D) Company Middlesex Hospital Chapel, Mortimer street, East Marylebone W1 Listed Building Grade II*, CA Fair	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for the surrounding site has been agreed subject to legal</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D) Company Middlesex Hospital Chapel, Mortimer street, East Marylebone W1 Listed Building Grade II*, CA Fair	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for the surrounding site has been agreed subject to legal</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Fair Vacant F (F) Company 41 Lancaster Gate W2 Listed Building Grade II, CA Poor Vacant D (D) Company Middlesex Hospital Chapel, Mortimer street, East Marylebone W1 Listed Building Grade II*, CA Fair Vacant D (D)	<ul> <li>Consent granted in 2010 for further alterations and use of the building for a private members' restaurant, retail and residential units.</li> <li>Contact: Matthew Pendleton (LPA) 020 7641 5971</li> <li>Part of a grand terrace of houses, 1865. Stucco with Doric porches. The building has suffered from poor maintenance and the removal of some internal plasterwork. Permission and consent granted in October 2011 for extensions, alterations and refurbishment. Has yet to be implemented.</li> <li>Contact: Alistair Taylor (LPA) 020 7641 2979</li> <li>Hospital, built 1891 by John Loughborough Pearson, completed 1929 by his son Frank Loughborough Pearson, in Italian Gothic style. A new redevelopment scheme for the surrounding site has been agreed subject to legal</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2012 / LONDON / WESTMINSTER, CITY OF

TRUE	site name:	Railings around Crescent Gardens, Regents Park, Park Crescent WI	Railings of circa 1812. Part of wider scheme for repair of paving, railings, gates and lodges in the park. Railings in places cracked and fractured. A major repair scheme,
	DESIGNATION:	Listed Building Grade II, CA	part funded by English Heritage, is currently underway with phases I and II completed. Phase III is currently in progress.
	CONDITION:	Fair	
AND IS IN SUPPORT F	OCCUPANCY:	N/A	
Not City	PRIORITY:	F (F)	
- AL	OWNER TYPE:	Crown	Contact: Matthew Pendleton (LPA) 020 7641 5971
	SITE NAME:	138 Park Lane WI	Large 1832 house, split into flats in the 1920s, ground floor retail units. Has been empty and boarded for a number of years; squatters have caused serious damage. Condition deteriorating. Planning permission and listed
	DESIGNATION:	Listed Building Grade II, CA	building consent were granted in February 2012 for the
HILL - HILF EAR	CONDITION:	Poor	use of the ground and basement floors for either retail
	OCCUPANCY:		or financial and professional services; and for the upper floors to be used as flats
	PRIORITY:	D (C)	
	OWNER TYPE:	Company	Contact: Matthew Pendleton (LPA) 020 7641 5971
	SITE NAME:	94 Piccadilly WI	Town Mansion of 1756-1760 by Matthew Brettingham for Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Building
bathaa	DESIGNATION:	Listed Building Grade I, CA	under new ownership. English Heritage and the Local Authority are monitoring the site. Pre-application
	CONDITION:	Poor	proposals are being prepared.
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	95 Piccadilly WI	A grade II town house dating from 1886. Now forms part of a larger site with Former Naval and Military Club.
		<b>95 Piccadilly WI</b> Listed Building Grade II, CA	
	DESIGNATION:	Listed Building Grade II, CA Poor Vacant	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Vacant C (C)	of a larger site with Former Naval and Military Club.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Vacant	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Vacant C (C)	of a larger site with Former Naval and Military Club.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair Vacant	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair Vacant E (E)	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY: OWNER TYPE:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place W1 Listed Building Grade II*, CA Fair Vacant E (E) Company Wharf side shelter and store to rear of builders' merchants, 22 Praed Street W2	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington Basin. The shelter will be re-erected as part of the
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place W1 Listed Building Grade II*, CA Fair Vacant E (E) Company Wharf side shelter and store to rear of builders' merchants, 22 Praed Street W2	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair Vacant E (E) Company Wharf side shelter and store to rear of builders' merchants, 22 Praed Street W2 Listed Building Grade II Fair	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington Basin. The shelter will be re-erected as part of the
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair Vacant E (E) Company Wharf side shelter and store to rear of builders' merchants, 22 Praed Street W2 Listed Building Grade II Fair	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington Basin. The shelter will be re-erected as part of the
<image/>	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Listed Building Grade II, CA Poor Vacant C (C) Company 26 Portland Place WI Listed Building Grade II*, CA Fair Vacant E (E) Company Wharf side shelter and store to rear of builders' merchants, 22 Praed Street W2 Listed Building Grade II Fair Vacant Yacant	of a larger site with Former Naval and Military Club. Contact: Matthew Pendleton (LPA) 020 7641 5971 Main house circa 1770s, with some C18 interiors. Works have commenced on site and are nearing completion. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Wharf side shelter and store circa 1840. Brick ground floor with timber first floor with large slated hipped roof. Part of redevelopment scheme for Paddington Basin. The shelter will be re-erected as part of the

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	35 Shepherd Market WI	Part of a block of terraced houses, some with shops. Mid to late C18. Scheme for alterations, refurbishment and change of use is being implemented.
	DESIGNATION:	Listed Building Grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
Production and a second	OWNER TYPE:	Company	Contact: Matthew Pendleton (LPA) 020 7641 5971
	SITE NAME:	20 Shepherd Street WI	Terraced house, probably late C18 with mid C20 shop front across ground floor. Part of a group with 2-5 Hertford Street, 35 Shepherd Market, 2, 2a and 4-8 Techeck Street, Planning pagesizion and listed building
	DESIGNATION:	Listed Building Grade II, CA	Trebeck Street. Planning permission and listed building consent granted for further alterations and use of
2 23 11 11 11 11 11 11 11 11 11 11 11 11 11	CONDITION:	Fair	building for a private members' restaurant, retail and
一 一 古 田	OCCUPANCY:	Vacant	seven residential units.
	PRIORITY:	F (F)	
	OWNER TYPE:	Company	Contact: Matthew Pendleton (LPA) 020 7641 5971
ER DOM Statistics	SITE NAME:	2, 2A and 4-8 (even) Trebeck Street WI	Part of a block of terraced houses, some with shops. Mid to late C18. Largely repaired but still unoccupied. Planning permission and listed building consent granted in February 2010 for further alterations and use of the
	DESIGNATION:	Listed Building Grade II, CA	building for a private members' restaurant, retail and
	CONDITION:	Fair	seven residential units.
	OCCUPANCY:		
	PRIORITY:	F (F)	
	OWNER TYPE:	Company	Contact: Matthew Pendleton (LPA) 020 7641 5971
	SITE NAME:	21 Upper Grosvenor Street WI	Terraced town house circa 1732. Building suffering from general lack of maintenance and repair with water ingress. Current application being considered for extension of
		21 Upper Grosvenor Street WI Listed Building Grade II, CA	general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted
			general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association
	DESIGNATION:	Listed Building Grade II, CA Poor	general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for
	DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor	general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association
	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Vacant B (A)	general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Listed Building Grade II, CA Poor Vacant B (A)	general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company 140 Westbourne Terrace W2	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F)	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F)	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F)	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F)	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> <li>Contact: John Wilman (LPA) 020 7641 2561</li> <li>Former Parish School and Church House dating from 1868-70 by William Butterfield. Building in full-time occupation and used for worship, library and residential accommodation. Substantial repairs are required to the</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company 140 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F) Company Buddhist Temple,	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> <li>Contact: John Wilman (LPA) 020 7641 2561</li> <li>Former Parish School and Church House dating from 1868-70 by William Butterfield. Building in full-time occupation and used for worship, library and residential</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company 140 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F) Company Buddhist Temple, Margaret Street W1	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> <li>Contact: John Wilman (LPA) 020 7641 2561</li> <li>Former Parish School and Church House dating from 1868-70 by William Butterfield. Building in full-time occupation and used for worship, library and residential accommodation. Substantial repairs are required to the roofs and external facades. An English Heritage grant has</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F) Company Buddhist Temple, Margaret Street W1 Listed Place of Worship Grade II*	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> <li>Contact: John Wilman (LPA) 020 7641 2561</li> <li>Former Parish School and Church House dating from 1868-70 by William Butterfield. Building in full-time occupation and used for worship, library and residential accommodation. Substantial repairs are required to the roofs and external facades. An English Heritage grant has</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Listed Building Grade II, CA Poor Vacant B (A) Company I40 Westbourne Terrace W2 Listed Building Grade II, CA Good Occupied F (F) Company Buddhist Temple, Margaret Street W1 Listed Place of Worship Grade II* Poor	<ul> <li>general lack of maintenance and repair with water ingress. Current application being considered for extension of time for commencement of a scheme previously granted permission and consent in 2009. This scheme was for alteration and extension of the property in association with use as a single residential unit.</li> <li>Contact: Robert Ayton (LPA) 020 7641 2978</li> <li>Detached villa dated to 1843-8 in Italianate style. Occupied as a number of bedsits. Planning permission and listed building consent were refused in November 2011 for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised works. This is currently being investigated as an enforcement matter.</li> <li>Contact: John Wilman (LPA) 020 7641 2561</li> <li>Former Parish School and Church House dating from 1868-70 by William Butterfield. Building in full-time occupation and used for worship, library and residential accommodation. Substantial repairs are required to the roofs and external facades. An English Heritage grant has</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME:	Church of St Mary Magdalene, Rowington Close, Paddington W2	1867-78 by GE Street, with crypt chapel of St Sepulchre of 1895 by Sir Ninian Comper. An exceptional High Victorian Gothic church with complete internal decorative scheme. Roof repairs completed with English Heritage grant in 2008 but further work required for which
	DESIGNATION:	Listed Place of Worship Grade I, CA	English Heritage has offered grant aid.
Adda Torres a	CONDITION:	Poor	
A CALL CALL CALT	PRIORITY:	B (B)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
ANT	SITE NAME:	Church of St Mark, Hamilton Terrace, Paddington NW8	Gothic church dating from 1846-7 by Thomas Cundy Senior with spire by Thomas Cundy Junior. English Heritage grant offered towards urgent repairs.
AND	DESIGNATION:	Listed Place of Worship Grade II*	
	CONDITION:	Very bad	
	PRIORITY:	D (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 020 7973 3000
	SITE NAME:	St John the Evangelist Church, Harrow Road, Paddington W10	Church dates from 1843 and was designed by HE Kendall Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered in 2011 towards urgent repairs, now in Stage L
		Harrow Road,	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent
		Harrow Road, Paddington W10	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered
	DESIGNATION:	Harrow Road, Paddington W10 Listed Place of Worship Grade II	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered
	DESIGNATION:	Harrow Road, Paddington W10 Listed Place of Worship Grade II Very bad	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered
	DESIGNATION: CONDITION: PRIORITY:	Harrow Road, Paddington W10 Listed Place of Worship Grade II Very bad D (New entry)	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered in 2011 towards urgent repairs, now in Stage I.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Paddington W10 Listed Place of Worship Grade II Very bad D (New entry) Religious organisation Church of St Gabriel, Warwick Square,	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered in 2011 towards urgent repairs, now in Stage I. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Church dating from 1851-3 by the architect Thomas Cundy II. The elevations are largely faced in Kentish Raglan Stone and are in need of repair, particularly to the tower:
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	Harrow Road, Paddington W10 Listed Place of Worship Grade II Very bad D (New entry) Religious organisation Church of St Gabriel, Warwick Square, Westminster SW1	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered in 2011 towards urgent repairs, now in Stage I. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Church dating from 1851-3 by the architect Thomas Cundy II. The elevations are largely faced in Kentish Raglan Stone and are in need of repair, particularly to the tower:
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Harrow Road, Paddington W10 Listed Place of Worship Grade II Very bad D (New entry) Religious organisation Church of St Gabriel, Warwick Square, Westminster SW1 Listed Place of Worship Grade II*	Junior in a Romanesque style with Gothic chancel. Significant water ingress at roof level and subsequent deterioration of fabric. English Heritage grant offered in 2011 towards urgent repairs, now in Stage I. Contact: Principal Heritage at Risk Adviser 020 7973 3000 Church dating from 1851-3 by the architect Thomas Cundy II. The elevations are largely faced in Kentish Raglan Stone and are in need of repair, particularly to the tower:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at **www.english-heritage.org.uk/risk** 

HERITAGE AT RISK

Published September 2012 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2012