


NORTH EAST

Contents

HERITAGE AT RISK	II
THE REGISTER	VI
Content and criteria	VI
Criteria for inclusion on the Register	VII
Reducing the risks	×
Publications and guidance	XII
Key to the entries	X۷
Entries on the Register by local planning authority	XVI
County Durham (UA)	I
Northumberland (UA)	11
Northumberland (NP)	30
Tees Valley Darlington (UA) Hartlepool (UA) Middlesbrough (UA) North York Moors (NP) Redcar and Cleveland (UA) Stockton-on-Tees (UA)	38 40 41 41 41
Tyne and Wear Gateshead Newcastle upon Tyne North Tyneside South Tyneside Sunderland	44 44 48 48 49

II





Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results. Heritage at Risk teams are now in each of our nine local offices, delivering national expertise locally.

The good news is that we are on target to save 25% (1,137) of the sites that were on the Register in 2010 by 2015. From Clifford's Fort, North Tyneside

to the Church of St Andrew, Haughton le Skerne, this success is down to good partnerships with owners, developers, the Heritage Lottery Fund (HLF), Natural England, councils and local groups. It will be increasingly important to build on these partnerships to achieve the overall aim of reducing the number of sites on the Register. Carol Pyrah, Planning and Conservation Director, North East

Despite the continued recession, the number of sites on the Register continues to fall. The economic climate may be uncertain, but successful partnerships across the North East are removing many important heritage assets from the Register. This year we have successfully removed 12 entries and offered £566,000 in grant towards 9 heritage at risk projects.

Not all our grant funding goes on repair. An increasing amount is being used to carry out detailed surveys and options appraisals to help owners understand issues and options. This reduces risks when investing in schemes to reuse buildings or regenerate conservation areas. Although we have a number of success stories this year we still have a high percentage of grade I and II* buildings at risk in the North East (7.1%) and the number of scheduled monuments at risk is increasing. The greatest threat to monuments is poorly managed plant, tree and scrub growth: in the North East 46% of archaeological sites on the Register are suffering from unrestricted plant growth (often bracken). We are working with Natural England and the Northumberland National Park to develop new ways of managing bracken across our upland landscapes. Everyone is managing a much tighter budget these days: every little bit of funding is vital. Partnerships that have removed heritage assets from the Register this year include the repair of Clifford's Fort, North Shields, part of the very successful regeneration of the Fish Quay; a project driven by a dynamic partnership of local businesses, residents and North Tyneside Council. Work continues at Ushaw College, a former Catholic seminary near Durham, where a partnership to reuse buildings has been developed between the Ushaw College Trustees and Durham University, and English Heritage has contributed £345,000 to the repair of the Bounds Wall. We are also delighted

that the HLF has continued to invest in the future of places of worship by supporting vital church repairs. HLF funding has also secured a future for the Bowes Railway Trust by helping them develop training, education and heritage skills. These projects are being successfully delivered by volunteers who deserve our support and encouragement.

Many of the sites that remain on the Register are ones where a solution will take many years to develop. With limited funding, we must explore new, effective and innovative ways of getting maximum value from our limited resources, focussing on assets where we are most likely to deliver successful projects. As the conservation deficit increases for individual properties, the challenge will be to bring together the people, organisations and developers with the energy and vision to deliver sustainable solutions. Dunston Staiths, Gateshead is a good example of just such a project. The seemingly impossible task of managing and repairing a huge structure from our industrial past is now underway thanks to a partnership between Tyne & Wear Building Preservation Trust, Gateshead Council, Durham Wildlife Trust, HLF and English Heritage.

Kate Wilson,

Principal Adviser, Heritage at Risk

Kate Lilson

USHAW HOME FARM, COUNTY DURHAM

The Home Farm at Ushaw formed the centre of the farming operation for Ushaw College, founded in 1808 as a Catholic seminary by refugees from English Catholic seminary and school at Douai in France. The farming operation at its height encompassed over 600 acres of mixed arable and grazing land. Listed at grade II*, the main farm building of three storeys incorporates cattle byres, haylofts, milking parlour, dairy, and machinery for milling and grinding. The Home Farm was designed by the architect Joseph Hansom in a Gothic style and constructed in 1852 at the height of interest in farm building design in England, and is a new entry on English Heritage's Heritage at Risk Register for 2013.

BUILDINGS AND STRUCTURES

- Nationally, 4.1% of grade I and II* listed buildings (excluding places of worship) are on the Register. In the North East the percentage is 7.1% (69 buildings).
- 6 building or structure entries have been removed from the 2012 North East Register because their futures have been secured, but 2 have been added.

PLACES OF WORSHIP

- Of the 487 listed places of worship assessed in the North East, 21 are on the Register.
- 2 places of worship have been removed from the 2012 Register following repair work.

ARCHAEOLOGY

- 3,265 (16.5%) of England's 19,792 scheduled monuments are on the Register, of which 194 are in the North East.
- 3 archaeology entries have been removed from the 2012 Register for positive reasons and 7 have been added.
- 21.8% of archaeology entries (37) on the North East baseline 2009 Register have been removed for positive reasons, compared to the national figure of 21.1%.
- Nationally, damage from arable cultivation is the greatest risk factor, accounting for 43% of those on the Register.
 In the North East the proportion is 11%. The greatest threat for 46% of entries on the North East Register is from unrestricted plant, scrub and tree growth.

PARKS AND GARDENS

• 100 (6.2%) of England's 1,624 registered parks and gardens are on the Register. In the North East, 3 are on the Register, the same as last year.

BATTLEFIELDS


• Of the 43 registered battlefields in England, 6 are on the Register. Of the 6 registered battlefields in the North East, I is on the Register.

WRECK SITES

• Of the 46 protected wreck sites around England's coast, 4 are on the Register. The North East's single protected wreck site is not on the Register.

CONSERVATION AREAS

- 8,179 of England's 9,839 conservation areas have been surveyed by local authorities. 510 (6.2%) are on the Register. Of the 270 conservation areas surveyed in the North East, 25 (9.3%) are on the Register.
- I conservation area has been removed from the 2012 North East Register for a positive reason, but 6 have been added.



UNION SUSPENSION BRIDGE, NORTHUMBERLAND

The Union Suspension Bridge was the longest wrought iron suspension bridge in the world when it opened in 1820 with a span of 137m (449 ft). Listed grade I, the bridge spans the River Tweed and the border between Northumberland (England), and Scotland. It was designed and built by Captain Samuel Brown, a naval officer in the Napoleonic Wars and later a chain manufacturer, who patented his invention of the wrought iron bar-linked chain used in the construction of this bridge. This is a new entry on English Heritage's Heritage at Risk Register.



CONSERVATION AREAS OF THE REGISTER

OF SCHEDULED MONUMENTS ON THE REGISTER

LJOOKIN GRANTS WAS OFFERED TO 9 SITES PREGISTER

PRIORITY HAR SITES

- Bowes Railway Incline, Birtley, Gateshead
- Greenhouse east of Felton Park with potting shed, Felton Park, Felton, Northumberland
- Harperley Working Camp, WWII POW Camp at Craigside, Wolsingham, County Durham
- Kirkleatham Hall Stables and Landscape (Kirkleatham Hall Stables, Bastion and ha-ha wall north of Kirkleatham Hall Stables, Bastion north west of Kirkleatham Hall Stables), Redcar, Tees Valley
- Monastic cell and medieval tower, Coquet Island, Hauxley, Northumberland
- Prebends' Bridge, Durham and Framwellgate, Durham, County Durham
- Ravensworth Castle, Lamesley (Ravensworth Castle and Nash House), Gateshead
- Small multivallate hillfort and tower mill on Shackleton Beacon Hill, Heighington, Darlington
- Sockburn Hall and Church (Sockburn Hall, and the Church of All Saints) Sockburn Lane, Sockburn, Darlington
- Ushaw College, Esh (Chapel of St Michael at College of St Cuthbert, Former Junior Seminary, Chapel of St. Aloysius and Bounds Wall), County Durham

FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser English Heritage North East Bessie Surtees House 41-44 Sandhill Newcastle upon Tyne NEI 3JF

Telephone: 0191 269 1200

Email: northeast@ english-heritage.org.uk



BATTLE OF NEWBURN FORD 1640

BACKGROUND AND HISTORY:

The Battle of Newburn Ford was the only battle of the Second Bishops' War prompted by King Charles I's attempt to impose a new prayer book on the Scots. A Scottish army of 20,000 men led by Alexander Leslie threatened Newcastle upon Tyne, but to avoid assaulting the strong city defences they decided to cross the River Tyne four miles upstream from Newcastle at the first fording point at Newburn.

To counter this, the English Commander, Lord Conway, took 3,500 infantry and cavalry from Newcastle to face him on the south bank of the River Tyne, arriving on the evening of the 27th August 1640. Although further reinforcements were sent the following day, the English were driven from their fortifications by the weight of the Scots' artillery bombardment and the Scottish cavalry forced the English to retreat to higher ground and finally drove them off.

The Registered Battlefield at Newburn covers a large area on both the north and south banks of the River Tyne and is owned by a variety of individuals and organisations including households, smallholdings, farmers, national utility companies and local authorities.

The boundaries of the Registered Battlefield include the Scottish camp and artillery positions on the north bank of the River Tyne and the English defensive earthworks. Part of the settlements of Ryton and Stella on the south bank, through which the English retreated, are also included in the Registered Battlefield.

IS IT AT RISK?

Yes. Although the area has been heavily industrialised and the landscape is profoundly different to the landscape of 1640, it is still possible to understand the topography and the course of the battle, which took place over pastureland and woods, much of

which still remains today.

Unfortunately a lack of understanding about the battlefield and encroachment by piecemeal, large-scale development, unsympathetic work that does not require planning permission, and neglect threaten the integrity of the battlefield.

WHAT'S THE CURRENT SITUATION?

This is a challenging site that requires a coordinated approach by both local authorities (Newcastle City Council and Gateshead Metropolitan Borough Council) and English Heritage to raise the profile of the battlefield with local residents and businesses. A recent report prepared by the Battlefields Trust for English Heritage has highlighted the issues and made a number of recommendations.

The most pressing task is to contact all the owners and occupiers of the battlefield and make them aware of the importance of the battle and registered area and the need for them to help protect its integrity by modifying their activities so that key views are not compromised and fragile archaeological deposits are protected.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (http://list.english-heritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces management controls. Some 1,624 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special. A change in legislation, part of the Enterprise and Regulatory Reform Act, makes this possible.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best know are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat. There are over 376,000 listing entries on the National Heritage List for England.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,792 examples have been designated because of their national importance. (Scheduled monuments are not graded). They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are I,624 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the

designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1185): almost half date from the period of the the civil wars in the mid-17th century. These are cherished for their memory, and for the respect owing to those who were killed, and whose remains still lie in the field.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological records. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy. Battlefields are not graded.

PROTECTED WRECK SITES

England's 46 protected wreck sites represent a tiny proportion of the 33,000 odd pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently over 9,800 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good' reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

English Heritage has assessed a proportion of the 14,800 listed places of worship. We are working with the respective denominations to assess the remaining places of worship. Those that are identified as at risk will be included on the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Whilst this is a challenge given the number of entries on the Register and the different kinds of risk they face, good progress is being made.

To help address this challenge we have created dedicated Heritage at Risk teams in each local office. We have published our National Heritage at Risk Strategy which is supported by nine local strategies. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all at risk assets. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including on new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk

Historic Environment Records, and local heritage at risk registers maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services, the inclusion of information about condition can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

English Heritage's role in securing the future of buildings and structures that are on the Register is primarily to provide practical advice, guidance and resources to local authorities, owners and developers.

Our local Heritage at Risk teams can help with analysis of the issues, investigating the feasibility of options and brokering solutions. We can advise on sources of grant aid and, where possible and appropriate, the provision of English Heritage's own grants. Our national advisers and specialists in structural engineering, quantity surveying, development economics and law provide support for local teams on particularly difficult cases. We work closely with grant providers, notably the Heritage Lottery Fund and Natural England as these are essential in helping secure the future of buildings or structures on the Register. In very exceptional cases, English Heritage may acquire and repair a particularly important building or structure, where it is clear that this is the only way of securing its long-term future. More information on funding can be found on the HELM website and at www.english-heritage.org.uk/professional/funding

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings. A local register, often compiled with the help of voluntary groups can identify the scale of the problem, promote monitoring and help prioritise resources and action. A range of enforcement powers are available for local authorities to tackle listed buildings at risk but declining resources in local authorities means that these powers are often under-used. In a bid to help, English Heritage now has a legal adviser dedicated to heritage at risk. We can also provide grant aid to underwrite some of the costs involved in serving Urgent Works Notices and Repairs Notices on historic buildings and we hope that this, together with our published guidance (Stopping the Rot) will encourage local authorities to take action to save historic buildings.

Building preservation trusts (BPTs) offer a tried and tested way of saving many buildings at risk. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk Officers to help not-for-profit organisations take forward building at risk projects. We also provide support for an Industrial Heritage Support Officer based at Ironbridge to work with similar groups running industrial sites. These officers aim to provide a supportive network offering guidance on the establishment of new BPTs, access to funding, training, information and links to associated groups. Case studies and our guidance on the transfer of heritage assets to community and voluntary organisations can be found at www.helm.org.uk/guidance-library/pillarsof-the-community-the-transfer-of-local-authorityheritage-assets

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

This year the Heritage Lottery Fund has started funding the new Grants for Places of Worship scheme, the main focus of which is fabric repairs but now also includes small changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but partfunded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

ARCHAEOLOGY

The continuing success in reducing the number of archaeological sites on the Register, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term

management on a regular basis. Many scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship schemes, administered on behalf of Defra. Continuing partnership with Defra and Natural England has resulted in much more effective information sharing which we use in analysing, updating and publishing so that resources whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. We have agreed a joint target with Natural England to specifically reduce the number of scheduled monuments on the 2010 Register by 25% by 2015. We also continue to work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Nationally, damage from arable cultivation is still the greatest risk factor to archaeological entries on the Register. To help address this, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project, a national survey which looks at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible will begin reporting in the autumn. Some causes of risk are neither so obvious nor dramatic in their effects however. Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites, even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

Most historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take many years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Our landscape architects can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens

BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation

requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood/

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) — a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2013 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2013 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for History Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Crime Prevention: A guide for Owners, Tenants and managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

Key to the entries

This Register includes the following risk assessment types:

- Buildings and structures
 - grade I and II* listed buildings and structural scheduled monuments
- · Places of worship
 - grade I, II* and II listed buildings
- Archaeology
 - scheduled monuments earthworks and buried archaeology
- · Parks and gardens
- Battlefields
- Conservation areas

ORDER

Entries are grouped and ordered alphabetically, first by County[†] (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

Sites that straddle more than one local planning authority are included under the lead authority.

[†]The sub-region Tees Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton-on-Tees; and North York Moors National Park.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- · Buildings and structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are included.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens and battlefields) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- · arable ploughing
- · coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- · visitor erosion.

For parks and gardens, battlefields and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2012 priority categories are given in brackets, otherwise 'New entry' is noted.

For **battlefields** the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- **B** Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)

- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- **F** Action implemented/strategy underway/ scheme in progress (any trend)

TREND

Trend for archaeology entries, parks and gardens and battlefields may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- · no significant change
- improving
- · improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the local Heritage at Risk Principal who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
EH English Heritage
HLF Heritage Lottery Fund

LB Listed Building

LPA Local Planning Authority

NP National Park

RPG Registered Park and Garden SM Scheduled Monument

UA Unitary Authority

Entries on the Register by local planning authority

Local Planning Authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
COUNTY DURHAM (UA)						
County Durham (UA)	26	5	23	1	0	0	8
NORTHUMBERLAND (U.	A)						
Northumberland (UA)	41	3	61	2	0	0	4
NORTHUMBERLAND (N	P)						
Northumberland (NP)	2	0	55	0	0	0	0
TEES VALLEY							
Darlington (UA)	3	2	I	0	0	0	3
Hartlepool (UA)	0	2	2	0	0	0	2
Middlesbrough (UA)	1	0	0	0	0	0	I
North York Moors (NP)	0	0	3	0	0	0	0
Redcar and							
Cleveland (UA)	6	0	2	0	0	0	3
Stockton-on-Tees (UA)	2	0	0	0	0	0	0
TYNE AND WEAR							
Gateshead	5	1	3	0	0	0	1
Newcastle upon Tyne	3	5	2	0	0	0	0
Newcastle upon Tyne / Gateshead [†]	0	0	0	0	I	0	0
North Tyneside	0	0	0	0	0	0	1
South Tyneside	2	1	0	0	0	0	0
Sunderland	4	2		0	0	0	2
Sunderland / Gateshead [†]	I	0	0	0	0	0	0
TOTAL	96	21	153	3	1	0	25

The sub-region Tees Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton-on-Tees and North York Moors National Park

 $^{\dagger}\text{Sites}$ that cross local planning authority boundaries

COUNTY DURHAM (UA)



© English Heritage

SITE NAME: West Mural Tower at Auckland Castle, Auckland Castle Park, Bishop Auckland

Listed Building grade I, RPG DESIGNATION: grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1196445

Two-storey viewing tower in the grounds of Auckland Castle. C13, with later alterations. The building requires urgent consolidation works as there is immediate risk of loss of historic fabric. A statement of significance was completed in 2011. Funding has been identified to allow a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221

The same of the sa

© English Heritage

SITE NAME: Brancepeth Castle, Brancepeth Listed Building grade I, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1159012

Brancepeth Castle is a medieval fortress that was greatly enlarged in the C19 by architects John Paterson and, later, Anthony Salvin. It was occupied by the army during World War II and then by glassware makers JA Joblings. Parts of the building are currently lived in and some areas are used as workshops and offices. There is a need for some urgent repairs as well as longer term maintenance.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Hedleyhill Colliery coke works, 500 metres south west of Hazlet House, Brandon and Byshottles / Hedleyhope DESIGNATION: Scheduled Monument Very bad N/A A(A)

been dislodged by livestock sheltering within them. Livestock have also eroded the grassy banks between each oven and established tree growth occurs along the entire structure.

C18-C19 lines of brick-built coke ovens. Many bricks have



SITE NAME:

© English Heritage

CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: Private LIST ENTRY NUMBER: 1018230

Contact: Kate Wilson 0191 269 1221

Church, 50 metres north east of Croxdale Hall, Croxdale Hall, Croxdale and Hett Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; I grade II, RPG grade II*, CA CONDITION:

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1019820 and 1120740; 1120741

Medieval former church with nave dating back to late CII and chancel to late C12. Altered in later centuries but Norman south doorway contains the original door with iron hinges. On the Croxdale Estate and rarely opened up. There is severe damp in the building, both rising damp in the floors and walls and penetrating damp over the chancel

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Durham Prison Officers' Club ("The Tithe Barn"), Hallgarth Street, Durham

DESIGNATION: Listed Building grade II*, CA

CONDITION: Fair

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1120616

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

C15 granary building, erroneously known as "The Tithe Barn", forming part of an important group of medieval farm buildings. The building lies outside the secure perimeter of the adjoining prison and is used as part of the Prison Officers' Club. The roof, stonework and close-studded upper floor require attention. Repointing of the barn has begun but further works are required, particularly to the granary.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Prebends' Bridge, Durham and Framwellgate Scheduled Monument and Listed DESIGNATION: Building grade I, CA, WHS CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1002337 and 1121354

Bridge over the River Wear designed in 1772-8 by George Nicholson for the Dean and Chapter of Durham Cathedral. The masonry of the arches has deteriorated significantly in recent years; however, a programme of remedial works, part-funded by English Heritage, was completed on the southern arch during 2011/12. Works have yet to be completed on the northern arch.

Contact: Kate Wilson 0191 269 1221



© Niven Architects

SITE NAME: Castle wall, behind 3, North Bailey, Durham and Framwellgate DESIGNATION: Listed Building grade I, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A)

1322845

Charity (heritage)

C12 castle wall with base of angle tower. Consists of coursed squared sandstone. Suffering from progressive collapse of wall face and the core requires urgent attention to avoid further substantial failure. Funding has been identified to allow a repair scheme to be drawn up.

© English Heritage

SITE NAME: Ushaw Home Farm, main block and wall attached, Esh DESIGNATION: Listed Building grade II* CONDITION: Poor Vacant/not in use OCCUPANCY: PRIORITY CATEGORY A (New entry) OWNER TYPE: Private

1185963

Part of a planned farm, constructed 1851-2 to designs by Joseph Hansom. Of three storeys, the main range is built into the bankside so that the lower two floors have ground level access. Two attached side wings and a projecting central bay create an E-shaped plan. Many original internal features survive. There is general deterioration to most external elements, including missing or displaced verge stones to some gable ends, defective rainwater goods and cracking to masonry walls. Many areas of slipped or displaced roof slates are allowing the ingress of rainwater.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Bounds Wall, Ushaw College, Ushaw, Esh DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: F (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1185962

Playing field boundary wall, incorporating racquet and handball courts. Designed c1850 by Joseph Hansom for the former Catholic seminary at Ushaw College. A section of one court is progressively collapsing and the remainder is at risk due to the difficulty of maintenance and repair. English Heritage offered a grant towards the full repair programme, which commenced in June 2013.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:



© English Heritage

SITE NAME:	Chapel of St Michael at College of St Cuthbert, Ushaw, Esh
DESIGNATION:	Listed Building grade I
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (E)
OWNER TYPE:	Private

1299435

Memorial mortuary chapel, of 1858/9, designed by EW Pugin. The chapel is part of the Ushaw College complex; a former seminary for the training of Catholic priests. English Heritage offered a grant towards urgent repair works which were completed in 2011, the same year in which the seminary closed. An options study is underway to find a sustainable long-term use for the site and its constituent buildings.

Former Roman Catholic junior seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. The roofs have been maintained in good condition but the interior and glazing are damaged. An options study is now underway to find a sustainable long-term use for the site

Contact: Kate Wilson 0191 269 1221

and its constituent buildings.



© English Heritage

SITE NAME:	Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1299434 Contact: Kate Wilson 0191 269 1221



Dovecote, 45 metres south of Gainford Hall, Gainford DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C(C)OWNER TYPE: Private LIST ENTRY NUMBER: 1121116

Dovecote, C17, within the grounds of Gainford Hall. Stone repairs, roof renewal and repointing required.

Manor house circa 1600-1603. Occupied but part of upper floor never completed. The building has a defective roof valley and localised structural deformation of walling.

Mid C18 Gothic country house, possibly with older core. The house also has C19 and C20 additions. The building was saved from dereliction by the previous owners, who also part-restored the front range. Options are now being explored to secure the site's immediate and long-term future following refusal of planning permission for an enabling development scheme in 2012.



© English Heritage

© English Heritage

SITE NAME:	Gainford Hall, Low Road, Gainford
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1323010

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Hamsterley Hall, Hamsterley, Consett
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1067550

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

	SITE NAME:	Medieval chapel at Harbour House Farm, Plawsworth, Kimblesworth and Plawsworth	Former chapel. A rare survival of a private manorial chapel dating to the C13-C14. A buttress was built in 2008 to support the leaning southern wall; however, further consolidation and repoliting work is required.
	DESIGNATION:	Scheduled Monument and Listed Building grade II	consolidation and repointing work is required.
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (F)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1002325 and 1120959	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley	Posts, gates and railings on the north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is
	DESIGNATION:	Listed Building grade II*, RPG grade II	slowly decaying. In 2010, English Heritage grant-aided a condition survey with costed priorities for repair works. The project has stalled, although options are now being
Constitution: [1] Ass.	CONDITION:	Poor	explored to help secure the long-term future of the various historic buildings and structures in the estate.
	OCCUPANCY:	N/A	riistorie buildings and structures in the estate.
The state of the s	PRIORITY CATEGORY:	C (C)	
© English Heritage	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1311161	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Lamb Bridge, Lambton Park, Little Lumley	Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, first Earl of Durham.
	DESIGNATION:	Listed Building grade II*, RPG grade II	The bridge has structural distortions that are causing concern about its stability. Work has been undertaken to the foundations and further upstream. The outcome of
A Property of the second	CONDITION:	Very bad	these works will be monitored prior to a further repair package being implemented.
	OCCUPANCY:	N/A	package being implemented.
	PRIORITY CATEGORY:	B (B)	
The Committee of the Co	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1120952	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Gateway, Mortham Tower, Rokeby	Late medieval gateway to grade I medieval fortified manor house, set within landscaped Rokeby Park (registered grade II*). An inspection has revealed structural movement
	DESIGNATION:	Listed Building grade I, RPG grade II*	in the gateway.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© English Heritage Archive	LIST ENTRY NUMBER:	1160832	Contact: Kate Wilson 0191 269 1221
	SITE NAME:	Sherburn House Bridge, Shincliffe	Mid-medieval stone bridge, dating from 1335 but upper part rebuilt at unknown later date. Tree growth and water
	DESIGNATION:	Scheduled Monument, CA	ingress has started to push out masonry, as evidenced by pronounced gaps running throughout the structure.
	CONDITION:	Very bad	Drainage channels empty adjacent to the bridge abutments and this compounds the ongoing erosion.
	OCCUPANCY:	N/A	and any compounds the ongoing crosion.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© English Heritage Archive	LIST ENTRY NUMBER:	1002341	Contact: Kate Wilson 0191 269 1221

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS



© English Heritage

SITE NAME: Brandon Walls lead mine, Stanhope DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Mid-C19 lead mining complex situated on the east bank of the Rookhope Burn. The site was abandoned around 1903 and some elements of the complex are now in need of conservation action.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Middle Level lead mine, Greenlaws, Daddry Shield, Stanhope

Private

1015831

Scheduled Monument and Listed DESIGNATION: Buildings - 6 grade II

CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: B (A) OWNER TYPE: Private

1015828 and 1231495; LIST ENTRY NUMBER: 1231496; 1231634; 1231675;

1278086; 1278087

C18 and C19 lead mine suffering from extensive flood damage and erosion problems. A Conservation Management Plan has been prepared and the first phase of works is planned to take place during 2013.



© English Heritage

Westgate Primitive Methodist SITE NAME: Chapel, Westgate, Stanhope DESIGNATION: Listed Building grade II*, CA CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Charity (heritage)

1232510

schoolroom, constructed in 1871 to the design of George Race Junior & Atkinson and incorporating parts of an earlier C19 chapel. Roof leaks have caused localised internal damage. Investigative works and urgent repairs, part-funded by English Heritage, commenced in 2011 and are due to be completed in 2013. An options study is being prepared.

Contact: Kate Wilson 0191 269 1221

Former Primitive Methodist chapel, with attached

Contact: Kate Wilson 0191 269 1221

SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:

© English Heritage

Coke ovens at Inkerman Farm, Tow Law / Cornsay Scheduled Monument Poor N/A PRIORITY CATEGORY: C(C)OWNER TYPE: Private

LIST ENTRY NUMBER 1018228

Post-medieval beehive coke ovens. The management of the site was reviewed in 1998 with the involvement of Tow Law Town Council, which had a local heritage initiative. English Heritage grant-aided the consolidation works, excavation and recording of finds. The initial repair programme is complete and half of the site is now open to the public. However, consolidation of the rest of the site is still required.

Contact: Kate Wilson 0191 269 1221



© English Heritage Archive

SITE NAME: Clock Tower, Windlestone Hall, Windlestone Park, Windlestone Listed Building grade II*, RPG DESIGNATION: grade II, CA CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Early C19 clock tower and stables gateway by Ignatius Bonomi. The cupola was repaired with an English Heritage grant in 1989, but stonework repairs are now needed. The clock faces have been removed.

LIST ENTRY NUMBER: 1160369 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

SITE NAME: Windlestone Hall, Windlestone Park, Windlestone

DESIGNATION: Listed Building grade II*, RPG grade II, CA

CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER: | 160327

Large house, circa 1835, by Ignatius Bonomi for Sir Robert Johnson Eden. Incorporates an earlier C16 house. Surrounded by gardens and parkland and a cluster of Estate buildings, including stables. The Hall is showing signs of a lack of maintenance, with some internal water ingress and minor structural movement.

Very rare surviving example of a World War II Prisoner of War camp. Used by both German and Italian prisoners of war. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a

series of investigative surveys, a programme of conservation works, funded by English Heritage, commenced in 2011. A second phase of work to the canteen and theatre is due to be completed in 2013.

Contact: Kate Wilson 0191 269 1221



© English Heritage Archive

SITE NAME:	Harperley Working Camp, World War II Prisoner of War camp at Craigside, Wolsingham
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Private

Private

1020730 Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Church of St Anne, Market Place, Bishop Auckland
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation

1292201

1846-8 by William Thompson, on the site of a medieval chapel. Tall aisled nave with clerestory windows, gabled south porch and distinctive west belfry. Chancel with organ chamber and vestry. The north roofslopes have undergone numerous repairs but have now reached the end of their serviceable lives. There is rainwater ingress and some areas of the external stonework require attention. A Repair Grant for Places of Worship has been offered.

Medieval church, substantially rebuilt following a fire in 1998 and comprising a west tower, aisled nave, transepts and chancel. North porch added c1630. C19 south porch. There are some deep pockets of external stone erosion, particularly towards the east end of the church, and the stonework of the south porch is in a poor and

deteriorating condition. The building has been subject to

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Church of St Brandon, North Drive, Brancepeth Park, Brancepeth
DESIGNATION:	Listed Place of Worship grade I, RPG grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1158956

Contact: Kate Wilson 0191 269 1221

heritage crime.



© English Heritage

SITE NAME:	Church of St Cuthbert and presbytery attached, Old Elvet, Durham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation

1160512

Roman Catholic church and presbytery built 1826-27 in Church Perpendicular style. West tower and Lady Chapel were added in 1869 to the designs of Bonomi. Signs of cracking in the tower masonry and pockets of erosion; the latter probably due to an earlier repair using cementitious repointing mortar. A Repair Grant for Places of Worship was offered in March 2012 towards a project development and repair programme.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© English Heritage

© English Heritage

SITE NAME:

Church of St John the Baptist, St John's Chapel, Stanhope

DESIGNATION:

Listed Place of Worship grade II, CA

CONDITION:

Poor

PRIORITY CATEGORY: F (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1232171

Church built in 1752 on the site of a medieval chapel and extended in 1881-83 by Ewan Christian. Contains an elegant Georgian interior but is suffering from water ingress due to blocked gutters and fall pipes. The roof coverings also need replacing. Structural movement in the tower will be arrested when surface water drainage is repaired. A Repair Grant for Places of Worship was offered in 2011 and, following investigative works, a repair programme commenced in 2012.

Contact: Kate Wilson 0191 269 1221



SITE NAME: Church of St Mary and St Stephen, Church Lane, Wolsingham

DESIGNATION: Listed Place of Worship grade II,

CA

CONDITION: Poor

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 23284|

Late C12 tower with later top. Remaining parts of the church (aisled nave, chancel with north vestry and organ chamber, and gabled south porch) of 1848 by William Nicholson. There are problems with the external stonework, including deep pockets of erosion to the north west buttress of the tower, areas of cracking, open joints and loose pointing. There is some internal water ingress.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Derwentcote steel cementation furnace, iron finery	y forge and drift coa	al mine
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1015522
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	English Heritage	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	A cairn and a carved rock, west of Cowclose Gill, i Barningham Moor, Barningham	n Scale Knoll Allotr	nent, 460 metres west of Haythwaite,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	A cairn, a carved rock and a rubble bank, in the sou south east of Far East Hope, Barningham Moor, Bar		Scale Knoll Allotment, 800 metres
SITE NAME: DESIGNATION:			Scale Knoll Allotment, 800 metres
	south east of Far East Hope, Barningham Moor, Bar	rningham	,
DESIGNATION:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised	rningham LIST ENTRY NUMBER:	1017431
DESIGNATION: CONDITION:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised problems	rningham LIST ENTRY NUMBER: TREND:	1017431 Declining
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised problems Plant growth	TREND: NEW ENTRY?: CONTACT:	1017431 Declining No Kate Wilson 0191 269 1221
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private A carved rock and boulder walling, near the south	TREND: NEW ENTRY?: CONTACT:	1017431 Declining No Kate Wilson 0191 269 1221
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private A carved rock and boulder walling, near the south Black Hill Gate, Barningham	rningham LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: wall of Scale Knoll A	Declining No Kate Wilson 0191 269 1221 Allotment, 500 metres north east of
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	south east of Far East Hope, Barningham Moor, Bar Scheduled Monument Generally unsatisfactory with major localised problems Plant growth Private A carved rock and boulder walling, near the south Black Hill Gate, Barningham Scheduled Monument Generally unsatisfactory with major localised	rningham LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: wall of Scale Knoll A	Declining No Kate Wilson 0191 269 1221 Allotment, 500 metres north east of

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full addresses in one in file to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS
CA Conservation

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument

A Unitary Authority
/HS World Heritage Site

	(- /		
SITE NAME:	Carved rock and cairn in Rowley Intake, 410 metro	es south east of Co	wclose House, Barningham Moor,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Carved rock and prehistoric enclosure on west sic Haythwaite, Barningham Moor, Barningham	le of Scale Knoll Gil	I, 410 metres south west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017440
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Prehistoric enclosure 530 metres, and a rubble bar Barningham Moor, Barningham	nk 500 metres, east	of Haythwaite in Scale Knoll Allotme
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Prehistoric enclosure on the west side of Scale Kn Moor, Barningham	oll Gill, 400 metres	WSW of Haythwaite, Barningham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017437
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Ring cairn 350 metres east of Haythwaite, Barningl	nam Moor, Barningh	nam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017424
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Unenclosed settlement, 260 metres south east of 0	Cowclose House, B	arningham Moor, Barningham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017423
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Grange and chapel, Bear Park, Bearpark		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002346
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Cup, ring and groove-marked rock 310 metres wes	st of East Loups's, C	Lotherstone Moor, Cotherstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018324
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cup-marked rock 100 metres north of West Loup	s's, Cotherstone M	oor, Cotherstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018326
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Remains of the Stockton and Darlington Railway, E	therley / Shildon / \	West Auckland
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, part in CA	LIST ENTRY NUMBER:	1002315 and 1159141; 1160402
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native settlement at Calf Holm, immediately west of Dine Holm Scar, Forest and Frith		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019162
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Packhorse bridge, Headlam		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1002359
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two Romano-British hut circles and three shielings Holwick	on Holwick Scars,	250 metres south of Hungry Hall,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019455
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Lanchester Roman fort (Longovicium), Lanchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C. Slow decay: no solution agreed.

 D. Slow decay; solution agreed but F not yet implemented.

 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial used). use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / NORTH				
SITE NAME:	Area of carved be	edrock, 120 metres south of The	Rigg, Lartington	
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1018253
CONDITION:	Generally unsatisf problems	actory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion -	extensive	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Carved bedrock	with cups and grooves, 170 metre	es south east of The	Rigg, Lartington
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1018251
CONDITION:	Generally unsatisf problems	actory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion -	extensive	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cup, ring and gro	oove-marked rock 170 metres sou	ith west of West Lo	oups's, Cotherstone Moor, Lartington
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1016595
CONDITION:	Generally satisfac	tory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Natural erosion -	Natural erosion - moderate		No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Four areas of carving on a rock outcrop 200 metres		es south west of Th	e Rigg, Lartington
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1018250
CONDITION:	Generally unsatisf problems	actory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion -	Natural erosion - extensive		No
OWNER TYPE:	Private	Private		Kate Wilson 0191 269 1221
SITE NAME:	Pike Law lead hus	shes and mines, Newbiggin / Fores	st and Frith	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1015835
CONDITION:	Generally satisfactory	Generally satisfactory but with significant localised problems		Declining
PRINCIPAL VULNERABILITY:	Animal burrowing	Animal burrowing - extensive		No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
	SITE NAME:	Croxdale Hall, Croxdale and Hett	and set in parklar	d garden accompanying a country house nd of early to mid C18 origin. The walled
	designation:	Registered Park and Garden grade II*, 17 LBs, 2 SMs, part in CA	Croxdale Hall ha the beginning of t	are by the designer Lewis Kennedy. s been the seat of the Salvin family since the C15. Maintenance of the gardens has ent years and the water bodies are in a
	CONDITION:	Generally satisfactory but with significant localised problems	poor and deterio	rating state. The notable "cranked" walls gery are in an advanced state of decay.

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.

VULNERABILITY:

NEW ENTRY?:

OWNER TYPE:

LIST ENTRY NUMBER:

TREND:

Medium

Declining

No

Private

1001271

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Kate Wilson 0191 269 1221

ABBREVIATIONS

SITE NAME:	Annfield Plain, Stanley		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Bishop Auckland		
DESIGNATION:	Conservation Area, 69 LBs, part in RPG grade II*, 2 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Bowburn, Cassop-cum-Quarrington		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	David Sparkes (LPA) 03000 267 12.
SITE NAME:	Cockfield		
designation:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
vulnerability:	High	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Kirk Merrington, Spennymoor		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
vulnerability:	High	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Seaham		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
vulnerability:	Medium	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Trimdon Village, Trimdon		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267 12
SITE NAME:	Windlestone Park, Windlestone		
DESIGNATION:	Conservation Area, 17 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267 12

NORTHUMBERLAND (UA)



Allenheads lead ore works,
Allendale

DESIGNATION: Scheduled Monument and Listed
Building grade II

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

Built in the C19, the Allenheads mine was the largest single lead mine in the North Pennines. Much of the complex is well cared for, but some buildings are not weathertight and are becoming increasingly endangered. A report on the required scope of works has been prepared by English Heritage.

© English Heritage

LIST ENTRY NUMBER: 1016348 and 1303925 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 F Under repair or in fair to good
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Holmslinn lead mine, 200 metres south east of Holmes, Sinderhope, Allendale
	Cabadulad Manusaant and List

DESIGNATION: Scheduled Monument and Listed Building grade II

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1015848 and 1154939

A series of standing and buried remains of one of four mine shafts in the East Allen valley. The shaft, 70 metres deep, was dug in 1855. The tower base enclosing the shaft, the engine bed and wheel pit (grade II listed) is being damaged by tree roots. Parts of the wheel pit collapsed in 2011. A broad repair solution has been agreed and it is hoped that a programme of works will be undertaken during 2014.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:

Bondgate Tower, Bondgate Within, Alnwick

DESIGNATION:

Scheduled Monument and Listed Building grade I, CA

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

PRIORITY CATEGORY: A (A)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1006597 and 1041513

The east gate of the former town wall, built circa 1450 by the second Earl of Northumberland. Consists of a recessed central portal between two projecting semi-octagonal towers. The main defects relate to damage from high-sided vehicles passing through the central portal. Further impact of a similar nature could cause a serious collapse. Discussions are underway to manage this risk.

Early C19 townhouse in plain ashlar, with three storeys and

a basement. Most of the original interior detailing is still

present. The building is vacant and deteriorating due to a

lack of maintenance. A condition survey has been prepared and discussions are underway to find a viable solution for

Winding house and shaft-head gear attached to the former Woodhorn Colliery. Built circa 1894, with later alterations. Repairs were carried out to the building as part of a major

completed in 2006. Significant corrosion has reappeared in the steelwork and concrete meaning that the structure requires further remedial work. A repair scheme is due to

improvement scheme for the entire site that was

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:

General Lambert's House, 31 and 33, Narrowgate, Alnwick

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Poor

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

LIST ENTRY NUMBER: 1041425 Contact: Kate Wilson 0191 269 1221

the site.



© English Heritage

SITE NAME:	Eastern winding house and shaft head building, Woodhorn Colliery, Ashington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Local authority

be completed in 2013.



© English Heritage

SITE NAME:	Hydraulic silo, 70 metres east of Cragend Farmhouse, Cartington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1153196

Experimental hydraulic silo, circa 1895, by Lord Armstrong. Linear plan comprising a rectangular silage bay on each side of a taller cross-gabled centre. Interior contains a hydraulic engine and turbine. The building is in a poor state of repair. Planning consent was granted in 2011 for the conversion of neighbouring farm buildings, and it is hoped that this scheme will help secure the future of the silo. Some repairs have been completed to make the building wind- and water-tight.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full lader repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Ruins of Cartington Castle, Cartington Farm, Cartington
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1011611 and 1042073

Fortified manor house of C14 origin but extensively altered in the C16 and C17. The ruins were modified in 1887-9 with a partial reconstruction of the south wall of the north tower. The site is in a ruinous condition. A scheme funded by Natural England was completed in 2012 and a further phase of work is due to take place in 2013.

Contact: Kate Wilson 0191 269 1221

	and the same
	MA

© English Heritage

SITE NAME:	Little Swinburne Tower, Little Swinburne, Chollerton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1011412 and 1044908

Remote C15 tower house in a poor state of repair. Part of Little Swinburne shrunken medieval village. Surrounded by fallen masonry and in need of urgent attention to prevent further falls. A repair scheme has been identified but has yet to be implemented.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Walkers Pottery, west bottle kilns, Milkwell Lane, Corbridge
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

Early C19 bottle kiln used to produce pipes, tiles and lowgrade pottery for agricultural purposes. One of the few remaining examples of a Tyne Valley rural pottery. In poor condition, although deterioration is slow and controlled. Discussions are underway to try and secure a programme of recording and repairs.

LIST ENTRY NUMBER: 1006441 and 1370576; 1155212

SITE NAME:

Contact: Kate Wilson 0191 269 1221



© English Heritage

	30 metres north west of farmhouse, Castle Heaton, Cornhill-on-Tweed
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Remains of Heaton Castle, circa

Vaulted defensible building. Late medieval. The interior has a high round tunnel vault rising three feet above the ground. The slated roof is in a very poor condition and water is discharging onto the wallheads. There is also evidence of structural movement to the north and east walls. A programme of analysis and investigation is required to inform repair works.



© English Heritage

SITE NAME:	Twizel medieval tower house and folly, Twizel, Duddo
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1018445 and 1042168

The present building incorporates the remains of a medieval tower house that was later developed into an C18 folly by Sir Francis Blake. Originally five storeys high, it now stands to three storeys. The site is unmanaged and shows signs of structural instability, including substantial vertical cracks around many of the arches and window openings. It is hoped that this structure along with the associated archaeological features will form part of a wider project that looks at the registered park and garden of Tillmouth Park (grade II*) which is also on the Heritage at Risk Register.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© English Heritage

© English Heritage

SITE NAME: Greenhouse, 120 metres east of Felton Park, with potting shed at rear, Felton Park, Felton

DESIGNATION: Listed Building grade II*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1154561

Unoccupied greenhouse of circa 1830 that incorporates an C18 garden wall. In very bad condition. English Heritage offered a grant in August 2011 to allow a repair scheme to be drawn up. Funding to allow repairs to be undertaken is being explored.

Contact: Kate Wilson 0191 269 1221



SITE NAME: Ford Castle, Ford DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY F (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1371004

Originally a C14 quadrilateral castle with four corner towers, converted to a mansion in 1694 and further altered in 1761 (for John Hussey Delaval) and 1862 (for the Marchioness of Waterford). Now used for residential courses and as a venue for functions. A number of repairs have been undertaken to address the areas most affected by rainwater ingress. Repairs to some rainwater goods have been completed.

Contact: Kate Wilson 0191 269 1221



© Reavell and Cahill architects

SITE NAME-Ford Colliery, Ford Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (C)

Charity (non-heritage) LIST ENTRY NUMBER: 1020746 and 1154125

Monument including above and below ground remains of Ford Colliery. The colliery worked from at least the middle of the C17 through to 1919. The site includes the engine house chimney which was repaired in 2008/9. A repair scheme to the engine house itself has been developed by the owner and the Northumberland Wildlife Trust, following investigative works funded by English Heritage.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© English Heritage Archive

SITE NAME: Entrance gates to Hartford Hall, Hartford Bridge, Hartford DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Commercial company

1041381

Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. English Heritage offered grant-aid towards the repair of the gates and the works duly started. However, the project is currently on hold whilst complex contractual issues are resolved.



© English Heritage

SITE NAME: North west pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (C) OWNER TYPE: Private

Pillbox or defensible latrine, circa 1917. Rare survival as part of World War I fort. Suffering from structural problems and lack of maintenance. Funding has been identified to allow a repair scheme to be drawn up.

LIST ENTRY NUMBER: 1041329 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

CITE NIAME.



SITE NAME:	Water tank, Fort House, A193 (east side), Hartley, Seaton Sluice
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

1303566

Water tank incorporating former ablutions building - a rare survival of part of a World War I fort. Circa 1917. Suffering from structural problems and lack of maintenance. Funding has been identified to allow a repair scheme to be drawn

Contact: Kate Wilson 0191 269 1221

© English Heritage

SITE INAME:	tower, Coquet Island, Hauxley
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Good
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014734 and 1371130

Manastic call and madiaval

Site of a monastic cell founded AD 684 comprising a domestic range and chapel. It survives as an east-west range of medieval stone buildings incorporated into C19 buildings associated with the island's lighthouse. The site is also an important seabird habitat. English Heritage has offered a grant towards a package of urgent repairs. These are due to be formally signed off in 2013.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Bastles at Chesterwood, Haydon Bridge, Haydon
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II
CONDITION:	Good
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

Two defended farmhouses dating from between 1575-1650 in the hamlet of Chesterwood. Both buildings were suffering from major structural problems but are now the subject of a repair programme which is nearing completion.

1006432 and 1042501; LIST ENTRY NUMBER: 1154494; 1154518

Contact: Kate Wilson 0191 269 1221



SITE NAME:	Stublick Colliery beam engine house, Haydon
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1370425

The beam engine house is part of the Stublick Colliery site - the finest group of early C19 colliery buildings in the region. Although other grade II* buildings on the site are in fair condition, the engine house is in urgent need of repair. The ground around the colliery buildings was scheduled in November 2003.

© English Heritage

SITE NAME:	Crawley Tower (with cottage inside), Crawley, Hedgeley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Remains of an early C14 towerhouse, with an C18 cottage built inside when the ruins were altered to form an eyecatcher on the Shawdon Estate. Constructed of massive squared stone; the cottage with a slate roof. The interior is now gutted and contains structural propping. The tower is vacant with no identified use, although the adjacent buildings form part of a working farm. A budget for project

development work has been identified.

Contact: Kate Wilson 0191 269 1221

© English Heritage

Private LIST ENTRY NUMBER: Contact: Kate Wilson 0191 269 1221 1057698

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Barn, north west of Burncliffe, Tow House, Bardon Mill, Henshaw
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (E)
OWNER TYPE:	Private

1045243

An extremely rare example in the county of a heatherthatched cruck barn. Probably C18 but restored in 1989. Rear pitch of barn roof now heavily decayed and this is affecting structural timbers. English Heritage offered a grant in 2010 towards a package of project development works designed to inform a full repair programme. These works should be completed during 2013/14.

Contact: Kate Wilson 0191 269 1221

CONTRACTOR OF CITY OF
TO THE REAL PROPERTY.
THE RESERVE OF THE PARTY OF THE
The state of the s
THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWI
The second secon
MICHAEL TO A STATE OF THE STATE

© English Heritage

SITE NAME:	Hepple Tower, Hepple
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1371440

C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of stone and pointing decay. Funding has been identified to allow a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Old Mill, 30 metres south west of Linnels Bridge, Linnels, Hexhamshire Low Quarter
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Private

1045330

Watermill and outbuilding circa 1700, enlarged and remodelled circa 1800. The interior has a complete set of machinery and an early C20 water turbine. Structural repairs, re-roofing and reinstatement of missing windows are needed. English Heritage has provided funding for project development work.



© English Heritage

SITE NAME:	The Palace, medieval house and Tudor supply base, Holy Island
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014571

Rare survival of a group of medieval buildings in a courtyard arrangement. The exterior north wall is suffering from localised areas of collapse. In an Area of Outstanding Natural Beauty and on the Heritage Coast. The site has been included in a Landscape Partnership Project, and it is hoped this will deliver a future repair programme.



© English Heritage

SITE NAME:	Union Suspension Bridge (that part in England), Horncliffe
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority

1042214

Spanning the border of Scotland and England across the River Tweed, the bridge was built in 1820. It is Britain's oldest suspension bridge in road use. Some repairs have been undertaken but a further programme of investigative and remedial works is required to safeguard the structure

Contact: Kate Wilson 0191 269 1221

in the long-term.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site



© English Heritage

	` '
SITE NAME:	Bastle, 100 metres south west of Ray Cottages, Kirkwhelpington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1011107

Ruined C16/C17 defended farmhouse, situated in the gardens of Ray Castle, with 1.4 metres thick stone walls standing to a maximum height of 2.2 metres. Very little mortar remains in the joints between the squared stonework. English Heritage offered a Management Agreement grant towards the clearance of mature vegetation that was dislodging masonry.

Contact: Kate Wilson 0191 269 1221

SITE NAME: Capheaton tilery, Mirlaw House, Kirkwhelpington DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Tilery built for Kirkharle Estate in circa 1800. Masonry and brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future.

LIST ENTRY NUMBER: 1006418 © English Heritage

LIST ENTRY NUMBER:

Contact: Kate Wilson 0191 269 1221



SITE NAME: Limekiln to east of the Limery, Little Mill, Longhoughton DESIGNATION: Listed Building grade II* CONDITION: Good OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Charity (non-heritage)

Early C19 limekiln, 30 x 18 metres with charring ramp. One of the largest C19 limekilns in the country. The building is redundant and is suffering from exposure to the elements and the encroachment of the natural environment. A detailed survey of the building was carried out in 2010 and repairs, funded by Natural England, will continue throughout 2013.

Country house of 1801 that incorporates earlier masonry. The building received grant aid towards repairs in 1986 but has deteriorated since these works were completed. English Heritage offered a grant in December 2011 towards a package of project development works that will inform a future repair programme. This work, which includes the preparation of a conservation plan and condition survey, is also being funded by Northumberland

Pithead baths of 1938 by FG Frizzell in Modern Movement style. Vacant for over twenty years and subject to vandalism. The future of the overall site continues to be in doubt, particularly since the closure of the associated

© English Heritage

LIST ENTRY NUMBER: 1041773

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Barmoor Castle, Barmoor, Lowick
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1156023

County Council. Contact: Kate Wilson 0191 269 1221



© Northumberland Council

SITE NAME:	Pithead baths at Lynemouth Colliery, Lynemouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Commercial company

1156081

Contact: Kate Wilson 0191 269 1221

Ellington Colliery in January 2005.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage

	` '
SITE NAME:	Mitford Castle, Mitford
DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade l
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)

OWNER TYPE: Commercial company

1017318 and 1370755; LIST ENTRY NUMBER: 1042645; 1370756; 1042647;

1042646

Late C11 motte and bailey castle converted to shell keep in C12. Five-sided keep of C13 includes C12 curtain wall, curtain wall structures and mid C12 chapel. It is now a roofless ruin but capable of consolidation. Grant offered for photographic recording (now complete). English Heritage offered grants towards three phases of the repair programme, the first two of which are now complete.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



Church of St Mary, Woodhorn, SITE NAME: Newbiggin by the Sea DESIGNATION: Listed Building grade I CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

Former parish church with surviving pre-Conquest elements. Significant rebuilding work took place throughout the C12 and C13 before a major rebuild was carried out in 1843-44 by B & | Green architects. The church closed as a place of worship in 1972 and was subsequently used as a museum and workspace for artists. However, the building is now vacant and showing signs of a lack of maintenance.

LIST ENTRY NUMBER: 1304471

SITE NAME:	Sharpe's Folly, Rothbury, Tosson
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1155472

Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 feet high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. The Local Authority in negotiation with owner to secure emergency repairs and English Heritage has advised on the schedule of works.

© English Heritage

© English Heritage

© English Heritage



SITE NAME: Mausoleum, east of Seaton Delaval Hall, Seaton Delaval Listed Building grade II*, RPG DESIGNATION:

grade II*, CA CONDITION: Fair

OCCUPANCY: N/A PRIORITY CATEGORY:

C (C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1154937

Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The landscape was restored in the 1950s-1960s. The mausoleum is roofless but stable following works grant aided by English Heritage in 1994. The site was acquired by the National Trust in 2009.

C13 tower house with C18 Gothick style additions to create a folly. Basement vault has suffered some collapse and there is damaging vegetation growth. In need of urgent repair. Management Agreement established with owner in

Contact: Kate Wilson 0191 269 1221

2005 to clear some of the vegetation.



© Tynedale District Council

SITE NAME:	Simonburn Castle, Castle Lane, Simonburn
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1012414 and 1302543

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2013 / NORTH
© English Heritage
and the same of th

SITE NAME:	Shilla Hill Bastle, west of Comb, Tarset
DESIGNATION:	Scheduled Monument
CONDITION:	Good
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Government or agency

LIST ENTRY NUMBER: 1008991

C16/C17 bastle standing on the summit of Shilla Hill. English Heritage offered a grant in 2006 towards rectified photography work plus production of a specification and schedule for repair works. A further grant was offered in 2008 towards consolidation works and vegetation clearance. The repair programme is now complete but further monitoring is required to ensure the building is

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Bastle and associated buildings northwest of Comb, Comb, Tarset
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Good
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)

OWNER TYPE: Government or agency LIST ENTRY NUMBER: 1008992 and 1370502

Ruins of C16 or early C17 bastle surviving to first floor level. Vault has mostly collapsed but a number of interesting features survive. English Heritage offered a grant towards rectified photography work plus production of a specification for repairs. A further grant offer was made in 2008 towards consolidation works; these are now complete but further monitoring is required to ensure the building is sound.

C14 tower containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first floor barrel-vaulting. The wall tops

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Cocklaw Tower, East Cocklaw, Wall
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1006602 and 1156641

LIST ENTRY NUMBER:

are perilous and there has been a partial collapse of the vaulting. The wall paintings show recent loss and are highly vulnerable. English Heritage has offered a grant towards specialist engineering advice on the emergency propping of the vault.

Contact: Kate Wilson 0191 269 1221

© English Heritage

SITE NAME: Carrshield lead mines and ore works, Carrshield, West Allen Scheduled Monument and Listed DESIGNATION: Buildings - 5 grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private

The remains of two lead mines and an ore works on the base and lower slopes of the West Allen valley at Carrshield. The site was used over three centuries, leaving a complex assortment of remains. The grade II lodging shop is the largest of its kind in the North Pennines but has severe structural damage and parts of the stone wall revetment have collapsed into the river.

1015849 and 1155612; LIST ENTRY NUMBER: 1303252; 1042930; 1042931; 1042932

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Mohopehead lead mine and ore works, Mohope, West Allen Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (A) OWNER TYPE: Private LIST ENTRY NUMBER:

1016349 and 1156464

collapsing recently. The bouse team is slowly deteriorating and trees are encroaching. Site included within the management plan and lead mining strategy for the North Pennines Area of Outstanding Natural Beauty. A phase of works is due to be completed in 2013.

Scheduled lead mine of C18/C19. The mineshop is in a

very dangerous condition, with the roof and rear wall

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise

I PA ΝP 'New entry' is noted. RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:



<u>බ</u>	Fno	lish	Her	itage

SITE NAME:	Church of St Cuthbert, Church Street, Haydon
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1154539 Contact: Kate Wilson 0191 269 1221

SITE NAME:	Haydon Old Church, Old Haydon, Haydon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER: 1042512 Contact: Kate Wilson 0191 269 1221





SITE NAME:	Christ Church, Hepple
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1041243

Parish church built in 1897, in Late Perpendicular style, to the designs of C Hodgson Fowler. Font has a C12 bowl on a C19 stem and there are medieval grave markers within the nave. Slate roof coverings have almost reached the end of their useful life, particularly on the north slope, causing leaks. A Repair Grant for Places of Worship was approved in May 2013 towards a repair programme.

The church was erected in 1796 by the Greenwich Hospital Trustees, to whom the Derwentwater estates passed in the C18. It has an elegant west tower, narrower than the nave, which is topped by a pagoda-like roof. A north transept was added in 1869 to accommodate children from the Shaftoe Trust School, and the chancel was enlarged, and other alterations made, in 1898. There is structural movement in the transept and rainwater ingress.

Former parish church with C12 chancel and C14 south chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. The roof has serious problems, with a heavy build-up of moss holding water and exacerbating the problems caused

by water penetration through holes in the roof.

Contact: Kate Wilson 0191 269 1221

© E	nglish	Heri	tage

SITE NAME:	Defended settlement, 1.05 kilometres north west of	f North Farm, Add	erstone with Lucker
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006478
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Iron Age defended settlement and cultivation terrac	es 600 metres nor	th east of Brown's Law Cottage, Akeld
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019139
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Allen smelt mill, flue system and chimneys, Allendale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016817
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2013 / NOR	TH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Camp on Alnwick Moor, Alnwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006474
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Haggerston dovecote, Ancroft		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006570
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round barrow 520 metres WNW of Quarry Cott	age, Bamburgh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014503
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Defended settlement and Roman signal station 410) metres south of V	Vest Crindledikes, Bardon Mill
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1018536
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Benthall round cairn, Beadnell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008430
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	St Ebba's chapel and monastic site, Beadnell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008563
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Chester's Hill camps, Belford / Easington / Middleto	on	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1006513
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Huckhoe palisaded enclosure, defended settlement Bolam West Houses, Belsay	, and romano-bilds	on secucinency 330 medies north east
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011838
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Springhill Roman camp, Berwick-upon-Tweed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Bewick Hill camp, Bewick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006580
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British farmstead, 520 metres north east of	of Birtley Shields, B	irtley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009676
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British settlement, 300 metres north of T	he Heugh, Birtley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010045
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Defended settlement, 450 metres NNW of Ferney	Chesters, Caphea	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British settlement and Iron Age defended Capheaton / Wallington Demesne	settlement, 550 me	etres north east of Shaftoe Grange,
	Scheduled Monument	LIST ENTRY NUMBER:	1013757
DESIGNATION:			
designation: Condition:	Generally unsatisfactory with major localised problems	TREND:	Unknown
CONDITION:		TREND: NEW ENTRY?:	Unknown
	problems		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERITAGE AT RISK 2013 / NOF	RTH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Double ditched enclosure south west of Broomho	ouse, Chatton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006410
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Simonside camp, Chatton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002907
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two cairn cemeteries west of Willie Law, Chatto	n / Chillingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006451
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hepburn Crags camp, Chillingham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006547
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Corbridge (Corstopitum) Roman station, Corbrid	lge / Sandhoe	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1006611
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the track to P in wall miles 22 and 23, Corbridge / Sandhoe / Wa	ortgate Cottage and	the field boundary east of milecastle 24
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010626
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the Fence Bur Corbridge / Whittington	n and the track to P	Portgate Cottage in wall miles 21 and 22
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1010625
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HERI FAGE AT RISK 2013 / NOF	RTH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Cornhill Castle, Cornhill-on-Tweed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006508
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Enclosed settlement, 620 metres south east of Co	rnhill Castle, Cornh	ill-on-Tweed
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006409
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ridsdale ironworks, Corsenside		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006420
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cresswell tower house, Cresswell		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014509
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Heiferlaw defended settlement, 100 metres north	of Holywell, Denwi	ck
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014080
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Incised rocks, 500 metres north west of Doddingto	on Dean Wood, Do	oddington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006555
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roughting Linn camp, Doddington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006601
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Two camps and cup and ring marked rocks on Do	d Law, Doddington	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002946
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Twizel medieval tower house and village, post-med	lieval folly and gard	en, Duddo
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade II*	LIST ENTRY NUMBER:	1018445 and 1042168
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Iron Age defended settlement in Camp Plantation,	350 metres north v	west of North Charlton Mill, Eglingha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Site south west of Thirlings, Ewart		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006436
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Haw Hill camp, Falstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006491
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Camp, 370 metres NNE of Flodden, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006445
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Circular enclosure west of Second Linthaugh, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006430
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

HEKITAGE AT KISK 2013 / NOR	TH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Flodden camp, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006481
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Flodden Edge camp, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006449
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ford Westfield settlement, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006423
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two incised rocks on Broom Ridge, Hunter's Moo	r, Ford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006554
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Langley Barony lead mines, Haydon Bridge, Haydon	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006413
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum from Throckley to East Heddon-on-the-Wall	Town House, Hedo	on-on-the-Wall in wall mile 11,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010616
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British enclosed settlement, 800 metres n	orth west of East B	Solton, Hedgeley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007446
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	<u> </u>		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Hut circle settlement and field system, Romano-Br north east of Burntshield Haugh, Hexhamshire	itish settlement, hu	sh and lead ore works, 750 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017959
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Medieval chapel and associated building on St Cuth	bert's Isle, Holy Isla	and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014485
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Nafferton castle and tower house, 750 metres east	t of Nafferton Farm	ı, Horsley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018369
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Remains of medieval bridge, Chollerford, Humshau	ıgh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006567
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn 790 metres west of Smithy Strip, Ilder	rton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016248
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Castle Hill camp, Kilham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006470
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Newminster Abbey, Mitford Road, Morpeth		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1006563 and 1155952
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Red House Roman camp, Newbrough		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1006492
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Overgrass tower house, 150 metres south east of	Newmoor Hall, Ne	wton-on-the-Moor and Swarland
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1016711
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Camp in Oakwood, south east of Plenmeller village	, Plenmeller with V	Vhitfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006484
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ellsnook round barrow, 175 metres north east of Heiferlaw Bridge, Rennington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006564
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cairn, 900 metres north east of Old Rothbury hillf	ort, Rothbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Old Rothbury multivallate hillfort and cairnfield, Ro	othbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011616
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	The vallum between Oatens Bank, Harlow Hill, and	l Whittle Dene Wa	tercourse in wall mile 16, Stamfordha
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010621
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Two round cairns, 590 metres and 610 metres east of Burn Brae, Whitton and Tosson				
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1017197	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners		CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Low Chibburn m	nedieval preceptory, C16 house an	l World War II pillbox, Widdrington Village		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1014679	
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221	
	SITE NAME:	Seaton Delaval		mains of early C18 park and garden, partially restore 1950s-60s. House designed by Sir John Vanbrugh in 19. The approach avenue is deteriorating, with natur generation concealing some key landscape features	
	DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, CA	1719. The appro regeneration con		
	CONDITION:	Generally satisfactory but with significant localised problems	including the Mausoleum. Hall and landscape acquired the National Trust in December 2009, opened to visite in May 2010. Parkland Plan, funded by Natural England be used to set priorities for conservation and repair we to the landscape and structures within it.		
	VULNERABILITY:	Medium			
TO A MA	TREND:	Improving			
	NEW ENTRY?:	No			
English Heritage	OWNER TYPE:	Charity (heritage)			
	LIST ENTRY NUMBER:	1001052	Contact: Kate W	'ilson 0191 269 1221	
	SITE NAME:	Tillmouth Park, Cornhill-on- Tweed / Duddo	formal gardens. 7	9 picturesque pleasure grounds and The picturesque walk alongside the Rive	
	DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, 2 SMs	woodland manag	natural regeneration, although some gement work has been undertaken belov al other individual heritage assets are also	
			situated within th		



	Tweed / Duddo
DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, 2 SMs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners

1001053

situated within the registered park and garden.

SITE NAME:	Amble, Morpeth, Amble By the Sea		
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Chris Burgess (LPA) 01670 622659
SITE NAME:	Berwick-upon-Tweed		
SITE NAME: DESIGNATION:	Berwick-upon-Tweed Conservation Area, 262 LBs, 4 SMs	NEW ENTRY?:	Yes
	'	NEW ENTRY?: TREND:	Yes Improving
DESIGNATION:	Conservation Area, 262 LBs, 4 SMs	· · · · · · · · · · · · · · · · · · ·	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Kate Wilson 0191 269 1221

ABBREVIATIONS

SITE NAME:	Spittal, Berwick-upon-Tweed		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Chris Burgess (LPA) 01670 622659
SITE NAME:	Tweedmouth, Berwick-upon-Tweed		
SITE NAME: DESIGNATION:	Tweedmouth, Berwick-upon-Tweed Conservation Area, 18 LBs, part in SM	NEW ENTRY?:	Yes
	· •	NEW ENTRY?: TREND:	Yes No significant change
DESIGNATION:	Conservation Area, 18 LBs, part in SM		

NORTHUMBERLAND (NP)



© English Heritage

SITE NAME: Hadrian's Wall from Cockmount Hill to Walltown. Greenhead, Northumberland (UA) Scheduled Monument and Listed DESIGNATION: Building grade I, WHS CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (C)

Private

1017535 and 1155916

LIST ENTRY NUMBER:

44 and 45. Many of the original issues have been addressed through a Higher Level Stewardship (HLS) scheme involving the owner, Natural England and English Heritage. Further sections of the Wall are under different ownerships and efforts will concentrate on addressing the remaining issues through a further Higher Level Stewardship agreement. It is hoped that a scheme of works will be completed in 2013.

Sections of unconsolidated Hadrian's Wall in Wall Miles 43,

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Bastle at Horneystead, 400 metres south west of The Ash, Wark, Northumberland (UA) DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: B (B) OWNER TYPE: Private

A defensive farmhouse of the type found only in the northern border counties of England. The walls stand up to 4.5 metres high but the first floor has collapsed on a barrel vault. The main cause for concern was a large tree growing out of the upper courses of the north wall, whose roots were displacing and dislodging original fabric. The tree was removed during 2009 but further consolidation works are required.

1009674 LIST ENTRY NUMBER: Contact: Kate Wilson 0191 269 1221

SITE NAME:	Romano-British farmstead 900 metres north east o Northumberland (UA)	f triangulation poin	t on Gains Law, Akeld,
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1017381
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British native farmstead 970 metres north Northumberland (UA)	east of triangulatio	on point on Gains Law, Akeld,
SITE NAME: DESIGNATION:		east of triangulation	on point on Gains Law, Akeld,
	Northumberland (UA)		
DESIGNATION:	Northumberland (UA) Scheduled Monument, RB Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1017382

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Unenclosed scooped settlement on the east slope Cottages, Akeld, Northumberland (UA)	of Harehope Hill, 7	50 metres south east of High Akeld
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014932
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Crigdon Hill round cairn, Alwinton, Northumberla	ınd (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008567
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Three cross dykes on Middle Hill, Alwinton, North	numberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007525
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Prehistoric field system and unenclosed hut circle south west of Earlehillhead, Earle, Northumberland		ern slopes of Hart Heugh, 550 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native enclosed settlement, 360 me (UA)	tres south east of B	roadstruther, Earle, Northumberland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native settlement on southeastern s Bridge, Earle, Northumberland (UA)	slope of Hart Heugh	n, 490 metres north west of Carey Bu
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016237
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native settlement, 750 metres north	n west of Carey Bui	rn Bridge, Earle, Northumberland (UA
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018440
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Two prehistoric enclosures, field clearance cairns a 600 metres south west of Wooler Common, Earle	and unenclosed hut e, Northumberland	circle settlement north of Hart Heu (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018442
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the field bound B6318 road in wall mile 46, Greenhead / Thirlwall,	dary west of Carvoi Northumberland (ran Roman fort and the west side of UA)
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010992
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Haltwhistle Burn Roman temporary camps 2 and 3 Northumberland (UA)	and area of cord r	ig cultivation, Haltwhistle,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010946
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Cross dyke, south of Campville, Harbottle, Northu	umberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011396
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Multivallate hillfort, 400 metres west of Harehaugh	, Harbottle, North	umberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Round cairn, 340 metres west of The Beacon, Har	bottle, Northumbe	rland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021032
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Stone alignment, 900 metres south west of Holysto	one Grange, Harbo	ttle, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009448
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

	` '		
SITE NAME:	Hadrian's Wall and associated features between the of milecastle 36 in wall miles 34, 35 and 36, Haydor	e boundary east of n / Simonburn / Bar	turret 34a and the field boundary west don Mill, Northumberland (UA)
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010964
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Shieling, 500 metres south west of Spy Crags, Hens	shaw, Northumberl	and (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011839
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and associated features between the Rigg car park in wall miles 37, 38 and 39, Henshaw	e field boundary we / Bardon Mill, Nor	est of turret 37a and the road to Steel thumberland (UA)
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010966
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Seatsides I Roman temporary camp and section of from Once Brewed to the south side of the B6318	the Stanegate Rom , Henshaw / Melkri	an road from the west side of the roadge, Northumberland (UA)
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010940
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	18th century water mill at Grasslees, Hepple, Nort	humberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006404
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Bastle 150 metres south west of Morrelhirst, Hollin	nghill, Northumber	land (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Long cairn on the south western slope of Dod Hill, Northumberland (UA)	, 1000 metres north	n east of The Dod, Ilderton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019417
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Romano-British farmstead on the eastern slope of Northumberland (UA)	Dod Hill, I kilomet	re north of The Dod, Ilderton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019419
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn cemetery 1000 metres north west of	Heddon Hill, Ildert	on, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019920
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn on the southern slope of Dod Hill, 800 (UA)	0 metres NNE of T	he Dod, Ilderton, Northumberland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019868
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlements south east of Heddon Hill, Ilderton, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006443
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Greaves Ash camp, Ingram, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006588
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Reaveley Hill cairn cemetery, Ingram, Northumber	land (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Reaveley Hill settlement, Ingram, Northumberland	(UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006468
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Settlement on south east slope of Ewe Hill, Ingram	, Northumberland	(UA)
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002916
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Unenclosed hut circle settlement, field system, cair Linhope Spout, Ingram, Northumberland (UA)	rnfield and cord rig	cultivation immediately north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ingram Farm: prehistoric to post-medieval settleme Northumberland (UA)	ent, agricultural and	funerary remains, Ingram / Alnham,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021382
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Elsdonburn Roman period native settlements and r	Elsdonburn Roman period native settlements and medieval shieling, Kilham, Northumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014505
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Enclosed settlement and subsidiary enclosures 160 Kilham, Northumberland (UA)	metres north of Ri	ing Chesters defended settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009527
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Northern ring cairn on Coldsmouth Hill, Kilham, N	Northumberland (U	A)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009531
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native enclosed settlement 700 met Northumberland (UA)	res south of Ring C	hesters defended settlement, Kilham,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Southern ring cairn on Coldsmouth Hill, Kilham, N	orthumberland (U	A)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hethpool tower house, Kirknewton, Northumberl	and (UA)	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018439
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native enclosed settlement 270 met	res ESE of Fleehope	e, Kirknewton, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014501
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native enclosed settlement and medieval sheiling 165 metres north east of Dunsdale, Kirknewton, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014680
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British settlement 810 metres south east	of Whitehall, Kirkn	ewton, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019927
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlement north of White Law, Kirknewton, Nort	humberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006456
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlement north west of Ell's Knowe, Kirknewton,	, Northumberland	(UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008478
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Settlement on north east slope of Yeavering Bell, k	Kirknewton, Northu	umberland (UA)	
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006459	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Settlement on north slope of Yeavering Bell, Kirkn	Settlement on north slope of Yeavering Bell, Kirknewton, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006466	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Settlement on the east slope of The Bell, Kirknewt	on, Northumberlar	nd (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006465	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Unenclosed settlement, part of a field system, Romano-British aggregate village and group of shielings, 470 metres south east of Whitehall, Kirknewton, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019929	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Hadrian's Wall and vallum between the field boundary at Brown Dikes and the field boundary east of turret 34a in wall miles 32, 33 and 34, Newbrough / Simonburn / Haydon, Northumberland (UA)			
designation:	Scheduled Monument, LB grade I, WHS	LIST ENTRY NUMBER:	1010963	
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Round cairn 230 metres west of Ridlees Cairn, Rochester, Northumberland (UA)		erland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021030	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Fishponds, 450 metres north east of Sewingshields,	, Simonburn, North	numberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011081	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

SITE NAME:	Tarset fortified house, 180 metres east of Tarset Hall, Tarset, Northumberland (UA)		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1015528
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Walwick Fell Roman temporary camp, Warden, No	orthumberland (UA	n)
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010935
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Blacka Burn shieling, Wark, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010038
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British farmstead, 175 metres south of Co	ckpit Well, Whitto	on and Tosson, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009582
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221

TEES VALLEY

DARLINGTON (UA)



Manor House, Houghton Bank Lane, Houghton Le Side DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A

Dovecote, 45 metres east of

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company © English Heritage

SITE NAME:

LIST ENTRY NUMBER: 1121194 Contact: Kate Wilson 0191 269 1221



© English Heritage

Church of All Saints, Sockburn SITE NAME: Lane, Sockburn Scheduled Monument and Listed DESIGNATION: Building grade I CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: OWNER TYPE: Religious organisation

1002340 and 1185947

An important site containing the remains of the church (C13-C15) and a major collection of pre-Conquest stone effigies housed in the nearby Conyers Chapel. The church was abandoned in 1838 and allowed to fall into ruin. Urgent repair works were completed in 2006 with English Heritage grant aid. A second phase of consolidation works was undertaken in 2010, again grant aided by English Heritage.

Dovecote, probably medieval. Disused and requires roof

repairs, repointing and removal of vegetation from walls.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

© English Heritage

SITE NAME:	Sockburn Hall, Sockburn Lane, Sockburn
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Private

1116156

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

of maintenance over many years. Water ingress has led to the localised collapse of floors and ceilings, and there is general decay throughout. The Sockburn Hall Project was established in 2007 and this has been effective in mobilising volunteer activity to improve the site. English Heritage provided funding in 2009 to make the property watertight and a detailed condition survey has been prepared. Further project development work is in progress, including a viability study.

Country house of 1834 which has deteriorated due to lack

Contact: Kate Wilson 0191 269 1221


自由自由。
TITLE BALL OF BEING

SITE NAME: Church of St Hilda, Park Gate, Darlington DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1322955

Built (1887-88) in red brick in the Early English style by eminent C19 church architect JL Pearson. The stained glass and interior fittings were removed soon after closure in 1986. The church then suffered a fire before being acquired and re-used for worship by the Life and Light Mission. Roof coverings are reaching the end of their life and low level brickwork is in need of repair.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Church of Holy Trinity, Woodland Road, Darlington
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER	1121226

Built in 1836-38 by Anthony Salvin, with a chancel and vestry by J Ross added in 1867. The church has historical importance as an early example of the Early English Gothic Revival and its building reflects Darlington's rapid growth at that time. Defective parapet gutters have led to outbreaks of dry rot and repairs are required urgently. The building has also been the subject of heritage crime.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Small multivallate hillfort and tower mill on Shackleton Beacon Hill, Heighington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016867
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Northgate		
DESIGNATION:	Conservation Area, 14 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Heather Nelson (LPA) 01325 388604
SITE NAME:	Victoria Embankment		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Heather Nelson (LPA) 01325 388604
SITE NAME:	West End		
DESIGNATION:	Conservation Area, 39 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Heather Nelson (LPA) 01325 388604

PRIORITY CATEGORIES


- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HARTLEPOOL (UA)



© English Heritage

SITE NAME:	Church of St Hilda, High Street, Hartlepool Headland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor

PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1263355

Built around 1200 on the site of a C7 monastery, incorporating the remains of an early C12 church. Many Saxon and medieval architectural fragments throughout the church, which has undergone several re-designs and was fully restored between 1925 and 1932. The church is on an exposed site near the sea and the parapets (and other masonry) are open-jointed. In addition to having a spalling roof, the tower has structural issues that are currently under investigation. The building has also been the subject of heritage crime.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Church of the Holy Trinity, Church Street, Seaton Carew
DESIGNATION:	Listed Place of Worship grade II CA
CONDITION:	Very bad
PRIORITY CATEGORY:	D (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1250751

Originally built as a chapel within the parish of Stranton, Holy Trinity was consecrated in 1831. Seaton Carew became a parish in its own right in 1841 and the church was extended, with a chancel and gallery built. Further alterations continued to be made to the building but some relatively recent repairs, using hard cement pointing, have accelerated the erosion of the stonework. Significant repairs are now required to the roof structure, masonry and rainwater goods. A Repair Grant for Places of Worship was offered in March 2012 towards a project development and repair programme.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Low Throston deserted medieval village		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006765
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Medieval farmstead and irregular open field system at High Burntoft Farm, Elwick		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1015207
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Headland, Hartlepool, Headland		
DESIGNATION:	Conservation Area, 34 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Seaton Carew, Hartlepool		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Scarr (LPA) 01429 523275

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

MIDDLESBROUGH (UA)



OWNER TYPE:

LIST ENTRY NUMBER:

© Middlesbrough Borough Council

SITE NAME:	Acklam Hall, Hall Drive, Acklam
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)

1136868

Educational (state sector)

Late C17 manor house with C19 and C20 additions. Situated in the remnants of a historic designed landscape. The building was last occupied by Middlesbrough College but became vacant in 2008. There is progressive deterioration to the fabric of the building and it is vulnerable to anti-social behaviour. A mixed-use scheme to secure the site's future was granted planning consent in 2012, but this has yet to commence.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Acklam Hall, Acklam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Sally Childes (LPA) 01642 729116

NORTH YORK MOOR	S (NP)		
SITE NAME:	Pinchinthorpe Hall moated site and post medieval g	gardens, Guisborou	gh, Redcar and Cleveland (UA)
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1013215
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Boulby Alum Quarries and works, Loftus, Redcar a	nd Cleveland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018336
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Unenclosed hut circle settlement on Waupley Moc Redcar and Cleveland (UA)	or, 800 metres sout	h west of Clay Hall Farm, Loftus,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016928
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

REDCAR AND CLEVELAND (UA)



SITE NAME:

Bastion and ha-ha wall, north of Kirkleatham Hall Stables, Kirkleatham, Redcar

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

B (B)

OWNER TYPE:

Local authority

Early-mid C18 bastion and adjoining ha-ha. The bastion is badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some consolidation work, part-funded by English Heritage, was carried out on the bastion during 2011/12 but further repairs are required and the ha-ha remains in a very poor condition.

© English Heritage
LIST ENTRY NUMBER: | 1329608 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

JA Unitary Authority
VHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



and Cleveland Borough Council

SITE NAME:	Bastion, north west of Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Local authority

1160124

Mid C18 bastion. Badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some urgent repairs, part-funded by English Heritage, were carried out during 2011/12 but further works are required to complete the consolidation of the structure.

Early C18 stable block. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. The stable block was repaired, part-funded by English Heritage grant aid, during 2011/12 and is now in good condition. However, further talks are required to identify a sustainable long-term use for the building.

Contact: Kate Wilson 0191 269 1221

© English Heritage Archive

SITE NAME:	Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority

1160085

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Redcar and Cleveland Borough

SITE NAME:	Turner Mausoleum, Church of St Cuthbert, Kirkleatham Lane, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1159896

Mausoleum, in memory of Marwood William Turner, attached to Church of St Cuthbert. 1739-40 by James Gibbs. The building has suffered from water penetration and rising damp, causing damage to the internal plasterwork and internal monuments. A grant was offered in 2011 towards a package of urgent repairs. These are due to be completed in 2013/14.

© English Heritage

SITE NAME:	Remains of Kilton Castle, Kilton Thorpe Lane, Kilton, Lockwood
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

C12-C13 castle ruin occupying a rocky outcrop. The building is in a very bad condition, with vertical cracks in its walls and there is some regeneration of vegetation. There is only limited management by the Estate.



© Redcar and Cleveland Borough Council

SITE NAME:	War Memorial, Saltburn by Sea, Glenside, Saltburn, Marske and
LIST ENTRY NUMBER:	1018946 and 1136489
OWNER TYPE:	Private
PRIORITY CATEGORY:	A (A)
OCCUPANCY:	Vacant/not in use

Arts and Crafts style memorial to the dead of the First World War 1914-18 with bronze sculpture by Sir William Reynolds-Stephens. Unveiled on 14 November 1920. The cross has open joints and cracking in its west arm. The surrounding paved area and retaining walls have suffered from subsidence and corrosion is affecting the heavily patinated bronze sculpture.

Listed Building grade II*, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Local authority

1387499

New Marske

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

	WITE STATES CHANGE SELECTION (STOCKTON STATES		
SITE NAME:	Eston Nab hill fort, palisaded settlement and beaco	on, Guisborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011273
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Manorial settlement, dovecote and fragment of fiel Marske and New Marske	d system, immediat	ely north of Marske Inn Farm, Saltburn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018948
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Brotton, Skelton and Brotton		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Phil Jones (LPA) 01287 612349
SITE NAME:	Guisborough		
DESIGNATION:	Conservation Area, 105 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Phil Jones (LPA) 01287 612349
SITE NAME:	Kirkleatham, Redcar		
DESIGNATION:	Conservation Area, 24 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
	Medium	CONTACT:	Phil Jones (LPA) 01287 612349

STOCKTON-ON-TEES (UA)



© English Heritage Archive

SITE NAME:	Phosphate rock silo (No. 15), Haverton Hill, Former ICI, Billingham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1115821

Reinforced concrete silo of 1928/29. Parabolic crosssection with reinforced concrete arches, with ribs at the ends. Designed by Monnoyer British Construction Ltd, for the storage of phosphate rock imported for the production of fertilizer. This is the earliest surviving example of this type of silo in England. The owner is considering options for repair and re-use.

Contact: Kate Wilson 0191 269 1221



© English Heritage Archive

SITE NAME:	Ruins of Church of St Thomas a Becket, Durham Road, Grindon
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

OWNER TYPE: Private

> LIST ENTRY NUMBER: 1017321 and 1329821

Ruins of late C12 church that was altered significantly in 1789. Now a roofless, part-collapsed ruin and consolidation of the remains is required.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

TYNE AND WEAR

GATESHEAD



© Richard Annis

SITE NAME: **Dunston Staiths** Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: F (C) OWNER TYPE:

Charity (heritage)

1005898 and 1248994

Built by the North Eastern Railway Company and opened in 1893. Closed in the 1970s after being the last working staiths on the River Tyne. Fire damage in 2003 resulted in 8% of the monument being lost and there was a further fire in July 2010. A conservation plan, condition survey and feasibility study have been produced to identify a future for the structure. A scheme of repair is due to commence in 2013 with funding from the Heritage Lottery Fund and English Heritage.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Gateshead Metropolitan Borough

SITE NAME:	Ravensworth Castle (Nash House), Lamesley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1025151

Nash house of 1808 for Sir Thomas Liddell. House completed in 1846 but now a ruin with only one remaining upstanding tower at the north end. A conservation plan was completed in 2008 for the entire site, followed in 2009 by a viability study and planning brief. Discussions are ongoing about a scheme to secure the tower and its neighbouring historic structures.

DESIGNATION:

SITE NAME:

LIST ENTRY NUMBER:

Ravensworth Castle, Cross Lane, Lamesley

Scheduled Monument and Listed Building grade II*, LB grade II,

CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: A(A)OWNER TYPE:

Medieval castle of which two C14 corner towers and part of the curtain wall survive in poor condition. A conservation plan was completed in 2008, and a viability study and planning brief have been prepared for the site. English Heritage offered a grant in 2010 to allow a repair scheme to be drawn up. Discussions are ongoing to secure the implementation of the necessary works.



Private LIST ENTRY NUMBER: 1016975 and 1025190 SITE NAME: Gibside Hall, B6314, Gibside

Estate, Rowlands Gill.

1017224 and 1299730

Contact: Kate Wilson 0191 269 1221



© English Heritage

	Whickham
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

Large house/hall of 1603-20, enlarged C18 and altered early C19. Fell into disrepair in early C20 and now a roofless shell in poor condition. Set in early/mid C18 park. The house requires major stabilisation and consolidation works. The National Trust has undertaken some works to improve public access to the immediate setting of the building. Potential funding for a scheme of repairs is now being explored.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© English Heritage Archive

SITE NAME:	Whinfield coking ovens, south east of Low Spen Farm, Whickham
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Charity (heritage)

Remains of what was originally a bank of 193 bee-hive coke ovens dating from the mid-C19. Part of an extensive former mining landscape that is now largely cleared and landscaped. The remaining ovens represent a rare example of intact bee-hive coke ovens. Currently under severe attack by vandals. Initial repairs carried out in 2003 but further works are required.

Contact: Kate Wilson 0191 269 1221

4	A .		9
	No.		The second
		1	The Later

SITE NAME: Church of St Paul, Scotland Head, Blaydon DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1025175

1018226

LIST ENTRY NUMBER:

Built 1827-9 to designs by the architect Ignatius Bonomi, St Paul's is a hall church with the nave and chancel accommodated under a continuous low-pitched roof and a bold west tower. There is extensive decay and erosion to the external surface of the sandstone walls. Part of the south parapet has been dismantled and there is evidence of pronounced damp staining in the vicinity of rainwater pipes.

Contact: Kate Wilson 0191 269 1221

0	Eng	lish	Her	itage

SITE NAME:	Coal mining remains at Dunston Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018227
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Road construction	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Washingwells Roman fort, Whickham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018645
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Site of Ravensworth coalmill, 600 metres north eas	st of Ravensworth (Castle, Lamesley
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1015922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ravensworth, Lamesley		
DESIGNATION:	Conservation Area, 11 LBs, 2 SMs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	M. P.	CONTACT:	Claura I a m. (LDA) 0101 422 2510
VOLINEIVABILITI.	Medium	CONTACT.	Clare Lacy (LPA) 0191 433 3510

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

NEWCASTLE UPON TYNE



© English Heritage

SITE NAME: The Keelmen's Hospital, City Road, Newcastle upon Tyne DESIGNATION: Listed Building grade II*

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE:

CITE NIAME

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1024902

Almshouses constructed in 1701 for keelmen and keelmen's widows. The building was last used as student accommodation but is now vacant and disused. It was a target for vandalism but the owner has improved security. Options for re-use are being actively discussed.

Four-storey shops and houses built circa 1835, probably by

including extensive water-staining below the top cornice of the front elevation. Planning consent has been granted,

John Wardle for Richard Grainger. The property is now largely vacant and showing signs of a lack of maintenance;

subject to conditions, for conversion to hotel use.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: 5-13, Grey Street, Newcastle upon Tyne DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Woolsington Hall, Woolsington Listed Building grade II*, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

1139021

Commercial company LIST ENTRY NUMBER: 1123737 Contact: Kate Wilson 0191 269 1221

Chunch of All Coints Dilaning

A compact late C17 country house, with later additions. It has service buildings, all set in fine gardens and parkland. The house is vacant. It was made weathertight in 2008 in advance of proposed further repairs and restoration designed to bring the property back into beneficial use.



© English Heritage

SITE INAPIE:	Street
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1106329

Built between 1786-96 by David Stephenson to replace a medieval church on the same site. Classical style, with baroque tower. All Saints was closed by the Church of England in 1961 and the building was subsequently occupied as an urban studies centre and concert hall. It is currently used for worship by the Church of St Willibrord. The building has been a victim of heritage crime. Recent works have been undertaken to stem the ingress of rainwater, however further repairs are required.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Church of St James, Benwell Lane, Benwell
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024959

Built as a chapel of ease in 1832, St James became a parish church in 1843. Re-designed in 1864 in a mostly Norman style by John Dobson. Spire, choir vestry and porch were added by Hicks and Charlewood in 1895. Roof coverings are in a bad condition, as are valley gutters which run the full length of the building. The church has also suffered from heritage crime in the past. A Repair Grant for Places of Worship was offered in March 2011 and, following investigative works, a repair programme commenced in

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Church of St Michael with St Lawrence, Avondale Road, Byker
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation

1024948

Parish church built 1862-63 by WL Moffat. North aisle and vestry added in 1936. Repair of roofs and gutters grant aided in past, but windows now require urgent attention and some areas of flooring are unsound. The building has also suffered from minor vandalism in the past. A repair scheme will form part of a wider programme of reordering to allow greater community use as well as being a place of worship. A Repair Grant for Places of Worship was offered in March 2011 and, following investigative works, a repair programme commenced in 2013.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME:	Life Transformation Church (former Church of St Paul), Havelock Place, High Elswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024846

Parish church of 1856-9 designed by John Dobson. Formally closed in 2006, the church lay vacant, and subject to heritage crime, until taken over by the Life Transformation Ministry in 2009. The Ministry plans to tackle the major structural issues from which the building suffers but, due to the parlous nature of the building, services are currently being held in an adjoining building. A grant towards investigative works was awarded in March 2012, with the aim of devising a phased repair programme. A further grant was offered in March 2013 for urgent repairs to the roof and rainwater goods.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



SITE NAME:	Christ Church (and hall attached), Shieldfield Green
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024748

Parish church, 1859-61 by AB Higham. Squared sandstone with ashlar dressings and Welsh slate roofs. The roofs are coming to the end of their life and water ingress is damaging internal plaster work. A Repair Grant for Places of Worship was offered in 2012 for a project development and repair programme.

© English Heritage

SITE NAME:	Dewley Hill round barrow and associated features, 350 metres north west of Dewley Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Newcastle upon Tyne town defences: section of	curtain wall including	Sallyport or Wall Knoll Tower
SITE NAME: DESIGNATION:	Newcastle upon Tyne town defences: section of Scheduled Monument, LB grade I	curtain wall including	Sallyport or Wall Knoll Tower
	, ,	J	71
DESIGNATION:	Scheduled Monument, LB grade I Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1019811

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

NEWCASTLE UPON TYNE / GATESHEAD



© Battlefields Trust

SITE NAME:	Battle of Newburn Ford
DESIGNATION:	Registered Battlefield, 5 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
PRIORITY CATEGORY:	С
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1000025

The Battle of Newburn Ford (1640) was the only battle of the Second Bishops War. The Scottish Army took Newcastle by defeating the English at this river crossing rather than attacking the northern defences of the city. The effect of the Scottish campaign was to force Charles I to raise an army against them and after the loss of Newcastle, to pay them off. This expense spelt the end for Charles' period of rule without Parliament and proved to be a critical step towards the English Civil War. The battlefield has been subject to piecemeal, peripheral development.

Large square chimney, detached from boiler house. Built in 1860-62 in Italianate style by Thomas Hawksley. A prominent local landmark and one of a series of pumping stations along the North East coast. Discussions are underway to secure the structure's initial repair and long-

Massive C19 industrial kilns of two types. In poor condition and in urgent need of repair. A recording programme has been completed and a programme of conservation works

Parish church of 1868 by Johnson and Hicks in the Early English style. Interior contains a Norman-style font made of Frosterley marble and a Gothic-style altar composed of high quality woodwork. Remedial work to the tip of the tall broach spire has been completed, however concerns remain about the condition of other parts of the tower.

Contact: Kate Wilson 0191 269 1221

NORTH	TYNESIDE
	111120100

SITE NAME:	St Peter's, Wallsend		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	lan McCaffery (LPA) 0191 6436334

SOUTH TYNESIDE



© English Heritage

SITE NAME:	Cleadon Chimney, Cleadon Pumping Station, Sunniside Lane, Cleadon, Boldon
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1232322 Contact: Kate Wilson 0191 269 1221



© English Heritage Archive

SITE NAME:	Marsden lime kilns, South Shields
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1005911

Contact: Kate Wilson 0191 269 1221

drawn up, with English Heritage grant-aid.

term maintenance.



© English Heritage

SITE NAME:	Christ Church, Grange Road West, Jarrow
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1025199

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SUNDERLAND



© English Heritage

SITE NAME: 'F' Pit Museum - colliery engine house, Albany Way (East side)

Scheduled Monument and Listed DESIGNATION: Building grade II

CONDITION:

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1018224 and 1025422

"F" Pit was sunk in 1777 but the engine house wasn't built until 1926. The pit closed in 1968 and the site was cleared, apart from the engine house. Representing a fine example of the winding technology used in the North East coalfield, the building re-opened as a museum in 1976. However, operational costs, coupled with low visitor figures, caused the museum to close, leaving the future of the building uncertain.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: World War I early warning acoustic mirror on Namey Hill, 570m north of Carley Hill Cricket Ground

Scheduled Monument and Listed DESIGNATION: Building grade II

Local authority

CONDITION: Poor

N/A OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER: 1020325 and 1355057

Acoustic mirror built during World War I to listen for the sound of approaching enemy airships and give warning to the surrounding area. Made of concrete, comprising a shallow dish measuring 15 feet in diameter either side of short ramped walls. The structure is slowly deteriorating, with the face of the concrete dish beginning to fall away. English Heritage has offered a grant to allow a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221



© English Heritage

SITE NAME: Doxford House, Warden Law Lane, Silksworth DESIGNATION: Listed Building grade II*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)

OWNER TYPE: Charity (non-heritage)

LIST ENTRY NUMBER: 1279879

Large house (previously known as Silksworth House), formerly used as a students' hall of residence. Mostly of the early C19 but with some earlier features. The property is vacant and highly vulnerable to theft and arson attacks; a recent fire has caused extensive damage. The roof is leaking. English Heritage has funded an options study and discussions are underway about a potential conversion scheme.

Contact: Kate Wilson 0191 269 1221



© Classic Masonry Ltd

SITE NAME: Screen wall at Monkwearmouth Museum of Land Transport, Sunderland DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

1209029

Sandstone ashlar high screen wall flanking the former Monkwearmouth Railway Station (North Bridge Street) on a north/south axis. Built in 1848 as a branch terminus for the York, Newcastle & Berwick Railway Co. The station closed in 1981 and is now a museum. The central museum building was recently repaired as part of a major programme of works but the screen wall was not included and remains in a poor condition.

Contact: Kate Wilson 0191 269 1221



© English Heritage

Guru Gobind Singh Gurdwara SITE NAME: Sikh Centre (Formerly Christ Church), Ryhope Road Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Very bad PRIORITY CATEGORY: D (C) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1209657

Formerly a parish church, built in 1862-64 by James Murray of Coventry. The building contains high quality glasswork, including an east window by Morris and Co. The church was closed by the Church of England but has been acquired by the Sikh community and continues as a place of worship. The spire is in need of urgent repair and currently has temporary protection attached to it. A Repair Grant for Places of Worship was offered in April 2012 towards a project development and repair programme.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of St Andrew, Park Avenue, Sunderland	
DESIGNATION:	Listed Place of Worship grade I,	

CONDITION: Poor

PRIORITY CATEGORY: D (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1207113

Church by Edward S Prior and his site architect A Randall Wells, 1906-7. The church has a big landmark tower at the east end, above the chancel, and a wide and broad nave giving the impression inside of the upturned keel of a boat. Highly innovative and the whole recognised as a rare artistic achievement. Window glazing is set in distinctive triangular-headed light and is in a very poor condition. A Repair Grant for Places of Worship was offered in 2012 for a further phase of glazing repairs.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Hylton Castle medieval fortified house, chapel, CI	7 and C18 country	houses and associated gardens
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017223
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Old Sunderland, East End of City to east of city centre		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Michael Lowe (LPA) 0191 5612546
SITE NAME:	Old Sunderland Riverside, Riverside location		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Michael Lowe (LPA) 0191 5612546

SUNDERLAND / GATESHEAD



© Gateshead Metropolitan Borough Council

SITE NAME:	Bowes Railway, track, Wagon Shop, Hauler Houses and associated sheds, structures and incline, Bowes Railway, Washington / Lamesley
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1003723

Sheds, track, blacksmiths, engineering and fitting workshops, hauler houses and incline track bed that form part of Bowes Railway. Designed by George Stephenson. Opened in 1826 as a rope-hauled colliery railway. This extensive site is vulnerable to vandalism. Wardley Locomotive shed suffered storm damage in 2005 and emergency repairs were completed in 2006. Blackham's Hill Hauler House was repaired, part-funded by EH grant aid, in 2009/10. At Springwell, Engineering and Blacksmiths workshops were repaired in 2003/04. Urgent repairs to the Wagon Shop, part-funded by EH grant aid, began in 2013.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2013 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST