



WEST MIDLANDS

Contents

HERITAGE AT RISK	111
THE REGISTER	VII
Content and criteria	VII
Criteria for inclusion on the Register	VIII
Reducing the risks	Х
Publications and guidance	XIII
Key to the entries	XV
Entries on the Register by local planning authority	XVII
Herefordshire, County of (UA)	I
Shropshire (UA)	13
Staffordshire Cannock Chase East Staffordshire Lichfield Newcastle-under-Lyme Peak District (NP) South Staffordshire Stafford Staffordshire Moorlands Tamworth Stoke-on-Trent, City of (UA) Telford and Wrekin (UA)	27 27 29 30 31 32 33 35 36 37
Warwickshire North Warwickshire Nuneaton and Bedworth Rugby Stratford-on-Avon Warwick	41 41 43 44 46 50
West Midlands Birmingham Coventry Dudley Sandwell Walsall Wolverhampton, City of	52 52 57 59 61 62 64

64
64
66
67
68
71

ENGLISH HERITAGE

2013

WEST WIDLANDS



Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results. Heritage at Risk teams are now in each of our nine local offices, delivering national expertise locally.

The good news is that we are on target to save 25% (1,137) of the sites that were on the Register in 2010 by 2015. From St Barnabus Church in Birmingham

to the Guillotine Lock on the Stratford Canal, this success is down to good partnerships with owners, developers, the Heritage Lottery Fund (HLF), Natural England, councils and local groups. It will be increasingly important to build on these partnerships to achieve the overall aim of reducing the number of sites on the Register. **Tim Johnston**, Planning and Conservation Director, West Midlands

Our partnership with Natural England is built on the importance of heritage to the value of the rural environment. In 2012 a combination of Natural England stewardship funding and specialist advice from English Heritage helped keep the number of scheduled monuments at risk in the West Midlands below the national average. 23 monuments, ranging from Roman villas to engine houses, have been removed from the Register and significant progress has been achieved at many more including Norbury medieval moated site in Staffordshire.

At 5.4%, the proportion of listed buildings on the Register in the West Midlands is slightly higher than the national average. Progress is, however, being made through English Heritage grant aid on a number of our priority sites. Repairs to the stonework at the Grand Hotel in Birmingham are now underway while the HLF has provided key additional funding for work which has started at the Birmingham Coffin Fitting Works, and Ditherington Flax Mill.

Our grants depend upon the real commitment of owners and local authorities for success. Without this commitment it would not have been possible to remove Rugeley Conservation Area from the Register, improve the condition of Longton Conservation Area in Stoke on Trent or progress repairs at 48 Mill Street in Bridgnorth. Additional help has come from increased activity by building preservation trusts (BPTs) helped by our investment in a Support Officer at the Architectural Heritage Fund. New BPTs have been formed for the Toll House, Stratford and Coventry Charterhouse, while an options appraisal has been completed for the former Moseley School of Art and a BPT is being explored for the Old Rectory, Whitchurch. Over the last year, we have focussed our efforts by creating a local Heritage at Risk Team to work proactively with owners and our partners to tackle heritage at risk. The new team includes our Heritage at Risk Architects: Cristina Gardiner, Chris Miners and John Tiernan who provide architectural advice for grant applications under our secular grants scheme, our Heritage at Risk Project Officers: Jenny Marriot and Imogen Sambrook, whose responsibilities include delivering Management Agreements for scheduled monuments and Kim Auston our Heritage at Risk Landscape Architect who specialises in registered parks and gardens. We have also funded three pilot projects on grade II listed buildings in the West Midlands. These have shown how important our local authority partners are in maintaining information on condition, in tapping the interest and enthusiasm of the voluntary sector and how English Heritage can help through the provision of specialist advice. The provision of technical advice like this is one of the ways we hope to address the challenge of declining resources in local authorities in the year ahead.

anois

Sarah Lewis, Principal Adviser, Heritage at Risk

NORBURY MANOR MOATED SITE, STAFFORDSHIRE

The scheduled remains of the medieval moated manor house at Norbury in Staffordshire. The revetment walls retaining the moat platform were collapsing as the joints were forced open by invasive vegetation. The presence of Great Crested Newts and the need to retain their habitat has resulted in a two-phase repair strategy. The first phase of which has been completed with funding from a Natural England Higher Level Stewardship scheme. The monument will be removed from the Heritage at Risk Register on the completion of the second phase of repair.

BUILDINGS AND STRUCTURES

- Nationally, 4.1% of grade I and II* listed buildings (excluding places of worship) are on the Register. In the West Midlands the percentage is 5.4% (103 buildings).
- 2 building or structure entries have been removed from the 2012 West Midlands Register because their futures have been secured, but 15 have been added.

PLACES OF WORSHIP

- Of the 169 listed places of worship assessed in the West Midlands, 41 are on the Register.
- I place of worship has been removed from the 2012 Register following repair work.

ARCHAEOLOGY

- 3,265 (16.5%) of England's 19,792 scheduled monuments are on the Register, of which 224 are in the West Midlands.
- 23 archaeology entries have been removed from the 2012 Register for positive reasons and 12 have been added.
- 36.2% of archaeology entries (94) on the West Midlands baseline 2009 Register have been removed for positive reasons, compared to the national figure of 21.1%.
- Nationally, damage from arable cultivation is the greatest risk factor, accounting for 43% of those on the Register. In the West Midlands the proportion is 39%.

PARKS AND GARDENS

• 100 (6.2%) of England's 1,624 registered parks and gardens are on the Register. In the West Midlands, 10 are on the Register, the same as last year.

BATTLEFIELDS

• Of the 43 registered battlefields in England, 6 are on the Register. None of the 6 registered battlefields in the West Midlands are on the Register.

WRECK SITES

• Of the 46 protected wreck sites around England's coast, 4 (off the South East coast) are on the Register.

CONSERVATION AREAS

- 8,179 of England's 9,839 conservation areas have been surveyed by local authorities. 510 (6.2%) are on the Register. Of the 667 conservation areas surveyed in the West Midlands, 54 (8.1%) are on the Register.
- 2 conservation areas have been removed from the 2012 West Midlands Register for positive reasons, but 2 have been added.



GRAND HOTEL, BIRMINGHAM

With the help of a grant from English Heritage, masons are working to chip away coatings of cement-based repairs and paints from the façade of the Grand Hotel in Birmingham. They are uncovering and repairing the original stonework and making the elevation stable to remove the building from risk.



Heritage assets are assessed based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

PRIORITY HAR SITES

- Former Ditherington Flax Mill (including the attached former malt kiln, Apprentice House, Flax dressing building, and the Stove House and Dye House), Spring Gardens, Ditherington, Shrewsbury
- Grand Hotel, Colmore Row, Birmingham
- Longton Town Centre Conservation Area, Longton, Stoke-on-Trent
- Ludlow town walls, Ludlow, Shropshire
- Middleport Pottery, Middleport, Stoke-on-Trent
- Newman Brothers Coffin Furniture Works, 13-15 Fleet Street, Hockley, Birmingham
- Snailbeach New Smeltmill and Candle House, Snailbeach Lead Mine, Worthen with Shelve, Shropshire
- Snodhill Castle and scheduled area, Snodhill, Peterchurch, Herefordshire
- The Old Rectory, Lower Brailes, Stratford upon Avon, Warwickshire
- Toll House, Clopton Bridge, Stratford upon Avon, Warwickshire

FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser English Heritage West Midlands The Axis 10 Holiday Street Birmingham B1 ITG

Telephone: 0121 625 6820

Email: west.midlands@ english-heritage.org.uk



ST BARNABAS CHURCH, ERDINGTON, BIRMINGHAM

BACKGROUND AND HISTORY:

The grade II listed St Barnabas church was designed by the Birmingham architect Thomas Rickman for the Church Commissioners in 1824. It is one of a number of large Victorian churches built in the 19th century when the villages around Birmingham expanded in response to the vibrant growth of the city.

Erdington now lies within the conurbation and has a mixed population facing considerable economic hardship; the church is the only landmark building. In 2007 an arson attack destroyed the church roof and the interior. The building was added to the Heritage at Risk Register in 2011 when places of worship were first added to the Heritage at Risk Register. For six years the congregation worshipped in a series of temporary locations while plans were made, funds were raised and repairs were carried out. The fire had destroyed the roof entirely and damaged the walls so that they could no longer take the load of a new roof. After much debate. a scheme which conserved as much of the historic building as possible and replaced missing elements with contemporary architecture was approved.

IS IT AT RISK?

The church was put on English Heritage's Heritage at Risk Register in 2011. It has been removed in 2013 following full repair and re-opening.

WHAT'S THE CURRENT SITUATION?

The congregation was keen to extend the church to create a cafe and to improve access for the disabled so that the church could deliver a wider community function. They chose a contemporary architectural style for the extension to reflect this new role.

A curving, standing-seam metal roof now shelters the nave and swoops low over the café extension on the north side which has a glazed wall giving views across the churchyard to the High Street. The Harbour Café has become a popular meeting place and meeting rooms on the first and second floors at the west end of the nave are now used across the community.

The interior of the church, whilst conserving the surviving historic fabric, has also been finished in a contemporary style. The result is a building which stands out as an example of high quality new design in the otherwise tired streetscape of Erdington. For the parish, it symbolises their triumph over the arson attack and provides a symbol of hope in a challenged community. As Reverend Freda Evans, the Vicar of St Barnabas says, the rebuilding has been a resurrection in every sense of the word.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at **www.english-heritage.org.uk/har** If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (http://list.englishheritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces management controls. Some 1,624 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special. A change in legislation, part of the Enterprise and Regulatory Reform Act, makes this possible.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best know are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat. There are over 376,000 listing entries on the National Heritage List for England. Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,792 examples have been designated because of their national importance. (Scheduled monuments are not graded). They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are 1,624 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1185): almost half date from the period of the the civil wars in the mid-17th century. These are cherished for their memory, and for the respect owing to those who were killed, and whose remains still lie in the field.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological records. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy. Battlefields are not graded.

PROTECTED WRECK SITES

England's 46 protected wreck sites represent a tiny proportion of the 33,000 odd pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently over 9,800 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good' reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

English Heritage has assessed a proportion of the 14,800 listed places of worship. We are working with the respective denominations to assess the remaining places of worship. Those that are identified as at risk will be included on the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Whilst this is a challenge given the number of entries on the Register and the different kinds of risk they face, good progress is being made.

To help address this challenge we have created dedicated Heritage at Risk teams in each local office. We have published our National Heritage at Risk Strategy which is supported by nine local strategies. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all at risk assets. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including on new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: **www.english-heritage.org.uk** or the Historic Environment Local Management (HELM) website: **www.helm.org.uk**

Historic Environment Records, and local heritage at risk registers maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services, the inclusion of information about condition can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

English Heritage's role in securing the future of buildings and structures that are on the Register is primarily to provide practical advice, guidance and resources to local authorities, owners and developers.

Our local Heritage at Risk teams can help with analysis of the issues, investigating the feasibility of options and brokering solutions. We can advise on sources of grant aid and, where possible and appropriate, the provision of English Heritage's own grants. Our national advisers and specialists in structural engineering, quantity surveying, development economics and law provide support for local teams on particularly difficult cases. We work closely with grant providers, notably the Heritage Lottery Fund and Natural England as these are essential in helping secure the future of buildings or structures on the Register. In very exceptional cases, English Heritage may acquire and repair a particularly important building or structure, where it is clear that this is the only way of securing its long-term future. More information on funding can be found on the HELM website and at www.english-heritage.org.uk/professional/funding

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings. A local register, often compiled with the help of voluntary groups can identify the scale of the problem, promote monitoring and help prioritise resources and action. A range of enforcement powers are available for local authorities to tackle listed buildings at risk but declining resources in local authorities means that these powers are often under-used. In a bid to help, English Heritage now has a legal adviser dedicated to heritage at risk. We can also provide grant aid to underwrite some of the costs involved in serving Urgent Works Notices and Repairs Notices on historic buildings and we hope that this, together with our published guidance (Stopping the Rot) will encourage local authorities to take action to save historic buildings.

Building preservation trusts (BPTs) offer a tried and tested way of saving many buildings at risk. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk Officers to help not-for-profit organisations take forward building at risk projects. We also provide support for an Industrial Heritage Support Officer based at Ironbridge to work with similar groups running industrial sites. These officers aim to provide a supportive network offering guidance on the establishment of new BPTs, access to funding, training, information and links to associated groups. Case studies and our guidance on the transfer of heritage assets to community and voluntary organisations can be found at www.helm.org.uk/guidance-library/pillarsof-the-community-the-transfer-of-local-authorityheritage-assets

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

This year the Heritage Lottery Fund has started funding the new Grants for Places of Worship scheme, the main focus of which is fabric repairs but now also includes small changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but partfunded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

ARCHAEOLOGY

The continuing success in reducing the number of archaeological sites on the Register, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term management on a regular basis. Many scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship schemes, administered on behalf of Defra. Continuing partnership with Defra and Natural England has resulted in much more effective information sharing which we use in analysing, updating and publishing so that resources – whether Environmental Stewardship or English Heritage can be more closely targeted where they will have the greatest impact. We have agreed a joint target with Natural England to specifically reduce the number of scheduled monuments on the 2010 Register by 25% by 2015. We also continue to work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Nationally, damage from arable cultivation is still the greatest risk factor to archaeological entries on the Register. To help address this, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project, a national survey which looks at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible will begin reporting in the autumn. Some causes of risk are neither so obvious nor dramatic in their effects however. Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites, even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

Most historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take many years to identify and implement solutions to reduce the risks to parks and gardens. To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Our landscape architects can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/ advice-by-topic/parks-and-gardens

BATTLEFIELDS

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from **www.helm.org.uk**

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/ get-involved/improving-your-neighbourhood/

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2013 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2013 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for History Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Crime Prevention: A guide for Owners, Tenants and managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk



This Register includes the following risk assessment types:

- Buildings and structures
 - grade I and II* listed buildings and structural scheduled monuments
- Places of worship
- grade I, II* and II listed buildings
- Archaeology
 - Scheduled monuments earthworks and buried archaeology
- Parks and gardens
- Conservation areas

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough). A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings and structures
- Places of worship
- Archaeology
- Parks and gardens
- Conservation Areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Conservation area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted. If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are included.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion.

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2012 priority categories are given in brackets, otherwise 'New entry' is noted.

TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the local Heritage at Risk Principal who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- EH English Heritage
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

Entries on the Register by local planning authority

Local Planning Authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HEREFORDSHIRE, COUN	ITY OF (UA)						
Herefordshire, County of (UA)	24	13	29	I	0	0	3
SHROPSHIRE (UA)							
Shropshire (UA)	30	2	45	2	0	0	2
Shropshire (UA) / Telford and Wrekin (UA) [†]	0	0	0	I	0	0	0
STAFFORDSHIRE							
Cannock Chase	0	0	0	0	0	0	1
East Staffordshire	3	0	7	0	0	0	2
Lichfield	3	0	5	0	0	0	1
Newcastle-under-Lyme	3	0	0	0	0	0	
Peak District (NP)		0	2	0	0	0	0
South Staffordshire	2	0	8	0	0	0	2
Stafford	3	0	3	0	0	0	4
Staffordshire Moorlands	5	0	2	0	0	0	3
Tamworth		0		0	0	0	0
STOKE-ON-TRENT, CITY	OF (UA)						
Stoke-on-Trent, City of (UA)	8	4	0	0	0	0	5
TELFORD AND WREKIN	(UA)						
Telford and Wrekin (UA)		1	8	0	0	0	0
WARWICKSHIRE							
North Warwickshire	7	0	5	0	0	0	0
Nuneaton and Bedworth	2	0	0	0	0	0	0
Rugby	0	2	9		0	0	0
Stratford-on-Avon	5	2	18	0	0	0	2
Warwick	3	0		2	0	0	0
WEST MIDLANDS	12	4		0	0	0	0
Birmingham Coventry	7	4	2	0	0	0	9
Dudley	4	4	2	0	0	0	4
Sandwell	2		3	0	0	0	2
Solihull	0	0	0	0	0	0	0
Walsall	U	2	0	0	0	0	7
Walsall / Sandwell [†]	0	0	0		0	0	0
Wolverhampton, City of	2		0	0	0	0	0
WORCESTERSHIRE	2		0	0	0	0	0
Bromsgrove	3	2	3		0	0	
Malvern Hills	2		2	0	0	0	
Redditch	0	0	0	0	0	0	0
Worcester	2	0		0	0	0	3
Wychavon	5	3	9		0	0	0
Wyre Forest	2	0	0	0	0	0	
TOTAL	143	41	176	10	0	0	54

[†]Sites that cross local planning authority boundaries

HEREFORDSHIRE, COUNTY OF (UA)




· · ·		
SITE NAME:	Gatehouse buildings at Wigmore Abbey, Grange, Adforton	Remains of late C12 and C14 abbey. The Gatehouse comprises two buildings, one is without a roof and in very poor condition. Survey work to inform conservation is
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs	required. Structural assessment by English Heritage has indicated that elements of collapse are likely.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005359 and 1179921	Contact: Sarah Lewis 0121 625 6886



+	SITE NAME:	Ruined Church of St Mary, Avenbury	A ruined C12 church. The tower stands to full height, the roof survived to the mid C20 but has fallen in, the walls of
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	the nave and chancel are half collapsed and survive only to a few feet in places. Fragments of decorated interior plaster survive. This building is in very bad condition. Vegetation
	CONDITION:	Very bad	clearance has been carried out by the owners under a management agreement. The walls are generally stable but
	OCCUPANCY:	N/A	are highly exposed.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1005356 and 1349633	Contact: Sarah Lewis 0121 625 6886

© English Heritage

© English Heritage



© English Heritage



SITE NAME:

LIST ENTRY NUMBER:

Clifford Castle, Clifford Late C13 castle. Some propping and fencing carried out in past. New owners have carried out beneficial vegetation Scheduled Monument and Listed clearance. Archaeological survey has been commissioned DESIGNATION: Building grade I and structural inspection has been carried out. Undermining of the tower is a particular concern. Repair CONDITION: Poor scheme in discussion with owner. N/A OCCUPANCY: PRIORITY CATEGORY: B(A) OWNER TYPE: Private

1001774 and 1167903

© English Heritage



	SITE NAME:	Craswall Priory ruins, Craswall	The remains of one of only three Grandmontine Houses in
2	DESIGNATION:	Scheduled Monument and Listed Building grade II	England dating from 1220-25. Severely exposed position has contributed to priory's decline. A management agreement is in place for ongoing management of
	CONDITION:	Very bad	vegetation and urgent repairs to the piscina, but further consolidation and the repair of exposed and deteriorating
	OCCUPANCY:	N/A	architectural details are required.
	PRIORITY CATEGORY:	A (A)	
96	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1014536 and 1342128	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Sarah Lewis 0121 625 6886

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2013 / WEST M	IDLANDS / HEREFORD	SHIRE, COUNTY OF (UA)	
July 10 1	SITE NAME:	Churchyard cross in St Michael's churchyard, Dewsall	The remains of a CI4 cross comprising a plinth of two stone steps upon which sits a single large square base
Can Sunda	DESIGNATION:	Scheduled Monument, LB grade II	stone, from which rises the stump of a shaft. The plinth stones have open joints and have cracked and shifted beneath the base, there has been significant downward
	CONDITION:	Poor	movement in the second step. The shaft appears sound but is wedged into an oversized square socket in which water
-4-1-1-2-2	OCCUPANCY:	N/A	pools and debris collects. Repairs to be funded by an
	PRIORITY CATEGORY:	C (New entry)	English Heritage Management Agreement are under discussion.
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1016130	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Hereford city walls, Hereford	Medieval city walls which have been fully recorded. A programme of consolidation work has been carried out to
The second	DESIGNATION:	Scheduled Monument, 2 LBs, CA	sections in the Council's ownership, but some sections in private ownership still in need of attention. The Council
	CONDITION:	Poor	has produced a Conservation Management Plan which identifies repair needs and a future plan of action.
	OCCUPANCY:	N/A	identifies repair freeds and a future plan of action.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority, multiple owners	
© English Heritage Archive	LIST ENTRY NUMBER:	1005528	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	The Farmers' Club, 42, Widemarsh Street, Hereford	An early CI7 timber-framed property with later alterations, now in use as a club. The ground and first
	DESIGNATION:	Listed Building grade II*, CA	floors are occupied but the top floor is vacant. The roof is in poor condition but has been patched. Water damage in
	CONDITION:	Poor	the valley gutters has led to severe rot in some of the timbers which puts the structure at risk.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
A BUL	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1293348	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Huntington Castle, Huntington	Castle remains. C13, or earlier, repaired in 1403, abandoned in 1460 (although one tower still in use as
	DESIGNATION:	Scheduled Monument and Listed Building grade II	prison in 1521). Motte and inner bailey are surrounded by a ditch and outer bailey. Traces of a curtain wall and C13
	CONDITION:	Fair	semi-circular tower have survived in a fair condition although they are very overgrown. Work to control
	OCCUPANCY:	N/A	vegetation being carried out by owner. Unstable
	PRIORITY CATEGORY:	C (C)	earthworks need long term management plan.
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1002939 and 1157544	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Kilpeck Castle, Kilpeck	Remains of medieval castle at the centre of well surviving and extensive earthworks. Vegetation clearance has been
distant to ward	DESIGNATION:	Scheduled Monument and Listed Building grade II	carried out with funding from Natural England. The two areas of standing masonry need repair and consolidation.
	CONDITION:	Very bad	Higher Level Stewardship will fund repairs to the masonry in 2013/14.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1001761 and 1301419	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.


 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

K	SITE NAME:	The Master's House, St Katherine's Hospital, High Street, Ledbury	St Katherine's Hospital was founded in 1232 and The Master's House constructed in the C15 for the overseer. A high quality timber frame survives within later brick facades.
	DESIGNATION:	Listed Building grade II*, CA	CI9 extensions have been repaired and are in use by the Council which has also won Heritage Lottery Fund and
": FIT	CONDITION:	Poor	English Heritage grants for the repair of the timber frame and re-use of the building as a library and information
	OCCUPANCY:	Part occupied/part in use	centre.
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1301731	Contact: Sarah Lewis 0121 625 6886



Outbuilding east of Marstow

Court (formerly listed as the Granary at Marstow), Marstow

Listed Building grade II*

Vacant/not in use

Poor

D (D)



	SITE NAME:	Lyonshall Castle, Lyonshall	C13 keep enclosed by inner bailey and outer enclosures.
市でで	DESIGNATION:	Scheduled Monument and Listed Building grade II	Owners undertaking maintenance of earthwork site in accordance with English Heritage advice. Much vegetation control carried out. Survey commissioned and long term
	CONDITION:	Poor	masonry consolidation being discussed with owner.
No. of Street, or Stre	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
ALK I	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1001720 and 1301287	Contact: Sarah Lewis 0121 625 6886

© English Heritage



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

© English Heritage



	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1214715	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Barn and attached cowhouse built onto Glibes Farmhouse, Michaelchurch Escley	Four-bay barn with an extra bay for cow house and further loft bay linking to farmhouse. Probably C18. Unused and in need of comprehensive repair. The owner has no
	DESIGNATION:	Listed Building grade II*	proposals for the repair of the building, and its future is uncertain.
-4	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1223446	Contact: Sarah Lewis 0121 625 6886

approved.

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

Reputedly associated with manor of the Knights

Hospitallers who held lands in Marstow and probably

originally a house, circa C15. Built of sandstone rubble under a Welsh slate roof with C18 and C19 alterations.

The building is now in low grade farm use. The stonework and pointing are generally in poor condition, there are

slipped and missing roof slates and the windows and doors are in poor condition. A scheme for conversion has been

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ŬA
- Unitary Authority World Heritage Site WHS

	S
	C
Frank Contraction	C
	C
	Ρ
	C

SITE NAME:	Glibes Farmhouse, Michaelchurch Escley	Farmhouse probably CI7 with alterations into CI8. Dry stone or thin coursed rubble walls with stone slate roofs.
DESIGNATION:	Listed Building grade II*	Unoccupied and in need of comprehensive repair. A programme of urgent works has been carried out, including
CONDITION:	Poor	a temporary roof and rebuilding of fallen masonry. Further long term repairs remain necessary.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1223549	Contact: Sarah Lewis 0121 625 6886

© English Heritage

© English Heritage

© English Heritage



	SITE NAME:	Dovecote south of Much Cowarne, Much Cowarne	A round stone dovecote, probably medieval, with conical tiled roof and C17 or C18 wooden louvre which is lined
	DESIGNATION:	Listed Building grade II*	with stone nesting boxes inside. Originally connected with Much Cowarne Court which no longer exists, the
	CONDITION:	Poor	dovecote is now isolated. There are some holes in the roof, allowing small trees to take root in the wall top.
	OCCUPANCY:	N/A	Urgent works are needed to slow its decay while long term
12	PRIORITY CATEGORY:	A (A)	future is determined.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1349680	Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Churchyard cross in St John the Baptist's churchyard, Orcop	Standing stone cross principally Medieval, with base of two steps, socket stone and lower part of shaft. Lists
DESIGNATION:	Scheduled Monument and Listed Building grade II	substantially to east. Cracked and displaced stone at base. Part of stone step missing at south west corner. In need of stabilisation and consolidation. A scheme of repair is in the
CONDITION:	Very bad	early stages of implementation.
OCCUPANCY:	N/A	
PRIORITY CATEGORY	D (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1016112 and 1348859	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Urishay Castle, Peterchurch	Remains of CI2 motte castle, a ruined CI7 house and a
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	partly ruined C16 chapel. The chapel is stable and in good condition, the C17 house is not. Without a roof the masonry is disintegrating, lintels are failing and in danger of
	CONDITION:	Poor	collapse. Requires assessment of structure to establish survival of medieval fabric and future strategy.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
itage	LIST ENTRY NUMBER:	1014547 and 1099487	Contact: Sarah Lewis 0121 625 6886

© English Herita



LIST ENTRY NUMBER:	1014547 and 1099487	Contact: Sarah Lewis 0121 625 6886
SITE NAME:	Snodhill Castle, Snodhill, Peterchurch	C14 castle with C12 motte. Standing remains in serious condition and heavily overgrown. Part of the curtain wall
DESIGNATION:	Scheduled Monument and Listed Building grade II*	has collapsed. Undermining by badgers and collapse as a result of fallen trees is putting masonry at great risk. English Heritage has funded a survey which will inform discussion
CONDITION:	Very bad	with the owners on a plan for long term care and preservation.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1015168 and 1172756	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Court Cottage (formerly Court Farmhouse), Preston Wynne	Timber-framed building with an adjoining house at the front. The rear range, dating from CI4-CI7, within which
	DESIGNATION:	Listed Building grade II*	are C14 trusses of high architectural quality, was seriously at risk of collapse. Essential works to stabilise structure at make weathertight have been completed with grant aid. Further grant was offered to complete the repairs but owners unable to proceed. Options for future use need to
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	be considered.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1099380	Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Churchyard cross in St Mary's churchyard, Walterstone	A C15 or early C16 churchyard cross of sandstone. The stepped plinth has open joints and fractured stonework
DESIGNATION:	Scheduled Monument, LB grade II*	and areas of collapse. The octagonal shaft sits in a massive square base with shaped and moulded stops. The condition of the plinth has allowed the base and shaft to move out of
CONDITION:	Poor	true. English Heritage and has started discussions with the Parish Council about funding repairs through a
OCCUPANCY:	N/A	Management Agreement.
PRIORITY CATEGORY:	A (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1016132	Contact: Sarah Lewis 0121 625 6886



No.	SITE NAME:	Penyard Castle, Weston under Penyard	Remains of C14 castle in split ownership and land use. F medieval and post medieval. Some remains are overgro
	DESIGNATION:	Scheduled Monument and Listed Building grade II	and in a poor state of repair. The remains in private ownership are in a fair state. Programme of vegetation control undertaken by Forestry Commission. A
1	CONDITION:	Very bad management agreement fo	management agreement for survey and stabilisation of medieval fabric is in discussion.
1 W	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1005385 and 1099662	Contact: Sarah Lewis 0121 625 6886



	LIST ENTRY NUMBER:	1005385 and 1099662	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Chuch of St Andrew, Wolferlow	Early C12 church restored in 1863 by Kempson, of stone construction under a clay tile roof with timber-framed
	DESIGNATION:	Listed Building grade II*	tower and shingle spire. The church has not been used for worship since 2006 and sits in an isolated location. Rainwater goods are absent and the roof has slipped and broken tiles. The building is currently on the market, and
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	suitable alternative use needs to be found.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1217197	Contact: Sarah Lewis 0121 625 6886



R II	SITE NAME:	Church of St Mary, Almeley	A substantial stone church with a C12 tower and medieval
	DESIGNATION:	Listed Place of Worship grade I, CA	aisles set adjacent to the motte and bailey castle in Almeley. Assorted repairs or replacement of defective construction or materials is required to the stone slate roof
	CONDITION:	Poor	coverings, one of the nave roof trusses and the rainwater goods. Localised stabilisation of gable masonry and re- pointing is also required. A Repair grant for Places of Worship was offered in March 2013 to address these and
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Religious organisation	Worship was offered in March 2013 to address these and other defects are currently in progress.
-Jacob - Atte	LIST ENTRY NUMBER:	1081702	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Andrew, Adforton	A Gothic Revival church built in 1875 to designs by JP
	DESIGNATION:	Listed Place of Worship grade II	Seddon in sandstone with limestone dressings and a clay tile roof. The roof is letting water into the church, the
	CONDITION:	Poor	guttering is in poor condition, and areas of stonework show heavy erosion. A Repair Grant for Places of Worsh was offered in April 2013.
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1349768	Contact: Sarah Lewis 0121 625 6886
the second se			

© English Heritage

	SITE NAME:	Aylton Parish Church, Aylton	A simple, small, C12 church comprising nave, chancel and
	DESIGNATION:	Listed Place of Worship grade II*, CA	belfry. Built of sandstone with a clay tile roof. The church has structural problems with cracking in the south wall in the south west corner. Rainwater goods and poor pointing are allowing water into the walls and the north roof slope needs re-roofing. A Repair grant for Places of Worship was offered in January 2013 to address these problems.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1099070	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Church of St Peter, Bromyard and Winslow	Large medieval civic church. The 2006 Quinquennial Inspection identified stonework and roof repairs as
	DESIGNATION:	Listed Place of Worship grade I, CA	necessary. A programme of work has been agreed and it is hoped that this will commence soon.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1307758	Contact: Sarah Lewis 0121 625 6886

© English Heritage

•	SITE NAME:	Church of St Mary Magdalene, Elton	St Mary Magdalene is a medieval church restored in 1875 and with a bellcote and an impressive C16 oak rood screen. The church is constructed from buff-coloured
NRG THE	DESIGNATION:	Listed Place of Worship grade II* sandstone rubble with dressed stone detailing to window	
	CONDITION:	Poor	and doorways. The roof is of plain clay tiles. A Repair Grant for Places of Worship was offered in February 2013
, III	PRIORITY CATEGORY: D (D) for masonry repa	for masonry repairs to the west gable wall, repairs to the	
	OWNER TYPE:	Religious organisation	bellcote and minor repairs to the roof coverings and rainwater goods.
	LIST ENTRY NUMBER:	1081770	Contact: Sarah Lewis 0121 625 6886

© English Heritage



SITE NAME:	Church of St John the Baptist, Grendon Bishop	Parish church built in the 1780s, which now looks Victorian in character. The church has damp problems, slipped tiles
DESIGNATION:	Listed Place of Worship grade II	are allowing water into the chancel, and the porch is decayed. Repairs have started to the porch.
CONDITION:	Poor	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1307407	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



Built in 1839 by Charles Day, this church is a dominant feature on Broad Street with its massive Doric portico. The SITE NAME: Church of St Francis Xavier, Broad Street, Hereford interior has an ornate coved plaster ceiling. Poor detailing Listed Place of Worship grade has caused problems with high level stonework and water penetration. A Repair Grant for Places of Worship was DESIGNATION: II*, CA offered in January 2013 to address this and will remove the CONDITION: Poor building from being at risk. PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1297462 Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive



	SITE NAME:	Church of St Michael and All Angels, Longford, Kingsland	A CI4 church with CI5 tower and timber-framed porch from the CI7. The church is of sandstone rubble, with
a the	DESIGNATION:	Listed Place of Worship grade I, CA	ashlar dressings with a stone slate roof. South facing roofs are in poor condition as are the rainwater goods. A Repair Grant for Places of Worship was offered in March 2013 to
	CONDITION:	Poor	address these issues.
ALC: N	PRIORITY CATEGORY: OWNER TYPE:	B (B)	
A Internet		Religious organisation	
-	LIST ENTRY NUMBER:	1167022	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Church of St Mary Magdalene, Leintwardine	Large complex church in the small town of Leintwardine. Several phases of medieval work and restoration in the late
	DESIGNATION:	Listed Place of Worship grade I, CA	C19 and early C20. Repairs were carried out in 2004, but further work is required to roofs over the north aisle, and chapel, and to rainwater goods. A Repair Grant for Places
	CONDITION:	Poor	of Worship was offered in February 2013.
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1349757	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Church of St Michael and All Angels, Lyonshall	St Michael and All Angels is a late C12 church located adjacent to the remains of Lyonshall Castle. Substantial
	DESIGNATION:	Listed Place of Worship grade II*	alterations were made in the C13 and C14, and the west tower was largely rebuilt in 1872. The church is built of
	CONDITION:	Poor	sandstone rubble with ashlar dressings under a stone tile roof and with a timber-framed porch. A Repair Grant for
	PRIORITY CATEGORY: D (D) Places of Worship was offer	Places of Worship was offered in January 2013 for repairs	
100	OWNER TYPE:	Religious organisation	to the tower roof and weather vane assembly and to reduce ground levels to improve drainage.
	LIST ENTRY NUMBER:	1349918	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Church of St Giles, Pipe Aston	St Giles is a small medieval church comprising a nave,
	DESIGNATION:	Listed Place of Worship grade I	chancel, small belfry and a projecting south vestry. The tympanum to the north door is of the Herefordshire
	CONDITION:	Poor	Romanesque school of sculpture. The nave walls retain stencilled wall paintings restored in the C19 which are threatened by damp. A Repair Grant for Places of Wor
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	was offered in January 2013 to address this problem and to re-tile the vestry roof.
	LIST ENTRY NUMBER:	34990	Contact: Sarah Lewis 0121 625 6886
Martin Martin - Statistica -			

© English Heritage

PRIORITY CATEGORIES

А

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

7

	SITE NAME:	Church of St James, Church Street, Wigmore	St James is a sandstone church with ashlar and tufa dressings built in the CII, set on rising ground in the centre
	DESIGNATION:	Listed Place of Worship grade I, CA	of the village. The chancel, south aisle and tower are additions of the C14 and C15. Few other alterations took place prior to a C19 restoration by G Bodley when the
	CONDITION:	Poor	chancel arch was rebuilt. A programme of grant-aided works has been agreed under the Repair Grant for Places
	PRIORITY CATEGORY:	B (B)	of Worship scheme offered in January 2013, with repairs to
	OWNER TYPE:	Religious organisation	the tower roof and rainwater goods being urgent.
	LIST ENTRY NUMBER:	1178822	Contact: Sarah Lewis 0121 625 6886

© English Heritage



	SITE NAME:	Church of St Peter and St Thomas, Wormbridge	A medieval church restored in the mid C19 with a new nave roof, spire and refacing of the stonework to
	DESIGNATION:	Listed Place of Worship grade II	elevations. Stonework to the tower is badly eroded, the spire slating is allowing water into the structure, rainwater
	CONDITION:	Poor	goods and drainage is generally poor. A Repair Grant for Places of Worship was offered in April 2013 to address
	PRIORITY CATEGORY:	B (B)	these issues.
	OWNER TYPE:	Religious organisation	
E.C.	LIST ENTRY NUMBER:	1099588	Contact: Sarah Lewis 0121 625 6886

© English Heritage

SITE NAME:	Almeley Castle, Almeley		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1001752
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Roman fort and outworks 550 yards (500 metres)	south west of Cano	on Frome Court, Canon Frome
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005347
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman settlement, Canon Frome		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1005271
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Clifford Castle, Clifford		
DESIGNATION:	Scheduled Monument and Listed Building grade I	LIST ENTRY NUMBER:	1001774 and 1167903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
GITE NAME:	Craswall Priory, associated building remains, pond	bays and hollow wa	ays, Craswall
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1014536 and 1342128
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

use).

b) solv decay, solution agreed but not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

(where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- LB Listed Building LPA Local Planning Authol NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Site of Rotherwas House, earthwork remains of fo	rmal gardens and R	otherwas Chapel Dinedor
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Promontory fort on Dorstone Hill, Dorstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bronsil Castle, Eastnor		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1001741
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman settlement, Ford and Stoke Prior / Humber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005322
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Ring ditches and rectilinear enclosures east of Tups	sley, Hampton Bisho	ор
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005348
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Row Ditch (entrenchment), Hereford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001780
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY ?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Huntington Castle, Huntington		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1002939 and 1157544
CONDITION:	Generally unsatisfactory with major localised	TREND:	Improving
condition.	problems		
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Turret Castle, Huntington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007314
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Turret Tump, Huntington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Kingsland Castle, Kingsland		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1007318
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
GITE NAME:	Offa's Dyke: section north west of Holme Marsh e	xtending 615 yards	(560 metres) to the railway, Lyonsha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Ringwork 750 metres west of Grove Farm, Much I	Dewchurch	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014893
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 460 metres south of Milton Cross, Po	embridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014103
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 490 metres south east of Milton Cro	ss, Pembridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014112
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TERTIAGE AT KISK 2013 / WES	T MIDLANDS / HEREFORDSHIRE, COUNTY OF (UA)		
SITE NAME:	Bowl barrow 550 metres south east of Milton Cros	ss, Pembridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014895
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	North Herefordshire Rowe Ditch, Pembridge / Sta	unton on Arrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005382
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Shell keep castle and associated fishponds at Snodh	ill, Peterchurch	
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1015168 and 1172756
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Moated site and fishponds immediately west of Up	per House Farm, St	aunton on Wye
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019476
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Sutton Walls (camp), Sutton / Marden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001747
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman fort at Coppice House, Tedstone Wafer		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005363
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Wall Hills Camp, Thornbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001748
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Motte and bailey, west of St Mary's Church, Walter	rstone	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001778
		TREND:	Declining
CONDITION:	Extensive significant problems		2 00000
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems Stock erosion - extensive	NEW ENTRY?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST N				
SITE NAME:		Ariconium, Weston under Penyard		
DESIGNATION:	Scheduled Monu		LIST ENTRY NUMBER:	1005364
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: Upperton Farm, two sections extending south from Yazor, Yazor		ng 195 yards (180	metres) and 370 yards (340 metres)
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1001736
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple o	owners	CONTACT:	Sarah Lewis 0121 625 6886
	SITE NAME:	Shobdon		l gardens (much modified) and mid C18 part of which is open to the public.
	DESIGNATION:	Registered Park and Garden grade II, 10 LBs, 3 SMs	Although some	garden buildings survive, their context is pmmercial fruit growing, a caravan park, a
	CONDITION:	Extensive significant problems	chicken farm, commercial forestry and intensive agric characterise the historic park.	
A Strate Ure	VULNERABILITY:	Medium		
	TREND:	Unknown		
	NEW ENTRY?:	No		
D English Heritage	OWNER TYPE: Mixed, multiple owners			
	LIST ENTRY NUMBER:	1000894	Contact: Sarah I	ewis 0121 625 6886
SITE NAME:	Kington			
DESIGNATION:	Conservation Ar	ea, 122 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad		TREND:	Deteriorating
VULNERABILITY:	Low		CONTACT:	Robert Walker (LPA) 01432 260140
site name:	Ross-on-Wye, R	oss-on-Wye / Bridstow		
DESIGNATION:	Conservation Ar	ea, 151 LBs, 4 SMs	NEW ENTRY ?:	No
CONDITION:	Very bad		TREND:	Deteriorating
VULNERABILITY:	High		CONTACT:	Robert Walker (LPA) 01432 260140
SITE NAME:	Widemarsh Com	nmon, Hereford		
DESIGNATION:	Conservation Ar	ea, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad		TREND:	Deteriorating
VULNERABILITY:	High		CONTACT:	Robert Walker (LPA) 01432 260140
	-			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SHROPSHIRE (UA)

	SITE NAME:	Wattlesborough Castle (uninhabited parts), Alberbury with Cardeston	Remains of large square tower of castle with fine quality detailing, now without roof. Probably late C13 for Sir Robert Corbet. There has been a recent fall of masonry
E	DESIGNATION:	Scheduled Monument and Listed Building grade I, part in LB grade II	from high level. The owner is considering consolidation and re-roofing for domestic use. An application for English Heritage grant aid is anticipated.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
© English Heritage Archive	PRIORITY CATEGORY:	A (A)	
english hentage / iteliive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1006285 and 1366883	Contact: Sarah Lewis 0121 625 6886
	LIST ENTRY NUMBER:	1006285 and 1366883 Alberbury Castle, Alberbury, Alberbury with Cardeston	Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Alberbury Castle, Alberbury,	Remains of tower keep from C13 castle. Rapidly eroding
	SITE NAME:	Alberbury Castle, Alberbury, Alberbury with Cardeston Scheduled Monument and Listed	Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. Survey commissioned by English Heritage as a basis for designing a programme of urgent
	SITE NAME: DESIGNATION:	Alberbury Castle, Alberbury, Alberbury with Cardeston Scheduled Monument and Listed Building grade II*, 2 LBs, CA	Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. Survey commissioned by English Heritage as a basis for designing a programme of urgent repair works for discussion with owner. Natural England
	SITE NAME: DESIGNATION: CONDITION:	Alberbury Castle, Alberbury, Alberbury with Cardeston Scheduled Monument and Listed Building grade II*, 2 LBs, CA Very bad	Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. Survey commissioned by English Heritage as a basis for designing a programme of urgent repair works for discussion with owner. Natural England

1020662 and 1175344

1053205

Fair

E (D)

Private

1177762

48, Mill Street, Bridgnorth

Vacant/not in use

Listed Building grade II*, CA

© English Heritage



SITE NAME: Barn to west of Hall Part of medieval house. Mainly C15 with open hall and Farmhouse, Aston Eyre solar wings. In agricultural use as a barn for many years. Consent given to restore to residential accommodation. DESIGNATION: Listed Building grade II* Derelict, but some roof repairs carried out to make the building weathertight and a detailed recording of the CONDITION: Poor stonework has been completed and substantial structural OCCUPANCY: Vacant/not in use repairs carried out. The owner is working on an ongoing programme of repair. PRIORITY CATEGORY: F (F) OWNER TYPE: Private

© English Heritage Archive



CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:

D

Е

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

© English Heritage

	SITE NAME:	The Hermitage, Bridgnorth / Worfield	Remains of chapel consisting of chancel separated from the rest by a moulded circular arch and containing a round
	DESIGNATION:	Scheduled Monument	headed recess at the east end and two rooms, all out of soft sandstone rock. Now eroded, gradual decay
The the	CONDITION:	Poor	continues. Future strategy to protect monument has been considered and a protective fence has been installed to
	OCCUPANCY:	Vacant/not in use	control access.
	PRIORITY CATEGORY:	C (C)	
ALC: ALC: T	OWNER TYPE:	Other not for profit group	
vestry Borough Council	LIST ENTRY NUMBER:	1004782	Contact: Sarah Lewis 0121 625 6886

© Oswestry Borough Council

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Sarah Lewis 0121 625 6886

Contact: Sarah Lewis 0121 625 6886

Contact: Sarah Lewis 0121 625 6886

occupied once more.

Circa 1675, this three storey building forms part of a

building fronting the road was in poor condition but extensive repairs have been completed with the benefit of

English Heritage grant. This part of the property is still

vacant, but the owners have plans for re-use and the building will be removed from the Register when it is

commercial premises used as an antique centre. The oldest

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

		(-)	
No. Carl	SITE NAME:	Rockley Farmhouse, Chirbury with Brompton	Farmhouse. Early C17, with mid C20 alterations. The farmhouse is run-down but apparently watertight. In need
ALA	DESIGNATION:	Listed Building grade II*	of basic repair and maintenance work.
PHA P	CONDITION:	Fair	
A Provent	OCCUPANCY:	Occupied/in use	
······································	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1054405	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Old Hall and attached garden wall, Old Marton, Ellesmere	Large farmhouse, mid to late C16 with later additions and alterations. Timber-framed with painted brick and

		Rural	rendered infill. The roof has been repaired but repairs to
	DESIGNATION:	Listed Building grade II*	the timber frame and infill panels are still taking place. The adjoining C18 garden wall, of red brick with moulded stone
	CONDITION:	Poor	coping, has partially collapsed.
	OCCUPANCY:	Part occupied/part in use	
© North Shropshire District Council	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1307787	Contact: Sarah Lewis 0121 625 6886

and the state	SITE NAME:	Ludlow town walls, Ludlow	Medieval town wall in multiple ownership. English Heritage
	DESIGNATION:	Scheduled Monument and Listed Buildings - 8 grade II, 2 CAs	have helped to fund a town walls management plan and the repair of substantial sections in local authority ownership. A Town Walls Trust has been established to promote the
	CONDITION:	Poor	protection and care of the walls. A major section of wall below the parish church collapsed in spring 2013, other
	OCCUPANCY:	N/A	small collapses have taken place on the south section
	PRIORITY CATEGORY:	C (D)	where ownership is disputed.
	OWNER TYPE:	Private, multiple owners	
© English Heritage	LIST ENTRY NUMBER:	1006278 and 1219038; 1289747; 1291656; 1202827; 1202825; 1202826; 1219077; 1282007	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	The Butter Cross, King Street, Ludlow	The Butter Cross was designed by William Baker and built c1746. It is a dominant public building in centre of Ludlow
A MAR	DESIGNATION:	Listed Building grade I, CA	which was used as the Town Council office, and chambers. The Council has moved into new accommodation and a
	CONDITION:	Fair	new user for the Butter Cross therefore needs to be found. External repairs were completed with the help of
	OCCUPANCY:	Vacant/not in use	English Heritage grant and final repairs to ceiling plaster will
	PRIORITY CATEGORY:	E (E)	be completed in 2013.
- Company	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1289674	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Remains of Lea Castle at Lower Lea Farm, Lea, Lydham	Fragmentary remains of a C12 castle surviving in the middle of a working farm. This was formerly a castle of the Bishops
	DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs	of Hereford. Victorian house abuts the castle remains which are heavily overgrown. Urgent need to reduce ivy growth, to be followed by repair and consolidation of
	CONDITION:	Poor	masonry. An application for English Heritage grant is expected.
	OCCUPANCY:	N/A	expected.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1021064 and 1054509	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES


- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument





Pentre Isaf is a farm complex with an attractive courtyard of outbuildings. The grade II* stone farmhouse is C17 but hides within it a CI5 timber- framed hall. The owner has embarked on a comprehensive programme of repairs.

Contact: Sarah Lewis 0121 625 6886

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© English Heritage

Canal Tak	SITE NAME:	Pitchford Hall, Pitchford	A large timber-framed country house built c1560-70 for
	DESIGNATION:	Listed Building grade I, RPG grade II	Adam Ottley but with an earlier CI4 or CI5 core. This is an outstanding example of a timber-framed building. The owner has completed some works but maintenance of the
A.	CONDITION:	Fair	roof, rainwater goods and infill panels is required. The property is vacant, but discussions have been opened
	OCCUPANCY:	Vacant/not in use	about a maintenance regime and the development of plans
	PRIORITY CATEGORY:	C (C)	for re-use.
ACTOR -	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	77907	Contact: Sarah Lewis 0121 625 6886

Nag's Head engine house,

Scheduled Monument

Pontesbury

Very bad

A (New entry)

N/A

Private

1018467

An engine house on the Pontesford coalfield which provided coal for the Pontesford lead smelters which served the south Shropshire lead mines. The building is in very poor condition, invasion of the structure by ivy and overhanging trees are an additional threat. The monument has been identified as part of a project in the Stiperstones and Corndon Hill Landscape Partnership funded by the Higher Level Stewardship scheme. English Heritage enabling grant has funded a survey, recording and the design of a repair programme, which now needs to be discussed with the owner.

Contact: Sarah Lewis 0121 625 6886

© English Heritage



	SITE NAME:	Brogyntyn Hall, Brogyntyn Park, Selattyn and Gobowen	centre of the park with pleasure grounds to the south
	DESIGNATION:	Listed Building grade II*, RPG grade II, CA	west. In institutional use until c1990. Now boarded up and deteriorating. Discussions are taking place with owner about the future of the building, the potential for alteration
	CONDITION:	Poor	and about different development options.
B	OCCUPANCY:	Vacant/not in use	
ł.	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1367373	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

CA LB

Conservation Area Listed Building

ABBREVIATIONS

WHS

- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UÁ

Unitary Authority World Heritage Site

HERITAGE AT RISK 2013 / WEST M	11DLANDS / SHROPSHIP	RE (UA)	
1	SITE NAME:	Lord Hill's Column, Abbey Foregate, Shrewsbury	A Coade stone statue, made in 13 sections, of Lord Hill of Hawkstone mounted on a giant stone column both taller
Shere .	DESIGNATION:	Listed Building grade II*	and wider than Nelson's Column. The monument was erected in 1816 to commemorate Rowland Hill as a
	CONDITION:	Poor	premier general in the Napoleonic War who was Wellington's second in command at Waterloo. The statue
	OCCUPANCY:	N/A	suffers badly from exposure to the weather, small sections
	PRIORITY CATEGORY:	A (New entry)	are flaking off and cracks have developed in the structure.
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1271374	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Town wall section west of Belmont Crescent, Shrewsbury	Medieval town walls. C13. Coursed and squared sandstone. The defences are subject to ongoing repair but
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II, CA	certain sections are deteriorating. Soft sandstone continues to weather and erode. Some damage from traffic. A condition survey and management plan are being prepared by Shropshire Council as the basis for a co-ordinated repair
	CONDITION:	Fair	programme.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1003709 and 1270530	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Town walls, Shrewsbury	Medieval town walls. C13. Coursed and squared
	DESIGNATION:	Scheduled Monument, CA	sandstone. The defences are subject to ongoing repair but certain sections are deteriorating. Soft sandstone continues
	CONDITION:	Poor	to weather and erode. Some damage from traffic. A Conservation Management Plan is needed.
	OCCUPANCY:	N/A	Conservation namagement nams needed.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1003710	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Apprentice House of former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury	Former apprentice house for flaxmill circa 1812, now disused. English Heritage is working in partnership with the Local Authority and the Homes and Communities Agency. A masterplan for the site now has Planning Permission, and
	DESIGNATION:	Listed Building grade II*, CA	the mill buildings have conditional Listed Building Consent. A Heritage Lottery Fund development grant has been
	CONDITION:	Poor	awarded to take forward the first phase of repair. The Friends group is flourishing.
	OCCUPANCY:	Vacant/not in use	Here's group is noursing.

© English Heritage

PRIORITY CATEGORY: D (B) OWNER TYPE: English Heritage LIST ENTRY NUMBER: 1254855 Contact: Sarah Lewis 0121 625 6886 Former flax mill, five storeys, built 1797 as first iron frame SITE NAME: Former Ditherington Flax Mill and attached former malt kiln, structure in the world. Converted to maltings 1897. The flax dressing building and flax flax dressing building, c.1803 and a flax warehouse. English Heritage is working in partnership with the Local Authority and the Homes and Communities Agency. A masterplan warehouse, Spring Gardens, Ditherington, Shrewsbury for the site now has Planning Permission. A Heritage DESIGNATION: Listed Building grade I, CA Lottery Fund development grant has been awarded to take forward the first phase of repair. The Friends group is CONDITION: Poor flourishing. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: **English Heritage** LIST ENTRY NUMBER: 1270576 Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good Е repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST M	IDLANDS / SHROPSHIP	RE (UA)		
	SITE NAME:	Stove House and Dye House at former Ditherington Flax Mill, Spring Gardens, Ditherington, Shrewsbury	Former drying stove house and dye house of flax mill, no disused. These buildings are an early and significant component of the flax mill complex. English Heritage is working in partnership with the Local Authority and the	
	DESIGNATION:	Listed Building grade II*, CA	Homes and Communities Agency. A masterplan for the site now has Planning Permission. A Heritage Lottery Fur	
	CONDITION:	Poor	development grant has been awarded to take forward th first phase of repair. The Friends group is flourishing.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	B (B)		
English Heritage	OWNER TYPE:	English Heritage		
	LIST ENTRY NUMBER:	1270566	Contact: Sarah Lewis 0121 625 6886	
	SITE NAME:	Pell Wall Hall, Newport Road, Sutton upon Tern	Country house, 1822-28 by Sir John Soane. After decade of neglect, compulsorily purchased by the Local Planning Authority and passed to a trust who repaired building she	
	DESIGNATION:	Listed Building grade II*, RPG grade II	and restored structural elements of the original Soane building with English Heritage grant. The property has	
	CONDITION:	Fair	changed hands several times. Repairs have started but ar	
	OCCUPANCY:	Vacant/not in use	currently stalled.	
	PRIORITY CATEGORY:	C (C)		
Particular	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1190426	Contact: Sarah Lewis 0121 625 6886	
	SITE NAME:	Hawkstone Windmill, Hawkstone Park, Weston- under-Redcastle	Late C18 windmill located just outside the registered par at Hawkstone Hall which was designed by William Emes the mid C18. The windmill sits in trees above the Hawk	
	DESIGNATION:	Listed Building grade II*	Lake in the part of the Park which is now a golf course. T building is unused and empty, a temporary roof was	
	CONDITION:	Poor	erected in August 1996 but the condition of the structure getting worse.	
maurin La Contra	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
*	OWNER TYPE:	Commercial company		
) English Heritage	LIST ENTRY NUMBER:	1264219	Contact: Sarah Lewis 0121 625 6886	
t an	SITE NAME:	Red Castle, Hawkstone Park, Weston-under-Redcastle	Remains of C12/C13 medieval castle in an important and largely restored C18 landscape. Masonry in vulnerable	
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I	condition and deteriorating. Invasive vegetation needs to be brought under control. A management approach need to be agreed.	
	CONDITION:	Poor		
No AND RECEIPT	OCCUPANCY:	N/A		
All with a	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1020850 and 1237180; 1264271	Contact: Sarah Lewis 0121 625 6886	
	SITE NAME:	The Old Pectory Claurit	Rectory, 1749. Listening station during World War II.	
	SHENARE.	The Old Rectory, Claypit Street, Whitchurch Urban	Urgent works were enforced to make roof watertight an	
	DESIGNATION:	Listed Building grade II*	arrest structural movement. The service wing remains in very poor condition. The property has recently changed	
IIIII .	CONDITION:	Poor	hands and Section 106 contributions have been secured.	
	OCCUPANCY:	Vacant/not in use	The new owner is exploring options for residential reuse	
And the Party of t	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1056008	Contact: Sarah Lewis 0121 625 6886	
) English Heritage				
) English Heritage				

- solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

redundant buildings with new use agreed but not yet implemented.

'New entry' is noted.

- LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM
 Scheduled Monument

 UA
 Unitary Authority

 WHS
 World Heritage Site

17

		()	
Alexander and	SITE NAME:	Cheney Longville Castle, Cheney Longville, Wistanstow	A fortified manor house complex dating from 1677 set around a courtyard. The north wing is in use as a
ALLER - PORT	DESIGNATION:	Listed Building grade II*, SM, CA	farmhouse and in fair condition but the rest of the buildings around the courtyard are only partially in use and are in a
	CONDITION:	Poor	vulnerable condition. Long term plans for a mixed use conversion to holiday accommodation and heritage
	OCCUPANCY:	Part occupied/part in use	interpretation have not yet been implemented. Emergency
	PRIORITY CATEGORY:	E (E)	repairs have been carried out with English Heritage grants and roof repairs completed under a Natural England
*	OWNER TYPE:	Private	stewardship scheme.
glish Heritage	LIST ENTRY NUMBER:	1269816	Contact: Sarah Lewis 0121 625 6886

© Engli



100	SITE NAME:	Hargreaves Farmhouse, Winnington, Wollaston	Timber-framed building dating from early C17 with C19 additions. Unoccupied for over 20 years and is in very poor
	DESIGNATION:	Listed Building grade II*	structural condition. The roof is holed, timber-framing is damaged by subsidence, and walls have collapsed. Owners
	CONDITION:	Very bad	have carried out urgent works including temporary roof to prevent water penetration/further collapse. The Local
	OCCUPANCY:	Vacant/not in use	Authority has offered grant towards repair costs but
	PRIORITY CATEGORY:	A (A)	without response.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1055173	Contact: Sarah Lewis 0121 625 6886

© English Heritage

© English Heritage



The monument comprises a smeltmill and slagmill built in SITE NAME: Snailbeach New Smeltmill, 1862 for the Snailbeach Mining Company. The slagmill has Worthen with Shelve been stabilised but standing remains of the smeltmill Scheduled Monument and Listed furnaces are in very poor condition due to invasive DESIGNATION: Buildings - 2 grade II uncontrolled vegetation. Extensive vegetation clearance and emergency propping has been carried out under a CONDITION: Very bad management agreement. OCCUPANCY: N/A PRIORITY CATEGORY: B (B) OWNER TYPE: Private LIST ENTRY NUMBER: 1017764 and 1307989; 1055031 Contact: Sarah Lewis 0121 625 6886



© English Heritage

SITE NAME:	Tankerville Lead Mine, Pennerley, Worthen with Shelve	C19 lead mine complex comprising engine house, chimney, ore hoppers, crushing and dressing floors. Major features including the engine house and shaft consolidated in 1996
DESIGNATION:	Scheduled Monument, 4 LBs, part in CA	with English Heritage grant aid. Tree and scrub growth has recolonized retaining walls to the dressing floor and reservoir. English Heritage grant has been offered for the
CONDITION:	Very bad	repair of the walls and should start in 2013 and be completed in 2014.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	B (New entry)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1014865	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park CA LB
- LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site





	SITE NAME:	Church of the Holy Trinity, Holdgate, Abdon	This medieval church stands within the bailey of what was once Holdgate Castle in the Corvedale below Clee Hill.
	DESIGNATION:	Listed Place of Worship grade I	The church is built of sandstone with a Broseley plain clay tile roof. The roofs and rainwater goods need replacement.
	CONDITION:	Poor	Poor drainage is causing rising damp and damage to a set of pews within the church. A Repair Grant for Places of
100	PRIORITY CATEGORY:	F (B)	Worship was offered and accepted in January 2013 and
S.M.	OWNER TYPE:	Religious organisation	repair works have begun to address these issues.
	LIST ENTRY NUMBER:	1383399	Contact: Sarah Lewis 0121 625 6886

© English Heritage

© English Heritage

	SITE NAME:	Heath Chapel, Stoke St Milborough, Heath	This small Norman chapel consists of a nave and lower chancel with broad full height clasping buttresses and
1	DESIGNATION:	Listed Place of Worship grade I, SM	lesenes, a continuous mid-height string course, tiny round head windows and a richly decorated south doorway. The church was repaired following SPAB principles by Basil
C	CONDITION:	Poor	Stallybrass in 1912 but assorted repairs including the relaying of the chancel roof, the renewal of rainwater
	PRIORITY CATEGORY:	C (New entry)	goods, the installation of a surface water drainage system
	OWNER TYPE:	Private, multiple owners	and assorted masonry consolidation and repointing works are now all urgently required.
	LIST ENTRY NUMBER:	1383722	Contact: Sarah Lewis 0121 625 6886

© English Heritage

SITE NAME:	Little Shrawardine motte and bailey castle, Alberbu	ry with Cardeston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019198
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Ringwork 540 metres north of Lane Farm, Alberbu	ry with Cardeston	
SITE NAME: DESIGNATION:	Ringwork 540 metres north of Lane Farm, Alberbu Scheduled Monument	ry with Cardeston	1019831
	5	7	1019831 Unknown
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WES	I MIDLANDS / SHROPSHIRE (UA)		
SITE NAME:	Stanwardine moated site and associated fishpond,	Baschurch	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	The Burgs, Bayston Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003016
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Lower Cleeton moat, a moat and fishponds 380 m	etres south east of	Cleeton Court, Bitterley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010496
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	White Ladies (St Leonard's) Priory, Boscobel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015290
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	ER TYPE: Mixed, multiple owners		Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 450 metres north west of Felton Far	m, Bromfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007712
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman camp north of Bromfield Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006273
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Castle Tump, a motte castle and causeway, 150 m	etres west of Teme	Bridge, Burford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Moated site and fishponds 250 metres south we	st of Middleton Farm	Chirbury with Brompton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019009
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems		Declining
PRINCIPAL VULNERABILITY:			No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Motte and bailey castle 150 metres north east o	f Wilmington, Chirbu	ry with Brompton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section 2/3 mile (1170 metres) long with Brompton	g, north from souther	n boundary of Rownal Covert, Chirbur
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1003013
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section one mile 750 yards (2290 n metres) north of Lack Brook - Also in Powys: V		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003797
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
DWNER TYPE: Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: two sections running 400 yards (37 Chirbury with Brompton	0 metres) south of Ca	amlad Stream - Also in Powys: Wales,
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1006259
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Motte castle 80 metres north east of Home Far	m, Church Stretton	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 390 metres south east of Stanley G	Cottage, Clunbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016664
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WES	T MIDLANDS / SHROPSHIRE (UA)		
SITE NAME:	Norton Camp: a large multivallate hillfort, Culming	ton / Craven Arms	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021073
CONDITION:	Generally unsatisfactory with major localised TREND: Stable problems		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	The Mount motte and bailey castle, 120 metres no	rth east of Hill Hou	ise Farm, Diddlebury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012856
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman villa north east of Cottage Coppice, Harley	/ Much Wenlock	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002934
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section 90 metres south of Brynorgan	, Llanfair Waterdin	e
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020905
CONDITION:	IDITION: Generally satisfactory but with significant localised TREND: problems		Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section 890 metres north west and 32	20 metres west of L	ittle Selley, Llanfair Waterdine
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section on the western slope of Llanfa Waterdine	ir Hill, 1.4 kilometr	es south west of Burfield, Llanfair
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020902
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Nickless moat, Milson		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009552
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

22

SITE NAME:	Callow Hill Camp: a small multivallate hillfort, Mins	terley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019828
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Sarah Lewis 0121 625 6886
site name:	Roman villa at Linley Hall, More		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1006253
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section 175 metres east of Cefn Bron	ydd, Newcastle on	Clun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020899
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Small enclosed settlement on Fron, 340 metres we	st of St John's Chu	rch, Newcastle on Clun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021069
CONDITION:	NDITION: Generally unsatisfactory with major localised TREN		Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Offa's Dyke: section 400 metres south west of Spr Waterdine	inghill Farm, Newca	ustle on Clun / Clun / Llanfair
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020901
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman villa 150 yards (140 metres) south east of L	ea Hall, Pontesbury.	/
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006246
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Wat's Dyke, 490 metres long section, immediately Gobowen / St. Martin's	north and south of	Preeshenelle Bridge, Selattyn and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020615
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY ?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Roman camps south west of Stoneyford Cottag	jes, Shifnal	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006249
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman fort 300 metres east of Drayton Lodge	Farm, Shifnal	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020283
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Uxacona Roman site (see also Telford and Wre Lilleshall and Donnington	ekin Unitary Authority)	, Shifnal / St. Georges and Priorslee /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003811
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman military site at Rhyn Park, St. Martin's		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003716
CONDITION:	Unknown	TREND:	Jnknown
PRINCIPAL VULNERABILITY:	BILITY: Arable ploughing N		No
WNER TYPE: Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Camp Ring motte and bailey castle, enclosure, t Farm, Stanton Lacy	ishpond and ridge and	furrow 400 metres east of Culmington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012855
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Medieval fishpond reservoir north east of Haug Uffington / Upton Magna	hmond Abbey and sou	th west of the hamlet of Haughton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002953
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Moated site and fishpond 450 metres north we	st of Hunkington, Upto	on Magna
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019645
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Robury Ring: a small enclosed settlement on Wenti	or Prolley Moor	Wenthor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021072
	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:		CONTACT:	
Owner TIFE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Hawcocks Mount ringwork castle 200 metres north	east of Hawcocks	s Farm, Westbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Upper Barn moat, Wistanstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Bowl barrow 120 metres south west of Dorrington	Cottage, Pipe Gat	e, Woore
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016829
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow at The Napp, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017347
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Moated site at Leigh Hall, Worthen with Shelve		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019010
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Snailbeach New Smeltmill, 350 metres north east o	f Green Acres, Wo	orthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Two bowl barrow	ws 290 metres north of Upper Ho	ouse Farm, Worthe	n with Shelve	
DESIGNATION:	Scheduled Monument Unknown		LIST ENTRY NUMBER:	1016666	
CONDITION:			TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886	
	SITE NAME:	Acton Burnell, Acton Burnell / Cound / Ruckley and Langley	Medieval deer park developed as landscape park asso with country house in the C18. In recent years signific		
	DESIGNATION:	Registered Park and Garden grade II, 8 LBs, part in SM, part in CA	within the registe	elopment of education and sports facilitie ered landscape. Areas of historic parkland , including boundary belts, parkland park wall.	
10.01	CONDITION:	Generally unsatisfactory with major localised problems		'	
	VULNERABILITY:	Medium			
) English Heritage	TREND:	Stable	Contact: Sarah Lewis 0121 625 6886		
Lingusti i leritage	NEW ENTRY?:	No			
	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1001112			
	SITE NAME:	Condover Hall, Condover	Gardens and pleasure grounds, mostly C19, developed from earlier layout around C16 Hall. Condition of pleas grounds generally good. Park has fared less well. Prominently sited post-war residential development,		
	DESIGNATION:	Registered Park and Garden grade II, 9 LBs, part in CA			
	CONDITION:	Generally unsatisfactory with major localised problems		ensive farming, deterioration of plantations and a lapsing section of park wall.	
	VULNERABILITY:	Medium			
	TREND:	Unknown			
	NEW ENTRY?:	No			
) English Heritage	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1001118	Contact: Sarah L	ewis 0121 625 6886	
SITE NAME:	Clee View, Highl	ey			
DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	No	
CONDITION:	Poor		TREND:	Deteriorating	
VULNERABILITY:	Low		CONTACT:	Colin Richards (LPA) 01743 255662	
SITE NAME:	Llanymynech, Lla	nymynech and Pant			
	C	ea, 12 LBs, 2 SMs	NEW ENTRY ?:	No	
DESIGNATION:	Conservation Are	za, 12 LD3, 2 51 15		110	
designation: Condition:	Very bad	ea, 12 LDS, 2 31 13	TREND:	Deteriorating significantly	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Shropshire (UA) / Telford and Wrekin (UA)					
© English Heritage	SITE NAME:	Lilleshall Hall, Sheriffhales / Chetwynd Aston and Woodcote / Lilleshall and Donnington	Designed landscape largely creation of the C19. Gardens and pleasure grounds survive, generally in satisfactory condition. However, substantial loss of design integrity where new buildings erected for National Sports Centre.		
	DESIGNATION:	Registered Park and Garden grade II, 12 LBs, part in SM, part in CA	Levels altered to facilitate sports pitches and golf course, although some historic plantings remain. Part of the park is in the district of Telford and Wrekin.		
	CONDITION:	Generally satisfactory but with significant localised problems			
	VULNERABILITY:	High			
	TREND:	Stable			
	NEW ENTRY?:	No			
	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1001126	Contact: Sarah Lewis 0121 625 6886		

STAFFORDSHIRE	
---------------	--

CANNOCK CHASE

SITE NAME:	Talbot Street/Lichfield Street, Rugeley / Brereton and Ravenhill		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Angela Grove (LPA) 01543 464517

EAST STAFFORDSHIRE

	SITE NAME:	The Orangery, Blithfield	The Orangery is a stone building designed by James
	DESIGNATION:	Listed Building grade II*, CA	'Athenian' Stuart for Sir William Bagot in circa 1769. It is one of a number of listed buildings and structures at
	CONDITION:	Poor	Blithfield Hall. Rainwater penetration is causing the deterioration of stonework and internal plasterwork. An
	OCCUPANCY:	N/A	English Heritage grant has been offered for repairs.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1038399	Contact: Sarah Lewis 0121 625 6886

© English Heritage



DESIGNAT CONDITIC OCCUPAN PRIORITY (SITE NAME:	Sinai Park, Burton on Trent, Branston	Mid C17 house. Part repaired, priority category applies to un-repaired parts of the house. First phase of repair
	DESIGNATION:	Listed Building grade II*, SM	programme completed some years ago, but remaining two thirds of building continues to deteriorate and now in
	CONDITION:	Very bad	critical condition with areas of partial collapse.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1038484	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

implemented.

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet

C Slow decay; no solution agreed.

А

В

© English Heritage

RIORITY CATEGORIES		
Immediate risk of further rapid deterioration or loss of fabric; no	D	Slow decay; solut not yet implement

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / EAST STAFFORDSHIRE

LIST ENTRY NUMBER:



Gates and gatepiers at Hoar Cross Hall, Maker Lane, Hoar SITE NAME: Cross, Yoxall DESIGNATION: Listed Building grade II*, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

1038479

Pair of gates and gate piers of circa 1700, moved to present site circa 1870. The wrought iron gates are corroding, the wall and piers need repair. Requires further inspection and review.

© English Heritage

Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Enclosures and cursus 300 yards (270 metres) so	outh east of Efflinch, B	arton-under-Needwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006073
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Timber circle, hengi-form monument and part o	f a pit alignment at Ca	tholme, Barton-under-Needwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019109
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosure 350 yards (320 metres) north of Tive;	r's House, Dunstall	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006075
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 330 metres east of Weaver Farm,	Wootton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009412
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Circular enclosures 100 yards (90 metres) south	west of Bonthorn, W	/ychnor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006094
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Circular enclosures centring 300 yards (270 met	res) west of Wychno	r Junction, Wychnor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006072
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / EAST STAFFORDSHIRE / LICHFIELD

SITE NAME:	Two large circular enclosures centring 150 metr	es south east of Bagga	ley's Wood, Wychnor	
DESIGNATION:	Scheduled Monument	Scheduled Monument LIST ENTRY NUMBER: 1006096		
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Clarence Street/Anglesey Road, Burton upon Tr	ent, Anglesey		
DESIGNATION:	Conservation Area, 2 LBs NEW ENTRY?: No		No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	High	CONTACT:	Peter Short (LPA) 01283 508624	
SITE NAME:	George Street, Burton			
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No	
CONDITION:	Very bad	TREND:	Improving	
VULNERABILITY:	High	CONTACT:	Peter Short (LPA) 01283 508624	

LICHFIELD



Wall and gate piers circa 1730. In poor condition. The Local Authority is in contact with the owners regarding possible grant aid. It has been necessary to carry out important repair work to the house over the last year, so as yet little work has been carried out on the gatepiers. It is hoped the repairs will be carried out soon.

Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

	SITE NAME:	Angel Croft Hotel, front railings and gates, Beacon Street, Lichfield	A fine three storey hotel, built circa1750 in brick with ashlar dressings, the railings and gates are included in listing and are also in poor condition. The building has been
	DESIGNATION:	Listed Building grade II*, CA	empty for some time. There has been water damage to ceilings as a result of break-ins but this has now dried out
	CONDITION:	Poor	and the building appears to have stabilised. A sale has been agreed on the building and discussions about repair and re-
	OCCUPANCY:	Vacant/not in use	use are due to begin with the Council.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1187354	Contact: Sarah Lewis 0121 625 6886



sie.	SITE NAME:	Church Tower north of Church of St John, St Johns Hill, Shenstone	Church tower. CI3 with later alterations. Derelict. No plans for future use at present. Local Planning Authority building inspectors have visited and structure considered
and the second	DESIGNATION:	Listed Building grade II*, CA	stable at present. English Heritage architect has visited and advised on removal of ivy. The Local Planning Authority is
10 - 2	CONDITION: Very bad	trying to open constructive discussions with the Parish Council and church to agree a repair scheme.	
	OCCUPANCY:	N/A	council and charen to agree a repair scheme.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1038830	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PR	IORITY C	CATEGORIES
	Income allow	

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / LICHFIELD / NEWCASTLE-UNDER-LYME

Bisters National Scheduled MonumentList PATRY NUMBER1006090CONDITIONUnknownTREND:UnknownPRENCENA VULNERABUTTY:OtherNEW ENTRY:NoPRENCENA VULNERABUTTY:OtherNEW ENTRY:NoPRENCENA VULNERABUTTY:OtherNEW ENTRY:NoPRENCENA VULNERABUTTY:OtherCONTACT:Sarah Lewis 0121 625 6886PRENCENA VULNERABUTY:Arable ploughingNEW ENTRY:NoDESIGNATION:UnknownNEW ENTRY:NoPRENCENA VULNERABUTY:Arable ploughingNEW ENTRY:NoDOWNERTYESCoasewayed enclosure, Fradley and Streethay1002964CONTACT:Scheduled MonumentILIT ENTRY NUMBER:1002964CONTACT:Scheduled MonumentNEW ENTRY:NoCONTACT:Scheduled MonumentILIT ENTRY NUMBER:1002964CONTACT:Scheduled MonumentILIT ENTRY NUMBER:1006091CONTACT:Scheduled MonumentILIT ENTRY NUMBER:1006091CONTACT:Scheduled MonumentILIT ENTRY NUMBER:1006091CONTA				
CONDITION-UnknownTREND:UnknownRRINCIPAL VULNEXABILITY:OtherNEW ENTRY:NoOWNER TYPE:Commercial company, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Air photographic site south west of Elford, FishervicUnknown1006100CONTON:Scheduled MonumentUST ENTRY NUMBER:1006100CONTON:UnknownTREND:UnknownCONTACT:Scheduled MonumentUST ENTRY NUMBER:1006100CONTACT:Causewayed enclosure, Fradley and StreethaySarah Lewis 0121 625 6886STE NAME:Causewayed enclosure, Fradley and StreethayUnknownCONTACT:Scheduled MonumentUST ENTRY NUMBER:1002964CONTACT:Scheduled MonumentUST ENTRY NUMBER:1002964CONTACT:Scheduled MonumentUST ENTRY NUMBER:1002964CONTACT:Scheduled MonumentUST ENTRY NUMBER:1002964CONTACT:Settlement sites and enclosures 500 yards (460 metry)Orthe ast of 211 625 6886Streethay EntryArable ploughingNew ENTRY:NoDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1006091CONTACT:Scheduled Monument, 3 LBS, CAUST ENTRY NUMBER:1006119CONTACT:Scheduled Monument, 3 LBS, CAUST ENTRY NUMBER:1006119CONTACT:Scheduled Monument, 3 LBS, CAUST ENTRY NUMBER:1006119CONTACT:Scheduled Monument, 3 LBS, CAUST ENTRY NUMBER:NoCONTACT:Scheduled Monument, 3 LBS, C	SITE NAME:	Site of round barrow near River Tame, Alrewas		
RINK CRALL VULNERABLITY: Other No DWNER TYPE: Commercial company, multiple owners CONTACT: Sarah Lewis 0121 625 6886 DUMNER TYPE: Air photographic site south west of Elford, Fisherwick 1006100 DESIGNATION: Scheduled Monument Lot INTRY NUMBER: 1006100 CONTACT: Scheduled Monument Lot INTRY NUMBER: 1006100 CONTACT: Sarah Lewis 0121 625 6886 Scheduled Monument Local authority, multiple owners CONTACT: Sarah Lewis 0121 625 6886 DESIGNATION: Causewayed enclosure, Fradley and Streethay CONTACT: Sarah Lewis 0121 625 6886 DESIGNATION: Scheduled Monument LST INTRY NUMBER: 1002964 CONDITION: Unknown TEEND: Unknown RINCRAL VULNERABUTY: Arable ploughing No No CONDITION: Unknown TEEND: Unknown RINCRAL VULNERABUTY: Arable ploughing No No CONDITION: Unknown TEEND: Unknown RINCRAL VULNERABUTY: Arable ploughing No Scheduled Monument; <td>DESIGNATION:</td> <td>Scheduled Monument</td> <td>LIST ENTRY NUMBER:</td> <td>1006090</td>	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006090
Control Control Control Sarah Lewis 0121 625 6886 STEE NAME Air photographic site south west of Elford, Fisherwick Sarah Lewis 0121 625 6886 STEE NAME Air photographic site south west of Elford, Fisherwick 1006100 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006100 DINKNOWN TREND: Unknown No REINCIPAL VULMERABILITY: Arable ploughing CONTACT: Sarah Lewis 0121 625 6886 DOWNER TYPE: Causewayed enclosure, Fradley and Streethay Io02964 Io02964 DOWNER TYPE: Chaknown TREND: Unknown RENDERING Unknown TREND: Unknown RENDERING Unknown TREND: No DESIGNATION: Scheduled Monument TREND: No	CONDITION:	Unknown	TREND:	Unknown
Air photographic site south west of Elford, Fisherwick Besignarition: Scheduled Monument UST ENTRY NUMBER 1006100 Unknown TREND: Unknown REND: Unknown Arable ploughing NEW INTRY: No Sarah Lewis 0121 625 6886 STE NAME: Constraction: Scheduled Monument UST ENTRY NUMBER: 1002964 Constraction: Unknown REND: Unknown REND: Unknown REND: Unknown REND: Unknown REND: Extensive significant problems REND: Declining REND: No 121 625 6886 REND: UNKREND: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER 1060119 CONDITION: Extensive significant problems REND: Declining REND: Declining REND: No 121 625 6886 REND: Declining REND: No 121 625 6886 REND: Declining REND: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER 106119 CONDITION: Extensive significant problems REND: Declining REND: No 121 625 6886 REND: Declining REND: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER 106119 CONDITION: Extensive significant problems REND: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER 106119 CONDITION: Extensive significant problems REND: No 121 625 6886 REND: No 121 625 6886 REND: NO 121 625 6886 REND: NO 121 625 6886 REND: NO 1	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
Designation:Scheduled MonumentUst ENTRY NUMBER:1006100CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Local authority, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Causewayed enclosure, Fradley and Streethay1002964CONDITION:UnknownTREND:UnknownCONTACT:Scheduled MonumentUST ENTRY NUMBER:1002964CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1006091DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1006091CONDITION:UnknownTREND:UnknownNoRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateContract:Sarah Lewis 0121 625 6886OWNER TYPE:UnknownTREND:UnknownRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateManor House, Hamstall RidwareSarah Lewis 0121 625 6886Streethay:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsREND:DecliningRINCIPAL VULNERABILITY:CollapseNoSarah Lewis 0121 625 6886Streetha	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION:UnknownTREND:UnknownRINCIPAL VULNERABILITY:Arable ploughingNeW ENTRY:NoDWNER TYPE:Local authority, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1002964CONTOR:UnknownTREND:UnknownRINICIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoDESIGNATION:OnlynamePrivate, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Settlement sites and enclosures 500 yards (460 metry:Stran Lewis 0121 625 6886DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091DESIGNATION:Control:Sarah Lewis 0121 625 6886Stran Lewis 0121 625 6886DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091DESIGNATION:Control:Sarah Lewis 0121 625 6886Stran Lewis 0121 625 6886DESIGNATION:Control:Sarah Lewis 0121 625 6886Stran Lewis 0121 625 6886DESIGNATION:Control:Sarah Lewis 0121 625 6886Stran Lewis 0121 625 6886DESIGNATION:Control:Stransve significant problemsIST ENTRY NUMBER:1006119CONTACT:Scheduled Monument, 3 LBs, CAStran Lewis 0121 625 6886Stran Lewis 0121 625 6886CONTACT:Scheduled Monument, 3 LBs, CAStran Lewis 0121 625 6886Stran Lewis 0121 625 6886CONTACT:Scheduled Monument, 3 LBs, CAStran Lewis 0121 625 6886Stran Lewis 0121 625 6886CONTACT:Scheduled Mon	SITE NAME:	Air photographic site south west of Elford, Fisher	wick	
RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Local authority, multiple owners CONTACT: Sarah Lewis 0121 625 6886 STE NAME Causewayed enclosure, Fradley and Streethay USE ENTRY NUMBER: 1002964 STE NAME Scheduled Monument USE ENTRY NUMBER: 1002964 CONTACT: Scheduled Monument USE ENTRY NUMBER: 1002964 CONTACT: Vanborn NEW ENTRY: No PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No ODWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 STEE NAME: Settlement sites and enclosures 500 yards (460 metry: No No CONTACT: Scheduled Monument LIST ENTRY NUMBER: 1006091 CONTOTION: Scheduled Monument LIST ENTRY NUMBER: 1006091 CONTACT: Sarah Lewis 0121 625 6886 Site ENTRY NUMBER: 1006091 CONTOTION: Unknown TREND: Unknown Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER: 1006119 CONTION:	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006100
DWNER TYPE:Local authority, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Causewayed enclosure, Fradley and Streethay:1002964DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1002964CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersOUTACT:Sarah Lewis 0121 625 6886DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1006091CONDITION:Scheduled MonumentINEND:UnknownCONDITION:Scheduled MonumentINEND:UnknownCONDITION:Arable ploughingNEW ENTRY:NoCONDITION:Arable ploughingNEW ENTRY:NoDESIGNATION:Scheduled Monument, 3 LBs, CAUST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningCONDITION:CollapseNEW ENTRY:NoCONDITION:CollapseNEW ENTRY:NoCONTACT:Brank Lewis 0121 625 6886Sarah Lewis 0121 625 6886CONDITION:CollapseNEW ENTRY:NoCONTACT:Scheduled Monument, 3 LBs, CAUST ENTRY NUMBER:NoCONTACT:CollapseNEW ENTRY:NoCONTACT:Scheduled Monument, 3 LBs, CANEW ENTRY:NoCONTACT:CollapseNEW ENTRY:NoCONTACT:Pri	CONDITION:	Unknown	TREND:	Unknown
STE NAME Causewayed enclosure, Fradley and Streethay DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002964 CONDITION: Unknown TREND: Unknown RRINCIPAL VULNERABILITY: Arable ploughing NeW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 STE NAME Settement sites and enclosures 500 yards (460 metry: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006091 CONDITION: Unknown TREND: Unknown DESIGNATION: Scheduled Monument No No CONDITION: Unknown TREND: Unknown OWNER TYPE: Private CONTACT: Sarah Lewis 0121 625 6886 DESIGNATION: Scheduled Monument, 3 LBS, CA UNEW ENTRY: No CONDITION: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER: 1006119 CONDITION: Scheduled Monument, 3 LBS, CA UST ENTRY NUMBER: 1006119 CONDITION: Scheduled Monument, 3 LBS, CA No Declining CONDITION: Collapse NEW ENTRY:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
Designations:Scheduled MonumentUST ENTRY NUMBER:1002964CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SETE NAMESettlement sites and enclosures 500 yards (460 met-s) north east of Steles Farm, Fradley and StreethayDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091CONDITION:UnknownTREND:UnknownCONDITION:UnknownREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningCONTACT:CollapseNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886CONDITION:Extensive significant problemsTREND:DecliningCONTACT:CollapseNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886CONTACT:Extensive significant problemsTREND:DecliningCONTACT:CollapseNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886CONTACT:Extensive significant problemsCONTACT:Sarah Lewis 0121 625 6886	OWNER TYPE:	Local authority, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Settlement sites and enclosures 500 yards (460 metry) north east of Streethay and StreethayDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091CONDITION:UnknownTREND:UnknownRRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoOWNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:ContractUnknownCONTACT:Sarah Lewis 0121 625 6886DOWNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886DESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119DESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningRRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886CONDITION:Extensive significant problemsCONTACT:Sarah Lewis 0121 625 6886CONDITION:Fazeley and Bonehill, Fazeley / Drayton BassettSarah Lewis 0121 625 6886CONTACT:Sarah Lewis 0121 625 6886Extensive significant problemsSarah Lewis 0121 625 6886CONDITION:Conservation Area, 12 LBSNEW ENTRY?:NoCONDITION:Very badNEW ENTRY? </td <td>SITE NAME:</td> <td>Causewayed enclosure, Fradley and Streethay</td> <td></td> <td></td>	SITE NAME:	Causewayed enclosure, Fradley and Streethay		
RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Settlement sites and enclosures 500 yards (460 metres) north east of Stress Farm, Fradley and Streethay DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006091 CONDITION: Unknown TREND: Unknown OWNER TYPE: Private CONTACT: Sarah Lewis 0121 625 6886 DESIGNATION: Scheduled Monument TREND: No OWNER TYPE: Private CONTACT: Sarah Lewis 0121 625 6886 DESIGNATION: Scheduled Monument, 3 LBs, CA UST ENTRY NUMBER: 1006119 DESIGNATION: Scheduled Monument, 3 LBs, CA UST ENTRY NUMBER: 1006119 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems EVENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 6	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002964
OWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SETE NAME:Settlement sites and enclosures 500 yards (460 meters) sorth east of SETER TAME with the Scheduled MonumentINSTENTRY NUMBER1006091DESIGNATION:OhnownTREND:UnknownTREND:CONTITION:OhnownTREND:OhnownNew ENTRY:PRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateManor House, Hamstall RidwareStentry NUMBER:100619STEN NAME:Manor House, Hamstall RidwareISTE NTRY NUMBER:100619CONDITION:Scheduled Monument, 3 LBs, CAISTE NTRY NUMBER:100619CONDITION:CollapseNEW ENTRY:NoCONDITION:CollapseNEW ENTRY:NoOWNER TYPE:Private, multiple ownersConTACT:Sarah Lewis 0121 625 6886OWNER TYPE:Fazely and Engle for Area, 12 LBsNEW ENTRY:NoDESIGNATION:Conservation Area, 12 LBsNEW ENTRY:NoCONDITION:Very badYery badTREND:Improving	CONDITION:	Unknown	TREND:	Unknown
Settlement sites and enclosures 500 yards (460 meters) north east of Stitles Farm, Fradley and Streethay DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006091 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private CoNTACT: Sarah Lewis 0121 625 6886 STEE NAME Manor House, Hamstall Ridware Information 1006119 CONDITION: Scheduled Monument, 3 LBS, CA LIST ENTRY NUMBER: 1006119 CONDITION: Extensive significant problems TREND: Declining CONDITION: Collapse New ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 CONDITION: Extensive significant problems TREND: Declining CONDITION: Fatee, multiple owners CONTACT: Sarah Lewis 0121 625 6886 STE NAME: Fazeey and Bonehill, Fazeley / Drayton Bassett Sarah Lewis 0121 625 6886 STE NAME: Fazeey and Bonehill, Fazeley / Drayton Bassett Sarah Lewis 0121 625 6886 STE NAME: Conservation Area, 12 LBs New ENTRY:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1006091CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNRER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Manor House, Hamstall RidwareScheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119DESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNRER TYPE:Frivate, multiple ownersCONTACT:Sarah Lewis 0121 625 6886STET NAME:Fazeley and Bonehill, Fazeley / Drayton BassettSontact:Sarah Lewis 0121 625 6886STET NAME:Conservation Area, 12 LBsNEW ENTRY?:NoDESIGNATION:Very badTREND:Improving	OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Manor House, Hamstall RidwareStehduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Fazeley and Bonehill, Fazeley / Drayton BassettSarah Lewis 0121 625 6886SITE NAME:Conservation Area, 12 LBsNEW ENTRY?:NoCONDITION:Very badTREND:Improving	site name:	Settlement sites and enclosures 500 yards (460 m	etres) north east of	Sittles Farm, Fradley and Streethay
PRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Manor House, Hamstall RidwareIsst ENTRY NUMBER:1006119DESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningCONDITION:CollapseNEW ENTRY?:NoPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886STEE NAME:Fazeley and Bonehill, Fazeley / Drayton BassettSteen Steen Stee	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006091
OWNER TYPE:PrivatePrivateCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Manor House, Hamstall RidwareUST ENTRY NUMBER:1006119DESIGNATION:Scheduled Monument, 3 LBS, CAUST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersConTACT:Sarah Lewis 0121 625 6886SITE NAME:Fazeley and Bonehill, Fazeley / Drayton BassettSarah Lewis 0121 625 6886DESIGNATION:Conservation Area, 12 LBSNEW ENTRY?:NoONDITION:Very badTREND:Improving	CONDITION:	Unknown	TREND:	Unknown
SITE NAME:Manor House, Hamstall RidwareDESIGNATION:Scheduled Monument, 3 LBs, CALIST ENTRY NUMBER:1006119CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Fazeley and Bonehill, Fazeley / Drayton BassettSocial Conservation Area, 12 LBsNEW ENTRY?:NoCONDITION:Very badTREND:Improving	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument, 3 LBs, CA LIST ENTRY NUMBER: 1006119 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Collapse New ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Fazeley and Bonehill, Fazeley / Drayton Bassett Very bad New ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:CollapseNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Fazeley and Bonehill, Fazeley / Drayton BassettVersion of Conservation Area, 12 LBsNEW ENTRY:NoCONDITION:Very badTREND:Improving	SITE NAME:	Manor House, Hamstall Ridware		
PRINCIPAL VULNERABILITY: Collapse NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Fazeley and Bonehill, Fazeley / Drayton Bassett Very bad Designation: Conservation Area, 12 LBs NEW ENTRY?: No CONDITION: Very bad TREND: Improving	DESIGNATION:	Scheduled Monument, 3 LBs, CA	LIST ENTRY NUMBER:	1006119
OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Fazeley and Bonehill, Fazeley / Drayton Bassett Very bad New ENTRY?: No CONDITION: Very bad TREND: Improving	CONDITION:	Extensive significant problems	TREND:	Declining
STEE NAME: Fazeley and Bonehill, Fazeley / Drayton Bassett Designation: Conservation Area, 12 LBs CONDITION: Very bad	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
DESIGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving	OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION: Very bad TREND: Improving	SITE NAME:	Fazeley and Bonehill, Fazeley / Drayton Bassett		
	DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
VULNERABILITY: Low CONTACT: Debbie Boffin (LPA) 01543 308203	CONDITION:	Very bad	TREND:	Improving
	VULNERABILITY:	Low	CONTACT:	Debbie Boffin (LPA) 01543 308203

NEWCASTLE-UNDER-LYME



	SITE NAME:	Model farm complex south west of Betley Old Hall, Main Street, Betley	Early C19 model farm including range of cowhouses, granary, cartshed, stables and watermill. The owner is preparing a scheme for repair and reuse.
20	DESIGNATION:	Listed Building grade II*, CA	
1	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
C. Sel	PRIORITY CATEGORY:	C (C)	
3	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1188395	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

PRIORITY CATEGORIES	
---------------------	--

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / NEWCASTLE-UNDER-LYME / PEAK DISTRICT (NP)

LIST ENTRY NUMBER:

ALAN	SITE NAME:
	DESIGNATION:
	CONDITION:
	OCCUPANCY:
Noperative Con	PRIORITY CATEGORY:
	OWNER TYPE:

Castle remains. Medieval, probably mainly early C13. Only fragments of walling survive due to being partly demolished in the Civil War. Heavily overgrown and masonry eroding. In very poor condition. Management Agreement to be Scheduled Monument and Listed considered with owner for vegetation clearance prior to condition survey and masonry consolidation.

Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

	SITE NAME:	Gatehouse, walls and bollards to Maer Hall, Maer	Late C18 gatehouse, walls and bollards, forming the approach to Maer Hall. The Hall is set in an early C19 park
	DESIGNATION:	Listed Building grade II*, CA	by John Webb. Property is associated with Wedgwood and Darwin families. Condition of gatehouse continues to
	CONDITION:	Poor	deteriorate. Repairs to roof, gables and stonework required. Further negotiations are underway regarding
	OCCUPANCY:	N/A	repairs.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1027834	Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Butterton, Newcastle under Lyme, Whitmore		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Louise Wallace (LPA) 01782 717717

Heighley Castle, Heighley Lane,

Madeley

Poor N/A A (A) Private

Building grade II

1011070 and 1353703

PEAK DISTRICT (NP)

· · ·			
A DE	SITE NAME:	Critchlow Monument, Sheen, Staffordshire Moorlands	Chest tomb and railing c1853. In poor condition.
	DESIGNATION:	Listed Building grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
eritage	LIST ENTRY NUMBER:	37455	Contact: Sarah Lewis 0121 625 6886

© English Heri

SITE NAME:	Bowl barrow 450 metres east of Stanshope, Alstonefield, Staffordshire Moorlands			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010798	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Copper mines on Ecton Hill, Wetton, Staffordshire	Moorlands		
SITE NAME: DESIGNATION:	Copper mines on Ecton Hill, Wetton, Staffordshire Scheduled Monument	Moorlands	1021175	
			1021175 Declining	
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SOUTH STAFFORDSHIR	E		
	SITE NAME:	Stable Court at Four Ashes Hall, Four Ashes, Enville	Stable court, incorporating extensive farm outbuilding ranges. Mid to late C18, with C20 alterations. One range
	DESIGNATION:	Listed Building grade II*	has virtually collapsed and roofs are in very bad state. A programme of urgent repairs to main frontage of building
	CONDITION:	Very bad	was completed in 2006 with English Heritage grant, but the rest of the building remains in very poor condition. English
	OCCUPANCY:	Vacant/not in use	Heritage architect has visited and discussions on funding
	PRIORITY CATEGORY:	A (A)	package continue.
A A A	OWNER TYPE:	Private	
© English Heritage Archive	LIST ENTRY NUMBER:	1277027	Contact: Sarah Lewis 0121 625 6886

CAMPES C	:
	I
A CAMPANE MAL	•
可能学生的	•
	l
Contraction of the second seco	•

	SITE NAME:	The Conservatory, Hilton Park, Hilton	Unusual circular domed Conservatory, thought to have been a forcing house. Built in the early C19 of brick, wood,			
	DESIGNATION:	Listed Building grade I	metal and glass. Derelict and in very poor condition. Cast iron corroding and splitting. Rear half of timber dome has			
ALC: NO	CONDITION:	Very bad	dropped significantly, and currently propped. Pointing is eroding badly and most of glass missing. The offer of an			
	OCCUPANCY:	Vacant/not in use	English Heritage grant for repairs has been accepted.			
ł	PRIORITY CATEGORY:	B (B)				
	OWNER TYPE:	Commercial company				
	LIST ENTRY NUMBER:	1039176	Contact: Sarah Lewis 0121 625 6886			

SITE NAME:	Roman fort west of Eaton House, Brewood and	Roman fort west of Eaton House, Brewood and Coven				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006098			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Roman villa 300 yards (270 metres) north west o	of Engleton Hall, Brew	vood and Coven			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006082			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886			
site name:	Site of Pennocrucium, east of Stretton Bridge, Br	ewood and Coven / I	apley, Stretton and Wheaton Aston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006121			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No			
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Two Roman camps near Greensforge, Kinver / S	windon				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006080			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No			
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / SOUTH STAFFORDSHIRE / STAFFORD

SITE NAME:	Camp north east of Stretton Mill, Lapley, Stretto	Camp north east of Stretton Mill, Lapley, Stretton and Wheaton Aston				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006120			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Two Roman camps north of Water Eaton, Lapley	Two Roman camps north of Water Eaton, Lapley, Stretton and Wheaton Aston				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006097			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No			
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Rodbaston Old Hall moated site and fishpond, Pe	enkridge				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011893			
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes			
OWNER TYPE:	Educational (independent)	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Roman camp, Kinvaston, Penkridge / Lapley, Stre	tton and Wheaton A	ston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006104			
CONDITION:	Unknown	TREND:	Unknown			
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No			
OWNER TYPE:	Government or agency	CONTACT:	Sarah Lewis 0121 625 6886			
SITE NAME:	Penkridge					
DESIGNATION:	Conservation Area	NEW ENTRY?:	No			
CONDITION:	Very bad	TREND:	Deteriorating			
VULNERABILITY:	Low	CONTACT:	Paul Collins (LPA) 01902 6960000			
SITE NAME:	Wombourne					
DESIGNATION:	Conservation Area	NEW ENTRY?:	No			
CONDITION:	Poor	TREND:	Deteriorating			
VULNERABILITY:	Medium	CONTACT:	Paul Collins (LPA) 01902 6960000			

STAFFORD



SITE NAME:	Remains of Creswell Chapel, Creswell	C13 villag
DESIGNATION:	Scheduled Monument and Listed Building grade II	Only the r mana
CONDITION:	Poor	has b cons
OCCUPANCY:	N/A	(July
PRIORITY CATEGORY:	D (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1006113 and 1242636	Con

chapel, in ruins standing alone in an open field. The ge has disappeared but probably stood near the church. y part of the chancel is standing but the foundations of rest are probably below the turf. With a conservation hagement plan completed, a schedule of repair work been drawn up and work is soon to start on solidation and repairs to the masonry and foundations 2013).

© English Heritage Archive

Contact. Sarah Lewis OTZT 025 0000	Contact:	Sarah	Lewis	0121	625	6886
------------------------------------	----------	-------	-------	------	-----	------

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / STAFFORD

	SITE NAME:	Trentham Tower, Sandon Park, Sandon, Sandon and Burston	Folly tower of c1840 located in centre of the C18 to C19 Upper Park, c700 metres north east of the house. Part of
© English Heritage	DESIGNATION:	Listed Building grade II*, RPG grade II	one of the stone towers from Trentham Hall, by Sir Charles Barry, moved to this location after Trentham's demolition in 1910-12. There are structural concerns and
	CONDITION:	Poor	general weathering and erosion of the stonework. The potential to fund repairs through a Natural England
	OCCUPANCY:	N/A	Stewardship scheme is being considered.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	89768	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Remains of Trentham Hall, the Grand Entrance and Orangery, Park Drive, Trentham Gardens, Swynnerton	Remains of a country house of 1833-42 by Sir Charles Barry and Orangery of 1808, situated in C18/C19 park by Lancelot Brown. Site being redeveloped in accordance with masterplan. Emergency repairs carried out and buildings
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	stabilised. Adjacent Italian gardens successfully restored. Main repairs scheduled under masterplan, but currently awaiting scheme for adjoining hotel development.
ALL	CONDITION:	Poor	
and the second s	OCCUPANCY:	N/A	
© English Heritage Archive	PRIORITY CATEGORY:	B (B)	
© English Heritage Archive	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1190243	Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Moated site in Reynold's Orchard, Eccleshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011051
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Norbury Manor moated site, eight fishponds and	l connecting channels,	Norbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011875
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow north of Hargreaves Wood, Swynr	nerton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009315
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Forebridge		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337
site name:	St George's Hospital		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / STAFFORD / STAFFORDSHIRE MOORLANDS

SITE NAME:	Trentham, Swynnerton		
DESIGNATION:	Conservation Area, 30 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337
SITE NAME:	Walk Mill, Eccleshall		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337

STAFFORDSHIRE MOORLANDS



SITE NAME:	Biddulph Old Hall, Biddulph	Substantial remains of a CI6 mansion. The house was
designation:	Scheduled Monument, part in LB grade II*	constructed in the 1580s for Francis Biddulph. It came under siege by the Parliamentarians in 1643 when the east range was destroyed and the house fired. Tower and rest
CONDITION:	Poor	of remains in need of consolidation. English Heritage grant offered for repairs to the tower. Works partially
OCCUPANCY:	N/A	completed.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1014688	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Prospect Tower and attached wing, Knypersley, Biddulph	Built in 1828 by John Bateman as a gamekeeper's house and eye-catcher on the Knypersley Hall estate. It is a three
	DESIGNATION:	Listed Building grade II*	storey octagonal structure in red sandstone with side wing and crenellated parapets. The building has been disused for
	CONDITION:	Poor	about 20 years and the fabric is gradually deteriorating. The County Council is considering alternative options for reuse.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage	LIST ENTRY NUMBER:	1037810	Contact: Sarah Lewis 0121 625 6886





© English Heritage Archive



	SITE NAME:	Alton Towers and attached garden walls and gatehouse, Alton Park, Farley	Country house, walls and gatehouse, c1810, set in early C19 valley gardens. Derelict when listed. Complete condition survey undertaken and emergency work
	DESIGNATION:	Listed Building grade II*, RPG grade I	completed. A phased programme of further works and a Conservation Management Plan are being prepared.
	CONDITION:	Poor	
Η.	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1374685	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Sharpecliffe Hall, Ipstones	Large house dated 1673, possibly with earlier fabric.
DESIGNATIO	DESIGNATION:	Listed Building grade II*	Restored and enlarged late C19. The condition of the building has been of concern for many years, but repairs

	SITE NAME:	Sharpecliffe Hall, Ipstones	Large nouse dated 1673, possibly with earlier fabric.
	DESIGNATION:	Listed Building grade II*	Restored and enlarged late C19. The condition of the building has been of concern for many years, but repairs
	CONDITION:	Poor	are being undertaken gradually by the owner.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
CONTROL OF	LIST ENTRY NUMBER:	3746	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

PRIORITY CATEGORIES

A Immediate risk of further rapid deterioration or loss of fabric; no

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / STAFFORDSHIRE MOORLANDS / TAMWORTH

	SITE NAME:	The Gazebo west of Whitehough, Ipstones	Gazebo, early C18. The roof was rebuilt in 1995 with the aid of an English Heritage grant. A small amount of repair
	DESIGNATION:	Listed Building grade II*	work is required to stonework and joinery to complete restoration. Cracked lintel and split stonework at corner is
	CONDITION:	Fair	visible.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
glish Heritage	LIST ENTRY NUMBER:	1374612	Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Paynsley Hall moated site and outer enclosure, I	Draycott in the Moors	S
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1011050
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Dieu-la-Cres Abbey (remains of), Leek		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006107
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Alton and Farley		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395 400
SITE NAME:	Cheadle		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395 400
site name:	Leek		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395 400

TAMWORTH

© Engli



	SITE NAME:	Deanery wall, Lower Gungate, Tamworth	A C14 masonry wall which was part of St Editha's Deanery. An English Heritage engineer has inspected the three
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, 3 LBs, CA	surviving sections of wall, parts of which are in urgent need of maintenance and repair. The removal of plant growth, pointing and resetting of stones to wall tops are all
1-17	CONDITION:	Poor	required. As a boundary wall, the ownership is uncertain, and liability for repair unclear. Investigation is necessary.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1006059 and 1197033; 1207833	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / TAMWORTH / STOKE-ON-TRENT, CITY OF (UA)

SITE NAME:	Saxon defences		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1006088
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886

stoke-on-trent, cit`	Y OF (UA)		
	SITE NAME:	Former Wedgwood Institute (Public Library), Queen Street, Burslem	Art school and library built 1869. In brick and terracotta with richly ornamented facade. Building now closed and some emergency repairs carried out. Proposals for the
	DESIGNATION:	Listed Building grade II*	future use of the building are being discussed.
	CONDITION:	Poor	
HIH CAREE TO	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
D English Heritage	LIST ENTRY NUMBER:	1195840	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Bethesda Methodist Chapel, Albion Street, Hanley	Former Methodist chapel, C19 with intact interiors knowr as "the Cathedral of the Potteries". The Historic Chapels
	DESIGNATION:	Listed Building grade II*	Trust have completed external repairs with the help of grants from English Heritage and the Heritage Lottery
	CONDITION:	Poor	Fund. A final phase of work to allow the reuse of the building is in development.
	OCCUPANCY:	Vacant/not in use	o 1
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
D English Heritage	LIST ENTRY NUMBER:	1195821	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Bottle oven and factory, Price and Kensington Teapot Works, Newcastle Street, Longport	An early C19 pottery complex, the bottle oven has been repaired. Only one range is occupied. A fire in the three storey range has resulted in the demolition of walls above
	DESIGNATION:	Listed Building grade II*	the second floor and the removal of the roof structure. Theft of slates from the roofs of many of the other
	CONDITION:	Very bad	buildings means that the complex is exposed and highly vulnerable. Urgent works are required to stabilise the
SULP A US	OCCUPANCY:	Part occupied/part in use	buildings while a new use is sought.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
) English Heritage	LIST ENTRY NUMBER:	1290799	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Middleport Pottery, Middleport	Pottery works 1888-9. Virtually complete purpose built Victorian pottery still in use as a working pottery. The
	DESIGNATION:	Listed Building grade II*	Prince's Regeneration Trust have acquired the site, the
	CONDITION:	Poor	pottery business will continue and the Trust will repair the remaining buildings for new businesses and an education
	OCCUPANCY:	Occupied/in use	centre. Emergency repairs are in progress with English Heritage funding.
	PRIORITY CATEGORY:	F (F)	ו זכו ונמצר ועוועוווצ.
	OWNER TYPE:	Charity (heritage)	

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

1297939

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / STOKE-ON-TRENT, CITY OF (UA)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

	SITE NAME:	Chatterley Whitfield Colliery, Biddulph Road, Stoke-on-Trent	Large redundant C19/C20 colliery in need of major repair and regeneration. Includes 15 scheduled structures and 5
	DESIGNATION:	Scheduled Monument, 5 LBs	listed buildings. Heritage-based regeneration programme started based on masterplan. Long-term solution still to be
	CONDITION:	Very bad	agreed, but progress with re-use of buildings and reclamation works has been slow. Discussions on private
	OCCUPANCY:	Vacant/not in use	sector engagement and longer term proposals ongoing.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1015947	Contact: Sarah Lewis 0121 625 6886

- Ur o	SITE NAME:	Pithead baths and canteen, Biddulph Road, Stoke-on-Trent	Opened in the 1860s, in 1937, Chatterley Whitfield became the first mine in Britain to draw more than a
	DESIGNATION:	Listed Building grade II*, SM	million tons of coal in a year. The pithead baths and canteen were erected at this time and are of special
H I B Cont	CONDITION:	Very bad	interest as an example of large scale provision for miners in the early C20. On the closure of the mine the buildings
	OCCUPANCY:	Vacant/not in use	the early C20. On the closure of the mine the buildings were used to accommodate a museum. The whole colliery
	PRIORITY CATEGORY:	A (New entry)	site is now vacant and these buildings are in very poor condition.
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1260223	Contact: Sarah Lewis 0121 625 6886

Hulton Abbey, Leek Road,

Stoke-on-Trent

Poor

N/A

C (C)

Scheduled Monument



	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1021284	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Mausoleum, Stone Road, Trentham	Mausoleum circa 1808. Connected with former Trentham Park. A package of urgent roof repairs has been carried out
	DESIGNATION:	Listed Building grade I	with funding from English Heritage and the Local Authority. Further repairs to doors and rear window completed
	CONDITION:	Fair	2007. The fabric is now sound, but the building remains at risk until responsibility for future upkeep is clearly
A started and	OCCUPANCY:	N/A	established.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1210451	Contact: Sarah Lewis 0121 625 6886



SITE NAME:	Church of St John the Baptist, Cross Hill, Burslem	This medieval church was largely rebuilt in 1717 but retains its medieval tower. Non-breathable paint on the nave is
DESIGNATION:	Listed Place of Worship grade II	trapping moisture in brickwork, leading to significant internal damp problems and deterioration of outer brick
CONDITION:	Poor	face. Dry rot to timber of apse stained glass windows has spread into walls and inappropriate use of cement tiles on
PRIORITY CATEGORY:	C (A)	hipped roof is leading to structural problems. The building
OWNER TYPE:	Religious organisation	has multiple fabric defects. This church has been the victim of heritage crime.
LIST ENTRY NUMBER:	1291065	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

The remains of Hulton Abbey, 1223, comprising transepts

and chancel at east end of church which survive as stub

and stone decay and require repair.

walls. The site is owned by the Council and managed as a

public amenity space. Below ground remains are not at risk but the hard capped wall tops are vulnerable to weathering

HERITAGE AT RISK 2013 / WEST MIDLANDS / STOKE-ON-TRENT, CITY OF (UA)

SITE NAME:	Roman Catholic Church of St Joseph, Hall Street, Burslem	This is a large brick-built, Italianate-style church built in 1925 to the designs of the Architect JS Brocklesbury. It has
DESIGNATION:	Listed Place of Worship grade II	a finely decorated interior. Recent grant-aided repairs to the sanctuary and ambulatory roofs have addressed issues
CONDITION:	Poor	relating to drainage and differential settlement but the nave roof and its asphalt-lined eaves gutters are time-expired
PRIORITY CATEGORY:	A (F)	and require renewal. Extensive re-pointing of the nave
OWNER TYPE:	Religious organisation	clerestory and buttresses is also urgently required to prevent continued water ingress and further damage to the
LIST ENTRY NUMBER:	1297960	structure, interior decorations and fixtures.
		Contact: Sarah Lewis 0121 625 6886
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Joseph, Hall Street, BurslemDESIGNATION:Listed Place of Worship grade IICONDITION:PoorPRIORITY CATEGORY:A (F)OWNER TYPE:Religious organisation

© English Heritage

-	SITE NAME:	Church of St John the Evangelist, High Street, Goldenhill	Church built in 1841 by Stanley of Shelton, a local architect, in the Byzantine Romanesque style. Blocked or defective rainwater goods in several locations have caused damage
	DESIGNATION:	Listed Place of Worship grade II	to the internal finishes and there are significant areas of rising damp. The nave roof has minor defects. The church
	CONDITION:	Poor	has suffered from heritage crime. The external masonry is slowly deteriorating: the latest quinquennial inspection
L. Carton	PRIORITY CATEGORY:	C (C)	report makes recommendations for a steeplejack
ALT R	OWNER TYPE:	Religious organisation	inspection of both the tower and spire.
	LIST ENTRY NUMBER:	1220492	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	All Saints Church, Leek Road, Hanley	All Saints is an Arts and Crafts Gothic church designed by Gerald Horsley in 1910. Built with red brick buttressed
	DESIGNATION:	Listed Place of Worship grade II	walls with sandstone dressings and steeply pitched roofs with both plain clay and replacement concrete tiles, failed
	CONDITION:	Poor	abutment flashings at the east end of the church and defective rainwater goods threaten the integrity and
	PRIORITY CATEGORY:	A (A)	viability of this largely unaltered building.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1245925	Contact: Sarah Lewis 0121 625 6886

© English Heritage

SITE NAME:	Caldon Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680
SITE NAME:	Longton Town Centre, Longton		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680
SITE NAME:	Newcastle Street, Middleport		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jane Corfield (LPA) 01782 236680
SITE NAME:	Stoke Town, Stoke		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jane Corfield (LPA) 01782 236680

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / STOKE-ON-TRENT, CITY OF (UA) / TELFORD AND WREKIN (UA)

SITE NAME:	Trent & Mersey Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680

TELFORD AND WREKIN (UA)

SITE NAME:	Charlton Castle, Wrockwardine	A medieval moated site which is very overgrown with
DESIGNATION:	Scheduled Monument	several uprooted trees damaging the earthworks. There are some elements of standing masonry exposed. The site
CONDITION:	Very bad	needs an assessment of condition and the development of an appropriate management regime. There is potential to
OCCUPANCY:	N/A	fund this through a management agreement.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1019649	Contact: Sarah Lewis 0121 625 6886
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:Scheduled MonumentCONDITION:Very badOCCUPANCY:N/APRIORITY CATEGORY:C (C)OWNER TYPE:Private

© English Heritage Archive

	SITE NAME: Church of St Mary the Virgin, Salthouse Road, Jackfield	This church was designed by A W Blomfield and built in 1863. It consists of an aisle-less nave, pseudo transepts, a	
DESIGN	DESIGNATION:	Listed Place of Worship grade II, CA, WHS	chancel and a north east tower with an open bell stage, all constructed in polychrome brickwork with steeply pitched tiled roofs. Defective roof coverings, rainwater goods and
	CONDITION:	Poor	corroded ferrous metal within the bell stage structure the principal items of construction that require repair of
PRIORITY CATEGOR	PRIORITY CATEGORY:	B (B)	renewal. A Repair Grant for Places of Worship was offered
	OWNER TYPE:	Religious organisation	in 2011 and accepted.
	LIST ENTRY NUMBER:	1038241	Contact: Sarah Lewis 0121 625 6886
rchitects			

© Stainburn Taylor architects

SITE NAME:	Enclosed Iron Age farmstead immediately adjace	nt to The Croft, Pave	Lane, Chetwynd Aston and Woodcote
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020275
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman camp on Red Hill, Lilleshall and Donning	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006269
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	St Leonard's Priory immediately adjacent to the	Church of St Mary an	d St Leonard, Wombridge, Oakengates
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	020661
		EIST EINTRY NOT BER.	1020001
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised		
	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised problems Scrub/tree growth	TREND: NEW ENTRY?:	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE:	Generally unsatisfactory with major localised problems Scrub/tree growth Religious organisation	TREND: NEW ENTRY?:	Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Generally unsatisfactory with major localised problems Scrub/tree growth Religious organisation Canal aqueduct over River Tern, Rodington	TREND: NEW ENTRY?: CONTACT:	Declining No Sarah Lewis 0121 625 6886
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Generally unsatisfactory with major localised problems Scrub/tree growth Religious organisation Canal aqueduct over River Tern, Rodington Scheduled Monument, LB grade I	TREND: NEW ENTRY?: CONTACT: LIST ENTRY NUMBER:	Declining No Sarah Lewis 0121 625 6886 1006275
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Generally unsatisfactory with major localised problems Scrub/tree growth Religious organisation Canal aqueduct over River Tern, Rodington Scheduled Monument, LB grade I Extensive significant problems	TREND: NEW ENTRY? CONTACT: LIST ENTRY NUMBER: TREND:	Declining No Sarah Lewis 0121 625 6886 1006275 Declining

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA LB LPA NP RPG SM

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / TELFORD AND WREKIN (UA) / NORTH WARWICKSHIRE

SITE NAME:	Uxacona Roman site (See also Shropshire Unitary a and Donnington	Authority), Shifnal /	St. Georges and Priorslee / Lilleshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006272
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Site revealed by aerial photography north of Castle	e Farm, St. Georges	and Priorslee
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006274
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Churchyard of St James's Church, Stirchley and Bro	ookside	
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1020852
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Moated site and a fishpond 160 metres and 280 me	etres south of The	Farm, Charlton, Wrockwardine
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

WARWICKSHIRE

NORTH WARWICKSHIRE

	SITE NAME:	Beech House, 19, Market Street, Atherstone	Fine town house in Queen Anne style dated 1708. Interiors largely unaltered and most of the original features are intact. Has been vacant for several years and is slowly
	DESIGNATION:	Listed Building grade II*, CA	and the Local Planning Authority to find a solution for the
	CONDITION:	Poor	and the Local Planning Authority to find a solution for the building, which is on the market.
	OCCUPANCY:	Vacant/not in use	bulleng, which is on the market.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1185175	Contact: Sarah Lewis 0121 625 6886



	SITE NAME:	Grendon Bridge, Grendon / Polesworth	Stone bridge, probably CI Now in poor condition wit
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	condition survey is needed Discussions are ongoing wi management agreement an
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1005756 and 1186247	Contact: Sarah Lewis 0121

5 constructed in sandstone. ith parts of the parapet missing. A d to assess the scale of repairs. vith the owners about a possible ind grant aid.

1 625 6886

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / NORTH WARWICKSHIRE

	SITE NAME:	Hartshill Castle, Castle Road, Hartshill	C13 castle ruins. Steady decay of surviving masonry due to erosion, structural problems and vandalism. The owner ha
	DESIGNATION:	Scheduled Monument and Listed Building grade II	set up a trust to look after the castle. Vegetation clearance and emergency repairs were carried out some time ago. Discussions are ongoing with the owner for a condition
HIST	CONDITION:	Poor	survey prior to masonry repairs.
North State	OCCUPANCY:	N/A	
Production of the second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ıglish Heritage	LIST ENTRY NUMBER:	1011197 and 1034748	Contact: Sarah Lewis 0121 625 6886



© English Heritage

And the second	SITE NAME:	Kingsbury Hall, Kingsbury	A manor house of circa 1500 with late C16 and C18	
	DESIGNATION: Scheduled Monument and Lis Buildings - I grade II*; I grade CA			
the real	CONDITION:	Very bad		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1019978 and 1116550; 1034721	Contact: Sarah Lewis 0121 625 6886	



	SITE NAME:	Maxstoke Priory, Church Road, Maxstoke	Substantial remains of an early C14 Augustinian monastery including infirmary, precinct walls, outer gatehouse with
	DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade II*, 2 LBs	attached barn and farmhouse. The buildings are steadily decaying, the precinct wall is in very poor condition and the infirmary structure is propped. Natural England will fund
	CONDITION:	Poor	some repairs under a Higher Level Stewardship scheme.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private, multiple owners	
© English Heritage Archive	LIST ENTRY NUMBER:	1011195 and 1034822; 1034823; 1365129; 1034821; 1116038; 1320105	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Stables range north east of Middleton Hall, Middleton	Originally stables and lodging block c1570. Timber-framed with brick infill panels. Consists of four bay main range with
	DESIGNATION:	Listed Building grade II*	two bay cross wing at north end and two storey gabled porch to left of centre. Courtyard of farm buildings to rear.
A	CONDITION:	Poor	Structure in need of urgent stabilisation. The building is currently vacant but a condition survey has been
A CONTRACTOR OF THE	OCCUPANCY:	Vacant/not in use	undertaken preparatory to developing a scheme.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage	LIST ENTRY NUMBER:	1365197	Contact: Sarah Lewis 0121 625 6886



	SITE NAME:	Moat, footbridge and gatepiers to Shustoke Hall Farmhouse, Moat House Lane, Shustoke	Homestead moat, footbridge and gate piers c1686, with late C18 service wing which is in poor condition. Substantial sections of overgrown walls and buttresses
	DESIGNATION:	Listed Building grade II*	leaning outwards which require rebuilding. Owners have finished restoring the house and are now attending to the
	CONDITION:	Poor	moat. Vegetation cleared and repairs now ongoing. Some repointing of walls and dismantling prior to rebuilding
A Dimension of the	OCCUPANCY:	N/A	leaning walls has been carried out.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
© English Heritage Archive	LIST ENTRY NUMBER:	1226189	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / NORTH WARWICKSHIRE / NUNEATON AND BEDWORTH

SITE NAME:	Astley Castle moated site, fishponds, garden remains and Astley College, Astley			
DESIGNATION:	Scheduled Monument and Listed Building grade II, LB grade II*	LIST ENTRY NUMBER:	1011194 and 1184837	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Oldbury Camp univallate hillfort, Hartshill			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018855	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Roman Camp, Mancetter			
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005736	
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Manduessedum Roman villa and settlement with as	sociated industrial	complex, Mancetter / Witherley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017585	
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886	
SITE NAME:	Merevale Abbey, a Cistercian monastery, associate	d water control fea	tures and industrial remains, Merevale	
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1014682	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886	

NUNEATON AND BEDWORTH

	SITE NAME:	Park Farmhouse, Arbury Park, Nuneaton	Late CI5 farmhouse with CI6 and CI7 alterations, to the north of Arbury Park. In a very bad condition. Following
	DESIGNATION:	Listed Building grade II*	building survey, urgent works have been carried out to support and protect structure while owners consider
	CONDITION:	Very bad	scheme for future use. Discussions are ongoing with Arbury Estate to formulate a strategy for all historic
	OCCUPANCY:	Vacant/not in use	buildings on estate.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
nglish Heritage	LIST ENTRY NUMBER:	1365048	Contact: Sarah Lewis 0121 625 6886

© Engl

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / NUNEATON AND BEDWORTH / RUGBY

LIST



E NAME:	The Tea House, Arbury Park, Nuneaton	Mid C18 summerhouse located c500 metres east north east of Arbury Hall. The Tea House is situated on the
SIGNATION:	Listed Building grade II*, RPG grade II*	north east shore of a small lake on the eastern edge of the C18 park. In a very bad state of repair (the dome has collapsed), and continues to deteriorate. Action needed
NDITION:	Very bad	urgently to halt decay. Discussions with the Local Authority and Arbury Estate to formulate strategy for all historic
CUPANCY:	Vacant/not in use	buildings on estate.
ORITY CATEGORY:	A (A)	
VNER TYPE:	Private	
FENTRY NUMBER:	1299615	Contact: Sarah Lewis 0121 625 6886

© English Heritage

RUGBY

	SITE NAME:	Church of St Peter, Main Street, Bourton and Draycote	This stone church has medieval origins but was entirely remodelled and largely rebuilt by J Potter in the mid C18.
	DESIGNATION:	Listed Place of Worship grade II	The C17 pulpit, communion rail and box pews survive inside. Some of the roofs are in a poor state and there are
	CONDITION:	Very bad	damp problems internally.
N NO	PRIORITY CATEGORY:	C (C)	
ALT.	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1185250	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Church of St John the Baptist, The Crescent, Brinklow	This sandstone church with its prominent tower has medieval origins and is characterised by its Perpendicular
	DESIGNATION:	Listed Place of Worship grade II*, CA	windows. Stonework is in poor condition causing dampness and plaster decay.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1034957	Contact: Sarah Lewis 0121 625 6886
© English Heritage			

SITE NAMEBrandon Castle, Brandon and BretfordDESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1011371CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Barrow cemetery 400 metres north east of Bretford-, Brandon and Bretford / King's NewnhamDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005722CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Farm, Church Lawford / ThurlastonIDST ENTRY NUMBER:1020937SITE NAME:UnknownTREND:UnknownUnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoDESIGNATION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoONNER TYPE:PrivateCONTACT:Sarah Lewis 0121 625				
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:NoOWNER TYPE:Commercial companyCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Barrow cemetery 400 metres north east of Bretford / Brandon and Bretford / King's NewnhamDESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1005722CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features or Farm, Church Lawford / ThurlastonCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Scheduled MonumentUIST ENTRY NUMBER:1020937DESIGNATION:Scheduled MonumentUIST ENTRY NUMBER:1020937CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	SITE NAME:	Brandon Castle, Brandon and Bretford		
CONDENTION:problemsProvide the formation of the formation	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1011371
OWNER TYPE: Commercial company CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Barrow cemetery 400 metres north east of Bretford, Brandon and Bretford / King's Newnham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005722 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Farm, Church Lawford / Thurlaston LIST ENTRY NUMBER: 1020937 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020937 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:		TREND:	Declining
SITE NAME: Barrow cemetery 400 metres north east of Bretford Brandon and Bretford / King's Newnham DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005722 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Sarah Lewis 0121 625 6886 SITE NAME: Prehistoric pit alignment and associated features on the stord Heath, adviso 0121 625 6886 SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1020937 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020937 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005722CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features on Lawford Heath, adjuscent to the northernmost BlueDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020937CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Farm, Church Lawford / ThurlastonIIST ENTRY NUMBER:1020937DESIGNATION:Scheduled MonumentIIST ENTRY NUMBER:1020937CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	SITE NAME:	Barrow cemetery 400 metres north east of Bree	tford, Brandon and Bro	etford / King's Newnham
PRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features on Farm, Church Lawford / ThurlastonJewford Heath, adjecent to the northernmost BlueDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020937CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005722
OWNER TYPE:Private, multiple ownersCONTACT:Sarah Lewis 0121 625 6886SITE NAME:Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost BlueDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020937CONDITION:UnknownTREND:UnknownPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	CONDITION:	Unknown	TREND:	Unknown
SITE NAME: Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Farm, Church Lawford / Thurlaston DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1020937 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020937 CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
CONDITION: Unknown TREND: Unknown PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Prehistoric pit alignment and associated features Farm, Church Lawford / Thurlaston	s on Lawford Heath, a	djacent to the northernmost Blue Boar
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020937
	CONDITION:	Unknown	TREND:	Unknown
OWNER TYPE: Private CONTACT: Sarah Lewis 0121 625 6886	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA LB

LPA NP RPG SM

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / RUGBY

SITE NAME:	Bowl barrow 470	metres south west of Coton Ho	use, Churchover	
DESIGNATION:	Scheduled Monun	nent	LIST ENTRY NUMBER:	1016883
CONDITION:	Generally unsatisf problems	actory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in	need of management	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Tripontium Roma	n Station, Churchover		
DESIGNATION:	Scheduled Monun	nent	LIST ENTRY NUMBER:	1005759
CONDITION:	Unknown		TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial com	oany, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Prehistoric circul	ar earthworks, King's Newnham		
DESIGNATION:	Scheduled Monun	nent	LIST ENTRY NUMBER:	1005717
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
site name:	Bowl barrow on	Lammas Hill, Wolston		
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1016885
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
site name:	Bowl barrow 490	metres north west of Abbey Far	m, Wolvey	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1016845
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Bowl barrow 900	motion north of Constan Form	Wolyoy	
		metres north of Copston Farm,	vvolvey	
DESIGNATION:	Scheduled Monun	-	LIST ENTRY NUMBER:	1016846
DESIGNATION: CONDITION:		-	-	1016846 Unknown
CONDITION:	Scheduled Monun	-	LIST ENTRY NUMBER:	
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monun Unknown	-	LIST ENTRY NUMBER:	Unknown
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monun Unknown Arable ploughing	-	LIST ENTRY NUMBER: TREND: NEW ENTRY: CONTACT: Small Regency Iar Regency villa. Lat	Unknown No Sarah Lewis 0121 625 6886 ndscape surrounding shell of grade II liste ee C20 extensions to villa extend over
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monun Unknown Arable ploughing Private	Ryton House, Ryton-on-	LIST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT: Small Regency lar Regency villa. Lat gardens. Boundai lakes badly negled	Unknown No Sarah Lewis 0121 625 6886 ndscape surrounding shell of grade II liste
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monun Unknown Arable ploughing Private SITE NAME:	Ryton House, Ryton-on- Dunsmore Registered Park and Garden	LIST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT: Small Regency lar Regency villa. Lat gardens. Boundai lakes badly negled	Unknown No Sarah Lewis 0121 625 6886 Indscape surrounding shell of grade II liste the C20 extensions to villa extend over ry belt, historic drive, shrubberies and cted. Setting compromised by roads and

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

TREND:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

use).

Declining

1001343

Mixed, multiple owners

No

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

use)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

STRATFORD-ON-AVON

SITE NAME:	Bidford Bridge, Bidford-on- Avon	An early C15 bridge over the river Avon thought to have been built by the monks of Bordesley Abbey. Constructed
DESIGNATION:	Scheduled Monument, LB grade I	from limestone, it has been repeatedly repaired over the centuries. The bridge is vulnerable to vehicle damage. Inappropriate historic repairs and stone erosion are
CONDITION:	Poor	problems.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1005766	Contact: Sarah Lewis 0121 625 6886



	SITE NAME:	The Old Rectory Farmhouse, Friars Lane, Lower Brailes, Brailes	Rectory of late C16 with earlier origins. Support scaffolding and temporary roof grant aided by English Heritage 10 years ago but structure has continued to deteriorate.	
	DESIGNATION:	Listed Building grade II*	Empty for some years and in a serious state. However, property changed hands in 2005. A condition survey gra	
1	CONDITION:	Very bad	aided by English Heritage has been undertaken and the owner is considering sale.	
-	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1024377	Contact: Sarah Lewis 0121 625 6886	

Toll House, Clopton Bridge,

Listed Building grade I, SM

Stratford-upon-Avon

Vacant/not in use

Listed Building grade II*

Vacant/not in use

Charity (heritage)

Packhorse bridge, Todenham /

Scheduled Monument, 2 LBs

Poor

Fair

F (F)

1382428

Tidmington

C (New entry)

Poor

N/A

Private

1005746

© English Heritage

© English Heritage



© English Heritage

negotiation with the Council which owns the building to C (C) find a new use and implement repairs. Local authority 1204167 Contact: Sarah Lewis 0121 625 6886 Umberslade Baptist Chapel, Exceptionally fine Nonconformist estate chapel of 1877 by Spring Lane, Tanworth-in-Arden

George Ingall for GF Muntz of Umberslade Park. The chapel has not been used as a place of worship for many years and has been acquired by the Historic Chapels Trust who plan to restore it for educational/community uses and occasional services. Main phase of repairs to external fabric completed, but funding for restoration of the interior still required.

Former toll house built in 1814 on the C15 Clopton Bridge in the centre of Stratford-upon-Avon. The building has

been disused for many years, the roof and stonework is in

poor condition. Some urgent stonework repairs have been carried out but further works are required. The Stratford

Historic Buildings Trust has commissioned a feasibility study

funded by the Architectural Heritage Fund and is in

Contact: Sarah Lewis 0121 625 6886

A CI6 pack horse bridge of dressed limestone, withou	It
kerb or parapet. The bridge was rebuilt in the C18. It	2
suffers from moderate stone decay.	

|--|

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ

Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2013 / WEST MIDLANDS / STRATFORD-ON-AVON

	SITE NAME:		All periods of medieval architecture are represented in the fabric of the church which is built of course lias rubble with
	DESIGNATION:	Listed Place of Worship grade II*	red sandstone buttresses and dressings. The roofs are plain tiled. Despite the vulnerability of lias, the general condition
	CONDITION:	Poor	of the church is good. However, stonework to the upper parts of the tower, in particular the parapets is very poor
	PRIORITY CATEGORY:	D (D)	and the stump of the spire is allowing water into the building. A Repair Grant for Places of Worship was offered
	OWNER TYPE:	Religious organisation	in January 2013 to complete necessary repairs.
	LIST ENTRY NUMBER:	1185674	Contact: Sarah Lewis 0121 625 6886

© English Heritage

3

SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Church of St Milburga, Wixford	St Milburga's Church is situated some distance from the	
	DESIGNATION:	Listed Place of Worship grade II*	village of Wixford, on higher ground overlooking the Arrow Valley. The church is small, with a nave and chancel
	CONDITION:	Poor	under one roof, and a chapel unusually attached to the south side. At the west end a bell turret rises from the
	PRIORITY CATEGORY:	D (D)	nave ridge with a shingled spire above a square louvred bell
	OWNER TYPE:	Religious organisation	chamber. The south slope of the roof is in poor condition and allowing water to enter the building. A Repair Grant
	LIST ENTRY NUMBER:	1355369	for Places of Worship was offered in August 2012 for the work.
			WUIK.

Contact: Sarah Lewis 0121 625 6886

© Brown Matthews Architects Ltd

SITE NAME:	Oversley Castle, Alcester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005750
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Beaudesert Castle: motte and bailey castle and two	o fishponds, Beaude	sert
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012703
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Castle Hill Motte, Brailes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018858
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Cursus and bowl barrow 450 metres south east of	Jackson's Barn, Ch	arlecote
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020437
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Double-ditched enclosure east of Thornton Farm,	Ettington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002990
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / STRATFORD-ON-AVON

SITE NAME:	Enclosures north of Old Pasture Farm, Hampton L	ucy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005714
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Settlement site east of Hatton Rock Farm, Hampto	on Lucy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005726
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Site of building and enclosure 460 metres east of H	latton Rock Farm, I	Hampton Lucy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005741
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Medieval settlement remains at Hodnell Manor, Ho	odnell and Wills Pas	stures
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Rectangular Earthwork on Nebsworth, Ilmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005734
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Multivallate hillfort on Meon Hill, Quinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011372
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Nadbury Camp, Ratley and Upton / Warmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003724
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
ITE NAME:	Enclosures 1200 metres north of Salford Priors, Sa	Ilford Priors	
	Scheduled Monument	LIST ENTRY NUMBER:	1005721
DESIGNATION:	Scheduled Fiohament		
	Unknown	TREND:	Unknown
DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:		TREND: NEW ENTRY?:	Unknown No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / STRATFORD-ON-AVON

HERITAGE AT RISK 2013 / WES	T MIDLANDS / STRATFORD-ON-AVON		
site name:	Romano-British cemetery and settlement site, Stre	tton-on-Fosse	
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1003725
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Studley Old Castle: a motte castle, Studley		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1013161
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Settlement site west of Welford Weir, Temple Gr	afton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005719
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Hob Ditch Earthwork, Ullenhall / Tanworth-in-Arc	len	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005729
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosures 550 metres east of King's Mead, Welles	sbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Lower Shuckburgh		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326
SITE NAME:	Southam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WARWICK

WARWICK

©

© English Heritage	SITE NAME:	Bridge, Goodrest Lodge, Leek Wootton and Guy's Cliffe	Sandstone ashlar bridge dated 1441 giving access across moat to site of medieval manor house of Goodrest. The
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	moated site has become overgrown with vegetation. Due to previous stone robbing, some of the masonry of the bridge is missing, including coping stones and a complete
	CONDITION:	Poor	section of the surface walkway. A condition survey is required. Discussions have started with new owners on
	OCCUPANCY:	N/A	possible management agreement.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1013158 and 1035180	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive	SITE NAME:	Remains of Old Castle Bridge, Mill Street, Warwick	Late Medieval bridge. Ownership of remains split three ways. Earlier proposals for stabilisation were very costly
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I	and beyond available resources. It has been proposed tha ownership should be transferred to a trust who would co ordinate restoration and funding package but this has not
	CONDITION:	Very bad	progressed. A fresh survey of condition and repair costs has been suggested to move things forward.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1005772 and 1035499	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Masters House, Warwick	The Leper Hospital of St Michael was founded in C12; the
	DESIGNATION:	Listed Building grade II*, SM	Master's House survives and is a timber-framed building of C15 date built upon C12 foundations. The timber frame
	CONDITION:	Very bad	and roof are in very poor condition, there are general structural problems throughout the building which has
	OCCUPANCY:	Vacant/not in use	been propped to prevent collapse and covered in
	PRIORITY CATEGORY:	A (B)	tarpaulins. An options appraisal was carried out by the Local Authority with English Heritage grant and a project is
	OWNER TYPE:	Private	in development.
	LIST ENTRY NUMBER:	1364850	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

SITE NAME:	Roman settlement at Glasshouse Wood, Ashow / Kenilworth				
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1005723		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886		
SITE NAME:	Circular ditches enclosures south west of Wiggerla	nd Wood Farm, Bi	shop's Tachbrook		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003740		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886		
SITE NAME:	Pit alignments north of Bubbenhall village, Bubbenh	all			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005718		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886		

PRIORITY CATEGORIES

implemented. C Slow decay; no solution agreed.

 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solu use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WARWICK

HERITAGE AT RISK 2013 / WES 			ale Maastern and Carls Cliffs
	Guy's Cave hermitage and other rock cut chamber	IIST ENTRY NUMBER:	· · · · · · · · · · · · · · · · · · ·
DESIGNATION:	Scheduled Monument, LB grade II, RPG grade II	LIST ENTRY NUMBER:	1019129
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Wedgnock Park pale, dam, two watermill sites, bri Farm, Leek Wootton and Guy's Cliffe	dge and hollow way	200 metres north east of Goodres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013159
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Cursus, enclosures and other cropmarks 900m NI	NW of Barford Chu	rch, Sherbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005710
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosures 410 metres north east of Sherbourne p	arish church, Sherb	ourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005711
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Warwick Castle (uninhabited parts), Warwick		
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosures 550 metres, SSW of Manor House Farr	n, Wasperton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005713
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosures and drove road 90 metres south of Ma	nor House Farm, W	/asperton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WARWICK / BIRMINGHAM

SITE NAME:	Enclosures and pits north of Hail End Bridge, Wasperton					
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1005715		
CONDITION:	Unknown		TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Mineral extraction	n/related subsidence	NEW ENTRY?:	No		
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886		
	SITE NAME:	Stoneleigh Abbey, Stoneleigh / Ashow	Complex multi-phase landscape, incorporating me deer park and work by Repton, Nesfield and Percy			
	DESIGNATION:	Registered Park and Garden grade II*, 30 LBs, 2 SMs	enclaves built wit Agricultural Socie	golf course. Business park and residentia hin historic landscape. Also contains Roy ety's permanent showground. Impressive		
	CONDITION:	Generally satisfactory but with significant localised problems	programme of restoration of cascades, bridges and water features through Natural England's Environme Stewardship scheme which is now complete, with a phase planned. Other parts of the historic estate rer vulnerable e.g. route of High Speed 2 (HS2) railway.			
	VULNERABILITY:	High				
	TREND:	Improving				
© English Heritage	NEW ENTRY?:	No				
	OWNER TYPE:	Mixed, multiple owners	ciple owners			
	LIST ENTRY NUMBER:	NTRY NUMBER: 1000377		ewis 0121 625 6886		
	SITE NAME:	Guy's Cliffe, Warwick / Leek Wootton and Guy's Cliffe / Old Milverton	Picturesque landscape either side of the River Avo house is a ruinous shell. Chapel now a Masonic ter Derelict gardens periodically cleared by volunteers			
	DESIGNATION:	Registered Park and Garden grade II, 9 LBs, SM		d majority of parkland trees lost. Urban arwick), affecting the park, has been		
	CONDITION:	Extensive significant problems				
	VULNERABILITY:	High				
A Contraction	TREND:	Stable				
🕽 English Heritage	NEW ENTRY?:	No				
	OWNER TYPE:	Mixed, multiple owners				
	LIST ENTRY NUMBER:	1001602	Contact: Sarah L	ewis 0121 625 6886		

WEST MIDLANDS

BIRMINGHAM

	SITE NAME:	British Rail goods office (Curzon Street Station), Birmingham	Original terminus of the London to Birmingham railway by Philip Hardwick. Built in 1838 in the Ionic style. The building is owned by the City Council and has been vacant
	DESIGNATION:	Listed Building grade I	for over five years. Repairs to the roof have been undertaken and the building is now watertight. Potential
	CONDITION:	Fair	redevelopment in association with High Speed 2 (HS2) is proposed in the area masterplan.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1343086	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

А

В

Immediate risk of further rapid deterioration or loss of fabric; no

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / BIRMINGHAM

	SITE NAME:	Grand Hotel, Colmore Row, Birmingham	Large Victorian hotel dating from 1875. It is a key landmark building overlooking Cathedral Square with an important
	DESIGNATION:	Listed Building grade II*, CA	suite of public rooms. The main elevations are in very bad condition due to the poor quality of the original stone,
	CONDITION:	Poor	English Heritage grant aid has been offered and work is in progress. Planning Permission for reuse has been granted.
	OCCUPANCY:	Part occupied/part in use	F. 68. cool i lannin, 8. composition i carco natio o con 8. anto c
	PRIORITY CATEGORY:	E (D)	
	OWNER TYPE:	Commercial company	
e	LIST ENTRY NUMBER:	1391246	Contact: Sarah Lewis 0121 625 6886

© English Heritage

© English Heritage



THE REAL	SITE NAME:	Methodist Central Hall, Corporation Street, Birmingham	A substantial building constructed in 1903/4 by E and JA Harper in red brick and terracotta. The ground floor is in various retail uses, the upper floors are vacant. Planning
	DESIGNATION:	Listed Building grade II*, CA	approval and Listed Building Consent have been granted for conversion to mixed office/residential use, but not yet
	CONDITION:	Fair	implemented.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
0	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1075607	Contact: Sarah Lewis 0121 625 6886

HA THE	SITE NAME:	The Red Lion Public House, Soho Road, Birmingham	Public house, 1901-2 by James & Lister Lea for the Holt Brewery Company. Built of red brick with terracotta
AN IN	DESIGNATION:	Listed Building grade II*	facade, the building is of unusual richness and completeness with interior detailing comparable with best surviving
	CONDITION:	Fair	examples nationally. Leaking roofs have caused significant problems. A new owner has undertaken urgent works and
	OCCUPANCY:	Vacant/not in use	has gained Listed Building Consent for re-use as a public
	PRIORITY CATEGORY:	F(C)	house restaurant.
	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1276278	Contact: Sarah Lewis 0121 625 6886

The All	SITE NAME:	Perrott's Folly, Waterworks Road, Edgbaston	Built in 1758 by John Perrott as folly adjacent to his house (long demolished). Six storey structure with circular stair		
	DESIGNATION:	Listed Building grade II*	tower attached. With adjoining waterworks tower said to be inspiration for Tolkien's 'Twin Towers'. Urgent repairs		
	CONDITION:	Fair	to address immediate structural problems completed. A business plan for long-term future use and completion of		
XX	OCCUPANCY:	Vacant/not in use	repairs is necessary.		
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Other not for profit group			
© English Heritage	LIST ENTRY NUMBER:	1076123	Contact: Sarah Lewis 0121 625 6886		
	SITE NAME:	Mortuary Chapel, Handsworth	Designed by WH Bidlake and built in 1909-10, this is a fine		
		Cemetery, Oxhill Road, Handsworth	example of the work of one of Birmingham's own architects. The chapel is in the Arts and Crafts style in red		
	DESIGNATION:	Listed Building grade I	brick with stone dressings and a slate roof. Unstable masonry to the towers has rendered the building unsafe for		
	CONDITION:	Poor	public access and use has been temporarily suspended by the Council. English Heritage has offered grant aid for		
	OCCURANCY		the Council. English her tage has one ed grant ald for		

© English Heritage

LIST ENTRY NUMBER: 1076218

Local authority

B (B)

Vacant/not in use

Contact: Sarah Lewis 0121 625 6886

repairs which are due to start in 2013.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

OCCUPANCY:

OWNER TYPE:

use).

PRIORITY CATEGORY:

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISH	2013	/ \//FST		
TILNITAGE AT NO	、ZUIJ/	VVLJI	I IIDLAIND3	

HERITAGE AT RISK 2013 / WEST M	IIDLANDS / BIRMINGH	AM	
	SITE NAME:	Newman Brothers Coffin Furniture Works, 13-15, Fleet Street, Hockley	1892 metal working factory including office, warehousing, workshops with drop stamps and hoist, and with an excellent collection of artefacts. The building is located in
	DESIGNATION:	Listed Building grade II*, CA	the Jewellery Quarter and owned by the Birmingham Conservation Trust. Grant aid has been secured from the
	CONDITION:	Poor	City Council, Heritage Lottery Fund and English Heritage. Repairs are due to start in 2013.
	OCCUPANCY:	Vacant/not in use	
FARICING .	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage	LIST ENTRY NUMBER:	38023	Contact: Sarah Lewis 0121 625 6886
1 -	SITE NAME:	303, Icknield Street, Hockley	Built 1883, by Martin and Chamberlain, in brick and
	DESIGNATION:	Listed Building grade II*	terracotta with tiled roof as master's house to the lcknield Street School. Now derelict and in poor state of repair
	CONDITION:	Poor	with risk of rapid deterioration. Upper storey windows and
	OCCUPANCY:	Vacant/not in use	door now boarded up.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1291556	Contact: Sarah Lewis 0121 625 6886
© English Heritage			
	SITE NAME:	Public Baths, Moseley	Municipal baths with lavish terracotta decoration and
1	DESIGNATION:	Listed Building grade II*	complete interiors. The baths were opened in 1907 as an
	CONDITION:	Poor	addition to the Free Library (1895) forming an impressive group of public buildings. A masterplan for future use of the
A share a	OCCUPANCY:	Part occupied/part in use	building has been prepared by the City Council but plans to bid for Heritage Lottery Fund grant have been abandoned.
	PRIORITY CATEGORY:	C (C)	Discussion is now focused on urgent interim works to keep
	OWNER TYPE:	Local authority	the building watertight pending a resurrection of the Heritage Lottery Fund bid.
	LIST ENTRY NUMBER:	1076274	Contact: Sarah Lewis 0121 625 6886
© English Heritage		10/02/1	
	SITE NAME:	Former School of Art, 496-500, Moseley Road, Moseley	Moseley School of Art was designed by Bidlake and built in 1899. It was bought from the Council in the 1960s by the
	DESIGNATION:	Listed Building grade II*	Moseley Muslim Community Association. The building is now suffering from neglect; spalling stonework and leaking
- <u>- LOUB</u> -	CONDITION:	Poor	roofs are problems. A conservation plan and fabric
	OCCUPANCY:	Occupied/in use	condition survey exist and an options appraisal has been funded by English Heritage and the Architectural Heritage
	PRIORITY CATEGORY:	C (C)	Fund with a view to developing an application to Heritage Lottery Fund for grant aid.
	OWNER TYPE:	Religious organisation	
© English Heritage Archive	LIST ENTRY NUMBER:	1343102	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	100 Sampson Road, Sparkhill	Built in 1901 as the vicarage to St Agatha's Church in Sparkbrook and designed in an Arts and Craft style by local Birmingham architect, WH Bidlake. Formerly converted to flats by a Housing Association, the building is now in private ownership but has been subject to vandalism, a small fire
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	and is now suffering from dry rot and isolated structural
	PRIORITY CATEGORY:	B (B)	issues.
	OWNER TYPE:	Private	
ARCA LAND	LIST ENTRY NUMBER:	1076179	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / BIRMINGHAM

	SITE NAME:	The Bellefield Inn, 36-38 Winson Street, Winson Green	Public house and attached outbuildings, C19 with early C2 remodelling by Wood and Kendrick. Outwardly modest, the interiors were unusual for their remarkable completeness. However, a fire has substantially destroyed the interior and much of the building is in very poor condition. The building has changed hands and Planning Permission for residential conversion has been granted, b no repairs carried out.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Commercial company	
© Shrewsbury and Atcham Borough Council	LIST ENTRY NUMBER:	1276279	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	Edward Road Baptist Church, Edward Road, Birmingham	This is a good example of the Birmingham terracotta school's work which combines Romanesque and
	DESIGNATION:	Listed Place of Worship grade II	Perpendicular details. There is evidence of damp at high level, roof needs attention and the joints to brick and

	Edward Road Baptist Church, Edward Road, Birmingham	school's work which combines Romanesque	ingham school's work which combines Romanesque a
0.82	DESIGNATION:	Listed Place of Worship grade II	Perpendicular details. There is evidence of dam level, roof needs attention and the joints to brid
THE REAL	CONDITION:	Poor	terracotta blocks are badly eroded.
-	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1343405	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	lcknield Street School, Icknield Street, Hockley	School 1883, by Martin and Chamberlain. The building is occupied by a religious group for the purpose of worship and community use. The roof to the fire damaged area has been repaired, but more comprehensive repair of the building is needed. Rainwater goods are in poor shape and unsympathetic security measures detract from the appearance of the building.
	DESIGNATION:	Listed Place of Worship grade II*	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1076315	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Bethel United Church, Coventry Road, Small Heath	An Italianate brick church built in 1911 and designed by JL Ball. There is a need for maintenance with some brickwork decay and windows in poor condition.
	DESIGNATION:	Listed Place of Worship grade II	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1234443	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Parish Church of St Margaret, St Margaret's Road, Ward End	Built in 1834 in a Commissioners' Gothic style with lancet windows and rendered elevations, this church is in
	DESIGNATION:	Listed Place of Worship grade II	generally poor condition and vulnerable to vandalism. Though currently closed, it is the subject of a proposal for redevelopment and extension to create a new community centre for which an application for Heritage Lottery Fund funding is in preparation.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1220802	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / BIRMINGHAM

SITE NAME:	Kent's Moat		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020538
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Barnsley Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
ITE NAME:	Digbeth / Deritend		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
SITE NAME:	Four Oaks		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
INERABILITY: Medium		CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
SITE NAME:	Ideal Village, Bordesley Green		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
SITE NAME:	Lozells and Soho Hill		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
/ULNERABILITY:	High	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
ITE NAME:	School Road		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Low	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258
SITE NAME:	Steelhouse		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 012 464 8258

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / BIRMINGHAM / COVENTRY

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

SITE NAME:	Sutton Coldfield High Street		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
SITE NAME:	Warwick Bar		
SITE NAME: DESIGNATION:	Warwick Bar Conservation Area, 7 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 7 LBs		

Ruined Cathedral Church of

Saint Michael, Coventry

Religious organisation

Poor

N/A

F (F)

1076651

Listed Building grade I, CA

COVENTRY

SITE NAME:	Cook Street Gate	The only remaining functional medieval gate to Coventry.
DESIGNATION:	Scheduled Monument, LB grade I, part in RPG grade II, CA	Construction of the gate began in the early C14 and was completed later that century following a licence to crenellate in 1363. Inappropriate historic repairs,
CONDITION:	Poor	vulnerability to vehicle damage and stone erosion are issues.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1005908	Contact: Sarah Lewis 0121 625 6886

The iconic ruins of the original Coventry Cathedral,

to make the ruins safe.

Contact: Sarah Lewis 0121 625 6886

destroyed by a bombing raid in November 1940. Areas of

exposed walls have become unstable. An English Heritage

grant has been offered and accepted and work is underway







© English Heritage Archive



SITE NAM		Basement on site of Old Star Inn, Earl Street, Coventry	Late medieval cellar of an inn, now incorporated in the Civic Centre. Significant erosion of sandstone has taken
DESIGNA	TION:	Listed Building grade II*	place through water penetration from adjacent road works. The damage to the stone vault was repaired in 2008
CONDITI	ON:	Fair	and tanked. Temporary support to rib vaulting installed. Phase II works to replace eroded ribs necessary.
OCCUPA	NCY:	Vacant/not in use	
PRIORITY	CATEGORY:	D (D)	
OWNER -	TYPE:	Local authority	
LIST ENTE	RY NUMBER:	1115642	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	The Old Grammar School (St Johns Hospital), Hales Street, Coventry	Former chapel of the C12 hospital of St John, used as grammar school from 1545. Currently unoccupied. The subject of a successful Heritage Lottery Fund bid, to be a
	DESIGNATION:	Listed Building grade I	part of the adjoining Transport Museum. Relevant consents have been granted and work is about to start.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
A Sent	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1320431	Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

- obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / COVENTRY

	SITE NAME:	The Charterhouse, London Road	Founded as a Carthusian Monastery dedicated to St Anne, the surviving building is a mixture of stone, brick and
	DESIGNATION:	Listed Building grade I and Scheduled Monument, CA	timber-frame construction incorporating centuries of change and adaptation. Exceptional and vulnerable wall paintings survive from the C15 and C16. The clay tile roof
	CONDITION:	Poor	is in poor condition and there is evidence of water damage within the building. Now in the ownership of Charterhous
	OCCUPANCY:	Part occupied/part in use	Coventry Preservation Trust, the building awaits re-use.
	PRIORITY CATEGORY:	C (New entry)	The Trust is embarking on an options appraisal and a phas of fundraising.
	OWNER TYPE:	Charity (heritage)	
D English Heritage	LIST ENTRY NUMBER:	1076621 and 1005901	Contact: Sarah Lewis 0121 625 6886
	SITE NAME:	The Charterhouse, precinct walls, London Road, Coventry	The inner precinct wall built of sandstone was extended in the centuries after the Reformation when the
	DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, I B grade II CA	Charterhouse became a dwelling. It is now in very bad condition with sections which have collapsed and others which are destabilised by vegetation growth. Now owned

© English Heritage

		A
-	T and	and the
10-	Til	FILE
		I PES
1	The second second	
		-
	100	

- P.			
	LIST ENTRY NUMBER:	1005901 and 1076621; 1342917	Contact: Sarah Lewis 0121 625 6886
	OWNER TYPE:	Charity (heritage)	
and a	PRIORITY CATEGORY:	B (C)	
	OCCUPANCY:	N/A	
200	CONDITION:	Very bad	application for English Heritage grant has been made.
	Designation:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA	Charterhouse became a dwelling. It is now in very bad condition with sections which have collapsed and othe which are destabilised by vegetation growth. Now ow by Charterhouse Coventry Preservation Trust, an
		walls, London Road, Coventry	the centuries after the Reformation when the

© English Heritage	SITE NAME:	Nonconformist Chapel to the Cemetery, London Road, Coventry	Cemetery chapel, 1846-47, probably by GH Stokes at southern end of the mid C19 cemetery, landscaped by Joseph Paxton in an informal style. The City Council
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	repaired roof to its original design following a fire and carried out other repairs including capping the pavilion walls, interior pointing, installing security grills and doors.
	CONDITION:	Fair	However, the building remains without a use and in a vulnerable condition.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1076624	Contact: Sarah Lewis 0121 625 6886

SITE NAME: Coventry city walls, Cook Street, Coventry DESIGNATION: Scheduled Monument, 2 LBs, part in RPG grade II, 2 CAs LIST ENTRY NUMBER: 1002979 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY?: No
CONDITION: Generally unsatisfactory with major localised problems TREND: Declining
problems
PRINCIPAL VUI NERARII ITY' Vandalism NEW ENTRY' No
Validaisti Validaisti
OWNER TYPE: Local authority CONTACT: Sarah Lewis 0121 625 6886
SITE NAME: Priory ruins
SITE NAME: Priory ruins DESIGNATION: Scheduled Monument, 2 LBs, CA LIST ENTRY NUMBER: 1005902
DESIGNATION: Scheduled Monument, 2 LBs, CA LIST ENTRY NUMBER: 1005902 CONDITION: Generally satisfactory but with significant localised TREND: Deslining

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

DUDLEY



SITE NAME:	Triangular Crane, Bumble Hole Boat Yard, Dudley	C19 triangular boat crane, in poor condition. English Heritage funded a report on the condition and repair of the
DESIGNATION:	Scheduled Monument, CA	monument. A grant application for repairs was made but later withdrawn as no other funding was available for
CONDITION:	Poor	repairs. The crane collapsed in 2002 and sections of structure remain stored in the yard. A joint initiative is
OCCUPANCY:	N/A	needed for the repair/reinstatement of the structure. An
PRIORITY CATEGORY:	A (A)	interpretation project has been carried out culminating on several panels, erected along the Boshboil Arm.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005884	Contact: Sarah Lewis 0121 625 6886

© English Heritage

	SITE NAME:	Brown bear pit at Dudley Zoo, Castle Hill, Dudley	Bear pit. Built in 1936-7. A major repair project is imminent, for which a Heritage Lottery Fund Stage 1 grant
	DESIGNATION:	Listed Building grade II*, CA	has been offered. A grant application for Stage 2 has been submitted.
	CONDITION:	Poor	
2	OCCUPANCY:	Occupied/in use	
120	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
hive	LIST ENTRY NUMBER:	1227748	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archi

© English Heritage Archive



Kiosk. Built in 1936-7. A major repair project is imminent, Kiosk to east of Brown Bear Pit, SITE NAME: Dudley Zoo, Castle Hill, Dudley for which a Heritage Lottery Fund Stage I grant has been offered. A grant application for Stage 2 has been submitted. DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (D)

	OWNER TYPE:	Commercial company				
	LIST ENTRY NUMBER:	1076024	Contact: Sarah Lewis 0121 625 6886			
	SITE NAME:	The Old Foundry, Lowndes Road, Stourbridge	Iron foundry 1820-1, formerly Foster & Rastricks Works and in continuous foundry use until 2001. Work on repairs			
	DESIGNATION:	Listed Building grade II*, CA	and conversion to a medical centre is being undertaken, the roof repairs are completed. Other repair and			
	CONDITION:	Poor	conversion works are well advanced.			
1	OCCUPANCY:	Vacant/not in use				
L	PRIORITY CATEGORY:	B (B)				
	OWNER TYPE:	Commercial company				
	LIST ENTRY NUMBER:	1262873	Contact: Sarah Lewis 0121 625 6886			

© English Heritage



4	SITE NAME:	Church of St Edmund, Castle Street, Dudley	Situated in the centre of Dudley, this is a red brick church built in the Palladian style in the 1720s. Shallow tile roofs
T	DESIGNATION:	Listed Place of Worship grade II*, CA	fall to parapets finished with stone dressings which are also a distinctive feature of the round-headed windows and the tower. Vegetation growing out of the tower is impacting on
V	CONDITION:	Poor	high level stonework and is a significant cause for concern.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
and the second	LIST ENTRY NUMBER:	1287455	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

use).

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious now user (applicable only obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park CA LB
- LPA
- NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

٦e

HERITAGE AT RISK 2013 / WEST MIDLANDS / DUDLEY

	SITE NAME:	Church of St James the Great, Salop Street, Dudley	A Commissioners' Church of the mid C19, designed by William Bourner. Sister church to St John the Evangelist,
	DESIGNATION:	Listed Place of Worship grade II	Kate's Hill. The church is built of limestone with ashlar stone dressings. A Repair Grant for Places of Worship for
A RANDOW	CONDITION:	Poor	stonework repairs was offered in March 2013 and Stage One for project development is being prepared.
	PRIORITY CATEGORY:	D (D)	One for project development is being prepared.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1270305	Contact: Sarah Lewis 0121 625 6886

© English Heritage

> KINK	SITE NAME:	Church of St John the Evangelist, St Johns Road, Dudley	St John's was designed in the Gothic lancet style by William Bourner and is the sister church to St James, Eve Hill also in Dudley. The church opened in 1849 but closed its doors
A STATE OF	DESIGNATION:	Listed Place of Worship grade II	for safety reasons in 2002. Worship now takes place in the parish hall. A feasibility study for re-use for worship,
	CONDITION:	Poor	concerts, a cafe and community and educational use has been carried out and fundraising is underway.
The second secon	PRIORITY CATEGORY:	C (C)	
28.02.2005	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1393300	Contact: Sarah Lewis 0121 625 6886
© English Heritage			

and a state of the	SITE NAME:	Presbyterian Chapel, Lower High Street, Stourbridge	A red brick Presbyterian chapel built in 1788 with round- headed windows, stone detailing, and a projecting porch.
STA	DESIGNATION:	Listed Place of Worship grade II, CA	Brickwork and cast iron windows are in poor condition.
_	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
*	LIST ENTRY NUMBER:	343 95	Contact: Sarah Lewis 0121 625 6886

© English Heritage

The Redhouse, Whitehouse and Newhouse glassworks			
Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1021378	
CONDITION: Generally unsatisfactory with major localised problems		Declining	
Deterioration - in need of management	NEW ENTRY?:	No	
Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886	
Wychbury Camp (see also Bromsgrove, Worcesters	hire), Hagley		
Scheduled Monument	LIST ENTRY NUMBER:	1005900	
Generally unsatisfactory with major localised problems	TREND:	Declining	
Deterioration - in need of management	NEW ENTRY?:	No	
Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886	
Brierley Hill High Street			
Conservation Area, 2 LBs	NEW ENTRY?:	Yes	
Very bad	TREND:	Improving	
	Scheduled Monument, LB grade II*, CA Generally unsatisfactory with major localised problems Deterioration - in need of management Mixed, multiple owners Wychbury Camp (see also Bromsgrove, Worcesters Scheduled Monument Generally unsatisfactory with major localised problems Deterioration - in need of management Private, multiple owners Brierley Hill High Street Conservation Area, 2 LBs	Scheduled Monument, LB grade II*, CALIST ENTRY NUMBER:Generally unsatisfactory with major localised problemsTREND:Deterioration - in need of managementNEW ENTRY?:Mixed, multiple ownersCONTACT:Wychbury Camp (see also Bromsgrove, Worcestershire), HagleyScheduled MonumentLIST ENTRY NUMBER:Generally unsatisfactory with major localised problemsTREND:Deterioration - in need of managementNEW ENTRY?:Private, multiple ownersCONTACT:Private, multiple ownersCONTACT:Brierley Hill High StreetNEW ENTRY?:Conservation Area, 2 LBsNEW ENTRY?:	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / DUDLEY / SANDWELL

SITE NAME:	Stourbridge Branch Canal (Canal Street)		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington 01384 814168
SITE NAME:	Wollaston		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington (LPA) 01384 814168
SITE NAME:	Wordsley Church		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington 01384 814168

SANDWELL

A 45-54	SITE NAME:	Soho Foundry, Foundry Lane, Smethwick	Foundry built in 1795: the world's first integrated manufactory of steam engines. Established by Boulton &
	DESIGNATION:	Listed Building grade II*	Watt. English Heritage and the Local Authority grant-aid a temporary roof to stabilise structure. Discussions
	CONDITION:	Poor	ongoing with the owners to find a new use.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
-	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1268451	Contact: Sarah Lewis 0121 625 6886

C nglish Heritage Archive

2.	SITE NAME:	Waterloo Hotel, Shireland Road, Smethwick	Built 1907 by Wood and Kendrick for local brewers, Mitchells & Butler, in baroque style with terracotta
T	DESIGNATION:	Listed Building grade II*	dressings. A near complete example of an Edwardian showpiece pub and commercial hotel, which retains many
	CONDITION:	Poor	interior features including the ornate basement grill room. The pub is now closed and boarded up and has recently
STILL THE REAL	OCCUPANCY:	Vacant/not in use	been broken into.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1261644	Contact: Sarah Lewis 0121 625 6886

SITE NAME:	Chances Glassworks, Smethwick		
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER:	1021387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Remains of the Boulton and Watt Soho foundry a	nd mint, Birmingham	n Canal, Smethwick
SITE NAME: DESIGNATION:	Remains of the Boulton and Watt Soho foundry a Scheduled Monument, LB grade II	nd mint, Birmingham	n Canal, Smethwick 1021388
	,		
DESIGNATION:	Scheduled Monument, LB grade II Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1021388

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / SANDWELL / WALSALL

SITE NAME:	Engine Arm Aqueduct, Warley		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1005904
CONDITION: Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Utility	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	High Street, West Bromwich, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	A Bishop (LPA) 0121 569 4033
SITE NAME:	Market Place, Wednesbury, Black Country		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	A Bishop (LPA) 0121 569 4033

WALSALL

©

	SITE NAME:	Great Barr Hall and chapel, Great Barr	Gothic country house of 1777 with 1863 chapel attributed to George Gilbert Scott. Set in late C18 landscaped park.
A DECEMBER OF	DESIGNATION:	Listed Building grade II*, RPG grade II, CA	Converted to hospital early C20, and surrounded by C20 hospital buildings, now abandoned. House vacant since 1978, suffering from continued decay, vandalism and loss of
ILL IN A	CONDITION:	Very bad	fabric. The property changed hands in spring 2012, and proposals from the new owner are expected.
	OCCUPANCY:	Vacant/not in use	proposals normale new owner are expected.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage Archive	LIST ENTRY NUMBER:	1076395	Contact: Sarah Lewis 0121 625 6886

	SITE NAME:	Church of St Matthew, Church Hill, Walsall	St Matthew's was rebuilt in the 1820s by Francis Goodwin, its soaring spire is a local landmark and its Bath stone
	DESIGNATION:	Listed Place of Worship grade II*, CA	facades stand out in the street scene. The style of the church is predominantly Perpendicular but C13 remains survive in the crypt. High level repairs are needed all over
	CONDITION:	Poor	this complex building. A Repair Grant for Places of Worship was offered in December 2012 and Stage One -
	PRIORITY CATEGORY:	B (A)	Project Development is being prepared.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1116151	Contact: Sarah Lewis 0121 625 6886
Horitago			

© English Heritage



	SITE NAME:	Life and Light Mission Church (fomer Trinity Methodist Church), Union Street, Willenhall	Built as a Methodist church in the 1860s, this large rendered church is in the Classical style, with round- headed windows and pilasters, making it prominent on the street frontage. The render is loose in many areas allowing
	DESIGNATION:	Listed Place of Worship grade II, CA	water to enter the building. A Repair Grant for Places of Worship was offered in March 2013 and Stage One project development is currently being prepared.
	CONDITION:	Poor	, , ,
	PRIORITY CATEGORY:	B (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1077170	Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WALSALL

SITE NAME:	Bloxwich High Street		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Bradford Street, Walsall		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Bridge Street, Walsall		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Caldmore Green, Walsall		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Church Hill, Walsall		
DESIGNATION:	Conservation Area, 19 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Elmore Green, Bloxwich		
DESIGNATION:	Conservation Area, 3 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Fuller (LPA) 01922 655537
SITE NAME:	Willenhall		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
			0

WALSALL / SANDWELL



Parkland and pleasure grounds, partly by Humphry Repton SITE NAME: Great Barr Hall, Walsall and John Nash. Much of historic park built over as mental Registered Park and Garden hospital in C20, in turn replaced by modern housing estate DESIGNATION: grade II, 3 LBs, part in CA circa 2005. Pleasure grounds overgrown and neglected; remaining area of park also in poor condition. Hall is dilapidated and also at risk. In 2010 English Heritage CONDITION: Extensive significant problems VULNERABILITY: High reviewed the area covered by the registered park and enlarged it. Change of ownership in spring 2012. Proposals TREND: Declining from new owners awaited. Part of the park is in the district of Sandwell. NEW ENTRY ?: No OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: 1001202 Contact: Sarah Lewis 0121 625 6886

© English Heritage

PRIORITY CATEGORIES

D

Е

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid в deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

WOLVERHAMPTON, CITY OF Mid C16 manor house, restored in 1930s. Of timber-SITE NAME The Greyhound and Punchbowl framed construction, strengthened with concrete skin in Inn (formerly Stoke Heath the 1930s. Now suffering complex structural problems to Manor House), High Street, supporting concrete frame requiring long-term solution. Bilston English Heritage engineer has prepared preliminary report. DESIGNATION: Listed Building grade II* A more detailed structural survey and investigation will be required to establish the most appropriate method of CONDITION: Poor repair. OCCUPANCY. Part occupied/part in use PRIORITY CATEGORY: C (C) © English Heritage OWNER TYPE: Other not for profit group LIST ENTRY NUMBER: 1201819 Contact: Sarah Lewis 0121 625 6886 Late CI5 timber-framed house with early CI8 alterations. SITE NAME Graiseley Old Hall, Carlton Road, Wolverhampton Gradual repairs being carried out, but more comprehensive approach required. Some movement and DESIGNATION: Listed Building grade II* cracking to external elevations apparent. Preliminary report by English Heritage engineer. Local preservation trust and CONDITION: Fair the Local Authority advising owner on structural survey needed to establish repair priorities. OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1205291 Contact: Sarah Lewis 0121 625 6886 © English Heritage Archive SITE NAME: Church of St Leonard, Church This church was built in 1825 to designs by Francis




Goodwin, and restored in the 1880s by Ewan Christian. It Street, Wolverhampton is in the neoclassical style, finished in render with elegant DESIGNATION: Listed Place of Worship grade II round-headed windows and a fine octagonal tower. The interior has decorative plaster ceilings and balconies. CONDITION: Poor Leaking parapet gutters are affecting the render externally PRIORITY CATEGORY: C (C) and the plaster internally. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1282492 Contact: Sarah Lewis 0121 625 6886

© English Heritage

WORCESTERSHIRE

BROMSGROVE



PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2013 / WEST MIDLANDS / BROMSGROVE

	SITE NAME:	Temple of Theseus, Hagley Hall, Hagley	Doric temple of 1758 designed by James 'Athenian' Stewart. It stands in the grade I registered landscape park
	DESIGNATION:	Listed Building grade I, RPG grade I	800 metres north of the Hall. It is separated from the rest of the estate by the A456; this relatively isolated location has rendered it vulnerable to vandalism so security fencing
English Heritage	CONDITION:	Poor	has been erected. Discussions continue with owner on a strategy to secure the future of the building.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1348599	Contact: Sarah Lewis 0121 625 6886

Commences of a	SITE NAME:	The Rotunda, Hagley	Designed by John Pitt in 1747 as one of a series of garden
SEN	DESIGNATION:	Listed Building grade II*, RPG grade I	monuments in the designed landscape at Hagley. The original domed roof and supporting timber structure has collapsed; the surviving stonework is in very poor
	CONDITION:	Very bad	condition. English Heritage grant has been offered for repairs to the structure.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Private	
h Heritage	LIST ENTRY NUMBER:	1348598	Contact: Sarah Lewis 0121 625 6886

All Saints is a large urban church in the centre of SITE NAME: Church of All Saints, Birmingham Road, Bromsgrove Bromsgrove built in the 1870s to the design of John Cotton. It is constructed from rock-faced sandstone with DESIGNATION: Listed Place of Worship grade II brick detailing and interior walling with a plain clay tile roof. The three-stage tower is capped by an octagonal in place CONDITION Poor of the spire that was planned but never built. Stonework to PRIORITY CATEGORY: F (D) the tower and walls requires repair and repointing, parts of the roof are in poor condition; the vestry roof leaks. Work OWNER TYPE: Religious organisation to address these issues, funded by a Repair Grant for Places of Worship, is underway. LIST ENTRY NUMBER: 1100370 Contact: Sarah Lewis 0121 625 6886

© English Heritage

© Er

© English

1 Pro	Street, Bromsgrove	Congregational Chapel, Chapel Street, Bromsgrove	Built in 1832 on the site of an earlier chapel and with a brick church hall adjacent. The windows are in poor
	DESIGNATION:	Listed Place of Worship grade II, CA	condition, paintwork on the stucco façade is peeling and the slate roofs have been the subject of inappropriate short-term repairs.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1348880	Contact: Sarah Lewis 0121 625 6886
Fradiah I Janizana			

© English Heritage

SITE NAME:	Moated site at Tardebigge Farm, Bentley Pauncefoot / Stoke			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017808	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

use).

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / BROMSGROVE / MALVERN HILLS

NEW ENTRY ?:

Low

No

SITE NAME:	Dodford Priory	moated site, Dodford with Grafton	n	
DESIGNATION:	Scheduled Monument, 2 LBs, CA		LIST ENTRY NUMBER:	1018278
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Moated site at Blackgreves Farm, Wythall			
DESIGNATION:	Scheduled Monument, LB grade II		LIST ENTRY NUMBER:	1017804
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Other not for pr	rofit group	CONTACT:	Sarah Lewis 0121 625 6886
	SITE NAME:	Hewell Grange, Tutnall and Cobley / Bentley Pauncefoot	Multi-phase landscape, including work influenced by Humphry Repton. Another major period of activity towards the end of C19 when current house built. Po war development by Prison Service has had a major i on legibility of design. Management plan and partners with County Gardens Trust has led to renewed inter and care for designed landscape, including restoration	
	DESIGNATION:	Registered Park and Garden grade II*, 15 LBs		
	CONDITION:	Extensive significant problems		
	VULNERABILITY:	High	bridge to island.	
	TREND:	Stable		

© English Heritage

	OWNER TYPE: Mixed, multiple owners			
	LIST ENTRY NUMBER: 1000886			
SITE NAME:	Bromsgrove Town Centre			
DESIGNATION:	Conservation Area, 53 LBs	NEW ENTRY?: No		

MALVERN HILLS

VULNERABILITY:

	SITE NAME:	Service wing, Croome Court, Croome D'abitot	The red brick service wing attached to east end of Croome Court, dated 1751-2 by Lancelot 'Capability' Brown. The
1	DESIGNATION:	Listed Building grade I, RPG grade I	Service Wing now belongs to the National Trust. A repair scheme to make the building wind and weather-tight by the end of 2013 is underway with the aid of an English Heritage
ALL MANAGE	CONDITION: Very bad grant.	Very bad	,
	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage	LIST ENTRY NUMBER:	1349526	Contact: Sarah Lewis 0121 625 6886

CONTACT:



SITE NAME:	Churchyard cross, St Mary's Church, Shrawley
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1014901

This cross is a good example of a medieval standing cross base of stepped form with a moulded plinth. It is believed to stand in its original position, and limited development in the area immediately surrounding the cross suggests that archaeological deposits relating to the monument's construction and use in this location are likely to survive intact. The joints between the plinth stones are open, some stones have cracked through and the surface of the stones is mossy.

Contact: Sarah Lewis 0121 625 6886

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Mary Worsfold (LPA) 01527 881329

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / MALVERN HILLS / WORCESTER



SITE NAME: Church of the Ascension including church hall to east, Malvern Link, Malvern DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1349465

This church was built in 1902 to a design by Sir Walter Tapper. The walls are rendered brick with dressings and a tower in limestone and a roof of graduated stone tiles. The rainwater goods are a particular part of the design and are in poor condition. A Repair Grant for Places of Worship was offered in April 2013 to carry out necessary repairs.

Contact: Sarah Lewis 0121 625 6886

© English Heritage

SITE NAME:	Enclosure 110 yards (100 metres) north of St Ba	artholomew's Church,	Grimley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005296
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosure west of Church Farm, Grimley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005315
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Tenbury Wells, Tenbury		
DESIGNATION:	Conservation Area, 55 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Heather Royle (LPA) 01684 862335

WORCESTER

	SITE NAME:	Remains of city wall, Worcester	Medieval city walls in multiple ownership, which results in a
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	lack of co-ordinated approach. A variety of repair and maintenance has taken place in the past. A Conservation Management Plan for the medieval defences has been
	CONDITION:	Poor	completed. Sections of the wall are under repair with English Heritage grant aid.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	E (D)	
	OWNER TYPE:	Private	
chive	LIST ENTRY NUMBER:	1005281 and 1063805	Contact: Sarah Lewis 0121 625 6886

© English Heritage Arch



SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	SITE NAME:	Waiting Room, Shrub Hill Station, Worcester	This ornate waiting room, circa 1880, is of cast iron frame construction with infill panels of glazed ceramic tiles. A			
	DESIGNATION:	Listed Building grade II*	scheme for full restoration and re-use progressed well but has stalled. The structure is fenced off on the platform.			
	CONDITION:	Fair	Repairs need to be completed.			
	OCCUPANCY:	Vacant/not in use				
	PRIORITY CATEGORY:	F (F)				
	OWNER TYPE:	Utility				
	LIST ENTRY NUMBER:	1390157	Contact: Sarah Lewis 0121 625 6886			

© English Heritage

Y CATE	GORIES
Y CATE	GORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / WORCESTER / WYCHAVON

SITE NAME:	Moated monastic grange and fishpond complex a Farm, St. Peter the Great County	t Middle Battenhall Fa	arm, 450m north of Upper Battenhall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017310
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Lark Hill, Worcester		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Jim Blackwell (LPA) 01905 722543
SITE NAME:	Lowesmoor, Worcester		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jim Blackwell (LPA) 01905 722543
SITE NAME:	The Canal, Worcester		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Jim Blackwell (LPA) 01905 722543

WYCHAVON



	SITE NAME:	Eckington Bridge, Birlingham / Defford / Eckington	Fine example of early C16 bridge of six arches built in sandstone. It is a narrow single track road bridge controlled
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	by traffic lights. The bridge has suffered from frequent traffic collisions. The Local Authority has undertaken stonework repairs and is about to embark on protection
	CONDITION:	Fair	measures for the bridge to reduce the harmful impact of traffic. Chemical erosion from roadsalt penetration of
	OCCUPANCY:	N/A	structure is causing stonework failure.
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1005264 and 1116724	Contact: Sarah Lewis 0121 625 6886



	LIST ENTRY NUMBER:	1005264 and 1116724	Contact: Sarah Lewis 0121 625 6886			
	SITE NAME:	31 High Street, Droitwich Spa	31 High Street is the solar wing of a C14 timber framed			
-	DESIGNATION:	Listed Building grade II*, SM, CA	town house. The front range is rendered but incorporates exceptional timber work in the roof and ceiling structures.			
	CONDITION:	Very bad	C17 extensions to the rear are in very bad condition with structural failure to the timber frame and walls. Failed			
	OCCUPANCY:	Part occupied/part in use	rainwater goods and a roof in poor condition are letting			
-	PRIORITY CATEGORY:		vater into the structure and rotting the frame. The building only partly occupied.			
	OWNER TYPE:	Commercial company				
	LIST ENTRY NUMBER:	1296659	Contact: Sarah Lewis 0121 625 6886			

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013	/ WEST MIDLANIDS	/ WYCHAVON

	SITE NAME:	Abbot Chyryton wall, Boat Lane, Evesham	Part of the outer precinct wall of Evesham Abbey, built by abbot William de Chyryton (1317-44), which originally	
	DESIGNATION:	Scheduled Monument and Listed Building grade II	extended from river to Abbey. Previous grant-aided consolidation has partially failed due to vandalism. Some parts of wall still in very bad condition, and wall footings are	
	CONDITION:	Very bad	diminishing. Discussions ongoing to agree long-term solution.	
Million Martines	OCCUPANCY:	N/A	Solution.	
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Private		
© English Heritage	LIST ENTRY NUMBER:	1005501 and 1350435	Contact: Sarah Lewis 0121 625 6886	
	SITE NAME:	West porch of Bengeworth Old Church, Church Street, Bengeworth, Evesham	The old church of St Peter was pulled down in 1870, leaving the remains of the porch that stood under the west tower. It is constructed of rubble masonry, which has been	
A Cased &	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	pointed with cement in the past and is now cracking. Issues include significant ivy growth on south side, missing roof tiles, salt erosion causing stone damage by road and	
	CONDITION:	Poor	structural cracking on southeast corner. Scheme of repair	
	OCCUPANCY:	N/A	prepared but not implemented. Condition is deteriorating.	
	PRIORITY CATEGORY:	C (C)		
© English Heritage	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1005299 and 1095958	Contact: Sarah Lewis 0121 625 6886	
and the second	SITE NAME:	Abbot Reginalds Wall, Evesham Abbey, Evesham	Abbot Reginalds wall forms part of the main ecclesiastical complex of Evesham Abbey, fragments of which still	
	DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, CA	survive. The rebuilding of the collapsed section and repairs to adjoining wall have been completed with grant aid. Sections of wall are still in poor condition and in need of an overall repair strategy.	
See and - MARY A	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	С (С)		
© English Heritage	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:		Contact: Sarah Lewis 0121 625 6886	
	SITE NAME:	Church of St John the Baptist, Church Walk, Crowle	The original medieval church was demolished and rebuilt in the 1880s to designs by Frederick Preedy in the Decorated	
	DESIGNATION:	Listed Place of Worship grade II*, CA	style with a tall west tower. The church is constructed from lias limestone rubble with ashlar dressings under a plain clay tile roof with decorative ridges. The roof and	
	CONDITION:	Poor	rainwater goods are in poor condition, minor repairs are	
	PRIORITY CATEGORY:	D (D)	required to the stonework. A Repair Grant for Places of Worship was offered in February 2013.	
	OWNER TYPE:	Religious organisation	· · ·	
	LIST ENTRY NUMBER:	1081275	Contact: Sarah Lewis 0121 625 6886	

	SITE NAME:	Church of St John the Baptist, Grafton Flyford	Medieval church dating from the C13 to C14 with Perpendicular window tracery. It was restored in 1875 by	
	DESIGNATION:	Listed Place of Worship grade II*	Hopkins. There are patches of weathered stonework on the tower and chancel as well as vegetation and moss	
	CONDITION:	Poor	growth on the tower, nave, vestry and chancel. Leaking	
	PRIORITY CATEGORY:	A (A)	guttering on the vestry has resulted in the saturation of surrounding stonework and there are some structural	
	OWNER TYPE:	Religious organisation	cracks in the east elevation of the vestry.	
	LIST ENTRY NUMBER:	1374136	Contact: Sarah Lewis 0121 625 6886	

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WYCHAVON

1	SITE NAME:	Church of St John the Baptist, Stock and Bradley	St John the Baptist was built in the 1860s to designs by WJ Hopkins and remains largely unaltered. This is a large
A	DESIGNATION:	Listed Place of Worship grade II	sandstone church with red brick bands picking out the chancel, tower and west end. It has a plain clay tile roof
	CONDITION:	Poor	which is in poor condition with many rusted nails putting the roof at risk. There is evidence of structural movement
A de T	PRIORITY CATEGORY:	B (B)	in the west and east ends. A Repair Grant for Places of
III FALL	OWNER TYPE:	Religious organisation	Worship was offered in February 2013 to address these issues.
	LIST ENTRY NUMBER:	1081660	Contact: Sarah Lewis 0121 625 6886

© English Heritage

SITE NAME:	Settlement site NNE of Fernhill Farm, Charlton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005287
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Enclosures north east of Fernhill Farm, Charlton /	Cropthorne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005286
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Roman settlement at Bays Meadow, Droitwich Spa	L	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020620
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Evesham Abbey (remains of), Evesham		
DESIGNATION:	Scheduled Monument, 4 LBs, CA	LIST ENTRY NUMBER:	1005297
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Settlement site north of Spring Hill, Fladbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005352
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Moated site 120 metres south east of Huntingdrop	Farm, Hanbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2013 / WEST MIDLANDS / WYCHAVON / WYRE FOREST

OWNER TYPE:

LIST ENTRY NUMBER:

SITE NAME:	Romano-British settlement remains 300m and 750m north east of Narrow Meadow Farm, Hinton on the Green / Evesham			
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1020257
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	Arable ploughing		No
OWNER TYPE:	Private, multiple o	owners	CONTACT:	Sarah Lewis 0121 625 6886
SITE NAME:	Anglo-Saxon cerr	netery at Bennett's Hill, Offenham		
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1020258
CONDITION:	Unknown	Unknown		Unknown
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	Private		Sarah Lewis 0121 625 6886
SITE NAME:	Double ditched e	enclosure north east of Wick villag	e, Wick	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1005310
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Sarah Lewis 0121 625 6886
-	SITE NAME:	Westwood Park, Westwood / Hampton Lovett	C20, generally go	asure grounds mostly late C19 and early bod condition. Vast majority of park in
A	DESIGNATION:	Registered Park and Garden grade II, 11 LBs	intensive cultivation, denuded of parkland trees. Some post-war development in vicinity of main house. Resid development and expansion of business park affect se particularly to north and east.	
	CONDITION:	Generally unsatisfactory with major localised problems		
	VULNERABILITY:	High		
	TREND:	Stable		
© English Heritage	NEW ENTRY?:	No		

Mixed, multiple owners

1000899

WYRE FOREST

© English Heritage



	SITE NAME:	Baches Forge, Churchill Lane, Churchill, Churchill and Blakedown	Early C19 hand forge building, comprising two brick structures which form part of a water-powered spade and shovel mill. The machinery still in working order and is	
	DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II	looked after by owners and small local trust. The building are now stable but an overall management plan addressir the condition of the monument and surviving plant is	
	CONDITION:	Poor	required.	
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private, multiple owners		
	LIST ENTRY NUMBER:	1005274 and 1348320; 1100650; 1100651	Contact: Sarah Lewis 0121 625 6886	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- В
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Sarah Lewis 0121 625 6886

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2013 / WEST MIDLANDS / WYRE FOREST

	SITE NAME:	Ribbesford House, Ribbesford	Mid C16 country house with late C17 and early C19
	DESIGNATION:	Listed Building grade II*	alterations. Owner continues to carry out remedial works Building structurally sound, but still in need of repairs to various parts of the building and still partially occupied. Internal modernisation to commence for reuse as apartments once interiors repaired. Discussions are ongoing with the owner.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
111 -	LIST ENTRY NUMBER:	1329928	Contact: Sarah Lewis 0121 625 6886

© English Heritage Archive

SITE NAME:	Gilgal, Stourport-on-Severn, East of Stourport Town Centre			
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562732928	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at **www.english-heritage.org.uk/risk**

HERITAGE AT RISK

Published October 2013 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2013