

# E Plade A 2014

YORKSHIRE

#### Contents

Heritage at Risk	II
The Register	VI
Content and criteria	VI
Criteria for inclusion on the Register	VII
Reducing the risks	×
Key statistics	XII
Publications and guidance	XIV
Key to the entries	XV
Entries on the Register by local planning authority	XVII
Cumbria	I
Yorkshire Dales (NP) East Riding of Yorkshire (UA)	 
Kingston upon Hull, City of (UA)	26
North East Lincolnshire (UA)	27
North Lincolnshire (UA)	28
North Yorkshire	31
Craven Hambleton Harrogate North York Moors (NP) Richmondshire Ryedale Scarborough Selby Yorkshire Dales (NP)  South Yorkshire Barnsley	31 32 37 41 52 56 73 77 81 83
Doncaster Peak District (NP) Rotherham Sheffield	86 90 90 93
West Yorkshire	97
Bradford Calderdale Kirklees Leeds Wakefield	97 103 108 113
York (UA)	121

II





Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results.

Over the past year we have focused much of our effort on assessing listed Places of Worship, and visiting those considered to be in poor or very bad condition as a result of local reports. We

now know that of the 14,775 listed places of worship in England, 6% (887) are at risk and as such are included on this year's Register. These additions mean the overall number of sites on the Register has increased to 5,753. However, 575 sites have been removed from the 2013 Register, which includes one of our biggest achievements this year, 39 (42%) of monuments in the North York Moors National Park.

Tammy Whitaker, Planning and Conservation Director, Yorkshire

In Yorkshire we have removed 32.7% of entries from the 2010 Register, against the national target of a 25% reduction by 2015. We have continued to make great progress, removing 122 assets from the Register, including 96 scheduled monuments, 18 places of worship and 5 buildings or structures. Our approach continues to focus on Yorkshire's most distinctive heritage.

#### The Ancient Landscapes of the Wolds and Moors

These landscapes contain some of England's most important prehistoric sites. Working with the North York Moors National Park and Natural England, we are addressing the threats to the area's many barrows and dykes. A national project focusing on the risks from arable cultivation was completed in 2014 and is helping us to work with owners to ensure effective management of their sites.

#### The Industrial Remains of the Dales

Lead mining has shaped the landscape of the Dales since Roman times and our successful partnership with the National Park has ensured the survival of significant structural remains and mining landscapes all over the Dales. Work has been completed at Gunnerside Gill, Red Scar, Grinton and Bolton Park mine.

#### South Yorkshire Metal Trades

Eagle Works, Sheffield, is being incorporated into an exciting mixed use development, with the repair of Green Lane Works forming part of a further phase of work, the overall project greatly enhancing to the Kelham Island Conservation Area. We are working with Sheffield City Council to secure the future of Leah's Yard in the heart of the city. With the East Peak Innovation Partnership we have secured the future of

important industrial remains, including the blast furnace and engine house at Rockley, near Barnsley.

#### Textile Industry of the West Riding

Finding viable uses for large textile mills remains challenging, but we have supported the successful repair and reuse of St Catherine's Home in the Manningham St Paul's conservation area in Bradford. At Manningham Mills we have supported the cost of urgent works to failing historic fabric and are working with the owners and other stakeholders to find an appropriate solution for the site. At Dalton Mills, Keighley, we are working with the new owner to support his vision for the site. He has already completed some repairs using his own resources. Next year we will focus our efforts on Hunslet Mill, Leeds, which suffered storm damage in late 2013.

#### Designed Landscapes of South Yorkshire

Bretton Park has been removed from the Heritage at Risk Register following conservation of the landscape with funding from Natural England and repairs to the chapel with grant from English Heritage and others. We are grant-aiding the repair of the gates at Oakes Park, Sheffield and the repair of the Ice House at High Melton. Other projects, at Wentworth Woodhouse and Wentworth Castle, are currently under discussion.

Craig McHugh,

Principal Adviser, Heritage at Risk

#### CHURCH OF ST WILFRID, HALTON, LEEDS

The spectacular interior of the grade II\* listed St Wilfrid's church has been repaired and redecorated following the completion of three phases of repair to its roofs and windows. The church was built in 1937-9 and is the last work of A Randall Wells. It marks the ultimate development of his individualistic Arts and Crafts style. The total cost of work was over £700,000 and was supported with almost £650,000 of public grants, allowing this fine church to continue to serve the local community.

# 2014 YORKSHIRE 1.22 SITES REMOVED FROM THE 2013 REGISTER 40/0 6.20/0 E892k 67 SITES WHAT'S ON THE HERITAGE AT RISK REGISTER? 71 CONSERVATION AREAS (7.1%) 15.20/0 19.60/0





#### ADLINGFLEET MEDIEVAL RECTORY, ADLINGFLEET, EAST RIDING OF YORKSHIRE

#### **BACKGROUND AND HISTORY:**

The current owners bought the site in the 1990s and after repairing the main house, which is now their family home, they turned their attention to the derelict outbuilding in the garden. This is actually the standing remains of a 13th century rectory incorporating a reset 12th century doorway along with later alterations. It is a very rare surviving example of a medieval secular building in this part of Yorkshire. Used as an agricultural building from the 18th century onwards, the roof was removed in c1970 and the condition of the building deteriorated over the next four decades. Without a roof to protect the fabric from the elements and to tie the walls together the structure was vulnerable. By the time it was added to the Heritage at Risk Register most of the east wall had collapsed, the west wall was bulging and cracking and the inserted south gable was unstable, having very little connection to the adjacent walls. Following a period of

investigation, survey and recording funded by the LEADER programme, English Heritage was able to offer a grant for repair in 2013. This, together with funding from the owners, was used to re-roof the structure and make it wind and watertight and structurally sound.

IN YORKSHIRE THERE ARE...

BUILDINGS & STRUCTURES

98

PLACES OF WORSHIP

#### IS IT AT RISK?

No, having first been placed on the Buildings at Risk Register in 1998 and the Heritage at Risk Register in 2008 the building has recently undergone a programme of extensive recording and repair funded by English Heritage, the LEADER programme and the building's owners. It was removed from the Heritage at Risk Register in 2014.

#### WHAT'S THE CURRENT SITUATION?

With grant funding the building was made wind and watertight and structurally sound, but the owners, Tim and Amanda Harding, have gone the extra mile to make the building usable and to secure its long term future. They have learned how to mix and work with lime mortar to re-point the internal walls. They have rebuilt part of the first floor to increase the amount of useful internal space. They have broken up a defective 20th century concrete floor and cleaned hundreds of reclaimed bricks to repair an earlier brick and cobble floor hidden beneath the concrete. They have dug a soak away to drain the site and have now turned their attention to the setting of the building and are recreating a medieval garden in the area where the construction site compound was located. The newly repaired building will be used by the owners and the local community for a variety of uses and events beginning with an official opening timed to coincide with Heritage Open Days 2014.

#### **HELP HISTORIC BUILDINGS**

Historic buildings are irreplaceable; they give us our sense of place and contribute to our quality of life. These precious buildings need to be looked after for future generations, but how do we know what needs our help the most? English Heritage is encouraging community groups, volunteers, building owners and local authorities across the country to come together to record the condition of grade II listed buildings in their area. Volunteers will visit a selection of grade II buildings local to them and answer questions, in the form of a survey, about the condition of the building. This information will be collected together and shared with local planning authorities to help identify those grade II buildings most at risk. Visit www.english-heritage.org.uk/helphistoricbuildings to find out more.

### FOR MORE INFORMATION CONTACT:

Craig McHugh English Heritage Yorkshire 37 Tanner Row York YOI 6WP

Telephone: 01904 601 901

Email: yorkshire@ english-heritage.org.uk



#### ROCKLEY ENGINE HOUSE AND BLAST FURNACE, BARNSLEY, SOUTH YORKSHIRE

#### **BACKGROUND AND HISTORY:**

Iron has been produced in England from at least 500 BC and in South Yorkshire the iron industry has played a major part in the history of the county with its importance peaking in the industrial revolution. With its fast flowing rivers and naturally occurring coal and iron ore, the county became a hub of

metal working in England.

The Blast Furnace at Rockley is a well preserved upstanding structure. Documentary evidence suggests that the furnace was constructed in 1652 by Lionel Copley of Rotherham in order to replace a bloomery which stood close to the site.

The Engine House is constructed of sandstone and stands to its full height and dates from 1813. The Engine House was built to house a Newcomen Engine showing how the improvements in technology were added to existing sites to increase and improve productivity. This engine has since been removed.

Together these monuments provide a fascinating insight into the development and changing needs of the iron industry from the 17th to 19th centuries.

In 1957 the Sheffield Trades Historical Society purchased Rockley Engine House from the Wentworth Estate. This society later became the South Yorkshire Industrial History Society (SYIHS). They have managed the monument since.

#### IS IT AT RISK?

No, both the Blast Furnace and Engine House have been removed from the Heritage at Risk Register in 2014 thanks to the partnership working of SYIHS, the East Peak Innovation Partnership and grant aid from LEADER and English Heritage. Both monuments were on the Heritage at Risk Register from 2012-2013. They were suffering from structural problems caused by plant growth. There was also evidence of antisocial behaviour in and around the site.

In 2010, The East Peak Innovation Partnership embarked on a project to promote the work of local groups in securing the long term sustainability of Industrial Heritage in the East Peak. Part of this project was the identification of monuments at risk and their repair.

#### WHAT'S THE CURRENT SITUATION?

Both the Furnace and Engine House are now fully consolidated and a management programme has been drawn up and agreed with the SYIHS to ensure that the monuments are regularly maintained. Not only will the monuments continue to be managed, but also the surrounding woodland will be managed to prevent any further encroachment onto the scheduled monuments. The site is fully open to the public and longer term plans include interpretation of the site to improve public understanding of this important piece of Yorkshire's industrial heritage.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# THE REGISTER Content and criteria

#### DESIGNATION Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets (http://list.english-heritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s planning acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a neverending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

#### LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are almost 376,000 listed entries on the statutory list of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

#### SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,833 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

#### REGISTERED PARKS AND GARDENS

There are 1,628 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls,

but there is a clear presumption in favour of upholding their significance in government planning guidance. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

#### REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the *Register of Historic Battlefields* for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy.

#### PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

#### **CONSERVATION AREAS**

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,848 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

# Criteria for inclusion on the Register

#### RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

#### **BUILDINGS AND STRUCTURES**

Buildings or structures (not in use as public places of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from very bad to poor, fair and (occasionally) good reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

#### PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in very bad or poor condition it is added to the Register.

English Heritage has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

#### **ARCHAEOLOGY**

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

#### PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

#### **BATTLEFIELDS**

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure - for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of factors can be enough to raise the risk of a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

#### WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

#### **CONSERVATION AREAS**

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, are defined as being at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

#### Reducing the risks

English Heritage is working to secure a reduction in the number of heritage sites at risk as part of our contribution to the National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Despite the challenge, given the number of entries on the Register and the different kinds of risk they face, excellent progress is being made.

The published Heritage at Risk National Strategy (www.english-heritage.org.uk/publications/eh-har-strategy-2011-15) sets out how this will be delivered through our dedicated Heritage at Risk teams in each local office. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Resolving cases requires working in close partnership with owners, local planning authorities and a wide variety of other relevant organisations. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including: new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk. Key publications and guidance are listed on pages XIV-XV.

Historic Environment Records and local heritage at risk registers, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

#### **BUILDINGS AND STRUCTURES**

Our nine local teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. We can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. Our own principal grant stream for buildings and structures is the Historic Buildings, Monuments and Designed Landscapes (HBMDL) grant but Section 17 Management Agreements can also be used to tackle risk to scheduled monuments. More information on funding can be found at www.english-heritage.org.uk/professional/funding.

We know from our own Register how useful it is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities and voluntary groups to enable them to compile local heritage at risk registers and develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers. Our Heritage at Risk Legal Adviser can support local authorities considering enforcement action and we have published guidance at www.englishheritage.org.uk/publications/stoppingtherot. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the Architectural Heritage Fund and fund their regional support officers to work across the county. They help BPTs and other not-for-profit organisations access funding, carry out feasibility studies and develop solutions for buildings at risk. For more information on support officers and BPTs visit www.ahfund.org.uk and www.ukapt.org.uk. Guidance and case studies can be found at www.english-heritage.org.uk/publications/pillars-of-the-community.

English Heritage also funds an Industrial Heritage Support Officer to work with groups running industrial heritage sites. For more information please visit www.industrialheritagesupport.wordpress.com.

#### PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the new Grants for Places of Worship scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

#### **ARCHAEOLOGY**

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites. The large majority (84%) of the 19,832 scheduled

monuments in England (in 2013) are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This will be especially important with the New Environmental Land Management Scheme (NELMS) which commences in 2015. Natural England now shares our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. Reporting in late 2013, however, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for 1587 sites on the Register, and features bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in a significant number of removals from the 2013 Register.

Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

#### PARKS AND GARDENS

Although a statutory list, the *Register of Historic Parks Gardens of Special Historic Interest in England* in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's *National Planning Policy Framework* (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the *Register of Historic Parks and Gardens of Special Historic Interest* and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens.

#### **BATTLEFIELDS**

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II\* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' understanding of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

#### **WRECK SITES**

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require

significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from www.helm.org.uk

#### CONSERVATION AREAS

The risks to conservation areas are difficult to address as these designated areas can constitute large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage them or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improve-your-neighbourhood.

#### Key statistics

#### **BUILDINGS AND STRUCTURES**

- Nationally, 4.0% of grade I and II\* listed buildings (excluding places of worship) are on the Register. In Yorkshire the percentage is 6.2% (99 listed secular buildings).
- 5 building or structure entries have been removed from the 2013 Yorkshire Register because their futures have been secured, and 8 have been added.
- 63.1% of buildings or structures (111) on the Yorkshire baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 59.4%.

#### PLACES OF WORSHIP

- Nationally, 6.0% of listed places of worship are on the Register. In Yorkshire, 7.1% (98) are on the Register.
- 18 places of worship have been removed from the Yorkshire Register following repair work, and 47 have been added.

#### **ARCHAEOLOGY**

- 3,012 (15.2%) of England's 19,833 scheduled monuments are on the Register. 515 (19.6%) of Yorkshire's 2,621 scheduled monuments are on the Register.
- 95 archaeology entries have been removed from the 2013 Yorkshire Register for positive reasons, and 14 have been added.
- 37.4% of archaeology entries (271) on the Yorkshire baseline 2009 Register have been removed for positive reasons, compared with the national figure of 29.2%.

 Nationally, damage from arable cultivation is the greatest cause of risk affecting 43% of archaeological entries on the Register. In Yorkshire the proportion is 60%.

#### PARKS AND GARDENS

- 93 (5.7%) of England's 1,628 registered parks and gardens are on the Register. Of the 120 registered parks and gardens in Yorkshire, 13 (10.8%) are on the Register.
- I park and garden entry has been removed from the 2013 Yorkshire Register for a positive reason.

#### **BATTLEFIELDS**

• Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. Of the 7 registered battlefields in Yorkshire, 3 (42.9%) are on the Register.

#### WRECK SITES

 Of the 49 protected wreck sites around England's coast, 4 are on the Register. Yorkshire's single protected wreck site is not on the Register.

#### **CONSERVATION AREAS**

- 8,206 of England's 9,848 conservation areas have been surveyed by local authorities and 497 (6.1%) are on the Register. Of the 912 conservation areas in the Yorkshire, 858 have been surveyed and 61 (7.1%) are on the Register.
- 3 conservation areas have been removed from the 2013 Yorkshire Register for positive reasons, and 9 have been added.

#### **ENGLISH HERITAGE FUNDING**

• £892,000 in grant was spent on 67 entries on the Yorkshire Register during 2013/14.

Risk assessments of heritage assets are based on the nature of the site. Building and structure assessments include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – English Heritage Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

English Heritage's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2014 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2014 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database:

#### www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/professional/protection.

#### CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications and www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation — revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012—2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

#### Key to the entries

This Register includes the following risk assessment types

Building or structure
 (grade I and II\* listed buildings and structural scheduled monuments)

 Place of worship (grade I, II\* and II listed buildings)

Archaeology
 (scheduled monuments – earthworks and buried archaeology)

Park and garden
 (Registered parks and gardens)

 Battlefield (Registered battlefields)

 Conservation area (Conservation areas)

#### **ORDER**

Entries are grouped and ordered alphabetically, first by County† (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

†The metropolitan counties of South Yorkshire and West Yorkshire are used to group the data. North Yorkshire is the only two tier planning authority in the region.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

#### **DESIGNATION**

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II\*
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

#### CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens and battlefields) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields and conservation areas, vulnerability is noted as high, medium or low.

#### PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

For **battlefields**, the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

2013 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

#### **TREND**

Trend for archaeology entries, parks and gardens and battlefields may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

#### CONTACT

This is the member of the English Heritage local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

CA Conservation Area EH English Heritage

HLF Heritage Lottery Fund

LB Listed Building

LPA Local Planning Authority

NP National Park

RPG Registered Park and Garden

SM Scheduled Monument UA Unitary Authority

WHS World Heritage Site

#### Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
CUMBRIA							
Yorkshire Dales (NP)	1	0	0	0	0	0	ı
EAST RIDING OF YORKSHII	RE (UA)						
East Riding of Yorkshire (UA)	7	11	159	2	I	0	2
KINGSTON UPON HULL, C	ITY OF (UA)						
Kingston upon Hull, City of (UA)	0	2	0	0	0	0	2
NORTH EAST LINCOLNSHI	RE (UA)						
North East Lincolnshire (UA)	2	0	2	0	0	0	7
NORTH LINCOLNSHIRE (U	A)						
North Lincolnshire (UA)	2	1	13	0	0	0	2
NORTH YORKSHIRE							
Craven	1	4	0	0	0	0	0
Hambleton	4	7	18	0	0	0	C
Harrogate	8	1	9	3	I	0	C
North York Moors (NP)	6	0	70	0	0	0	C
Richmondshire	7	2	12	0	0	0	C
Ryedale	12	6	96	2	0	0	C
Scarborough	0	3	18	I	0	0	4
Selby	4	4	19	0	0	0	C
Yorkshire Dales (NP)	4	1	5	0	0	0	3
SOUTH YORKSHIRE					I	1	
Barnsley	4	2	6	0	0	0	2
Doncaster	2	6	14	0	0	0	$\epsilon$
Peak District (NP)	0	0	3	0	0	0	C
Rotherham	5	2	9	0	0	0	3
Sheffield	5	3	6	2	0	0	5
WEST YORKSHIRE					I	1	
Bradford	6	11	7	I	0	0	- 11
Bradford / Kirklees / Leeds <sup>†</sup>	0	0	0	0	I	0	C
Calderdale	12	6	4	0	0	0	3
Kirklees	7	13	4	0	0	0	4
Leeds		7	6	2	0	0	4
Leeds / Selby <sup>†</sup>	0	0	2	0	0	0	C
Peak District (NP)	0	0	0	0	0	0	C
Wakefield	4	4	5	0	0	0	C
YORK (UA)							
York (UA)	0	3	0	0	0	0	2
TOTAL	114	99	487	13	3	0	61

 $<sup>^{\</sup>dagger}$  Sites that cross local planning authority boundaries

#### **CUMBRIA**

© English Heritage

#### YORKSHIRE DALES (NP)



High Hall Farmhouse including SITE NAME:

cartshed, Dent, South Lakeland

DESIGNATION: Listed Building grade II\*

CONDITION: Very bad

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: A (A) OWNER TYPE: Private

LIST ENTRY NUMBER: 1383893

C17 farmhouse once owned by Richard Trotter who led the Dent "statesmen" to purchase the manor of Dent from the crown in 1670. Partially derelict and collapsing.

Contact: Giles Proctor 01904 601981

SITE NAME:	Farfield Mill (Sedbergh), Sedbergh, South Lakeland		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Robert White (LPA) 01969 652360

#### EAST RIDING OF YORKSHIRE (UA)



© English Heritage Archive

SITE NAME: Flamborough Castle, Tower Street, Flamborough Scheduled Monument and Listed DESIGNATION:

Building grade II, LB grade II, CA CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER:

LIST ENTRY NUMBER: 1014896 and 1083401 Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

Contact: Jenny Lee 01904 601933



© English Heritage

SITE NAME: Boat hoist on south side of south dock, Bridge Street, Goole DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Commercial company

1083214

Boat hoist of c1862 invented by WH Bartholomew to transfer coal from canal compartment boats, known locally as 'Tom Puddings', into seagoing vessels. The compartment boats were raised hydraulically and tipped to empty their contents down a chute and into the hold of the waiting vessel. There were originally five of these hoists, which were peculiar to Goole; this is the last remaining example. Refurbishment works were carried out in the late 1990s but the condition of the structure has since deteriorated.

Contact: Zoe Kemp 01904 601911



© English Heritage

SITE NAME: Gates, gate piers, flanking walls and abutments, Londesborough Listed Building grade I, RPG DESIGNATION: grade II\*, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1310607

Gateway, 1660-70, probably by Robert Hooke, forming the principal entrance to Londesborough Park. The caps of the gate piers are deteriorating and trees are growing from the joints. The ball finials have fallen.

Contact: Nicola Brown 01904 601985

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Paull Holme Tower, Thorngumbald Road, Paull
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (B)

Private

1007875 and 1366242

1007751 and 1083773

1019825 and 1103364

Mid C15 three storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871; roofless since the early C20 and suffering from longterm neglect. An options appraisal has been carried out and urgent propping has been undertaken. Grant offered towards project development for full consolidation.

Contact: Giles Proctor 01904 601981

	Y	
B. T	T IZ	

© English Heritage Archive

SITE NAME:	Outbuildings to Watton Abbey, Church Lane, Watton
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and ruinous. A feasibility study has been carried out and funding identified for repair and re-roofing. Project development has commenced.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Haltemprice Priory Farmhouse, Abbey Lane, Willerby
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE	Privata

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and C16 fabric. In a very advanced state of decay. Proposals for repair and residential re-use are in preparation.



© English Heritage

SITE NAME:	Wressle Castle, Breighton Road, Wressle
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s. Repairs are underway with grant from Natural England and English Heritage for separate phases of work.

OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1005210 and 1083170

Contact: Giles Proctor 01904 601981

Contact: Craig McHugh 01904 601972



© English Heritage

SITE NAME:	Church of St Mary, Cowlam Lane, Cowlam, Cottam
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1083789

Small church of 1853, apparently by Miss Sykes of Sledmere, unusually located in a farmyard. The roofs are in poor condition and the stonework is deteriorating.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Mary, Driffield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1083376

CI2 church with CI5 west tower, restored by Temple Moore in 1889. Tower roof and stonework in poor condition, some structural movement, glazing and drainage issues. Grant offered in December 2012 under Repair Grants for Places of Worship and work has started on site.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

© English Heritage



SITE NAME:	Church of All Saints, Main Street, Aughton, Ellerton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1346742

Medieval village church, associated with the Pilgrimage of Grace. Generally in good condition, but with some structural movement to the top of the tower.

© English Heritage



SITE NAME:	Church of St Martin, Fangfoss
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1083833

Church with C12 origins, partially rebuilt in 1849-50 by Chantrell. Masonry and drainage in poor condition, localised issues with roofs, glazing and internal finishes. Grant offered in December 2012 under Repair Grants for Places of Worship and repairs underway.

Contact: Giles Proctor 01904 601981

© English Heritage



SITE NAME:	Church of St Mary, The Green, Full Sutton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1083836

A small medieval church. The calcareous sandstone of the walls is eroding and the roof is in poor condition.

© English Heritage



SITE NAME:	Church of St John, Church Street, Goole
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1083215

An early Victorian church, dominating the skyline of Goole. The stonework to the upper part of the central tower is eroding and the roofs are in poor condition.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

© English Heritage

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:



© English Heritage

© English Heritage

SITE NAME:	Church of St Augustine, Church Lane, Hedon
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)

Religious organisation

Large medieval church, C13-C15. The central tower dominates the town. A programme of repairs over the years has addressed many issues, but parts of the building are still in poor repair, including the north transept and nave aisles.

Contact: Giles Proctor 01904 601981

1.1		1./1
0)		
t litt.	TO	למל ול ב

SITE NAME:	Holme Hall Chapel, Holme upon Spalding Moor
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1346568

Roman Catholic chapel attached to country house. The chapel was built in 1766, probably by Carr of York, and has a fine classical interior. The exterior is very modest. The roof covering is failing and there is water damage to the plasterwork.

LIST ENTRY NUMBER: 1083338 Contact: Giles Proctor 01904 601981



SITE NAME:
Church of St Mary, Church
Lane, Hook

DESIGNATION:
Listed Place of Worship grade II\*

CONDITION:
Poor

PRIORITY CATEGORY:
C (New entry)

OWNER TYPE:
Religious organisation

LIST ENTRY NUMBER:
1160360

Small medieval church. The roof coverings are in poor condition and there is some deterioration of the stonework.

Contact: Giles Proctor 01904 601981

© English Heritage

4	4		
			NAME OF TAXABLE
		- AR	
	NAME .	-0	4

©	English	Heritage

SITE NAME:	Church of All Saints, Shiptonthorpe
designation:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1310431

A small medieval church. The tower was repaired a few years ago, but the roofs are in poor condition. The lower stonework is open-jointed, with decayed stone in the gables.

Parish church with elements dating to the C13. Roofs and rainwater goods in poor condition. Grant offered in December 2012 under Repair Grants for Places of

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Church of St Mary, Main Street, Welwick
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1366256

Worship and repairs have commenced.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental and first a good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Gar

RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bewick Hall moated site, Aldbrough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007848
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Rectilinear enclosures, Barmby Moor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005209
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Four round barrows 780m north east of Littlewoo	d Lodge, Bishop Bu	rton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007563
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 900m north east of Littlewood Lod	ge, Bishop Burton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007440
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 1000m north east of Littlewood Lo	dge, Bishop Burton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007572
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Three round barrows 800m north east of Littlewo	od Lodge, Bishop B	Surton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007573
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Five round barrows 700m north east of Littlewood	I Lodge, Bishop Bur	rton / Newbald
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007401
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 400m north east of Wold Farm, Bis	hop Wilton Wold,	Bishop Wilton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008344
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

	TOTAL PLANT RIBING OF FORGINE (OA)		
SITE NAME:	Round barrow south east of Cot Nab Farm, Bishop	Wilton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Site of Archbishop's moated palace and fishponds,	Hall Garth, Bishop	Wilton
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1009383
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Romano-British villa at Cockle Pits, near Brantingh	am, Brantingham	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014736
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Bowl barrow, 500m south of Buckton Barn, Bridlin	gton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013624
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Moated site at North Park Farm, Burstwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008047
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Wharram Hill embankment cross, Burton Agnes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005199
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Site revealed by aerial photography north west of	Argam Cottages, Bu	urton Fleming
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005211
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 200m west of Crest Cottages, Carna	by	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007733
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

	A CONTROL OF TOTAL CONTROL (CAY)		
SITE NAME:	Iron Age square barrow cemetery on Haisthorpe I Agnes	Moor, 750m WNW	of Demming Farm, Carnaby / Burto
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013706
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Moated site and two fishponds 80m south west of	Parkhouse Farm, C	herry Burton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007842
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow 300m south west of High Gardham	Farm, Cherry Burt	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007726
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 430m north west of High Gardham	Farm, Cherry Burt	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012121
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 430m north west of High Gardham	Farm, Cherry Burt	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007727
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 700m west of High Gardham Farm,	Cherry Burton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007728
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Seven round barrows 530m west of High Gardham	n Farm, Cherry Bur	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012187
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows 600m north west of High Gar	dham Farm, Cherry	y Burton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008785
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Round barrow 700m north east of Collingwood Fa	ırm, Cottam	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007861
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Linear earthwork north east of Collingwood Farm,	, Cottam / Sledmere	2
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007862
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Baynard Castle, Cottingham		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1019823
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Money Hill round barrow, Dalton Holme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007923
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Site of deserted village of Grimston, East Garton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021241
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Motte and bailey castle, fishpond and moated site r	north and east of A	ughton church, Ellerton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007973
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bolton Old Hall moated site, Fangfoss		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008045
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OVA/NIED TYPE	Private	CONTACT:	Tammy Whitaker 01904 601880
OWNER TYPE:	Tilvate		Tailing VVIIItakei 01704 001000

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

TENTINGE / CT TUSIC 2011 / TO	MOTINE / EAST MIDING OF FORMSTIME (OA)		
SITE NAME:	Bowl barrow 150m NNE of Towthorpe H	ligh Barn, Fimber	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013702
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bowl barrow, 150m south east of Towtho	orpe Reservoir, Fimber	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013703
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Settlement at Blealands Nook, Fimber / Sle	edmere / Wetwang	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005205
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 350m south east of Low Fa	arm, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007852
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 400m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007856
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 420m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007857
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 440m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007854
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 450m south west of Low F	arm, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007853
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Round barrow 500m south east of Low Farm	n, Garton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008810
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 500m south of Low Farm, Ga	rton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009394
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 700m south of Low Farm, Ga	rton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007850
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 700m south of Low Farm, Ga	rton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007855
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 750m south of Low Farm, Ga	rton	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007851
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Linear earthwork running from the head of V settlement site, Garton / Sledmere / Wetwar	Varren Dale towards Slee	dmere Field Farm and associated
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007736
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 230m south west of Enthorpe I	House, Goodmanham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012835
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
	Bowl barrow 550m south west of Enthorpe I	House, Goodmanham	
SITE NAME:	•		
	Scheduled Monument	LIST ENTRY NUMBER:	1008923
DESIGNATION:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER: TREND:	1008923 Declining
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:			

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Bowl barrow 700m south west of Enthorpe	e House, Goodmanham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008922
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 1000m north east of Goodma	anham Wold Farm, Goodm	anham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008934
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 730m NNW of Goodmanha	am Wold Farm, Goodmanh	am
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007328
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Twelve bowl barrows 800m north of Good	dmanham Wold Farm, Goo	dmanham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007642
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Romano-British villa east of Sandy Lane, 80	0m north west of Harpham	Grange, Harpham
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013628
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Park Closes moated lodge, 130m south we	st of Park Farm, Holme upo	on Spalding Moor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015311
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 230m south west of High Bar	n Farm, Huggate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013464
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 400m NNW of East Greenw	ick Farm, Huggate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014727
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
FRINCIPAL VOLINERABILITY:	7 trable ploagring		. , , ,
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

TERT / GE / CT TGSK 2011 / TG	TRANSFIRE / EAST RIBITO OF FORROSTIRE (GA)		
SITE NAME:	Bowl barrow 780m north east of Waterm	anhole Reservoir, Huggate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013864
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bowl barrow on Huggate Pasture, 350m n	orth east of Pasture Dale Pl	antation, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013868
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Pasture, 450m N	NNE of Pasture Dale Plantat	on, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Pasture, 500m n	orth of Pasture Dale Plantat	ion, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013866
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 400m NN	NW of Watermanhole Rese	rvoir, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013861
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 460m WI	NW of western corner of H	Iorsedale Plantation, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013858
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bowl barrow on Huggate Wold, 480m no	rth of Watermanhole Reser	voir, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013862
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 500m NN	NW of Horsedale Plantation	, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013854
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Bowl barrow on Huggate Wold, 580m nor	rth west of Horsedale Planta	ation, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013857
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 600m NN	NW of Horsedale Plantation	, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013853
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 600m we	st of Horsedale Plantation, I	Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013859
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 700m NN	NW of Watermanhole Rese	rvoir, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013863
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 700m no	rth west of Horsedale Planta	ation, Huggate
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013856
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow on Huggate Wold, 840m EN	E of Watermanhole Reserv	oir, Huggate
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 240m south west of High B	Barn Farm, Huggate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012491
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 320m south west of High B	Barn Farm, Huggate	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012479
	Extensive significant problems	TREND:	Declining
CONDITION:	Extensive significant problems		D celli lili 6
CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	·		

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Scheduled Monument LETOTOTYNUMBOL 1012493  EXERCISE Scheduled Monument LETOTOTYNUMBOL 1012493  EXERCISE ALL STREET SCHEDULES STATES AND LECTRINGS TERRORS Declining  RESIDENCE AND LETOTOTYNUMBOL 1012493  EXERCISE ALL STREET SCHEDULES SCH	TERMIT NO ETT I MORE ZOTT I TOT	TOTAL POT HOUSE OF TOTAL (OF)		
Extensive significant problems   TRIND   Declining   No   Declining   Declini	SITE NAME:	Round barrow 360m south west of High Barn Farr	n, Huggate	
Arable ploughting Now INTER: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012493
ROWART TYPE ROUND BATTON SOME SOUTH WEST OF High Barn Farm, Huggate  STEAMANN Scheduled Monument Extensive significant problems RECEIONATION Extensive significant problems RECEIONATION Private ROUND BATTON ROUND ROUN	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow 380m south west of High Barn Farm, Huggate  Scheduled Monument  Extensive significant problems  Arable ploughing  Private  CONTACT:  Benny Lee 01904 601933  Declining  New PHINTY  No  ONNASTIVE  Round barrow 390m south west of High Barn Farm, Huggate  Section Of a single and double linear boundary dyke in Cow Tact:  Private  CONTACT:  Private  CONTACT:  Private  Scheduled Monument  Extensive significant problems  Section of a single and double linear boundary dyke in Cow Tact:  DECIDION  Scheduled Monument  CONTACT:  Private  CONTACT	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTER NUMBER 1012505  CONDITION Extensive significant problems TRADE Declining  REMISCIAL VILLERABELITY Arable ploughing New MITETY NO  CONDITION Physics Control of the plant of	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems TREND: Declining  Arable ploughing New YNINET  Private CONTACT: Jenny Lee 01904 601933  SILENAME: Round barrow 390m south west of High Barn Farm, Huggate  SPERIALISM Scheduled Monument  Extensive significant problems  Exten	SITE NAME:	Round barrow 380m south west of High Barn Farr	n, Huggate	
Arable ploughing New York TYPE. Private CONTACT: Jenny Lee 01904 601933  JET NAME: Round barrow 390m south west of High Barn Farm, Huggate  Scheduled Monument UST ENTRY NAMER: No Declining  RINGORAL VULKEABULTY: Arable ploughing NEW ENTRY: No CONTACT: Jenny Lee 01904 601933  JET NAME: Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale Part Northfield Farm, Huggate  Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate  Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION Sections of linear boundary dyke in Cow Dale Plantation, Rabbit D	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012505
Private Private Private CONTACT: Jenny Lee 01904 601933  STE NAME: ROund barrow 390m south west of High Barn Farm, Huggate  SCHOOLDION Extensive significant problems Private Declining  SCHOOLDION Extensive significant problems Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private Description  SCHOOLDION Generally satisfactory but with significant localised Private School Monument School Monument Description  SCHOOLDION Generally satisfactory but with significant localised Private School Monument School Monumen	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow 390m south west of High Barn Farm, Huggate  2550RAFION Scheduled Monument  2561 Extensive significant problems  2570 Extensive significant problem	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012489  Declining  Arable ploughing NEW PRIVATE  Private CONTROL  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015566  CONDITION: Generally satisfactory but with significant localised problems  Private North Private North Control  CONTROL  Private North Private North Private  Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015569  TRENCIPAL VILLIANTERBUILTY: A rable clipping NEW Private UST ENTRY NUMBER: 1015569  TRENCIPAL VILLIANTERBUILTY: A rable ploughing NEW PRIVATE NORTH NORTH NUMBER: 1015569  TRENCIPAL VILLIANTERBUILTY: A rable ploughing NEW PRIVATE NORTH NUMBER: 1015569  DECIDING NEW PRIVATE NORTH NUMBER: 1015569  TRENCIPAL VILLIANTERBUILTY: A rable ploughing NEW PRIVATE NORTH NUMBER: 1015569  DEVELOPMENT OF PRIVATE CONTROL  SECTION OF Innear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015570  DECIDING NUMBER TYPE: Private CONTROL: Jenny Lee 01904 601933  DEVELOPMENT OF PRIVATE NUMBER: 1015570  DECIDING NUMBER TYPE: Private CONTROL: Jenny Lee 01904 601933  DEVELOPMENT NUMBER: 1015570  DECIDING NUMBER TYPE: Private LIBERT NUMBER: 1013855  DECIDING NUMBER TYPE: NO  DECIDING NUMBER: 1007847  DECI	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  Extensive significant problems  New DRIKY:  Arable ploughing  New BRIKY:  No  CONTACT:  Jenny Lee 01904 601933  TREND:  Private  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate  SESSIGNATION:  Scheduled Monument  Generally satisfactory but with significant localised problems  SINCIPAL WULNERABILITY:  Arable clipping  NEW ENTRY:  Private  Section of linear boundary dyke south of Middleham  Plantation and Harper Dale Plantation, Huggate  SESSIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1015569  TREND:  CONTACT:  Tammy Whitaker 01904 601880  TREND:  CONTACT:  Jenny Lee 01904 601933  TREND:  CONTACT:  Jenny Lee 01904 601933	SITE NAME:	Round barrow 390m south west of High Barn Farr	n, Huggate	
Arable ploughing New ENTRY: No DOWNERTYPE Private CONTACT: Jenny Lee 01904 601933  SECTION Of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015566  Generally satisfactory but with significant localised TREND: Stable  Private Private CONTACT: Tammy Whitaker 01904 601880  STENAME: Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER 1015569  CONDITION: Extensive significant problems TREND: Declining  Private CONTACT: Jenny Lee 01904 601830  STENAME: Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015570  DECIDION: Extensive significant problems TREND: Declining  FRENCIPAL VULLIFICABILITY: Arable ploughing List ENTRY NUMBER: 1015570  DECIDION: Extensive significant problems TREND: Declining  FRENCIPAL VULLIFICABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015570  DECIDION: Extensive significant problems TREND: Declining  FRENCIPAL VULLIFICABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013855  DECONDITION: Extensive significant problems TREND: Declining  RENCEPAL VULLIFICABILITY: Arable ploughing NEW ENTRY: No  DECINION: Scheduled Monument UST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007847  DECINION: Scheduled Monument UST ENTRY NUMBER: 1007847  DECINION: Scheduled Monument UST ENTRY NUMBER: 1007847  DECINION: Schedule	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012489
Private Private Contact: Jenny Lee 01904 601933  Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate Designation: Scheduled Monument LISTENTRY NUMBER: 1015566  CONDITION: Generally satisfactory but with significant localised problems  Private Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate Dissipation: Scheduled Monument LISTENTRY NUMBER: 1015569  CONDITION: Scheduled Monument LISTENTRY NUMBER: 1015569  CONDITION: Extensive significant problems TIEND: Declining Remarks Private Control Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate Dissipation: Scheduled Monument LISTENTRY NUMBER: 1015570  CONDITION: Extensive significant problems LISTENTRY NUMBER: 101570  CONDITION: Scheduled Monument LISTENTRY NUMBER: 1015570  CONDITION: Extensive significant problems LISTENTRY NUMBER: 1013855  CONDITION: Extensive significant problems LISTENTRY NUMBER: 1007847  CONDITION: COND	CONDITION:	Extensive significant problems	TREND:	Declining
Private Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate Sessination.  Scheduled Monument LST ENTRY NUMBER: 1015566  CONDITION. Generally satisfactory but with significant localised problems  Private CONTACT: Tammy Whitaker 01904 601880  DETERMINENT VALINERABILITY: Arable clipping NEW ENTRY: No CONTACT: Tammy Whitaker 01904 601880  DETERMINENT SCHEDULE VALINERABILITY: Arable ploughing NEW ENTRY: No Declining New Entry: No CONTACT: Jenny Lee 01904 601933  DETERMINENT SCHEDULE VALINERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Jenny Lee 01904 601933  DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1015570  DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1013855  DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1007847  DESIGNATION: Scheduled M	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Harper Dale, north west of Northfield Farm, Huggate DISIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems DISIGNATION: Arable clipping NEW ENTRY: No DISIGNATION: Arable clipping NEW ENTRY: No DISIGNATION: Arable clipping NEW ENTRY: No DISIGNATION: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: DISIGNATION: Scheduled Monument UST ENTRY NUMBER: DISIGNATION: DESIGNATION: DESIGN	OWNER TYPE:		CONTACT:	Jenny Lee 01904 601933
Scheduled Monument Generally satisfactory but with significant localised problems  New Entry: Arable clipping NEW ENTRY: No DWINER TYPE: Private Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Private Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Private Scheduled Monument UST ENTRY NUMBER: Private No DWINER TYPE: Private Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument UST ENTRY NUMBER: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Private CONTACT: Jenny Lee 01904 601933  TREND: Declining NEW ENTRY: No DWINER TYPE: Private CONTACT: Jenny Lee 01904 601933  TREND: Declining NEW ENTRY: No DWINER TYPE: Private CONTACT: Jenny Lee 01904 601933  TREND: DEClining NEW ENTRY: No DWINER TYPE: Private CONTACT: Jenny Lee 01904 601933  TREND: DEClining NEW ENTRY: No DECLINING SCHEDULE Anable ploughing NEW ENTRY: No DWINER TYPE: Private Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007847  Jenny Lee 01904 601933  TREND: Declining NEW ENTRY: No Declining NEW ENTRY: No Declining NEW ENTRY: No DESIGNATION: DES	SITE NAME:			d the junctions of Holm Dale and
PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No CONTACT: Tammy Whitaker 01904 601880 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015569 DECIDING NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015569 DECIDING NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DECIDING NEW ENTRY?: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1015570 DECIDING NEW ENTRY?: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1015570 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1015570 DECIDING NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DECIDING NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DECIDING NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DECIDING NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1013855 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1007847 LIST ENTRY NUMBER: 1007847 DECIDING NEW ENTRY: No DOWNER TYPE: Private LIST ENTRY NUMBER: 1007847	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015566
Private  Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOS ENTRY NUMBER: No DWNER TYPE: Private  Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LOS	CONDITION:		TREND:	Stable
Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015569  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Scheduled Monument LIST ENTRY NUMBER: No  DESIGNATION: Scheduled Monument LIST ENTRY NU	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1015569  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Sched	OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
Designation: Scheduled Monument LIST ENTRY NUMBER: 1015569  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Sched	SITE NAME:	Section of linear boundary dyke south of Middleha	m Plantation and H	arper Dale Plantation, Huggate
Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  STEND: Stable  PRINCIPAL VULNERABILITY: No  Generally satisfactory but with significant localised problems  SCHENCIPAL VULNERABILITY: No  NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015569
Private Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Scheduled Monument LIST ENTRY NUMBER: No  CONTACT: Stable  PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY): No	CONDITION:	Extensive significant problems	TREND:	Declining
Private Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015570  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Scheduled Monument LIST ENTRY NUMBER: No  CONTACT: Stable  PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY): No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument  LIST ENTRY NUMBER: 1015570  Declining  PRINCIPAL VULNERABILITY: Arable ploughing  Private  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION: Scheduled Monument  Extensive significant problems  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DEWIENTRYP: No  DEWIENTRYP: No  DEWIENTRYP: VILNERABILITY: Jenny Lee 01904 601933  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1007847  CONTACT: Jenny Lee 01904 601933  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: No  Scrub/tree growth  New ENTRYP: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  Extensive significant problems  REMO:  Declining  NEW ENTRYP:  No  CONTACT:  Jenny Lee 01904 601933  EXTENDE:  Description:  Extensive significant problems  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUISIENT NUMBER:  Declining  REMOIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW ENTRYP:  No  CONTACT:  Jenny Lee 01904 601933  EXTENDE:  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  DO7847  Stable  PRINCIPAL VULNERABILITY:  Scrub/tree growth  NEW ENTRYP:  No	SITE NAME:	Sections of linear boundary dyke in Cow Dale Plan	tation, Rabbit Dale	and Oxland Plantation, Huggate
Arable ploughing Private  Private  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate Designation: Scheduled Monument  LIST ENTRY NUMBER: Declining Private  Trend: Declining Private  Declining Private  Contact: Denny Lee 01904 601933  Declining Private  Contact: Denny Lee 01904 601933  Declining Private  Contact: Designation: Designation: Designation: Designation: Designation: Designation: Scheduled Monument Designation: Designat	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015570
Private  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW ENTRYP:  No  CONTACT:  Jenny Lee 01904 601933  Designation:  Designation:  Designation:  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  Jenny Lee 01904 601933  TREND:  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  No  Stable  PRINCIPAL VULNERABILITY:  Scrub/tree growth  NEW ENTRYP:  No	CONDITION:	Extensive significant problems	TREND:	Declining
Private  Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW ENTRYP:  No  CONTACT:  Jenny Lee 01904 601933  Designation:  Designation:  Designation:  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  Jenny Lee 01904 601933  TREND:  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  No  Stable  PRINCIPAL VULNERABILITY:  Scrub/tree growth  NEW ENTRYP:  No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1013855  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  Arable ploughing  Private  CONTACT: Jenny Lee 01904 601933  Site Name: Shaw Fosse moated site, Humbleton  Designation: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth  TREND: Declining  No  Declining  No  CONTACT: Jenny Lee 01904 601933  LIST ENTRY NUMBER: 1007847  TREND: Stable  PRINCIPAL VULNERABILITY: No  No	SITE NAME:	Two bowl barrows on Huggate Wold, 600m north	west of Horsedale	e Plantation, Huggate
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth  NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013855
Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth  New ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Shaw Fosse moated site, Humbleton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Scrub/tree growth  New ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007847  CONDITION: Generally satisfactory but with significant localised problems TREND: Stable  PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	OWNER TYPE:		CONTACT:	Jenny Lee 01904 601933
Generally satisfactory but with significant localised problems  **RINCIPAL VULNERABILITY:** Scrub/tree growth  Generally satisfactory but with significant localised problems  NEW ENTRY?: No	SITE NAME:	Shaw Fosse moated site, Humbleton		
problems problems  PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007847
PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	CONDITION:	Generally satisfactory but with significant localised	TREND:	Stable
•	PRINCIPAL VULNERABILITY:	·	NEW ENTRY?:	No
	OWNER TYPE:	•	CONTACT:	Yvonne Luke 01943 605128

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

	CONTINUE / EAST REDITED OF TORISHINE (OA)		
SITE NAME:	Nunnery Hill and adjacent earthworks, Little Kelk,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005202
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Gallows Hill round barrow, Kilham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016737
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Iron Age barrow cemetery, Kilham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005208
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 350m south east of Fordham Farm,	Kirby Underdale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013165
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 500m south east of Painsthorpe W	old Cottages, Kirby	Underdale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008347
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 850m north east of Wayrham Farm	n, Kirby Underdale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008351
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 900m north east of Wayrham Farm	n, Kirby Underdale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008362
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow south east of South Wold Farm, Ki	rby Underdale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009384
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
	Arable clipping		INO

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Moated site at Metham Hall Farm, Laxton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007972
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Moated site 100m north of Parkhouse Farm, Lecor	nfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008292
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Moated site 310m north east of Scorborough chur	ch, Leconfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015818
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Moated site 550m south east of Scorborough Hall,	Leconfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016250
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Moated site of Leconfield Castle, Leconfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007949
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Hayholme moated site, Leven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008043
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Hall Garth motte and bailey, Lockington		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021289
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Barf Hill moated site, Lockington / Beswick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007717
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Cleaving Hall moated site, Londesborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007817
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 100m north east of High Wold Farm	, Market Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013672
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 110m east of High Wold Farm, Mark	et Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012091
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 200m south east of High Wold Farm	, Market Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012092
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 320m north east of High Wold Farm	, Market Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012090
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 400m south of High Wold Farm, Mar	ket Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012100
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 450m north east of High Wold Farm	, Market Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014256
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

TENTINGE / THISIC 2011 / TOI	(IO) IIILE / EAST RIBITYO OF FORGOTHILE (OA)		
SITE NAME:	Bowl barrow 450m north of High Wold Farm, N	1arket Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012089
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 550m north of High Wold Farm, N	1arket Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012088
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Nine round barrows south east of Arras Cottag	es, Market Weighton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005228
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Six bowl barrows 300m north east of High Wol	d Farm, Market Weigl	hton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007501
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Four bowl barrows 450m south east of High W	old Farm, Market We	ighton / Sancton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012103
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Iron Age barrow group north east of Middleton	on the Wolds, Middle	eton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003597
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 340m south east of Watermanhole	e Reservoir, Millingtor	1
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013865
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Dane's Graves, Nafferton / Kilham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005230
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	' Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Five round barrows 750m south east of Ne	ewbald Lodge, Newbald	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007325
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 400m south west of Newba	ıld Lodge, Newbald	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011654
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 550m south east of Newbal	d Lodge, Newbald	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007320
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 600m south east of Newbal	ld Lodge, Newbald	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007321
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 620m south east of Newbal	ld Lodge, Newbald	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007323
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 700m north east of Littlewo	ood Lodge, Newbald	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007353
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 610m east of Blanch Farm, N	orth Dalton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013460
			1013460 Declining
CONDITION:	Scheduled Monument	LIST ENTRY NUMBER:	
CONDITION: PRINCIPAL VULNERABILITY:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER: TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Private	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Private  Bowl barrow 620m ESE of Blanch Farm, No	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: orth Dalton	Declining No Jenny Lee 01904 601933
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Private  Bowl barrow 620m ESE of Blanch Farm, No. Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: orth Dalton LIST ENTRY NUMBER:	Declining No Jenny Lee 01904 601933
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Scheduled Monument Extensive significant problems Arable ploughing Private  Bowl barrow 620m ESE of Blanch Farm, No Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  orth Dalton LIST ENTRY NUMBER: TREND:	Declining No Jenny Lee 01904 601933  1013461 Declining

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 600m ESE of Blanch Farm, North Dal	ton / Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Paull Point Battery, coastal artillery battery and Sub	omarine Mining Esta	blishment, Paull
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1020425
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Paull Holme moated site and tower, Paull		
DESIGNATION:	Scheduled Monument and Listed Building grade I	LIST ENTRY NUMBER:	1007875 and 1366242
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Giles Proctor 01904 601981
SITE NAME:	Earthwork on the Sheepwalk stretching north from	wold Gate for 53	0yds (480m), Rudston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005223
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Roman villa site, Rudston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005222
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Rudston Beacon and round barrows to east, Rudst	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005231
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 550m south of High Wold Farm, Sand	cton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012102
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Moated monastic grange 300m south west of Wins	etts Farm, Skeffling	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015309
	Extensive significant pueblance	TREND:	Declining
CONDITION:	Extensive significant problems		2 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	·	NEW ENTRY?: CONTACT:	9

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Hallgarth medieval hall and moat, Skipsea		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013705
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Royal Observer Corps underground monitoring po Southfield House, Skipsea	ost and World War	· II visual spotting post, 200m north c
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Skipsea Castle: 11th century motte and bailey castl	e and inland harbou	ır, Skipsea
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011212
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Moated site, fishponds and associated earthworks a	at Manor House, Sk	kirpenbeck
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015614
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
ITE NAME:	Round barrow 1300m east of Life Hill, Sledmere		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007858
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 1400m east of Life Hill, Sledmere		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007859
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 1650m east of Life Hill, Sledmere		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Kings Manor moated site, 450m south of Little Lor	idon, Snaith and Co	owick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015307
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Moated site at St Lois Farm, Sutton upon Derwent		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007818
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Willy Howe round barrow, Thwing / Burton Flemi	ng	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008040
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Hall Garth moated site, associated drainage channe	els and fishpond, Tw	vin Rivers
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013190
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bowl barrow 170m north west of Farberry Garth	Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013471
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 210m south east of Blanch Farm, Wa	rter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013456
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 290m south east of Blanch Farm, Wa	rter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013457
CONDITION:	Extensive significant problems	TREND:	Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing		140
PRINCIPAL VULNERABILITY:  OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 500m east of Blanch Farm, V	Varter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013459
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 560m NNW of Farberry Ga	rth Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013467
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 720m NNW of Farberry Ga	rth Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013466
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 760m NNE of Farberry Gar	th Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013465
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 100m south west of Cobda	ale Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011895
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 400m north west of Cobda	ale Farm, Warter	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012508
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 450m north east of Blanch	Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011906
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 520m south of Warren Far	rm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011890
	Extensive significant problems	TREND:	Declining
CONDITION:	0 1		
CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	· ·	NEW ENTRY?: CONTACT:	

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Round barrow 915m north east of Dalton Gates F	arm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011911
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 930m north east of Dalton Gates F	arm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011910
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Thirty Acres, Warter		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011908
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of linear boundary dyke between Sylvan Da Warter	ale and Warren Far	m, north west of Coldwold Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016191
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Two bowl barrows 300m south east of Blanch Fari	m, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013458
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Two bowl barrows 500m north west of Farberry 0	Garth Farm, Warter	r
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013470
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Two round barrows 820m north east of Dalton G	ates Farm, Warter	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011912
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Haltemprice Augustinian priory, Willerby		
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1019825 and 1103364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Private	CONTACT:	Craig McHugh 01904 601972

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 580m west of High Fordon Farm, Wold Newton			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1007743
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 600m west of High Fordon Farm, Wol		old Newton	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1007742
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Hall Garth moated site south of Beverley Minster,		Woodmansey / Bev	verley
DESIGNATION:	Scheduled Monur	ment, CA	LIST ENTRY NUMBER:	1008122
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Tammy Whitaker 01904 601880
	SITE NAME:	Thwaite Hall, Cottingham		a developed mainly in the 1870s/80s, bu
	DESIGNATION:	Registered Park and Garden grade II, CA	modified in the mid C20 to provide accommodation the University College of Hull. Grounds partly devel- as a botanical garden. Problems with flood damage in	
	CONDITION:	Generally satisfactory but with significant localised problems	and drainage pro lawns around the	blems are affecting mature planting and a lake.
	VULNERABILITY:	High		
	TREND:	Declining		
do the state of th	NEW ENTRY?:	No		
English Heritage	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1000137	Contact: Erika D	iaz Petersen 01904 601901
	SITE NAME:	Londesborough Park,	Gardens laid out	in the late C17 wholly or partly by Rob
		Londesborough		st Lord Burlington, with alterations and third Lord Burlington in the early to mid
出入。	DESIGNATION:	Registered Park and Garden		venues of early C18 date with earlier



© English Heritage

SITE NAME:	Londesborough Park, Londesborough
DESIGNATION:	Registered Park and Garden grade II*, 4 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000924

origins. Kitchen garden of 1730-5 with cascades and entrances aligned with parkland avenues. Extensive parkland requiring more detailed study of historic development of the planting design, key avenues and vistas. Structures in walled garden in state of deterioration.

Contact: Erika Diaz Petersen 01904 601901

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site



© Battlefields Trust

SITE NAME:	Battle of Stamford Bridge, Stamford Bridge
DESIGNATION:	Registered Battlefield
CONDITION:	Generally satisfactory but with minor localised problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1000035

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later C20 and little of the battlefield remains undeveloped.

Contact: Keith Emerick 01904 601988

SITE NAME:	Bridlington Quay, Bridlington		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Malte Klockner (LPA) 01482 393725
SITE NAME:	Goole, East Riding of Yorkshire		
SITE NAME: DESIGNATION:	Goole, East Riding of Yorkshire Conservation Area, LB grade II	NEW ENTRY?:	No
	•	NEW ENTRY?: TREND:	No Deteriorating significantly

#### KINGSTON UPON HULL, CITY OF (UA)



SITE NAME:	St Albans Church, Hall Road
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1382106

Parish church dating to 1938, completed 1954. Constructed from orange brick under a pantile roof. Interior has flat concrete arches. Tower repaired with grant offered in March 2007 under Repair Grants for Places of Worship. Grant offered for recovering the aisle and eastern roofs and work is underway.

Contact: Giles Proctor 01904 601981

© PCC



SITE NAME:	Church of St Charles Borromeo, Jarratt Street, Kingston Upon Hull		
DESIGNATION:	Listed Place of Worship grade II*, CA		
CONDITION:	Fair		
PRIORITY CATEGORY:	F (C)		
OWNER TYPE:	Religious organisation		
LICT ENITRY NILIMBER.	1107722		

Built to the designs of John Earle in 1829, altered and enlarged by JJ Scholes in 1835. Further enlarged between 1894 and 1900 by Smith, Brodrick and Lowther. Roofs and rainwater goods are in poor condition which has led to water ingress that has damaged internal plasterwork and decorations. Some windows and stucco also in poor condition. Repairs are underway with the support of a Heritage Lottery Fund grant.

© English Heritage Contact: Giles Proctor 01904 601981 1197723

SITE NAME:	Beverley Road, Hull		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Philip Hampel (LPA) 01482 612343

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## I PA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	St Andrew's Dock, Hull		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	Philip Hampel (LPA) 01482 612343

#### NORTH EAST LINCOLNSHIRE (UA)



The Grimsby Ice Factory, Gorton Street, Grimsby DESIGNATION: Listed Building grade II\* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1379842

Ice production works dating from 1900-1910 with later additions and alterations. The Ice Factory served the Grimsby fishing fleet, facilitating its development and international renown during the C20. The Factory closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. The loss of roof coverings and the security of openings are of particular concern. The interior, including extensive wooden floors and machinery, has been exposed to increasing levels of weather damage and bird infestation.

© English Heritage

SITE NAME:

Contact: Ben Robinson 01480 412107



Church of Saint Margaret, Barton Street, Hawerby cum Beesby DESIGNATION: Listed Building grade II\* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F)

Former parish church. C12, C13 and C17 with mid C19 restorations. Empty and disused since closed in 1978. Suffering from neglect, with localised collapses of walling. Scaffold propping has been erected. Grant offered and project development phase underway.

© English Heritage Archive

OWNER TYPE: Private LIST ENTRY NUMBER: 1310283

Contact: Giles Proctor 01904 601981

SITE NAME:	Civil War earthwork fort 350m north east of Walk	Farm, Irby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Premonstratensian priory chapel 170m south west	of Priory Farm, We	est Ravendale
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019867
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Central Area, Grimsby		
DESIGNATION:	Conservation Area, 23 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
SITE NAME:	Central Sea Front, Cleethorpes		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Great Coates, Grimsby, Great Coates		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
SITE NAME:	Holme Hill, Grimsby		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
SITE NAME:	Laceby		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
SITE NAME:	Waltham		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
SITE NAME:	Wellow, Grimsby		
DESIGNATION:	Conservation Area, 26 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Conservation Officer 01472 324252
NORTHUNICOLN			

#### NORTH LINCOLNSHIRE (UA)



© English Heritage Archive

SITE NAME:	Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade II*; I grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)

Private

1008528 and 1083709; 1162093

Combined wind and watermill, 1802, by James Middleton of Hibaldstow. Some repairs undertaken, but further work required to both exterior and interior.



© English Heritage Archive

SITE NAME:	Manor Farmhouse, East Halton Road, North Killingholme
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Private

1346854

Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A feasibility study has been completed.

Contact: Ben Robinson 01480 412107

Contact: Ben Robinson 01480 412107

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:



DESIGNATION: PRIORITY CATEGORY:

Church of All Saints, Church Lane, Saxby All Saints

Listed Place of Worship grade II, CA

CONDITION: Fair F(D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1103702 Late C13 church rebuilt in 1845-9 by George Gilbert Scott in the Decorated style, with tower rebuilt by Neville in 1873. Roofs, rainwater goods and high-level masonry in poor condition. Grant offered in March 2013 under Repair Grants for Places of Worship and repairs are underway. A further phase of works is needed to the tower.

Contact: Giles Proctor 01904 601981

©	English	Heritage
---	---------	----------

SITE NAME:	Heavy Anti-aircraft gunsite 220m east of West N	1arsh Cottage, Barrov	w upon Humber
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020024
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Moated site 285m east of Castlethorpe House, E	Broughton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016429
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Yarborough Camp large univallate hillfort, Croxt	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016427
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Money Field Roman site, Dragonby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005224
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Romano-British settlement near Staniwells Farm	, Hibaldstow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005221
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Roman settlement, Kirmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005206
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	MOTINE / NORTH ENGOLISHINE (OA)		
SITE NAME:	Romano-British villa at Mount Pleasant Farm, Kirto	n in Lindsey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013627
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Moated site and fishpond 200m south east of Melto	on Hall, Melton Ros	ss
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007747
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	North Garth moated site and associated enclosure	s, North Killingholr	me
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007815
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Kinaird motte and bailey castle, Owston Ferry		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017556
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Old Winteringham Roman settlement, Winteringha	am	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1005243
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Howe Hill bowl barrow, Wootton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009346
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Roman site 400yds (370m) north east of Worlaby	Church, Worlaby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005233
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 01480 412107
SITE NAME:	Crowle		
designation:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	lan Goldthorpe (LPA) 01724 297396

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Winterton		
DESIGNATION:	Conservation Area, 25 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Goldthorpe (LPA) 01724 297396

#### **NORTH YORKSHIRE**

#### **CRAVEN**



© English Heritage Archive

SITE NAME: Dale End Mills, Dale End, Lothersdale Scheduled Monument, 2 LBs, DESIGNATION: CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1004071

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel, which is Scheduled, is the largest in England and is in poor condition. The mill roofs are deteriorating. The base of the stack is also in need of remedial work. Discussions are underway with the owner to find a solution for the whole complex. The condition of the chimney, wheel and mill building have been assessed in detail.

Contact: Giles Proctor 01904 601981



SITE NAME:

LIST ENTRY NUMBER:

Church of St James, Church Avenue, Clapham cum Newby Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Fair PRIORITY CATEGORY:

F (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1132398

Parish church dating to 1814 with C15 tower and c1900 alterations. Parapets are in poor condition and water ingress has damaged internal finishes. Grant offered in March 2013 under Repair Grants for Places of Worship scheme and work has started.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981



© English Heritage

© English Heritage

SITE NAME: Church of St Mary the Virgin, Kirk Lane, Embsay with Eastby Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation

Gothic village church of 1852-3. The roof slates are failing and the long valley gutter between the slopes is poorly detailed, leading to water penetration.



© English Heritage

LIST ENTRY NUMBER: 1301524 SITE NAME: Church of St Mary the Virgin, Church Street, Long Preston DESIGNATION: CONDITION:

1157818

Listed Place of Worship grade I, Poor PRIORITY CATEGORY: F(D) Religious organisation

Late C14/early C15 parish church with C19 and C20  $\,$ alterations. Chancel restored 1867-68 by Healey of Bradford. Windows by Capronnier of Brussels. Glazing in poor condition and localised roof and masonry issues. Grant offered in December 2012 under Repair Grants for Places of Worship and work on the conservation of the

windows is now underway.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Peter, Church Lane, Rylstone
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1132129

Church of 1852-3 by EG Paley. In generally good condition, but the tower is in need of significant repair - the upper stonework is open-jointed and stone louvres are falling from the west belfry window.

Contact: Giles Proctor 01904 601981

© English Heritage

#### **HAMBLETON**



SITE NAME:	Landmoth Hall, Landmoth-cum- Catto
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Other not for profit group

Part of the east wing of a medieval manor house. Now in an unstable condition. A grant has been offered towards project development for a scheme to consolidate the ruins.

© English Heritage

LIST ENTRY NUMBER: 1013350

Contact: Jenny Lee 01904 601933



SITE NAME:	West Lodge, Thornton Stud, Newsham Road, Newsham w Breckenbrough
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Late C18 lodge and entrance gateway. Some roof repairs were undertaken in Spring 2014.

Castle dated to circa 1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins,

© English Heritage

LIST ENTRY NUMBER: 1150821

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Snape Castle, Snape with Thorp
DESIGNATION:	Scheduled Monument and Listed Building grade I, RPG grade II, part in CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (B)

including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Tammy Whitaker 01904 601880

Programme of works agreed with the owner.

SITE NAME:	Stables at Harlsey Castle
LIST ENTRY NUMBER:	1004908 and 1190147
OWNER TYPE:	Private
	A (D)

Remains of medieval castle keep; in use as farm buildings.



© Hambleton District Council

SITE NAME:	Stables at Harlsey Castle Farmhouse, West Harlsey
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1004183 and 1188946

Contact: Nicola Brown 01904 601985

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise

LPA ΝP 'New entry' is noted. RPG

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Peter, Birkby
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1315131

Church of 1776 with alterations dating to 1872. The roof is in a poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship Scheme.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of All Saints, Town Street, Brandsby-cum-Stearsby
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

Small classical church of 1767-70 by Thomas Atkinson. The domed and arcaded cupola is supported on arcades running across the width of the building internally. Fittings by Temple Moore. The stonework of the cupola is being split by rusting ironwork.

LIST ENTRY NUMBER: 1150750 Contact: Giles Proctor 01904 601981

© English Heritage



SITE NAME:	Church of St Michael and All Angels, Main Street, Cowesby
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1190796

Neo-Norman church of 1846 by Salvin, with central tower. The roofs are in very poor condition and the interior is damp.

© English Heritage



SITE NAME:	Church of St John the Evangelist, Main Street, Dalton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1150818

Church by William Butterfield, 1868. Exterior of stone and slate, but elaborate interior of coloured brick and tile. Morris glass. The rainwater goods are in poor repair and the stonework is in need of repointing.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

© English Heritage



© English Heritage

SITE NAME:	All Saints Church, Cherry Avenue, Newton-on-Ouse
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1190709

Church of 1848 by GT Andrews, incorporating the Norman tower from the previous building. The roofs are in poor condition and some of the stonework is severely eroded. The spire is a local landmark.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Wilfrid, South Kilvington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1241263

Small medieval church, exterior cement rendered. Important C15 font and elaborate furnishings. The render is cracked and detaching and the east wall is suffering from structural movement. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Giles Proctor 01904 601981

© English Heritage



SITE NAME:	Wesleyan Chapel, Church Street, Topcliffe
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

Wesleyan Methodist chapel dated 1840. Roofs are in poor condition. Red brick in Flemish bond, stone dressings, Welsh slate roof.

© English Heritage

LIST ENTRY NUMBER: 1188966 Contact: Zoe Kemp 01904 601911

SITE NAME:	Medieval moated grange 160m south east of The G	Grange, Balk	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015920
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 150m south of Warren House, Brandsby-cum-Stearsby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013601
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 300m east of Warren House, Brandsby-cum-Stearsby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013600
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 300m west of Quarry House, Brandsby-cum-Stearsby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013602
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
	riivate	CONTACT.	Jenny Lee 01704 001733

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Round barrow 450m north east of Hagg Farm, Bra	ndsby-cum-Stearsb	y / Dalby-cum-Skewsby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013592
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Moated site immediately south of Danby Wiske ch	urch, Danby Wiske	with Lazenby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020346
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Deighton moated site, Deighton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004099
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Lime kilns 400m south west of Furlands, Kepwick /	Borrowby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021190
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of cross ridge dyke and earthworks in Rom	nan Plantation, Ouls	ston Moor, Oulston
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1013438
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	A moated site 100m east of St Mary Magdalene's C	Church, Thirsk	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008179
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow known as Gospel Hill, 80m south w	est of Pasture Hou	se, Thornton Watlass
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Maiden Bower and Cock Lodge: a motte and bailey outwork, Topcliffe	castie, moated site	e, windmili mound and associated lineal
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011612
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Three round barrows at Three Hills 500m north e	ast of Camp House	, West Tanfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015764
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Earth circles, cursus, pit alignments and burial sites round barrow, West Tanfield / East Tanfield	near Nosterfield a	nd Thornborough, including Centre Hi
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004912
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Four round barrows on Yearsley Moor 200m south west of High Lions' Lodge, Yearsley		
esignation:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1013446
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow on Yearsley Moor 330m SSW of Hi	gh Lions' Lodge, Ye	earsley
esignation:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1013448
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow on Yearsley Moor 400m south west of High Lions' Lodge, Yearsley		
esignation:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1013447
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
TE NAME:	Two round barrows on Yearsley Moor 550m south	h west of High Lion	ıs' Lodge, Yearsley
DESIGNATION:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1013449
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **HARROGATE**



© English Heritage

SITE NAME: Church of St Mary, Harlow Terrace, Harrogate

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (F)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1149482 Former church built circa 1916 by Sir Walter Tapper. Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. Proposals to convert the church to a new use are under consideration.

Coach house with bee hives. Mid C18 and C16. The rear

hall of the coach house is settling and the end return of the

bee hives is failing. There are structural cracks to the right

hand return and rear, and some of the copings are missing

from the rear gable. Pointing is failing to cut stone on

Contact: Giles Proctor 01904 601981

facades leaving some stone loose.



© Harrogate Borough Council

SITE NAME: Coach house and bee hives approx 10 metres to north of Nutwith Cote, Grewelthorpe Road, Burton-on-Yore

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Part occupied/part in use

Private

PRIORITY CATEGORY: A(A)

OWNER TYPE:

LIST ENTRY NUMBER: 1132066

Contact: Tammy Whitaker 01904 601880



© Harrogate Borough Council

SITE NAME: Outbuilding approx 20m to north of Nutwith Cote, Grewelthorpe Road, Burtonon-Yore DESIGNATION: Listed Building grade II\* CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1316886

LIST ENTRY NUMBER:

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Tammy Whitaker 01904 601880



© Harrogate Borough Council

Temple of Victory with railed enclosure, Allerton Park, Flaxby
Listed Building grade II*, RPG grade II
Fair
Vacant/not in use
C (C)
Charity (heritage)

1315590

Summerhouse or view point, 1790, situated on a knoll in the park, to north west of the house. Re-roofed, cornice repaired and building made secure some years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs needed to stonework below cornice level and to steps and railings. Interior needs to be reinstated. Extensive views from the Temple over the park and surrounding landscape.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

N M		6
	1	
		1

© English Heritage

SITE NAME:	The Old Hall, Middleton Quernhow
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable. Programme of repairs has been agreed.

Contact: Nicola Brown 01904 601985



© Harrogate Borough Council

SITE NAME:	Orangery with flanking walls, botheys and pavilion (Ripley Castle), Ripley
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)

Private 1315394

1005473 and 1150058

Classical Orangery in walled garden with flanking pavilions, circa 1785 by William Belwood. One surviving glasshouse circa 1840, now repaired. Botheys, in poor condition, to rear. East Pavilion repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Tammy Whitaker 01904 601880



SITE NAME:	Butterton Bridge, Sawley
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1004202

Medieval bridge, now crossed by a public footpath. The structure is overgrown and decaying and there is danger of structural collapse. The bridge is now under new ownership.



© Harrogate Borough Council

SITE NAME:	Dob Park Lodge, Dob Park Lane, Weston
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)

Ruins of a C17 park lodge, now roofless structure three storeys high. Scheduled as a monument in 1997. English Heritage has grant-aided emergency works. An archaeological assessment and feasibility study have been produced and a way forward has been agreed.

© English Heritage

CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (F)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1015630	

Contact: Giles Proctor 01904 601981

Contact: Yvonne Luke 01943 605128



© English Heritage

SITE NAME:	Church of St James, Wide Howe Lane, Baldersby
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1296495

Church of 1856 designed in a High Victorian style by William Butterfield for Viscount Downe of Baldersby Park. Constructed from snecked stone with ashlar dressings and a roof of mixed materials. Internally Butterfield's interior remains intact. The roof coverings are in poor repair, leading to some water ingress.

Contact: Giles Proctor 01904 601981

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise ΝP 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Cairnfield, enclosures, boulder walling, hollow way at 370m south east of Crag House, Askwith	and carved rocks t	cowards edge of Snowden Carr centre
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014304
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Henge monument 300m north of Nunwick, Huttor	n Conyers	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012724
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
ITE NAME:	Hutton Hall (site of), Hutton Conyers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004074
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
ITE NAME:	Round barrow 150m east of Burtree Hill, Hutton 0	Conyers	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow in Harland's Plantation, Hutton Cor	nyers	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009785
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
ITE NAME:	Motte and bailey castle, known as Mowbray Castle	, east of Kirkby Ma	lzeard, Kirkby Malzeard
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012994
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Medieval monastic fishponds immediately east of P	ark House, Marking	gton with Wallerthwaite
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Moated site 50m	north west of Red House, Moor	- Monkton		
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1020887	
CONDITION:	Generally unsatis	factory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Drainage/dewate	ering	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Yvonne Luke 01943 605128	
SITE NAME:	Howe Hill motte	and bailey castle, North Deighto	on		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1015541	
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing	g - extensive	NEW ENTRY?:	Yes	
OWNER TYPE:	Private		CONTACT:	Yvonne Luke 01943 605128	
	SITE NAME:	Allerton Park, Allerton Mauleverer with Hopperton / Flaxby	country house, s enlarged in the I	Mid C19 terraced gardens which provide the setting for country house, surrounded by parkland which was enlarged in the 1720s and reworked in the 1770s. C20 woodland planting has significantly changed the characte the historic landscape and a number of listed structures in poor condition.	
	DESIGNATION:	Registered Park and Garden grade II, 19 LBs	the historic lands		
	CONDITION:	Generally unsatisfactory with major localised problems			
	VULNERABILITY:	Medium			
English Heritage	TREND:	Declining			
	NEW ENTRY?:	No			
	OWNER TYPE:	Private, multiple owners			
	LIST ENTRY NUMBER:	1000402	Contact: Erika D	Contact: Erika Diaz Petersen 01904 601901	
	SITE NAME:	Plumpton Rocks, Plompton	Mid C18 pleasure	e grounds laid out with advice from John	
1 1 m	DESIGNATION:	Registered Park and Garden grade II*, 12 LBs, CA	existing park of 0 1798. Landscape	Carr as the grounds for a country house built within a p existing park of C16 origin. Painted by JMW Turner in 1798. Landscape designed around an artificial lake contained by dam, probably designed by John Carr. Lak surrounded by picturesque sandstone outcrops frequer surmounted by trees. Progressive silting of lake and	
	CONDITION:	Generally satisfactory but with significant localised problems	surrounded by p		
	VULNERABILITY:	Medium	regeneration of t	rees and shrubs is severely compromisir	
	TREND:	Declining		the historic views within the site and the relationships planting, rocks and lake. Natural England Higher Level	
	NEW ENTRY?:	No	Stewardship agre		
English Heritage	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1000535	Contact: Erika D	iaz Petersen 01904 601901	



© English Heritage

SITE NAME:	Swinton Castle, Swinton with Warthermarske
DESIGNATION:	Registered Park and Garden grade II*, 6 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001074

Gardens and extensive pleasure grounds with grottos, rustic bridges and rockwork laid out between 1796 and c 1820 under the direction of Adam Mickle the second and others for Sir William Danby, incorporating lakes and landscaping of c1760. The park probably has C17 or earlier origins. A significant proportion of the tree cover has reached maturity and beyond, some structures are in poor condition and water bodies in Quarry Gill woods are heavily silted.

Contact: Erika Diaz Petersen 01904 601901

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument LIST ENTRY NUMBER:



© Battlefields Trust

	,
SITE NAME:	Battle of Boroughbridge, Boroughbridge / Langthorpe / Milby
DESIGNATION:	Registered Battlefield, 2 LBs, part in CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1000003

Thomas Earl of Lancaster's 1322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north of the river.

Contact: Keith Emerick 01904 601988

#### NORTH YORK MOORS (NP)



© English Heritage Archive

SITE NAME:	Ruins of Whorlton Castle Undercroft, Castle Bank, Whorlton, Hambleton	
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I; I grade II*, part in CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (D)	

Private OWNER TYPE:

1007641 and 1151332; LIST ENTRY NUMBER: 1294328; 1189310

C14 castle. Parts of two vaulted chambers remain. English Heritage grant has been offered towards project development for a scheme to convert the adjacent gatehouse into holiday accommodation and this is now well advanced. If the project goes ahead the undercroft will be repaired as part of the scheme.

Contact: Giles Proctor 01904 601981



© English Heritage Archive

SITE NAME:	Whorlton Castle Gatehouse, Castle Bank, Whorlton, Hambleton
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I; I grade II*, part in CA
CONDITION:	Fair

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

1007641 and 1151332; LIST ENTRY NUMBER: 1294328; 1189310

Shell remains of a late C14 gatehouse, which was altered in the C16. Conversion to holiday accommodation, including reroofing, is being considered and English Heritage grant has been offered towards project development, which is now well advanced.



© English Heritage

SITE NAME:	lonic Temple, Duncombe Park Estate, Helmsley, Ryedale
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1149311

Decorative temple, circa 1730, attributed to Vanbrugh, situated at the north end of the approximately 800 metres long, grass East Terrace, approximately 120 metres east of the house. The column shafts are badly decayed. Grant has been offered for repair and work has started.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Tuscan Temple, Duncombe Park Estate, Helmsley, Ryedale
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1295364

Decorative temple circa 1730 in the Palladian style situated at the south end of the East Terrace. The column shafts are badly decayed and internal plasterwork in poor repair. A repair scheme is in preparation and funding has been identified.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Rosedale East Mines: South 'Stone' kilns and North 'Iron' kilns, Rosedale East Side, Ryedale
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private

South 'Stone' kilns; massive rectangular stone structure 90 metres long part of the C19 iron mining complex at Rosedale East. Recent major collapse in several places. North 'Iron' kilns; also a massive rectangular stone structure 90 metres long, partly constructed with wrought iron plates which were removed following abandonment. Recent collapse.

LIST ENTRY NUMBER: 1018981 Contact: Jenny Lee 01904 601933



© English Heritage Archive

SITE NAME:	Ayton Castle, Castle Rise, West Ayton, Scarborough
DESIGNATION:	Scheduled Monument and Listed Building grade I, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. Grant has been offered for a second phase of work and repairs are underway.

LIST ENTRY NUMBER: 1015410 and 1148147 Contact: Giles Proctor 01904 601981

SITE NAME:	Round barrow 550m east of Cam House, Bilsdale Midcable, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Cock Howe round barrow, Bilsdale Midcable / Haw	nby, Hambleton	
SITE NAME:  DESIGNATION:	Cock Howe round barrow, Bilsdale Midcable / Haw Scheduled Monument	nby, Hambleton	1015761
		, ·	1015761 Declining
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	111111111111111111111111111111111111111

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  I ledge repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Pit alignment forming part of the Cleave Dyke system 1000m north west of Dialstone Farm, Boltby, Hambleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010345	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	
SITE NAME:	Pit alignment, part of the Cleave Dyke prehistoric boundary system and round barrow 450m south east of High Paradise, Boltby, Hambleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015576	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Round barrow 400m south east of Hill Fort Windy	pit, Boltby, Hamble	eton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010341	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	
SITE NAME:	Round barrow 500m south east of Hill Fort Windypit, Boltby, Hambleton			
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010342	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	
SITE NAME:	Round barrow 600m north east of South Woods,	Boltby, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013085	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	
SITE NAME:	Round barrow 650m east of South Woods, Boltby, Hambleton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010343	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	
SITE NAME:	Round barrow 350m west of Green Bank, Carlton	, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008856	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880	

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument  Generally satisfactory but with significant localised problems  Vandalism  Private	LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:	1012731 Declining
PRINCIPAL VULNERABILITY:	problems  Vandalism  Private	NEW ENTRY?:	Declining
	Private		
OWNER TYPE:			No
	A - D - 1 - 1 - 0 - A - 11 - 11 -	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Ayton Banks alum works, Great Ayton, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020347
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of the Cleave Dyke system known as Hesketh Dike and Silver Hill round barrow, Hawnby / Old Byland and Scawton / Boltby, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015575
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Kirby Bank Trod, a section of paved trackway extending 400m southwards from just east of The Warren, Kirkby, Hambleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1405913
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 50m north of Snotterdale Plantation	, Whorlton, Hamb	leton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012735
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow at northern edge of Snotterdale Plan	ntation, Whorlton,	Hambleton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012736
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Oxmoor and Givendale Dikes: prehistoric linear boand Yedingham, Ryedale	oundaries and assoc	iated features, Allerston / Ebberston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020834
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  By Slow decay; solution agreed but for tyet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

	RKSHIRE / NORTH YORK MOORS (NP)		
SITE NAME:	Byland Moor round cairns, Byland with Wass, Ryed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Blackpark medieval farmstead 140m south of Black	park Lodge, Cropto	on, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018595
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Round barrow at Blanket Head, 350m north west	of Broad Head Farr	n, Ebberston and Yedingham, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020698
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Blakey Howe round barrow, Farndale East / Rosedale West Side, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018983
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Pike Howe round cairn, Farndale East / Rosedale V	Vest Side, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018986
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Cairnfield 200m east of Hazelshaw House, Hawnby	, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008860
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Cairnfield 500m north east of Bumper Castle, Haw	nby, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009358
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Monastic grange belonging to Rievaulx Abbey at La	skill Farm, Hawnby	, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010340
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow I Im east of Hazel Head Wood, Ha	wnby, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008585
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 150m north east of Silver Hill Farm	, Hawnby, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016052
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 500m east of Silver Hill Farm, Hawnby, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016066
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Three round barrows 500m south west of Far Hou	use, Hawnby, Ryeda	ıle
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1008590
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows at Sour Milk Hills, Hawnby, Ry	yedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008442
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Ana Cross round barrow and wayside cross, Lastin	ngham, Ryedale	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018976
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Four round barrows 320m east of High Pastures, L	ockton, Ryedale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 400m north east of Low Pasture Fa	rm, Lockton, Ryed	ale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021097
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Cross dyke centred 480m south of Fox and Rabbit	Farm, Lockton / T	hornton-le-Dale, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Potato Nab round barrow 1020m south west of Penny Holme, Nawton, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019592
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Scawton Moor, 620m north wes	st of High Lodge, C	old Byland and Scawton, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019824
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Four round barrows 875m north west of High Blar	nsby, Pickering, Rye	edale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020818
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Linear boundary earthwork 370m east of Oscar Pa	ırk Farm, Rievaulx,	Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019340
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Hollins Mine and Bank Top iron calcining kilns, Ros	sedale West Side / S	Spaunton / Lastingham, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018982
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Pry Rigg round barrows, Sproxton, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004086
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Rabbit type 570m south east of Pexton Moor Farm	n, Thornton-le-Dale	, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020675
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 520m north west of St Hilda's Church, Ellerburn, Thornton-le-Dale, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 650m north west of St Hilda's Church, Ellerburn, Thornton-le-Dale, Ryedale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020694
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Warrening enclosure 975m north east of High Pap	er Mill Farm, Thorr	nton-le-Dale, Ryedale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020680
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow in Wykeham Forest, 440m east of J	enny Thrush Spring	, Brompton, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019356
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
	Audiental Laurence de la contraction	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive		140
PRINCIPAL VULNERABILITY:  OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Round barrow known as Hunter Howe, Cloughton	n, Scarborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019770
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow in Raincliffe Woods, 420m north of	Osborne Lodge, Ea	ast Ayton, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021235
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Wheeldale Moor, 1150m west o	of Wheeldale Lodge	, Egton, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021256
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Fyling medieval deer park wall section, Fylingdales, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015542
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 510m north east of Cook House, Fylingdales, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019698
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Site of Stoupe Brow alum works, 210m south east	of Stoupe Bank Far	m, Fylingdales, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow in Springwood Heights Plantation, 220m north west of Springwood Cottage, Hackness, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019620
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Bow decay; solution agreed but for tyet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial lise) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Round barrow on Reasty Hill Top, 550m WSW of	Breckenhurst, Hac	kness, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019561
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow in Harwood Dale Forest known as	Penny Howe, Harw	vood Dale, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round cairn on Cowgate Rigg, 790m south west o	f Teydale Farm, Hai	rwood Dale, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020226
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round cairn on Cowgate Rigg, 870m north of Brooklands Farm, Harwood Dale, Scarborough		ood Dale, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019769
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Moated site at Low Laithes Farm, Whitby Laithes, Hawsker-cum-Stainsacre, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020402
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Saltwick Nab alum quarries, Hawsker-cum-Stainsac	cre, Scarborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017779
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow and 20th century Royal Observer C Beacon, Hinderwell, Scarborough	Corps post on Beaco	on Hill, known as the site of Hinderw
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016956
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

SITE NAME:	Round barrow in School Belt, 1050m north west of	of Jenny Spring, Hutt	on Buscel, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 420m north east of Cook House, L Scarborough	CPs of Fylingdales a	nd Hawsker-cum-Stainsacre,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019701
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows 560m north east of Cook Ho Scarborough	use, LCPs of Fylingo	dales and Hawsker-cum-Stainsacre,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019689
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Medieval dyke known as Green Dike, LCPs of Fylingdales and Hawsker-cum-Stainsacre / Stainton Dale, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020116
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Alum works at Kettleness, Lythe, Scarborough		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1018144
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Brockrigg, 400m east of Brockri	gg Farm, Lythe, Sca	rborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016539
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Cow Hill, 410m south west of S	cratch Alley, Lythe,	Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016538
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

	RSHIRE / NORTH TORK PIOORS (NF) / RICHPIONDSHIRE		
SITE NAME:	Round barrow 920m south west of Silpho Brow Fa	arm, Silpho, Scarbor	ough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019626
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Prehistoric linear boundary and associated features south east of Moorsome Farm, Snainton / Brompto		al monastic grange, north, east and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020836
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Square barrow in Broxa Forest, 285m west of Swa	rth Howe, Suffield-	cum-Everley, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019888
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Square barrow in Broxa Forest, 720m south west	of Surgate Brow Fa	rm, Suffield-cum-Everley, Scarborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019562
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	The Thieves' Dikes: prehistoric linear boundaries and associated features, Suffield-cum-Everley / Silpho, Scarborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019627
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933

#### **RICHMONDSHIRE**



© English Heritage Archive

SITE NAME:	The Old Gatehouse (occupied part), Jervaulx Park, East Witton	
DESIGNATION:	Listed Building grade I, SM	
CONDITION:	Very bad	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1318555	(

The house, known as the Old Gatehouse, was probably constructed from re-used medieval masonry in the C19, on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair. This entry relates to the occupied part of the Gatehouse.

Contact: Nicola Brown 01904 601985

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage Archive

SITE NAME:	The Old Gatehouse
	(unoccupied part), Jervauly
	Park, East Witton

Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; I grade II, LB grade I

CONDITION: Very bad

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1020493 and 1130961; 1130962

The house, known as the Old Gatehouse, was probably constructed from re-used medieval masonry in the C19, on medieval foundations and it is occupied and in fair repair. The western end of the house is built into in situ medieval fabric, which ruinous and in need of repair. This entry relates to the non-occupied ruins of the Gatehouse.

Contact: Nicola Brown 01904 601985

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME: Grotto and Icehouse, Forcett and Carkin Listed Building grade II\*, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1157748

A late C18 Grotto and Icehouse, constructed of cyclopean dry-stone masonry forming three roundish arches. It stands at the head of the lake in Forcett park. The stonework is eroding and stones are becoming loose.



© English Heritage

SITE NAME: Keld Heads lead smeltmill and mine complex, Preston-under-Scar, Preston-under-Scar / Wensley Scheduled Monument and Listed DESIGNATION: Buildings - 2 grade II

CONDITION: Poor

N/A PRIORITY CATEGORY: D(D)


OCCUPANCY:

OWNER TYPE:

OWNER TYPE: Private

LIST ENTRY NUMBER: 1014763 and 1179229; 1130869

The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 and C19. Scrub clearance was undertaken by North Yorkshire County Council volunteers in 2005 to assist with the preparation of survey documents. Options appraisal complete.





© English Heritage Archive

SITE NAME: Ravensworth Castle and park wall, The Green, Ravensworth Scheduled Monument and Listed DESIGNATION: Building grade I, part in LB grade CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

LIST ENTRY NUMBER: 1013087 and 1166522

Private

Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower, are now at risk. A detailed record of the standing fabric has been completed.

Contact: Tammy Whitaker 01904 601880

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Old Grandstand, Richmond
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1131277

A rare example of an C18 racecourse grandstand. The racecourse was closed in the late C19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

Contact: Tammy Whitaker 01904 601880



SITE NAME:

St. Martins Priory Ruins, A6136, St. Martin's

DESIGNATION:

Scheduled Monument and Listed Building grade I

CONDITION:

Poor

OCCUPANCY:

N/A

PRIORITY CATEGORY:

A (A)

OWNER TYPE:

Private

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.

© English Heritage

LIST ENTRY NUMBER: 1012995 and 1131548 Contact: Tammy Whitaker 01904 601880



SITE NAME:	Church of St Michael and All Angels, Hudswell
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1130830

Small church of 1884 in rock-faced sandstone with Westmorland slate roofs. Roofs poor, leading to significant water ingress to the interior.

© English Heritage

SITE NAME:	Church of Holy Trinity, Melbecks
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1318631

A small early C19 church, set in Swaledale. The window mullions are split by rusting dowels and the west wall is suffering from severe water penetration.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

© English Heritage

SITE NAME:	Section of Scots Dyke linear boundary 150m ENE of Olliver, Aske		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013780
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area is LB Listed Building LDPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

HERITAGE AT RISK 2014 / TOP	NOTINE / RICHITONDSHIKE		
SITE NAME:	St Giles medieval hospital, post-medieval farmstead Giles Farm, Brough with St. Giles	l and Iron Age occi	upation site immediately north of St
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021210
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Cataractonium Roman forts and town, Brough wit	h St. Giles / Catteri	ick / Brompton-on-Swale
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021181
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Medieval settlement of Dalton upon Tees and asso	ciated field system,	, Dalton-on-Tees
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019724
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two moated sites, the site of a dovecote and furth of The Old Hall, East Layton / Forcett and Carkin	er associated featu	res 120m north west and 180m nort
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021039
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Medieval village of Hunton and field system, Hunto	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of Scots Dike linear boundary north west	of High Merrybent,	Melsonby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014799
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of Scots Dyke linear boundary east of Lang	dale Rush, Melsont	ру
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014240
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	William's Hill, Middleham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004907
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of Scots Dyke linear boundary and portion / Easby	of field system 100	m east of Whitefields Farm, Richmond
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013777
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Section of the Scots Dyke linear boundary 225m so	outh of St Martin's I	Priory, St. Martin's
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018143
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jenny Lee 01904 601933
	,		•
SITE NAME:	Stanwick Late Iron Age oppidum, Iron Age and me post-medieval emparkment, Stanwick St. John / Ald		
SITE NAME: DESIGNATION:	Stanwick Late Iron Age oppidum, Iron Age and me		
	Stanwick Late Iron Age oppidum, Iron Age and me- post-medieval emparkment, Stanwick St. John / Ald	lbrough / Forcett ar	nd Carkin / Melsonby
designation: Condition:	Stanwick Late Iron Age oppidum, Iron Age and me post-medieval emparkment, Stanwick St. John / Ald Scheduled Monument, 5 LBs, part in RPG grade II Generally satisfactory but with significant localised	brough / Forcett ar	nd Carkin / Melsonby
DESIGNATION:	Stanwick Late Iron Age oppidum, Iron Age and me post-medieval emparkment, Stanwick St. John / Ald Scheduled Monument, 5 LBs, part in RPG grade II Generally satisfactory but with significant localised problems	lbrough / Forcett ar LIST ENTRY NUMBER: TREND:	nd Carkin / Melsonby  1016199  Declining

## **RYEDALE**



SITE NAME:	Lime Kilns, A170, Allerston
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)

Bank of four lime kilns circa 1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair. Some parts are starting to collapse. Section 17 Management Agreement works to remove damaging trees completed.

© English Heritage

Private LIST ENTRY NUMBER: 1021084 and 1206153

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

Contact: Yvonne Luke 01943 605128



© English Heritage Archive

SITE NAME: Yedingham Priory, Ebberston and Yedingham Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (C)

1003684 and 1149556

Private

Former priory, C12-C13. Little of the standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging in places. A programme of repair has been identified.

Contact: Nicola Brown 01904 601985

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© English Heritage

SITE NAME:	Wall of cascade approximately 50 metres north of Ebberston Hall, A170, Ebberston and Yedingham
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C(C)

Private

1206196

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale circa 50 metres to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME:	Wall of cascade approximately 100 metres north of Ebberston Hall, A170, Ebberston and Yedingham
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1315781

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale approximately 50 metres to the north of the Hall by Colen Campbell. Forms the lowest cascade of the two in the water garden.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME:	Walled garden gate piers to Central north south Lane, Henderskelfe
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private

1173032

Pairs of monumental gate piers crossing the walled garden at Castle Howard, probably by Vanbrugh. The stonework is suffering from the effects of rusting iron cramps and frost damage.



© English Heritage

SITE NAME:	The Stray, Castle Howard, Henderskelfe
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1316058

Castellated walls, four metres high, with square and round interval towers stretching for one mile to either side of the main drive, immediately south of the pyramid gate. Built to the designs of Sir John Vanbrugh c 1723 as a landscape feature. Eastern half repaired with the support of Natural England, but repairs are still required to the western half. Grant has been offered and work has started on site.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site



© English Heritage Archive

ITE NAME:	The Mausoleum and bastion wall with gates and railings, Kirk Hill, Castle Howard Estate, Henderskelfe
DESIGNATION:	Listed Building grade I, RPG grade I

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1149010

Mausoleum by Hawksmoor, from 1729 to 1742, modelled on the tomb of Metella. Situated on a bluff circa 1.2 kilometres east of the mansion and visible from the Temple Terrace and the Temple of the Four Winds (from 1724 to 1728 by Vanbrugh), both south east of the mansion. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME: The Pyramid, St Annes Hill, Castle Howard Estate, Henderskelfe Listed Building grade I, RPG DESIGNATION: grade I CONDITION: Poor OCCUPANCY: N/A

OWNER TYPE: Private LIST ENTRY NUMBER: 1148971

F (F)

PRIORITY CATEGORY:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Commemorative monument of 1728 by Hawksmoor, situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone pyramid suffering from cramp damage. Five of the eight piers at the corners have been repaired with the support of a grant and grant has recently been offered for the repair of the remaining piers and the Pyramid. Repair work has started on site. Set in late C17/early C18 park, one of the most historically significant landscapes in the country.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

Walls to the walled garden, early C18 by Sir John

Vanburgh. The brick walls are in fair condition but the

calcareous sandstone piers are decaying, largely due to



© English Heritage

SITE NAME: Walls to walled garden with gates and corner piers, Castle Howard Estate, Henderskelfe Listed Building grade I, RPG DESIGNATION: grade I CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: D(D)

Private

1296425

corrosion of iron cramps. They are in need of extensive repair. Programme of repair identified.

© English Heritage Archive

SITE NAME: Screen wall, north west of Malton Lodge, Old Maltongate, DESIGNATION: Listed Building grade II\*, SM, CA CONDITION: Very bad N/A OCCUPANCY: PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1219922

Courtyard wall circa 1604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Tammy Whitaker 01904 601880

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

		711
	*	
Na.		
	R	

© English Heritage

SITE NAME:	Sheriff Hutton Castle, Main Street, Sheriff Hutton
DESIGNATION:	Scheduled Monument and Listed Building grade II*, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Other not for profit group

1019593 and 1149592

Ruinous castle begun in 1382 by John, Lord Neville, with C15 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Emergency works to south west tower are complete. The castle is in a relatively stable condition.

Contact: Tammy Whitaker 01904 601880

1		
1		
1	9	

© English Heritage

SITE NAME:	Slingsby Castle, Slingsby
DESIGNATION:	Scheduled Monument and Listed Building grade II, part in LB grade II, part in CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

C16 Great House built on the site of a medieval castle. Ruinous, but surviving up to the eaves in height. In need of urgent consolidation; the site is deteriorating as a result of natural erosion and some vandalism.

LIST ENTRY NUMBER: 1004178 and 1149761 Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Church of St Helen, Church Lane, Amotherby
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER	1149153

Partly medieval church, extensively restored by George Fowler Jones between 1870 and 1872. Decay to medieval west tower and Victorian north aisle. Some loose roof slates.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Church of St Michael, Main Street, Barton-le-Street
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1148993

Church dating to 1871, but incorporating C12 fabric. Constructed from sandstone ashlar with a slate roof. The church is well maintained and in a good condition internally. However, externally the building has a number of missing ridge pieces and some severely eroded stone.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Church of St Giles, Village Street, Lockton
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1260741

1260741

Medieval church at the centre of a moorland village. Generally well maintained, but significant repair needed to the tower. The drainage needs to be overhauled.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© English Heritage

SITE NAME:	Church of St Mary, Main Street, Sandhutton
DESIGNATION:	Listed Place of Worship grade II,

CONDITION: Poor

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Religious organisation

CA

LIST ENTRY NUMBER: 1315734 Mid-Victorian church designed by Anthony Salvin, remodelled in the late C19 by Charles Hodgson Fowler. The spire is covered in mineral felt, which is in poor condition. Roofs of Westmorland slate, also poor. The walls are constructed of a soft sandstone, now eroding. The tower and west gable are in particularly poor condition.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981



SITE NAME: Church of St Martin, Town Street, Scampston DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1315719

Small village church from 1845 to 18466 by GT Andrews, with fittings from 1906 to 1914 by Temple Moore. The slating to the south roof slopes is deteriorating and the bellcote has been split by rusting ironwork.

© English Heritage



Wesleyan Chapel and Hall, The SITE NAME: Green, Slingsby

Methodist chapel of 1837. The roof slates are in poor condition and there is erosion to the gable stonework.

© English Heritage

ALT	DESIGNATION:	Listed Place of Worship grade II, CA
	CONDITION:	Poor
	PRIORITY CATEGORY:	C (New entry)
	OWNER TYPE:	Religious organisation
	LIST ENTRY NUMBER:	1149791

Contact: Giles Proctor 01904 601981

SITE NAME:	Acklam Wold barrow group: a bowl barrow 300m	north west of Ackl	am Wold House, Acklam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011541
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Acklam Wold barrow group: a bowl barrow 450m	south of Acklam V	Vold House, Acklam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011574
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Acklam Wold barrow group: a bowl barrow 450m	south west of Ackl	am Wold House, Acklam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011573
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Acklam Wold barrow group: a bowl barr	ow on Wooing Nab, Acklam		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011539	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Acklam Wold barrow group: a pair of bel House, Acklam	Acklam Wold barrow group: a pair of bell barrows and a bowl barrow 200m south west of Acklam Wold House, Acklam		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1011547	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Acklam Wold barrow group: two bowl ba	arrows on Wooing Nab, Ack	klam	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011537	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Acklam Wold barrow group: a bowl barro	ow 220m north west of Ack	lam Wold House, Acklam / Leavenir	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011543	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Round barrow 250m NNE of Easthorpe C	Cottages, Amotherby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014566	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Round barrow 310m NNE of Easthorpe L	odge, Amotherby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014565	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Round barrow 380m NNW of Easthorpe	Lodge, Amotherby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014569	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
SITE NAME:	Iron Age settlement, Barton-le-Street			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003666	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933	
OWNER THE.	Tivace		Jenny Lee 01701 001755	

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

HERITAGE AT RISK 2014 / YO	RKSHIRE / RYEDALE		
SITE NAME:	Pockley Gates round barrow 600m west of Bead	lam Grange, Beadlam	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019341
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	A bowl barrow on Birdsall Wold, 250m south ea	st of Vessey Pasture	Farm, Birdsall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007569
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	A bowl barrow on Birdsall Wold, 300m north east of Vessey Pasture Farm, Birdsall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007570
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	A bowl barrow on Birdsall Wold, 425m east of A	Aldro Farm, Birdsall	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007512
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	A bowl barrow on Birdsall Wold, 750m east of A	Aldro Farm, Birdsall	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007468
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	A bowl barrow on Birdsall Wold, between Birdsa	all Dale and Vessey Pa	asture Dale, Birdsall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	A bowl barrow on Birdsall Wold, between Birdsa	all Dale and Vessey Pa	asture Dale, Birdsall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007443
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	A bowl barrow on Birdsall Wold, between Birdsa	all Dale and Vessey Pa	asture Dale, Birdsall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007442
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
	•		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Two bowl barrows on Birdsall Wold, between Bi	irdsall Dale and Vesse	ey Pasture Dale, Birdsall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007441
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Aldro earthworks: a linear boundary, two cross-c Leavening / Thixendale / Acklam	dykes and nine round	barrows on Birdsall Wold, Birdsall /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007500
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Hedon Howe tumulus, Burythorpe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bossall Hall: a quadrangular castle, Buttercrambe	with Bossall	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1008016
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Cawthorne medieval settlement remains 150m n	orth east of West Ca	wthorne, Cropton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018951
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 350m north west of Hen Flatts, C	ropton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018408
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 550m north of High Nova Farm, 0	Cropton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015440
CONDITION:	Extensive significant problems	TREND:	Declining
	A I. I I	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing		INO

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

HERITAGE AT RISK 2014 / YO	RKSHIRE / RYEDALE		
SITE NAME:	Long barrow 630m north west of Scamridge Farm,	, Ebberston and Ye	dingham / Allerston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020832
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Foston medieval settlement and moated monastic	grange, Foston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019388
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Boythorpe settlement site, Foxholes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004059
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Romano-British settlement, Foxholes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004046
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Settlement site at Butterwick, Foxholes		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004047
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow 250m ENE of High Baxtonhowe, Fr	yton / Hovingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 530m NNW of Maidensworth Farn	n, Grimstone	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Round barrow on Grimston Moor 350m north eas	t of Black Gill Plant	ation, Grimstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013444
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 300m north of Rye House Farm, He	elmsley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019596
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 420m north of Rye House Farm, He	elmsley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019595
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	East Heslerton Brow barrow group: a bowl barrow	750m east of Man	or Wold Farm, Heslerton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011580
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	East Heslerton Brow barrow group: a bowl barrow	/ I,100m east of Ma	anor Wold Farm, Heslerton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011578
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	East Heslerton Brow barrow group: a bowl barrow	/ 1,300m east of Ma	anor Wold Farm, Heslerton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011579
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Heslerton Brow barrow group: a bowl barrow 230	m north east of W	old Barn, Heslerton
	Heslerton Brow barrow group: a bowl barrow 230 Scheduled Monument	m north east of W	old Barn, Heslerton
DESIGNATION:			
DESIGNATION: CONDITION:	Scheduled Monument	LIST ENTRY NUMBER:	1011585
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Scheduled Monument  Extensive significant problems	LIST ENTRY NUMBER: TREND:	1011585 Declining
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument Extensive significant problems Arable ploughing	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	1011585 Declining No
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Private	LIST ENTRY NUMBER: TREND: NEW ENTRY?:	1011585 Declining No
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument Extensive significant problems Arable ploughing Private  New Bield round barrow and ringwork, Heslerton	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Declining No Jenny Lee 01904 601933
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument Extensive significant problems Arable ploughing Private  New Bield round barrow and ringwork, Heslerton Scheduled Monument	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER:	1011585  Declining  No  Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Round barrow 250m west of Calf Close Wood, Ho	ovingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 350m south west of Moor House F	arm, Hovingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013545
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
ITE NAME:	Round barrow 700m north of Moor House Farm, I	Hovingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013546
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Medieval moated site 150m south east of Low Hut	ton Post Office, Hu	ttons Ambo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014384
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Moated site known as Vivers Hill Castle, 300m nor	th east of the paris	h church, Kirkbymoorside
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Starfits round barrow, 450m north east of Starfits	House, Kirkbymooi	rside
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015810
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman villa, Langton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004884
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- A Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

HERITAGE AT RISK 2014 / YOI	RKSHIRE / RYEDALE		
SITE NAME:	Esh's round barrow: a long barrow and later bowl	barrow 400m north	n of Cross Thorns Barn, Luttons
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011576
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Long barrow 650m south east of Cross Thorns Ba	rn, Luttons	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011575
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Three bowl barrows 200m west of Belle Vue Farm	, Luttons	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011514
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Middleton Heights round barrow, Middleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003258
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Black Howe round barrow, Newton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019777
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Beacon Hill ringwork siege castle and Royal Obser	ver Corps post, Pic	kering
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1019091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 140m west of Haugh Rigg, Pickering	3	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020230
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 280m south west of Haugh Rigg, Pic	ckering	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019781
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

ITE NAME:	Round barrow 400m north east of Haugh Rigg, Pic	kering	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019778
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 570m south of Saintoft Grange, Pic	kering	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020115
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow 600m SSW of Saintoft Grange, Pick	ering	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020114
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Iron Age barrow cemetery, East Field, Rillington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004072
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Moated site and ridge and furrow cultivation 230m	south east of Man	or Farm, Scackleton
ESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015491
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
ITE NAME:	Round barrow on Knapton Brow, Scampston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004109
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
TE NAME:	Part of Leppington medieval village, a moated site a Scrayingham	and site of the form	er parish church of St Helen,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011515
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
ITE NAME:	Round barrow north east of Lawson's Wold Barn,	Sherburn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003140
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYY: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Barrow near Middle Plantation, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004171  CONDITION: Extensive significant problems  TREND: Improving  PRINCIPAL VULNERABILITY: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Barrow west of Bradeham Farm, Thixendale  DESIGNATION: CONTACT: Jenny Lee 01904 601933  SITE NAME: Barrow west of Bradeham Farm, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004170  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private  CONTACT: Jenny Lee 01904 601933	SITE NAME:	Three round barrows south of Prodham's	Wold Farm, Sherburn	
PRINCEPLY LUNEAR PRINCE  Arable ploughing  Private  CENTACT:  Aldro earthworks: a bowl barrow on Hanging Grimston Wold 400m north west of Stone Sleights Farm, Thisendale  Extensive significant problems  Barrow near Middle Plantation, Thisendale  Estensive significant problems  Estensiv	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004089
Aldro earthworks: a bowl barrow on Hanging Grimston Wold 400m north west of Stone Sleights Farm, Thixendale Scheduled Monument Extensive significant problems Extensive significant proble	CONDITION:	Extensive significant problems	TREND:	Declining
Aldro earthworks: a bowl barrow on Hanging Grimston Wold 400m north west of Stone Sleights Farm, Thixendale  Scheduled Monument  Extensive significant problems  Private  CONTACT:  Barrow near Middle Plantation, Thixendale  Scheduled Monument  Extensive significant problems  Private  CONTACT:  Barrow near Middle Plantation, Thixendale  Scheduled Monument  Extensive significant problems  Private  CONTACT:  Barrow near Middle Plantation, Thixendale  Scheduled Monument  Extensive significant problems  RISH MARKEN MARKEN  Private  CONTACT:  Barrow west of Bradeham Farm, Thixendale  Scheduled Monument  Extensive significant problems  RISH MARKEN MARKEN  Scheduled Monument  Extensive significant problems  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN  RISH MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKEN  No  CONTACT:  Jenny Lee 01904 601933  RISH MARKE	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Thixendale Thixendale Scheduled Monument Scheduled	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems TREND: Declining  NEWDRITTE: No  DOWNERT TITLE  Barrow near Middle Plantation, Thixendale  DESCRIPTION  Extensive significant problems  DESCRIPTION  DESCRIPTION  Extensive significant problems  DESCRIPTION  Extensive significant problems  DESCRIPTION  DESCRIPT	SITE NAME:		ging Grimston Wold 400m i	north west of Stone Sleights Farm,
PRINCIPAL VALIANDAMENTY:  Arable ploughing  NEW RATEXY:  Private  Barrow near Middle Plantation, Thixendale  Scheduled Monument  Extensive significant problems  Private  Barrow near Middle Plantation, Thixendale  Scheduled Monument  Extensive significant problems  Private  Barrow west of Bradeham Farm, Thixendale  Scheduled Monument  Barrow Repairer  Barrow Private  CONTACT:  Benny Lee 01904 601933  September Valuandament  Barrow Repairer  Barrow Repai	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007496
Devinition Private Barrow near Middle Plantation, Thixendale DESIGNATION: Scheduled Monument UST ENTRYNUMBER: 1004171  CONDITION: Extensive significant problems TREAD: Improving Private CONTRYNUMBER: 1004171  Arable ploughing New BATRYN: No DOWNER TYPE: Private CONTRYNUMBER: 1004170  Extensive significant problems TREAD: Jenny Lee 01904 601933  Barrow west of Bradeham Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRYNUMBER: 1004170  Extensive significant problems TREAD: Declining Private CONTRACT: Jenny Lee 01904 601933  BET NAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRYNUMBER: 1007906  DECRINICAN: Extensive significant problems IREND: Declining  BET NAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRYNUMBER: 1007906  DECRINICAN: Extensive significant problems IREND: Declining  STENAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument IST ENTRYNUMBER: 1007982  DECRINICAN: Scheduled Monument IST ENTRYNUMBER: 1007982  DECRINICAN: Scheduled Monument IST ENTRYNUMBER: 1007982  DECRINICAN: Scheduled Monument UST ENTRYNUMBER: 1007982  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYN: No DECRINICAN: Scheduled Monument UST ENTRYNUMBER: 1007982  DECRINICAN: Scheduled Monument UST ENTRYNUMBER: 1007982  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYN: No DECRINICAN: Scheduled Monument UST ENTRYNUMBER: 1008481  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYN NOBEL  DECRINICAN: Extensive significant problems TREAD: Declining  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYNUMBER: 1007982  DECRINICAN: Extensive significant problems TREAD: Declining  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYNUMBER: 1007992  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYNUMBER: 1007992  DECRINICAN: UNIVERABILITY: Arable ploughing New BATRYNUMBER: 1007	CONDITION:	Extensive significant problems	TREND:	Declining
Barrow near Middle Plantation, Thixendale  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  1004171  JEMPOVING  Extensive significant problems  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER 1779:  Private  Barrow west of Bradeham Farm, Thixendale  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  1004170  Declining  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER TYPE:  Private  CONDITION:  Extensive significant problems  RENO.  Declining  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER TYPE:  Private  CONDITION:  Extensive significant problems  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER TYPE:  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  1007906  Extensive significant problems  TRENO.  Declining  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  Declining  RENORM VULNEMABULY:  Arable ploughing  NEW BNIRY:  No  DOWNER TYPE:  Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  1007982  DECIDINING  Extensive significant problems  TRENO.  Declining  NEW BNIRY:  No  DOWNER TYPE:  No  DOWNER TYPE:  No  DOWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW BNIRY:  No  DOWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW BNIRY:  No  DOWNER TYPE:  No  DOWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW BNIRY:  No  DOWNER TYPE:  No  DOWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  Declining  NEW BNIRY:  No  DOWNER TYPE:  DIAMAGE  Hanging Grimston barrow group: a bowl barrow 450m south west of Thixendale Grange, Thixendale  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  1009782  Declining  RENORM VULNEMABULY:  No  DOWNER TYPE:  DIAMAGE  DESIGNATION:  Scheduled Monument  LEST ENTRY NUMBER:  LOOP TO THE CONTACT:  Jenny Lee 01904 601933  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  D	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LIST ENTRY NUMBER 1004171  Extensive significant problems TREND: Improving  Private CONTACT: Jenny Lee 01904 601933  STENAME: Barrow west of Bradeham Farm, Thixendale  ESTENAME: Scheduled Monument LIST ENTRY NUMBER: 1004170  EXTENAME: Scheduled Monument LIST ENTRY NUMBER: 1004170  EXTENAME: Private CONTACT: Jenny Lee 01904 601933  STENAME: Declining  PREVENTEY: No  CONTACT: Jenny Lee 01904 601933  STENAME: Private CONTACT: Jenny Lee 01904 601933  STENAME: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007906  EXTENAME: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007902  STENAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007902  STENAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007902  DEClining  STENAME: Hanging Grimston barrow group: a bowl barrow 450m south west of Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007902  DECLINITION: Extensive significant problems TREND: Declining  STENAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange. Thixendale  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 100848    STENAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehiston time and problems Scheduled Monument LIST ENTRY NUMBER: 1007922  DESGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems TREND: Improving RENDEMENTATE: Arable ploughing NEW ENTRY: No DWINERTYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Barrow west of Bradeham Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004170  DEClining RENDEMENTATION: DEClining RENDEMENTATION: Arable ploughing NEW ENTRY: No DWINERTYPE: No DWINERTYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale DESIGNATION: Extensive significant problems RENDEMENTATION: Declining RENDEMENTATION: RENDEMENTATION RENDEMENTATION: Declining RENDEMENTATION: Declining RENDEMENTATION: RENDEMENTATION RENDEMENTATION: RENDEMENTATION RENDEMENTATION: Declining	SITE NAME:	Barrow near Middle Plantation, Thixendale		
REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STET NAME: Barrow west of Bradeham Farm, Thixendale  DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1004170  DECIning  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale  DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1007906  DECINITION: Extensive significant problems TREND: Declining  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  DECINITION: Extensive significant problems TREND: Declining  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Extensive significant problems TREND: Declining  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  DECENDATION: Extensive significant problems TREND: Declining  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  DECINION: Extensive significant problems TREND: Declining  REPRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DECINION: Extensive significant problems TREND: Declining  DESIGNATION: Extensive significant problems TR	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004171
DOWNER TYPE  Private  Barrow west of Bradeham Farm, Thixendale  Scheduled Monument  Extensive significant problems  Scheduled Monument  Extensive significant problems  Barrow west of Bradeham Farm, Thixendale  Declining  REND:	CONDITION:	Extensive significant problems	TREND:	Improving
Barrow west of Bradeham Farm, Thixendale  DESIGNATION: Scheduled Monument  Extensive significant problems  FRINCIPAL WUNERABILITY: Arable ploughing  Private  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale  DESIGNATION: Scheduled Monument  Extensive significant problems  FRINCIPAL WUNERABILITY: Arable ploughing  PRINCIPAL WUNERABILITY: Arable ploughing  PRINCIPAL WUNERABILITY: Arable ploughing  FRINCIPAL WUNERABILITY: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument  Extensive significant problems  FRINCIPAL WUNERABILITY: No  CONDITION: Extensive significant problems  FRINCIPAL WUNERABILITY: Arable ploughing  PRINCIPAL WUNERABILITY: Arable ploughing  FRINCIPAL WUNERABILITY: Arable ploughing  FRINCIP	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004170  CONDITION: Extensive significant problems TREND: Declining  RRINGIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNIR TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007906  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  EXTENAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehiste linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  Extensive significant problems TREND: Declining  RENNERABLE Scheduled Monument LIST ENTRY NUMBER: 1007922	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERAB	SITE NAME:	Barrow west of Bradeham Farm, Thixenda	le	
PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRYP:  No  OWNER TYPE:  Private  Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1007906  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRYP:  Private  CONTACT:  Jenny Lee 01904 601933  STE NAME:  Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1007982  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRYP:  No  OWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1007982  TREND:  Declining  NEW ENTRYP:  No  OWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1008481  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRYP:  No  OWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1008481  TREND:  Declining  PRINCIPAL VULNERABILITY:  No  OWNER TYPE:  Private  CONTACT:  Jenny Lee 01904 601933  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1007922  Extensive significant problems  TREND:  Declining  NEW ENTRYP:  No  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1007922  Extensive significant problems  TREND:  Declining  NEW ENTRYP:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004170
Private Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007906  Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  EXTENAME: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  STENAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  EXTENAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  EXTENAME: Arable ploughing NEW ENTRY: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922	CONDITION:	Extensive significant problems	TREND:	Declining
Private Private CONTACT: Jenny Lee 01904 601933  STENAME Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007906  EXTENDITION: Extensive significant problems TREND: Declining Private Private CONTACT: Jenny Lee 01904 601933  STENAME Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  EXTENAME Scheduled Monument LIST ENTRY NUMBER: 1007982  EXTENAME Arable ploughing NEW ENTRY: No  DECINING  EXTENAME Private CONTACT: Jenny Lee 01904 601933  STENAME Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  STENAME Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  EXTENAME Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  EXTENAME Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor inear boundary, Thixendale  EXTENAME Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor inear boundary, Thixendale  EXTENAME Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor inear boundary, Thixendale  EXTENAME: Arable ploughing NEW ENTRY: NO  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  EXTENAME: Arable ploughing NEW ENTRY: NO  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  EXTENAME Arable ploughing NEW ENTRY: NO	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007906  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehister linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehister linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYY: No  OWNER TYPE: Private  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 100848    CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Number: 1007922  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Number: 1007922  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Namber: 1007922	SITE NAME:	Hanging Grimston barrow group: a bowl b	arrow 300m east of Stone S	Sleights Farm, Thixendale
Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 100848    CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007906
Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehister linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	CONDITION:	Extensive significant problems	TREND:	Declining
Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehister linear boundary, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007982  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehisted linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  CONTACT: Jenny Lee 01904 601933  EXTENAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 100848 I  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  CONTACT: Jenny Lee 01904 601933  EXTENAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehister linear boundary, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1007922  EXTENDITION: Extensive significant problems  TREND: Declining  NO  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  Declining  NO  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No	SITE NAME:	Hanging Grimston barrow group: a bowl b	arrow 450m north east of \	Wold Farm, Thixendale
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007982
Private CONTACT: Jenny Lee 01904 601933  ETE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Private Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1008481  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:		CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  New Entry?: No  Declining  Declining  No  Declining  Declining  Declining  Declining  No  Declining	SITE NAME:	Hanging Grimston barrow group: a bowl b	arrow 650m south west of	Thixendale Grange, Thixendale
PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  CONTACT:  Jenny Lee 01904 601933  Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOO7922  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008481
Private  CONTACT: Jenny Lee 01904 601933  Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistor linear boundary, Thixendale  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No.	CONDITION:	Extensive significant problems	TREND:	Declining
Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehiston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehiston besignation:  Scheduled Monument  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
linear boundary, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1007922  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	OWNER TYPE:			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		Hanging Grimston barrow group: a long ba linear boundary, Thixendale	arrow 400m east of Wold F	arm, incorporating part of a prehistor
	SITE NAME:	linear boundary, Thixendale		
	SITE NAME: DESIGNATION:	linear boundary, Thixendale Scheduled Monument	LIST ENTRY NUMBER:	1007922
	SITE NAME:  DESIGNATION:  CONDITION:	linear boundary, Thixendale Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER: TREND:	1007922 Declining

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

DECOMPTION   Scheduled Monument   INTERNITY NUMBER   1008484   COMPTION   Arable ploughing   NOV OTTIVE   No   CONTRACT   Jerny Lee 01904 601933   CONTRACT   Jerny Lee 01904	SITE NAME:	Hanging Grimston barrow group: four bowl barrow Grange, Thixendale	ws and part of a cro	oss dyke 600m SSW of Thixendale
PRINCIPAL VOLUMEABULTY: Arable ploughing NEW ENTRYS: No CONTACT: Jenny Lee 01904 601933  THE NAME: Hanging Grimston barrow group: four bowl barrows on Uncleby Stoop, Thixendale Designation: Scheduled Monument LEE DITTON NAMES: 1008474  CONDITION: Extensive significant problems TRURE: Declining NAMES: No CONTACT: Jenny Lee 01904 601933  SILENAME: Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale Designation: Scheduled Monument LEE FARTS NAMES: NO CONTACT: Jenny Lee 01904 601933  SILENAME: Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale Designation: Scheduled Monument Teacher State S	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008484
Private Contracts Jenny Lee 01904 601933  SIENAME Hanging Grimston barrow group: four bowl barrows on Uncleby Stoop, Thixendale  SIENAME Scheduled Monument IST EATER NUMBER 1008474  CERRATION EXTENSIVE significant problems IMPN Declining  RENORM VOLUME/BUILTY: Anabe ploughing New North IMPN Declining  STENAME Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale  SCHEDITION Scheduled Monument IST EATER NUMBER 1007977  CENTRACTE Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale  SCHEDITION Scheduled Monument IST EATER NUMBER 1007977  CENTRACTE Private CONTACT: Jenny Lee 01904 601933  SIENAME Anabe Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale  SIENAME Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale  SIENAME Anabe Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale  SIENAME ANABE Private CONTACT: Jenny Lee 01904 601933  SIENAME EXPENSEMBLITY  Anable ploughing New NERTHY. No  CONTACT: Jenny Lee 01904 601933  SIENAME RENORM VALERWARISTY  Anable ploughing New NERTHY. No  CONTACT: Jenny Lee 01904 601933  SCHEMANICA CONTACT: Jenny Lee 01904 601933  SIENAME RENORM VALERWARISTY  Anable ploughing NEW NERTHY. No  CONTACT: Jenny Lee 01904 601933  SCHEMANICA CONTACT: Jenny Lee 01904 601933  SCHE	CONDITION:	Extensive significant problems	TREND:	Declining
Hanging Grimston barrow group: four bowl barrows on Uncleby Stoop, Thixendale  Scheduled Monument  STENDAME  Extensive significant problems  Private  Private  CONDITION  Extensive significant problems  Private  CONTACT:  Jenny Lee 01904 601933  Scheduled Monument  Extensive significant problems  Private  CONTACT:  Jenny Lee 01904 601933  Scheduled Monument  Extensive significant problems  Private  CONTACT:  Jenny Lee 01904 601933  Private  CONTACT:  Jenny Lee 01904 601933  Declining  Private	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST DITTER NUMBERS 1008474  CONTROLS  Extensive significant problems  TIREND  CONTROLS  Private  Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale ISSEGNATION  Scheduled Monument  Scheduled Monument  Scheduled Monument  Extensive significant problems  TIREND  CONTROLS  Declining  Arable ploughing  Arable ploughing  Private  CONTROLS  Jenny Lee 01904 601933  Declining  Arable ploughing  Arable plough	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems TREND: No Declining NEW DITEM?: No OWNERTHER PRIVATE Private CONTACT: Jenny Lee 01904 601933 DECEMBER PRIVATE PRIVATE PRIVATE CONTACT: Jenny Lee 01904 601933 DECEMBER PRIVATE PRIVATE PRIVATE CONTACT: Jenny Lee 01904 601933 DECEMBER PRIVATE PRIVATE DECEMBER PRIVATE DECEMBER PRIVATE PRIVATE DECEMBER PRIVATE PRIVATE DECEMBER PRIVATE DECEMBER PRIVATE PRIVATE DECEMBER PRIVATE	SITE NAME:	Hanging Grimston barrow group: four bowl barro	ws on Uncleby Stoc	pp, Thixendale
Private CONDITION Extensive significant problems (INTERNALL PRIVATE) (INTERNALL PRIVAT	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008474
DOWNER TYPE: Private  CONTACT:  Jenny Lee 01904 601933  STENAME  Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale SESONATION  Scheduled Monument  Extensive significant problems  TREND: Declining NEWENIRY: No  Developing  New ENDIRY: Private  CONTACT: Jenny Lee 01904 601933  STENAME: Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale Scheduled Monument  LIST ENTRY NUMBER: 1008483  Scheduled Monument  Extensive significant problems  TREND: Declining NEW ENTRY: No  Declining  NEW ENTRY: No  DECLINING SERVICIAL YOUNGRABUTY: Arable ploughing  NEW ENTRY: Private  CONTACT: Jenny Lee 01904 601933  STENAME: Round barrow north of manor house, Thixendale SEGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004128  SEGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004128  SEGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004128  SEGNATION: Scheduled Monument  CONTACT: Jenny Lee 01904 601933  STENAME: Round barrow south east of Gill's Farm, Thixendale SEGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004537  Declining STENAME: ROUND BARROWS SUBJECT OF STENAME: SCHEDULE	CONDITION:	Extensive significant problems	TREND:	Declining
Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1007977  Declining PRINCIPAL VOLUMERABILITY: Arable ploughing NEW BNIRY: No OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  ETT NAME: Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1008483  EXTENSIVE Significant problems TREND: Declining NEW BNIRY: No OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  ETT NAME: Arable ploughing NEW BNIRY: No OWNER TYPE: No OWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow north of manor house, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow north of manor house, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow south east of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow south east of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow south east of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow south east of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrow south east of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south of Gill's Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south west of Riggs Farm, Thixendale CONTACT: Jenny Lee 01904 601933  ETT NAME: Round barrows south west of Riggs Farm, Thixendale CONTACT: Jenny Lee 01904 601933	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LIST ENTRY NUMBER: 1007977  EXTENDED Declining  Arable ploughing NEW ENTRY: No  Declining  Arable ploughing NEW ENTRY: No  DECLINING  TREAD: Deny Lee 01904 601933  LIST NAME: Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale  DESCRIPTION: Scheduled Monument LIST ENTRY NUMBER: 1008483  DESCRIPTION: Scheduled Monument LIST ENTRY NUMBER: 1008483  DECLINING  RENCIPAL VALINERABILITY: Arable ploughing NEW ENTRY: No  Declining  RENCIPAL VALINERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Jenny Lee 01904 601933  LIST ENTRY NUMBER: 1004128  DECLINING  RENCIPAL VALINERABILITY: Arable ploughing NEW ENTRY: No  DECLINING  EXTENDED: Declining  ARABLE Private CONTACT: Jenny Lee 01904 601933  LIST ENTRY NUMBER: 1004128  DECLINING  DECLI	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Jenny Lee 01904 601933  ITE NAME: Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale BESGNATION: Scheduled Monument UST ENTRY NUMBER: CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: Private  Round barrow north of manor house, Thixendale DESGNATION: Scheduled Monument UST ENTRY NUMBER: ROUND BARROW NORTH OF MANOR NORTH OF MAN	ITE NAME:	Hanging Grimston barrow group: three bowl barro	ows 350m north eas	st of Wold Farm, Thixendale
Arable ploughing NEW ENTRY: No  Declining  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DEVENTED SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  SCHEDULE MONITOR: Extensive significant problems TREND: Declining  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DEVENTED DECLINING  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DEVENTED DECLINING  SERICIPAL VULNERABILITY: NO  DECLINING  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  SERICIPAL VULNERABILITY: NO  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  DECLINING  SERICIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  DECL	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007977
Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1008483  CONDITION: Extensive significant problems IREND: Declining  RINCIPLA VULNERABILITY: Arable ploughing NEW ENTRYT: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow north of manor house, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004128  DECINITION: Extensive significant problems TREND: Declining  RINCIPLA VULNERABILITY: Arable ploughing NEW ENTRYT: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004537  DECINITION: DECINING  STEENAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004149  DECINITION: Declining  PRINCIPLA VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  DECINITION: Declining  PRINCIPLA VULNERABILITY: Arable ploughing NEW ENTRY: No  DECINITION: Declining  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 100455	CONDITION:	Extensive significant problems	TREND:	Declining
Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale DESIGNATION:  Scheduled Monument  Extensive significant problems  FRINCIPAL WUNERABILITY:  Arable ploughing  NEW ENTRYP:  Private  CONTACT:  Jenny Lee 01904 601933  STENAME  Round barrow north of manor house, Thixendale  DESIGNATION:  Scheduled Monument  Extensive significant problems  FRINCIPAL WUNERABILITY:  Arable ploughing  NEW ENTRYP:  No  Declining  FRINCIPAL WUNERABILITY:  Arable ploughing  NEW ENTRYP:  Private  CONTACT:  Jenny Lee 01904 601933  STENAME:  Round barrow south east of Gill's Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUSSTENAME:  Round barrow south east of Gill's Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUSSTENAME:  Round barrows south of Gill's Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUSSTENAME:  Round barrows south of Gill's Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUSSTENAME:  Round barrows south of Gill's Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOUST ENTRY NUMBER:  LOU	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1008483  CONDITION: Extensive significant problems TREND: Declining  NEW ENTRY: No  DOWNER TYPE Private Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow north of manor house, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004128  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004537  SCHEDULING Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004537  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004149  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1004149  DECINITION: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004154  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Round barrow north of manor house, Thixendale  Sesignation:  Scheduled Monument  Extensive significant problems  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Round barrow south east of Gill's Farm, Thixendale  Sesignation:  Scheduled Monument  Extensive significant problems  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Round barrows south of Gill's Farm, Thixendale  Sesignation:  Scheduled Monument  LIST ENTRY NUMBER:  1004133  Rencipal volunerability:  Round barrows south of Gill's Farm, Thixendale  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  1004149  Declining  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Arable ploughing  Rencipal volunerability:  Round barrows south west of Riggs Farm, Thixendale  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1004149  Declining  Rencipal volunerability:  No  Declining  Rencipal volunerability:  Rencipal volunerabili	SITE NAME:	Hanging Grimston barrow group: three bowl barro	ows 600m south we	est of Thixendale Grange, Thixendal
Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow north of manor house, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004128  DESIGNATION: Extensive significant problems TREND: Declining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  DEClining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  DECLINING  DEVELOPMENT OF TREND: Declining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  DECONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004159  DEClining  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument  EXTEND: Declining  NEW ENTRY: No  DEClining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004554  DESIGNATION: Arable ploughing NEW ENTRY: No  DEClining  REINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DECLINING  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004554  DESIGNATION: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008483
Private Round barrow north of manor house, Thixendale  SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004128  DESIGNATION: Extensive significant problems TREND: Declining  STRINGPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  SCHEDULERABILITY: Arable ploughing NEW ENTRY: NO  DEVINER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Round barrow south east of Gill's Farm, Thixendale  SESSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  SCHEDULERABILITY: Arable ploughing NEW ENTRY: NO  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  SERINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  DEVINER TYPE: Private CONTACT: Jenny Lee 01904 601933  STENAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 10041601933  STENAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  DESIGNATION: Arable ploughing NEW ENTRY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow north of manor house, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004128  DECONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004537  DECLINING  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STEND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004149  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004149  DECONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: No  DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1004   28  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004   49  CONDITION: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004   49  CONDITION: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  EXENCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  EXENCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  OWNER TYPE: Private  Round barrow south east of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  DESIGNATION: Scheduled Monument  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument  CONDITION: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  Declining  PRINCIPAL VULNERABILITY: No  Deviner TYPE: Private  Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument  CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument  CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument  CONTACT: Jenny Lee 01904 601933  STE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No	SITE NAME:	Round barrow north of manor house, Thixendale		
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrow south east of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrows south of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No DWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrows south west of Riggs Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004154  CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrows south west of Riggs Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004128
Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrow south east of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004537  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONTACT: Declining  Private Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow south east of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004537  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWINER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWINER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004554  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1004537  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  NEW ENTRY?: No  Private  Round barrows south of Gill's Farm, Thixendale  Designation: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  Private  Round barrows south west of Riggs Farm, Thixendale  Designation: Scheduled Monument  CONTACT: Jenny Lee 01904 601933  TREND: Declining  Private  Declining  New ENTRY: No  Declining  New ENTRY: No  Declining  Round barrows south west of Riggs Farm, Thixendale  Designation: Scheduled Monument  LIST ENTRY NUMBER: Jenny Lee 01904 601933  TREND: Declining  NEW ENTRY: Declining  Round barrows south west of Riggs Farm, Thixendale  Designation: Scheduled Monument  LIST ENTRY NUMBER: Jenny Lee 01904 601933  TREND: Declining  Round barrows south west of Riggs Farm, Thixendale  Designation: Scheduled Monument  Extensive significant problems  TREND: Declining  No  No	SITE NAME:	Round barrow south east of Gill's Farm, Thixendal	e	
Arable ploughing New Entry?: No DANNER TYPE: Private CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrows south of Gill's Farm, Thixendale DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DANNER TYPE: Private CONTACT: Jenny Lee 01904 601933  BITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems  TREND: Declining  NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004537
Private CONTACT: Jenny Lee 01904 601933  Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DESIGNATION: CONTACT: Jenny Lee 01904 601933  ROUNDER TYPE: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems  TREND: Declining  NO  NO  NO  NO  NO  NO  NO  NO  NO  N	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrows south of Gill's Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  Declining  PRINCIPAL VULNERABILITY: Private  CONTACT: Jenny Lee 01904 601933  SITE NAME: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004149  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing  Private  Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument  EXTENDED: Declining  NO  LIST ENTRY NUMBER: 1004154  LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  NO	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  Private CONTACT: Jenny Lee 01904 601933  ROUNDERTYPE: Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Round barrows south of Gill's Farm, Thixendale		
problems  PRINCIPAL VULNERABILITY: Arable ploughing  Private  Round barrows south west of Riggs Farm, Thixendale  Designation: Scheduled Monument  Extensive significant problems  Principal Vulnerability: Arable ploughing  New Entry?: No  CONTACT: Jenny Lee 01904 601933  LIST ENTRY NUMBER: 1004554  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004149
Private CONTACT: Jenny Lee 01904 601933  Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:		TREND:	Declining
Round barrows south west of Riggs Farm, Thixendale  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004554  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No	SITE NAME:	Round barrows south west of Riggs Farm, Thixend	ale	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:			1004554
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	2201011110111		TDENID	D 1: :
		Extensive significant problems	TREND:	Declining
	CONDITION:			-

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

SITE NAME:	Round barrow east of Weaverthorpe Ling, Wea	verthorpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004098
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow north west of Mount Spaniel, We	averthorpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003141
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Section of linear earthwork in Pasture Plantation	, Weaverthorpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows south east of Pasture Farm,	Weaverthorpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004166
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 800m west of High Fordon Farm, \	Villerby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007744
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Bowl barrow 1100m west of High Fordon Farm,	Willerby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007745
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Prior Moor round barrow, Willerby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004106
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow south east of Willerby Wold Hou	ise, Willerby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004112
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Round barrow west of Willerby Wold House, W	/illerby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004107
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows, Staxton Brow, Willerby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004090
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Wilton Hall moated site 250m south of Manor Fa	arm, Wilton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021269
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow 1/4 mile (400m) south east of Ne	wton South Wold Fa	rm, Wintringham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003136
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow 330yds (300m) NNW of Ladyhills	, Wintringham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003135
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Round barrow north east of Wintringham South	Wold Farm, Wintrin	gham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004163
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow west of Newlands Lane, Wintring	ham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004538
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Three round barrows on West Heslerton Wold,	Wintringham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004110
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.



0	Engli	sh H	leritage
---	-------	------	----------

SITE NAME:	Ebberston Hall, Ebberston and Yedingham
DESIGNATION:	Registered Park and Garden grade II*, 5 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Low
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001062

Gardens with water features c1718 integral to the design of Ebberston Hall and views of the wider landscape from it. Stepped cascade water features (listed grade II\*) in need of consolidation and repair, trees in parkland to the south are over-mature.

Contact: Erika Diaz Petersen 01904 601901

35
The state of the s
STATE WALLS TO STATE OF THE STA
TO PARTY AND PROPERTY OF THE PARTY OF THE PA

© English Heritage

SITE NAME:	Castle Howard, Henderskelfe / Huttons Ambo / Slingsby / Welburn / Bulmer / Coneysthorpe
DESIGNATION:	Registered Park and Garden grade I, 65 LBs, 2 SMs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Low
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001059

Gardens, pleasure grounds and park with a mixture of geometric and less formal features developed c1698-1738 by Charles Howard, third Earl of Carlisle and Sir John Vanbrugh (1664-1726) possibly with some advice from Stephen Switzer (1682-1745). Key buildings and structures in the landscape are in need of consolidation and repair; sections of the grand approach avenues have over-mature trees in need of replacement. A management plan for the Avenues has been prepared as part of a Natural England Stewardship Agreement.

Contact: Erika Diaz Petersen 01904 601901

#### **SCARBOROUGH**



SITE NAME:

Glaisdale Head Methodist
Church and walls, Glaisdale

DESIGNATION:

Listed Place of Worship grade II

CONDITION:
PRIORITY CATEGORY:

C (New entry)

OWNER TYPE:
Religious organisation

LIST ENTRY NUMBER:

1148582

Small Georgian Methodist chapel in a moorland setting. Gothick sash windows and original benches. The roof covering is deteriorating and the interior is damp - the chapel is built into the hillside.

Substantial C12 church with later medieval alterations. Nave roof recovered and nave south wall repaired with grant offered in December 2009. Further stonework repairs are required, particularly to the chancel.

Contact: Giles Proctor 01904 601981

© English Heritage



© English Heritage

SITE NAME:	Church of St Martin, Main Street, Seamer
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1316472

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Gar

RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St John the Evangelist, Baxtergate, Whitby
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1244949

Early Victorian church with three parallel roofs. Main roofs re-slated with grant offered in March 2010. Further grant offered in March 2013 for urgent repairs to lower roofs and stonework under Repair Grants for Places of Worship and work is now on site.

Contact: Giles Proctor 01904 601981

#### © English Heritage

SITE NAME:	Round barrow 460m south of Oliver's Mount Farm	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021233
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Three barrows at Seamer Beacon and the ruins of	Baron Albert's Tov	ver
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008486
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 700m north of Betton Farm, East Ay	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008128
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 920m north of Betton Farm, East Ay	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008129
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 950m north of Betton Farm, East Ay	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008130
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Roman signal station, Carr Naze, Filey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004187
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nicola Brown 01904 601985

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LPA NP RPG UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Elf Howe round barrow, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004091
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow on Flixton Wold, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004113
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow on Flotmanby Brow, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004096
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Round barrow on Flotmanby Wold, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004095
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Round barrow south of Long Plantation, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004539
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Sharpe Howes, round barrows, Folkton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004182
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Two round barrows north west of Danebury Mand	or, Folkton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004092
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
	Round barrow south of Grange Farm, Hunmanby		
SITE NAME:	· · · · · · · · · · · · · · · · · · ·	LIST ENTRY NUMBER:	1004093
	Scheduled Monument	LIST EINTKT INOTIBER:	1007073
DESIGNATION:	Scheduled Monument  Extensive significant problems	TREND:	Declining
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:			

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

HERITAGE AT RISK 2014 / YORKSI	HIRE / SCARBOROUG	4		
SITE NAME:	Group of circula Fleming	r and rectangular enclosures, near	Cansdale Whin, H	unmanby / Wold Newton / Burton
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004065
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Bowl barrow 800	Om north west of Moor House Far	m, Seamer	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1008137
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Section of linear	earthwork on Seamer Moor Hill, S	Seamer	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1008135
CONDITION:	Generally satisfac problems	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Government or agency		CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Star Carr Early N	1esolithic settlement site, 960m N	NW of Woodhous	e Farm, Seamer
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1401425
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Tammy Whitaker 01904 601880
	SITE NAME:	Valley Gardens and South Cliff Gardens	Public gardens, comprising a series of seaside walks a gardens with features from the mid C19 to the 1930 including contributions from George Knowles, Willia Skipsey, Sir Joseph Paxton, HW Smith and Alfred Shuttleworth. Deterioration of the wider park comb	
and the second	DESIGNATION:	Registered Park and Garden grade II, 6 LBs		
	CONDITION:	Generally satisfactory but with significant localised problems	with cliff erosion path systems and	is resulting in the loss of sections of the park integrity.
1111	VULNERABILITY:	Medium		
大和 是 接	TREND:	Declining		
English Heritage	NEW ENTRY?:	No		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1001528	Contact: Erika D	iaz Petersen 01904 601901
SITE NAME:	Dean Road / Mai	nor Road Cemetery		
DESIGNATION:	Conservation Ar	,	NEW ENTRY?:	No
CONDITION:	Very bad		TREND:	Improving
VULNERABILITY:	Medium		CONTACT:	Derek Green (LPA) 01723 232468
SITE NAME:	Falsgrave			
DESIGNATION:	Conservation Ar	ea	NEW ENTRY?:	Yes
CONDITION:	Fair		TREND:	Deteriorating
				_

VULNERABILITY:

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Medium

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

CONTACT:

## **ABBREVIATIONS**

Derek Green (LPA) 01723 232468

SITE NAME:	Flixton		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Derek Green (LPA) 01723 232468
SITE NAME:	Coorbonough		
SITE INALIE.	Scarborough		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	Yes
	<u> </u>	NEW ENTRY?: TREND:	Yes Deteriorating
DESIGNATION:	Conservation Area, LB grade II		

#### **SELBY**



SITE NAME: Chapel to Huddleston Hall (now barn), west of house,

Laith Staid Lane, Huddleston with Newthorpe Listed Building grade II\* Poor

Vacant/not in use

PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER: 1167970

Former chapel with C15 origins, C16 rebuilding to the east and later alterations. The building is disused and the roof coverings are in poor repair, resulting in water ingress to the interior.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME: Huddleston Hall, Laith Staid Lane, Huddleston with Newthorpe DESIGNATION: Listed Building grade II\* CONDITION: Poor

Private

OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1167923

SITE NAME:

LIST ENTRY NUMBER:

Late C16 manor house, now used as a farmhouse. The roofs are in poor condition resulting in water ingress to the interior, and there is some decaying stonework. A full repairs programme has been planned, but work has not yet been carried out.

Contact: Giles Proctor 01904 601981



© English Heritage

south east of house, Laith Staid Lane, Huddleston with Newthorpe DESIGNATION: Listed Building grade II\* CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1167953

Stables to Huddleston Hall,

Stables of the late C16 with C19 additions and alterations. The roof coverings have some missing tiles.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Selby District Council

SITE NAME:	Abbot's Staith Buildings, Water Lane, Selby
DESIGNATION:	Scheduled Monument and Liste Building grade II*, 2 LBs
CONDITION:	Poor

C (C)

Private

LIST ENTRY NUMBER:

Part occupied/part in use

1004181 and 1167663

C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesian limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating. Discussions are underway with a local community group regarding reuse of the building

Church of 1842 by Pritchett of York, of sandstone with cast-iron windows. Some of the stonework is suffering from extensive erosion, particularly to the tower and the

Contact: Nicola Brown 01904 601985

south elevation.

FORM	

© English Heritage

© English Heritage

SITE NAME:	Church of St Edward, Church Street, Brotherton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1132452

Contact: Giles Proctor 01904 601981

SITE NAME:	Church of All Saints, Church Hill, Sherburn in Elmet
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1148444

Medieval parish church, from C12 to C16 with east end restored by Anthony Salvin in 1857. Magnesian limestone masonry is very badly eroded to clerestories, east and west windows and spiral stair to the belfry. Localised defects to glazing, rainwater goods and south aisle roof. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911



SITE NAME:	Church of All Saints, Church Hill, Wistow
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174776

Medieval church incorporating early C13 arcade to the south aisle. Although the earliest extant fabric dates to C13, the church is probably of earlier origin. Constructed from magnesian limestone which is susceptible to weathering. Areas of the masonry, particularly to the south porch, are severely decayed, parapet gutters are defective and allowing water into the building and the vestry roof is in poor condition. Movement also appears to be affecting the porch and chancel. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911



© English Heritage

© English Heritage

SITE NAME:	Church of St Martin, Park Lane, Womersley
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174486

Medieval church predominantly of the C13 and C14, notable for a decorative scheme added by Bodley in the C19. Roofs and rainwater goods in poor condition. Some stonework, most notably at the east and west ends, is very eroded. Grant offered in December 2012 under Repair Grants for Places of Worship and work is on site.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	St Andrew's College and moat, 440m north east of College Farm, Acaster Selby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017457
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Mote Hill: a moated site, two fishponds and part of Appleton Roebuck	f an adjacent field sy	vstem 500m west of Nun Appleton H
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008229
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Parkshaw moated site, 170m north west of Wood	Farm, Balne	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016025
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Catterton Hall moated site and adjacent building platform, Catterton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017456
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Castle Hill moated site, 350m south of St Peter and	d St Paul's Church,	Drax
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017455
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Scurff Hall moated site, Newland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017485
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Toulston medieval village, manor house site and ea	rly garden earthwo	·
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017922
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Two Roman forts, two Roman camps, vicus, Iron A monument west of Newton Kyme, Newton Kyme	Age enclosure, Bror cum Toulston	nze Age barrows and Neolithic heng
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Paradise Lodge moated site and grange of the Prior	r of Bolton, Ryther	cum Ossendyke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008225
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Thorpe Hall moated monastic grange, Selby		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1017460
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
ITE NAME:	Danes Hills square barrow cemetery on Crook Mo	oor, Skipwith	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016619
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Moated site and fishpond 140m south of St Helen's	Church, Skipwith	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015543
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
ITE NAME:	Round barrow on Skipwith Common, 800m south	east of Adamson F	arm, Skipwith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018604
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
ITE NAME:	Round barrow on Skipwith Common, 810m south	of Skipwith Church	n, Skipwith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018601
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
			Nicola Brown 01904 601985

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Round barrow on Skipwith Common, 830m south	east of Adamson F	arm, Skipwith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018605
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Danes Hills square barrow cemetery, 300m south	of Adamson Farm,	Skipwith / Riccall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018603
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Steeton Hall medieval magnate's residence and manorial centre, South Milford		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1015504
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Steeton medieval village, moated site and fishponds	s, Steeton	
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017555
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Whitley Thorpe moated Templar grange site, 600m north west of Fulham House, Whitley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017458
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

## YORKSHIRE DALES (NP)



SITE NAME:	Henry Simpson's Barn, Appletreewick, Craven
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)

Barn built in 1737 for Lord Burlington. Of a high level of embellishment and craftsmanship, unusual for the date. The roof was partly stripped in 1995 and the roof timbers are consequently in poor condition.

Contact: Giles Proctor 01904 601981 LIST ENTRY NUMBER: 1249282 © English Heritage

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LPA NP RPG UA Unitary Authority
WHS World Heritage Site



© English Heritage

© English Heritage

SITE NAME:	Barden Church, Barden, Craven
DESIGNATION:	Listed Building grade I, SM
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1131761

C16 former chapel. The interior is derelict and there is some water penetration and damage, despite past repairs to the roof. An options appraisal has been undertaken with the Estate and Yorkshire Dales National Park Authority. Grant has been offered for project development and work on this is underway.

Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof leaks badly with attendant decay. Integral part of a working farm.

Contact: Giles Proctor 01904 601981

1	2.0
	- 4
. 111	
	A STATE OF THE PARTY OF THE PAR

SITE NAME:	Lodge Hall, Ingman Lodge Road, Selside, Horton in Ribblesdale, Craven
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1289489

LIST ENTRY NUMBER

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

SITE NAME:	Nappa Hall, Askrigg, Richmondshire
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1157398

A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. There has recently been a change in ownership and some repairs have been carried out. However, the floors in the west tower are still in a rotten and dangerous state and the roof coverings over the great hall and the south east wing are in very poor condition. Discussions are underway regarding repair and reuse.

Contact: Giles Proctor 01904 601981



SITE NAME:	Church of St Margaret, Gruel Street, Hawes, Richmondshire
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166758

1851 church with later furnishings. Two phases of grant offered in March 2012 and March 2013 under Repair Grants for Places of Worship. First phase of repair and works, to south aisle and chancel, is now complete. The second phase, to north aisle and tower, is underway. A third phase is proposed in order to complete the repair of the church.

Contact: Giles Proctor 01904 601981

(C)	English	Heritage

SITE NAME:	Kinsey Cave, Giggleswick Scar, Giggleswick, Craven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010295
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Meal Bank Quarry Hoffmann kiln, quarry and lime works, Ingleton, Craven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020889
DESIGNATION:  CONDITION:	Scheduled Monument  Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND:	1020889 Declining
	Generally unsatisfactory with major localised		.02000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG

## **ABBREVIATIONS** Conservation Area Listed Building

Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

IEM MOE MI MON ZOTT / TOT	TOTALE TOTALE BY LEES (TAT ) T BY ALL TO LET		
SITE NAME:	Large univallate hillfort on Ingleborough Hill, Ingleton / Clapham cum Newby, Craven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008876
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Marrick ore hearth lead smeltmill, Marrick, Richmo	ondshire	
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1015824
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Gunnerside Gill lead mines and ore works, Melbecks, Richmondshire		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015830
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Littondale barns and walls, Halton Gill / Hawkswick / Litton / Arncliffe / Conistone with Kilnsey, Craven		
DESIGNATION:	Conservation Area, 58 LBs, 3 SMs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Robert White (LPA) 01969 652360
SITE NAME:	Starbotton, Kettlewell with Starbotton, Craven		
designation:	Conservation Area, 12 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Robert White (LPA) 01969 652360
SITE NAME:	Swaledale and Arkengarthdale barns and walls, Mu Grinton / Marrick / Melbecks, Richmondshire	ker / Reeth, Fremin	gton and Healaugh / Arkengarthdale /
DESIGNATION:	Conservation Area, 135 LBs, 9 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating

## SOUTH YORKSHIRE

#### **BARNSLEY**



SITE NAME:	Grimethorpe Hall, Brierley Road, Brierley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1151202

House, circa 1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is residential. The setting has been eroded by construction of housing to the west. Consent was granted for conversion to a restaurant in 2005, but the scheme failed.

Contact: Tammy Whitaker 01904 601880

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

#### tegory is L herwise L N R

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument



© Stephen Elliott, Purcell Miller Tritton

TE NAME:	Gun Room, Wentworth Castle
	Stainborough

Listed Building grade II\*, RPG DESIGNATION: grade I, CA

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E)

OWNER TYPE:

LIST ENTRY NUMBER:

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1151066 Probably built as a banqueting house or a bath-house, it was used as a gun room in the C19. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006 and 2007, but a further phase of conservation is required to the interior which is in very poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME:	Dovecote at Glebe Farm, Tankersley
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)

Private

the Glebe Farm for Richard Goodwin, Rector from 1715 to 1752. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes. In a state of serious disrepair with a temporary roof structure in place. Potential for low key use, ancillary to residential. Project development grant underway.

Stone built dovecote and cart shed, built in 1735 as part of

Contact: Nicola Brown 01904 601985



© English Heritage

SITE NAME:	Low Forge, Wortley / Hunshelf	
DESIGNATION:	Scheduled Monument	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1020626	

1016549 and 1151075

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair. Tree and scrub clearance undertaken. Solution agreed for repair of masonry.

Contact: Nicola Brown 01904 601985



© English Heritage

SITE NAME:	Church of St Peter including attached wall and gateway to south west, Brinckman Street
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1314984

Church and attached wall and gateway, 1893 to 1910 by Temple Moore. In generally good order; nave appears to have been re-slated. Slates to chancel roof appear to be in poor condition and there is salting brickwork to the Lady Chapel.

Contact: Giles Proctor 01904 601981



© English Heritage

SITE NAME:	Church of St Helen, High Street, Thurnscoe
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1151168

Victorian church with Georgian tower, the rest rebuilt in 1887. Clay tiled roofs to nave and south east corner are failing and need to be regularly overhauled. Eroded stonework to porch.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

TENTINGE / THISIC 2011 / TOI	ANOTHINE I BANNIGEET		
SITE NAME:	East Gawber Hall colliery fanhouse, 800m north	east of Croft Farm	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017748
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Elsecar Colliery Newcomen engine		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004790
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Heavy anti-aircraft gunsite 330m south east of L	owfield Farm	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Wortley Top Forge, Hunshelf / Thurgoland		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1018262
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Romano-British settlements at Finkle Street, Wo	ortley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004801
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Water powered bloomery, iron forge and rolling	g mill at Low Forge, V	Vortley / Hunshelf
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020626
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Elsecar, Hoyland Nether		
DESIGNATION:	Conservation Area, 19 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tony Wiles (LPA) 01226 772576
SITE NAME:	Worsbrough		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tony Wiles (LPA) 01226 772576

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

#### **DONCASTER**



© English Heritage

SITE NAME:	Moat Hall ruins, Braithwell	
DESIGNATION:	Scheduled Monument, LB grade II	
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	B (B)	

Private

1012461

Contact: Nicola Brown 01904 601985

residential units.

Ruins of medieval monastic grange and post-medieval dwelling, consisting of arched doorway and low walls, in bad repair. Programme of works agreed with the owner.

Mid C18 stable block, now store and house with attached walls and gate piers. Possibly by James Paine, who designed Hickleton Hall, between 1745 and 1748, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. Repairs have been carried out to the roofs and the building is now in fair condition, but disused. Planning application agreed for conversion to

-	
- Jan	
-	
and	
The state of the s	

OWNER TYPE:

SITE NAME:

LIST ENTRY NUMBER:

© English Heritage

© English Heritage

SITE NAME:	Stable to Hickleton Hall including the Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton	
DESIGNATION:	Listed Building grade II*, RPG grade II, CA	
CONDITION:	Fair	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	E (F)	

OWNER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1151659 Contact: Craig McHugh 01904 601972

Christ Church, Thorne Road



	DESIGNATION:	Listed Place of Worship grade II*, CA
	CONDITION:	Fair
-	PRIORITY CATEGORY:	F (F)
	OWNER TYPE:	Religious organisation
i i	LIST ENTRY NUMBER:	1286309

A Gothic style church dating to 1827 or 1829. It is constructed from limestone ashlar with a slate roof and copper spire. It has a four-stage west tower. Closed in 1989, it was bought by Reachout Christian Fellowship in 1994. Ten years later and at significant cost, it opened again for worship. Grant-aided remedial roof works and repairs to failing internal ceiling plaster are underway following a grant offer in December 2012 under Repair Grants for Places of Worship scheme.

Contact: Giles Proctor 01904 601981



SITE NAME:	Church of St Peter, Warmsworth Road	Known as 'The White Church'. Consementioned in a wartime broadcast from	
DESIGNATION:	Listed Place of Worship grade II	notorious 'Lord Haw Haw'. Steel-fram condition.	
CONDITION:	Poor		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1096038	Contact: Giles Proctor 01904 601981	

Known as 'The White Church'. Consecrated in 1942 and mentioned in a wartime broadcast from Berlin by the notorious 'Lord Haw Haw'. Steel-framed windows in poor condition.

		-	I	iii
© English Herit	age			
HILL				

SITE NAME:	Church of St George, Church Lane, Doncaster
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1151447

Major Victorian church, replacing the Medieval parish church which was destroyed by fire. Several phases of repair undertaken, but further work required to stonework, including to the central tower. Grant offered in December 2011 under Repair Grants for Places of Worship for repairs to the north transept and work is

underway.

Contact: Giles Proctor 01904 601981


## © English Heritage

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBR	eviations
CA	Conservation Area
	Local Planning Authority
	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site
LB LPA NP RPG SM UA	Listed Building Local Planning Authority National Park Registered Park and Garde Scheduled Monument



SITE NAME:	Church of St Lawrence, Station Road, Hatfield
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Norman church. C12 origin, C13 arcades, the rest mostly C15. 1872 alterations by Thomas Jackson, 1882 restoration by Edwin Dolby. Tower in poor condition.

LIST ENTRY NUMBER: 1192628 Contact: Zoe Kemp 01904 601911



SITE NAME: Church of St Helen, Church Lane, Marr Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation

Church of C12 origin. West tower added and rest remodelled C13 to early C14. South porch, tower parapet and spire added in C15. The church is constructed from rubble limestone with stone slate roofs. Roof coverings, rainwater goods, window tracery and masonry are in poor condition with failing temporary repairs.

© English Heritage

LIST ENTRY NUMBER: 1192644 Contact: Zoe Kemp 01904 601911



Church of St Mary Magdalene, SITE NAME: High Street, Norton Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation

1151464

LIST ENTRY NUMBER:

Large Perpendicular church of cruciform plan with embattled west tower and nave parapets. Elements of the structure date to the CI2, with CI3, CI4 and CI5 additions. The restored C12 west door has shafts to a four-order round arch, scalloped capitals and zig-zag ornament. Roofs, rainwater goods and masonry are in poor condition.

© English Heritage

Contact: Zoe Kemp 01904 601911

SITE NAME:	Castle Hills motte and bailey castle, Langthwaite, Ad	lwick le Street	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013654
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Moat Hills moated site, Bentley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Site of St Helen's Chapel, Barnburgh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004799
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Manor Holt moated site, Bawtry		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012453
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Moat Hall moated site and site of external ancillary	buildings, Braithwe	ell
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1012461
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Roman fort at Robin Hood's Well, Burghwallis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002930
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Roman potteries 300yds (270m) north east of Ross	sington Bridge, Can	tley / Rossington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004787
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Edlington Wood Roman settlement, Edlington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004824
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Moat Hill moated site, Fenwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011920
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Icehouse 720m south east of Bath House Farm, Hig	gh Melton	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020715
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Earthworks on Sutton Common, Norton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004816
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Rossington Roman fort, Rossington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004823
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jenny Lee 01904 601933
SITE NAME:	Thorpe in Balne moated site, chapel and fishpond,	Thorpe in Balne	
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1012111
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Tickhill Castle, Tickhill		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004828
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Giles Proctor 01904 601981
SITE NAME:	Hatfield High Street, Hatfield		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Malcolm Thomas (LPA) 01302 73519
SITE NAME:	Marr		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Malcolm Thomas (LPA) 01302 73519
SITE NAME:	St George's, Doncaster		
DESIGNATION:	Conservation Area, 2 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
/ULNERABILITY:	Low	CONTACT:	Malcolm Thomas (LPA) 01302 73519
ITE NAME:	Thorne Central, Thorne		
DESIGNATION:	Conservation Area, 15 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Malcolm Thomas (LPA) 01302 73519
SITE NAME:	Thorne Road, Doncaster		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Malcolm Thomas (LPA) 01302 73519

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

HERITAGE AT RISK 2014 / TORRSHIKE / DONCASTER / PEAR DISTRICT (NP) / ROTHERHAM			
SITE NAME:	Woodlands		
DESIGNATION:	Conservation Area, 26 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Malcolm Thomas (LPA) 01302 735199
PEAK DISTRICT (NF	<b>?</b> )		
SITE NAME:	Bailey Hill motte and bailey castle, High Bra	adfield, Bradfield, Sheffield	
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1013217

SITE NAME:	Bailey Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1013217
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Castle Hill motte and bailey castle, High Bradfield,	Bradfield, Sheffield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017612
	Generally satisfactory but with significant localised		D 10.0

SITE NAME:	Cowell Flat prehistoric field system 350m south e	ast of Mortimer Ho	use Bradfield Sheffield
OWNER TYPE:	Local authority	CONTACT:	Yvonne Luke 01943 605128
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017612

SITE NAME:	Cowell Flat prehistoric field system, 350m south east of Mortimer House, Bradfield, Sheffield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017833
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Yvonne Luke 01943 605128

#### **ROTHERHAM**



© Rotherham Metropolitan Borough Council

SITE NAME:	25 and 27, High Street, Rotherham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1132712 Known as The Three Cranes. Late medieval house. Signs of structural decay, faulty rainwater goods. Repair works are underway as part of the Rotherham Townscape Heritage Initiative.

Contact: Zoe Kemp 01904 601911



© English Heritage

SITE NAME:	Keppels Column, Admirals Crest, Thorpe Common
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1314632

Monumental column built 1773 to 1780. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. The internal staircase is unsafe.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© English Heritage

Thorpe Salvin Old Hall (ruins SITE NAME: of), Ladyfield Road, Thorpe

N/A

Scheduled Monument and Listed DESIGNATION: Buildings - 2 grade II\*

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1004788 and 1286372; 1314668 Contact: Zoe Kemp 01904 601911

1582) standing in an open courtyard.



© English Heritage

SITE NAME: Camellia House, Wentworth Woodhouse, Wentworth Listed Building grade II\*, RPG DESIGNATION: grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Private

Wentworth Estate. Set within the park remodelled by Humphry Repton in the early 1790s. The condition of the Camellia House has deteriorated, in part due to vandalism and the roof and glazing are in poor condition.

in the C18 and C19 gardens. Built as part of the

Early C19 conservatory incorporating mid-C18 section to

rear, situated approx 400 metres south west of the house

Gatehouse and imposing three storey south facade of mid C16 stone-built mansion built by Henry Sanford (died

LIST ENTRY NUMBER: 1286162 Contact: Giles Proctor 01904 601981



© English Heritage

Wentworth Woodhouse. Wentworth Listed Building grade I, RPG DESIGNATION: grade II\* CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (E)

Stable block and riding school,

Stable block and riding school, 1760s, situated approximately 300 metres north west of the house. The roof coverings are deteriorating and there is some structural damage. Discussions underway with the owner regarding repair and reuse.

OWNER TYPE: Private LIST ENTRY NUMBER: 1203779

SITE NAME:

Contact: Giles Proctor 01904 601981



SITE NAME: Church of All Saints, Church Street, Wath Upon Dearne DESIGNATION: Listed Place of Worship grade I CONDITION: Fair PRIORITY CATEGORY: F (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1132786

Church with north arcades and lower part of tower dating to C12. Nave and chancel rebuilt and added to in C13 and C14 and tower heightened in C14 or C15. Roofs, highlevel masonry and rainwater goods in poor condition. Grant offered under Repair Grants for Places of Worship and repairs are underway.

Contact: Zoe Kemp 01904 601911





SITE NAME:	Church of St Peter and St Paul, Todwick
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1151903

Medieval church with CII nave, CI4 chancel and CI5 tower with C18 and C19 alterations. Tower parapets and pinnacles are in poor condition.

@ PCC

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Contact: Zoe Kemp 01904 601911

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

SITE NAME:	Kimberworth motte and bailey castle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Roman Ridge: section 110yds (100m) long, 450yds	(410m) NNE of Kii	mberworth Park Farm
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004835
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman Ridge: section 400yds (370m) long from Hi	ll Top Lane to Little	e Common Lane
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004808
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman Ridge: section 400yds (370m) long in Wath	Wood	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman Ridge: south east of Hill Top (section 700y	ds (660m) long, Me	adowhall Road to Hill Top)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004807
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Swinton Pottery (The Rockingham Works), 310m	and 120m north we	est of Keeper's Cottage
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020067
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman Ridge (Roman road): section 135yds (120m	n) long, east of Hoo	ber House, Brampton Bierlow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004830
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TERMINGE / CITAGON 2014 / TOI	ACOUNTE / NOTTIEN I/A I / SHEITIELD		
SITE NAME:	Roman Ridge: section 400yds (370m) long south	of Abdy Farm, Bramp	oton Bierlow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004810
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Roman Ridge: section 500yds (460m) long, north	of Dog Kennel Pond	l, Wentworth Park, Wentworth
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1004832
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Doncaster Road, Rotherham Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Jonathan Bell (LPA) 01709 823811
SITE NAME:	Rotherham Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jonathan Bell (LPA) 01709 823811
SITE NAME:	Wales, Rotherham South		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jonathan Bell (LPA) 01709 823811

#### **SHEFFIELD**



_	Establish.	1. 5	

SITE NAME:	Entrance gateway to Green Lane Works, Green Lane
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company

Imposing entrance gateway, dated 1860, incorporating a tripartite triumphal arch flanked by relief panels depicting "Art" and "Industry" and topped with a pediment and cupola with clock stage and lantern. Rear masonry range, roofs and rainwater goods are in very poor condition and water ingress has caused internal timbers to decay. Grant awarded towards investigative works and urgent repairs. Forms part of housing-led redevelopment scheme with adjacent Eagle Works site, which has commenced.

LIST ENTRY NUMBER: 1255044 Contact: Craig McHugh 01904 601972



© English Heritage

SITE NAME:	Gateway and adjoining walls at garden entrance to Oakes Park, Norton
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

1271161

Early C18 and early C19 gateway with ornamental iron gates leading to C18 gardens. The gates are rusty and the gate piers are in poor condition. The park is also at risk. A grant has been accepted.

Contact: Nicola Brown 01904 601985

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



© English Heritage

SITE NAME:	Leah's Yard, 20-22, Cambridge Street, Sheffield
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)

Mid C19 cutlery/silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food/drink outlets proposed as part of urban regeneration scheme. Urgent repairs are to be undertaken, prior to shell repair.

Contact: Craig McHugh 01904 601972



© English Heritage Archive

SITE NAME:	Nonconformist Chapel, General Cemetery, Cemetery Road, Sheffield
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor

Local authority

1247012

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE:

LIST ENTRY NUMBER:

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1247073

LIST ENTRY NUMBER:

Cemetery chapel built in circa 1836. Lead has been stolen from the roof and not reinstated, risking further structural deterioration. Fundraising is in progress to restore the building and open it to the public.

Contact: Craig McHugh 01904 601972

Contact: Zoe Kemp 01904 601911



© English Heritage

SITE NAME:	Loxley United Reformed Church, Loxley Road, Bradfield
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1314565

Former United Reformed church of 1787, closed in 1994. Condition deteriorating.



© English Heritage

SITE NAME:	Seventh Day Adventist Church adjoining school and boundary wall, Andover Street
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1246453

Victorian chapel, now Seventh Day Adventist Church. Church 1865 by William Hill of Leeds. For the Methodist New Connexion, School dated 1862. Rock-faced stone with ashlar dressings and steep pitched gabled and hipped slate roofs with coped gables. Gothic Revival style. Roofs and rainwater goods in poor condition.



© English Heritage

SITE NAME:	Church of St Mary, Howard Road, Sheffield
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER	1270449

Parish church in the Gothic Revival style dating to 1869, with vestry added in 1928. Roof coverings and rainwater goods are in poor condition and water ingress has damaged internal finishes. Some glazing is in poor condition. Grant offered under Repair Grants for Places of Worship and repairs are underway.

Contact: Zoe Kemp 01904 601911

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.



SITE NAME:	Church of St Paul, Wordsworth Avenue, Sheffield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1376605

1960s church by Sir Basil Spence. Repairs carried out to body of church, but extensive repair needed to the concrete cloisters which extend from the front of the church. Some grant-aided repairs have been completed. Further phases are required.

Contact: Giles Proctor 01904 601981

© English Heritage

SITE NAME:	Roman Ridge: section 600yds (550m) long between	n Jenkin Lane (now	Road) and Tylers Street
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004806
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Little Matlock rolling mill immediately south and ea	ast of Olive Terrace	e, Bradfield
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1019857
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Handlands Romano-British settlement, 460m south west of Woodseats Farm, Ecclesfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017835
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Willow Garth moated site and fishpond, Ecclesfield	d, Ecclesfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012477
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Mousehole Forge, Malin Bridge		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004804
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Iron Age and Roman quern workings on Wharnclif	ffe Rocks, Stocksbri	dge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004802
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Yvonne Luke 01943 605128

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



© English Heritage

SITE NAME:	Oakes Park, Sheffield
DESIGNATION:	Registered Park and Garden grade II, 9 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1001160

LIST ENTRY NUMBER:

Gardens and pleasure grounds with early to mid C18 origins, an early C19 terrace and parkland probably of early C19 date. Park and gardens compromised by multiple use, condition of park is poor and listed structures in very poor condition.

Contact: Erika Diaz Petersen 01904 601901



© English Heritage

SITE NAME:	Sheffield General Cemetery
DESIGNATION:	Registered Park and Garden grade II*, 9 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001391

Cemetery of 1836 designed by Sheffield architect Samuel Worth (fl.1830) with a chapel, catacombs, a cemetery office and a layout which makes dramatic use of a quarried hillside site. An extension of 1846 for Anglican burials, laid out by Robert Marnock (1800 to 1889). The cemetery retains both its Anglican and Non-conformist chapels (listed grade II\*) the latter a building at risk. The site is owned by Sheffield City Council, with the buildings leased to multiple owners.

Contact: Craig McHugh 01904 601972

SITE NAME:	Furnace Hill, Sheffield		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	John Stonard (LPA) 0114 273 4472
SITE NAME:	Hillsborough Park		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	John Stonard (LPA) 0114 273 4472
SITE NAME:	Kelham Island		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	John Stonard (LPA) 0114 273 4472
SITE NAME:	Sheffield General Cemetery		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	John Stonard (LPA) 0114 273 4472
SITE NAME:	Well Meadow		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	John Stonard (LPA) 0114 273 4472
			, <i>,</i>

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

#### **WEST YORKSHIRE**

#### **BRADFORD**



© English Heritage Archive

SITE NAME Manningham Mill (ancillary buildings and boiler house), Heaton Street, Heaton, Bradford

DESIGNATION: Listed Building grade II\*, CA

CONDITION:

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1314426 Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion complete. Mill no longer at risk but ancillary buildings and boiler house are. Condition surveys of the at risk buildings have been completed with English Heritage grant aid. Grant offered for urgent repairs to perimeter wall.

Contact: Craig McHugh 01904 601972



© English Heritage

SITE NAME: Leventhorpe Hall, 1289 and 1291, Thornton Road, Lower Grange, Bradford DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

1133692

Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. The whole site has been granted consent for a residential scheme, but work has stalled.

Contact: Tammy Whitaker 01904 601880

Contact: Tammy Whitaker 01904 601880



SITE NAME:

LIST ENTRY NUMBER:

New Hall, Rooley Lane, Newhall

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Charity (non-heritage)

LIST ENTRY NUMBER: 1314521

LIST ENTRY NUMBER:

A fine C17 hall, built by the Richardson Family of Bierley Hall. Of gritstone with excellent detailing. New Hall was formerly the club house of West Bowling Golf Club, which has now been redeveloped for commercial use. The Hall is empty and deteriorating.



© English Heritage

© English Heritage

SITE NAME: Dalton Mills, all attached buildings and yard surface, Dalton Lane, Keighley DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: E (New entry) OWNER TYPE: Private

1134129

Worsted mill built between 1866 and 1877 for |&| Craven. The site comprises three multi-storey mills: Tower Mill, Genappe Mill and New Mill. There are also several ancillary buildings, an elaborate chimney and intact surviving machinery. The site was acquired by a new owner early in 2014 who has begun to implement a programme of phased repair and refurbishment to create a mixed commercial development. Tower Mill is occupied and in fair condition, Genappe Mill is in poor condition but is currently undergoing repair, New Mill and the building linking it to Genappe Mill are in very poor condition.

Contact: Zoe Kemp 01904 601911

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



© English Heritage

SITE NAME:	Mill Building at Low Mills, Low Mill Lane, Keighley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use

Commercial company

Commercial company

B (D)

1200162

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

OWNER TYPE:

Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use but little progress on site as yet.

Main four storey mill is in fair condition and in use. The Chimney was extensively repaired in 2005. The engine house, which retains its engine, is in poor repair, with cracking to the concrete roof and some water penetration.

Contact: Zoe Kemp 01904 601911

Repair proposals have been developed.



© English Heritage

SITE NAME:	Waterloo Mill, Howden Road, Silsden
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)

LIST ENTRY NUMBER: Contact: Giles Proctor 01904 601981 1266636



SITE NAME:	Church of St Clement, Barkerend Road
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184649

Church dating to 1894, of dressed limestone with a slate roof. Its principal feature of interest is the interior designed by Morris and Co. Grant-aided repairs to the nave and north aisle roofs have been completed, but the south aisle roof remains in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

© PCC



© English Heritage

SITE NAME:	Bradford Synagogue (Reform), Bowland Street, Bradford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1227613

Synagogue of 1880 to 1881 in the Islamic revival style by Francis and Thomas Healey. The principal elevation is of gold and red banded ashlar with bracketed eaves and an ornate pierced parapet. It has a central raised panel with a Hebrew inscription beneath the cresting incorporating the Star of David. Roof coverings and rainwater goods are in poor condition with water ingress causing damage to timbers, masonry and finishes. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Large church with prominent spire and crossing tower dating from 1847 to 1848 by architects Mallinson and

Contact: Zoe Kemp 01904 601911

Healy. Roofs are in poor condition.



© English Heritage

SITE NAME:	Church of St Paul and St Jude, Church Street, Bradford
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1133216

Contact: Zoe Kemp 01904 601911

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



SITE NAME:	Church of St Stephen, Donisthorpe Street, Bradford
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1133174

Victorian city church. The roofs are in poor condition, leading to extensive water penetration and timber decay throughout the church. Grant assisted works to repair the east end of the church have been completed. Repair works to the south elevation, with grant offered under the Repair Grants for Places of Worship scheme, are underway.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St John, Wakefield Road, Bradford
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1314137

Dating to 1842, this church was built at the expense of the Bowling Iron Company. The architects, RH and S Sharpe of York, were assisted by Fred Stott, works engineer at the Bowling Foundry, as its construction made extensive use of iron. Roof coverings, rainwater goods and cast iron windows are in poor condition.

Contact: Zoe Kemp 01904 601911

© English Heritage



Church of St Saviour, Ings Way, Fairweather Green, Bradford
Listed Place of Worship grade II
Poor
D (New entry)
Religious organisation
1392312

Church of 1966 with attached hall of 1971, both designed by architect George Pace. Characterized by asymmetric arrangement of roofs, exposed structure and juxtaposition of materials, this is a complete and largely unaltered example of Pace's work. The asphalt roof and windows are in very poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

© English Heritage

© English Heritage



SITE NAME:	Church of St James, Haworth Road Crossroads, Keighley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1266785

Parish church of 1909 to 1910 designed by JB Bailey & Son of Keighley. The building comprises nave with north and south aisles; chancel with organ chamber, vestry and sacristy and a north-west porch which was to have formed the lowest stage of a tower that was never built. Queen post nave roof and double hammerbeam chancel roof. Aisle windows incorporate interesting modern stained glass. Roofs, rainwater goods and clerestory windows are in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

(C)	English	Heritage
9	LIIGHSIII	1 ici icago

SITE NAME:	Church of St Mary the Virgin, Hebden Bridge Road, Keighley
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER:	1199947

Neo-Norman church of 1849 by Ignatius Bonomi and JA Cory. The west tower suffers from severe water penetration. Heritage Lottery Fund grant has been offered for project development.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG

**ABBREVIATIONS** 

OWNER TYPE:



SITE NAME:	St Michael and All Angels, Church Street, Haworth, Keighley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (F)

Religious organisation

Large Victorian church with C16 tower. Burial place of the Brontes. Roof coverings and rainwater goods to north elevation are in poor condition, as are the internal wall paintings. Repairs to roof coverings to the south elevation have been completed with grant offered in 2012. A Heritage Lottery Fund grant was offered towards the recovering of north roof slopes in 2014.

© English Heritage

LIST ENTRY NUMBER: 1283403 Contact: Giles Proctor 01904 601981



SITE NAME:	Church of St Paul, Kirkgate, Shipley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1133546

Commissioners' Church of 1823 to 1825 designed in the Perpendicular style by John Oates of Halifax. Roofs, rainwater goods, high-level masonry and glazing are all in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

Contact: Giles Proctor 01904 601981

© English Heritage



SITE NAME:	Church of St James, Thornton Road, Thornton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1133695

Large Victorian church with Morris glass. The roofs have recently been re-slated with the support of grant. A second phase of grant-aided repair, through the Heritage Lottery Fund Repair Grants for Places of Worship scheme, largely involving the conservation of the Morris glass, is underway.

© English Heritage

SITE NAME:	Cup and ring marked rock north of Pennythorn Hi	ll, Baildon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012684
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Cup-marked rock on slight bank north east of Glov	vershaw quarry, Bai	ldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009724
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Enclosed settlement known as 'Soldier's Trench' in	cluding a cup-marke	ed rock, Baildon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009718
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Yvonne Luke 01943 605128

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**

HERITAGE AT RISK 2014 / YORK	SHIRE / BRADFORD			
SITE NAME:	Round cairn and	curving bank on Pennythorn Hill	, Baildon	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1012683
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion -	moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Twelve Apostles	stone circle, Burley Moor, Burle	·y	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1011763
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion -	extensive	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Late prehistoric	enclosed settlement known as C	atstones Ring on Car	tstones Hill, Cullingworth
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1018240
CONDITION:	Generally satisfac	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Cairnfield, carve Reservoir, Ilkley	d rocks and associated curved ba	ink at north west end	d of Green Crag Slack, east of Gill Head
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1013872
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	Vandalism		No
OWNER TYPE:	Local authority		CONTACT:	Yvonne Luke 01943 605128
	SITE NAME:	Whinburn, Keighley		asure grounds partly laid out c1897 with
<b>一人</b>	DESIGNATION:	Registered Park and Garden grade II, 3 LBs	to 1938, with so Mawson and Sor	l landscaping and features dating from 191 me design work in the latter period by Th n. Formerly owned by Bradford City
	CONDITION:	Generally satisfactory but with minor localised problems	a number of year	private ownership. The site laid vacant for rs suffering decay and vandalism. The new e process of repairing the house and
	VULNERABILITY:	Low	grounds.	
是是無事人的	TREND:	Stable		
	NEW ENTRY?:	No		
English Heritage	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1001643	Contact: Erika D	iaz Petersen 01904 601901
SITE NAME:	Apsley Crescent	, Manningham, Bradford		
DESIGNATION:	Conservation Ar		NEW ENTRY?:	No
CONDITION:	Poor	,	TREND:	Deteriorating
VULNERABILITY:	Low		CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Devonshire Park	and Cliffe Castle, Keighley		
DESIGNATION:	Conservation Ar		NEW ENTRY?:	No
CONDITION:	Poor		TREND:	Deteriorating
VULNERABILITY:	Low		CONTACT:	Jon Ackroyd (LPA) 01274 433952
				, , ,

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

CITE NIAME	<b>6</b>		
SITE NAME:	Great Horton		
DESIGNATION:	Conservation Area, 42 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Heaton Estates		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Idle and The Green		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Little Horton Lane, Bradford, Trident		
DESIGNATION:	Conservation Area, 60 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	North Park Road		
DESIGNATION:	Conservation Area, 12 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Southfield Square, Manningham, Bradford		
designation:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	St Paul		
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	The Goitside, Bradford		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952
SITE NAME:	Thornton		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Ackroyd (LPA) 01274 433952

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### BRADFORD / KIRKLEES / LEEDS



© Battlefields Trust

SITE NAME:	Battle of Adwalton Moor, Drighlington
DESIGNATION:	Registered Battlefield, LB grade II
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1000000

The 1643 battle during the English Civil War on moorland outside Bradford in which some 14,000 men fought, gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

Aisled barn. One of the farm buildings of the Priory (now gone), with a C15 timber frame, which was later stoneclad. The north east corner of stables and north threshing porch appear to be unstable. The estate has recently changed hands and some maintenance has been carried

Contact: Keith Emerick 01904 601988

#### **CALDERDALE**



© English Heritage

SITE NAME:	Double aisled barn to north west of Kirklees Priory Gatehouse, Kirklees Park, Brighouse
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

out.

LIST ENTRY NUMBER: 1133848

SITE NAME:

LIST ENTRY NUMBER:

Contact: Tammy Whitaker 01904 601880



© English Heritage

	Kirklees Park, Brighouse
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Home Farm Building No. 6,

Early C17 cowhouse, two cell house, possibly slaughter house. Gable wall and roof partially collapsed and unstable.

LIST ENTRY NUMBER: 1133805

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME:	Kirklees Priory Gatehouse, Kirklees Park, Brighouse
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1314039

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs recently carried out and support scaffold in place. Reuse proposals have been drawn up following a recent change of ownership.

Contact: Tammy Whitaker 01904 601880

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# **ABBREVIATIONS**



© English Heritage

ITE NAME:	L-shaped aisled barn, Kirklee
	Park. Brighouse

Listed Building grade II\*, RPG DESIGNATION:

grade II

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1133808 Aisled barn, early C16, encased in stone during the early to mid-C17. Part of a little used farm complex. Area of roof missing to north and some timber decay to frame. Some maintenance has been undertaken following a recent change of ownership.

Contact: Tammy Whitaker 01904 601880

Malthouse, late C17. It forms part of a little used farm complex. The building is in a stable condition.



© English Heritage

SITE NAME: Malthouse, Kirklees Park, Brighouse

Listed Building grade I, RPG DESIGNATION:

grade II Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C) OWNER TYPE: Private

LIST ENTRY NUMBER: 1133809 Contact: Tammy Whitaker 01904 601880

Contact: Zoe Kemp 01904 601911



© English Heritage

SITE NAME: Former boiler house and attached chimney to north of Old Lane Mill, Old Lane

DESIGNATION: Listed Building grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1272533

Boiler house and integral chimney of 1827 to 1828, built to serve Old Lane Mill which is the oldest and largest surviving example of a multi-storey, steam-powered, iron-framed textile mill in Halifax. Not in use and in poor repair.



C (New entry)

DESIGNATION: Listed Building grade II\*

CONDITION: Poor


OCCUPANCY: Vacant/not in use

OWNER TYPE: Private

PRIORITY CATEGORY:

LIST ENTRY NUMBER: 1244144

Worsted mill of 1825 to 1828, the oldest and largest surviving example of a multi-storey, steam-powered, ironframed textile mill in Halifax. Unoccupied and in poor repair.





LIST ENTRY NUMBER: 1242456

C17 traditional stone house with C18 service wing and C19 west wing. Roofs are in poor condition with attendant decay.



© English Heritage

SITE NAME: Ovenden Hall, Ovenden Road DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Commercial company

Contact: Zoe Kemp 01904 601911

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



SITE NAME:	Scout Hall, Lee Lane, Halifax
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Private

1203783

LIST ENTRY NUMBER

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Late C17 house. Part repaired with English Heritage grant, part derelict. The repair and reuse of the building is under discussion with the Conservation Officer at Calderdale.

© English Heritage



SITE NAME:	Former lock-up, 121, Keighley Road, Illingworth, Halifax
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1314017

Located on the north side of the A629 Halifax to Keighley Road, the lock-up is a small two storey building of coursed sandstone walls and stone slate roof dated 1823. The building is vacant. The roof covering and roof drainage is in very poor condition. The North Halifax Historic Buildings Preservation Trust has completed a condition survey and options appraisal with a grant from the Architectural Heritage Fund. Calderdale Council is considering asset transfer to the Trust.

Contact: Tammy Whitaker 01904 601880

© English Heritage

LIST ENTRY NUMBER:

Broad Bottom Old Hall, SITE NAME: Mytholmroyd, Hebden Royd DESIGNATION: Listed Building grade II\* Fair Vacant/not in use C (C)

Late medieval timber-framed open hall which was encased in stone in the mid C16. Watertight but vacant for some

Late C16 aisled barn. Major failure of roof structure and

years. Vulnerable to decay without a sustaining use.



© English Heritage

CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: Private LIST ENTRY NUMBER: 1279330

Contact: Tammy Whitaker 01904 601880

loss of roof covering.

Contact: Craig McHugh 01904 601972



© English Heritage Archive

SITE NAME:	Barn to north west of Greenwood Lee, Widdop Road, Heptonstall
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1265719

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME:	Church of St Thomas Charlestown, St Thomas Street, Halifax
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation

1254025

A Victorian church, prominently located above Halifax. The roof slates and rainwater goods are in poor condition and the stonework is deteriorating.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG

Unitary Authority World Heritage Site



0	English	Haritago

© English Heritage

SITE NAME:	Church of St Peter, Town Gate, Halifax
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313775

Church of 1763 to 1766 in the classical style, based on the design for the Church of the Holy Trinity, Leeds. The building incorporates a nave with massive composite columns and horseshoe gallery, north organ chamber and vestry, apsidal sanctuary and three-stage west tower. The finely decorated interior is particularly noteworthy and includes Royal Arms dated 1766 flanked by four cartouches with coats of arms by Guiseppe Cortese, the Ten Commandments and relief figures of Moses and Jesus. Water ingress is causing damage to the finishes and decorations.

Contact: Zoe Kemp 01904 601911

SITE NAME: Christ Church, Wharfe Street, Sowerby Bridge Listed Place of Worship grade II, DESIGNATION: CONDITION: Fair PRIORITY CATEGORY: F (F) OWNER TYPE: Religious organisation


1313761

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Fine early C19 town church with prominent west tower. Lower parts of the church have been repaired with grant under Repair Grants for Places of Worship. Grant-assisted repairs to the tower roof and parapets are currently underway.

Contact: Zoe Kemp 01904 601911



SITE NAME:	Church of St James, Church Lane, Hebden Royd
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1229139

Early C19 Gothic church, with additions by Richard Norman Shaw. The roof covering and rainwater goods are in poor condition, with consequential damage to the interior. Heritage Lottery Fund development funding offered in September 2013 under Grants for Places of Worship scheme, and project development is in progress.

© English Heritage

Contact: Giles Proctor 01904 601981



© Engl	ish He	ritage	

SITE NAME:	Hope Baptist Church, New Road, Hebden Bridge, Hebden Royd
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Fair
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation

1230080

1857 classical chapel and Sunday School. Extensive repairs carried out to roofs and interior of church with grant offered in March 2012 under Repair Grants for Places of Worship. Further work is needed to the roofs of the vestries to the rear of the church, to the lower stonework and to the steps.

© English Heritage

SITE NAME:	Church of St Michael and All Angels, Burnley Road, Todmorden
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1133755

A Gothic/Tudor Revival church dating to 1902 with embattled west tower and octagonal spire. The building is constructed from hammer-dressed stone with ashlar dressings. Roofs, rainwater goods and masonry of north aisle, porch, clergy vestry and chancel are in poor condition with dry rot present in these areas. Tower and spire are also in poor condition. Grant offered under Repair Grants for Places of Worship.

Contact: Zoe Kemp 01904 601911

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise

'New entry' is noted.

HERITAGE AT RISK 2014 / YOF	RKSHIRE / CALDERDALE		
SITE NAME:	Camp at Kirklees Park		
DESIGNATION:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1005806
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Mill gas plant, Shaw Lodge Mills		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005783
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Ventilation chimney and furnace house 260m so	uth of Park Farm	
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1017655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Cairnfield on Ringstone Edge Moor, 240m south	west of Clay House,	Ripponden
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018560
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Akroydon		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Kate Peach (LPA) 01422 392265
SITE NAME:	Elland		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kate Peach (LPA) 01422 392265
SITE NAME:	Todmorden		
DESIGNATION:	Conservation Area, 47 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kate Peach (LPA) 01422 392265

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### **KIRKLEES**



© Kirklees Metropolitan Borough Council

SITE NAME: Milnsbridge House, 2-6, Dowker Street, Huddersfield

DESIGNATION: Listed Building grade II\*

CONDITION: Fair

Part occupied/part in use OCCUPANCY:

Private

PRIORITY CATEGORY: E (E)

LIST ENTRY NUMBER: 1290158 Mid C18 house now in engineering use. Pediments conceal modern flat roof. Scheme approved for residential conversion but works not yet commenced.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME: Boiler house, engine house, rope race, water tower and powerhouse at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield

DESIGNATION: Listed Building grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1271263

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME: Mill Dam at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield

DESIGNATION: Listed Building grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1271264

SITE NAME:

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.

An early C19 mill complex with some later C19 alterations.

Buildings include former scribbling, carding, and fulling mill, office, warehouse workshops, boiler and engine house.

Contact: Tammy Whitaker 01904 601880



© English Heritage

Mills, Lowestwood Lane, Interiors and roofs stripped for refurbishment. Part lacks roof covering.

North Range at Westwood

Contact: Tammy Whitaker 01904 601880

	Linthwaite, Huddersfield
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1216965

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© English Heritage

SITE NAME:	Offices and workshop ranges at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

1217132

Commercial company

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.

Contact: Tammy Whitaker 01904 601880

An early C19 mill complex, with some later C19

alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part

	3000
101	A part
None -	


© English Heritage

SITE NAME:	West Block at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Contact: Tammy Whitaker 01904 601880

Contact: Tammy Whitaker 01904 601880

lacks roof covering.



© English Heritage

SITE NAME:	Hopton Congregational Church, Calder Road, Mirfield
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1134675

1216966

Former church and attached school buildings to rear dated 1829. Largely unaltered and retaining box pews in the body of the church and original windows throughout. Water penetration has resulted in patches of timber decay and a failing roof truss. Planning Permission granted for enabling development subject to a Section 106 agreement over phasing of repair work to the church. Some repairs to roof already carried out.

SITE NAME:	Christ Church, Church Lane, Batley and Liversedge
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313710

1812 to 1816 by Thomas Taylor of Leeds. Gothic in style with west tower. Roofs are in poor repair. Grant offered under Repair Grants for Places of Worship and repair works are underway.

Contact: Zoe Kemp 01904 601911



© English Heritage

© English Heritage

SITE NAME:	Church of St Mary, Spen Lane, Cleckheaton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184613

1850 to 1851 by Dobson of Leeds, Gothic in style with a north-west tower. The tower is in poor condition and roofs at the east end of the church are leaking. Grant has been offered under Repair Grants for Places of Worship for repairs to the low-level roofs and the works are currently underway.

Contact: Zoe Kemp 01904 601911

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.



SITE NAME:	Church of St John, Boothroyd Lane, Dewsbury
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313651

Commissioners' church in Lancet style by Thomas Taylor dating to 1823 to 1827. Parapet gutters and rainwater goods are in poor condition and the tower shows evidence of structural movement. Water ingress has caused extensive damage to the internal plasterwork.

Contact: Zoe Kemp 01904 601911

© English Heritage




SITE NAME:	Church of All Saints, Church Street, Dewsbury
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1134712

Large parish church, raised to minster status in 1993, with stonework in the nave dating to c980, a north arcade of c1220 and medieval, Georgian and Victorian additions. Reordered in the 1970s, 1990s and early 2000s. Roofs and high level masonry are in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Michael, Church Street, Denby Dale
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1135290

Church in the Perpendicular style. South wall probably early medieval, the rest early C15 with slightly later tower and chapel of 1632. Tower roof, rainwater goods and south porch in poor condition. Grant offered under Repair Grants for Places of Worship and repairs are currently underway.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Stephen, Lidget Street, Huddersfield	
DESIGNATION:	Listed Place of Worship grade II	
CONDITION:	Poor	
PRIORITY CATEGORY:	D (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1134994	

1829 by John Oates of Halifax in Gothic style. Tower roof, masonry, rainwater goods and drainage in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Aidan, Radcliffe Street, Skelmanthorpe, Denby Dale
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1135306

St Aidan's was opened on September 28 1895. Urgent repairs have been carried out to the bellcote and chimney. Further roof repairs will be required in the near future.

© PCC

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument



SITE NAME:	Church of St Peter, Kirkgate, Huddersfield	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Fair	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1134977	

The present church is the third to have stood on the site and was built in 1836. The internal plaster work and the roofs have recently been repaired with grant offered under Repair Grants for Places of Worship. A further phase of grant-assisted work to repair the stonework is currently underway.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Thomas, Manchester Road, Huddersfield	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (D)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1134950	

Church of 1857 to 1859 by Sir George Gilbert Scott. Roofs and tower masonry in poor condition. Grant offered under Repair Grants for Places of Worship and works to repair north roof slopes have been successfully completed. Further phases of work are required to repair south roof slopes, tower and spire.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Mark, St Marks Road, Huddersfield
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1217677

Parish church of 1877 to 1882 in the Decorated style with south-west tower added in 1914. Roofs, rainwater goods and masonry are in poor condition.

© English Heritage



SITE NAME:	Church of St John, St John's Road, Huddersfield	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Fair	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1217625	

Fine Victorian church by William Butterfield with tower and spire. Works to stabilise and repair the east end of the church have been carried out with grant assistance under Repair Grants for Places of Worship; a further phase of work, to repair the north elevation of the building, is underway.

Contact: Zoe Kemp 01904 601911

Contact: Giles Proctor 01904 601981

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME:	Church of St Bartholomew, Greens End Road, Meltham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313662

Georgian church with early Victorian tower and late Victorian chancel. The tower has recently been repaired with grant. A further phase of repair is required, to recover the nave and transept roofs.

© English Heritage

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Mary, Church Lane, Mirfield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1134677

Large Victorian church dating from 1871, designed in the Early English style by Sir George Gilbert Scott. High-level tower masonry and tower roof covering are in poor condition, rainwater goods are also in poor condition. These defects are allowing water into the building, which is damaging the fabric and finishes of the church. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

#### © English Heritage

SITE NAME:	Emley Day Holes, 200m east of Churchill Farm, De	enby Dale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017656
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Late prehistoric enclosed settlement on Castle Hill	l, 550m north of Br	oadstone Lodge, Denby Dale
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018554
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tammy Whitaker 01904 601880
SITE NAME:	Medieval ironstone pits south of Bentley Grange, E	Denby Dale	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005786
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Crosland Lower Hall moated site, Meltham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013896
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Birkby, Huddersfield		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Nigel Hunston (LPA) 01484 2416924
SITE NAME:	Dewsbury		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Nigel Hunston (LPA) 01484 2416924
SITE NAME:	Edgerton, Huddersfield		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nigel Hunston (LPA) 01484 2416924

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

SITE NAME:	Holmfirth		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nigel Hunston (LPA) 01484 2416924

#### **LEEDS**



SITE NAME: Rothwell Castle, Church Street (off) DESIGNATION: Scheduled Monument, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

Ruined chapel to medieval manor complex. C14. Masonry needs to be consolidated. The site is part of an active Local Heritage Initiative scheme to investigate its surroundings.

© English Heritage

LIST ENTRY NUMBER: 1005792 Contact: Nicola Brown 01904 601985



SITE NAME: Stank Hall quasi-manorial site, Dewsbury Road Scheduled Monument and Listed DESIGNATION: Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Local authority

Remains of a major yeoman farm of sub-manorial type, with surviving barn of C15 of eight bays. Southern-most bays rebuilt in stone mid C17. Roof slates missing. Temporary roof now put in place.

LIST ENTRY NUMBER: 1002985 and 1375339 Contact: Nicola Brown 01904 601985



SITE NAME: Temple Works gate lodge, Marshall Street, Holbeck DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

Small derelict gate lodge to spinning, water, steam and flax mill of 1836 to 1840 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

© English Heritage Archive

LIST ENTRY NUMBER: 1375166

Contact: Craig McHugh 01904 601972



© English Heritage

SITE NAME: Ledston Hall, Hall Lane, Ledston Listed Building grade I, RPG DESIGNATION: grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D(D)OWNER TYPE: Private LIST ENTRY NUMBER: 1237569

Country house now partly subdivided into flats, situated in late C17 to C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. A conservation plan and strategic plan have been completed for the estate and discussions are ongoing about future long-term uses. A programme of priority repairs has been identified.

Contact: Craig McHugh 01904 601972

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



© English Heritage

First Leeds White Cloth Hall, SITE NAME: 98-101 (consecutive), Kirkgate,

Leeds

DESIGNATION: Listed Building grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1375042 An exceptionally rare example of an early C18 arcaded cloth hall, built in 1711. The building is derelict and deteriorating, the west wing was subjected to emergency demolition in 2010. Part of generally dilapidated block along Kirkgate, which has been included in a Heritage Lottery Fund Townscape Heritage Initiative programme.

Contact: Zoe Kemp 01904 601911



© English Heritage

SITE NAME: Temple Mill, Marshall Street, Holbeck, Leeds

DESIGNATION: Listed Building grade I, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (D)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1375162

The majestic Egyptian facade, by Ignatius Bonomi, 1836 to 1840 fronts a brick-vaulted spinning shed with circular roof lights. Failure of tie bar has caused collapse of two front bays. Other bays are vulnerable to similar failure. Proposals for structural repair have been developed and are under discussion.

Contact: Craig McHugh 01904 601972

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

SITE NAME: Hunslet Mill, Goodman Street, Hunslet, Leeds

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (D)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1256253 Flax mill of 1838 with later infill in south block. Housing development agreed, but not yet underway.




© English Heritage Archive

St Marys Convent Church SITE NAME: (Mount Saint Mary), Church Road, Richmond Hill, Leeds Listed Building grade II\* DESIGNATION: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1255558

Former Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing, the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development has received consent.



C (C)

© English Heritage Archive

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Tammy Whitaker 01904 601880

Local authority LIST ENTRY NUMBER: 1255642 Contact: Nicola Brown 01904 601985

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

PRIORITY CATEGORY:

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or ùser identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

#### **ABBREVIATIONS**



© English Heritage

SITE NAME:	Gazebo north of Clumpcliffe Farmhouse, Methley Lane, Methley, Rothwell
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use

B (A)

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

Private

1135669

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs has failed. Residential conversion has been agreed with consents issued in March 2014.

Former farmhouse, 1735. Unitary Development Plan proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling collapsed in one

Contact: Nicola Brown 01904 601985

© English Heritage

SITE NAME:	Thorpe Hall, Middleton Lane, Thorpe on the Hill
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

Private

1135039

Contact: Nicola Brown 01904 601985

room. Roof holed.



SITE NAME:

Sikh Temple (former Potternewton Park Mansion)

DESIGNATION:

Listed Place of Worship grade II

CONDITION:

Poor

PRIORITY CATEGORY:

D (New entry)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1256051

Originally known as Harehills Grove, this classical mansion was constructed in the early C19 for a local wool merchant. It was sold to the Leeds Corporation at the turn of the century and remained in educational use until 2006 when it was purchased for use as a Sikh Gurdwara. It is currently in poor condition due to extensive high level water ingress. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911



SITE NAME:	Church of the Epiphany, Beech Lane
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1255904

Grade I listed 1930s art deco church. Roofs, masonry and windows are in poor condition. Grants have been offered under Repair Grants for Places of Worship for phased repairs. The first phase of roof repairs has recently been completed and a second phase of work to repair the remaining roofs, masonry and windows is underway.

LIST ENTRY NUMBER: 1255904 Contact: Zoe Kemp 01904 601911



© English Heritage

© English Heritage

SITE NAME:	Church of St Mark, St Mark's Road
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1256144

Early C19 Commissioners' Church with fine west tower. Roof repaired with grant. A further grant was offered in March 2012 for tower, vestry roof and aisle stonework and work is ongoing.

Contact: Giles Proctor 01904 601981

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© English Heritage

SITE NAME:	Church of St John the Evangelist, New Street, Pudsey
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation

1214466

LIST ENTRY NUMBER

Gothic Revival style church dating to 1842 to 1843 by William Wallen of Huddersfield with west tower rebuilt c1895. Stained glass windows by William Wailes, Powell Brothers of Leeds, JW Appleyard and Kayll and Reed. Windows and rainwater goods are in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Zoe Kemp 01904 601911

Contact: Zoe Kemp 01904 601911

A PAR	

Church of St Paul, Whitehall Road, Morley

DESIGNATION: Listed Place of Worship grade II

CONDITION: Fair

PRIORITY CATEGORY: F (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1313446

Church in the Gothic Revival style dating to 1876 to 1878 with sanctuary remodelled c1928 by Sir Charles Nicholson. Roofs and windows in poor condition. Grant offered under Repair Grants for Places of Worship and repairs are underway.

© English Heritage

© English Heritage



SITE NAME:	Church of St Andrew, Haw Lane, Yeadon and Guiseley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1313171

Church by Thomas and Francis Healey dating to 1890 to 1891 in the Arts and Crafts Perpendicular style. Distinctive octagonal bell turret with wooden traceried bellcote and ogival cap. Roofs, rainwater goods and some glazing in poor condition. Bell turret also in poor condition. Water ingress has caused internal rot and damage to finishes. Grant offered under Repair Grants for Places of Worship and repairs are underway

Contact: Zoe Kemp 01904 601911



SITE NAME:	Church of St Mary, Town Street, Leeds
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1255815

Built in the Early English style to designs by RD Chantrell, this mid-C19 church was constructed on land conveyed by the local mine owner and local miners reputedly contributed a week's earnings or a week's unpaid labour to help with its construction. It survives much as originally built with the exception of the spire, which was taken down in 1939 due to subsidence. The west gable wall is in poor structural condition, masonry and roofs are also in poor condition.

Contact: Zoe Kemp 01904 601911

(C)	English	Heritage
•	LIIGHSII	1 ici icago

SITE NAME:	Cairn west of Craven Hall Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010355
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Medieval farmstead in Ireland Wood, 150m north ea	ast of Cookridge H	ospital
SITE NAME: DESIGNATION:	Medieval farmstead in Ireland Wood, 150m north ea	ast of Cookridge H	ospital 1018553
		_	·
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1018553

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
- solution agreed

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Stone hut circle settlement in Clayton Wood on the	ne south west side	of Iveson Drive
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018814
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Stone hut circle settlement in Iveson Wood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018815
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Howley Hall: a 16th century country house and gar	rdens, Morley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016323
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Settlement site revealed by aerial photography nea	r Moat House, Wal	ton / Wighill
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1003801
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
	SITE NAME: Oulton Hall		e grounds laid out in 1809 to 1810 in 1
	Registered Park and Garden	to designs by Humphry Repton, with mid CIS	



© English Heritage

SITE NAME:	Oulton Hall	Park and pleasure grounds laid out in 1809 to
DESIGNATION:	Registered Park and Garden grade II, 2 LBs, part in CA	to designs by Humphry Repton, with mid CI WA Nesfield. Chequered C20 history and no hotel and golf course. The De Vere hotel gro
CONDITION:	Generally satisfactory but with significant localised problems	the main building. The garden layout survives the golf course and new development predoi
VULNERABILITY:	Low	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000413	Contact: Erika Diaz Petersen 01904 601901

WA Nesfield. Chequered C20 history and now split as a hotel and golf course. The De Vere hotel group restored the main building. The garden layout survives in part but the golf course and new development predominate.



© English Heritage

SITE NAME:	High Royds Hospital, Aireborough
DESIGNATION:	Registered Park and Garden grade II, LB grade II
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001469

The grounds of an echelon-style psychiatric hospital, opened in 1888, including airing courts, sports grounds, woodland and parkland. The hospital is under conversion to residential use including extensive new build within the grounds. The historic landscape is now significantly compromised and peripheral areas neglected.

Contact: Erika Diaz Petersen 01904 601901

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

Buslingthorpe, Leeds			
Conservation Area	NEW ENTRY?:	No	
Poor	TREND:	Deteriorating	
High	CONTACT:	Phil Ward (LPA) 0113 247 8146	
NAME: Headingley Hill, Hyde Park and Woodhouse Moor, Leeds			
Conservation Area	NEW ENTRY?:	No	
Poor	TREND:	Deteriorating	
Low	CONTACT:	Phil Ward (LPA) 0113 247 8146	
Holbeck, Leeds			
Conservation Area	NEW ENTRY?:	No	
Very bad	TREND:	No significant change	
Medium	CONTACT:	Phil Ward (LPA) 0113 247 8146	
Stank Hall, Leeds			
Conservation Area, 3 LBs, SM	NEW ENTRY?:	No	
Very bad	TREND:	Deteriorating	
	Conservation Area Poor High  Headingley Hill, Hyde Park and Woodhous Conservation Area Poor Low  Holbeck, Leeds Conservation Area Very bad Medium  Stank Hall, Leeds	Conservation Area  Poor  TREND:  High  CONTACT:  Headingley Hill, Hyde Park and Woodhouse Moor, Leeds  Conservation Area  NEW ENTRY?:  Poor  TREND:  Low  CONTACT:  Holbeck, Leeds  Conservation Area  NEW ENTRY?:  TREND:  Low  CONTACT:  Stank Hall, Leeds	

#### WEST YORKSHIRE / NORTH YORKSHIRE

#### LEEDS / SELBY

SITE NAME:	Linear earthwork, part of the Aberford Dyke system, extending //0m east from Humphrey Dale Cottage, Aberford / Stutton with Hazlewood			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016953	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985	
	Linear earthworks known as Woodhouse Moor Rein and South Dyke, part of the Aberford Dyke system, Lotherton cum Aberford / Saxton with Scarthingwell			
SITE NAME:			, part of the Aberford Dyke system,	
SITE NAME:  DESIGNATION:			, part of the Aberford Dyke system,	
	Lotherton cum Aberford / Saxton with Scarthingv	vell		
DESIGNATION:	Lotherton cum Aberford / Saxton with Scarthingv Scheduled Monument Generally unsatisfactory with major localised	vell  LIST ENTRY NUMBER:	1016954	

#### **WEST YORKSHIRE**

#### WAKEFIELD



SITE NAME:	Crown Court House, Wood Street
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1258996

Built in 1810 in the neo-Greek style with extensions of 1849 to 1850. Two storeys, sandstone ashlar with banded rustication to all walls. Tetrastyle Doric pedimented portico with eight side steps to stylobate. Central door flanked by sash windows with glazing bars. Plain parapets to one-storey side wings. Set back two-storey left section has three pairs of windows and an entablature and blocking course continuous with return of main block. Unoccupied, grave condition. Roofs in very poor condition.

Contact: Giles Proctor 01904 601981

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## LPA NP RPG



© English Heritage

SITE NAME: Malt House approx 15 metres south west of Blacker Hall Farmhouse, Crigglestone

Branch Road, Chevet Listed Building grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

LIST ENTRY NUMBER:

LIST ENTRY NUMBER

OWNER TYPE: Private

LIST ENTRY NUMBER: 1135604

Rare early-mid C17 malt house located approx 15 metres south west of Blacker Hall Farmhouse. Impressive group value. Recent partial collapse of front wall, roof covering missing, roof timbers collapsing. Imminent danger of total collapse. English Heritage grant completed for project development work. Longer term solution agreed.

Contact: Tammy Whitaker 01904 601880

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey has been prepared. Grant has been awarded for the first three phases of



© English Heritage

SITE NAME:	Pontefract Castle, Pontefract
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Local authority

1010127

Contact: Nicola Brown 01904 601985

repair. Emergency works complete.



© English Heritage

SITE NAME:	The Hermitage, Southgate, Pontefract
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Health authority

1135427

The Hermitage consists of two below ground chambers hewn out of sandstone. The deeper chamber dates from 1386 and consists of a short corridor which leads to a spiral stair which descends to a well. The second chamber, known as the Oratory, is later and consists of a spiral stair which leads to a cell with altar and fireplace. At risk due to flooding. Following completion of a Hydrological Survey a solution to flooding has been identified and is being implemented.

Rock-faced magnesian limestone church dating to 1878 in

C12 northern French style to designs of Sir Arthur Blomfield. Roofs, masonry and windows are in poor

Contact: Nicola Brown 01904 601985

condition.



© English Heritage

SITE NAME:	Church of St John, Jackson Lane, Darrington
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1135502

SITE NAME:

Church of All Saints, Ackton Lane, Featherstone DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: F (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1288962

Late medieval church in the Perpendicular style restored in the late C19 and re-ordered in the late 1990s. Roofs, masonry and rainwater goods are in poor condition. Grant offered under Repair Grants for Places of Worship and repairs to the chancel are currently underway.

© English Heritage

Contact: Zoe Kemp 01904 601911

Contact: Zoe Kemp 01904 601911

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

I PA ΝP RPG



SITE NAME:	Church of the Holy Trinity, Church Street, Ossett
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184049

Victorian church with central tower and spire. Mostly in good repair but stonework and glazing to the east elevation is in poor condition. Work to repair the west end has recently been completed with a grant offered under Repair Grants for Places of Worship and grant-assisted repairs to the east end are currently underway.

Contact: Zoe Kemp 01904 601911

© English Heritage



SITE NAME: Church of St Giles, Market Place, Pontefract Listed Place of Worship grade DESIGNATION: II\*, CA Poor CONDITION: PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER:

Medieval and Georgian town church. South elevation masonry recently repaired under Repair Grants for Places of Worship. North elevation stonework and aisle roof in poor condition. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

© English Heritage

1135461

Contact: Zoe Kemp 01904 601911

SITE NAME:	Earthwork west of Ferrybridge, Knottingley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005789
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Newland Preceptory, Newland with Woodhouse I	Moor / Normanton	
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1012153
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Sharlston Common coal and ironstone workings, S	harlston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018399
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nicola Brown 01904 601985
SITE NAME:	Site of post-medieval tannery, Felkirk, South Hiend	lley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Yvonne Luke 01943 605128
SITE NAME:	Prehistoric enclosed settlement known as South K	irkby Camp, South	Kirkby and Moorthorpe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018818
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Health authority	CONTACT:	Nicola Brown 01904 601985

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**

#### YORK (UA)



© English Heritage

SITE NAME: Church of St Paul, Holgate Road, York Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (New entry)

1257544

Church of 1850 to 1851 by JB & W Atkinson, in the Early English Style. Three parallel roofs, walls of rock-faced sandstone. The west bellcote and the flanking pinnacles are severely decayed and stone is falling from high level. Heritage Lottery Fund project development funding has been offered under the Grants for Places of Worship scheme.

Contact: Giles Proctor 01904 601981

Contact: Giles Proctor 01904 601981

Places of Worship and works are underway.

© English Heritage

SITE NAME: Church of St Thomas, Lowther Street, York DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1257401

Religious organisation

Victorian church with severe erosion to the stonework of the transept gables and also at low level. Recent repairs have been carried out to the west gable and nave walls but further repairs will be needed.

Late C12 church with earlier origins, restored in 1879. Bell turret, high-level stonework and glazing in poor condition.

Grant offered in December 2012 under Repair Grants for

© English Heritage

OWNER TYPE:

LIST ENTRY NUMBER:

SITE NAME: Church of St Mary, Jackson's Walk, Askham Richard Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Fair PRIORITY CATEGORY: F (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1316686

Contact: Giles Proctor 01904 601981

SITE NAME:	The Nestle / Rowntree Factory, York		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Janine Riley (LPA) 01904 551305
SITE NAME:	The Racecourse and Terry's Factory, York		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Janine Riley (LPA) 01904 551305

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

## **ABBREVIATIONS**



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2014 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST