Heritage at Risk



Contents

The Register	III
Content and criteria	III
Criteria for inclusion on the Register	V
Reducing the risks	VII
Key statistics	XI
Publications and guidance	XII
Key to the entries	XIV
Entries on the Register by local planning authority	XVI
County Durham (UA)	[
Northumberland (UA)	П
Northumberland (NP)	27
Tees Valley	34
Darlington (UA) Hartlepool (UA) Middlesbrough (UA) North York Moors (NP) Redcar and Cleveland (UA) Stockton-on-Tees (UA)	34 35 36 37 37 40
Tyne and Wear	40
Gateshead Newcastle upon Tyne North Tyneside South Tyneside Sunderland	40 42 45 46 47

II

THE REGISTER

Content and criteria

LISTING Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of listed assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the system of statutory protection of heritage assets. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now over 400,000 assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Digital, Culture, Media and Sport who makes the decisions on whether an asset is listed. Understanding and appreciation develop constantly, which makes keeping the listing database up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of listing a site, and better communication of what makes something special.

In June 2016 Historic England launched Enriching the List, a crowdsourcing initiative opening up the entries on the National Heritage List to contributions by users. Anyone can register as a volunteer and submit extra information about assets on the List or submit photographs to illustrate them. This additional content will then be available for anyone to view with (but separate from) the official List Entry.

Alongside the nationally listed assets found on the National Heritage List for England are locally listed assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is the most commonly encountered type of statutory protection of heritage assets. A listed building (or structure) is one that has been granted protection as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Digital, Culture, Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly important buildings of more than special interest; together they amount to 8.3% of all listed buildings. The remaining 91.7% are of special interest and are listed grade II. There are over 378,000 entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory List.

Structures can occasionally have dual List entries (be both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. Nearly 20,000 examples have been listed because of their national importance. Scheduled monuments are not graded. They cover human activity from the Paleolithic era, such as cave sites, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record. The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic sites that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside.

Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and, often most seriously of all, wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not scheduled. Instead, they are managed through the planning system and other regimes.

Ш

REGISTERED PARKS AND GARDENS

There are over 1,600 landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II*, and the Gardens Trust on sites of all grades. The setting of other listed heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of listing. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where often thousands were killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now nearly 50 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive and damaging metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

PROTECTED WRECK SITES

There are over 50 protected wreck sites in England, which represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to list a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are listed by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For over 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis.

There are currently nearly 10,000 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of listing. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections, depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England;
- a grade I or II* listed building;
- a grade II listed building in London;
- a structural scheduled monument with upstanding remains;
- in secular (non-worship) use.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of

buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern, or are believed to no longer be at risk.

Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. An overall category for condition, vulnerability and trend is included for each conservation area on the Heritage at Risk Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

One of the primary aims of the <u>Historic England</u> <u>Corporate Plan 2017-2020</u> is protecting places through Heritage at Risk grants and advice, thereby reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grant aid to help remove sites from the Register.

Dedicated Heritage at Risk teams in our regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, www.historicengland.org.uk. Key publications and

guidance are also listed in this Register. **BUILDINGS AND STRUCTURES**

Historic England regional teams can help owners and local authorities better understand buildings and

structures at risk, advise on necessary repairs and on finding new uses. Our teams can provide support with commissioning specialist surveys, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the expertise of Historic England's national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law.

Historic England can help with access to funding. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk and Section 17 Management Agreements (which are smaller grants for scheduled monuments). More information on funding can be found on the Historic England website. The support of other grant providers, including the Heritage Lottery Fund, the Architectural Heritage Fund and Natural England, is also critical.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We also know that heritage, when well cared for, helps create vibrant and successful places. Our regional teams are therefore working with local authorities to encourage them to develop their own strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our legal team can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and help fund their regional support officers to work across the country. They help BPTs and other not- for-profit organisations to access funding, carry out feasibility studies and develop solutions for places at risk. The <u>Heritage Trust Network</u> is also a valuable source of advice. Further guidance and case studies are available on the <u>Historic England</u> website.

PLACES OF WORSHIP

Historic places of worship are cared for by thousands of volunteers throughout the country. Sometimes these treasured buildings will require major repairs. However, regular maintenance will help prevent minor problems developing into unnecessary crises. Keeping drains and gutters clear is essential: the overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable. In some

areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The practical resources created by the Maintenance Cooperatives Project run by the Society for the Protection of Ancient Buildings are available from their website. These are a great starting point for local groups wanting to work together to do basic, regular maintenance safely.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. Our advice web pages help congregations understand how changes can be achieved. The Heritage Lottery Fund welcomes applications from places of worship seeking to do repairs, develop facilities or welcome more visitors.

A network of support officers, employed locally but part-funded by Historic England, offers direct advice and encouragement to congregations. Projects to achieve repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

From September 2018 to March 2020 the Department for Digital, Culture, Media and Sport is funding a pilot study to explore a slightly different approach. This is focusing on fabric maintenance (supported by a small grant fund) and community development to explore opportunities for wider engagement beyond the congregation in voluntary, social and commercial sectors. Pilot schemes, which cover listed places of worship of all denominations and faiths, are running in Greater Manchester and Suffolk.

The Government's <u>Listed Places of Worship scheme</u>, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

ARCHAEOLOGY

The continued excellent progress which is being made with reducing the number of scheduled monuments on the Register demonstrates the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agri-environment

grant schemes to best effect. This has been especially important under the Countryside Stewardship Scheme, where our advice has resulted in the removal of 29 sites from being at risk this year. Our work in partnership with Natural England on agrienvironment schemes has removed well over 800 scheduled monuments from the Register since 2009 and we therefore welcomed the recognition given to the value and importance of heritage within the 25 Year Environment Plan and the Agriculture Bill. The Bill proposes that the conservation of rural heritage will be one of the environmental public goods funded through the domestic successor to the Common Agricultural Policy after the UK leaves the European Union. We also continue to work closely with local trusts, volunteers and the Heritage Lottery Fund to identify the nationally important monuments for enhanced conservation, presentation and access projects which is providing increased public value and enjoyment of our heritage.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register, affecting 38% of archaeological entries on it. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke recommendations for each monument, enabling cultivation to continue where it does not present a risk. It will also be an important tool for advising owners on the longer term management of their monuments as the existing ten year Environmental Stewardship agreements expire.

Although great progress has been made, analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites. Such vegetation growth, combined, makes up 30% of the risk factors affecting monuments at risk. To help address one of these key risk factors Historic England have been working with landowners and scientists to research and provide guidance on bracken control.

In most cases simple, low cost but regular maintenance is the key, with such improvements in management removing 36 sites from the Register this year alone. The delivery of these will always be reliant upon the help and goodwill of landowners. We are also sponsoring a number of projects to help volunteers and the public to get involved – which not only helps owners but also promotes wellbeing and public understanding of heritage.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities.

Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the NPPF makes it clear that registered battlefields are 'assets of the highest significance', and of equal significance to scheduled monuments, buildings listed grade I and II*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage policy and legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contributes towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra and Natural England through environmental stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of

ploughing and as part of a wider drive to prevent unauthorised and damaging metal detecting.

Local authorities invite comments from Historic England and the Battlefields Trust on planning applications that affect registered battlefield sites.

Historic England also continues to encourage greater access to battlefields and the enhancement of their amenity value. We wish to ensure an increased understanding and wider appreciation of the ways that these dramatic historic events have shaped our nation.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival. Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from <u>Historic England</u>.

CONSERVATION AREAS

Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them, as well as those of us whose job it is to manage them or make decisions about their future.

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management.

Local authorities assess conservation areas and fill in a questionnaire for those newly at risk, giving us an

insight into the issues which have had a negative effect upon the conservation area, and so help us to establish how these issues can be addressed.

Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area questionnaires we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 834 (3.7%) of grade I and II* listed buildings (excluding places of worship) are on the Register. In the North East the percentage is 6.1% (59 listed secular buildings).
- 3 building or structure entries have been removed from the 2017 North East Register because their futures have been secured, and 4 have been added.
- 71.3% of buildings or structures (82) on the North East baseline 1999 Register have been removed because their futures have been secured, compared to the national figure of 64.4%.

PLACES OF WORSHIP

- Nationally, 6.2% of listed places of worship are on the Register. In the North East, 6.1% (30) are on the Register.
- 7 places of worship have been removed from the North East Register following repair work, and 2 have been added.

ARCHAEOLOGY

- 2,431 (12.2%) of England's 19,852 scheduled monuments are on the Register. 170 (12.2%) of the North East's 1,397 scheduled monuments are on the Register.
- 5 archaeology entries have been removed from the 2017 North East Register for positive reasons, and 8 have been added.
- 40.6% of archaeology entries (69) on the North East baseline 2009 Register have been removed for positive reasons, compared to the national figure of 47.7%.

• Nationally, damage from arable cultivation is the greatest cause of risk affecting 38.3% of archaeological entries on the Register. In the North East the proportion is 27.1%. The greatest risk, to 33.1% of entries on the North East Register is from unrestricted plant, scrub and tree growth. The national figure for plant, scrub and tree growth is 26.4%.

PARKS AND GARDENS

- 99 (5.9%) of England's 1,664 registered parks and gardens are on the Register. Of the 55 registered parks and gardens in the North East, 6 (10.9%) are on the Register.
- No park and garden entries were added or removed from the 2017 North East Register.

BATTLEFIELDS

• Of the 47 registered battlefields in England, 4 (8.5%) are on the Register. Of the 6 registered battlefields in the North East, 1 (16.7%) is on the Register.

WRECK SITES

 Of the 53 protected wreck sites around England's coast, 4 (7.5%) are on the Register. The North East's single protected wreck site is not on the Register.

CONSERVATION AREAS

- There are currently 502 Conservation Areas on the Heritage at Risk Register. Of these 31 are in the North East.
- I conservation area has been removed from the 2017 North East Register for positive reasons, and I has been added.

HISTORIC ENGLAND FUNDING

• £1.15 million in grant was spent on 18 entries on the North East Register during 2017/18.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

<u>Assessment of Heritage at Risk from</u> <u>Environmental Threat: Key Message</u> (2013)

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – <u>Historic</u> <u>England Research News 21</u>, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

Heritage at Risk 2010 - Report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2018 – national summary leaflet

<u>Heritage at Risk Online Register</u> – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database.

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire.

<u>Historic Wreck Sites at Risk: A Risk</u> <u>Management Toolkit</u> (2017)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2016)

<u>Vacant Historic Buildings: Guidelines on</u> <u>Managing Risks</u> (2018)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit <u>Heritage at Risk</u> where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database. Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address.

GUIDANCE NOTES AND APPLICATION FORMS FOR GRANTS

<u>Historic England Grant Schemes</u> – online overview of all our current grant schemes, including the Repair Grants for Heritage at Risk scheme.

<u>Grants to Local Authorities to Underwrite Urgent</u> Works Notices

Acquisition Grants to Local Authorities to Underwrite Repairs Notices

Repair Grants for Heritage at Risk

CONSERVATION ADVICE AND GUIDANCE

The following publications are among the numerous guidance documents available for free on <u>Historic England Advice</u> web page:

Conservation Area Designation, Appraisal and Management (2018)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

<u>Conservation and Management of War</u> <u>Memorial Landscapes</u> (2016)

<u>The Conservation, Repair and Management of War Memorials</u> (2015)

Guidance on Constructive Conservation

Guidance on Improving Streets and Public Spaces

Guidance on Looking after Historic Buildings

<u>Guidance on Looking after Historic Cemeteries and</u> Burial Grounds

<u>Guidance on Looking after Historic Parks, Gardens</u> <u>and Landscapes</u>

Guidance on Looking after Places of Worship

<u>Guidance on Protecting the Rural Historic</u> Environment

Guidance on Tackling Heritage Crime

<u>Heritage Works: a Toolkit of Best Practice in</u> <u>Heritage Regeneration</u> (2017)

<u>Latest Advice and Guidance</u> – this web page highlights our most recent advice on a wide range of heritage-related topics.

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2017)

Metal Theft from Historic Buildings. Prevention, Response and Recovery (2017)

<u>Practical Building Conservation</u> – revised ten-part series: Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing, Glass & Glazing; Metals; Mortars, Renders & Plasters; Stone; Timber (2012–2015)

<u>Pillars of the Community: the Transfer of Local</u> <u>Authority Heritage Assets</u> (2015)

<u>Post-War Public Art: Protection, Care and Conservation</u> (2016)

<u>Registration Selection Guide: Battlefields</u> (2017)

<u>Scheduled Monument Consents: A</u>
<u>Guide for Owners and Occupiers</u> (2014)

The Disposal of Heritage Assets: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

The Installation of Telecommunications Equipment, Including Broadband and Mobile, in Churches and Other Listed Places of Worship (2017)

Key to the entries

The Register includes the following risk assessment types:

• Building or structure

(grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)

Place of worship

(grade I, II* and II listed buildings)

Archaeology

(scheduled monuments – earthworks and buried archaeology)

• Park and garden

(Registered parks and gardens)

Battlefield

(Registered battlefields)

Wreck site

(Protected wreck sites)

Conservation area

(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

LISTING

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
HE Historic England
HLF Heritage Lottery Fund
LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site
RB Registered Battlefield

RPG Registered Park and Garden SM Scheduled Monument

SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
COUNTY DURHAM (UA)							
County Durham (UA)	25	6	22	I	0	0	9
NORTHUMBERLAND (UA)							
Northumberland (UA)	31	7	52	2	0	0	2
NORTHUMBERLAND (NP)							
Northumberland (NP)	2	0	46	0	0	0	0
TEES VALLEY							
Darlington (UA)	2	2	1	0	0	0	3
Hartlepool (UA)	0	2	2	0	0	0	4
Middlesbrough (UA)	0	0	0	0	0	0	2
North York Moors (NP)	0	0	2	0	0	0	0
Redcar and Cleveland (UA)	5	2	3	I	0	0	3
Stockton-on-Tees (UA)	2	0	0	0	0	0	0
TYNE AND WEAR							
Gateshead	6	I	2	0	0	0	I
Newcastle upon Tyne	6	5	2	2	0	0	0
Newcastle upon Tyne / Gateshead [†]	0	0	0	0	I	0	0
North Tyneside	0	0	0	0	0	0	1
South Tyneside	2	I	0	0	0	0	3
Sunderland	5	3	1	0	0	0	3
Sunderland / Gateshead [†]	1	0	0	0	0	0	0
TOTAL	87	29	133	6		0	31

 $The sub-region Tees \ Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton- on -Tees and North York Moors National Park$

 $^{^\}dagger$ Sites that cross local planning authority boundaries

COUNTY DURHAM (UA)



© Historic England

No.4, and castle wall incorporated, North Bailey

DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (non-heritage)

LIST ENTRY NUMBER: | |2|42|

The castle walls in this section are of varying periods, from the medieval through to modern repair. The walls are in a poor condition, with open joints, eroding foundations and structural cracks. Management of the walls is impeded by difficulty of access. A Historic England grant has been awarded for project development and a detailed scheme for repair is currently in preparation.

C12 castle wall with base of angle tower. Consists of

coursed squared sandstone. Suffering from progressive

collapse of wall face and the core requires urgent attention

to avoid further substantial failure. A Historic England grant

has been awarded for project development and a detailed

Contact: Sara Rushton 0191 269 1222

scheme for repair is currently in preparation.



© Niven Architects

Castle Wall, behind 3, North Bailey, Durham and Framwellgate

DESIGNATION: Listed Building grade I, CA

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: B (B)

Charity (non-heritage)

LIST ENTRY NUMBER: 1322845

Contact: Sara Rushton 0191 269 1222



© Historic England

West Mural Tower at Auckland Castle, Auckland Castle, Auckland Castle Park, Bishop Auckland

DESIGNATION: Listed Building grade I, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (heritage)

Two-storey tower in the grounds of Auckland Castle, part of the west precinct wall. Probably C15 with later alterations. The building is in a highly fragile state. Historic England funded a condition survey and other project development work in 2014. Discussions are underway about a further Historic England grant to enable the completion of substantial repairs in 2018. The site is located in the Bishop Auckland Heritage Action Zone.

LIST ENTRY NUMBER:

TENTRY NUMBER: 1196445 Contact: David Farrington 0191 269 1230

© Historic England

SITE NAME:

Brancepeth Castle, Brancepeth

DESIGNATION:

Listed Building grade I, RPG
grade II, CA

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

D (D)

OWNER TYPE:

Private

LIST ENTRY NUMBER:

1159012

Brancepeth Castle is a medieval fortress that was greatly enlarged in the C19 by architects John Paterson and (later) Anthony Salvin. It was occupied by the army during World War II and then by glassware makers, J A Joblings. Parts of the building are currently occupied while others are used for events and other activities. Some urgent repairs have been completed in recent years, including major works in 2018 with Historic England funding. Further repairs are being planned. Options for developing the site's business potential are also being explored.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME: Hedleyhill Colliery coke works, 500 metres south west of Hazlet House, Brandon and Byshottles / Hedleyhope DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private LIST ENTRY NUMBER: 1018230

C18-C19 lines of brick-built coke ovens. Many bricks have been dislodged by livestock sheltering within the ovens. Livestock has also eroded the grassy banks between each oven and established tree growth occurs along the entire structure.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LOCal Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

Unitary Authority
HS World Heritage Site

I

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Lamb Bridge, Lambton Park, Bournmoor / North Lodge
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1120952

Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, first Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Some works have been undertaken, including on-going structural monitoring. A substantive repair programme has yet to be undertaken but options are now being explored to help secure the long-term future of the various historic buildings and structures on the estate.

Contact: Rosie Brady 0191 269 1231



© Historic England

SITE NAME:	Church, 50 metres north east of Croxdale Hall, Croxdale Hall, Croxdale and Hett
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Medieval former church with nave dating back to late CII and chancel to late C12. Altered in later centuries but Norman south doorway contains the original door with iron hinges. On the Croxdale Estate and rarely opened up. There is severe damp in the building, both rising damp in the floors and walls and penetrating damp over the chancel

LIST ENTRY NUMBER: 1019820 and 1120740; 1120741 Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME:	Durham Prison Officers' Club, ('The Tithe Barn'), Hallgarth Street, Durham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1120616

C15 granary building, erroneously known as 'The Tithe Barn', forming part of an important group of medieval farm buildings. The building lies outside the secure perimeter of the adjoining prison and is used as part of the Prison Officers' Club. The roof, stonework and close-studded upper floor require attention. Repointing of the barn has been completed but further works are required, particularly to the granary.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Prebends' Bridge, Durham and Framwellgate
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA, WHS
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Bridge over the River Wear designed in 1772-8 by George Nicholson for the Dean and Chapter of Durham Cathedral. The masonry of the arches has deteriorated significantly in recent years; however, a programme of remedial works, part-funded by Historic England, was completed on the southern arch during 2011-12. Works have yet to be completed on the northern arch.

Religious organisation LIST ENTRY NUMBER: 1002337 and 1121354

Contact: Kate Wilson 0191 269 1221



© Historic England	
--------------------	--

Ushaw Home Farm, main block and wall attached, Esh
Listed Building grade II*
Poor
Vacant/not in use
A (A)
Charity (non-heritage)

1185963

Part of a planned farm, constructed 1851-2 to designs by Joseph Hansom. Of three storeys, the main range is built into the bankside so that the lower two floors have ground level access. Two attached side wings and a projecting central bay create an E-shaped plan. Many original internal features survive. There is general deterioration to most external elements, including missing or displaced verge stones to some gable ends, defective rainwater goods and cracking to masonry walls. Many areas of slipped or displaced roof slates are allowing the ingress of rainwater.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Former Junior Seminary Chape of St Aloysius, Ushaw College, Ushaw, Esh
DESIGNATION:	Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use PRIORITY CATEGORY:

A(A)OWNER TYPE: Charity (non-heritage)

1299434 LIST ENTRY NUMBER:

Former Roman Catholic junior seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. Temporary urgent repairs were undertaken at the end of 2015 to stop significant water ingress caused by heritage crime. Discussions are in progress to define an economically viable strategy for the site as a whole and to ensure the early completion of a substantive phase of permanent repairs to the chapel.

Contact: Kate Wilson 0191 269 1221

	W.
	4
	A
	A
型加速等等	

© Historic England

SITE NAME:	Dovecote, 45 metres south of Gainford Hall, Gainford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1121116

C17 dovecote in the grounds of Gainford Hall. Vegetation removal, stone repairs and repointing are required.

Contact: Kate Wilson 0191 269 1221



SITE NAME:	Gainford Hall, Low Road, Gainford
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Manor house circa 1600-1603, substantially restored in the late-C19. A condition survey was completed in 2004 with funding from Historic England. Discussions are underway about a programme of substantive repairs to the roofs and external walling.

Former chapel. A rare survival of a private manorial chapel dating to the C13-C14. A buttress was built in 2008 to support the leaning southern wall; however, further consolidation and repointing work is required.

© Historic England

LIST ENTRY NUMBER: 1323010

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Medieval chapel at Harbour House Farm, Plawsworth, Kimblesworth and Plawsworth
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002325 and 1120959

Contact: Tom Gledhill 0191 269 1203



SITE NAME: Iron gates and railings, Lambton Castle, Lambton Park, North Lodge Listed Building grade II*, RPG DESIGNATION: grade II CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (C)

Posts, gates and railings on the north west drive to Lambton Castle, forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, Historic England grant-aided a condition survey with costed priorities for repair works. Further analysis is now being carried out which will inform their subsequent restoration.

© Historic England

OWNER TYPE: Private LIST ENTRY NUMBER: 1311161

Contact: Rosie Brady 0191 269 1231

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	ò
	3
7	

© Historic England

SITE NAME:	Church of St Mary, Rokeby Rokeby
	List of Deciding a second of UK DDA

Listed Building grade II*, RPG DESIGNATION: grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Private LIST ENTRY NUMBER: 1121673

Contact: Kate Wilson 0191 269 1221



© Historic England

Gateway, Mortham T Rokeby	Ower,
DESIGNATION: Listed Building grade I grade II*	, RPG
condition: Poor	

OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1160832

Late-medieval gateway to grade I medieval fortified manor house, set within landscaped Rokeby Park (registered grade II*). There is structural movement in the gateway. A support scaffold has been installed due to safety concerns. The flanking courtyard walls are also showing signs of deterioration with some invasive plant growth.

Former parish church, consecrated in 1778 with the chancel added in 1877. It stands on high ground within Rokeby Park (registered grade II*) and just 30 metres from

the relentless A66. The building has been subject to

multiple instances of heritage crime leading to water ingress. Discussions are underway about its future.

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME:	Sherburn House Bridge, Shincliffe
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1002341

Mid-medieval stone bridge, dating from 1335 but upper part rebuilt at unknown later date. Tree growth and water ingress has started to push out masonry, as evidenced by pronounced gaps running throughout the structure. Drainage channels empty adjacent to the bridge abutments and this compounds the ongoing erosion.



© Historic England

SITE NAME:	Brandon Walls lead mine, Stanhope
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1015831

LIST ENTRY NUMBER:

Mid-C19 lead mining complex situated on the east bank of the Rookhope Burn. The site was abandoned around 1903 and some elements of the complex are now in need of conservation action.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME: Middle Level lead mine, Greenlaws, Daddry Shield, Stanhope Scheduled Monument and Listed DESIGNATION: Buildings - 6 grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1015828 and 1231495; LIST ENTRY NUMBER: 1231496; 1231634; 1231675; 1278086; 1278087

C18 and C19 lead mine suffering from extensive flood damage and erosion problems. A Conservation Management Plan has been prepared. Funding to deliver the necessary repair works has yet to be identified.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Westgate Primitive Methodist Chapel, Westgate, Stanhope
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Charity (heritage)

1232510

Former Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior & Atkinson and incorporating parts of an earlier C19 chapel. Investigative works and urgent repairs, part-funded by Historic England, were completed in 2013. While an agreed viable use for the chapel and schoolroom has yet to be found, an updated condition assessment and conservation statement have been prepared to help inform a management plan. Urgent roof repairs were carried out in 2017 with funding from Historic England.

Contact: Kate Wilson 0191 269 1221

	No.	
		n=
T/X		

© Historic England

SITE NAME:	Coke ovens at Inkerman Farm, Tow Law / Cornsay
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1018228

Post-medieval beehive coke ovens. The management of the site was reviewed in 1998 with the involvement of Tow Law Town Council, which had a local heritage initiative. Historic England grant-aided the consolidation works, excavation and recording of finds. The initial repair programme is complete and half of the site is now open to the public. However, consolidation of the rest of the site is still required.

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME:	Clock Tower, Windlestone Hall, Windlestone Park, Windlestone
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Early-C19 clock tower and stables gateway by Ignatius Bonomi. The cupola was repaired with a Historic England grant in 1989, but stonework repairs and general maintenance are now needed. The clock faces have been removed.



© Historic England

SITE NAME:	Windlestone Hall, Windlestone Park, Windlestone
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1160327

LI II VAZ: II

1160369

Large house, circa 1835, by Ignatius Bonomi for Sir Robert Johnson Eden. Surrounded by gardens and parkland and a cluster of estate buildings, including stables. Serious metal theft and vandalism in 2016 / 2017 has left the building in a serious condition. A temporary roof cover has been installed and discussions are taking place with a new owner about its re-use.

Contact: Martin Lowe 0191 269 1233

Contact: Martin Lowe 0191 269 1233



© Historic England Archive

SITE NAME:	Harperley Working Camp, World War II Prisoner of War camp at Craigside, Wolsingham
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020730

Very rare surviving example of a World War II Prisoner of War camp. Used by both German and Italian prisoners of war. 85% of original buildings are in roofed condition and wall paintings and internal fittings have also survived. Following a series of investigative surveys, a programme of conservation works, funded by Historic England, commenced in 2011. A second phase of work to the canteen and theatre was completed in 2013. Discussions are now underway with the owner to secure the completion of a programme of urgent works to some of the other buildings.

Contact: Lee McFarlane 0191 269 1239

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBREVIATIONS		
CA LB LPA	Conservation Area Listed Building Local Planning Authority	
NP RPG	National Park Registered Park and Garde	
SM UA WHS	Scheduled Monument Unitary Authority World Heritage Site	



SITE NAME:	Christ Church, Church Street, Consett
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1242728

Christ Church was built in 1866 in a distinctive Neo-Norman style. It has a squat west tower and semicircular chancel. The tower is in need of a comprehensive programme of repairs due to open cracks, voids and eroded pointing.

Contact: Kate Wilson 0191 269 1221

© Historic England



SITE NAME:	Church of St Mary Magdalene, Broomside Lane, Belmont
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1159108

Designed by the influential Victorian architect, William Butterfield, the Church of St Mary Magdalene was consecrated in 1857. It consists of a simple nave and chancel; there are no aisles and no tower. A north porch was added in 1889 and a vestry in 1901. The external stonework at the base of the main perimeter walls is deteriorating. Funding was awarded in 2017, through the Heritage Lottery Fund Grants for Places of Worship scheme, to enable a programme of essential repairs to be drawn up. Those repairs are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

© Historic England



Church of St Anne, Market SITE NAME: Place, Bishop Auckland Listed Place of Worship grade II, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1292201

Church of 1846-8 by William Thompson, on the site of a medieval chapel. Tall aisled nave with clerestory windows, gabled south porch and distinctive west belfry. Chancel with organ chamber and vestry. A first phase of repairs to the north roof slopes was completed in 2015 through funding from the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme. Funding to enable a second phase of repairs to the south roof slopes, and to areas of high-level stonework, is being pursued. The site is located in the Bishop Auckland . Heritage Action Zone.

Contact: Kate Wilson 0191 269 1221

© Historic England



SITE NAME:	Church of St Andrew, Dalton- le-Dale
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1231690

A small medieval church, St Andrew's consists of an aisleless nave and continuous chancel. It has a late-C12 north doorway. Repair works to address water ingress at the west end of the nave were completed in 2017 with a Listed Places of Worship Roof Repairs Grant. Funding was awarded in 2017, through the Heritage Lottery Fund Grants for Places of Worship scheme, for a supplementary phase of works to alleviate dampness and to conserve the deteriorating stonework of the north doorway. Those works are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

© Historic England



© Historic England

SITE NAME:	Church of St Helen, Church Kelloe, Kelloe
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1120748

St Helen's has a west tower and nave of Norman origin. The C13 chancel was substantially rebuilt in 1854 and refitted in 1901. Repairs to alleviate water ingress to the chancel were completed in 2017 with a Listed Places of Worship Roof Repairs Grant. Funding was awarded in 2017, through the Heritage Lottery Fund Grants for Places of Worship scheme, to enable the repair of areas of decaying and deeply eroded external stonework. Those repairs are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

Church of St Mary, Town End, SITE NAME: Middleton in Teesdale

Listed Place of Worship grade II, DESIGNATION: CA

CONDITION: Poor

PRIORITY CATEGORY: D (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1322768

The present church was built in 1878 on the site of an earlier building. Defective gutters and downpipes, together with leaking gable coping stones and other roof details, are causing water ingress. An unsuccessful application to the Heritage Lottery Fund Grants for Places of Worship scheme was made in 2017. Other funding options are being explored.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Derwentcote steel cementation furnace, iron finery forge and drift coal mine		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1015522
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	English Heritage	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Barnard Castle: ringwork, shell keep castle, chapel	and dovecote, Barr	nard Castle
DESIGNATION:	Scheduled Monument, 2 LBs, CA	LIST ENTRY NUMBER:	1007505
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	A cairn, a carved rock and a rubble bank, in the south west corner of Scale Knoll Allotment, 800 metres south east of Far East Hope, Barningham Moor, Barningham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017431
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Cairnfield partly enclosed by a bank, on the east sign Moor, 550 metres south of Hurst Hill, Barningham		Gill, Scale Knoll Allotment, Barningham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Carved rock and cairn in Rowley Intake, 410 metro Barningham	es south east of Co	wclose House, Barningham Moor,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Carved rock and prehistoric enclosure on west sid Haythwaite, Barningham Moor, Barningham	e oi scale Kiloli Gi	ii, Tio ilieu es soudi west oi
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017440
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Prehistoric enclosure 530 metres, and a rubble bar Barningham Moor, Barningham	ık 500 metres, east	of Haythwaite in Scale Knoll Allotme
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Ring cairn 350 metres east of Haythwaite, Barningh	nam Moor, Barning	ham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017424
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Unenclosed settlement, 260 metres south east of G	Cowclose House, B	Barningham Moor, Barningham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017423
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Grange and chapel, Bear Park, Bearpark		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002346
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Enclosures and industrial workings on Cockfield Fell, Cockfield / Evenwood and Barony / Lynesack and Softley		
DESIGNATION:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1002314
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Lee McFarlane 0191 269 1239
SITE NAME:	Remains of the Stockton and Darlington Railway, E	therley / Shildon / '	West Auckland
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, part in CA	LIST ENTRY NUMBER:	1002315 and 1159141; 1160402
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial lise) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Roman period native settlement at Calf Holm, imm	ediately west of Di	ine Holm Scar, Forest and Frith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019162
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Packhorse bridge, Headlam		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1002359
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native settlement and a bloomery 10	60 metres north we	est of Bleabeck Force, Holwick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017120
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Two Romano-British hut circles and three shielings Holwick	on Holwick Scars,	250 metres south of Hungry Hall,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019455
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Lanchester Roman fort (Longovicium), Lanchester		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Area of carved bedrock, 120 metres south of The	Rigg, Lartington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018253
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Carved bedrock with cups and grooves, 170 metre	s south east of The	e Rigg, Lartington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018251
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Cup, ring and groove-marked rock 170 metres south west of West Loups's, Cotherstone Moor, Lartington			
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1016595
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Natural erosion -	moderate	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Four areas of car	ving on a rock outcrop 200 metre	s south west of Th	e Rigg, Lartington
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1018250
CONDITION:	Generally unsatist problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion -	extensive	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Pike Law lead hu	shes and mines, Newbiggin / Fores	t and Frith	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1015835
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing	Animal burrowing - extensive		No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
	SITE NAME:	Croxdale Hall, Croxdale and Hett	A late-C18 walled garden accompanying a country houset in parkland of early to mid-C18 origin. The walled garden and lakes are by the designer Lewis Kennedy. Croxdale Hall has been the seat of the Salvin family sin the C15. Maintenance of the gardens has fallen back in recent years and the waterbodies are in poor and deteriorating condition. The notable 'cranked' walls flathe orangery are in an advanced state of decay. Historic England has carried out recent research into the significance of the walled garden and is in discussion withe owner regarding future management.	
	DESIGNATION:	Registered Park and Garden grade II*, 17 LBs, 2 SMs, part in CA		
	CONDITION:	Generally unsatisfactory with major localised problems		
	VULNERABILITY:	Medium		
) Historic England	TREND:	Declining		
, riscorie England	NEW ENTRY?:	No		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1001271	Contact: Chris N	1ayes 0191 269 1226
SITE NAME:	Annfield Plain, St	anlev		
DESIGNATION:	Conservation Are	,	NEW ENTRY?:	No
CONDITION:	Very bad	,	TREND:	Deteriorating
	, -			

SITE NAME:	Annfield Plain, Stanley		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Bishop Auckland		
DESIGNATION:	Conservation Area, 72 LBs, part in RPG grade II*, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Bowburn, Cassop-cum-Quarrington		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	David Sparkes (LPA) 03000 267125

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

TERMITAGE / CETTO /	THE REPORT OF STATE O		
SITE NAME:	Cockfield		
DESIGNATION:	Conservation Area, 10 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Kirk Merrington, Spennymoor		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Seaham		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Shildon		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Trimdon Village, Trimdon		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Windlestone Park, Windlestone		
DESIGNATION:	Conservation Area, 17 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly

NORTHUMBERLAND (UA)



SITE NAME: Akeld Bastle and attached walling to south, Akeld DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Unknown PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER:

This late-medieval bastle has random rubble walls over one metre thick and a tunnel vault on the first floor. The original doorway in the west wall has a chamfered surround with drawbar holes. The upper storey appears to have been rebuilt in the C16 or C17 and incorporates a dovecote with five stone alighting ledges in the north gable. The Welsh slate roof is in poor condition and has a hole caused by the adjacent ash tree rubbing on it.

1042370 Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME: Holmslinn lead mine, 200 metres south east of Holmes, Sinderhope, Allendale Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

A series of standing and buried remains of one of four mine shafts in the East Allen valley. The shaft, 70 metres deep, was dug in 1855. The tower base enclosing the shaft, the engine bed and wheel pit (grade II listed) is being damaged by tree roots. Parts of the wheel pit collapsed in 2011. A broad repair solution has been agreed, and a Management Plan prepared, with support from Natural England. Funding has yet to be identified for the necessary works.

Private LIST ENTRY NUMBER: 1015848 and 1154939

OWNER TYPE:

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

OWNER TYPE:



© Historic England

SITE NAME:	Bondgate Tower, Bondgate Within, Alnwick
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use

A(A)

Private

1006597 and 1041513

The east gate of the former town wall, built circa 1450 by the second Earl of Northumberland. Consists of a recessed central portal between two projecting semi-octagonal towers. The main defects relate to damage from high-sided vehicles passing through the central portal. Further impact of a similar nature could cause a serious collapse.

Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME:	General Lambert's House, 31 and 33, Narrowgate, Alnwick
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1041425

and a basement. Most of the original interior detailing is still present. The building is vacant and deteriorating due to a lack of maintenance. A condition survey has been prepared and the owner has consent to convert the building to a new use. A Historic England grant was offered in early 2018 to allow for survey work and urgent repairs to the building to take place, which will be completed by mid 2019.

Early-C19 townhouse in plain ashlar, with three storeys

Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME:	Woodhorn Colliery, east & west shaft head gear and Walker fan house, Ashington
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority

1016976

The first shaft to the former Woodhorn Colliery was sunk in 1894. Production stopped in 1981 and the site opened as a museum in 1989. Repairs were completed to the east shaft head gear and enclosing structure in 2014. Significant corrosion has reappeared and the enclosing structure is leaking. The roof to the adjoining Walker Fan House is also leaking and the steelwork to the west shaft head gear is corroding and in need of repair. Discussions are underway about a prioritised programme of capital repair and maintenance works to the site as a whole.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Hydraulic silo, 70 metres east of Cragend Farmhouse, Cartington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1153196

Experimental hydraulic silo, circa 1895, by Lord Armstrong. Linear plan comprising a rectangular silage bay on each side of a taller cross-gabled centre. The interior contains a hydraulic engine and turbine. Repairs have been completed to the roof of the central section. A further phase of works is required to bring the external envelope back into full repair. Options are being explored for the building's repair and potential use.

Remote C15 tower house in a poor state of repair. Part of Little Swinburne shrunken medieval village. Surrounded by fallen masonry and in need of urgent attention to prevent further falls. A repair scheme has been identified but has

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Little Swinburne Tower, Little Swinburne, Chollerton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011412 and 1044908

Contact: Kate Wilson 0191 269 1221

yet to be implemented.

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME: Walker's Pottery, Corbridge

DESIGNATION: Scheduled Monument and Listed Buildings - 2 grade II*, 2 LBs

CONDITION: Poor

OCCUPANCY: N/A
PRIORITY CATEGORY: A (New entry)

LIST ENTRY NUMBER:

OWNER TYPE:

OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1006441 and 1155212; 1370576

The site includes the standing and buried remains of a postmedieval pottery. The two bottle kilns were repaired through an Historic England Repair Grant in 2016. The remainder of the site suffers from a lack of long term maintenance and several of the buildings are in a poor condition.

Remains of a medieval single-span bridge of early-C16 date, spanning the River Till near Twizel Castle. It is believed to be the largest single-arched medieval bridge in England. The bridge retains its medieval appearance and character and has been the subject of some repairs, probably in the C18, but no major strengthening works. Superseded by a modern road bridge to the south in the 1980s. The eastern abutment is leaning to south and has structural issues. In 2017-18 conservation re-pointing was done to arch and

Contact: Sara Rushton 0191 269 1222



© Historic England

SITE NAME:	Twizel Bridge, Cornhill-on- Tweed / Duddo
DESIGNATION:	Scheduled Monument, LB grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1020743

abutments. Issues still need addressing to stop water ingress at east abutment.

Contact: Lee McFarlane 0191 269 1239



© Historic England

SITE NAME:	Twizel medieval tower house and folly, Twizel, Duddo
DESIGNATION:	Scheduled Monument and Listed Building grade II*, part in RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

The present building incorporates the remains of a medieval tower house which continued to be developed and added to into the C19. Much of the C19 structure was demolished and the building, which was once five storeys high, now stands to three storeys. The site has been subject to longstanding lack of regular maintenance. It shows signs of structural instability, including substantial vertical cracks around many of the arches and window openings. A measured survey has been completed and discussions are underway to develop a repair scheme.

LIST ENTRY NUMBER: 1018445 and 1042168

Private

Contact: Sara Rushton 0191 269 1222



© Historic England

SITE NAME:	Ford Castle, Ford
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1371004

Originally a C14 quadrilateral castle with four corner towers, converted to a mansion in 1694 and further altered in 1761 (for John Hussey Delaval) and 1862 (for the Marchioness of Waterford). Now used for residential courses and as a venue for functions. A number of repairs have been undertaken to address the areas most affected by rainwater ingress, but further work is required. A programme of repairs is in progress.

Contact: Rosie Brady 0191 269 1231



© Historic England

SITE NAME:	Ford Colliery, Ford
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1020746 and 1154125

Monument including above and below ground remains of Ford Colliery. The colliery worked from at least the middle of the C17 through to 1919. The site includes the engine house chimney which was repaired in 2008-9. A condition survey has been prepared for the engine house and pit head. A programme of archaeological recording and borehole investigations has informed the preparation of a full repair scheme, funded by Historic England. The repair scheme now needs to be implemented to enable public access to these structures.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Entrance gates to Hartford Hall, Hartford Bridge, West Bedlington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Unknown

1041381

later stalled when the then owners of the estate went into administration. The gates are now in safe temporary storage. An updated condition assessment was completed with Historic England funding in 2014 and options to try and secure a sustainable long-term solution are being explored. A Historic England funded project in 2017 has catalogued and placed in storage all smaller elements for

Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. Historic England offered grant-aid towards the repair of the gates, but that project

future conservation works.

Contact: Kate Wilson 0191 269 1221

	10.10		
AF.		127 A	N

© Historic England

SITE NAME:	North west pillbox, Fort House, A193 (east side off), Hartley, Seaton Sluice, Seaton Valley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private

1041329

Pillbox or defensible latrine, circa 1917. Rare survival as part of a World War I fort. Suffering from structural problems and lack of maintenance. A repair scheme has been drawn up with funding from Historic England but this project has subsequently stalled and a solution is yet to be finalised and implemented.

Contact: Rosie Brady 0191 269 1231



@ Northumberland Council

SITE NAME:	Water tank, Fort House, A193 (east side), Hartley, Seaton Sluice, Seaton Valley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1303566

Water tank incorporating former ablutions building, built circa 1917 and a rare survival of part of a World War I fort. Suffering from structural problems and lack of maintenance. A repair scheme has been drawn up with funding from Historic England but this project has subsequently stalled and a solution is yet to be finalised and implemented.

The site consists of the scheduled remains of four defended

Contact: Rosie Brady 0191 269 1231



© Historic England

SITE NAME:	Pair of bastles, north-west of the Green at Chesterwood, Haydon Bridge, Haydon
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (F)

Private

farmhouses dating from between 1575 and 1650. Those to the south and west of the Green have recently been repaired and converted to residential use. The pair to the far north-west of the Green are not actively used and are deteriorating. There are areas of loose, unstable and openjointed stone walling. Discussions are underway with the owner to help bring forward a programme of repairs.

LIST ENTRY NUMBER:

OWNER TYPE:

1006432 and 1042501; 1154494: 1154518

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Stublick Colliery beam engine house, Haydon
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1370425

The beam engine house is part of the Stublick Colliery site -the finest group of early-C19 colliery buildings in the region. Although other grade II* buildings on the site are in fair condition, the engine house is in urgent need of repair. The ground around the colliery buildings was scheduled in November 2003.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

	, ,
SITE NAME:	Crawley Tower (with cottage inside), Crawley, Hedgeley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1057698

Remains of an early-C14 tower house, with an C18 cottage built inside when the ruins were altered to form an eyecatcher on the Shawdon Estate. Constructed of massive squared stone; the cottage with a slate roof. The interior is now gutted and contains structural propping. The tower is vacant with no identified use, although the adjacent buildings form part of a working farm. A budget for project development work has been identified.

Contact: Kate Wilson 0191 269 1221



LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

SITE NAME:	Hepple Tower, Hepple
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Private

1371440

C14 ruined tower. The south wall stands to almost 40 feet but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of stone and pointing decay. A repair scheme grant aided by Historic England is starting on site in summer 2018.

Contact: Tom Gledhill 0191 269 1203

. 20	-		
	4		
	AH	#1	

© Historic England

© Historic England

SITE NAME:	Union Suspension Bridge (that part in England), Horncliffe
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

1042214

Spanning the border of Scotland and England across the River Tweed, the bridge was built in 1820. It is Britain's oldest suspension bridge in road use. Some repairs have been undertaken but further substantial works are required to safeguard the structure in the long-term. A first round Heritage Lottery Fund grant was awarded in March 2018 to enable a comprehensive repair scheme to be drawn up. Historic England is continuing to offer technical advice and support as part of a cross-border partnership of local Councils and other groups.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Bastle, 100 metres south west of Ray Cottages, Kirkwhelpington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1011107

Ruined medieval defended farmhouse, situated in the grounds of Ray Castle, with 1.4 metres thick stone walls standing to a maximum height of 2.2 metres. Recent clearance of mature vegetation has reduced the risk of disturbance, although some areas of loose, displaced or unstable stones remain. Discussions are underway to help establish a planned maintenance and repair regime for the

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Capheaton tilery, Mirlaw House, Kirkwhelpington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006418

Tilery built for the Kirkharle Estate c I 800. Masonry and the brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help secure its long-term future.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Barmoor Castle, Barmoor, Lowick
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1156023

Country house of 1801 that incorporates earlier masonry. The building received grant-aid towards repairs in 1986 but further deterioration has occurred. A grant was offered by Historic England in 2011 towards a package of project development works. That work, which included the preparation of a conservation plan and condition survey, is helping to inform discussions about the site's future.

Contact: David Farrington 0191 269 1230



@ Northumberland Council

SITE NAME:	Pithead baths at Lynemouth Colliery, Lynemouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Mitford Castle, Mitford

1156081

style. Vacant for over twenty years and subject to vandalism. There have been recent discussions with the new owner of the site about the repair and re-use of the structure.

Pithead baths of 1938 by FG Frizzell in Modern Movement

Contact: Martin Lowe 0191 269 1233



LIST ENTRY NUMBER:

SITE NAME:

	DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade I
	CONDITION:	Poor
	OCCUPANCY:	N/A
	PRIORITY CATEGORY:	D (D)
	OWNER TYPE:	Commercial company
		1017210 and 1042/4E.

Late-C11 motte and bailey castle converted to a shell keep in the C12. The five-sided keep of the C13 includes a C12 curtain wall, curtain wall structures and mid-C12 chapel. It is now a roofless ruin but capable of consolidation. Grantaided photographic recording for the castle is now complete. Historic England offered grants towards three phases of the repair programme, the first two of which are now complete.

1017318 and 1042645: LIST ENTRY NUMBER: 1370756; 1042647; 1042646;

1370755

Contact: Kate Wilson 0191 269 1221



© Historic England

© Historic England

SITE NAME:	Cocklaw Tower, East Cocklaw, Wall
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

C14 tower containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first floor barrel-vaulting. Areas of the wall tops are vulnerable and there has been a partial collapse of the vaulting. The wall paintings show recent loss and are highly vulnerable. Recent, and on-going, discussions with owner on options to record and secure the paintngs from further loss.

PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006602 and 1156641

Contact: Mike Collins 0191 269 1212



© Historic England

SITE NAME:	Church of St Mary, Woodhorn, Newbiggin by the Sea
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER	1304471

Former parish church with surviving pre-Conquest elements. Significant rebuilding work took place throughout the C12 and C13 before a major rebuild was carried out in 1843-44 by B & J Green architects. The church closed as a place of worship in 1972 and was subsequently used as a museum and workspace for artists. Structural movement has been identified in some parts of the building and other repairs are required. Discussions are underway to help secure the church's repair and future use.

Contact: David Farrington 0191 269 1230

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Carrshield lead mines and ore works, Carrshield, West Allen
DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNED TYPE	Privato

Private 1015849 and 1155612; 1303252; 1042930; 1042931; The remains of two lead mines and an ore works on the base and lower slopes of the West Allen valley at Carrshield. The site was used over three centuries. The grade II lodging shop is the largest of its kind in the North Pennines but has severe structural damage and parts of the stone wall revetment have collapsed into the river. Exploratory works have identified options for the repair and consolidation of the revetment and work is progressing. Building repairs to the lodging shop are taking place in 2018 with funding from Historic England and Active Northumberland.

Contact: Tom Gledhill 0191 269 1203



© Historic England

Mausoleum, east of Seaton Delaval, Seaton Valley

DESIGNATION: Listed Building grade II*, RPG grade II*, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

1042932

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1154937 Contact: Chris Mayes 0191 269 1226

Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early-C18 landscaping incorporating earlier and later features. The mausoleum is roofless and subject to graffiti and vandalism. Urgent works were funded by Historic England in 1994, but further works are required to the building and its setting.



© Historic England

SITE NAME:

Simonburn Castle, Castle Lane, Simonburn

DESIGNATION:

Scheduled Monument and Listed Building grade II

CONDITION:

Very bad

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

A (A)

1012414 and 1302543

Private

C13 tower house with C18 Gothick style additions to create a folly. The basement vault has suffered some collapse and there is damaging vegetation growth. The building is in need of urgent repair. A Management Agreement was established with the owner to clear some of the vegetation.



© Historic England

SITE NAME:

Sharpe's Folly, Rothbury,
Tosson, Whitton and Tosson

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Fair

OCCUPANCY:

Vacant/not in use

PRIORITY CATEGORY:

D (D)

OWNER TYPE:

Commercial company

Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 feet high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Discussions are underway with the owner, Local Authority and Historic England to secure urgent repairs.

Contact: Kate Wilson 0191 269 1221

LIST ENTRY NUMBER: 1155472

SITE NAME: Church of St Michael, Alnham

DESIGNATION: Listed Place of Worship grade I

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: | 1303455

St Michael's has a nave with west bellcote, chancel, transepts and a south porch. It dates largely to the late-C12/early-C13, but there are Saxon stones at the northeast and south-east corners of the nave. The building was restored in 1870. There is some internal water ingress due to problems with the stone-slated roofs and related roof details. Rainwater gutters and pipes also need overhauling. Funding has been awarded, through the Heritage Lottery Fund Grants for Places of Worship scheme, to allow a

Contact: Kate Wilson 0191 269 1221

programme of repairs to be completed in 2018.

Contact: Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

© Historic England

A Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBR	EVIATIONS
CA LB	Conservation Area Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



0	Llic	tor	ic	En	~l~	n	4

SITE NAME:	Church of St George, Prudhoe
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1044950

The original church was built in 1825. Cruciform in plan, the present building dates almost entirely from an extensive remodelling in 1886. The red tiled roof coverings have reached the end of their serviceable life due to corroded fixings and require replacement. Funding was awarded in 2016, through the Heritage Lottery Fund Grants for Places of Worship scheme, for re-roofing works. Those works are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

CONTROL OF THE PARTY OF THE PAR
A LANGE BERTHAM

© Historic England

© Historic England

SITE NAME:	Church of St Cuthbert, Church Street, Haydon
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER:	1154530

passed in the C18. It has an elegant west tower, narrower than the nave, which is topped by a pagoda-like roof. A north transept was added in 1869 to accommodate children from the Shaftoe Trust School. The chancel was enlarged, and other alterations made, in 1898. There is structural movement in the transept and rainwater ingress.

The church was erected in 1796 by the Greenwich Hospital Trustees, to whom the Derwentwater estates

Contact: Kate Wilson 0191 269 1221



SITE NAME:	Church of St James, Middle Road, Shilbottle
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1041723

Built in 1884, and incorporating fragments from an earlier C12 church, St James is cruciform in plan with a central tower, south porch and north vestry. The tower roof is covered with felt and is allowing significant water ingress. Rainwater gutters and pipes also require overhauling. Funding was awarded in 2016, through the Heritage Lottery Fund Grants for Places of Worship scheme, for essential repairs. Those works are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221



×	
VIII.	

SITE NAME:	Haydon Old Church, Old Haydon, Haydon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1042512

Former parish church, still used for occasional worship, with C12 chancel and C14 south chapel. There are dampness problems due to failure of the stone slated roof, together with inadequately sized gutters and pipes and high external ground levels to the north wall. Funding for repairs is being pursued and discussions are underway about enhancing the building's future use.

Contact: Kate Wilson 0191 269 1221

© Historic England

© Historic England

SITE NAME:	Church of St Aidan, Tarset, Northumberland (UA)
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1302858

Built in 1818 by HH Seward for the Commissioners of Greenwich Hospital, the church has an embattled west tower, continuous nave and chancel, and north vestry. A porch at the base of the tower provides access to a simple, well proportioned interior. High level stonework is deteriorating due to water ingress. Rainwater gutters and pipes are in poor condition and some roof details and junctions are in need of repair.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of Our Lady, Seaton Delaval, Seaton Valley
DESIGNATION:	Listed Place of Worship grad- RPG grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C(C)

Religious organisation LIST ENTRY NUMBER: 1041317

Originally the private chapel of the Delaval family, the church has a short and tall nave, lower chancel and west porch. It dates from the early-C12, but may incorporate earlier fabric. Structural movement, which is affecting two internal arches and the east wall, has been monitored since 1998. Following a specialist report in 2011, exploratory work is underway to determine the cause of the movement and potential repair solutions. This work is being funded through the Heritage Lottery Fund Grants for Places of Worship scheme, with advice provided by Historic England.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Defended settlement, 1.05 kilometres north west of North Farm, Adderstone with Lucker				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006478		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Iron Age defended settlement and cultivation terraces 600 metres north east of Brown's Law Cottage, Akelo				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019139		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Haggerston dovecote, Ancroft				
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006570		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Round barrow 520 metres WNW of Quarry Cottage, Bamburgh				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014503		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Defended settlement and Roman signal station 410	metres south of V	Vest Crindledikes, Bardon Mill		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1018536		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212		
SITE NAME:	Benthall round cairn, Beadnell				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008430		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

STENDAGE USBORDATION Scheduled Monument USBORDATION Scheduled Monument CONDITION Generally unastificatory with major localised problems MINICIPAL VALUE MODEL MINICIPAL VALUE MO	HERITAGE AT RISK 2018 / NO	RTH EAST / NORTHUMBERLAND (UA)					
Control Contro	SITE NAME:	St Ebba's chapel and monastic site, Beadnell					
problems problems problems problems problems problems problems Coastal erosion NEW ENTRY: Coastal erosion NEW ENTRY: Coastal erosion NEW ENTRY: Contract: Kate Wilson 0191 269 1221 ITENAMY: Chester's Hill camps, Belford / Easington / Middleton Usersentione Scheduled Monument, part in CA Generally unsatisfactory with major localised problems RINGEN VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Kate Wilson 0191 269 1221 ITENAMY: CONTACT: Contract: Contra	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008563			
DOWNER TYPE Chester's Hill camps, Belford / Easington / Middleton Scheduled Monument, part in CA Generally unsatisfactory with major localised problems Springhill Roman camp, Berwick-upon-Tweed Springhill Roman camp, Berwick-upon-Tweed	CONDITION:		TREND:	Declining			
Chester's Hill camps, Belford / Easington / Middleton Scheduled Monument, part in CA Generally unsatisfactory with major localised problems Scrub/tree growth Mixed, multiple owners CONTACT: Scheduled Monument Springhill Roman camp, Berwick-upon-Tweed Sosionation: Scheduled Monument Generally unsatisfactory with major localised problems RINGRAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONTACT: Kate Wilson 0191 269 1221 Unknown Private CONTACT: Kate Wilson 0191 269 1221 CONTACT:	PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No			
Scheduled Monument, part in CA Generally unsatisfactory with major localised problems Sensonation: Scheduled Monument, part in CA Generally unsatisfactory with major localised problems Sensonation: Scheduled Monument Generally unsatisfactory with major localised problems Springhill Roman camp, Berwick-upon-Tweed Sprin	OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221			
Generally unsatisfactory with major localised problems RINGORAL VILLINEABILITY: Scrub/tree growth Mixed, multiple owners Springhill Roman camp, Berwick-upon-Tweed Sessionations Scheduled Monument Scheduled Monument Generally unsatisfactory with major localised problems RINGORAL VILLINEABILITY: Arable ploughing RINGORAL VILLINEABILITY: Beginstations Scheduled Monument Scheduled Monument Generally unsatisfactory with major localised problems RINGORAL VILLINEABILITY: Forestry RINGORAL VILLINEABILITY: RINGORAL V	SITE NAME:	Chester's Hill camps, Belford / Easington / Middl	Chester's Hill camps, Belford / Easington / Middleton				
problems problems Scrub/tree growth Mixed, multiple owners CONTACT: Kate Wilson 0191 269 1221 THE NAME: Springhill Roman camp, Berwick-upon-Tweed Sescinations: Scheduled Monument LISTENTRY NUMBER: 1003655 Generally unsatisfactory with major localised problems RINGRIPAL VULNEMBRILITY: Arable ploughing New ENTRY: No OWNER TYPE Private Romano-British farmstead, 520 metres north east of Birdey Shields, Birdey Scheduled Monument LISTENTRY NUMBER: 1009676 Generally unsatisfactory with major localised problems RINGRIPAL VULNEMBRILITY: Forestry No OWNER TYPE ROMANO-British settlement, 300 metres north of The Heugh, Birdey SEGMATION: Scheduled Monument LISTENTRY NUMBER: 1010045 Generally unsatisfactory with major localised problems RINGRIPAL VULNEMBRILITY: Forestry ROMANO-British settlement, 300 metres north of The Heugh, Birdey SEGMATION: Scheduled Monument LISTENTRY NUMBER: 1010045 Generally unsatisfactory with major localised problems RINGRIPAL VULNEMBRILITY: Forestry ROMANO-British settlement LISTENTRY NUMBER: 1010045 Generally unsatisfactory with major localised problems RINGRIPAL VULNEMBRILITY: Forestry No OWNER TYPE: No OWNER TYPE Private CONTACT: Kate Wilson 0191 269 1221 TENAME: TINKIP'S Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callay SEGMATION: Scheduled Monument LISTENTRY NUMBER: 101 1095 TREND: Declining RINGRAL VULNEMBRILITY: No OWNER TYPE Private CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTACT: Kate Wilson 0191 269 1221 THE NAME: Defended settlement, 450 metres NNW of Ferney CONTA	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1006513			
Mixed, multiple owners CONTACT: Kate Wilson 0191 269 1221 STENAME Springhill Roman camp, Berwick-upon-Tweed Scheduled Monument Scheduled Monu	CONDITION:		TREND:	Declining			
Springhill Roman camp, Berwick-upon-Tweed Scheduled Monument Generally unsatisfactory with major localised problems RENOIDEN Arable ploughing RENOIDEN CONTACT: Rate Wilson 0191 269 1221 STENAME: ROMAND-British farmstead, 520 metres north east of Birtley Shields, Birtley DESIGNATION: Scheduled Monument UST ENTRY NUMBER: CONTACT: Kate Wilson 0191 269 1221 STENAME: ROMAND-British farmstead, 520 metres north east of Birtley Shields, Birtley DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Declining PRINCIPLE WILSON OF BERNOIDEN SCHEDIER OF STENAME: ROMAND-British settlement, 300 metres north of The Heugh, Birtley DESIGNATION: Scheduled Monument UST ENTRY NUMBER: DECINITION: Scheduled Monument UST ENTRY NUMBER: Declining PRINCIPLE WILSON O191 269 1221 STENAME: ROMAND-British settlement, 300 metres north of The Heugh, Birtley DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Declining PRINCIPLE WILSON O191 269 1221 STENAME: Private CONTACT: Kate Wilson 0191 269 1221 STENAME: Private Tinkler's Dene univaliate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Tinkler's Dene univaliate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Tinkler's Dene univaliate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Total Private CONTACT: Kate Wilson 0191 269 1221 STENAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Uniknown TREND: Unknown TREND: Unknown TREND: Unknown TREND: Unknown	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No			
Scheduled Monument LIST ENTRY NUMBER: 1003655 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Kate Wilson 0191 269 1221 Romano-British farmstead, 520 metres north east of Birtley Shields, Birtley DISIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009676 CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Kate Wilson 0191 269 1221 ROMAILE TREND: Declining Private CONTACT: Kate Wilson 0191 269 1221 REMINISH TYPE: No CONTACT: Kate Wilson 0191 269 1221 REMINISH TYPE: NO CONTACT: Kate Wilson 0191 269 1221 REMINISH TYPE: NO CONTACT: Kate Wilson 0191 269 1221 REMINISH TYPE: NO CONTACT: Kate Wilson 0191 269 1221 REMINISH T	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221			
Generally unsatisfactory with major localised problems Arable ploughing Arable plo	SITE NAME:	Springhill Roman camp, Berwick-upon-Tweed					
problems Arable ploughing Ar	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003655			
Private Romano-British farmstead, 520 metres north east of Birtley Shields, Birtley DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1009676 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New Entray: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1010045 SETE NAME: Romano-British settlement, 300 metres north of The Heugh, Birtley DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1010045 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry NEW ENTRY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1010045 SETE NAME: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Bracken NEW ENTRY: No DEVENTRY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 EXTENAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: NEW ENTRY: No DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: NEW ENTRY: No	CONDITION:		TREND:	Unknown			
Romano-British farmstead, 520 metres north east of Birtley Shields, Birtley Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry No OWNER TYPE: Private Romano-British settlement, 300 metres north of The Heugh, Birtley DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry No Declining PRINCIPAL VULNERABILITY: Forestry No DEVENTRY: No DESIGNATION: Scheduled Monument DESIGNATION: NEW ENTRY: No DESIGNATION: Scheduled Monument DESIGNATION: NEW ENTRY: No DESIGNA	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No			
Designation: Scheduled Monument UST ENTRY NUMBER: 1009676 CONDITION: Generally unsatisfactory with major localised problems Problems Forestry New ENTRY: No CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Romano-British settlement, 300 metres north of The Heugh, Birtley Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Kate Wilson 0191 269 1221 TREND: Declining Problems Private CONTACT: Kate Wilson 0191 269 1221 Trend: CONTACT: Kate Wilson 0191 269 1221 Forestry New ENTRY: No CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011095 Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheator DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011835 EXERCIPAL VULNERABILITY: Defended settlement, 450 metres NNW of Ferney Chesters, Capheator DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011835 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1011835 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1011835 Unknown PRINCIPAL VULNERABILITY: Plant growth	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221			
Generally unsatisfactory with major localised problems Forestry Forestry Forestry Forestry Frivate Forestry Romano-British settlement, 300 metres north of The Heugh, Birtley Scheduled Monument Generally unsatisfactory with major localised problems Forestry Forestry	SITE NAME:	Romano-British farmstead, 520 metres north east of Birtley Shields, Birtley					
problems Problems Problems Problems Problems Problems Problems Private Priva	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009676			
Designation: Contact: Rate Wilson 0191 269 1221 Site Name: Romano-British settlement, 300 metres north of The Heugh, Birtley Designation: Scheduled Monument List entry number: Condition: Condition: Generally unsatisfactory with major localised problems Private Contact: Kate Wilson 0191 269 1221 Declining Private Contact: Kate Wilson 0191 269 1221 Site Name: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly Designation: Scheduled Monument List entry number: 1011095 Condition: Scheduled Monument List entry number: 1011095 Condition: Extensive significant problems TREND: Declining Private Contact: Kate Wilson 0191 269 1221 Site Name: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument List entry number: 1011045 Condition: Contact: Kate Wilson 0191 269 1221 Site Name: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument List entry number: 1011045 Contact: Kate Wilson 0191 269 1221 Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument List entry number: 1011045 Unknown Principal vulnerability: Plant growth New entry: No	CONDITION:		TREND:	Declining			
Romano-British settlement, 300 metres north of The Heugh, Birtley DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1010045 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry Private CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Bracken Private CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No			
Scheduled Monument Generally unsatisfactory with major localised problems FRINCIPAL VULNERABILITY: Forestry Private Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly Designation: Scheduled Monument Extensive significant problems TREND: Declining Frincipal Vulnerability: Designation: Scheduled Monument Extensive significant problems TREND: Declining FRINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No CONTACT: Kate Wilson 0191 269 1221 Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONTACT: Kate Wilson 0191 269 1221 Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Private CONDITION: Private Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Unknown Private Vinknown Private Private Private Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221			
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry Forestry Private CONTACT: Kate Wilson 0191 269 1221 STE NAME: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Bracken Private Defended settlement, 450 metres NNW of Ferney Chesters, Capheator DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems TREND: Unknown PRINCIPAL VULNERABILITY: No Designation: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	SITE NAME:	Romano-British settlement, 300 metres north o	f The Heugh, Birtley				
problems pro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010045			
Private CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	CONDITION:		TREND:	Declining			
Tinkler's Dene univallate hillfort, 400 metres north east of Dancing Hall Farm, Callaly Scheduled Monument Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Bracken Private Defended settlement, 450 metres NNW of Ferney CONTACT: Scheduled Monument LIST ENTRY NUMBER: 1011095 Declining New ENTRY?: No CONTACT: Kate Wilson 0191 269 1221 STEENAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No	PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011095 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Bracken NEW ENTRY?: No OWNER TYPE: Private CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221			
Extensive significant problems FRINCIPAL VULNERABILITY: Bracken Private Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining No New ENTRY?: No Unknown New ENTRY?: No	SITE NAME:	Tinkler's Dene univallate hillfort, 400 metres no	rth east of Dancing H	all Farm, Callaly			
PRINCIPAL VULNERABILITY: Bracken NEW ENTRYP: No CONTACT: Kate Wilson 0191 269 1221 SITE NAME: Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRYP: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011095			
Private Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton Designation: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth CONTACT: Kate Wilson 0191 269 1221 Kate Wilson 0191 269 1221 LIST ENTRY NUMBER: 1011835 TREND: Unknown NEW ENTRY: No	CONDITION:	Extensive significant problems	TREND:	Declining			
Defended settlement, 450 metres NNW of Ferney Chesters, Capheaton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1011835 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth LIST ENTRY NUMBER: 1011835 Unknown NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221			
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth Generally unsatisfactory with major localised TREND: Unknown NEW ENTRY?: No	SITE NAME:	Defended settlement, 450 metres NNW of Ferr	ney Chesters, Caphea	ton			
problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011835			
	CONDITION:		TREND:	Unknown			
OWNER TYPE: Private CONTACT: Sara Rushton 0191 269 1222	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No			
	OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222			

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Romano-British settlement and Iron Age defended s Capheaton / Wallington Demesne	ettlement, 550 m	etres north east of Shaftoe Grange,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Simonside camp, Chatton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002907
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two cairn cemeteries west of Willie Law, Chatton	Chillingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006451
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hepburn Crags camp, Chillingham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006547
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Corbridge (Corstopitum) Roman station, Corbridge	e / Sandhoe	
DESIGNATION:	Scheduled Monument, LB grade II, part in CA, WHS	LIST ENTRY NUMBER:	1006611
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Hadrian's Wall and vallum between the track to Por in wall miles 22 and 23, Corbridge / Sandhoe / Wall		the field boundary east of milecastle
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010626
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Hadrian's Wall and vallum between the Fence Burn Corbridge / Whittington	and the track to F	Portgate Cottage in wall miles 21 and 2
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1010625
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Mike Collins 0191 269 1212

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION Scheduled Monument UST ENTITY NUMBER 1006409 DESIGNATION Scheduled Monument UST ENTITY NUMBER 1006409 CONDITION Extensive significant problems TREND Unknown PRINCIPAL WULNERABUTY: Arable ploughing NEW ENTITY: No OWNER TYPE Private CONTACT: Kate Wilson 0191 269 122 SILE NAME: Ridsdale ironworks, Corsenside DESIGNATION Scheduled Monument UST ENTITY NUMBER 1006420 CONDITION Generally satisfactory but with significant localised problems PRINCIPAL WULNERABUTY: Ocliapse NEW ENTITY: No OWNER TYPE Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION Scheduled Monument, LB grade II* UST ENTITY NUMBER: 1014509 CONDITION Scheduled Monument, LB grade II* UST ENTITY NUMBER: 1014509 CONDITION Scheduled Monument, LB grade II* UST ENTITY NUMBER: 1014509 CONDITION CONTENT: No OWNER TYPE: Commercial company ConTacT: Tom Gledhill 0191 269 120 DESIGNATION Scheduled Monument UST ENTITY NUMBER: 101480 CONDITION Generally unsatisfactory with major localised problems PRINCIPAL WULNERABUTY: Office of the problems of the	HERITAGE AT RISK 2018 / NO	RTH EAST / NORTHUMBERLAND (UA)		
CONDITION Generally unsatisfactory with major localised problems PRINCIPLA VALUE PRABLETT: STENAME: Enclosed settlement, 620 metres south east of COTHILL Castle, COTHILL ON 191 269 122 STENAME: Enclosed settlement, 620 metres south east of COTHILL CASTLE, COTHILL ON 191 269 122 STENAME: Enclosed settlement, 620 metres south east of COTHILL CASTLE, COTHILL ON 191 269 122 STENAME: Enclosed settlement, 620 metres south east of COTHILL CASTLE, COTHILL ON 191 269 122 STENAME: Enclosed settlement, 620 metres south east of COTHILL CASTLE, COTHILL ON 191 269 122 STENAME: Enclosed settlement, 620 metres south east of COTHILL CASTLE, COTHILL ON 191 269 122 STENAME: Arabic significant problems STENAME: Ridsdale ironworks, Corsenside DESIGNATION: Scheduled Monument COMPICION Generally satisfactory but with significant localised problems PRINCIPLA VALUENBAREITY: Collapse New PRINCIPL Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STENAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* DESIGNATION: Scheduled Monument D	SITE NAME:	Cornhill Castle, Cornhill-on-Tweed		
Problems President Scrub/tree growth Private P	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006508
OWNERTYTE Private CONTACT: Kate Wilson 0191 269 122 SITE NAME: Enclosed settlement, 620 metres south east of Cornhill Castle, Cornhill-on-Tweed DESIGNATION: Scheduled Monument LETENTER NAMBER: 1006409 CONDITION Extensive significant problems PRINCE Unknown PRINCIPLE VULNEAURITY: No CONTACT: Kate Wilson 0191 269 122 SITE NAME: Ridsdale ironworks, Corsenside DESIGNATION: Scheduled Monument LETENTER NAMBER: 1006420 CONDITION: Generally satisfactory but with significant localised problems PRINCIPLE VULNEAURITY: No CONNERTYTE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STEENAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* LETENTER NAMBER: 1014509 CONNERTYTE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STEENAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* LETENTER NAMBER: 1014509 CONNERTYTE: No CONNERTYT	CONDITION:		TREND:	Declining
EINCLOSED SETTLEMENT. 620 meteres south east of Committee Committee Committee Scheduled Monument Streams (1006409) EXENSIVE Significant problems IREND: Unknown PRINCEPAL MUNICIPAL MUNIC	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
EBSIGNATION Scheduled Monument ISTENTRY NUMBER 1006409 CONDITION Extensive significant problems TEND: Unknown PRINCE VALUE REAL PRIVATE NO CONTACT: Kate Wilson 0191 269 122 SITE NAME: Riddale ironworks, Corsenside DESIGNATION Scheduled Monument USTENTRY NUMBER 1006420 CONDITION Generally satisfactory but with significant localised problems PRINCE Private Numbers 1006420 CONDITION Generally satisfactory but with significant localised TEND: Declining PRINCE Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* USTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade II* USTENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCE COMMERTITY: Vandalism NEW INTERTRY NUMBER: 1014509 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwitter DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCE Heiferlaw defended settlement, 100 metres north of Holywell, Denwitter DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCE PRIVATE Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 10066555 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 10066555 TREND: Declining PRINCE VUNBERABULY: Natural erosion - extensive NEW NIKY: No OWNER TYPE: Rivate Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monume	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
CONDITION Extensive significant problems TARND: Unknown RRINGIPAL VULNERABILITY: Arable ploughing NEW ENTRY! NO OWNER TYPE: Private CONTACT: Kate Wilson 0191 269 122 STE NAME: Ridsdale ironworks, Corsenside DESIGNATION: Scheduled Monument LETENTRY NUMBER: 1006420 CONDITION: Generally satisfactory but with significant localised problems RRINGIPAL VULNERABILITY: Collapse NEW ENTRY! No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* LST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems RRINGIPAL VULNERABILITY: Vandalism OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 122 STE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwisch DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1014800 CONTACT: Tom Gledhill 0191 269 122 STE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwisch DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1014080 CONTACT: Sara Rushton 0191 269 122 STE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwisch DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1014080 CONTACT: Sara Rushton 0191 269 122 STE NAME: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1006555 STE NAME: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1006555 TREND: Declining PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: RESTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: RESTRY NUMBER: 1006601 TREND: DESIGNATION: Scheduled Monument LST ENTRY NUMBER: 1006601 TREND: DESIGNATION: NEW ENTRY: No OWNER TYPE: NEW ENTRY:	SITE NAME:	Enclosed settlement, 620 metres south east of Co	rnhill Castle, Cornh	nill-on-Tweed
PRINCIPAL VIULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private Private CONTACT: Kate Wilson 0191 269 122 SITE NAME: Ridsdale ironworks, Corsenside DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006420 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VIULNERABILITY: Collapse NEW ENTRY: No OWNER TYPE: Private, multiple owners Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade III* UST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VIULNERABILITY: Vandalism CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VIULNERABILITY: Vandalism CONDITION: Commercial company CONTACT: Tom Gledhill 0191 269 120 STENAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VIULNERABILITY: Private CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VIULNERABILITY: Forestry NEW ENTRY: No CONTACT: Sara Rushton 0191 269 122 STENAME: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 STENAME: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 DECINITION: Declining PRINCIPAL VIULNERABILITY: No CONDITION: Scheduled Monument UST ENTRY NUMBER: 1006555 DECINITION: No WEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STENAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VIULNERABILITY: No DECLINING: Declining PRINCIPAL VIULNERABILITY: No DECLINING: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VIULNERABILITY: No DECLINING: DECLINING: DECLINING: NO DECLI	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006409
OWNER TYPE: Private Ridsdale ironworks, Corsenside DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1006420 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Collapse OWNER TYPE: Private, multiple owners CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument, LB grade ** LISTENTRY NUMBER: 1014509 CONDITION: Scheduled Monument New Desireman New N	CONDITION:	Extensive significant problems	TREND:	Unknown
Riddale ironworks, Corsenside DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument, LB grade II* PRINCIPAL VULNERABILITY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: No DESIGNATION: Scheduled Monument DESIGNATION: Scheduled	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DISIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006420 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL WUNDRABILITY: Collapse NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade * UST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL WUNDRABILITY: Vandalism OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL WUNDERABILITY: Porestry NEW ENTRY: No OWNER TYPE: No OWNER TYPE: No CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL WUNDERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: No OWNER TYPE: No CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL WUNDERABILITY: No OWNER TYPE: NO	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Collapse OWNER TYPE Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vandalism OWNER TYPE Commercial company STE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE Private Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 STE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 STE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: NO	SITE NAME:	Ridsdale ironworks, Corsenside		
PRINCIPAL VULNERABILITY: Collapse Private, multiple owners Contact: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* UST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1014080 DECLINING SCHEDULED UNSATISFACTORY WITH major localised problems PRINCIPAL VULNERABILITY: Forestry No OWNER TYPE: No OWNER TYPE: Private Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 STE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 STE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006501 Kate Wilson 0191 269 122 STE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006601 ESSIGNATION: Sch	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006420
OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* USTENTRY NUMBER: 1014509 Stable PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY?: Vandalism NEW ENTRY?: Vandalism NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry NEW ENTRY: No OWNER TYPE: Private Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: No Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: ROUGHTION: CONDITION: Scheduled Monument UST ENTRY NUMBER: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: ROUGHTION: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: ROUGHTION: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: ROUGHTION: Scheduled Monument UST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No	CONDITION:		TREND:	Declining
SITE NAME: Cresswell tower house, Cresswell DESIGNATION: Scheduled Monument, LB grade II* LST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vandalism OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New ENTRY: No OWNER TYPE: Private CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monu	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, LB grade II* LIST ENTRY NUMBER: 1014509 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Vandalism NEW ENTRYP: No OWNER TYPE: Commercial company SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry NEW ENTRYP: No OWNER TYPE: Private Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRYP: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 TREND: Declining PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601	OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
Generally unsatisfactory with major localised problems NEMOLIFICATION: Vandalism NEWENTRY: No OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO 14080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New ENTRY: No OWNER TYPE: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO06555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: IO06601 CONDITION: Generally unsatisfactory with major localised problems Scheduled Monument LIST ENTRY NUMBER: IO06601 CONDITION: Scheduled Monument LIST ENTRY NUMBER: IO06601	SITE NAME:	Cresswell tower house, Cresswell		
PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New ENTRY: No OWNER TYPE: Private CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Number: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014509
OWNER TYPE: Commercial company CONTACT: Tom Gledhill 0191 269 120 SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New ENTRYP: No OWNER TYPE: Incised rocks, 500 metres north west of Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRYP: No OWNER TYPE: Private Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems Resulting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems Scheduled Monument LIST ENTRY NUMBER: 1006601 Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRYP: No No	CONDITION:		TREND:	Stable
SITE NAME: Heiferlaw defended settlement, 100 metres north of Holywell, Denwick DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry NEW ENTRY?: No OWNER TYPE: Private CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014080 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New ENTRY?: No CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	OWNER TYPE:	Commercial company	CONTACT:	Tom Gledhill 0191 269 1203
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Forestry New Entry?: No OWNER TYPE: Private Incised rocks, 500 metres north west of Doddington Designation: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No Scrub/tree growth NEW ENTRY?: No	SITE NAME:	Heiferlaw defended settlement, 100 metres north	of Holywell, Denwi	ick
problems PRINCIPAL VULNERABILITY: Forestry New Entry?: No OWNER TYPE: Private Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument DESIGNATION: Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive Private, multiple owners Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument DESIGNATION: Scrub/tree growth NEW ENTRY?: No Declining PRINCIPAL VULNERABILITY: No No NEW ENTRY?: No Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014080
OWNER TYPE: Private CONTACT: Sara Rushton 0191 269 122 SITE NAME: Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 100660 1 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	CONDITION:		TREND:	Declining
Incised rocks, 500 metres north west of Doddington Dean Wood, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006555 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Natural erosion - extensive NEW ENTRY?: No CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No No	SITE NAME:	Incised rocks, 500 metres north west of Doddingto	on Dean Wood, Do	oddington
PRINCIPAL VULNERABILITY: Natural erosion - extensive OWNER TYPE: Private, multiple owners Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth New ENTRY: No Declining Declining No New ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006555
OWNER TYPE: Private, multiple owners CONTACT: Kate Wilson 0191 269 122 SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No	CONDITION:		TREND:	Declining
SITE NAME: Roughting Linn camp, Doddington DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006601 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Generally unsatisfactory with major localised problems TREND: Declining No	SITE NAME:	Roughting Linn camp, Doddington		
problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006601
0	CONDITION:		TREND:	Declining
OWNER TYPE: CONTACT: Kate Wilson 0191 269 122	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Two camps and cup and ring marked rocks on D	od Law, Doddington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002946
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Iron Age defended settlement in Camp Plantatio	n, 350 metres north	west of North Charlton Mill, Eglingha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Site south west of Thirlings, Ewart		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006436
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Circular enclosure west of Second Linthaugh, Fo	ord	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006430
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Flodden camp, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006481
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two incised rocks on Broom Ridge, Hunter's M	oor, Ford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006554
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Langley Barony lead mines, Haydon Bridge, Hayd	don	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006413
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HENTAGE AT NISK 2016 / INO	RTH EAST / NORTHOMBERLAND (UA)		
SITE NAME:	Hadrian's Wall and vallum from Throckley to East Heddon-on-the-Wall	Town House, Hed	don-on-the-Wall in wall mile 11,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010616
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Defended settlement, Romano-British settlement a Lantern, Hedgeley	and field system, 10	0 metres south and east of Jenny's
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008839
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British enclosed settlement, 800 metres r	orth west of East I	Bolton, Hedgeley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007446
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Nafferton castle and tower house, 750 metres east	t of Nafferton Farm	n, Horsley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018369
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Remains of medieval bridge, Chollerford, Humshau	ıgh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006567
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn 790 metres west of Smithy Strip, Ilder	rton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016248
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Earthwork 370 yards (340 metres) east of Low Ste	ad, Lowick	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006529
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

	RTH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Newminster Abbey, Mitford Road, Morpeth		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1006563 and 1155952
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Camp in Oakwood, south east of Plenmeller villag	e, Plenmeller with V	Vhitfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006484
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
ITE NAME:	Ellsnook round barrow, 175 metres north east of	Heiferlaw Bridge, R	ennington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006564
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Cairn, 900 metres north east of Old Rothbury hill	fort, Rothbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Old Rothbury multivallate hillfort and cairnfield, R	othbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011616
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Allensford blast furnace, Shotley Low Quarter		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006405
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
ITE NAME:	The vallum between Oatens Bank, Harlow Hill, an	d Whittle Dene Wa	atercourse in wall mile 16, Stamfordha
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010621
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Hadrian's Wall and vallum between St Oswald's Cottages, east of Brunton Gate and the North Tyne in warmiles 25, 26 and 27, Wall				
DESIGNATION:	Scheduled Monur	ment, WHS	LIST ENTRY NUMBER:	1018581	
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	Yes	
OWNER TYPE:	Other		CONTACT:	Mike Collins 0191 269 1212	
SITE NAME:	Medieval monastic sheep farm (bercaria), 550 metres north east of Whittondean Farm, Whitton and To				
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1011292	
CONDITION:	Extensive significa	ant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken		NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple o	wners	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Two round cairn	s, 590 metres and 610 metres east	of Burn Brae, Wh	itton and Tosson	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1017197	
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple o	owners	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Low Chibburn m	edieval preceptory, C16 house and	l World War II pil	lbox, Widdrington Village	
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1014679	
CONDITION:	Generally unsatist problems	factory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221	
	SITE NAME:	Tillmouth Park, Cornhill-on- Tweed / Duddo	Early and late-C19 picturesque pleasure grounds formal gardens. The picturesque walks alongside		
	DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, 2 SMs	Castle, are mask Several other her	ean and to the 'eye-catcher', Twizel ed by natural woodland regeneration. ritage assets situated within the park and	
	CONDITION:	Generally unsatisfactory with major localised problems		or condition, including ha-ha walls, gardo Gothick bridge and the Henlaw Tunnel.	
	VULNERABILITY:	High			
1-11-	TREND:	Declining			
Historic England	NEW ENTRY?:	No			
	OWNER TYPE:	Local authority, multiple owners			
	LIST ENTRY NUMBER:	1001053	Contact: Chris M	1ayes 0191 269 1226	
	SITE NAME:	Seaton Delaval, Seaton Valley	Remains of an ea	rly-C18 park and garden, partially	
	DESIGNATION:	Registered Park and Garden grade II*, 20 LBs, part in CA	restored in the 1950s-60s. The house and landscap designed by Sir John Vanbrugh in 1719. The approa avenue is deteriorating and woodland regeneration		
	CONDITION:	Generally satisfactory but with significant localised problems	concealing key la and the mausole	ndscape features, including earthworks um. Ha-ha walls and corner bastions are	
The same of the sa	VULNERABILITY:	Medium	partial collapse. A	y scrub and tree growth, with areas of Conservation Management Plan has	
The second	TREND:	Stable		The site was awarded a Heritage Lotter I 6 and conservation works are due to	
	NEW ENTRY?:	No	begin in autumn	2018.	
Historic England	OWNER TYPE:	Charity (heritage)			
		G. iai 15/ (1151.16485)			

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

1001052

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Chris Mayes 0191 269 1226

ABBREVIATIONS

OWNER TYPE:

LIST ENTRY NUMBER:

SITE NAME:	Berwick-upon-Tweed		
DESIGNATION:	Conservation Area, 264 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Liz Williams (LPA) 01670 620305
SITE NAME:	Tweedmouth, Berwick-upon-Tweed		
SITE NAME: DESIGNATION:	Tweedmouth, Berwick-upon-Tweed Conservation Area, 18 LBs, part in SM	NEW ENTRY?:	No
	· •	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 18 LBs, part in SM		

NORTHUMBERLAND (NP)



© Historic England

Hadrian's Wall from Cockmount Hill to Walltown, Greenhead, Northumberland (UA)

DESIGNATION: Scheduled Monument and Listed Building grade I, WHS

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: C (C)

1017535 and 1155916

Private

44 and 45. Issues lie with a short section of the Wall above Walltown quarry and the remains of Wall turret 44b. Initial inspections suggest limited consolidation and capping works would address the remaining management issues, but agreement on how to undertake this work (including a funding package) has yet to be reached..

Sections of unconsolidated Hadrian's Wall in Wall Miles 43,

Contact: Mike Collins 0191 269 1212



0	∐istoris	England	

Bastle at Horneystead, 400 metres south west of The Ash, Wark, Northumberland (UA)

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY: B (B)

OWNER TYPE: Private

A defensive farmhouse of the type found only in the northern border counties of England. The walls stand up to 4.5 metres high but the first floor has collapsed on a barrel vault. Several sections of maonry are unstable and at risk of collapse. Repair works, funded through a Repair Grant for Heritage at Risk, will be completed during Summer 2018.

LIST ENTRY NUMBER: 1009674 Contact: Sara Rushton 0191 269 1222

SITE NAME:	Romano-British farmstead 900 metres north east of triangulation point on Gains Law, Akeld, Northumberland (UA)			
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1017381	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Unenclosed scooped settlement on the east slop Cottages, Akeld, Northumberland (UA)	e of Harehope Hill, 7	750 metres south east of High Akeld	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014932	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:				

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Settlement 500 yards (460 metres) south west of \	White Law, Akeld /	Kirknewton, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006455
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Enclosures on Meggrim's Knowe, Alnham, Northui	mberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006589
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Three cross dykes on Middle Hill, Alwinton, North	numberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007525
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Prehistoric field system and unenclosed hut circle south west of Earlehillhead, Earle, Northumberland		ern slopes of Hart Heugh, 550 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Haltwhistle Burn Roman temporary camps 2 and 3 Northumberland (UA)	and area of cord r	ig cultivation, Haltwhistle,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010946
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Cross dyke, south of Campville, Harbottle, Northu	ımberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011396
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and associated features between th of milecastle 36 in wall miles 34, 35 and 36, Haydo	e boundary east of n / Simonburn / Bai	turret 34a and the field boundary we
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010964
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Mike Collins 0191 269 1212

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Shieling, 500 metres south west of Spy Crags, Hen	shaw, Northumber	land (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011839
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and associated features between th Rigg car park in wall miles 37, 38 and 39, Henshaw		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010966
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Seatsides I Roman temporary camp and section of from Once Brewed to the south side of the B6318 (UA)	the Stanegate Ron , Henshaw / Melkri	nan road from the west side of the road idge / Haltwhistle, Northumberland
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010940
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	C18 water mill at Grasslees, Hepple, Northumberl	and (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006404
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Bastle 150 metres south west of Morrelhirst, Holli	nghill, Northumber	land (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
ITE NAME:	Hut circle 320 metres west of Threestoneburn Ho	ouse, Ilderton, Nort	thumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019924
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Greaves Ash camp, Ingram, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006588
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2018 / NOI	RTH EAST / NORTHUMBERLAND (NP)		
SITE NAME:	Reaveley Hill cairn cemetery, Ingram, Northumb	erland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Reaveley Hill settlement, Ingram, Northumberla	nd (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006468
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement on south east slope of Ewe Hill, Ingra	am, Northumberland	(UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002916
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Unenclosed hut circle settlement, field system, c Linhope Spout, Ingram, Northumberland (UA)	airnfield and cord rig	cultivation immediately north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ingram Farm: prehistoric to post-medieval settle Northumberland (UA)	ment, agricultural and	f funerary remains, Ingram / Alnham,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021382
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
ITE NAME:	Elsdonburn Roman period native settlements an	d medieval shieling, K	ilham, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014505
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Enclosed settlement and subsidiary enclosures I Kilham, Northumberland (UA)	60 metres north of R	ing Chesters defended settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009527
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Northern ring cairn on Coldsmouth Hill, Kilham, Northumberland (UA)				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009531		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222		
SITE NAME:	Roman period native enclosed settlement 700 metres south of Ring Chesters defended settlement, Kilham, Northumberland (UA)				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014678		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Southern ring cairn on Coldsmouth Hill, Kilham, N	lorthumberland (U	A)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009530		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222		
SITE NAME:	Roman period native enclosed farmstead 320 metres north west of Southernknowe, Kirknewton, Northumberland (UA)				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014488		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203		
SITE NAME:	Roman period native enclosed farmstead 370 metr Northumberland (UA)	Roman period native enclosed farmstead 370 metres WNW of Southernknowe, Kirknewton, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014491		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203		
SITE NAME:	Roman period native enclosed settlement 270 met	res ESE of Fleehop	e, Kirknewton, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014501		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203		
SITE NAME:	Roman period native enclosed settlement and med Kirknewton, Northumberland (UA)	lieval sheiling 165 n	netres north east of Dunsdale,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014680		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Roman period native farmstead 550 metres south (UA)	west of Trowupbu	rn rarm, Kirknewton, Northumberlar
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009528
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Romano-British settlement 810 metres south east	of Whitehall, Kirkr	newton, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019927
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Romano-British settlements east of Yeavering Bell to the west and south of it, Kirknewton, Northum	containing the Old berland (UA)	Sheepfold settlement and settlement
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
SITE NAME:	Settlement north of White Law, Kirknewton, North	thumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006456
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Settlement north west of Ell's Knowe, Kirknewton	, Northumberland	(UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008478
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Settlement on north east slope of Yeavering Bell, k	Kirknewton, North	umberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006459
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlement on north slope of Yeavering Bell, Kirkn	ewton, Northumb	erland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Sottlement on the east slope of The Pall Visiter and	on Northumberle	od (LIA)
DESIGNATION:	Settlement on the east slope of The Bell, Kirknewt Scheduled Monument	LIST ENTRY NUMBER:	1006465
DESIGNATION.		LIST EINTIKT INOTIBER.	1000463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlement WSW of Ell's Knowe, Kirknewton, No	rthumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009039
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Settlement, field systems and terraces on the south Northumberland (UA)	n east slope of Yeav	vering Bell, Kirknewton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006460
CONDITION:	Optimal/generally satisfactory	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Stephen Allott 0191 269 1235
ITE NAME:	Unenclosed settlement, part of a field system, Romano-British aggregate village and group of shielings, 470 metres south east of Whitehall, Kirknewton, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019929
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the field bound 34a in wall miles 32, 33 and 34, Newbrough / Simo		
DESIGNATION:	Scheduled Monument, LB grade I, WHS	LIST ENTRY NUMBER:	1010963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Mike Collins 0191 269 1212
ITE NAME:	Romano-British farmstead 850 metres south of Tre	oughend, Otterburi	n, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sara Rushton 0191 269 1222
ITE NAME:	Fishponds, 450 metres north east of Sewingshields.	, Simonburn, North	numberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011081
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Walwick Fell Roman temporary camp, Warden, Northumberland (UA)		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010935
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Romano-British farmstead, 175 metres south of C	ockpit Well, Whitto	on and Tosson, Northumberland (UA)
SITE NAME: DESIGNATION:	Romano-British farmstead, 175 metres south of Conscience of Scheduled Monument	ockpit Well, Whitto	on and Tosson, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009582

TEES VALLEY

DARLINGTON (UA)



© Historic England

SITE NAME:	Dovecote, 45 metres east of Manor House, Houghton Bank Lane, Houghton Le Side
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1121194

SITE NAME:

Dovecote, probably medieval. Disused and requires roof repairs, repointing and removal of vegetation from walls.

An important site containing the ruined remains of a pre-

Conquest church. Repair works were completed in 2006,

and again in 2010, with Historic England funding. Discussions are underway about the site's future, with

Contact: Kate Wilson 0191 269 1221

interest from a potential new owner.



© Historic England

	Lane, Sockburn
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1002340 and 1185947

Church of All Saints, Sockburn

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Cuthbert, Market Place, Darlington
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1121280

St Cuthbert's is one of the most important churches in the Early English style of Gothic architecture in the north of England. The nave, transepts and chancel are housed beneath steeply pitched roofs whose covering is affected by significant problems. The building is becoming increasingly difficult to maintain in a weathertight condition. A first phase of roof repairs was undertaken in 2016 and a second phase is due to be completed in 2018. Both phases have been made possible with funding from the Heritage Lottery Fund Grants for Places of Worship scheme.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA

ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Hilda, Park Gate, Darlington
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1322955

Built (1887-88) in red brick in the Early English style by eminent C19 church architect JL Pearson. The stained glass and interior fittings were removed soon after closure in 1986. The church then suffered a fire before being acquired and re-used for worship by the Life and Light Mission. Roof coverings are reaching the end of their life and low level brickwork is in need of repair.

Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME:	Small multivallate hillfort and tower mill on Shacklet	on Beacon Hill, H	eighington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016867
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Northgate		
DESIGNATION:	Conservation Area, 14 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosalind Kain (LPA) 01325 406326
SITE NAME:	Victoria Embankment		
DESIGNATION:	Conservation Area, LB grade II, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosalind Kain (LPA) 01325 406326
SITE NAME:	West End		
DESIGNATION:	Conservation Area, 39 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosalind Kain (LPA) 01325 406326

HARTLEPOOL (UA)



© Historic England

SITE NAME:	Church of St Mary, Durham Street, Hartlepool, Headland
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1250263

limestone walls are displaying numerous problems, including multiple vertical fractures at the west end of the building, some pockets of deep erosion, open joints, internal powdering and inappropriate cement repairs which are failing. Funding is being pursued as part of a site-wide strategy that includes the repair of the adjoining Presbytery and a neighbouring property.

Designed in 1850 by the architect JA Hansom, St Mary's church has a west tower (from which a spire was removed c1945) and a bowed apsidal chancel. The external

Contact: Kate Wilson 0191 269 1221



Historic England

SITE NAME:	Church of St Hilda, High Street Hartlepool Headland, Headland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1263355

Built around 1200 on the site of a C7 monastery, incorporating the remains of an early-C12 church. The church includes many Saxon and medieval architectural fragments and has undergone several re-designs, being fully restored between 1925 and 1932. It is on an exposed site near the sea. The tower has structural issues that are under investigation and many windows require repair. The building has been the subject of heritage crime. Funding for repairs is being explored following an unsuccessful bid in 2017 to the Heritage Lottery Fund Grants for Places of Worship scheme.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Low Throston deserted medieval village		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006765
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Medieval farmstead and irregular open field system	at High Burntoft F	arm, Elwick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015207
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Church Street, Hartlepool		
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Headland, Hartlepool, Headland		
DESIGNATION:	Conservation Area, 35 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Park, Hartlepool		
DESIGNATION:	Conservation Area, 10 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Seaton Carew, Hartlepool		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
MIDDLESBROUGH (U	A)		
SITE NAME:	Acklam Hall, Acklam		
DESIGNATION:	Conservation Area, LB grade I	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Heather Nelson (LPA) 01642 72911
SITE NAME:	Middlesbrough Historic Quarter		
DESIGNATION:	Conservation Area, 20 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

	` '	` '		
NORTH YORK MOORS (NP)				
SITE NAME:	Pinchinthorpe Hall moated site and post medieval gardens, Guisborough, Redcar and Cleveland (UA)			
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1013215	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Round barrow on Codhill Heights, 860 metres south east of Codhill Farm, Guisborough, Redcar and Cleveland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016574	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	

REDCAR AND CLEVELAND (UA)



SITE NAME: Red Barns House and Red Barns Hotel, Kirkleatham Street DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Private

Red Barns was commissioned and built in the mid nineteenth century as the family home of the Bell's (Sir Hugh Bell). It was designed by Philip Webb a member of William Morris and Partners. A blue plaque on the wall of Red Barns honours Gertrude Bell (daughter of Sir Hugh) the archaeologist, writer and traveller. The building is vacant and deteriorating due to a lack of regular maintenance. Planning permission has been granted for the conversion and reuse of part of the building.

Early to mid-C18 bastion and adjoining ha-ha. The bastion is badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some consolidation work, part-funded by Historic England, was carried out on the

LIST ENTRY NUMBER: 1139613 Contact: Kate Wilson 0191 269 1221 © Historic England



© Historic England

SITE NAME:	Bastion and ha-ha wall, north of Kirkleatham Hall Stables, Kirkleatham, Redcar		
DESIGNATION:	Listed Building grade II*, CA		
CONDITION:	Very bad		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	A (A)		

Local authority

1329608

bastion during 2011-12 but further repairs are required and the ha-ha remains in a very poor condition.

Contact: Martin Lowe 0191 269 1233



© Redcar and Cleveland Borough

SITE NAME:	Bastion, north west of Kirkleatham Hall Stables, Kirkleatham, Redcar	Mid-C18 bastion. Badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some
DESIGNATION:	Listed Building grade II*, CA	urgent repairs, part-funded by Historic England, were carried out during 2011-12 but further works are require
CONDITION:	Poor	to complete the consolidation of the structure.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	

1160124

Contact: Martin Lowe 0191 269 1233

PRIORITY CATEGORIES Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

OWNER TYPE:

LIST ENTRY NUMBER

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England Archive

SITE NAME:	Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority

1160085

Early-C18 stable block. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. The stable block was repaired, part-funded by Historic England grant-aid, during 2011-12 and is now in good condition. The Local Planning Authority has recently commissioned a detailed feasibility study which will look at potential new

Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME:	Remains of Kilton Castle, Kilton Thorpe Lane, Kilton, Lockwood
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

Private

LIST ENTRY NUMBER: 1018946 and 1136489 Contact: Kate Wilson 0191 269 1221

C12-C13 castle ruin occupying a rocky outcrop. The building is in a very bad condition, with vertical cracks in its walls and there is some regeneration of vegetation. There is only limited management by the Estate.



© Historic England

SITE NAME:	Church of St Cuthbert, Church Lane, Ormesby, Redcar
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1139628

Built in 1875 on an Anglo-Saxon foundation, the church comprises a nave with north aisle and chancel. The north porch, vestry, organ chamber and oak-shingled spire are later additions. The rainwater management system needs repair along with the roof coverings and there are deep pockets of erosion affecting the external stonework. The building has also been subject to heritage crime.

Contact: Kate Wilson 0191 269 1221



© Histor	ic England

SITE NAME:		Christ Church, Coatham Road, Redcar
	DESIGNATION:	Listed Place of Worship grade II, CA
	CONDITION:	Very bad
	PRIORITY CATEGORY:	B (B)
	OWNER TYPE:	Religious organisation

LIST ENTRY NUMBER: 1159776

Christ Church was built in 1854 and its soaring spire of sandstone with limestone dressings is a local landmark. The external stonework is subject to advanced weathering and decay; this is particularly pronounced to the spire and tower. The slated roof coverings are also reaching the end of their serviceable life. Funding was awarded in 2017, through the Heritage Lottery Fund Grants for Places of Worship scheme, for essential repairs to the tower and spire. Those works are due to commence in 2018.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Bowl barrow, I kilometre north west of High Court Green, Guisborough			
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1011285			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / NORT	'H EAST / REDCAR AN	D CLEVELAND (UA)			
SITE NAME:	Eston Nab hill fo	Eston Nab hill fort, palisaded settlement and beacon, Guisborough			
DESIGNATION:	Scheduled Monu	ument	LIST ENTRY NUMBER:	1011273	
CONDITION:	Generally unsati problems	sfactory with major localised	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No	
OWNER TYPE:	Local authority	Local authority		Lee McFarlane 0191 269 1239	
SITE NAME:	Manorial settler Marske and Nev		d system, immediat	ely north of Marske Inn Farm, Saltburn	
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1018948	
CONDITION:	Generally satisfa problems	Generally satisfactory but with significant localised problems		Stable	
PRINCIPAL VULNERABILITY:	Stock erosion -	Stock erosion - moderate		No	
OWNER TYPE:	Local authority	Local authority		Kate Wilson 0191 269 1221	
	SITE NAME:	Valley Gardens, Saltburn, Saltburn, Marske and New Marske / Skelton and Brotton	Public pleasure grounds developed from 1861 to de principally by Joseph Newton. Paths and steps have subsided and tree and shrub growth has been allow		
	designation:	Registered Park and Garden grade II, 2 LBs, CA	nature of the site	ed, mainly due to the steeply sloping e. The Albert Memorial (grade II) and around the site have suffered from	
	CONDITION:	Generally satisfactory but with		nplanned management. Development of the site.	



© Historic England

SITE NAME:	Valley Gardens, Saltburn, Saltburn, Marske and New Marske / Skelton and Brotton	
DESIGNATION:	Registered Park and Garden grade II, 2 LBs, CA	
CONDITION:	Generally satisfactory but with significant localised problems	
VULNERABILITY:	Medium	
TREND:	Declining	
NEW ENTRY?:	No	
OWNER TYPE:	Local authority, multiple owners	
LIST ENTRY NUMBER:	1001429	

active 'friends group' has been established and a conservation management plan is now being produced.

Contact: Chris Mayes 0191 269 1226

SITE NAME:	Coatham (formerly Redcar)		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Tim Brown (LPA) 01287 612616
SITE NAME:	Guisborough		
DESIGNATION:	Conservation Area, 105 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tim Brown (LPA) 01287 612616
SITE NAME:	Loftus		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tim Brown (LPA) 01287 612616

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM UA Unitary Authority
WHS World Heritage Site

STOCKTON-ON-TEES (UA)



© Historic England Archive

SITE NAME: Phosphate rock silo (No. 15), Haverton Hill, Former ICI., Billingham

DESIGNATION: Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1115821 Reinforced concrete silo of 1928-29. Parabolic crosssection with reinforced concrete arches, with ribs at the ends. Designed by Monnoyer British Construction Ltd, for the storage of phosphate rock imported for the production of fertilizer. This is the earliest surviving example of this type of silo in England. The owner is considering options for repair and re-use.

Contact: Kate Wilson 0191 269 1221

ATTO LEARNS	

© Historic England Archive

SITE NAME:	Ruins of Church of St Thomas a Becket, Durham Road, Grindon
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1017321 and 1329821

Ruins of late C12 church that was altered significantly in 1789. Now a roofless, part-collapsed ruin and consolidation of the remains is required.

Contact: Kate Wilson 0191 269 1221

TYNE AND WEAR

GATESHEAD



SITE NAME:	Winlaton Mill ironworks, south east of Winlaton Mill village
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

LIST ENTRY NUMBER: 1021272

Most of this large and complex site is protected as it is buried beneath the ground; however, there are important upstanding structures, including the remains of Crowley Dam and spillway. Damaging vegetation was removed by the local authority in 2018. Project development for a proposed repair scheme was funded in 2018 through an Historic England Repair Grant for Heritage at Risk and local authority funding.

Contact: Sara Rushton 0191 269 1222



© Historic England

© Historic England

SITE NAME:	Dunston Staiths
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1005898 and 1248994

in 1893. Closed in the 1970s after being the last working staiths on the River Tyne. Fire damage in 2003 resulted in 8% of the monument being lost; with a further fire in 2010. A conservation plan, condition survey and feasibility study have been produced to identify a future for the structure. The first phase of repair was completed in 2016 funded by the Heritage Lottery Fund and Historic England. Project development for a further phase of repair was funded by Historic England and completed Summer 2018.

Built by the North Eastern Railway Company and opened

Contact: Sara Rushton 0191 269 1222

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

<u></u> t

© Historic England

SITE NAME:	Ravensworth Castle (Nash House), Lamesley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1025151

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Nash house of 1808 for Sir Thomas Liddell, completed by 1846 but now a ruin following extensive demolition in the 1950s. Urgent repairs were completed by the owners in 2015 following a condition survey commissioned by the Local Authority using Historic England grant-aid. An outline scope of works and costings for repair have also been produced. In-principle agreement with the owner to repair all of the designated heritage assets within the castle complex as ruins on a phased basis, beginning with the scheduled medieval remains.

Contact: Mike Collins 0191 269 1212



© Historic England

SITE NAME:	Ravensworth Castle, Cross Lane, Lamesley
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1016975 and 1025190

Medieval castle of which two C14 corner towers and part of its curtain wall survive in poor condition, as well as associated archaeological deposits. Urgent repairs were completed by the owners in 2015 following a condition survey commissioned by the Local Authority using Historic England grant-aid. A detailed repair scheme for the medieval castle remains has been prepared, and contractors appointed by the owners to implement this. This work will be phased over 5 years, and is due to start in 2018.

Contact: Mike Collins 0191 269 1212



© Historic England

SITE NAME:	Gibside Hall, B6314, Gibside Estate, Rowlands Gill, Whickham
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)

Large house/hall of 1603-20, enlarged in the C18 and altered early in the C19. Fell into disrepair early in the C20 and now a roofless shell in poor condition. Set in an early to mid-C18 park. The house requires major stabilisation and consolidation works. Natural England has funded the preparation of a management plan and prioritised schedule of repair works.

PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1017224 and 1299730

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME:	Whinfield coking ovens, south east of Low Spen Farm, Whickham
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

1018226

Remains of what was originally a bank of 193 bee-hive coke ovens dating from the mid-C19. Part of an extensive former mining landscape that is now largely cleared and landscaped. The remaining ovens represent a rare example of intact bee-hive coke ovens. Initial repairs were carried out in 2003 and 2016. This site was included in the "Land of Oak and Iron" Landscape Partnership Scheme and repairs are due to be completed by autumn 2018.

Contact: Sara Rushton 0191 269 1222



© Historic England

SITE NAME:	Church of St Chad, Rawling Road, Gateshead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1277841

St Chad's is cruciform in plan with a large octagonal tower at its centre. Designed by the architect William Searle Hicks, it was consecrated in 1903. The slated roof coverings are approaching the end of their serviceable life and there is some water ingress internally. The roofs of the nave and tower were replaced in 2016 through funding from a Listed Places of Worship Roof Repairs Grant. Funding options are currently being explored for the repair of the remainder of the roofs following two unsuccessful bids to the Heritage Lottery Fund Grants for Places of Worship scheme.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

gory is
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

ABBREVIATIONS

SITE NAME:	Coal mining remains at Dunston Hill		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1018227
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Road construction	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Site of Ravensworth coalmill, 600 metres north eas	t of Ravensworth	Castle, Lamesley
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1015922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ravensworth, Lamesley		
DESIGNATION:	Conservation Area, 11 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Clare Richardson (LPA) 0191 433 3510

32, Close (The Cooperage)

NEWCASTLE UPON TYNE



DESIGNATION: Listed Building grade II*, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

One of a group of late-medieval buildings on the Newcastle-upon-Tyne water front. Sandstone ground floor, supporting timber-framed upper floors. Gabled front of one bay and three storeys, with jettied first and second floors. Originally a merchant house and more recently a public house and restaurant. The building is vacant and deteriorating due to a lack of maintenance.

© Historic England

© Historic England

SITE NAME: Church of All Saints, Pilgrim

LIST ENTRY NUMBER:

SITE NAME:

Street, Newcastle upon Tyne

DESIGNATION: Listed Building grade I, CA

CONDITION: Poor

1024916

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C(C)

OWNER TYPE: Local authority

LIST ENTRY NUMBER: 1106329

Former church, built between 1786-96 by David Stephenson to replace a medieval church on the same site. Classical style, with baroque tower. All Saints was closed by the Church of England in 1961 and the building was subsequently occupied as an urban studies centre and concert hall before being temporarily used for worship by a faith group. Some works have been undertaken to stem the ingress of rainwater, however, further repairs are required and a new use needs to be found. The building has been subject to heritage crime. Discussions are underway about the site's future.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

The Keelmen's Hospital, City Road, Newcastle upon Tyne

DESIGNATION: Listed Building grade II*

CONDITION: Fair

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Local authority

1024902

Almshouses constructed in 1701 for keelmen and keelmen's widows. The building was last used as student accommodation but is now vacant and disused. It was a target for vandalism but the owner has improved security. Options for re-use are being actively explored.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:

5-13, Grey Street, Newcastle upon Tyne

DESIGNATION:

Listed Building grade II*, CA

CONDITION:

Poor

OCCUPANCY:

Part occupied/part in use

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Private

1139021

Four-storey shops and houses built circa 1835, probably by John Wardle for Richard Grainger. The property is now largely vacant and roof and rainwater goods in a poor condition with spalling and delamination shown on elevations. Interior suffering from dry rot. Proposals for reuse are being discussed.

A three-storey presbytery, attached to the south-east corner of St Michael's church, with a gabled front, stone walls and slated roofs. The building has not been actively used for some time. Gutters are choked with vegetation, there is some water ingress, and internal cracks adjacent to the end gable wall could indicate structural movement. Many of the external building elements are deteriorating and in need of a comprehensive programme of repairs. Discussions are underway to find a new use for the

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Presbytery attached to St Michael's church, Westmorland Road, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1024743

Contact: Kate Wilson 0191 269 1221

building.



© Historic England

SITE NAME:	Church of St Michael with St Lawrence, Avondale Road, Byker
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024948

Parish church built in 1862-63 to the design of WL Moffat. A north aisle and vestry were added in 1936. The building has suffered from roof leaks, general dampness and heritage crime. Urgent repairs were completed in 2013 with funding from the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme. Further funding was awarded in 2017, through the Heritage Lottery Fund Grants for Places of Worship scheme, for a supplementary phase of repairs to enable the building to dry out. Those repairs are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME:	Woolsington Hall, Woolsington
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1123737

A compact late-C17 country house, with later additions. It has service buildings, all set in fine gardens and parkland. A planning application to convert the building to a five-star hotel and spa was approved by the Local Authority in 2015. The Hall was gutted by a fire in December 2015 and the owners are now carrying out stabilisation and repair works to make the structure wind and weather tight.

SITE NAME:

LIST ENTRY NUMBER:

© Historic England

SITE NAME:	(former Church of St Paul), Havelock Place, High Elswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024846

Former parish church of 1856-9 designed by John Dobson. Closed in 2006, the church lay vacant and subject to heritage crime. It was taken over by the Life Transformation Ministry in 2009. Funding through the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme enabled a first phase of urgent repairs to be completed in 2014. Further funding, this time through the Heritage Lottery Fund Grants for Places of Worship scheme, facilitated a second phase of urgent repairs that were completed in 2017. Further works are required to secure the site's long-term use.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Church of St Luke, Claremont Road, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade I CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1355224

Religious organisation

Completed in 1890 to designs by Oliver & Leeson, St Luke's has a short nave with south porch, paired transepts and a chancel with north vestry and south chapel. It is constructed of red brick with steeply pitched roofs of Welsh slate, stone window surrounds and a west belfry. A scheme of external repairs was completed in 2014. Proposals for the repair of the interior are being developed to enable the main body of the church to be brought back into use for worship. Whilst these proposals develop, the adjoining parish hall is temporarily being used for worship.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Christ Church (and hall attached), Shieldfield Green, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024748

Parish church of 1859-61, by AB Higham, constructed of squared sandstone with ashlar dressings and Welsh slate roofs. The roofs are coming to the end of their life and water ingress is damaging internal plaster work. Funding, through the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme, allowed a first phase of roof repairs to be completed in 2015. Discussions are underway about a second phase.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Matthew, Summerhill Street, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1024757

LIST ENTRY NUMBER:

Built in 1877 by the local architect RJ Johnson, with a striking west tower added in 1895 by Hicks & Charlewood. The church has sandstone walls and a roof of plain clay tiles. The interior is tall and spacious with double aisles on either side of the nave. Funding, through the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme, enabled the completion of repairs to the nave and chancel roofs, and rainwater pipes, in 2014. A phased programme of work is being developed to address issues affecting the external stonework.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Dewley Hill round barrow and associated features, 350 metres north west of Dewley Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018678
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
	Hadrian's Wall and vallum in wall mile 9, Blucher to Dene House		
SITE NAME:	Hadrian's Wall and vallum in wall mile 9, Blucher to	Dene House	
SITE NAME: DESIGNATION:	Hadrian's Wall and vallum in wall mile 9, Blucher to Scheduled Monument, WHS	Dene House LIST ENTRY NUMBER:	1003790
	,		1003790 Declining
DESIGNATION:	Scheduled Monument, WHS Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building I PA

Local Planning Authority National Park ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	St John's Cemetery, Newcastle upon Tyne
DESIGNATION:	Registered Park and Garden grade II, 4 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1000761

A burial board cemetery of 1857 where the twinned northern entrance lodges and ornate joining arch (all listed grade II) are derelict and subsiding, the latter permanently propped. The chapels (grade II) are unused and fenced off although in fair condition. Boundary walls are subsiding. Many monuments are in poor condition, including the Mather Tomb (grade II), which is also fenced-off to prevent further damage. Terraces and steps on Miser Hill are in poor condition and overgrown.

Contact: Chris Mayes 0191 269 1226

	A PARTY	

© Historic England

SITE NAME:	Westgate Hill Cemetery, Newcastle upon Tyne		
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA		
CONDITION:	Generally unsatisfactory with major localised problems		
VULNERABILITY:	Medium		
TREND:	Declining		
NEW ENTRY?:	No		
OWNER TYPE:	Local authority		
LIST ENTRY NUMBER:	1001680		

One of the earliest garden cemeteries in England (1829) and the earliest in the North East. Despite having lost its chapel, and the original layout being obscured by vegetation, the character of the site remains legible. The remaining monuments are of a style particular to early cemeteries and many have been damaged through weathering, vandalism and ivy growth. Invasive weeds and scrub, along with vandalism, anti-social behaviour and minimal management, risks the loss of further legibility and fabric. Liaison with the Council has developed a project to produce a conservation plan for the site.

Contact: Chris Mayes 0191 269 1226

NEWCASTLE UPON TYNE / GATESHEAD



© Historic England

SITE NAME:	Battle of Newburn Ford
DESIGNATION:	Registered Battlefield, 6 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000025

The Battle of Newburn Ford (1640) was the only battle of the Second Bishops' War. The Scottish Army took Newcastle by defeating the English at this river crossing. The Scottish campaign forced Charles I to raise an army against them and, after the loss of Newcastle, to pay them off. This expense meant Charles had to recall Parliament, which proved to be a critical step towards the English Civil War. The battlefield has been subject to piecemeal, peripheral development but an outline action plan has been agreed between Historic England, the local authorities and the Battlefields Trust.

Contact: Tom Gledhill 0191 269 1203

NORTH TYNESIDE

SITE NAME:	St Peter's, Wallsend		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Planning Policy (LPA) 0191 6432310

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

SOUTH TYNESIDE



© Historic England

SITE NAME: Detached chimney at Cleadon Pumping Station, off Sunniside Lane DESIGNATION: Listed Building grade II*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

Commercial company

Large square chimney, detached from boiler house. Built in 1860-62 in Italianate style by Thomas Hawksley. A prominent local landmark and one of a series of pumping stations along the north east coast. A condition survey and schedule of repairs have been prepared with funding from Historic England. Discussions are underway about a first phase of work.

Contact: David Farrington 0191 269 1230

	9
	[
2	(
	(
	F
A LANDSON	

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© Historic England Archive

SITE NAME:	Marsden lime kilns, South Shields
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1005911

1416041

Massive C19 industrial kilns, of two types, that were in poor condition and in urgent need of repair. Following completion of project development work, urgent repairs have begun part-funded by Historic England, This outstanding repair work has now stalled due to the previous owners going into administration in autumn 2017.

SITE NAME: Christ Church, Grange Road West, Jarrow DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1025199

Parish church of 1868 by Johnson and Hicks in the Early English style. It has an aisled nave with steeply pitched slated roofs, a south porch and tall spire. Remedial works have been completed to the tip of the spire, however concerns remain about the deteriorating condition of the tower stonework. Discussions have taken place to identify potential sources of funding for repairs.

Contact: Kate Wilson 0191 269 1221

Contact: Tom Gledhill 0191 269 1203

SITE NAME:	Cleadon, South Tyneside		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lucy Routledge (LPA) 0191 424 7592
SITE NAME:	East Boldon, South Tyneside		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lucy Routledge (LPA) 0191 424 7592
SITE NAME:	Whitburn, South Tyneside		
DESIGNATION:	Conservation Area, 23 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VUI NFRABILITY:	1	CONTACT:	Lucy Poutledge (LDA) 0101 424 7502
VOLIVEIVABILITY.	Low	CONTACT.	Lucy Routledge (LPA) 0191 424 7592

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SUNDERLAND



© Historic England

SITE NAME: Old South Pier Lighthouse in Roker Cliff Park, Whitburn Road, Sunderland DESIGNATION: Listed Building grade II* CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Local authority

1218440

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Lighthouse, originally built on the old South Pier in Roker in 1856 by the engineer Thomas Meik. Constructed of iron and steel, it was transferred to its current site in 1983. Repair and redecoration works were completed in 2017 following problems of water ingress and localised decay due to corrosion. These were funded by Sunderland City Council. An updated maintenance plan is being finalised for the site.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME: 'F' Pit Museum - colliery engine house, Albany Way (East side) Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE:

Local authority LIST ENTRY NUMBER: 1018224 and 1025422

'F' Pit was sunk in 1777 but the engine house wasn't built until 1926. The pit closed in 1968 and the site was cleared, apart from the engine house. Representing a fine example of the winding technology used in the north east coalfield, the building re-opened as a museum in 1976. The museum continues to open to limited, seasonal, hours. However, the future of the building is uncertain and there has been no progress in preparing a condition survey.

© Churches Conservation Trust

SITE NAME-Church of Holy Trinity, Church Street East, Sunderland DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Charity (heritage)

1208056

Former parish church with west tower, in the care of the Churches Conservation Trust since 1988. Built 1718-19, with a rounded eastern apse added in 1735. The fabric of the building is deteriorating and there is some structural movement, particularly at the east end. A substantial grant was awarded by the Heritage Lottery Fund in 2018 to repair the building and establish it as a new cultural venue ('The Canny Space'). Urgent temporary repairs were completed with Historic England funding in March 2016 to safeguard the building pending the implementation of The Canny Space project.

Contact: David Farrington 0191 269 1230

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME: Doxford House, Warden Law Lane, Silksworth DESIGNATION: Listed Building grade II*, CA CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private

1279879

Large house (previously known as Silksworth House), formerly used as a students' hall of residence. Mostly of the early-C19 but with some earlier features. The property is vacant but has recently been acquired by a new owner who has made the building weathertight and secure. Work has started to implement the approved planning consent scheme which will see the building returned to a single residence.

Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME: Monkwearmouth Station Museum, with screen walls, footbridge and waiting room, Sunderland DESIGNATION: Listed Building grade II* CONDITION: Fair OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY C(C)OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: 1209029

1879, now a museum but closed for refurbishment. The site includes the main station building with pedimented portico and screen walls, an attached cast iron footbridge to the rear, and a waiting room and long screen wall to the west platform. There is a maintenance backlog, resulting in decay and some water ingress. A package of urgent repairs has recently been completed, and initial discussions have taken place to try and establish a maintenance regime for the site as a whole.

Former railway station, built in 1848 with additions of

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise.

I PA ΝP New Entry is noted). RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site



(0)	Histo	oric	Fng	hael

© Historic England

SITE NAME:	Church of Holy Trinity, Usworth
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1025382

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Guru Gobind Singh Gurdwara Sikh Centre (Formerly Christ Church), Ryhope Road,
	Sunderland

Listed Place of Worship grade II, DESIGNATION:

CONDITION: Poor PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER:

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1209657

LIST ENTRY NUMBER:

Formerly a parish church, built in 1862-64 by James Murray of Coventry. Closed by the Church of England, the building has been acquired by the Sikh community and continues as a place of worship. It contains high quality stained glass. A first phase of urgent repairs, including works to rainwater pipes and gutters, was completed in 2014 with funding from the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme. The spire is in need of urgent repair.

Designed by John and Benjamin Green of Newcastle, Holy Trinity church was built in 1831-2. It consists of a wide aisleless nave with a bellcote over the west gable and a chancel with a south lean-to vestry. The slated roof coverings over the nave are showing significant signs that they are reaching the end of their serviceable life, with many areas of slipped and patched slating. There has been some water leakage internally. An unsuccessful funding bid for repairs was submitted in 2017 through the Heritage Lottery Fund Grants for Places of Worship scheme.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Andrew, Park Avenue, Sunderland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation

1207113

Church built in 1906-7 by Edward S Prior and his site architect A Randall Wells. The church has a large landmark tower at the east end, above the chancel, and a wide and broad nave. A highly innovative structure recognised as a rare artistic achievement. Repairs to window glazing were completed in 2016 following the award of funding from the Heritage Lottery Fund Grants for Places of Worship scheme. A further grant from the same source was awarded in 2016 to fund repairs to the tower stonework. Those repairs are due to be completed in 2018.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Hylton Castle medieval fortified house, chapel, C17 and C18 country houses and associated gardens		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017223
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Lee McFarlane 0191 269 1239
SITE NAME:	Old Sunderland		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Mark Taylor (LPA) 0191 5611515
SITE NAME:	Old Sunderland Riverside		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
DESIGNATION: CONDITION:	Conservation Area, 11 LBs Very bad	NEW ENTRY?: TREND:	No Improving
	,		
CONDITION:	Very bad Low	TREND:	Improving
CONDITION:	Very bad	TREND:	Improving
CONDITION: VULNERABILITY:	Very bad Low	TREND:	Improving
CONDITION: VULNERABILITY: SITE NAME:	Very bad Low Sunniside	TREND: CONTACT:	Improving Mark Taylor (LPA) 0191 5611515
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION:	Very bad Low Sunniside Conservation Area, 45 LBs, part in RPG grade II	TREND: CONTACT: NEW ENTRY?:	Improving Mark Taylor (LPA) 0191 5611515 No

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SUNDERLAND / GATESHEAD



© Gateshead Metropolitan Borough

SITE NAME: Bowes Railway, track, wagon shop, hauler houses and associated sheds, structures and incline, Bowes Railway, Lamesley DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: B (B) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1003723

Track and inclined track bed, sheds, hauler houses and associated workshops comprising part of the Bowes Railway, one of the earliest and best preserved examples of a rope haulage system. The site is vulnerable to vandalism. Since 2003, several repair schemes have been undertaken, all part-funded by Historic England. These include repairs to the stone walling of the engineering shop at Springwell, completed in 2017. A condition survey of the track bed and related structures between Blackfell and Blackham Hill hauler houses has also recently been prepared with Historic England funding.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

This document is one in a series of publications produced as part of Historic England's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk
Published November 2018
4th Floor, Cannon Bridge House
25 Dowgate Hill
London EC4R 2YA
© Copyright Historic England 2018

Product code: 52098

