## Heritage at Risk



## Contents

The Register	III	Somerset	173
Content and criteria	III	Exmoor (NP)	173
Criteria for inclusion on the Register	V	Mendip Sedgemoor	177 182
Reducing the risks	VII	South Somerset	186
Key statistics	ΧI	Taunton Deane West Somerset	191
Publications and guidance	XII	South Gloucestershire (UA)	193 195
Key to the entries	XIV	Swindon (UA)	198
Entries on the Register by local planning authority	XVI	Torbay (UA)	200
Bath and North East Somerset (UA)	1	Wiltshire (UA)	202
Bournemouth (UA)	3		
Bristol, City of (UA)	4		
Cornwall (UA)	8		
Devon	47		
Dartmoor (NP) East Devon Exeter Exmoor (NP) Mid Devon North Devon South Hams Teignbridge Torridge West Devon  Dorset  Christchurch East Dorset North Dorset Purbeck West Dorset	47 70 77 78 79 82 87 94 96 105 108 108 113 120 128		
Weymouth and Portland  Gloucestershire	145 146		
Cheltenham Cotswold Forest of Dean Gloucester Stroud Tewkesbury	146 146 151 154 155 159		
Isles of Scilly (UA)	162		
North Somerset (UA)	167		
Plymouth, City of (UA)  Poole (UA)	168 173		
FUOIE (UA)	1/3		

II

## THE REGISTER

### Content and criteria

## LISTING Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of listed assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the system of statutory protection of heritage assets. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now over 400,000 assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Digital, Culture, Media and Sport who makes the decisions on whether an asset is listed. Understanding and appreciation develop constantly, which makes keeping the listing database up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of listing a site, and better communication of what makes something special.

In June 2016 Historic England launched Enriching the List, a crowdsourcing initiative opening up the entries on the National Heritage List to contributions by users. Anyone can register as a volunteer and submit extra information about assets on the List or submit photographs to illustrate them. This additional content will then be available for anyone to view with (but separate from) the official List Entry.

Alongside the nationally listed assets found on the National Heritage List for England are locally listed assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

#### LISTED BUILDINGS

Listing is the most commonly encountered type of statutory protection of heritage assets. A listed building (or structure) is one that has been granted protection as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Digital, Culture, Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly important buildings of more than special interest; together they amount to 8.3% of all listed buildings. The remaining 91.7% are of special interest and are listed grade II. There are over 378,000 entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory List.

Structures can occasionally have dual List entries (be both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

### SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. Nearly 20,000 examples have been listed because of their national importance. Scheduled monuments are not graded. They cover human activity from the Paleolithic era, such as cave sites, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record. The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic sites that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside.

Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and, often most seriously of all, wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not scheduled. Instead, they are managed through the planning system and other regimes.

#### REGISTERED PARKS AND GARDENS

There are over 1,600 landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II\*, and the Gardens Trust on sites of all grades. The setting of other listed heritage assets can also protect registered landscapes.

#### REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of listing. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where often thousands were killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now nearly 50 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive and damaging metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

#### PROTECTED WRECK SITES

There are over 50 protected wreck sites in England, which represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to list a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

#### **CONSERVATION AREAS**

Conservation areas are listed by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For over 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis.

There are currently nearly 10,000 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

# Criteria for inclusion on the Register

#### RISK ASSESSMENTS

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of listing. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections, depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

#### **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England;
- a grade I or II\* listed building;
- a grade II listed building in London;
- a structural scheduled monument with upstanding remains;
- in secular (non-worship) use.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of

buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

#### PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II\* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

#### **ARCHAEOLOGY**

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

#### PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II\* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

#### **BATTLEFIELDS**

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

#### WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

#### **CONSERVATION AREAS**

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern, or are believed to no longer be at risk.

Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. An overall category for condition, vulnerability and trend is included for each conservation area on the Heritage at Risk Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

## Reducing the risks

One of the primary aims of the <u>Historic England</u> <u>Corporate Plan 2017-2020</u> is protecting places through Heritage at Risk grants and advice, thereby reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grant aid to help remove sites from the Register.

Dedicated Heritage at Risk teams in our regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, <a href="https://www.historicengland.org.uk">www.historicengland.org.uk</a>. Key publications and

www.histoncengland.org.uk. Key publications and guidance are also listed in this Register.

#### **BUILDINGS AND STRUCTURES**

Historic England regional teams can help owners and local authorities better understand buildings and

structures at risk, advise on necessary repairs and on finding new uses. Our teams can provide support with commissioning specialist surveys, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the expertise of Historic England's national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law.

Historic England can help with access to funding. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk and Section 17 Management Agreements (which are smaller grants for scheduled monuments). More information on funding can be found on the Historic England website. The support of other grant providers, including the Heritage Lottery Fund, the Architectural Heritage Fund and Natural England, is also critical.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We also know that heritage, when well cared for, helps create vibrant and successful places. Our regional teams are therefore working with local authorities to encourage them to develop their own strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our legal team can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and help fund their regional support officers to work across the country. They help BPTs and other not- for-profit organisations to access funding, carry out feasibility studies and develop solutions for places at risk. The <u>Heritage Trust Network</u> is also a valuable source of advice. Further guidance and case studies are available on the <u>Historic England</u> website.

#### PLACES OF WORSHIP

Historic places of worship are cared for by thousands of volunteers throughout the country. Sometimes these treasured buildings will require major repairs. However, regular maintenance will help prevent minor problems developing into unnecessary crises. Keeping drains and gutters clear is essential: the overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable. In some

areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The practical resources created by the Maintenance Cooperatives Project run by the Society for the Protection of Ancient Buildings are available from their website. These are a great starting point for local groups wanting to work together to do basic, regular maintenance safely.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. Our advice web pages help congregations understand how changes can be achieved. The Heritage Lottery Fund welcomes applications from places of worship seeking to do repairs, develop facilities or welcome more visitors.

A network of support officers, employed locally but part-funded by Historic England, offers direct advice and encouragement to congregations. Projects to achieve repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

From September 2018 to March 2020 the Department for Digital, Culture, Media and Sport is funding a pilot study to explore a slightly different approach. This is focusing on fabric maintenance (supported by a small grant fund) and community development to explore opportunities for wider engagement beyond the congregation in voluntary, social and commercial sectors. Pilot schemes, which cover listed places of worship of all denominations and faiths, are running in Greater Manchester and Suffolk.

The Government's <u>Listed Places of Worship scheme</u>, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

#### **ARCHAEOLOGY**

The continued excellent progress which is being made with reducing the number of scheduled monuments on the Register demonstrates the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agri-environment

grant schemes to best effect. This has been especially important under the Countryside Stewardship Scheme, where our advice has resulted in the removal of 29 sites from being at risk this year. Our work in partnership with Natural England on agrienvironment schemes has removed well over 800 scheduled monuments from the Register since 2009 and we therefore welcomed the recognition given to the value and importance of heritage within the 25 Year Environment Plan and the Agriculture Bill. The Bill proposes that the conservation of rural heritage will be one of the environmental public goods funded through the domestic successor to the Common Agricultural Policy after the UK leaves the European Union. We also continue to work closely with local trusts, volunteers and the Heritage Lottery Fund to identify the nationally important monuments for enhanced conservation, presentation and access projects which is providing increased public value and enjoyment of our heritage.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register, affecting 38% of archaeological entries on it. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke recommendations for each monument, enabling cultivation to continue where it does not present a risk. It will also be an important tool for advising owners on the longer term management of their monuments as the existing ten year Environmental Stewardship agreements expire.

Although great progress has been made, analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites. Such vegetation growth, combined, makes up 30% of the risk factors affecting monuments at risk. To help address one of these key risk factors Historic England have been working with landowners and scientists to research and provide guidance on bracken control.

In most cases simple, low cost but regular maintenance is the key, with such improvements in management removing 36 sites from the Register this year alone. The delivery of these will always be reliant upon the help and goodwill of landowners. We are also sponsoring a number of projects to help volunteers and the public to get involved – which not only helps owners but also promotes wellbeing and public understanding of heritage.

#### PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities.

Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

#### **BATTLEFIELDS**

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the NPPF makes it clear that registered battlefields are 'assets of the highest significance', and of equal significance to scheduled monuments, buildings listed grade I and II\*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage policy and legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contributes towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra and Natural England through environmental stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of

ploughing and as part of a wider drive to prevent unauthorised and damaging metal detecting.

Local authorities invite comments from Historic England and the Battlefields Trust on planning applications that affect registered battlefield sites.

Historic England also continues to encourage greater access to battlefields and the enhancement of their amenity value. We wish to ensure an increased understanding and wider appreciation of the ways that these dramatic historic events have shaped our nation.

#### WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival. Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from Historic England.

#### CONSERVATION AREAS

Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them, as well as those of us whose job it is to manage them or make decisions about their future.

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management.

Local authorities assess conservation areas and fill in a questionnaire for those newly at risk, giving us an

insight into the issues which have had a negative effect upon the conservation area, and so help us to establish how these issues can be addressed.

Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area questionnaires we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

## Key statistics

#### **BUILDINGS AND STRUCTURES**

- Nationally, 834 (3.7%) of grade I and II\*
  listed buildings (excluding places of worship)
  are on the Register. In the South West the
  percentage is 2.8% (151 listed secular
  buildings).
- 16 building or structure entries have been removed from the 2017 South West Register because their futures have been secured, and 9 have been added.
- 67.4% of buildings or structures (124) on the South West baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 64.4%.

### PLACES OF WORSHIP

- Nationally, 6.2% of listed places of worship are on the Register. In the South West, 5.6% (165) are on the Register.
- 21 places of worship have been removed from the South West Register following repair work, and 7 have been added.

#### **ARCHAEOLOGY**

- 2,431 (12.2%) of England's 19,852 scheduled monuments are on the Register. 1,088 (15.6%) of the South West's 6,984 scheduled monuments are on the Register.
- 62 archaeology entries have been removed from the 2017 South West Register for positive reasons, and 33 have been added.
- 41% of archaeology entries (582) on the South West baseline 2009 Register have been removed for positive reasons, compared with the national figure of 47.7%.

• Nationally, damage from arable cultivation is the greatest cause of risk affecting 38.3% of archaeological entries on the Register. In the South West the proportion is 31.7%. The risk to 33.8% of entries on the South West Register is from unrestricted plant, scrub and tree growth. The national figure for plant, scrub and tree growth is 26.4%.

#### PARKS AND GARDENS

- 99 (5.9%) of England's 1,664 registered parks and gardens are on the Register. Of the 303 registered parks and gardens in the South West, 16 (5.3%) are on the Register.
- No park and garden entries have been added or removed from the 2017 South West Register.

#### **BATTLEFIELDS**

Of the 47 registered battlefields in England, 4
 (8.5%) are on the Register. Of the 10
 registered battlefields in the South West, 1
 (10.0%) is on the Register.

#### WRECK SITES

• Of the 53 protected wreck sites around England's coast, 4 (7.5%) are on the Register. None of the South West's 27 protected wreck sites are on the Register.

#### **CONSERVATION AREAS**

- There are currently 502 Conservation Areas on the Heritage at Risk Register. Of these 33 are in the South West.
- 2 conservation areas have been removed from the 2017 South West Register for positive reasons, and none have been added.

#### HISTORIC ENGLAND FUNDING

• £1.53 million in grant was spent on 69 entries on the South West Register during 2017/18.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

<u>Assessment of Heritage at Risk from</u> <u>Environmental Threat: Key Message</u> (2013)

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – <u>Historic</u> <u>England Research News 21</u>, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

Heritage at Risk 2010 - Report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2018 – national summary leaflet

<u>Heritage at Risk Online Register</u> – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database.

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire.

<u>Historic Wreck Sites at Risk: A Risk</u> <u>Management Toolkit</u> (2017)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2016)

<u>Vacant Historic Buildings: Guidelines on</u> <u>Managing Risks</u> (2018)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit <u>Heritage at Risk</u> where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database. Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address.

## GUIDANCE NOTES AND APPLICATION FORMS FOR GRANTS

<u>Historic England Grant Schemes</u> – online overview of all our current grant schemes, including the Repair Grants for Heritage at Risk scheme.

<u>Grants to Local Authorities to Underwrite Urgent</u> Works Notices

Acquisition Grants to Local Authorities to Underwrite Repairs Notices

Repair Grants for Heritage at Risk

## CONSERVATION ADVICE AND GUIDANCE

The following publications are among the numerous guidance documents available for free on <u>Historic England Advice</u> web page:

Conservation Area Designation, Appraisal and Management (2018)

<u>Conservation Principles, Policies and Guidance</u> <u>for the Sustainable Management of the</u> <u>Historic Environment (2008)</u>

<u>Conservation and Management of War</u> <u>Memorial Landscapes</u> (2016)

<u>The Conservation, Repair and Management of War Memorials</u> (2015)

**Guidance on Constructive Conservation** 

Guidance on Improving Streets and Public Spaces

**Guidance on Looking after Historic Buildings** 

<u>Guidance on Looking after Historic Cemeteries and</u> Burial Grounds

<u>Guidance on Looking after Historic Parks, Gardens</u> <u>and Landscapes</u>

Guidance on Looking after Places of Worship

<u>Guidance on Protecting the Rural Historic</u> Environment

Guidance on Tackling Heritage Crime

<u>Heritage Works: a Toolkit of Best Practice in</u> <u>Heritage Regeneration</u> (2017)

<u>Latest Advice and Guidance</u> – this web page highlights our most recent advice on a wide range of heritage-related topics.

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2017)

Metal Theft from Historic Buildings. Prevention, Response and Recovery (2017)

<u>Practical Building Conservation</u> – revised ten-part series: Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing, Glass & Glazing; Metals; Mortars, Renders & Plasters; Stone; Timber (2012–2015)

<u>Pillars of the Community: the Transfer of Local</u> <u>Authority Heritage Assets</u> (2015)

<u>Post-War Public Art: Protection, Care and Conservation</u> (2016)

<u>Registration Selection Guide: Battlefields</u> (2017)

<u>Scheduled Monument Consents: A</u>
<u>Guide for Owners and Occupiers</u> (2014)

The Disposal of Heritage Assets: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

The Installation of Telecommunications Equipment, Including Broadband and Mobile, in Churches and Other Listed Places of Worship (2017)

## Key to the entries

The Register includes the following risk assessment types:

• Building or structure

(grade I and II\* listed buildings, grade II listed buildings in London and structural scheduled monuments)

Place of worship

(grade I, II\* and II listed buildings)

Archaeology

(scheduled monuments – earthworks and buried archaeology)

Park and garden

(Registered parks and gardens)

Battlefield

(Registered battlefields)

Wreck site

(Protected wreck sites)

Conservation area

(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

#### **ORDER**

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

#### **LISTING**

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II\*
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

#### CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

#### TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

### **OWNERSHIP**

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

#### CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

CA Conservation Area
HE Historic England
HLF Heritage Lottery Fund
LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site
RB Registered Battlefield

RPG Registered Park and Garden

SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

## Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
BATH AND NORTH EAST S	OMERSET (UA)						
Bath and North East	3	0	8	0	0	0	3
Somerset (UA)		0	0			0	
BOURNEMOUTH (UA)	1			T	1		
Bournemouth (UA)	0	4	I	0	0	0	1
BRISTOL, CITY OF (UA)		l		T	1		
Bristol, City of (UA)	9	5	4	0	0	0	1
Bristol, City of (UA) / Bath and North East Somerset (UA) <sup>†</sup>	0	0	0	1	0	0	0
CORNWALL (UA)	'			1	'		
Cornwall (UA)	34	26	186	ı	ı	0	1
DEVON							
Dartmoor (NP)	2	3	154	0	0	0	0
East Devon	3	5	36		0	0	
Exeter	0	2	I	0		0	
Exmoor (NP)	0	2	7	0		0	
Mid Devon	2	I	16	0		0	
North Devon	3	8	17	0		0	
South Hams	8	13	21	0		0	
Teignbridge	2	3	7	2		0	
Torridge	3	12	36			0	
West Devon	6	3	9	1		0	
DORSET	0		7		0	0	0
Christchurch	0	0	2	0	0	0	0
	0			0			
East Dorset	1	0	33			0	
North Dorset	4	1	43	0		0	
Purbeck	3	0	48	0		0	2
West Dorset	13	3	97	1	0	0	0
Weymouth and Portland GLOUCESTERSHIRE	3	0	3	0	0	0	ı
	0	2			0	0	0
Cheltenham	0	2	0			0	
Cotswold	3	9	21	0		0	
Forest of Dean	•	,	8	0		0	
Gloucester	3	0	0			0	
Stroud	5	7	5			0	
Tewkesbury	7	4	7	0	0	0	I
ISLES OF SCILLY (UA)							
Isles of Scilly (UA)	2	0	30	0	0	0	0
NORTH SOMERSET (UA)				1		_	
North Somerset (UA)	3	2	I	0	0	0	4
PLYMOUTH, CITY OF (UA)				T	1		
Plymouth, City of (UA)	13	I	13	0	0	0	0
POOLE (UA)		l		I	1		
Poole (UA)	0	I	I	0	0	0	I
SOMERSET				T.	I		
Exmoor (NP)	2	0	22			0	0
Mendip	5	9	17		0	0	0
Sedgemoor	2	8	12		0	0	
South Somerset	8	12	3	2	0	0	0
Taunton Deane	6	<u> </u>	8	0	0	0	1
West Somerset	1	1	7	I	0	0	0
SOUTH GLOUCESTERSHIRE	(UA)						
South Gloucestershire (UA)	6	2	3	2	0	0	2
SWINDON (UA)							
Swindon (UA)	1	I	11	0	0	0	0
·							

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
TORBAY (UA)							
Torbay (UA)	4	l I	I	3	0	0	1
WILTSHIRE (UA)							
Wiltshire (UA)	13	9	153	I	0	0	0
Wiltshire (UA) / New Forest (NP) <sup>†</sup>	0	0	I	0	0	0	0
TOTAL	187	165	1053	16	I	0	33

 $<sup>^{\</sup>dagger}$  Sites that cross local planning authority boundaries

OWNER TYPE:

LIST ENTRY NUMBER:

#### BATH AND NORTH EAST SOMERSET (UA)



© Historic England Archive

SITE NAME: King Edward's School, Broad Street, Bath Listed Building grade II\*, CA, DESIGNATION: WHS CONDITION: OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1395027

School dating from 1752. A scheme for use as a hotel was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has therefore diminished but the building remains vacant. Permission for hotel use was granted in 2010 and renewed in 2013. As of summer 2018 scheme of works is being defined which will see the external envelope and setting to the front and rear, external joinery, rainwater goods and drainage all prioritised (expected 2018/19).

Dating from 1815, Cleveland Baths are believed to be the

and Caretaker's Cottage. Listed Building Consent was

Fund bid to finance the works after an application was

granted in April 2017 for a scheme of repair and renovation works that will enable the baths to be re-

oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms

opened for use. The Cleveland Pools Trust have confirmed their intention to continue with a further Heritage Lottery

Contact: Samuel Souter 0117 975 0690

Table 1	4	38.0
-41	111	n z
		A A
Sh. ekr.		

© Jim Warren

SITE NAME: Cleveland Baths, Hampton Row, Listed Building grade II\*, CA, DESIGNATION: WHS CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D)

Local authority

1396146

Contact: Stephen Guy 0117 975 0725

rejected in December 2017.



© Historic England

SITE NAME:	Hinton Priory, Hinton Charterhouse
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade I, LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coach house and garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures in use except chapter house, which is the area at risk. Some parts are in need of a condition assessment.

1007014 and 1136191; LIST ENTRY NUMBER: 1320809; 1129461

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Camerton Romano-British town and associated Norton-Radstock	prehistoric and early	medieval monuments, Camerton /
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013881
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman road 720 yards (660 metres) long, north	of Abbey Farm, Hinto	on Charterhouse
SITE NAME:  DESIGNATION:	Roman road 720 yards (660 metres) long, north Scheduled Monument	of Abbey Farm, Hinto	on Charterhouse
	, , , , ,	•	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005421

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Stantonbury camp and adjacent sections of Wansd	yke, Marksbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Lansdown Roman camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005422
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Little Down camp, North Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004677
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Wansdyke: south east of Newbarn Farm, Norton 1	Malreward	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003066
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Wansdyke: section 1230 yards (1120 metres) easts	wards from Burnt H	House Inn, Southstoke
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007003
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa at Upper Hayes, Wellow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007002
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Keynsham		
DESIGNATION:	Conservation Area, 52 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020
SITE NAME:	Midsomer Norton and Welton, Norton-Radstock		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Adrian Neilson (LPA) 01225 477020

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Paulton (including Paulton Basin)		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Adrian Neilson (LPA) 01225 477020

#### **BOURNEMOUTH (UA)**



© Historic England

SITE NAME: Church of St John the Evangelist, Christchurch Road, Bournemouth DESIGNATION:

Listed Place of Worship grade II\*, CA

Religious organisation

CONDITION: Poor PRIORITY CATEGORY: C (C)

LIST ENTRY NUMBER: 1152799

OWNER TYPE:

Flint-clad Victorian church. A Listed Places of Worship Roof Repairs Grant was awarded in 2015, and stage 1 repairs to the roof and cast-iron rainwater goods are complete, however the west end and tower are also in a poor state, with crumbling stone and falling masonry, and funding is currently sought for this second phase.

Contact: Katy Hoskyn 0117 975 1311



SITE NAME: Church of St Michael, Poole Road, Bournemouth Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1324732 Substantial Victorian church with very large tower. This tower has significant problems and is difficult to access for maintenance. The rainwater goods are not taking water away and interior wall paintings are vulnerable to water ingress.



SITE NAME: Church of St Clement, St Clement's Road, Bournemouth DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1324751

A large Victorian church set in a public park. The tower roof is leaking badly and needs to be replaced. The rainwater goods are inadequate to carry water away from the building and the masonry is showing signs of damp.

Contact: Katy Hoskyn 0117 975 1311

Contact: Katy Hoskyn 0117 975 1311



© Historic England



SITE NAME:	Church of St Stephen, St Stephen's Road, Bournemouth
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENITRY NILIMBER.	1224754

Monumental Victorian church with a faceted east end, set within a small, restricted site. There is some water penetration, and there have been falls of interior masonry due to rusting ferramenta (iron fittings). The church has been subject to heritage crime in recent years.

© Historic England

Contact: Katy Hoskyn 0117 975 1311 132<del>4</del>/56

SITE NAME:	Two round barrows 300 yards (270 metres) north	west of Double D	ykes, Hengistbury Head
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002397
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

SITE NAME:

SITE NAME:	Churchill Gardens, Boscombe		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Caroline Peach (LPA) 01202 451323

#### BRISTOL, CITY OF (UA)



© Historic England

SITE NAME: Two lodges and attached garden walls opposite former Kings Weston stables, Napier Miles Road Listed Building grade II\*, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Educational (state sector)

1187186

pond and attached to a garden wall. 1763, by Robert Mylne. The buildings have been vacant for a number of years and are in poor condition. Damaged rainwater goods have led to water ingress and deterioration of some areas of ashlar stonework. The pond is suffering from water loss, extensive vegetation growth and damage to its lining.

Imposing mid-C18 Palladian suburban villa, until recently in

Square pedimented ashlar lodges, flanking a central square

Contact: Alessandra Perrone 0117 975 1345

hospital use, now vacant. A scheme of repair and conversion was granted consent in 2013, and works to the exterior of the main building are largely complete. The house was sold to a new owner in November 2015. Permission has been granted for conversion to an office

and works are still underway as of May 2018.



© Historic England

SITE NAME:	Mortimer House, Clifton Down Road, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1202096

ENTRY NUMBER: 1202096 Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1202186

Wrought iron bridge built c1844 by IK Brunel with tubular supporting members. Moved to current location in 1873. It has been redundant and decaying on the dock since construction of Plimsoll Bridge in C20. Since 2014 a number of surveys on the condition of the fabric along with some trial repairs have been carried out with the help of grant funding from Historic England. In 2018 investigations were focussed on the condition and functionality of the rotational mechanism.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

	Court Vicarage, Inns Court Green, Knowle, Bristol
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1202314

Stair turret (Holy Cross), Inns

C15 stair turret attached to C20 building. Situated in the middle of a housing estate. The house the turret is attached to changed hands in 2014 and the roof of the stair turret was repaired when improvement works were undertaken to the house.

Contact: Sarah Ball 0117 975 0666

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

rity category is LE ets (otherwise, LF oted). NI RF

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Church of St Michael and attached railings, St Michael's Hill, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1282109

Church, rebuilt between 1775 and 1777 in a Gothic style, but retaining the mid C15 tower. The interior is divided in three aisles by classical colonnades and has some late C19 fittings. The church was last in use in the late 1990s, and the roofs of the nave and north aisle were damaged by fire in October 2016. In April 2018 Bristol DAC announced that they have selected a buyer for the church who intends to install the new roof later in the year and seek consent for use of the church as a community event space and heritage centre.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	28, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1202444

One of a terrace of seven houses located in a largely complete Georgian square, c1789-1820. Limestone ashlar, brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. A planning application for repair works and conversion to hotel use was approved in November 2016.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

SITE NAME:	31 and 32, Portland Square, St Pauls, Bristol
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1208879

Terraced houses, built from 1789 to 1820. Emergency repairs to the roof were carried out with Historic England grant aid in 1996. Further damage occurred in 2005 when part of the facade collapsed. The buildings have been vacant for over 20 years and conditions continue to deteriorate. An approved scheme for repairs and residential conversion expired in December 2015.

Contact: Alessandra Perrone 0117 975 1345



© Historic England Archive

SITE NAME:	Carriage Works, 104, Stokes Croft, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1025273

Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site including 4, Ashley Road (grade II), also in very bad condition. Planning permission for a mixed use redevelopment of the site was granted in October 2015 and the site was sold to new owners in summer 2017. Work on site to deliver the approved development commenced at the beginning of May 2018.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	The Trinity Centre, Holy Trinity Church, Trinity Road, Bristol
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Charity (non-heritage)

1282076

Large perpendicular Gothic Revival Commissioners' Church c 829. Trinity Community Arts Ltd lease building for use as arts venue. First phase of improvements carried out 2013-14 with Big Lottery funding. Historic England grant aided repairs to south aisle roof; completed in 2013. Historic England grant accepted in 2017 for repairs to north aisle roof and unstable high level stonework and a Heritage Lottery Fund grant for stonework and windows in 2017. Work underway.

Contact: Sarah Ball 0117 975 0666

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS	
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garde
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of All Hallows, All Hallows Road, Bristol
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1201954

Bristol architect Sir George Oatley. Plan and form are a creative fusion of congregational and liturgical style. Site was a former clay quarry and the foundations rest on filled ground at differing levels. The building suffered from differential settlement and was monitored for structural movement. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship was accepted in 2012 for surface water drainage works and structural repairs. Repairs completed 2014. Some roofing and drainage issues yet to be addressed.

Large Decorated Gothic Revival church of c1900 by the

Contact: Chris Miners 0117 975 1308



SITE NAME:

LIST ENTRY NUMBER:

SITE NAME:	Church of St Mary the Virgin, Church Close, Bristol
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1205113

A C13 church with C19 restoration. Roof coverings and rainwater goods are all in poor condition and there is vegetation growing out of the eroding masonry. Areas of mortar erosion and cement render are in need of replacement. This building has been subject to heritage

Contact: Katy Hoskyn 0117 975 1311



	Road, Bristol
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1205207

Church of St Peter Church

Norman Revival style parish church, completed in 1842 by SC Fripp. Squared lias rubble with limestone ashlar dressings and a slate roof. Short, square chancel tower with a pyramidal roof. Significant areas of stone decay to the south elevation and southern face of the tower. Some areas of falling masonry.

© Bill Wood

120	75
7	-7
1881 1881	-74

SITE NAME:	Church of St Philip and St Jacob, Tower Hill, Bristol
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1218100

Contact: Alessandra Perrone 0117 975 1345



© Ferguson Mann Architects

SITE NAME:	Church of St Philip and St Jacob, Tower Hill, Bristol
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1218100

Large parish church in the eastern part of central Bristol. Believed to stand on the site of the oldest church in the Bristol area; a Benedictine Priory dating from at least AD 900. The chancel, nave and lower tower are C13/C14 whilst the north chancel aisle and upper tower are mid C15 with a distinctive Gothic revival phase in 1764, and alterations in 1836-41. The roof is leaking and causing damage to roof structure and ceiling plaster. The building has been subject to heritage crime. Heritage Lottery Fund Grant for Places of Worship accepted and roof repairs underway in 2018.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Roman Catholic Church of St Bernadette, Wells Road, Bristo
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1436044

Parish church designed in 1967 by James Leask of Kenneth Nealon, Tanner & Partners to accompany the Catholic school built on the centenary of the apparitions at Lourdes. Bold and innovative in design and materials, it features a double hyperbolic paraboloid roof carried on projecting concrete piers on a rotated square plan. Some of the original materials are now showing signs of deterioration and this has led to serious issues of water ingress through the roof coverings, affecting the ceiling and the reinforced concrete roof structure. Some episodes of vandalism have also taken place.

Contact: Alessandra Perrone 0117 975 1345

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HENTAGE AT NISK 2016 / 300	of H WEST / BRISTOL, CITT OF (OA)		
SITE NAME:	Anti-aircraft gun site, Purdown		
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1004531
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Civil War earthworks on Brandon Hill		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006989
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Heavy Anti-aircraft battery 520 metres east of Hol	es Mouth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021291
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	St Mary-le-Port Church, High Street		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1021385
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Stokes Croft		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kingsley Fulbrook (LPA) 0117 922 2966

### BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)



© Historic England

SITE NAME:	Brislington House
DESIGNATION:	Registered Park and Garden grade II*, 4 LBs, CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001529

One of the first and most influential asylum landscapes in Britain. Now subdivided between a sixth form college, private residential development, commercial sports facilities, industrial units and a management training centre. Despite this, some elements of the designed landscape survive. Its designation was re-evaluated by Historic England in 2017. Some adjustment to the boundary was made but no change to the grade. Part of the park is in Bath and North East Somerset Unitary Authority.

Contact: Jo McAllister 0117 975 0696

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

#### CORNWALL (UA)



© Historic England

DESIGNATION: Scheduled Monument and Listed Building grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1004347 and 1140707

being kept under reasonable control. Works have been undertaken to stop water ingress and repairs to metalwork throughout site. Drawbridge and main gate repairs were completed in 2014. The ditch was cleared in 2015.

Built 1868, used for military training purposes. Vegetation is

Contact: Annie Evans 0117 975 1308

1
AAAT
TO THE REAL PROPERTY.

© Ministry of Defence

SITE NAME:	Tregantle Fort, Antony
DESIGNATION:	Scheduled Monument and Liste Building grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

OWNER TYPE: Government or agency
LIST ENTRY NUMBER: 1004346 and 1159255

Fort, built 1858-1865. The fort is vacant, with no end use identified. The interior of the keep is in poor condition, notably the wooden floors. New external doors and windows have been fitted. Interior partitions are still awaiting re-installation. Elsewhere in the fort, the barracks accommodation is no longer used full time with interiors deteriorating in places due to moisture penetration. A section of the counterscarp wall has collapsed. Significant localised problems remain to be tackled elsewhere on the site.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Becket 45 metres east of the church, Priory Road, Bodmin
DESIGNATION:	Scheduled Monument, LB grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
	D (C)

The monument is the roofless ruin of a C14 chapel, located within the churchyard of St Petroc's church. The building suffers ivy growth on the walls, vandalism and anti-social use of the crypt.

PRIORITY CATEGORY: B (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1002937

Contact: Ann Preston-Jones 07917 642388

Large early C19 H-plan granite town house in its own grounds. Latterly a residential home but vacant for some time. Lack of maintenance and vandalism resulted in rapidly increasing deterioration. Repairs agreed in 2012 and a revised scheme approved in 2013. The building has been made secure and weatherproof. Work continues to be implemented in line with the approved scheme (2018).



© Historic England

SITE NAME:	Rosewarne House (Gladys Holman House), Tehidy Road, Camborne
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Private

1142639

in use

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Church, Church Street, Carharrack
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1160248

Grade II\* Methodist chapel built in 1815, was purchased in 2017 following its redundancy as a place of worship. Water ingress through the deterioration of the roof cover and under sized rainwater goods has resulted in structural issues with the window lintels and floor of gallery. Discussions were held regarding the future use of the building in May 2017 but no further correspondence has been held.

Contact: Catherine Marlow

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LOCAL Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Historic England

© Historic England

SITE NAME:	Marlborough House, Silverdale Road, Falmouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company

1270002

LIST ENTRY NUMBER:

Grade II\* former country house now in suburbs of Falmouth. Building was sold having been vacant and in poor condition. Discussions with the new owner over its repair and use have since taken place. A listed building application for its refurbishment as a single dwelling was made in 2016. A subsequent consent was granted in 2017 and has been completed as of May 2017. Work continues on the property. No further update as of May 2018.

Contact: Catherine Marlow



SITE NAME:	Church of St Rumon, Ruan Major, Grade-Ruan
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Medieval former parish church. Roof removed shortly after closure in 1963. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level. Discussions for the future of the ruin are ongoing.

LIST ENTRY NUMBER: 1141915 Contact: Chris Miners 0117 975 1308



© Cornwall Council

SITE NAME:	Cusgarne Manor farmhouse and mounting block to rear, Higher Cusgarne, Gwennap
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1140913

Early C17 manor farmhouse, possibly with earlier origins, remodelled in early C18 and preserving important windows from that date. The building had been in decline for a considerable time before being sold at auction in late 2015 in a very dilapidated condition. Discussions have taken place with regards the refurbishment and repair proposals, with particular focus on the traditional scantle slate roof and early sash windows, both being particularly vulnerable. Repairs to the roof and windows were underway in 2017. Ongoing discussions with owners and agents 2018 to verify extent of repairs.

Contact: Catherine Marlow



© Historic England

SITE NAME:	Chapel at Hall, Lanteglos
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1004361

Site consists of walls and well-preserved bell turret of a C14 manorial chapel. Re-use as a farm building in the C19 caused modifications to the structure which still retained its original oak wagon roof until the 1960s. Conservation in the 1990s helped to stabilise the structure but now water seeping into the rear wall has built up causing it to become unstable. Scaffolding funded by Historic England in 2015 was urgently needed to save the wall from falling and remedial works were carried out in 2017 to sections of wall. Further long term measures are required to protect the ruin from decay.

Contact: Chris Miners 0117 975 1308



© Cornwall Council

SITE NAME:	13, High Street, Launceston
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1206510

Jettied and timber-framed corner house, prominent on town's market square. Roof structure and upper level party wall in poor condition. Some of the structural work undertaken but condition of building remains serious. A recent application for replacement of an C18 window has been modified by subsequent negotiations to a repair of the existing window. However, there is no sign of comprehensive repairs being undertaken and recent inspection revealed the rear of the building to be in a deteriorating state with plastic sheeting protecting the walls.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

Market Street, Street, or other Designation of the last of the las
The second secon
at a later management to the
The state of the s
AND REAL PROPERTY AND ADDRESS OF THE PARTY O
MAN THE RESERVE TO THE PARTY OF
STATE OF THE PARTY
©Cornwall Council/Barry Gamble
Contiwali Council/Barry Gamble


© Cornwall Council

SITE NAME:	Treffry Viaduct, Luxulyan / Lanlivery
DESIGNATION:	Scheduled Monument, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1007279

Combined viaduct and aqueduct. Granite built ten-arched bridge with a span approximately 200 metres, standing up to 27 metres above the valley floor. Water had been gushing from the leat within the structure, so water flow over the viaduct has been stopped. Leaks became evident at abutments and locations within the main spans of the structure. A solution to the leaking channel has now been agreed. The Cornwall Heritage Trust is working with Historic England to develop an investigation project to finalise the solution to the high level leakage problems of the leats within the viaduct.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Maker Heights Barracks Block, Maker-with-Rame
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Charity (heritage)

1375582

Built 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. The twostorey block was altered in the mid C19 when the formerly tile-hung first floor was rebuilt in brick. It is the most complete small garrison barracks from this significant period. Partially repaired and in use as a community art centre. A phased scheme of window repairs is now being undertaken with Historic England grant aid.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Maker Heights Guard House, boundary wall and attached ancillary buildings, Maker-with- Rame
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

Built in 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of the other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Caponier. Now in seperate private ownership from the Barrack Block that forms the raison d'etre for this group of buildings.

© Vickery Holman Ltd

LIST ENTRY NUMBER:	1329099
SITE NAME:	Boundary wall to Lanherne Carmelite Convent, Mawgan-in- Pydar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A

C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost one metre thick standing up to four metres in places. Neglected, heavily overgrown with ivy and partially collapsed in places. Historic England continues to work with agent to encourage urgent remedial repairs. Condition survey needed to understand and monitor decay and to prioritise repairs.

PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1137593	•

Contact: Annie Evans 0117 975 1308

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Remains of Carclew House, Mylor
DESIGNATION:	Listed Building grade II*, RPG grade II, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1160291

The remains of Carclew House are the formal centre of a Registered park and garden also at risk. Started in 1720 by Samuel Kemp, this palladian style house was one of Cornwall's finer C18 country houses but was partly burned down in 1934. It is now a ruin, overgrown and neglected. Vegetation management is now ongoing with a program of repairs in development.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME: Dry sand and green sand shop, Perran Foundry, Perran Wharf,

Listed Building grade II\*, CA, DESIGNATION: WHS

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY CATEGORY:

F (F) OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1141603

Early to mid C19 mould and casting buildings. This is the main furnace building, an impressive and intact structure. Urgent repairs carried out early 2005. Listed Building Consent and Planning Permission for repair and conversion granted 2008. The buildings have been reroofed but the consented scheme for reuse has not yet been implemented as of May 2018.

Contact: Catherine Marlow



© Historic England

SITE NAME: Engineers' Shop, Perran Foundry, Perran Wharf, Mylor Listed Building grade II\*, CA, DESIGNATION: WHS CONDITION: Very bad OCCUPANCY: N/A

PRIORITY CATEGORY: D (D) OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1141643

Engineers' shop, boring mill and pattern shop c early-mid C18. Listed Building Consent and Planning Permission for repair and conversion of whole Perran Foundry site granted 2008 and now being implemented in a phased manner. Works as yet have not commenced on site to repair the building as of May 2018 - negotiations are ongoing with agent.

Contact: Catherine Marlow



© Historic England

SITE NAME: Threshing barn on north side of yard at Trebartha Barton. North Hill DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1250152

Mid C19 threshing barn forming one side of the farmyard to Trebartha Barton Farm. Two-storey 'E' plan with projecting midstryes infilled with first floor lean-to, forming impressive elevation to the yard. Rubble walls with granite dressings. Rag slate covered king post trussed roofs with slate hung infill walls. Slates are slipped or missing causing structural decay. There is harmful vegetation growth. First floor boarding is decayed and unsafe.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME: Trenearne, Padstow DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C(C)OWNER TYPE: Private LIST ENTRY NUMBER: 1211508

House, now farmhouse, circa early C17, possibly remodelled in 1660 (datestone) for 'PW'. The house only survives in part and was probably of overall 'H' shaped plan. It has been a tenanted farm for a number of years but a lack of maintenance had left all the buildings in a poor state of repair. The estate which owns Trenearne has been granted listed building consent to refurbish the house including much needed repairs, as well as the conversion of farm buildings.

Contact: Catherine Marlow



@ Penwith District Council

SITE NAME: Trinity Methodist Chapel, Chywoone Hill, Newlyn, Penzance DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C(C)OWNER TYPE: Religious organisation

1866. One of the most complete early C19 chapels in Cornwall. No longer used for religious worship. It is planned to re-submit a Heritage Lottery Fund bid for multipurpose community use, However nothing has yet happened and the building remains empty.

Former Nonconformist Wesleyan chapel c1834, enlarged

LIST ENTRY NUMBER: 1386515 Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

91		Control of the Contro

© Cornwall Council

SITE NAME:	Tolgus Calciner, New Portreatl
	Road, Redruth

Scheduled Monument, LB grade DESIGNATION: II, WHS

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1021240 Remains of a calciner used in the production of arsenic. It has been vacant for many years and is vulnerable with a damaged main roof and a collapsed adjoining tin-roofed extension. The main hipped slate roof of the building has been damaged through vandalism and there is an urgent need for weather proofing.

Contact: Ann Preston-Jones 07917 642388



© Cornwall Council

SITE NAME: Sara's Foundry, Tolgus Place, Redruth DESIGNATION: Listed Building grade II\*, WHS CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE:

Private

LIST ENTRY NUMBER: 1142573

C19 and C20 iron foundry and engineering works, containing associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration have continued.

Large town centre Market House built in 1844. It is formed of a town hall facing the church with an imposing street frontage and with a large glazed market area behind. Leaks and other rainwater system faults to the town hall and especially to the glazed market area are getting steadily worse. Occupancy rates in both areas have fallen as a result. Major repairs to all parts of the building are now needed before the building becomes beyond repair.

Former Wesleyan chapel (1827) and attached schoolroom (mid C19), now closed for worship. Listed Building Consent was granted for conversion of the building including two new units in 2013. New units were built but work to chapel and school rooms did not commence. The school room has continued to deterioration. A revised scheme to address the condition of the building was submitted in 2017 and approved in May 2018. Work began to the main body of the chapel in June 2018 with works to the school room expected to commence soon afterwards.

Locomotive turntable associated with adjacent roundhouse is deteriorating through lack of maintenance having been taken out of service in 2002. The roundhouse building is in light industrial use. A community interest group has been formed to develop a project to restore the site and bring it into more sympathetic uses. A Coastal Communities Fund grant was awarded in 2016 to develop the project.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Market House, Market Street, St. Austell
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (non-heritage)

1289697

Contact: Chris Miners 0117 975 1308



© Cornwall Council

SITE NAME:	Charlestown Methodist Church, Charlestown Road, St. Austell Bay
DESIGNATION:	Listed Building grade II*, CA, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Private

1144292

LIST ENTRY NUMBER:

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Engine Sheds, Stack and Turntable, St Blazey Road, St. Blaise
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1289905

Contact: Simon Hickman 0117 975 0717

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

,	•
SITE NAME:	Hockings House Bible Christian Chapel, St. Cleer
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1311103

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Chapel dated 1846. Good interior with gallery and original fittings including leaders' pew. Separated from the small Sunday school and damaging partial conversion works preceded its sale in 2012. Lengthy negotiations are currently ongoing with the owner about the possible extent of conversion, although currently no further communication. The building has deteriorated in the interim with its roof falling into a very poor state, with consequential damage occurring to the interior. Listed Building Consent was granted in 2015 for roof repairs, completed in 2017.

Contact: Catherine Marlow

N.A.		
<b>国际</b>		

@ Cornwall Council

SITE NAME:	Flanking walls and gateway to the bridge over moat about 8 metres east of Old Rectory, Old Rectory Drive, St. Columb Major
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Mid C19, part of William White's layout for the Bishop's Palace which became a Rectory and latterly a hotel. Obscured and threatened by dense vegetation. White's wrought iron gate, referred to in the List description, is not at present hung and its whereabouts is unknown. Vegetation clearance has taken place to allow for conservation of the moat.

Contact: Chris Miners 0117 975 1308



© Cornwall Council

SITE NAME:	Old Bishop's Palace, Old Rectory Drive, St. Columb Major
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1144096

1144097

1851 by William White. Picturesque Gothic Revival country gentleman's rectory, a classic of the type. In very poor state of repair caused by lack of maintenance, vandalism, vegetation, inappropriate finishes and unlived-in state. Water ingress has resulted in dry rot and damage to historic fabric. Statutory action by Local Planning Authority on hold. Vegetation clearance has taken place and is being maintained.

Contact: Chris Miners 0117 975 1308



© Cornwall Council

	stable adjacent to north, Port Eliot Estate, St. Germans
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Calf House at Lithiack and

Late C18/early C19 estate agricultural building. Attributed to Soane for the Port Eliot Estate. In low key use but condition remains very poor. Currently tenanted by a roofing company who are undertaking localised repairs. Condition improving.

Private LIST ENTRY NUMBER: 1140518

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Little Trethewey Methodist Chapel, Little Trethewey, St. Levan
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1311918

stuccoed Italianate front. Modest and complete interior with closed box pews. The chapel is in a bad condition with holes in the roof. The downpipes are blocked and external render is failing. Front gable is unstable and resulted in damage to the interior. Chapel closed April 2013. The condition continues to deteriorate. Historic England grantaided repairs in 2015 that covered the roof with a temporary sheet covering. The chapel was then put on the market and there has been no change since.

Built as Wesleyan Chapel in 1868. Small chapel with

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

建设///	WX4 -
To the second	23
一种人	
	1

© Historic England

,	<i>'</i>
SITE NAME:	Gunpowder works at Kennall Vale, Stithians / St. Gluvias
DESIGNATION:	Scheduled Monument, 9 LBs, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (non-heritage)

1020143

LIST ENTRY NUMBER:

This large scheduled area is centred on a steep sided, wooded valley, which contains remains of ruined buildings, mills, leats and bridges associated with a C19 gunpowder works. After years of abandonment, the many ruined structures on the site are at risk from tree and vegetation growth, water and footpath erosion and collapse. Recently, the most 'at risk' structures and leats were consolidated through a Natural England Stewardship scheme but there remain many outstanding management needs.

Contact: Ann Preston-Jones 07917 642388

ALTO	

© Historic England

SITE NAME:	Holmbush Mine: Windsor Lane rotative engine house with adjacent boiler house, loadings and platform, Stokeclimsland
DESIGNATION:	Scheduled Monument, LB grade II, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Crown
LIST ENTRY NUMBER:	1020327

This is a substantial mine engine house in deteriorating condition. The building is densely covered in ivy and surrounded by trees. The roof is mostly collapsed but still retains a few slates and roof timbers which are vulnerable to further damage. Timber fittings are deteriorated and rotten. Arched window openings have slipped bricks.



LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

© Historic England

SITE NAME:	Part of the china clay works known as Wheal Martyn, Treverbyn
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company

1003265

Site includes well preserved remains of china clay processing works displayed as part of a museum. The complex includes a range of features, including drying sheds, water wheels, settling tanks, machinery. It is maintained to a basic level with repairs undertaken as needed but there has been little capital investment in the site for a long time. However a Conservation Management Plan and structural survey recently prepared for the site have identified a number of significant weaknesses in the structures and this has led to an application to the HLF to repair and restore one of the big driers.

Contact: Ann Preston-Jones 07917 642388

Cornwall Council. The repairs are ongoing.

Former Wesleyan Methodist chapel, built 1866. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and obtained Listed Building Consent for conversion to residential use from

Contact: Ann Preston-Jones 07917 642388



© Historic England

SITE NAME:	Wesleyan Chapel, Porkellis, Wendron
DESIGNATION:	Listed Building grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Other not for profit group

1162569

Contact: Chris Miners 0117 975 1308

SITE NAME:	Church of St Protus and St Hyacinth, Blisland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1142367

Large parish church on the south of the village green, high on the edge of Bodmin Moor. Three aisles, C15 formed from C12 cruciform plan and with projecting south transept and north tower. Rubble stone walling for the early work and granite ashlar for the later. Restored by FC Eden 1896. Graduated Cornish slate roofs. Internal damp problems persist although rainwater goods have been repaired.



### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

Contact: Chris Miners 0117 975 1308

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of St Breaca, Churchtown, Breage
DESIGNATION:	Listed Place of Worship grade I, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1158264

Large rural parish church. Three parallel aisles with a three-stage west tower, projecting south porch, and north and south chapels. Rebuilt c I 466 mostly in granite ashlar. Slate roofs. Crenellated tower parapets with large corner pinnacles corbelled out. Tower has C I 9 roof with unlined parapet gutters draining to gargoyle shoots. Steeplejack survey shows two of the pinnacles are in urgent need of stabilisation. A Heritage Lottery Fund Grant application for the repair has been developed.

Contact: Chris Miners 0117 975 1308

-1			u.fo
	<u></u>		
	T	5	
		多	

Church of St Julitta, Lanteglos, Camelford

DESIGNATION: Listed Place of Worship grade I
CONDITION: Very bad

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1 | 142729

Large rural parish church, historically serving Camelford two miles to the east. Norman origins with rubble stone nave, chancel and north transept. Slate walled west tower added in C14 and the granite ashlar south aisle and porch added C15. Restored by JP St Aubyn. Cornish rag slate roofs. There is excessive vegetation growth in the damp walls on the north side. The slates have slipped and fractured. The gutters are under-sized, leaking and part fallen and there are symptoms of valley gutter leaks. A Heritage Lottery Fund Grant has been successfully applied for and been developed.

Contact: Chris Miners 0117 975 1308



SITE NAME:	Church of St Crewen, Crowan
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1160230

Large rural parish church in the centre of a small village. Cornish three-aisle church with a tall west tower. C14 and C15 restored 1872, with a C20 south organ chamber. All granite ashlar and Cornish slate roofs. The rainwater system has had some repair. A leaking valley gutter has caused interior damage.

Contact: Chris Miners 0117 975 1308



SITE NAME:	Church of St Cuby, Cuby
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291868

Small parish church. The tower is C14, of slate. The rest of the church is of rubble with granite dressings and has medieval origins but mostly displays the 1828 rebuilding with the 1899 St Aubyn restoration. Cornish slate roofs. The church is in fair condition overall but the tower has major problems with its drainage resulting in a wet north wall with harmful excessive vegetation growth.

Contact: Chris Miners 0117 975 1308

© His	to	ric I	Ξηį	glar	nd

LIST ENTRY NU
SITE NAME:
DESIGNATION

LIST ENTRY NUMBER:

SITE NAME:	Church of St Michael, Penwerris, Falmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

N 4 - 1

A large suburban parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grout and has remained substantially unaltered since. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship was offered for roof repairs and this was completed in 2012. However, work is still needed to the timber windows which are progressively decaying and the building has been subject to heritage crime.

1269974 Contact: Chris Miners 0117 975 1308

#### © Historic England

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Grade, Grade- Ruan
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1141938

Small church in an isolated site. Plan of tower, nave and east chancel. C14 origins. The roof needs repair and the tower has excessive damp and vegetation growth.

Contact: Chris Miners 0117 975 1308

Contact: Chris Miners 0117 975 1308

© Historic England



SITE NAME:	Church of St Rumon, Ruan Minor, Grade-Ruan
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1141916

Small church at the edge of a small village. Plan of west tower, nave with north aisle and higher east chancel. Granite rubble walls and slate roofs. Rainwater system faults are causing serious damp ingress problems within the church.

Historic England



SITE NAME:	Church of St Hydroc, Lanhydrock Park, Lanhydrock
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1158013

Small parish church sited in Lanhydrock Park estate. Granite walled with a slate roof and a simple three-aisle plan with a west tower and south porch. The roofs need essential repairs.

© Historic England



SITE NAME:	Church of St Nivet, Lanivet
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1158241

Large Anglican parish church in the centre of a large village. Classic Cornish pattern plan of three aisles with tall west tower. Granite and slate roofed mostly C15. The rainwater system is under-sized, rusted and part displaced. High level stonework needs repair and some roofs need reslating.

Contact: Chris Miners 0117 975 1308

Contact: Chris Miners 0117 975 1308

© Historic England



0	Historic	England

SITE NAME:	Church of St Stephen, St Stephen's Hill, Launceston
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1297830

Large urban parish church and the mother church for Launceston. Norman core with many additions finishing with the C16 tower. Restored 1883. Granite ashlar tower and outer walls to the west and south, the rest slatestone rubble with granite or greenstone dressings. The roof leaks and needs extensive renewal and repair.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

egory is Lerwise, L R

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument

M Scheduled Monumen: JA Unitary Authority VHS World Heritage Site



© Historic England

TE NAME:	Church of the English Martyrs
	and attached walls and steps, St
	Stephen's Hill, Launceston

Listed Place of Worship grade DESIGNATION: II\*, CA

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1297829

Small Roman Catholic parish church designed by Arthur Langdon in a blend of Byzantine and Romanesque styles. It was built in 1911 and constructed of dressed stones including Slate stone and Polyphant stone, to give a polychrome effect. The Polyphant stone masonry is now decaying badly. The roofs now need urgent repair as they are leaking.

Contact: Chris Miners 0117 975 1308



SITE NAME:	Church of St Martin, Lewannick
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1277508

Small parish church with tall tower. Plan of three parallel aisles with opposing north and south gabled porches and a west tower. Mostly granite ashlar with slate roofs. Extensively rebuilt late C19. The tower has serious faults at high level on the north side. The bell opening and the parapet above have serious structural faults. A crack on the projecting stair turret appears to be active.

Contact: Chris Miners 0117 975 1308



SITE NAME: Church of St Torney, North Hill DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1249982

Large parish church on the eastern edge of Bodmin Moor. There are structural problems in the tower where the floors are unsafe for use. The rainwater goods are rusted and leaking. There are major damp problems in the east end and structural problems in the tower.

Contact: Chris Miners 0117 975 1308

© Historic England



SITE NAME:	Church of St Denis, North Tamerton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1142437

A parish church set in a hillside churchyard. Plan of twin aisles with south porch, north vestry and west tower. Early C15 with C19 north vestry added in 1875 restoration. Rubble stone with granite dressings, complete ashlar tower and porch. Cornish slate roofs, some pitches rag slate. The rainwater goods are in poor condition and the slate roofs have slipped with fractured slates needing replacement.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary, Sheviock
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1140579

Large parish church in the centre of a small village. Twin aisle plan with a transept and a slender west tower. This tower has a thin spire which has severe wet ingress problems through open joints and eroded stonework. This damp has caused decay in the timber floors of the tower below. There is also fallen plaster from the nave ceiling.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



(C)	Historic	Fngland

SITE NAME:	Church of St Mary, St Blazey Gate, St. Blaise
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212089

Rural parish church built in 1844 by GE Street in the early Gothic style. Local stone rubble with Pentewan stone dressings. Plan of nave/chancel and a south aisle with a projecting tower and spire. The tower and spire have structural defects that date back to poor initial design with the spire shedding stonework. A Heritage Lottery Fund Grant for Places of Worship has been awarded for which work is soon to start.

Contact: Chris Miners 0117 975 1308

SITE NAME:	St Buryan Church, St. Buryan
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1327526

A large three-aisled church with a tall tower that is a famous maritime landmark. The valley gutters were leaking, causing active decay to the wall heads above the internal arcades. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship was given to renew the valley gutters and repair the inner slate roof slopes, and that repair work was undertaken in 2012. The tower roof remains in poor condition.

Contact: Chris Miners 0117 975 1308



© Historic England

© Historic England

SITE NAME:	Methodist Chuch (former Wesleyan Chapel), Chapel Road, St. Just
DESIGNATION:	Listed Place of Worship grade II*, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)

Large and prominent chapel at the edge of the small town of St Just. Granite walled with slate roof. Generally plain with large multi-paned arch headed windows but with a grand portico on the street front. Complete galleried interior. Serious rain ingress is affecting the interior especially around the organ chamber at the back end, together with falls of gutters. Some repairs to this area have now taken place.

LIST ENTRY NUMBER: 1143291 Parish Church of St lust SITE NAME:

Religious organisation

Contact: Chris Miners 0117 975 1308



© Historic England

311211112	Church Street, St. Just
DESIGNATION:	Listed Place of Worship grade II, CA, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1159637

Large parish church in the centre of the most westerly town in England. Classic Cornish pattern church of three aisles and a tall west tower. C13 cruciform church remodelled in the early CI5 creating the outer aisles and tower. C19 restoration created the current roofs. All of granite ashlar with Cornish slate roofs. The slate roofs are failing and have caused the fall of ceiling plaster. Rainwater goods are rusted and failing. A Heritage Lottery Fund Grant for Places of Worship has been awarded and the project is in development.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Pynnochus, St. Pinnock
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1140308

Small parish church. Norman cruciform origins with C15 north aisle and nave rebuilds, the tower of C14, C16 south porch. Coursed rubble with granite dressings. Cornish slated roofs with some slates slipped. Damp tower with much vegetation growth and problem downpipe on the north side. The church faces formal closure for worship.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG

Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



(0)	Historic	Fng	land

© Historic England

SITE NAME:	Church of St Stephen, St. Stephen-in-Brannel
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1137033

Large parish church. Classic Cornish plan of three parallel ranges with a west tower and south porch. C12 origins and developed in the C15 and C19 restorations. Granite walls and sized Cornish slates, with ragslates on the outer pitches. The porch roof and the south outer pitch had sufficient slippage to need replacement. The south valley gutter arcade plate had dry rot from a former leak. The tower roof had stress cracking. A Heritage Lottery Fund Grant for Places of Worship was awarded, and repair work was completed in 2016. More faults on the north roof slopes still keep the church at risk.

Contact: Chris Miners 0117 975 1308



SITE NAME:	Church of St Gregory, Treneglos
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Fair
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1310214

Small parish church high on the North Cornish plateau. Two aisles and a high west tower are from the C15, heavily restored 1858. Tower rebuilt 1871. A Listed Places of Worship Roof Repair Grant was awarded in 2016 for roof and rainwater repairs. However the outer roof slopes and the timber floor of the tower still need urgent repair.

Contact: Chris Miners 0117 975 1308

Contact: Chris Miners 0117 975 1308



Church of St Werburgh, Warbstow

DESIGNATION: Listed Place of Worship grade II\*

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1161531

Small parish church. Nave and chancel of Norman origin and of rubblestone, coursed slate tower and granite ashlar north aisle added in C15 and north porch in 1601. Restored 1861. Cornish slate roofs which have slipped slates, especially the porch. Rainwater system needs overhaul and there is harmful vegetation growth.

© Historic England

	1
	DATA !
- N	

© Historic England

SITE NAME:	Church of St Gwendron, Wendron
DESIGNATION:	Listed Place of Worship grade I, WHS
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1328447

Small rural parish church. Plan of nave/chancel with south aisle and north transept with west tower. C13 origins and restored 1868. Granite walls with slate roofs. The tower roof together with the outer roof pitches and the valley gutters are in a poor condition. The rainwater system and the low level drainage also need renewal. A Heritage Lottery Fund Grant for Places of Worship has been awarded which is in development.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Parish Church of St Anne, Whitstone Head, Whitstone
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1142426

Large parish church with a C13 core with C15 upper tower and three-aisle plan. The porch and the chancel originate from the 1882 restoration. Mostly slatestone rubble with granite dressings. Cornish slate roofs. In fair condition overall but very bad damp in the tower due to a leaking downpipe on the north side. Unguttered pitches on the north and south eaves. Slates are starting to slip from the roof pitches.

Contact: Chris Miners 0117 975 1308

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Deserted medieval settlement and field system wit post-medieval farmhouse north west of Tresibbet	n incorporated pre Farm, Altarnun	nistoric settlement and field system
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric coaxial field system, incorporated and a medieval settlement on Fox Tor and Treburland Fa	adjacent hut circles, arm, Altarnun	stone setting, linear boundaries and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008245
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric irregular field system and hut circle set deserted settlement south east of Tresibbet Farm,		ent medieval regular field system and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Prehistoric stone alignment 1 kilometre SSE of Eas	tmoorgate, Altarnu	n
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012228
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Nine Stones stone circle 1.03 kilometres NNW of	Bowhayland Farm,	Altarnun / North Hill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008631
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Scraesdon Fort, Antony		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1004347 and 1140707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Hut circle group and enclosure north east of Carw	ven, Blisland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004659
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Peverells Cross, Blisland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006641
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Castle Pencaire hillfort, two rounds and a field syst	em, Tregonning Hi	II, Breage / Germoe
DESIGNATION:	Scheduled Monument, LB grade II, CA, WHS	LIST ENTRY NUMBER:	1007293
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows south east of Middle Tap	house, Broadoak	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004433
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of round barrows south of Penadlake, Broa	doak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004436
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrows west of West Taphouse, Broadoak	(	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004617
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows north west of Middle Taphous	se, Broadoak	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003077
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow 310 yards (280 metres) south of Ki	lmansag, Broadoak	/ St. Pinnock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004434
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Binhamy moat 500 yards (460 metres) west of Binh	namy Farm, Bude-Si	tratton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gunnislake Clitters copper, tin, arsenic and wolfrar	m mine, Calstock	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1017088
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Okeltor C19 arsenic, copper and tin mine, Calstoc	k	
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1019440
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prince of Wales Mine at Harrowbarrow, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021411
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Tamar Canal, Gunnislake, Calstock		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007302
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	The remains of the Chapel of St la and adjacent cel	l, Camborne	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1441204
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cardinham Castle, Cardinham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004443
	Generally satisfactory but with significant localised	TREND:	Stable
CONDITION:	problems		Stable
CONDITION: PRINCIPAL VULNERABILITY:		NEW ENTRY?:	Yes

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / CORNWALL (UA)		
SITE NAME:	Carn Brea Castle, Carn Brea		
DESIGNATION:	Scheduled Monument, 2 LBs, CA, WHS	LIST ENTRY NUMBER:	1006704
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Busy, Chacewater		
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Melangoose camp, Colan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Killibury Castle later prehistoric hillfort, Egloshay	rle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010439
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Jewish and Congregationalist cemeteries at Ponsl	narden, Falmouth / Pe	enryn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020815
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	An early Christian memorial stone 380 metres so	outh east of Worthy	ale Manor, Forrabury and Minster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018701
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Group of round barrows north of Hayle Kimbro	Pool, Grade-Ruan / I	Mullion
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003082
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

STEENAME: Grambla Roman camp, Gweek  CONDITION: Extensive significant problems  Extensive sign	HERITAGE AT RISK 2018 / SOL	JTH WEST / CORNWALL (UA)		
CONDITIONS Generally unsatisfactory with major localised problems PRINCIPLA VALIDEMBRUTT: Coastal erosion NEW ENTER: No OWNER TITE: Charity (heritage) CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Grambla Roman camp. Gweek  DESIGNATION: Scheduled Monument UST DYTRY NUMBER: 1003078  CONDITIONS Extensive significant problems RESIGNATION: CONDITIONS Extensive significant problems RESIGNATION: COMMINIONS COMMINIONS Extensive significant problems RESIGNATION: COMMINIONS COMMINIO	SITE NAME:	Cliff castle west of Gunwalloe Church, Gunwallo	oe .	
PROBLEMS  PROBLEMS  PROBLEMS  PROBLEMS  PROBLEMS  PROBLEMS  CONTACT:  Contracting (heritage)  CONTACT:  Ann Preston-Jones 07917 642381  Strick Mayer  Contraction  Scheduled Monument  Stock erosion - moderate  CONTACT:  CONTACT:  CONTACT:  CONTACT:  Ann Preston-Jones 07917 642381  CONTACT:  CONTA	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004265
CONTRACT: Ann Preston-Jones 07917 642381 STENAME: Grambla Roman camp, Gweek DESIGNATION: Scheduled Monument INTENTEY NUMBER: 1003078 CONDITION: Extensive significant problems TRENCE Declining STENAME: Stock erosion - moderate NEW PRINTY: No CONTRACT: Ann Preston-Jones 07917 642381 STENAME: Round barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004269 CONDITION: Generally unsatisfactory with major localised problems PRINCIPLY VULNEARBUTY: Anabe ploughing NEW PRINTY: Yes CONTRACT: Ann Preston-Jones 07917 642381 STENAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468 STENAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468 CONDITION: Generally unsatisfactory with major localised problems TRENCHAULUNITERABILITY: Anabe ploughing CONTRACT: Ann Preston-Jones 07917 642381 STENAME: Roseworthy Arsenic Works, 700 metres west of Contract: Ann Preston-Jones 07917 642381 STENAME: Roseworthy Arsenic Works, 700 metres west of Contract: Ann Preston-Jones 07917 642381 STENAME: Roseworthy Arsenic Works, 700 metres west of Contract: Ann Preston-Jones 07917 642381 STENAME: Roseworthy Arsenic Works, 700 metres west of Contract: Ann Preston-Jones 07917 642381 STENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696 DECINION: Extensive significant problems Trevarnon Round, Gwithian, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696 DECINION: Extensive significant problems TRENCE UST ENTRY NUMBER: 1006698 DECINION: Scheduled Monument UST ENTRY NUMBER: 1006698 DECINION: Extensive significant problems TRENCE UST ENTRY NUMBER: 1006688 DECINION: Scheduled Monument UST ENTRY NUMBER: 1006688 DECINION: Scheduled Monument UST ENTRY NUMBER: 1006688	CONDITION:		TREND:	Declining
STEINAME Grambla Roman camp, Gweek  CONDITION Extensive significant problems  Extensive significant problems  Extensive significant problems  Extensive significant problems  TRENDE.  Declining  REMINISTRAL YULNIFERABILITY:  Stock erosion - moderate  NEW PRITATE:  No  CONTRATTY:  COMMERCIAL COMMERCIAL COMPANY  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  ROUND darrow 20 yards (18 metres) north west of Tolvan Cross, Gweek  CESIGNATION:  Scheduled Monument  Generally unsatisfactory with major localised problems  REMINISTRAL YULNIFERABILITY:  Arable ploughing  RECTANGER Private  RECTANGER RECTANGULAR CAMPS on the Major localised problems  RECTANGER RECTANGULAR CAMPS on the Major localised problems  REMINISTRAL YULNIFERABILITY:  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  RECTANGULAR CAMPS on the Major localised problems  REMINISTRAL YULNIFERABILITY:  CONTRACT:  Ann Preston-Jones 07917 64238:  REMINISTRAL YULNIFERABILITY:  CONTRACT:  Ann Preston-Jones 07917 64238:  REMINISTRAL YULNIFERABILITY:  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  ROSEWORTHY Areaic Works, 700 metres west of Contract:  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  ROSEWORTHY Areaic Works, 700 metres west of Contract:  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  REMINISTRAL YULNIFERABILITY:  COLLEGE  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  IO06696  TRENDE DEclining  PRINCIPAL YULNIFERABILITY:  Private, multiple owners  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  IO06696  TRENDE DEClining  REMINISTRAL YULNIFERABILITY:  Private, multiple owners  CONTRACT:  Ann Preston-Jones 07917 64238:  STEINAME  CONTRACT:  Ann Preston-Jones 07917 6	PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1003078  EXTENSIVE SIGNATION: Extensive significant problems TRAD: Declining  PRENCIPAL VILLINEARILITY: Stock erosion - moderate  NEW ENTRY: No  COMMERTYPE: Commercial company  CONTACT: Ann Preston-Jones 07917 642381  STENAME: Round barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek  DESCRIATION: Scheduled Monument  LIST ENTRY NUMBER: 1004269  Generally unsatisfactory with major localised TRADD: Declining  PRINCIPAL VILLIERABILITY: Arable ploughing  NEW ENTRY: Yes  CONTACT: Ann Preston-Jones 07917 642381  STENAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  EDSCRIATION: Scheduled Monument  Generally unsatisfactory with major localised TRADD: Declining  PRINCIPAL VILLIERABILITY: No  CONDITION: Generally unsatisfactory with major localised TRADD: Declining  PRINCIPAL VILLIERABILITY: No  CONNETTIVE: No  CONNETTIVE: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  EDSCRIATION: Scheduled Monument  EST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised TRADD: Declining  PRINCIPAL VILLIERABILITY: No  CONNETTIVE: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  EDSCRIATION: Scheduled Monument  EST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised TRADD: Declining  PRINCIPAL VILLIERABILITY: No  CONNER LYPE: Private, multiple owners  CONNITION: Scheduled Monument  EST ENTRY NUMBER: 1006696  CONNITION: Extensive significant problems  PRIVATE, multiple owners  CONTACT: Ann Preston-Jones 07917 642381  STENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  EST ENTRY NUMBER: 1006698  CONNITION: Ann Preston-Jones 07917 642381  STENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  EST ENTRY NUMBER: 1006696  CONNITION: Ann Preston-Jones 07917 642381  STENAME: Caste Kayle (earthwork), Phillack, Hayle  EST ENTRY NUMBER: 1006688  EST ENTRY NUMBER: 1006688  EST ENTRY NUMBER: No	OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
Extensive significant problems TREND: Declining  RRINGPAL VULNEARBUTY: Stock erosion - moderate  RRINGPAL VULNEARBUTY: Stock erosion - moderate  RRINGPAL VULNEARBUTY: Stock erosion - moderate  ROUND barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1004269  Generally unsatisfactory with major localised problems  RRINGPAL VULNEARBUTY: Arable ploughing  RRINGPAL VULNEARBUTY: Arable ploughing  RRINGPAL VULNEARBUTY: Arable ploughing  RECTANDER RECTANDER RECTANDER 1004468  GENERATION: Scheduled Monument  BETENTRY NUMBER: 1004468  Generally unsatisfactory with major localised problems  RRINGPAL VULNEARBUTY: Arable ploughing  RRINGPAL VULNEARBUTY: No  DECINION: Generally unsatisfactory with major localised problems  RRINGPAL VULNEARBUTY: Arable ploughing  RRINGPAL VULNEARBUTY: No  DECINION: Generally unsatisfactory with major localised problems  RRINGPAL VULNEARBUTY: Arable ploughing  RRINGPAL VULNEARBUTY: No  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1021418  CONDITION: Scheduled Monument  BETENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  RRINGPAL VULNEARBUTY: No  DECINING Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  STENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1006696  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  STENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1006696  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  STENAME: Caste Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1006698  TREND: Declining  PRINCIPAL VULNEARBUTY: No  DECLINING  DECLINING  PRINCIPAL VULNEARBUTY: No  DECLINING  DECLINING  DESIGNATION: Scheduled Monument  BETENTRY NUMBER: 1006698  DECLINING  DECL	SITE NAME:	Grambla Roman camp, Gweek		
RENICIPAL VULNERABILITY:  Stock erosion - moderate  NEW ENTRY:  No OWNER TYPE:  Commercial company  CONTACT:  Ann Preston-Jones 07917 64238!  STEINAME  Round barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek  DERIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04269  Declining  PRINCIPLE VULNERABILITY:  Arable ploughing  REVENTER:  Private  Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  DERIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04468  Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  DERIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04468  Declining  RENED Decl	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003078
Commercial company Contract: Ann Preston-Jones 07917 64238/ STENAME Round barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004269  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPL VULNERABILITY: Arable ploughing NEW ENTRY: Yes  CONTACT: Ann Preston-Jones 07917 64238/  STET NAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLA VULNERABILITY: Arable ploughing NEW ENTRY: No  CONNER TYPE: Commercial company CONTACT: Ann Preston-Jones 07917 64238/  STET NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised TILIND: Declining  PRENCIPLA VULNERABILITY: Collapse NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238/  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696  EXTENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006696  EXTENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006696  EXTENAME: CASILE Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006688  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 100	CONDITION:	Extensive significant problems	TREND:	Declining
STENAME ROUND barrow 20 yards (18 metres) north west of Tolvan Cross, Gweek  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004269  Generally unsatisfactory with major localised problems  PRINCIPLY VILNERABILITY: Arable ploughing NEW ENTRY: Yes  CONTACT: Ann Preston-Jones 07917 642381  STENAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST INTRY NUMBER: 1004468  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLY VILNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 07917 642381  STENAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  STENAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLA VILNERABILITY: Ocllapse NEW ENTRY: No  OWNER TYPE: NO  OW	PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER 1004269 CONDITION Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: Yes CONTACT: Ann Preston-Jones 07917 642381 STE NAME REctangular camp south west of Trevarnon Round, Gwinear-Gwithian DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1004468 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No CONTACT: Ann Preston-Jones 07917 642381 STE NAME Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1021418 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Oliapse New ENTRYP: No CONTACT: Ann Preston-Jones 07917 642381 STE NAME ROSEWORTHY Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1021418 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Ocilapse NEW ENTRYP: No OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 642381 STE NAME Trevarnon Round, Gwithian, Gwinear-Gwithian DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1006696 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 642381 STE NAME: Castle Kayle (earthwork), Phillack, Hayle DEBIGNATION: Scheduled Monument UST ENTRY NUMBER 1006698 DESIGNATION: Scheduled Monument UST ENTRY NUM	OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: Yes  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: No  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Roseworthy Arable ploughing  RENORMAL VULNERABILITY: No  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  RENORMAL VULNERABILITY: Collapse  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  TREND: Declining  TREND: Declining  RENORMATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  TREND: Declining  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  TREND: Declining  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238!  STE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  DECLINING  DEC	SITE NAME:	Round barrow 20 yards (18 metres) north west	of Tolvan Cross, Gw	eek
PRINCIPAL WULNERABILITY: Arable ploughing NEW ENTRY: Yes OWNER TYPE Private CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL WULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL WULNERABILITY: Collapse NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  PRINCIPAL WULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  REND: Declining  PRINCIPAL WULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL WULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004269
DOWNER TYPE Private Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468 DESIGNATION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: A rable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 07917 642381  STE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Collapse NEW ENTRY: No DOWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 642381  STE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696 DESIGNATION: Scheduled Monument UST ENTRY: No DOWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 642381  STE NAME: Castle Kayle (earthwork), Phillack, Hayle DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  STE NAME: Castle Kayle (earthwork), Phillack, Hayle DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining REND: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining REND: DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  DESIGNATION: Scheduled Monument UST ENTRY: No	CONDITION:		TREND:	Declining
Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004468  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse NEW ENTRYP: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004468  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development  NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
Generally unsatisfactory with major localised problems  Generally unsatisfactory with major localised problems  New entry: No  CONTACT: Ann Preston-Jones 07917 64238:  ETENAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  Designation: Scheduled Monument List entry number: 1021418  CONDITION: Generally unsatisfactory with major localised problems  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  TREND: Declining  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  ETENAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument List entry number: 1006696  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  Deviner type: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  CONTACT: Ann Preston-Jones 07917 64238:  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONTACT: Ann Preston-Jones 07917 64238:  ETENAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  EXTENAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  EXTENAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  EXTEND: Declining  REND: Declining  PRINCIPAL VULNERABILITY: No	SITE NAME:	Rectangular camp south west of Trevarnon Rou	nd, Gwinear-Gwithiar	1
problems pro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004468
Commercial company  CONTACT: Ann Preston-Jones 07917 642386  STE NAME: Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse  NEW ENTRY?: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 642386  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 642386  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONTACT: Ann Preston-Jones 07917 642386  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development  NEW ENTRY?: No	CONDITION:		TREND:	Declining
Roseworthy Arsenic Works, 700 metres west of Cornhill Farm, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse NEW ENTRYP: No  OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021418  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse  Private, multiple owners  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERABILITY: Arable ploughing  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  TREND: Declining  PRINCIPAL VULNERABILITY: No  DOWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: Permitted development  NEW ENTRY?: No	OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Collapse  Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  OWNER TYPE: Private, multiple owners  CONTACT: Ann Preston-Jones 07917 64238:  CONTACT: Ann Preston-Jones 07917 64238:  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development  NEW ENTRYP: No	SITE NAME:	Roseworthy Arsenic Works, 700 metres west o	f Cornhill Farm, Gwir	near-Gwithian
problems  PRINCIPAL VULNERABILITY:  Collapse  Private, multiple owners  CONTACT:  Ann Preston-Jones 07917 64238:  EXTENAME:  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 006696  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  CONTACT:  Ann Preston-Jones 07917 64238:  SITE NAME:  Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 006688  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Declining  No  No  No  No  No  No  No  No  No  N	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021418
Private, multiple owners  CONTACT: Ann Preston-Jones 07917 642381  Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Anable ploughing  NEW ENTRY?: No  CONTACT: Ann Preston-Jones 07917 642381  Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  New ENTRY?: No	CONDITION:		TREND:	Declining
Trevarnon Round, Gwithian, Gwinear-Gwithian  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 642386  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006696  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  CONTACT: Ann Preston-Jones 07917 642383  SITE NAME: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY?: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
Extensive significant problems  TREND:  Declining  NEW ENTRY?:  No  OWNER TYPE:  Private, multiple owners  Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  No  LIST ENTRY NUMBER:  Declining  TREND:  Declining  No  No  No  No  No  No  No  No  No  N	SITE NAME:	Trevarnon Round, Gwithian, Gwinear-Gwithian		
PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  CONTACT:  Ann Preston-Jones 07917 64238:  SITE NAME:  Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOO6688  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Permitted development  NEW ENTRY:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006696
Private, multiple owners  Contact: Ann Preston-Jones 07917 642388  Site Name: Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Permitted development  New Entry: No	CONDITION:	Extensive significant problems	TREND:	Declining
Castle Kayle (earthwork), Phillack, Hayle  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006688  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY: No	OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY?: No	SITE NAME:	Castle Kayle (earthwork), Phillack, Hayle		
PRINCIPAL VULNERABILITY: Permitted development NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006688
	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 07917 64238	PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
	OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Late C18-C19 mill complex, ropeworks and associated Millpond Avenue, Foundry, Hayle	ated water manage	ment system immediately east of
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1402648
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Carvannel cliff castle, Illogan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004390
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	'Headon Barrow' near Headon Cross, Jacobstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow 650 metres east of Carrine, Kea		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019086
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round 200 metres north west of Penventinnie, Ker	nwyn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016063
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Castles, Kilkhampton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003079
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Five bowl barrows 480 metres and 510 metres nor	rth of Hendra Farm	, Ladock
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019021
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Pound and appears 720 metres W/SW of Tragger I	adock	
DESIGNATION:	Round and annexe 720 metres WSW of Tregear, I Scheduled Monument	LIST ENTRY NUMBER:	1020179
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Respryn Bridge, Lanhydrock / St. Winnow		
DESIGNATION:	Scheduled Monument, 2 LBs, RPG grade II*	LIST ENTRY NUMBER:	1006701
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Neolithic settlement and hut circle on Helman Tor	, Lanlivery	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007306
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Giants Hedge, Lerryn to Lanreath, Lanreath / St. V	еер	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006681
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Mabel Barrow, Lansallos		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earlier prehistoric hillfort, two cairns, medieval por transhumance huts on Stowe's Hill, Linkinhorne	und and adjacent pr	rehistoric field systems, hut circles and
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012352
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Early medieval transhumance hut 740 metres west	of Blackcoombe Fa	rm, Linkinhorne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Prehistoric funerary cist 1.275 kilometres north we	est of Wardbrook I	Farm, Linkinhorne	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1012043	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Round cairn with central cist on Bearah Common,	1.106 kilometres n	orth of Wardbrook Farm, Linkinhorn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010411	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Two adjacent transhumance huts on Caradon Hill,	450 metres north	of East Caradon Farm, Linkinhorne	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011900	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
ITE NAME:	Two cairns, centred 82 metres and 110 metres south west of Caradon Hill summit, Linkinhorne			
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011810	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	Yes	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Neolithic long cairn, prehistoric regular and irregul enclosure 625 metres west of Blackcoombe Farm,	ar aggregate field sy Linkinhorne / Nort	ystems, linear boundaries and medieva	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010221	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Medieval and post-medieval tin and copper mines v northern slopes of Caradon Hill, Linkinhorne / St. (		system on the middle and lower	
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020942	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Castle an Dinas, Ludgvan			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006725	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but F not yet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial slow decay; no solution agreed but F not yet implemented. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Round 450 yards (405 metres) north west of Low	er Chellew Farm, L	udgvan
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004262
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Innis Downs earthwork, Luxulyan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006684
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Ancient village and fields at Boswarva Carn, Madro	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Courtyard houses north east of Newmill, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004356
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circles with associated field system 400 yards	(360 metres) south	west of Little Higher Bosullow, Madr
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1004316
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round 300 yards (270 metres) north east of New	mill, Madron	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004627
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Settlement 450 yards (400 metres) north west of	Middle Carnaquidde	en, Madron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003100
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	St Madron Well 500 yards (460 metres) south east	of Boswarthen, M	adron
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004310
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Village settlement north of Bodrifty, Madron		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004481
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chun Downs prehistoric landscape complex, incoryards (180 metres) south west of Chun Farm, Mad		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007264
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Barrow 800 yards (730 metres) WNW of Boswen	s Farm, Madron / S	t. Just
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004286
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cawsand Fort, Maker-with-Rame		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1016102
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earthwork redoubts Nos. 1, 2 and 3, Maker-with-F	Rame	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004254
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Grenville Battery 550 yards (500 metres) SSW of N	Maker Farm, Maker	-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003114
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Incomplete Palmerstonian fort 650 yards (600 met	res) west of Forder	, Maker-with-Rame
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007299
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Mount Edgcumbe round barrow, Maker-with-Rame	2	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004496
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	No. 5 redoubt 450 yards (410 metres) north west	of Maker Farm, Ma	ker-with-Rame
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1004255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort at Blacketon Farm, Menheniot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007296
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Inswork Chapel, Millbrook		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1003095
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round barrow on Bin Down, Morval		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006651
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of four round barrows east of Bottaboroug	h, Morwenstow / K	ilkhampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Group of round barrows south west of Penhale, N	1ullion		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004444	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Trevelgue promontory camp and two barrows, N	ewquay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006712	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Battens Cross, one of three medieval wayside cross	sses 70 metres sout	h west of Trebartha Hall, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012045	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Hut circle settlement 975 metres north east of Trewortha Farm, North Hill			
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1009806	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Prehistoric co-axial and regular aggregate field syst on Bastreet Downs, south of Bowda Farm, North		ated and adjacent hut circle settlemen	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011558	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Round cairn 1,175 metres WSW of East Castick F	arm, North Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010412	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Stone hut circle 1,225 metres WSW of East Castion	ck Farm, North Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010414	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME: Three adjoining prehistoric linear boundaries on Bearah Tor, 687 metres south west of Node Farm, North Hill				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010220	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Three stone hut circles 1.06 kilometres north east	of Trewortha Farr	n, North Hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009807	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Two stone hut circles and adjacent prehistoric boo Hill	undary wall 575 me	tres west of West Berriow Farm, No	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Unenclosed hut circle settlement and adjacent prehistoric linear boundary 800 metres SSE of Trewortha Farm, North Hill			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008958	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Unenclosed hut circle settlement with incorporate Farm, North Hill	ed enclosure 1.5 kilo	ometres north west of Wardbrook	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008954	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Two adjacent prehistoric coaxial field systems inco and medieval fields on East Moor and Ridge, North		ield systems, stone hut circles, cairns	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008439	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
ITE NAME:	Three barrows 550 metres ENE of Cansford, Otte	erham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005463	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Roundago, hut circle and field system on Castallack	Carn, Paul	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004654
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bake Rings later prehistoric-Roman round with att	ached enclosure an	d outwork, Pelynt
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Group of three round barrows north of Hendra, P	elynt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004621
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hall Rings, Pelynt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006682
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Ten barrows south of Wilton Mill, Pelynt		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004465
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Glasney College, Penryn		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1007260
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Lescudjack Castle, Penzance		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003270
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	St Piran's Oratory and associated early medieval ce	emetery, Perranzab	uloe
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Tolgus arsenic works 80 metres south east of	East Tolgus House	, Redruth
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1021240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Botrea barrows, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004467
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Caer Bran, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006717
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Early Christian memorial stone and churchyard cro Sancreed	oss in Sancreed chu	rchyard, 10 metres south of the churc
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015615
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Enclosed hut circle settlement and field system, 50	0 metres north we	st of Jericho Farm, Sancreed
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1418283
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Field system on Boswens Common, Sancreed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007268
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

	JTH WEST / CORNWALL (UA)		
SITE NAME:	Hut cluster Chirgwidden Vean, Sancreed	LICT EN ITOMA " " ASE	100/715
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006715
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Boslow Cross 550 yards (500 metres) north west	of Boslow Farm, Sa	ncreed / St. Just
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1003110
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bolster Bank, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1016444
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Wheal Kitty C20 tin processing works, St. Agnes		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Promontory fort and Civil War battery, Little Den	nis Head, St. Antho	ony-in-Meneage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004431
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Black Head promontory fort, St. Austell Bay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004391
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Stone circle on Emblance Common, St. Breward		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004459
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Scheduled Monument Construct Control C	SITE NAME:	Boskenna Gate Cross, St. Buryan		
problems problems problems Other New INTEXT: Ves OWNER TYPE Local authority Contract: Local authority Local au	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010918
Local authority  CAMP 900 yards (820 metres) south east of St Buryan village, St. Buryan  Scheduled Monument  Scheduled Monument  Scheduled Monument  Extensive significant problems  PRENCIPAL VILLEMBRIDE  Arable ploughing  REVENTIVE  ROUND Arable ploughing  REVENTIVE  Reventions  Reventions  Reventions  Reventions  Reventions  Reventions  Reventions	CONDITION:		TREND:	Stable
Camp 900 yards (820 metres) south east of St Buryan village, St. Buryan DERIGNATION Scheduled Monument Extensive significant problems Prescribe William (1990) Arable ploughing New NUTTOR No DOWNER TITLE Private, multiple owners Round barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan DERIGNATION Scheduled Monument Extensive significant problems Round barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan DERIGNATION Scheduled Monument Extensive significant problems Scheduled Monument Scheduled Monument Extensive significant problems Scheduled Monument Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer DERIGNATION Scheduled Monument, CA LIST DITRYNLINGER Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer DERIGNATION Scheduled Monument, CA LIST DITRYNLINGER Embanked platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer DERIGNATION Scheduled Monument, CA, WHS LIST DITRYNLINGER Extensive seast of Trewalla Farm, St. Cleer DERIGNATION Scheduled Monument, CA, WHS LIST DITRYNLINGER Extensive seast of Trewalla Farm, St. Cleer DERIGNATION Scheduled Monument, CA, WHS LIST DITRYNLINGER Private DERIGNATION Scheduled Monument, CA, WHS LIST DITRYNLINGER Private DERIGNATION Scheduled Monument S	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes
Scheduled Monument LIST DITAY NUMBERS 1004483  CONDITION Extensive significant problems HEND Declining  Private CONDITION CONTACT: Ann Preston-Jones 07917 642388  SITE NAME Round barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan  DESIGNATION Scheduled Monument LIST ENIRT NUMBERS 1004338  CONDITION Generally unsatisfactory with major localised problems  Private CONTACT: Ann Preston-Jones 07917 642388  SITE NAME REMAINS CONTACT: No CONTACT: Ann Preston-Jones 07917 642388  SITE NAME REMAINS CONTACT: Ann Preston-Jones 07917 642388  SITE NAME Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBERS 1015976  CONDITION Private CONTACT: Daniel Bashford 07824 103102  PRENCIPAL VULNEAMBURY: No CONTACT: Daniel Bashford 07824 103102  SITE NAME Embanked platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBERS 1010323  CONDITION Private Contact universal mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBERS 1010323  CONDITION Private CONTACT: Daniel Bashford 07824 103102  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBERS 1010323  CONDITION Private Private CONTACT: Daniel Bashford 07824 103102  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBERS 1010323  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBERS 1010323  TREND DESIGNATION: Scheduled Monument LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument LIST ENTRY NUMBERS 1018630  CONDITION Private Private LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument CA LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBERS 1018630  DESIGNATION: Scheduled	OWNER TYPE:	Local authority	CONTACT:	Ann Preston-Jones 07917 642388
Extensive significant problems  Extensive significant problems  Extensive significant problems  Arable ploughing  New ENTEXT:  No Private, multiple owners  CONTACT:  Ann Preston-Jones 07917 642388  SITE NAME:  Round barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan  Scheduled Monument  Scheduled Monument  Scheduled Monument  CONTACT:  Private  CONTACT:  CONTACT:  Ann Preston-Jones 07917 642388  STERNALL DISTABLEM:  CONDITION  Private  Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESGNATION:  Scheduled Monument, CA  CONTACT:  CONTACT:  CONTACT:  CONTACT:  Ann Preston-Jones 07917 642388  STERNALL DISTABLEM:  Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESGNATION:  Scheduled Monument, CA  CONTACT:  Declining  Preston-Jones 07917 642388  TREND:  Declining  TREND:  Declining  Preston-Jones 07917 642388  TREND:  Declining  Preston-Jones 07917 642388  TREND:  Declining  TREND:  Declining  Preston-Jones 07917 642388  TREND:  Declining  TREND:  D	SITE NAME:	Camp 900 yards (820 metres) south east of St Bur	yan village, St. Bury	an
Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 0.7917 642388  SITE NAME: Round barrow 200 yards (180 metres) north of the Merry Maidens, Sc. Buryan  DESIGNATION: Scheduled Monument  Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DECIDING  Generally unsatisfactory with major localised TREND: Declining  PRINCIPLY WINFERBUTY: Scrub/tree growth NEW ENTRY: No  DOWNER TYPE: Ann Preston-Jones 0.7917 642388  SPIENAME: Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LET ENTRY NUMBER: 1015976  CONDITION: Generally satisfactory but with minor localised problems  PRINCIPLY WINFERBUTY: Scrub/tree growth NEW ENTRY: No  DOWNER TYPE: Private  CONTACT: Daniel Bashford 0.7824 103102  STENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS LET ENTRY NUMBER: 1010323  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPLY WINFERBUTY: Vandalism  PRINCIPLY WINFERBUTY: Vandalism  Private  CONTACT: Daniel Bashford 0.7824 103102  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs. 570 metres north west of Smallacoombe Tor. St. Cleer  DESIGNATION: Scheduled Monument  Scheduled Monument  DESIGNATION: Scheduled Monument  CONTACT: Daniel Bashford 0.7824 103102  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs. 570 metres north west of Smallacoombe Tor. St. Cleer  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  CONTACT: Daniel Bashford 0.7824 103102  STENAME: Prehistoric enclosure 325 metres west of Trewalls Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA  DESIGNATION: Schedule	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004483
OWNER TYPE Private, multiple owners CONTACT: Ann Preston-Jones 07917 642388  STENAME ROund barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan DESGNATION Scheduled Monument LIST ENTRY NUMBER 1004358  CONDITION Generally unsatisfactory with major localised problems  SERNICIPAL VILINERABILITY: Scrub/tree growth NEW BNITRY: NO DWINST TYPE: Private CONTACT: Ann Preston-Jones 07917 642388  STENAME Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer DESGNATION Scheduled Monument, CA LIST ENTRY NUMBER 1015976  CONDITION Generally satisfactory but with minor localised problems  STENAME: CONTACT: Daniel Bashford 07824 103102  STENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  CONDITION Scheduled Monument, CA, WHS LIST ENTRY NUMBER 1010323  CONDITION Generally satisfactory but with significant localised problems  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs. 570 metres north west of Smallacoombe Tor, St. Cleer  DESGNATION: Scheduled Monument  Scheduled Monument  Scheduled Monument  Generally satisfactory but with significant localised problems  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs. 570 metres north west of Smallacoombe Tor, St. Cleer  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs. 570 metres north west of Smallacoombe Tor, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESGNATION: Scheduled Monument  CONTACT: Daniel Bashford 07824 103102  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESGNATION: Scheduled Monument, CA  USTENTRY NUMBER: 1010434  Generally unsatisfactory with major localised problems  TREND: Declining  DECLINION D	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow 200 yards (180 metres) north of the Merry Maidens, St. Buryan  Scheduled Monument  Generally unsatisfactory with major localised problems  FRENCISH VULNERABILITY:  Scrub/tree growth  Private  Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  SCONDITION:  Generally satisfactory but with minor localised problems  FRENCISH VULNERABILITY:  Scrub/tree growth  Scheduled Monument, CA  LIST ENTRY NUMBER:  ID 15976  Generally satisfactory but with minor localised problems  FRENCISH VULNERABILITY:  Scrub/tree growth  NEW ENTRY:  No  Declining  FRENCISH VULNERABILITY:  Scrub/tree growth  NEW ENTRY:  No  CONTACT:  Daniel Bashford 07824 103102  SILE NAME:  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  CEGERAATION:  Scheduled Monument, CA, WHS  LIST ENTRY NUMBER:  ID 10323  TREND:  Declining  FRENCIPLA VULNERABILITY:  Vandalism  New ENTRY:  No  CONDITION:  FRENCIPLA VULNERABILITY:  Vandalism  New ENTRY:  Private  CONTACT:  Daniel Bashford 07824 103102  STE NAME:  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Smallacoombe Tor, St. Cleer  Designation  Scheduled Monument  CONDITION:  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation  Scheduled Monument, CA  LIST ENTRY NUMBER:  ID 10434  Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004358  CONDITION: Generally unsatisfactory with major localised problems  RINGIPAL VULNERABILITY: Scrub/tree growth  REWINDRAL TYPE: Private  CONTACT: Ann Preston-Jones 07917 642388  STEENAME: Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA  UST ENTRY NUMBER: 1015976  CONDITION: Generally satisfactory but with minor localised problems  RERINCIPAL VULNERABILITY: Scrub/tree growth  RERINCIPAL VULNERABILITY: One Daniel Bashford 07824 103102  STIENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Cleer  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Cleer  Cleer  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Cleer  Cleer  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Cleer  Cleer  Contact: Daniel Bashford 07824 103102  STIENAME: Private  CONTACT: Daniel Bashford 07824 103102  STIENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  SCHEDULING Statisfactory but with significant localised problems  FRINCIPAL VULNERABILITY: Plant growth NEW INTERY: No  OWNER TYPE:	OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
Generally unsatisfactory with major localised problems  RINGIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No  DOWNER TYPE: Private Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA USTENTRY NUMBER: 1015976  Generally satisfactory but with minor localised problems  RINGIDEL VULNERABILITY: Scrub/tree growth NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  STENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  CONDITION: Scheduled Monument, CA, WHS USTENTRY NUMBER: 1010323  CONDITION: Scheduled Monument, CA, WHS USTENTRY NUMBER: 1010323  CONDITION: Private CONTACT: Daniel Bashford 07824 103102  STENAME: Repeat platform cairn with significant localised problems  RINGIDEL VULNERABILITY: Vandalism NEW ENTRY: No  CONTITON: Private CONTACT: Daniel Bashford 07824 103102  STENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  SCHOOLITION: Scheduled Monument UST ENTRY NUMBER: 1018630  CONDITION: Mixed, multiple owners CONTACT: Daniel Bashford 07824 103102  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  STENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Clee	SITE NAME:	Round barrow 200 yards (180 metres) north of the	e Merry Maidens, S	t. Buryan
Problems  SCRUD/Tree growth  NEW ENTRYP:  No  DANNER TYPE:  Private  Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION:  Scheduled Monument, CA  Generally satisfactory but with minor localised problems  SCRUD/Tree growth  NEW ENTRY:  No  Declining  Private  CONTACT:  Daniel Bashford 07824 103102  STENAME:  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Contract:  Cleer  Contract:  Contract:  Daniel Bashford 07824 103102  SEBIGNATION:  Scheduled Monument, CA, WHS  Contract:  Contract:  Daniel Bashford 07824 103102  SEBIGNATION:  Scheduled Monument, CA, WHS  Contract:  Contract:  Declining  Private  Contract:  Declining  SEBIGNATION:  Scheduled Monument, CA, WHS  Contract:  Daniel Bashford 07824 103102  SEBIGNATION:  Scheduled Monument CA, WHS  Contract:  Daniel Bashford 07824 103102  SEBIGNATION:  Scheduled Monument CA, WHS  Scheduled Monum	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004358
Private Private Private CONTACT: Ann Preston-Jones 07917 642388  Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015976  CONDITION: Generally satisfactory but with minor localised problems  Private CONTACT: Daniel Bashford 07824 103102  EXEMPLIANCE: Cleer  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBER: 1010323  CONDITION: Generally satisfactory but with significant localised problems  Private CONTACT: Daniel Bashford 07824 103102  EXEMPLIANCE: Vandalism NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  EXEMPLIANCE: Control of the problems o	CONDITION:		TREND:	Declining
Embanked platform cairn with central mound 375 metres north west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA UST ENTRY NUMBER: 1015976  CONDITION: Generally satisfactory but with minor localised problems  Scrub/tree growth NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  SETENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS UST ENTRY NUMBER: 1010323  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  SETENAME: Private CONTACT: Daniel Bashford 07824 103102  SETENAME: Private CONTACT: Daniel Bashford 07824 103102  SETENAME: Prehistoric cist, cairns and cairmfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018630  TREND: Stable  PRINCIPAL VULNERABILITY: No  DOWNER TYPE: No  DOWNER TYPE: No  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1018630  TREND: Stable  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument NEW ENTRY: No  DESIGNATION: Scheduled Monument, CA  LET ENTRY NUMBER: 1010434  TREND: Declining  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: Declining  DESIGNATION: Scheduled Monument, CA  UST ENTRY NUMBER: 1010434  TREND: Declining  DESIGNATION: Scheduled Monument, CA  UST ENTRY NUMBER: 1010434  TREND: Declining  DEClining  PRINCIPAL VULNERABILITY: No  Declining	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1015976  CONDITION: Generally satisfactory but with minor localised problems  FRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No  OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  SITE NAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBER: 1010323  CONDITION: Generally satisfactory but with significant localised problems  FRINCIPAL VULNERABILITY: Vandalism NEW ENTRY: No  OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  SITE NAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  FRINCIPAL VULNERABILITY: No  OWNER TYPE: No  OWNER TYPE: No  Mixed, multiple owners CONTACT: Daniel Bashford 07824 103102  SITE NAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Prehistoric enclosure 325 metres west of Trewalls Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Prehistoric enclosure 325 metres west of Trewalls Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Prehistoric enclosure 325 metres west of Trewalls Farm, St. Cleer  DESIGNATI	OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
Generally satisfactory but with minor localised problems  SCNUDITION: Scrub/tree growth  New ENTRY: No  Daniel Bashford 07824 103102  STENAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Scheduled Monument, CA, WHS  CONDITION: Scheduled Monument, CA, WHS  CONDITION: Generally satisfactory but with significant localised problems  Private  CONTACT: Daniel Bashford 07824 103102  Declining  REND: Declining  Precisionation: Scheduled Monument, CA, WHS  CONTACT: Daniel Bashford 07824 103102  Declining  Private  Private  Private  Private  CONTACT: Daniel Bashford 07824 103102  Declining  Precisionation: Scheduled Monument  LIST ENTRY NUMBER: 1018630  CONTACT: Daniel Bashford 07824 103102  Declining  Precisionation: Scheduled Monument  LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  Prenticipal vulnerability: Plant growth  Mixed, multiple owners  CONTACT: Daniel Bashford 07824 103102  Devention: Scheduled Monument, CA  LIST ENTRY NUMBER: 1018630  CONTACT: Daniel Bashford 07824 103102  Devention: Scheduled Monument, CA  LIST ENTRY NUMBER: 1018630  CONTACT: Daniel Bashford 07824 103102  Devention: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Devention: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Declining  Declining	SITE NAME:	Embanked platform cairn with central mound 375	metres north west	of Trewalla Farm, St. Cleer
Problems  Scrub/tree growth  New ENTRY?:  No  Daniel Bashford 07824 103102  Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Sesignation:  Scheduled Monument, CA, WHS  LIST ENTRY NUMBER:  CONDITION:  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY:  Vandalism  New ENTRY?:  No  Daniel Bashford 07824 103102  TREND:  Declining  Private  CONTACT:  Daniel Bashford 07824 103102  TREND:  Declining  Private  Private  Private  Private  Private  Private  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Sesignation:  Scheduled Monument  LIST ENTRY NUMBER:  Downer Type:  Plant growth  NEW ENTRY:  No  Daniel Bashford 07824 103102  TREND:  Stable  Problems  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Daniel Bashford 07824 103102  TREND:  Daniel Bashford 07824 103102  TREND:  Daniel Bashford 07824 103102  TREND:  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Declining  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Declining	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015976
Private CONTACT: Daniel Bashford 07824 103102  Sette NAME: Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA, WHS LIST ENTRY NUMBER: 1010323  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Vandalism NEW ENTRY: No  CONTACT: Daniel Bashford 07824 103102  Sette NAME: Private CONTACT: Daniel Bashford 07824 103102  Sette NAME: Stephen Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No  CONTACT: Daniel Bashford 07824 103102  STEPHEN STEPHEN STEPHEN NO  CONTACT: Daniel Bashford 07824 103102  STEPHEN SCHEDER SCHEDULING NO NEW ENTRY: No  CONTACT: Daniel Bashford 07824 103102  STEPHEN NEW ENTRY: NO  CONTACT: Daniel Bashford 07824 103102  STEPHEN NEW ENTRY: NO  CONTACT: Daniel Bashford 07824 103102  STEPHEN NEW ENTRY: NO  DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	CONDITION:		TREND:	Declining
Kerbed platform cairn with kerbed central mound and outer bank 600 metres east of Trewalla Farm, St. Cleer  Scheduled Monument, CA, WHS  CONDITION:  Generally satisfactory but with significant localised problems  Private  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument  CONTACT:  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  DI 18630  CONDITION:  Generally satisfactory but with significant localised problems  Plant growth  NEW ENTRY:  No  DWNER TYPE:  Mixed, multiple owners  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  No  DWNER TYPE:  Mixed, multiple owners  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  1010434  CONDITION:  Generally unsatisfactory with major localised problems  Plant growth  NEW ENTRY:  No  Declining  Plant growth  NEW ENTRY:  No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Cleer  DESIGNATION: Scheduled Monument, CA, WHS  DESIGNATION: Scheduled Monument, CA, WHS  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Vandalism  NEW ENTRYY: No  DANIEL Bashford 07824 103102  DANIEL Bashford 07824 103102  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument, CA  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monumen	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
Generally satisfactory but with significant localised problems  NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Daniel Bashford 07824 103102  STEENAME: Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Designation: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: Daniel Bashford 07824 103102  STEENAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth New ENTRY?: No	SITE NAME:		and outer bank 600	) metres east of Trewalla Farm, St.
problems  Private  Private  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Designation:  Scheduled Monument  CONTACT:  Daniel Bashford 07824 103102  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Designation:  Scheduled Monument  LIST ENTRY NUMBER:  1018630  CONDITION:  Generally satisfactory but with significant localised problems  Prehistoric problems  Plant growth  New ENTRY:  No  OWNER TYPE:  Mixed, multiple owners  CONTACT:  Daniel Bashford 07824 103102  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  1010434  CONDITION:  Generally unsatisfactory with major localised problems  Prenicipal vulnerability:  Plant growth  New ENTRY:  No  Declining  Prenicipal vulnerability:  Plant growth  New ENTRY:  No	DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1010323
Private Private CONTACT: Daniel Bashford 07824 103102  Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  Designation: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  Plant growth NEW ENTRY?: No  Daniel Bashford 07824 103102  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  Plant growth New ENTRY: No	CONDITION:		TREND:	Declining
Prehistoric cist, cairns and cairnfield on north east Smallacoombe Downs, 570 metres north west of Smallacoombe Tor, St. Cleer  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  Plant growth NEW ENTRY!: No  DWNER TYPE: Mixed, multiple owners CONTACT: Daniel Bashford 07824 103102  STEE NAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
Smallacoombe Tor, St. Cleer  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018630  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners  ONTACT: Daniel Bashford 07824 103102  SITE NAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
DESIGNATION: Scheduled Monument  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  Designation: Scheduled Monument, CA  CONTACT: Daniel Bashford 07824 103102  Designation: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  New Entry: No  Declining  PRINCIPAL VULNERABILITY: Nounder: New Entry: No	SITE NAME:		Smallacoombe Dov	wns, 570 metres north west of
problems  PRINCIPAL VULNERABILITY: Plant growth  New Entry?: No  CONTACT: Daniel Bashford 07824 103102  SITE NAME: Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1010434  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  New Entry?: No	DESIGNATION:	•	LIST ENTRY NUMBER:	1018630
Mixed, multiple owners  CONTACT:  Daniel Bashford 07824 103102  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  DESIGNATION:  Scheduled Monument, CA  LIST ENTRY NUMBER:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  CONTACT:  Daniel Bashford 07824 103102  TREND:  Declining  New ENTRY?:  No	CONDITION:		TREND:	Stable
Mixed, multiple owners  CONTACT:  Daniel Bashford 07824 103102  Bite Name:  Prehistoric enclosure 325 metres west of Trewalla Farm, St. Cleer  Designation:  Scheduled Monument, CA  LIST ENTRY NUMBER:  1010434  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  New ENTRY?:  No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  LIST ENTRY NUMBER: 1010434  TREND: Declining  NEW ENTRY?: No	OWNER TYPE:	•	CONTACT:	Daniel Bashford 07824 103102
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  NEW ENTRY?: No	SITE NAME:	Prehistoric enclosure 325 metres west of Trewalla	Farm, St. Cleer	
problems problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY?: No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010434
-	CONDITION:		TREND:	Declining
-	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
	OWNER TYPE:	•	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** 

east of Sparret DESIGNATION: Scheduled Mor	ts Farm, St. Cleer	LIST ENTRY NUMBER:	nedieval field system 350 metres sout
CONDITION: Generally unsate problems			1013216
problems	tisfactory with major localised		
PRINCIPAL VULNERABILITY: Plant growth		TREND:	Declining
		NEW ENTRY?:	No
OWNER TYPE: Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME: Prehistoric irre Farm, St. Cleer		corporated stone h	ut circles 375 metres SSE of Sparretts
DESIGNATION: Scheduled Mor	nument, CA	LIST ENTRY NUMBER:	1008765
CONDITION: Generally satisf problems	actory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth		NEW ENTRY?:	No
OWNER TYPE: Private, multiple	e owners	CONTACT:	Daniel Bashford 07824 103102
Prehistoric irre of Siblyback Fa		stems with incorpor	rated stone hut circles 750 metres EN
DESIGNATION: Scheduled Mor	nument, part in CA	LIST ENTRY NUMBER:	1011315
CONDITION: Generally unsate problems	tisfactory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth		NEW ENTRY?:	No
OWNER TYPE: Mixed, multiple	e owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME: Prehistoric irre boulder 750 m	egular and regular aggregate field systems ESE of Siblyback Farm, St. Cle	stems, enclosure, steer	one hut circles, cairnfield and kerbed
DESIGNATION: Scheduled Mor	nument, CA	LIST ENTRY NUMBER:	1010060
CONDITION: Generally unsate problems	tisfactory with major localised	TREND:	Unknown
PRINCIPAL VULNERABILITY: Plant growth		NEW ENTRY?:	No
OWNER TYPE: Private		CONTACT:	Daniel Bashford 07824 103102
	ular aggregate field system with incometres WSW of Trewalla Farm, St.		ent stone hut circles and an adjacent
DESIGNATION: Scheduled Mor	nument, part in CA	LIST ENTRY NUMBER:	1009731
CONDITION: Generally satisf problems	actory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY: Plant growth		NEW ENTRY?:	No
OWNER TYPE: Private, multiple	e owners	CONTACT:	Daniel Bashford 07824 103102
Prehistoric to north eastern S	post-medieval field systems, bounda Siblyback Moor, St. Cleer	ries, settlements an	d railway at Smallacoombe Parks and
DESIGNATION: Scheduled Mor	nument	LIST ENTRY NUMBER:	1018631
CONDITION: Generally satisf problems	actory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY: Forestry		NEW ENTRY?:	No
OWNER TYPE: Mixed, multiple	eowners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

	JTH WEST / CORNWALL (UA)		
SITE NAME:	Round cairn 450 metres east of Sparretts Farm, St.		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009838
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 525 metres east of Trewalla Farm, St.	Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1012041
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 740 metres SSW of Caradon Hill sum	mit, St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011774
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn and shelters 812 metres SSW of Cara	don Hill summit, St	:. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn with peripheral berm 402 metres SSV	V of Caradon Hill s	ummit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011822
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	South Caradon C19 copper mine, St. Cleer		
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1020614
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Stone hut circle 750 metres ESE of Trewalla Farm,	St. Cleer	
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011909
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	The Tinners' Dyke 160 yards (150 metres) in lengt	h south of Henderg	grove Wood, St. Cleer
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Tor cairn with adjacent sub-rectangular hut 650 me	etres SSW of Carac	don Hill summit, St. Cleer
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1011793
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Trethevy Quoit, St. Cleer		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017579
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two adjacent stone hut circles 265 metres WNW	of Trewalla Farm,	St. Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009738
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two adjacent stone hut circles 290 metres west of	Trewalla Farm, St.	Cleer
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009703
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric to medieval settlements, field systems, railway on north east Smallacoombe Down, St. Cle		ns, with post-medieval boundary and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018629
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric round cairn on Caradon Hill, 310 metro	es west of Heather	House, St. Cleer / Linkinhorne
DESIGNATION:	Scheduled Monument, CA, WHS	LIST ENTRY NUMBER:	1020939
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	The Nine Maidens stone alignment, The Fiddler sta Columb Major / St. Issey	nding stone and tw	o Bronze Age round barrows, St.
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021223
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Bury camp, St. Dominick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004393
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Medieval wayside cross in the churchyard at St End	lellion, St. Endellion	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014011
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Warren's Barrow, St. Erme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016888
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Enclosures east of Gurlyn, St. Erth		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1007282
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Redcliff Castle, later prehistoric cliff castle 550 met	res south west of E	Bedruthan, St. Eval
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021006
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
	Promontory fort north of village St. Connus		
SITE NAME:	Promontory fort north of village, St. Gennys		
	Scheduled Monument	LIST ENTRY NUMBER:	1003097
SITE NAME:  DESIGNATION:  CONDITION:		LIST ENTRY NUMBER: TREND:	1003097 Declining
DESIGNATION:	Scheduled Monument  Generally unsatisfactory with major localised		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Gunpowder storage complex at Kennall Vale, St. G	Gluvias	
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1020441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Camp 500 yards (460 metres) west of Trenance, S	t. Issey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004235
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Cadson Bury hillfort, St. Ive		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hut circles, Higher Bussow, St. Ives		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006689
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Whitesand Bay (or Tregonhawke) battery, St. John		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004664
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Bartine Castle, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006716
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Chambered barrow 100 yards (90 metres) east of	Kerrow Farm, St. J	ust
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1004637
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Geevor Mine, St. Just		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1021361
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Russell 0117 975 0671
ITE NAME:	Nanjulian Farm courtyard house, St. Just		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004498
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Ann Preston-Jones 07917 642388
TE NAME:	Numphra Common tin streamworking complex, St	t. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Standing stone 200 yards (180 metres) west of Chy	ycarne, St. Just	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003116
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Wayside cross in St Just vicarage garden, St. Just		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1016753
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Chapel enclosure 150 yards (140 metres) south of	Trelease Farm, St.	Keverne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004334
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
TE NAME:	Settlement sites 500 yards (460 metres) SSE of Tre	ebarveth, St. Keverr	ne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004319
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
		NIEW ENITEY).	NI-
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth  Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SELEVANCE Scheduled Monument UST ENTRY NUMBER 1007285 CONDITION: Scheduled Monument UST ENTRY NUMBER 1007285 CONDITION: Generally unsatisfactory with major localised problems Private Constitution: Constitution Private Constitution Private Constitution Private Constitution Private Constitution Private UST ENTRY NUMBER 1006733  STEENANTE: Treryn Dinas fort, St. Levan DESCRAFTOR: Scheduled Monument UST ENTRY NUMBER 1006733  SCHOOLTION: Generally unsatisfactory with major localised problems NINCOMINATION: Scheduled Monument UST ENTRY NUMBER 1006733  STEENANTE: Scheduled Monument UST ENTRY NUMBER 1006733  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick UST ENTRY NUMBER 1018019  STEENANTE: UST ENTRY NUMBER 1018019  STEENANTE: Constitution of UST ENTRY NUMBER 1018019  STEENANTE: Constitution of UST ENTRY NUMBER 1018019  STEENANTE: UST	
CONDITION. Generally unsatisfactory with major localised problems PRINCIPLA VALADRAMBUTY: COSTAIL CONTACT: Private CONTACT: Ann Preston-Jones 0791  SITE NAME: Treryn Dinas fort, St. Levan DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPLA VALADRAMBUTY: CONDITION: CONDITION: CONDITION: CONDITION: CONTACT: CONTACT: CONDITION: CONTACT: CONT	
Problems Problems Problems Private Constance: Con	
OWNER TYPE.  Private  Treryn Dinas fort, St. Levan  DESIGNATION  Scheduled Monument  CONDITION  Generally unsatisfactory with major localised problems  SCRUD/Tree growth  New BRITEN  CONDITION  CONTROL (ULINEABBLITY)  CONDITION  CONTROL  Generally satisfactory with major localised problems  STENAME  Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick  DESIGNATION:  CONDITION  Generally satisfactory but with significant localised problems  SENICIPAL VULNEABBLITY:  Other  OWNER TYPE:  Colf castle at Winecove Point, St. Merryn  DESIGNATION:  CONDITION  Generally satisfactory but with significant localised problems  Scheduled Monument  CONDITION  Generally satisfactory but with significant localised problems  RENCIPAL VULNEABBLITY:  CONDITION  Generally satisfactory but with significant localised problems  RENCIPAL VULNEABBLITY:  CONDITION  Generally satisfactory but with significant localised problems  RENCIPAL VULNEABBLITY:  CONDITION  Generally satisfactory with major localised problems  RENCIPAL VULNEABBLITY:  COMMERTITY:  Scheduled Monument, LB grade II  CONDITION:  Generally unsatisfactory with major localised problems  RENCIPAL VULNEABBLITY:  No  CONTROL  CONTROL  Scheduled Monument, LB grade II  CONTROL  CONTROL  CONTROL  Scheduled Monument, LB grade II  CONTROL  CONTROL  CONTROL  CONTROL  Scheduled Monument  CONTROL  CONTROL  CONTROL  Ann Preston-Jones 079 II  RENCIPAL VULNEABBLITY:  No  CONTROL  CONT	
Treryn Dinas fort, St. Levan  EBEGNATION:  Scheduled Monument  CONDITION:  Generally unsatisfactory with major localised problems  FIRINCIPAL VALNERABILITY:  SCRUP/Tree growth  CONTRET TYPE:  Charity (heritage)  CONTRET TYPE:  CONT	
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006733  CONDITION Generally unsatisfactory with major localised problems  PRINCIPAL VULNEARBILITY: Scrub/tree growth NEW ENTRY: No OWNER TYPE Charity (heritage) CONTACT: Ann Preston-Jones 0791  SITE NAME: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018019  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNEARBILITY: Other NEW ENTRY: No OWNER TYPE Local authority CONTACT: Daniel Bashford 07824  SITE NAME: Cliff castle at Winecove Point, St. Merryn DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004234  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNEARBILITY: Ocastal erosion New ENTRY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: St. Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  SITE NAME: St. Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNEARBILITY: No OWNER TYPE: Ann Preston-Jones 0791  SITE NAME: ROUND 790 metres north east of Trebollack, St. Michael Penkevil DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNEARBILITY: Prostry OWNER TYPE: Private CONTACT: Ann Preston-Jones 0791  SITE NAME: ROUND 790 metres north east of Trebollack, St. Michael Penkevil DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019612  CONDITION: Private CONTACT: Ann Preston-Jones 0791  SITE NAME: Private CONTACT: Ann Presto	7917 642388
Generally unsatisfactory with major localised problems  PRINCIPAL VUNERABILITY: Scrub/tree growth  Charity (heritage)  CONIACE: Ann Preston-Jones 0791  STEINAME: Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick Designations  Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Other  CONNER TYPE: Local authority  CONTACE: Daniel Bashford 07824  STEINAME: Cliff castle at Winecove Point, St. Merryn  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Oberea NEW ENTRY: No Declining  STEINAME: Cliff castle at Winecove Point, St. Merryn  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY: No CONTACE: Ann Preston-Jones 0791  STEINAME: St. Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II INSTENDINGER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  CONTACE: Ann Preston-Jones 0791  STEINAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019612  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  CONDITION: Scheduled Monument  UST ENTRY NUMBER: 1019612  TREND: Stable  PRINCIPAL VULNERABILITY: Forestry  CONTACE: Ann Preston-Jones 0791  STEINAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019612  TREND: Stable  PRINCIPAL VULNERABILITY: Forestry  CONTACE: Ann Preston-Jones 0791  STEINAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: DESIG	
PRINCIPAL VILINIFIABILITY: Scrub/tree growth NEW INTERY: No OWNER TYPE: Charity (heritage) CONTACT: Ann Preston-Jones 0791  STE NAME Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018019  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILINIFIABILITY: Other NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Daniel Bashford 07824  STE NAME: Cliff castle at Winecove Point, St. Merryn  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004234  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1004234  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILINERABILITY: Coastal erosion NEW ENTRY: No OWNER TYPE: No OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 0791  STE NAME: St Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  CONDITION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  TREND: Declining  PRINCIPAL VILINERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: N	
OWNER TYPE Charity (heritage) Charity (heritage) Charity (heritage)  Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick DESIGNATION Scheduled Monument Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Other NEW ENTRY: No OWNER TYPE Local authority CONTACT: Daniel Bashford 07824  STE NAME CONDITION: CONTACT: Daniel Bashford 07824  STE NAME CONDITION: CONTACT: Daniel Bashford 07824  STE NAME CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY: No OWNER TYPE Private, multiple owners CONTACT: Ann Preston-Jones 0791  STE NAME St Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: Plant growth NEW ENTRY: No OWNER TYPE: COMMERTIFE: CONDITION: Generally satisfactory with major localised problems PRINCIPAL VULNERABILITY: No OWNER TYPE: CONTACT: Ann Preston-Jones 0791  STE NAME Scheduled Monument LIST ENTRY NUMBER: 1019612  STE NAME Scheduled Monument LIST ENTRY NUMBER: 1019612  TREND: DESIGNATION: CONTACT: Ann Preston-Jones 0791  STE NAME ROUND Scheduled Monument LIST ENTRY NUMBER: 1019612  TREND: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  TREND: TREND: TREND: TREND: TREND: Ann Preston-Jones 0791  STE NAME The Rumps promontory fort, St. Minver Highlands DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  TREND: DESIGnation: DESIGnation: Scheduled Monument LIST ENTRY NUMBER: 1004625  TREND: DESIGnation: DESIGnation: DESIGnation: DESIGnation: DESIGnation: D	
STENAME Westcott Cross, 480 metres south east of Westcott Lodge, St. Mellion / St. Dominick DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Other  NEW ENTRY): No Daniel Bashford 07824  STENAME: Cliff castle at Winecove Point, St. Merryn DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004234  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Ocastal erosion NEW ENTRY): No DOWNER TYPE Private, multiple owners  St. Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  STENAME St. Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No DOWNER TYPE: No DESIGNATION: Scheduled Monument ust ENTRY NUMBER: 1019612  STENAME: Scheduled Monument UST ENTRY NUMBER: 1019612  SCHEDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Private  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Private  CONTACT: Ann Preston-Jones 0791  STENAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: Declining  PRINCIPAL VULNERABILITY: Private  CONTACT: Ann Preston-Jones 0791  TREND: Declining  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: Declining  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: Declining  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: Declining  DESIGNATION: NEW ENTRY: No	
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018019  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Other  Othe	7917 642388
Generally satisfactory but with significant localised problems  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Other  Other  NEW ENTRY:  No  OWNER TYPE:  Local authority  Contact:  Daniel Bashford 07824  STE NAME:  Cliff castle at Winecove Point, St. Merryn  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  IO04234  TREND:  Declining  PRINCIPAL VULNERABILITY:  No  OWNER TYPE:  St Constantine's chapel and holy well, St. Merryn  DESIGNATION:  Scheduled Monument, LB grade II  UST ENTRY NUMBER:  IO18569  TREND:  Declining  PRINCIPAL VULNERABILITY:  Plant growth  NEW ENTRY:  No  OWNER TYPE:  Commercial company  CONTACT:  Ann Preston-Jones 0791  STE NAME:  DESIGNATION:  CONTENT:  REND:  Declining  PRINCIPAL VULNERABILITY:  Plant growth  NEW ENTRY:  No  OWNER TYPE:  CONTENT:  Ann Preston-Jones 0791  STE NAME:  ROund 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO19612  TREND:  Stable  PRINCIPAL VULNERABILITY:  Private  CONTACT:  Ann Preston-Jones 0791  STE NAME:  ROUND 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO19612  TREND:  Stable  PRINCIPAL VULNERABILITY:  Yes  OWNER TYPE:  Private  The Rumps promontory fort, St. Minver Highlands  Scheduled Monument  UST ENTRY NUMBER:  IO04625  Ann Preston-Jones 0791  TREND:  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04625  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04625  Generally satisfactory but with significant localised problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Private  CONTACT:  Ann Preston-Jones 0791  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04625  DECLINING  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04625  DECLINING  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  IO04625  DECLINING  DESIGNATION:  D	
PRINCIPAL VULNERABILITY: Other  OWNER TYPE  Local authority  Other  OWNER TYPE  Contract:  Designation:  Scheduled Monument  Contract:  Ann Preston-Jones 079 I  Contract:  Cont	
OWNER TYPE:  Local authority  CONTACT:  Daniel Bashford 07824  STE NAME:  Cliff castle at Winecove Point, St. Merryn  DESIGNATION:  Scheduled Monument  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Coastal erosion  NEW ENTRY:  No  OWNER TYPE:  Private, multiple owners  St. Constantine's chapel and holy well, St. Merryn  DESIGNATION:  Scheduled Monument, LB grade II  LIST ENTRY NUMBER:  1018569  CONTACT:  Ann Preston-Jones 079 I  DESIGNATION:  Scheduled Monument, LB grade II  LIST ENTRY NUMBER:  1018569  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  NEW ENTRY:  No  OWNER TYPE:  Commercial company  CONTACT:  Ann Preston-Jones 079 I  STE NAME:  Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1019612  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Forestry  NEW ENTRY):  Yes  OWNER TYPE:  Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1004625  Ann Preston-Jones 079 I  STE NAME:  The Rumps promontory fort, St. Minver Highlands  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1004625  Ann Preston-Jones 079 I  STE NAME:  The Rumps promontory fort, St. Minver Highlands  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1004625  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Declining  Declining  Declining	
DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004234  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  DESIGNATION: Scheduled Monument  CONTACT: Ann Preston-Jones 079 I  SITE NAME: St Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: No  CONTACT: Ann Preston-Jones 079 I  STE NAME: Scheduled Monument, LB grade II  UST ENTRY NUMBER: 1018569  Declining  PRINCIPAL VULNERABILITY: No  CONTACT: Ann Preston-Jones 079 I  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  NEW ENTRY): Yes  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  Ann Preston-Jones 079 I  STE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  TREND: Declining  PRINCIPAL VULNERABILITY: OSAtal erosion  NEW ENTRY): No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004234  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  OWNER TYPE: Private, multiple owners  St Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II  LIST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Commercial company  CONTACT: Ann Preston-Jones 079 II  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  PRINCIPAL VULNERABILITY: Forestry  Private  CONTACT: Ann Preston-Jones 079 II  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  Stable  PRINCIPAL VULNERABILITY: Forestry  NEW ENTRY: Yes  OWNER TYPE: Private  CONTACT: Ann Preston-Jones 079 II  STE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  Declining	24 103102
Generally satisfactory but with significant localised problems  REINCIPAL VULNERABILITY: Coastal erosion NEW ENTRYP: No  OWNER TYPE: Private, multiple owners  St Constantine's chapel and holy well, St. Merryn DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: IO18569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRYP: No  OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 079 II  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO19612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Private CONTACT: Ann Preston-Jones 079 II  STE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: Ann Preston-Jones 079 II  STE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO4625 CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO4625 CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO4625 CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: IO4625 Declining  Declining  PRINCIPAL VULNERABILITY: No	
PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRYP: No  OWNER TYPE: Private, multiple owners  St Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II UST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRYP: No  OWNER TYPE: Commercial company  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  CONTACT: Ann Preston-Jones 079 II  STE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  NEW ENTRY: Declining  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY: No	
OWNER TYPE: Private, multiple owners CONTACT: Ann Preston-Jones 079 I  SITE NAME: St Constantine's chapel and holy well, St. Merryn  DESIGNATION: Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 079 I  SITE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry NEW ENTRY: Yes  OWNER TYPE: Private CONTACT: Ann Preston-Jones 079 I  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY: No	
DESIGNATION: Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  OWNER TYPE: Commercial company  STE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Porestry  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1019612  Stable  PRINCIPAL VULNERABILITY: Forestry  NEW ENTRY?: Yes  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONTACT: Ann Preston-Jones 0791  STITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: Coastal erosion	
DESIGNATION: Scheduled Monument, LB grade II LIST ENTRY NUMBER: 1018569  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  OWNER TYPE: Commercial company  SITE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  NEW ENTRY?: Yes  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  Ann Preston-Jones 079 II  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  CONDITION: Declining  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY?: No	7917 642388
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth New Entry?: No OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 079 I  SITE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry NEW ENTRY?: Yes OWNER TYPE: Private CONTACT: Ann Preston-Jones 079 I  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY?: No	
problems  problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY?: No  CONTACT: Ann Preston-Jones 079 I  SITE NAME: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  Ann Preston-Jones 079 I  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY?: No	
OWNER TYPE: Commercial company CONTACT: Ann Preston-Jones 079 Issue Name: Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry NEW ENTRY?: Yes  OWNER TYPE: Private CONTACT: Ann Preston-Jones 079 Issue Name: LIST ENTRY NUMBER: 1004625  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion New ENTRY?: No	
Round 790 metres north east of Trebollack, St. Michael Penkevil  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry NEW ENTRY?: Yes  OWNER TYPE: Private CONTACT: Ann Preston-Jones 0791  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY?: No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019612  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY?: No	7917 642388
Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Forestry OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: Declining  PRINCIPAL VULNERABILITY: Coastal erosion  LIST ENTRY: New ENTRY?: No	
problems  PRINCIPAL VULNERABILITY: Forestry  OWNER TYPE: Private  The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion  NEW ENTRY?: No  Stable  Yes  CONTACT: Ann Preston-Jones 079 I  LIST ENTRY NUMBER: 1004625  TREND: Declining  NEW ENTRY?: No	
OWNER TYPE: Private CONTACT: Ann Preston-Jones 079 I  SITE NAME: The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY?: No	
The Rumps promontory fort, St. Minver Highlands  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY?: No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004625  CONDITION: Generally satisfactory but with significant localised problems TREND: Declining  PRINCIPAL VULNERABILITY: Coastal erosion NEW ENTRY?: No	7917 642388
Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Coastal erosion  Declining  New Entry:  No	
problems  PRINCIPAL VULNERABILITY: Coastal erosion  New entry?: No	
CONTACT AND DOLLAR OF THE CONTACT AND DOLLAR	
OWNER TYPE: Charity (heritage) CONTACT: Ann Preston-Jones 079 l	7917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Hobbs Hill tin mine, openwork and lodeback tinwork 530 metres east and 160 metres north east of Chyseger Farm, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021410
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hut circle village 330 yards (300 metres) west of V	Vest Northwood F	arm, St. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004662
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Prehistoric field systems, enclosure, hut circles and field system on Higher Langdon Farm, St. Neot	l rounds, with adjac	cent medieval settlement, longhouse a
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007475
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Prehistoric settlements and field system with adjacent medieval settlement, field systems, boundaries and ti streamworks on the Brown Gelly Downs, St. Neot		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007770
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 1.062 kilometres south west of Highe	r Langdon Farm, St	. Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007476
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Round cairn 1.17 kilometres south west of Higher	Langdon Farm, St.	Neot
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007477
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Castle Dore (camp), St. Sampson / Tywardreath ar	nd Par	
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1006691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / CORNWALL (UA)			
SITE NAME:	Tregargus stone grinding mill No. 2, St. Stephen-in	-Brannel		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1003101	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Other not for profit group	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Round barrow north east of Kernick, St. Stephens By Launceston Rural			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003272	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Two round barrows north east of Fairy Cross, St.	Winnow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004439	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	New Consols Mine: surface, buried and undergrou	nd remains, Lucket	t , Stokeclimsland	
DESIGNATION:	Scheduled Monument, 5 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1409595	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	Condolden Barrow, Tintagel			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004652	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388	
SITE NAME:	The Ballast Pond, Torpoint			
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1007261	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102	
SITE NAME:	Carne Beacon round barrow 320 metres north of	Carne Farm, Verya	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019745	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Ann Preston-Jones 07917 642388	

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Ancient village south of Carburrow Tor, Warleggan			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1003073
CONDITION:	Generally satisfac	tory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Chapel Jane medieval chapel 600 yards (550 metres) NNW of Treen, Zennor			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004631
CONDITION:	Generally satisfac	ctory but with significant localised	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion		NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	)	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Hut circle settler	ment at Sperris Croft 500 yards (4	60 metres) south e	ast of Tregerthen Cottage, Zennor
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004307
CONDITION:	Generally unsatis	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Round barrow on Tremeador Common 600 yards		(550 metres) SSE of	of Tregerthen Cottage, Zennor
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004306
CONDITION:	Generally unsatis	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Treen Common	barrows, Zennor		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004473
CONDITION:	Generally satisfac	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners		CONTACT:	Ann Preston-Jones 07917 642388
	SITE NAME:	Carclew, Mylor		terraced and water gardens, together wi
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs, WHS	1934 and the site	e park. The main house burned down in e is now in divided ownership. Infill opment has taken place in the park belts,
	CONDITION:	Extensive significant problems	. له حديد حاد حديد ما له مداله مدين م عديد ما دينه المحديد المتعدد المتعدد المتعدد المتعدد المتعدد المتعدد	of woodland have been cleared and mar
<b>《公司》</b>	VULNERABILITY:	High		



© Historic England

SITE NAME:	Carclew, Mylor
DESIGNATION:	Registered Park and Garden grade II, 5 LBs, WHS
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000544

Contact: Jo McAllister 0117 975 0696

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

LIST ENTRY NUMBER



© Historic England

WEST / COMWINEL (ON) / BARTITOOK (IVI)			
SITE NAME:	Battle of Braddock Down, Broadoak / St. Pinnock		
DESIGNATION:	Registered Battlefield, LB grade II, 2 SMs		
CONDITION:	Extensive significant problems		
VULNERABILITY:	High		
TREND:	Declining		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Private		

1000005

Battle of Braddock Down, 1643. A large proportion of the designated area of the battlefield is under plough, including two of the scheduled barrows. The site is therefore at risk. Geophysical survey work was undertaken in 2015 on two of the barrows within the battlefield, surrounding ditches, and a small area of adjacent ground. If arable reversion follows to protect the barrows, it will also afford protection from further disturbance to the battlefield and any buried deposits, particularly in the barrow ditches. However the battlefield as a whole will still be at risk.

Contact: Daniel Bashford 07824 103102

SITE NAME:	Bodmin		
DESIGNATION:	Conservation Area, 96 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Alyson Cooper (LPA) 01872 323603

## **DEVON**

### DARTMOOR (NP)



SITE NAME: Higher Sigford, Sweet's Sigford, llsington, Teignbridge DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

A rare example of a longhouse derivative in a farmstead context which has been used for agricultural storage in more recent years. Conditional consents for reoccupation of the house have been granted. Historic England has met with the owner and repair works are now proceeding.

© Historic England

LIST ENTRY NUMBER: 1389617 Contact: Annie Evans 0117 975 1308



© Historic England Archive

	Mills, a partially enclosed stone hut circle settlement and round cairn, Dartmoor Forest, West Devon
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Crown

Gunpowder factory at Powder

Devon's only C19 gunpowder factory dates to 1844 and comprises of at least 18 buildings involved in the production, storage and management of gunpowder. These buildings are now vacant and neglected, and there are unmanaged trees growing across the site. In 2015, a tree fell and knocked down the gable end of one building.



© Historic England

LIST ENTRY NUMBER: 1016635 SITE NAME: Church of St Petrock, Church Street, South Brent, South Hams

C12 parish church of which the west tower (formerly at the crossing) of the originally cruciform church survives. The west end was demolished c early C14 when the present nave was rebuilt with two transepts. North and south aisles of early C15, restored late C19. The congregation was awarded a Heritage Lottery Fund Grant for Places of Worship and in 2016-17 the tower was grouted and repointed and the vestry roof was repaired. The nave roof remains in poor condition.

Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1147794

Contact: Annie Evans 0117 975 1308

Contact: Andy Crabb 01626 832093

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Thomas à Becket, Bridford, Teignbridge
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1097825

A medieval granite church in an exposed location on the southern fringe of Dartmoor National Park. The pointing on the tower is failing and falling, and this is allowing water ingress into the fabric, while rainwater disposal is inadequate. The church was awarded a Listed Places of Worship Roof Repair Grant in July 2016.

Contact: Annie Evans 0117 975 1308

© Historic England



SITE NAME: Parish Church of Holy Trinity, Church Hill, Buckfastleigh, Teignbridge DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1209920

Former parish church. Sited on a high hill. C13 tower; chancel and transepts possibly also C13 in origin; C15 aisles and chancel chapels. Thorough restoration in 1844-1845. Left gutted and roofless after fire on 20 July 1992. The stonework, especially the window tracery, needs further repair. Despite the fire damage, services are still held at the church.

Contact: Annie Evans 0117 975 1308

© Historic England

SITE NAME:	Enclosure on the west side of the Erme valley below Stalldown, Cornwood, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012767	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	The southern of three enclosures north of Ford W	aste, Cornwood, S	outh Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012700	
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Unknown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Three unenclosed stone hut circles on the west side of the Erme Valley, north of Lower Piles, Cornwood, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012768	
DESIGNATION:  CONDITION:	Scheduled Monument  Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER:	1012768  Declining	
	Generally unsatisfactory with major localised			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
CONDITION: PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised problems  Plant growth	TREND:  NEW ENTRY?:  CONTACT:	Declining No Andy Crabb 01626 832093	
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Generally unsatisfactory with major localised problems Plant growth Private	TREND:  NEW ENTRY?:  CONTACT:	Declining No Andy Crabb 01626 832093	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Generally unsatisfactory with major localised problems  Plant growth  Private  Two hut circles on the south east slope of Stalldow	TREND:  NEW ENTRY?:  CONTACT:  vn, Cornwood, Sou	Declining  No  Andy Crabb 01626 832093  oth Hams	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Generally unsatisfactory with major localised problems  Plant growth  Private  Two hut circles on the south east slope of Stalldow Scheduled Monument  Generally satisfactory but with significant localised	TREND:  NEW ENTRY?:  CONTACT:  VI, Cornwood, Sou	Declining  No Andy Crabb 01626 832093  ath Hams 1012766	

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument

SITE NAME:	Unenclosed stone hut settlement north east of Yao	dsworthy, Cornwo	od, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and hut circles east of Huntingdon Ford,	, Dean Prior, South	Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002536
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Agglomerated enclosure with hut circles, south of	Lower Piles, Harfo	rd, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009578
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Blowing house at junction of Hook Lake and River	Erme, Harford, So	uth Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002605
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Blowing house north of Dry Lake, Harford, South	Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002609
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles east of Addicombe, Harr	ford, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012484
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles east of Addicombe, Harr	ford, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017609
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Enclosure with hut circles in Higher Piles newtake, Harford, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013110		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Enclosure with hut circles to the north east of Pile	Enclosure with hut circles to the north east of Piles Copse, Harford, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013106		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut circles and enclosure to south of Left Lake, Ha	arford, South Hams	1		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004574		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Hut circles in Erme Pound east of River Erme, Harford, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002604		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Stone row, cairn and enclosures near Hook Lane,	Erme Valley, Harfoi	rd, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002493		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Unenclosed stone hut settlement on the east side Hams	of the Erme Valley,	North Harford Moor, Harford, South		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012747		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Unenclosed stone hut settlement with enclosures	north of Piles Cops	se, Harford, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012765		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / DARTMOOR (NP)		
SITE NAME:	Enclosed prehistoric settlement and three round of Hams	airns 870 metres so	outh east of Horn's Cross, Holne, Sout
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Four cairns 560 metres east of Hapstead Ford and cemetery in the Mardle Valley, Holne, South Hams	1660 metres east o	of Ryder's Hill, forming part of a cairn
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019270
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Part of the Dartmeet coaxial field system and othe west of Venford Reservoir, Holne, South Hams	r archaeological re	mains on Holne Moor west and north
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020487
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Partially enclosed stone hut circle settlement 350	metres south west	of Horn's Cross, Holne, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019274
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Partially enclosed stone hut circle settlement 420 Holne, South Hams	metres north west	and 440 metres west of Horn's Cross
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020185
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric fields and settlements north east of Ve system, Holne, South Hams	nford Reservoir for	ming part of the Dartmeet coaxial fiel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020091
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Prehistoric fields, settlements and cairn south east field system, Holne, South Hams	of Venford Reserve	oir forming part of the Dartmeet coa
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020092
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval farmstead and field system, post-medieva west of Gibby Coombe, Holne / West Buckfastleig	l tinworks, prehisto h, South Hams	oric settlements and cairns north and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019591
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Barrow near Shaugh Cross, Shaugh Prior, South H	ams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003824
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cross Dyke reave, Shaugh Prior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Eight pillow mounds and a vermin trap on the nort Trowlesworthy Warren, Shaugh Prior, South Ham	hern slope of Little s	Trowlesworthy Tor forming part of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015758
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosed stone hut circle settlement and three rou	ınd cairns on Giant	's Hill, Shaugh Prior, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019081
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles west of Saddlesborough, Shaugh Prior,	South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002520
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012172		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Multi-period remains at Hentor Warren, Shaugh P	rior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019082		
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012214		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	One of three stone hut circles 500 metres SSE of Legis Tor, Shaugh Prior, South Hams				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012631		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Pillow mound 100 metres south east of Great Tro Shaugh Prior, South Hams	wlesworthy Tor, fo	orming part of Trowlesworthy Warren		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014666		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Pillow mound 160 metres south west of Great Tro Shaugh Prior, South Hams	owlesworthy Tor, fo	orming part of Trowlesworthy Warre		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014665		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Pillow mound 270 metres south east of Ditsworth Prior, South Hams	y Warren House fo	orming part of Hentor Warren, Shaugh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014477		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093		

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Scheduled Monument Constriction Constraint C	SITE NAME:	Pillow mound 610 metres SSW of Ditsworthy Wa Prior, South Hams	rren House formin	g part of Willings Walls Warren, Shau	
Pale growth Plant	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014469	
OWNERTIFIC Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  BILL MANUEL  BI	CONDITION:		TREND:	Declining	
Fillow mound 620 metres ESE of Legis Tor forming part of Willings Walls Warren, Shaugh Prior, South Has Dissonation.  Scheduled Monument IST INTERNATION.  Scheduled Monument IST INTERNATION.  Generally satisfactory but with significant localised Problems.  Plant growth New Harm.  Plant growth New Harm.  Plant growth No.  CONTACT.  Andy Crabb 01626 832093  STENANC.  Scheduled Monument UST ENTERNATION.  Generally unsatisfactory with major localised Problems.  Plant growth No.  CONTACT.  Plus mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams.  Dissonation.  Scheduled Monument UST ENTERNATION.  Plus mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  Plus mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  Plant growth New Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  Plant growth New Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  Plant growth New Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  No.  Declining.  PRINCIPAL VALUETABULTY.  Plant growth New Hams.  Dissonation.  Scheduled Monument IST ENTERNATION.  No.  Declining.  PRINCIPAL VALUETABULTY.  Plant growth New ENTERN.  No.  Declining.  PRIOD LAGE 832093  TRENCIPAL VALUETABULTY.  Plant growth New ENTERN.  No.  Declining.  PRIOD LAGE 832093  TRENCIPAL VALUETABULTY.  Plant growth New ENTERN.  No.  Declining.  PRIOD LAGE 832093  TRENCIPAL VALUETABULTY.  Plant growth New ENTERN.  No.  Declining.  PRIOD LAGE 832093  TRENCIPAL VALUETABULTY.  Plant growth New ENTERN.  Prior, South Hams.  Disconation.  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Mon	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
Scheduled Monument UST ENTRY NUMBER: 1014457 CONDITION: Generally satisfactory but with significant localised TREND: Declining PRENCENDAL YULNISABILITY: Plant growth  Plant growth  COMMERTYPE: Commercial company  CONTACT: Andy Crabb 01626 832093  SITE NAME: South Hams  CONDITION: South Hams  CONDITION: UST ENTRY NUMBER: 1014662  CONDITION: Declining  PRENCEDAL YULNISABILITY: Plant growth  South Hams  CONDITION: Declining  PRENCEDAL YULNISABILITY: Plant growth  Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior CONDITION: Problems  SCHEDULA YULNISABILITY: Plant growth  Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior Condition  Generally unsatisfactory with major localised problems  PRENCEDAL YULNISABILITY: Plant growth NEW ENTRY: No  CONTACT: Andy Crabb 01626 832093  SITE NAME: Plant growth New Entry: No  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESCRAPICEN YULNISABILITY: Plant growth New Entry: No  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESCRAPICEN YULNISABILITY: Plant growth New Entry: No  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESCRAPICEN YULNISABILITY: Plant growth New Entry: No  CONNECTION Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESCRAPICEN YULNISABILITY: Plant growth New Entry: No  CONNECTION Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Private Yulnistic Plant growth New Entry: No  CONNECTION Private Yulnisti	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
CONDITION  Generally satisfactory but with significant localised problems  PRINCIPLY VOLKERABILITY: Plant growth  NEW DATAYS: No  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 790 metres NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument  Generally unsatisfactory with major localised problems  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument  With Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument  Scheduled Monument  Generally unsatisfactory with major localised problems  Principle owners  CONTRACT: Andy Crabb 01626 832093  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Declining  Principle owners  CONTRACT: Andy Crabb 01626 832093  SITE NAME  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DEGINATION: Scheduled Monument  Scheduled Monume	SITE NAME:	Pillow mound 620 metres ESE of Legis Tor forming	g part of Willings V	Valls Warren, Shaugh Prior, South Ha	
Problems problems Plant growth	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	101 <del>44</del> 57	
Commercial company  COMMERTYPE  Pillow mound 790 metres NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument  Scheduled Monument  COMMINION  Scheduled Monument  COMMINION  COMMERTYPE  Mixed, multiple owners  COMMINION  Scheduled Monument  South Hams  DESIGNATION  COMMINION  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  DESIGNATION  Scheduled Monument  Scheduled Monument  COMMINION  COMMERTYPE  Mixed, multiple owners  COMMINION	CONDITION:		TREND:	Declining	
Pillow mound 790 metres NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument  CONDITION:  Generally unsatisfactory with major localised problems  Plant growth  Meed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Private  CONTACT:  Andy Crabb 01626 832093  PRINCIPLA VULNERABILITY:  Plant growth  Private  Priv	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
South Hams  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  Plant growth  Mixed, multiple owners  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  Prior, South Hams  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: No  Declining  PRINCIPAL VULNERABILITY: No  Declining  PRINCIPAL VULNERABILITY: No  Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  DESIGNATION: Scheduled Monument  DESIGNATION: Declining  DESIGNATION: Declining  PRINCIPAL VULNERABILITY: No  DECINITION: No  DECINITION: Declining  PRINCIPAL VULNERABILITY: No  DECINITION: No  DECINITION: Declining  PRINCIPAL VULNERABILITY: No  DECINITION: Declining  PRINCIPAL VULNERABILITY: No  DECINING	OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093	
Generally unsatisfactory with major localised problems  PRINCIPLE VULNERABILITY: Plant growth  Mixed, multiple owners  Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Pricesouth Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLE VULNERABILITY: No  OWNER TYPE: Mixed, multiple owners  Principle vulnerability: Plant growth  Mixed multiple owners  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  PRINCIPLE VULNERABILITY: No  OWNER TYPE: Mixed, multiple owners  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  PERINCIPLE VULNERABILITY: Declining  PRINCIPLE VULNERABILITY: Plant growth  NEW ENTRY: No  OWNER TYPE: Mixed, multiple owners  PRINCIPLE VULNERABILITY: Plant growth  Mixed, multiple owners  Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1002516  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLE VULNERABILITY: No  OWNER TYPE: No  OWNER TYPE: No  CONTACT: Andy Crabb 01626 832093  BITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1002516  CONDITION: Plant growth  NEW ENTRY: No  OWNER TYPE: No  OWNER TYPE: Private  Private  Private  Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  Scheduled Monument  UST ENTRY NUMBER: 1020011  CONDITION: Scheduled Monument  UST ENTRY NUMBER: 1020011  CONDITION: Private  Private Private Numbers: 1020011  CONDITION: Private  Private Private  Private Numbers: No  OWNER TYPE: No  OWNER T	SITE NAME:				
PRINCIPAL VULNERABILITY: Plant growth NEW BATRY: No CONTACT: Andy Crabb 01626 832093  SITE NAME: Plilow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  Scheduled Monument List Entry Number: 1014664  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth New BATRY: No CONTACT: Andy Crabb 01626 832093  SITE NAME: Plilow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  PRINCIPAL VULNERABILITY: Plant growth New BATRY: No CONTACT: Andy Crabb 01626 832093  SITE NAME: Plant growth New BATRY: No Declining  PRINCIPAL VULNERABILITY: Plant growth New BATRY: No CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516  Generally unsatisfactory with major localised problems  STENAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW BATRY: No  OWNER TYPE: No  OWNER TY	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014662	
Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  STIE NAME: Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Charles of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Mixed, multiple owners  DESIGNATION: Contract: No  Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  STIE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002516  Generally unsatisfactory with major localised problems  Prior South Hams  DESIGNATION: Condition: Declining  Prior South Hams  DESIGNATION: Condition: Plant growth  NEW ENTRY: No  OWNER TYPE: No  OWNER TYPE: No  OWNER TYPE: Plant growth  Private  CONTACT: Andy Crabb 01626 832093  STIE NAME: Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1020011  Generally satisfactory but with significant localised  TREND: Declining  Declining  PRINCIPLE WUNNERABBILITY: Plant growth  Prior South Hams  DESIGNATION: Declining  Prior South Hams  DESIGNATION: Declining  PRINCIPLE WUNNERABBILITY: Plant growth  Prior South Hams  DESIGNATION: Declining  PRINCIPLE WUNNERABBILITY: Plant growth  Prior South Hams  DESIGNATION: Declining  PRINCIPLE WUNNERABBILITY: Plant growth  PRINCIPLE WUNNERABBILITY: Plant growth  PRINCIPLE WUNNERABBILITY: Plant growth  PRINCIPLE WUNNERABBILITY: Plant growth  PRI	CONDITION:		TREND:	Declining	
Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior South Hams  DESIGNATION:  Scheduled Monument  Generally unsatisfactory with major localised problems  Pillow growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  STEENAME  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1014616  Generally unsatisfactory with major localised problems  Pillow growth  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  Pillow for an and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1002516  Generally unsatisfactory with major localised problems  Scheduled Monument  UST ENTRY NUMBER:  1002516  Generally unsatisfactory with major localised problems  Pillow problems  Pillow problems  RINNO:  Declining  Pillow problems  Pillow problems  RINNO:  Declining  Pillow problems  RINNO:  Declining  Pillow problems  RINNO:  Declining  Pillow problems  RINNO:  Declining  RINNO:  Declining  Pillow problems  RINNO:  Declining  RINNO:  RIN	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
DESIGNATION: Scheduled Monument	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
Generally unsatisfactory with major localised problems  Plant growth  New ENTRY:  Plant growth  Mixed, multiple owners  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  SETE NAME:  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  IO14616  CONDITION:  Generally unsatisfactory with major localised problems  Plant growth  NEW ENTRY:  No  OWNER TYPE:  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  STE NAME:  Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  IO02516  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  New ENTRY:  No  OWNER TYPE:  Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams:  Scheduled Monument  LIST ENTRY NUMBER:  IO20011  Andy Crabb 01626 832093  TREND:  Declining  PRINCIPAL VULNERABILITY:  Plant growth  Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams:  Scheduled Monument  LIST ENTRY NUMBER:  IO20011  Declining  PRINCIPAL VULNERABILITY:  Plant growth  Privation:  Scheduled Monument  LIST ENTRY NUMBER:  IO20011  Declining  PRINCIPAL VULNERABILITY:  Plant growth  Plant growth  NEW ENTRY:  No	SITE NAME:	Pillow mound 860 metres NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prio South Hams			
PRINCIPAL VULNERABILITY: Plant growth New ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  SITE NAME: Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1014616  CONDITION: Generally unsatisfactory with major localised problems  Plant growth NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  Scheduled Monument LIST ENTRY NUMBER: 1020011  CONDITION: Scheduled Monument LIST ENTRY: No OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014664	
Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY? No  OWNER TYPE: Private  CONTACT: Andy Crabb 01626 832093  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY? NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY? NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY? NUMBER: 1020011	CONDITION:		TREND:	Declining	
Pillow mound 860 metres SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1014616  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No  OWNER TYPE: Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002516  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No  OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Private CONTACT: Andy Crabb 01626 832093  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY!: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Mixed, multiple owners  Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Mixed and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002516  CONDITION: Declining  PRINCIPAL VULNERABILITY: No  OWNER TYPE: No  OWNER TYPE: Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: Plant growth  New ENTRY: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY?: No  Declining  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY?: No	SITE NAME:		Varren House, for	ming part of Trowlesworthy Warren,	
problems  PRINCIPAL VULNERABILITY: Plant growth  New ENTRYP: No  OWNER TYPE: Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  New ENTRY: No  OWNER TYPE: Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Declining  PRINCIPAL VULNERABILITY: No  Declining  New ENTRY: No  No  New ENTRY: No  Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014616	
Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  SITE NAME: Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: UST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY: No  Declining  NEW ENTRY: NUMBER: 1020011  TREND: Declining  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRY: No	CONDITION:		TREND:	Declining	
Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  New ENTRY?: Declining  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1020011  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  New ENTRY?: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002516 CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRYP: No  CONTACT: Andy Crabb 01626 832093  BESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRYP: No  Declining  NEW ENTRYP NUMBER: 1020011  TREND: Declining	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  PESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  REND: Declining  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh 1020011  Reprivate Private Note Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh 1020011  Reprivate Note Private Note Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh 1020011  Reprivate Note Private Note Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh 1020011  Reprivate Note Private Note Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh 1020011  Reprivate Note Private Note Plant growth Note Plant	SITE NAME:	Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams			
problems  PRINCIPAL VULNERABILITY:  Plant growth  Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Plant growth  New Entry:  No  Declining  New Entry:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002516	
Private  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION:  Scheduled Monument  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Plant growth  CONTACT:  Andy Crabb 01626 832093  LIST ENTRY NUMBER: 1020011  TREND:  Declining  NEW ENTRY:  No	CONDITION:		TREND:	Declining	
Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams  DESIGNATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh  LIST ENTRY NUMBER: 1020011  TREND: Declining  New ENTRY: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
Prior, South Hams  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020011  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  New ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Generally satisfactory but with significant localised problems  TREND:  Declining  New entry:  No	SITE NAME:	Rectangular building 420 metres north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams			
problems problems  PRINCIPAL VULNERABILITY: Plant growth  New entry: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020011	
•	CONDITION:		TREND:	Declining	
OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Stone hut circle north east of Hentor Brook, Shaug	gh Prior, South Har	ms	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012175	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle north of Hentor Brook, Shaugh Pr	ior, South Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012083	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Three pillow mounds and a linear gully 200 metres north of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014481	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two pillow mounds 640 metres ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015747	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two pillow mounds and a small area of tin streamwork 510 metres south west of Ditsworthy Warren Hous forming part of Willings Walls Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014467	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two pillow mounds and a small area of tin streamwork earthworks 770 metres north of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014663	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Vermin trap 350 metres south west of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014475	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Vermin trap 510 metres WSW of Great Trowlesv Prior, South Hams	vorthy I or forming	part of Trowlesworthy Warren, Sha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014465
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Vermin trap 520 metres SSW of Trowlesworthy V Shaugh Prior, South Hams	Varren House form	ning part of Trowlesworthy Warren,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Vermin trap 800 metres south east of Trowleswood Warren, Shaugh Prior, South Hams	rthy Warren House	e forming part of Trowlesworthy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014464
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cist with a retaining kerb north west of Corringdo	on Ball, South Brent	, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010180
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Enclosure and hut circle north of Old Hill, South B	Brent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003200
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles and rectangular pens, so	outh of Bala Brook,	South Brent, South Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012775
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles north of Bala Brook inta	ake, South Brent, So	outh Hams
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Enclosure with hut circles north of Bala Brook intake, South Brent, South Hams			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012783	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosures and hut circles at Petre's Pits Bottom, S	outh Brent, South	Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004557	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut circle and fields, Bishop's Mead, South Brent, S	outh Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002537	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut enclosure north of Old Hill, South Brent, Sout	h Hams		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002664	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	One of several stone hut circles north of Corringd	on Ball, South Brer	it, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010202	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Three enclosed hut groups, Black Tor, Shipley Brid	ge, South Brent, So	outh Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002505	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two conjoined huts between two enclosures north	n of Bala Brook inta	ake, South Brent, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012778	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Two hut circles on the right bank of Red Brook, So	outh Brent, South F	Hams
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013035
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure with hut circles north of Scad Brook, Ug	gborough, South Ha	ims
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012485
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of a number of cairns at Black Pool, Ugborou	gh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012232
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	One of a number of cairns at Black Pool, Ugborou	gh, South Hams	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012285
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone alignment and cairn south east of Western E	Beacon, Ugborough	, South Hams
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017604
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn 240 metres north of Crownley Parks, llsingto	on, Teignbridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019588
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Settlement on Smallacombe Rocks, Ilsington, Teign	bridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002531
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / DARTMOOR (NP)		
SITE NAME:	Settlement west of Holwell Tor, Ilsington, Teignbr	idge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002529
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric and medieval settlements and their field	d systems at Hound	Tor, Manaton, Teignbridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Medieval strip fields, tinworks, prehistoric settleme Down, Manaton / Widecombe in the Moor, Teignl		the lower western slopes of Hamel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021394
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure south west of Hingston Rocks, Moreton	nhampstead, Teignb	ridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002496
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles on Hedge Down, Widecombe in the M	loor, Teignbridge	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002620
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two cairns on Cator Common, Widecombe in the	e Moor, Teignbridge	e
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1003297
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	A double stone hut circle and enclosure 280 metro	es south of Deadlak	te Foot, Dartmoor Forest, West Devo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011569
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Camp 325 yards (300 metres) south east of Archerton, Dartmoor Forest, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002636	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Coaxial fields, prehistoric settlement, two cairns ar metres south east of Stannon Tor, Dartmoor Fore	nd a stone alignmen st, West Devon	t in Little Stannon Newtake, 900	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1021339	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Medieval settlement 470 metres east of Hartyland,	Dartmoor Forest,	West Devon	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1021338	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Prehistoric enclosed settlement 740 metres north	west of Hartland T	or, Dartmoor Forest, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021335	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Hut circle and field system north west of Saddle Br	idge, Dartmoor Fo	rest / Holne, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002601	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Prestonbury Castle (hillfort), Drewsteignton, West	Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003861	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Chambered cairn 430 metres south of Buttern, Gio	dleigh, West Devor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021217	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOL	JTH WEST / DARTMOOR (NP)			
SITE NAME:	Chambered cairn 830 metres south of Buttern, Gio	dleigh, West Devor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021216	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Part of a coaxial field system, prehistoric settlemer	nts and cairns on Bu	ıttern Hill, Gidleigh, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021215	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle 380 metres north west of North (	Creaber, Gidleigh, \	West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021220	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle and field system 580 metres north west of North Creaber, forming part of a coaxial field system on Buttern Hill, Gidleigh, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021219	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle settlement and post-medieval shel metres east of the Thirlstone, Gidleigh, West Deve		th east of Hawthorn Clitter, 1030	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019981	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Two stone hut circles and field system, 590 metres Buttern Hill, Gidleigh, West Devon	s south of Buttern,	forming part of a coaxial field system on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021218	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Enclosure, two stone hut circles and an alignment of Tor, Lands common to the Parishes of Bridestowe			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007648	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Hut circles and a length of enclosure wall, forming Nodden Gate, Lands common to the Parishes of B	part of a stone hut ridestowe and Sou	circle settlement 600 metres east orton / Lydford, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008638
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 530 metres ESE of Nodden Gate f Lydford, West Devon	orming an outlying	part of a stone hut circle settlement
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008639
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle 610 metres ESE of Nodden Gate f Lydford, West Devon	orming an outlying	part of a stone hut circle settlement
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Four round barrows on Wigford Down, Meavy, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002522
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Greenwell Girt socket stone 600 metres SSW of L	ovaton hamlet, Me	eavy, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008929
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hut circles south east of Brisworthy, Meavy, West	Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004585
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric enclosures on Dewerstone Hill, 500 m Devon	etres south east of	Dewerstone Cottage, Meavy, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020241
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Settlement on Wigford Down, Meavy, West Devo	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002550
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Settlement on Wigford Down south of Durance, N	leavy, West Devor	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002523
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Three hut circles north west of Cadworthy, Meavy	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003057
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two hut circles south of Catstor Down, Meavy, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002548
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	An enclosed stone hut circle settlement, three rou Tor, Peter Tavy, West Devon	nd cairns and a leng	gth of reave 650 metres WSW of Ger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008711
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairnfield and two stone hut circles 490 metres an Devon	d 550 metres soutl	n west of Cox Tor, Peter Tavy, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020004
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Coaxial field system and prehistoric settlement 410	) metres west of C	ox Tor, Peter Tavy, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020090
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but F not yet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial slow decay; no solution agreed but F not yet implemented. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Prehistoric settlement 610 metres south west of C	Cox Tor, Peter Tavy	, West Devon
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020002
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Stone hut circle and a short length of boundary wa settlement on the north east slope of Cox Tor, Pe	III forming part of a ter Tavy, West De	n unenclosed stone hut circle von
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011432
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairnfield 460 metres south east of Cox Tor, Pete	r Tavy / Whitchurc	h, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020005
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn east of Scout Hut, Sheepstor, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011993
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn south west of Lower Hartor Tor, Sheepstor	, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012293
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn with a cist north of Drizzlecombe stone align	nments, Sheepstor,	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010654
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Cairn with cist north of Gutter Tor, Sheepstor, W	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012473
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Enclosed stone hut settlement south west of Gutte	er Tor, Sheepstor, '	West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure north west of Gutter Tor, Sheepstor, V	est Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012032
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Part of Eylesbarrow reave, Sheepstor, West Devo	า	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011958
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric enclosed settlement 950 metres north Devon	east of Ditsworthy	Warren House, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021058
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Prehistoric settlement, three round cairns and a po	ost-medieval rabbit	warren at Legis Tor, Sheepstor, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019876
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Round cairn east of Whittenknowles Rocks, 960 m	netres ENE of Gutte	er Tor, Sheepstor, West Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021052
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two enclosures and a length of the Eylesbarrow w Sheepstor, West Devon	ratershed reave 800	) metres WSW of Eylesbarrow,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013474
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but F not yet implemented.

  Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial slow decay; no solution agreed but F not yet implemented. use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Unenclosed stone hut settlement south west of Gu	utter Tor, Sheepsto	r, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012239	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Warren at Sheeps Tor, 520 metres north of Chub	stone Cottage, She	epstor, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021391	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Agglomerate enclosure and 15 stone hut circles 56 Devon	00 metres west of C	Cawsand Beacon, South Tawton, West	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010791	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Agglomerate enclosure and ten stone hut circles 500 metres west of Cawsand Beacon, South Tawton, We Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010790	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	An agglomerated enclosed settlement 480 metres	west of Stoneyhurs	t, South Tawton, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017285	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	A prehistoric settlement complex, length of reave, Cosdon Hill, South Tawton / Dartmoor Forest, W		d stamping mill on the western slopes o	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015760	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Coaxial field system, associated and later remains a Gidleigh, West Devon	at Throwleigh Com	mon and Kennon Hill, Throwleigh /	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018916	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	ITH WEST / DARTMOOR (NP)				
SITE NAME:	A length of the Great Western Reave, a prehistori Walkhampton Common, Walkhampton, West De	ic settlement, three von	cairns and two field systems on		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019589		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	An enclosed stone hut circle settlement and later to, Walkhampton, West Devon	tin working earthwo	orks, 540 metres south east of Down		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009088		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	An enclosure, attached stone hut circle and length West Devon	of reave 180 metre	es NNE of Leather Tor, Walkhampton,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011248		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	An enclosure containing one stone hut circle 460 i	metres west of Cro	ss Gate, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009091		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	An enclosure, six stone hut circles, a length of rear Leather Tor, Walkhampton, West Devon	ve and several pros	pecting pits 170 metres north east of		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011247		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		
SITE NAME:	Eleven stone hut circles, a length of boundary wall settlement on the north east slope of Sharpitor, W	Eleven stone hut circles, a length of boundary wall and a field system forming part of an unenclosed settlement on the north east slope of Sharpitor, Walkhampton, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007435		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Enclosure and stone hut circle 320 metres north e settlement, Walkhampton, West Devon	ast of Sharpitor for	ming part of a stone hut circle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007434
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Enclosure and stone hut circle 700 metres west of	Sharpitor, Walkhai	mpton, West Devon
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1019590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Medieval settlement on Peek Hill, 240 metres and West Devon	280 metres north e	east of Lowery Tor, Walkhampton,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020237
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Prehistoric coaxial field system and cairns, an histo around Peek Hill, Walkhampton, West Devon	ric enclosure and p	art of RAF Sharpitor, situated on and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020238
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Round cairn 340 metres ESE of Norsworthy Bridge	e, Walkhampton, V	Vest Devon
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1008651
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone alignment, two round cairns and a length of Sharpitor and Leeden Tor, Walkhampton, West D	Walkhampton Con evon	nmon reave lying in a valley between
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007433
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Stone hut circle 155 metres east of Sharpitor, Wal	khampton, West D	evon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007421
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

	Stand has sized 240 masses as subject Davis Tan V	A/allaha	- Davies	
SITE NAME:  DESIGNATION:	Stone hut circle 240 metres south of Down Tor, V	Valkhampton, Wes  LIST ENTRY NUMBER:		
DESIGNATION:  CONDITION:	Scheduled Monument  Generally satisfactory but with significant localised	TREND:	1008641  Declining	
	problems		Ü	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle 315 metres north east of Sharpito Walkhampton, West Devon	or forming part of a	stone hut circle settlement,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007436	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle 350 metres north east of Sharpito Walkhampton, West Devon	Stone hut circle 350 metres north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007437	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle 370 metres north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007438	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle settlement 250 metres east of Cu	ckoo Rock, Walkha	mpton, West Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021057	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Stone hut circle settlement, irregular aggregate fiel medieval field system 700 metres SSW of Black To	d system, two long or, Walkhampton, V	houses and a medieval and post- Vest Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011170	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Tinworks and other archaeological remains in the Tor, Walkhampton, West Devon	Meavy valley at Star	nlake, Black Tor, Hart Tor and Cramb	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020129	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Two stone hut circles 570 metres south west of Down Tor, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two stone hut circles, a reave, round cairn and sho	elter south east of S	Sharpitor, Walkhampton, West Devor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011167
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Unenclosed stone hut circle settlement 370 metres south west of Routrundle, Walkhampton, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019565
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Enclosure and stone hut circle 770 metres south of Cox Tor, Whitchurch, West Devon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Eluvial tin streamworks and prehistoric coaxial field Whitchurch Common, Whitchurch / Peter Tavy / S	d system together v Sampford Spiney, V	with other archaeological remains on Vest Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020089
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Andy Crabb 01626 832093

# EAST DEVON

© Historic England



SITE NAME:	Poltimore House, Poltimore
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1098310

C16 country house with later additions. Acquired by a trust with funding from Historic England and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken 2007 with grant-aid from the Architectural Heritage Fund and Historic England. Historic England is offering technical advice to the trust to help find a repair solution for the house, but as of 2018 a comprehensive plan is still required.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Stable block at Bishop's Court, Clyst St Mary, Sowton
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Private

1333998

Long early C16 range of stables attached to Bishop's Court tithe barn. Site is not in use. Historic England funded a feasibility study, which was completed in 2011.

Large mid-C14 barn with arch-braced base-cruck roof of seven bays, and long early C16 range of stables. The site is unused with a temporary corrugated roof. The owners undertook a Historic England grant-aided feasibility study into potential uses, completed 2011.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Tithe barn at Bishop's Court, Sowton
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER:

Contact: Sarah Ball 0117 975 0666 1164637



Church of St Michael and All SITE NAME: Angels, Awliscombe DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1098097

Parish church. Largely late C15/early C16, mostly rebuilt in 1846 by Robert Medley Fulford. Mostly local flint with Beerstone dressings and a slate roof. Medieval and C19 features. Tower roof and valley gutter in a poor condition. Some other minor areas of concern.

Large parish church, mainly C19. Rainwater system needs a

complete overhaul. South-facing gables and valley gutters need work. Green mould in south transept at high level and the building is damp with poor stonework. The building has been subject to heritage crime.

Contact: Annie Evans 0117 975 1308

© Historic England



© Historic England

SITE INAME:	Street, Chardstock
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1333540

Church of St Androw Church

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of Holy Trinity, Dunkeswell
DESIGNATION:	Listed Place of Worship grade II, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1308999

Parish church, built on the site of Dunkeswell Abbey Church in 1842. Local stone and flint rubble with Hamstone dressings and detail and a slate roof. The roofs have had substantial leaks which have caused significant water ingress. This has damaged the internal plaster. The congregation reroofed the church in 2015, but considerable interior work is still required and glazing is also in poor condition. Discussions over the future of the church are underway with the Dunkeswell Abbey Preservation Trust.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



SITE NAME:	Church of St Michael, Honiton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1306112

Former parish church, now chapel-of-ease. Dates mainly from late C15. Interior destroyed by fire and rebuilt 1912. Metal corroding internally in arcaded capital heads. The church has been closed pending a decision on the future of the building.

Contact: Annie Evans 0117 975 1308

© Historic England



SITE NAME:	Church of St Paul, High Street, Honiton
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

Parish church. Completed 1838 by architect Charles Fowler. Romanesque style with apse. Seven bays with round-arched aisle and clerestorey windows. Galleries. Restored 1849. Stone and plaster falling internally. Beerstone hoodmoulds are cement on nails which is causing decay problems. Windows are in need of repair and there are cracks in the tower.

LIST ENTRY NUMBER: | | 16954 Contact: Annie Evans 0117 975 1308 © Historic England

SITE NAME:	Newenham Abbey, Axminster		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1011671
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Trinity Beacon, Axminster		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017950
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hawkesdown Camp and associated outwork, Axmouth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017775
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	The Axe Boat, 22 metres north of the Axmouth Road Bridge, Axmouth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1433819
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 400 metres north east of Common F	arm, Aylesbeare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOU			
SITE NAME:	Bowl barrow 210 metres north east of Starved Oak	Cross, Brampford	d Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010633
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow in Long Plantation, 610 metres north	east of Starved Oa	k Cross, Brampford Speke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010636
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Bowl barrow in Long Plantation, 680 metres north east of Starved Oak Cross, Brampford Speke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010634
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Bowl barrow 320 metres north east of Starved Oak	Cross, Brampford	d Speke / Upton Pyne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Dunkeswell Abbey, Dunkeswell		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs	LIST ENTRY NUMBER:	1009303 and 1098253
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows at Big Wood, 580 metres south Exmouth	west and 470 met	cres south of Moorland Cottage,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017949
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery on Broad Down, Farway /	Southleigh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017642
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / EAST DEVON		
SITE NAME:	A bowl barrow 370 metres WNW of Ring-in-the-Gittisham Hill, Gittisham	Mire, forming part	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A bowl barrow 460 metres NNW of Ring-in-the-N Gittisham Hill, Gittisham	Mire, forming part o	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014248
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A bowl barrow 500 metres WNW of Ring-in-the- Gittisham Hill, Gittisham	Mire, forming part	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014250
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A bowl barrow 570 metres NNE of Putts Corner, Hill, Gittisham	forming part of a r	ound barrow cemetery on Gittisham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014254
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A cairn 450 metres WNW of Putts Corner, formi Gittisham	ng part of a round l	barrow cemetery on Gittisham Hill,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014255
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A ring cairn and bowl barrow 54 metres NNE of F Gittisham Hill, Gittisham	Putts Corner, formi	ng part of a round barrow cemetery o
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014253
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	A bowl barrow 420 metres NNW of Ring-in-the-I Gittisham Hill, Gittisham / Honiton	Mire, forming part o	of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows, 220 metres ESE of Putts Corr Hill, Gittisham / Sidmouth	ner, forming part of	a round barrow cemetery on Gittishar
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Membury Castle, Membury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017951
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cursus, long mortuary enclosure, ring ditch and o Barton, Nether Exe	ther associated crop	pmarks 700 metres east of Netherexe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows north of Green Lane, 430 met	res and 330 metres	west of Rewe Cross, Nether Exe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016565
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Belbury Castle, Ottery St. Mary		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017774
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	A bowl barrow 120 metres south west of Ring-in- Gittisham Hill, Sidmouth	the-Mire, forming p	art of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014246
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Stockland Great Castle, Stockland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017952
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 470 metres east of Fortescu	e, Stoke Canon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016564
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Roman villa 300 yards (270 metres) SSW o	of Holcombe Farm, Uplyme	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002558
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 metres NNE of Starved	Oak Cross, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010638
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 300 metres SSE of Stevensto	one Farm, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015973
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 350 metres NNE of Starved	Oak Cross, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010639
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 450 metres SSE of Stevensto	one Farm, Upton Pyne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015974
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclosure 330 yards (300 metr	es) south west of Three Ho	orse Shoes Inn, Upton Pyne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002645
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Two bowl barrows, 350 metres south of Stevensto	one Farm, Upton Py	vne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010631
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Castle Hill, Widworthy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017477
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Woodbury Castle, Woodbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003862
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
with all their	SITE NAME: Bicton, Bicton / Colaton Raleigh	C18 and C19 co	untry house estate developed from ea



DESIGNATION:

Registered Park and Garden grade I, 19 LBs, SM

CONDITION:

Generally unsatisfactory with major localised problems

VULNERABILITY:

High

TREND:

Stable

/ East Budleigh

C18 and C19 country house estate developed from earlier manor. Large park, important gardens and arboretum. Registered park in three main ownerships. The core of the site, including the principal house, has been developed in the post-war era as a land-based college. Continuous pressure for development as the college has expanded has tended to erode the integrity of the designed landscape. The absence of a masterplan to guide and inform development remains a major cause for concern.

© James Carter

TREND: Stable

NEW ENTRY?: No

OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1000338

Contact: Jo McAllister 0117 975 0696

#### **EXETER**



© Historic England

SITE NAME:	Church of St Thomas the Apostle, Cowick Street, Exeter
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1169954

Church largely rebuilt in 1657. The west tower, south aisle and east end of north aisle are C17. Due to poor original design and lack of maintenance, roofs were in poor condition, rainwater goods failed and water penetrated parapet walls and gutters damaging the structure and decorative detail. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship funded a first phase of repairs (2013). The Heritage Lottery Fund Grants for Places of Worship funded additional phases (2015 and 2017). Further work to the aisle roof and interior of the body of the church is still needed.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary Steps, West Street, Exeter
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Religious organisation

1224263

C15 fabric. Restored 1868-72 by Edward Ashworth. Chancel re-ordered 1966 by Lawrence King. Nave, chancel, south west tower, south aisle and chapel, north west vestry. The church is very compact, which reflects its constricted site just within the walls of medieval Exeter. Slate roofs. Red Heavitree stone in large blocks with limestone dressings. A Heritage Lottery Fund Grant for Places of Worship funded the repair of the tower, completed in early 2018. There are cracks in the south east corner and the aisle roof structure and covering are poor. A further phase of work will be needed.

Contact: Sarah Ball 0117 975 0666

## PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Exeter city walls		
DESIGNATION:	Scheduled Monument, 2 RPGs, 4 CAs	LIST ENTRY NUMBER:	1003858
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

#### EXMOOR (NP)



Church of St Brendan, Church Hill, Brendon, North Devon

DESIGNATION: Listed Place of Worship grade II

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1289343

Parish church. Nave, chancel and south porch of 1738, tower rebuilt 1828; the whole restored and north aisle, north transept and vestry added in 1873. Dressed and roughly dressed stone with some brick dressings to vestry, the C19 work snecked with ashlar dressings. There are problems with the foundation beams and dampness in the tower. The gutters and drainage need repair and the external walls need repointing.

Contact: Annie Evans 0117 975 1308

© Historic England



Church of St Martin, Martinhoe, North Devon

DESIGNATION: Listed Place of Worship grade II\*

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1106778

Small parish church dating from C13 with later additions. Stone rubble, tower roughly coursed, with ashlar dressings and slate roofs. Some slipped slates, cracked cement, ground gutter and rainwater goods in bad condition. Cement pointing round tower arch, blistering paint on north aisle and south wall of chancel.

Contact: Annie Evans 0117 975 1308

© Historic England

SITE NAME:	Badgworthy deserted medieval village, Doone's I	Houses, Brendon, No	rth Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003886
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows on Cheriton Ridge, Brendo	n, North Devon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002583
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork defences of Countisbury Castle prom Devon	ontory fort (Wind H	ill), Lynton and Lynmouth, North
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020807
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

	TI WEST / EXTIGOR (NI ) / TIID BETON		
SITE NAME:	Remains of leat serving former hydro-electric gene metres east of Oxen Tor, Lynton and Lynmouth, N	rating station, on th Iorth Devon	ne south bank of the East Lyn River, 210
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020808
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	Yes
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Standing stones on eastern edge of Furzehill Comn	non, Lynton and Ly	nmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003300
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows and cairn cemetery, Ilkerton F	Ridge, Lynton and L	ynmouth, North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002566
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two round barrows near Warcombe Water, Lynto	on and Lynmouth, I	North Devon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003299
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

#### MID DEVON

© Historic England

© Historic England



SITE NAME: The Manor House Hotel, 2, Fore Street, Cullompton DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1105901

Hotel in partial use, formerly early C17 merchant's house. Concerns regarding the structural stability and public safety led Mid Devon District Council to serve a repairs notice. Whilst most of the external items of work specified in the notice were complied with in 2015-16, some reinstatement of finishes internally remains outstanding. Subsequently, concerns have arisen regarding the stability of the ornate shell hood porch and the hanging sign on the main facade and the Council is considering (as of spring 2018) serving an additional repairs notice to secure these areas.

Contact: Jenny Chesher 0117 975 0686

Prescott Baptist Chapel, Culmstock DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1147714

Simple C18 church in an isolated rural location. There are two other Baptist churches within a five mile radius which are closer to centres of population. Its physical problems are putting historic window fabric at risk, and could rapidly escalate into more serious repair problems if not remedied. The chapel has been sold and is no longer in use as a place of worship. Historic England has had discussions with the owner but work is required.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

viigiii, vviiiaiid	SITE NAME:	Parish Church of St Mary the Virgin, Willand
--------------------	------------	---

DESIGNATION: Listed Place of Worship grade I,

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1306617

Church of C15 with C16 north aisle and some window tracery renewed in the C19. The fabric of the church is generally well maintained, but the tower suffers from damp problems, the roof and roof structure are in poor condition, and there are problems with the drainage. Historic England understands that a scheme of repair is currently under consideration and the parish is actively fundraising.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Roman fort 300 metres north east of Cudmore Fa	rm, Bampton / Clay	rhanger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011251
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	A henge, two barrows, two ring ditches, two enclo	osures and part of a	linear feature 420 metres north west
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015472
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 80 metres south west of Hampson C	Cottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 140 metres south east of Burston Cr	ross, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015471
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Bowl barrow 220 metres south west of Hampson	Cottage, Bow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015474
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two bowl barrows 180 metres south west of Ham	npson Cottage, Bow	<b>V</b>
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015475
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

Self-Garder Field Media	SITE NAME:	Two bowl barrows 250 metres north of Natson Fa	rm, Bow	
Remotive Veneration Arable ploughing New Private Contract: Andy Crabb 01626 832093  Streamed Canonsielph Abbey, Burlescombe Canonsielph Canons	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015476
Private Canonsleigh Abbey, Burlescombe Schedulad Monument, LB grade II, CA IST MINTERNAMER, 1003830 Generally unsatisfactory with major localised problems Private, multiple owners COMMACTIVE Private Private CoMMACTIVE Private COMM	CONDITION:	Extensive significant problems	TREND:	Declining
Canonsleigh Abbey, Burlescombe  Scheduled Monument, I.B grade II. CA UST ENTRY NUPRER 1003830  CONGRITION Generally unsatisfactory with major localised problems  RENCONLYULNEANBUTY: Other NEW ENTRY: No CONTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: Other NEW ENTRY: No CONTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: Other NIBOME Castle, Coldridge  SCHEDULED Scheduled Monument IST ENTRY NUPREM 1016227  CONTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: Plant growth NEW ENTRY: Yes  SCHEDULED Problems  RENCONLYULNEANBUTY: Plant growth NEW ENTRY: Yes  SCHEDULED Problems  RENCONLYULNEANBUTY: Plant growth Scheduled Monument USI ENTRY NUPREM 1003826  Generally satisfactory but with significant localised problems  SCHEDULED Problems  RENCONLYULNEANBUTY: Plant growth NEW ENTRY: NUPREM 1003826  Generally satisfactory but with significant localised problems  RENCONLYULNEANBUTY: Plant growth NEW ENTRY: NO Declining  RENCONLYULNEANBUTY: Plant growth NEW ENTRY: NO NO NOTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: Plant growth USIS ENTRY NURREN NO NOTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: Declining  RENCONLYULNEANBUTY: Other NEW ENTRY NURREN NO NOTACT: Andy Crabb 01626 832093  RENCONLYULNEANBUTY: NO Roman forts and two Roman camps at St Andrew's Hill, Cullompton  SCHEDULED Problems  RENCONLYULNEANBUTY: NO Roman forts and two Roman camps at St Andrew's Hill, Cullompton  SCHEDULED Problems  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  SCHEDULED Problems  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  SCHEDULED Problems  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  SCHEDULED Problems  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  Declining  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  Declining  RENCONLYULNEANBUTY: NO ROMAN forts and two Roman camps at St Andrew's Hill, Cullompton  Declini	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument, LB grade II, CA UST ENTRY NUMBER 1003830  CONDITION: Generally unsatisfactory with major localised problems  Private, multiple owners  CONTACT: Andy Crabb 01626 832093  AND CRABTITIES  Private, multiple owners  CONTACT: Andy Crabb 01626 832093  AND CRABTITIES  Millsome Castle, Coldridge  WILLIAM Scheduled Monument  CONCINION: Generally unsatisfactory with major localised problems  REMINION WAS INSPERIOR Scheduled Monument  CONCINION: Private  CONTACT: Andy Crabb 01626 832093  TECHNIC  Private  CONTACT: Andy Crabb 01626 832093  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC  TECHNIC  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC  TECHNIC  TECHNIC  TECHNIC  CONTACT: Andy Crabb 01626 832093  TECHNIC	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
Generally unsatisfactory with major localised problems  Other  Other  NEW ENTRY:  Other  NEW ENTRY:  No  OWNER ITTPE  Millsome Castle, Coldridge  SESCRATION  Scheduled Monument  Generally unsatisfactory with major localised problems  Scheduled Monument  Generally unsatisfactory with major localised problems  Private  Generally unsatisfactory with major localised problems  REMODIAL UNINEASELITY:  Plant growth  Private  CONTACT:  Andy Crabb 01626 832093  AND CRABBILITY:  Private  Private  CONTACT:  Andy Crabb 01626 832093  AND CRABBILITY:  Private  CONTACT:  AND Crabb 01626 832093  AND CRABBILITY:  No  CONTACT:  AND CRABBILITY:  No	SITE NAME:	Canonsleigh Abbey, Burlescombe		
problems Other New STIRTS No Andy Crabb 01626 832093  Andy Crabb 01626	DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003830
Private, multiple owners  Millsome Castle, Coldridge  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Plant growth  Private  Posbury camp, Castle Down, Crediton Hamlets  Scheduled Monument  Scheduled Monument  Posbury camp, Castle Down, Crediton Hamlets  Scheduled Monument	CONDITION:		TREND:	Unknown
Millsome Castle, Coldridge  DESCRATIONE  Scheduled Monument  Generally unsatisfactory with major localised problems  PREACTION Private  CONTRET:  Private  Posbury camp, Castle Down, Crediton Hamlets  DESCRATIONE  Scheduled Monument  Scheduled Monument  Generally satisfactory but with significant localised problems  CONDITION  Generally satisfactory but with significant localised problems  CONTRET:  Private  CONTRET:  Andy Crabb 01626 832093  AND CRABBULTY:  Private  CONTRET:  Andy Crabb 01626 832093  AND CRABBULTY:  No  CONTRET:  Andy Crabb 01626 832093  AND CRABBULTY:  No  CONTRET:  And CRABBULTY:  No  CONTRET:  AND CRABBU	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
Scheduled Monument LEST ENTRY NUMBER: 1016227  CONDITION: Generally unsatisfactory with major localised problems  CONDITION: Private CONTACT: Andy Crabb 01626 832093  AND CREATIVE PRIVATE PRIVATE CONTACT: AND CRABBE PRIVATE P	OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
Generally unsatisfactory with major localised problems  Generally unsatisfactory with major localised problems  RINCHAL VULNERABILITY: Plant growth  Private Private CONTACT: Andy Crabb 01626 832093  RINCHANTE: Posbury camp, Castle Down, Crediton Hamlets  RESIGNATION: Scheduled Monument  Generally satisfactory but with significant localised problems  RINCHAL VULNERABILITY: Plant growth New ENTRY: No  CONTACT: Andy Crabb 01626 832093  RINCHAL VULNERABILITY: Plant growth New ENTRY: No  CONTACT: Andy Crabb 01626 832093  RINCHAL VULNERABILITY: Private CONTACT: Andy Crabb 01626 832093  RINCHAL VULNERABILITY: Other New ENTRY: No  CONTACT: Andy Crabb 01626 832093  RINCHAL VULNERABILITY: Arable ploughing New ENTRY: No  CONTACT: Andy Crabb 01626 832093  RINCHAL VULNERABILITY: Arable ploughing New ENTRY: No  CONTACT: Andy Crabb 01626 832093  RITT NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SEGMANTION: Scheduled Monument  LET ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  RINCHAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  RITT NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SEGMANTION: Scheduled Monument  LET ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  RINCHAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  RITT NAME: Three bowl barrows 250 metres north west of Putson Cross, Tiverton  SEGMANTION: Scheduled Monument  LET ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems  RINCHAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  RITT NAME: RITT NUMBER: 1017132  CONDITION: Extensive significant problems  RINCHAL VULNERABILITY: Arable ploughing  RINCHAL VULNERABILITY: Arable ploughing  RI	SITE NAME:	Millsome Castle, Coldridge		
Problems  Problems  Private Pr	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016227
Private CONTACT: Andy Crabb 01626 832093  STET NAME: Posbury camp, Castle Down, Crediton Hamlets  Scheduled Monument  Generally satisfactory but with significant localised problems  SERICHATION: Scheduled Monument  CONDITION: Generally satisfactory but with significant localised problems  SERICHATION: NEWENTRY: No  DESCRIPTION: Private  CONTACT: Andy Crabb 01626 832093  STE NAME: Romano-British villa, Downes, near Crediton, Crediton Hamlets  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002668  CONDITION: Extensive significant problems  TREND: Declining  CONDITION: Development  Private  Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  LIST ENTRY NUMBER: 1019543  TENDE: Declining  RENCIPAL VULNERABILITY: No  CONDITION: Extensive significant problems  TREND: Declining  RENCIPAL VULNERABILITY: No  CONDITION: Extensive significant problems  TREND: Declining  RENCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  TREND: Declining  RENCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  TREND: Declining  RENCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STE NAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  SESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems  TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: NUMBER: 1017132	CONDITION:		TREND:	Declining
Posbury camp, Castle Down, Crediton Hamlets  Scheduled Monument  Generally satisfactory but with significant localised problems  Plant growth  NEW ENTRY:  Plant growth  NEW ENTRY:  Private  Romano-British villa, Downes, near Crediton, Crediton Hamlets  Scheduled Monument  LIST ENTRY NUMBER:  Romano-British villa, Downes, near Crediton, Crediton Hamlets  Scheduled Monument  LIST ENTRY NUMBER:  CONDITION:  Extensive significant problems  TREND:  Private  Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  LIST ENTRY NUMBER:  Town Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  LIST ENTRY NUMBER:  Town Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  LIST ENTRY NUMBER:  Town Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  LIST ENTRY NUMBER:  Town Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Extensive significant problems  TREND:  Declining  RINGERAL VULNERABUTY:  Arable ploughing  NEW ENTRY:  No  DOWNER TYPE:  Mixed, multiple owners  CONTACT:  Andy Crabb 01626 832093  Andy Crabb 01626 832093  TREND:  Declining  RINGERAL VULNERABUTY:  Other  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SISSIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  1017134  CONTACT:  Andy Crabb 01626 832093  And Crabb 01626 832093  TREND:  Declining  RINGERAL VULNERABUTY:  Other  Private  Other  Other  Scheduled Monument  LIST ENTRY NUMBER:  1017134  CONTACT:  Andy Crabb 01626 832093  And Crabb 01626 832093  TREND:  Declining  RINGERAL VULNERABUTY:  No  DOWNER TYPE:  Private  Other  Other  Scheduled Monument  LIST ENTRY NUMBER:  1017132  Declining  RINGERAL VULNERABUTY:  No  Declining  RINGERAL VULNERABUTY:  Arable ploughing  NEW ENTRY:  No  Declining  RINGERAL VULNERABUTY:  Declining  RINGERAL VULNERABUTY:  No  Declining  RINGERAL VULNERABUTY:  Declining  RINGERAL VULNERABUTY:  No  Declining  RINGERAL VULNERABUTY:  No  Declining  RINGERAL VULNERAB	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
Scheduled Monument UST ENTRY NUMBER 1003826  CONDITION: Generally satisfactory but with significant localised problems  Plant growth NEW ENTRY!: No  CONTACT: Andy Crabb 01626 832093  STEINAME: Romano-British villa, Downes, near Crediton, Crediton  Scheduled Monument UST ENTRY NUMBER: 1002668  CONTACT: Declining  RINCIPAL VULNERABILITY: Determined Supplied Not Scheduled Monument  Scheduled Monument UST ENTRY NUMBER: 1002668  CONTACT: Andy Crabb 01626 832093  STEINAME: NEW ENTRY: No  CONTACT: Andy Crabb 01626 832093  STEINAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019543  CONTACT: Andy Crabb 01626 832093  STEINAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1019543  CONTACT: Andy Crabb 01626 832093  STEINAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017134  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  TRIND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STEINAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems  TRIND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STEINAME: Bowl barrows 260 metres north west of Putson Cross, Tiverton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017132  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017132  Declining  RINCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  STEINAME: Bowl barrows 260 metres north west of Putson Cross, Tiverton  SESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017132  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1017132  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 101	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
Generally satisfactory but with significant localised problems  Generally satisfactory but with significant localised problems  RINGUPAL WUNDERABILITY: Plant growth NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  ITE NAME: Romano-British villa, Downes, near Crediton, Crediton Hamlets  DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1002668  DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1002668  DECLINING  RINGUPAL WUNDERABILITY: Other NEW ENTRY!: No  DOWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  ITE NAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1019543  DECLINING  Extensive significant problems TREND: Declining  RINGUPAL WUNDERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  ITE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1017134  DESIGNATION: Scheduled Monument USTENTRY NUMBER: 1017132	SITE NAME:	Posbury camp, Castle Down, Crediton Hamlets		
Problems  RINGIPAL VULNERABILITY: Plant growth  Private  ROMAND-British villa, Downes, near Crediton, Crediton Hamlets  DESIGNATION: Scheduled Monument  USTENTRY NUMBER: 1002668  CONDITION: Extensive significant problems  TREND: Declining  RINGIPAL VULNERABILITY: No  DAVINER TYPE: Private  Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  USTENTRY NUMBER: 1019543  TREND: Declining  RINGIPAL VULNERABILITY: Analy Crabb 01626 832093  ITE NAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Scheduled Monument  USTENTRY NUMBER: 1019543  Extensive significant problems  TREND: Declining  RINGIPAL VULNERABILITY: Analy Crabb 01626 832093  ITE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  USTENTRY NUMBER: 1017134  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  Scheduled Monument  USTENTRY NUMBER: 1017134  Extensive significant problems  TREND: Declining  RINCIPAL VULNERABILITY: No  DOWNER TYPE: Private  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  USTENTRY NUMBER: 1017132  DOWNER TYPE: Private  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  USTENTRY NUMBER: 1017132  DOWNER TYPE: Declining  RINCIPAL VULNERABILITY: No  Declining  RINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  USTENTRY NUMBER: 1017132  DECLINING  RINCIPAL VULNERABILITY: No  Declining  RINCIPAL VULNER	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003826
Private Romano-British villa, Downes, near Crediton, Creditor  Romano-British villa, Downes, near Crediton, Creditor  Romano-British villa, Downes, near Crediton, Creditor  Resignation: Scheduled Monument List entry number: 1002668  Condition: Extensive significant problems TREND: Declining  Reincipal vulnerability: Other New Entry: No  Contact: Andy Crabb 01626 832093  TRENDE: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  Sesignation: Scheduled Monument List entry number: 1019543  Condition: Extensive significant problems TREND: Declining  Reincipal vulnerability: Arable ploughing New Entry: No  Deviner type: Mixed, multiple owners Contact: Andy Crabb 01626 832093  The Name: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  Sesignation: Scheduled Monument List entry number: 1017134  Condition: Extensive significant problems TREND: Declining  Reincipal vulnerability: Other New Entry: No  Declining  Reincipal vulnerability: No	CONDITION:		TREND:	Declining
ROMAINO-British villa, Downes, near Crediton, Crediton Hamlets DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002668  CONDITION: Extensive significant problems TREND: Declining RINIOPAL VULNERABILITY: Other NEW ENTRY: No DOWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  SITE NAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019543  CONDITION: Extensive significant problems TREND: Declining RINIOPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  SITE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: No DOWNER TYPE: No DOWNER TYPE: No DOWNER TYPE: No DOWNER TYPE: Private Bowl barrow 260 metres north west of Putson Cross, Tiverton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Other NEW ENTRY: No DOWNER TYPE: Bowl barrow 260 metres north west of Putson Cross, Tiverton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  RENDERABILITY: Arable ploughing NEW ENTRY: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems REND: Declining  RENDERABILITY: Arable ploughing NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1002668  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Other  Private  Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019543  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Anable ploughing NEW ENTRY): No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No  DEVINER TYPE: Mixed, multiple owners CONTACT: Analy Crabb 01626 832093  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No  DEVENTED Private  CONTACT: Analy Crabb 01626 832093  TREND: Declining  PRINCIPAL VULNERABILITY: No  DEVENTED PRIVATE  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Number: 1017132  CONDITION: Extensive significant problems  TREND: Declining  RIPLE NUMBER: 1017132  CONDITION: Extensive significant problems  TREND: Declining  RIPLE NUMBER: 1017132  CONDITION: Extensive significant problems  TREND: Declining  RIPLE NUMBER: 1017132  CONDITION: Extensive significant problems  TREND: Declining  RIPLE NUMBER: 1017132  CONDITION: Extensive significant problems  TREND: Declining	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
Extensive significant problems  TREND: Declining  Other  Other  NEW ENTRY?: No  DWNER TYPE: Private  CONTACT: Andy Crabb 01626 832093  EXTENAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  DESIGNATION: Scheduled Monument  Extensive significant problems  RENCIPAL VULNERABILITY: Arable ploughing  Private  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Andrew Discontinuous Contact: Andrew Crabb 01626 832093  EXTENAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DWNER TYPE: Private  CONTACT: Andrew Crabb 01626 832093  EXTENAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  EXTENAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  EXTENAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  EXTEND: Declining  PRINCIPAL VULNERABILITY: Declining  EXTEND: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  EXTEND: Declining  PRINCIPAL VULNERABILITY: No  DECLINING  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  EXTEND: Declining  PRINCIPAL VULNERABILITY: No	SITE NAME:	Romano-British villa, Downes, near Crediton, Cred	liton Hamlets	
PRINCIPAL VULNERABILITY: Other NEW ENTRYP: No  CONTACT: Andy Crabb 01626 832093  Andy Crabb 0162	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002668
Private CONTACT: Andy Crabb 01626 832093  And Crabb 01626 832093  Arable ploughing New Entry: No  Designation: Scheduled Monument List entry number: 1019543  CONDITION: Extensive significant problems TREND: Declining  Arable ploughing New Entry: Andy Crabb 01626 832093  And Crabb 01626 832093	CONDITION:	Extensive significant problems	TREND:	Declining
ESTE NAME: Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DWNER TYPE: Private  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Declining  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No	PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
Scheduled Monument  Extensive significant problems  TREND: Declining  NEW ENTRY?: No  Wixed, multiple owners  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  Scheduled Monument  Extensive significant problems  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  Scheduled Monument  Extensive significant problems  TREND: Declining  Private  Declining  New Entry?: No  CONTACT: Andy Crabb 01626 832093  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Andy Crabb 01626 832093  TREND: Declining  Declining  TREND: Declining	OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
Extensive significant problems  TREND: Declining  NEW ENTRYP: No  Declining  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  RINCIPAL VULNERABILITY: No  Declining  TREND: Declining  RINCIPAL VULNERABILITY: No  Declining  RINCIPAL VULNERABILITY: Other  REVENTRYPE: Private  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017134  CONTACT: Andy Crabb 01626 832093  ITE NAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017132  EXENDITION: Extensive significant problems  TREND: Declining  RINCIPAL VULNERABILITY: No	ITE NAME:	Two Roman forts and two Roman camps at St And	lrew's Hill, Cullomp	oton
Arable ploughing New Entry?: No DWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093  ATE NAME: Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Other NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  AND CRABBO OF PRIVATE  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNIATION:			
Mixed, multiple owners  CONTACT: Andy Crabb 01626 832093  Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  RINCIPAL VULNERABILITY: Other  New ENTRYPE: No  DEVINER TYPE: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1017132  CONTACT: Andy Crabb 01626 832093  TREND: Declining  Declining  NEW ENTRY: NO  Declining  NEW ENTRY: No  Declining  NEW ENTRY: No  No	DESIGNATION.	Scheduled Monument	LIST ENTRY NUMBER:	1019543
Three bowl barrows 250 metres south east of Gibbet Moor Cross, Templeton  Scheduled Monument  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Other  New ENTRY?:  Private  CONTACT:  Andy Crabb 01626 832093  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 017134  CONTACT:  Andy Crabb 01626 832093  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 017132  CONDITION:  Extensive significant problems  TREND:  Declining  Declining  NEW ENTRY?:  No				
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017134  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Other  Private CONTACT: No  CONTACT: Andy Crabb 01626 832093  CHE NAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: No  NEW ENTRY): No	CONDITION:	Extensive significant problems	TREND:	Declining
Extensive significant problems  TREND: Declining  Other  Other  New Entry?: No  CONTACT: Andy Crabb 01626 832093  ITE NAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  NEW ENTRY?: No  No  New Entry?: No	CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing	TREND: NEW ENTRY?:	Declining No
PRINCIPAL VULNERABILITY: Other NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Andy Crabb 01626 832093  BITE NAME: Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION: PRINCIPAL VULNERABILITY:  DWNER TYPE:	Extensive significant problems Arable ploughing Mixed, multiple owners	TREND:  NEW ENTRY?:  CONTACT:	Declining No Andy Crabb 01626 832093
Private  Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION:  Scheduled Monument  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  CONTACT:  Andy Crabb 01626 832093	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gibb	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, Te	Declining No Andy Crabb 01626 832093  empleton
Bowl barrow 260 metres north west of Putson Cross, Tiverton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, Te	Declining No Andy Crabb 01626 832093  empleton 1017134
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017132  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument  Extensive significant problems	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, To  LIST ENTRY NUMBER:  TREND:	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument  Extensive significant problems  Other	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, Te  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining No
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gibb Scheduled Monument  Extensive significant problems  Other  Private	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, To  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining No
	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument  Extensive significant problems  Other  Private  Bowl barrow 260 metres north west of Putson Cree	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, To  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  Doss, Tiverton	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining No Andy Crabb 01626 832093
OWNER TYPE: Mixed, multiple owners CONTACT: Andy Crabb 01626 832093	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument  Extensive significant problems  Other  Private  Bowl barrow 260 metres north west of Putson Cree Scheduled Monument	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, To  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  Doss, Tiverton  LIST ENTRY NUMBER:	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining No Andy Crabb 01626 832093
	CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Extensive significant problems  Arable ploughing  Mixed, multiple owners  Three bowl barrows 250 metres south east of Gible Scheduled Monument  Extensive significant problems  Other  Private  Bowl barrow 260 metres north west of Putson Cresscheduled Monument  Extensive significant problems	TREND:  NEW ENTRY?:  CONTACT:  Det Moor Cross, To  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  DSS, Tiverton  LIST ENTRY NUMBER:  TREND:	Declining No Andy Crabb 01626 832093  empleton 1017134 Declining No Andy Crabb 01626 832093

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Eggesford Castle, 640 metres north east of Eggesford House, Wembworthy			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016208	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Bowl barrow 130 metres north east of Bur	Bowl barrow 130 metres north east of Burston Cross, Zeal Monachorum		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015152	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093	
SITE NAME:	Bow			
DESIGNATION:	Conservation Area, 20 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	No significant change	
VULNERABILITY:	Medium	CONTACT:	Sue Warren (LPA) 01884 234264	
SITE NAME:	Cullompton			
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264	
SITE NAME:	Tiverton			
DESIGNATION:	Conservation Area, 194 LBs, 2 SMs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Low	CONTACT:	Sue Warren (LPA) 01884 234264	

#### **NORTH DEVON**



Hall House, Bishop's Tawton SITE NAME: DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1107730

Built c1846-50 by Philip Hardwick, with a rear range by RD Gould. The house lies within an estate, and there are several other listed structures within the vicinity. The main range is generally fair. The rear range is still in poor condition, though the roof is weathertight. The owners are very gradually addressing the repair issues.

Contact: Annie Evans 0117 975 1308

© Historic England Archive



© Historic England

SITE NAME:	Bunksland Farmhouse and attached outbuildings, East Anstey
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1106670

A remarkably unspoilt medieval farmhouse, multiphased, with a surviving CI5 roof structure of some architectural detail and an interesting plan form. The property has been vacant since 2009 and has suffered from deterioration at the external cob wall as well as the collapse of an internal cob partition and roof truss supporting the floor above. Ownership uncertainties are delaying a resolution. Historic England has arranged for our engineer to visit the site to advise on temporary stablisation and protection works. Further discussions are to be held with the estate.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England Archive


© Historic England

© Historic England

SITE NAME:	Broomham Farmhouse, King's Nympton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

Early C16 longhouse with later additions. The roof was rethatched with Historic England grant aid in 2013. Improvements have permitted the family to return to the house, and work is very gradually continuing, but further structural work is still required.

Contact: Annie Evans 0117 975 1308



SITE NAME: Church of St James, Arlington DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1106820

1152877

Parish church. Late C15 or early C16 tower with some C19 work. Set in the landscape of Arlington Court, which is owned by the National Trust. Options are being explored by the very small congregation, possibly in conjunction with the neighbouring National Trust. Blocked downpipes are causing significant damage to the interior and roofing repairs are also required. The congregation made an unsuccessful application to the Listed Places of Worship Roof Fund in 2016.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Michael, East Anstey
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325768

West tower and south porch CI5; nave and chancel rebuilt 1871 by Ashworth. Unrendered stone rubble with ashlar dressings. Slate roof with gables. Most of walls and all of tower pointed in cementicious mix. Widely open joints in stonework of tower. Decay and fracturing to the dressed stone of stringcourses and bell chamber windows. Interior of tower wet and stained with algae. The church was awarded a first round Heritage Lottery Fund Grant for Places of Worship in 2016 and repair work is underway, due to be completed late in 2018.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St John the Baptist, East Down	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1163326	

Parish church sited adjacent to the manor house. Surviving C13 fabric to tower, Ć15 south aisle and some C19 work. The congregation is steadily working through repairs. Roof repairs were completed under the Heritage Lottery Fund and Historic England Repair Grants for Places of Worship scheme in 2005. Tower is very damp and has structural issues with significant cracking. Condition of windows also remains poor.

Contact: Annie Evans 0117 975 1308

© Historic England



© Historic England

SITE NAME:	Parish Church of Holy Trinity, Church Road, Ilfracombe		
DESIGNATION:	Listed Place of Worship grade I, CA		
CONDITION:	Poor		
PRIORITY CATEGORY:	C (A)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1208207		

Large parish church. Early tower with church, enlarged in the 1320s and again in the C15. Problems with roof and gutters led to water penetration and subsequent damage of internal fabric. Congregation has been in discussions with Historic England and in 2017 was repairing the east end of the roofs with a Listed Places of Worship Roof Repairs Grant. The tower (with Norman stonework) and west end of the church, including windows with notable Kempe glass, remain in poor condition.

Contact: Annie Evans 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



(C)	Historic	Fngland

© Historic England

SITE NAME:	Church of St Michael, Marwood
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1107157

Parish church. C13 fabric to chancel with two lancets to north side and pointed south doorway. South transept with single lancet in east wall and unmoulded pointed arch into nave. Battered plinth in north aisle indicates former north transept and original cruciform plan. Cracked ridge tiles and missing slates. Rainwater goods need overhauling. Internal damp staining to walls. Bench ends with active insect infestation. Vegetation growth on stonework to tower, vestry chimney and north aisle wall. An application to the Listed Places of Worship Roof Repair Grant scheme in 2016 was unsuccessful.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St John, Satterleigh and Warkleigh
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1258818

Parish church, sited in a farmyard. Damp has caused deterioration of the fabric and significant works are needed. The east end of the south aisle has cracking and there is some structural movement in the fabric.

Contact: Annie Evans 0117 975 1308



Church of St Mary Magdalene, SITE NAME: The Churchyard, South Molton Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1317855

Large parish church mainly C15, restored in C19. The stonework has started to decay and the roofs are in bad condition. Water ingress to the interior is causing continuing damage. The church was been awarded a maximum Listed Places of Worship Roof Repairs Grant and during 2018 the south aisle, south transept and Lady Chapel roofs have been re-slated. Further funding is still required.

© Historic England

Contact: Annie Evans 0117 975 1308

SITE NAME:	Barnstaple Castle, Barnstaple		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1020922
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505



Church of St Bartholomew, Stoke Rivers		
Listed Place of Worship grade I		
Poor		
C (C)		
Religious organisation		
1107658		

Parish church. Mainly late C15 to early C16 but may be some earlier fabric. Some C18 work survives. Main restoration in 1880s and in 1905, but possibly some earlier restoration work of 1831. Stone rubble with stone dressings. Slate roofs with coped gabled ends. West tower, nave, chancel, south aisle and south porch. There has been work to the chancel south gutter but overhaul of other rainwater goods still needed. Poor drainage. Roofs reported to be in a poor condition. Tower is damp with vegetation growth and tower internal timbers are also reported to be poor.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Hillfort on Whitechapel Moors, 640 metres north east of Garliford Mill, Bishop's Nympton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016214
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOU	JTH WEST / NORTH DEVON		
SITE NAME:	Round barrow cemetery 210 metres south west o	f Hillcrest, Centery	Lane, Bittadon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019252
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrow cemetery 500 metres east of Little	Bray Cross, Bratto	n Fleming
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017137
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Wayside cross known as Eastacott Cross or the St	onen Hammer, Ch	ittlehampton
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1013727
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 metres north east of Beacon Moor Cross, forming part of a round barrow cemetery, Chulmleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015153
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 330 metres east of Beacon Moor Cro	oss, forming part of	a round barrow cemetery, Chulmle
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015154
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Round barrow cemetery on West Burrow Moor, I	East Worlington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016215
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
ITE NAME:	Stone Row on Isley Marsh, Lower Yelland, Freming	gton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003847
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Castle Roborough, Loxhore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002543
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Hillfort 400 metres north west of Woodhouse, Qu	een's Nympton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015463
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 100 metres east of Catkill Cros	s, Rose Ash	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015145
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Camp south of Birch Ham Wood, Stoke Rivers		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002533
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 225 metres south east of Elworthy C	ross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016650
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 300 metres north west of Witheridge	Moor Cross (wes	t), Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016652
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 610 metres south east of Elworthy C	ross, Witheridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016651
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Dart Raffe Moor lying 550 metres	south west of Bro	adridge Farm, Witheridge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015150
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	llfracombe		
designation:	Conservation Area, 118 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
00110111	1 001		
VULNERABILITY:	High	CONTACT:	Collette Hall (LPA) 01271 388352

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

#### **SOUTH HAMS**



© Historic England

Deer Park wall at Berry Pomeroy Castle, Berry Pomeroy

DESIGNATION: Listed Building grade II\*

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: F (F)

OWNER TYPE: Private

1108572

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Medieval deer park wall, extended in the C16. Neglected, heavily overgrown with ivy and partially collapsed in places. The Estate has prepared a condition survey in order to understand and monitor mechanisms of decay and to prioritise repairs. A pilot repair scheme was undertaken in 2013/14 with funding from Natural England. This was extended in 2014/15 and a team from the estate continues to make repairs for a period every summer. There have been some further areas of collapse and as of 2018 significant work is still required to stabilise other sections, but progress is being made.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Week, Berry Pomeroy
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1108575

Small house reduced in size and now derelict. C16, date 1584 on interior plasterwork now removed to Totnes museum. Also barn at right angles. Stone rubble walls with gabled ends, new slate roof and concrete ring-beam replacing scantle roof. Originally L-shaped on plan but south wing replaced by an adjoining linhay. South east wall partly rebuilt in blockwork. No first floor, stair or glazing, wall footings concreted, ground level raised at north sides. Condition stable but vulnerable. Historic England is in discussion with owner and lessee regarding repair and reuse.

Contact: Annie Evans 0117 975 1308



© South Hams District Council

SITE NAME:	Yarde Farmhouse, Malborough
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1108479

Late C16 evolved manor house. The house, its detached kitchen and also the early C18 chamber block are now wind and weathertight externally. The greatest area of uncertainty remains the interior of the lodging range and the important painted hangings whose conservation and future display are not resolved.

Contact: Annie Evans 0117 975 1308



© Historic England Archive

SITE NAME:	39, The High Street, Totnes
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1236133

Fine C17 plasterwork and interior threatened by poor condition of roof and opening up of floor on the second floor. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Slipped slates and windows in very poor condition.

Contact: Annie Evans 0117 975 1308



© Historic England Archive

SITE NAME:	Fort Bovisand, Wembury
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1002584

Major C19 fort complex forming part of the ring of defences around Plymouth. Most recently used as a base for training divers, it is now disused. Most of the site and buildings are leased by a trust and a scheme was agreed in 2016 for an enabling development for mixed residential and heritage use. Heritage Lottery Fund grant for this scheme has been turned down, however, and the trust is now considering how it could take the project forward without substantial grant aid.

Contact: Simon Hickman 0117 975 0717

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

Garden wall, steps and gate piers south of Langdon Court Hotel, Langdon, Wembury

DESIGNATION: Listed Building grade II\*, RPG grade II

CONDITION: Fair

OCCUPANCY: N/A

PRIORITY CATEGORY: F (F)

Private

1169143

Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool. The present owner has instigated a programme of phased repair, which is partially completed and condition remains static as at May 2018.

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Pair of garden houses south of Langdon Court Hotel, Langdon Wembury
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Private

1108587

Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. Extensive repairs have been undertaken to the building exteriors and an application was made in 2014 for their use as ancillary accommodation to the hotel in the main house. That was withdrawn pending further discussions with the local planning authority and Historic England. A revised application has been made in April 2018 which is currently being considered.

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Watch House battery and ditch, Wembury
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Government or agency

Constructed 1904 but utilising an 1860s ditch system, with First and Second World War additions. The site was leased to a private company until 2009, and since then has been vacant and subject to vandalism. Recording has been put in hand but no options for repair/reuse have been agreed.



© Historic England

SITE NAME:	Church of St Mary, Berry Pomeroy
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108535

1002585

Parish church. Rebuilt in C15 restored in the late C17 and 1878-79. Tower has C13 or C14 west doorway. Stone rubble with freestone dressings and slate roofs, tower rendered. Nave and chancel in one. The church is generally very well maintained and a number of significant repairs have been undertaken. Despite this, the tower remains damp with problems with the render, and the main roofs also need work. The congregation applied in 2017 for grant aid from the Heritage Lottery Fund but was not successful.

Contact: Annie Evans 0117 975 1308

Contact: Annie Evans 0117 975 1308

		1000

© Historic England

SITE NAME:	Church of St Lawrence, Bigbury
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325078

A C14 and C15 church much rebuilt by Sedding in the C19. Nave, chancel, north aisle, south transept, south porch, west tower with spire. Though the congregation has done a lot of work including undertaking works to the rainwater goods there is still a notice in the church that the plaster is dangerous. Damp tower. Ringing chamber has little ventilation.

Contact: Annie Evans 0117 975 1308

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:



,		Street, Blackawton
6	DESIGNATION:	Listed Place of Worship grade I
g	CONDITION:	Poor
29	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Religious organisation
	LIST ENTRY NUMBER:	1108023

Church of St Michael, Main

Parish church. C14 chancel and possibly tower; nave and aisle rebuilt c later C15 or early C16. Restored in 1887, 1893, 1895 and 1898. Local shale rubble with granite and some red sandstone dressings slate roof. The church is generally well-maintained and the roofs are all in good condition. However the tower masonry is damp and friable. Steeplejacks have undertaken emergency tower repairs but it still needs further work.

Contact: Annie Evans 0117 975 1308

© Historic England



SITE NAME:	Church of St Mary, Charleton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108510

Parish church. C15 heavily restored in 1849-50. Slatestone rubble walls; windows largely of Caen stone, slate roofs. The fittings are all Victorian and the octagonal font, pulpit and desk are also of Caen stone. High level tower repointed. Rainwater goods rusting and undersized and failing to get the water away from the church resulting in cracking and staining to the interior. Internal decorations poor. The church is generally well maintained and slate roof repairs have been completed. However, significant repairs still need to be undertaken.

Contact: Annie Evans 0117 975 1308

© Historic England



SITE NAME:	Church of St Sylvester, Chivelstone
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108470

Parish church. C15 restored in late C19 or early C20. Slatestone rubble walls. Gabled slate roofs. Good collection of medieval joinery. Small, rural parish church with a number of problems which add up to a significant amount of work: roofs, rainwater goods, damp ingress and structural movement all need addressing. The congregation has made an application to the Heritage Lottery Fund in summer 2018 for work to address structural and waterproofing issues.

Contact: Annie Evans 0117 975 1308

Contact: Annie Evans 0117 975 1308

SITE NAME:	Baptist Church, Baptist Lane, Kingsbridge
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1107546

Previous problems with ivy are under control as of 2016. Stonework fair but the condition of the roof is still of some concern.

© Historic England

© Historic England



	-
	СО
1	PRI
<u>e</u>	OV
	LIST

SITE NAME: Church of St Edmund, Fore Street, Kingsbridge DESIGNATION: Listed Place of Worship grade I NDITION: Poor ORITY CATEGORY: C (C) VNFR TYPE Religious organisation TENTRY NUMBER: 1165559

Large parish church of cruciform plan with transepts, north and south aisles to nave, chancel aisles and two-storey south porch. The CI3 tower remains, church was rebuilt and dedicated 1414. Restored and extended 1849 and 1896. Internal decorations are in poor condition and have staining in numerous places. Staining below valley gutters that may be failing. Windows and stonework problems urgent. An application to the Listed Places of Worship Roof Repairs scheme in 2016 was unsuccessful.

Contact: Annie Evans 0117 975 1308

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Church of the Blessed Virgin Mary, Rattery
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1147626

Parish church. C13, enlarged in C15 by addition of aisles and enlargement of transepts. Restored probably c1860s. Roughcast stone with slate roofs. Internally the walls are entirely plastered with unique incised and painted decoration. This has been affected by previous high level roof leaks and more so from rising damp retained by hard cementitious external pointing which is causing significant salt damage internally. The parish has begun to plan a campaign of repair and to consider sources of funding.

Contact: Annie Evans 0117 975 1308

A LAIATA
I PA INTE

SITE NAME:	Church of St Paul, Staverton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1108524

Early C14 church, largely rebuilt in the C15, with north and south aisles, western tower and two-storey porch. Rainwater goods rusty but undergoing repair during 2017. Vestry roof poor. Cement render. Very damp at low level with damage to tile floors and evidence of beetle in pew platforms and white salts. Crack in cement render. In need of stonework repair and repointing.

Contact: Annie Evans 0117 975 1308



Church of St Michael, Strete
Listed Place of Worship grade II
Poor
C (C)
Religious organisation
1165589

Parish church in Perpendicular Gothic style built in 1836 with older tower. Cementitious render over local slate rubble. Single span Welsh slate roof over nave and aisles with gabled ends and eaves brackets to moulded cast-iron gutters. Very damp tower. High level water penetration with salts and damage to interior plaster and decorations.

Contact: Annie Evans 0117 975 1308



© Historic England

© Historic England

SITE NAME:	Church of St John, Totnes
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325376

A 1980s church within 1830s shell following fire. Five-bay nave built of coursed grey limestone, with shallow rectangular apse and western tower. The sides of the nave have tall windows divided by buttresses, their mullions and tracery replaced c 1980 with steel frames. Interior not inspected. Tower sprouting vegetation and rainwater goods in poor condition. Re-roofed within last 15 years but fibreglass windows deteriorating. The congregation has been offered a Heritage Lottery Fund Grant for Places of Worship and repairs are expected to start later in 2018.

Contact: Annie Evans 0117 975 1308

			1
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	M	V	2
			(i
		11/2	

© Historic England

SITE NAME:	Church of St Mary, High Street, Totnes
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1236065

Former priory church rebuilt 1430-60. Random Devonian rubble with red sandstone dressings, some pale limestone dressings and parapets, and sandstone tower. Tower stonework poor needing repointing and vegetation removal. North aisle parapet and stonework decaying. Ground gutters poor with north side broken. Rainwater goods need painting and vegetation removed. Internal damage to windows from rusty ferramenta (iron work) and damaged paint to north aisle east end on chancel south wall. Historic England has been in discussion with the church regarding proposals for repair and reordering.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# I PA ΝP RPG

**ABBREVIATIONS** 

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Church of St Peter, The Square, Ugborough
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1168309

Large parish church, dubbed 'The Cathedral of the South Hams'. The north aisle roof has become porous allowing significant water ingress, threatening the integrity of medieval carved roof bosses. The congregation has completed a phase of repair with a Heritage Lottery Fund Grant for Places of Worship but the church remains very damp and further works are still being planned.

Contact: Annie Evans 0117 975 1308

© Le Page Architects

SITE NAME:	Hilltop enclosure known as Maristow Camp, 240 r	metres east of Midd	le Park House, Bickleigh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019784
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Medieval holy well known as St Ann's Well, 120 metres south of Holwell Farm, Bigbury		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019315
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Iron Age hillfort known as Wasteberry Camp, medieval deer park and post-medieval warren, 800 metres north west of Lyneham House, Brixton / Yealmpton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020160
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two round barrows on Ridding Down, Cornwood	i	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002586
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Levelling	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hilltop enclosure and woodbanks in Chacegrove Wood, 540 metres north west of Dartington Hall, Dartington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020553
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hilltop enclosures in North Wood, 780 metres N	NW of Old Parson	age Farm, Dartington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020381
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Daniel Bashford 07824 103102

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Four bowl barrows at Bickleigh Brake 540 metres s barrow cemetery, Halwell and Moreleigh	south west of Bick	leign, forming part of a linear round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019238
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort and two bowl barrows at Halwell Camp, H	alwell and Morelei	gh
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	D-Day landing craft maintenance site on the River Kingswear	Dart immediately t	to the south of Lower Noss Point,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021076
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Gomerock Tower, Kingswear		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003852
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Two ring cairns 330 metres south east of Coldharb	oour Cross, Loddis	well
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014244
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Hilltop enclosure 380 metres east of Middle Soar,	Malborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019533
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Two hut circles and associated field systems and er	nclosure at Mousel	nill Brake, Malborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020573
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Two bowl barrows at Beacon Hill, 120 metres sou	th of The Beacon, I	Marldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020164
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Fort Charles, Salcombe		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1020165
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Hut circle 1000 yards (915 metres) east of Colelan	d Bridge, Sparkwel	I
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002596
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Post-medieval deer park, medieval fishpond, and a C19 lead mine, ore works and smelt mill at Boringdon Park, Sparkwell		
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II*	LIST ENTRY NUMBER:	1020565 and 1386330
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Woodbury Camp, Stoke Fleming		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019783
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Hillfort known as Slapton Castle, Stokenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019236
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
ITE NAME:	Roman settlement site at Bantham Ham, Thurlesto	ne	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019322
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Hilltop enclosure at Yellowberries Copse, 430 metres west of Higher Turtley, Ugborough		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1019325		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

#### **TEIGNBRIDGE**



© Teignbridge District Council

SITE NAME:	Former stables to Stover House, Stover, Teigngrace
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)

Commercial company LIST ENTRY NUMBER: 1308968

OWNER TYPE:

LIST ENTRY NUMBER:

Built as stables, 1779. The stables were stripped out when they were superseded by a larger stable block in 1843, and were converted to a magnificent backdrop to the newly laid out gardens for the 11th Duke of Somerset. It is a key feature of the Stover's grade II designed landscape. Now in very bad condition due to the spread and distortion of single ashlar front, rusting cramps, and water and vegetation damage. Currently fenced off. Repairs have been agreed under a Natural England Stewardship scheme.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	The Granite Lodge adjacent A38 approx 1550 metres NNW of Stover House, Teigngrace
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

Contact: Annie Evans 0117 975 1308

Disused pedimented lodges, with linking screen, gates, and flank walls to former drive to Stover House. Likely c1830, possibly by Philip Hardwick. Banded rusticated granite ashlar with slate roofs. Single windows front and rear and doors with steps flanking the drive. South west lodge in extremely poor condition and open to the weather, with a collapsed roof and collapsed suspended timber floor. North east lodge in better condition, but vacant with graffiti on the internal plaster wall. Connecting portico appears to be in reasonable condition but has not been closely inspected.

		1
	行	

SITE NAME:	Church of St Mary the Virgin, Bickington		
DESIGNATION:	Listed Place of Worship grade I		
CONDITION:	Poor		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1097150		

1308943

Parish church. C15 Nave, chancel, with early C16 north aisle, west tower restored in 1883-4 when the south wall, south porch, and east and west gables of north aisle were rebuilt. Devonian limestone, with granite detail in the medieval work and Ham stone used in the C19. Slated roofs with lots of tingles. Tall tower with cementitious pointing and vegetation growth. Black and green staining to east end at high level.

Contact: Annie Evans 0117 975 1308

	魚	1	
			<b>阿</b> 拉伯
-			
2	Ti		A
			100

© Historic England

© Historic England

SITE NAME:	Church of St Thomas, Mamhead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1170048

Parish church. Probably C13 or earlier in origin with surviving early windows in the chancel, C15 three-bay north aisle, south transept (now the baptistery) probably CI3 or CI4 but much altered, CI5 tower. CI9 restorations including one attributable to Anthony Salvin. Red sandstone and grey limestone rubble and red sandstone dressings and slate roofs. The high level stonework is in poor condition.

Contact: Annie Evans 0117 975 1308

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

I PA ΝP RPG

**ABBREVIATIONS** 

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Earthwork (possibly civil war) on Bovey Heath, Bovey Tracey		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1002657		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102



SITE NAME:

St Michael the Archangel, Den Promenade, Teignmouth

Listed Place of Worship grade II, CA

CONDITION:

Poor

PRIORITY CATEGORY:

D (C)

OWNER TYPE:

Religious organisation

1269103

LIST ENTRY NUMBER:

The church dates from 1821 in neo-Norman style by Andrew Patley. In 1875 the Chancel by Fredric Deshom was added, followed by the Vestry in 1885. The Early English style west tower by Fulford was added in 1887-9; it has five stages with a distinctive castellated parapet with pierced panels and octagonal corner towers with spirelets. The roofs were repaired in 2011/12. Many of the windows are in poor condition, some requiring urgent conservation work. A Heritage Lottery Fund Grant for Places of Worship was granted in June 2018 for window repairs which are due for completion at the end of 2018.

Contact: Sarah Ball 0117 975 0666

© Historic E	ngland
--------------	--------

SITE NAME:	Bishop's Palace, Chudleigh		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1008679
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Denbury camp, Denbury and Torbryan		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003857
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Earthwork enclosure south of Blackall's Copse, Ex	minster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004579
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Linear round barrow cemetery at Castle Park, Alp	hington, Exminster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012347
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Kingskerswell Manor House, Kingskerswell		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1020875
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA Conservation Area
Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Prehistoric field system and settlements on Kerswell Down and Whilborough Common, Kingskerswell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021377
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102

SITE NAME:	Oxton House, Kenton
DESIGNATION:	Registered Park and Garden grade II, 7 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1001269

In the mid-C19 the picturesque grounds comprised lawns, parterres, shrubberies, parkland and a lake. In the C20 the property was occupied by a school before being divided into apartments. The pleasure grounds are neglected and much of the park is ploughed, with considerable loss of parkland planting.

Contact: Jo McAllister 0117 975 0696



Historic England

SITE NAME:	Stover Park, Teigngrace
DESIGNATION:	Registered Park and Garden grade II, 7 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1001268

LIST ENTRY NUMBER:

Very bad

Medium

Late C18 gardens, pleasure grounds and park in divided ownership. A large area of the park is run by the County Council as a country park and other parts developed as mineral workings. The main house and environs are in use as a school. The setting is under threat from development, including road widening and housing allocation. A parkland plan was produced through a Natural England Stewardship Scheme in 2014. An application to the Heritage Lottery Fund (to implement the plan's recommendations) is being revised.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Bovey Tracey, Pottery Road, Bovey Tracey		
DESIGNATION:	Conservation Area, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maureen Pearce (LPA) 01626 215705
SITE NAME:	Cockwood Sod, Dawlish Parish, Starcross / Dawlish		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown

## VULNERABILITY: **TORRIDGE**



© Historic England

SITE NAME:	Winsford Hospital, Halwill Junction, Halwill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1105657

Winsford Centre was built as a cottage hospital in 1899, designed by Charles Voysey and founded by a local landowner. The NHS closed the hospital in 1998 and it was bought by the Winsford Trust. Since then it has been run as a day centre and community resource. Historic England grant aid led to the production of a Conservation Management Plan, options appraisal and costed condition survey in 2012. A Heritage Lottery Fund grant has been given to develop a project to restore the building in conjunction with the Landmark Trust who have taken on the ownership of the building.

CONTACT:

Contact: Chris Miners 0117 975 1308

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Maureen Pearce (LPA) 01626 215705

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Richmond Dock, Northam
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

1140140

Commercial company

Dry dock, 1856. It is said to have been the largest dry dock in the Bristol Channel at the time it was built. The dock is now vacant. In 2015 the gates were in poor condition, and as of 2017 no repair proposals have been made to Historic England. Ongoing discussions for alternative uses being held with LPA as of 2018.

Contact: Catherine Marlow

	J.V	
		A CONTRACTOR
THE A	1	
	1	
100		100

© Historic England Archive

World War II air traffic control building 400 metres north west of Seckington Cross, on the former airfield of RAF Winkleigh, Winkleigh

DESIGNATION: Scheduled Monument

CONDITION: Poor

OWNER TYPE:

LIST ENTRY NUMBER

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A(A)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1020765

The monument is a World War II brick and concrete control tower. Although structurally sound, the tower has suffered from vandalism and lack of maintenance and has failing concrete as a result of oxidising steel reinforcement.

Contact: Charlotte Russell 01271 831505



© Historic England

© Historic England

SITE NAME:	Church of All Saints, Bradford
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105088

Parish church with Norman origins, C14 chancel, C15 north aisle and porch, restored from a ruinous state in 1869 and 1875-89. The tower suffers from water ingress and damp and the bell ropes drip with water. The rest of the church is damp. The gutters and downpipes need overhauling.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Bridget, Bridgerule
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1104976

Externally the tower has black staining, indicating that is damp. There are no rainwater goods and areas of cement ribbon pointing. The church is in need of patch repointing. This has contributed to some paint blistering internally, such as in the east end of the south aisle.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary and St Gregory, Frithelstock
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105177

Parish church. C13 north wall; chancel rebuilt and south aisle built in early C14; c1500 south-east chapel and roofs, and west tower rebuilt in C15. Coursed slatestone rubble; squared and coursed stone to tower; ashlar dressings. Stone-gabled and gabled slate roofs. This church is in need of external patch repointing and the overhaul and renewal of all of the rainwater goods is required.

Contact: Annie Evans 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Michael, Great Torrington
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1104787

Mainly Perpendicular with some fabric C13. Western end rebuilt 1646-51 following an explosion in the Civil War. Tower 1828, by WB Cock. Chancel with flanking vestries, nave with aisles, south west porch, west tower with spire. Mixed local rubble stones, limestone dressings with slate roofs. Lias stonework of tower very poor. Straight joints to arrises of spire, and rusting iron beams within. Counterweight structure rotting. The church was awarded a Heritage Lottery Fund Grant for Places of Worship in 2016 and repairs are expected to be completed at the end of 2018.

Contact: Annie Evans 0117 975 1308



SITE NAME: Church of St Swithun, Littleham DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1105152

Parish church. Mid C13 nave and chancel; late C13 north transept; early C15 south aisle and west tower which was restored in 1892. Rainwater goods do not appear to be installed. The tower shows signs of damp.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Helena, Lundy
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1104955

Small parish church in a very exposed position on the top of the cliffs. South tower, south porch, nave and lower east chancel. Granite ashlar walls and sized slates. Slate roofs are poor, the walls are damp and support vegetation growth and need repointing. Floors damaged by salt expansion. Some of the rainwater goods have been blown

Contact: Chris Miners 0117 975 1308



	# /

SITE NAME:	Church of Holy Trinity, Milton Damerel
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1162778

Parish church. Late C13 origins with C14 fabric, remodelled in C16 restored c1900-1910. Stone rubble walls. Gable-ended slate roof. Tower destroyed by lightning in 1879 and in ruins for 20 years but re-opened in 1904. Tower partly re-erected in 1892 and rebuilt in 1910-11. The church is generally well maintained, but needs a significant project to secure loose stones on top of the tower, tackle damp problems, and repair roofs. The congregation has made three applications for Heritage Lottery Fund Grant for Places of Worship but has not been successful.

Contact: Annie Evans 0117 975 1308

© Historic England

SITE NAME:	Church of St Margaret, Northam
designation:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation

1169270

Large parish church. Mainly C15 although lower part of tower is older. Thoroughly restored between 1849 and 1865. The roof slating is nearing the end of its life, and the ceilings are plastered to the underside of roofing battens. The church was awarded a Heritage Lottery Fund Grant for Places of Worship in late 2016 for repair of the nave and vestry roofs. It is planned for work to start on site by the end of 2018. At least one further phase of work to the roofs will be needed.

Contact: Annie Evans 0117 975 1308

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Pancras, Village Centre, Pancrasweek
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1164477

© Historic England

© Historic England

© Historic England

Parish church. Chancel C13 in part, church rebuilt and enlarged C15, restored 1894-8 and 1927. Squared and coursed local stone, granite dressings, slate roofs. There were issues with the tower masonry with cracking and bulging but this has been repaired. There are also holes in the roof and fallen slates in the churchyard and rainwater goods are in poor condition. The church was offered a Heritage Lottery Fund Grant for Places of Worship in 2017 and it is expected that repair work will start by the end of 2018.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Petrock, Petrockstow
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1333084

Parish church. C14 aisle and C15 tower, the rest rebuilt in 1878-80. There are some problems with the roof covering, especially verges and eaves, parapets and flashings. The rainwater goods and drainage need repair and overhauling. This has led to water ingress and salt damage to the interior. The parish made an application for funding under the Heritage Lottery Fund Grant for Places of Worship scheme in 2017 but was not successful.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Michael, Shebbear
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1309558

Rural Devon church. Most significant feature is mid-C12 south doorway. Plain nave and south aisle; simple rendered tower. Damp interior with carpet hiding salt damage to floor. Vegetation needs to be removed from the external ground gutter and there is a poor vestry valley gutter arrangement, worsening the internal problems.

Contact: Annie Evans 0117 975 1308

		A		
	4			
		NUSA NUSA NUSA NUSA NUSA NUSA NUSA NUSA		
	100			
		-		
tion.		S. di		
			A	
			-	-

SITE NAME:	Church of the Holy Cross, Tetcott
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1252173

Parish church. Fabric of nave and chancel C13, south transept C13 or C14, tower C15, vestry probably C19. Stone rubble with granite dressings, the tower ashlar masonry with granite quoins and lacing, slate roofs. Fittings including several good C18 wall monuments. The church forms part of an important group including Tetcott Manor and associated buildings. The north wall is still moving, even after works to stop the roof spreading. Tower masonry needs repointing and the roof re-covering to prevent water ingress to the belfry and ringing chamber.

Contact: Annie Evans 0117 975 1308

_ 8		$\mathbb{R}_{\mathbb{R}}$	
© H	listori	c Eng	lanc

SITE NAME:	Bowl barrow 250 metres north east of Oak Cottag	ge, forming part of	a round barrow cemetery, Ashwater
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020079
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 540 metres south east of Sandymoor Ashwater	Cross, forming pai	rt of a round barrow cemetery,
SITE NAME:  DESIGNATION:	· · · · · · · · · · · · · · · · · · ·	Cross, forming par	rt of a round barrow cemetery,
	Ashwater		,
DESIGNATION:	Ashwater Scheduled Monument	LIST ENTRY NUMBER:	1020080

#### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

SITE NAME:	Bowl barrow 770 metres south east of Sandymoor Ashwater	Cross, forming pa	rt of a round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020081
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hillfort known as Castle Hill Settlement, 350 metro	es south of Woolle	eigh Bridge, Beaford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021417
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Holy well 480 metres north west of Beaford Mill, E	Beaford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015142
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hallsannery limekiln, Bideford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004578
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 420 metres north west of Dural Cro	ss, Bradworthy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016643
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 280 metres south west of Upcott Cr	oss, Broadwoodwi	dger
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019546
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 690 metres and 760 metres so	uth west of Lewort	thy, Clawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017974
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / TORRIDGE		
SITE NAME:	Clovelly Dykes hillfort, Clovelly		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018522
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Four bowl barrows 110 metres and 360 metres we cemetery, East Putford	est of Wrangworth	y Cross forming part of a round barro
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018526
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Three fishponds at Winslade, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017979
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows 600 metres and 750 metres we cemetery, East Putford	Two bowl barrows 600 metres and 750 metres west of Wrangworthy Cross forming part of a round barrocemetery, East Putford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018515
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Two bowl barrows one immediately north and one 100 metres south of Commonmoor Cottage forming part of a round barrow cemetery, East Putford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018516
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hender Barrow, Halwill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019727
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 520 metres west of Higher Welsford	, Hartland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017138
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Ring cairn and bowl barrow 540 metres south wes	t of Higher Welsfo	rd, Hartland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017139
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Ugworthy Moor 510 metres sout	h of West Ugworth	ny House, Holsworthy Hamlets
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017977
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 60 metres west of St James's Church	, Luffincott	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020476
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 325 metres north west of Tibbett's Lookout	, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016019
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 530 metres west of Quarterwall Cottages, L	undy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016012
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chambered tomb 165 metres north east of the Ro	ocket Pole Pond, Lu	ndy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015931
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chapel remains, cemetery and prehistoric settleme	ent on Beacon Hill,	Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016040
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Coastal defence platforms at the Mousehole and T	rap, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016031
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
	, 1		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Fog battery at Battery Point, Lundy		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1016038
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Granite quarry on East Sidelands, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016041
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Gun battery at Brazen Ward, Lundy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016030
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Hut circle and small enclosure 270 metres north w	vest of The Old Ligi	nthouse, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016014
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Long house and enclosure 160 metres north of W	idow's Tenement, L	undy.
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018547
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Medieval settlement immediately south of Halfway	Wall, Lundy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017647
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ruined cottages and well 190 metres north west o	f Quarterwall Cott	ages, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016027
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JIH WESI / TOKKIDGE		
SITE NAME:	The Widow's Tenement medieval settlement and p	prehistoric settleme	ent sites, Lundy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017646
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Moated site at Grange Farm, Merton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017867
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cross ridge dyke on Godborough Castle earthwor	k north west of Tu	ırner's Wood, Northam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002640
CONDITION:	Unknown	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 685 metres NNE of Moorfield, Shebbear / Peters Marland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017963
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	World War II air traffic control building 400 metre of RAF Winkleigh, Winkleigh	es north west of Se	ckington Cross, on the former airfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bideford, Clovelly Road		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Chappell (LPA) 01237 42874
SITE NAME:	Northam		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Chappell (LPA) 01237 42874

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

#### WEST DEVON



© Historic England

© Historic England

SITE NAME: Gawton Mine complex, Gulworthy / Bere Ferrers DESIGNATION: Scheduled Monument, WHS CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1002667

Former copper and arsenic mine and processing complex, comprising a full range of buildings from cooperage to engine houses. The site has suffered damage from vehicles. Despite recent extensive clearance and emergency support works, the structures remain at risk.

Contact: Nick Russell 0117 975 0671

	S
	E
	C
1	C
	F

SITE NAME:

LIST ENTRY NUMBER:

SITE NAME:	Kelly House, Kelly
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1318194

of renewal, rear medieval wing is partly propped. Main house is weathertight and maintenance is gradually being

C18 house with serious maintenance issues. Roof is in need

Contact: Annie Evans 0117 975 1308



House, Kelly DESIGNATION: Listed Building grade II\* CONDITION: Very bad

Stable block north of Kelly

Stables, 1740. Partly used, part collapsed.

© Historic England

OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1104813

Contact: Annie Evans 0117 975 1308



© South Hams District Council

SITE NAME:	Lower Sessland Farm including cob walls adjoining to north west and south west, Sessland Lane, South Tawton
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

Late medieval thatched farmhouse with later additions, including C17 hall bay and parlour wing. Further C17 addition to north west has been used as a separate cottage, and since 2012 has been vacant and in very poor condition, with severe water penetration and decay of thatch and roof timbers. Temporary protection was erected in 2006 following an Urgent Works Notice. The building has now been returned to single ownership and a scheme of repairs is underway for use as a farm cottage.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Tavistock Abbey, Tavistock
DESIGNATION:	Scheduled Monument, 16 LBs, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1020401

1170877

Tavistock Abbey is central to the history and character of the medieval town which developed around it. The Saxon foundation of the abbey places it amongst the earliest of the medieval religious houses founded in Britain. Its occupation from 974 to 1579 included continuous use by the same Benedictine order for over five and a half centuries. The ruins are suffering from water ingress and damaging vegetation growth. Historic England has offered a grant to carry out a full condition survey and conservation management plan for the West Gate House (Betsy Grimbals Tower) and the Still Tower.

Contact: Andy Crabb 01626 832093

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:



© West Devon Borough Council

SITE NAME:	Guildhall and police station, Abbey Place, Guildhall Square, Tavistock
DESIGNATION:	Listed Building grade II*, SM, CA, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use

Local authority

D(D)

1309358

Completed 1848, incorporating medieval fabric in part. Use as court ended 1997 and police station has relocated. The first known example of a combined police station and magistrates' court. Roof is in very poor condition and fabric in general urgently needs attention. Devon Historic Buildings Trust sold the building to the Town Council, who made a successful Heritage Lottery Fund bid in 2015 and are working on their second.

Contact: Annie Evans 0117 975 1308

	1	4 A	
1			
			2
		1	

© Historic England

SITE NAME:	Church of St Mary, Bratton Clovelly
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1326312

Parish church. Mainly mid to late C14 although the chancel may be earlier, porch probably early C15; various repairs made in C19 and restored in 1891-2. Granite and slate rubble walls with granite dressings, tower is constructed of coursed dressed granite blocks of irregular sizes. Medieval structure enhanced by the remarkable survival of a large number of wall paintings. The church suffers from water ingress and there is some structural movement at the east end.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of Holy Cross, Highampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1165844

Parish church. C12 origins with c late C15 tower and the rest of the church rebuilt in 1837. Restored in 1876. The church suffers from water ingress and damp possibly associated with its very exposed position. The tower walls are damp; the parish and appointed architect are investigating the causes. Active insect infestation to ceiling timber ribs. Some roof slates cracked and missing. North west window buckled and missing glass.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Mary, Walkhampton, West Devon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1105371

Church in an elevated position on the edge of Dartmoor about a mile outside the village. Largely C14 but may be pre-conquest in foundation. Aisle and tower added in the C15. Local rubble with granite dressings. Cornish slate roofs. Tower is wet with large amounts of vegetation growth. Valley gutter and rainwater goods in need of work.

Contact: Annie Evans 0117 975 1308

0	Historic	Eng	lanc

© Historic England

SITE NAME:	Iron Age defended settlement in Dunterue Wood,	570 metres south	of Castle Head, Dunterton
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1020273
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Andy Crabb 01626 832093

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 375 metres north east of Higher Ewo	orthy, Germanswee	k
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020084
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Bowl barrow 620 metres north of Higher Eworthy	, Germansweek	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017971
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Morwellham Quay: transport infrastructure, part o Gulworthy	of the water contro	system and a manganese mill,
DESIGNATION:	Scheduled Monument, 3 LBs, WHS	LIST ENTRY NUMBER:	1021461
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Gawton arsenic mine and flue, Gulworthy / Bere Fo	errers	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002667
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Russell 0117 975 0671
SITE NAME:	Round barrow cemetery and beacon at Heathfield, / Brentor	650 metres west o	of Moorlands, Lamerton / Milton Abbo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020075
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
ITE NAME:	Roman forts, marching camps and associated monu	ıments, North Taw	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021151
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Andy Crabb 01626 832093
SITE NAME:	Two bowl barrows 200 metres north east of New	land Cross, North	Tawton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017131
		TDENID	D 1: :
CONDITION:	Extensive significant problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing	NEW ENTRY?:	Yes
	· ·		5

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Guide post at Place Cross, Okehampton Hamlets		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020069
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Andy Crabb 01626 832093

	$\overline{}$	-	_		_
D	O	к		ы	

#### **CHRISTCHURCH**

DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016092  CONDITION: Extensive significant problems TREND: Declining
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016092 CONDITION: Extensive significant problems TREND: Declining
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016092
·
Bowl barrow on East Parley Common 610 metres south west of Fir Grove Farm, Hurn

SITE NAME:	Works, Hurn	h west and 1080 m	netres south west of Palmers Ford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016091
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

#### **EAST DORSET**



SITE NAME: Grotto 250 metres south east of St Giles House, Wimborne St. Giles Listed Building grade II\*, RPG DESIGNATION: grade II\* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: E (E) OWNER TYPE: Private

Grotto c1751-53, located 250 metres to the south east of the house, at the east end of a winding channel of water running towards the lake. One of several garden buildings situated in the C17 and C18 landscape. The Grotto was subject to a major programme of repair during 2014, under a Natural England Stewardship scheme. External consolidation and much of the internal shell decoration reinstated. A further and final phase of repair to the vault is anticipated.

LIST ENTRY NUMBER: 1120131 Contact: Sarah Ball 0117 975 0666

SITE NAME:	Length of deer park bank and ditch at Alderholt	, Alderholt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002394
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Section of Roman road 150 metres south of Par	k Farm Cottages, Col	ehill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018028
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Bell barrow 500 metres north east of Beacon Farr	n, Ferndown Town	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015995
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow known as Belle Vue Barrow and a bov Town	vl barrow 250 metr	es north east of Hillamsland, Ferndo
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 250 metres west of Ferndown Uppe	r School, Ferndown	n Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015791
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Utility	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Part of Ackling Dyke (Roman road), including Rom Michael / Pentridge / Wimborne St. Giles	nan road on Oakley	Down, Gussage All Saints / Gussage
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1003309
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrow on Parsonage Hill, Gussage St. Michael		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002783
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long mound 1500 yards (1370 metres) east of Hig	ther Farm, Gussage	St. Michael
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002784
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows near Ackling Dyke, Gussage St. Mich	nael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002786
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
MINCHAE VOLINEIVABILITI.	Alable ploughing		INO

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Two long barrows on Gussage Hill, Gussage St. Mi	chael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002707
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows on Gussage Down, Gussage S	t. Michael	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Earthworks on Gussage Down, Gussage St. Michae	el / Sixpenny Handle	ey .
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002740
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrows near Thickthorn Farm, Gussage St.	Michael / Tarrant	Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north west of High Lea Farm, Hinto	on Martell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004552
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow cemetery and a cross dyke on Horto	n Common 800 me	etres south of Bridge Farm, Horton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018411
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 250 metres north west of Veiny Che	ese Pond, Long Cri	chel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015191
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows 165 metres west of Veiny Che	ese Pond, Long Cri	chel
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015785
CONDITION:	Extensive significant problems	TREND:	Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Private	NEW ENTRY?: CONTACT:	No Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

DESIGNATION  Scheduled Monument  Extensive significant problems  TREND  Declining  RININGPAL VULNERABILITY:  Arable ploughing  REMEDITATION  CONTACT:  Raty Hoskyn 011  STEENAME:  Bradford Barrow, Pamphill  DESIGNATION  Scheduled Monument  LIST ENTRY NUMBER. 1002713  CONDITION  Generally unsatisfactory with major localised problems  RININGPAL VULNERABILITY:  Animal burrowing - extensive  Private  CONTACT:  Katy Hoskyn 011  STEENAME:  Celtic fields on Pentridge Down, Pentridge  DESIGNATION  Scheduled Monument  LIST ENTRY NUMBER. 1002796  CENDITION:  Generally unsatisfactory with major localised problems  RININGPAL VULNERABILITY:  Arable clipping  NEW ENTRY:  No  OWNER TYPE  Private  CONTACT:  Katy Hoskyn 011  STEENAME:  Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1002792  EXTENAME:  Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1002722  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1003222  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1003222  TREND:  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1003225  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER. 1003225  TREND:  DESIG	richel / Tarrant
PRINCIPAL VULNERABILITY: Arable ploughing NEW INTRYP: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Bradford Barrow, Pamphill DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002713  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ITRYP: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  STE NAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 10027722  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 10027722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 10027722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No OWNER TYPE: Private Contract: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRYP: No OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
OWNER TYPE Private CONTACT: Katy Hoskyn 011  STEENAME: Bradford Barrow, Pamphill  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002713  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  STEENAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  STEENAME: Contract: Katy Hoskyn 011  STEENAME: Contract: Katy Hoskyn 011  STEENAME: Contract: Katy Hoskyn 011  STEENAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002722  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  STEENAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  STEENAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private Contact: Katy Hoskyn 011  STEENAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002455  DESIGNATION: Scheduled Monu	
STIE NAME: Bradford Barrow, Pamphill  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY: No  CONTACT: Katy Hoskyn 011  STIE NAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 011  STIE NAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 011  STIE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 011  STIE NAME: Private  CONTACT: Katy Hoskyn 011  STIE NAME: Private  CONTACT: Katy Hoskyn 011  STIE NAME: Private  CONTACT: Katy Hoskyn 011  STIE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 011  STIE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  TREND: Declining  PRINCIPAL VULNERABILITY: Anable ploughing NEW ENTRYP: No  CONTACT: Katy Hoskyn 011  STIE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRYP: No  CONTACT: Katy Hoskyn 011	
Scheduled Monument LIST ENTRY NUMBER: 1002713  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  DESIGNATION: Extensive significant problems TREND: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	7 975 1311
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive New entry: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping New entry: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private Contact: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive New entry: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Celtic fields on Pentridge Down, Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping New entry: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private Contact: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
OWNER TYPE: Private Celtic fields on Pentridge Down, Pentridge  CESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
Celtic fields on Pentridge Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  OWNER TYPE: Private  CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  OWNER TYPE: Private  CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  CONTACT: Katy Hoskyn 011  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  CONTACT: Katy Hoskyn 011	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002796  CONDITION: Generally unsatisfactory with major localised problems  New ENTRY: No  Declining  NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  DOWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	7 975 1311
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  Private  CONTACT: Katy Hoskyn 011  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  DOWNER TYPE: Private  CONTACT: Katy Hoskyn 011  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERABILITY: Arable ploughing  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  DOWNER TYPE: Private  CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  DOWNER TYPE: Charity (non-heritage)  CONTACT: Katy Hoskyn 011	
problems  PRINCIPAL VULNERABILITY: Arable clipping  NEW ENTRYP: No  OWNER TYPE: Private  CONTACT: Katy Hoskyn 01 I  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  OWNER TYPE: Private  CONTACT: Katy Hoskyn 01 I  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  OWNER TYPE: Private  CONTACT: Katy Hoskyn 01 I  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  TREND: Declining  PRINCIPAL VULNERABILITY: No  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Charity (non-heritage)  CONTACT: Katy Hoskyn 01 I	
OWNER TYPE: Private CONTACT: Katy Hoskyn 01 I  SITE NAME: Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 01 I  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 01 I	
Long barrows and group of round barrows on Bokerley Down, Pentridge  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 01 I'  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  CONTACT: Katy Hoskyn 01 I'	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002722  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 01 I'  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 01 I'	7 975 1311
Extensive significant problems  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing  Private  Private  CONTACT: Katy Hoskyn 01 I  SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  CONTACT: Katy Hoskyn 01 I  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  CONTACT: Katy Hoskyn 01 I  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  CONTACT: Katy Hoskyn 01 I	
PRINCIPAL VULNERABILITY: Arable ploughing Private CONTACT: Katy Hoskyn 011 CONTACT: CONTAC	
OWNER TYPE: Private CONTACT: Katy Hoskyn 011 SITE NAME: Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011 SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
Part of Dorset Cursus, Pentridge / Wimborne St. Giles  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003222  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1003222  CONDITION:  Extensive significant problems  TREND:  Declining  NEW ENTRY?:  NO  OWNER TYPE:  Private  Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1002455  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  CONTACT:  No  NEW ENTRY?:  No  OWNER TYPE:  No  CONTACT:  Katy Hoskyn 011	7 975 1311
Extensive significant problems  TREND: Declining  NEW ENTRY?: No  OWNER TYPE: Private  Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument  Condition: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Charity (non-heritage)  TREND: Declining  Declining  NEW ENTRY: No  Katy Hoskyn 011	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Katy Hoskyn 011  SITE NAME: Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
Private Contact: Katy Hoskyn 011  Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
Camp in Mistlebury Wood, Sixpenny Handley  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002455  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
DESIGNATION:  Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  Contact:  Contact:  Katy Hoskyn 011	7 975 1311
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New entry?:  No  Charity (non-heritage)  CONTACT:  Katy Hoskyn 011	
problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  OWNER TYPE: Charity (non-heritage)  CONTACT: Katy Hoskyn 011	
OWNER TYPE: Charity (non-heritage) CONTACT: Katy Hoskyn 011	
SITE NAME: Enclosure south of Humby's Stock Coppice, Sixpenny Handley	7 975 1311
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005575	
CONDITION: Extensive significant problems TREND: Declining	
PRINCIPAL VULNERABILITY: Arable ploughing New entry?: No	
OWNER TYPE: Commercial company CONTACT: Katy Hoskyn 011	7 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### **ABBREVIATIONS**

SITE NAME:	Three bowl barrows in Avon Heath Country Park, Matcham's House, St. Leonards and St. Ives	two 620 metres ar	nd one 700 metres north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Stephen's Castle, a bowl barrow 720 metres east o	of Eastworth Farm,	Verwood
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1021148
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Parley Barrow, a bowl barrow on the corner of Ell	esfield Drive and D	ruid's Close, West Parley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barrows south of Cranborne Farm, W	imborne St. Giles	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002459
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows in and near St Giles Park, Wimborne St. C	Giles / Edmondshan	า
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002782
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows in and near The Drive Plantation, Wimbo	rne St. Giles / Guss	sage All Saints
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1002788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Barrows in Salisbury Plantation, Wimborne St. Gile	es / Pentridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002817
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Group of henge monuments, an associated group at Knowlton, Woodlands	of round barrows, a	a Saxon cemetery and a Norman church
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020580
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow cemetery south of New Barn Farn	n, associated with th	e Knowlton Circles, Woodlands
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020582
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:			
OWINER TITE.	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

#### **NORTH DORSET**



© Historic England

SITE NAME: Abbey Church of St Mary, St Sansom and St Branwalader, Milton Abbas Listed Building grade I, RPG DESIGNATION: grade II\* CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: E (D)

OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1304822

LIST ENTRY NUMBER:

Formerly church of a Benedictine abbey now used as a school chapel. Mainly C14, upper part of tower and north transept C15. Restored c1790 by J Wyatt and 1865 by Sir Gilbert Scott. Walls of stone and flint with ashlar dressings. Nave and aisles not rebuilt after fire in C14. Repairs to roofs, windows and drainage carried out in 2016 with Viridor funding. Further grant from Viridor has enabled the completion of works to the floors. A Heritage Lottery Fund 'Great Stare Project' grant has been offered to carry out remaining urgent high level repairs. Work is due to start by the end of 2018.

Ruins of C14 stone built manor house within Sturminster Newton Castle, a probable Iron Age promontory fort

overlooking the River Stour. Upstanding remains are in a

consolidation work is urgently required to avoid significant areas of collapse. Historic England architectural survey

team has recorded the structure. The site is up for sale and

we hope to engage in discussions with the new owner as soon as possible to discuss the most urgent works.

very precarious position and a considerable amount of

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME: Sturminster Newton Castle. Sturminster Newton Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1002719 and 1324461 Contact: Katy Hoskyn 0117 975 1311



© Historic England

Barn and outbuilding range, SITE NAME: Tarrant Abbey Farm, Tarrant Crawford Scheduled Monument and Listed DESIGNATION: Building grade II\* CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private, multiple owners

LIST ENTRY NUMBER: 1002715 and 1110841

C15 barn with C18 outbuildings and alterations. No longer in agricultural use. Works have been undertaken to support the structure but deterioration is on-going and part of the roof has collapsed.

Contact: Nick Croxson 07795 665645

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Manor Farm barn, Winterborne Clenston
DESIGNATION:	Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)

C (New entry)

Mixed, multiple owners

LIST ENTRY NUMBER: 1110166

OWNER TYPE:

Huge late C16 tithe barn part used for storage. The hammerbeam roof may have been reused from a monastic building at Milton Abbey. Partial roof collapse resulted in Historic England funding the erection of scaffolding as a temporary roof support. These repair works were completed in 2008, but there has been no further progress and the building is slowly deteriorating.

Contact: Sarah Ball 0117 975 0666



© Marcus Chantrey, Benjamin Beauchamp Architects

SITE NAME:	Church of St Peter and St Paul, Market Place, Blandford Forum
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1251913

This church is a prime example of Georgian church architecture outside London. It was rebuilt after a fire between 1732 and 1739 to designs by John and William Bastard. The external stonework is in poor condition and there is water ingress to the interior causing damage to the plaster work. The tower and cupola were repaired in 2016 with a Heritage Lottery Fund Grant for Places of Worship. A recent request for a further grant to carry out works to the roof, plasterwork and masonary has been rejected.

Contact: Sarah Ball 0117 975 0666

SITE NAME: Linear boundary 870 metres south west of Spring Farm, Ashmore			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020729
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Linear boundary and section of Roman road, 550 metres south east of Ashmore Farm, Ashmore / Tollard Royal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020728
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	St Leonard's Chapel, Blandford Forum		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002726
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Field system in Old Park, Bryanston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002427
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres south of Gorcombe Farm	, Charlton Marsha	II
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow 500 metres south west of Gorcom	be Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014847
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 650 metres south west of Gorcom	be Farm, Charlton M	arshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014849
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 1020 metres south east of Charisw	orth Cottages, Charl	ton Marshall
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014846
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 360 metres SSW of Chettle House	, Chettle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bowl barrows 380 metres west of West E	end Barn, Dewlish / M	ilborne St. Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015031
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Causewayed camp on Hambledon Hill, Iwerne C	ourtney or Shroton /	Child Okeford / Hanford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002767
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow known as Folly Barrow, Iwerne Mi	nster	
	Scheduled Monument	LIST ENTRY NUMBER:	1020030
DESIGNATION:			
	Generally unsatisfactory with major localised problems	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised	TREND:  NEW ENTRY?:	Declining No
CONDITION: PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised problems		-
CONDITION: PRINCIPAL VULNERABILITY:  DWNER TYPE:	Generally unsatisfactory with major localised problems  Scrub/tree growth	NEW ENTRY?: CONTACT:	No Nick Croxson 07795 665645
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Generally unsatisfactory with major localised problems  Scrub/tree growth  Commercial company	NEW ENTRY?: CONTACT:	No Nick Croxson 07795 665645
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Generally unsatisfactory with major localised problems  Scrub/tree growth  Commercial company  Two bowl barrows 350 metres south west of Ke	NEW ENTRY?:  CONTACT:  eeper's Lodge, south 6	No Nick Croxson 07795 665645 east of Bareden Down, Iwerne Minste
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Generally unsatisfactory with major localised problems  Scrub/tree growth  Commercial company  Two bowl barrows 350 metres south west of Kennercial Monument	NEW ENTRY?:  CONTACT:  eeper's Lodge, south of the control of the	No Nick Croxson 07795 665645 east of Bareden Down, Iwerne Minster
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Generally unsatisfactory with major localised problems  Scrub/tree growth  Commercial company  Two bowl barrows 350 metres south west of Ke Scheduled Monument  Extensive significant problems	NEW ENTRY?:  CONTACT:  eeper's Lodge, south &  LIST ENTRY NUMBER:  TREND:	No Nick Croxson 07795 665645  east of Bareden Down, Iwerne Minst 1013745  Declining

Immediate risk of further rapid deterioration or loss of fabric; no

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 70 metres south east of West End	Barn, Milborne St. Ai	ndrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014854
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 480 metres south east of West End	d Barn, Milborne St. A	Andrew
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014855
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bowl barrows on Milborne Down 520 me Castle hillfort, Milborne St. Andrew	tres and 585 metres	north east of obelisk on Weatherby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows and two ring ditches 450 metres north west of Haywards Farm, Milborne St. Andrew		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019365
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Weatherby Castle, an Iron Age hillfort 1020 met	res north west of As	hley Barn Farm, Milborne St. Andrew
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019360
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Stable Barrow 230 metres NNE of Frogmore Fai	rm, Milborne St. And	rew / Milton Abbas
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014761
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	King's Court Palace moated site, Motcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017276
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Hugh Beamish 0117 975 0726

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Enclosure south of Pimperne Down, Pimperne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Castle Hill, Shaftesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002724
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Crawford Castle (or Spetisbury Rings), Spetisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004563
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Hod Hill camp and Lydsbury Rings, Stourpaine / Ha	anford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Keith Miller 0117 975 0670
SITE NAME:	Slight univallate hillfort 850 metres north east of Bo	usseys Stool Farm,	Tarrant Gunville
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020611
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 200 metres south east of Pimperne L	ong Barrow, Tarra	nt Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013794
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Prehistoric habitation site between north and sout	h Hinton Downs, T	arrant Hinton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003235
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Roman villa on Little Barton Hill, Tarrant Hinton / Tarrant Gunville		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002424
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 350 metres south west of Buzbury	Rings, Tarrant Keyne	eston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013789
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 850 metres ESE of Hill Farm, Tarra	nt Keyneston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015182
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Buzbury Rings, Tarrant Keyneston / Tarrant Rav	ston / Langton Long	Blandford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002718
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 600 metres south of Plantation Far	m, Tarrant Launcesto	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015190
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow on The Cliff 680 metres east of Lu	ton Farm, Tarrant Ra	wston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015187
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow on The Cliff 680 metres NNW of	Smith's Cottages, Tar	rant Rawston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015186
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow and two bowl barrows 140 metres	north west of Dorm	y House, Tarrant Rawston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
	Scrub/tree growth	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	50. d5/ ti 55 g. 5 Wei.		
PRINCIPAL VULNERABILITY: OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	Roman enclosure on Keyneston Down, Tarrant Ra	awston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002373
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 150 metres north east of Dunbury, \	Vinterborne Hough	nton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 500 metres south of West Down Ba	rn, Winterborne Ki	ngston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020986
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 900 metres north west of Pond Down Buildings, Winterborne Stickland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013749
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 25 metres south of Whitechurch Hil	l Barn, Winterborn	e Whitechurch
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Milling House, West Farm, Winterborne Whitech	urch	
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002396
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 120 metres south of the southern extent of Horse Close Plantation, Winterborne Whitechure / Bere Regis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015387
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bul Barrow, 750 metres east of Rawlsbury Camp, Woolland		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013787
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Blandford Forum, North Dorset		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kevin Morris (LPA) 01258 484276
SITE NAME:	Gillingham, North Dorset		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kevin Morris (LPA) 01258 484276

#### **PURBECK**



North Lodges, Lulworth Castle, SITE NAME: Coombe Keynes Scheduled Monument and Listed DESIGNATION: Building grade II\*, part in RPG grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Private

Ornamental gate lodges and gateway to Lulworth Castle, 1785. The lodges and gates are stable but the flank walls and mock-fortifications are in poor condition. A 2015 bid for a Natural England Stewardship scheme was unsuccessful and the estate is exploring other possible funding for the repair of the lodges. It is hoped that with the Estate's newly appointed architect working on nearby Bindon, that the Estate's direct labour will be able to carry out repairs to the walls. They are currently successfully repairing outer walls.

© Historic England

SITE NAME: Royal Naval Cordite Factory at Holton Heath, Wareham St. Martin Scheduled Monument, LB grade DESIGNATION: CONDITION: Very bad

Vacant/not in use

1016685 and 1323333

PRIORITY CATEGORY: A(A)

LIST ENTRY NUMBER:

OCCUPANCY:

OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1019151

The cordite factory was built in 1916, and continued to produce explosives until 1945. It covers a large area of land, with lots of small workshops surrounded by earth banks, to contain any accidental blasts. A large number of individual buildings and structures still remain, now in varying degrees of collapse, and a programme of works to identify and repair the most significant of these is urgently needed. Much of the site is within a nature reserve and only open to the public by prior arrangement. The area included in the scheduling was extended in 2016.

Contact: Katy Hoskyn 0117 975 1311

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME-Bindon Abbey (site), Wool Scheduled Monument, LB grade DESIGNATION: CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)OWNER TYPE: Private LIST ENTRY NUMBER: 1002703

Bindon Abbey was founded as a Cistercian monastic house in 1172 and converted to a fine house in 1539 following the Dissolution. Much of the building was burnt down during the English Civil War but some of the structure survives as a standing ruin of up to 7 metres high. The tallest part, once the outer wall of the monastic church, is now supported by scaffolding. The masonry is very precarious and has suffered several recent falls of stone. In May 2018, the estate received a repair grant from Historic England. We are working with their appointed architect to develop a repair programme.

Contact: Katy Hoskyn 0117 975 1311

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOU	JIH WEST / PURBECK		
SITE NAME:	The Double Barrow, a bowl barrow in Kite Hill Affpuddle	Plantation 250 metre	s south east of Roger's Hill Cottages,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Worgret Heath, 320 metres north west of High Tor, Arne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018190
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bowl barrow 515 metres south of the southern extent of Horse Close Plantation, Bere Regis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015386
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 590 metres north east of Bere Do	wn Farm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015378
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 610 metres east of Bere Heath Fai	rm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015365
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Bowl barrow 790 metres north east of Hayward	ls Farm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015330
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Warren Heath, 350 metres sou	ıth west of Warren H	louse, Bere Regis
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019367
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / <b>PURBECK</b>			
SITE NAME:	Four bowl barrows 240 metres east of Oak Cot	tage, Bere Regis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015369	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Long barrow on Bere Down, 1100 metres north	Long barrow on Bere Down, 1100 metres north east of Roke Barn, Bere Regis		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015329	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	The End Barrow, a bowl barrow 320 metres sou	ıth west of White Ho	use, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017462	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Three bowl barrows 230 metres south west of	Haywards Farm, Bere	Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015333	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Two bell barrows and a bowl barrow, 200 metro	es north east of Hayw	vards Farm, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015332	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Two bowl barrows on South Heath, 900 metres	SSE of The Bungalow	, Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017694	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Bell barrow on Blackhill Clump 470 metres nort	h of Mintern's Ferry,	Bere Regis / Turners Puddle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015899	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Two bowl barrows both 350 metres north east	of Spring Garden Barı	n, Bere Regis / Turners Puddle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015898	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Bowl barrow 470 metres south east of Down Barn: an outlier of the Chaldon Down barrow group, Chaldo Herring			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008146	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Bowl barrow 650 metres south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008523	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	The Round Pound, an enclosure on Chaldon Down, Chaldon Herring			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018436	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Two bowl barrows 200 metres south east of Hi	ll Barn: two of a group	o of three barrows, Chaldon Herring	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008162	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Wardstone Barrow: a bowl barrow on the Dorset coastal ridge 300 metres south of Chideock Farm, Chaldon Herring			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008676	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Bowl barrow on Creech Barrow Hill, Church K	Bowl barrow on Creech Barrow Hill, Church Knowle / Steeple		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014830	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOI	UTH WEST / <b>PURBECK</b>		
SITE NAME:	The Rings: a ringwork and bailey and a Civil Wa Castle	r battery 400 metres	south west of Corfe Castle, Corfe
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011479
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three bowl barrows in Holme Lane Plantation, 200 metres south west of Squirrel's Cottages, East Holme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows known as 'Water Barrows' 650 m cemetery to the south east of East Lulworth, Ea		eway Farm: part of a round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008144
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Flower's Barrow: a small multivallate hillfort and	associated outwork	on Rings Hill, East Lulworth / Tyneha
designation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008141
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 60 metres north east of Hethfelto	n Farm, East Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018192
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Farm Heath, 470 metres south east of Hill Cottages, East Stoke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016272
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Farm Heath, 480 metres south	east of Hill Cottages,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016271
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2018 / SOL	JTH WEST / <b>PURBECK</b>		
SITE NAME: Section of Battery Bank on Binnegar Plain, 830 metres north east of Stokeford Farm, East Stoke			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018189
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Section of Battery Bank on South Heath, East St	oke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016273
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows on South Heath, 290 metres	and 370 metres east	of Binnegar Hall, East Stoke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016276
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Alum works, other multi-period industrial remains and an associated group of jetties and breakwaters, Kimmeridge Bay, Kimmeridge		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017307
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow in Morden Park 350 metres south	west of Hunting Bridg	ge, Morden
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016281
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bowl barrows 760 metres north east of Mi	ller's Farm, Morden	
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1016283
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Obelisk on Fir Hill, Moreton		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002425
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Group of three bell barrows and a bowl barrow or	n Godlingston Hea	th, Studland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014291	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Bowl barrow in Piddle Wood, 530 metres north east of Gate Barn, Turners Puddle			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015901	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311	
ITE NAME:	Group of six bowl barrows, forming a round barro	w cemetery on Bla	ack Hill, Turners Puddle / Bere Regis	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015897	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	
ITE NAME:	Decoy pond and associated overnight shelter on Decoy Heath, Wareham St. Martin			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016916	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	
ITE NAME:	Light Anti-aircraft battery on Holton Heath, 210 m	etres west of Sand	ford House, Wareham St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019153	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311	
SITE NAME:	Light Anti-aircraft battery on Holton Heath, 650 m	etres south east o	f Sandford House, Wareham St. Marti	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019152	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311	
ITE NAME:	Royal Naval Cordite Factory at Holton Heath, Wa	reham St. Martin		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019151	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311	

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Four bowl barrows 150 metres north east of Seven	n Barrows Farm, W	/areham Town
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015373
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bindon Hill camp, West Lulworth / East Lulworth		
DESIGNATION:	Scheduled Monument, part in CA, WHS	LIST ENTRY NUMBER:	1002705
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Drove Hill round barrows, Winfrith Newburgh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002765
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 300 metres south east of Hyford Cor	ttage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015894
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 380 metres north west of Hyford Co	ttage, Wool	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Emmett's Hill, Worth Matravers		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1017268
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Lytchett Minster, Lytchett Minster and Upton		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Benjamin Webb (LPA) 01929 55738
SITE NAME:	Swanage		
DESIGNATION:	Conservation Area, 87 LBs, SM, WHS	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
	/		Benjamin Webb (LPA) 01929 55738

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

## WEST DORSET



© Historic England

SITE NAME The dovecote, malthouse, outer gatehouse and walling, gateway, granary and tithe barn, St Peter's Abbey, Abbotsbury

Scheduled Monument and Listed DESIGNATION: Buildings - 5 grade I; 5 grade II\*; 4 grade II, LB grade II, part in CA

CONDITION:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY D (C)

OWNER TYPE: Mixed, multiple owners

> 1015693 and 1305224;

LIST ENTRY NUMBER 1172220; 1324227; 1118741;

1118742; 1118744; 1118745;

1118748

This large scheduled site contains 12 individually listed buildings, four of which are in poor or very bad condition. Several of the buildings were included in a 2013/14 condition survey to inform a future repair strategy. The published photo shows the dovecote, which is disused and unstable. It has potential for low-key use in conjunction with a visitor attraction centred on the nearby Tithe Barn complex. Historic England and the estate are developing a programme of repairs for several of the buildings in the complex. The estate has repaired the precinct walls.

Contact: Katy Hoskyn 0117 975 1311



© Historic England

SITE NAME:	Parnham House, Beaminster
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1221178

1810 by Nash. Suffered catastrophic fire in April 2017. Majority of roof and internal structure has been destroyed, but much external fabric survived. A complex set of circumstances has left the building unrepaired and still unprotected 12 months on, and Historic England's Conservation Engineer has assessed it as being in an increasingly vulnerable condition. Discussions are currently underway between Historic England and the local authority regarding the serving of an urgent works notice to stabilise the most fragile areas of fabric.

C16 country house, much refashioned and extended in

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Literary and Scientific Institute, East Street, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1118999

Founded 1835 as Mechanics Institute and reconstituted 1855 as Literary and Scientific Institute. Since 2012 a local trust has carried out project development work, grant aided by Historic England, which included a conservation management plan, a condition survey and feasibility study exploring the viability of using the building for community purposes. The trust completed this work in March 2014. Heritage Lottery Fund grant in place and Historic England grant offered in December 2014. Works began on site in 2016 for repair and conversion. Due for completion 2018.

Contact: Sarah Ball 0117 975 0666



© Historic England

	warehouse, Station Road, West Bay, Bridport
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1228722

Messrs Norman goods

C18, possibly older. Former bonded stores. The yard is being used as an antiques/pop-up market. Discussions are ongoing with the Local Planning Authority, the head lessee and Historic England regarding the repair of the listed building and use of the site.

Contact: Eve Van Der Steen 01179750685

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

SITE NAME:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME: Marshwood Castle, Marshwood Scheduled Monument and Listed DESIGNATION: Building grade II\*, LB grade II CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Private

The site comprises a rectangular earthwork enclosure with a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structures require consolidation and careful on-going management. The masonry is precarious and currently being eroded by both stock and vegetation.

© Historic England

LIST ENTRY NUMBER: 1002836 and 1324105 Contact: Katy Hoskyn 0117 975 1311



SITE NAME:	Icehouse at Ringstead, 660 metres south west of Pit House, Osmington
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

A small C19 icehouse, built to serve the needs of the local fishing community. It is now in unmanaged woodland, with trees and ivy growing over it. The roots will have weakened the roof and there is a high risk of damage from falling trees.

© Historic England

Private LIST ENTRY NUMBER: 1020358

Contact: Katy Hoskyn 0117 975 1311



© Historic England

SITE NAME:	Cart shed and stables 10 metres south of Waddon House, Portesham
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

Former stables and cart shed, dated 1702. Application for repair and conversion to holiday let use has been approved. The roof has been re-thatched, but other works still needed.

LIST ENTRY NUMBER: 1152606

LIST ENTRY NUMBER:

Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	Sherborne House, Newland, Sherborne
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority

1110694

formerly a school. Fine internal features such as the formal stairhall decorated with Thornhill wall paintings. Planning Permission for gallery/office use has been approved but reinstatement of residential use is still an option. External repairs completed but interior was damaged by dry rot, and refurbishment is still awaited whilst the building remains unoccupied. Enabling development works have included the installation of a lift/stair core at the rear of the house. Put on the market in early 2018.

Grand town house of c1720 with earlier elements,

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Tithe Barn, Church Lane, Sydling St. Nicholas
DESIGNATION:	Scheduled Monument and Listed Building grade II*, part in CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1003209 and 1119426

Impressive C16 barn. It has an interesting constructional history and is part of an important complex of historic buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Progress on finding a suitable use has stalled and part of the protective roof covering has become dislodged.

1003209 and 1119426

Contact: Sarah Ball 0117 975 0666

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Holditch Court Tower, Thorncombe
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1002835

This monument includes part of a fortified house situated within a farmyard. The part of the fortified house survives as a three-storeyed roofless rectangular plan tower with a projecting circular stair-turret in the south west angle and stands to a height of approximately eight metres. The tower is covered in ivy. There have been some falls of masonry into the interior. The corework in the former stair scar is exposed and decaying. Structural repairs may also be required. A project development grant is under discussion with the owner.

Contact: John Ette 0117 975 0687



© Historic England

SITE NAME:	Little Toller Farmhouse, Toller Fratrum
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1228875

Grade II\* Farmhouse attributed to John Samways of Winterborne St Martin in mid C16, which contains a rare domestic example of a barrel roof intended to support a decorative plaster ceiling. The building is part of a very interesting complex of buildings including the Grade II\* Stable block. Following a serious fire in July 2015 the roof and upper floor was extensively damaged. Listed building consent for reinstatement was granted and repairs commenced later in 2017. By the end of May 2018 external and structural repairs were largely finished but internal plasterwork is still to be completed.

Contact: Jenny Chesher 0117 975 0686



© Historic England

SITE NAME:	Stable Block immediately south east of Little Toller Farm, Toller Fratrum
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Mid C16 stable building, forming part of a working farm but currently disused. The thatch is in a very degraded state leading to partial collapse of the roof and rear wall structure at the end of 2011. The stable building has been scaffolded with a temporary roof structure which is protecting the collapsed historic fabric. The long term repair of the structure needs to be explored along with possible funding sources.

Former Methodist church, c1818, and the meeting place of the Tolpuddle Martyrs. Building bought by Tolpuddle Old Chapel Trust at the beginning of 2015. Historic England grant awarded in 2014 to carry out emergency works and undertake project development work; works were

completed in spring 2015. Heritage Lottery Fund grant offered in 2017. Historic England offered grant in May 2017

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Former Methodist Chapel, Dorchester Road, Tolpuddle
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1119849

1228876

for repairs to fabric of former chapel. Project development is now underway.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Church of St John, The Harbour, West Bay, Bridport
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1279418

This 1930s Arts and Crafts church is a simple, low building on the quayside, built to serve the local fishing community. Since it was added to the Heritage at Risk register in 2014, the congregation have made very good progress. Although there are still some areas of damp, and the leaded windows are leaking, the roofs have been repaired and the building is beginning to dry out. Some further work is needed but it is improving.

Contact: Katy Hoskyn 0117 975 1311

# PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Lindon repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:



© Marcus Chantrey, Benjamin Beauchamp Architects

© Historic England

SITE NAME:	Church of St Andrew, The Street, Charmouth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1215162

Parish church. Entirely rebuilt 1836-8, by Charles Fowler in Gothic Revival style. Nave, north and south aisles, north porch, south vestry, chancel slightly projecting and 21 metre high three-stage west tower. Forest marble plinth, chert rubble walls with "long-and-short style" stone dressings. Window dressings of Beer stone. Boscastle slate roofs; nave has tiled ridge. Tower and church walls are cement pointed which is failing causing water ingress. Works are planned and funding being sought to address the water ingress and damage caused.

Contact: Sarah Ball 0117 975 0666

2
MA

SITE NAME: Parish Church of St Andrew, Trent Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: B (B) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1323927

Medieval church with a richly decorated interior. There is internal damp, and structural work to the tower and spire is needed. The church also has important and high quality medieval and Victorian window glass, some of which is showing signs of structural instability and paint detachment. A trial of isothermal glazing has taken place with positive results and advice was provided by Historic England in 2015 regarding formal application of this approach to create a more controlled and stable climate. The congregation is seeking funding for the agreed glazing works.

Contact: Sarah Ball 0117 975 0666

SITE NAME: Abbotsbury Castle (camp), Abbotsbury				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002710	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670	
SITE NAME:	Four bowl barrows 725 metres ESE of Wears Farm	, Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002825	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670	
SITE NAME: Group of five round barrows on White Hill, Abbotsbury				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003213	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670	
SITE NAME:	Round barrow 230 yards (210 metres) east of White Hill Plantation, Abbotsbury			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002824	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670	

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Two fishponds in Oddens Wood, Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015696
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670
SITE NAME:	Two round barrows on Wears Hill, Abbotsbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Keith Miller 0117 975 0670
SITE NAME:	Barrow east of Burnt House Bottom, Alton Pancra	as	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002862
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Earthwork 80 yards (70 metres) long, north west of	of Coombe Bottom	ı, Askerswell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002734
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north west of Coombe Bottom, As	skerswell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003061
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Beaminster Down 530 metres so	uth east of East Ax	noller Farm, Beaminster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015049
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Beaminster Down 770 metres no	orth east of Higher	Meerhay Farm, Beaminster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015050
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Roman villa south east of East Farm, Bradford A	bbas	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002414
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow in Highfield Plantation and two bow Bradford Peverell	l barrows immediately	y north west of Forty Acre Plantation
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019415
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 380 metres west of Whitfield Farm	n, Bradford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows in Seven Barrow Plantation, E	Bradford Peverell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002812
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Long barrow and four bowl barrows 500 metre	s north west of Whitf	ield Farm, Bradford Peverell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019416
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Discontinuous surviving sections of Roman aque	duct, Bradford Pevere	ell / Dorchester
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002730
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Culliford Tree long barrow and group of round	barrows, Broadmayne	e / Whitcombe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003304
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Two bowl barrows on Lord's Down 580 i	metres south east of Crawth	orne Farm, Burleston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017277
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Wood Hill 310 metres n	orth east of Cowden, Charr	ninster
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019395
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Round barrow east of Forston Farm, Cha	rminster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002851
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Cheselbourne West Do	own, Cheselbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002878
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 360 metres south of Compt	on Barn, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019741
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Settlement south east of Soaper's Hill Plan	ntation, Compton Valence	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003234
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 450 metres east of Dennet's	Bottom Barn, Dewlish	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015427
CONDITION:	Extensive significant problems	TREND:	Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:		CONTACT	Katy Hoskyn 0117 975 1311
	Private	CONTACT:	
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Bowl barrow 550 metres WNW of West		Nacy Hoskyll OTT7 773 1311
OWNER TYPE: SITE NAME:			1015032
OWNER TYPE: SITE NAME:	Bowl barrow 550 metres WNW of West	End Barn, Dewlish	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Bowl barrow 550 metres WNW of West	End Barn, Dewlish  LIST ENTRY NUMBER:	1015032
OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Bowl barrow 550 metres WNW of West Scheduled Monument Extensive significant problems	End Barn, Dewlish  LIST ENTRY NUMBER:  TREND:	1015032 Declining

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Earthwork east of Stake Farm, East Chelborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002845
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bell barrow and five bowl barrows 1000 metres round barrow cemetery, Kingston Russell / Little	south east of Kingsto bredy	on Russell Farm, part of the Black Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 600 metres west of Well Bottom \ cemetery, Littlebredy	Vood, forming part o	of the Pitcombe Down round barrow
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013249
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three bowl barrows 300 metres south west of vound barrow cemetery, Littlebredy	Well Bottom Wood,	forming part of the Pitcombe Down
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013251
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow 550 metres north east of Pitcombe Littlebredy / Kingston Russell	Farm, part of the Bla	ack Down round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Lambert's Castle: an Iron Age hillfort 425 metre: post-medieval fair and a telegraph station, Marsh	west of Nash Farm,	with a bowl barrow, and the sites of a
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017035
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Keith Miller 0117 975 0670
SITE NAME:	Earthwork and ancient fields south east of Lysco	mbe Bottom, Melcon	nbe Horsey / Cheselbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002456
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Ancient settlement south west of Incombe Wood,	Nether Cerne	
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1002438
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Keith Miller 0117 975 0670
ITE NAME:	Bowl barrow 230 metres north east of Great Stro	de House, Netherb	oury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016372
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Upton Fort, a coastal artillery battery and two sea	rchlight emplaceme	nts, Osmington
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1021435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Four barrows on Moigns Down, Owermoigne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow south west of Bourne Farm, Piddlel	hinton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004550
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows on Little Puddle Hill, Piddlehinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003224
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows west of Little Piddle Down, Piddlehi	nton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002805
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Bowl barrow on Plush Hill 600 metres ESE of Lowe	er Farm, Plush, Pide	dletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015037
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
WNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
TE NAME:	Bowl barrow on Pond Eweleaze 500 metres north	east of Dole's Ash	Farm, Piddletrenthide
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015035
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 131
ITE NAME:	Round barrow on Hog Leaze, Piddletrenthide		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003238
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131
ITE NAME:	Pilsdon Pen hillfort and associated remains, Pilsdon		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019394
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Keith Miller 0117 975 0670
ITE NAME:	Round barrow north east of Friar Waddon, Portes	ham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 131
ITE NAME:	Two round barrows on Ridgeway, Portesham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 131
SITE NAME:	Barrow near east boundary of parish, Powerstock		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002809
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 131

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME: Group of barrows east of Northdown Barn, Poxwell  DESIGNATION: Scheduled Monument, part in CA  LIST ENTRY				
DESIGNATION: Scheduled Monument, part in CA LIST ENTRY	·			
	NUMBER:   002770			
CONDITION: Extensive significant problems TREND:	Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR	110			
OWNER TYPE: Commercial company CONTACT:	Katy Hoskyn 0117 975 1311			
Bowl barrow on Little Puddle Hill, 920 metres north west of	Fidler's Green Farm, Puddletown			
DESIGNATION: Scheduled Monument LIST ENTRY	NUMBER: 1017261			
CONDITION: Extensive significant problems TREND:	Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR	Y?: No			
OWNER TYPE: Private CONTACT:	Katy Hoskyn 0117 975 1311			
Round barrow west of Druce Higher Barn, Puddletown				
DESIGNATION: Scheduled Monument LIST ENTRY	NUMBER: 1002874			
CONDITION: Extensive significant problems TREND:	Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR	Y?: No			
OWNER TYPE: Private CONTACT.	Katy Hoskyn 0117 975 1311			
Three round barrows on Puddletown Down, Puddletown				
DESIGNATION: Scheduled Monument LIST ENTRY	NUMBER: 1002450			
CONDITION: Extensive significant problems TREND:	Declining			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR	Y?: No			
OWNER TYPE: Private CONTACT:	Katy Hoskyn 0117 975 1311			
Two bowl barrows 320 metres south west of Laycock Dairy	Farm, Puddletown			
DESIGNATION: Scheduled Monument LIST ENTRY	NUMBER: 1017266			
CONDITION: Extensive significant problems TREND:	Declining			
CONDITION: Extensive significant problems TREND:	Deciming			
- · · · · · · · · · · · · · · · · · · ·				
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR	Y?: No			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR  DWNER TYPE: Private CONTACT:	No Katy Hoskyn 0117 975 1311			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR DWNER TYPE: Private CONTACT:  ITE NAME: Two round barrows south west of Well House Cottage, Pud	No Katy Hoskyn 0117 975 1311			
Arable ploughing  NEW ENTR  DWNER TYPE:  Private  CONTACT:  SITE NAME:  Two round barrows south west of Well House Cottage, Pud  DESIGNATION:  Scheduled Monument  LIST ENTRY	No Katy Hoskyn 0117 975 1311			
PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR DWNER TYPE:  Private  CONTACT:  SITE NAME:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY CONDITION:  Extensive significant problems  TREND:	No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875  Declining			
Arable ploughing  NEW ENTR  DWNER TYPE:  Private  CONTACT:  Two round barrows south west of Well House Cottage, Pud  DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Extensive significant problems  TREND:  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875 Declining Y2: No			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Extensive significant problems  TREND: PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR  DWNER TYPE:  Private  CONTACT:	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875 Declining  Y?: No Katy Hoskyn 0117 975 1311			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  SITE NAME:  Two round barrows south west of Well House Cottage, Pud  DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Extensive significant problems  TREND:  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR  OWNER TYPE:  Private  CONTACT:  SITE NAME:  Bowl barrow 400 metres north east of Look Farm, Puncknow	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Extensive significant problems  TREND:  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR  CONTACT:  SITE NAME:  Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Generally unsatisfactory with major localised  TREND:	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  SITE NAME:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY CONDITION:  Extensive significant problems  TREND: PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR DOWNER TYPE:  Private  CONTACT:  SITE NAME:  Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION:  Scheduled Monument  LIST ENTRY CONDITION:  Generally unsatisfactory with major localised problems	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY  CONDITION:  Extensive significant problems  TREND:  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR  DWNER TYPE:  Private  CONTACT:  BOWL BARROW  DESIGNATION:  Scheduled Monument  LIST ENTRY  CONTACT:  CONT	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875  Declining  Y?: No Katy Hoskyn 0117 975 1311  vle  NUMBER: 1016370  Declining  Y2: No  No  No  No  No  No  No  No  No  No			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  CONTACT:  Two round barrows south west of Well House Cottage, Pud DESIGNATION:  Scheduled Monument  LIST ENTRY CONDITION:  Extensive significant problems  TREND: PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTR DOWNER TYPE:  Private  Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION:  Scheduled Monument  LIST ENTRY CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  NEW ENTR CONTACT  CONTACT  CONTACT  TREND: PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  NEW ENTR CONTACT	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR DOWNER TYPE: Private CONTACT  SITE NAME: Two round barrows south west of Well House Cottage, Pud DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Extensive significant problems TREND: PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR DOWNER TYPE: Private CONTACT:  SITE NAME: Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTR DOWNER TYPE: Private CONTACT:  SITE NAME: Bell barrow 70 metres west of Fidler's Green, Stinsford	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR DOWNER TYPE: Private CONTACT  SITE NAME: Two round barrows south west of Well House Cottage, Pud DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Extensive significant problems TREND: PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR DOWNER TYPE: Private CONTACT  SITE NAME: Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTR DOWNER TYPE: Private CONTACT  SITE NAME: Bell barrow 70 metres west of Fidler's Green, Stinsford DESIGNATION: Scheduled Monument LIST ENTRY DOWNER TYPE: Private CONTACT  SITE NAME: Bell barrow 70 metres west of Fidler's Green, Stinsford DESIGNATION: Scheduled Monument LIST ENTRY	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR OWNER TYPE: Private CONTACT  Two round barrows south west of Well House Cottage, Pud DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Extensive significant problems TREND: PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTR OWNER TYPE: Private CONTACT  SITE NAME: Bowl barrow 400 metres north east of Look Farm, Puncknow DESIGNATION: Scheduled Monument LIST ENTRY CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTR OWNER TYPE: Private CONTACT  SITE NAME: Bell barrow 70 metres west of Fidler's Green, Stinsford DESIGNATION: Scheduled Monument LIST ENTRY Generally unsatisfactory with major localised DESIGNATION: Scheduled Monument LIST ENTRY DESIGNATION: Scheduled Monument LIST ENTRY DESIGNATION: Scheduled Monument LIST ENTRY Generally unsatisfactory with major localised DESIGNATION: Scheduled Monument LIST ENTRY	Y?: No Katy Hoskyn 0117 975 1311  dletown  NUMBER: 1002875			

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Round barrow north east of Hog Hill Barn, Strattor	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003237
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow north west of Jackman's Cross, Strat	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002470
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Stratton Down, Stratton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002871
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
ITE NAME:	Earthworks on Loscombe Hill, Sydling St. Nicholas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002820
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on Eype Down 275 metres east of Fro	ogmore Farm, Sym	ondsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016100
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Holditch Court Tower, Thorncombe		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1002835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	John Ette 0117 975 0687
SITE NAME:	Four bowl barrows 710 metres north, 750 metres i Tolpuddle	north west and 950	metres north west of Clyffe House
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016378
CONDITION:	Extensive significant problems	TREND:	Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable plougring		
PRINCIPAL VOLNERABILITY:	Private	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Scheduled Monument	SITE NAME:	Dyke south east of Eggardon Hill camp, West Con	npton	
Market Ma	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002404
Private, multiple owners  Barrow near Eggardon, West Compton / Powerstock  Scheduled Monument  Generally unsatisfactory with major localised problems  Private, multiple owners  CONDITION:	CONDITION:	Extensive significant problems	TREND:	Declining
Barrow near Eggardon, West Compton / Powerstock  Scheduled Monument  TWO DOWN ATTIVE  Private, multiple owners  Scheduled Monument  Scheduled Monu	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTEX NUMBER  Generally unsatisfactory with major localised problems  RECEIVED Arable dipping  Arable dipping  Private, multiple owners  Two bowlb barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  SEGMANDIAN  The Scheduled Monument  Two bowlb barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  SEGMANDIAN  Scheduled Monument  Two bowlb barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  SEGMANDIAN  Scheduled Monument  Two bowlb barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  SEGMANDIAN  Scheduled Monument  Extensive significant problems  Private  Enclosure on Mount Pleasant Hill, West Stafford / Dorrchester  SEGMANDIAN  Scheduled Monument  Extensive significant problems  Private  Extensive significant problems  Private  Extensive significant problems  Private  Extensive significant problems  Private  CONTACT:  Katy Hoskyn 0117 975 1311  CONTACT:  Katy Hoskyn 0117 975 1	OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
Generally unsatisfactory with major localised problems  RRECOMMENTATE  Arable clipping  RRECOMMENTATE  Private, multiple owners  CONTACT:  Katy Hoskyn 0117 975 1311  THE NAME:  Two bowl barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  CONGRIGHON:  Scheduled Monument  Extensive significant problems  TREND:  Declining  RRECOMMENTATE  Arable ploughing  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMMENTATE  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  RECOMMENTATE  RECOMME	ITE NAME:	Barrow near Eggardon, West Compton / Powersto	ock	
problems pro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004567
Development Private, multiple owners Contact: Katy Hoskyn 0117 975 1311  The home bown barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  DESIGNATION Scheduled Monument UST INTRIVIDUAL 1019875  DECIDING  Extensive significant problems THEND: Declining  MININGRAL VALUERABILITY: Arable ploughing New PATHY: No  CONTACT: Katy Hoskyn 0117 975 1311  THEND: Declining  MININGRAL VALUERABILITY: Arable ploughing New PATHY: No  CONTACT: Katy Hoskyn 0117 975 1311  THEND: Declining  THEND:	CONDITION:		TREND:	Declining
Two bowl barrows on Frome Hill 520 metres west of Frome Farm, West Stafford  Scheduled Monument  Extensive significant problems  Extensive significant problems  Extensive significant problems  Extensive significant problems  RENDERAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  Private  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  Scheduled Monument  Extensive significant problems  Scheduled Monument  Extensive significant problems  Extensive significant problems  RENDERAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  CONTACT:  Katy Hoskyn 0117 975 1311  Declining  RENDERAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  CONTACT:  Katy Hoskyn 0117 975 1311  Declining  RENDERAL VULNERABILITY:  CONTACT:  Katy Hoskyn 0117 975 1311  Declining  RENDERAL VULNERABILITY:  CONTACT:  Katy Hoskyn 0117 975 1311  Declining  RENDERAL VULNERABILITY:  CONTACT:  Keith Miller 0117 975 0670  Declining  RENDERAL VULNERABILITY:  CONTACT:  Keith Miller 0117 975 0670  Declining  RENDERAL VULNERABILITY:  CONTACT:  Keith Miller 0117 975 0670  Declining  RENDERAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  Declining  RENDERAL VULNERABILITY:  No  Declining  RENDERAL VULNERABILITY:  No  Declin	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
SESIONATION Scheduled Monument UST ENTRY NUMBER 1019875  CONDITION Extensive significant problems TRIND: Declining  MINOPIAL YULKERBRUTY: Arable ploughing NEW PRIVEY: No  CONTACT: Kary Hoskyn 0117 975 1311  CENTRY NUMBER: Private Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  SEGIONATION: Scheduled Monument UST ENTRY NUMBER: 1002463  CENTRY NUMBER: Declining  RINGERIA YULKERBRUTY: Arable ploughing NEW INTRY: No  CONDITION: Extensive significant problems IREND: Declining  RINGERIA YULKERBRUTY: Arable ploughing NEW INTRY: NO  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1003208  CENTRY NUMBER: 1003408  CENTRY NUMBER: 1003418  CENT	OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
EXTENSIVE Significant problems  EXTENSIVE SIGNIFICAN  Arable ploughing  NEW ENTRY?:  Arable ploughing  NEW ENTRY?:  Arable ploughing  NEW ENTRY?:  Private  Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  EXECUATION:  Scheduled Monument  EXTENSIVE NUMBER:  1002463  TREND:  Declining  NEW ENTRY:  Arable ploughing  TRENAME:  Concy's Castle camp, Whitchurch Canonicorum  EXEGRATION:  Scheduled Monument  EXECUATION:  Scheduled Monument  EXECUATION:  Scheduled Monument  EXECUTION:  Contract:  Katy Hoskyn 0117 975 1311  Declining  NEW ENTRY:  No  WARRE TYPE:  Charity (heritage)  Contract:  Keith Miller 0117 975 0670  TRENAME:  Three bowl barrows \$30 metres and \$50 metres north east of Whitcombe  EXECUATION:  Scheduled Monument  UST ENTRY NUMBER:  1019413  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Keith Miller 0117 975 0670  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 975 1311  TREND:  Declining  RINGRAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  CONTACT:  Katy Hoskyn 0117 9	ITE NAME:	Two bowl barrows on Frome Hill 520 metres wes	t of Frome Farm, V	Vest Stafford
RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  FER NAME Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  ESIGNATION: Scheduled Monument LET ENTRY NUMBER 1002463  CONDITION: Extensive significant problems TILIND: Declining  RENCEIVAL VULNERABILITY: Arable ploughing NEW ENTRY: No  WATER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  FER NAME CONSTITUTE CONSTITUTE Private LUST ENTRY NUMBER 100320B  Generally satisfactory but with significant localised TREND: Declining  PRINCIPAL VULNERABILITY: Scrub/ tree growth NEW ENTRY: No  CONTACT: Keith Miller 0117 975 0670  FER NAME TYPE: Charity (heritage) CONTACT: Keith Miller 0117 975 0670  FER NAME Three bowl barrows \$30 metres and \$30 metres north east of Whitcombe Barn, Whitcombe  DESIGNATION: Extensive significant problems TREND: Declining  RENCEIVAL VULNERABILITY: No  CONTACT: Keith Miller 0117 975 0670  FER NAME Three bowl barrows \$30 metres and \$30 metres north east of Whitcombe Barn, Whitcombe  DESIGNATION: Extensive significant problems TREND: Declining  RENCEIVAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  FER NAME OVAL Barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  Broadmaryne Scheduled Monument LIST ENTRY NUMBER: 1019414  FER NAME OVAL BARROW: No  CONTACT: Katy Hoskyn 0117 975 1311  FER NAME Scheduled Monument LIST ENTRY NUMBER: 1019414  FER NAME OVAL BARROW: No  FER NAME NUMBER BUTY: No  FER NAME NO  FER NAME NO  FER NAME NUMBER BUTY: No  FER NAME NO  FER NAME NO  FER NAME NO  FER NAME NUMBER BUTY: No  FER NAME NO  FER NAME NUMBER BUTY: No  FER NAME NO  FER NAME NUMBER 100282B  FER NAME NUMBER 100282B  FER NAME NUMBER 100282B  FER NAME NUMBER 100282B  FER NAME NUMBER BUTY: No  FER NAME NUMBER 100282B  FER NAME NUMBER 100282B  FER NAME NUMBER 100282B	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019875
Devine Private Control Katy Hoskyn 0117 975 1311  STENAME: Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  Scheduled Monument LIST ENTRY NUMBER: 1002463  CONDITION: Extensive significant problems TREND: Declining  RENCIFIED VILLIERRABBILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private Control Scheduled Monument LIST ENTRY NUMBER: 1003208  SCHEDULTION: Scheduled Monument LIST ENTRY NUMBER: No  DOWNER TYPE: Charity (heritage) CONTACT: Keith Miller 0117 975 0670  STENAME: Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  SCHEDULTION: Extensive significant problems TREND: Declining  RENCIPAL VILLIERRABBILITY: No  DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BEGGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019413  STENAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BEGGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VILLIERRABBILITY: Arable ploughing NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Two round barrows north of Came Farm, Winterborne Came  SCHEDULTION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Two round barrows north of Came Farm, Winterborne Came  SCHEDULT VILLIERRABBILITY: Arable ploughing NEW ENTRY: No  Declining  SCHEDULT VILLIERRABBILITY: Arable ploughing NEW ENTRY: No	CONDITION:	Extensive significant problems	TREND:	Declining
Enclosure on Mount Pleasant Hill, West Stafford / Dorchester  Scheduled Monument  Extensive significant problems  RINCIPAL VILLIARRABILITY:  Arable ploughing  NEW ENTRY:  No  OWNER TYPE:  Coney's Castle camp, Whitchurch Canonicorum  Scheduled Monument  LIST ENTRY NUMBER:  CONTACT:  Katy Hoskyn 0117 975 1311  Scheduled Monument  LIST ENTRY NUMBER:  CONDITION:  Scheduled Monument  CONDITION:  Scheduled Monument  CONDITION:  Scheduled Monument  CONTACT:  Keith Miller 0117 975 0670  STENAME:  Charity (heritage)  CONTACT:  Keith Miller 0117 975 0670  SCHENAME:  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  BESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I 1019413  CONDITION:  Extensive significant problems  TREND:  Declining  RINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  OWNER TYPE:  CONTACT:  Katy Hoskyn 0117 975 1311  STENAME:  Declining  RINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  OVAL BARTOW and three bowl barrows 250 metres and 30 metres south of Whitcombe Barn, Whitcombe  Broadmayne  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  No  OVAL BARTOW and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  Broadmayne  Scheduled Monument  LIST ENTRY NUMBER:  No  OVAL BARTOW and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  Broadmayne  Scheduled Monument  LIST ENTRY NUMBER:  No  OWNER TYPE:  No  OWNER TYPE:  No  OWNER TYPE:  Private  CONTACT:  Katy Hoskyn 0117 975 1311  STENAME:  TREND:  Declining  NEW ENTRY:  No  OWNER TYPE:  Private  CONTACT:  Katy Hoskyn 0117 975 1311  STENAME:  TWO round barrows north of Came Farm, Winterborne Came  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  Declining  NEW ENTRY:  No  OWNER TYPE:  Private  OWNER TYPE:  No  OWNER TYPE:	'RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRY NUMBER 1002463  CONDITION: Extensive significant problems TREND: Declining  Private Condition: New ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STENAME Coney's Castle camp, Whitchurch Canonicorum  Scheduled Monument UST ENTRY NUMBER: 1003208  Generally satisfactory but with significant localised problems  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1003208  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1003208  CONDITION: Scheduled Monument UST ENTRY NUMBER: 1003208  CONTACT: Keith Miller 0117 975 0670  Charity (heritage) CONTACT: Keith Miller 0117 975 0670  STENAME Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe DESIGNATION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmanne  SEGNATION: Scheduled Monument UST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmanne  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002828	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems TREND. Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DWNER TYPE: Private CONFACT: Katy Hoskyn 0117 975 1311  STENAME: Coney's Castle camp, Whitchurch Canonicorum  SESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1003208  CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No  DWNER TYPE: Charity (heritage) CONTACT: Keith Miller 0117 975 0670  STENAME: Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe Barsinguisticant problems  TREND: Declining  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Broadmayne  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems and 330 metres south of Whitcombe Barn, Whitcombe Broadmayne  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Trend: Trend: CONTACT: Katy Hoskyn 0117 975 1311  STENAME: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002828  DOWNER TYPE: Three Trend: Declining  RINCIPAL VULNERABILITY: Arable ploughing  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument  UST ENTRY NUMBER: 1002828  DONNER TYPE: Declining  RINCIPAL VULNERABILITY: Arable ploughing  RINCIPAL VULNERABILITY: No	ITE NAME:	Enclosure on Mount Pleasant Hill, West Stafford /	Dorchester	
Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Coney's Castle camp, Whitchurch Canonicorum  Scheduled Monument UST ENTRY NUMBER: 1003208  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No  OWNER TYPE: Charity (heritage) CONTACT: Keith Miller 0117 975 0670  THE NAME: Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1019413  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BEGINATION: Scheduled Monument UST ENTRY NUMBER: 1019414  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OVAL Barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Two round barrows north of Came Farm, Winterborne Came  SESGNATION: Scheduled Monument UST ENTRY NUMBER: 1002828  EXENSIVE TYPE: Two round barrows north of Came Farm, Winterborne Came  SESGNATION: Scheduled Monument UST ENTRY NUMBER: 1002828  EXENSIVE EXTENSIVE Significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002463
Private Coney's Castle camp, Whitchurch Canonicorum  SESGNATION: Scheduled Monument UST ENTRY NUMBER 1003208  CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No  CONTACT: Keith Miller 0117 975 0670  THE NAME: Three bowl barrows 530 metres and 350 metres north east of Whitcombe  SESGNATION: Scheduled Monument UST ENTRY NUMBER 1019413  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DEVINER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BESGNATION: Scheduled Monument UST ENTRY NUMBER 1019413  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BESGNATION: Scheduled Monument UST ENTRY NUMBER 1019414  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BESGNATION: Scheduled Monument UST ENTRY NUMBER 1019414  THE NAME: Two round barrows north of Came Farm, Winterborne Came  BESGNATION: Scheduled Monument UST ENTRY: No  DECINING  THE NAME: Two round barrows north of Came Farm, Winterborne Came  BESGNATION: Scheduled Monument UST ENTRY NUMBER 1002828  TONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  DECLINING  THE NAME: Two round barrows north of Came Farm, Winterborne Came  BESGNATION: Scheduled Monument UST ENTRY NUMBER 1002828  DONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  Declining	CONDITION:	Extensive significant problems	TREND:	Declining
THE NAME: Coney's Castle camp, Whitchurch Canonicorum  Scheduled Monument  Scrub/tree growth  New Entry:  No  Declining  RINCIPAL VULNERABILITY:  Scrub/tree growth  New Entry:  No  Declining  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  Scheduled Monument  Schedule	RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1003208  CONDITION: Generally satisfactory but with significant localised problems  RENCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY!: No  CONTACT: Keith Miller 0117 975 0670  ATTEND: CONTACT: Keith Miller 0117 975 0670  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019413  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe  BESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Katy Hoskyn 0117 975 1311  THE NAME: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Katy Hoskyn 0117 975 1311  TWO round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  RENCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Generally satisfactory but with significant localised problems  Scrub/tree growth  NEW ENTRY!: No  OWNER TYPE: Charity (heritage)  CONTACT: Keith Miller 0117 975 0670  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe Sesignation: Scheduled Monument  Extensive significant problems  RINCIPAL VULNERABILITY: Arable ploughing  RINCIPAL VULNERABILITY: Arable ploughing  CONDITION: Scheduled Monument  Extensive significant problems  RINCIPAL VULNERABILITY: No  OWNER TYPE: Private  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311	SITE NAME:	Coney's Castle camp, Whitchurch Canonicorum		
problems  Scrub/tree growth  NEW ENTRY?:  No  DWNER TYPE:  Charity (heritage)  CONTACT:  Keith Miller 0117 975 0670  STE NAME:  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1019413  CONDITION:  Extensive significant problems  TREND:  Declining  RINGIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  DWNER TYPE:  Private  Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmayne  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  1019414  CONDITION:  Extensive significant problems  TREND:  Declining  NEW ENTRY?:  No  Declining  NEW ENTRY NUMBER:  1019414  CONDITION:  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  I MO 200428  DECIDING  TWO round barrows north of Came Farm, Winterborne Came  DESIGNATION:  Scheduled Monument  UST ENTRY NUMBER:  I MO 202828  CONDITION:  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No  Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003208
Charity (heritage)  CONTACT: Keith Miller 0117 975 0670  Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe Sesionation: Scheduled Monument  Extensive significant problems  RINCIPAL VULNERABILITY: Arable ploughing  CONDITION:  CONTACT:  CONTA	CONDITION:		TREND:	Declining
Three bowl barrows 530 metres and 350 metres north east of Whitcombe Barn, Whitcombe Science Scheduled Monument LIST ENTRY NUMBER: 1019413  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Katy Hoskyn 0117 975 1311  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Katy Hoskyn 0117 975 1311  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No  CONTACT: Katy Hoskyn 0117 975 1311  CONTACT: Came	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Scheduled Monument  Extensive significant problems  TREND: Declining  NEW ENTRY?: No  Development  Trend: Development  No  Development  Develop	OWNER TYPE:	Charity (heritage)	CONTACT:	Keith Miller 0117 975 0670
Extensive significant problems  TREND: Declining  NEW ENTRYP: No  Arable ploughing  NEW ENTRYP: No  CONTACT: Katy Hoskyn 0117 975 1311  TENAME: Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmayne  Scheduled Monument  Extensive significant problems  TREND: Declining  NEW ENTRYP: No  Extensive significant problems  TREND: Declining  NEW ENTRYP: No  CONTACT: Katy Hoskyn 0117 975 1311  TWO round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument  Extensive significant problems  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  No  Declining  TREND: Declining  No  Declining  TREND: Declining  No  Declining  No  No  No  No  No  No  No  No  No  N	ITE NAME:	Three bowl barrows 530 metres and 350 metres r	orth east of Whitc	ombe Barn, Whitcombe
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmayne  Designation: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  TENAME: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019413
Owner type:  Designation:  Des	CONDITION:	Extensive significant problems	TREND:	Declining
Oval barrow and three bowl barrows 250 metres and 330 metres south of Whitcombe Barn, Whitcombe Broadmayne  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Katy Hoskyn 0117 975 1311  ATENAME: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Broadmayne  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019414  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DEVINER TYPE: Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems  TREND:  Declining  No  PRINCIPAL VULNERABILITY:  Arable ploughing  Private  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  No  LIST ENTRY NUMBER:  1002828  EXTEND:  Declining  No	ITE NAME:			uth of Whitcombe Barn, Whitcombe
Arable ploughing  Private  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION:  Scheduled Monument  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No  CONTACT:  Katy Hoskyn 0117 975 1311  LIST ENTRY NUMBER:  1002828  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY?:  No	DESIGNATION:	•	LIST ENTRY NUMBER:	1019414
Private CONTACT: Katy Hoskyn 0117 975 1311  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Private CONTACT: Katy Hoskyn 0117 975 1311  Two round barrows north of Came Farm, Winterborne Came  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	RINCIPAL VULNERABILITY:	·	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002828  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:		CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	ITE NAME:	Two round barrows north of Came Farm, Winterl	oorne Came	
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002828
1 3 3	CONDITION:	Extensive significant problems	TREND:	Declining
	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:		CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

CONTROLLED   Controlled Monument   Lat Topins Number   Declining	SITE NAME:	Long barrow immediately north west of Maiden	Castle, Winterborne	Monkton
PRESCRIPTION VALIMENABILITY  Arable ploughing  Convent TYPE  Crown  Contract:  Kary Hoskyn 0117 975 1311  Line Numbe.  Ling barrow, three bell barrows, fancy barrow and a linear earthwork 800 metres north of Maiden Castle, Winterborne Monkton  PRESCRIPTION  Scheduled Monument  Extensive significant problems  Prescription  Contract:  Kary Hoskyn 0117 975 1311  Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton  CONTRACT:  Kary Hoskyn 0117 975 1311  Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton  CONTRACT:  Kary Hoskyn 0117 975 1311  Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton  CONTRACT:  Kary Hoskyn 0117 975 1311  Extensive significant problems  Those  CONTRACT:  Kary Hoskyn 0117 975 1311  CONTRACT:  CONTRACT:  Kary Hoskyn 0117 975 1311  CONTRACT:  CONTRACT:  Kary Hoskyn 0117 975 1311  CONTRACT:  C	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015779
Crown Crown Contract: Katy Hoskyn 0117 975 1311  Long barrow, three bell barrows, fancy barrow and a linear earthwork 800 metres north of Maiden Castle, Winterborne Monkton  Scheduled Monument  Extensive significant problems  REVENTANT: No  CONTRACT: Katy Hoskyn 0117 975 1311  Crown  Crown  Crown  Contract: Katy Hoskyn 0117 975 1311  Crown  Contract: Katy Hoskyn 0117 975 1311  Crown  Contract: Katy Hoskyn 0117 975 1311  Control Castle, Winterborne Monkton  Contract: Katy Hoskyn 0117 975 1311  Control Castle, Winterborne Monkton  Contract: Katy Hoskyn 0117 975 1311  Control Castle, Winterborne Monkton  Control Castle, Winterborne St. Martin  Control Castle	CONDITION:	Extensive significant problems	TREND:	Declining
Long barrow, three bell barrows, fancy barrow and a linear earthwork 800 metres north of Malden Casde, Winterborne Monkton  Scheduled Monument  ESTANTIONE  Scheduled Monument  Detailing  New Histor  Arable ploughing  New Histor  Scheduled Monument  DETAILING  Round barrow cemetery immediately south east of Maiden Caste, Winterborne Monkton  Scheduled Monument  DESCRIPTIONE  Scheduled Monument  DETAILING  Detailing  New Histor  No  Detailing  No  Detail	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Winterborne Monkton Scheduled Monument Scheduled Monument Extensive significant problems PRENCIPAL VALIMENABULTY Arable ploughing NAMINENTE Crown Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NAMINENTE Crown Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NAMINENTE Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton Scheduled Monument Elicitation Scheduled Monument Arable ploughing NEW PAINTE No Declining NAMINENTE Private, multiple owners Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NEW PAINTE No Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NEW PAINTE No Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NEW PAINTE No Contract: Contract: Contract: Katy Hoskyn 0117 975 1311  Arable ploughing NEW PAINTE No Contract: Contr	OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems IRRND Declining NEWENTAME Arable ploughing NEWENTAME No CONTACT: Katy Hoskyn 0117 975 1311  STENANTE Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton Editionation Scheduled Monument IST ENTRY NAMED Declining REBISCIANATION Scheduled Monument IST ENTRY NAMED DECIDING Extensive significant problems IRRND Declining NEWENTAME NO CONSISTENCY VILLEARABILITY: Arable ploughing NEWENTAME NO CONSISTENCY VILLEARABILITY: Arimal burrowing - extensive New New New New New New New New New Ne	SITE NAME:		and a linear earthworl	k 800 metres north of Maiden Castle
Arable ploughing NEW ENTRY: No CONNACT: Katy Hoskyn 0117 975 1311  STENAME: Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton  DESIGNATION: Scheduled Monument  Extensive significant problems  Scheduled Winterborne Scheduled Monument  Extensive significant problems  Selegatory: No CONNACT: Katy Hoskyn 0117 975 1311  STENAME: Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  DESIGNATION: Scheduled Monument  Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  DESIGNATION: Scheduled Monument  Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  DESIGNATION: Scheduled Monument  Scheduled Monument  Scheduled Monument  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Scheduled Monument  Separatly unsatisfactory with major localised problems  Scheduled Monument  Separatly unsatisfactory with maj	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015783
COVENANTE: Crown CONTACT: Kary Hoskyn 0117 975 1311  STENAME Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton  Scheduled Monument Ust Enter Names: Declining  Renderal Voluntariability: No  Scheduled Monument  Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  Declining  Declining  Renderal Voluntariability: No  CONTACT: Renderal Volun	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton DESIGNATION Scheduled Monument USI ENTRY NUMBER 1015778 Declining RESCHANCE CONDITION Extensive significant problems TREND: Declining NEW ENTRY: No OWNERT THE Private, multiple owners CONTACT: Katy Hoskyn 0117 975 1311 STET NUMB: Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester DESIGNATIONE Scheduled Monument USI TRITITY NUMBER 1002409  CONDITION: Problems Problems PRESCHAL VULNERABILITY: Arable ploughing NEW ENTRY: CONNINCE CONTACT: Katy Hoskyn 0117 975 1311  STETNAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin DESIGNATION Extensive significant problems PRESCHAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STETNAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin DESIGNATION: DESIGNATION: Scheduled Monument USI TRITITY NUMBER: DESIGNATION: DESIGNATION: Scheduled Monument USI TRITITY NUMBER: DESIGNATION: DESIGNATION: Scheduled Monument USI TRITITY NUMBER: DESIGNATION: DESIGNATION: DESIGNATION: Scheduled Monument USI TRITITY NUMBER: DESIGNATION: DESIGNATION: DESIGNATION: Scheduled Monument USI TRITITY NUMBER: DESIGNATION:	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument UST ENTRYNUMBERS 1015778  Declining MERICAL VULNERABUTY: Arable ploughing NEW ENTRY: No OWNER TYPE Private, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SETEMANTE Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester Designation Scheduled Monument UST ENTRYNUMBERS 1002409  CONDITION Scheduled Monument UST ENTRYNUMBERS 1002409  CONDITION Generally unsatifactory with major localised problems  Frencioral vulnerabuty: Arable ploughing New ENTRY: No OWNER TYPE Connection of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of barrows south of Goldsmith's Plantation. Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of Barrows south of Goldsmith's Plantation. Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of Found barrows near Eweleaze Barn, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows near Eweleaze Barn, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows near Eweleaze Barn, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows near Eweleaze Barn, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows near Eweleaze Barn, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows on and to east of Great Hill, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows on and to east of Great Hill, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows on and to east of Great Hill, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round barrows on and to east of Great Hill, Winterborne St. Martin Designation of Contract: Katy Hoskyn 0117 975 1311  SETEMANTE Group of round	OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems  Arable ploughing  New ENTRY:  Arable ploughing  New ENTRY:  Arable ploughing  New ENTRY:  Private, multiple owners  CONTACT:  Katy Hoskyn 0117 975 1311  Arable ploughing  RENCIPAL VULNEARBULTY:  Arable ploughing  New ENTRY:  Arable ploughing  New ENTRY:  Arable ploughing  New ENTRY:  Arable ploughing  RENCIPAL VULNEARBULTY:  Animal burrowing - extensive  RENCIPAL VULNEARBULTY:  Animal burrowing - extensive  CONTACT:  Katy Hoskyn 0117 975 1311  Arable ploughing  RENCIPAL VULNEARBULTY:  Animal burrowing - extensive  RENCIPAL VULNEARBULTY:  AND Declining  RENCIPAL VULNEARBULTY:  AND Declining  RENCIPAL VULNEARBULTY:  No  CONTACT:  Katy	SITE NAME:	Round barrow cemetery immediately south east	of Maiden Castle, W	interborne Monkton
Arable ploughting NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEINAME: Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002409  CONDITION: Generally unsatisfactory with major localised problems  PREMICIPAL VILLIARRABILITY: Arable ploughting NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 1311  STEINAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining  PREMICIPAL VILLIARRABILITY: Arable ploughting NEW ENTRY: No CONTACT: Katy Hoskyn 0117 975 1311  STEINAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PREMICIPAL VILLIARRABILITY: Animal burrowing - extensive significant problems  PREMICIPAL VILLIARRABILITY: Animal burrowing - extensive New Entrave: No CONNECTION: Extensive significant problems  PREMICIPAL VILLIARRABILITY: Animal burrowing - extensive New Entrave: No CONTACT: Katy Hoskyn 0117 975 1311  STEINAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1004564  CONTROLT: Katy Hoskyn 0117 975 1311  STEINAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1004564  CONTROLT: Katy Hoskyn 0117 975 1311  STEINAME: Round barrow north of Ridgeway, Winterborne St. Martin DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002759  DEClining DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002759  DEClining DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002759  DEClining DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002759  DECLINITED: Declining DESIGNATION: Scheduled Monument LISTENTRY NUMBER: 1002759  DECLINITED: Declining DESIGNATION: Scheduled Monument LISTE	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015778
OWNER TYPE Private, multiple owners  Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  Scheduled Monument  LIST ENTRY NUMBER: 1002409  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPIL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  Scheduled Monument  Extensive significant problems  Scheduled Monument  Extensive significant problems  TREND: Declining  RENDERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: OR OWNER TYPE: No  CONDITION: Extensive significant problems  TREND: Declining  RENDERABILITY: No  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002756  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  RENDERABILITY: Animal burrowing - extensive  NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004764  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: No  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Round barrows north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004759  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONTACT: Katy Hoskyn 0117 975 1311	CONDITION:	Extensive significant problems	TREND:	Declining
Settlement remains north of Maiden Castle, Winterborne Monkton / Dorchester  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002409  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLE VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining  PRINCIPLE VULNERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPLE VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004564  CONDITION: Extensive significant problems TREND: Declining  PRINCIPLE VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLE VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPLE VULNERABILITY: Arable ploughing  NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1002409  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing  REND: Declining  REND: No  CONTACT: Katy Hoskyn 0117 975 1311  STE NAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEWENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  STE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEWENTRY: No  CONDITION: Extensive significant problems CONTACT: Katy Hoskyn 0117 975 1311  STE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1004564  CONDITION: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEWENTRYE: No  CONTACT: Katy Hoskyn 0117 975 1311  STE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTITY NUMBER: 1002759  DESIGNATION: Scheduled Monument LIST ENTITY: NOMBER: 1002759  DESIGNATION: Scheduled Monument LIST ENTITY: NOMBER: 1002759	OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
Generally unsatisfactory with major localised problems  RRINCIPAL VULNERABILITY: Arable ploughing NEWENTRYP: No  OWNER TYPE Crown CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002810  Extensive significant problems TREND: Declining  RRINCIPAL VULNERABILITY: Arable ploughing NEWENTRYP: No  OWNER TYPE Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEENAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002756  Extensive significant problems TREND: Declining  RRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRYP: No  OWNER TYPE Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEENAME Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  Generally unsatisfactory with major localised problems  RRINCIPAL VULNERABILITY: No  OWNER TYPE Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEENAME ROUND BARNOW, MIXED NEWENTRYP: No  OWNER TYPE Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEENAME ROUND BARNOW, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  OWNER TYPE Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  STEENAME ROUND BARNOW, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  DECLINING NEWENTRYP: No  OWNER TYPE COMMERCIAL Scheduled Monument LIST ENTRY NUMBER: 1002759  DECLINING NEWENTRYP: No  OWNER TYPE COMMERCIAL SCHEDULE SCHE	SITE NAME:	Settlement remains north of Maiden Castle, Wir	nterborne Monkton /	Dorchester
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  DOWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  DOWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1004564  CONDITION: Principal VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002759  Extensive significant problems NEW ENTRY!: No  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002759  Extensive significant problems NEW ENTRY!: No  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1002759  Extensive significant problems NEW ENTRY!: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002409
Crown  Crown  Contact: Katy Hoskyn 0117 975 1311  STENAME: Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  Mixed, multiple owners  Contact: Katy Hoskyn 0117 975 1311  STENAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Mixed, multiple owners  Contact: Katy Hoskyn 0117 975 1311  STENAME: Group of round barrows and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  REVERTIFY: No  DOWNER TYPE: Mixed, multiple owners  Contact: Katy Hoskyn 0117 975 1311  STENAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive Scheduled Monument  Extensive Significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  New Entry: No  Commercial company, multiple owners  Contact: Katy Hoskyn 0117 975 1311  STENAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  REVERTIFY: No  DECLINING  EXTENAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  TREND: Declining  REVERTIFY: No  Declining  REVERTIFY: No  DECLINING  DECLINING  REVERTIFY: Number: 1002759  DECLINING  DECLIN	CONDITION:		TREND:	Declining
Group of barrows south of Goldsmith's Plantation, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  DOWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  DOWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY: NO  DOWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONTACT: ROUND REABILITY: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002810  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  CONNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  EXTENSIVE ROUND Scheduled Monument LIST ENTRY NUMBER: 1002759  EXTENSIVE Scheduled Monument LIST ENTRY NUMBER: 1002759  Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No	OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Mixed, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  FRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  OWNER TYPE: Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No	SITE NAME:	Group of barrows south of Goldsmith's Plantation	on, Winterborne St. N	<b>1</b> artin
Arable ploughing NEW ENTRY?: No  DWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	designation:	Scheduled Monument	LIST ENTRY NUMBER:	1002810
Mixed, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument  Extensive significant problems  REND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Mixed, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY): No  OWNER TYPE: No  Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: No  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY): No	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Group of round barrows near Eweleaze Barn, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  COWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1002756  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Mixed, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY): No  OWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY): No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
Extensive significant problems  FREND: Declining  Animal burrowing - extensive  Mixed, multiple owners  Croup of round barrows on and to east of Great Hill, Winterborne St. Martin  Designation: Scheduled Monument  Condition: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Commercial company, multiple owners  Round barrow north of Ridgeway, Winterborne St. Martin  Designation: Scheduled Monument  LIST ENTRY NUMBER: 1004564  CONTACT: No  CONTACT: Katy Hoskyn 0117 975 1311  EXTENSIVE ROUND ON TACT: Katy Hoskyn 0117 975 1311  EXTENSIVE ROUND ON TACT: Katy Hoskyn 0117 975 1311  EXTENSIVE ROUND ON TACT: CONTACT: C	SITE NAME:	Group of round barrows near Eweleaze Barn, V	Vinterborne St. Martir	1
Animal burrowing - extensive  Mixed, multiple owners  Group of round barrows on and to east of Great Hill, Winterborne St. Martin  Stename:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New Entry?:  No  Comparison:  Contact:  Katy Hoskyn 0117 975 1311  Declining  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New Entry?:  No  Commercial company, multiple owners  Contact:  Katy Hoskyn 0117 975 1311  Stename:  Round barrow north of Ridgeway, Winterborne St. Martin  Declining  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  1002759  CONDITION:  Extensive significant problems  New Entry?:  No  No  New Entry?:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002756
Mixed, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  Extensive significant problems  TREND: Declining  NO  NO  NO  NO  NO  NO  NO  NO  NO  N	CONDITION:	Extensive significant problems	TREND:	Declining
Group of round barrows on and to east of Great Hill, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Commercial company, multiple owners CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004564  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  SITE NAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY?: No	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New Entry?:  Commercial company, multiple owners  CONTACT:  Katy Hoskyn 0117 975 1311  Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LOO2759  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No	SITE NAME:	Group of round barrows on and to east of Grea	t Hill, Winterborne S	t. Martin
problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRY?: No  Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  EXTERNAME: Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004564
Commercial company, multiple owners  CONTACT: Katy Hoskyn 0117 975 1311  Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument  CONTACT: Katy Hoskyn 0117 975 1311  LIST ENTRY NUMBER: 1002759  Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: New ENTRY: No	CONDITION:		TREND:	Declining
Round barrow north of Ridgeway, Winterborne St. Martin  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1002759  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Round barrow north of Ridgeway, Winterborne	St. Martin	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002759
1 0 0	CONDITION:	Extensive significant problems	TREND:	Declining
OWNER TYPE: Crown CONTACT: Katy Hoskyn 0117 975 1311	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	OWNER TYPE:	Crown	CONTACT:	Katy Hoskyn 0117 975 1311

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Round barrows on Four Barrow Hill, Winterbor	ne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002755
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrows on Grove Hill, Winterborne St.	Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002757
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Three barrows south of Hart Hill Plantation, Wi	nterborne St. Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002814
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two barrows at Rew, Winterborne St. Martin		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002811
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of round barrows on Shorn Hill and Bron	ıkham Hill, Winterbo	rne St. Martin / Portesham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002699
CONDITION:	Generally satisfactory but with minor localised		Improving
	problems	TREND:	Improving
PRINCIPAL VULNERABILITY:		NEW ENTRY?:	No
	problems		
PRINCIPAL VULNERABILITY: OWNER TYPE:	problems  Dumping	NEW ENTRY?: CONTACT:	No Katy Hoskyn 0117 975 1311
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	problems  Dumping  Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne	NEW ENTRY?: CONTACT:	No Katy Hoskyn 0117 975 1311
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	problems  Dumping  Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas	NEW ENTRY?:  CONTACT:  Poor Lot, part of the	No Katy Hoskyn 0117 975 1311 Winterbourne Poor Lot round barrov
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	problems Dumping Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas Scheduled Monument Generally unsatisfactory with major localised	NEW ENTRY?:  CONTACT:  Poor Lot, part of the  LIST ENTRY NUMBER:	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrov 1012027
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	problems  Dumping  Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas  Scheduled Monument  Generally unsatisfactory with major localised problems	NEW ENTRY?:  CONTACT:  Poor Lot, part of the  LIST ENTRY NUMBER:  TREND:	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrow 1012027  Declining
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	problems Dumping Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas  Scheduled Monument Generally unsatisfactory with major localised problems Arable clipping	NEW ENTRY?:  CONTACT:  Poor Lot, part of the  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrow 1012027  Declining  No Katy Hoskyn 0117 975 1311
PRINCIPAL VULNERABILITY:	problems Dumping Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas Scheduled Monument Generally unsatisfactory with major localised problems Arable clipping Private  Bowl barrow 400 metres north east of Manor Fa	NEW ENTRY?:  CONTACT:  Poor Lot, part of the  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrow 1012027  Declining  No Katy Hoskyn 0117 975 1311
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	problems Dumping Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas Scheduled Monument Generally unsatisfactory with major localised problems Arable clipping Private  Bowl barrow 400 metres north east of Manor Fawinterbourne Abbas	NEW ENTRY?:  CONTACT:  Poor Lot, part of the  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  arm, part of the Pounce	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrov 1012027 Declining No Katy Hoskyn 0117 975 1311 d Hill round barrow cemetery,
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	problems Dumping Mixed, multiple owners  Bell barrow 100 metres south of Winterbourne cemetery, Winterbourne Abbas  Scheduled Monument  Generally unsatisfactory with major localised problems  Arable clipping  Private  Bowl barrow 400 metres north east of Manor Fawinterbourne Abbas  Scheduled Monument  Generally unsatisfactory with major localised	NEW ENTRY?: CONTACT:  Poor Lot, part of the LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  Arm, part of the Pounce LIST ENTRY NUMBER:	No Katy Hoskyn 0117 975 1311  Winterbourne Poor Lot round barrov 1012027 Declining No Katy Hoskyn 0117 975 1311  d Hill round barrow cemetery, 1011692

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

TERITAGE AT RISK 2016 / SOC	DIH MESI / MESI DOKSEI		
SITE NAME:	Bowl barrow 450 metres north east of Manor Fal Winterbourne Abbas	rm, part of the Poun	d Hill round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011691
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Triple barrow and bowl barrow forming part of a metres north east of Winterbourne Poor Lot, W		nd part of an associated field system 2
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012030
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two bell barrows 15 metres north of Well Botto Winterbourne Abbas	m Wood, part of th	e Poor Lot round barrow cemetery,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow in Well Bottom Wood, Winterbourne Abbas / Littlebredy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013255
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Four round barrows north west of Blagdon Barn, Winterbourne Steepleton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002750
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow on Pound Hill, Winterbourne Stee	Round barrow on Pound Hill, Winterbourne Steepleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002870
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Round barrow south west of village, Winterbour	ne Steepleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002751
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Katy Hoskyn 0117 975 1311

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  Slow decay; solution agreed but for tyet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOUTH	H WEST / WEST DORSE	T		
SITE NAME:	Round barrows	on Sheep Down, Winterbourne Ste	eepleton	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1003306
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two conjoined b	oowl barrows 550 metres north eas	st of Manor Farm,	Pound Hill, Winterbourne Steepleton
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1002687
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Two round barre	ows on North Hill, Winterbourne	Steepleton	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1002865
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	No
OWNER TYPE:	Commercial company		CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Group of barrows near Big Wood, Winterbourne St		Steepleton / Winte	erbourne Abbas
DESIGNATION:	Scheduled Monu	ment, part in RPG grade II	LIST ENTRY NUMBER:	1002696
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Bowl barrow on	e kilometre south west of Manor F	arm, Wraxall	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1015051
CONDITION:	Generally satisfact problems	ctory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Katy Hoskyn 0117 975 1311
	SITE NAME:	Kingston Maurward, Stinsford		ape around early C18 house with notable
	DESIGNATION:	Registered Park and Garden grade II*, 8 LBs, part in SM, part in CA	nucleus of expan buildings which in	iding land-based college. Many post-war mpact on view lines and appreciation of pe. In 2011 Natural England grant-aided
	CONDITION:	Generally satisfactory but with minor localised problems	restoration plan proposals appea	for part of the park. Further developmer r to have been shelved, for the present. remains of the view that a masterplan is
	VULNERABILITY:	High		e future development.
	TREND:	Stable		
© Historic England	NEW ENTRY?:	No		
	OWNER TYPE:	Educational (state sector)		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1000719

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Jo McAllister 0117 975 0696

# **ABBREVIATIONS**

OWNER TYPE:

LIST ENTRY NUMBER:

# WEYMOUTH AND PORTLAND



© Historic England Archive

SITE NAME:	Rufus Castle, Church Ope Road, Easton, Portland
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, LB grade II, CA, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C(C)

Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works carried out in 2010 with Historic England grant although more work is still needed. Site was sold in late 2016 and discussions with the new owner are at an early stage. The monument also includes the ruins of a C12 grade II church, St Andrews, believed to stand on the site of an earlier Saxon church.

LIST ENTRY NUMBER: 1002698 and 1280727; 1205384

Private

Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME:	Road, Grove, Portland
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1205607

Former Church of England church in robust Romanesque style, erected in 1872. Designed by Major General Edmund du Cane, built by convict labour from Portland's prison and later transferred to the parish. No longer used for worship and in poor condition. Relatively complete interior of interest as an undivided space and with robust contemporary fittings. Local Authority considering taking action against owner.

Contact: Eve Van Der Steen 01 179750685



© Historic England

SITE NAME:	Maiden Street Methodist Church, Maiden Street, Weymouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1142294

Former Methodist church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent was granted in 2007 but not implemented for conversion / reconstruction to mixed residential and commercial use. The site changed hands in 2016. Historic England is in discussions with the new owner regarding the options available to them.

Contact: Eve Van Der Steen 01 179750685

SITE NAME:	Group of round barrows on Ridgeway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002760
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Battery 200 yards (180 metres) east of the Naval ce	emetery, Portland	
SITE NAME:  DESIGNATION:	Battery 200 yards (180 metres) east of the Naval co	emetery, Portland	1002412
	, , , , , ,	,	1002412 Declining
DESIGNATION:	Scheduled Monument, LB grade II  Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise. New Entry is noted).

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG

**ABBREVIATIONS** 

SITE NAME:	Mesolithic sites near Culver Well, Portland		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1002406
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Weymouth Town Centre		
DESIGNATION:	Conservation Area, 211 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Paul Wyeth (LPA) 01305 838264

# **GLOUCESTERSHIRE**

# **CHELTENHAM**



Church of St Mark, Church Road, Cheltenham

DESIGNATION: Listed Place of Worship grade II

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1386790

Parish church built in 1860-6 by John Middleton, with transepts of 1888. Drilled Cotswold stone with Bath stone quoins and dressings, Forest of Dean stone forming alternating polychromy in voussoirs (wedge shaped stones), red tile roof. Gothic Revival, Decorated style. Nave roof is in poor condition. Plain clay tile loss on the north vestry and chancel roofs were repaired in 2015. Water ingress in some areas is exacerbating the poor condition of the interior.

Contact: Chris Miners 0117 975 1308

© Historic England



© Historic England

SITE NAME:	Church of St Luke, College Road, Cheltenham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
I IST ENITRY NII IMRER-	1207000

Church built in 1853-4 by Frederick W Ordish, partly intended for schoolboys from nearby Cheltenham College. Drilled Cotswold stone with ashlar quoins and dressings and with plain tile roof. Middle Pointed style. Cruciform plan with west tower; four-bay aisled nave with clerestory and south porch, crossing with north and south transepts, four-bay chancel with south Lady Chapel, north vestry. West tower has heavily broached spire. The roof covering is in poor condition and the interior is damaged by water ingress. The rainwater goods have been repaired in 2016.

Contact: Chris Miners 0117 975 1308

# COTSWOLD



© Historic England Archive

SITE NAME:	Elizabeth Pengree Memorial, The Square, Blockley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1341728

Commemorative monument (1770s) decaying on one side and the railings are displaced and in poor condition. Basic maintenance has been undertaken, but no significant repairs.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Auth

LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Alfreds Hall, Cirencester Park, Cirencester
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1298719

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the earliest C18 mock-Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood. The building is in very bad condition and continues to deteriorate.

Contact: Alessandra Perrone 0117 975 1345

Mary Mary	
Alkan	
	ř
	7
THE RESERVE OF SHIPPING	
	1
COUNTY OF THE PARTY OF THE PART	

© Historic England

SITE NAME:	Dovecote at the Manor House, Lower Slaughter
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Commercial company

1341062

stone roof. This large dovecote hosts two separate columbaria inside, built of nesting boxes from ground to the roof. It is currently without a use and in poor condition. Both the roof structure and its coverings are suffering from deterioration following the loss of some stone tiles around a lantern. Some emergency repairs are planned for summer 2018.

A late C16 structure of coursed rubble and Cotswold

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Church of St Peter, Daylesford, Adlestrop
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1341122

Parish church in the high Gothic style by JL Pearson 1863. Cruciform plan with a pyramidal spire. Limestone with red sandstone features, stone slate roofs. The stone slates are slipping or fractured and need renewal. The sandstone colonettes are heavily eroded on the outside and are structurally unsafe. The church is now owned by the St Peter's Daylesford Charitable Trust and shares services between the Church of England and the Roman Catholic church.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St James, Colesbourne
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1341787

Small parish church adjacent to Colesbourne Park. C12 with C15 tower and chancel; largely rebuilt 1851-53 by David Brandon. Random rubble limestone with ashlar tower; stone slate roof. Nave with north and south transept; west tower; south porch; and chancel. The roof slates have slipped or fallen and need repair on the north nave roof.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Edward, Evenlode
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1089794

restoration by JEK Cutts 1879. Coursed squared and dressed limestone and sandstone. Stone slate roof. Plan: nave with north vestry, south aisle, projecting porch from west end of south aisle, west tower, chancel. The stone slate roofs, especially on the south side, have reached the end of their life and need renewal.

Parish church. C12, C14, C19 vestry and porch,

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Arnold Bartosch Ltd

ITE NAME:	Church of St Bartholomew, Whittington
	***************************************

Listed Place of Worship grade DESIGNATION: II\*, CA

CONDITION: Very bad PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1341364

Norman in origin; restoration by Waller around 1872 included roofs, porch and vestry, and removal of rood screen formerly dividing nave from chancel. South chapel possibly late C16-17. South aisle probably C18 rebuilt on smaller scale incorporating C12 elements. Stone slate roofs are in extremely poor condition and are likely to date from the 1872 restoration. Heritage Lottery Fund Grant for Places of Worship awarded in 2017 for repairs to roofs. Project development underway in early 2018 and work on the roofs is anticipated to start in late 2018.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Two bowl barrows 690 metres and 790 metres no	rth of The Manor F	arm, Avening
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017337
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Perrott's Brook dykes, Bagendon / North Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Long barrow 800 metres north east of Oldwalls Fa	rm, Bibury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018163
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	West Barrow: a long barrow 200 metres west of L	eighterton School,	Boxwell with Leighterton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013590
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	A - 11 - 1 - 1 - 171 1	NIEVA / EN ITENZO	No
	Animal burrowing - localised/limited	NEW ENTRY?:	INO
OWNER TYPE:	Animal burrowing - localised/limited  Private	CONTACT:	Alessandra Perrone 0117 975 1345
	•		
SITE NAME:	Private		
SITE NAME: DESIGNATION:	Private  Chedworth Roman villa, Chedworth	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME: DESIGNATION:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised	CONTACT:  LIST ENTRY NUMBER:	Alessandra Perrone 0117 975 1345
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems	CONTACT:  LIST ENTRY NUMBER:  TREND:	Alessandra Perrone 0117 975 1345  1003324  Declining
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems  Rain entry	CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	Alessandra Perrone 0117 975 1345 1003324 Declining No
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems  Rain entry  Charity (heritage)	CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	Alessandra Perrone 0117 975 1345 1003324 Declining No
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems  Rain entry  Charity (heritage)  Settlement south east of Chesterton Farm, Cirence	CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  ester / Siddington	Alessandra Perrone 0117 975 1345 1003324 Declining No Melanie Barge 0117 9751300
OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Private  Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems  Rain entry  Charity (heritage)  Settlement south east of Chesterton Farm, Cirence Scheduled Monument	CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  ester / Siddington  LIST ENTRY NUMBER:	Alessandra Perrone 0117 975 1345  1003324  Declining  No  Melanie Barge 0117 9751300
SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Chedworth Roman villa, Chedworth  Scheduled Monument  Generally satisfactory but with significant localised problems  Rain entry  Charity (heritage)  Settlement south east of Chesterton Farm, Cirence Scheduled Monument  Extensive significant problems	CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  ester / Siddington  LIST ENTRY NUMBER:  TREND:	Alessandra Perrone 0117 975 1345  1003324  Declining  No  Melanie Barge 0117 9751300  1003444  Improving

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Three bowl barrows, known as Emma's Grove rou	nd barrows, Cober	ley
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017079
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Two bowl barrows, known as Crippet's Wood rou Dryhill Farm, Coberley	und barrows, 560 m	netres and 590 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Norbury Camp hillfort, Colesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Tump Barn bowl barrow, Didmarton		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016077
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Camp at Upper Dowdeswell, Dowdeswell		
designation:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003321
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Hoar Stone long barrow, Duntisbourne Abbots		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018161
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow in Three Ash Belt, 460 metres north	east of Westwood	Farm, Edgeworth
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016840
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

HERITAGE AT RISK 2018 / SOU	JTH WEST / COTSWOLD		
SITE NAME:	Icomb camp, Icomb		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003342
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	The Chessalls Roman town, Kingscote / Wottor	-under-Edge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018607
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Summerhill prehistoric site, Naunton		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1003339
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow in Inlands Plantation, 650 metres so	outh of Hazleton Man	or Farm, Rodmarton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008788
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 120 metres north of Home Farm,	Sherborne	
DESIGNATION:	Scheduled Monument, RPG grade II, CA	LIST ENTRY NUMBER:	1017082
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	South Cerney castle, South Cerney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 335 metres south east of Broadfiel	d Farm, Tetbury Upto	on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016838
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Four bowl barrows forming part of a round barr Hill Farm, Upper Slaughter	ow cemetery, and a lo	ong barrow 550 metres NNE of Eyfor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020987
CONDITION	Extensive significant problems	TREND:	Declining
CONDITION:	Extensive significant problems		2
CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

# FOREST OF DEAN



© Historic England Archive

SITE NAME:	Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Former non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required.

Contact: Alessandra Perrone 0117 975 1345

	4	de	
	A		
	網	CEL	Men
La	A	i.	
ERROR.			
			100
160			

© Historic England Archive

SITE NAME:	Gunns Mill Furnace, Littledean
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1186386

Formerly a C17 charcoal blast furnace and later an C18 paper mill. Now unused and in perilous condition, despite some emergency holding repairs. The Forest of Dean Building Preservation Trust is working with Historic England to secure the future of the building. Funding to date has completed various surveys and improved the landscape and setting. A 2017 Heritage Lottery Fund application was rejected. A revised application will be made late 2018 for funding to develop a proposal to reuse the site and restore the furnace.

Contact: Melanie Barge 0117 9751300



© Historic England

SITE NAME:	Lydney Docks and Harbour, Naas Lane, Lydney
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency

1002079 and 1338556

1002080 and 1186479


The docks and harbour date from c1810 to 1821 and were once the main commercial port serving industry in the district. The Inner Basin is still in poor condition and needs extensive repairs. The Environment Agency has advertised the site and selected a preferred bidder to take over the ownership of the site. The final details of this sale are still being resolved. A local partnership group through the Local Authority are looking for funding to repair some structures and enhance the visitor experience of the site. Work has also been on-going to clear and control vegetation on the

C15 or early C16 tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural storage.

Contact: Melanie Barge 0117 9751300

Some maintenance has been undertaken.

Contact: Chris Miners 0117 975 1308



© Historic England Archive

Tithe Barn, Highleadon Court, Rudford and Highleadon
Listed Building grade II*
Poor
Part occupied/part in use
C (C)
Private

1152574

© Historic England

SITE NAME:	Church of St Mary the Virgin, Flaxley, Blaisdon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1186458

1186458

Parish church, 1856, by Sir George Gilbert Scott. Red sandstone ashlar, with grey sandstone ashlar dressings, timber porch, tiled roof with crested ridge, shingles to spire. Nave, north aisle, with tower at its west end, chancel, organ chamber and south porch. The nave roofs have had repairs, however the chancel and organ chamber roofs need urgent re-tiling. The spire shingling needs renewing following woodpecker damage.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England	

SITE NAME:	Church of St Michael and All Angels, Blaisdon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299195

Places of Worship Roof Repairs Grant was accepted in 2015 for repairs which have addressed some of the issues.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME: Church of St John the Evangelist, Boxbush Road, Coleford DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1211330

A late Victorian parish church overlooking the centre of Coleford, the last phase of which was completed in 1907. The roof has been partly repaired but the remainder is leaking badly, which has damaged the interior of the

Parish church, C15 tower, the rest rebuilt 1867-9 by FR Kempson of Hereford in the Early English style. Tower thin coursed rubble, church squared red Forest stone with Bath stone ashlar dressings; slate roof. West tower, four-bay nave, with north aisle, chancel with vestry, south entrance porch. The damp penetration into the church stonework at both high and low level put the building at risk. A Listed

Contact: Chris Miners 0117 975 1308



Church of St Mary, Dymock SITE NAME: Listed Place of Worship grade I, DESIGNATION: CONDITION: Poor PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1303073

Large parish church. C11, C12, C14, C15, probably C18, Cl9 restoration. Tower, well-squared coursed stone; west end nave and east end chancel random rubble with ashlar dressings; transepts and vestry roughly squared, coursed stone with ashlar dressings; squared, coursed stone to east end nave, and bottom part west end, also west part of chancel. Tiled roofs, shingled spire. The stonework of the tower and buttresses is heavily eroded and a repair scheme is planned. The tiled roof pitches have been repaired.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Michael, High Street, Mitcheldean
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100286

Large parish church with a tall tower and needle spire. Slate roofs, south aisle flat roof. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship remedied some structural problems of the spire and the high level west aisle gables in 2012. A Listed Places of Worship Roof Repairs Grant repaired further roof problems, however more problems remain with instability in apex of the spire.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Saviour, Redbrook, Newland
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1212814

Small parish church, now sharing community hall uses, by JP Seddon in 1873. Nave with south porch and chancel with south chapel and bellcote; in red sandstone with buff limestone dressings. The limestone and sandstone mix has been auto-destructive with severe erosion of the sandstone on the north wall and to the limestone on the dressings on the south side. The tiled roof on the south nave pitch has slipped or missing tiles.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	Church of St Bartholomew, The Causeway, Redmarley D'abitot
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

C13, and part of the tower probably dates from that time; but the majority of the building goes back only to 1855when most of the church was in serious disrepair, demolished and rebuilt. The stonework of the tower is seriously eroded with open jointing and structural cracking and rainwater disposal problems. Some falls of stone have been reported.

Large parish church of sandstone ashlar with tiled roofs.

Contact: Chris Miners 0117 975 1308



SITE NAME:	Church of St Mary, Upleadon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1153374

1341976

Small parish church; C12, C15, C18, restored 1850, 1879 by Ewan Christian; vestry added 1884. West tower is close-studded timber-framed tower, brick nogged, on squared, coursed stone plinth: with pyramidal slate roof. Nave sandstone ashlar with south entrance porch, lower east chancel with projecting north vestry. All with graduated stone slate roofs. The timber frame has patches of decay and some stone slates are slipping.

Contact: Chris Miners 0117 975 1308

-	
A.	
	WHILE PARTY

© Historic England

SITE NAME:	Church of St Peter and St Paul, Westbury-on-Severn
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1101724

This church's tower with its tall shingled spire is a landmark on the Severn estuary; the tower dates from c1270, the timber-framed spire was added C14. Spire needed recovering as the shingles had fallen and fixings had failed so that the steeplejacks could no longer safely carry out repairs. Heritage Lottery Fund and Historic England Repair Grant for Places of Worship awarded in December 2012, with the structure repaired in 2016. A second Heritage Lottery Fund Grant for Places of Worship was accepted to re-fix the shingles in 2018.

Contact: Chris Miners 0117 975 1308

SITE NAME:	Whitecliff Iron Works, Coleford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021420
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Melanie Barge 0117 9751300
SITE NAME:	Motte in Castle Hill Wood, Huntley, Taynton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002070
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Caswell Wood, 280 metres	west of Beeches F	arm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020601
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HENTIAGE AT KISK 2016 / 3OC	OTH WEST / FOREST OF DEAIN / GLOUCESTER		
SITE NAME:	Offa's Dyke: section in Chapelhouse Wood, 240 m	netres west of the F	Recreation Ground, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020639
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Lippets Grove, 680 metres	WSW of Beeches	Farm, Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020602
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Passage Grove, 660 metres	west of Sheepcot,	Tidenham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020603
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Offa's Dyke: section in Worgan's Wood, 800 metr	es west of Chase F	arm, Tidenham
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1020605
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa 600 yards (550 metres) south west of	Woolaston Station	, Woolaston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004860
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

# **GLOUCESTER**



© Gloucester City Council

SITE NAME:	Llanthony Priory, remains of precinct wall north of Inner Gatehouse, Llanthony Road, Gloucester	(
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade I, LB grade II, part in CA	c c
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1002091 and 1271693; 1271697; 1271694; 1271696;	(

1271695; 1271698

Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust successfully bid for Heritage Lottery
Fund grant and works to most of the Priory site are now complete, with the buildings due for occupation by the end of 2018. This length of wall will remain unrepaired for the short term due to budget constraints.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	The Fleece Hotel, 19, Westgate Street, Gloucester
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

C15 timber-framed range most recently occupied as the Fleece Hotel. The building has been vacant for some time. It is in poor repair, with some internal decay. A series of opening up works were carried out early summer 2010 to provide more information on the condition. Ownership has passed to Gloucester City Council who have done some emergency repairs, and a Timber Frame Report and Options Appraisal have now been produced. A deliberately-started fire in the rear Edwardian wing in July 2017 destroyed the roof, although the main C15 core was not affected.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Old Judges House, 26, Westgate Street, Gloucester
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1245450

1245447

Late C15 timber-framed merchant house, greatly enlarged and remodelled in late C16/early C17. Refronted and altered internally c1815. Operated as seed merchant for c100 years until 1989, then partly occupied as bookshop, before becoming vacant. Whilst some repairs have been undertaken, there remain many areas which require attention, particularly the roof and significant joinery. The ground and first floors are now occupied and consent has been granted to install a lift which will enable the upper floors to be used by the antiques centre to help fund roof and joinery repairs.

Contact: Stephen Guy 0117 975 0725

DESIGNATION: Conservation Area, 5 LBs  NEW ENTRY?: No  CONDITION: Very bad TREND: Deteriorating  VULNERABILITY: Medium  CONTACT: Charlotte Bowles-Lewis (LPA) 01452  396855  SITE NAME: Southgate Street  DESIGNATION: Conservation Area, 31 LBs  NEW ENTRY?: No  CONDITION: Very bad TREND: Improving significantly  VULNERABILITY: Contact: Charlotte Bowles-Lewis (LPA) 01452  CONDITION: Very bad TREND: Improving significantly  VULNERABILITY: Contact: Charlotte Bowles-Lewis (LPA) 01452  396855				
CONDITION: Very bad TREND: Deteriorating  VULNERABILITY: Medium  CONTACT: Charlotte Bowles-Lewis (LPA) 01452  SITE NAME: Southgate Street  DESIGNATION: Conservation Area, 31 LBs  NEW ENTRYP: No  CONDITION: Very bad  TREND: Improving significantly  VULNERABILITY: Contact: Charlotte Bowles-Lewis (LPA) 01452	SITE NAME:	Barton Street, Gloucester		
VULNERABILITY:  Medium  CONTACT:  Charlotte Bowles-Lewis (LPA) 01452 396855  SITE NAME:  Southgate Street  DESIGNATION:  CONDITION:  Very bad  TREND:  Improving significantly  VULNERABILITY:  LOW  CONTACT:  Charlotte Bowles-Lewis (LPA) 01452	DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
SITE NAME:  Southgate Street  DESIGNATION:  Conservation Area, 31 LBs  New ENTRY:  No  CONDITION:  Very bad  TREND:  Improving significantly  VALUE NERABILITY:  Low  CONTACT:  Charlotte Bowles-Lewis (LPA) 01452	CONDITION:	Very bad	TREND:	Deteriorating
DESIGNATION: Conservation Area, 31 LBs NEW ENTRY?: No  CONDITION: Very bad TREND: Improving significantly  VILINERABILITY: CONTACT: Charlotte Bowles-Lewis (LPA) 01452	VULNERABILITY:	Medium	CONTACT:	
DESIGNATION: Conservation Area, 31 LBs NEW ENTRY?: No  CONDITION: Very bad TREND: Improving significantly  VILINERABILITY: CONTACT: Charlotte Bowles-Lewis (LPA) 01452				
CONDITION: Very bad TREND: Improving significantly  VILINERABILITY: CONTACT: Charlotte Bowles-Lewis (LPA) 01452	SITE NAME:	Southgate Street		
VIJI NERABILITY: CONTACT: Charlotte Bowles-Lewis (LPA) 01452	DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
	CONDITION:	Very bad	TREND:	Improving significantly
		1617 544		improving significantly

# **STROUD**



© Historic England

SITE NAME:	Guise Mausoleum to north west of Church of St John the Baptist, Stroud Road, Brookthorpe, Elmore
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Charity (heritage)

Built in 1733 for Sir John Guise of Elmore Court and his family in neoclassical style, as an exact copy of what the commissioner thought to be Virgil's tomb in Italy. The monument, which includes a burial vault, has been left ruinous after the collapse of its pyramidal roof in the early C20. The ashlar and decorative elements which remain have been affected by weathering and erosion. Vegetation has also taken hold of the plot and is obscuring some of the

Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with Historic England grant. A proposal for repair and conservation was granted consent in 2011. The planning permission has been implemented by a commencement on the factory building.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Main building at Stanley Mills, Ryeford, King's Stanley
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1171285

1247875

Main works to the mill are yet to begin and condition is deteriorating, particularly following recent heritage crime. This is now being investigated and temporary repairs are being pursued.

Contact: Stephen Guy 0117 975 0725

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is

shown in brackets (otherwise. I PA ΝP New Entry is noted). RPG

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England Archive

SITE NAME:	St Mary's House, London Road, Minchinhampton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1091156

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Former mill owner's house and weavers' cottages, late C16 and late C17. Roof in exceptionally poor condition and is covered with tarpaulin.

Centrepiece of an extensive industrial complex, from 1766. This is one of two buildings on site to remain vacant after a residential redevelopment that has refurbished and re-used the rest of the complex. Repairs and conservation proposals are being explored by a local Trust.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Old Mill Building at Longfords Mills, Avening Valley, Minchinhampton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Woodchester Mansion, Woodchester
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)

1340703

1305339

Mansion c1854-68 incorporating a magnificent private chapel. The Woodchester Mansion Trust was formed in 1989 to do a continuous programme of conservation and display of the uncompleted Gothic-style masterpiece. In 1991 a protective scaffold was built to cover the leaking roof of the chapel. The scaffold is now decaying and unsafe. Repairs are immediately needed to the scaffold or, ideally, the roof underneath. Other adjacent roofs are now developing serious faults. Development work is being organised in order to apply for the large grant funding now needed.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Lane, Berkeley
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Religious organisation

1304581

Parish church. C12 foundation on probable site of important early medieval minster church, altered in C13 and C15, and in C19. Random coursed rubblestone, roofs with coped verges and cross finials. Nave and aisles of seven bays with clerestory windows to south only, north porch, lower chancel with flanking chapels. The roof has been extensively repaired. The extensive interior wall paintings continue to decay.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St James, Fretherne with Saul
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1090510

from C15 and C16. Enlarged and restored at different times in C19. Roof coverings, which vary from stone slate on some areas to concrete tiles on others, are in very bad condition. The rainwater goods need repairing and replacing where previous patch repairs have failed. The stonework of the tower is delaminated in places.

Church said to date originally from 1140, with elements

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Auth

LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



SITE NAME:	Church of St Giles, High Street, Hillesley, Hillesley and Tresham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1129364

Church, 1851 by Reverend B Perkins, Vicar of Wotton Under Edge, in Early English style. Coursed rubble with freestone dressing; Cotswold stone slate roofs. Nave with clerestory, north and south aisles, chancel and south porch. The roofs at east end of the church have stone slates in bad condition

© Historic England

as i

SITE NAME:	Church of St John the Baptist, B4072, Edge, Painswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172665

Small Victorian rural church. Cotswold stone walls, roof tiles and tower with a squat spire. The congregation has completed a repair scheme to the tower and spire, however the stone slate roofs are in a poor condition especially the north slopes with a number of missing slates.

Contact: Chris Miners 0117 975 1308

Contact: Chris Miners 0117 975 1308

© Historic England



SITE NAME:	Church of St Mary Magdalene, Church Place, Rodborough
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1340958

St Mary Magdalene is a parish church with an early C16 west tower. The body of the church dates largely from 1842, to a design by Thomas Foster and Son of Bristol, with 1895 additions by FS and FW Waller all in the Decorated style. The roof pitches have some missing or fractured stone slates and the rainwater goods need an urgent overhaul.

Contact: Chris Miners 0117 975 1308

4
6-3

© Historic England

The	
	1

© Historic England

SITE NAME:	Congregational Church, Bedford Street, Stroud	
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	F (D)	
OWNER TYPE:	Religious organisation	

1340941

A Congregational church of 1835-7 by Charles Baker of Painswick, with later alterations of 1851. Rectangular on plan with an apsidal north west end and a stair tower to the south east. The street facade is in the Greek Revival style. It is of two storeys with a gallery inserted in the first floor. The timber windows are rotten and a Heritage Lottery Fund Grant for Places of Worship was accepted in 2017 for repairs which are underway in summer 2018.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Andrew, Whitminster
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation

1303052

Small church. Cll foundation, earliest work probably of C14, altered and tower added late C15/early C16, north aisle added 1842, restored c1884-5 by Sir Arthur Blomfield. Random coursed and dressed stone, ashlar tower and part ashlar walls, stone slate roof with coped east verges with saddle stones and cross finials. West tower, nave with south porch and north aisle, chancel, with north vestry of 1880s. The stone slates have slipped or fallen on the nave and north aisle pitches and the porch.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOU	DIH MESI / SIKOOD		
SITE NAME:	Bowl barrow 450 metres south east of Upper Hyd	e Farm, Minchinhar	npton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008626
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Gatcombe long barrow, 400 metres east of Gatcor	mbe Farm, Minchinl	nampton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008623
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Miserden Castle mound, Miserden		
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1004870
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 720 metres south east of Longwood	Farm, Woodcheste	er
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017084
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 330 metres north of Symonds' Hall F.	arm, Wotton-unde	r-Edge
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017083
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Stanley Mills, Kings Stanley, King's Stanley / Stoneho	ouse	
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Kate Russell (LPA) 01453 766321
		· · · · · · · · · · · · · · · · · · ·	
SITE NAME:	Stroud Industrial Heritage (IHCA), Multiple parishe Bisley-with-Lypiatt / Brimscombe and Thrupp / Cai Fretherne with Saul / King's Stanley / Leonard		
	Bisley-with-Lypiatt / Brimscombe and Thrupp / Cai		
SITE NAME:  DESIGNATION:  CONDITION:	Bisley-with-Lypiatt / Brimscombe and Thrupp / Cai Fretherne with Saul / King's Stanley / Leonard	nscross / Chalford	/ Eastington / Frampton on Severn /

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

# **TEWKESBURY**



© Mr John Brookes. Source Historic England Archive.

SITE NAME: Dovecote approximately 75 metres south east of Manor Farm, Ashchurch, Ashchurch Rural

DESIGNATION: Listed Building grade II\*

CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1091923

Dovecote, 1637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have taken place.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME: Dovecote three metres north of Bridge House, Bentham, Badgeworth DESIGNATION:

Listed Building grade II\*

C(C)

CONDITION: Poor OCCUPANCY: N/A

OWNER TYPE: Private

PRIORITY CATEGORY:

LIST ENTRY NUMBER: 1304753

Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels are fragmenting. Some timber decay on the west side and cement repairs to the roof are also of concern.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME: Southam tithe barn and shelter shed, Southam Lane, Southam DESIGNATION: Listed Building grade II\* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)

OWNER TYPE: Private LIST ENTRY NUMBER: 1091668

Large late medieval tithe barn converted to assembly uses but now vacant. Weather boarded timber-framed walls on a high stone plinth. Artificial stone (concrete) moulded tile roof has holes. The roof truss frames have structural faults. One bay of the roof (east end) exhibits severe bowing due to failed purlins. Short term holding repairs have prevented an immediate collapse of the roof.

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME: Mythe Bridge, A438, Tewkesbury Listed Building grade II\*, part in DESIGNATION: CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C(C)OWNER TYPE:

Local authority, multiple owners LIST ENTRY NUMBER: 1282810

Road bridge over the River Severn. Built 1823-26 by Thomas Telford, cast iron bridge of six segmental arched latticed beams, latticed roadway beam with latticed ironwork filling the spandrels. Each abutment has outer and inner sandstone piers separated by six brick arched tunnel vaults with cast iron colonettes. Cast iron roadway balustrade between piers. Ironwork of the balustrades is rusting at connections. Sandstone piers, especially above roadway level, are severely fractured and eroded, some covered in excessive and harmful ivy growth. Also in West Midlands Heritage at Risk Register.

Contact: John Ette 0117 975 0687



© Tewkesbury Borough Council

SITE NAME: Malthouse to the rear of 23, Barton Street, Tewkesbury DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private LIST ENTRY NUMBER:

1281018

Workshop, former malthouse. C17. Building has been

unoccupied for some time. Listed Building Consent was

approved in 2016 for conversion from a workshop to a

Contact: Stephen Guy 0117 975 0725

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

dwelling

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



ewkesbury Borough Council

SITE NAME:	88, Church Street, Tewkesbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners

1205905

Contact: Alessandra Perrone 0117 975 1345

with broken windows on second floor.

Late C15 town house, altered C16 and C19, with shop under. Building only partly occupied and in poor condition

A.B	SI
	DI
	C
	0
	PF
	0

LIST ENTRY NUMBER

© Historic England Archive

SITE NAME:	Toddington Manor, Toddington
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1340101

Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house was mothballed for more than 15 years, but has been purchased by a new owner who has engaged in an extensive programme of urgent works and repairs in consultation with the Local Planning Authority and Historic England. Following extensive stabilisation work, a temporary protective roof was installed and is in good order. There is no apparent further deterioration to the fabric. Discussions are ongoing with the owner's agent regarding building repairs.

Contact: Stephen Guy 0117 975 0725



SITE NAME:	Church of St Nicholas, Ashchurch Rural	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1153103	

Parish church. C12, C13, late C14, and C15, restored 1889 and 1931, small mid-late C20 extension. Nave; random limestone. Clerestory; coursed squared and finely dressed limestone and sandstone. South porch and tower; large blocks coursed finely dressed limestone. Artificial stone slate roof to chancel. Red tile roof to C12 nave with C15 clerestory. Nave south wall; two raking buttresses (possibly added C14). The roof is in bad condition masked behind the nave parapet. The chancel north pitch has slipped

Contact: Chris Miners 0117 975 1308



© Historic England

© Historic England

SITE NAME:	Church of St Mary Magdalene, Boddington
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172312

Small parish church. C12, C13, C14, possibly early C17, C18, restored late C19, mid C20 vestry. Random rubble stone, larger quoins, ashlar buttresses; north and east walls rendered; stone slate roof, band of concrete tiles to north slope nave; concrete tiles to vestry. There are structural problems with the nave that put this church at risk.

Contact: Chris Miners 0117 975 1308



© Historic England

Church of St John the Baptist, Oxenton
Listed Place of Worship grade I
Poor
C (C)
Religious organisation
1303393

Parish church. C13, C14 and C15, restored 1905. Nave and chancel coursed limestone rubble except the south wall of chancel which is coursed squared and dressed limestone. Porch and north aisle also coursed squared and dressed limestone. Tower and mortuary chapel: ashlar; stone slate roof. Nave with north aisle with mortuary chapel at right angles, chancel and west tower. The key issue is the decay of the interior plaster and the threat that this poses to the wall paintings.

Contact: Chris Miners 0117 975 1308

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Martin, Charlton Abbotts, Sudeley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1340100

Tiny parish church in a small hillside churchyard. Nave with south porch and north vestry and lower chancel all in limestone ashlar. All from an 1887 rebuild of a ruin, incorporating medieval features, except for the vestry added in 1933. Graduated limestone slate roofs which are in need of repair especially on the north side.

Contact: Chris Miners 0117 975 1308

© Historic England

SITE NAME:	Great Witcombe Romano-British villa, Great Wi	tcombe / Brockwortl	h
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014826
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Over earthwork, Highnam		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002092
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Hailes Wood camp, Hailes, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004843
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Milhampost Roman site, Stanway		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004844
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Spoonley Wood Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004847
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Melanie Barge 0117 9751300
SITE NAME:	Wadfield Roman villa, Sudeley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004846
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Romano-British villa 170 metres south west of Winchcombe School, Greet Road, Winchcombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021449
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Winchcombe		
SITE NAME:  DESIGNATION:	Winchcombe  Conservation Area, 176 LBs, part in RPG grade II*, part in SM	NEW ENTRY?:	No
	Conservation Area, 176 LBs, part in RPG grade II*,	NEW ENTRY?: TREND:	No Deteriorating

Late C19-early C20 Woolpack

Battery on The Garrison, St.

Mary's

# ISLES OF SCILLY (UA)



Scheduled Monument, LB grade DESIGNATION: II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) © Historic England Archive

SITE NAME:

Late C19/early C20 battery. Generally good condition and secure but unoccupied since 2015. Converted to volunteer hostel accommodation in late C20/early C21 but now suffering from problems with water ingress into the former magazines, now dormitories. Discussions regarding repair and potential new uses are underway with the site owner, and the Local Authority.

OWNER TYPE: Crown LIST ENTRY NUMBER: 1014783

Contact: Helen Woodhouse 0117 975 0676



© Historic England Archive

SITE NAME:	Post-medieval cottages, Samson, Tresco
DESIGNATION:	Scheduled Monument, part in CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Crown

Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by Historic England is now complete. The results of the consolidation trials are being studied to ultimately inform a wider programme of repair.

LIST ENTRY NUMBER: Contact: Ann Preston-Jones 07917 642388 1016509

SITE NAME:	Civil War battery on The Green, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1010176
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Gig shed on the north coast of Great Porth, Bryher		
SITE NAME:  DESIGNATION:	Gig shed on the north coast of Great Porth, Bryher Scheduled Monument, CA	LIST ENTRY NUMBER:	1016173
	·		1016173 Declining
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOC	JTH WEST / ISLES OF SCILLY (UA)		
SITE NAME:	Prehistoric enclosure south east of The Brow, Bry	her	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and post-medieval quay in	Great Porth, Bryhe	r
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014987
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and Romano-British cist in	Green Bay, Bryher	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014989
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric hut circle south of The Brow, Bryher		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014990
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric linear boundary and cairns south west	of The Bar, Bryher	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric linear boundary SSE of The Island, Bryh	ner	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014991
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric cairns, entrance graves, field system and Gugh, St. Agnes	d settlements and p	ost-medieval kelp pits on Kittern Hill,
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014792
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Russell 0117 975 0671

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# **ABBREVIATIONS**

SITE NAME:	Prehistoric entrance grave and two round cairns of	n the Clapper of W	orks, Gugh, St. Agnes
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008337
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and post-medieval breastw	ork and maze on C	Castella Down, St. Agnes
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015697
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Kerbed round cairn with central cist on Gun Hill, S	t. Martin's	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013809
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	Yes
OWNER TYPE: Crown CONTACT:		CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Platform cairn on Turfy Hill, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018114
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric cairn cemetery and field system on Tinkler's Hill, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1018109
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric entrance grave, the middle one of three	on Cruther's Hill,	St. Martin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013804
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric entrance grave, the northern one of the	ee on Cruther's H	ill, St. Martin's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013803
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Prehistoric entrance grave, the southern one of three, and kerbed round cairn with cist on Cruther's Hill, St. Martin's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1013805
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and kerbed cairn, with pos Island, St. Martin's	t-medieval kelp pit	and linear boundary on southern Wh
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1014789
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Russell 0117 975 0671
ITE NAME:	Ennor Castle, Old Town, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1014994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	Hut circle settlement in Pendrathen, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015663
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown CONTACT: Ann Preston-Jones 0791		Ann Preston-Jones 07917 642388
SITE NAME:	Post-medieval breastwork, curtain wall and associa St. Mary's	ted defensive struc	tures on the periphery of The Garris
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1018370
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	The Old Quay, Old Town Bay, St. Mary's		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1015656
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
ITE NAME:	World War II pillbox between Thomas' Porth and	Porthaloo, St. Mary	y's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016517
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

SITE NAME:	World War II pillbox west of Porth Hellick, 90 met	res north of Drum	n Rock, St. Mary's
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016516
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric cairn group on Abbey Hill, Tresco		
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016183
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and hut circle north of Cra	o's Ledge, Tresco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and settlement in Bathingho	ouse Porth, Tresco	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016423
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric field system and settlement north of Ap	pletree Point, Tres	sco
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1016182
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	Prehistoric to post-medieval funerary, field system and settlement remains, with post-medieval kelp pit and deer park on and adjacent to Samson, Tresco		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1016509
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388
SITE NAME:	St Nicholas' Priory, Tresco		
DESIGNATION:	Scheduled Monument, LB grade I, RPG grade I, CA	LIST ENTRY NUMBER:	1016184
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Ann Preston-Jones 07917 642388

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

### **NORTH SOMERSET (UA)**



© Historic England

SITE NAME:	Ashton Court, Long Ashton
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1129841

Historic England in discussions with Bristol City Council.

Contact: Sarah Ball 0117 975 0666



LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

.....

© Historic England

SITE NAME: Elms Colliery, Nailsea Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority


1004533 and 1320976

complete examples of an early C19 colliery in England. However the surviving structures are in a poor and vulnerable condition. Since 2015 Historic England has been working with the owners and other stakeholders to help improve its condition, and have grant-aided repairs to the boundary wall to make the site safe and secure.

Known locally as Middle Engine Pit, this is one of the most

Large country house with various elements dating from C15, C17, C18 and C19. House partly used but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between owners, Local Planning Authority, Historic England and other interested parties for many years. Historic England grant offered 2011 for project development works including Conservation Management Plan, condition survey and business plan. Majority of work completed by 2013.

Contact: Alessandra Perrone 0117 975 1345



© Historic England

SITE NAME:	Birnbeck Pier, Weston-Super- Mare
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

1129718

Main pier which connects Birnbeck Island to the mainland below the Prince Consort Gardens. The structure is dated 1862 opened in 1867. Negotiations ongoing between the Local Planning Authority, owner, Historic England and other interested parties about repair of pier and development of island. Trial repairs grant-aided by Historic England in 2009-2010 to help establish likely total repair costs. Storm damage continues to destroy both the north jetty and the main pier which are now too dangerous to walk over or under.

C12 parish church, altered and extended early C13 and C14/C15, and restored 1870-5. The stone slate roofs of the chancel, vestry and associated lean-to roofs have come to the end of their life. Water has been getting in causing ceiling plaster falls. A Heritage Lottery Fund Grant for Places of Worship enabled roof repairs to be completed in 2014. However, further problems with the poor state of the sandstone wall especially on the south transept keeps

Contact: John Ette 0117 975 0687



© Historic England

SITE NAME:	Portbury
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1311826

the church at risk. A further Heritage Lottery Fund grant has been awarded and the project development is nearing completion. Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Christ Church, Montpelier, Weston-Super-Mare
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1137768

The church is said to date from 1855 with a number of extensions and alterations in the late C19. These include the building of the chancel and installation of clerestory windows. The list description refers to an enlargement in 1878 by Hans Price. In 2006 the Spire Centre extension was built on the north side. The high level stonework to the tower and spire is eroding and there is corroding embedded ironwork. Heritage Lottery Fund Grant for Places of Worship accepted and repairs to spire and tower due to be completed by the end of 2018.

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

## I PA ΝP RPG

**ABBREVIATIONS** 

## Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

TWEST / TOKT TO STIEROET (O/I) / TETT OOTT, OF TO (O/I)		
Worlebury Camp: a large multivallate hillfort on Worlebury Hill, Weston-Super-Mare		
Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011260
Generally unsatisfactory with major localised problems	TREND:	Declining
Forestry	NEW ENTRY?:	No
Local authority	CONTACT:	Alessandra Perrone 0117 975 1345
Clevedon Triangle, Clevedon		
Conservation Area, 4 LBs	NEW ENTRY?:	No
Very bad	TREND:	Deteriorating
Medium	CONTACT:	Kate Hudson-McAulay (LPA) 01275 888169
Birnbeck, Weston-Super-Mare		
Conservation Area, 29 LBs, part in SM	NEW ENTRY?:	No
Very bad	TREND:	Deteriorating
Medium	CONTACT:	Kate Hudson-McAulay (LPA) 01275 888169
Boulevard/Montpelier, Weston-Super-Mare		
Conservation Area, 4 LBs	NEW ENTRY?:	No
Poor	TREND:	Deteriorating
Medium	CONTACT:	Kate Hudson-McAulay (LPA) 01275 888169
Melrose/Grove Park, Weston-Super-Mare		
Melrose/Grove Park, Weston-Super-Mare Conservation Area, 20 LBs, RPG grade II*, SM	NEW ENTRY?:	No
·	NEW ENTRY?: TREND:	No Deteriorating
	Scheduled Monument, part in CA Generally unsatisfactory with major localised problems Forestry Local authority  Clevedon Triangle, Clevedon Conservation Area, 4 LBs Very bad Medium  Birnbeck, Weston-Super-Mare Conservation Area, 29 LBs, part in SM Very bad Medium  Boulevard/Montpelier, Weston-Super-Mare Conservation Area, 4 LBs Poor Medium	Worlebury Camp: a large multivallate hillfort on Worlebury Hill, West Scheduled Monument, part in CA  Generally unsatisfactory with major localised problems  Forestry  Local authority  Clevedon Triangle, Clevedon  Conservation Area, 4 LBs  Very bad  Medium  Contact:  Birnbeck, Weston-Super-Mare  Conservation Area, 29 LBs, part in SM  Very bad  Medium  Contact:  Boulevard/Montpelier, Weston-Super-Mare  Conservation Area, 4 LBs  New ENTRY:  Contact:  Remb:  Medium  Contact:  Boulevard/Montpelier, Weston-Super-Mare  Conservation Area, 4 LBs  New ENTRY:  TREND:  Medium  Contact:  Contact:

### PLYMOUTH, CITY OF (UA)



© Historic England Archive

<i>'</i>	
SITE NAME:	Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1386483

Former variety theatre and hotel, built 1898. A significant building in an area where major regeneration has been underway. Historic England has offered grant aid in the past, which was not taken up. Temporary repairs were undertaken in 2013 and 2015 to make the theatre weather tight. Further temporary weatherproofing has been put in place in the last two years but a full condition report and detailed scheme of repairs, and a business plan, are still required. A new local charitable trust has formed which hopes to take forward the future of the building.

Contact: Annie Evans 0117 975 1308



© Historic England Archive

SITE NAME:	Agaton Fort, Plymouth
DESIGNATION:	Scheduled Monument
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1002613

One of the ring of C19 land forts built to defend Plymouth. Overlooks River Tamar. Irregular pentagonal plan, with deep ditch on four sides protected by caponiers and a counterscarp gallery. Internally the officer's quarters, cookhouse and barracks, seven of twenty open gun positions, one Haxo casement, five expense magazines and two of previous six mortar batteries survive. Ceased military use in 1958 but was used as Heavy Goods Vehicle testing centre (partly in a modern building) until 2015. Vacancy is concerning and there are significant problems with dry rot and vegetation management.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Amphitheatre in grounds of
	Saltram House, Merafield Road,
	Plympton

Listed Building grade II\*, RPG DESIGNATION: grade II\*

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: C(C)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1386231

OWNER TYPE:

Late C18 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse. A condition survey of the structure has recently been undertaken, and the owners are in the process of updating their conservation management plan for the Saltram Estate. However, no physical repair works have yet been undertaken.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME: Boringdon Arch, Plymbridge Road, Plymouth Listed Building grade II\* and DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

Private, multiple owners

LIST ENTRY NUMBER: 1386330 and 1020565

Designed by Robert Adam and built in 1783, it is believed the arch was built as a triumphal arch and eye-catcher to be viewed from Saltram House. The arch was advertised for sale in 2014, which included approximately two acres of associated woodland. There has been no further interest in the arch and as of 2018 it is unclear if the arch was successfully sold.

Contact: Simon Hickman 0117 975 0717



© Plymouth City Council

SITE NAME: Efford Fort and Emplacement, Military Road, Efford DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A (A) OWNER TYPE: Mixed, multiple owners

LIST ENTRY NUMBER: 1021135 Palmerston Fort built between 1863 and 1869. Partially occupied, as the parade ground is used for seasonal accommodation whilst buildings are vacant or used for storage. Buildings are suffering from benign neglect with heavy vegetation growth on the ramparts which may lead to water penetration and structural problems. No solution agreed as of 2018.

Contact: Annie Evans 0117 975 1308



© Peter Grills

SITE NAME: Elizabethan House Museum, 32, New Street DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Local authority LIST ENTRY NUMBER:

Early C17 three-storey timber frame and jettied merchant's house with rubble side wall and evidence of former adjoining house, restored in 1926 by AS Parker. Interior has many original features and it is probably the most complete and unaltered example of a jettied merchant's house in Plymouth. Historic England has funded investigation into causes of structural weakness and water ingress and repair work is expected to be underway in 2018-19.

Contact: Annie Evans 0117 975 1308 1386279



© Historic England

SITE NAME: Melville Building, Royal William Yard, Plymouth DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (D) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1378531

The Melville building was constructed c1826 to 1832 as stores and offices for the Victualling Board to the design of Sir John Rennie Jnr, and forms part of the impressive Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future for the whole of Melville has yet to be implemented. Planning permission was granted in 2014 for the repair of Melville and conversion of most of the building for use as a hotel. Initial clearance work is underway with main works due to commence August 2018.

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## I PA ΝP RPG

## **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Oddfellows Hall, Ker Street, Devonport
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1322006

Hall built by John Foulston, 1823, in the Egyptian style. Part of a group with the Guildhall and Devonport Column. Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. Historic England grant-aided a feasibility study and emergency repairs to the roof, completed in 2007. The building has been acquired by new owners. Historic England has met with the new owners and is in discussions over the future repair of the building.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Old Cooperage, Royal William Yard, Plymouth
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

1378536

The Cooperage was built c1826 to 1832 for the Victualling Board, and forms part of the Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future for the whole of the Cooperage has yet to be secured. Part of the building has been successfully converted into artists' studios; Historic England grant-aided the stone conservation works. The condition of the rest of the building is very bad and potential uses need to be found. Historic England is in dialogue with the leaseholder.

Contact: Sarah Ball 0117 975 0666



SITE NAME:	South Saw Mills, South Yard, HM Naval Base, Plymouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Government or agency

Sawmill built between 1856 and 1859. The saw mills ceased to be used as such in 1987 but the ground floor remained in light industrial use and for storage until 1997. An options report was issued in 2010, but the building remains vacant with no identifiable use.

© Historic England

LIST ENTRY NUMBER: 1388413

Contact: Simon Hickman 0117 975 0717



© Historic England

SITE NAME:	South Smithery, South Yard, HM Naval Base, Plymouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Government or agency

1392692

Dockyard smithery built 1771, modified in the C19 and reconstructed c1897. It remained in use until 1987 when structural faults were discovered. There is continued deterioration of the roof, masonry and interiors. An options report was issued in 2010, but a repair strategy has not yet been put in place. Historic England provided advice in November 2015 in response to a request from the owner to remove the building's roof.

Contact: Simon Hickman 0117 975 0717



© Historic England

SITE NAME:	The coastal fortifications of Drake's Island, Plymouth
DESIGNATION:	Scheduled Monument, LB grade
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1010910

The island incorporates numerous defences/military monuments from 1549 to C20. It was held for Parliament during the Civil War and used for defence purposes until 1958. All buildings and structures are in a derelict condition. A planning application for conversion to hotel use was granted in 2017, works are yet to commence.

Contact: Helen Woodhouse 0117 975 0676

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

SITE NAME:	Woodland Fort, Crownhill Road, Crownhill
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1002615

Palmerston Fort, built between 1863 and 1869. Part of barrack block in use as a social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation has recently been cleared. Site is prone to vandalism and rubbish dumping. Historic England grant-aided repair works in 2016-17 which has cleared part of the ditch and helped to drain the caponier, but considerable further work is still required.

Contact: Annie Evans 0117 975 1308

SITE NAME: Church of St Mary and All Saints, Church Road, Plymouth DESIGNATION: Listed Place of Worship grade II\* CONDITION: Poor PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1330541

Roof coverings, particularly the nave and inner slopes of north and south aisle, are desperately in need of renewal. Slates to these areas have previously been covered with bitumen-coated hessian and will not be reusable for repairs. Valley gutter also needs renewing. Interior suffers from condensation and poor ventilation. Gullies need clearing out. Downpipe to tower leaking or blocked. Some ivy growth to masonry. Buttresses need repointing. Excessive tree growth near north wall. A bid to the last round of Listed Places of Worship Roof Repair Grants was unsuccessful.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Austin Fort and section of military road		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021380
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Efford Fort and Efford Emplacement, Military Road,	Efford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Egg Buckland Keep		
SITE NAME: DESIGNATION:	Egg Buckland Keep Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1020543
	<u>.</u>	LIST ENTRY NUMBER:	1020543 Unknown
DESIGNATION:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised		
DESIGNATION: CONDITION:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised problems	TREND:	Unknown
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised problems  Development requiring planning permission	TREND:  NEW ENTRY?:	Unknown
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised problems  Development requiring planning permission  Private	TREND:  NEW ENTRY?:	Unknown
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised problems  Development requiring planning permission  Private  Fort Stamford	TREND:  NEW ENTRY?:  CONTACT:	Unknown No Daniel Bashford 07824 103102
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument, LB grade II*  Generally satisfactory but with significant localised problems  Development requiring planning permission  Private  Fort Stamford  Scheduled Monument  Generally unsatisfactory with major localised	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:	Unknown No Daniel Bashford 07824 103102

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

meritage at KISK 2018 / SOU	JTH WEST / PLYMOUTH, CITY OF (UA)		
SITE NAME:	Knowle Battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002614
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Annie Evans 0117 975 1308
SITE NAME:	Laira Battery		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021134
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Laira Emplacement, immediately south west of Lair	ra Battery	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020686
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Mount Batten: C17 artillery tower, Civil War brea	stwork, and World	War II remains
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1017599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Plympton Priory		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1017594
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Lee Moor Tramway Bridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002637
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Daniel Bashford 07824 103102
SITE NAME:	Stonehouse Manor wall		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003850
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Daniel Bashford 07824 103102

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	The coastal fortifications of Drake's Island		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010910
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Helen Woodhouse 0117 975 0676
SITE NAME:	Woodland Fort		
SITE NAME: DESIGNATION:	Woodland Fort Scheduled Monument	LIST ENTRY NUMBER:	1002615
		LIST ENTRY NUMBER:	1002615 Stable
DESIGNATION:	Scheduled Monument  Generally unsatisfactory with major localised		

### POOLE (UA)



© Borough of Poole Council

SITE NAME:	Church of St Dunstan (formerly St Osmund), Bournemouth Road
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1273602

Former parish church now used for worship by Greek Orthodox congregation. Constructed largely of red brick in 1904 by GAB Livesay in the free Byzantine style, and completed by ES Prior in partnership with Arthur Grove between 1913 and 1914. The dome was partially rebuilt in 1922-4 by Sidney Tugwell. Suffering extensively from the failure of guttering, drainage and roof maintenance, there has been a substantial impact on the internal decoration and integrity of the brick work. Heritage Lottery Fund Grant for Places of Worship offered. Project development works due to complete in summer 2018.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Round barrow cemetery on Barrow Hill 150 metres south west of Brookvale Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018029
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Katy Hoskyn 0117 975 1311
SITE NAME:	Town Centre, Poole		
DESIGNATION:	Conservation Area, 92 LBs, 3 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
	very bad	THEIRD.	improving

### **SOMERSET**

### EXMOOR (NP)



© T. Thurlow HBO with kind permission of Exmoor National Park Authority

	Selworthy, West Somerset
DESIGNATION:	Scheduled Monument, LB grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Charity (heritage)

1020774

Dovecote at Little Blackford,

This dovecote which survives well requires some repointing, limewashing and repairs to the roof covering in order to secure it in good condition. The setting also requires improvement to safeguard it against inadvertent vehicle damage.

Contact: John Ette 0117 975 0687

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

SITE NAME:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise,

New Entry is noted).

## LPA ΝP RPG

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© T. Thurlow HBO with kind permission of Exmoor National Park Authority

Packhorse Bridge about 50 metres west of Lyncombe, Winsford, West Somerset

DESIGNATION: Listed Building grade II\*

CONDITION: Poor OCCUPANCY: N/A

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Unknown

LIST ENTRY NUMBER: | | 74|59

Packhorse Bridge. C17-C18, possibly earlier. Lias. Dry stone flat bedded rubble; single span, pointed arch; rubble voussoirs; curved abutments; parapet of undressed stone set on end, ramped up to centre. Hump-backed bridge with remains of pebble pathway. A recent condition survey has identified loss or covering of cobble pathway, partial loss of parapet and extensive plant growth including ivy and large saplings rooting into fabric.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Barlinch Priory, Brompton Regis, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006213
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bury Castle, Brompton Regis, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006170
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bat's Castle: a small multivallate hillfort and associa	ited outwork, Carh	ampton, West Somerset
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007667
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Later prehistoric defended enclosure, Long Wood	, Carhampton, Wes	st Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008255
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Mounsey Castle, Dulverton, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021357
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Black Ball Camp: a later prehistoric defended settle	ement on Gallox H	ill, Dunster, West Somerset
DESIGNATION:	Scheduled Monument, RPG grade II*	LIST ENTRY NUMBER:	1007668
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Hillfort on Grabbist Hill, 275 metres south west of	St Leonard's Well	Dunster, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021060
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	St Leonard's Well, Dunster, West Somerset		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1021154
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Almsworthy Common: a stone alignment 560 metrosomerset	res south west of C	Chetsford Bridge, Exford, West
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015017
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Chains Valley stone alignment 400 metres north w	est of Exe Head, Ex	kmoor, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014278
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth - General	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cow Castle, Exmoor, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002955
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Kittuck stone setting and cairn, 200 metres south	west of Three Com	bes Foot, Exmoor, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014284
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sweetworthy deserted medieval settlement, Lucco	mbe, West Somers	set
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 610 metres ESE of the fire tower on	Monkham Hill, Lux	borough, West Somerset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021227
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow 780 metres ESE of the fire tower on Monkham Hill, Luxborough, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021231
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Berry Castle, Iron Age enclosure in Berry Castle Wood, Porlock / Luccombe, West Somerset		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006204
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Allerford packhorse bridge, immediately north of C	Cross Lane Farm, Se	elworthy, West Somerset
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1020776
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bury Castle, an Iron Age defended settlement, Selv	vorthy, West Some	erset
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008808
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Earthwork enclosure on Rodhuish Common, 300 r	metres west of Mod	or Barn, Withycombe, West Somers
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021122
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Brewer's Castle, Withypool and Hawkridge, West	Somerset	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021358
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:  Brightworthy Barrows on Withypool Common, Withypool and Hawkridge, West Somerset  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1021264  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Visitor erosion - extensive  NEW ENTRY?:  No  CONTACT:  Charlotte Russell 01271 831505  SITE NAME:  Stone circle on Withypool Hill 670 metres ESE of Portford Bridge, Withypool and Hawkridge, West	SITE NAME:			
CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Visitor erosion - extensive  OWNER TYPE:  Private  Stone circle on Withypool Hill 670 metres ESE of Portford Bridge, Withypool and Hawkridge, West		Brightworthy Barrows on Withypool Common, W	ithypool and Hawk	ridge, West Somerset
problem's PRINCIPAL VULNERABILITY: Visitor erosion - extensive NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505  SITE NAME: Stone circle on Withypool Hill 670 metres ESE of Portford Bridge, Withypool and Hawkridge, West	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021264
OWNER TYPE: Private CONTACT: Charlotte Russell 01271 831505  Stone circle on Withypool Hill 670 metres ESE of Portford Bridge, Withypool and Hawkridge, West	CONDITION:		TREND:	Declining
Stone circle on Withypool Hill 670 metres ESE of Portford Bridge, Withypool and Hawkridge, West	PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
	OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
	SITE NAME:		Portford Bridge, W	ithypool and Hawkridge, West
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021261	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021261
	CONDITION:	Generally satisfactory but with significant localised	TREND:	Improving
CONDITION: Generally satisfactory but with significant localised TREND: Improving problems	CONDITION.	F. 55.55		
		'	NEW ENTRY?:	No

### **MENDIP**



© Historic England

SITE NAME:	Kilmersdon Lodges, Kilmersdon
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1307411

Pair of lodges, gate piers and gates, associated with Ammerdown House, built from 1788 to 1794, situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was prohibitive. A schedule of work to stabilise the structures has been undertaken; a programme of monitoring is being carried out by the owners.

Contact: Eve Van Der Steen 01179750685


Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Former Anglo-Bavarian Brewery, Commercial Road, Shepton Mallet
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1296561

Brewery, now warehouses, built in 1864. Whilst partly occupied at ground floor level, most of the building has been vacant for many years. A feasibility study has been undertaken which has identified a substantial conservation deficit. A partial collapse has now been repaired. No further work has been undertaken as of 2018.



Private

1175928

Early C17 timber-framed brewhouse later utilised as a cottage, now part calf shed/hay store. In poor condition due to lack of maintenance and beneficial use for many years. Emergency clearance and stabilisation works to the building have been undertaken by Mendip District Council. Discussions underway with Historic England regarding the building's full repair.



© Mendip District Council

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Gatehouse to west of Manor Farmhouse, Whatley
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1175158

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

weak, particularly around the small door under the arch. The vegetation to the east side needs to be removed.

Contact: Sarah Ball 0117 975 0666

-320		).	
1			
社。	and a		

© Historic England

SITE NAME:	Fenny Castle Cross: a medieval wayside cross 20 metres north west of Castle Farm, Castle, Wookey
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Private, multiple owners

1015797

Private, multiple owners

Contact: Alessandra Perrone 0117 975 1345

mortar and vegetation is slowly encroaching.



© Historic England

SITE NAME:	Baptist Chapel, Frome Road, Beckington
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1296104

Chapel dated 1786 now converted to community use as a pre-school as well as a place of worship. Random rubble, with plain corner pilasters, pilasters between each bay and a central pediment with balustraded parapet to each side. Roof aging and some slate slippage. Stone balustraded parapet needs repair work. Some broken panes of glass.

Gatehouse, C15 built from random local limestone rubble with a plain tile roof. Two storeys, all window openings blocked apart from left side of ground floor. The arched entry is slightly left of centre and there is a Tudor arch doorway within the passage. Rear has stone steps to first floor doorway on the left side. The building is showing signs of structural movement to the south gable and significant deflection to the roof. Some areas of stone work are very

A medieval stone cross thought to date back to the early C14. Despite the loss of its shaft, the rest of structure survives in situ though in very bad condition. Several stones show signs of fracture, the joints are open and missing

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of the Holy Trinity, Binegar
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058641

Parish church rebuilt in the CI5 with the tower dating from 1858. The building is generally very well maintained but the slated roofs require complete recovering and new ceilings. The roofs are covered in asbestos cement slates with fibreboard ceilings below. The slates require annual attention to deal with leaks, which have significantly disfigured the ceilings. The floors also need work, due to rotten joists.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St John the Baptist, Church Lane, Chilcompton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1345096

Parish church dating from the C15 much rebuilt in the C19. The nave north parapet has been secured, and there was a significant problem in the eastward parts of the building which had severe frost damage to limestone copings and string courses and further problems with poor walling stone and pointing. Some very significant boundary wall repairs are required. Interior decorations have been damaged by water ingress, now largely under control. A Listed Places of Worship Roof Repairs Grant awarded in 2015 has enabled most work to be completed.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Mary the Virgin Church Street, Croscombe
DESIGNATION:	Listed Place of Worship grade CA

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1174682

Very fine parish church dating mainly from C15 and C16, with C19 restoration. South aisle and nave roofs are leaking. Parapet gutters require redesign. Heritage Lottery Fund Grant for Places of Worship offered and accepted in 2016 for roofing works. Works due to commence in 2018.

Contact: Sarah Ball 0117 975 0666

1	1	

SITE NAME:	Church of All Saints, Pound Lane, Downhead
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174065

Parish church with a perpendicular tower from the C14. Nave, chancel and south porch from the mid C18, the building also has some C19 restorations. The building is generally well maintained. Water penetration to the tower is now spreading and affecting the nave roof structure.

Contact: Annie Evans 0117 975 1308



Christ Church, Christchurch SITE NAME: Street West, Frome Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: C(C)OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1057853

Built 1817-1818 as an aisled nave, with crenellated east tower. Eastern extension built 1904-1905, the south transept in 1899, and the north transept 1929. Perpendicular style, with traceried openwork parapets, pinnacles and gargoyles over buttresses. The rainwater goods are in poor condition. There is detrimental external secondary glazing and large number of tingles (temporary repairs) on chancel roof.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St Giles, Church Walk, Leigh-on-Mendip
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058345

Medieval parish church dating from c1350, rebuilt c1500. Well maintained. Iron cramps are pushing apart the joints in the parapet but as yet not splitting the stones. A programme of repairs addressing the external walling and parapets as well as repairs to the C18 roof coverings is needed. The chancel roof was repaired with Listed Places of Worship Roof Repairs Grant and in 2017, the congregation received a Heritage Lottery Fund Grant for Places of Worship to address the repair of the Nave roof. Work is in development. The congregation is also developing proposals for repairs and reordering.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St Andrew, Mells
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1295876

Parish church. Predominantly late C15, tower of mid C16, mid C19 restoration. Doulting ashlar; low pitched roofs. Clerestoried nave with north and south aisles, continuing as chapels clasping the chancel and polygonal vestry of  $148\bar{5}.$ Important fixtures, fittings and furnishings. The church is generally very well maintained but the roofing materials are coming to the end of their lives. The poor condition classification therefore relates to the roof only.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



SITE NAME:	Church of St Matthew, High Street, Wookey
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1295105

Parish church, dated predominantly from CI5 but with C13 chancel. The building is well maintained, however the nave and aisle roofs are improperly fixed and thus split and leak annually letting water into the C15 roof structure.

Contact: Annie Evans 0117 975 1308

© Historic England

SITE NAME:	Small multivallate promontory fort on Blacker's Hi	II, Chilcompton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015493
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 300 metres north east of Whitnell C	orner, Emborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011670
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Drying house at The Coach House, Willow Vale, F	rome	
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1016955
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Glastonbury lake village, Godney		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006156
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Lake villages north west of Oxenpill, Meare		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006160
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Section of the Abbot's Way trackway, 500 metres	WSW of Honeygar	Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014432
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG SM Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

HERITAGE AT RISK 2018 / SOL	UTH WEST / MENDIP		
SITE NAME:	Sections of the Sweet Track and Post Track, 240 r	netres south west o	of Sunnyside Farm, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014440
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Sections of the Sweet Track and Post Track, 250 r	netres ESE of Statio	on House, Meare
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014831
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Timber trackway site, 700 metres west of Honeyg	ar Farm, Meare	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014434
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Fussell's Lower Works: an iron edge tool works, 2	210 metres south ea	ast of Wadbury, Mells
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019796
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Melanie Barge 0117 9751300
SITE NAME:	Whatley Combe Roman villa, Nunney		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006188
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 250 metres north east of King Down	n Farm, Priddy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 300 metres south west of Moor View	w, Priddy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009773
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bowl barrow 800 metres south of Townsend Farm	n, Priddy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009740
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Romano-British settlement on Stoke Moor, Rodno	ey Stoke / Cheddar	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011125
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Group of round barrows 750 metres north west	of Ivy Cottage, St. C	uthbert Out
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Marston Moat, Trudoxhill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016302
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alessandra Perrone 0117 975 1345

### **SEDGEMOOR**



© Historic England

SITE NAME:	Castle House, Queen Street, Bridgwater
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Charity (heritage)

1355168

LIST ENTRY NUMBER:

House in the centre of Bridgwater in the early Tudor Revival style, built for William Ackerman in 1851. It is notable for the earliest surviving use of prefabricated cast concrete and constructional post tensioning. The building has been in a structurally precarious condition and has had an arson attack. Owned by SAVE Building Preservation Trust. Historic England has grant aided phases of repair with a final phase taking place in 2018, which should take the complete building off the Register. SAVE is still pursuing a sustainable long term future for the building.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Westonzoyland Pumping Station, Westonzoyland
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1174295

A former pumping station, built in the early C19, now preserved by the Westonzoyland Engine Trust. The first pumping station to be built to lift floodwater from the Somerset Levels and Moors, and the only one to survive with the steam engine still working and with the buildings intact. Much work has been done however the buildings are still in need of repair, and are under possible threat from rapid alteration of surrounding drainage and implementation of new drainage schemes. The Trust has been working on a scheme for reuse and repair and is continuing discussions with Historic England.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of All Saints, High Street, Ashcott
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058957

Parish church. Mainly C15 with alterations in the C19. The woodblock floor has lifted and is decayed in many places. This could be due to a leak from the buried C19 cast iron heating pipework. The vestry roof needs re-covering and significant masonry repairs to the tower and nave parapets will be needed in the near future.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

A Unitary Authority
/HS World Heritage Site



© Historic England

© Historic England

© Historic England

© Historic England

SITE NAME:	Baptist Church, St Mary Street, Bridgwater
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1298798

Baptist church, built in 1837 by Edwin Down. Rectangular plan with schoolrooms to the rear. Classical frontage with Bath stone pediment and cornice, flight of steps up to central Egyptian style doors. High level stonework is in poor condition. Rainwater goods are also poor. Rear of the building has vegetation growth and the brickwork needs repointing.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Church of St Edward, Church Lane, Chilton Polden
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060126

Parish church of C15 origin, largely rebuilt in 1889. Rubble, slate roofs with coped verges and bellcote at west end. Chancel and nave, north aisle, north transept, north and south porches and vestry. Neo-Perpendicular with some Perpendicular features remaining. There is cracking to the vestry wall and the roof covering is failing. The church was awarded a Listed Places of Worship Roof Repairs Grant in 2016 but more repairs are required.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Mary, Fore Street, North Petherton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1058924

The church was mostly built in the late C14 and early C15 including the tower, in a Perpendicular style. Inside the tower at the height of the nave is a fine fan vault, unusual for a village church. The north aisle parapet and south aisle roof have been repaired with a Heritage Lottery Fund and Historic England Repair Grant for Places of Worship, completed in 2013. Further work to rainwater goods is now complete, funded by a Listed Places of Worship Roof Repairs Grant. The tower stonework is also in need of repair; some unsafe parts removed and set aside by rope access masons in 2017.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Michael and All Angels, Rye, Puriton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1344664

Parish church. C14 to C15 chancel nave and north aisle and early C13 unbuttressed west tower with lancet window. South porch, north vestry. Coursed rubble, freestone dressings, mixed material roofs, interior has Perpendicular rood screen. Tower render failing and falling from the tower. Historic England gave advice following removal of the render in late 2016. Additional issues with the vestry wall and aisle roof remain.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary Magdalene, Stockland Bristol
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1059049

Parish church built in 1865 of blue lias rubble stone. Designed by Arthur of Plymouth for the Daniel family of Stockland Manor. Roofs need re-covering and there are a number of slipped tiles. Structural stability is poor with cracking to window surrounds and major fracture through the tower, with loose stonework on the parapet and vice turret. Some repairs to valley gutter and one window which was blown in were carried out in 2017 but the church remains in a very poor state.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



@ Historic	England

SITE NAME:	Church of St Peter, Church Lane, West Huntspill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1060138

Large parish church, with chancel, nave, quire aisles and nave aisles, two-storeyed south porch and western tower. Largely C14, lias with Ham stone dressings. The church was gutted by fire in 1878 and comprehensively restored in neo-medieval style. The aisle roofs leak every six months and are patched with sealant and flashband as they are too fragile for more reliable repairs. Lias stone has problems in some places, notably the north parapet, north aisle vice turret and tower. The parish was unsuccessful in its bid for Listed Places of Worship Roof Repairs Grant in late 2016.

Contact: Annie Evans 0117 975 1308

TE STORY	SITE NAME:
	DESIGNATION:
	CONDITION:
	PRIORITY CATEGO
14	OWNER TYPE:
	LIST ENTRY NUMBE

SITE NAME:	Church of St Mary, Main Road, Westonzoyland
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Fair
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1174351

Parish church of C13, C14, C15, C16 and C19 with significant additions by WD Caroe 1933-1939. Notable for housing 500 defeated rebels following the Battle of Sedgemoor in 1685. The C15 timber roof structure is of considerable significance with carved angel corbels. The congregation undertook a large scheme of roof repair in 2016 with a Listed Places of Worship Roof Repairs Grant but there are concerns about the condition of the tower.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Medieval estate boundary earthwork on Shute She	lve Hill, Axbridge /	Winscombe and Sandford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015495
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Horsey medieval settlement immediately north of Board's Farm, Bridgwater Without		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020438
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Ruborough Camp large univallate hillfort, Broomfie	eld	
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1007670
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Timber trackways 850 metres east of Catcott Burn	tle Farm, Burtle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014433
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cynwit Castle, Cannington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006225
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

HERITAGE AT RISK 2018 / SOU	JTH WEST / SEDGEMOOR		
SITE NAME:	World War II anti-aircraft rocket battery and bo Ashridge Farm, Cheddar	mbing decoy control	building 265 metres north east of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020994
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Platform cairn, 180 metres east of Wilmot's Poo	l, Over Stowey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1417363
CONDITION:	Optimal/generally satisfactory	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bronze Age and Iron Age timber trackways, 700 metres north west of Coppice Gate Farm, Shapwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014431
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Sections of the Sweet Track, the Post Track and associated remains 500 metres north east of Moorgate Farm, Shapwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014438
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bronze Age and Iron Age trackways 600 metres	north east of Northb	prook Farm, Shapwick / Ashcott
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014444
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Round barrows 600 yards (550 metres) north west of Longbottom Farm, Shipham		
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1006223
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Prehistoric timber trackways, 670 metres SSE of	Parchey Bridge, Staw	vell
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014430
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Charlotte Russell 01271 831505

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**



© Historic England

SITE NAME:	Halswell Park, Goathurst / Broomfield
DESIGNATION:	Registered Park and Garden grade II, 17 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001145

An C18 landscape park. Local preservation trusts have restored two important garden buildings but some other structures remain in poor condition. The centrepiece of the design, Mill Wood, was largely denuded of trees, however it changed hands in spring 2015 and was reunited with the house. This has led to a major programme of replanting and repairs to structures including the listed Bath stone bridge. Despite this, the majority of the park remains under intensive cultivation.

Contact: Jo McAllister 0117 975 0696

### SOUTH SOMERSET



© South Somerset District Council

SITE NAME:	Top mill building, Higher Flax Mills, Torbay Road, Castle Cary
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1056226

This mid C19 former mill has been sold and an application approved for conversion to one live/work unit in 2011. Works are underway and making slow but good progress. The southern roof is now complete. The building is mostly occupied but work is still on-going.

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Chard School, Fore Street, Chard Town
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Educational (independent)
LIST ENTRY NUMBER:	1205594

The building dates to 1583. It became Chard Grammar School in 1671 and has been a school ever since. It has an L-Plan layout with five bays, a rear wing and two storeys with attics. The building was an advanced plan form for its date, notable for passage access to the main rooms. Features include squared chert Hamstone dressings, window hoods and mullions, plain tile roof and brick stacks. The rainwater goods are inadequate, areas of water ingress and structural issues where trusses have been altered.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A, Fore Street, Chard Town
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1197449

Late C16/early C17 group of shops, offices, houses and flats with two prominent projecting two and three storey porches. A 2010 planning appeal refused a proposed subdivision to create smaller units. In 2014 the Local Authority commissioned a feasibility study with Historic England grant-aid. Discussions with the multiple owners over the options suggested are continuing. Work begun in 2017 to repair the three-storey porch to 7A has been completed in 2018 with Historic England grant-aid.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Madey Mill, East Street, Martock
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1226550

are largely C17. The building is situated on a working farm, is under-used and is suffering from lack of maintenance. Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. A Historic England funded condition survey has been completed, identifying urgent repairs.

Water mill with medieval origins, although current buildings

Contact: Chris Miners 0117 975 1308

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise.

### I PA ΝP New Entry is noted). RPG

## **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

Secular college at Parsonage Farm, Stoke Sub Hamdon SITE NAME: Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; 6 grade II,

CONDITION: Poor

OCCUPANCY: Vacant/not in use

C (C) PRIORITY CATEGORY:

OWNER TYPE: Charity (heritage)

1020665 and 1260178; LIST ENTRY NUMBER: 1242240; 1260179; 1242150; 1260105; 1260180; 1242246

Attached to this chantry college is a group of medieval and C16 farm buildings, some of which are in poor condition and unroofed. However others, such as the threshing barn, are capable of beneficial use. Owned by the National Trust, Historic England has had a number of meetings on site and in 2015 and 2016 funded an options appraisal to consider ways of bringing the buildings back into use. Discussions are continuing and the National Trust is considering ways to improve the use of the site and safeguard the roofless buildings.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME: The east Rope Walk, at Job Gould's West of England Twine Works, East Street, West Coker DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B)

OWNER TYPE: Private LIST ENTRY NUMBER: 1057116

OWNER TYPE:

Early C19 Rope walk. Extremely long (97 metres) building of three-storeys, partly open at ground floor level, oak trusses with some weatherboarding and windows along the east and west; later brick southern end; undulating double roman clay tile roof, five ropewalks on two levels, some original machinery. The building is fragile, roof has been patched but battens have slipped in numerous places allowing in water; trusses fractured and structure under stress. Historic England grant-aided temporary works to support the structure in 2016-17 whilst options for repair and re-use are considered.

Contact: Annie Evans 0117 975 1308



© South Somerset District Council

SITE NAME:	The former Ropewalk, 75 metres north east of Millbrook House, High Street, West Coker
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)

Charity (heritage) LIST ENTRY NUMBER: 1057092

Former twine works, now store and workshop. Late C19 with C20 alterations and extensions. Historic England grant-aided urgent repairs have been undertaken and supporting scaffolding has been erected. In 2011 the lease was taken over by the Coker Rope and Sail Trust which has undertaken structural repairs. In September 2016 the Heritage Lottery Fund approved a grant which will fund completion of Dawe's restoration, and works are underway.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	White Horse Hotel, 4, High Street, Wincanton
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1274102

Inn dated 1733 built by Nathaniel Ireson in free baroque style. Local stone cut and squared with painted ashlar dressings; plain clay tile roof behind parapet, simple gables; brick end chimney stacks. Three-storey and three bays to road. Early cross-wing, also second cross-wing with columns that may relate to use as an inn. Early C20 dance hall at the rear. Building in poor condition with façade parting from roof, and floors decayed. Work had commenced on site but has now stopped.

Contact: Rhiannon Rhys 0117 975 0685

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

© Historic England

© Historic England

SITE NAME:	Church of St Andrew, Aller
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1227327

Small church of Saxon origin with C12/C13 and C15 additions and major restoration 1861 to 1862 by H John Norton. Tower stonework was repaired under the joint Heritage Lottery Fund and Historic England Repair Grant for Places for Worship scheme in 2013. The Nave ceiling is at risk of loss in several areas, and parts have been roped off for safety in the past. The church was offered a Listed Places of Worship Roof Repairs Grant and in 2017-18 the nave and south porch roofs were recovered, and ceilings repaired. The chancel, north aisle and north porch roofs remain in poor condition.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of the Holy Trinity, Main Street, Ash
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057286

Parish church built in 1841 by Sampson Kempthorne, chancel added 1887, and tower added 1919. Ham stone cut and squared with ashlar dressings and a Welsh slate roof between coped gables. The coping stones have become dangerous and the tower masonry is in poor

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Mary Magdalene, Church Lane, Barwick
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057217

Parish church C13 and later. Ham stone roughly squared and coursed, with ashlar dressings; plain clay tiles between coped gables to chancel south aisle and nave, stone slates to south porch. Chancel is an 1885 rebuild incorporating earlier fragments. The tower roof is in poor condition, the bell frame needs work and the nave and aisle roofs are also in poor condition. The church has been awarded a Heritage Lottery Fund Grant for Places of Worship and it is expected that repairs to the tower roof will start by the end of 2018.

Contact: Annie Evans 0117 975 1308

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of St Nicholas, Bratton Seymour
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177220

Parish church with C13 origins. Two-cell plan, of two-bay chancel and three-bay nave, with west tower and south porch, and small north-east vestry. High level stonework needs repairing urgently. Interior poor with ceilings at risk of falling and some plaster already having fallen.



SITE NAME:	Church of St John the Baptist, Charcroft Hill, Brewham
designation:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1056463

Parish church reputed to date from the C13 with much C19 rebuilding. The tower is inhabited by birds making inspection difficult. The church has been subject to heritage crime previously and the roofs are generally in need of repair. The rainwater goods are in poor condition.

Contact: Annie Evans 0117 975 1308

© Historic England

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.

SITE NAME:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, West Charlton, Charlton Mackrell
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1056728

Parish church. C13 origins, but restored in 1792-1794 and in 1847. Local lias stone cut and squared, with Ham stone ashlar dressings. Stone slate roof between coped gables. Signs in the churchyard warning of the danger of slipping roof slates. All roofs need recovering as the fixings have rusted and the stone tiles are laminating.

Contact: Annie Evans 0117 975 1308

Contact: Sarah Ball 0117 975 0666



SITE NAME: Church of St Stephen, Charlton Musgrove

DESIGNATION: Listed Place of Worship grade II\*

CONDITION: Poor

PRIORITY CATEGORY: D (New entry)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1346185

C13 church with later additions and alterations. The stone slate roofs are slipping and areas around the church have been cordoned off pending repairs. The congregation was awarded a Heritage Lottery Fund Grant for Places of Worship in 2017.

© Historic England

© Historic England

© Historic England



SITE NAME:

Church Without Dedication, High Ham

DESIGNATION:

Listed Place of Worship grade I

CONDITION:

POOR

PRIORITY CATEGORY:

C (C)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1346080

Parish church, formerly private chapel to manor. On site of earlier church, started early C17, damaged in Civil War, completed in 1690. Local lias stone cut and squared Ham stone dressings; Welsh slate roofs, coped gables behind castellated parapets. In a Gothic Revival style. East side of the tower has been repointed but there is still repair work needed to stonework in poor condition. Parapet unstable. Nave re-roofed c 1999 but chancel roof poor. The tower roof will need re-covering in the near future.

Contact: Annie Evans 0117 975 1308



SITE NAME:	Church of All Saints, Isle Brewers
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1263514

Parish church built 1861 by CE Giles. Built of lias stone with Ham stone dressings. The roof tiling is poor and the ceiling (which appears to be plastered directly onto the underside of the rafters) is falling in so that the whole of the interior of the nave is netted. A couple of the windows are in need of repair. The stair tower has severe fracturing. A Heritage Lottery Fund Grant for Places of Worship has been awarded.

Contact: Sarah Ball 0117 975 0666



© Historic England

SITE NAME:	Church of St Mary, Church Street, Limington
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1056844

Church dating from C13 onwards. Local squared random rubble with Ham stone dressings. Tiled roofs except for the fine north chapel of 1328 which has an unusual stone roof over ribbed barrel vault. The nave roof is at the end of its life particularly the south slope. The chantry chapel roof is leaking and causing damage to the interior. The congregation has secured a Heritage Lottery Fund Grant for Places of Worship and, as of 2018, is developing a scheme for repair.

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Church of St Mary the Virgin, Stoke Sub Hamdon	
DESIGNATION:	Listed Place of Worship grade I, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Religious organisation	

1260420

Parish church of mainly C12 and C13 with later additions. Water ingress problems leading to damp as evidenced by the algal growth on the north and south side of the nave (and in the porch). Vegetation needs clearing from between the coping stones and roof slates. Rainwater goods in need of repair. The congregation has been awarded a Listed Places of Worship Roof Repairs Grant and some work was carried out in 2016-17 but more repairs are needed.

Contact: Annie Evans 0117 975 1308

B
i i tit di

SITE NAME: Church of St Martin of Tours, Church Street, West Coker Listed Place of Worship grade DESIGNATION: II\*, CA CONDITION: Poor PRIORITY CATEGORY: A(A)OWNER TYPE: Religious organisation

1345829

C13 or C14 origins, mostly rebuilt in 1863-1864. The church itself is well used, however recent failure of the nave roof and water ingress through the chancel roof are causing significant damage. A Heritage Lottery Fund Grant for Places of Worship was offered in 2016. Project development work has been completed and works commenced in early 2018.

Contact: Sarah Ball 0117 975 0666

© Historic England

SITE NAME:	Low Ham Roma	n villa, High Ham			
DESIGNATION:	Scheduled Monu	Scheduled Monument		1006192	
CONDITION:	Generally unsatis	Generally unsatisfactory with major localised problems		Stable	
PRINCIPAL VULNERABILITY:	Animal burrowir	ng - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Commercial con	Commercial company		Alessandra Perrone 0117 975 1345	
SITE NAME:	Northover House, late Roman cemetery, Ilchester				
DESIGNATION:	Scheduled Monu	ment, CA	LIST ENTRY NUMBER:	1006128	
CONDITION:	Generally unsatis	Generally unsatisfactory with major localised problems		Stable	
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)		CONTACT:	Annie Evans 0117 975 1308	
SITE NAME:	Large multivallat	e hillfort and associated earthwork	s at South Cadbury	, South Cadbury	
DESIGNATION:	Scheduled Monument, 2 CAs		LIST ENTRY NUMBER:	1011980	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Improving	
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Alessandra Perrone 0117 975 1345	
DE CC	SITE NAME:	Redlynch Park, Bruton / Shepton Montague	Redlynch is a larg	Formerly the principal seat of the Earls of Ilchester, Redlynch is a large landscape park near Wincanton. The main house has gone and the stables and ancillary buildin	
	DESIGNATION:	Registered Park and Garden grade II, 10 LBs	are now in multip parkland planting	ble ownership. The majority of the has disappeared, boundary walls and	
	CONDITION:	Generally unsatisfactory with major localised problems	also on-going de	e generally in poor condition. There are velopment pressures. An C18 Gothic Fowers, was repaired in 2012 and is no	
	VULNERABILITY:	Medium	longer at risk, an	d sections of the park wall have been	
	TREND:	Stable	repaired with a N	Natural England Stewardship Scheme.	
© Historic England	NEW ENTRY?:	No			
	OWNER TYPE:	Private, multiple owners			

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

1000420

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Jo McAllister 0117 975 0696

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Cricket House, Cricket St. Thomas / Winsham	
DESIGNATION:	Registered Park and Garden grade II*, 8 LBs	
CONDITION:	Generally satisfactory but with significant localised problems	
VULNERABILITY:	Medium	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	

1001142

C18 landscape park and pleasure grounds surrounding listed mansion, partly by Sir John Soane. Pressure for development from a large hotel and from farm diversification into the leisure market. Parts of the park have been restored through a Natural England Stewardship Scheme.

Contact: Jo McAllister 0117 975 0696

### TAUNTON DEANE



© Historic England

SITE NAME:	Sandhill Park, Bishop's Lydeard
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1295317

Country house c1720. A fire in 2011 caused serious damage to the roof structure and top floor. In 2013, planning permission was granted for an enabling development scheme, which has now been completed, although works to the house did not commence. In 2017, consent was granted for conversion of the ancillary buildings and a new roof to the main house. The new roof has been completed, and works to the ancillary buildings are underway. Pre-application discussions continue in respect of the principle building.

Contact: Rhiannon Rhys 0117 975 0685

Contact: Rhiannon Rhys 0117 975 0685



© Historic England

SITE NAME:	Gatehouse at Cothelstone Manor, Cothelstone
DESIGNATION:	Listed Building grade I, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
	· /

1059192

A mid C16 gatehouse which is part of a much larger estate. Consent has been granted for use as holiday let with associated repairs, but has not yet been implemented.



© Historic England

SITE NAME:	Cloth finishing works at Tone Mills, North Range, Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

A near complete example of a C19 cloth dyeing and finishing works which developed between c1830 and c1920. Taunton Deane Council and Historic England are actively engaged in trying to find a solution to conserve the buildings. The site has suffered from vandalism on multiple occasions during the last five years.

LIST ENTRY NUMBER: 1271246 Contact: John Ette 0117 975 0687



© Historic England

SITE NAME:	Tonedale Mills (east complex), Milverton Road, Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Commercial company, multiple owners
LIST ENTRY NUMBER:	1176514

textile factory, now largely disused. Consent granted for mixed use redevelopment of the complex. Works halted on site in 2008 and owners went into receivership leaving some buildings in a very vulnerable condition. The site has since been sold.

Eastern complex of an integrated multi-component wool

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental and first a good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

ABBREVIATIONS

CA Conservation Area
y is LB Listed Building
ise, LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Tonedale Mills (west complex), Wellington
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1051987

Western complex of an integrated multi-component wool textile factory, now largely disused. Consent was granted for mixed use redevelopment of the complex. Works halted on site in 2008 and pre owners went into receivership leaving some buildings in a very vulnerable condition. The site had some scaffolding and work carried out in 2017 but following concerns raised by the Local Authority this ceased. Enforcment Action has been undertaken to secure Tonedale House following unauthorised works with further ongoing discussions concerning the future of the site and its conservation.

Contact: John Ette 0117 975 0687



© Historic England Archive

SITE NAME:	Wellington Monument, Wellington Without
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1060281

175 feet high triangular tower commemorating the Duke of Wellington's victory at the Battle of Waterloo. Construction began in 1817; money ran out and a cheaper revised design was then followed, completed in 1854. The stonework has extensive cracking, with successive repair campaigns over generations. The National Trust has owned it since 1934, but closed the monument to the public in 2007 due to safety concerns. An extensive programme of work has been undertaken to understand the problems and to devise a strategy for repair. Part of the funding has been secured but more is required.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	Church of St John, Park Street, Taunton
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1059951

Built 1858-1863, by George Gilbert Scott. Chancel, nave, north and south aisles; north chapel; south porch and choir vestries at the north-east. Prominent tower and spire with polychrome banded decoration, and figures of the apostles in tabernacles masking the broaches. A faculty was granted in 2016 for alterations to the west end to make the church accessible to a wider range of people. The roofs are also aging and in need of work, and the high level stonework is potentially fragile.

Contact: Annie Evans 0117 975 1308

SITE NAME:	The Castles, Bathealton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019150
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow and folly ruins on Cothelstone Hill, I	kilometre north ea	ast of St Agnes' Well, Cothelstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015086
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Bowl barrow on Cothelstone Hill, 1,070 metres no	orth east of St Agne	es' Well, Cothelstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015087
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Charlotte Russell 01271 831505

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

SITE NAME:	Duck decoy 250 metres north west of Moredon H	ouse, North Curry	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1014441
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Norton Camp large univallate hillfort, Norton Fitzy	varren	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1008467
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Poundisford Park Pale, Pitminster / Trull		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1002957
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Cairn 280 metres south of Triscombe Stone, West	: Bagborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016707
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Camp south of Manor Farm, Wiveliscombe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006167
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Wellington		
DESIGNATION:	Conservation Area, 90 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Nigel Pratt (LPA) 01823 356492

### **WEST SOMERSET**



© Historic England

SITE NAME:	Remains of Chantry at Kilve, Sea Lane, Kilve
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1002960 and 1345688

to be remains of collegiate dwelling of chantry priests. A Historic England survey has shown that the ruins are part of an important manorial complex. Historic England funded emergency repairs in 2010 and 2011, a conservation plan and further works in 2013 and 2014. Ongoing talks between Historic England and the owner are positive and further jointly funded consolidation works were undertaken in 2015. Structural movement in one gable, which is propped, remains to be addressed and another phase of work is planned for 2018-19.

Early C14, with later medieval additions, formerly believed

Contact: Annie Evans 0117 975 1308

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



SITE NAME:	Church of St Mary, Brompton Regis, West Somerset
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1057978

Anglican parish church with C13 west tower, chancel possibly partly C13 with later rebuilding, C14 south transept much rebuilt in C19, nave and north aisle rebuilt around 1490. Restored in 1853 and reroofed in 1885. The tower was restored in 1895 but is now leaking badly with algal growth inside. A Heritage Lottery Fund Grant for Places of Worship has been awarded and repairs are planned for 2018-19.

Contact: Annie Evans 0117 975 1308

© Historic	England
------------	---------

SITE NAME:	Barrow and cairn cemetery on Black Hill, 490 met	res north west of C	Crowcombe Park Gate, Holford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019381
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Dowsborough hillfort and associated round barro	w, Holford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010494
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Entrenchment on Heydon Hill, Huish Champflowe	r	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006173
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Four medieval fish weirs 500 metres east of the H	arbour, Minehead	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020017
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Curdon Wood Camp, Stogumber		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006158
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Charlotte Russell 01271 831505
SITE NAME:	Stringston churchyard cross, Stringston		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006171
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Charlotte Russell 01271 831505

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious power (applicable only). obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Round barrow cemetery at Battle Gore immediately west of North Road, Williton		load, Williton	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1019032
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Charlotte Russell 01271 831505
	SITE NAME:	St Audries (House), West Quantoxhead / Williton	mansion, togeth	19 gardens and pleasure grounds, surrounding a C19 ansion, together with parkland developed from the m 18 and improved in the mid-C19. St Audries has had a ccession of institutional uses; derelict former school ildings remain in the walled garden. The parkland is ostly under cultivation and few parkland trees survive. Idries house and gardens are in use as a wedding venu
	DESIGNATION:	Registered Park and Garden grade II, 16 LBs	succession of ins	
	CONDITION:	Generally unsatisfactory with major localised problems		
	VULNERABILITY:	Medium		
	TREND:	Stable		
	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1001155	Contact: Jo McA	llister 0117 975 0696

## SOUTH GLOUCESTERSHIRE (UA)



SITE NAME: Monument to Lord Robert Edward Somerset, Hawkesbury DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER:

A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast iron balcony and stonework.

© Historic England Archive

1320834

Contact: Sarah Ball 0117 975 0666



© Historic England

Ragged Castle or Keeper's SITE NAME: Lodge, Badminton Park, Hawkesbury Listed Building grade II\*, RPG DESIGNATION: grade I CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Folly Castle. Set on a motte at end of a main drive from Badminton House, c1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure is in poor condition. Interior has been lost. There has been clearance of vegetation on and around the structure.

OWNER TYPE: Private LIST ENTRY NUMBER: 1156209 Contact: Sarah Ball 0117 975 0666



© Historic England Archive

SITE NAME: Whitfield Tabernacle, Park Road DESIGNATION: Listed Building grade I, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE: Private

1116201

Former chapel, built in 1741. The building has been redundant for many years and a fire has placed the building in an even more vulnerable position. In 2013 Historic England funded an Options Appraisal and South Gloucestershire Council have served an Urgent Works Notice and undertook emergency repairs and consolidation work in 2013-14. Discussions between the Local Authority and the owners to establish a sustainable and viable long term strategy for the site are on-going in 2018.

Contact: Alessandra Perrone 0117 975 1345

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Brandy Bottom Colliery, Pucklechurch
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OVA/NIED TYPE	C

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1019400

A former C19 steam-powered colliery built on the site of C18 colliery. The Avon Industrial Buildings Trust have taken on the site and run regular work parties. They have undertaken vegetation clearance and minor repairs to stabilise the structures. Historic England grant aided works since 2014 have included repairs to the chimney, the structures within the Old Pit and some interpretation. A Heritage Partnership Agreement document forms the basis of an on-going programme of repair and research.

Contact: Alessandra Perrone 0117 975 1345

Coach house and stables, built 1722 in a mannered provincial baroque. The building is under a temporary roof. Listed Building Consent was approved in 2011 for substantial repair works. A separate application was made for a wind turbine which was approved in 2013 on the basis that the revenue generated from it should assist in funding the repairs to both listed properties on the site. Historic England provided structural advice in early 2018 on the condition of the scaffolding with the view of securing maintenance works to the temporary supporting structure.



© Historic England

SITE NAME:	Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1312305

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1321124

Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part occupied. Vacant part has serious decay of floor structures and in areas is unsafe, but emergency repairs have been implemented. Discussions over full repair remain on-going. Some enabling development has been permitted in the form of renewable energy.

Contact: Stephen Guy 0117 975 0725



© Historic England

SITE NAME:	Parish Church of St Andrew, Church Lane, Cromhall
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER	1114974

Parish church. C12, rebuilt in C13/C14 and altered C15; restored 1852. Rubble with freestone dressings; stone slate roof with coped raised verges, slate to the nave. The sandstone slates have slipped or are missing. The rainwater system is rusted and leaking. There is structural cracking over the south aisle east window and over the west window.

Large urban parish church with a nave, chancel, aisles, transepts and west tower. Sandstone with limestone dressings and roofed with stone slates. Localised leaks over many years are steadily worsening over much of the roof. The north aisle and the south chancel roofs should be the

Contact: Chris Miners 0117 975 1308



© Historic England

SITE NAME:	Church of St Mary the Virgin, Church Road, Yate
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1128753

Contact: Chris Miners 0117 975 1308

first to be repaired.

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise. New Entry is noted).

**ABBREVIATIONS** Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Round barrow on Barrow Hill, Bitton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1004521
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Roman villa and earlier settlement remains in Badn Hawkesbury	ninton Park, 340 me	etres south of Hinnegar Lodges,
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1021415
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
SITE NAME:	Bury Hill camp, Moorend, Winterbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007023
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alessandra Perrone 0117 975 1345
	SITE NAME: Tortworth Court, Cromhall / Falfield / Tortworth		rian house and grounds, including etum. House now a hotel and part of



© Historic England

SITE NAME:	Tortworth Court, Cromhall / Falfield / Tortworth
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners

1000394

LIST ENTRY NUMBER:

grounds lost to Leyhill Open Prison. Walled garden being redeveloped for light industrial use. Arboretum neglected. Extensive loss of trees in park. The registered area is in multiple ownership and suffers from a lack of holistic management. In 2016 a Conservation Management Plan for part of the registered park was produced with grant aid from Historic England. This was followed in 2017 by a grant to assist with de-silting the lake, which forms the centrepiece of the design.

Contact: Jo McAllister 0117 975 0696



© Historic England

SITE NAME:	Stoke Park, Stoke Gifford
DESIGNATION:	Registered Park and Garden grade II, 10 LBs, SM, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000129

Mid-C18 park laid out around crenellated Dower House. The park is in a dramatic location on a hill overlooking the city of Bristol and is embellished by monuments and eye-catchers. Now bisected by the M32 motorway. Setting compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use, particularly affecting park structures. In 2012, the majority of the site was transferred to Bristol City Council who received a Historic England grant towards a Conservation Management Plan in 2015-16. The park is now under a Natural England Stewardship Scheme.

Contact: Jo McAllister 0117 975 0696

SITE NAME:	Whitfield Tabernacle		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ian Gething (LPA) 01454 863578

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Warmley, Siston / Oldland		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Ian Gething (LPA) 01454 863578

### SWINDON (UA)



SITE NAME: The Mechanics Institute, Emlyn Square DESIGNATION: Listed Building grade II\*, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C)

Commercial company

Mechanics Institute, 1853-5; now vacant. Outstanding example at heart of railway village. The council served an Urgent Works Notice on the owner in 2009 and implemented works in 2010 to secure the building. The shell of the building has been stabilised. Forward Swindon are looking to find a sustainable future for the building.

© Historic England Archive

LIST ENTRY NUMBER: 1198947

OWNER TYPE:

Contact: John Ette 0117 975 0687



© Historic England

SITE NAME:	Church of St Margaret, Church Street, Stratton St. Margaret
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1185393

Large parish church now within northern suburbs of Swindon. Consists of nave, chancel, north aisle, north vestry (an extension of the aisle), south aisle with twostorey south porch and two-stage west tower. C13 origins, C19 low two-stage west tower. The stone slating to the roofs of the porch, chancel and south slope of the south aisle roofs are in poor condition. Heritage Lottery Fund Grant for Places of Worship offered in 2017 for roof repairs. Project in Project Development stage during 2018 with work anticipated to start towards the end of in 2018.

Contact: Sarah Ball 0117 975 0666

SITE NAME:	Bowl barrow 280 metres north of Downs Barn,	Bishopstone	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010419
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Hinton Downs, Bishopstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010461
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Disc barrow on Burderop Down, I kilometre no	orth east of Upper He	erdswick Farm, Chiseldon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010457
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Bowl barrow I kilometre west of Sheppard's Farm	Dairy, Chiseldon /	Ogbourne St. George	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012439	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Field system and earthwork enclosure on Burdero	p Down, Chiseldor	n / Ogbourne St. George	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016383	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Four Highworth circles 150 metres north east of P	ickett's Copse, Hig	hworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016386	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
ITE NAME:	Three Highworth circles 600 metres east of North	Three Highworth circles 600 metres east of North Leaze Farm, Highworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018221	
CONDITION:	Extensive significant problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 700 metres south west of Liddington	Warren Farm, Lid	dington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009634	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Long barrow 700 metres north of Liddington War	ren Farm, Liddingto	on / Wanborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009631	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Remains of Holy Rood Church, The Lawn, Old To	wn		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1018057	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Site of Roman town, west of Wanborough House, Wanborough / Covingham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004684
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645

### TORBAY (UA)



© Historic England

SITE NAME:	Lupton House (Gramercy Hall School)
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1195173

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate garden. Altered after a fire in 1928. In use as a school from mid C20 to 2004. A charitable trust has acquired the house and parts are used for weddings and community health activities. Historic England grant-aided development work to the Italianate Garden in 2015, and for a condition survey of the house and ancillary structures and emergency repairs, including a trial area of repair to the Italianate Garden, in 2017. Further major funding from other sources will be required.

Contact: Annie Evans 0117 975 1308



. 4	3/4	事 部		Car.		N.
		を		1000	233	ä
	- Name	100	0	- 1		
11 - 4	<i>( )</i>					
					- 33	
	0.5					
0.00	1000			The same of	1000	

SITE NAME:	llsham Manor Oratory, llsham Road, llsham
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	1206789

Redundant oratory, part of the demolished medieval Ilsham Manor. Sited in the grounds of a school, which is now closed. Neglected and in poor condition, when assessed in 2012 the chapel was not in use. By 2015 large holes in the roof coverings had opened up and the rainwater goods were missing, causing significant water ingress. Historic England grant-aided a condition survey in 2016 and urgent repairs to the roof were completed with Historic England grant-aid in 2017. Repointing, window, and interior repairs remain to be tackled.

Contact: Annie Evans 0117 975 1308



© Torbay Council

© Historic England

SITE NAME:	Torbay Cinema, Torbay Road, Paignton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (B)
OWNER TYPE:	Charity (heritage)

1208209

Cinema first licensed in 1912 and frequented by Agatha Christie. An extremely well preserved example of an early purpose-built cinema. The building closed in 1999 and Historic England helped with the transfer of ownership of the building to a new Trust. The Trust secured Coastal Revival funds in 2016 which have allowed the building to be accessible for public visits. A proposed grant from Historic England is in discussion in 2018 to address emergency work to the two-storey bay window. Further funding from other sources is being sought.

Contact: Annie Evans 0117 975 1308



© Historic England

SITE NAME:	The Bishop's Palace, Tower Road, Paignton
DESIGNATION:	Scheduled Monument, 2 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1020764

C14 curtain wall and tower, forming part of the medieval fortified residence of the Bishop of Exeter. Vegetation growth, especially valerian on the wall tops and growing from crevices, threatens the medieval walls. Their root system grows to a large bulbous form within the wall, pushing stones out of line and leading to breakdown of the structure. Ivy has also taken hold and is rapidly spreading along the south wall. In 2016 Historic England grant-aided a programme of vegetation removal and door rerfubishment.

Contact: Daniel Bashford 07824 103102

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

### **ABBREVIATIONS**

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

Church of St Mary Magdalene, SITE NAME: Upper Union Street, Torquay Listed Place of Worship grade DESIGNATION: II\*, CA

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1219197

Parish church. Built between 1843 and 1849 to the designs of A Salvin, by contractor Jacob Harvey. Altered and partly re-fitted under GG Scott 1881-82; further embellishment 1906 and 1927. Local grey limestone rubble with Bath stone dressings; slate roof. Rainwater goods all need overhauling. The church received a Listed Places of Worship Roof Repairs Grant in 2017 and rainwater goods have been overhauled. High level stonework in very bad condition and difficult to access. The clerestory stonework spalling badly. A rope access survey has identified these problems in more detail.

Contact: Annie Evans 0117 975 1308

SITE NAME:	Ashhole Cavern, Brixham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1019133
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Daniel Bashford 07824 103102



© Historic England

SITE NAME:	Oldway Mansion
DESIGNATION:	Registered Park and Garden grade II, 12 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001368

Formal gardens laid out to complement a grand house, apparently inspired by the Palace of Versailles. Built by the Singer sewing machine dynasty, the grounds have been steadily rationalised and simplified. Permission was granted in 2012 for mixed-use development, including a hotel in the main house and housing in the grounds, but this was never implemented. The property remains in Local Authority ownership, with no scheme identified.

Contact: Jo McAllister 0117 975 0696

Contact: Jo McAllister 0117 975 0696



© Historic England

SITE NAME:	Lupton Park, Kingswear
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000696

The designed landscape was principally developed from the late-C18 through to mid-C19. After World War II the house became a hotel, then a school. Today a trust occupies the house (at risk) with the degraded Italianate garden, while other owners occupy the park, walled garden, pleasure grounds and woodlands. In 2015 Historic England funded a condition report for the Italianate Garden and a further grant for development work on the house and garden was offered with work underway in 2017-18. The condition of the park is being tackled by a Natural England Stewardship Scheme.



© Historic England

SITE NAME:	Princess Gardens and Royal Terrace Gardens, Torquay
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001507

Important formal Victorian seaside park with later phases and additions. Major development agreed, including a multi-storey, mixed-use building to be attached to the grade II listed Pavilion and the seasonal installation of a Ferris wheel. A condition report and management plan for the gardens was completed in early 2017.

Contact: Jo McAllister 0117 975 0696

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise.

New Entry is noted).

SITE NAME:	Brixham Town, Brixham		
DESIGNATION:	Conservation Area, 107 LBs, 3 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Hal Bishop (LPA) 01803 207788

### WILTSHIRE (UA)



SITE NAME:	Rudloe Manor, Box
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1022808

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger Ministry of Defence site which was vacated in 1998. The current owners have consent for a residential scheme with enabling development. Work has been undertaken to the exterior of the listed building to make it watertight but it remains vacant. The property has recently been put up for sale but not sold.

Contact: Jacqueline Smith 0117 975 2232



© Wiltshire Council

© Historic England

SITE NAME:	Buildings to the rear of the Lansdowne Arms Hotel, The Strand, Calne
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1247495

LIST ENTRY NUMBER:

Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent Works Notices have previously been complied with; however, the condition of these buildings continues to decline. Pre-application discussions and assessment work on-going with progress meetings having taken place in early 2018.

Contact: Samuel Souter 0117 975 0690



(C)	Historic	England

SITE NAME:	The Lansdowne Monument, Calne Without
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1253569

Obelisk constructed in 1845 by Sir Charles Barry for the 3rd Marquess of Lansdowne in memory of Sir William Petty, ancestor of the Petty-Fitzmaurice family. The condition of this monumental local landmark is in decline due to the effect of weathering on the stonework.



© Historic England

SITE NAME:	Medieval market cross immediately east of St Andrew's Church, Castle Combe
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1019387

Late medieval market cross in the centre of Castle Combe, in a later roofed open structure built to provide shelter. The central cross sits on a plinth that is raised on two steps and sits on a stone platform. On this sits the sheltering structure made up of stone. The market cross is in its original position, built when Castle Combe was an important and wealthy settlement based around the cloth industry. Historic England grant-aided project development work which was completed in 2017. Sources of funding for required roofing works are being investigated by the Parish Council.

Contact: Sarah Ball 0117 975 0666

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Former hangars at Yatesbury Airfield, Cherhill
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1283146

Two aircraft hangars, built c1917 as part of a training centre. Two hangars from the first years of military flying. One hangar has been repaired, though there is no current end use. Consent has been granted to demolish the second hangar and this is currently in a collapsed state. Previously approved applications not implemented as of 2018.

Law courts and police station, 1835. Wind and weather tight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have been implemented. Planning Permission and Listed Building Consent granted in 2012 for a new residential scheme was renewed in 2015 and expires in 2018. Urgent works carried out in 2015. There is a current drive to secure ownership by the Wiltshire Historic Buildings Trust in partnership with Wiltshire Council to

Contact: Jacqueline Smith 0117 975 2232



© Historic England Archive

SITE NAME:	Former Law Courts and County Police Station, Northgate Street, Devizes
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Commercial company

1251744

Contact: Jacqueline Smith 0117 975 2232

carry out the conversion.



© Historic England Archive

SITE NAME:	Stable block to Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1365488

Impressive stable block of 1818, by Thomas Cundy, located 150 metres NNW of Tottenham House. Following neglect, the structure is currently in an unsafe and partially ruinous condition. A planning application was granted early 2018 supporting the return of Tottenham House back to a single family dwelling with some additional development and the conversion of the Stable Block for ancillary leisure use. The works will result in the buildings being removed from the Heritage At Risk Register.

Contact: Jacqueline Smith 0117 975 2232



© Historic England Archive

SITE NAME:	Tottenham House, Great Bedwyn
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private

1183809

Country house, 1825, by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot 'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s) now vacant. A planning application was granted early 2018 supporting the return of Tottenham House to a single family dwelling with some additional development and the conversion of the Stable Block for ancillary leisure use. The works will result in the buildings being removed from the Heritage at Risk Register.

Early C15 former chapel in curtilage of a listed house. In poor condition and needs some work and repair to roof

Contact: Jacqueline Smith 0117 975 2232



© Historic England

SITE NAME:	Chapel at Knowle House, Little Bedwyn
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Unknown
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1004708

Contact: John Ette 0117 975 0687

and gable wall.

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	The Red House at Eastwell Manor, Eastwell Road, Potterne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1258775

Red brick garden building. Built c1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector. Access to the site is currently restricted.

Contact: Jacqueline Smith 0117 975 2232



© Historic England

SITE NAME:	Courtfield House, Polebarn Road, Trowbridge
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1021635

Courtfield House is a clothier's house built in c1754 with an earlier C17 building at the rear. The house was used as a preparatory school which closed in April 2012 and is consequently redundant. Adjoining the house is a relatively unaltered wool store. The roof structure of the house is in poor condition with a collapsing valley gutter. The property is currently vacant and subject to vandalism. Purchased in April 2016 by a developer to convert the main house to residential units with new build residential in the grounds. Applications are expected to be submitted to the authority in 2018.

Contact: Samuel Souter 0117 975 0690

Contact: Sarah Ball 0117 975 0666



© Salisbury District Council

SITE NAME:	Chapel, immediately north of Pythouse, Pythouse Park, West Tisbury
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1131162

Former private chapel to country house c1827. Built by John Bennett of Pythouse for his wife nee Lucy Lambert of Boyton. The chapel is derelict and overgrown and the stonework has been vandalised. The building is now scaffolded. Some of the vegetation has been removed.



© Historic England Archive

SITE NAME:	Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1364424

Late C19 privately owned mausoleum, within a local authority municipal cemetery. The building is currently disused and continues to deteriorate. It is the subject of on-going vandalism but has been secured against break-ins.



© Historic England

SITE NAME:	Church of St Peter, Calne Without
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1261936

Parish church, probably C13, altered and extended 1859 and restored 1907 by CE Ponting. Rubble stone with stone slate roofs, coped chancel gable and gabled stone slate hung west bellcote. The church has structural movement and monitoring was carried out for over a year to inform a specification for repair. Advice on repairs was given by Historic England in Spring 2018 following which the congregation are progressing a repair project.

Contact: Sarah Ball 0117 975 0666

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### Last year's priority category is shown in brackets (otherwise, New Entry is noted).



SITE NAME:	Church of St Peter, Charlton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1365532

Parish church. C16 and 1857-8 by JL Pearson. Medieval work in ashlar limestone. C19 work in flint banded with limestone ashlar and brick. Tiled roof. North porch with tower over and north chapel, all C15-C16. Nave and chancel in one, rebuilding original work. The plain clay tiles to the roof are failing and although regular patching and repair is being undertaken, the roof will need renewing.

Contact: Sarah Ball 0117 975 0666

Contact: Sarah Ball 0117 975 0666

© Historic England



SITE NAME:	Church of St Mary, A419, Chilton Foliat
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1034139

Parish church, c1300, early C14 and C19. Flint with Bath stone dressings. North nave wall, tower and chancel rendered. Stone tile roof with slate to nave. Nave, south aisle and porch, chancel, west tower and vestry. Chancel and nave roofs and rainwater goods in poor condition.

© Historic England



Church of St Peter and St Paul, High Street, Heytesbury

DESIGNATION: Listed Place of Worship grade I, CA

CONDITION: Poor

PRIORITY CATEGORY: D (D)

OWNER TYPE: Religious organisation

1036357

LIST ENTRY NUMBER:

Collegiate parish church. Late C12, C13, C14, C15, C16; restored between 1864 and 1867 by W Butterfield. Limestone, rubble stone and ashlar, Possibly Delabole slate roofs, ceramic ridge cresting. Plan: cruciform church with aisles to chancel and nave, south porch. Roofs and rainwater goods are in poor condition. Listed Places of Worship Roof Repair Grant awarded in 2017 for repairs of roofs to nave, aisles and south porch.

© Historic England



SITE NAME:	Church of St Mary, Church Road, Kilmington
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1318459

Church of England parish church. C15 tower, chancel rebuilt 1864, complete rebuilding 1869, tower restored 1903 by CE Ponting. Dressed limestone, rubblestone, tiled roof with ceramic ridge cresting and coped verges. West tower and entrance, nave and north aisle, south transept, north vestry and chancel. Narrow three-stage tower of Somerset type. Roofs and masonry in poor condition, particularly tower.

Contact: Sarah Ball 0117 975 0666

Contact: Sarah Ball 0117 975 0666

© Marcus Chantrey, Benjamir Beauchamp Architects



SITE NAME:	Road, Langley Burrell Without
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1199423

Parish church, c1200, c1300, C14 and C15, carefully restored 1890 (chancel) by CE Ponting and 1898 (nave and north aisle) by H Brakspear. Rubble stone with stone slate roofs and coped gables. Nave, north aisle, transeptal south tower with porch, chancel and south east chapel. Stone tiles to nave roof in poor condition and rainwater goods require overhauling.

© Historic England

Contact: Sarah Ball 0117 975 0666

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

  Fundamental and first a good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).



SITE NAME:	All Saints Chapel, Swan Lane, Leigh
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1356042

Parish church. C14 and 1896 by CE Ponting. Squared limestone rubble, stone slate roof. Nave rebuilt from old church and new chancel added. C14 porch entrance with wave moulding and hood. Sundial above. Stone slate roof and rainwater goods are in poor condition. Render to bell turret is failing.

Contact: Sarah Ball 0117 975 0666

© Historic England

© Historic England



SITE NAME:	Church of St Andrew, Church Lane, Melksham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1286098

Parish Church 1876 by Charles Adye. Ashlar, decorative tiled roof with coped verges, cross finials and cresting. Nave and chancel with south door and north vestry. Early English style. The clay tiled roofs and rainwater goods to the nave and chancel are in poor condition. In 2017, a scheme was drawn up to redevelop the modern extension to provide community use as part of the church. Funding sources for this will be explored.

Contact: Sarah Ball 0117 975 0666

SITE NAME:

Church of St Peter, High Street, Stourton with Gasper

DESIGNATION:

Listed Place of Worship grade I, RPG grade I, CA

CONDITION:

POOR

PRIORITY CATEGORY:

D (D)

OWNER TYPE:

Religious organisation

LIST ENTRY NUMBER:

1318468

Parish church. Early C14, C15, 1720s, early C19 and 1877 restoration, 1848 south aisle. Dressed limestone, roof of mixed materials. West tower, nave with aisles, chancel with south organ chamber, north chapel and porch. Nave and aisle roofs have temporary felt roofing. Plain clay tiles to chancel in poor condition and there are blocked rainwater downpipes causing damage to walls. The building has been subject to heritage crime. Listed Places of Worship Roof Repair Grant awarded in 2017.

Contact: Sarah Ball 0117 975 0666

© Historic	England
------------	---------

SITE NAME:	Wermere pond, Alvediston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004774
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
A bell barrow and two bowl barrows east of The Avenue on Countess Farm: part of a linear round barro cemetery, Amesbury			s Farm: part of a linear round barrow
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010331
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 550 metres east of New Barn, Earl's Farm Down, Amesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009872
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### gory is LB erwise, LP NF RP SM

SITE NAME:	Linear boundary earthwork on Amesbury Down w	est of Stock Botto	m, Amesbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015218
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Three bell barrows 300 metres north east of New	Barn, Earl's Farm [	Down, Amesbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009572
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Linear boundary earthwork 250 metres west of St	ockport, Amesbury	/ Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015689
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Beckhampton round barrow cemetery 150 metres north east of the 'Waggon and Horses', Avebury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008221
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 770 metres south west of the junction round barrow cemetery on Avebury Down, Avebu		and Green Street, forming part of a
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008107
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Earthwork enclosure 950 metres SSE of Manor Fai	m, Avebury	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1014031
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Pair of round barrows 400 metres west of the Ridgon Avebury Down, Avebury	geway, forming part	t of a round barrow cemetery situate
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008075
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Pair of round barrows forming part of the Bronze A West Kennett Farm, Avebury	Age round barrow	cemetery 400 metres north east of		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008101		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Remains of 'Falkner's Circle', a Neolithic stone circ	Remains of 'Falkner's Circle', a Neolithic stone circle 180 metres east of the West Kennet Avenue, Avebury			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008109		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Round barrow cemetery 400 metres south of Avel	oury henge monum	ent on Waden Hill, Avebury		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008216		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Ten barrows forming part of Fox Covert round barrow cemetery, West Down, Avebury				
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008293		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	West Kennet Avenue and an earthwork bank east	of West Kennett F	arm, Avebury		
DESIGNATION:	Scheduled Monument, LB grade II, 2 CAs, WHS	LIST ENTRY NUMBER:	1015547		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	A henge, four Bronze Age barrows and part of a R / Bishops Cannings	oman road 500 me	tres south west of Fox Covert, Aveb		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007491		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	West Kennett Farm palisaded enclosures, Avebury	/ East Kennett			
DESIGNATION:	Scheduled Monument, 2 LBs, part in CA, WHS	LIST ENTRY NUMBER:	1015157		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Grovely Ditch, Barford St. Martin / Burcombe V	Vithout / Great Wish	ford / Wilton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005584
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow west of Rotherley Wood, 750 med	res WNW of Park C	Cottage, Berwick St. John
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020464
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	South Lodge camp Bronze Age enclosure with a metres east of Rushmore Farm, Berwick St. John	ssociated field systen า	n and round barrow cemetery, 350
DESIGNATION:	Scheduled Monument, RPG grade II	LIST ENTRY NUMBER:	1020962
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 300 metres east of Furze Knoll, Bi	shops Cannings	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013068
CONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 550 metres north east of Baltic Farm, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012629
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 950 metres SSW of Beckhampton Horton Down, Bishops Cannings	Plantation, forming p	part of a round barrow cemetery on
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012983
CONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow situated 500 metres SSW of Sheph	nerds' Shore, Bishops	Cannings
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1013756
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Eleven round barrows 1000 metres north of Baltic enclosed Iron Age farmstead on North Down, Bish	Farm forming part nops Cannings	of a barrow cemetery, and a probable
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013773
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Enclosed Iron Age farmstead 450 metres south of	Down Barn on Bish	nop's Cannings Down, Bishops Cannir
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013230
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Five round barrows 1040 metres NNE of Baltic Fa Bishops Cannings	rm forming part of	a barrow cemetery on North Down,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014737
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Four bowl barrows forming part of a cemetery 270 Cannings	metres east of lor	ng barrow on Roughridge Hill, Bishop
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014027
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Group of three bowl barrows 250 metres north ea	ast of Shepherds' Sh	nore, Bishops Cannings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013232
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Kitchen Barrow: a long barrow on Kitchen Barrow	Hill, Bishops Cann	ings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012519
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Long barrow 650 metres WSW of Shepherds' Sho	re, Bishops Canning	gs
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014030
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Amble plaughing	NEW ENTRY?:	No
MINGITAL VOLINEIVABILITY.	Arable ploughing	11211 21111111	110

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial list). use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Long barrow on Easton Down, Bishops Cannings		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013366
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Saucer barrow 600 metres west of Beckhampton E	Buildings, Bishops C	annings
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012193
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two saucer barrows and a pair of bowl barrows 75 of a round barrow cemetery on Horton Down, Bis	50 metres SSW of lands	Beckhampton Plantation, forming part
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012982
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 85 metres north of Bishopstrow Hou	use, Bishopstrow	
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1019507
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Woodminton Down round barrow, Bower Chalke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003729
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Corton long barrow, Boyton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010518
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Scrubbed Oak enclosure and linear boundary earth	nwork, Boyton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Long barrow on Cold Kitchen Hill, Brixton Deveri	II	
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1010416
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Pertwood Down, 1400 metres no	rth west of Lower	Pertwood, Brixton Deverill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010463
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Knowle Hill round barrow, Broad Chalke		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003033
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow 860 yards (786 metres) south east of	of Knighton Hill Bu	ildings, Broad Chalke
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004771
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Knighton Roman road (stretching from Reddish Go	ore to reservoir), B	road Chalke / Bishopstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003728
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman road in Spye Park, Bromham		
designation:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003010
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow: one of a group of round barrows so	uth of Bulford, Bulf	ord
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009545
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009564	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009602	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow: one of a group of round barrows	south of Bulford, Bulf	ord	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009604	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow: one of a group of round barrows south of Bulford, Bulford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009605	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Multiple trackway south of Bulford Camp, Bulfor	d / Cholderton / Ame	esbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009613	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	Yes	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Long barrow 240 metres south west of Green B	arrow Farm, Castle C	Combe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018419	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 350 metres north east of White H	orse Plantation, Cher	hill	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010134	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 700 metres south east of Field Barn,	Chicklade	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015937
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow, part of the round barrow cemetery	south of Codford [	Down, Codford
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016557
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Three bowl barrows in Colerne Park, 450 metres	north of Keeper's (	Cottage, Colerne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010758
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Wick Down, Collingbourne Ducis	S	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012510
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 650 metres east of Summer Down Fa	arm, Collingbourne	Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 400 metres south of Summer I	Down Farm, Colling	bourne Kingston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012518
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Crowdown Clump earthwork (Godsbury), Colling	bourne Kingston / I	Burbage
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004759
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

**ABBREVIATIONS** CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow on Little Toyd Down, 650 metres so	uth west of Grims	Lodge Farm, Coombe Bissett
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015704
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Moated site and surrounding earthwork enclosure,	100 metres south	of Chelworth Farm, Cricklade
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013353
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Devizes Castle, Devizes		
DESIGNATION:	Scheduled Monument and Listed Building grade II, 3 LBs, part in CA	LIST ENTRY NUMBER:	1021375 and 1249362
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Hugh Beamish 0117 975 0726
SITE NAME:	Berwick Coombe ditch, Donhead St. Andrew / Ber	wick St. John	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005587
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow on Ashmore Down, 775 metres nort	h of Ashgrove Cott	tages, Donhead St. Mary
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015938
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 600 yards (550 metres) south east of	Vanity, Downton /	Whitsbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003004
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Ogbury camp, Durnford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Nine bowl barrows, two disc barrows and two sau cemetery on Durrington Down, Durrington	icer barrows formi	ng the majority of a round barrow
designation:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1008943
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Nine round barrows forming a round barrow cem Durrington	etery 400 metres n	orth of the eastern end of The Cursu
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009067
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	East Kennett long barrow, 600 metres south of Eas	st Kennett church,	East Kennett
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1012323
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Round barrow on Easton Down, Easton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Edington Priory (site of), Edington		
DESIGNATION:	Scheduled Monument, LB grade I, CA	LIST ENTRY NUMBER:	1004709
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow, Tinhead Hill, Edington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009783
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	North Hill round barrows, Grafton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004746
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 100 metres north of Great Botley	Copse, Grafton / Sha	lbourne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012301
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Grovely Castle and earthworks north of Grovel Martin	y Wood, Great Wish	ford / Steeple Langford / Barford St.
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005604
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 340 metres east of Holly Bush Far	m, Grittleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018418
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow 250 metres NNE of the sports grou Down, Idmiston	nd: one of a group of	round barrows north west of Idmist
designation:	Scheduled Monument	LIST ENTRY NUMBER:	1013971
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bell barrow, three bowl barrows and gas testing	trenches on Idmistor	n Down, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014818
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 260 metres SSE of the southern cobarrows on Porton Down, Idmiston	orner of Moll Harris's	Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014096
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 440 metres SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014094
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

	TH WEST / WILTSHIRE (UA)		
SITE NAME:	Bowl barrow 530 metres SSW of the southern of barrows on Porton Down, Idmiston	corner of Moll Harris'	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014092
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 535 metres SSW of the southern of barrows on Porton Down, Idmiston	orner of Moll Harris'	s Clump: one of a group of round
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014093
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bronze Age enclosure and two bowl barrows 52 Down, Idmiston	0 metres north east	of Moll Harris's Clump on Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014819
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Long barrow 140 metres WSW of the Battery F	lill triangulation point	, Idmiston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014089
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Saucer barrow 400 metres north east of the spo Idmiston Down, Idmiston	rts ground: one of a g	group of round barrows north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013970
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Two bowl barrows 265 metres south of the sou round barrows on Porton Down, Idmiston	thern corner of Moll	Harris's Clump: part of a group of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014095
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Two disc barrows and two bowl barrows 900 metres north of Moll Harris's Clump on Idmi Idmiston  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015557  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  OWNER TYPE: Government or agency CONTACT: Nick Croxson 07795  SITE NAME: Bowl barrow on Keysley Down, 250 metres west of the A350 Warminster-Shaftesbury Roa Deverill  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1013877  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive New ENTRY: No  OWNER TYPE: Private CONTACT: Nick Croxson 07795  SITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION: Scheduled Monument, CA UST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Plant growth New Entry: No  OWNER TYPE: Plant growth New Entry: No  OWNER TYPE: Private CONTACT: Nick Croxson 07795  SITE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument  DESIGNATION: Scheduled Monument  Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY: No  OWNER TYPE: Scheduled Monument  Mineral extraction/related subsidence NEW ENTRY: No  OWNER TYPE:	ston Down,
Generally unsatisfactory with major localised problems  Generally unsatisfactory with major localised problems  Animal burrowing - extensive  New entry?: No  OWNER TYPE: Government or agency  CONTACT: Nick Croxson 07795  SITE NAME: Bowl barrow on Keysley Down, 250 metres west of the A350 Warminster-Shaftesbury Road Deverill  Designation: Scheduled Monument  LIST ENTRY NUMBER: 1013877  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  OWNER TYPE: Private  CONTACT: Nick Croxson 07795  SITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: No  OWNER TYPE: Plant growth  NEW ENTRY?: No  OWNER TYPE: Private  CONTACT: Nick Croxson 07795  SITE NAME: New ENTRY?: No  OWNER TYPE: Private  CONTACT: Nick Croxson 07795  SITE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  EXTENDEDESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  EXTENDEDESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Mineral extraction/related subsidence  NEW ENTRY?: No	
Problems Problems Problems Problems Problems Problems Problems Problems Principal vulnerability: Animal burrowing - extensive Principal vulnerability: Animal burrowing - extensive Principal vulnerability: Animal burrowing - extensive Principal vulnerability: Animal burrow on Keysley Down, 250 metres west of the A350 Warminster-Shaftesbury Road Deverill Principal vulnerability: Scheduled Monument Principal vulnerability: Animal burrowing - extensive Private P	
Government or agency  Bowl barrow on Keysley Down, 250 metres west of the A350 Warminster-Shaftesbury Road Deverill  LIST ENTRY NUMBER: 1013877  Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRYP: No  DOWNER TYPE: Private  CONTACT: Nick Croxson 07795  GETE NAME: Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  NEW ENTRYP: No  DOWNER TYPE: Private  CONTACT: Nick Croxson 07795  GETE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: No  Declining  REND: Declining	
Bowl barrow on Keysley Down, 250 metres west of the A350 Warminster-Shaftesbury Road Deverill  Scheduled Monument  UST ENTRY NUMBER: 1013877  CONDITION:  Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY:  Animal burrowing - extensive  NEW ENTRY?:  No  Declining  Private  CONTACT:  Nick Croxson 07795  THE NAME:  Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION:  Scheduled Monument, CA  LIST ENTRY NUMBER:  1013876  CONDITION:  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY:  Plant growth  NEW ENTRY?:  No  Declining  RINCIPAL VULNERABILITY:  Private  Scheduled Monument  LIST ENTRY NUMBER:  No  Declining  TREND:  Declining  TREND:  Declining  Declining  TREND:  Declining  TREND:  Declining  TREND:  Declining  Declining  Declining  TREND:  Declining	
Deverill  Scheduled Monument  LIST ENTRY NUMBER: 1013877  Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY:  Animal burrowing - extensive  New ENTRY:  No  Declining  NEW ENTRY:  No  Declining  NEW ENTRY:  No  Declining  No  DWNER TYPE:  Private  Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION:  Scheduled Monument, CA  LIST ENTRY NUMBER:  LONDITION:  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY:  Plant growth  New ENTRY:  No  Declining  RINCIPAL VULNERABILITY:  Private  Settlement west of Latton, Latton  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  No  Nick Croxson 07795  TIE NAME:  Settlement west of Latton, Latton  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LONGER:  LIST ENTRY NUMBER:  LONGER:  NEW ENTRY:  No  Declining  RINCIPAL VULNERABILITY:  Mineral extraction/related subsidence  NEW ENTRY:  No	665645
Generally unsatisfactory with major localised problems  RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Nick Croxson 07795  ITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock  DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Nick Croxson 07795  ITE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004689  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	d, Kingston
problems  Problems  RINCIPAL VULNERABILITY: Animal burrowing - extensive  New Entry?: No  OWNER TYPE: Private  CONTACT: Nick Croxson 07795  ITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock  Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth  Private  CONTACT: Nick Croxson 07795  ITE NAME: Settlement west of Latton, Latton  Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1004689  CONDITION: Extensive significant problems  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence  NEW ENTRY?: No	
Private  Moated site and fishponds south east of Rowden Farm, Lacock  Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth  Private  Settlement west of Latton, Latton  Settlement west of Latton, Latton  Scheduled Monument  LIST ENTRY NUMBER: 1013876  Declining  New ENTRY?: No  Nick Croxson 07795  LIST ENTRY NUMBER: 1004689  CONTACT: Nick Croxson 07795  THE NAME: Settlement west of Latton, Latton  Scheduled Monument  LIST ENTRY NUMBER: 1004689  ENTRYPE: Declining  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence  NEW ENTRY?: No	
Moated site and fishponds south east of Rowden Farm, Lacock  Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth  New ENTRY?: No  Nick Croxson 07795  OVENIER TYPE: Settlement west of Latton, Latton  Scheduled Monument  Extensive significant problems  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence  NEW ENTRY?: No  No  NEW ENTRY?: Declining  TREND: Declining  No	
DESIGNATION: Scheduled Monument, CA  LIST ENTRY NUMBER: 1013876  CONDITION: Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY: Plant growth  Private  CONTACT: Nick Croxson 07795  ITE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument  EXEMPTION: Extensive significant problems  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence  NEW ENTRY NUMBER: 1004689  TREND: Declining  No	665645
Generally satisfactory but with significant localised problems  RINCIPAL VULNERABILITY:  Plant growth  Private  Private  CONTACT:  No  Nick Croxson 07795  Declining  No  Nick Croxson 07795  Declining  Declining  No  No  Nick Croxson 07795  Declining  Nick Croxson 07795  Declining  Nick Croxson 07795  Declining  New Entry:  No  No  Nick Croxson 07795  Declining  No  No  No  No  No  No  No  No  No  N	
problems  Problems  RINCIPAL VULNERABILITY:  Plant growth  New entry?:  No  CONTACT:  Nick Croxson 07795  ITE NAME:  Settlement west of Latton, Latton  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  LO04689  Extensive significant problems  RINCIPAL VULNERABILITY:  Mineral extraction/related subsidence  NEW ENTRY?:  No	
Private CONTACT: Nick Croxson 07795  ITE NAME: Settlement west of Latton, Latton  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004689  EXECUTION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	
ITE NAME: Settlement west of Latton, Latton  Scheduled Monument LIST ENTRY NUMBER: 1004689  EXTEND: Declining  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1004689  CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	665645
CONDITION: Extensive significant problems TREND: Declining  RINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	
RINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	
OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795	
	665645
TE NAME: Medieval pottery kilns, Milford Farm, Laverstock	
ESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003252	
ONDITION: Extensive significant problems TREND: Unknown	
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	
OWNER TYPE: Mixed, multiple owners CONTACT: Nick Croxson 07795	665645
TE NAME: Bell barrow on Rook Hill, 200 metres west of Pertwood Wood, Longbridge Deverill	
ESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1010470	
Generally unsatisfactory with major localised TREND: Unknown problems	
RINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	
OWNER TYPE: Private CONTACT: Nick Croxson 07795	665645
TE NAME: Two saucer barrows 775 metres south east of Rodmead Farm, Maiden Bradley with Yarnfie	
esignation: Scheduled Monument List entry number: 1017697	ld
ONDITION: Extensive significant problems TREND: Unknown	ld
RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	ld
OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795	ld

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 190 metres north east of Burton Far	m, Mere	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017711
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Black Field Roman site, Mildenhall		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1004726
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Camp on Forest Hill, Mildenhall / Savernake / Marl	borough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004697
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 200 metres north east of Everleigh A	shes, Milton Lilbou	rne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009543
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Roman tile and brick kiln site 1000 yards (900 met	res) west of Tidling	Corner, Minety
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004702
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Bowl barrow 900 metres north of Down Farm, Ne	ettleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018391
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Long barrow 400 metres north west of Fox Cover	t, Nettleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010396
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Nick Croxson 07795 665645
ITE NAME:	Early medieval settlement, palace, church and Bron Norton / St. Paul Malmesbury Without	ze Age ring ditches	340 metres east of Cowage Farm,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018389
JESIGNATION:			
	Extensive significant problems	TREND:	Unknown
CONDITION:  PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing	NEW ENTRY?:	Unknown

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

DEGISHATION Scheduled Monument US DITATIVILUSIAN (109830 CONTROTO)  Extensive significant problems THIND Stable  RIBICIDEA VILLEAN (1998)  ROWNER TITO  Government or agency  ROWNER TITO  GOVERNMENT ROWNER TO GOVERNMENT (109835 CONTROTO)  Scheduled Monument US TO THIND NOTION BAYANT  RECENSION Scheduled Monument US TO THIND NOTION BAYANT  RECENSION Scheduled Monument US TO THIND NOTION BAYANT  RIBICIDEA VILLEA (1998)  GOVERNMENT ATABLE ploughing NOWINGTON NOTION (1998)  GOVERNMENT ATABLE ploughing NOWINGTON NOTION (1998)  GOVERNMENT ON COOTION (1998)  GOVERNMENT (1998)  GOVERNM	SITE NAME:	Bowl barrow: one of a group of dispersed barro	ws south east of Nor	ton Plantation, Norton Bavant
Remontal Valuement Info Government or agency Government or agency Government or agency Government or agency Government Generally unsatisfactory with major localised profession Government Governmen	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009830
CONTROL 1791.  Government or agency  Round barrow on the south side of Cotley Hill, Norton Bavant  Scheduled Monument  Extensive significant problems  Anable ploughing  CONCRITION:  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  CONCRITION:  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  CONCRITION:  COVERNATION:  CONTROL:  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  CONTROL:  CONT	CONDITION:	Extensive significant problems	TREND:	Stable
Round barrow on the south side of Cotley Hill, Norton Bavant  Scheduled Monument  Extensive significant problems  Rische Stending Monument  Extensive significant problems  Rische Valueseastiff  Arable ploughing  New North Title  Government or agency  Control  Arable ploughing  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  Condition  Scheduled Monument  UST DATEN NUMBER  1005670  Declining  Rische Valueseastiff  Arable clipping  Now North Title  Private  Control  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Selectual Monument  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Selectual Monument  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Selectual Monument  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Private  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Selectual Monument  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Private  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Selectual Monument  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Declining  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Declining  Bell barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Declining  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Declining  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Declining  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Declining  Private  De	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument LIST ENTRY NUMBER 1009835  EXERNATION Extensive significant problems 19643 Declining  PRINCIPLA VULNIFIBRATY: Arable ploughing NEW BOTTON: No ONTACT: Nick Croxson 07795 665645  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north of Rockley Plantation, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) north of Rockley Plantation, Ogbourne St. Andrew  BATTON ON COOMBD DOWN, 1070 yards (980 metres) 1012195  BATTON ORD ON COOMBD DOWN, 1070 yards (980 metres) 1012195  BATTON ON COOMBD DOWN, 1070 yards (980 metres) 1012195  BATTON ORD ON COOMBD DOWN, 1070 yards (980 metres) 1012195  BATTON ORD ON COOMBD DOWN, 1070 yards (980 metres) 1012195  BATTON ORD ORD ORD OWN, 1070 yards (980 metres) 1012195  BATTON ORD ORD ORD OWN, 1070 yards (980 metres) 1012197  BATTON ORD ORD ORD OWN, 1070 yards (980 metres) 1012197  BATTON ORD ORD ORD OWN, 1070 yards (980 metres) 1012197  BATTON ORD ORD ORD ORD OWN, 1070 yards (980 metres) 1012197  BATTON ORD	OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems IRRNO Decining Arable ploughing New National Nick Crosson 07795 665645  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  Bell barrow 200 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  CONTACT: Nick Crosson 07795 665645  CONTACT: Nick Crosson 07795	SITE NAME:	Round barrow on the south side of Cotley Hill,	Norton Bavant	
RENIGIPAL VALIDITABILITY:  Arable ploughing  SOWNER TITTE:  Government or agency  GONTACT:  Nick Croxson 07795 665645  Salt NAME:  Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew DOSGONATION:  Scheduled Monument  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  LIST ENTRY NUMBER:  Declining  Private  CONTACT:  Nick Croxson 07795 665645  Salt NAME:  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  RENGULAY AULIENMENT:  Private  CONTACT:  Nick Croxson 07795 665645  Salt NAME:  Bell barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew DOSGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No DOWNER TITTE:  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew DOSGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No DOWNER TITTE:  No DOWNER TITTE:  Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew DOSGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No DOWNER TITTE:  No Downer St. Andrew DOSGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No DOWNER TITTE:  No Downer St. Andrew DOSGONATION:  Scheduled Monument  Extensive significant problems  TREND:  Declining  NEW ENTRY:  No DOWNER TITTE:  No Downer St. Andrew DOSGONATION:  Scheduled Monument  LIST ENTRY NUMBER:  1015814  Declining  NEW ENTRY:  No DOWNER TITTE:  No Downer St. Andrew DOSGONATION:  Declining  NEW ENTRY:  No Downer TITTE:  No Downer St. Andrew DOSGONATION:  Declining  NEW ENTRY:	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009835
CONTACT:   Nick Croxson 07795 665645	CONDITION:	Extensive significant problems	TREND:	Declining
Barrow on Coombe Down, 1070 yards (980 metres) north east of Upper Poughcombe, Ogbourne St. Andrew DRIGNATION: Scheduled Monument IISTENTRYNUMMER: 1005670  Generally unsatisfactory with major localised problems Problems New Parity: No Condition: Problems New Parity: No Condition: Nick Croxson 07795 665645  BRINGIAN VILNERABILITY: Arable clipping New Parity: No Condition: Nick Croxson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: Problems New Parity: No Condition: Declining New Parity: No Condition: Nick Croxson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Declining New Parity: No Condition: New Parity: No Condition: Nick Croxson 07795 665645  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Declining New Parity: No Condition: Nick Croxson 07795 665645  Bell barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Scheduled Monument Ust Entray Number: 1015814  CONDITION: Extensive significant problems TREND: Declining Number: No Condition: Nick Croxson 07795 665645  BETE NAME Bowl barrow 430 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Octobardon: Nick Croxson 07795 665645  BETE NAME Bowl barrow 430 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Nick Croxson 07795 665645  BETE NAME Bowl barrow 430 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Nick Croxson 07795 665645  BETE NAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: Nick Croxson 07795 665645  BETE NAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: Nick Croxson 07795 665645  BETE NAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: Nick Croxson 07795 665645  BETE NAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: N	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Andrew Scheduled Monument UST ENTRY NUMBER: 1005670  Declining FRENCING. VULNERABILITY: Arable clipping Arable dipping Arable diversification of Rockley Plantation, Ogbourne St. Andrew CONTACT: Arable diversification of Arable diversified d	OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
Generally unsatisfactory with major localised problems  RENCIPAL VULNERABILITY: Arable clipping New ENTRY: No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SET ENAME: Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST BITRY NLMBER: 1012.195  CONTROTT: No  Declining  RENCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SET ENAME: Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST BITRY NLMBER: 1015.814  DESIGNATION: Scheduled Monument UST ENTRY NLMBER: 1015.803  DESIGNATION: Scheduled Monument UST ENTRY NLMBER: 1015.803  DESIGNATION: Scheduled Monument UST ENTRY NLMBER: 1015.803  DECONDITION: Extensive significant problems TREND: Declining  PRENCIPAL VULNERABILITY: Anable ploughing NEW ENTRY: No  DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  DESIGNATION: Scheduled Monument UST ENTRY NLMBER: 1012.197  DEVENTE TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  DESIGNATION: Scheduled Monument UST ENTRY NLMBER: 1012.197  DEVENTE TYPE: Commercial company Declining  PRENCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No  DOWNER TYPE: No  DOWNER TYPE: No  DOWNER TYPE: No  DECLINING	SITE NAME:		tres) north east of Up	oper Poughcombe, Ogbourne St.
PRINCIPAL VILINERABILITY: Arable clipping NEW ENTRY: No  OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  STENAME Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012 195  CONDITION: Extensive significant problems REND: Declining  PRINCIPAL VILINERABILITY: Animal burrowing - extensive No  OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SETENAME Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018 14  Extensive significant problems TREND: Declining  PRINCIPAL VILINERABILITY: Arable ploughing NEW ENTRY: No  OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SETENAME Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015803  DECONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VILINERABILITY: Arable ploughing NINW INTRY: No  OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SETENAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VILINERABILITY: Animal burrowing - extensive NEW ENTRY: No  CONNER TYPE: No  DECINING: Private CONTACT: Nick Croxson 07795 665645  SETENAME ROUND BARROW CENTER TYPE: No  CONTACT: Nick Croxson 07795 665645  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012197  CONTACT: Nick Croxson 07795 665645  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016779  DESIGNATION: Scheduled Monume	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005670
DOWNER TYPE  Private  Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012 195  CONDITION: Extensive significant problems  TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Private  CONTACT: Nick Croxson 07795 665645  STENAME  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 10158 14  CONDITION: Extensive significant problems  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Nick Croxson 07795 665645  STENAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1015803  TREND: DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1015803  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONNER TYPE: Commercial company  CONTACT: Nick Croxson 07795 665645  STENAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1015803  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRY: No  CONTACT: Nick Croxson 07795 665645  STENAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012 197  CONTACT: Nick Croxson 07795 665645  STENAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012 197  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: Private  ROUNDER TYPE: Private  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645  STENAME  ROUNDER TYPE: No  CONTACT: Nick Croxson 07795 665645	CONDITION:		TREND:	Declining
Bell barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012195 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No DOWNER TYPE: Private Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015814  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Scheduled Monument UST ENTRY NUMBER: 1015803  TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive New ENTRY: No DOWNER TYPE: No DESIgnation: Scheduled Monument UST ENTRY NUMBER: 1012197  Declining PRINCIPAL VULNERABILITY: No DOWNER TYPE: No Declining PRINCIPAL VULNERABILITY: No Declining	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
Scheduled Monument  Ext Entry Number: 1012195  CONDITION: Extensive significant problems  RRINGIPAL VULNERABILITY: Animal burrowing - extensive  NEW BOTRY: No  OWNER TYPE: Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  Ext Ensive significant problems  RRINGIPAL VULNERABILITY: Arable ploughing  RRINGIPAL VULNERABILITY: Arable ploughing  RRINGIPAL VULNERABILITY: Arable ploughing  RRINGIPAL VULNERABILITY: No  OWNER TYPE: Commercial company  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  Ext Entry Number: 1015803  STEENAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  Ext Entry Number: 1015803  CONDITION: Extensive significant problems  RRINGIPAL VULNERABILITY: No  OWNER TYPE: Commercial company  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems  RRINGIPAL VULNERABILITY: No  OWNER TYPE: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems  RRINGIPAL VULNERABILITY: No  OWNER TYPE: No  OWNER TYPE: No  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  DECIning  RRINGIPAL VULNERABILITY: Arable clipping  NEW ENTRY: No  DECINING: No  DECINING: NEW ENTRY: NO	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems  TREND: Declining  Private  Animal burrowing - extensive  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Designation: Scheduled Monument  Extensive significant problems  Private  Declining  Private  Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Designation: Scheduled Monument  Extensive significant problems  Private  Combition: Extensive significant problems  Private  Commercial company  Contact: Nick Croxson 07795 665645  Declining  Private  Designation: Octobrition: Declining  Private  Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  Designation: Scheduled Monument  Extensive significant problems  TREND: Declining  Private  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Designation: Scheduled Monument  Extensive significant problems  Extensive significant problems  Private  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Designation: Scheduled Monument  Extensive significant problems  TREND: Declining  Private  Contract: Nick Croxson 07795 665645  Description: Extensive significant problems  TREND: Declining  Private  Private  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument  Extensive significant problems  Extensive significant problems  Extensive significant problems  TREND: Declining  Private  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument  Extensive significant problems  Extensive significant problems  REND: Declining  Private  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  Designation: Scheduled Monument  Extensive significant problems  REND: Declining  REND: Declining  REND: Declining  REND: Declining  REND: Declining	SITE NAME:	Bell barrow 200 metres north of Rockley Planta	tion, Ogbourne St. Ar	ndrew
Animal burrowing - extensive New ENTRY: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SETENAME: Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Scheduled Monument LIST ENTRY NUMBER: 1015814  CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SETENAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew Designation: Scheduled Monument LIST ENTRY NUMBER: 1015803  CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SETENAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew Designation: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No OWNER TYPE: Designation: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining NEW ENTRY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SETENAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey Designation: Scheduled Monument LIST ENTRY NUMBER: 1016779  DESI	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012195
DOWNER TYPE BOWLD BATTON: Scheduled Monument LIST ENTRY NUMBER: 1015814  CONDITION: Extensive significant problems TREND: Declining  REFINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: NO  CONTACT: Nick Croxson 07795 665645  STE NAME: BOWLD BATTON 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015803  STE NAME: BOWLD BATTON 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: NO  DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SETE NAME: BOWLD BATTON And a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY): No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SETE NAME: BOWLD BATTON AND AND AND AND AND AND AND AND AND AN	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 375 metres east of Wick Bottom Barn, Ogbourne St. Andrew  Scheduled Monument  UST ENTRY NUMBER: 1015814  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY!: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY!: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1016779  DESIGNA	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015814  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No  DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Arable clipping NEW ENTRY: No	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems  Extensive significant problems  Arable ploughing  NEW ENTRY:  No  OWNER TYPE:  Commercial company  CONTACT:  Nick Croxson 07795 665645  SITE NAME:  Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I015803  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable ploughing  NEW ENTRY:  No  OWNER TYPE:  Commercial company  CONTACT:  Nick Croxson 07795 665645  Nick Croxson 07795 665645  SITE NAME:  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I012197  CONDITION:  Extensive significant problems  TREND:  Declining  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  NEW ENTRY:  No  OWNER TYPE:  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER:  I016779  CONDITION:  Generally unsatisfactory with major localised  problems  Arable clipping  NEW ENTRY:  No  Declining  PRINCIPAL VULNERABILITY:  Arable clipping  NEW ENTRY:  No	SITE NAME:	Bowl barrow 375 metres east of Wick Bottom I	Barn, Ogbourne St. A	ndrew
PRINCIPAL VULNERABILITY: Arable ploughing New Entry?: No DWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  BOWNER TYPE: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No DWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No DWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  REND: Declining  PRINCIPAL VULNERABILITY: No  CONDITION: Generally unsatisfactory with major localised problems  REND: Declining  REND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015814
Commercial company  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1015803  CONDITION: Extensive significant problems  REND: Declining PRINCIPAL VULNERABILITY: Arable ploughing  NEW ENTRYP: No  CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  NEW ENTRYP: No  DOWNER TYPE: Private  CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  CONDITION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  NEW ENTRYP: No  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  NEW ENTRYP: No	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow 630 metres north east of Wick Bottom Barn, Ogbourne St. Andrew  Designation: Scheduled Monument LIST entry NUMBER: 1015803  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYP: No  DOWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645  SITE NAME: Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRYP: No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRYP: No  NEW ENTRYP: Declining  REND: Declining	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
Scheduled Monument  Extensive significant problems  TREND: Declining  NEW ENTRY?: No  OWNER TYPE: Commercial company  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012197  CONTACT: Nick Croxson 07795 665645  TREND: Declining  RINCIPAL VULNERABILITY: Animal burrowing - extensive DESIGNATION: TREND: Declining  RINCIPAL VULNERABILITY: Animal burrowing - extensive DESIGNATION: TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Nick Croxson 07795 665645  TREND: Declining  RINCIPAL VULNERABILITY: No  CONTACT: Nick Croxson 07795 665645  TREND: Declining  RINCIPAL VULNERABILITY: Animal burrow cemetery 320 metres south east of Down Farm, Pewsey  CONTACT: Declining  RINCIPAL VULNERABILITY: Declining  RINCIPAL VULNERABILITY: Arable clipping  NEW ENTRY?: No	OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems  TREND: Declining  Arable ploughing  NEW ENTRY?: No  COMTACT: Nick Croxson 07795 665645  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems  TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  REND: Declining  NEW ENTRY?: No  CONTACT: Nick Croxson 07795 665645  TREND: Declining  NEW ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  REND: Declining	SITE NAME:	Bowl barrow 630 metres north east of Wick Bo	ttom Barn, Ogbourne	e St. Andrew
Arable ploughing  Deviner type:  Commercial company  Contact:  Nick Croxson 07795 665645  Site name:  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  Designation:  Scheduled Monument  List entry number:  List entry number:  List entry number:  Declining  PRINCIPAL VULNERABILITY:  Animal burrowing - extensive  New Entry?:  No  Contact:  Nick Croxson 07795 665645  Site name:  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  Designation:  Scheduled Monument  List entry number:  No  Contact:  Nick Croxson 07795 665645  TREND:  Declining  Condition:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  New Entry?:  No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015803
Commercial company  CONTACT: Nick Croxson 07795 665645  Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Animal burrowing - extensive  Private  CONTACT: Nick Croxson 07795 665645  Round barrow cemetery 320 metres south east of Down Farm, Pewsey DESIGNATION: Scheduled Monument  LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping  NEW ENTRY?: No	CONDITION:	Extensive significant problems	TREND:	Declining
Bowl barrow and a saucer barrow 200 metres north of Rockley Plantation, Ogbourne St. Andrew  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DOWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012197  CONDITION: Extensive significant problems TREND: Declining  PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  DWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645
Extensive significant problems  Final Declining  Animal burrowing - extensive  Private  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION:  Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  TREND:  Declining  No  Declining  TREND:  Declining  No	SITE NAME:	Bowl barrow and a saucer barrow 200 metres n	orth of Rockley Plant	ation, Ogbourne St. Andrew
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No  OWNER TYPE: Private CONTACT: Nick Croxson 07795 665645  SITE NAME: Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012197
Private  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION:  Scheduled Monument  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Arable clipping  New Entry:  Nick Croxson 07795 665645  Nick Croxson 07795 665645  Nick Croxson 07795 665645  Round barrow cemetery 320 metres south east of Down Farm, Pewsey  LIST ENTRY NUMBER: 1016779  TREND:  Declining  NEW ENTRY:  No	CONDITION:	Extensive significant problems	TREND:	Declining
Round barrow cemetery 320 metres south east of Down Farm, Pewsey  DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1016779  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable clipping NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
DESIGNATION:  Scheduled Monument  LIST ENTRY NUMBER: 1016779  TREND:  Declining  PRINCIPAL VULNERABILITY:  Arable clipping  New ENTRY?:  No	OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
Generally unsatisfactory with major localised problems  TREND: Declining  PRINCIPAL VULNERABILITY: Arable clipping  New entry?: No	SITE NAME:	Round barrow cemetery 320 metres south east	of Down Farm, Pews	еу
problems  PRINCIPAL VULNERABILITY: Arable clipping  NEW ENTRY: No	designation:	Scheduled Monument	LIST ENTRY NUMBER:	1016779
11 3	CONDITION:		TREND:	Declining
OWNER TYPE: Commercial company CONTACT: Nick Croxson 07795 665645	PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
	OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	The Spectacles, Pewsey			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005638	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Long barrow, Winterbourne, Pitton and Farley			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005623	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Local authority	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Moated site 300 metres north east of Potterne P	ark Farm, Potterne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012152	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME: Bell barrow 350 metres south west of Barbury Barn, Preshute				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012190	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 300 metres east of Ivy House Farm	, Preshute		
DESIGNATION:		LIST ENTRY NUMBER:	1012294	
DESIGNATION:	Scheduled Monument	LIST ENTINE NOTIBEN.	1012274	
	Scheduled Monument  Extensive significant problems	TREND:	Unknown	
CONDITION:				
CONDITION: PRINCIPAL VULNERABILITY:	Extensive significant problems	TREND:	Unknown	
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Extensive significant problems  Arable ploughing	TREND:  NEW ENTRY?:  CONTACT:	Unknown No	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Extensive significant problems Arable ploughing Private	TREND:  NEW ENTRY?:  CONTACT:	Unknown No	
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Extensive significant problems  Arable ploughing  Private  Group of round barrows on Rough Hill, Preshute	TREND:  NEW ENTRY?:  CONTACT:	Unknown No Nick Croxson 07795 665645	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Extensive significant problems  Arable ploughing  Private  Group of round barrows on Rough Hill, Preshute  Scheduled Monument	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:	Unknown No Nick Croxson 07795 665645	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing  Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument  Extensive significant problems	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:	Unknown No Nick Croxson 07795 665645  1003034 Declining	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Extensive significant problems  Arable ploughing  Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument  Extensive significant problems  Arable ploughing	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:	Unknown No Nick Croxson 07795 665645  1003034 Declining No	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:	Unknown No Nick Croxson 07795 665645  1003034 Declining No	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645	
DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  CONDITION:  PRINCIPAL VULNERABILITY:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645  1004763 Declining	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  CONDITION:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems Arable ploughing	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  NEW ENTRY?:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645  1004763 Declining No	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private	TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  CONTACT:  LIST ENTRY NUMBER:  TREND:  NEW ENTRY?:  NEW ENTRY?:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645  1004763 Declining No	
CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Scheduled Monument Extensive significant problems Arable ploughing Private  Sharpridge field system, Preshute	TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645  1004763 Declining No Nick Croxson 07795 665645	
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: SITE NAME:	Extensive significant problems  Arable ploughing Private  Group of round barrows on Rough Hill, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Preshute Down field system, Preshute Scheduled Monument Extensive significant problems Arable ploughing Private  Scheduled Monument Extensive significant problems Arable ploughing Private  Sharpridge field system, Preshute Scheduled Monument	TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:  LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	Unknown No Nick Croxson 07795 665645  1003034 Declining No Nick Croxson 07795 665645  1004763 Declining No Nick Croxson 07795 665645	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Roundway Hill Farm round barrows, Roundway / I	Bishops Cannings			
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1004773		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Bowl barrow 450 metres north of Cross Droves, Shalbourne				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012274		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Long barrow on Smay Down, 300 metres east of 7	The Hassock, Shalbo	ourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010467		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Wansdyke: Daniel's Lane section, Shalbourne				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005594		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Great Botley Copse long barrow, and disc barrow near it, Shalbourne / Grafton				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005692		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Long barrow 250 metres east of Boyton Field Barr	n, Sherrington / Boy	rton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010520		
CONDITION:	Extensive significant problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645		
SITE NAME:	Six bowl barrows and two disc barrows forming the west of Fargo Road ammunition compound, Shrew		nd barrow cemetery 300 metres nort		
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1009124		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645		

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Newton Barrow, South Newton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005687	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Earthwork enclosure on Milk Hill, Stanton St. Bern	ard		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004735	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Stapleford Castle, Stapleford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005686	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Barrow north of 'The Spectacles', Steeple Langford	I		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004742	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 240 metres east of The Penning, Steeple Langford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015025	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Deptford Down round barrow, Steeple Langford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005615	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Little Langford round barrow, north of Upper Farn	n Down, Steeple La	ngford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005605	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
DDINIGIDAL VILLAIED ADILITY	Arable clipping	NEW ENTRY?:	No	
PRINCIPAL VULNERABILITY:		CONTACT:	Nick Croxson 07795 665645	
OWNER TYPE:	Mixed, multiple owners			
	Mixed, multiple owners  Round barrow 230 yards (210 metres) north west	of New Field Plant	ation, Steeple Langford	
OWNER TYPE:		of New Field Plant:	ation, Steeple Langford 1004725	
OWNER TYPE: SITE NAME:	Round barrow 230 yards (210 metres) north west		· · · · · · · · · · · · · · · · · · ·	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Round barrow 230 yards (210 metres) north west Scheduled Monument	LIST ENTRY NUMBER:	1004725	
DWNER TYPE:  SITE NAME:  DESIGNATION:  CONDITION:	Round barrow 230 yards (210 metres) north west Scheduled Monument Extensive significant problems	LIST ENTRY NUMBER:	1004725 Unknown	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bell barrow on Parsonage Down, 1.3 kilometres so	outh east of Lord's	Hill Farm, Sutton Veny
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016677
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Littlecombe Down, Sutton Veny		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005683
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Fosbury camp, Tidcombe and Fosbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005682
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Castle Ditches camp, Tisbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005701
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow on Woodley Down 675 metres NNE	of Ashmore Farm	, Tollard Royal
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020465
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Casterley Camp and associated monuments, Upavo	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010074
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645
SITE NAME:	Bowl barrow 500 metres south of Upton Scudamo	re, Upton Scudamo	ore
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010398
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

Enclosure and linear earthworks between Bishopstrow Down and South Down Sleight, Warminster / Bishopstrow / Norton Bavant			uth Down Sleight, Warminster /	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010283	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow in The Belt, 350 metres north east of Hill Barn, West Overton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019901	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Nick Croxson 07795 665645	
ITE NAME:	Bowl barrow 400 metres west of Normanton Gor	se, Wilsford cum L	ake	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010831	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
ITE NAME:	Ten bowl barrows, five disc barrows, a bell barrow, a pond barrow and a saucer barrow forming the Wilsford round barrow cemetery, Wilsford cum Lake			
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010874	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Horse Barrow, Winterbourne / Idmiston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005610	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bell barrow 450 metres south east of Greenland Fa of the Lesser Cursus, Winterbourne Stoke	arm, forming part o	of a linear round barrow cemetery w	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010899	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
ITE NAME:	Bowl barrow 350 metres north west of Greenland	Farm, Winterbou	ne Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010892	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**

SITE NAME:	Bowl barrow 830 metres south west of Greenla	nds Bungalow, east of	f Shrewton, Winterbourne Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015217	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bronze Age enclosure and bowl barrow 100 metres west of Longbarrow Cross Roads on Winterbourn Stoke Down, Winterbourne Stoke			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011048	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Disc barrow and pond barrow 350 metres NNV	V of Greenland Farm,	, Winterbourne Stoke	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010891	
CONDITION:	Extensive significant problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bell barrow and bowl barrow 500 metres NNW of Long Orchard, Winterslow			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013984	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 750 metres NNE of Easton Down	Farm, Winterslow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013986	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 175 metres west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013352	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645	
SITE NAME:	Bowl barrow 275 metres west of Square Copse Rivers	part of the Square C	opse barrow cemetery, Wootton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013364	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Crown	CONTACT:	Nick Croxson 07795 665645	

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

  E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### **ABBREVIATIONS**



© Historic England

SITE NAME:	Tottenham House and Savernake Forest, Savernake / Burbage / Great Bedwyn / Little Bedwyn / Marlborough / Mildenhall
DESIGNATION:	Registered Park and Garden grade II*, 20 LBs, 7 SMs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Improving
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000472

Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Planning permission for hotel development has lapsed. The house and core of the landscape have been sold to a private owner and the process of conservation and repair has begun, allied to major development proposals (application under consideration). The Forestry Commission manages Savernake Forest on a long lease. There is a Natural England Stewardship Scheme over part of the park.

Contact: Jo McAllister 0117 975 0696

WILTSHIRE (UA) / NEW FOREST (NP)				
SITE NAME:	Barrows in Bath Hole and Bury Hill Plantations, Redlynch, Wiltshire (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004754	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Croxson 07795 665645	

### PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### CA ory is LB wise, LPA NP RPG

This document is one in a series of publications produced as part of Historic England's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk
Published November 2018
4th Floor, Cannon Bridge House
25 Dowgate Hill
London EC4R 2YA
© Copyright Historic England 2018

Product code: 52101

