Heritage at **Risk**



London & South East Register 2021

Contents

The Register	IV	Hastings	132
Content and criteria	IV	Lewes Rother	134 135
Key statistics	VI	South Downs (NP)	135
		Wealden	130
Key to the Entries	VII	Hampshire	139
Entries on the Register by local planning	IX	Basingstoke and Deane	139
authority		East Hampshire	139
Greater London	I	Eastleigh	139
Barking and Dagenham	I	Fareham	140
Barnet	2	Gosport	140
Bexley	4	Hart	142
Brent	4	Havant	143
Bromley	6	New Forest	143
Camden	11	New Forest (NP)	144
City of London	17	Rushmoor	145
Croydon	18	Test Valley	148
Ealing	21	Winchester	149
Enfield	23	Isle of Wight (UA)	151
Greenwich	27	Kent	156
Hackney	29		
Hammersmith and Fulham	35	Ashford	156
Haringey	38	Canterbury	157
Harrow	41	Dartford	159 160
Havering	45	Dover Follostone and Lythe	160
Hillingdon	47	Folkestone and Hythe Maidstone	162
Hounslow	55	Sevenoaks	164
Islington	60	Swale	167
Kensington and Chelsea	65 74	Thanet	170
Kingston upon Thames Lambeth	74 75	Tonbridge and Malling	170
Lewisham	83	Tunbridge Wells	172
London Legacy (MDC)	83 87	•	
Merton	88	Kent (off)	173
Newham	92	Medway (UA)	174
Redbridge	94	Milton Keynes (UA)	177
Richmond upon Thames	96		
Southwark	99	Oxfordshire	178
Sutton	106	Cherwell	178
Tower Hamlets	107	Oxford	179
Waltham Forest	4	South Oxfordshire	179
Wandsworth	117	Vale of White Horse	182
Westminster, City of	118	West Oxfordshire	183
Bracknell Forest (UA)	122	Portsmouth, City of (UA)	184
Brighton and Hove, City of (UA)	123	Reading (UA)	187
South Downs (NP)	126	Southampton, City of (UA)	188
Buckinghamshire (UA)	126	Surrey	189
East Sussex	131	Elmbridge	189
	131	Epsom and Ewell	189
Eastbourne	131	Guildford	190

Mole Valley	190
Reigate and Banstead	192
Runnymede	192
Spelthorne	192
Tandridge	193
Waverley	193
Woking	193
West Berkshire (UA)	194
West Sussex	197
Adur	197
Arun	197
Chichester	198
Horsham	199
Mid Sussex	200
South Downs (NP)	200
Worthing	204
Windsor and Maidenhead (UA)	204
Wokingham (UA)	205

THE REGISTER

The Heritage at Risk Register includes historic buildings and sites at risk of being lost through neglect, decay or deterioration.

It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful <u>publications</u> and <u>guidance</u> is available on our <u>website</u>.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are assessed according to the nature of the site. The risk assessment methodologies outlined below are based on factors which can threaten the different types of heritage assets and lead to them becoming at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England; and
- in secular (non-worship) use. And either:
- a grade I or II* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'partoccupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern, or are believed to no longer be at risk.

Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. An overall category for condition, vulnerability and trend is included for each conservation area on the Heritage at Risk Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

THE EFFECT OF COVID-19 ON THE COLLECTION AND COLLATION OF THE STATISTICS USED FOR THE 2021 REGISTERS

As with last year, the collection of this year's data has been affected by Covid-19. Depending on the region, site visits were either not possible or very limited for both our staff and our local authority colleagues throughout the year. Although the usual level of on-site checking of entries on, additions to and removals from the Register was not possible for a second year, deskbased assessments and updates were carried out.

Key Heritage at Risk Statistics for London & South East 2021

BUILDINGS AND STRUCTURES

- Of the 22,514 grade I and II* listed buildings (excluding places of worship) in England, 772 (3.4%) are on the Register. Of the 5,926 listed secular buildings (of grade I and II*) in London & South East 134 (2.3%) are on the Register.
- Of the 16,754 grade II secular buildings in London 371 (2.2%) are on the Register.
- In addition to this, of the 2,843 scheduled monuments in London & South East, 75 (2.6%) are on the Register assessed as structural scheduled monuments (ie using the buildings or structures methodology).
- 32 building or structure entries (of all grades and including structural scheduled monuments) have been removed from the previous London & South East Register (2020) for positive reasons and 18 have been added.

PLACES OF WORSHIP

- Of the 14,785 listed places of worship in England, 923 (6.2%) are on the Register. Of the 3,082 listed places of worship in London & South East 174 (5.6%) are on the Register.
- 5 places of worship entries have been removed from the previous London & South East Register (2020) for positive reasons and 8 have been added.

ARCHAEOLOGY

- Of the 19,923 scheduled monuments in England, 2,001 (10.0%) are on the Register assessed as archaeology. Of the 2,843 scheduled monuments in London & South East, 163 (5.7%) are on the Register assessed as archaeological.
- I6 archaeology entries have been removed from the previous London & South East Register (2020) for positive reasons, and 5 have been added.

PARKS AND GARDENS

• Of the 1,696 registered parks and gardens in England 104 (6.1%) are on the Register. Of the

547 registered parks and gardens in London & South East, 36 (6.6%) are on the Register.

 No park and garden entries have been removed for positive reasons or added to the previous London & South East Register (2020).

BATTLEFIELDS

• Of the 47 registered battlefields in England, 3 (6.4%) are on the Register. None of the seven registered battlefields in London & South East are on the Register.

WRECK SITES

- Of the 54 protected wreck sites around England's coast, 4 (7.4%) are on the Register.
 Of the 4 on the Register, 3 are off the coast of Kent and one is in the Thames Estuary.
- One protected wreck site has been added to the previous London & South East Register (2020).

CONSERVATION AREAS

- There are 491 conservation areas on the Register. Of these, 140 are in London & South East.
- One conservation area has been removed from the previous London & South East Register (2020) for positive reasons and one has been added.

HISTORIC ENGLAND FUNDING

- £2.36 million in grant was spent on 40 entries (including conservation areas) on the London & South East Register during 2020/21.
- In addition, £0.40 million of Covid-19 pandemic recovery funding was spent on 2 entries.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of both buried and structural remains.

2020 HAR data as at 12am 12 June 2020 2021 HAR data as at 12 am 19 July 2021

Key to the entries

The Register includes the following risk assessment types:

- Building or structure (grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship
 - (grade I, II* and II listed buildings)
- Archaeology
 - (scheduled monuments earthworks and buried archaeology)
- Park and garden
 (Registered parks and gardens)
- Battlefield
 - (Registered battlefields)
- Wreck site
 - (Protected wreck sites)
- Conservation area
 - (Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

LISTING

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CÀ)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- HE Historic England
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- PWS Protected Wreck Site
- RB Registered Battlefield
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON		1					
Barking and Dagenham	4	I	I		0 0	0	I
Barnet	4	4	l		0 0	0	
Bexley	3	0	0		0 0	0	0
Brent	8	3	0	1	0 0	0	0
Bromley	19	I	3		1 0	0	1
Camden	17	14	0		0 0	0	0
City of London	0	2	2		0 0	0	0
Croydon	6	5	2		0 0	0	1
Ealing	6	I	2		0 0	0	5
Enfield	11	2	0		3 0	0	2
Greenwich	10	2	0		0 0	0	
Hackney	17	9	0		1 0		
Hammersmith and Fulham	12		0		0 0		
Haringey	11	3	0		0 0		
Harrow	13	1	5				
Havering	9	0			0 0		
Hillingdon	29		3		0 0		
Hounslow	20		2				
Islington	12		0	1	0 0		
Kensington and Chelsea	31	4	0				
	5	4	0		0 0		
Kingston upon Thames		1					
Lambeth	32		0		0 0		
Lewisham	16		0		0 0		
London Legacy (MDC)	4		0		0 0		
Merton	4				0		
Newham	3		0		0 0		
Redbridge	3	2			I 0		
Richmond upon Thames	4		0		0 0		
Southwark	25	4	2		I 0		
Sutton	5	1	0		0 0		
Tower Hamlets	22		<u> </u>		0 0		5
Waltham Forest	12	4	0		0 0	0	0
Wandsworth	7				0 0	0	
Westminster, City of		9	0	1	0 0	0	0
BRACKNELL FOREST (UA)		1					
Bracknell Forest (UA)	0	0	0	1	2 0	0	0
BRIGHTON AND HOVE, CI	TY OF (UA)	1		1			1
Brighton and Hove, City of	6	5	0		1 0	0	6
(UĂ)	3	5			·	•	0
SOUTH DOWNS (NP)	_	-			-	-	
South Downs (NP)	0	0	l		0 0	0	
BUCKINGHAMSHIRE (UA)		1		1			1
Buckinghamshire (UA)	9	5	8		2 0	0	0
EAST SUSSEX		1					
Eastbourne	4		I		0 0	0	0
Hastings	5	6	0		0 0	0	1
Lewes	1	0	0		0 0	0	0
Rother	4	I			0 0	0	0
South Downs (NP)	2	0	5		0 0	0	0
South Downs (NP) / Brighton and Hove, City of (UA) / Lewes [†]	0	0	0	,	I 0	0	0
Wealden	0	2	0		1 0	0	0
Wealden / Tunbridge							
Wells [†]	0	0	I		0 0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HAMPSHIRE		-		-	-	-	
West Berkshire (UA) / Basingstoke and Deane [†]	0	0	0	I	0	0	0
Basingstoke and Deane	1	0	3	0	0	0	0
East Hampshire	0	0	I	0	0	0	0
Eastleigh	0	0	I	0	0	0	0
Fareham	2	0	0	0	0	0	0
Gosport	7	0	3	0	0	0	3
Hart	1	0	0	2	0	0	0
Havant	0	I	0	0	0	0	1
New Forest	0	2	5	0	0	0	0
New Forest (NP)	0	0	3	0	0	0	0
Rushmoor	2	I	0	0	0	0	0
South Downs (NP)	2	0	9	0	0	0	5
Test Valley	0	0	9	I	0	0	0
Winchester	1	1	4	0	0	0	8
Portsmouth, City of (UA) / Winchester ^{T}	I	0	0	C	0	0	0
ISLE OF WIGHT (UA)							
Isle of Wight (UA)	7	9	2	2	0	0	7
KENT							
Ashford	4	0	I	0	0	0	0
Canterbury	5	3	2	0	0	0	0
Dartford	0	0	3	0	0	0	0
Dover	5	3	2	0	0	0	3
Folkestone and Hythe	7	2	3	0	0	0	0
Maidstone	7	3	2	0	0	0	2
Sevenoaks	I	0	I	I	0	0	0
Sevenoaks / Tunbridge Wells [†]	0	0	0	I	0	0	0
Swale	5	3	0	0	0	0	8
Thanet	3	1	4	0	0	0	1
Tonbridge and Malling	0	I	3	0	0	0	0
Tunbridge Wells	1	0	0	0	0	0	1
Tunbridge Wells / Wealden [†]	0	0	I	I	0	0	0
KENT (OFF)							
Kent (off)	0	0	0	0	0	4	0
MEDWAY (UA)							
Medway (UA)	11	0	0	0	0	0	4
MILTON KEYNES (UA)				·			
Milton Keynes (UA)	0	I	3	0	0	0	1
OXFORDSHIRE							
Cherwell	2	1	2	0	0	0	2
Oxford	I	2	0	0	0	0	0
South Oxfordshire	4	I	8	C	0	0	0
South Oxfordshire / Wokingham (UA) [†]	0	0	0	I	0	0	0
Vale of White Horse	1	1	4	0	0	0	0
West Berkshire (UA) / Vale of White Horse [†]	0	0	I	C	0	0	0
West Oxfordshire	0	1	7	C	0	0	0
PORTSMOUTH, CITY OF (L	JA)						
Portsmouth, City of (UA)	12	3	0	C	0	0	0
READING (UA)							
Reading (UA)	2	0	0	0	0	0	1

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
SOUTHAMPTON, CITY OF	(UA)						
Southampton, City of (UA)	2	I	0	0	0	0	I
SURREY	1	1	1		1		
Elmbridge	3	0	0	0	0	0	I
Epsom and Ewell	0	0	0	0	0	0	3
Guildford	1	1	0	I	0	0	0
Mole Valley	3	1	2	I	0	0	0
Reigate and Banstead		0	0	0	0	0	C
Runnymede	0	0	0	I	0	0	C
Spelthorne	0	1	0	0	0	0	C
Tandridge	1	1	0	0	0	0	0
Waverley	0	1	I	0	0	0	0
Woking	0	0	0		0	0	I
WEST BERKSHIRE (UA)	1	1	1	1	1		1
West Berkshire (UA)	4	3	4	2	0	0	C
WEST SUSSEX		1		1			
Adur	0	I	0	0	0	0	I
Arun	2	I	0	0	0	0	C
Chichester	2	0	3	1	0	0	I
Horsham	1	2	2	0	0	0	I
Mid Sussex	0	1	1	0	0	0	I
South Downs (NP)	4	1	17	0	0	0	I
Worthing	0	1	0	0	0	0	C
WINDSOR AND MAIDENH	EAD (UA)	1		1			
Windsor and Maidenhead (UA)	3	0	0	0	0	0	I
WOKINGHAM (UA)		1	1	1	1		
Wokingham (UA)	2	0	3	I	0	0	C
TOTAL	580	174	163	36	0	4	140

[†] Sites that cross local planning authority boundaries

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

GREATER LONDON

BARKING AND DAGENHAM

	SITE NAME:	The Old Vicarage, Crown Street, Dagenham	House, dated 1665, and remodelled in the C19. The building is currently partly occupied and has been at risk of
	DESIGNATION:	Listed Building grade II, CA	vandalism. Planning Permission has been granted for residential conversion into flats. The Local Authority is
	CONDITION:	Poor	awaiting the submission of conditions relating to the consented scheme.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
land	LIST ENTRY NUMBER:	1064411	Contact: Mark Tyson (LPA) 020 8227 5236

© Historic Engla




SITE NAME:	The Marks Stones, Whalebone Lane North, Chadwell Heath	Boundary marker of the Liberty of Havering-atte-Bower, set up in 1642. There are two stones; one inscribed 'Marks
DESIGNATION:	Listed Building grade II	Stone' and one inscribed 'Marks Stone Sept 1642'. One stone is broken and in safekeeping, the other remains in its
CONDITION:	Very bad	original position. The stones are to be repaired by the quarry operators once restoration of the area is complete.
OCCUPANCY:	N/A	A feasibility report, with funding from the National Lottery
PRIORITY CATEGORY:	D (D)	Heritage Fund in 2015, explored the potential of the site. The site's use and maintenance is being discussed with the
OWNER TYPE:	Crown	Local Authority, the Crown Estate and Historic England.
LIST ENTRY NUMBER:	1079887	Contact: Mark Tyson (LPA) 020 8227 5236

© Historic England



© Historic England Archive





The Warren Stone, Whalebone

Lane North, Chadwell Heath

Listed Building grade II

Poor

N/A

D (D)

Crown

1184884

Contact: Mark Tyson (LPA) 020 8227 5236 The remains of a World War II anti-aircraft battery, with pits for eight guns in two groups of four, and associated structures. The buildings are in an isolated spot and have been subject to vandalism. The former quarry is being restored, including the land levels around the gun site, and when complete there will be a five-year aftercare plan. A feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site.

Discussions are ongoing between the Local Authority, the

Crown Estate and Historic England regarding its future use

Contact: Mark Tyson (LPA) 020 8227 5236

Boundary stone erected in 1642. The stone marked the boundary of Hainault Forest, along with the Marks Stones

and the Forest Bounds Stone. The stone is in storage at

Warren Farm during ongoing quarrying operations. The stone will be reinstated in its original position once

quarrying is finished and land levels have been restored. A

The site's use and maintenance is being discussed with the Local Authority, the Crown Estate and Historic England.

feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site.

© Historic England



SITE NAME:	Church of St Peter and St Paul, Crown Street, Dagenham	Most of the church was rebuilt in 1800 in the Strawberry Hill Gothic style, using red brick quoins and dressings to
DESIGNATION:	Listed Place of Worship grade II*, CA	frame ashlar and ragstone panels. A fine open-truss roof spans the nave. The chancel and north chapel are medieval, rendered over ragstone; the interior has been re-ordered.
CONDITION:	Poor	Repairs to the tower roof and lantern, held up by Covid19, were funded by the National Lottery Heritage Fund and
PRIORITY CATEGORY:	F (F)	are now complete. Drainage to the north side of the
OWNER TYPE:	Religious organisation	church is being investigated.
LIST ENTRY NUMBER:	1359302	Contact: Ian Harper 020 7973 3786

and management.

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BARKING AND DAGENHAM / BARNET

SITE NAME:	Barking Abbey		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1003581
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Chadwell Heath Anti-Aircraft Gun Site, Marks Ga	ite	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Mark Tyson (LPA) 020 8227 5236

BARNET

© Histo

	SITE NAME:	College Farm - main building, Fitzalan Road N3	Stables, teashop and dairy, built in 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy
Lat	DESIGNATION:	Listed Building grade II, CA	farm of the Express Dairy Company. The site is owned by the College Farm Trust. The building is in a deteriorating
	CONDITION:	Fair	condition and discussions are ongoing regarding the future use of the site and necessary repairs.
	OCCUPANCY:	Occupied/in use	abe of the site and necessary repairs.
	PRIORITY CATEGORY:	C (C)	
and the second second	OWNER TYPE:	Charity (heritage)	
toric England	LIST ENTRY NUMBER:	1359127	Contact: Jonathan Hardy (LPA) 020 8359 4655

and the second sec	
NE	Antes a

Harris Andrews	SITE NAME:	College Farm Dairy, Fitzalan Road N3	Dairy built in 1883 to the design of Frederick Chancellor, with an ornate timber lantern roof and decorative tilework
	DESIGNATION:	Listed Building grade II, CA	to the interior. The site is owned by the College Farm Trust. The building is in a deteriorating condition and
	CONDITION:	Fair	discussions are ongoing regarding the future use of the site and necessary repairs.
	OCCUPANCY:	Vacant/not in use	and necessary repairs.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1064789	Contact: Jonathan Hardy (LPA) 020 8359 4655

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

use).

PRIORITY CATEGORY:

LIST ENTRY NUMBER

© Historic	England
OTINCOTIC	- Burne



SITE NAME:	Silo, Fitzalan Road, College Farm N3	Silo built in 1883 to the design of Frederick Chancellor as part of the Express Dairy Company's pioneering model
DESIGNATION:	Listed Building grade II, CA	farm. The site is owned by the College Farm Trust. The building is in a deteriorating condition and discussions are
CONDITION:	Fair	ongoing regarding the future use of the site and necessary repairs.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1359128	Contact: Jonathan Hardy (LPA) 020 8359 4655

The Railway Hotel dates from 1931 and was designed by AE Sewell for the brewers, Truman Hanbury Buxton. It is a large three storey half-timbered roadhouse, no longer in use as a public house and damaged by a fire in 2016. The listing includes the former off-sales building and the gibbet sign on the frontage. An approved scheme for hotel use has not been implemented. The Local Authority has taken enforcement action relating to the building's condition and use of the surrounding site.

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

Railway Hotel including sign in

building to west, Station Road,

front and former off-sales

Listed Building grade II

Part occupied/part in use

Edgware

Poor

C (C)

Private

1096066

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Jonathan Hardy (LPA) 020 8359 4655

A	BBR	EVIA	ONS

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Church of St Jude, Central Square, Hampstead Garden Suburb NW11	Designed by Sir Edwin Lutyens, St Jude's was consecrated in 1911 with the west end completed in 1935. There are frescoes throughout by Walter Starmer, dating from 1919-
-	DESIGNATION:	Listed Place of Worship grade I, CA	30. The church has damp issues; there is cracking evident internally and some areas of the frescoes are suffering from salt damage. The heating system requires overhauling.
	CONDITION:	Poor	Works on site in summer 2021 to reinstate the weathervane and repair the lead spire, damaged when the
	PRIORITY CATEGORY:	C (C)	weathervane fell. A Historic England Heritage at Risk grant
N. L.	OWNER TYPE:	Religious organisation	was awarded for emergency repointing of open joints in the brick tower at the same time.
© Historic England	LIST ENTRY NUMBER:	1294714	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Parish Church of St Mary, Church End, Hendon NW4	St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added
	SITE NAME: DESIGNATION:		St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in
		Church End, Hendon NW4 Listed Place of Worship grade	St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in the roofs and gutters; structural movement particularly to
	DESIGNATION:	Church End, Hendon NW4 Listed Place of Worship grade II*, CA	St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in the roofs and gutters; structural movement particularly to the south and west; hard renders on the external walls; and issues with drainage at and below ground level. These
	DESIGNATION: CONDITION:	Church End, Hendon NW4 Listed Place of Worship grade II*, CA Poor	St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in the roofs and gutters; structural movement particularly to the south and west; hard renders on the external walls; and

© Historic England



© Historic England

LIST ENTRY NUMBER: 1359029 water is damaging wall paintings.	
Contact: Tracey Craig 020 7973 3756	
SITE NAME: All Saints Church, Durham Road, East Finchley N2 This is a prominent suburban church of I designed by JEK and JP Cutts and built in	1892. Thé chancel
DESIGNATION: Listed Place of Worship grade II with transepts was built in 1911, with par side. There is a fine hammer-beam roof	
CONDITION: Fair part of a re-ordering by Bruno Hooker i the rood screen was moved to the west	
PRIORITY CATEGORY: F (F) adjacent hall (c1935) demolished. The p	lain tiled roofs
OWNER TYPE: Religious organisation were repaired in 2019, funded by the Na Heritage Fund. The cracking in brick mas	
LIST ENTRY NUMBER: 1396401 end is still under investigation.	

Contact: lan Harper 020 7973 3786

	SITE NAME:	Church of All Saints, Oakleigh Road, Friern Barnet N20	Built in 1883, designed by Joseph Clark in Early English style, with tiled pitched roofs and flint faced walling with ashlar
	DESIGNATION:	Listed Place of Worship grade II	dressings. It has a tall tower and stone spire. The structure has suffered from general erosion of stonework and has
Form MA	CONDITION:	Poor	extensive cementitious repairs, which are failing. There are areas of bulging and missing flints. Repairs to the spire and
	PRIORITY CATEGORY:	C (C)	tower grant-aided by the National Lottery Heritage Fund
	OWNER TYPE:	Religious organisation	were completed in 2019. Further repairs to masonry are required, particularly to the west end and to the south
- inditer	LIST ENTRY NUMBER:	1064881	porch.
uis Factured			Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Brockley Hill Romano-British pottery and settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	College Farm, Finchley N3		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BEXLEY / BRENT

BEXLEY




© London Borough of Bexley

SITE NAME:	Section of garden wall to the north of Hall Place, Bourne Road, Bexley, DA5	C16 red brick garden wall which was part rebuilt in C18, enclosing Hall Place and its formal gardens. A section of the wall between the gatehouse and a brick pier has a severe
DESIGNATION:	Listed Building grade I, part in RPG grade II	lean and in places has collapsed and requires structural repair. There is also severe erosion of brickwork and mortar pointing parallel with the A223 Bourne Road. A
CONDITION:	Poor	potential solution with Listed Building Consent is being discussed by the Local Authority and Historic England.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1064250	Contact: Elizabeth Whitbourn 07889 808145



	SITE NAME:	Crossness Pumping Station, Belvedere Road SE28	Opened 4 April 1865; the engineer was Joseph Bazalgette. The building retains important cast iron interior fittings and
	DESIGNATION:	Listed Building grade I, CA	four colossal beam engines by James Watt and Co. The Crossness Engines Trust opens the building regularly and
	CONDITION:	Good	has a programme of restoration work. Repairs to embedded rainwater pipes are still needed.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
antical la	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1064241	Contact: Elizabeth Whitbourn 07889 808145

© Historic England



BRENT



SITE NAME: 842 Harrow Road, Queens Park Early C19 detached villa with later alterations and **NWI0** extensions. The building has been unoccupied for a number of years and is in very poor condition, with some DESIGNATION: Listed Building grade II, CA unauthorised and harmful works having been carried out by the previous owner. Planning Permission and Listed CONDITION: Fair Building Consent have been granted; works are in progress OCCUPANCY: Vacant/not in use and are due to finish in mid 2021. PRIORITY CATEGORY: F (F) OWNER TYPE: Private 1078879 Contact: Mark Price (LPA) 020 8937 5236 LIST ENTRY NUMBER:

© Historic England



		10/00/	
	SITE NAME:	Former Savoy Cinema, Burnt Oak Broadway, Edgware	The Savoy Cinema was built for the independent circuit Goide & Glassman and was designed by cinema architect
	DESIGNATION:	Listed Building grade II	George Coles. It opened on 29th June 1936 with Bobby Breen in "Rainbow on the River". It is an impressive cinema
	CONDITION:	Poor	with all of its internal Moderne fittings intact. It operated as a bingo hall from the 1960s but closed in 2014. The
	OCCUPANCY:	Vacant/not in use	building remains empty and in a declining state with
	PRIORITY CATEGORY:	D (C)	crumbling plasterwork. Applications for Planning Permission and Listed Building Consent to re-purpose and
	OWNER TYPE:	Commercial company	restore the building were approved in March 2021.
	LIST ENTRY NUMBER:	1384932	Contact: Mark Price (LPA) 0208 937 5236

© London Borough of Brent

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

A A	SITE NAME:	Cambridge Hall, Cambridge	Built in 1863 as St James's Episcopal Chapel. It is a
	LIST ENTRY NUMBER:	389534	Contact: Mark Price (LPA) 020 8937 5236
© Historic England	OWNER TYPE:	Unknown	
	PRIORITY CATEGORY:	A (A)	
In the second second is	OCCUPANCY:	N/A	
CHA	CONDITION:	Fair	of the allegorical cowled figures is missing. Discussions are underway regarding the necessary repair works.
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	ascribed to Sir Alfred Gilbert. Commemorates James Goetze and his wife Rosina and is the only listed memorial in the cemetery. It is vulnerable to heritage crime and one
	SITE NAME:	Goetze Grave, Paddington Cemetery, Willesden Lane NW6 NW6	Pink granite Celtic cross on a two-stage base set within a kerb of granite surrounded by railings. Circa 1911, by Kelly, monumental masons, incorporating figural elements



	SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6	Built in 1863 as St James's Episcopal Chapel. It is a prefabricated structure of corrugated iron with boarded
	DESIGNATION:	Listed Building grade II, CA	roof covered in corrugated asbestos. Since 1920 it has been the home of the Willesden & St Marylebone Cadet
	CONDITION:	Poor	Corps, which converted the interior to resemble a boat, in itself of historic interest. In 2020 Historic England awarded
	OCCUPANCY:	Part occupied/part in use	a Covid-19 Emergency Heritage at Risk Response Fund
	PRIORITY CATEGORY:	C (C)	grant for high priority repairs. Discussions and an options appraisal, funded by Historic England, are ongoing, prior to
	OWNER TYPE:	Other not for profit group	seeking funding for full repair.
	LIST ENTRY NUMBER:	1271962	Contact: Mark Price (LPA) 0208 937 5236

© Historic England



© Historic England

	SITE NAME:	Old Oxgate Farm, Coles Green Road, Cricklewood NW2	C16 and C17 timber-framed building suffering from subsidence to the brick plinth and structural failure of beam
	DESIGNATION:	Listed Building grade II*	ends to the ground floor due to damp penetration. A condition assessment was produced in 2016, with funding
	CONDITION:	Poor	from Historic England, and priority works identified in that survey to safeguard the building were completed in 2017.
	OCCUPANCY:	Part occupied/part in use	Funding for repair of the front façade has been secured
	PRIORITY CATEGORY:	A (A)	through a Section 106 agreement but this has not yet been implemented. The building has recently been sold and
	OWNER TYPE:	Private	discussions are underway with the new owner.
	LIST ENTRY NUMBER:	1078875	Contact: Elizabeth Whitbourn 07889 808145

	SITE NAME:	Summerhouse, Kingsbury Manor, 288, Kingsbury Road	Summerhouse, circa 1899, by William West Neve, who designed the adjoining Kingsbury Manor for Mary Blair, Duchess of Sutherland. Built in the Arts and Crafts style, timber-framed with patterned brick nogging on a brick plinth edged with stone, and a hipped thatched roof. The thatched roof is deteriorating and the building is in need of repair. The Local Authority and the owner have begun discussions to develop a strategy for the summerhouse's repair and re-use.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A REAL PROPERTY AND A REAL	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© London Borough of Brent	LIST ENTRY NUMBER:	1322049	Contact: Mark Price (LPA) 020 8937 5236

	SITE NAME:	Wembley Hill Lodge, 114, Wembley Hill Road, Brent HA9	Early C19 orné style cottage which was formerly a lodge to Wembley Park. Single storey and attic with gable to the front. Featuring twin chimneys and thatched catslide roof. The detached property was severely damaged by a fire in 2013. The new owner submitted applications in 2021 for Planning and Listed Building Consent, which includes reinstatement of the lodge, and these are under consideration.
	DESIGNATION:	Listed Building grade II	
THE MARKED	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1359001	Contact: Mark Price (LPA) 0208 937 5236

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

grade II, CA

Vacant/not in use

Local authority

Very bad

A (A)



Mid-C19 twin Anglican and Nonconformist chapels The Chapels at Paddington connected by a pair of carriage-porches and a central bell Cemetery, Willesden Lane tower, behind which is a lodge. Designed by Thomas Little Listed Building grade II, RPG in 1855 as part of a new cemetery. The vacant buildings are isolated within the cemetery and too dangerous to use. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for holding repairs to the walls, roof and rainwater goods, with the purpose of allowing the Heras fencing surrounding the building to be removed.

© Historic England



	LIST ENTRY NUMBER:	1359002	Contact: Mark Price (LPA) 0208 937 5236
	SITE NAME:	New Parish Church of St Andrew, Church Lane, Kingsbury NW9	Built 1847 in Wells Street in London's West End, designed by Guy Daukes. It fell into disuse and in 1933 was dismantled and rebuilt in Kingsbury. The interior was
	DESIGNATION:	Listed Place of Worship grade II*, CA	reconstructed in its entirety apart from the north and south galleries and has works commissioned from many leading C19 architects and artists. Holding works have been
	CONDITION:	Poor	carried out to the spire, which has suffered from rust jacking. In 2020 Historic England awarded a Covid-19
	PRIORITY CATEGORY:	C (C)	Émergency Heritage at Risk Response Fund grant for
	OWNER TYPE:	Religious organisation	project development for the roof and spire and holding repairs to gutters to prevent the ingress of water.
	LIST ENTRY NUMBER:	1078874	Contact: Tracey Craig 020 7973 3756

© John Scott



SITE NAME:	Church of St Andrew, High Road, Willesden Green NW10	Designed by James Brooks and built in 1885. Brooks also designed the adjacent grade II vicarage. The church suffers
DESIGNATION:	Listed Place of Worship grade II*, CA	from cracking, some severe, mainly at the eastern end. Potentially loose stones internally have been pinned to secure them and the church is undergoing monitoring and
CONDITION:	Poor	various investigations in order to ascertain the cause of the movement which is resulting in the cracking. In 2020
PRIORITY CATEGORY:	C (C)	Historic England awarded a Covid-19 Emergency Heritage
OWNER TYPE:	Religious organisation	at Risk Response Fund grant to address a number of maintenace issues to the church fabric.
LIST ENTRY NUMBER:	1078881	Contact: Tracey Craig 020 7973 3756
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Road, Willesden Green ŇW10 DESIGNATION: Listed Place of Worship grade II*, CA CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

© Historic England

SITE NAME:	St Michael's Church, St Michael's Road, Cricklewood NW2	Designed by John Samuel Alder and built in 1910 in stone with tiled pitched roofs and flat roofs to the aisles, which are felted. In the north west corner is the base of a tower
DESIGNATION:	Listed Place of Worship grade II	which was never built. The church generally is in poor condition with movement resulting in cracking, and faulty
CONDITION:	Very bad	rainwater goods allowing water ingress with much stair internally. The west end window is supported by a
PRIORITY CATEGORY:	A (A)	framework of scaffolding poles.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1262125	Contact: Tracey Craig 020 7973 3756
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Michael's Road, Cricklewood NW2DESIGNATION:Listed Place of Worship grade IICONDITION:Very badPRIORITY CATEGORY:A (A)OWNER TYPE:Religious organisation

© Historic England

BROMLEY



SITE NAME:	Base of the Southern Crystal Palace Water Tower, SE 19	Base Pala
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	by F King was
CONDITION:	Poor	thicl subt
OCCUPANCY:	N/A	con
PRIORITY CATEGORY:	C (New entry)	cem now
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1469984	Cor

e, trenches and pipework of the southern Crystal ace water tower. Built for the Crystal Palace Company Fox, Henderson and Company to designs by Isambard gdom Brunel between 1854 and 1856. The tower itself s demolished in 1940-1941. The structure comprises a k, tapering, ring of brickwork, beneath which is a terranean area enclosed within the circular mass ncrete foundation. The brickwork has a coating of nent render which has fallen off in places so that it is w vulnerable to further weather and vegetative damage.

ontact: Simon Went (LPA) 020 8464 3115

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site WHS



SITE NAME:	The Ice House and Ha-Ha Wall at Bromley Palace Park, Kentish Way	Ice house and ha-ha wall to Bromley Old Palace. Ice house probably dating from the late C18, and remodelled in the early C19 as a garden shelter. Considerable repairs have
DESIGNATION:	Listed Building grade II	been undertaken, and a fence constructed to protect the rear chamber, but further substantial works are required
CONDITION:	Very bad	and it has been subject to extensive vandalism. The ha-ha is severely overgrown, and requires repair. The Civic Centre
OCCUPANCY:	N/A	complex has been designated a development site within the
PRIORITY CATEGORY:	C (C)	Bromley Town Centre Area Action Plan and it is expected that nearby development will fund repair of these heritage
OWNER TYPE:	Local authority	assets, amongst others.
LIST ENTRY NUMBER:	1393912	Contact: Simon Went (LPA) 020 8464 3115

© Historic England

© Historic England



	SITE NAME:	Victorian Folly of 'Medieval Ruins' in Bromley Palace Park, Rafford Way	Folly with Norman style detailing, probably of mid-1860s and by the important firm of garden contractors, Pulham. The structure has been cleared of ivy and other woody
	DESIGNATION:	Listed Building grade II	vegetation which was seriously damaging the stonework and lime render. The Civic Centre complex has been
	CONDITION:	Very bad	designated a development site within the Bromley Town Centre Area Action Plan and it is expected that nearby
48	OCCUPANCY:	N/A	development will fund repair of this heritage asset, amongst
CHART -	PRIORITY CATEGORY:	C (C)	others.
At	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1186785	Contact: Simon Went (LPA) 020 8464 3115

1	SITE NAME:	Wickham Court, Layhams Road	A large C15 semi-fortified manor house built by Sir Henry
	DESIGNATION:	Listed Building grade I	Heydon. The square plan has castellated octagonal turrets located at each corner. The once-open courtyard has beer roofed in and contains a central stair. The house is leased and occupied by a private school. The building suffered from storm damage resulting in the partial collapse of the south west turret. This was also caused by a lack of regular maintenance that is evident in the failed roof covering and
A CHARTER PARTY OF	CONDITION:	Very bad	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE: Private	timber beams. Repair proposals are currently being prepared.	
listeria England	LIST ENTRY NUMBER:	1055809	Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic England



	SITE NAME:	Pedestrian subway under Crystal Palace Parade, Crystal Palace SE19	The Subway was designed by Charles Barry Junior and opened in 1865. It provided a direct link from his High Level Station (demolished 1961) into the Crystal Palace via
	DESIGNATION:	Listed Building grade II*, part in RPG grade II*	a ticketing hall. The hall is now roofless, and the spectacular diaper brickwork of the subway vaulting is suffering from long-term water ingress. Historic England funded a
	CONDITION:	Poor	condition survey in 2014 and is providing grant aid for a full repair project, funded primarily by the London
	OCCUPANCY:	N/A	government's Strategic Investment Pot, with support from
	PRIORITY CATEGORY:	E (D)	the Friends of Crystal Palace Subway. Repairs are due to commence later in 2021.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1385457	Contact: Ian Harper 020 7973 3786



	SITE NAME:	Prehistoric animal sculptures, geological formations and lead mine on islands in lake, Crystal Palace Park SE19	Sculptures of dinosaurs and other prehistoric animals, with associated geological strata, constructed between 1852 and 1855 for The Crystal Palace Company. The structures form a unique display of prehistoric life as understood at the
	DESIGNATION:	Listed Building grade I, RPG grade II*, CA	time. The dinosaurs are deteriorating, which is likely to be caused by ground movement, vegetation growth and water ingress. Major damage to the Megalosaurus in 2020 has
	CONDITION:	Very bad	been repaired, funded by a Historic England Covid-19 Emergency Heritage at Risk Response Fund grant.
ALC: YE	OCCUPANCY:	N/A	Stakeholders are developing a joint approach to
	PRIORITY CATEGORY:	A (A)	investigating the causes of deterioration.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1067798	Contact: Verena McCaig 020 7973 3718

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

			1000	
			A 100	
				_
ALL CONTRACTOR OF A				
STATISTICS HH				
A SHIT ASTR				
Wall of			-	
			-	
		U	1	
		-10	1	
		-N	1	
	i i i		1	

JOIN AND SOUTH EAST	/ BROMLET	
SITE NAME:	Upper and Lower Terraces, Crystal Palace Park SE19	Terraces designed by Sir Joseph Paxton and situated to the east of the site of Crystal Palace (re-erected here in 1852-4
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	and burnt down in 1936), on the west of Crystal Palace Park. The terraces are in a very poor condition and suffering from erosion. Repair and conservation works
CONDITION:	Poor	have been completed on the six sphinxes which adorn them, funded by the Local Authority, the Mayor of London,
OCCUPANCY:	N/A	and Historic England. Discussions are ongoing to determine
PRIORITY CATEGORY:	C (C)	an approach to further conservation works as part of the wider strategic regeneration plan for the park.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1064352	Contact: Simon Went (LPA) 020 8464 3115
SITE NAME:	Building 10 (Junior Ranks Mess, former Airmen's Institute), West Camp, Main Road, A233 (east side), Biggin Hill	Former Airmen's Institute and recreation centre of c1926 design and built in 1930. It was one of the principal barracks buildings at Biggin Hill, the internationally renowned historic fighter base. The building has been

© Historic England



		(east side), Biggin Hill	renowned historic fighter base. The building has been
	DESIGNATION:	Listed Building grade II, CA	vacant since the RAF withdrew from Biggin Hill in 1993. Repairs have been undertaken to the roof. Having met with
	CONDITION:	Poor	the owner, the Local Authority and Historic England are discussing ways in which they can assist in identifying new
	OCCUPANCY:	Vacant/not in use	uses for the building.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1416723	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	North and south railings, Crystal Palace Parade, Crystal Palace Park SE19	Decorative cast iron railings on gault brick plinths with stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in
	SITE NAME: DESIGNATION:	Crystal Palace Parade, Crystal	stone copings, which formed the main pedestrian entrance
		Crystal Palace Parade, Crystal Palace Park SE19 Listed Building grade II, RPG	stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in 1936) from Crystal Palace Parade. There is damage to some cast iron panels and the dwarf wall, and a long section of curved railing is missing from the north section. A condition survey of the railings was completed in 2015,
	Designation:	Crystal Palace Parade, Crystal Palace Park SE19 Listed Building grade II, RPG grade II*	stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in 1936) from Crystal Palace Parade. There is damage to some cast iron panels and the dwarf wall, and a long section of curved railing is missing from the north section.

© Historic England



OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Local authority

91, High Street, St Mary Cray

Listed Building grade II, CA

1393659

Very bad

B (B)

Private

1298993

Vacant/not in use

© Historic England



	SITE NAME:	The Royal Bell Hotel, 173-177, High Street, Bromley	The Royal Bell Hotel is part of a range of buildings rebuilt in 1898 on the site of an earlier hostelry of 1666. It has been
	DESIGNATION:	Listed Building grade II, CA	vacant for some years and is in need of repair to halt its decline. Following a change of owner, Planning Permission
	CONDITION:	Poor	and Listed Building Consent have been granted to bring the hotel back into use, with enabling development on the
	OCCUPANCY:	Vacant/not in use	stable yard. Works have commenced on site.
	PRIORITY CATEGORY:	F (F)	
ą.	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1054095	Contact: Simon Went (LPA) 020 8464 3115

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Simon Went (LPA) 020 8464 3115

CI6 dwelling with crown post roof. The building is in a very

poor condition and a flank wall is at risk of collapse. Listed

Listed Building Consent have been approved for works in connection with development for residential use.

Building Consent has been granted for repairs to the structure, and applications for Planning Permission and

However, no works have yet been carried out.

Contact: Simon Went (LPA) 020 8464 3115

ABBREVIATIONS

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LOINDC	JIN AIND SOUTH EAST	BROMLET		
	Former Sergeants' Mess), West Ministry's Dir Camp, Main Road, A233 (east has been vaca side), Biggin Hill 1993. The Lo		Sergeants' mess, dating from 1932, built by the Air Ministry's Directorate of Works and Buildings. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. The Local Authority is considering action to secure	
	DESIGNATION:	Listed Building grade II, CA	works. Having met with the owner, the Local Authority and Historic England are discussing ways in which they can	
	CONDITION:	Poor	assist in identifying new uses for the building.	
Lange and the second	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
© London Borough of Bromley	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1391606	Contact: Simon Went (LPA) 020 8464 3115	
	SITE NAME:	Building 15, Hawkinge Block, West Camp, Main Road, A233 (east side), Biggin Hill	Barrack block dated 1934, built by the Air Ministry's Directorate of Works and Buildings. The building has been vacant since the RAF withdrew from Biggin Hill in 1993.	
	DESIGNATION:	Listed Building grade II, CA	The Local Authority is considering action to secure works. Having met with the owner, the Local Authority and	
	CONDITION:	Poor	Historic England are discussing ways in which they can	
	OCCUPANCY:	Vacant/not in use	assist in identifying new uses for the building.	
	PRIORITY CATEGORY:	C (C)		
and the second second second	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1391604	Contact: Simon Went (LPA) 020 8464 3115	
1	SITE NAME:	Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill	Office block dated 1931, formerly the station headquarters building. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. The Local Authority is	
CITERING SALS	DESIGNATION:	Listed Building grade II, CA	considering action to secure works. Having met with the owner, the Local Authority and Historic England are	
	CONDITION:	Poor	discussing ways in which they can assist in identifying new	
	OCCUPANCY:	Vacant/not in use	uses for the building.	
A A CONTRACTOR OF A CONTRACTOR	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Commercial company		
© London Borough of Bromley	LIST ENTRY NUMBER:	1391587	Contact: Simon Went (LPA) 020 8464 3115	
	SITE NAME:	Buildings I-5 (Airmen's barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill	Group of five airmen's barracks blocks, dating from 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill in 1993. Roof repairs have been carried out to one block but urgent repairs are required to the roofs	
	DESIGNATION:	Listed Building grade II, CA	and rainwater goods of the remaining blocks. The Local Authority is considering action to secure these works.	
	CONDITION:	Very bad	Having met with the owner, the Local Authority and	
	OCCUPANCY:	Vacant/not in use	Historic England are discussing ways in which they can assist in identifying new uses for the buildings.	
	PRIORITY CATEGORY:	A (A)		
© Historic England	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1391589	Contact: Simon Went (LPA) 020 8464 3115	
	SITE NAME:	lce house to Sundridge Park, Plaistow Lane, Bromley	Ice house circa 1800, in the south west corner of a late C18 landscape park designed by Humphry Repton, now a	
	DESIGNATION:	Listed Building grade II, RPG grade II	golf course. The ice house has previously been subject to vandalism despite strenuous efforts by the owners to prevent access. A local archaeological group has identified	
	CONDITION:	Very bad	its exact location but access is difficult. Liaison continues with the group and the site manager to reassess its	
	OCCUPANCY:	N/A	condition and current management issues.	
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1254001	Contact: Simon Went (LPA) 020 8464 3115	
 PRIORITY CATEGORIES A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed. 	 D Slow decay; solution not yet implemented E Under repair or in fa repair, but no user in under threat of vacar obvious new user (a to buildings capable use). 	I. (where applicable) end use o ir to good user identified; or functionall dentified; or edundant buildings with new ncy with no agreed but not yet implemen pplicable only	r Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority y use New Entry is noted). NP National Park	


	SITE NAME:	Pulhamite fernery, Stockwell Close, Bromley Palace Park	Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley
	DESIGNATION:	Listed Building grade II	Palace that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the
	CONDITION:	Poor	ornamental lake and is in need of repair. The Civic Centre complex has been designated a development site within the
	OCCUPANCY:	N/A	Bromley Town Centre Area Action Plan and it is expected
	PRIORITY CATEGORY:	C (C)	that nearby development will fund repair of this heritage asset, amongst others.
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1392584	Contact: Simon Went (LPA) 020 8464 3115



	SITE NAME:	Pulhamite waterfall, Stockwell Close, Bromley Palace Park	Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley
1 AL	DESIGNATION:	Listed Building grade II	Palace that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end,
- B	CONDITION:	Poor	adjacent to an ice house, probably of late C18, and is in need of repair. Vegetation clearance has taken place but
N	OCCUPANCY:	N/A	structural works are needed. The Civic Centre complex
e.	PRIORITY CATEGORY:	C (C)	has been designated a development site within the Bromley Town Centre Area Action Plan and it is expected that
	OWNER TYPE:	Local authority	nearby development will fund repair of this heritage asset, amongst others.
	LIST ENTRY NUMBER:	1392583	Contact: Simon Went (LPA) 020 8464 3115

© Historic England

© Historic England



-	SITE NAME:	Church of St John the	The church was designed by John Nash and Edwin Nash of
	LIST ENTRY NUMBER:	1299012	Contact: Simon Went (LPA) 020 8464 3115
2	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	F (F)	
	OCCUPANCY:	Vacant/not in use	
	CONDITION:	Fair	leisure uses. Works which do not require consent have commenced on site.
	DESIGNATION:	Listed Building grade II, CA	for Planning Permission and Listed Building Consent have been submitted to convert the building for office, hotel and
	SITE NAME:	Old Town Hall, Tweedy Road, Bromley	Former Town Hall building built in 1906 and used as premises for Bromley College until 2006/07. Applications

٥f Bermondsey in the Early English style and completed in 1849. It is built of ragstone with Bath stone dressings, including the spire. The church suffers from water ingress at roof and lower levels, and dampness at lower levels. High level repairs were completed in 2013 at the east end, grant-aided by Historic England and the National Lottery Heritage Fund. Further repairs are required to the west end but await the outcome of discussions between Historic England and the church regarding a development scheme,

© Historic England

SITE NAME:	Iron Age settlement and Roman villa at Warbank, K	eston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002024
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Scadbury Manor moated site and fishponds		
SITE NAME: DESIGNATION:	Scadbury Manor moated site and fishponds Scheduled Monument, CA	LIST ENTRY NUMBER:	1409786
		LIST ENTRY NUMBER: TREND:	1409786 Declining
DESIGNATION:	Scheduled Monument, CA		

Evangelist, High Street, Penge

Religious organisation

Listed Place of Worship grade II,

SE20

CA

Poor

C (C)

1186832

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: lan Harper 020 7973 3786

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
 - Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

SITE NAME:	1E: Romano-British masonry building and Saxon cemetery, Fordcroft, Orpington				
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1001973	
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Stable	
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No	
OWNER TYPE:	Local authority, multiple owners		CONTACT:	Elizabeth Whitbourn 07889 808145	
	SITE NAME:	Crystal Palace Park SE19	Mid-C19 pleasur	e grounds designed by Sir Joseph Paxton	
	DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, part in CA	park is in variable	as a setting for the Crystal Palace, burnt down in 1936. park is in variable condition with related listed structure: also at risk. The Local Authority has approved a	
	CONDITION:	Generally satisfactory but with significant localised problems	regeneration plan for the park to realise much of the of the 2010 masterplan and is securing the agreement its implementation alongside a new sustainable goverr and management model. The Local Authority and His		
3.9	VULNERABILITY:	Medium			
and a free to the	TREND: St	Stable		ded a hydrology study of park water now complete and will inform	
	NEW ENTRY?:	No	improvement works.		
© Historic England	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1000373	Contact: Christo	pher Laine 07780 545 979	

SITE NAME:	Biggin Hill RAF		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Simon Went (LPA) 020 8464 3115

CAMDEN

	SITE NAME:	Former Hampstead Police Station, Rosslyn Hill NW3 NW3	Former police station and courthouse including stable and harness room, railings and lamps. Built in 1913 by J Dixon Butler, surveyor to the Metropolitan Police. The building
	DESIGNATION:	Listed Building grade II, CA	has been empty since 2013 and is now secure after illegal entry in 2014 and 2020. Applications for a proposed new
	CONDITION:	Poor	use as a school were refused by the Local Authority in 2019 and were dismissed at appeal in 2020.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Government or agency	
© London Borough of Camden	LIST ENTRY NUMBER:	1130397	Contact: Alan Wito (LPA) 020 7974 6392



© Historic England

	SITE NAME:	Wall to the south of St George's Gardens, Handel Street, WCI WCI	C18 red brick graveyard wall with stone copings to the piers. The burial ground was closed in 1854 and reopened as public gardens in the late C19. The wall is lined with
	DESIGNATION:	Listed Building grade II, part in RPG grade II*, CA	gravestones formerly located within the burial ground. Some sections of wall have been repaired but there are structural problems on this southern section. Discussions
	CONDITION:	Poor	are underway with the owners of the wall regarding the necessary repairs.
	OCCUPANCY: N/A		
	PRIORITY CATEGORY:	C (C)	
(OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1378729	Contact: Alan Wito (LPA) 020 7974 6392

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

П

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

LIST ENTRY NUMBER:



SITE NAME:	Cattle trough to south east of the Roundhouse, Chalk Farm Road NW1	Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist Charles Kingsley. Some
DESIGNATION:	Listed Building grade II, CA	repairs have been carried out but investigation into the security of the trough on the plinth is required. It is
CONDITION:	Fair	vulnerable given its location adjacent to the bus lane and bus stop.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1258104	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

© Historic England



	SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NWI	Late CI9 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but the drinking
	DESIGNATION:	Listed Building grade II, CA	fountain remains prone to littering and damage. Options for repair are being explored with the relevant partner
	CONDITION:	Fair	organisations.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1258105	Contact: Alan Wito (LPA) 020 7974 6392



© Historic England



have started on site and are progressing. PRIORITY CATEGORY: F (F) OWNER TYPE: Health authority LIST ENTRY NUMBER: 1242917 Contact: Alan Wito (LPA) 020 7974 6392 SITE NAME: 26, Denmark Street WC2 Early C18 terraced house; windows altered in C20. The windows, parapets and gutters are in poor condition. DESIGNATION: Listed Building grade II, CA Listed Building Consent and Planning Permission have been granted as part of a wider scheme which includes CONDITION: Poor residential use on the upper floors and repairs to the roof OCCUPANCY: and front parapet. Repair works are continuing on site with Vacant/not in use the front façade being refurbished and tied back into the PRIORITY CATEGORY: F (F)

building.

Former Strand Union

Street WI

Fair

Private

1271982

Workhouse (Middlesex

Listed Building grade II, CA

Part occupied/part in use

Hospital Annex), 44, Cleveland

© Historic England

	SITE NAME:	3, Endsleigh Street	One in a terrace of four houses, dating from circa 1825,
	DESIGNATION:	Listed Building grade II, CA	built by Thomas Cubitt and constructed from multi- coloured stock brick. It comprises four storeys and a
	CONDITION:	Poor	basement with a round-arched doorway and first floor casements with continuous cast iron balconies. The
TH TH TH	OCCUPANCY:	Vacant/not in use	property is empty and whilst externally it is in fair condition
	PRIORITY CATEGORY:	D (D)	there have been unauthorised works internally. Planning Permission and Listed Building Consent were granted in
	OWNER TYPE:	Private	2018 to convert the ground floor to a gallery but works have not yet started.
	LIST ENTRY NUMBER:	1078298	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Alan Wito (LPA) 020 7974 6392

ABBREVIATIONS

Former Strand Union Workhouse, dating from 1778, with

Street behind later high brick walls. Vacated by University

College London Hospital and in temporary occupation by

residential accommodation and mixed-use development to

the rear of the listed building have been approved. Works

an austere symmetrical brick building facing Cleveland

live-in guardians and site staff in the adjoining unlisted

buildings. The buildings are weathertight and secure. Applications for refurbishment and alterations to provide

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

H

HERITAGE AT RISK 2021 / LONDO	on and south east	/ CAMDEN	
	SITE NAME:	The Elms (formerly Elm Lodge), Fitzroy Park N6	Detached house built between 1838 and 1840 to the design of George Basevi. A listed building enforcement
	DESIGNATION:	Listed Building grade II, CA	notice was served in 2012 following unauthorised works during refurbishment. Planning Permission and Listed
	CONDITION:	Good	Building Consent have been granted to rectify these unauthorised works, but have not yet been implemented.
	OCCUPANCY:	Vacant/not in use	The building is wind and watertight.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1078355	Contact: Alan Wito (LPA) 020 7974 6392
- A	SITE NAME:	43, Fitzroy Street	One of a terrace of four houses, dating from the late C18, constructed from darkened multi-coloured stock brick with
	DESIGNATION:	Listed Building grade II, CA	some stucco dressings. It comprises four storeys and a
	CONDITION:	Poor	basement. The property is partially occupied and in a deteriorating condition. The Local Authority has contacted
	OCCUPANCY:	Part occupied/part in use	the owner to discuss the building's condition.
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1322184	Contact: Alan Wito (LPA) 020 7974 6392
© Historic England			
	SITE NAME:	34 and 39, Great James Street	Two in a terrace of 14 houses, dating from 1720-24, all of
	DESIGNATION:	Listed Building grade II*, CA	four storeys with basements and constructed from brown brick. Both properties are currently empty. Listed Building
	CONDITION:	Poor	Consent and Planning Permission were granted in 2018 f refurbishment and a rear extension at 39, and in 2019 fo
	OCCUPANCY:	Vacant/not in use	34 Great James Street. Works have started at 34 Great
	PRIORITY CATEGORY:	F (F)	James Street.
	OWNER TYPE:	Commercial company, multiple owners	
© Historic England	LIST ENTRY NUMBER:	1113203	Contact: Elizabeth Whitbourn 07889 808145
	SITE NAME:	Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6	Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. The original sculptures are missing from the completed scheme.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
ALS V SERVE	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379028	Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	College Chapel, Kings College, Kidderpore Avenue	Former Kings College chapel built 1928-9 by Percy Morley Horder and Verner Rees. Rendered brickwork with a
	DESIGNATION:	Listed Building grade II, CA	stone portico. Shallow hipped roof with projecting eaves. Austere and restrained classical design; rectangular in plan
	CONDITION:	Good	with a semi-circular apse internally. The building has been repaired for use as a single dwelling but is presently
	OCCUPANCY:	Vacant/not in use	unoccupied.
The Part of the second second	PRIORITY CATEGORY:	F (F)	
The second second	OWNER TYPE:	Educational (independent)	
		12702.10	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

1379249

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Alan Wito (LPA) 020 7974 6392

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



SITE NAME:	Drinking fountain on north west corner, Lincoln's Inn Fields	Stone gabled drinking fountain with a semi-circular basin on a half pedestal. Erected in 1861, restored circa 1992, and
DESIGNATION:	Listed Building grade II, RPG grade II, CA	inscribed "The Fear of the Lord is a Fountain of Life". An early public drinking fountain erected at the time when the St Giles's parish wells were polluted and when Lincoln's Inn
CONDITION:	Poor	Fields was being restored and renovated. The fountain is not functioning and has a plaque missing. The Local
OCCUPANCY:	N/A	Authority replaced the rear maintenance panel in 2019 and
PRIORITY CATEGORY:	C (C)	is working towards a repair scheme.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1379337	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England



	SITE NAME:	Heath House, North End Way NW3	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following
	DESIGNATION:	Listed Building grade II*, CA	war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have
	CONDITION:	Poor	been removed. In 2019 the building was protected by scaffolding, monoflex wrapping and a temporary roof. The
	OCCUPANCY:	Vacant/not in use	owner is pursuing a scheme which was granted consent in
	PRIORITY CATEGORY:	A (A)	2008 to restore the building as a single dwelling, which has been partially implemented.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	3 83	Contact: Elizabeth Whitbourn 07889 808145

© London Borough of Camden



SITE NAME:	Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3	Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and
DESIGNATION:	Listed Building grade II, CA	fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved
CONDITION:	Poor	an application for further remedial works to part of the wall.
OCCUPANCY:	N/A	wan.
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Charity (non-heritage)	
LIST ENTRY NUMBER:	1130395	Contact: Alan Wito (LPA) 020 7974 6392

Church built 1869-71 to the design of SS Teulon, in an SITE NAME: St Stephen's Church, Rosslyn early French Gothic style. The London Diocesan Fund has Hill NW3 leased the church to St Stephen's Restoration and DESIGNATION: Listed Building grade I, CA Preservation Trust for use by Hampstead Hill School and as a community lifelong learning centre. Repair works to CONDITION: Poor the south slope of the nave roof, grant-aided by Historic OCCUPANCY: Occupied/in use England, were completed in March 2016. Further repairs are needed to the other roofs and the tower. PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1130394 Contact: lan Harper 020 7973 3786

© Historic England Archive



-	SITE NAME:	Toll Gate House, Spaniards Road, Highgate NW3	Late C18 toll house, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic
	DESIGNATION:	Listed Building grade II, part in CA	bottleneck on a busy road and has suffered impact damage from heavy vehicles. A bollard was erected in late 2008 to provide protection from traffic. Roof and guttering repair
	CONDITION:	Good	works have been undertaken and the property is regularly inspected. It is now in good condition, but remains
	OCCUPANCY:	Vacant/not in use	unoccupied.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1378793	Contact: Alan Wito (LPA) 020 7974 6392

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LOINDO	JIN AIND SOUTH EAST		
	SITE NAME:	St George's Cathedral (formerly Christ Church), Albany Street, Camden NWI	Former parish church. Antiochian Orthodox Cathedral since 1989. Designed by Sir James Pennethorne, built in 1837 in neo-Grecian style to serve Nash's development
	DESIGNATION:	Listed Place of Worship grade II*, CA	east of Regents Park, with later alterations. The Roman cement mouldings and past repairs in cementitious mortar are failing in places. Cracking is evident, particularly on the
	CONDITION:	Poor	principal street elevations. The tower, spire and main cornice have been netted for safety. In 2020 Historic
	PRIORITY CATEGORY:	A (A)	England awarded a Covid-19 Emergency Heritage at Risk
	OWNER TYPE:	Religious organisation	Response Fund grant for a condition survey of the spire to inform a future package of repairs.
© Historic England	LIST ENTRY NUMBER:	1378620	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Michael, Camden Road, Camden NWI	The nave and aisles were built in 1881, designed by GF Bodley and T Garner; the chancel was added in 1894 and
	DESIGNATION:	Listed Place of Worship grade II*	the vestries in 1908. The church has undergone structural and stonework repair, re-roofing and drainage works. New
	CONDITION:	Poor	electrical and lighting installations were completed in early 2016, grant-aided by the National Lottery Heritage Fund.
	PRIORITY CATEGORY:	C (C)	The interior fabric and heating remain in need of attention.
	OWNER TYPE:	Religious organisation	In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk grant to investigate and consolidate part of
	LIST ENTRY NUMBER:	1244156	the nave painted ceiling where water damage has resulted in flaking paint.
© Historic England			Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of the Holy Trinity with St Barnabas, Clarence Way, Kentish Town NWI	Built in 1849-50 in a C14 Gothic style to the design of Thomas H Wyatt and David Brandon. The building was bomb damaged during World War II. The tower roof was
The second	DESIGNATION:	Listed Place of Worship grade II	re-covered and the roofs re-slated with a grant from the National Lottery Heritage Fund and Historic England. The
	CONDITION:	Poor	church was awarded a subsequent grant from the National
T AT LUS	PRIORITY CATEGORY:	C (C)	Lottery Heritage Fund for repairs to the tower stonework and this was completed in summer 2015. The western end
	OWNER TYPE:	Religious organisation	of the south aisle has suffered from structural movement and in part there is shoring in place externally and
Gra The second	LIST ENTRY NUMBER:	1356761	scaffolding internally.
© Historic England			Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of the Holy Cross, Cromer Street, Camden Town WC1	Church in the Early English style built in 1885 by Joseph Peacock, with internal features by Charles Nicholson circa 1913. Built of yellow stock brick under clay tiled roofs;
	DESIGNATION:	Listed Place of Worship grade II, CA	stone dressings inside and out with red brick banding inside. An unusual two-storey narthex houses the organ gallery. There is settlement of the foundations at the north
	CONDITION:	Very bad	east corner causing structural cracking to the vestry and adjacent walls of the church. Other repairs are needed to
	PRIORITY CATEGORY:	A (A)	the east end roofing, north side guttering and brickwork.
	OWNER TYPE:	Religious organisation	The congregation and Diocese are actively exploring possible sources of funding.
© Historic England	LIST ENTRY NUMBER:	1067375	Contact: lan Harper 020 7973 3786
	SITE NAME:	Church of St Mary Brookfield, Dartmouth Park Road, Hampstead NW5	The church was built in the late C19 by W Butterfield with the chancel added by WC Street in 1881. Construction is of stock brick with red brick bands, diaper work and stone
	DESIGNATION:	Listed Place of Worship grade II*, CA	dressings under a slated roof. The church has a fine interior. There is severe spalling to brickwork internally to chancel walls and weathering of stone dressings at high
1	CONDITION:	Poor	level externally, caused by previous failure of parapet gutters and rainwater goods at the east end. The parish is
	PRIORITY CATEGORY:	C (C)	preparing a project to carry out the necessary repairs and
-	OWNER TYPE:	Religious organisation	is investigating sources of funding.
© Historic England	LIST ENTRY NUMBER:	1067389	Contact: Ian Harper 020 7973 3786

PRIORITY CATEGORIES


- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© Historic England

© Historic Eng

	SITE NAME:	Christ Apostolic Church (formerly Church of St John), Highgate Road, Kentish Town NW5	Church built on the site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. High level repairs to the west end, grant-aided by the
	DESIGNATION:	Listed Place of Worship grade II	National Lottery Heritage Fund and Historic England, were completed in 2011. The Diocese commissioned a full
	CONDITION:	Poor	dilapidations report in 2020 and is in discussion with the church. Some stained-glass windows have been sent to a studio for repair. The church is seeking funding for this a
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	other necessary internal and external repairs.
ngland Archive	LIST ENTRY NUMBER:	1379013	Contact: lan Harper 020 7973 3786



SITE NAME: This church was constructed in the style of a three-aisled St Andrew's Cathedral (former Church of St Barnabas), Kentish basilica (without a dome) by Ewan Christian in 1884-85. It has been in use by the Greek Orthodox Church since 1957 Town Road, Hampstead NWI and became St Andrew's Cathedral in 1970. All internal Listed Place of Worship grade II, walls and ceilings have been decorated in the traditional DESIGNATION: CA Byzantine style, and large areas have been repainted where damaged by dampness. Externally the tabled guttering to CONDITION: Poor the aisles and apse needs renewal. PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1379241 Contact: lan Harper 020 7973 3786

	SITE NAME:	Church of St Mary Magdalene, Munster Square, Camden Town NWI	The church, designed by RC Carpenter and completed in 1852, was described in the Ecclesiologist as the 'most artistically correct new church in London'. Even so, it was
	DESIGNATION:	Listed Place of Worship grade II*, CA	altered in 1866-67, and in 1883-84 the north aisle and crypt were added. Built of ragstone with Welsh slate roofs on Baltic fir collar-braced trusses. The interior is richly
	CONDITION:	Poor	decorated with marbles and frescoes. The condition of the frescoes is poor as a result of damp caused by leaks in the
	PRIORITY CATEGORY:	A (A)	roof and defective rainwater goods. Externally there is
	OWNER TYPE:	Religious organisation	localised decay to the stonework.
© Historic England	LIST ENTRY NUMBER:	1113157	Contact: Ian Harper 020 7973 3786

© Historic England



			·
	SITE NAME:	St Pancras Old Church, Pancras Road, Camden NWI	Church dating from the CI3 and enlarged in the mid CI9 by AD Gough and RL Roumieu, retaining CI3 and CI5
	DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA	fabric and wall memorials. Restored by AW Blomfield in the late C19 and again by Erith and Terry in 1980. The church has cracks externally and internally along with
	CONDITION:	Very bad	blown plaster. A deep and narrow C19 gully around the building was modified in 2015 along with new drainage
	PRIORITY CATEGORY:	B (B)	works, with a grant from the National Lottery Heritage
	OWNER TYPE:	Religious organisation	Fund. Emergency repairs to unstable masonry were completed in March 2021, grant aided with a Historic
	LIST ENTRY NUMBER:	1113246	England Heritage at Risk repair grant.
			Contact: Tracey Craig 020 7973 3756

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CAMDEN / CITY OF LONDON

	SITE NAME:	Church of St Mary, Priory Road, Camden NW6	Designed by Frederick and Horace Francis in 1856 with the spire added in 1872. The church is built of Kentish ragstone
	DESIGNATION:	Listed Place of Worship grade II, CA	with Bath stone dressings and slate roofs. Stonework repairs to the north and south transept gables and east end of the nave were carried out in 2008, grant-aided by
	CONDITION:	Poor	Historic England. Repairs to the west elevation of the nave and north aisle are also complete, jointly funded by the
	PRIORITY CATEGORY:	C (C)	National Lottery Heritage Fund and Historic England.
	OWNER TYPE:	Religious organisation	Further repairs are required to the tower and spire stonework.
	LIST ENTRY NUMBER:	1139083	Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England



	SITE NAME:	Church of St George the Martyr, Queen Square, Holborn WC1	Built 1706 by Arthur Tooley with major re-modelling in 1869 by SS Teulon who altered the exterior, added a chancel, and removed most of the galleries. The roof is in
C PI	DESIGNATION:	Listed Place of Worship grade II*, CA	poor condition and this, along with defects in the rainwater goods, may have contributed to falls of plaster in the worship area which necessitated the church to close.
	CONDITION:	Poor	Emergency stabilisation works were carried out in 2019 which permitted worship in the church again. In 2020
	PRIORITY CATEGORY:	C (C)	Historic England awarded a Covid-19 Emergency Heritage
	OWNER TYPE:	Religious organisation	at Risk Response grant to undertake a condition survey of the ceiling and prepare a schedule of work.
	LIST ENTRY NUMBER:	1245485	Contact: Tracey Craig 020 7973 3756



	SITE NAME:	Church of St Pancras, Upper Woburn Place, Camden NWI	Designed by H and HW Inwood, built in 1822 and restored in 1953. The earliest Greek Revival church in
	DESIGNATION:	Listed Place of Worship grade I, CA	London. The west end has an lonic portico to a vestibule with tower above. The north and south facades each have a tribune with a portico supported by four caryatids with a
	CONDITION:	Poor	sarcophagus behind. Repairs to the west portico roof and surrounding stone parapets were completed in early 2016,
	PRIORITY CATEGORY:	C (C)	with funding from the National Lottery Heritage Fund. The
	OWNER TYPE:	Religious organisation	condition of the tower, front portico and caryatids has been investigated and all are in need of repair.
	LIST ENTRY NUMBER:	1379062	Contact: Tracey Craig 020 7973 3756

© Historic England

	SITE NAME:	Church of St Martin, Vicars Road, Gospel Oak, Camden NW5	Designed by Edward Buckton Lamb and built 1864-6. The choir vestry added in 1928 is now subdivided for wider community use. Repairs to the tower stonework and
	DESIGNATION:	Listed Place of Worship grade I	restoration of the pinnacles were completed in 2014, grant-aided by the National Lottery Heritage Fund. The
	CONDITION:	Poor	church has a history of subsidence and has been underpinned in part but there is cracking to the choir
	PRIORITY CATEGORY:	C (C)	vestry and more recently in the south east corner. The
	OWNER TYPE:	Religious organisation	west end window to the choir vestry was repaired in 2020. The church is undergoing continual structural monitoring.
	LIST ENTRY NUMBER:	1379098	Contact: Tracey Craig 020 7973 3756

© Historic England

CITY OF LONDON

100		
		H-H-
	AW/O	

SITE NAME:	Church of St Mary Woolnoth, King William Street, City of London EC3	This square-plan churc by Nicholas Hawksmo Street and King Williar
DESIGNATION:	Listed Place of Worship grade I, CA	Butterfield raised the c galleries, setting the ca church is dominated b
CONDITION:	Poor	settlement cracks whice Elsewhere asphalt roo
PRIORITY CATEGORY:	C (C)	Historic England awar
OWNER TYPE:	Religious organisation	at Risk Response Fund dilapidations report to
LIST ENTRY NUMBER:	1064620	Contact: Ian Harper 0

rch was built between 1716 and 1727 oor on a tight site between Lombard am Street. In 1875-6 William chancel floor and removed the carved fronts against the walls. The by a baroque tower: this has ofing needs to be repaired. In 2020 rded a Covid-19 Emergency Heritage d grant for investigations and a costed o inform a repairs programme.

020 7973 3786

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- Conservation Area Listed Building Local Planning Authority National Park LPA
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

17

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CITY OF LONDON / CROYDON

	SITE NAME:	Church of St Margaret, Lothbury, City of London EC2	Designed by Sir Christopher Wren, the church was built between 1686 and 1695. The form is a simple rectangle
1 Local	DESIGNATION:	Listed Place of Worship grade I, CA	orientated north-south with a vestry to the east and a tower to the west. The south elevation is faced in Portland stone; the others are rendered brick with stone quoins.
	CONDITION:	Poor	Internal fittings are contemporary. The spire was fully repaired in 2018-2019 with a grant from the National
	PRIORITY CATEGORY:	C (D)	Lottery Heritage Fund. However, further settlement of the
	OWNER TYPE:	Religious organisation	nave floor is causing concern and is being monitored, along with the tower which leans towards the street.
	LIST ENTRY NUMBER:	1064634	Contact: Ian Harper 020 7973 3786
toric England			

© Historic England

SITE NAME:London Wall: remains of Roman and medieval wall For west end of All Hallows Church to 38 CamomileDESIGNATION:Scheduled Monument, 2 CAsLIST ENTRY NUMBER:1002050CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWINER TYPE:Local authority, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145SITE NAME:London Wall: section bounding All Hallows Churc+verd EC2I002067DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002067CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningSITE NAME:London Wall: section bounding All Hallows Churc+verd EC2I002067DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002067CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWINER TYPE:Private, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145				
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWNER TYPE:Local authority, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145SITE NAME:London Wall: section bounding All Hallows Churc+vet EC2Scheduled Monument, CALIST ENTRY NUMBER:1002067CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:No	SITE NAME:		from west end of a	All Hallows Church to 38 Camomile
CONDITION:problemsproblemsPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWNER TYPE:Local authority, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145SITE NAME:London Wall: section bounding All Hallows Church-yrd EC2DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002067CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:No	DESIGNATION:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1002050
OWNER TYPE:Local authority, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145SITE NAME:London Wall: section bounding All Hallows Churchyard EC2DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002067CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:No	CONDITION:		TREND:	Declining
SITE NAME: London Wall: section bounding All Hallows Churchyard EC2 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002067 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002067 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	SITE NAME:	London Wall: section bounding All Hallows Churcl	hyard EC2	
problems Deterioration - in need of management NEW ENTRY?: No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002067
	CONDITION:		TREND:	Declining
OWNER TYPE:Private, multiple ownersCONTACT:Elizabeth Whitbourn 07889 808145	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
	OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145

CROYDON




© London Borough of Croydon



© London Borough of Croydon

	SITE NAME:	Kennedy's, 18a, High Street, South Norwood SE25	Built in 1926 for Kennedy, a chain of South London butchers, now closed. It is hoped the ground floor shop
	DESIGNATION:	Listed Building grade II, CA	can be brought back into use. Applications for residential use of the upper floors were consented in 2015 and 2016,
	CONDITION:	Poor	and works to implement these have now commenced. The Local Authority's enforcement team has a live case
	OCCUPANCY:	Vacant/not in use	regarding unauthorised works to the building's front
	PRIORITY CATEGORY:	F (F)	elevation.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1392596	Contact: Robert Buckley (LPA) 020 8726 6000



PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Segas offices, 32, Park Lane, Croydon	Gas company showroom and office, built 1939-41 in Moderne style. The building is in need of maintenance and
	DESIGNATION:	Listed Building grade II, CA	is vacant. Approved soft strip works and temporary use of the ground floor as a marketing suite are being
	CONDITION:	Fair	implemented, and discussions are ongoing regarding the long-term use of the building as part of the wider Queen's
	OCCUPANCY:	Vacant/not in use	Square development (St George's Walk). The Mid Croydon Masterplan and Opportunity Area Planning Framework emphasise the need for a new use to be fou
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	for the building.
© Historic England	LIST ENTRY NUMBER:	1262041	Contact: Robert Buckley (LPA) 020 8726 6000



© London Borough of Croydon

N

©

	SITE NAME:	Former lodge to Croydon Airport Terminal, Purley Way, Croydon	Single storey lodge to Airport House, built circa 1928. In spring 2019 works were completed on repairs to the roof, walls and interior to ensure it is secure and watertight. The
	DESIGNATION:	Listed Building grade II	building is vacant and discussions are ongoing between the owner and the Local Authority, with advice from Historic
	CONDITION:	Fair	England, regarding the building's use and a second phase of work to include further internal works and repair of the
	OCCUPANCY:	Vacant/not in use	Crittal windows.
	PRIORITY CATEGORY:	D (F)	
2.12.14	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1079299	Contact: Robert Buckley (LPA) 020 8726 6000

	SITE NAME:	Surrey Street Pumping Station, Surrey Street, Croydon	Pumping station, built in four phases from 1851. The building is secure and watertight, but remains vacant.
	DESIGNATION:	Listed Building grade II, CA	Located within the Old Town Masterplan area, its future use has been identified as key to the regeneration of
	CONDITION:	Fair	Croydon's Old Town. Discussions with the Local Authority are ongoing regarding the future use and repair of the
	OCCUPANCY:	Vacant/not in use	pumping station and regeneration of the surrounding area.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
D Historic England	LIST ENTRY NUMBER:	1079248	Contact: Robert Buckley (LPA) 020 8726 6000

Norwood SE25 catslide roof to the rear. The building is unoccupied and i poor condition following fire damage in 1991. Planning Permission and Listed Building Consent for residential use were granted in 2015. The Local Authority and Historic England are continuing to advise on the condition of the				
DESIGNATION: Listed Building grade II Permission and Listed Building Consent for residential use were granted in 2015. The Local Authority and Historic England are continuing to advise on the condition of the building and repair works. The chimneys have been rebuil and the roof is in the process of being reinstated to make the building wind and weathertight. VINCE Private		SITE NAME:	· · ·	Early C18 timber-framed house with brick gable ends and catslide roof to the rear. The building is unoccupied and in
OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Private	目的自己	DESIGNATION:	Listed Building grade II	Permission and Listed Building Consent for residential use
OCCUPANCY: Vacant/not in use building and repair works. The chimneys have been rebuil and the roof is in the process of being reinstated to make the building wind and weathertight. OWNER TYPE: Private UNST ENTRY NUMBER: 1070290 Constant: Robert Building (I BA) 020 9726 (2000)		CONDITION:	Poor	were granted in 2015. The Local Authority and Historic
PRIORITY CATEGORY: F (F) OWNER TYPE: Private	THE REAL	OCCUPANCY:	Vacant/not in use	building and repair works. The chimneys have been rebuilt
		PRIORITY CATEGORY:	F (F)	
n of Groydon LIST ENTRY NUMBER: 1079280 Contact: Robert Buckley (LPA) 020 8726 6000		OWNER TYPE:	Private	
	n of Croydon	LIST ENTRY NUMBER:	1079280	Contact: Robert Buckley (LPA) 020 8726 6000

© London Borough



-	SITE NAME:	Church of St Mark, Albert Road, South Norwood SE25	Designed by GH Lewis of Linden and Lewis, the nave was built in 1852 and the rest completed by 1890. The church
	DESIGNATION:	Listed Place of Worship grade II, CA	has slate pitched roofs and Kentish ragstone walling. Stonework repairs were completed in 2013, grant-aided by Historic England and the National Lottery Heritage Fund.
	CONDITION:	Poor	The chancel and south slopes of the nave and aisle were re-roofed in 2016 with funding secured from the Listed
	PRIORITY CATEGORY:	C (C)	Places of Worship Roof Repair Fund. The north slopes of
	OWNER TYPE:	Religious organisation	the nave and aisle roofs remain in need of repair.
	LIST ENTRY NUMBER:	1323688	Contact: Tracey Craig 020 7973 3756

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Old Tithe Barn, Purley Way, Waddon	C18 former barn, now in use as a place of worship. The barn is an unusual structure of two parallel ranges with an
	DESIGNATION:	Listed Place of Worship grade II	M-shaped roof. The timber frame is clad in light brickwork with steeply pitched tiled roofs and wooden louvres at the
T	CONDITION:	Fair	end of each range. Some repairs have been undertaken to make the building watertight, however further work is
	PRIORITY CATEGORY:	C (C)	required to the roof and to clear the rainwater goods.
	OWNER TYPE:	Religious organisation	
H.C.	LIST ENTRY NUMBER:	1079247	Contact: Tracey Craig 020 7973 3756

© Historic England

10	SITE NAME:	Church of St Andrew, Southbridge Road, Croydon	Church dating from 1857 by Benjamin Ferrey, with aisles added in 1879; chancel rebuilt and Lady Chapel added in	
	DESIGNATION:	Listed Place of Worship grade II	1891, designed by HB Walton. The church has been re- ordered internally. The unusual bellcote feature has been	
	CONDITION:	Fair	dismantled due to its poor structural condition and needs to be reinstated. Works are also required to the roofs,	
A AALAAN .	PRIORITY CATEGORY:	C (C)	rainwater goods, stonework and windows.	
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1079305	Contact: Tracey Craig 020 7973 3756	

© Historic England

© Historic England

1 305

SITE NAME:	Church of St Augustine, St Augustine's Avenue, South Croydon	Designed by John Oldrid Scott and built in 1884. Re- ordered in 1989 to provide hall accommodation. The church has clay tiled roofs, with flint walling. Roof repairs to
DESIGNATION:	Listed Place of Worship grade II*	the south transept and south chapel, along with associated overhauling of rainwater goods and stone and flint repairs,
CONDITION:	Poor	were completed in 2015 grant-aided jointly by the National Lottery Heritage Fund and Historic England. Further repairs
PRIORITY CATEGORY:	C (C)	are needed to the north aisle roof and tower stonework.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1079301	Contact: Tracey Craig 020 7973 3756
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Augustine's Avenue, South CroydonDESIGNATION:Listed Place of Worship grade II*CONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

SITE NAME: Church of St John, Sylvan Road, Upper Norwood SE19 Built in 1882, designed by John Loughborough Pearson. The church is located on a hill of shrinkable clay and has been subject to ongoing differential movement for many Listed Place of Worship grade DESIGNATION: years which has resulted in substantial cracking, mainly to II*, CA the south side of the building. Underpinning, stitching of the most severe cracks and securing the brick and stone vaulting in the south aisle was completed in 2017, grant-CONDITION: Poor PRIORITY CATEGORY: C (C) aided by the National Lottery Heritage Fund. Outstanding work includes repair of weathered stone dressings and the OWNER TYPE: Religious organisation remaining cracks externally, re-roofing and works to rainwater goods. LIST ENTRY NUMBER: 1079275 Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Three of four World War II fighter pens at the former airfield of RAF Kenley				
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021242		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145		
	i mate, matuple owners				
SITE NAME:	Surrey Iron Railway embankment, approximately I	30m south west of			
SITE NAME: DESIGNATION:		30m south west of LIST ENTRY NUMBER:			
	Surrey Iron Railway embankment, approximately I		Lion Green Road, Coulsdon		
DESIGNATION:	Surrey Iron Railway embankment, approximately I Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	Lion Green Road, Coulsdon		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM

UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CROYDON / EALING

SITE NAME:	South Norwood, South Norwood, Croydon SE25			
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	No significant change	
VULNERABILITY:	Low	CONTACT:	Lucy Morrow (LPA) Lucy Morrow@croydon.gov.uk	

EALING			
VAL.	SITE NAME:	Stable Block at Brent Lodge Park, Church Road, Hanwell W7	Late C19 two-storey building, built of yellow stock brick. Urgent works to the slate hipped roof and underpinning were undertaken to control water ingress and stabilise the
	DESIGNATION:	Listed Building grade II, CA	building. Planning Permission and Listed Building Consent were granted in 2018 for works and repairs to convert it to
	CONDITION:	Good	a children's nursery. Work is in progress on site.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1079410	Contact: Planning Officer (LPA) 020 8825 5000
	SITE NAME:	Hanwell Community Centre, Cuckoo Avenue, Hanwell W7	Administration block of the former London District Schools, 1856. The Local Authority carried out major
	DESIGNATION:	Listed Building grade II, CA	repairs in 2010 and the building is now in good condition. Management of the building has reverted to the Local
	CONDITION:	Good	Authority. Planning Permission and Listed Building Consent have been granted for conversion to a learning and
	OCCUPANCY:	Part occupied/part in use	development centre with a new café, dance studio and
HHAR CONTRACTOR	PRIORITY CATEGORY:	C (C)	community facilities. A long-term business plan has been formulated to support the new school which has taken
	OWNER TYPE:	Local authority	over one of the wings.
© London Borough of Ealing	LIST ENTRY NUMBER:	1358760	Contact: Planning Officer (LPA) 020 8825 5000
	SITE NAME:	Norwood Hall, Norwood Green Road, Southall	Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and
	SITE NAME: DESIGNATION:		estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled
		Green Road, Southall	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the
	DESIGNATION:	Green Road, Southall Listed Building grade II, CA	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for
	DESIGNATION: CONDITION:	Green Road, Southall Listed Building grade II, CA Fair	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house
	DESIGNATION: CONDITION: OCCUPANCY:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house
© Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F)	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private 1079330 Two chapels at South Ealing Cemetery, South Ealing Road	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now considered too dangerous to use. Discussions about the
Image: state of the state of	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private 1079330 Two chapels at South Ealing Cemetery, South Ealing Road W5	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now considered too dangerous to use. Discussions about the full repair and long-term use of the building are ongoing in association with a Building Preservation Trust. An options
Iteration is a series of the series of th	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: IUST ENTRY NUMBER: SITE NAME: DESIGNATION:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private 1079330 Two chapels at South Ealing Cemetery, South Ealing Road W5 Listed Building grade II	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now considered too dangerous to use. Discussions about the full repair and long-term use of the building are ongoing in association with a Building Preservation Trust. An options appraisal and condition survey of the building, funded by the National Lottery Heritage Fund, was completed in
<image/> <caption></caption>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private 1079330 Two chapels at South Ealing Cemetery, South Ealing Road W5 Listed Building grade II Very bad	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now considered too dangerous to use. Discussions about the full repair and long-term use of the building are ongoing in association with a Building Preservation Trust. An options appraisal and condition survey of the building, funded by the National Lottery Heritage Fund, was completed in 2020 and discussions are ongoing to identify funding
<image/> <caption></caption>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UST ENTRY NUMBER: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Green Road, Southall Listed Building grade II, CA Fair Part occupied/part in use F (F) Private 1079330 Two chapels at South Ealing Cemetery, South Ealing Road W5 Listed Building grade II Very bad Vacant/not in use	estate agent John Robins. Extended in the late C19 and includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for several years but is now used as a community centre by the present owner. Works are ongoing to restore the house and a new school complex has been built in the grounds. Contact: Planning Officer (LPA) 020 8825 5000 The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now considered too dangerous to use. Discussions about the full repair and long-term use of the building are ongoing in association with a Building Preservation Trust. An options appraisal and condition survey of the building, funded by the National Lottery Heritage Fund, was completed in

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

21

©⊦

	SITE NAME:	Twyford Abbey, Twyford Abbey Road NW10	Gothic country house built 1807-9 by William Atkinson; brick and cement fronted with a crenelated parapet, last
	DESIGNATION:	Listed Building grade II	used as a nursing home. In 2017 some urgent stabilisation works were carried out and Planning Permission and Listed
	CONDITION:	Very bad	Building Consent were granted for an educational use. However the building is now being marketed.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
Carl State and	OWNER TYPE:	Educational (independent)	
) Historic England	LIST ENTRY NUMBER:	1079383	Contact: Planning Officer (LPA) 020 8825 5000

	SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall	Former mental asylum of 1829 by William Alderson; extended in 1854-57. Part of the original complex has been
	DESIGNATION:	Listed Building grade II	restored for continuing healthcare use. Applications for the conversion of the listed wards to private residential use
	CONDITION:	Fair	were approved in 2013 and the site is now partially refurbished. The chapel, ballroom and remaining wards are
	OCCUPANCY:	Part occupied/part in use	still vacant but work on these is now in progress.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Health authority	
© Historic England Archive	LIST ENTRY NUMBER:	1079364	Contact: Planning Officer (LPA) 020 8825 5000

	SITE NAME:	Christ the Saviour Church, New Broadway, Ealing W5	C12 in origin, largely rebuilt in C15 and clad in brick in 1772. Restored in 1855 and 1871 by Ewan Christian and in
	DESIGNATION:	Listed Place of Worship grade II*, CA	1889 by W Gilbert Scott. The church was awarded a grant from the National Lottery Heritage Fund for repair works to the tower; these works were completed in early 2016.
	CONDITION:	Poor	The nave and aisle roofs are in need of re-covering. Historic England awarded a Covid-19 Emergency Heritag at Risk Response Fund grant in 2020 to carry out a
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	condition survey of high-level roofs and gutters along with costings for permanent and holding repairs to slates,
	LIST ENTRY NUMBER:	1079392	gutters and rainwater goods.
© Historic England			Contact: Tracey Craig 020 7973 3756

SITE NAME:	Hanwell flight of locks and brick boundary wall of S	St Bernard's Hospit	al
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Moated site at Down Barns Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Acton Town Centre, Acton W3		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000

PRIORITY CATEGORIES

А

- В
- C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but F Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial user. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / EALING / ENFIELD

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

SITE NAME:	Cuckoo Estate, Hanwell W7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Ealing Town Centre, Ealing W5		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Haven Green, Ealing W5		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area, 7 LBs, part in RPG grade II*	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000

Holly Hill Farmhouse, The

Listed Building grade II

Vacant/not in use

Local authority

Ridgeway

Very bad

A (A)

1188655

ENFIELD



© Historic England



SITE NAME:	North Lodge, Whitewebbs Road	Small Victorian Gothic stuccoed cottage of one storey and an attic, with a steep-pitched roof of fishscale tiles with
DESIGNATION:	Listed Building grade II	barge-boarded gable ends. The building has been empty and neglected for many years and part of the building has
CONDITION:	Very bad	now been subject to unauthorised demolition works. The Local Authority has undertaken extensive works to secure
OCCUPANCY:	Vacant/not in use	and protect the building under enforcement regulations.
PRIORITY CATEGORY:	A (A)	Steps are now being taken to ensure appropriate consents are obtained, and full repair of the building secured.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1079477	Contact: Christine White (LPA) 020 8379 3852

© London Borough of Enfield



SITE NAME:	Southgate House, High Street N14	Late with
DESIGNATION:	Listed Building grade II*	is nov now
CONDITION:	Poor	grow buildi
OCCUPANCY:	Vacant/not in use	Auth
PRIORITY CATEGORY:	A (A)	owne future
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1079541	Cont

C18 house with early C19 extension in similar style, an elliptical entrance hall. Formerly used as a college, it w vacant whilst a new use is secured. Water ingress, halted, has led to outbreaks of dry rot, and vegetation vth has hampered ventilation and drainage to the ling. The building was sold in 2020 and the Local nority and Historic England are working with the new er to bring forward a suitable proposal to secure its e.

Mid C19 villa of London stock brick, formerly a farmhouse

from the effects of water ingress, blocked rainwater goods, vegetative growth, broken windows and rotten joinery.

The building is now secured, and Historic England and the

Local Authority have identified urgent works needed to

arrest further decline whilst a decision is made on the

Contact: Christine White (LPA) 020 8379 3852

future use of the building.

and with later additions and outbuildings to the rear. The

house has been vacant for many years and has suffered

tact: Verena McCaig 020 7973 3718

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ÍΙΑ Unitary Authority World Heritage Site WHS



© Historic England

© Histo

	SITE NAME:	Broomfield House, Broomfield Park, Broomfield Lane N13	C16 house with late C18 additions, situated in a public park. The building is severely fire damaged, although
	DESIGNATION:	Listed Building grade II*, RPG grade II	significant parts of the interior are in safe storage. Additional scaffolding works were carried out in 2016 funded by Historic England and the Local Authority.
	CONDITION:	Very bad	Following extensive discussions and commissioned reports, further work is being carried out to help inform a decision
	OCCUPANCY:	Vacant/not in use	on the future of the building.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1078934	Contact: Verena McCaig 020 7973 3718

coric England	SITE NAME:	Stable block in Broomfield Park, Broomfield Lane N13	Early C18 stable block to Broomfield House. The building is vacant. Internal propping works have been undertaken to
	DESIGNATION:	Listed Building grade II*, RPG grade II	stabilise the floors, and further works carried out following subsequent fire and water damage. Following extensive discussions and commissioned reports, further work is
	CONDITION:	Very bad	being carried out to help inform a decision on the future the building.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1188544	Contact: Verena McCaig 020 7973 3718

© Historic England

	SITE NAME:	Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road	1870-1 Gothic Revival cemetery chapel. The chapel is in poor condition and in need of an appropriate use. Repairs are required to arrest deterioration of damaged stonework
	DESIGNATION:	Listed Building grade II	and a decision is needed on the future of the building.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079458	Contact: Christine White (LPA) 020 8379 3852

SITE NAME:	Former Edmonton Girls' Charity School, Church Street, Edmonton N9	Single storey building, with a central arched doorway to the street and sash windows to either side. Above the doorway is a statuette of a female pupil. Historic England and the Local Authority are working with the current owners and London Historic Buildings Trust to secure a repair project. Potential new users have been identified ar discussions are ongoing to identify funding sources. In the meantime, live-in guardians continue to safeguard the
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	property.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1079547	Contact: Christine White (LPA) 020 8379 3852
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Charity School, Church Street, Edmonton N9DESIGNATION:Listed Building grade II, CACONDITION:PoorOCCUPANCY:Part occupied/part in usePRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

SITE NAME:	24, Church Street, Edmonton N9	Former teacher's accommodation to the adjoining Charity School. C18 cottage of red brick with renewed pantile
DESIGNATION:	Listed Building grade II, 2 CAs	roof. Historic England and the Local Authority are working with the current owners and London Historic Buildings
CONDITION:	Poor	Trust to secure a repair project. Potential new users have been identified and discussions are ongoing to identify
OCCUPANCY:	Occupied/in use	funding sources. In the meantime, live-in guardians continue
PRIORITY CATEGORY:	C (C)	to safeguard the property.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1079546	Contact: Christine White (LPA) 020 8379 3852

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SIT
	DE
	CC
STATISTICS IN CONTRACTOR	00
	PRI
	OV

TE NAME: Trent Park House terrace, Brick and stone terrace reconstructed in the 1920s. The terrace is in very poor condition, with temporary propping Cockfosters Road, Trent Park in place. Vegetation clearance and further propping works Listed Building grade II, RPG were undertaken after additional surveys were carried out. SIGNATION: grade II, CA Full repair and conservation are expected to take place as part of the planned redevelopment of the wider site, which ONDITION: Very bad is in progress. CCUPANCY: N/A RIORITY CATEGORY: D (D) WNER TYPE: Commercial company LIST ENTRY NUMBER: 1078931 Contact: Christine White (LPA) 020 8379 3852

© Historic England

© Historic England



	SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield	Former Enfield Electricity Works dating from 1906, architect unknown. The building is partially occupied.
	DESIGNATION:	Listed Building grade II	Extensive works have been undertaken to stabilise the building and make it watertight. However, further works
	CONDITION:	Poor	are required to the exterior stone and tile-work to prevent water ingress and further damage. Future operational
	OCCUPANCY:	Part occupied/part in use	options are under consideration for the site which will
	PRIORITY CATEGORY:	C (C)	inform its future repair and re-use.
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1389537	Contact: Christine White (LPA) 020 8379 3852

© London Borough of Enfield

SITE NAME: Barn at Whitewebbs Farm, Simple, timber-framed barn probably dating from the late Whitewebbs Road C17. Works have been undertaken to prop the building to secure the structure. Planning Permission and Listed DESIGNATION: Listed Building grade II Building Consent have been granted for residential conversion. Planning conditions have yet to be discharged CONDITION Very bad and works have yet to commence on site. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Private LIST ENTRY NUMBER: 1079480 Contact: Christine White (LPA) 020 8379 3852

C12 in origin, largely rebuilt in the C15 and clad in brick in SITE NAME: All Saints Church, Church 1772. Restored in 1855 and 1871 by Ewan Christian and in Street, Edmonton N9 1889 by William Gillbee Scott. The church has a Kentish Listed Place of Worship grade ragstone medieval tower, 1772 brick-faced east and north DESIGNATION: II*, CA sides, and stone south and west sides. The church was awarded a grant from the National Lottery Heritage Fund CONDITION: Poor for repair works to the tower and these works were PRIORITY CATEGORY: C (C) completed in early 2016. The nave and aisle roofs are in need of re-covering. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1079548 Contact: Tracey Craig 020 7973 3756

© Colin Kerr (Architect)



SITE NAME:	Church of St Andrew, Church Walk, Enfield	The church and tow C15 and C16 (Sir TI restored in C19 (inc Lochner, St Anbyn a including brick and f dressings. There are these are deteriorat drainage. The leakin failure in the belfry. Parish is seeking fun- and repair project.
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Very bad	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1079549	

wer have CI2 origins, were extended in homas Lovell), repaired in C18, and cluding all new roofs) by variously and Scott. It is built of rubble masonry flint with stone quoins and window re fine CI5 and CI6 monuments but ting due to dampness caused by poor ng tower roof has caused a structural Holding repairs are in place and the nding for a comprehensive development

Contact: Ian Harper 020 7973 3786

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ΪA
- Unitary Authority World Heritage Site WHS

a subscription of the second se				
	SITE NAME:	Broomfield Park N13		nal gardens associated with Broomfield
and a	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA	of formal lakes, for use as a pul	ising a walled enclosure focussed on a serie , and set within a landscape park. Converte blic <u>p</u> ark in the early C20, with input from
	CONDITION:	Generally satisfactory but with significant localised problems	historic parklar	on. The lakes are in poor condition and th nd has suffered losses to development. The ole block are in very bad condition and
All and a second second	VULNERABILITY:	Medium	further work is	being carried out to help inform a decision
A Property and a property of the second seco	TREND:	Declining	Plan exists for 1	of the buildings. A Conservation Manageme the landscape and discussions are needed t
	NEW ENTRY?:	No	secure its imple	
© Historic England	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1000517	Contact: Chris	topher Laine 07780 545 979
	SITE NAME:	Grovelands Park N14	Late C18 lands	cape park and lake by Humphry Repton,
	designation:	Registered Park and Garden grade II*, 5 LBs, part in CA	the early C20 b immediate grou	e mid-C19 and laid out as a public park in by Thomas Mawson. The mansion and unds are now a private hospital. The divide
	CONDITION:	Generally satisfactory but with significant localised problems	Thames Water	he park between the Local Authority, r and the hospital has led to differential egimes. The sports area is in very bad
Rep. 78	VULNERABILITY:	Medium	A Conservation Management Plan requires complet discussions are needed in order to then secure its implementation.	
	TREND:	Declining		
) Historic England	NEW ENTRY?:	No		
	OWNER TYPE:	OWNER TYPE: Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000395	Contact: Christopher Laine 07780 545 979	
	SITE NAME:	Trent Park	Late C18 landscape park further developed in the ear C20 by Sir Philip Sassoon. Developers are implement their approved scheme for improvements to the cor the historic landscape around the mansion house. The remain significant issues in the surrounding parkland, owned and managed by the Local Authority as a court present the improving the intervention of the surrounding parkland, owned and managed by the Local Authority as a court present the improving the imp	
	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, part in CA		
	CONDITION:	Generally satisfactory but with significant localised problems		
			Dark, Discussio	
	VULNERABILITY:	High	relationship be	ons continue towards improving the inter- tween the wider park and the historic core
A CARLER	VULNERABILITY: TREND:	High Stable	relationship be and improveme	ons continue towards improving the inter-
Nilsenia Enderd		-	relationship be and improveme	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the
) Historic England	TREND:	Stable	relationship be and improveme	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the
9 Historic England	TREND: NEW ENTRY?:	Stable No	relationship be and improveme parkland and w	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the
	TREND: NEW ENTRY?: OWNER TYPE:	Stable No Mixed, multiple owners 1000484	relationship be and improveme parkland and w	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the vater bodies more generally.
SITE NAME:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER:	Stable No Mixed, multiple owners 1000484 dmonton N9	relationship be and improveme parkland and w	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the vater bodies more generally.
D Historic England SITE NAME: DESIGNATION: CONDITION:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER: Church Street, E	Stable No Mixed, multiple owners 1000484 dmonton N9	relationship be and improveme parkland and w Contact: Chris	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the vater bodies more generally. topher Laine 07780 545 979
SITE NAME: DESIGNATION:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER: Church Street, E Conservation Are	Stable No Mixed, multiple owners 1000484 dmonton N9	Contact: Christ	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the vater bodies more generally. topher Laine 07780 545 979
SITE NAME: DESIGNATION: CONDITION:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER: Conservation Are Very bad Low Fore Street, Edm	Stable No Mixed, multiple owners 1000484 dmonton N9 ea, 8 LBs	relationship be and improveme parkland and w Contact: Christ NEW ENTRY?: TREND:	ons continue towards improving the inter- tween the wider park and the historic core ents are sought to the management of the vater bodies more generally. topher Laine 07780 545 979 No No significant change
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER: Conservation Are Very bad Low	Stable No Mixed, multiple owners 1000484 dmonton N9 ea, 8 LBs	relationship be and improveme parkland and w Contact: Christ NEW ENTRY?: TREND:	ons continue towards improving the inter- tween the wider park and the historic cord ents are sought to the management of the vater bodies more generally. topher Laine 07780 545 979 No No significant change
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY:	TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER: Conservation Are Very bad Low Fore Street, Edm	Stable No Mixed, multiple owners 1000484 dmonton N9 ea, 8 LBs	relationship be and improveme parkland and w Contact: Christ NEW ENTRY?: TREND: CONTACT:	No No significant change Christine White (LPA) 020 8379 3852

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

GREENWICH



	SITE NAME:	Conduit Head, Hyde Vale SE10	The conduit head is a limestone drinking fountain, about
	DESIGNATION:	Listed Building grade II, CA	three feet square and nine feet tall. It may be older than the adjacent memorial cattle trough which is of granite and
	CONDITION:	Poor	dated 1877. The stone work was eroded and cracked and the original lantern missing. The stone work has recently
	OCCUPANCY:	N/A	been cleaned and restored and the lantern and taps
	PRIORITY CATEGORY:	C (C)	replaced. Funding has been provided by the Heritage of London Trust and by a Historic England Covid-19
	OWNER TYPE:	Local authority	Emergency Heritage at Risk Response Fund grant.
	LIST ENTRY NUMBER:	1031858	Contact: Conservation Team (LPA) 020 8921 5355

© Royal Borough of Greenwich




© Historic England

	SITE NAME:	Garden House to south east of Rush Grove House, Rush Grove Street SE18	an open loggia with round wooden arches set in trellis.		
	DESIGNATION:	Listed Building grade II, CA	Extensive loss of tiles from the roof has led to considerable water ingress. The building is suffering from a prolonged		
	CONDITION:	Very bad	lack of maintenance and is deteriorating rapidly.		
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	A (A)			
	OWNER TYPE:	Commercial company			
	LIST ENTRY NUMBER:	1289930	Contact: Conservation Team (LPA) 020 8921 5355		
	LIST EINTRT NOPIBER:	1289930	Contact: Conservation Team (LPA) 020 8921 5355		



© Royal Borough of Greenwich





	SITE NAME:	Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Large conservatory built in 1889 in a classical style, with domed glass roofs and surmounted by a figure of Mercury. The wider site has been sold for new educational use. The
	DESIGNATION:	Listed Building grade II	Local Authority is ensuring that urgent works are being carried out to improve the building's condition. Discussions
	CONDITION:	Poor	continue to secure the future management and use of the building.
	OCCUPANCY:	Occupied/in use	building.
and the second second	PRIORITY CATEGORY:	C (C)	
all the	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1079082	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England



	SITE NAME:	Lock and swing bridge, Broadwater Estate SE28	The Royal Arsenal Canal was built 1812-14 to bring supplies into the arsenal. The swing bridge was built circ
	DESIGNATION:	Listed Building grade II	1876 to carry railway tracks across the canal. Some work was carried out to the bridge in the early 1980s but since
	CONDITION:	Fair	then the lock and bridge have both lain derelict. Listed Building Consent has been granted for the first phase of
	OCCUPANCY:	N/A	conservation and repair works, which will include
and the	PRIORITY CATEGORY:	F (D)	repointing of brick and stonework, patch repairs, and removal of rust and graffiti.
1	OWNER TYPE:	Commercial company	-
	LIST ENTRY NUMBER:	1213695	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / GREENWICH

England	SITE NAME:	Garden House to north west of Charlton House, Charlton Road, Charlton SE7	Small red brick garden house with undercroft and high pyramidal swept roof, dating from the mid to late C17 and attributed to Inigo Jones. It was previously used as a public
	DESIGNATION:	Listed Building grade I, CA	lavatory, but is now vacant. A condition survey and heritage assessment commissioned by the Royal
	CONDITION:	Poor	Greenwich Heritage Trust is informing a programme of works to restore and re-use the building. Further enabling
	OCCUPANCY:	Vacant/not in use	and investigative works are being carried out, funded by
	PRIORITY CATEGORY:	F (F)	Historic England.
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1291892	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	95A, Eltham High Street, Eltham SE9	C17 or earlier stable building with three diagonal chimney shafts. Although the building has been made weathertight,
	DESIGNATION:	Listed Building grade II	it is showing signs of a lack of maintenance. It is currently in residential use.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ric England	LIST ENTRY NUMBER:	1219821	Contact: Conservation Team (LPA) 020 8921 5355

Railings, entrance gateway and lodge to the former Red SITE NAME: Forecourt railings and gates to Red Barracks, and Gate Lodge, Barracks (1858-60 but now demolished). Structural repairs and repointing to the small watch tower to the north were Frances Street, Woolwich SEI8 completed in 2013. The railings, piers, and gate piers are generally in good condition. The gate lodge is in very poor DESIGNATION: Listed Building grade II condition, although the Local Authority has removed CONDITION: Very bad debris and most of the vegetation threatening the building. OCCUPANCY: However, the main structure is derelict and continues to Vacant/not in use deteriorate. The Local Authority and Historic England are PRIORITY CATEGORY: A (A) in discussion regarding potential approaches to secure its repair and new use. OWNER TYPE: Local authority © Historic England LIST ENTRY NUMBER: 1358950 Contact: Conservation Team (LPA) 020 8921 5355

SITE NAME: 24-sided polygon, single storey building designed by John The Rotunda, Green Hill, Nash. Concave conoid roof. First erected in the grounds of Woolwich Common SEI8 Carlton House in 1814 for (premature) celebration of DESIGNATION: Listed Building grade II*, CA Allied victory in the Napoleonic Wars. The Rotunda housed the reserve collection of the 'Firepower' museum CONDITION: Very bad but is now vacant. The roof covering is leaking and there is OCCUPANCY: Vacant/not in use considerable concern about the condition of internal timbers. Urgent works are needed and investigations into PRIORITY CATEGORY: A (A) the roof structure are outstanding. Efforts are being made by the Local Authority and Historic England to secure OWNER TYPE: Government or agency these urgent repairs. LIST ENTRY NUMBER: 1078987 Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic E

© Histori

1	
x ·	
	THAT THE

24, Royal Hill, Greenwich SEI0 Early C18 small urban house of central chimneystack plan, SITE NAME the smallest known example of the 1703 Moxon Plan. The Listed Building grade II, CA, building has been vacant for some years and is in poor DESIGNATION: WHS condition. A scheme for restoration and conversion was agreed in 2011-2012 but, although works were started, CONDITION: Poor they were halted for some years. Following discussions OCCUPANCY: with the Local Authority and Historic England, the owner Vacant/not in use re-commenced internal works but this has been sporadic. PRIORITY CATEGORY: D (D) Progress is being monitored and discussions regarding the works programme are taking place with the owner. OWNER TYPE: Private LIST ENTRY NUMBER: 1391248 Contact: Conservation Team (LPA) 020 8921 5355

© Historic England

D

Е

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site WHS

SITE NAME:

DESIGNATION:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

CONDITION:

OWNER TYPE:

	SITE NAME:	Church of St Saviours, Middle Park Avenue, Eltham SE9	This vast church of purple brick and shallow concrete roofs was built in 1932 to the designs of Cachemaille-Day and is
	DESIGNATION:	Listed Place of Worship grade II	largely unaltered since then. The RIBA gold medal was awarded for the design in 1933. The vicarage was built in
	CONDITION:	Poor	1960. The church has always suffered from having internal rainwater pipes and from poor access for high-level
	PRIORITY CATEGORY:	A (A)	maintenance. Roof coverings were repaired in late C20 but
	OWNER TYPE:	Religious organisation	are now in need of renewal. Windows to the Lady Chapel are decayed and high-level plasterwork partially removed.
	LIST ENTRY NUMBER:	1212904	are decayed and high-level plasterwork partially removed. The church is seeking funding for emergency repairs and health and safety works.
			nearch and safety works.

© Photo © Stephen Craven (cc-bysa/2.0)



Roman Catholic Church of St This church in the Gothic style was completed by AW Peter, Woolwich New Road, Pugin in 1843. It is listed together with detached school buildings on the south side, completed a decade later by Woolwich SEI8 EW Pugin. The external masonry and roofing of the Listed Place of Worship grade II church, along with internal plastered ceilings, were repaired in 2017 with a grant from the National Lottery Heritage Poor Fund. The condition of the adjacent two-storey school C (C) buildings is poor; the upper hall is closed due to structural problems and roof leaks. The congregation is now seeking Religious organisation funding to repair the school buildings to bring them back into use. 1212426

Contact: lan Harper 020 7973 3786

Contact: lan Harper 020 7973 3786

© Historic England

SITE NAME:	Charlton Village SE7		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Conservation Team (LPA) 020 8921 5355
SITE NAME:	Thames Barrier and Bowater Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Unknown
VULNERABILITY:	High	CONTACT:	Rebecca Duncan (LPA) 0208 9215355
SITE NAME:	Westcombe Park, Greenwich SE3		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Conservation Team (LPA) 020 8921 5355
SITE NAME:	Woolwich Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Unknown
VULNERABILITY:	High	CONTACT:	Rebecca Duncan (LPA) 0208 9215355

HACKNEY



	SITE NAME:	98 and 98a, Clapton Common (also known as 1-4 Belz Terrace) E5	Rege entra nearl	
in the second	DESIGNATION:	Listed Building grade II, CA	childı a sch	
	CONDITION:	Very bad	work Perm repai comr and t	
	OCCUPANCY:	Vacant/not in use		
1	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation	again	
	LIST ENTRY NUMBER:	1226457	Cont	

ency stucco fronted villa of 1825 with central portico ance and pairs of curved bay windows, facing onto the by common. It was used as a home for destitute rén in C19 and converted into flats in 1928, becoming hool in about 1985. There are longstanding unlawful ks and the building suffered a fire in 2017. Planning nission and Listed Building Consent were granted for irs and extensions as a school in 2018, and works have menced. However, the building is still deteriorating, the Local Authority has since taken enforcement action nst the owner.

tact: Tim Walder (LPA) 020 8356 4813

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	SITE NAME:	175, Stoke Newington Church Street N16	Mid C18 two-storey building of brown brick with red brick dressings, cornice band and parapet, and sash windows,
	DESIGNATION:	Listed Building grade II, CA	with mid-late C19 projecting ground floor shop. The roof is leaking and there are structural issues in evidence, although
	CONDITION:	Poor	the building is propped in places. The building is generally in a very poor condition and there are areas of dry rot.
	OCCUPANCY:	Vacant/not in use	Planning Permission and Listed Building Consent were
	PRIORITY CATEGORY:	D (D)	granted in January 2020 for a scheme to repair the building and bring it back into use as a shop and office, with modest
	OWNER TYPE:	Private	extensions to the roof and rear. However, this has not been implemented.
gh of Hackney	LIST ENTRY NUMBER:	1235427	I
gilolillackney			Contact: Tim Walder (LPA) 020 8356 4813



DESIGN. CONDI	SITE NAME:	179, Stoke Newington Church Street N16	The western half of a mid C18 house, converted to shops in C19. The building, including an unusual C19 extension to
	DESIGNATION:	Listed Building grade II, CA	the rear side, was in use as a Chinese restaurant at ground floor level with staff accommodation above. Planning
	CONDITION:	Poor	Permission was granted for conversion and extension to the rear to form a shop and flats in 2018, but the scheme
	OCCUPANCY:	Vacant/not in use	has yet to be implemented. There are both structural and
	PRIORITY CATEGORY:	C (C)	asbestos issues. The building has been vacant for several years and is in poor condition.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1235521	Contact: Tim Walder (LPA) 020 8356 4813

Forecourt Wall, Gates and

Shepherd, Rookwood Road

Listed Building grade II

Religious organisation

NIĠ

Poor

N/A

C (New entry)

1235330

Railings to Church of the Good

Late C19 wall and railings with decorated square piers

by neighbouring trees. There is also evidence of

Contact: Tim Walder (LPA) 020 8356 4813

inappropriate previous repairs.

topped with obelisk finials associated with the church. The

wall is suffering from structural movement possibly caused

© Historic England

© London Borough



© Historic England



SITE NAME: Row of workshops built 1895-8 to the design of Reginald Cleeve Workshops, Calvert Minton Taylor of London County Council as part of the Avenue E2 Boundary Estate. All the workshops are in use and some DESIGNATION: Listed Building grade II, CA repair and security works have taken place. Following extensive pre-application discussions, Listed Building CONDITION: Fair Consent was granted in 2019 for the refurbishment of the OCCUPANCY: Occupied/in use workshops and the erection of additional workspace and toilets. This has not been completed. The Local Authority PRIORITY CATEGORY: D (D) is considering enforcement action against multiple incidences of unlawful works. OWNER TYPE: Private LIST ENTRY NUMBER: 1264906 Contact: Tim Walder (LPA) 020 8356 4813

© London Borough of Hackney



	SITE NAME:	7, Clapton Square E5	Early C19 terraced house. Listed Building Consent was granted for the restoration and conversion of the building to accommodate three flats. However the building has suffered from inappropriate and unauthorised works and the Local Authority took enforcement action. The	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use	property was sold in autumn 2019 and the new owner	
	PRIORITY CATEGORY:	F (C)	a list of enforcement works and conditions to progress.	
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	2264	Contact: Tim Walder (LPA) 020 8356 4813	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

use)

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

	SITE NAME:	St Columba's Vicarage and link to church, Kingsland Road E2	Gothic Revival vicarage built 1873-4 to the design of Jan Brooks. The vicarage forms part of a larger group of list
	DESIGNATION:	Listed Building grade I, CA	buildings by the same architect, including the church and Sisters' House. A condition survey was prepared in June
	CONDITION:	Poor	2017, and will help guide future repairs. Detailed discussions have taken place regarding a programme of roof and other high-level repairs, which led to the submission of an application for Listed Building Consent early 2020.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
England Archive	LIST ENTRY NUMBER:	1265658	Contact: Ian Harper 020 7973 3786

© Historic

SHOES

SITE NAME: 592		592, Kingsland Road E8	C18 terraced house with a shop on the ground floor and
ð 1	DESIGNATION:	Listed Building grade II, CA	vacant upper floors. Listed Building Consent was granted in 2008 and again in 2018 for rebuilding the upper parts of the
	CONDITION:	Poor	north and east wall following structural problems. These works were completed in March 2020. However, the roof
	OCCUPANCY:	Part occupied/part in use	is still in poor condition with signs of water ingress and
	PRIORITY CATEGORY:	C (D)	unlawful sub-divisions throughout the property, and the Local Authority is considering enforcement action.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226776	Contact: Tim Walder (LPA) 020 8356 4813

© London Borough of Hackney



© London Borough of Hackney

SITE NAME:	Portico to former London Orphan Asylum, Linscott Road E5	The remaining part of the London Orphan Asylum, circa 1823 by WS Inman. From 1882 the building was the Salvation Army Congress Hall. The rest of the building was
DESIGNATION:	Listed Building grade II	demolished in 1975 and the portico was derelict until 2003. The building now consists of an entrance portico with
CONDITION:	Fair	colonnades. Behind the entrance is a computer centre by Brady Mallalieu from 2005 on the site of the former chapel.
OCCUPANCY:	Part occupied/part in use	The building was associated with the nearby Clapton Girls
PRIORITY CATEGORY:	C (C)	Academy until 2017. Discussions are now taking place regarding its repair and conversion to a new use.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1265630	Contact: Tim Walder (LPA) 020 8356 4813

SITE NAME:	New Lansdowne Club, 195, Mare Street E8	Substantial detached house, dating from 1699. In April 2018 Planning Permission and Listed Building Consent were
DESIGNATION:	Listed Building grade II*, CA	granted, subject to a Section 106 agreement, to convert the house to offices, with enabling residential development
CONDITION:	Poor	to the rear. Listed Building Consent was also granted in 2018 for emergency repairs. Following a change of
OCCUPANCY:	Vacant/not in use	ownership, repairs to ensure the building is weathertight
PRIORITY CATEGORY:	E (E)	have taken place but planning conditions have not yet been discharged. The Local Authority is taking enforcement
OWNER TYPE:	Commercial company	action.
LIST ENTRY NUMBER:	1265590	Contact: Verena McCaig 020 7973 3718

© Historic England Archive



	SITE NAME:	Station, Millfields Road E5 for Hackney Bord condition followir	Disinfecting station built in 1900 by Gordon and Gunton for Hackney Borough Council. The building is in very poor
	DESIGNATION:		condition following years of water ingress. A number of surveys and reports have been undertaken in order to
	CONDITION:	Very bad	better understand the building's significance and condition. Asbestos and stored items have been cleared. An
L	OCCUPANCY:	Vacant/not in use application	application for emergency repairs and mothballing has been
	PRIORITY CATEGORY:	A (A)	approved and works will begin in winter 2021. The Local Authority is in discussions with internal and external
	OWNER TYPE:	Local authority	stakeholders regarding its restoration and to identify and secure a new use.
	LIST ENTRY NUMBER:	1253493	Contact: Tim Walder (LPA) 020 8356 4813

PRIORITY CATEGORIES

© London Borough of Hackney

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Air Raid Precaution Centre, Rossendale Street (east side) E5	Air raid shelter built in 1938. The building has previously suffered from flooding. Planning Permission and Listed
	DESIGNATION:	Listed Building grade II	Building Consent were granted in 2004 for the retention of the air raid shelter as a museum and the construction of
	CONDITION:	Fair	flats above. These works are largely complete and the flats occupied. However, the ownership of the Air Raid
	OCCUPANCY:	Vacant/not in use	Precaution Centre is uncertain, and the space is currently
	PRIORITY CATEGORY:	E (E)	used for storage.
	OWNER TYPE:	Local authority	
of Hackney	LIST ENTRY NUMBER:	1235876	Contact: Tim Walder (LPA) 020 8356 4813



© Historic England Archive

© London Borough of

SITE NAME:	Walls and gates to Bishopsgate Goods Station, Shoreditch High Street EI	Late C19 walls to the demolished goods station. The gates were repaired some years ago and are now in situ beneath the hoarding. The repair of the listed wall formed part of a	
DESIGNATION:	Listed Building grade II	large redevelopment proposal for the entire Bishopsgate Goodsyard site, which was approved by the Mayor of	
CONDITION:	Poor	London in 2020.	
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	D (C)		
OWNER TYPE:	Utility		
LIST ENTRY NUMBER:	1235316	Contact: Tim Walder (LPA) 020 8356 4813	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	ConditionListed Building grade IIDESIGNATION:PoorOCCUPANCY:N/APRIORITY CATEGORY:D (C)OWNER TYPE:Utility	

	SITE NAME:	187, Shoreditch High Street EI	Early C18 terraced house with an altered facade. The roof,
	DESIGNATION:	Listed Building grade II, CA	front elevation and windows have been restored and the building is now weathertight. A new shopfront has also
	CONDITION:	Fair	been fitted. The future use of the building forms part of a wider development scheme currently being implemented.
	OCCUPANCY:	Vacant/not in use	when development scheme currently being implemented.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1235320	Contact: Tim Walder (LPA) 020 8356 4813
© London Borough of Hackney			

1	SITE NAME:	Shrubland Road Evangelical Church, Shrubland Road E8	A rare and complete example of a temporary iron mission church built in 1858. The building is now clad in corrugated
A	DESIGNATION:	Listed Building grade II, CA	asbestos sheeting. The building is in use occasionally as a church. The property is currently advertised for sale.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (F)	
	OWNER TYPE:	Private	
storic England	LIST ENTRY NUMBER:	1245303	Contact: Tim Walder (LPA) 020 8356 4813

© Histo



© Historic England

	SITE NAME:	Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16	Gothic Revival cemetery chapel, dating from 1839. The chapel is situated in the centre of the early C19 cemetery. A first phase of repairs to the roof, spire and high-level
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	stonework was completed in 2017, with funding from Hackney Council and Historic England. The Local Authority has been awarded a Stage II pass from the National Lottery
	CONDITION:	Fair	Heritage Fund for a project to improve the cemetery landscape. This includes a second phase of repairs to the
N.	OCCUPANCY:	Part occupied/part in use	chapel including underpinning, enabling it to be used for
	PRIORITY CATEGORY:	F (F)	community uses and events. Works have started on site.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1265023	Contact: Tim Walder (LPA) 020 8356 4813

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

24	SITE NAME:	Haggerston Baths, Whiston Road E2	Public baths and swimming pool, dating from 1904. The building is vacant and in a state of disrepair. Following a
	DESIGNATION:	Listed Building grade II	competitive bidding process and public consultation, the Local Authority selected a developer in 2017 to repair the building and bring it back into use. Applications have been
	CONDITION:	Poor	submitted for Planning Permission and Listed Building
	OCCUPANCY:	Vacant/not in use	Consent for a scheme involving restoration and re-
Talan	PRIORITY CATEGORY:	C (C)	purposing as community space, workshops, café, gym other uses, with demolition of part of the building and
	OWNER TYPE:	Local authority	erection of a new six-storey office building. These applications are currently being assessed.
storic England	LIST ENTRY NUMBER:	1235838	Contact: Tim Walder (LPA) 020 8356 4813

The church was built in 1883-4 by Sir Arthur Blomfield in SITE NAME: Church of St Andrew, Bethune Road, Stoke Newington N16 the Early English style, using Kentish ragstone with Bath stone dressings. Although plain externally, the interior is DESIGNATION: Listed Place of Worship grade II* richly decorated. Two phases of repairs are complete, funded by the National Lottery Heritage Fund. The nave CONDITION: Poor and aisle roofs are repaired and also external masonry and PRIORITY CATEGORY: F (F) windows to clerestory and west wall. A third and final phase of roofing repair is required to the transepts and OWNER TYPE-Religious organisation chancel roofs and related masonry. LIST ENTRY NUMBER: 1264896 Contact: lan Harper 020 7973 3786

© Historic England

© Histo

	SITE NAME:	Church of St Chad, Dunloe Street, Hackney E2	Church by Victorian Gothicist architect James Brooks, completed in 1869 to provide for rapidly expanding but
1	DESIGNATION:	Listed Place of Worship grade I	poor suburbs. The adjacent vicarage dates from 1874. The church is high and lofty, with plain detailing in red brick and
6 6 AN	CONDITION: PRIORITY CATEGORY:	Poor	contrasting with Bath stone dressings under slated roofs. The vicarage, transept roofs and north nave brickwork
III UI		A (A)	were repaired in the late C20. More repairs are needed to
THE TA	OWNER TYPE:	Religious organisation	brickwork and rainwater goods, and the timber bellcot above the crossing is in urgent need of assessment and
A 2 Hours	LIST ENTRY NUMBER:	1265793	repair. The church is actively seeking funding.
			Contact: Ian Harper 020 7973 3786

© Historic England



SITE NAME: Christ Apostolic Church The Parish Church was built in the Gothic Revival style (formerly St Columba), in 1868-9 by James Brooks and the mortuary chapel was added in 1904-5 by E Geldart. It forms an enclosed Kingsland Road, Hackney E2 courtyard with the vicarage and Sisters' House, listed Listed Place of Worship grade I, separately. Construction is in red brick with Bath stone DESIGNATION: CA dressings. A drone survey has confirmed serious decay in the high-level lantern above the central tower and the CONDITION: Poor rainwater goods, and a drainage survey was funded in 2020 PRIORITY CATEGORY: by a Covid-19 Emergency Heritage at Risk Response Fund A (A) grant. The Diocese and the congregation are discussing OWNER TYPE: Religious organisation future management of the church and the site. LIST ENTRY NUMBER: 1226862 Contact: lan Harper 020 7973 3786

© Historic England



SITE NAME:	Church of St Thomas, Old Hill Street, Clapton Common N16	Only the crypt (c1777), the tower and belfry (1827) survived World War II bomb damage in December 1940.
Designation:	Listed Place of Worship grade II, CA	The church was re-opened in October 1958 to designs by NF Cachemaille-Day; he incorporated the apse from William Burges's remodelling in 1873 and the 1921 World
CONDITION:	Poor	War I memorial. The asphalt finish of the reinforced concrete roof slab has been much repaired over previous
PRIORITY CATEGORY:	A (A)	decades, raising concerns about the structural integrity of
OWNER TYPE:	Religious organisation	the roof. The congregation is seeking funding for a repair project and has commissioned a development appraisal.
LIST ENTRY NUMBER:	1265859	Contact: Ian Harper 020 7973 3786

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

ÍΙΑ WHS

Unitary Authority World Heritage Site

SITE NAME

SITE NAME:	Church of St John the Baptist, Pitfield Street, Hackney NI	St John the Baptist, a Commissioners' church funded under the 1818 Act, was completed in 1826 by Francis Edwards,
DESIGNATION:	Listed Place of Worship grade II*	a pupil of Sir John Soane. Built of stock bricks contained within limestone dressings under a slated roof, the spacious
CONDITION:	Poor	interior has galleries on three sides and a fine early C20 painted ceiling by J A Reeve. The tower and galleried
PRIORITY CATEGORY:	C (C)	cupola at the west end have structural problems due to t
OWNER TYPE:	Religious organisation	rusting of embedded cramps. These are causing jacking in the masonry above roof level, which needs to be
LIST ENTRY NUMBER:	1235285	addressed.
		Contact: Ian Harper 020 7973 3786

© Historic England

	SITE NAME:	Church of the Ark of the Covenant, Rookwood Road, Stoke Newington N16	The church, located at the north end of Clapton Common in Hackney, was designed by Joseph Morris and Sons for the Agapemonite Church and finished in 1895. Carvings on
1 117	DESIGNATION:	Listed Place of Worship grade II*	the west tower were by A G Walker, and the window glass was designed by Walter Crane. The building passed
	CONDITION:	Poor	to the Catholic Church 1956 -2007, and then to the Georgians. External elevations are in squared rubble
	PRIORITY CATEGORY:	A (New entry)	ragstone: at some time hard cement pointing has led to
	OWNER TYPE:	Religious organisation	stone decay. The plain clay roof tiles are slipping off causing plaster falls in the nave.
	LIST ENTRY NUMBER:	1235310	Contact: Ian Harper 020 7973 3786

Church of St Leonard,

Shoreditch High Street,

Built 1740 to the design of George Dance the Elder.

Constructed in brick with a Portland stone facade and

© Historic England



© Historic England Archive



		Shoreditch El	dressings, and slate roofs. The roofs to the north and south
	DESIGNATION:	Listed Place of Worship grade I, CA	aisles and the flat roofs either side of the tower have been repaired with funding from the National Lottery Heritage Fund and Historic England. The nave roof was re-slated in
	CONDITION:	Poor	2017 with funding from the Listed Places of Worship Roof Repair Fund. Repairs were completed in 2019 to the
	PRIORITY CATEGORY:	C (C)	tower, pediment, columns and portico roofs, and
	OWNER TYPE:	Religious organisation	temporary repairs were made to the spire, grant-aided by the National Lottery Heritage Fund.
	LIST ENTRY NUMBER:	1235382	Contact: Tracey Craig 020 7973 3756
MAX.	SITE NAME:	Old Church of St Mary, Stoke Newington Church Street, Stoke Newington N16	The old parish church of St Mary dates from 1563. It was restored in 1827-29 by Charles Barry who raised the nave roof on a clerestory, added the spire, and the outer north
	DESIGNATION:	Listed Place of Worship grade II*, CA	aisle which was then lost in WWII; the exposed soft brick of the north wall is now weathering badly. In 2017 the south aisle roof was repaired with a grant from the Listed
	CONDITION:	Poor	Places of Worship Roof Repair Fund. Further work is needed to repair floors, deal with dampness, and monitor
	PRIORITY CATEGORY:	A (A)	structural movement. In 2020 Historic England awarded a
Sec.	OWNER TYPE:	Religious organisation	Covid-19 Emergency Heritage at Risk Response Fund grant for repairs to the tower windows.
	LIST ENTRY NUMBER:	1235419	Contact: Ian Harper 020 7973 3786

The church was completed in 1851 to an innovative design SITE NAME: Church of St Matthias, Wordsworth Road, Stoke by William Butterfield in free Gothic style. Stock brick with Bath stone dressings. Repairs to the nave roof and Newington N16 rainwater goods were completed in May 2015 with funding DESIGNATION: Listed Place of Worship grade I from the National Lottery Heritage Fund and Historic England. Another phase of work is required to the aisle CONDITION: Poor roofs, as well as the roof, belfry louvers and masonry of the PRIORITY CATEGORY: C (C) tower. The church is seeking funding for project development and repair. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1265031 Contact: lan Harper 020 7973 3786

© Historic England

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HACKNEY / HAMMERSMITH AND FULHAM

	- And

SITE NAME:	Abney Park Cemetery N16	Laid out as an arboretum cemetery in 1840 from the
DESIGNATION:	Registered Park and Garden grade II, 18 LBs, part in CA	gardens of two C17 houses, Abney Park is one of London' most important Nonconformist cemeteries. Features of the historic designed landscape survive but are in poor
CONDITION:	Generally unsatisfactory with major localised problems	condition and, in places, illegible. A Development Board is using a Conservation Management Plan to guide future management and maintenance, and volunteers continue to
VULNERABILITY:	High	carry out improvements. A major restoration project
TREND:	Improving	developed by the Local Authority and partners, with grant funding from the National Lottery Heritage Fund and the
NEW ENTRY ?:	No	National Lottery Community Fund, is now underway.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1000789	Contact: Christopher Laine 07780 545 979

© Historic England

SITE NAME:	Mare Street, Hackney Central E8		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY: Low		CONTACT:	Matt Payne 020 8356 8106
SITE NAME:	Sun Street, City of London EC2		
SITE NAME: DESIGNATION:	Sun Street, City of London EC2 Conservation Area, LB grade II	NEW ENTRY?:	No
	•	NEW ENTRY?: TREND:	No Unknown
DESIGNATION:	Conservation Area, LB grade II		

HAMMERSMITH AND FULHAM

A. A. M.	SITE NAME:	Draped woman sculpture, North Verbena Gardens W6	Cast concrete sculpture, circa 1959 by Karel Vogel, situated in an open space off the Great West Road. It was
	DESIGNATION:	Listed Building grade II, CA	an early commission of the London County Council's Patronage of the Arts scheme, unusually commissioned
	CONDITION:	Poor	provide visual amenity in compensation for a major road scheme. The cast concrete is now cracking in many places,
	OCCUPANCY:	N/A	damaged by rusting structural iron elements, and past
Life Bries	PRIORITY CATEGORY:	C (C)	repairs are both unsightly and failing. A condition surve has been carried out, funded by local amenity groups.
	OWNER TYPE:	Local authority	Funding is now being sought to undertake further investigations prior to planning for full repair.
toric England	LIST ENTRY NUMBER:	43 422	Contact: Adam O'Neill (LPA) 020 8753 3318

© Histo



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER

© Historic England



SITE NAME:	Number 2 Gasholder, Former Fulham Gas Works, Imperial Road SW6	Gasholder dating from 1830, and considered to be the oldest surviving gasholder in the world. It consists of a single lift wrought iron holder, with cast iron guide
DESIGNATION:	Listed Building grade II*, CA	standards in tripod form and wrought iron framework. The Gas Works site has been decommissioned. Outline
CONDITION:	Very bad	Planning Permission for redevelopment has been obtained, with a \$106 Agreement to secure protective and
OCCUPANCY:	N/A	investigatory works. Preliminary works are underway, and
PRIORITY CATEGORY:	C (C)	the results will help inform the future restoration and re- purposing of the gasholder on site in consultation with the
OWNER TYPE:	Commercial company	developer, Local Authority and Historic England.
LIST ENTRY NUMBER:	1261959	Contact: Verena McCaig 020 7973 3718

Single-storey octagonal brick building with a slate roof, circa 1869, probably by George Saunders, built to provide temporary resting places for bodies prior to burial. The rainwater goods are inadequate and failing, leading to deterioration of stone dressings, brickwork and mortars. The Friends of Margravine Cemetery funded a costed condition survey. The Local Authority has commissioned consultants to oversee repair and conservation works, and is working with the Friends of Margravine Cemetery and Historic England to identify appropriate funding sources.

Contact: Adam O'Neill (LPA) 020 8753 3318

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Reception House, Hammersmith Cemetery,

Poor

N/A

A (A)

1436663

Local authority

Margravine Road W6

Listed Building grade II, CA

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIO	NS

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG

SM

ΪA WHS

Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HAMMERSMITH AND FULHAM

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Harwath Mausoleum, St

Thomas Of Canterbury

Listed Building grade II, CA

Circular garden building,

Hammersmith Road

Vacant/not in use

Listed Building grade II

boundary wall and railings, formerly to St Paul's School,

Churchyard SW6

C (New entry)

Unknown

1463196

Very bad

 Λ (Λ)

1392791

F

Poor

N/A

	SITE NAME:	Refreshment Room, Ravenscourt Park W6	Former stable block of C18 Ravenscourt Park House, partially demolished and converted into a refreshment
	DESIGNATION:	Listed Building grade II, CA	room late C19. Recently used as a park tea room, it has been vacant since the end of 2019. The roof is failing,
	CONDITION:	Poor	exacerbated by heritage crime and subsequent water ingress, and needs replacement, along with rainwater
	OCCUPANCY:	Vacant/not in use	goods. One floor is inaccessible owing to previous layout
	PRIORITY CATEGORY:	C (C)	interventions. The Local Authority is exploring options to fund repairs and return the building back to long-term
	OWNER TYPE:	Local authority	viable use. Urgent works to make the building watertight are due to start summer 2021, subject to consents.
Hammersmith and	LIST ENTRY NUMBER:	1358588	Contact: Adam O'Neill (LPA) 020 8753 3318

© London Borough of Ha Fulham



© Historic England

			Contact: Adam O Nelli (LFA) 020 8755 5516
たい	SITE NAME:	Tomb of Abraham Smith, Hammersmith Cemetery, Margravine Road W6	White marble monument with a tall, enriched cross surmounting a rubble-carved base circa 1923, by CJ Jordan & Son, Acton, dedicated to a gold prospector. A carved
	DESIGNATION:	Listed Building grade II, CA	vignette on the cross depicts a gold prospector in a shelter. The surface of the marble is suffering considerable decay
	CONDITION:	Poor	and soiling, leading to a loss of detail, and the monument is also leaning significantly. A full condition survey has been
	OCCUPANCY:	N/A	undertaken to inform future repair works and advice
	PRIORITY CATEGORY:	C (C)	sought from a structural engineer. The Local Authority, Historic England and Friends of Margravine Cemetery are
	OWNER TYPE:	Unknown	exploring funding options.
	LIST ENTRY NUMBER:	1072616	Contact: Adam O'Neill (LPA) 020 8753 3318



© London Borough of Hammersmith and Fulham



© London Borough of Hammersmith a Fulham



-33	TRIORITI CATEGORI.	A (A)			
and	OWNER TYPE:	Local authority			
	LIST ENTRY NUMBER:	1079820	Contact: Adam O'Neill (LPA) 020 8753 3318		
e	SITE NAME:	Former Hope and Anchor public house, 20 Macbeth Street, Hammersmith W6	Public house in neo-Georgian style dating from 1936. Built for Truman's as part of a housing estate. The building is an unusual survival with two exceptionally intact 1930s bar		
17	DESIGNATION:	Listed Building grade II, CA	interiors. The public house business closed in 2012. The ground floor is used for occasional filming and the upper		
-	CONDITION:	Good	floors are occupied and in residential use. Original external signage and some internal ironmongery in the bar areas		
-	OCCUPANCY:	Part occupied/part in use	have been removed.		
	PRIORITY CATEGORY:	E (E)			
	OWNER TYPE:	Private			

© Historic England

Contact: Adam O'Neill (LPA) 020 8753 3318

Neoclassical stone mausoleum dating from 1918 with

interior designer who assisted in the design of the Eiffel Tower and interiors of RMS Titanic and RMS Olympic. It

was built by Simon Harwath, a Slovenian immigrant who

helped manage their businesses. The decorative ceiling and plaques are damaged, likely from water ingress through the

Circular red brick building and boundary wall, with railings

Paul's School, 1881-85 by Alfred Waterhouse, now part of St Paul's Open Space. The building is disused and subject to

Authority commissioned a condition survey for the building and will be seeking consents for its repair and future re-use

for garden storage. Conservation repairs to the adjacent wall following damage from a car collision are complete.

and terracotta finials to brick piers, all formerly part of St

vandalism, with missing roof tiles and damp. The Local

became a West End hotelier, for his wife Mathilde who

roof. Further investigation is required to determine an

Contact: Adam O'Neill (LPA) 020 8753 3318

Repairs to the railings are being investigated.

appropriate conservation approach.

elaborate exterior and intact interior fittings. It was designed by Arthur Henry Durand FRIBA, architect and

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

LIST ENTRY NUMBER:

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA

WHS

- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA

Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HAMMERSMITH AND FULHAM

	SITE NAME:	Tomb of Frederick Harold Young, Hammersmith Cemetery, Margravine Road W6	Mausoleum dating from 1884. The parapet to the west elevation is missing and there is some broken and missing glass. There are structural defects to the floor. The Local Authority has commissioned a structural report and architectural commutants to prepare a fully detailed
	DESIGNATION:	Listed Building grade II, CA	architectural consultants to prepare a fully detailed schedule of repairs and conservation works, with funding
	CONDITION:	Very bad	from Historic England. The Local Authority is also working with the Friends of Margravine Cemetery and Historic
	OCCUPANCY:	N/A	England to identify appropriate funding sources to enable
and the second states of	PRIORITY CATEGORY:	A (A)	full repair and conservation works to be carried out.
) Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1072617	Contact: Adam O'Neill (LPA) 020 8753 3318
1-1-1	SITE NAME:	Tomb of Samuel Jones, Queen Caroline Street, St Paul's Churchyard W6	Table tomb over a brick and stone plinth dating from the end of the C18. There is evidence of severe mechanical damage and erosion as well as rusting of the remaining
	DESIGNATION:	Listed Building grade II, CA	railings. Invasive vegetation and dumped rubbish continue to be a problem. The Local Authority, Historic England and
	CONDITION:	Very bad	the church are in discussion to agree a suitable project that will secure the repair of the monument and improve its
	OCCUPANCY:	N/A	setting.
	PRIORITY CATEGORY:	A (A)	
D Historic England	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1246022	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Ashlar Court, Former Royal Masonic Hospital Nurses' Home, Ravenscourt Gardens W6	Nurses' home, 1938, by Burnet, Tait and Lorne. Works for conversion to residential use have been completed and the building is now occupied. Outstanding conditions attached to the Listed Building Consent, including the display of
	DESIGNATION:	Listed Building grade II, CA	artefacts, are yet to be discharged.
	CONDITION:	Good	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1269052	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Former Royal Masonic Hospital, Ravenscourt Park, Hammersmith W6	Hospital, 1933, by Thomas Tait, funded by the Freemasons. The building has been vacant since the closure of the NHS facility in 2006. Walls within the landscaped
	DESIGNATION:	Listed Building grade II*, CA	garden were demolished in anticipation of implementation of an approved scheme, but works then stalled. The
I amount	CONDITION:	Fair	building is currently mothballed whilst a suitable scheme fo its repair and re-use is awaited.
Contraction of the second	OCCUPANCY:	Vacant/not in use	is repair and re-use is awaited.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
Historic England	LIST ENTRY NUMBER:	1192740	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Church of St John, North End Road, Walham Green SW6	Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles
	DESIGNATION:	Listed Place of Worship grade II, CA	were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the
	CONDITION:	Poor	Listed Places of Worship Roof Repair Fund. The church interior and electrics remain in poor condition and a new
	PRIORITY CATEGORY:	C (C)	drainage system is required. Work is due to commence
1 and an	OWNER TYPE:	Religious organisation	summer 2021 on a first phase replacing and upgrading of al the hoppers, overflows and downpipes serving the nave
	LIST ENTRY NUMBER:	1079751	and aisle roofs.
) Historic England			Contact: Tracey Craig 020 7973 3756

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HAMMERSMITH AND FULHAM / HARINGEY



Church of St Stephen the Martyr and St Thomas, Uxbridge Road, Shepherd's Bush WI2 Listed Place of Worship grade II, CA Poor C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1261971

Built in 1850, designed by Antony Salvin. The spire was removed following war damage and the tower is now surmounted with a low octagonal fleche. Roofs and rainwater goods are in poor condition resulting in water ingress. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant towards re-roofing the north aisle roof along with overhauling of associated rainwater goods, and repair of rafter feet and gutter linings. Work is currently on site and due to complete summer 2021.

© Historic England

Contact: Tracey Craig 020 7973 3756

SITE NAME:	St Mary's, Kensal Green NW10		
DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Adam O'Neill (LPA) 020 8753 3318

HARINGEY

•			
	SITE NAME:	37, North Road N6	Early C19 house of two storeys and basement, part of two
	DESIGNATION:	Listed Building grade II, CA	pairs linked by recessed porches. The building is built of red brick, with cement detailing including pilaster strips,
	CONDITION:	Poor	entablature and cornice. The condition of the property is deteriorating. The Local Authority is considering options to
	OCCUPANCY:	Unknown	secure the full repair of the building.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	893	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© London Borough of Haringey

	SITE NAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N10	Entertainment complex including exhibition halls and theatre, built 1868-75. From 1935 part of Alexandra Palace
	DESIGNATION:	Listed Building grade II, part in RPG grade II, CA	was leased to the BBC. Urgent repairs to the loggia on the south terrace (western end) and south east roofs were completed in 2013. Repairs to the eastern part of the
	CONDITION:	Poor	building, including the theatre, were completed in 2018, with funding from Haringey Council and the National Lottery Heritage Fund, and the theatre is now open to th
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	public. Works are progressing on the east court and north yard and discussions are ongoing regarding other parts of
	OWNER TYPE:	Charity (heritage)	the building.
	LIST ENTRY NUMBER:	1268256	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© Historic England

© Historic England

			× ,
SITE NAME: Hornsey Town Ha N8	Hornsey Town Hall, Broadway N8	Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important	
	DESIGNATION:	Listed Building grade II*, CA	influence in subsequent British town hall design. The building is in a poor condition, particularly the Assembly
T	CONDITION:	Poor	Hall to the rear. The Local Authority has agreed to transfer ownership to Far East Consortium International Ltd. This
and the second	OCCUPANCY:	Part occupied/part in use	includes an agreement to guarantee continued public
-	PRIORITY CATEGORY:	F (F)	access to, and use of, parts of the building. The town hall will also accommodate a hotel, with new residential
	OWNER TYPE:	Local authority	development to the rear. Work has started on site.
	LIST ENTRY NUMBER:	1263688	Contact: Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Public toilets, Bruce Grove, Tottenham N17	Public toilet circa 1920, with fine external ironwork. The building is currently empty. Some works to secure the
TENT	DESIGNATION:	Listed Building grade II, CA	building have been carried out and the ironwork has been restored. The Local Authority commissioned a structural
	CONDITION:	Poor	survey in 2018 and has secured funding for repair and renovation of the building. Discussions with all relevant
	OCCUPANCY:	Vacant/not in use	parties are underway and work is progressing on
	PRIORITY CATEGORY:	D (C)	discharging the conditions in respect of the approved Planning and Listed Building Consent applications prio
	OWNER TYPE:	Local authority	work to refurbish the toilets as a community arts cafe, expected to start in summer 2021.
gh of Haringey	LIST ENTRY NUMBER:	1259316	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

	SITE NAME:	7, Bruce Grove, Tottenham NI7	One of a pair of early C19 houses. The building is vacant and has suffered substantial internal collapse. A scheme of
	DESIGNATION:	Listed Building grade II, CA	refurbishment and conversion to flats has been approved. A proposal to amend the approved scheme in order to
	CONDITION:	Very bad	optimise the configuration of the second and top floors is under discussion. The building was sold to a new owner in
- 5	OCCUPANCY:	Vacant/not in use	2020. The Council has recently (May 2021) taken
	PRIORITY CATEGORY:	B (B)	enforcement action to obtain access and carry out a condition survey.
	OWNER TYPE:	Commercial company	
Haringey	LIST ENTRY NUMBER:	1 1 8 8 6 0 5	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© London Borough of ⊢

© London Borough



© London Borough of Haringey

© Historic England

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17	C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as the brickwork is
DESIGNATION:	Listed Building grade II, CA	deteriorating. An initial programme of repairs has been undertaken, but further works are needed.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1294666	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

662, High Road, Tottenham

Listed Building grade II, CA

Vacant/not in use

Commercial company

NI7

Fair

F (F)

1358832

Early C18 building of three storeys, in stock brick with stone coped parapet, lower than the neighbouring properties with which it has group value. The building was badly fire damaged during the 2011 riots. The upper floors and roof of the building have been renovated and repaired. Listed Building Consent was granted in 2019 for renovations to the ground floor of the building with restoration of the shop frontage, and works are due to start on site.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

511	n'u'		1
-			
		- m	

4

© London Borough of Haringey	© London	Borough	of Haringey
------------------------------	----------	---------	-------------

2	SITE NAME:	810, High Road, Tottenham N17	Fine house built circa 1715 as part of a symmetrical pair. Planning Permission and Listed Building Consent have bee
	DESIGNATION:	Listed Building grade II*, CA	granted for the refurbishment and re-use of the building a part of Tottenham Hotspur Football Club's wider
	CONDITION:	Fair	redevelopment proposals. Work has not yet started.
	OCCUPANCY:	Vacant/not in use	
ł	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1358835	Contact: Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

LIST ENTRY NUMBER:



	SITE NAME:	Retaining wall along Highgate Hill (The Bank), Highgate Hill, Highgate N6	Early C19 retaining wall along Highgate Hill between the street pavement and higher paved walk. Some repairs were carried out in 2010/11. Temporary measures were
	DESIGNATION:	Listed Building grade II, CA	implemented in January 2018 to safeguard the wall and the Local Authority is undertaking investigations to identify an
	CONDITION:	Poor	appropriate permanent solution.
	OCCUPANCY:	N/A	
H	PRIORITY CATEGORY:	D (D)	
4	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079237	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© London Borough of Haringey



© London Borough of Haringey

	LIST EINTRE NOT DER.	1079237	Contact: Elisabetta Tonazzi (LFA) 020 6469 4497
	SITE NAME:	South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17	Red brick wall of probable early C17 date in Flemish bond, with tall sloped coping and plinth. The wall is ramped gently up at intervals towards the west. It is now seriously
	DESIGNATION:	Listed Building grade II, CA	deteriorating with open decayed pointing, loose and unstable brickwork, previous re-pointing damage, and
	CONDITION:	Poor	extensive ivy/creeper and frost damage. A programme of urgent repairs has been undertaken, but further repairs are
	OCCUPANCY:	N/A	required.
34	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079218	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



© London Borough of Haringey



PRIORITY CATEGORY: F (F) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1079222 Contact: Elisabetta Tonazzi (LPA) 020 8489 4497 SITE NAME: The Art Workers Guild background of the three architects Church of St Augustine, involved in this late C19 church is very apparent. JF Sedding Archway Road, Hornsey N6 started the work, was succeeded by his pupil Henry Listed Place of Worship grade II, Wilson (west nave and Lady Chapel) and Harold Gibbons, DESIGNATION: CA who in 1916 completed the Arts and Crafts facade with its Calvary. The London stock brickwork is dressed in Bath CONDITION: Fair stone and red brick under a plain tiled roof. Internal fittings F (F) PRIORITY CATEGORY: are of a high quality. The tower roof was repaired in 2017 and the Calvary Statuary in 2018, with grants from the OWNER TYPE: Religious organisation

Porters and Walters

Wood Green N22

Occupied/in use

Poor

1358860

Almshouses, St Leonard's

Listed Building grade II, CA

Almshouses, Nightingale Road,

© Historic England



	SITE NAME:	Parish Church of All Hallows, Church Lane, Tottenham N17	This medieval church incorporates a C14 tower with C18 battlements. The north aisle was rebuilt in 1855. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	chancel, east end extensions and raised clerestories were by William Butterfield in 1875-7. In 2017 the roofs and valley gutters were repaired with a grant from the Listed
	CONDITION:	Poor	Places of Worship Roof Repair Fund. Much C14 and C15 architectural fabric survives internally but is suffering from
	PRIORITY CATEGORY:	C (C)	the effects of dampness and requires repair and
	OWNER TYPE:	Religious organisation	conservation. In 2020 Historic England awarded a Covid- 19 Emergency Heritage at Risk Response Fund grant for
2	LIST ENTRY NUMBER:	1188633	repairs to the vestry roof.

Contact: lan Harper 020 7973 3786

Contact: lan Harper 020 7973 3786

Four two-storey almshouses, circa 1904, which form a

the boundary wall in 2018. Listed Building Consent has

been granted for partial demolition and rebuilding, and

National Lottery Heritage Fund. There remain repairs to

work is in progress.

roofs and gutters.

group with a commemorative stone and front railings. The buildings have suffered from a lack of proper maintenance

over a number of years and there was a partial collapse of

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HARINGEY / HARROW

	SITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The former Tottenham Palace Theatre was built in 1908 by Wylson Long as a variety theatre. The building is now in use for worship. It is suffering from water ingress, which is
	DESIGNATION:	Listed Place of Worship grade II, CA	causing significant damage to both the structure and interior plaster work. Some repairs were carried out to the front roofs in 2015, but considerable further work is
The second se	CONDITION:	Very bad	required. Discussions between the Local Authority and the congregation are ongoing to secure necessary urgent
	PRIORITY CATEGORY:	A (A)	works.
	OWNER TYPE: Relig	Religious organisation	
Historic England	LIST ENTRY NUMBER:	1249660	Contact: Ian Harper 020 7973 3786

SITE NAME:	Bruce Grove N17		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Clyde Circus N15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Hornsey Water Works and Filter Beds, Hornsey	N8	
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	North Tottenham High Road N17		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Scotland Green N17		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497

HARROW

6 7

© I



SITE NAME:	Interview Station, High Street HA3 INATION: Listed Building grade II DITION: Fair	Former police station with magistrates' court, later part library and then entirely a police station. Built in 1908-9 by Dixon Butler in Free Tudor style. The building has been empty since 2015 and is currently boarded up and secure
DESIGNATION:		
CONDITION:		after illegal entry by squatters in 2016. Applications were refused in 2016 and 2017 for a proposed new use with
OCCUPANCY:		extensions and new buildings, and an appeal was dismisse
PRIORITY CATEGORY:	D (A)	in 2018. A new application for reuse of the building was approved in 2019 and applications to clear the conditions
OWNER TYPE:	Private	attached to this were submitted in early 2020 and are under consideration.
LIST ENTRY NUMBER:	1245418	Contact: Lucy Haile (LPA) 020 8736 6101

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDO	on and south east	/ HARROW	
100	SITE NAME:	Former White Hart Hotel, High Street, Edgware HA8	C17 three storey stuccoed building with a hipped tile roof and wooden eaves cornice. It is no longer in use as a public
-	DESIGNATION:	Listed Building grade II	house or as a restaurant but is closed and out of use. The upper floors are in a poor condition after unauthorised
	CONDITION:	Poor	works and there are holes in the walls and ceilings. A new
	OCCUPANCY:	Vacant/not in use	leaseholder took over in 2020. More extensive unauthorised works were carried out in parts of the
	PRIORITY CATEGORY:	C (C)	building during Covid-19 Lockdown. The Local Planning Authority halted these and is carrying out enforcement
The second	OWNER TYPE:	Commercial company	action.
© Historic England	LIST ENTRY NUMBER:	1079726	Contact: Lucy Haile (LPA) 020 8736 6101
0			
	SITE NAME:	Kenton Lane Farmhouse, Kenton Lane HA3	Two-storey former farmhouse built circa 1808, to the designs of William Loudon and Robert Abraham in Flemish
	DESIGNATION:	Listed Building grade II	bond red brick with a hipped slate roof. Listed Building Consent and Planning Permission were approved in 2013
	CONDITION:	Poor	for repairs and conversion to residential, linked to an adjacent housing scheme. Whilst the new homes have
At the set of the set of the	OCCUPANCY:	Vacant/not in use	been built, works to the listed buildings have not been
Constantine Marine - 100 M	PRIORITY CATEGORY:	D (D)	carried out. The house and farm buildings were damaged by illegal entry in early 2019 but the site is now secure and
	OWNER TYPE:	Commercial company	discussions are ongoing between the Local Authority and
© Historic England	LIST ENTRY NUMBER:	1253950	the owner regarding the scheme. Contact: Lucy Haile (LPA) 020 8736 6101
-			Contact. Eucy Maile (ELA) 020 0750 0101
-	SITE NAME:	Kenton Lane former farm buildings, Kenton Lane HA3	Former farm buildings built circa 1808, to designs of William Loudon and Robert Abraham in colour washed
	DESIGNATION:	Listed Building grade II	Flemish bond brick. The vacant buildings surround three sides of a designed courtyard. Listed Building Consent and
	CONDITION:	Poor	Planning Permission were approved in 2013 for conversion to residential, linked to an adjacent housing scheme. Whilst
	OCCUPANCY:	Vacant/not in use	the new homes have been built, works to the listed
LANG- T	PRIORITY CATEGORY:	D (D)	buildings have not been carried out. The buildings were damaged by illegal entry in 2019 but the site is now secure
the state of the second	OWNER TYPE:	Commercial company	and discussions are ongoing between the Local Authority
© Historic England	LIST ENTRY NUMBER:	1253952	and the owner regarding the scheme. Contact: Lucy Haile (LPA) 020 8736 6101
-			Contact. Eucy Maile (ELA) 020 0750 0101
	SITE NAME:	Old Pye House, West Street, HAI 3EL	The CI5 two-storey building was part of a larger hall building. It has a slate roof, timber framed walls and gable
	DESIGNATION:	Listed Building grade II, CA	ends with a central tie beam, and a plain kingpost. The south front is C18 or early C19 red brick. Unoccupied and
	CONDITION:	Poor	in poor condition the original first floor was removed when
	OCCUPANCY:	Vacant/not in use	it was used as a plastics factory. Internal scaffolding has now been installed, a modern extension and yew tree have
A CONTRACTOR	PRIORITY CATEGORY:	A (A)	been removed, and the ground level lowered inside the building. Discussions about proposals, including external
	OWNER TYPE:	Private	scaffolding, are taking place between the owner and the
© Historic England	LIST ENTRY NUMBER:	1358651	Local Authority. Contact: Lucy Haile (LPA) 020 8736 6101
1	SITE NAME:	South Lodge to Grim's Dyke Hotel, Old Redding HA3	South lodge to Grim's Dyke Hotel. The hotel was originally designed as a private residence in 1870-72, by Richard Norman Shaw for the artist Frederick Goodall and
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	subsequently owned by WS Gilbert (Gilbert and Sullivan). The lodge is of two stories with red brick walls, tile-hung
	CONDITION:	Very bad	gables, stone dressings and a prominent chimney stack. The building was severely damaged by a fire in April 2020, but
	OCCUPANCY:	Vacant/not in use	parts remain including some of the external walls and the
	PRIORITY CATEGORY:	D (A)	chimney. Planning and Listed Building applications have been submitted for its full restoration and urgent repairs
Olender Person to (11)	OWNER TYPE:	Local authority	are in progress (May 2021).
© London Borough of Harrow	LIST ENTRY NUMBER:	1193943	Contact: Lucy Haile (LPA) 020 8736 6101

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Wall to west and north of Springbok House, Wood Lane	C19 wall, 11 foot high, with stone copings, recessed in the centre to pass through the porte-cochere. The wall forms a
	DESIGNATION:	Listed Building grade II, CA	curved forecourt and screening to Springbok House, no the Hussaini Shia Islamic Centre. A leaning section of the
	CONDITION:	Poor	wall was deemed a dangerous structure by the Local Authority and was taken down in 2018 for safety reasons.
	OCCUPANCY:	N/A	The wall has temporary protective hoarding and scaffolding in place whilst discussions continue with the owner on its
	PRIORITY CATEGORY:	C (C)	in place whilst discussions continue with the owner on i reinstatement and funding of the work.
and the second second second	OWNER TYPE:	Charity (non-heritage)	
© London Borough of Harrow	LIST ENTRY NUMBER:	358673	Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow

	SITE NAME:	Brick Kiln to south east of the Kiln, Common Road, Stanmore	Lower part of a C18 brick kiln conical chimney, of which the upper part no longer exists. In urgent need of structura	
	DESIGNATION:	Listed Building grade II	stabilisation and repair.	
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1079710	Contact: Lucy Haile (LPA) 020 8736 6101	



© London Borough of Harrow







	SITE NAME:	Pinner Park Farmhouse, George V Avenue, Pinner	The building dates from circa 1750. It is two storeys with three bays plus hipped wing. The windows to the main
	DESIGNATION:	Listed Building grade II	house are altered. The building appears in good condition externally but the interior requires attention. There has
	CONDITION:	Poor	been some damage from water penetration and the building is partly vacant. Listed Building Consent was
	OCCUPANCY:	Part occupied/part in use	approved in 2018 to replace an existing steel beam and
	PRIORITY CATEGORY:	C (C)	repair the central valley gutter and in 2019 this work was completed.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079715	Contact: Lucy Haile (LPA) 020 8736 6101

	SITE NAME:	Garden wall to Bernays Gardens, Old Church Lane, Stanmore	C19 wall with buttresses. Many of the bricks are significantly decayed and the wall is in need of repointing. The Local Authority has obtained Listed Building Consent
	DESIGNATION:	Listed Building grade II, CA	for works to repair the wall and is investigating funding options.
	CONDITION:	Poor	
35112	OCCUPANCY:	N/A	
9 Same	PRIORITY CATEGORY:	D (D)	
10	OWNER TYPE:	Local authority	
arrow	LIST ENTRY NUMBER:	1079749	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Boundary wall fronting road from Nos 118-128, Stanmore Hill (east side), Stanmore	C18 brick wall with buttresses with chamfered bases. Many bricks at the base have weathered away and parts require repointing. The Local Authority is discussing repairs with
The second	DESIGNATION:	Listed Building grade II, CA	the owners.
ALL T	CONDITION:	Poor	

© London Borough of Harrow

Contact: Lucy Haile (LPA) 020 8736 6101

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

N/A

C (C)

Private

1194205

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDO	on and south east	/ HARROW		
	SITE NAME:	Boundary wall fronting road (Wellington House), Stanmore Hill (West Side), Stanmore	This brick wall originates from the C18 or early C19. 10 foot high, built of red brick with chamfered pilaste buttresses. Many sections of the wall have weathered and parts require repointing. Listed Building Consent	
	DESIGNATION:	Listed Building grade II, CA		for repairs to part of the wall and these
	CONDITION:	Poor	were completed in 2018. A suitable scheme for the remaining section is awaited.	
	OCCUPANCY:	N/A		
A COMPANY OF THE OWNER OWNER OF THE OWNER	PRIORITY CATEGORY:	GORY: C (C)		
	OWNER TYPE:	Private, multiple owners		
© Historic England	LIST ENTRY NUMBER:	1079648	Contact: Lucy Haile (LPA) 020 8736 6101	
•. T T	SITE NAME:	The Rayners public house, 23, Village Way East	internal plan forr	red 1930s public house retaining its n and original fittings. Listed Building
-	DESIGNATION:	Listed Building grade II	Consent was gra of the building. T	Inted for the repair, renovation and re-use hese works have largely been
	CONDITION:	Good	implemented an	d the building is now in educational use. horised signage and some alterations to
	OCCUPANCY:	Occupied/in use	the interior still r	
- 1 sain / -	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Private		
© London Borough of Harrow	LIST ENTRY NUMBER:	3923 0	Contact: Lucy H	aile (LPA) 020 8736 6101
	SITE NAME:	Old Stanmore Church, Church Road, Stanmore	was built in 1632, attributed to Nicholas Stone. The was heads have exposed brickwork allowing rainwater ingre	
	DESIGNATION:	Listed Place of Worship grade II*, CA		
ALTER	CONDITION:	Poor		
THE REAL PROPERTY OF	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation		
© Historic England	LIST ENTRY NUMBER:	1079747		
SITE NAME:	Grim's Ditch: sec	tion extending 1500yds (1370m) r	orth east from O	khey Lane
DESIGNATION:		nent, part in RPG grade II, part in	LIST ENTRY NUMBER:	1002044
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growt	h	NEW ENTRY ?:	No
OWNER TYPE:	Local authority, n	nultiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: sec	tion north of Blythwood House		
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1002007
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growt	h	NEW ENTRY ?:	No
OWNER TYPE:	Local authority		CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Linear earthwork	s in Pear Wood, west of Watling	Street	
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1001996
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Stable

OWNER	TYPE

PRIORITY CATEGORIES

PRINCIPAL VULNERABILITY:

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

D

Е

use).

Scrub/tree growth

Local authority

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

No

NEW ENTRY ?:

CONTACT:

ABBREVIATIONS

Elizabeth Whitbourn 07889 808145

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HARROW / HAVERING

DESIGNATION:

CONDITION:

VULNERABILITY:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

TREND:

SITE NAME:	Pinner deer park, Pinner Park Farm		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1019135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: four linear sections between Uxbridg	e Road and Oxhey	⁷ Lane
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY ?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
A MAN	SITE NAME: Bentley Priory		arged and improved in the late C18. Sir

Registered Park and Garden

Generally satisfactory but with

significant localised problems

Mixed, multiple owners

grade II, LB grade II*

Medium

1001440

Stable

No



© Historic England

HAVERING

	SITE NAME:	The Rom Skatepark	Built in 1978, The Rom Skatepark was designed by Adrian
	DESIGNATION:	Listed Building grade II	Rolt of G-Force and in 2014 became the first skatepark in England to receive national listed status. Following a fire in
	CONDITION:	Poor	2018 the park lost its (unlisted) indoor facilities which ultimately led to its closure in September 2019. The park
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	OCCUPANCY:	Vacant/not in use	currently has little income and requires concrete and
The state	PRIORITY CATEGORY:	C (New entry)	drainage repairs.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1419328	Contact: Azizul Karim (LPA) 01708 433 100

© London Borough of Havering



© London Borough of Havering

C16 and later garden walls to Ockendon Hall (now demolished). These extensive walls are slowly deteriorating SITE NAME: Garden walls to former North Ockendon Hall, Church Lane, North Ockendon although the owners are making efforts to prevent further damage from vegetation. DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1300500

Uvedale Price and William Gilpin influenced the design in

the mansion from 1936, which played a central role in World War II, now converted to a museum with

residential units, and new housing in the grounds. The

have been restored, but boundary treatment, views and

the character of the lake in land owned and managed by

the Local Authority, much of it a Site of Special Scientific

Interest, remain issues to be resolved.

Contact: Christopher Laine 07780 545 979

the early C19. Royal Air Force Fighter Command occupied

Italian gardens and pleasure grounds around of the mansion

Contact: Azizul Karim (LPA) 01708 433 100

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ÍΙΑ

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Outbuilding to the rear of The Old Anchor, Harwood Hall Lane	C19 timber-framed outbuildings which continue the line of the rear wing of The Old Anchor, a C18 timber-framed house. The building is currently used as a workshop. It is in
	DESIGNATION:	Listed Building grade II, CA	need of roof and brickwork repairs, new rainwater goods, and renewal of the timber lintels. The Local Authority and
	CONDITION:	Very bad	Historic England are monitoring the condition of the building and have discussed essential repairs with the
	OCCUPANCY:	Part occupied/part in use	owner.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	07989	Contact: Azizul Karim (LPA) 01708 433 100
	SITE NAME:	High House Farmhouse, Ockendon Road	Three-storey house of brick and timber frame circa 1700 with an older timber-framed wing. The timber frame to the
Sultan.	DESIGNATION:	Listed Building grade II*, CA	three-storey section is under stress, the porch is propped by scaffold and there is significant water damage from the
	CONDITION:	Very bad	roof. A number of the rooms are uninhabitable. Much of
	OCCUPANCY:	Part occupied/part in use	the extensive vegetation growth on the exterior of the building has been removed and some surveys have been
	PRIORITY CATEGORY:	A (A)	carried out but the building requires urgent repairs to
	OWNER TYPE:	Private	prevent further decay and possible localised collapse. The Local Authority and Historic England are continuing
11	LIST ENTRY NUMBER:	1079867	discussions with the owners.
© Historic England	LIST ENTRY NORBER.	10/7007	Contact: Verena McCaig 020 7973 3718
A	SITE NAME:	Two brick barns and garden walls to south of Bretons House, Rainham Road, Hornchurch	Two Tudor barns set around a cobbled courtyard close to the CI6 garden walls, all associated with Bretons House. One barn is watertight and in partial use although deteriorating, with some earlier unsympathetic alterations
Mk 2	DESIGNATION:	Listed Building grade II	and additions. The other barn is in need of extensive repair, particularly to the roof and walls, and suffers from
WET THE THE	CONDITION:	Very bad	vandalism. The garden walls are also in need of extensive
	OCCUPANCY:	Part occupied/part in use	repair and protection, with areas of collapse. A Conservation Statement has been prepared for these
	PRIORITY CATEGORY:	A (A)	assets and plans for the wider site are being developed. However, immediate repairs are required.
© London Borough of Havering	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1300053	Contact: Azizul Karim (LPA) 01708 433 100
+	SITE NAME:	Upminster Windmill, St Mary's Lane, Upminster	Smock mill 1803, retaining original machinery. The Friends of Upminster Windmill, in conjunction with the Local
	DESIGNATION:	Listed Building grade II*	Authority, have been awarded a grant from the National Lottery Heritage Fund. The project includes the full
	CONDITION:	Fair	restoration of the mill, and the provision of a workshop
	OCCUPANCY:	Vacant/not in use	and visitors' centre on the site. Restoration works are near completion on the windmill and the sails are operational. It
	PRIORITY CATEGORY:	F (F)	is due to open to the public in spring 2022.
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1079878	Contact: Verena McCaig 020 7973 3718
100	SITE NAME:	Garden walls at Cranham Hall, The Chase, Cranham	CI6 walls to an earlier house on the site of Cranham Hall. The wall is in need of extensive repairs. Previous localised
	DESIGNATION:	Listed Building grade II, CA	repairs are inappropriate and uncontrolled tree and other
A CHEMINE	CONDITION:	Very bad	plant growth is causing further damage and deterioration.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1183600	Contact: Azizul Karim (LPA) 01708 433 100

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

4A	SITE NAME:	Mill Cottage, The Dell, High Street, Hornchurch	Single storey timber-framed range, now one dwelling, dating from the C17. The building is in very bad condition
11	DESIGNATION:	Listed Building grade II, CA	and continuing to deteriorate. The roof has undergone extensive temporary repair but continues to present major
M.V.	CONDITION:	Very bad	maintenance problems.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
-Aller	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079898	Contact: Azizul Karim (LPA) 01708 433 100

	SITE NAME:	Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s
	DESIGNATION:	Listed Building grade II	for Sir James Esdaile, Lord Mayor of London 1777-78. Erection of fencing on the bridge has seriously damaged t
	CONDITION:	Very bad	structure. Extensive vegetation growth is further threatening its stability. Some structural repairs have been
	OCCUPANCY:	N/A	carried out in the past but further works are urgently
	PRIORITY CATEGORY:	A (A)	required.
SUP SAME X	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1323729	Contact: Azizul Karim (LPA) 01708 433 100

SITE NAME:	Dagnam Park Farm moated site, Noak Hill, Romfo	ord	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001988
CONDITION: Generally satisfactory but with minor localised problems		TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romford		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Planning Service (LPA) 01708 433100

HILLINGDON

© MRDA

© Historic England

-	SITE NAME:	Wall and gate piers at St Martin's churchyard entrance, Church Road, Hillingdon UB7	Restored C16 red brick churchyard entrance wall and gate piers, with wrought iron gates, at St Martin's Church. Lower parts of C16 red brick, with the upper part rebuilt
© Historic England	LIST ENTRY NUMBER:	1376634	Contact: Mark Butler (LPA) 020 7361 2465
A CALLER OF THE REAL OF THE RE	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	A (A)	
	OCCUPANCY:	N/A	collapsed.
	CONDITION:	Very bad	granary re-uses a C18 six-panel door and has a queen strut roof with clasped purlins. The southern granary has now
Allin Ja	DESIGNATION:	Listed Building grade II	roofs. These are examples of a once-common agricultural building type in Middlesex, but now rare. The northern
A A A A A A A A A A A A A A A A A A A	SITE NAME:	Granaries at Knightscote Farm, Harefield UB9	A pair of early to mid C19 weatherboarded granaries, each with timber frames, standing on staddle stones, with tiled

Charles A	The second	
	The second second	
		1 1
s Parish Church		S.al
		A REAL PROPERTY.
生命 四	a have b	

	SITE NAME:	Wall and gate piers at St Martin's churchyard entrance, Church Road, Hillingdon UB7	Restored C16 red brick churchyard entrance wall and gate piers, with wrought iron gates, at St Martin's Church. Lower parts of C16 red brick, with the upper part rebuilt	
	DESIGNATION:	Listed Building grade II, CA	probably in the C19. A survey of the churchyard walls ha been carried out, with funding from Historic England, and	
	CONDITION:	Poor	funding will be sought to enable the necessary repair works to be carried out.	
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (New entry)		
The second	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1080275	Contact: Mark Butler (LPA) 01895 558196	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	SITE NAME:	Wall running south from the Old Gatehouse west along Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have beer repaired, but the quality is varied and much of the
-	DESIGNATION:	Listed Building grade II*, CA	remainder is in poor condition. A condition assessment been prepared, with funding from Historic England, and
	CONDITION:	Poor	discussions are underway with the owners of the wall regarding the necessary repairs.
	OCCUPANCY:	N/A	regarding the necessary repairs.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ngland	LIST ENTRY NUMBER:	1358326	Contact: Elizabeth Whitbourn 07889 808145

	SITE NAME:	Walls around St Martin's churchyard, north side, Church Road, Hillingdon UB7	Red brick boundary and retaining wall for St Martin's churchyard. C16 red brick walls, with tall sloped coping, along the east and north sides of the churchyard and the
	DESIGNATION:	Listed Building grade II*, CA	northern part of the west side. At the south end of the east side there is a square pier with stone cornice and ball
	CONDITION:	Very bad	finials. A survey of the churchyard walls has been carried out, with funding from Historic England, and funding will be
ken ja	OCCUPANCY:	N/A	sought to enable the necessary repair works to be carried
WE	PRIORITY CATEGORY:	A (C)	out.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1286366	Contact: Elizabeth Whitbourn 07889 808145

Walls around St Martin's

Listed Building grade II, CA

Road, Hillingdon UB7

Religious organisation

Very bad

N/A

A (C)

1080276

Poor

N/A

C (C)

churchyard, south side, Church

Lych gate to south of Church of St Mary, Church Walk, Hayes

Listed Building grade II, CA

Religious organisation



© Historic England

© Historic England

© Historia





© Historic England



	LIST ENTRY NUMBER:	1080234	Contact: Mark Butler (LPA) 01895 558196
	SITE NAME:	Barn to the west of Weekly House, Bath Road, Harmondsworth	Late C17 or early C18 weatherboarded barn with tiled roof and Queen post truss at the west end. Weekly House, the boundary wall and the barn form a group. The
	DESIGNATION:	Listed Building grade II, CA	barn is in a dilapidated state.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
A DECK	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1286544	Contact: Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

© London Borough of Hillingdon

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Red brick boundary and retaining wall along the south part

churchyard. Lower parts of C16 red brick, with the upper

churchyard walls has been carried out, with funding from Historic England, and funding will be sought to enable the

Circa C16 timber lych gate with tiled roof. The timber

supports and base are in a very poor state of repair and tiles are slipping from the roof. No repairs are planned.

of the west side and the south side of St Martin's

part rebuilt probably in the CI9. A survey of the

necessary repair works to be carried out.

Contact: Mark Butler (LPA) 01895 558196

Conservation Area Listed Building CA

- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

48




© London Borough of Hillingdon

	SITE NAME:	Former King Henry public house and stables, 456, Bath Road, Longford	Converted to a house, the rear of the building is the former King Henry public house. The front part of the property has been rebuilt, using old material, after a fire. All
いたの	DESIGNATION:	Listed Building grade II	the walls have exposed timber framing with brick filling and tiled roofs. The adjacent stables are also of interest with an
	CONDITION:	Poor	early diamond mullioned window. The buildings are in poor condition, but have been secured by the owner. They have
	OCCUPANCY:	Vacant/not in use	been included in larger development proposals.
1	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080296	Contact: Mark Butler (LPA) 01895 558196

XX	SITE NAME:	Enterprise House, Blyth Road, Hayes	1912 factory building by the Trussed Concrete Steel Company for HMV. It has an unusual design with a high-
	DESIGNATION:	Listed Building grade II, CA	level water tank and is an important local landmark. The building is partially occupied but in a deteriorating
	CONDITION:	Poor	condition. Proposals for conversion to residential use have now been agreed but not yet been implemented.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
lillingdon	LIST ENTRY NUMBER:	1244861	Contact: Mark Butler (LPA) 01895 558196

© London Borough of Hill



	SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield	C17 red brick garden walls in need of extensive repairs. Some works have already been undertaken to a good standard. Planning Permission and Listed Building Consent
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	applications were approved in 2021 for work which will include repairs to the walls.
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
A south and the	PRIORITY CATEGORY:	B (B)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080272	Contact: Mark Butler (LPA) 01895 558196



	SITE NAME:	Wall in front of numbers 30 to 36 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
	DESIGNATION:	Listed Building grade II, CA	remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and
	CONDITION:	Poor	discussions are underway with the owners of the wall regarding the necessary repairs.
	OCCUPANCY:	N/A	regarding the necessary repairs.
200	PRIORITY CATEGORY:	C (C)	
A A	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080277	Contact: Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D


Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



	SITE NAME:	Walls in front of numbers 52-58 (even) and along west end of property, Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has
	DESIGNATION:	Listed Building grade II, CA	been prepared, with funding from Historic England, and discussions are underway with the owners of the wall regarding the necessary repairs.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1286348	Contact: Mark Butler (LPA) 01895 558196

	SITE NAME:	Walls to east and south of garden of number 28 (Coombe House), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has
	DESIGNATION:	Listed Building grade II*, CA	been prepared, with funding from Historic England, and discussions are underway with the owners of the wall
and the second s	CONDITION:	Poor	regarding the necessary repairs.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193014	Contact: Elizabeth Whitbourn 07889 808145

- Ch		Cinema, RAF Uxbridge, Grays Road, Uxbridge	Designed in 1918, the building has a large auditorium use historically as a lecture hall, cinema or concert hall. It was converted to a gymnasium in the 1960s. The building is vacant and in poor condition. The slate roof of the main hall was repaired in 2020 and its condition is being monitored. The Local Authority is considering options fo re-use.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© London Borough of Hillingdon	LIST ENTRY NUMBER:	1392376	Contact: Mark Butler (LPA) 01895 558196



	SITE NAME:	World War II Bofors gun tower and ancillary building, Ruislip HA4	1940s reinforced concrete gun tower platform with red brick infill walls and external access stair. The associated ancillary building is also brick with a flat reinforced concrete
	DESIGNATION:	Listed Building grade II	roof. It has previously been used as storage for the adjacent football ground. The structure is not weathertight,
	CONDITION:	Very bad	and the openings and rear roof require securing and rep There is severe vegetation growth on the ancillary building
TP	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1414202	Contact: Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

SITE NAME:	The Dower House, 393, High Street, Harlington	Two-storey house with C18 brick front to an older timber- framed structure, with large rebuilt C16 chimney. The
DESIGNATION:	Listed Building grade II	house is four bays wide, built of brown brick with red bric quoins and window dressings. The building suffered sever
CONDITION:	Very bad	fire damage in May 2011. In May 2018 the Council took enforcement action to ensure that the building was made
OCCUPANCY:	Vacant/not in use	wind and weathertight, and it has a temporary roof. The house was sold in 2020 and initial pre-application discussions have taken place with the Council regarding it
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	repair and future uses.
LIST ENTRY NUMBER:	1080196	Contact: Mark Butler (LPA) 01895 558196
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Street, HarlingtonDESIGNATION:Listed Building grade IICONDITION:Very badOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Private




SITE NAME:	Harefield Park (annexe to Harefield Hospital), Hill End Road, Harefield	The site comprises the main building and two flanking stable buildings of early C18 date. The house is vacant and in very poor condition, with no use identified. The building
DESIGNATION:	Listed Building grade II*, CA	is propped and a temporary roof is in place. A condition survey has been prepared to inform repairs.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	DRY: A (A)	
OWNER TYPE:	Health authority	
LIST ENTRY NUMBER:	1080177	Contact: Elizabeth Whitbourn 07889 808145

© London Borough of Hillingdon



© London Borough of Hillingdon



	SITE NAME:	The stable block, south east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	One of two stable buildings of early C18 date. The stable building is currently being used in the short-term for clinical storage and staff accommodation. A long-term use needs to be identified.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1358396	Contact: Mark Butler (LPA) 01895 558196



1	SITE NAME:	Nurses Home in grounds of Hillingdon Hospital, Pield Heath Road, Hillingdon	Early C19 house in the grounds of Hillingdon Hospital, currently used as offices, but generally in poor condition.
4	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
Hillingdon	LIST ENTRY NUMBER:	1080153	Contact: Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

© London Borough of H

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

use).

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site



	SITE NAME:	Harefield Grove, Rickmansworth Road, Harefield	Probably early C19 country house of three storeys. Stucco with stone cornice and parapet concealing a fairly low
FEF IN W	DESIGNATION:	Listed Building grade II	pitched hipped slate roof. The building has a two-storey modern courtyard wing for office use with an atrium link. I
	CONDITION:	Fair	has been vacant for a number of years and is deteriorating. Listed Building Consent and Planning Permission have been
	OCCUPANCY:	Vacant/not in use	granted for residential use but work has not yet started.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© Antonio Cruz, Comer Homes Group	LIST ENTRY NUMBER:	8 48	Contact: Mark Butler (LPA) 01895 558196



© London Borough of Hillingdon

A CONTRACTOR	SITE NAME:	Mount Vernon Hospital, Rickmansworth Road, Northwood	1902-4 by FL Wheeler in Edwardian Free Style. Built as a hospital for the treatment of tuberculosis patients, and as a branch hospital of the original Mount Vernon hospital in
-	DESIGNATION:	Listed Building grade II	Hampstead (built 1879-80). The building is noted for its advanced plan, including isolation wards and facilities such
	CONDITION:	Poor	as an X-ray room and dental unit. It is still in use by the hospital, but in a poor state of repair and under pressure
	OCCUPANCY:	Occupied/in use	from the redevelopment of the site.
	PRIORITY CATEGORY:	C (C)	
300	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1080083	Contact: Mark Butler (LPA) 01895 558196



Brick vaulted cellars to Cranford House circa 1722 SITE NAME: Cellars of former Cranford House, Roseville Road, (demolished). The cellars are suffering from structural weakening and their condition is deteriorating. The Cranford National Lottery Heritage Fund awarded the Local DESIGNATION: Listed Building grade II, CA Authority a grant under the Parks for People programme which included funds towards repair of the cellars. Public CONDITION: Poor consultations were undertaken in 2019 to discuss future OCCUPANCY: uses for the site and Planning Permission and Listed Vacant/not in use Building Consent applications were approved in 2020. PRIORITY CATEGORY: D (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1285115 Contact: Mark Butler (LPA) 01895 558196

SITE NAME: Stables to Cranford House circa 1720, owned and Cranford House Stables, managed by the London Borough of Hillingdon. The east Roseville Road, Cranford block is in very poor condition and the site is in need of a DESIGNATION: Listed Building grade II, CA long-term use. The National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for CONDITION: Very bad People programme which included funds towards repair of OCCUPANCY: Vacant/not in use the stables. Public consultations were undertaken in 2019 to discuss future uses for the site and Planning Permission PRIORITY CATEGORY: B (A) and Listed Building Consent applications were approved in 2020. OWNER TYPE: Local authority LIST ENTRY NUMBER: 1080157 Contact: Mark Butler (LPA) 01895 558196

© Historic England

© Historic England



D

Е

© London Borough of Hillingdon

SITE NAME:	Benlow Works, Silverdale Road, Hayes	Orchestrelle Factory of 1909-11. Reinforced concrete frame, with brick exterior. Four storeys with a 19-bay
DESIGNATION:	Listed Building grade II	elevation. The entrance bay has a semi-circular stepped brick architrave to the doorway and segmental arched
CONDITION:	Very bad	metal casements flanked by rusticated pilasters slightly set forward and breaking the parapet. Temporary repairs have
OCCUPANCY:	Part occupied/part in use	been undertaken so that the building is weathertight.
PRIORITY CATEGORY:	C (C)	Discussions have been held with the owner, but no solution is agreed for future use as yet.
OWNER TYPE:	Private	, , , , , , , , , , , , , , , , , , ,
LIST ENTRY NUMBER:	1080121	Contact: Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

WHS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
 - Unitary Authority World Heritage Site



© London Borough of Hillingdon

SITE NAME:	Gatehouse at Hillingdon- Uxbridge Cemetery, Uxbridge Road	Mid-C19 gatehouse by Benjamin Ferry, with an adjacent stock brick boundary wall. The gatehouse is constructed of rubble with stone dressings, tiled roof and five bays with a
DESIGNATION:	Listed Building grade II	wide central entrance under the arch. It is in a deteriorating condition and vacant, and the wall has partially collapsed. A
CONDITION:	Poor condition survey has been completed and	condition survey has been completed and the extent of repairs required agreed, but not yet implemented.
OCCUPANCY:	Vacant/not in use	repairs required agreed, but not yet implemented.
PRIORITY CATEGORY	· D (D)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1358415	Contact: Mark Butler (LPA) 01895 558196



© London Borough of Hillingdon

	SITE NAME:	Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge	Two barns dating from the C16, both now collapsed. Historic timbers have been salvaged for re-use. Listed Building Consent and Planning Permission have been
	DESIGNATION:	Listed Building grade II	granted for a residential scheme incorporating re-use of the salvaged timbers. The barns are being re-erected on site
	CONDITION:	Very bad	with work due to complete in late 2021.
	OCCUPANCY:	Vacant/not in use	
S.C.	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1284866	Contact: Mark Butler (LPA) 01895 558196



© Historic England



SITE NAME:	Church of St Mary, High Street, Harmondsworth	St Mary's has fabric from the CI2 to the CI6 including a fine CI2 stone doorway. It has a tall square tower cI500
DESIGNATION:	Listed Place of Worship grade II*, CA	on top of which is a cupola and weathervane supported or four cast iron columns. The church is largely constructed ir flint with stone dressings and the upper stages of the towe
CONDITION:	Fair	are in brick. The roofs are tiled. Much of the dressed st including quoins and the copings to the battlemented parapet, has been refaced in a cementitious render. The
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	refacings are failing in places exposing the substructure. There is cracking around the western end, particularly
LIST ENTRY NUMBER:	1080201	severe in the tower.
		Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Church of St John, Royal Lane, Hillingdon	C13 chancel arch and C14 nave and aisles. Tower rebuilt 1629. In 1848 Sir G Gilbert Scott refurbished the building
	DESIGNATION:	Listed Place of Worship grade II*, CA	and added transepts and chancel. The tower is surmounted by a wooden cupola which is in poor condition with decay, splits and unsympathetic past repairs. Clay tiles are
	CONDITION:	Poor	beginning to fail, valley gutters are poor and patched and, rainwater goods are also in need of attention. The flint walling has some loss of pointing. In 2020 Historic England
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for a timber survey of the cupola and also some
	LIST ENTRY NUMBER:	1080160	stabilisation works.
			Contact: Tracey Craig 020 7973 3756

© Alex Veal

SITE NAME:	Moated site, west bank of River Pinn, near Ickenham (1/2 mile (800m) north west of church)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002001
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Park Pale, Ruislip		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021402
CONDITION:	TION: Generally satisfactory but with significant localised TREND: problems		Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Manor Farm moat, Ickenham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002006
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Bulls Bridge, Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Cranford Park, Cranford		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Harmondsworth Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	Northwood Town Centre, Green Lane, Northwoo	bd	
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


SITE NAME:	Old Uxbridge/ Windsor Street, Uxbridge		
DESIGNATION:	Conservation Area, 43 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mark Butler (LPA) 01895 558196
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 01895 558196

HOUNSLOW



	SITE NAME:	21, Chiswick High Road W4	Stucco fronted early C19 three storey house which has
	DESIGNATION:	Listed Building grade II	been empty for some time. It is in a state of considerable disrepair. Planning Permission and Listed Building Consent
	CONDITION:	Poor	for its repair and extension were refused in 2016. Discussions are on-going between the owner, Local
	OCCUPANCY:	CUPANCY: Vacant/not in use Authority and H	Authority and Historic England to identify a suitable
	PRIORITY CATEGORY: C (C)		scheme.
OWNER TYPE: Private		Private	
	LIST ENTRY NUMBER:	189230	Contact: Sean Doran (LPA) 020 8583 4941

© London Borough of Hounslow





SITE NAME: C18 brick wall and gateway, with impost bands, iron gate Kitchen garden wall, including and carved wooden door. Reputedly built by Princess carved door and wrought iron gate, Gunnersbury Park, Amelia out of the profits from gambling. A large section of the wall is evidently unstable and requires extensive repair, Gunnersbury Avenue W3 and other sections also require repair and vegetation Listed Building grade II, RPG removal. Funding is being sought to enable repairs to be DESIGNATION: grade II*, CA undertaken to the western section to allow this area to be used. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority, multiple owners

Contact: Sean Doran LPA 020 8583 4941

OWNER TYPE:	SITE NAME:	Pair of chapels at Isleworth Cemetery, Park Road	Pair of cemetery chapels with central porte cochère built in 1879. They were last used for a service in 1970 and
	DESIGNATION:	Listed Building grade II	subsequently used as a council store and suffered considerable dereliction. Hounslow Men's Shed have
	CONDITION:	Poor	secured a lease on the chapels and carried out preliminary works to enable their use for workshops, along with the
	OCCUPANCY:	Occupied/in use	nearby mortuary buildings. Works have also been carried
	PRIORITY CATEGORY:	F (F)	out to conserve and protect the windows and minor repairs are on-going but high-level stonework still requires
	OWNER TYPE:	Local authority	repair, and the group are seeking funding to carry these out.
	LIST ENTRY NUMBER:	1272433	Contact: Sean Doran (LPA) 020 8583 4941

© Historic England

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

LIST ENTRY NUMBER:

1080336

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

WHS

- Conservation Area Listed Building CA
- LB LPA
 - Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument
- SM ŬA

Unitary Authority World Heritage Site

	SITE NAME:	Westlink House, Great West Road	Modernistic factory building built in 1928 by Wallis, Gilbert and partners. It is one of a number of factories from this
	DESIGNATION:	Listed Building grade II	period that line the Great West Road. The building has been empty for several years. The Local Authority is
	CONDITION:	Fair	addressing unauthorised works with the owners.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
ondon Borough of Hounslow	LIST ENTRY NUMBER:	1255218	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	The Keep (Armoury) to Hounslow Cavalry Barracks, Beavers Lane, Hounslow	Built in 1875, consisting of three storeys with four storey staircase towers at each end and in the centre of the south west front. Many windows retain heavy cast iron shutters
	DESIGNATION:	Listed Building grade II, CA	with firing loops and massive bolts to the interior. The building has been unused for some years and the top
	CONDITION:	Very bad	storeys are now inaccessible. This is as a result of rainwate
	OCCUPANCY:	Vacant/not in use	penetration from the rooftop parapet and blockages in the flat roof drainage rainwater pipes. There are currently no
	PRIORITY CATEGORY:	C (C)	specific plans for repairs, but discussions are continuing concerning the future of the wider site.
	OWNER TYPE:	Government or agency	concerning the luttice of the wider site.
istoric England	LIST ENTRY NUMBER:	1240633	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	Boston Manor House, Boston Manor Park, Boston Manor Road	Built in 1623 for Lady Mary Reade, extended in the 1670s and with later additions. Major works are in progress to conserve the building and increase access, funded by
	DESIGNATION:	Listed Building grade I, CA	Historic England, the National Lottery Heritage Fund and others. It is planned that the building will reopen to the
	CONDITION:	Fair	public in 2022.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
The second s	OWNER TYPE:	Local authority	
listoric England	LIST ENTRY NUMBER:	1079603	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Feltham House, Elmwood Avenue, Feltham	Built in the mid-C18 in stock brick and modelled on other Palladian villas, extended in the late C18 with the addition
	DESIGNATION:	Listed Building grade II, CA	of side wings. The interior has been modernised but retain C18 decorations of interest, which may partly be
	CONDITION:	Very bad	attributable to James Wyatt who lived at Hanworth. The
	OCCUPANCY:	Vacant/not in use	building has been unused for some years, and there is extensive rot damage in the principal storey and rainwater
	PRIORITY CATEGORY:	A (A)	penetration. Some ceilings have collapsed and extensive repairs are required. Discussions are pending to secure its
	OWNER TYPE:	Government or agency	repair and re-use as part of plans for the wider site.
listoric England	LIST ENTRY NUMBER:	1189466	Contact: Sean Doran (LPA) 020 8583 4941
NY AVALANTIN'I ANDREA		A 1	
	SITE NAME:	Archway near east entrance lodge, Gunnersbury Park, Gunnersbury Avenue W3	Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park. Urgent repairs to secure the structural stability of the arch
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	were undertaken in 2012, grant-aided by Historic England. Vegetation clearance has been undertaken by volunteers but repairs are still required. The future of this structure is
	DESIGNATION:		Vegetation clearance has been undertaken by voluntee

© Historic England

	Gunnersbury Avenue W3	Urgent repairs to secure the structural stability of the ar
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	were undertaken in 2012, grant-aided by Historic Engla Vegetation clearance has been undertaken by volunteer but repairs are still required. The future of this structure
CONDITION:	Poor	being considered as part of studies evaluating future use for the Small Mansion.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1080332	Contact: Sean Doran (LPA) 020 8583 4941

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

2	SITE NAME:	Boundary wall at Gunnersbury Park, Gunnersbury Avenue W3	Part of the boundary wall to the garden of the original Gunnersbury House, built 1658-63 by John Webb for Sir
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	John Maynard. Repairs have been carried out to a large section with funding from the National Lottery Heritage Fund. Further extensive sections require repair.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
The Property of the	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Community interest group	
© Historic England	LIST ENTRY NUMBER:	322060	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	East Lodge to Gunnersbury Park, Gunnersbury Avenue W3	Entrance lodge circa 1837. All that remains are small sections of the south and west elevations. Urgent repairs to
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance has been undertaken by
	CONDITION:	Very bad	volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating
	OCCUPANCY:	N/A	future uses for the Small Mansion.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1080334	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue W3	Stable block dating from 1835, on the eastern edge of Gunnersbury Park. The building has suffered considerable
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	dereliction. The Local Authority, Historic England, Gunnersbury 2026 Community Investment Company and other key stakeholders secured significant funding, including
1.1.0000	CONDITION:	Very bad	from Highways England and Historic England. This was used to undertake extensive investigative works and urgent
	OCCUPANCY:	Vacant/not in use	repairs and is now being used to replace the roof to make
	PRIORITY CATEGORY:	F (C)	it watertight. A feasibility study has tested potential future viable and sustainable uses, with further public consultation
	OWNER TYPE:	Local authority	planned.
© Historic England	LIST ENTRY NUMBER:	1358316	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Gothic Boathouse, Gunnersbury Park, Gunnersbury Avenue	Mid-C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	funded by Historic England. Extensive further repairs are required and a new use needs to be secured. Discussions are continuing between stakeholders in order to set out
	CONDITION:	Very bad	timescales for a future project, and potential new funding
	OCCUPANCY:	Vacant/not in use	sources are being explored.
	PRIORITY CATEGORY:	C (C)	
D Historic England	OWNER TYPE:	Community interest group	
		· · · ·	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LOINDO	DIVAND SOOTHEAST	/ HOONSLOW		
	SITE NAME:	The Small Mansion - Gunnersbury House, Gunnersbury Park, Gunnersbury Avenue W3	Built circa 1802, the smaller of the two houses on the site of Gunnersbury House which was demolished circa 1801. The house has been deteriorating rapidly. The Local Authority, Historic England, Gunnersbury 2026	
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Community Investment Company and other key stakeholders secured significant funding, including from Highways England and Historic England. This was used to	
	CONDITION:	Very bad	undertake extensive surveys and investigations and is now being used to repair the roof, balustrades and rainwater	
	OCCUPANCY:	Vacant/not in use	goods. A feasibility study has tested potential future viable	
© Historic England	PRIORITY CATEGORY:	F (A)	and sustainable uses, with public consultation planned.	
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1080330	Contact: Sean Doran (LPA) 020 8583 4941	
*	SITE NAME:	West Lodge to Gunnersbury Park, Gunnersbury Avenue	Lodge building dating from 1875 in the manner of a gatehouse, located at the south entrance to the park, partly in residential use. Historic England awarded a grant	
	DESIGNATION:	Listed Building grade II, RPG grade II*	towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway. The Local Authority is	
	CONDITION:	Poor	considering options for its full repair and re-use.	
	OCCUPANCY:	Part occupied/part in use		
The second secon	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority		
© Historic England	LIST ENTRY NUMBER:	1389619	Contact: Sean Doran (LPA) 020 8583 4941	
	SITE NAME:	West stable block in Gunnersbury Park, Gunnersbury Avenue W3	Early C19 stables situated within Gunnersbury Park. We to stabilise and repair the shell of the building were completed in 2014. The Local Authority, Historic Engla	
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Gunnersbury 2026 Community Investment Company and other key stakeholders secured significant funding, including from Highways England and Historic England, which has	
	CONDITION:	Poor	been used to undertake extensive surveys and investigative works. A feasibility study has been undertaken to test	
	OCCUPANCY:	Vacant/not in use	potential future viable and sustainable uses, with further	
	PRIORITY CATEGORY:	C (C)	public consultation planned.	
© Historic England	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1096950	Contact: Sean Doran (LPA) 020 8583 4941	
and the second		Columnation Character (Community)	Former C15 church tower, with nave dating from 1764 by	
	SITE NAME:	St Lawrence's Church (former), High Street, Brentford	Thomas Hardwick and later Victorian additions. The	
	DESIGNATION:	Listed Building grade II*, CA	building has been empty since the 1960s and stripped of its fittings. Extensive stonework repairs have been carried out,	
	CONDITION:	Poor	along with works to the roof and rainwater goods. Listed Building Consent and Planning Permission have been	
	OCCUPANCY:	Vacant/not in use	secured for conversion to retail and leisure facilities, and	
THE REPART	PRIORITY CATEGORY:	F(C)	works are underway.	
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1080302	Contact: Verena McCaig 020 7973 3718	
	SITE NAME:	Roman Bridge, Jersey Road, Osterley Park	Rusticated and stone-faced bridge with one segmental arch and flanking pairs of rusticated Doric half columns, dating	
	DESIGNATION:	Listed Building grade II*, RPG grade II*, part in CA	from 1780, by Robert Adam. The bridge is severed from the historic park by the M4 and straddles the borough boundary between Ealing and Hounslow. It is in need of	
	CONDITION:	Very bad	considerable repair and consolidation, and is subject to heritage crime. Vegetation, potential collapse, and	
	OCCUPANCY:	N/A	redundancy are key threats to address.	
ALC THE ALL AND	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1079401	Contact: Verena McCaig 020 7973 3718	
PRIORITY CATEGORIES			ABBREVIATIONS	
 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed. 	 D Slow decay; solution not yet implemented E Under repair or in fa repair, but no user is under threat of vaca obvious new user (a to buildings capable use). 	d. (where applicable) end use c user identified; or functionall dentified; or redundant buildings with nev ncy with no agreed but not yet implemer pplicable only	nd NOTE CA Conservation Area or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority v use New Entry is noted). NP National Park	

© Histor

© Historic England

© Bob Wilson

SITE NA DESIGN/ CONDI PRINCIP OWNER

SITE NA DESIGNATION: CONDITION PRINCIPAL VULNER OWNER TYPE:

	SITE NAME:	The Hermitage, 17, Upper Sutton Lane, Heston	Late C15 timber-framed house with later additions. It was badly damaged by fire in 2003 and suffered further
	DESIGNATION:	Listed Building grade II	deterioration following theft of the temporary protective roof. Management of the site has improved. The Local
	CONDITION:	Very bad	Authority and developer are in discussion regarding long- term plans.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
oric England	LIST ENTRY NUMBER:	1260544	Contact: Sean Doran (LPA) 020 8583 4941

40.600	SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth	e Road, Hanworth I 860. The building has suffered significant deterioration. Some urgent works have been undertaken to stabilise the
	DESIGNATION:	Listed Building grade II	building and a series of condition reports have been
	CONDITION:	Very bad	produced with recommendations for repair. The owners and the Local Authority are working together to develop a
-	OCCUPANCY:	Vacant/not in use	scheme to bring the house back into full repair and re-use
	PRIORITY CATEGORY:	A (A)	for residential and community use under an enabling development scheme.
CARLEND .	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1240343	Contact: Sean Doran (LPA) 020 8583 4941

Constructed in the 1950s, designed by NF Cachemaille-SITE NAME: Church of All Saints, Uxbridge Road, Hanworth Day. Built in brick with reinforced concrete dressings and roofs covered in asphalt. It has a tall square nave with DESIGNATION: Listed Place of Worship grade II lower side aisles and a semi-domical sanctuary. Over the nave is a large circular lantern with twenty-four stained CONDITION: Poor glass panels between slender concrete mullions PRIORITY CATEGORY: A (A) surmounted by a tall cross finial. Some mullions are suffering from cracking and spalling of the concrete. There OWNER TYPE: Religious organisation is concern over the stability of several of the glass panels, some of the glass is cracked and past repairs have been LIST ENTRY NUMBER: 1241073 carried out in non-matching glass.

Contact: Tracey Craig 020 7973 3756

AME:	Romano-British site 1000yds (910m) west of East Bedfont parish church			
ER TYPE:	Commercial company	CONTACT:	Elizabeth Whitbourn 07889 808145	
IPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
ITION:	Extensive significant problems	TREND:	Unknown	
NATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002043	
AME:	Double ditched enclosure beside A30 road 500yds (460m) west of East Bedfont parish church			

	Scheduled Monument	LIST ENTRY NUMBER:	1002042
	Extensive significant problems	TREND:	Unknown
RABILITY:	Arable ploughing	NEW ENTRY ?:	No
	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145



A landscape park developed in the C18 by Princess Amelia SITE NAME: Gunnersbury Park W5 and in the C19 by Baron Lionel de Rothschild. It became a Registered Park and Garden public park in 1925. The Local Authorities have been DESIGNATION: grade II*, 22 LBs, part in CA addressing conservation issues affecting the designed landscape through implementation of a phased masterplan: 'Gunnersbury 2026'. Historic England have funded an Generally satisfactory but with CONDITION: significant localised problems updated masterplan to inform priorities for the next phases of works, subject to further public consultation. The VULNERABILITY: Medium majority of the park and buildings are now leased to a Improving Community Interest Company (CIC) to oversee the longterm development and management of the park. NEW ENTRY ?: No OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1000808 Contact: Christopher Laine 07780 545 979

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
 - Local Planning Authority National Park NP
 - Registered Park and Garden Scheduled Monument RPG
 - SM ΪA
 - Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HOUNSLOW / ISLINGTON

SITE NAME:	Grand Union Canal and Boston Manor, Brentford		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Sean Doran (LPA) 020 8583 4941
SITE NAME:	Gunnersbury Park, Brentford W3		
DESIGNATION:	Conservation Area, 21 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving

ISLINGTON

© London Borough of Islir



	SITE NAME:	Railings and gates to Islington Tennis Centre and King George's Field, Market Road N7	Cast iron railings and gates with elaborate piers and finials, probably designed by JB Bunning, 1854. Some cast iron finials have failed, and several have been removed and
lington	DESIGNATION:	Listed Building grade II	placed into store for safety reasons. A condition survey has been carried out to inform their future conservation and
	CONDITION:	Poor	funding now needs to be identified.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	9568	Contact: Claire Sutton (LPA) 020 7527 4936



This grade II* church was built 1826-9 to the design of Sir SITE NAME: Holy Trinity Church, Charles Barry. Repairs to the roof and parapets were Cloudesley Square NI funded by the National Lottery Heritage Fund and Historic DESIGNATION: Listed Building grade II*, CA England in 2006-7. After closing the church, the Diocese of London carried out a new use options appraisal and set up CONDITION: Very bad the multi-functional Cloudesley Centre to provide for a sustainable future. The aisle roofs were repaired in 2020 OCCUPANCY: Vacant/not in use and the nave ceiling is being renewed in 2021, funded by PRIORITY CATEGORY: D (A) Historic England, while other funding is being sought to complete further external fabric repairs and to provide OWNER TYPE: Religious organisation new internal facilities. LIST ENTRY NUMBER: 1195557 Contact: lan Harper 020 7973 3786

SITE NAME: Cinema, built as the Gaumont 1937-8, architect C Howard Odeon Cinema, Holloway Road Crane of Chicago. The cinema has been in poor general N7 condition, with cracking and damage to faience decoration. DESIGNATION: Listed Building grade II, CA Inappropriate modern shop fronts in poor condition have undermined the design aesthetic. However, major CONDITION: Fair upgrading works are at an advanced stage. OCCUPANCY: Occupied/in use PRIORITY CATEGORY: F (F) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1384986 Contact: Rachel Godden (LPA) 020 7527 5967

© Historic England

DELCT N

© Historic England



	SITE NAME:	Soley Mews Chapel (former), Lloyd Baker Street WCI	Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. The	
	DESIGNATION:	Listed Building grade II, CA	building is of stock brick with tracery windows in stone, slate roof, late Decorated Gothic style. It now appears to	
	CONDITION:	Fair	be occupied and in fair condition following its conversior residential use. However, the Local Authority and Histo	
	OCCUPANCY:	Occupied/in use	England need to reassess the condition of the whole	
	PRIORITY CATEGORY:	F (F)	building in order to be assured of its current status.	
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1195670	Contact: Rachel Godden (LPA) 020 7527 5967	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ŬA

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

- . -H

HERITAGE AT RISK 2021 / LONDO	on and south east	/ ISLINGTON		
	SITE NAME:	Islington War Memorial Arch, Manor Gardens N7	War memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the archway	
	DESIGNATION:	Listed Building grade II	around which the new building has been constructed. Repairs have been carried out including works to the	
	CONDITION:	Fair	lettering and stonework, but problems remain with drainage and damp. The Local Authority has been working	
	OCCUPANCY:	N/A	closely with consultants and stakeholders to better	
	PRIORITY CATEGORY:	C (C)	understand the issues with the asset and identify appropriate solutions.	
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1392555	Contact: Rachel Godden (LPA) 020 7527 5967	
	SITE NAME:	Railings, walls, gate piers and gates to Caledonian Park, Market Road N7	Railings, walls and gates to Caledonian Market built in 1854 (market demolished). There are major failures to the cast iron, with severe cracking in places. As part of the	
	DESIGNATION:	Listed Building grade II	Caledonian Clock Tower Project, funded by the National Lottery Heritage Fund and the Local Authority, general	
	CONDITION:	Very bad	repairs are proposed, with two lamps and eight animal heads to be reinstated. Works on this phase have not yet	
	OCCUPANCY:	N/A	commenced. Significant further funding is required in order	
and the second s	PRIORITY CATEGORY:	C (D)	to reinstate all the decorative features and effect suitable repairs.	
	OWNER TYPE:	Local authority	· · · · · · ·	
© Historic England	LIST ENTRY NUMBER:	1208009	Contact: Claire Sutton (LPA) 020 7527 4936	
	SITE NAME:	Finsbury Health Centre, Pine Street ECI	Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Whilst some urgent works	
	DESIGNATION:	Listed Building grade I, CA	have been carried out, including removal of asbestos, further repairs are still required, particularly to the roof,	
	CONDITION:	Poor	external walls and windows. Assessment reports and proposals for priority repairs have been prepared and	
A CARLE	OCCUPANCY:	Occupied/in use	discussions are taking place with the Local Authority and	
	PRIORITY CATEGORY:	C (C)	Historic England to secure repair.	
	OWNER TYPE:	Health authority		
© Historic England	LIST ENTRY NUMBER:	1297993	Contact: Verena McCaig 020 7973 3718	
	SITE NAME:	Finsbury Town Hall, Rosebery Avenue EC1	Town hall, built in 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style, with a public hall on	
	DESIGNATION:	Listed Building grade II*, CA	the first floor with elaborate plasterwork in Belle Epoque manner. The building is now in use as dance studios with	
	CONDITION:	Poor	the main halls available for public use. The owners have undertaken some repairs, but further external works are	
	OCCUPANCY:	Occupied/in use	urgently necessary.	
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1293112	Contact: Verena McCaig 020 7973 3718	
	SITE NAME:	Cells, former House of Detention, Sans Walk ECI	Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. Previous water ingress issues have been addressed.	
	DESIGNATION:	Listed Building grade II, CA	issues have been addressed.	
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private, multiple owners		
		1007070		

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

1297973

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Rachel Godden (LPA) 020 7527 5967

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

H

R-R	SITE NAME:	St Paul's Church, St Paul's Road NI	St Paul's Church was built in 1826-28 to the design of Sir Charles Barry in an early Gothic Revival style. It was
	DESIGNATION:	Listed Building grade II*, CA	declared redundant in 1980 when the parish united with St Jude in Mildmay Park. After neglect and vandalism the
the second	CONDITION:	Poor	building was leased to St Paul's Steiner Project in 1995 for
	OCCUPANCY:	Part occupied/part in use	use as a school. Although many repairs have been undertaken, more are required, including the repair of the
	PRIORITY CATEGORY:	C (C)	aisle roofs and internal restoration of the nave and ceilings. Funding options are being explored.
	OWNER TYPE:	Charity (non-heritage)	
© Historic England	LIST ENTRY NUMBER:	1208912	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Railings, Thornhill Square NI	Cast iron railings, circa 1852, to the perimeter of the
1 M FT & Sector 1	DESIGNATION:	Listed Building grade II, CA	central garden square, with foliated spear-head finials set ir a moulded plinth on brickwork. Parts of the railings are
	CONDITION:	Poor	misaligned, degraded and cracked, with missing elements. Historic England part-funded pilot repairs in 2010, and a
	OCCUPANCY:	N/A	specialist measured survey and costed condition survey
	PRIORITY CATEGORY:	C (C)	2017. In 2018 a project to repair the enclosed gardens was not able to proceed after funding was withdrawn.
	OWNER TYPE:	Local authority	Interested parties are in early talks with the Local Authorit
	LIST ENTRY NUMBER:	1297982	about another possible initiative to secure the necessary repairs.
© Historic England			Contact: Claire Sutton (LPA) 020 7527 4936
	SITE NAME:	Railings, Wilmington Square WCI	Cast iron railings of 1819-1841, in very poor condition. Urgent works have previously been carried out, but
Contra de las	DESIGNATION:	Listed Building grade II, CA	currently no funding has been identified for a full repair programme.
THE STREET	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
And	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	95789	Contact: Claire Sutton (LPA) 020 7527 4936
	SITE NAME:	Church of St Andrew,	St Andrews was designed by Francis Newman and John

Designation: Listed Place CONDITION: Very bad PRIORITY CATEGORY: A (B)	SITE NAME:	Church of St Andrew, Bridgeman Road, Islington NI	St Andrews was designed by Francis Newman and John Johnson as part of a development laid out by Joseph Kay,
	DESIGNATION:	Listed Place of Worship grade II, CA	surveyor, for the Thornhill family. The church was completed in 1854. It is built of Kentish ragstone with Bath stone used for the architectural dressings and the spire.
	CONDITION:	Very bad	The church was temporarily closed in July 2019 due to falling stone from the spire. There is serious settlement in
	PRIORITY CATEGORY:	A (B)	the north east vestry and chancel, In 2020 Historic England
	OWNER TYPE:	Religious organisation	awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for the preparation of specifications for a full
	1195481	programme of repairs.	
			Contact: Ian Harper 020 7973 3786
1	SITE NAME:	Church of St James and attached railings, Clerkenwell Close, Islington EC1	The church was built by architect James Carr between 1788 and 1792 for a Methodist congregation; it was re- ordered in 1882 by Reginald Blomfield for a Church of



en reof Close, Islington ECI England congregation. The steeple was rebuilt in 1849, and in 1900 the vaulted crypt was deepened. The nave parapet Listed Place of Worship grade gutters and the roofs were repaired in 2018, funded by the Listed Places of Worship Roof Repair Fund. There are cracks on the west front and decayed iron windows. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant towards repairs to Religious organisation the tower and nave roof.

© Historic England

© Historic England

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

Contact: lan Harper 020 7973 3786

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

II*, CA

Poor

C (C)

1207786

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / ISLINGTON

	SITE NAME:	Union Chapel, Compton Terrace NI	A Congregational chapel, schools and offices by James Cubit, built in 1886-87 with the tower finished in 1889.
	DESIGNATION:	Listed Place of Worship grade I, CA	Three phases of repairs to the tower and high-level roofs were funded by the National Lottery Heritage Fund and Historic England in the 2000s. In 2015 the church carried
	CONDITION:	Fair	out repairs to the lower level roofs, funded by the Liste Places of Worship Roof Repair Fund. In 2020 Historic
	PRIORITY CATEGORY:	D (D)	England awarded a Covid-19 Emergency Heritage at Risk
	OWNER TYPE:	Religious organisation	Response Fund grant for various repairs to address water penetration into the buildings.
Sand Shares Street	LIST ENTRY NUMBER:	1208365	Contact: Ian Harper 020 7973 3786
listoric England			-

© His




	SITE NAME:	Church of St John, Duncan Terrace, Islington NI	Built in 1841, designed by Joseph John Scoles. The towers flanking the gabled front elevation were added in 1877,
	DESIGNATION:	Listed Place of Worship grade II, CA	II, designed by Francis W Tasker. The towers have copper clad pyramidal roofs which were in poor condition. Stonework had been painted in the past and repairs carried out in cementitious mortar, as had the repointing of the brickwork. Repairs were completed to the front elevation
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	and tower roofs in 2019. Repairs are now required to the
9	OWNER TYPE:	Religious organisation	remaining roofs, windows and rainwater goods.
	LIST ENTRY NUMBER:	1195583	Contact: Tracey Craig 020 7973 3756

© Historic England

TITTTTTTTTTTTT

	SITE NAME:	Former Mecca Bingo, 161-169, Essex Road NI	Built as the Carlton Cinema in 1930 by George Coles, previously a bingo hall and now used as a place of worship
	DESIGNATION:	Listed Place of Worship grade II*	by Resurrection Manifestations. The building has coloured faience to the front, the rest being of yellow brick with a
	CONDITION:	Poor	slate roof. The façade is in Egyptian style. The church has temporary consent for use of the building and for division
	PRIORITY CATEGORY:	C (C)	of the main auditorium. Some repairs and restoration h
	OWNER TYPE:	Religious organisation	been carried out, but there is evidence of damage to the faience tiles. Proposals for repair and re-use are being
	LIST ENTRY NUMBER:	1292870	explored, in discussion with the Local Authority and Historic England.
			Contact: Ian Harper 020 7973 3786

© Historic England





	SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19	The Passionists (a Roman Catholic religious order) acquired the site in 1858 and built a monastery and chapel.
	DESIGNATION:	Listed Place of Worship grade II*, CA	The chapel was rebuilt in 1887-9 by Albert Vicars in a Neo- Romanesque style. Some localised roof repairs were carried out in 2015 with a grant from the Listed Places of
	CONDITION:	Poor	Worship Roof Repair Fund. The interior has been repainted. There are still parts of the external fabric in
	PRIORITY CATEGORY:	C (C)	poor condition and a comprehensive repair programme is
	OWNER TYPE:	Religious organisation	needed.
	LIST ENTRY NUMBER:	1279729	Contact: Ian Harper 020 7973 3786

© Jim Linwood

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / ISLINGTON

DESIGNATION	Hope Church (former Church of St Mary Magdalene) and attached railings, Holloway Road, Islington N7	Church in 2013 Chapel of Ease London stock b	of England church re-opened as Hope 8; built 1812-14 by William Wickings as the to St Mary's Islington. The church is built of pricks with Portland stone dressings. The
Designation.	Listed Place of Worship grade II*, CA	south porches	has settled structurally, and the north and have settled and pulled away from the aisles. and west porch have also settled. The crypt
CONDITION:	Very bad	is at risk of floo	ding due to high underground water levels,
PRIORITY CATEGORY:	C (C)	of London is ar	olled by permanent pumping, The Diocese ranging for the north and south porches to
OWNER TYPE:	Religious organisation	be supported.	
© Historic England LIST ENTRY NUMBER:	1195637	Contact: Ian Ha	arper 020 7973 3786
			•
SITE NAME:	Church of St Clement with St Barnabas and St Matthew, King Square, Islington EC I	forming one sic 1960s housing	nomas Hardwick and built in the 1820s, de of a Georgian square now replaced with blocks. The interior was re-ordered by
DESIGNATION:	Listed Place of Worship grade II		is in 1953. Works to re-slate the nave roof airs to the parapets and coping stones, and
CONDITION:	Poor	the overhauling	g of rainwater goods were completed in ing from the National Lottery Heritage
PRIORITY CATEGORY:	C (C)		repairs are required to the tower and spire.
OWNER TYPE:	Religious organisation		
LIST ENTRY NUMBER:	1366078	Contact: Trace	y Craig 020 7973 3756
© Historic England			
SITE NAME:	Church of St Silas, Penton Street, Islington NI	EP Loftus Brocl	esigned by SS Teulon, completed in 1863 by k and chancel added in 1884 by W White.
DESIGNATION:	Listed Place of Worship grade II, CA		e re-slated in 2010, the south slope with es matching the slates in size and colour, le associated high level stone repairs.
CONDITION:	Poor	Structural repairs to cracks at the west end were completed in 2016, grant-aided by the National Lo	
PRIORITY CATEGORY:	F (F)	Heritage Fund.	Stone repairs were carried out in 2018 to
OWNER TYPE:	Religious organisation		Repairs were completed to the north ework and windows in 2020. The equivalent
LIST ENTRY NUMBER:	1208241		d to the south elevation.
© Historic England		Contact: Trace	y Craig 020 7973 3756
SITE NAME: Angel NI			
DESIGNATION: Conservation Are	a, 27 LBs	NEW ENTRY ?:	No
condition: Fair		TREND:	Deteriorating
VULNERABILITY: Medium		CONTACT:	Rachel Godden (LPA) 020 7527 5967
			× /
SITE NAME: Bunhill Fields, Fins	<i>i</i> 1		
DESIGNATION: Conservation Are	a, 95 LBs, RPG grade I	NEW ENTRY?:	No
CONDITION: Fair		TREND:	Deteriorating
VULNERABILITY: Medium		CONTACT:	Rachel Godden (LPA) 020 7527 5967
1 logidini			
SITE NAME: Chapel Market N	a, 6 LBs	NEW ENTRY?:	No
SITE NAME: Chapel Market N	a, 6 LBs	NEW ENTRY?: TREND:	
SITE NAME: Chapel Market N DESIGNATION: Conservation Are	a, 6 LBs		No No significant change Rachel Godden (LPA) 020 7527 5967
SITE NAME: Chapel Market N DESIGNATION: Conservation Are CONDITION: Poor	a, 6 LBs	TREND:	No significant change
SITE NAME: Chapel Market N DESIGNATION: Conservation Are CONDITION: Poor VULNERABILITY: High		TREND:	No significant change
SITE NAME: Chapel Market N DESIGNATION: Conservation Are CONDITION: Poor VULNERABILITY: High SITE NAME: Clerkenwell ECI		TREND: CONTACT:	No significant change Rachel Godden (LPA) 020 7527 5967
SITE NAME: Chapel Market N DESIGNATION: Conservation Are CONDITION: Poor VULNERABILITY: High SITE NAME: Clerkenwell ECI DESIGNATION: Conservation Are		TREND: CONTACT: NEW ENTRY?:	No significant change Rachel Godden (LPA) 020 7527 5967 No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hat and Feathers ECI		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Rachel Godden (LPA) 020 7527 5967
SITE NAME:	Holborn Union Infirmary		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Emma Lawrence 02075272327
SITE NAME:	Moorfields EC I		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Emma Lawrence 02075272327
SITE NAME:	St John's Grove N19		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	David McKinstry 0207527524
SITE NAME:	St Lukes EC1		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rachel Godden (LPA) 020 7527 5967
SITE NAME:	Tollington Park N4		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Rachel Godden (LPA) 020 7527 5967

KENSINGTON AND CHELSEA



SITE NAME:	Entrance Arch From Courtfield Gardens, Gaspar Mews SW5	Stucco carriage arch, c1870, with foot arches on either side. The central arch has plain piers, a central channelled
DESIGNATION:	Listed Building grade II, CA	arch with vermiculated keystone, and pediment. The stucco has deteriorated, and resultant water penetration is
CONDITION:	Poor	damaging the structure. A sapling has disrupted one side arch, causing loss of stucco and brickwork and extensive
OCCUPANCY:	N/A	cracking. No owner can be traced and the Local Authority
PRIORITY CATEGORY:	B (A)	has undertaken to fund the works which are due to commence in summer 2021.
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1190812	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England



	SITE NAME:	Mausoleum of Joseph Hudson, Harrow Road, Kensal Green Cemetery W10	Opulent classical mausoleum of Portland stone dating from circa 1850. Invasive vegetation and saplings are damaging the roof, and the joints in the stonework are separating,
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	allowing further water ingress. A condition survey and specification are required.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
AN AN	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389190	Contact: Sarah Buckingham (LPA) 07970 944 428

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Tomb of Mary, Lady Montgomerie, Kensal Green Cemetery, Harrow Road W10	Massive sarcophagus of Carrara marble on a grey granite base with a frieze of paterae and fleurs de lys. It is now completely submerged under ivy. Ash saplings further
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	threaten its structural stability.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389241	Contact: Sarah Buckingham (LPA) 07970 944 428
	SITE NAME:	Tomb of Robert Coombes, Brompton Cemetery, Old	Elongated Portland stone chest tomb on a York stone slab, of unusual design with niches at the four corners each

	Brompton Cemetery, Old Brompton Road SW10	of unusual design with niches at the four corners each containing a statue of an oarsman. An upturned boat
DESIGNATION:	Listed Building grade II, RPG grade I, CA	surmounts the tomb lid, draped with a Doggett's coat and badge, the prize awarded in the annual Thames rowing race. The monument commemorates a famous rower. All
CONDITION:	Poor	niche statues have lost their heads and are covered with carbon deposits. The architectural detailing is eroding, an the stone is spalling severely in places leading to a loss of
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (C)	fabric. Heritage consultants have been appointed and discussions have commenced.
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1403329	Contact: Sarah Buckingham (LPA) 07970 944 428
	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Brompton Cemetery, Old Brompton Road SW10DESIGNATION:Listed Building grade II, RPG grade I, CACONDITION:PoorOCCUPANCY:N/APRIORITY CATEGORY:D (C)OWNER TYPE:Unknown

	SITE NAME:	Tomb of Thomas Hardwick and Philip Hardwick, Kensal Green Cemetery, Harrow Road W10	Pair of sandstone slab tombs, circa 1870, with marble cross commemorating the architectural dynasty of Thomas, Philip and Philip Charles Hardwick. Philip (1792-1870) was
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	designer of the Euston Arch. The slabs have been subject to considerable subsidence causing the marble cross to lean significantly and progressively.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
- as a way	PRIORITY CATEGORY:	C (C)	
ric England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246086	Contact: Sarah Buckingham (LPA) 07970 944 428



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England

© Histor



MA.	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	F (F)		
-	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1080723	Contact: Sarah	
	SITE NAME:	I, Campden Hill W8	Private house b	
DESIGNATION CONDITION:	DESIGNATION:	Listed Building grade II, CA	Arts and Crafts house in an urb	
	CONDITION:	Poor	The Local Auth	

Vacant/not in use

C (C)

Private

1391138

31, Brompton Square, South Kensington SW3

Listed Building grade II, CA

Poor

built 1914-15. It represents an Edwardian s led interpretation of a large C17 country ban setting. The building is in poor condition. hority is in pre-application discussions with a new owner for the repair of the building as a family home.

Buckingham (LPA) 07970 944 428

House dating from 1824-39, part of Brompton Square. A

extensions. Works on site are ongoing.

series of Planning Permissions and Listed Building Consents have been granted for internal alterations and rear

Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10	High brick boundary wall to Harrow Road, a 100-metre section of which collapsed in 2006. Further bays were
	DESIGNATION:	Listed Building grade II, part in RPG grade I, part in CA	subsequently reduced in height due to safety concerns. Historic England awarded a grant towards the first phase of rebuilding the collapsed section which involves piling,
	CONDITION:	Very bad	casting a ground beam and rebuilding the wall as original. Repair works have been completed to ten bays in total,
	OCCUPANCY:	N/A	funded by Historic England and the General Ćemetery
	PRIORITY CATEGORY:	C (F)	Company. However, considerable further funding is required to complete essential works to the entire wall.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1191000	Contact: Sarah Buckingham (LPA) 07970 944 428

	SITE NAME:	Mausoleum of Andrew Ducrow, Harrow Road, Kensal Green Cemetery W10	Mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson, with later embellishments following Ducrow's own interment. The
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	mausoleum is in poor condition with loss of sculptural elements and ironwork, and general erosion. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1358179	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Mausolea of Isabella Gregory and Hall, Harrow Road, Kensal Green Cemetery NW10	Two mausolea dating to the early 1830s, amongst the very earliest in the cemetery, one to Isabella Gregory and the other to Hall. Overgrown vegetation obscures the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition of much of the Gregory mausoleum but spalled stone due to corroding iron cramps is evident. A comprehensive condition survey of the Gregory tomb was
	CONDITION:	Very bad	produced in 2013, funded by Historic England. The Hall mausoleum has been cleared of vegetation but now requires a full condition survey. The commissioning of th
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	survey and subsequent works are being considered alongside other priorities in the cemetery.
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1227650	Contact: Sarah Buckingham (LPA) 07970 944 428



SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10	1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco central chapel of a Greek Doric tetra style, with (now roofless) pavilions
DESIGNATION:	Listed Building grade I, RPG grade I, CA	containing marble memorial sculptures. There are large catacombs below. The building is no longer in use and is suffering from water ingress. An options appraisal has beer
CONDITION:	Very bad	carried out and an updated condition survey is planned. Discussions on the future of the building, in conjunction
OCCUPANCY:	Vacant/not in use	with key stakeholders, are progressing.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1190995	Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10	Built by John Griffith in 1833 to display tablets and monuments, with brick vaulted catacombs underneath. It is currently in poor condition, with damaged stone and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	plasterwork. The restoration of a sample bay has been completed, part funded by Historic England, but considerable further funding is required to complete the
	CONDITION:	Poor	works.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080629	Contact: Sarah Buckingham (LPA) 07970 944 428
Antonia	SITE NAME:	Tomb of Admiral Henry Collins Deacon, Harrow Road, Kensal Green Cemetery W10	Mid-C19 sculptural monument in Portland stone with cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	monument on its base and a significant lean. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
	CONDITION:	Poor	accordingly.
all and and	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389226	Contact: Sarah Buckingham (LPA) 07970 944 428
ant. A	SITE NAME:	Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery W10	Marble memorial with sculpture of an anchor and cross a tall pedestal, commemorating the arctic explorer Sir Jo Ross (1777-1856). There is a significant lean to the sout and risk from invasive plants. A comprehensive conditio survey was produced in 2013, funded by Historic Englar Works are being prioritised accordingly.
1	DESIGNATION:	Listed Building grade II, RPG grade I, CA	
handler IT & and	CONDITION:	Very bad	
ALL AND ALL AN	OCCUPANCY:	N/A	
ALEAN T	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	3892 5	Contact: Sarah Buckingham (LPA) 07970 944 428
		1307213	
	SITE NAME:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut
		Tomb of Alexander Bruce, Harrow Road, Kensal Green	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
	SITE NAME:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
	SITE NAME: DESIGNATION:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
	SITE NAME: DESIGNATION: CONDITION:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA Poor	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
© Historic England	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA Poor N/A	Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised

Contact: Sarah Buckingham (LPA) 07970 944 428

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1389188

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

	SITE NAME:	Tomb of Alfred Cooke, Harrow Road, Kensal Green Cemetery W10	A limestone tomb by Thomas Milnes from the mid C19, with a statue of a horse and infant on a pedestal. The sculpture is very badly damaged. A comprehensive
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389167	Contact: Sarah Buckingham (LPA) 07970 944 428



©Ні

	SITE NAME:	Tomb of Colonel Gideon Gorrequer, Harrow Road, Kensal Green Cemetery NW10	Elaborate military monument dating from 1841 to Colonel Gorrequer, ADC (aide-de-camp) to the Governor of St Helena during Napoleon's banishment. There is evidence
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	of erosion at foundation level and architectural elements are threatened by ivy growth. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
A HALL MILLION	OCCUPANCY:	N/A	
Barries - August	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389244	Contact: Sarah Buckingham (LPA) 07970 944 428

Tomb of Daboda Dewanjee,

Harrow Road, Kensal Green

Listed Building grade II, RPG

Cemetery W10

grade I, CA

Poor

N/A

C (C)

Unknown





	LIST ENTRY NUMBER:	1246079	Contact: Sarah Buckingham (LPA) 07970 944 428
DI	SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10	Portland stone mausoleum dating from the mid C19. There is erosion at foundation level, and spalling stone due to rusting cramps. The entrance has been secured temporarily
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	to minimise any risk from anti-social behaviour. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
	CONDITION:	Poor	accordingly.
CONTRACTOR OF	OCCUPANCY:	N/A	
1.	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389242	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Indian grave marker of red sandstone from the mid C19.

The tomb has a significant lean due to severe erosion of

the base. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has

been prioritised for conservation and funding is now being

sought to carry this out.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME: DESIGNATION: CONDITION:	SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10	Portland stone sarcophagus with effigy of a sleeping child in Carrara marble from around 1840. There is a slight lean to the north east, erosion of foundations and invasive
	Listed Building grade II, RPG grade I, CA	vegetation growth. The effigy of the child has been removed for safekeeping. A comprehensive condition survey was produced in 2013, funded by Historic England.	
	CONDITION:	Poor	Works are being prioritised accordingly.
and the second	OCCUPANCY: N/A		
A CARLES AND	PRIORITY CATEGORY:	C (C)	
oric England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389182	Contact: Sarah Buckingham (LPA) 07970 944 428



1.0

© Histor

and a start	SITE NAME:	Tomb of James Poole, Harrow Road, Kensal Green Cemetery W10	Slate chest tomb from the mid C18. Structural settlemen has led to compression and shearing of some slate elements. This structural movement needs to be arreste
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	The tomb has also suffered from the loss of decorative features. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has
	CONDITION:	Very bad	been prioritised for conservation and funding is now bei sought to carry this out.
	OCCUPANCY:	N/A	sought to carry this out.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1271534	Contact: Sarah Buckingham (LPA) 07970 944 428

	SITE NAME:	Tomb of John Gibson, Harrow Road, Kensal Green Cemetery W10	Gothic style tomb of architect John Gibson d. 1859, designed by the architect himself. There is severe erosion of the upper registers and widening of joints. Tree works
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	are also required to minimise the risk of damage from overhanging branches. A comprehensive condition survey was produced in 2013, funded by Historic England. This
	CONDITION:	Very bad	monument has been prioritised for conservation and funding is now being sought to carry this out.
	OCCUPANCY:	N/A	Turining is now being sought to early this out.
	PRIORITY CATEGORY:	C (C)	
) Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080632	Contact: Sarah Buckingham (LPA) 07970 944 428



-	SITE NAME:	Tomb of John Lucas, Harrow Road, Kensal Green Cemetery W10	Tall grey Cornish granite obelisk with Carrara marble bas- relief dating from the end of the C19. The landing stone is broken and sinking into the vault and the monument is
_	DESIGNATION:	Listed Building grade II, RPG grade I, CA	leaning significantly. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389238	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

©

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

	SITE NAME:	Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10	Monumental tomb from 1856 comprising a carved coffin under an open aedicule with twelve Corinthian columns which are surmounted by four angels, each with an arm
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	held aloft to support a central wreath, now missing. The monument is in poor condition due to the loss of sculptu elements, sinking on the west side, widespread erosion a dirt accretions. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	funding is now being sought to carry this out.
) Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1293490	Contact: Verena McCaig 020 7973 3718



No. of Street, or other

٥I


SITE NAME:	Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10	Portland stone altar tomb on a stepped granite base, from circa 1830. The tomb is in poor condition due to erosion and loss of detailing, corrosion of ironwork and heavy	
DESIGNATION:	Listed Building grade II, RPG grade I, CA	overgrowth which has exacerbated the disruption of ston Railings are missing and bollards have fallen. A comprehensive condition survey was produced in 2013,	
CONDITION:	Poor	funded by Historic England. Works are being prioritised accordingly.	
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Unknown		
LIST ENTRY NUMBER:	1389237	Contact: Sarah Buckingham (LPA) 07970 944 428	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Harrow Road, Kensal Green Cemetery W10DESIGNATION:Listed Building grade II, RPG grade I, CACONDITION:PoorOCCUPANCY:N/APRIORITY CATEGORY:C (C)OWNER TYPE:Unknown	

accordingly.



© Historic England

© Historic England



Tomb of Sir Charles Newton, Harrow Road, Kensal Green

Listed Building grade II, RPG

Cemetery W10

grade I, CA

Poor

N/A

C (C)

Unknown

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Tall Greek grave stele style headstone dating from the end of the C19. Now laid flat and very vulnerable to dirt and

organic growth. There is some erosion and cracking. A comprehensive condition survey was produced in 2013,

funded by Historic England. Works are being prioritised

- CA
- LB I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

1 Alex	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery NW10	Carrara marble pedestal surmounted by a draped urn with a relief of a dog at its base, dating from 1874. The tomb is in poor condition due to erosion of its carving,		
Section 2	DESIGNATION:	Listed Building grade II, RPG grade I, CA	deterioration of the inscription, the heavy lean of the monument towards the west and encroaching vegetation which has almost obscured the monument entirely. A		
	CONDITION:	Poor	comprehensive condition survey was produced in 2013,		
	OCCUPANCY:	N/A	funded by Historic England. Works are being prioritised accordingly.		
The ANN AND	PRIORITY CATEGORY: C (C)				
) Historic England	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	1389246	Contact: Sarah Buckingham (LPA) 07970 944 428		
- the set					
	SITE NAME:	Tomb of William Price Lewis, Harrow Road, Kensal Green Cemetery W10	Portland stone obelisk with armorial and Anthemion relie from the mid C19. The corrosion of iron cramps is causin spalling of the stone. The ground is eroded around the		
1 and	DESIGNATION:	Listed Building grade II, RPG grade I, CA	tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised		
	CONDITION:	Poor	accordingly.		
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
D Historic England	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	1246083	Contact: Sarah Buckingham (LPA) 07970 944 428		
, 22	SITE NAME:	Holland House, Kensington High Street W8	Remains of a large C17 mansion of considerable architectural and historic importance damaged during		
	DESIGNATION:	Listed Building grade I, RPG grade II, CA	World War II. The east wing is occupied as a youth hoste and the courtyard used for summer opera events. However, both wings require considerable maintenance		
A ALECON 1	CONDITION:	Poor	and repair, along with the walls to the northern side. The Local Authority has secured Listed Building Consent to		
	OCCUPANCY:	Occupied/in use	carry out necessary works, and these are at an advanced		
	PRIORITY CATEGORY:	F(C)	stage.		
and the second se	OWNER TYPE:	Local authority			
) Historic England	LIST ENTRY NUMBER:	1267135	Contact: Verena McCaig 020 7973 3718		
	SITE NAME:	Enclosing walls to Moravian Burial Ground, King's Road SW10	The historic brick walls enclosing the Moravian Burial Ground once enclosed a garden in Sir Thomas More's estate, and are mostly of Tudor origin, with later addition		
	DESIGNATION:	Listed Building grade II, part in CA	Historic repairs have used damaging cementitious mortar for pointing. Other problems relate to structural instabilit and brick decay. A pilot repair project, grant-aided by		
	CONDITION:	Poor	Historic England, was carried out on three sections of the walls and finished in April 2017. This will be used to inform		
Contraction of the second	OCCUPANCY:	N/A	the strategy for the repair of the remaining walls. The		
	PRIORITY CATEGORY:	D (D)	owners are exploring possible sources of funding.		
) Historic England	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1224734	Contact: Sarah Buckingham (LPA) 07970 944 428		
	SITE NAME:	All Saints Church, Clydesdale Road, Kensington W11	Designed by William White and completed in 1861, although the spire was never realised. The sanctuary has		
	DESIGNATION:	Listed Place of Worship grade II*, CA	paintings by Henry Holiday. The slates are suffering from nail sickness and the gutters have many patch repairs. Rainwater leaks are ongoing. There is cracking through th		
444 144	CONDITION:	Poor	stonework at the west end of the north aisle in the south		
	PRIORITY CATEGORY:	С (С)	transept. Repairs are also necessary to the tower stonework and to the uneven floor internally. In 2020		
	OWNER TYPE:	Religious organisation	Historic England awarded a Covid-19 Emergency Heritage		
NT CONTRACTOR	LIST ENTRY NUMBER:	1080701	at Risk Response Fund grant to erect scaffolding to inspec and repair the crack in the south transept.		
			Contact: Tracey Craig 020 7973 3756		

- B Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

user identified; or functionally redundant buildings with new use agreed but not yet implemented.

shown in brackets (otherwise, New Entry is noted).

- LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

72

	SITE NAME:	Church of St John the Baptist, Holland Road, Kensington W14	Early English style church dating from 1874-1911 by J Brooks and JS Atkins architects. The church has slate		
	DESIGNATION: Listed Place of Worship grade I, CA		pitched roofs, coursed rubble walling with Bath stone dressings and a large rose window at the west end. Extensive repairs to the roofs, high level masonry and		
	CONDITION:	Fair	rainwater goods were completed in early 2015, grant aided by the National Lottery Heritage Fund and Historic		
	PRIORITY CATEGORY:	C (C)	England. Works to repair the west end roofs and masonry,		
	OWNER TYPE:	Religious organisation	grant aided by the National Lottery Heritage Fund, were completed in 2017. Further roof repairs are required.		
	LIST ENTRY NUMBER:	1080593	Contact: Tracey Craig 020 7973 3756		

© Historic England

© Historic England



Mar	SITE NAME:	Church of St Michael and All Angels, Ladbroke Grove, Kensington W10	Designed by J and JS Edmeston, built in 1871. Rhineland Romanesque style in London stock brick with terracotta, red Mansfield and Forest of Dean stone dressings, and clay
1	DESIGNATION:	Listed Place of Worship grade II, CA	roof tiles. The roofs and rainwater disposal system are in poor condition with water damage evident internally. Some stone and brickwork is also in need of repair.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
til	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1226579	Contact: Tracey Craig 020 7973 3756

1 AL	SITE NAME:	Church of St Augustine, Queen's Gate, Kensington SW7	Completed in 1876, designed by William Butterfield in Gothic style. Constructed in Gault brick with stone and r brick banding, areas of patterned diaper work to parapet and gables, and decorative carved stone panels. There is rich polychromatic decoration internally. Re-slating of the north slope of the nave and the north aisle was complete in 2011 with funding from Historic England and the National Lottery Heritage Fund. The south side is in need of similar work, along with brick and stone repairs, particularly to the west elevation where mortar re-facing
	DESIGNATION:	Listed Place of Worship grade II*, CA	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1226161	of brickwork are failing.
© Historic England			Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Kensal Green (All Souls) Cemetery W10	London's first metropolitan cemetery, designed by John William Griffith in 1833. The cemetery contains a large
	DESIGNATION:	Registered Park and Garden grade I, 159 LBs, 2 CAs	number of listed monuments and key buildings also at risk. The Management Plan from 2004 needs revision. Three further sections of the boundary wall have been rebuilt.
	CONDITION:	Generally unsatisfactory with major localised problems	Discussions are taking place between key stakeholders to identify funding opportunities for further investment in ke structures and infrastructure.
	VULNERABILITY:	Medium	
	TREND:	Stable	
© Historic England	NEW ENTRY?:	No	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1000817	Contact: Christopher Laine 07780 545 979

SITE NAME:	Kensal Green Cemetery W10		
DESIGNATION:	Conservation Area, 154 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Sarah Buckingham (LPA) 07970 944 428

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

KINGSTON UPON THAMES

© Historic England	SITE NAME:	Garden and boundary walls to Cimero, Thatchers and Wansbeck, Traps Lane	C17 dark red brick walls about seven feet high with tapered flange and offsets, which run along the frontage of houses along Traps Lane and enclosing the garden of
	DESIGNATION:	Listed Building grade II, CA	'Cimero'. The structure of the wall has been compromised by failing pointing and vegetative growth. Part of the wall
	CONDITION:	Poor	cóllapsed in spring 2020 and works are being undertaken on this stretch following the granting of Listed Building
	OCCUPANCY:	N/A	Consent. An application for Listed Building Consent to
	PRIORITY CATEGORY:	F (C)	prop a separate section of the wall is being considered.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1299858	Contact: Barry Lomax (LPA) 020 8547 5560

Kingston Telephone Exchange,

Ashdown Road, Kingston upon

Listed Building grade II

Vacant/not in use

Thames

Fair

F (F)



SITE NAME:	Mortuary Chapels, Bonner Hill Road	Symmetrical Gothic-style twin chapels either side of a carriageway through the cemetery. The slate roofs are
DESIGNATION:	Listed Building grade II	steeply pitched with a central stone spire and open octagonal lantern. The west chapel is still used for
CONDITION:	Poor	memorial purposes. There is general spalling to stonework, and vegetation growing at high level. The east chapel is
OCCUPANCY:	Part occupied/part in use	closed owing to structural movement, and propping is in
PRIORITY CATEGORY:	C (C)	place. The Local Authority has carried out condition and structural surveys. An application for Listed Building
OWNER TYPE:	Local authority	Consent to carry out structural repairs was made in spring 2021 and is being assessed.
LIST ENTRY NUMBER:	1358433	Contact: Barry Lomax (LPA) 020 8547 5560

Purpose built telephone exchange, built in 1907 and

ready for fit out by a new end user.

opened in 1908. Arts and Crafts style with an asymmetrical

plan. The building has been vacant for many years. Planning

Permission has been granted for a wider redevelopment,

including the repair and re-use of this building, and works are at an advanced stage, with shell repairs completed

© Historic England

©



© Historic England



OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1080059 Contact: Barry Lomax (LPA) 020 8547 5560 SITE NAME: Former Head Post Office, 42, Post office built in 1875. Three storeys in red brick with stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider Eden Street, Kingston upon Thames redevelopment, including the repair and re-use of this DESIGNATION: Listed Building grade II building, and works are progressing well on site. Part of the building is now being used as a marketing suite for the CONDITION: Fair overall development, and will later become restaurants and OCCUPANCY: Vacant/not in use community space. PRIORITY CATEGORY: F (F) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1080100 Contact: Barry Lomax (LPA) 020 8547 5560

© Historic England



	SITE NAME:	Lambeth uncovered coal store including tower and attached tunnels, Portsmouth Road, Surbiton	Uncovered coal store with tower and attached underground tunnels, built 1851-1852 to the design of James Simpson in a Romanesque style for the Lambeth Waterworks. Sited on what is now a student campus, it has
	DESIGNATION:	Listed Building grade II, CA	been unused for many years. Planning Permission and Listed Building Consent have been secured for works to
	CONDITION:	Poor	the building to convert it for use in relation to the surrounding university.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1031864	Contact: Barry Lomax (LPA) 020 8547 5560

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Е

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA

ŴĤS

- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UÁ
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / KINGSTON UPON THAMES / LAMBETH



ITE NAME:	Church of St Matthew, St Matthew's Avenue, Surbiton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
RIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
IST ENTRY NUMBER:	84929

Designed by CL Luck in Gothic style and built in 1875. It has a square tower crowned with a tall octagonal stone spire. The spire and tower suffered from erosion of stone and pointing, and rusting of embedded ironwork had resulted in cracking of stone. The mullions to the belfry openings had to be strapped temporarily due to loss of stone. Repairs to the tower, spire and belfry openings were completed in 2019, grant aided by the National Lottery Heritage Fund. The condition of the roofs has been investigated and the repairs needed have been identified.

Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Coombe Wood		
DESIGNATION:	Conservation Area, 8 LBs, 2 SMs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Chloe Clay (LPA) 0208 547 5318
SITE NAME:	Fairfield / Knights Park, Kingston Town		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Chloe Clay (LPA) 0208 547 5318
SITE NAME:	Grove Crescent, Kingston Town		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Chloe Clay (LPA) 0208 547 5318

LAMBETH



	SITE NAME:	Mausoleum of George Dodd, Norwood Road, West Norwood Memorial Park SE27	Mausoleum, circa 1865, by Thomas Allom. Built of white marble in an Italian Gothic style, with a rectangular plan of three bays defined by pinnacle buttresses. The mausoleum
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	is in a poor state of repair and is overgrown with vegetation. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for
	CONDITION:	Very bad	People programme which secured funding for the repair of priority monuments. Work is currently progressing on
	OCCUPANCY:	N/A	surveys and statutory approvals prior to commencing the
	PRIORITY CATEGORY:	B (B)	repair works, which are now anticipated to start in 2021.
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1325944	Contact: Douglas Black (LPA) 020 7926 4065





© London Borough of Lambeth

SITE NAME:	St Gabriel's College, Cormont Road, Lambeth SE5	Large Art Nouveau four-storey building, formerly Charles Edward Brooke Girls School and listed as St Gabriel's
DESIGNATION:	Listed Building grade II, CA	College. Vacant following the relocation of the school. The Local Authority commissioned a condition survey in March
CONDITION:	Poor	2016. However planned works to make the building wind and weathertight have yet to be carried out. No future
OCCUPANCY:	Vacant/not in use	user has been identified.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1080484	Contact: Douglas Black (LPA) 020 7926 4065

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	SITE NAME:	Streatham Hill Theatre, 110, Streatham Hill SW2 SW2	Constructed by WGR Spague and WH Barton in 1928. Steel framed construction clad in brick with the frontage	
	DESIGNATION:	Listed Building grade II, CA	clad in Doulton Carrara terracotta. An unusually lavish example, with a significant amount of survival, despite a	
	CONDITION:	Poor	direct hit during World War II after which the interior w repaired to the original design. It remained in use as a theatre until 1962 and then as a bingo hall until 2017, bu now much of the building is no longer in use. There is flooding in the basement subways causing deterioration	
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (New entry)		
	OWNER TYPE:	Commercial company	the fabric and other areas show signs of water ingress.	
Historic England	LIST ENTRY NUMBER:	1244564	Contact: Nicola Xuereb (LPA) 0207 926 1217	

© Historic England

©Н

	SITE NAME:	Tomb of Peter Pandia Rodocanachi and Family, Norwood Road, West Norwood Memorial Park SE27	Pink granite table tomb dating from circa 1899 within the Greek Burial Ground. Invasive vegetation is causing damage to the stepped base and the pillars surrounding the central pedestal. In 2019 the National Lottery Heritage Fund
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work is currently progressing on
	CONDITION:	Poor	surveys and statutory approvals prior to commencing the repair works, which are now anticipated to start in 2021.
	OCCUPANCY:	N/A	repair works, which are now anticipated to start in 2021.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1396403	Contact: Douglas Black (LPA) 020 7926 4065



© London Borough of Lambeth



© Historic England



SITE NAME: Wrought iron railings in a scalloped pattern on a granite Gates, piers and railings at plinth and three pairs of wrought iron gates, circa 1907. Western Block of Number 39 Currently in poor condition, suffering from deterioration (Beaufoy School Technical Block), Black Prince Road, and pigeon damage. Discussions are underway regarding Vauxhall SETT the necessary repair works and funding sources. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1183436 Contact: Douglas Black (LPA) 020 7926 4065

Wall and piers around St Mark's

Churchyard, Kennington Park

Listed Building grade II, CA

Religious organisation


Road SÉLL

Poor

N/A

C (C)

1358301



PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е

- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Low, dark granite walls with tall pale granite piers at

Contact: Douglas Black (LPA) 020 7926 4065

intervals with Portland stone round pedimented caps. The

railings and finials are missing in places and the walls are cracked and being damaged by vegetation growth.

ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
 - Local Planning Authority National Park NP
 - RPG
 - Registered Park and Garden Scheduled Monument SM
 - ΪA WHS

Unitary Authority World Heritage Site

	SITE NAME:	Dorchester Court, Herne Hill SE24	Eight blocks with 96 flats around a central landscaped courtyard, dating from 1933-4 by Leslie H Kemp and
	DESIGNATION:	Listed Building grade II	Frederick E Tasker. There are structural problems with the balconies and general external deterioration. Discussions
	CONDITION:	Poor	are ongoing regarding a comprehensive programme of refurbishment.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1390780	Contact: Douglas Black (LPA) 020 7926 4065


© Historic England



SITE NAME:	Off-licence attached to the Old Red Lion public house, 44, Kennington Park Road SEI I	Tudorbethan style off-licence, built circa 1929. Damage includes a broken window pane. Planning Permission and Listed Building Consent for the erection of a three storey
DESIGNATION:	Listed Building grade II	extension were granted on appeal in 2014. The Local Authority is currently considering the details submitted in
CONDITION:	Poor	connection with the scheme.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1061361	Contact: Douglas Black (LPA) 020 7926 4065



C Historic Englan	А



	N	Augustus Ralli Mortuary Chapel, Norwood Road, West Norwood Memorial Park SE27	Doric temple mortuary chapel circa 1872, attributed to J Oldrid Scott, within the Greek Burial Ground and known as St Stephen's Chapel. The chapel is in poor condition due
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	to subsidence, collapsed steps and internal water damage. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People
	CONDITION:	Poor	programme which secured funding for the repair of priority monuments. Work is currently progressing on surveys and
	OCCUPANCY:	N/A	statutory approvals prior to commencing the repair works,
	PRIORITY CATEGORY:	D (D)	which are now anticipated to start in 2021.
listoric England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1064989	Contact: Elizabeth Whitbourn 07889 808145

© His

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site



SITE NAME: Catacombs beneath the Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority 12/2102

Catacombs circa 1837; cemetery laid out circa 1837 by Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs. Moisture surveys are ongoing; levels appear to be stabilising/reducing. Discussions are ongoing regarding potential funding sources and long-term use.

© Historic England



	LIST ENTRY NUMBER:	1263192	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of C Auffrey and E O'Gorman, Norwood Road, West Norwood Memorial Park SE27	Pedestal tomb dating from 1893 with carved wreaths, faces and anchor. The tomb is leaning significantly. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme
「「「「「「「」」」」	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	which secured funding for the repair of priority monuments. Work is currently progressing on surveys and statutory approvals prior to commencing the repair works,
	CONDITION:	Very bad	which are now anticipated to start in 2021.
1000	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250576	Contact: Douglas Black (LPA) 020 7926 4065



SITE NAME:	Tomb of Captain John Wimble, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1851 with finely carved reliefs showing ships at sea. The stone ship surmounting the tomb is subject to movement. In 2019 the National Lottery
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work is currently
CONDITION:	Fair	progressing on surveys and statutory approvals prior to commencing the repair works, which are now anticipated
OCCUPANCY:	N/A	to start in 2021.
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1065020	Contact: Douglas Black (LPA) 020 7926 4065

© Historic England

© Historic England



Tomb of Christopher Gabriel, Norwood Road, West SITE NAME: Chest tomb in Portland stone dating from 1873 with carvings by Kelsey. There is cracking to the stone panels on the side of the tomb. In 2019 the National Lottery Heritage Norwood Memorial Park SE27 Fund awarded the Local Authority a grant under the Parks Listed Building grade II, RPG for People programme which secured funding for the DESIGNATION: grade II*, CA repair of priority monuments. Work is currently progressing on surveys and statutory approvals prior to CONDITION: Poor commencing the repair works, which are now anticipated OCCUPANCY: to start in 2021. N/A PRIORITY CATEGORY: B (B) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1064988 Contact: Douglas Black (LPA) 020 7926 4065

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Tomb of Elizabeth King, Norwood Road, West Norwood Memorial Park SE27	Statue of an angel mounted against a rough headstone over rough base, dating from 1922. In the style of the 1878 Oneto Monument by Giulio Monteverge in Genoa. The
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	statue and headstone are leaning significantly. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme
	CONDITION:	Very bad	which secured funding for the repair of priority
	OCCUPANCY:	N/A	monuments. Work is currently progressing on surveys and statutory approvals prior to commencing the repair works.
Contraction of	PRIORITY CATEGORY:	В (В)	which are now anticipated to start in 2021.
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250589	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on a pedestal with grave slab dating from 1904. Tiles are missing and cementitious repairs are
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	causing further damage. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for
	CONDITION:	Poor	the repair of priority monuments. Work is currently
	OCCUPANCY:	N/A	progressing on surveys and statutory approvals prior to commencing the repair works, which are now anticipated
	PRIORITY CATEGORY:	B (B)	to start in 2021.
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250687	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of James Baldwin Brown, Norwood Road, West Norwood Memorial Park SE27	Celtic cross on pedestal faced in terracotta in Romanesque/Gothic style, dating from 1885. The tomb is leaning heavily, with its side tablet disengaged and the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	pinnacle tip missing. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the
Same of the second second	CONDITION:	Very bad	repair of priority monuments. Work is currently progressing on surveys and statutory approvals prior to
- Standard	OCCUPANCY:	N/A	commencing the repair works, which are now anticipated
A REAL PROPERTY	PRIORITY CATEGORY:	B (B)	to start in 2021.
D Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250584	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of James Kershaw, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1864 in Gothic style with elaborate carving. Designed by Alfred Waterhouse commemorating the MP James Kershaw. The structural
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	ironwork is corroding, causing splitting of the stone. The railings are also being affected by movement to the plinth. In 2019 the National Lottery Heritage Fund awarded the
+===	CONDITION:	Poor	Local Authority a grant under the Parks for People programme which secured funding for the repair of priorit
A			- CONSTRUCTER WOULD SECTION UNDOING THE PEDAIL OF DEIOPIT

© Historic England

OCCUPANCY: N/A monuments. Work is currently progressing on surveys and statutory approvals prior to commencing the repair works, PRIORITY CATEGORY: D (D) which are now anticipated to start in 2021. OWNER TYPE: Unknown LIST ENTRY NUMBER: 1263197 Contact: Douglas Black (LPA) 020 7926 4065

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Tomb of Mrs Alice Moffatt.	An arcaded chest tomb, circa 1847. The columns and top
	LIST ENTRY NUMBER:	1064983	Contact: Douglas Black (LPA) 020 7926 4065
© Historic England	OWNER TYPE:	Unknown	
	PRIORITY CATEGORY:	B (B)	
	OCCUPANCY:	N/A	to start in 2021.
	CONDITION:	Very bad	progressing on surveys and statutory approvals prior to commencing the repair works, which are now anticipated
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority monuments. Work is currently
	SITE NAME:	Tomb of John Stevens, Norwood Road, West Norwood Memorial Park SE27	Obelisk monument dating from 1861 by Anderson and McKenzie of Aberdeen with incised fret pattern. The tom is leaning significantly. In 2019 the National Lottery
	LIST ENTRY NUMBER:	1064995	Contact: Douglas Black (LPA) 020 7926 4065
© Historic England	OWNER TYPE:	Unknown	
	PRIORITY CATEGORY:	B (B)	repair works, which are now anticipated to start in 2021.
	OCCUPANCY:	N/A	priority monuments. Work is currently progressing on surveys and statutory approvals prior to commencing the
	CONDITION:	Poor	awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	movement and is now close to the edge of the sarcophagus. In 2019 the National Lottery Heritage Fund
		Schilizzi, Norwood Road, West Norwood Memorial Park SE27	sarcophagus surmounted by a white marble female figure with flowing robes and veiled head. The figure is subject to
All and a second se	SITE NAME:	Tomb of John and Virginia	Monument dating from 1908 within the Greek Burial Ground. It comprises a stepped granite base with
	LIST ENTRY NUMBER:	1250680	Contact: Douglas Black (LPA) 020 7926 4065
	OWNER TYPE:	Unknown	
) Historic England	PRIORITY CATEGORY:	D (D)	
	OCCUPANCY:	N/A	
	CONDITION:	Poor	which are now anticipated to start in 2021.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	programme which secured funding for the repair of priori monuments. Work is currently progressing on surveys an statutory approvals prior to commencing the repair work
ALL ALL	SITE NAME:	Tomb of Johann and Annie Sparenborg and family, Norwood Road, West Norwood Memorial Park SE27	Tomb in the style of a small Greek temple, dating from 1904. Movement is evident to the columns and base. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People



I*I0ff slab have been lost, leaving the structural rods exposed. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II, RPG programme which secured funding for the repair of priority DESIGNATION: grade II*, CA monuments. Work is currently progressing on surveys and statutory approvals prior to commencing the repair works, which are now anticipated to start in 2021. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: B (B) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1357922 Contact: Douglas Black (LPA) 020 7926 4065

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Tomb of Thomas De La Garde Grissell, Norwood Road, West Norwood Memorial Park SE27	Chest tomb, circa 1847. Cast iron, stucco and pink granite. The plinth is broken and parts are exposed. In 2019 the National Lottery Heritage Fund awarded the Local
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Authority a grant under the Parks for People programm which secured funding for the repair of priority monuments. Work is currently progressing on surveys a statutory approvals prior to commencing the repair wor which are now anticipated to start in 2021.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	which are now anticipated to start in 2021.
	PRIORITY CATEGORY:	B (B)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065021	Contact: Douglas Black (LPA) 020 7926 4065

Tomb of XE Balli Family, Norwood Road, West Norwood Memorial Park SE27

Listed Building grade II, RPG

grade II*, CA

Very bad

Unknown

N/A

B (B)



	SITE NAME:	Tomb of William Grane, Norwood Road, West Norwood Memorial Park SE27	Tomb dating from 1856, noted in the list description as having a pink granite cross with foliated arms and vine trails to stem. This cross is missing and there is clear evidence of
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	movement to the base of the monument. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme
OCCUP/	CONDITION:	Poor	which secured funding for the repair of priority monuments. Work is currently progressing on surveys and
	OCCUPANCY:	N/A	statutory approvals prior to commencing the repair works,
	PRIORITY CATEGORY:	D (D)	which are now anticipated to start in 2021.
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357900	Contact: Douglas Black (LPA) 020 7926 4065



© Historic England

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:



LIST ENTRY NUMBER:	1120820	Contact: Douglas Black (LPA) 020 7926 4065
SITE NAME:	Monument to George Abell, St Leonard's churchyard, Streatham High Road, Streatham SW16	Chest tomb of circa 1826 commemorating George and Elizabeth Abell. The slab of Portland limestone with curved edged top has broken and the plinth is in a bad condition. A condition survey has been prepared, with support from
DESIGNATION:	Listed Building grade II, CA	Historic England, and funding is now being sought to secure the necessary repair works.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1323730	Contact: Douglas Black (LPA) 020 7926 4065

© London Borough of Lambeth

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

lonic temple mausoleum dating from the late C19 within the Greek Burial Ground. There is evidence of movement

to the entablature and collapse of the steps. In 2019 the National Lottery Heritage Fund awarded the Local

Authority a grant under the Parks for People programme

monuments. Work is currently progressing on surveys and

statutory approvals prior to commencing the repair works,

which secured funding for the repair of priority

which are now anticipated to start in 2021.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

81

HERITAGE AT RISK 2021 / LONDO	on and south east	/ LAMBETH	
- Line	SITE NAME:	Monument to Joseph Hay, St Leonards churchyard, Streatham High Road, Streatham SW16	Coade stone chest tomb in railed enclosure, dated 1808 by Coade and Sealy. The railings are broken and in a poor state of repair. A condition survey has been prepared, with support from Historic England, and funding is now being
REAST	DESIGNATION:	Listed Building grade II, CA	sought to secure the necessary repair works.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
CONTRACTOR DESIGNATION	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1323732	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa 1808 by Coade and Sealy. The Coade stone is in an advanced state of decay. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to
	DESIGNATION:	Listed Building grade II, CA	secure the necessary repair works.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1323731	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	335-337, Wandsworth Road SW8	Pair of Regency houses, formerly undertaker's premises. The buildings are occupied and the freeholders are co-
	DESIGNATION:	Listed Building grade II, CA	operating with the Local Authority on a phased programme of repairs.
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
1	OWNER TYPE:	Commercial company	
© London Borough of Lambeth	LIST ENTRY NUMBER:	1081047	Contact: Douglas Black (LPA) 020 7926 4065
·			
	SITE NAME:	Wall on the south side of St John with All Saints' churchyard, Waterloo Road SEI	Early C19 stock brick walls, spalled with cracked brickwork. The finials are broken and missing. A structural survey has been carried out and Historic England and the
	DESIGNATION:	Listed Building grade II, CA	Local Authority are in discussion regarding repairs and potential funding sources.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
E CAR PETRIC	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1068687	Contact: Douglas Black (LPA) 020 7926 4065
-	SITE NAME:	The Clapham Orangery, Worsopp Drive SW4	Orangery built in 1793 to the design of William Burgh, in a Palladian style. It stood in the grounds of Thornton House,
No.	DESIGNATION:	Listed Building grade II	demolished in the 1940s. Now standing in the middle of a housing estate. Discussions regarding maintenance of the
	CONDITION:	Fair	roof and rainwater goods have commenced.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	С (С)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1068843	Contact: Douglas Black (LPA) 020 7926 4065
C . Intoine England			5 (<i>, , ,</i>

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Leonard, Streatham High Road, Streatham SW16	Designed by J Parkin, built 1841, chancel added 1862 by Benjamin Ferrey. The lower tower and spiral stair date from mid C14. The church was burnt out in 1975; repaired
	DESIGNATION:	Listed Place of Worship grade II, CA	and re-ordered by Douglas Feast. The aisle and nave roofs have been re-slated and the flat roofs either side of the tower re-covered along with stucco repairs to the north
	CONDITION:	Poor	side in 2015 and the south side in 2018, both with fundi from the National Lottery Heritage Fund. Works to
	PRIORITY CATEGORY:	C (C)	underpin and repair the north porch were completed in
	OWNER TYPE:	Religious organisation	2019. Historic England has awarded a Covid-19 response grant to repair the stained glass windows.
© Historic England	LIST ENTRY NUMBER:	1100267	Contact: Tracey Craig 020 7973 3756

SITE NAME:	Leigham Court Estate, Streatham SW2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065
SITE NAME:	Vassall Road, Brixton SW9		
DESIGNATION:	Conservation Area, 43 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065
SITE NAME:	West Norwood SE27		
DESIGNATION:	Conservation Area, 75 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065

LEWISHAM

	SITE NAME:	Olympia Convoy's Wharf, Prince Street SE8	Cast and wrought iron slip covers of 1845-47 by Messrs George Baker and Sons in the former Deptford Royal
	DESIGNATION:	Listed Building grade II	Dockyard. The arched iron construction of two main spans and perimeter cantilevered aisles is clad in corrugated iron
	CONDITION:	Poor	to the roof and sides. The iron frame is heavily corroded in certain areas and previous ad hoc repairs are temporarily
	OCCUPANCY:	Vacant/not in use	providing support. Used previously for storage through
	PRIORITY CATEGORY:	C (New entry)	the late C20, it is now empty. Outline planning permission was granted in 2015 for the redevelopment of the wider
	OWNER TYPE:	Commercial company	Convoys Wharf site and a proposal for re-use of this building is expected in 2021.
m	LIST ENTRY NUMBER:	1213012	Contact: Joanna Ecclestone (LPA) 020 8314 9912

© London Borough of Lewisham



© Historic England

SITE NAME:	Holland and Company's Distillery, 14 and 16, Deptford Bridge SE8	Former offices of the Holland and Company's Distillery, dating from the late C18. On the ground floor at the east end is a double door and a carriage entrance, framed in late
DESIGNATION:	Listed Building grade II	C19 stonework with dentil cornice and an inscription in the small pediment over: "Established 1779. Holland and Co's
CONDITION:	Poor	Distillery and Bonded Store". The building has been empty for a number of years and is deteriorating. The Local
OCCUPANCY:	Vacant/not in use	Authority has written to the owner to discuss the building's
PRIORITY CATEGORY:	C (C)	condition.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1080000	Contact: Joanna Ecclestone (LPA) 020 8314 9912

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site



SITE NAME:	Beckenham Place, Foxgrove Road, Beckenham Place Park	Mansion built c1773 and situated within former park land. Some emergency repairs were carried out in 2012 with a
DESIGNATION:	Listed Building grade II*, CA	grant from Historic England. The National Lottery Heritage Fund completed a Parks for People project in 2019 for the
CONDITION:	Fair	wider park, which restored the setting of the mansion. The mansion currently accommodates several meanwhile uses
OCCUPANCY:	Part occupied/part in use	whilst the Local Áuthority investigates funding options for
PRIORITY CATEGORY:	C (C)	its full repair, as well as options for its long-term use. In 2020 Historic England awarded the Local Authority a
OWNER TYPE:	Local authority	Covid-19 Emergency Heritage at Risk Response Fund grant for high priority repairs.
LIST ENTRY NUMBER:	1359317	Contact: Elizabeth Whitbourn 07889 808145

© Historic England

	SITE NAME:	Old Swimming Baths, Ladywell Road SEI3	Public baths, consisting of first and second class swimming pools, constructed in 1884. Designed in the Gothic style by
	DESIGNATION:	Listed Building grade II, CA	Wilson and Son and Thomas Aldwinkle. The building is unused and the second class pool hall was badly damaged
	CONDITION:	Poor	by fire in 2005. In 2011 urgent works to the roof and dry rot stabilised the building although in isolated areas some
	OCCUPANCY:	Vacant/not in use	water ingress persists. The Local Authority successfully
	PRIORITY CATEGORY:	C (C)	secured a restoration partner in 2017 and discussions are in progress regarding the full repair of the building, its long-
	OWNER TYPE:	Local authority	term use and interim repairs.
	LIST ENTRY NUMBER:	39 8	Contact: Natasha Peach (LPA) 0208 314 6049

© Historic England



© Historic England

	OWNER TYPE:	Local authority	in progress regarding the full repair of the building, its long- term use and interim repairs.
	LIST ENTRY NUMBER:	1391811	Contact: Natasha Peach (LPA) 0208 314 6049
	SITE NAME:	Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old Churchyard SE13	A stone chest tomb from the middle of the C18 commemorates Captain Limeburner of the Royal Navy and his wife. The south side has lost its central panel and the
	DESIGNATION:	Listed Building grade II, CA	angle balusters are displaced. A condition survey has been prepared, with funding from Historic England, and funding
13	CONDITION:	Very bad	for repair and restoration works has been secured through a Section 106 agreement.
-	OCCUPANCY:	N/A	a section roo agreement.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392002	Contact: Natasha Peach (LPA) 0208 314 6049

listoric England	SITE NAME:	Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard SEI3	An elaborate Rococo tomb of 1769 in Portland stone and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from
	DESIGNATION:	Listed Building grade II*, CA	vegetation growth, and some collapse. A condition survey has been prepared, with funding from Historic England, an funding for repair and restoration works has been secured through a Section 106 agreement.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1391993	Contact: Elizabeth Whitbourn 07889 808145

© His



	SITE NAME:	Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE13	Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head, dating from 1752. The monument has lost its railings, back plates and inscription panels, and vegetation growth is causing further damage. A
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	condition survey has been prepared, with funding from Historic England, and funding for repair and restoration
	OCCUPANCY:	N/A	works has been secured through a Section 106 agreement.
	PRIORITY CATEGORY:	A (A)	
and he	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1391998	Contact: Natasha Peach (LPA) 0208 314 6049

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

Н

	on and south east		
	SITE NAME:	Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SEI3	Raised ledger stone of 1727. Ground subsidence has caused some sinking and movement to the ledger, which is now set at an angle. A condition survey has been prepared,
	DESIGNATION:	Listed Building grade II, CA	with funding from Historic England, and funding for rep and restoration works has been secured through a Sect
	CONDITION:	Poor	106 agreement.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392012	Contact: Natasha Peach (LPA) 0208 314 6049
	SITE NAME:	Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SEI3	Stone chest tomb erected in 1767. The tomb is badly damaged by vegetation growth through open joints. A condition survey has been prepared, with funding from
	DESIGNATION:	Listed Building grade II, CA	Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.
E BILLY	CONDITION:	Poor	works has been seed of an ough a seedon roo agreement.
A starting of the	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392013	Contact: Natasha Peach (LPA) 0208 314 6049
	SITE NAME:	Tomb of Lord Dacre, Lee Terrace, St Margaret's Old Churchyard SEI3	This composite urn monument to Lord Dacre dates from 1794. All the elements now lie disassembled on the ground. The monument needs urgent attention to avoid
	DESIGNATION:	Listed Building grade II, CA	further damage or loss of its components. A condition survey has been prepared, with funding from Historic
	CONDITION:	Very bad	England, and funding for repair and restoration works has
	OCCUPANCY:	N/A	been secured through a Section 106 agreement.
	PRIORITY CATEGORY:	A (A)	
The second second	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392008	Contact: Natasha Peach (LPA) 0208 314 6049
	SITE NAME:	Tomb of Rev. Thomas Negus, Lee Terrace, St Margaret's Old Churchyard SE13	Chest tomb of 1765, badly damaged from vegetation which has infiltrated through open joints and cracked the ledger slab. One angle baluster has been lost and there is a risk of
	DESIGNATION:	Listed Building grade II, CA	further collapse. A condition survey has been prepared, with funding from Historic England, and funding for repair
and a start of the	CONDITION:	Very bad	and restoration works has been secured through a Section 106 agreement.
	OCCUPANCY:	N/A	i ob agreement.
L MARTIN	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392011	Contact: Natasha Peach (LPA) 0208 314 6049
			end have collapsed exposing brickwork and making the
	SITE NAME:	Tomb of Thomas Butler, Lee Terrace, St Margaret's Old Churchyard SEI3	Chest tomb of 1733. The panels on both sides and on one end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition
	SITE NAME: DESIGNATION:	Terrace, St Margaret's Old	end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has
		Terrace, St Margaret's Óld Churchyard SEI3	end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic
	DESIGNATION:	Terrace, St Margaret's Old Churchyard SEI3 Listed Building grade II, CA	end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has
	DESIGNATION: CONDITION:	Terrace, St Margaret's Óld Churchyard SEI3 Listed Building grade II, CA Very bad	end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has
Pittoric England	DESIGNATION: CONDITION: OCCUPANCY:	Terrace, St Margaret's Old Churchyard SE13 Listed Building grade II, CA Very bad N/A	end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© Historic England

8

© Historic

	SITE NAME:	Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SEI3	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. The end panel of the upper part is broken. A condition survey has
and the second s	DESIGNATION:	Listed Building grade II, CA	been prepared, with funding from Historic England, and funding for repair and restoration works has been secured
	CONDITION:	Poor	through a Section 106 agreement.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
1	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392010	Contact: Natasha Peach (LPA) 0208 314 6049

ic Ergland	SITE NAME:	Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE13	Coade stone chest tomb from the late C18. The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. The tomb is in need of
	DESIGNATION:	Listed Building grade II, CA	attention to avoid serious structural damage. A condition survey has been prepared, with funding from Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392001	Contact: Natasha Peach (LPA) 0208 314 6049

A COLUME	SITE NAME:	Rileys (former Temperance Billiard Hall), 233-241, Lewisham High Street SE13	A temperance billiard hall built 1909-10, originally incorporating a café, lounge and shops facing Lewisham High Street. Listed as a well-surviving example of an uncommon building type. The building has been empty for a number of years. It had been gutted internally and was showing signs of neglect. Planning Permission and Listed Building Consent were granted in 2017 for conversion to a church, with associated changes to restore and change parts of the building. Works are currently in progress and are due to complete in early 2022.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
© Historic England	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392397	Contact: Joanna Ecclestone (LPA) 020 8314 9912

	SITE NAME:	Baring Hall Hotel and Stable Block, Baring Road, SE12 SE12	Public house and stable block designed by Ernest Newtor 1881-1882, with later additions. The pub is a prominent landmark in the centre of Grove Park. It was occupied at ground and basement only and in use as a pub but was closed and broken into during lockdown. The stable block is unoccupied and derelict. The building is now secure and weathertight. Discussions between the Local Authority ar the owner are underway regarding listed building application works to protect and preserve the building.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Commercial company	
© Baring Hall Trust	LIST ENTRY NUMBER:	1456451	Contact: Joanna Ecclestone (LPA) 020 8314 9912



	SITE NAME:	Church of St Swithun, Hither Green Lane, Lewisham SEI3	This church was completed in 1893 to the designs of Ernest Newton, with an extension in 1905. A small mission church
	DESIGNATION:	Listed Place of Worship grade II	of 1884 survives at the east end. Built of red Wrotham brick, Bath stone is used for windows and dressings, and
10.00	CONDITION:	Poor	Portland stone for copings, all under slated roofs. A programme of repairs to windows and masonry at the
- Aller	PRIORITY CATEGORY:	C (C)	west end was completed in 2015, grant aided by the
1 day	OWNER TYPE:	Religious organisation	National Lottery Heritage Fund and Historic England. Further repairs are required.
E1 31	LIST ENTRY NUMBER:	1192516	Contact: lan Harper 020 7973 3786

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / LEWISHAM / LONDON LEGACY (MDC)

	()	
SITE NAME:	Church of St Mary the Virgin, Lewisham High Street, Lewisham SEI 3	This unusual Georgian church, raised over a crypt, was completed in 1774 by George Gibson Jr; it replaced a medieval church and incorporated the original tower. The
DESIGNATION:	Listed Place of Worship grade II*, CA	nave was re-modelled and the chancel added in 1882 by William Blomfield. The chancel was re-ordered in 1995-96. A nave re-roofing and drainage project was completed in
CONDITION:	Poor	2016 with a grant from the National Lottery Heritage Fund. The congregation is actively exploring options for funding
PRIORITY CATEGORY:	C (C)	for a second phase of roofing repairs to the tower and
OWNER TYPE:	Religious organisation	chancel.
LIST ENTRY NUMBER:	1 193297	Contact: Ian Harper 020 7973 3786
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Lewisham High Street, Lewisham SE13DESIGNATION:Listed Place of Worship grade II*, CACONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

SITE NAME:	Deptford High Street SE8		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Natasha Peach (LPA) 0208 314 6049

LONDON LEGACY (MDC)

© Historic England	SITE NAME:	Abbey Mills Pumping Station (Station C) with associated Valve House, Abbey Lane E15	Pumping station 1910-14, white stock brick with terracotta and moulded stone dressings. The internal pumping floor is sunk deep below ground level. Works are planned to
	DESIGNATION:	Listed Building grade II, CA	ensure that the building remains wind and watertight. There are no long-term proposals for the re-use of the
	CONDITION:	Poor	building at this stage, although options are being discussed.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1392550	Contact: Planning Officer (LPA) 020 3288 8820

Bases of pair of chimneystacks at Abbey Mills Pumping Station,

Listed Building grade II, CA

Abbey Lane EI5

Very bad

N/A

A (A)

Utility

1357995

and the second second second	
© Historic England	



SITE NAME: Ancillary Pump House at Abbey Pump house circa 1868, probably by Bazalgette and Mills Pumping Station (Station Cooper, built in a similar style to the main pumping station. B), Abbey Road EI5 There is some evidence of water ingress and the design of the exterior downpipes makes them vulnerable to plant DESIGNATION: Listed Building grade II, CA growth and blockages. The building is vacant and has no identified use. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Utility LIST ENTRY NUMBER: 1357994 Contact: Planning Officer (LPA) 020 3288 8820

© Historic England

PRIORITY CATEGORIES D

Е

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Two chimney bases built in 1865 by Sir Joseph Bazalgette.

crowned by stone bases of octagonal stacks (demolished). The brick and stonework have been severely damaged by

invasive plant growth, although this is now being monitored and removed regularly. The stonework porches have

suffered partial collapse. A survey has been carried out to


enable Thames Water to consider options for repair.

Contact: Planning Officer (LPA) 020 3288 8820

Elaborate pedimented porches to battered brick plinths

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / LONDON LEGACY (MDC) / MERTON



E NAME:	Tide Mill (known as the House Mill), Three Mill Lane E3
SIGNATION:	Listed Building grade I, CA
NDITION:	Poor
CUPANCY:	Part occupied/part in use
ORITY CATEGORY:	C (C)
VNER TYPE:	Charity (heritage)
FENTRY NUMBER:	1080970

Tide Mill dating from 1776 and last used in 1941. Much of the building fabric has been repaired, but work is needed to the undershot water wheels and surviving machinery, and to find a solution to significantly increased flooding at ground floor level. The House Mill Trust continues to work towards a sustainable strategy for repair of machinery, along with improvements to education and community facilities. Consents have been secured to carry out repair and decorative works to external doors and windows, and funding is being sought for implementation.

Contact: Verena McCaig 020 7973 3718

© Historic I	England
--------------	---------

SITE NAME:	Sugar House Lane, Stratford E15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574
SITE NAME:	Three Mills, Stratford/Bow E15		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	Νο
CONDITION:	Very bad	TREND:	Improving significantly
CONDITION: VULNERABILITY:		TREND: CONTACT:	

MERTON

© Historic England

の日本のないのであると

©

©



Late C19 cast iron cylindrical electricity substation with SITE NAME Electricity Substation at junction three rows of moulded cast iron patterned panels, with Sunnyside Passage, Sunnyside SW19 projecting cornice, and foliated finial. The structure has not been properly maintained with an appropriate paint finish; DESIGNATION: Listed Building grade II, CA there is visible rust. The owners have commissioned analysis of the historical paint finishes and have secured CONDITION: Poor Listed Building Consent to carry out full repair. OCCUPANCY: N/A PRIORITY CATEGORY: D (C) OWNER TYPE: Utility LIST ENTRY NUMBER 1358028 Contact: Jill Tyndale (LPA) 020 8545 3041

	SITE NAME:	Wall to rear of the block of flats west of easternmost block, 9, 11, 15 and 17, Windsor Avenue SW19	Fragments of medieval and probably later precinct wall of the former Merton Priory, constructed from flint and rubble stone. The walls have been subjected to extensive damage and loss through unauthorised works and the Local
	DESIGNATION:	Listed Building grade II, CA	Authority are considering appropriate enforcement action.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1194014	Contact: Jill Tyndale (LPA) 020 8545 3041

P Historic England	SITE NAME:	Garden wall enclosing four sides of playing field, Church Lane, Merton Park SW19	Garden wall dating from the C16 to C17, with later alterations. There are many areas of eroded brick and inappropriate past repair. Damaging vegetation has been
	DESIGNATION:	Listed Building grade II, CA	removed and a comprehensive survey with specification for repair has been prepared. The Local Authority has
	CONDITION:	Poor	previously carried out rebuilding and repairs to a section
	OCCUPANCY:	N/A	around the entrance gateway which had been dismantle for safety reasons, but further works are needed, includ control of vegetation.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1286387	Contact: Jill Tyndale (LPA) 020 8545 3041

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
- Unitary Authority World Heritage Site ŴĤS



	SITE NAME:	Tomb of Thomas Stanly, St Peter and St Paul's Churchyard, Church Road, Mitcham	Table tomb over large podium erected in the early C18. The podium is severely damaged by vegetation. A condition survey has been carried out, funded by Historic
	DESIGNATION:	Listed Building grade II, CA	England. The church, Local Authority and Historic England are working together to secure funding to enable the
	CONDITION:	Very bad	necessary works to be carried out.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
i.	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080949	Contact: Jill Tyndale (LPA) 020 8545 3041

© Historic England

© Historic England



1 N	SITE NAME:	Portion of wall on the west side of River Pickle between Merton High Street and Merantun Way, High Street, Wimbledon Village SW19	Formerly part of the precinct wall to Merton Priory, consisting of medieval flint and rubblestone. Sections of th wall are in poor condition and have collapsed due to vegetation growth. The National Trust has developed a plan towards its conservation and long-term maintenance
	DESIGNATION:	Listed Building grade II, part in CA	with improved public access. This has been achieved in conjunction with Historic England, the Local Authority, Merton Local History Society and Merton Priory Trust. In
	CONDITION:	Very bad	2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for emergency
	OCCUPANCY:	N/A	stabilisation work pending full repairs.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1358009	Contact: Jill Tyndale (LPA) 020 8545 3041



Public house, formerly the Kings Head Hotel, with C16 SITE NAME: Burn Bullock Public House, 315, interior and exterior features and C18 front. No longer London Road operating as a public house, it had been illegally occupied as DESIGNATION: Listed Building grade II, CA a House in Multiple Occupation and has suffered associated deterioration. Essential repairs have been CONDITION: Poor carried out to make the building weatherproof, and it has been externally decorated. No applications for OCCUPANCY: Part occupied/part in use development and re-use of the building have been PRIORITY CATEGORY C (C) submitted by the owner, although early discussions have taken place and a building archaeology study undertaken. OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1193391 Contact: Jill Tyndale (LPA) 020 8545 3041

© Historic England



© Historic England



SITE NAME:	Ravensbury Mill (North Wing), 245, Morden Road, Morden	C18 and C19 snuff mill powered by water. The north wing is subject to a Section 106 agreement. There is slow
DESIGNATION:	Listed Building grade II, CA	progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the north
CONDITION:	Fair	wing by Wandle Industrial Museum. Discussions are ongoing to resolve these outstanding issues.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1080857	Contact: Jill Tyndale (LPA) 020 8545 3041

Portland stone mausoleum from the end of the CI9. Bazalgette was the designer of the main London trunk sewer system and the builder of the Victoria and Albert Embankments in the 1860s. The ironwork requires repair and the gates are missing. Water ingress is causing gradual collapse of the internal brickwork to the roof. A condition survey has been carried out, funded by Historic England. The church, Local Authority, Historic England and other stakeholders are working together to secure funding to enable the necessary works to be carried out.

Contact: Jill Tyndale (LPA) 020 8545 3041

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE-

use)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Mausoleum of Sir Joseph William Bazalgette, St Mary's Churchyard, St Mary's Road,

Listed Building grade II, CA

Wimbledon SW19

Poor

N/A

A (A)

Unknown

1080887

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS			
CA	Conservation Area		
LB	Listed Building		


- LPA Local Planning Authority
- NP National Park
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site WHS

LIST ENTRY NUMBER:

1080888

	SITE NAME:	Tomb of Gerard De Visme 10 Feet to north of west tower of Chapel in Churchyard of St Mary, St Mary's Road, Wimbledon SW19	Stone tomb of Gerard de Visme, who died in 1797, consisting of a square plan, rusticated pyramid with corner acroteria to the base. An acroterion has fallen due to movement in the stone blocks, and another is dislodged. Slow deterioration continues. A condition survey has been
	DESIGNATION:	Listed Building grade II, CA	carried out, funded by Historic England. The church, Local Authority and Historic England are working together to
	CONDITION:	Poor	secure funding to enable the necessary works to be carried out.
P. Share	OCCUPANCY:	N/A	out.
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080883	Contact: Jill Tyndale (LPA) 020 8545 3041
	SITE NAME:	Tomb of Bankes, St Mary's Churchyard, St Mary's Road, Wimbledon SW19	Table tomb from the mid C18 with inset panels and baluster profiled corners. The tomb is suffering from continued waste dumping activity. It has been previously
	DESIGNATION:	Listed Building grade II, CA	subject to poor quality repairs. A condition survey has been carried out, funded by Historic England, and funding
RTT.	CONDITION:	Poor	will be sought to enable the necessary works to be carried out.
	OCCUPANCY:	N/A	out.
	PRIORITY CATEGORY:	C (C)	
c	OWNER TYPE:	Unknown	

© Historic England





SITE NAME: Table tomb on a stepped podium, dating from circa 1704. Tomb of John Lawson, St Mary's Churchyard, St Mary's Road, There is evidence of joints widening and the plinth Wimbledon SW19 collapsing. A condition survey has been carried out, funded by Historic England. The church, Local Authority and DESIGNATION: Listed Building grade II, CA Historic England are working together to secure funding to enable the necessary works to be carried out. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1080886 Contact: Jill Tyndale (LPA) 020 8545 3041

© Historic England



	SITE NAME:	Base of windmill at Mill House, Windmill Road	Brick with timber framing comprising the base of a hollow- post windmill. It is located within the car park of the Mill
	DESIGNATION:	Listed Building grade II	House public house with its timber superstructure exposed to the elements. The owners have undertaken works to
	CONDITION:	Fair	preserve the timbers which have now been reinstated. The structure remains at risk without a protective cover.
	OCCUPANCY:	N/A	Repairs are now required to the supporting walls.
- ALASSA	PRIORITY CATEGORY:	C (C)	
ALTERN CONTRACTOR	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1194005	Contact: Jill Tyndale (LPA) 020 8545 3041

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Jill Tyndale (LPA) 020 8545 3041

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

	SITE NAME:	Wall to rear of flats, 27-33 (consecutive), Windsor Avenue, Colliers Wood SW19	Fragment of medieval, and probably later, precinct wall of the former Merton Priory. Constructed from flint and rubble stone, it is being damaged by vegetation growing out
	DESIGNATION:	Listed Building grade II, CA	of the wall structure.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1080856	Contact: Jill Tyndale (LPA) 020 8545 3041

SITE NAME:	Merton Priory	(site of), Merantun Way, Colliers W	ood SW19	
DESIGNATION:	Scheduled Monument, part in CA		LIST ENTRY NUMBER:	1001976
CONDITION: Generally satisfactory but with significant localised problems		TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission		NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners		CONTACT:	Elizabeth Whitbourn 07889 808145
	SITE NAME:	Wimbledon Park SW19	A remnant of the	CI8 landscape by Lancelot 'Capability'
	DESIGNATION:	Registered Park and Garden grade II*, 2 CAs	Wimbledon, itse	t Earl Spencer's manor house at If developed from a C16 estate. The Loc es Brown's lake and land to the east as a



CONDITION:

TREND:

VULNERABILITY:

NEW ENTRY ?:

OWNER TYPE-

LIST ENTRY NUMBER:

High

No

Declining

1000852

Mixed, multiple owners

© Historic England

Authority manages Brown's lake and land to the east as a municipal park with an emphasis on sport, with land to the Generally unsatisfactory with west in private ownership as golf and sports clubs. The major localised problems divided ownership results in differential landscape management. A masterplan exists for the municipal park, and a project to address lake safety is underway. Proposals for major new development on the golf course may deliver considerable investment across the site.

Contact: Christopher Laine 07780 545 979

SITE NAME:	Bathgate Road SW19		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Drax Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	The Broadway		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Unknown
VULNERABILITY:			
VOENERABIENTI.	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	High Upper Morden	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
		CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Upper Morden		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS

Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MERTON / NEWHAM

SITE NAME:	Wimbledon Chase		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Wimbledon Hill Road		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jill Tyndale (LPA) 020 8545 3041

NEWHAM

© Historic England



	SITE NAME:	Police Station, with walls and gatepiers to side, High Street South, E6	Red brick police station with Portland stone dressings and bands, and a slate roof. 1904, by John Dixon Butler for the Metropolitan Police. The building has been vacant since
THE	DESIGNATION:	Listed Building grade II, CA	2013. Repairs have been carried out to the roof. Applications for Planning Permission and Listed Building
	CONDITION:	Poor	Consent were submitted in spring 2021 for works in relation to re-use of the building for educational purposes
	OCCUPANCY:	Vacant/not in use	but have yet to be determined.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1253087	Contact: Ben Hull (LPA) 020 3373 9574



© Historic England



SITE NAME:	West Ham Pumping Station Engine House, Abbey Road EI5	Engine house, built in 1897, containing original Lilleshall Company beam engines. The building is currently in use as
DESIGNATION:	Listed Building grade II	a training facility. Discussions are ongoing regarding the future of this site but there are no specific plans as yet
CONDITION:	Fair	identified.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1357997	Contact: Ben Hull (LPA) 020 3373 9574

1.	SITE NAME:	Barking Road, East Ham E6 ground a	mpressive corner public house dating from 1900. The ground and first floor function rooms are being used for
	DESIGNATION:	Listed Building grade II	weddings and parties. The flats on the upper floors are vacant. Restoration works were undertaken following fire
TIM	CONDITION:	Fair	damage. There is some unauthorised signage and repairs are needed to the cornice and string courses. Planning
	OCCUPANCY:	Part occupied/part in use	consents were secured in spring 2021 for conversion and extension for residential and community uses. Works hav not yet started on site.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1392558	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

1	SITE NAME:	Coach and Horses public house, 100, High Street, Plaistow E13	Three-storey C18 public house, yellow brick with red brick arches and reveals. The interior has been extensively
	DESIGNATION:	Listed Building grade II	damaged. Planning Permission and Listed Building Consent have been granted for conversion of the building into
	CONDITION:	Poor	residential units. Works are on-going.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1080959	Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



Chimney dating from 1887 to 1889, designed by Joseph Chimney to Beckton Sewage Bazalgette, as part of the improvements to the northern Works, Jenkins Lane, Beckton E6 outfall of the London drainage network. Listed Building Consent has been granted for works to facilitate the Lee Listed Building grade II Tunnel and Beckton extension works. The chimney has been dismantled and is in storage, pending re-erection Poor following completion of the tunnelling works. Regular N/A surveys are carried out to review its condition and maintenance works are being undertaken based on these D (D) findings. Utility 1393160 Contact: Ben Hull (LPA) 020 3373 9574

© Historic England



	SITE NAME:	Silo D, North Woolwich Road, Canning Town E16	Grain silo, 1920, built of reinforced concrete. Vegetation threatening the building has been mostly cleared but pigeon
	DESIGNATION:	Listed Building grade II	ingress remains an issue. Discussions are ongoing as to how the building might be brought back into use as part of the
	CONDITION:	Poor	overall development of the wider site but there are currently no specific plans.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1245030	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England



© Historic England

No. of Concession, Name	PRIORITY CATEGORY:	C(C)	
Sale -	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1245030	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	North Woolwich Station including turntable and platform lamp standards, Pier Road, North Woolwich E16	Former railway station, 1847. Extensive works are needed to the roof, and the rear canopy has been dismantled following partial collapse. Essential remedial works were carried out prior to recent sale of the building. Discussions
	DESIGNATION:	Listed Building grade II	are now taking place between the new owners, Historic England and the Local Authority to identify a suitable
nn	CONDITION:	Poor	scheme for the full repair and re-use of the building.
	OCCUPANCY:	Part occupied/part in use	
Sector Sector	PRIORITY CATEGORY:	C (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1376229	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Earl of Essex public house, 616, Romford Road, Newham E12	Impressive Edwardian public house by Henry Poston and WE Trent, dating from 1902, on a prominent corner site.
	DESIGNATION:	Listed Building grade II	The ground floor is empty and boarded up, with no future use identified. The upper floors are occupied. Repairs are
THIT FOR THE TATE	CONDITION:	Fair	needed, particularly to external architectural details. Planning Permission and Listed Building Consent have been
	OCCUPANCY:	Part occupied/part in use	granted for the refurbishment and extension of the building
	PRIORITY CATEGORY:	D (D)	for use as a public house and restaurant, with residential accommodation on upper floors. Works have yet to
	OWNER TYPE:	Commercial company	commence on site.
c England	LIST ENTRY NUMBER:	1357990	Contact: Ben Hull (LPA) 020 3373 9574

© Historic



	SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16	Restaurant, built in 1883 to the design of Vigers and Wagstaffe in a free Classical style. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Poor	repairs undertaken. Planning Permission and Listed Building Consent have been granted for restoration and use as a
	OCCUPANCY:	Vacant/not in use	restaurant as part of the wider Royals Business Park
沿	PRIORITY CATEGORY:	F (F)	development of Albert Dock. The implementation phase of these plans is imminent.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1380201	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / NEWHAM / REDBRIDGE

TAGE AT RISK 2021 / LONDO	on and south east	/ NEWHAM / REDBRIDGE	
	SITE NAME:	Central offices at Custom House, Royal Albert Dock E16	Offices, built in 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Poor	repairs undertaken. Planning Permission and Listed Building Consent have been granted for restoration and use as a
	OCCUPANCY:	Vacant/not in use	club and art gallery as part of the wider Royals Business
	PRIORITY CATEGORY:	F (F)	Park development of Albert Dock. The implementation phase of these plans is imminent.
	OWNER TYPE:	Commercial company	
oric England	LIST ENTRY NUMBER:	1376228	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Spotted Dog public house, 212, Upton Lane E7	Weatherboarded C15 timber-framed public house. The property has remained vacant for some years. Urgent repairs have been carried out to stabilise the building. Planning Permission and Listed Building Consent have bee secured for the repair and re-use of the building as pub, restaurant and hotel.
E JUR	DESIGNATION:	Listed Building grade II	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
oric England	LIST ENTRY NUMBER:	9 297	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	West Ham Court House, West Ham Lane E15	The first Court House of 1884, to the design of Lewis Angell, was extended symmetrically in 1905 to provide a
	DESIGNATION:	Listed Building grade II, CA	second courtroom. Having been vacated it suffered from theft, vandalism and decay over many years, as well as from
	CONDITION:	Very bad	fire damage in 2014, resulting in the loss of much of the historic interior. In 2019 the Local Authority undertook to
	OCCUPANCY:	Vacant/not in use	remove asbestos and decayed fabric, to stabilise the

© Historic England

© Histo

© Histo



Northern block and courtyard walls of Alice Billings House, Stratford EI5 Listed Building grade II, part in DESIGNATION: CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

SITE NAME:

C (C)

1080974

1443788

Local authority

© Historic England

Contact: Ben Hull (LPA) 020 3373 9574

surviving walls and to protect the site. This work was

exploring its long-term future.

Contact: Ben Hull (LPA) 020 3373 9574

completed in early 2020 with partial grant funding from Historic England. The Local Authority is committed to

A block of firemen's accommodation built for the West

from the fire station building. The building was used for

deteriorating for many years. The Local Authority is exploring options for its re-use.

offices from the 1980s. It has since been vacant and slowly

Ham Fire Brigade c1905-06; a rare example of the incorporation of a practice hose/drying tower separate

REDBRIDGE

	SITE NAME:	831, High Road, Ilford	Shop with circa 1900 interior, featuring striking glazed
	DESIGNATION:	Listed Building grade II	decorative wall tiling and Minton floor tiling. The tiles have been severely damaged by nailed studwork and
	CONDITION:	Poor	plasterboard to the wall, and cement screeding of the floor. The building is in need of major tile repairs and
	OCCUPANCY:	Occupied/in use	replacements to restore the interior. An application for Listed Building Consent was refused in 2017. A suitable scheme of repair and conservation is awaited.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1271968	Contact: Suzanne Lansley (LPA) 020 8708 6690

© London Borough of Redbridge

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / REDBRIDGE

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



	SITE NAME:	The Grotto, Wanstead Park EII	Ruined grotto boathouse of circa 1762. It consists of a honeycomb rockwork facade of segmental plan with
and the second	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	several arches at lake level, and window openings above. The area is fenced off from public access. The grotto has been managed as a ruin but its stability is threatened by
	CONDITION:	Poor	mortar failure, loss of rockwork, and self-sown vegetation. The City of London has carried out repairs and clearance,
	OCCUPANCY:	N/A	and commissioned a Conservation Management Plan to
	PRIORITY CATEGORY:	C (C)	identify the most appropriate approach to securing the structure's long term future. Further discussions are
容	OWNER TYPE:	Local authority	required to take this forward.
	LIST ENTRY NUMBER:	1183624	Contact: Suzanne Lansley (LPA) 020 8708 6690

© Historic England

© Historic England



	SITE NAME:	Garden Temple in garden of Temple House, 14, The Avenue, Wanstead E11	Garden temple, circa 1730-40, with lonic pedimented portico. The structure once formed part of the Wanstead Grove Estate. Extensive repairs to the roof and one of the
	DESIGNATION:	Listed Building grade II*, CA	columns have been carried out, grant-aided by Historic England. Further repairs are needed to the remaining
	CONDITION:	Poor	columns, which are showing signs of significant decay, as well as the decorative finishes. Structural and condition
	OCCUPANCY:	N/A	surveys were prepared in 2016 to inform these repairs,
	PRIORITY CATEGORY:	A (A)	with funding from Historic England. The Local Authority and Historic England are jointly considering options to
	OWNER TYPE:	Private	secure full repair of the structure.
	LIST ENTRY NUMBER:	1357974	Contact: Verena McCaig 020 7973 3718



© Historic England



Church of St Mary, Overton This church of 1790 was designed by architect Thomas Hardwick in the Neo-classical style. The chancel is designed around the monument to Sir Josiah Child. The Listed Place of Worship grade I, west end supports a Doric portico, hipped slate roof and a timber clock tower with open belfry and cupola. The interior has been redecorated and retains all original furnishings. The Portland stone masonry is spalling due to rusting cramps. Two elevations of repairs, including the clock turret, were repaired in 2018 funded by the National Lottery Heritage Fund. Funding is being sought for the repair of the two remaining elevations. Contact: lan Harper 020 7973 3786

> Gothic style church built as a chapel of ease to St Mary the Virgin and still sharing the parish. It was built between 1861 between 1867, to the designs of George Gilbert Scott; construction is of ragstone with ashlar dressings under slated roofs. The valley gutters were renewed in 2013. A specialist survey in the same year identified masonry at belfry level in a dangerous condition. Some emergency repairs have been done but the condition is worsening and there is a risk of falls of stone. The tower is in need of a comprehensive repair programme. The parish is

© Historic England

© Historic England



SITE NAME:	Wanstead Park EI2
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, 2 CAs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY ?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1000194

Drive, Wanstead EII

Religious organisation

Religious organisation

Christ Church, Wanstead Place,

Listed Place of Worship grade

RPG grade II*, CA

Poor

D (D)

1081008

II*, CA

Poor

B (B)

1081017

Wanstead EII

Contact: lan Harper 020 7973 3786

investigating sources of funding.

Remains of an important landscape dating from the late CI7 to the early CI9 and associated with George London and Humphry Repton, further developed in the late C19 by the City of London as a public park. The central area was converted to a private golf course in the early C20. Features of the historic designed landscape survive but are in poor condition. A Parkland Plan has been prepared and a steering group of stakeholders meets regularly to promote implementation. Possible sources of funding are being explored. A project to ensure the lakes comply with the Reservoirs Act is in development.

Contact: Christopher Laine 07780 545 979

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / REDBRIDGE / RICHMOND UPON THAMES

SITE NAME:	Mayfield, Ilford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Wanstead Park EII		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Woodford Bridge, Bridge		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690

RICHMOND UPON THAMES

A Latin	SITE NAME:	Boathouse and deep-water dock, riverside landing stage, steps, balustrade and gates, Thames Eyot, Cross Deep, Twickenham	Built in the 1870s as part of Frederick Chancellor's remodelling of the house and grounds of Poulett Lodge for William Punchard. The boathouse and dock are disused and falling into disrepair, with encroaching vegetation threatening the masonry. The balustrade is structurally
	DESIGNATION:	Listed Building grade II, CA	compromised and shows evidence of cracking and leaning. This also affects the landing stage and gates. Discussions
A REAL AND	CONDITION:	Poor	towards a solution are at an early stage with the owners.
	OCCUPANCY:	Vacant/not in use	
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1400159	Contact: Nicolette Duckham (LPA) 020 8891 7335

	SITE NAME:	Building number 14, Platts Eyot, Hampton	Late C19 office building in stock brick with an ogee-shaped cupola, formerly with a wooden balcony. It possibly once housed electric works and a boathouse to the ground floor. Long-term solutions for this building are being discussed as part of the expected overall strategy for Platts Eyot island. In May 2021, a fire broke out on the island which caused significant damage to several structures to the east of the island. It is understood that building number 14 also caught fire but fire fighters brought this under control. However the extent of any damage is not yet clear.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
9	LIST ENTRY NUMBER:	1254430	Contact: Lauren Way (LPA) 020 8891 7928

		Contact: Lauren VVay (LPA) 020 8891 7928
SITE NAME:	Loggia in the grounds of Thames Eyot, Cross Deep, Twickenham	Stone loggia of nine Doric columns, probably C18, situated in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The roof has suffered partial
DESIGNATION:	Listed Building grade II, CA	collapse and structural movement has caused distortion to the colonnade. An options appraisal was completed in
CONDITION:	Very bad	2011 but not taken forward. Time-limited Listed Building Consent has been granted for temporary propping of the
OCCUPANCY:	N/A	loggia with scaffolding. This has now been carried out and
PRIORITY CATEGORY:	C (C)	should prevent major loss of fabric whilst the freeholders develop a permanent scheme. Discussions with the
OWNER TYPE:	Private, multiple owners	freeholder and leaseholders are ongoing.
LIST ENTRY NUMBER:	1401819	Contact: Nicolette Duckham (LPA) 020 8891 7335

© Historic England

Ē

© Historic England

LIST ENTRY NUMBER: 1401819	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / RICHMOND UPON THAMES

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY.

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

1	SITE NAME:	Norfolk House, 8, Montpelier Row	C18 plain brown brick house with red window arches and many remaining original internal features. Vacant for some
	DESIGNATION:	DESIGNATION: Listed Building grade II*, CA years, a major water leak has caused considerable to the rear sections of the house, leading to proble	years, a major water leak has caused considerable damage to the rear sections of the house, leading to problems with
	CONDITION: Very had rot and damp. Initial works hav	rot and damp. Initial works have been carried out to the rear section of the roof through enforcement action by the	
	OCCUPANCY:	Vacant/not in use	Local Authority. The Local Authority are continuing to
	PRIORITY CATEGORY:	C (C)	make efforts to engage the absentee owners in order to ensure that appropriate works are carried out but this has
	OWNER TYPE:	Private	been with limited success to date. Alternative approaches are being explored.
ngland	LIST ENTRY NUMBER:	1065390	Contact: Verena McCaig 020 7973 3718

Pope's Grotto in grounds of

Radnor House School, Cross

Deep (east side), Twickenham

Listed Building grade II*, RPG

Educational (independent)

Church of England Cemetery

Listed Building grade II

Part occupied/part in use

Chapel, Grove Road, Richmond

grade II, CA

Fair

N/A

D (D)

1192178

Cemetery

A (New entry)

1261361

Charity (heritage)

Poor

© Historic Engl

© Historic England



SITE NAME:	Grotto or shell house in grounds of Thames Eyot, Cross Deep, Twickenham	Later C18 or early C19 grotto or shell house, altered in the mid C19, now in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The grotto is
DESIGNATION:	Listed Building grade II*, CA	decorated in a precise geometric pattern to resemble a coffered vault which is separated by a deep horizontal band
CONDITION:	Poor	from the more randomly decorated vertical walls. Considerable amounts of the shellwork have been lost or
OCCUPANCY:	N/A	damaged and it is in need of conservation to prevent
PRIORITY CATEGORY:	C (C)	further deterioration. Historic England has provided advice to the Local Authority and discussions with the freeholder
OWNER TYPE:	Private, multiple owners	and leaseholders are ongoing.
LIST ENTRY NUMBER:	1080812	Contact: Verena McCaig 020 7973 3718

Grotto with rusticated arched entrance facing the river,

with a long passage and two 'chapels'. The grotto is seen as the 'locus classicus' of English C18 garden history. The

structural condition is sound, but much of the decorative

lining is loose or missing. Conservation and cleaning of the

statuary, grant-aided by Historic England, was carried out in 2016. A pilot project on the South Chamber was

completed in 2017. The National Lottery Heritage Fund

Cemetery Chapel built in 1875 by Sir Arthur Blomfield.

and Heritage, it has operated as a nursery until major

structural problems meant it had to be vacated. The

separation of the gable wall from the roof. It is being

Contact: Nicolette Duckham (LPA) 020 8891 7335

monitored by structural engineers and currently cannot be

occupied. Funding is being sought to carry out propping

building is suffering from ground movement and subsidence, causing cracks above windows and the

and further investigative reports.

Formerly leased out by the locally-based charity Habitats

has awarded a grant which will enable the Trust to complete the preservation project and this work is

anticipated to take place in summer 2022.

Contact: Elizabeth Whitbourn 07889 808145



© Historic England



© Historic England



SITE NAME:	Boathouse 5 (easternmost 13 bays), Platts Eyot, Hampton	Timber-framed boathouse built in 1917 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build torpedo
DESIGNATION:	Listed Building grade II, CA	boats for the Admiralty. A full measured survey of the remaining structure has been completed, but it is in very
CONDITION:	Very bad	bad condition with a large area of collapse. Solutions for this structure, including the rebuilding of the Belfast trusses,
OCCUPANCY:	Vacant/not in use	will be discussed as part of the expected overall strategy
PRIORITY CATEGORY:	A (A)	for Platts Eyot. A fire broke out on the island in May 2021, however, and it is unclear at the time of writing if
OWNER TYPE:	Commercial company	Boathouse 5 was affected.
LIST ENTRY NUMBER:	1254429	Contact: Lauren Way (LPA) 020 8891 7928

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

ΪA Unitary Authority World Heritage Site WHS

H

HERITAGE AT RISK 2021 / LONDO	N AND SOUTH EAST /	RICHMOND UPON THAMES	
	SITE NAME:	Boathouse 2, Platts Eyot, Hampton	Timber-framed boathouse clad in corrugated zinc with a Belfast truss roof. It was constructed in 1916 by Augustine
LANG STRANGE ME	DESIGNATION:	Listed Building grade II, CA	Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May
	CONDITION:	Very bad	2021, a significant fire took place on the island which it is believed has destroyed a large extent of boathouse 2. The
	OCCUPANCY:	Unknown	cause of the fire has been established as accidental. Prior to
	PRIORITY CATEGORY:	A (C)	the fire, condition surveys were being carried out.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1254428	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME:	Boathouse 4, Platts Eyot, Hampton	Timber-framed boathouse clad in corrugated zinc with a Belfast truss roof. It was constructed in 1916 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May 2021, a significant fire took place on the island which it is believed has destroyed a large extent of Boathouse 4. The cause of the fire has been determined by the Fire Brigade as accidental. Prior to the fire, condition surveys were being carried out.
FILE	DESIGNATION:	Listed Building grade II, CA	
ALA TE	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (C)	
Contraction of the second s	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1261295	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME:	Wick House, Richmond Hill, Richmond	Designed by Sir William Chambers circa 1772 for Sir Joshua Reynolds. Planning Permission has been granted to
	DESIGNATION:	Listed Building grade II, CA	convert the building from a nurses' home to a single residence. Agreed stabilisation works have taken place to
	CONDITION:	Poor	address significant cracks in the later Victorian wing. Further applications for Planning Permission and Listed
	OCCUPANCY:	Vacant/not in use	Building Consent have been approved but no work has
	PRIORITY CATEGORY:	D (D)	taken place on site.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1263475	Contact: Nicolette Duckham (LPA) 020 8891 7335

	SITE NAME:	Doughty House, 142, Richmond Hill, Richmond	C18 house with C19 alterations, including the addition of an art gallery, made by the Cook family. Planning
	DESIGNATION:	Listed Building grade II, CA	Permission and Listed Building Consent have been granted to retain the main property as a single dwelling and to
	CONDITION:	Poor	convert the gallery (listed separately) to ancillary
	OCCUPANCY:	Vacant/not in use	accommodation, along with re-instating Doughty Cottage as the link between the house and gallery. An application for further work has been approved, including an alternative access arrangement, but work has not yet
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	restarted on site.
© Historic England	LIST ENTRY NUMBER:	1249955	Contact: Nicolette Duckham (LPA) 020 8891 7335

t n	SITE NAME:	The Gallery at Doughty House, 142, Richmond Hill, Richmond	Gallery built c1880 for Sir Francis Cook, extended 1915 by Brewer Smith, comprising eleven bays in giant lonic order
11	DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use	Listed Building grade II, CA	with balustrade, the lower order containing door and window openings between Doric pilasters. Works are
		Poor	needed to the roof, balustrade and rainwater goods. An application for further work has been approved, including
		an alternative access arrangement, but work has not yet	
	PRIORITY CATEGORY:	D (D)	restarted on site.
OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1387232	Contact: Nicolette Duckham (LPA) 020 8891 7335

© London Borough of Rich Thames

	PRIORITY CATEGORY:	
	OWNER TYPE:	Pr
nmond on	LIST ENTRY NUMBER:	13

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / RICHMOND UPON THAMES / SOUTHWARK

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Poor

D (D)

1393730

Religious organisation

	SITE NAME:	Air Raid Shelter, St Leonard's Court, St Leonard's Road, East Sheen SW14	Air raid shelter, probably built in 1938 to serve St Leonard's Court which was built in 1934-38 by local builder Mr FG Fox. It was designed to hold 48 people; at
Mar I	DESIGNATION:	Listed Building grade II	the time there were 83 flats. Locally-based charity Habitats and Heritage commissioned a structural survey leading to
	CONDITION:	Fair	minor works. Work and fundraising are ongoing to enable the building's use as an educational resource.
© Historic England	OCCUPANCY:	N/A	the building's use as an educational resource.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1395422	Contact: Nicolette Duckham (LPA) 020 8891 7335
	SITE NAME:	Church of St Michael and St George, Wilcox Road, Fulwell	Built in 1913, designed by John Standen Adkins. The church was closed in 2000 but is now being used for Church of
	DESIGNATION:	Listed Place of Worship grade II	England worship again. The Lady Chapel has been repaired and made fit for worship, as has the nave. The

Listed Place of Worship grade II and made fit for worship, as has the nave. The congregation has consent for some re-ordering to get the rest of the building back into beneficial use. Repairs to the fabric, renewal of services and the reordering works are due to commence later in 2021 and complete in 2022.

Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Platt's Eyot, Hampton		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lauren Way (LPA) 020 8891 7928

SOUTHWARK

	SITE NAME:	Office, Licensed Victuallers Almshouses, 12a, Asylum Road SE15	Annexe to the offices of the Licensed Victuallers' Almshouses, 1913-14 by FE Harford, in a restrained Baroque style. There are significant structural cracks to the
	DESIGNATION:	Listed Building grade II, CA	front and side elevations, and failing stonework at upper levels. The Local Authority is carrying out works to the
	CONDITION:	Very bad	pediment and flat roof. They have also commissioned investigatory works, including structural monitoring, and a
	OCCUPANCY:	Occupied/in use	suitable approach to securing the future of the building is
© Historic England	PRIORITY CATEGORY:	C (C)	being considered.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1376536	Contact: Catherine Jeater (LPA) 020 7525 5375
	SITE NAME:	Number 8, Addington Square and attached railings SE5	One of a pair of early C19 houses in the Addington Square Conservation Area. The house has suffered from
	DESIGNATION:	Listed Building grade II, CA	considerable water ingress owing to faulty rainwater goods, and there are signs of some structural movement,
	CONDITION:	Very bad	particularly to the porch. Some urgent works to the roof have been carried out. The property is likely to change
	OCCUPANCY:	Occupied/in use	hands in 2021.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	

© Historic England

C

PRIORITY CATEGORIES А

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

1376521

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Catherine Jeater (LPA) 020 7525 5375

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Railings and gates to Caroline Gardens, Asylum Road SEI5	Iron railings to the Licensed Victuallers' Almshouse complex, dating largely to circa 1830-40. Sections of the
	DESIGNATION:	Listed Building grade II, CA	ironwork are in a poor state of repair with some elements cracked or missing. Some backstays and a pair of gates
	CONDITION:	Poor	have been removed to storage. The Local Authority is pro- actively seeking funding to carry out a condition survey with
	OCCUPANCY:	N/A	a view to securing funding to carry out full conservation.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
nd	LIST ENTRY NUMBER:	1376543	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

© Historic England

© Historic England

©۲

10



	SITE NAME:	Licensed Victuallers Almshouses: Chapel, Asylum Road SE15	Former almshouse chapel, dating from 1827-31. The building is leased by the Local Authority to a local artists' group. The building suffered bomb damage in World War
	DESIGNATION:	Listed Building grade II, CA	II. Following completion of urgent repairs, jointly funded by the Local Authority and Historic England, the leaseholders
	CONDITION:	Poor	have been working closely with strategic funders and stakeholders to develop a long-term strategy. This is likely
	OCCUPANCY:	Occupied/in use	to lead to further funding bids and major conservation
	PRIORITY CATEGORY:	C (C)	works in the next couple of years to secure a fully sustainable future for the building.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1376538	Contact: Catherine Jeater (LPA) 020 7525 5375



Chest tomb from 1815 with original railings. Overgrowth SITE NAME: Chest tomb, St Mary Magdalene Churchyard, Bermondsey Street has caused damage to the stone and ironwork. Historic England has funded a condition survey and specification for SEI works to the tomb but the identified works have not yet DESIGNATION: Listed Building grade II, SM, CA been carried out. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1376573 Contact: Catherine Jeater (LPA) 020 7525 5375

the state of the second se			
Historic England	LIST ENTRY NUMBER:	1376578	Contact: Catherine Jeater (LPA) 020 7525 5375
	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	N/A	
	CONDITION:	Fair	carried out.
	DESIGNATION:	Listed Building grade II, CA	funded a condition survey and specification for works to the tomb but the identified works have not yet been
H h T p	SITE NAME:	Table tomb, St Mary Magdalene Churchyard, Bermondsey Street SEI	Unusual C18 table tomb under a stone canopy with tapered, fluted columns. There is some deterioration to the stone elements and railings. Historic England has



Ţ,	SITE NAME:	Tomb of John Sargeant, St Mary Magdalene Churchyard, Bermondsey Street SEI	England has funded a condition survey and specification fo
	DESIGNATION:	Listed Building grade II, CA	works to the tomb but the identified works have not yet been carried out.
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
C BE	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1376580	Contact: Catherine Jeater (LPA) 020 7525 5375

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDC	IN AND SOUTH EAST	/ SOUTHWARK	
	SITE NAME:	Presbyterian Chapel, 109, Borough Road SE1	Former Presbyterian chapel, 1846. Consent was granted in 2006 for facade retention and the conditions discharged,
	DESIGNATION:	Listed Building grade II, CA	but works ceased. South Bank University has been in discussion with the Local Authority and Historic England to
	CONDITION:	Very bad	develop appropriate plans for redevelopment of the building for student and community use. Planning
	OCCUPANCY:	Vacant/not in use	Permission and Listed Building Consent have now been
	PRIORITY CATEGORY:	F (F)	secured for this scheme, stabilisation works have been carried out, and major works are now underway.
	OWNER TYPE:	Educational (state sector)	
© Historic England	LIST ENTRY NUMBER:	1378375	Contact: Catherine Jeater (LPA) 020 7525 5375
	SITE NAME:	Monument to Charles Waters, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1910 to Charles Waters. Marble group of a seated woman with book/bible in her lap embracing a small child on a battered plinth. The monument, which was leaning, has been returned to an upright position and stabilized However, the formers have been demaged
	DESIGNATION:	Listed Building grade II	stabilised. However, the figures have been damaged through cleaning processes and require assessment for
	CONDITION:	Poor	further repair. A scheme for stabilisation has been agreed but has yet to be carried out.
A second second	OCCUPANCY:	N/A	
and the second second	PRIORITY CATEGORY:	D (D)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1385530	Contact: Catherine Jeater (LPA) 020 7525 5375
	SITE NAME:	Monument to Rebekah Horniman, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1895 to Rebekah, wife of FS Horniman. In prominent bronze tablet depicting a figure of an angel is missing, presumed stolen. There are no current plans for its restoration.
	DESIGNATION:	Listed Building grade II	
the set	CONDITION:	Poor	
1 Province	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1385533	Contact: Catherine Jeater (LPA) 020 7525 5375
	SITE NAME:	38, Glengall Road, Peckham SEI5	Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. The Ionic entran
	DESIGNATION:	Listed Building grade II, CA	porch is in very bad condition, and the roof is not watertight to the rear.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1385563	Contact: Catherine Jeater (LPA) 020 7525 5375
	SITE NAME:	55, Great Suffolk Street SEI	Unaltered mid-C19 warehouse. The building is in a poor condition having been vacant for a number of years.
a partici	DESIGNATION:	Listed Building grade II	Applications for Listed Building Consent and Planning
43 712	CONDITION:	Poor	Permission have been secured for change of use from warehouse use to a mixed-use scheme comprising offices
	OCCUPANCY:	Vacant/not in use	at ground floor level with flats above. Works are yet to progress.
	PRIORITY CATEGORY:	D (D)	pi 061 033.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1393123	Contact: Catherine Jeater (LPA) 020 7525 5375
© Historic England			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



SITE NAME:East Lodge to Nunhead Cemetery, Linden Grove SEISOne of a pair of gate lodges dating from 1840, by James Bunstone Bunning, adjacent to the main entrance gates. The lodge is in a ruinous condition. Condition and structural surveys have been undertaken, along with a feasibility study, both jointly funded by Historic England and the Local Authority to inform options for the building's future. Enabling works have been carried out to stabilise the structure. The Local Authority has identified funding to repair the building for re-use and, following stakeholder consultation, is engaged in pre-application discussions on proposals.OWNER TYPE:I385647Contact: Catherine Jeater (LPA) 020 7525 5375			
DESIGNATION:Listed Building grade II, RPG grade II*, CAstructural surveys have been undertaken, along with a feasibility study, both jointly funded by Historic England and the Local Authority to inform options for the building's future. Enabling works have been carried out to stabilise the structure. The Local Authority has identified funding to repair the building for re-use and, following stakeholder consultation, is engaged in pre-application discussions on proposals.	SITE NAME:	East Lodge to Nunhead Cemetery, Linden Grove SE15	Bunstone Bunning, adjacent to the main entrance gates.
CONDITION:Very badthe Local Authority to inform options for the building's future. Enabling works have been carried out to stabilise the structure. The Local Authority has identified funding to repair the building for re-use and, following stakeholder 	DESIGNATION:		structural surveys have been undertaken, along with a feasibility study, both jointly funded by Historic England and
OCCUPANCY:Vacant/not in usethe structure. The Local Authority has identified funding to repair the building for re-use and, following stakeholder consultation, is engaged in pre-application discussions on proposals.PRIORITY CATEGORY:A (A)OWNER TYPE:Local authority	CONDITION:	Very bad	the Local Authority to inform options for the building's
PRIORITY CATEGORY: A (A) consultation, is engaged in pre-application discussions on proposals. OWNER TYPE: Local authority	OCCUPANCY:	Vacant/not in use	the structure. The Local Authority has identified funding to
Local autionty	PRIORITY CATEGORY:	A (A)	
LIST ENTRY NUMBER: 1385647 Contact: Catherine Jeater (LPA) 020 7525 5375	OWNER TYPE:	Local authority	proposals.
	LIST ENTRY NUMBER:	1385647	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England



(k)	SITE NAME:	Tomb of Maria Proom, Nunhead Cemetery, Linden Grove SE15	Visually prominent monument of 1872 in pink and grey granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure presents a
B.	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	praying figure carried on a tall column and plinth, and an angel statue at its base which was perhaps originally unrelated to the monument. The railings around it are
	CONDITION:	Fair	missing. There is concern over the structural stability of t monument due to ground subsidence nearby. Further
198	OCCUPANCY:	N/A	investigations are required.
4	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	38565	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England



© Historic England



© London Borough of Southwark



SITE NAME:	The Kentish Drovers public	Mid-C19 public house, now partly in use as a restaurant.
LIST ENTRY NUMBER:	1385671	Contact: Catherine Jeater (LPA) 020 7525 5375
OWNER TYPE:	Religious organisation	
PRIORITY CATEGORY:	A (A)	conservation of the building.
OCCUPANCY:	Vacant/not in use	discussing further steps to secure the repair and
CONDITION:	Very bad	urgent repairs required; however, these have not been carried out. The Local Authority and Historic England are
DESIGNATION:	Listed Building grade II, CA	suffering from structural movement and lack of maintenance. Historic England has provided advice on
SITE NAME:	St Peter's Church Hall, 522, Lordship Lane, East Dulwich SE22	Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Lordship Lane, East Dulwich SE22DESIGNATION:Listed Building grade II, CACONDITION:Very badOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Religious organisationLIST ENTRY NUMBER:1385671

r	SITE NAME:	The Kentish Drovers public house, 720, Old Kent Road, Peckham SEI5	Mid-C19 public house, now partly in use as a restaurant. The Local Authority commissioned a specialist survey of the damaged tiled mural and full conservation works
	DESIGNATION:	Listed Building grade II	commenced in 2020 using Section 106 funding.
	CONDITION:	Fair	
R.	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1385740	Contact: Catherine Jeater (LPA) 020 7525 5375

	SITE NAME:	112, Peckham Park Road, Peckham SE15	One of a group of four pairs of early C19 houses. The house is in a poor state of repair, in particular the exterior,
	DESIGNATION:	Listed Building grade II	and continues to deteriorate.
-	CONDITION:	Very bad	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1385765	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

use).

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

N. M	SITE NAME:	40, Queens Road, Peckham SEI5	Early-C19 terraced building. The building is in poor condition and has suffered from extensive unauthorised
	DESIGNATION:	Listed Building grade II	works.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ic England	LIST ENTRY NUMBER:	1385796	Contact: Catherine Jeater (LPA) 020 7525 5375

	SITE NAME:	Former Clare College Mission Church, Southwark Park SE16	Former mission church of circa 1900 and 1911-1912, by John W Simpson and Maxwell Ayrton, built for Clare
A GP	DESIGNATION:	Listed Building grade II	College, Cambridge in Italianate style. The walls are ferro- concrete with shallow pitched tiled roofs. Following
	CONDITION:	Poor	refurbishment, the building is used as gallery space by the Bermondsey Artists' Group, There are further repairs
Restored To The Party of the Pa	OCCUPANCY:	Occupied/in use	Bermondsey Artists' Group. There are further repairs required to external walls and tile detail, and investigation
AN , IN	PRIORITY CATEGORY:	C (C)	necessary into structural movement. The Local Authority and Historic England are helping to advise the Group.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1385919	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

© Historic



© Historic England



	SITE NAME:	Number 1 and attached railings, 1, Stamford Street SE1	Mid-C19 red brick building that occupies a prominent position looking towards Blackfriars Bridge. Works to
	DESIGNATION:	Listed Building grade II	convert the building to offices are at an advanced stage. An application for Listed Building Consent has been secured
	CONDITION:	Fair	for extensive repairs and repointing to the flank wall, which is the last phase in the repair of the building. These works
815-	OCCUPANCY:	Occupied/in use	have yet to commence.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1385933	Contact: Catherine Jeater (LPA) 020 7525 5375
5	SITE NAME:	Peckham Rye Station, Station Way, Peckham SEI5	The station is an H-shaped building, built in 1864-65 by Charles Henry Driver for the London, Brighton and South East Coast Bailway. The porthern wing has been
			East L Dast Kallw/av Line northern wing has been

DESIGNATION:	Listed Building grade II, 2 CAs	East Coast Railway. The northern wing has been refurbished and brought back into use. Discussions are
CONDITION:	Fair	ongoing to bring the vacant areas in the southern wing back into use. Works to restore the staircase are complete,
OCCUPANCY:	Part occupied/part in use	funded by the Railway Heritage Trust, the Local Authority
PRIORITY CATEGORY:	C (D)	and Network Rail following local campaigns. Network Rail is consulting on a wider station upgrade.
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1392389	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England



SITE NAME: Beltwood House, 41, Sydenham Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. The house was remodelled in Hill, Camberwell SE26 the Neoclassical style circa 1895. The building contains fine DESIGNATION: Listed Building grade II, CA interiors, but is currently partially occupied by live-in guardians and suffering from the effects of water ingress. CONDITION: Poor The curtilage buildings are in a very poor state of repair. OCCUPANCY: Part occupied/part in use Planning Permission and Listed Building Consent have now been granted for conversion to flats, with development in PRIORITY CATEGORY: F (F) the surrounding gardens. Works have commenced on site following consents being granted for amendments to the OWNER TYPE: Commercial company scheme. LIST ENTRY NUMBER: 1385958 Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

_	
PR	NORITY CATEGORIES
	Increased in the state of fronthe on sensi

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ŬA Unitary Authority World Heritage Site WHS



	SITE NAME:	Southwark Municipal Offices and attached railings, Walworth Road SE17	Built as a vestry hall circa 1863-64, then later used as a town hall and more recently as municipal offices for Southwark Council. The building was severely damaged by
	DESIGNATION:	Listed Building grade II, CA	fire in 2013. It has since been stabilised and remedial works have been undertaken, including construction of a new roof
	CONDITION:	Very bad	and provision of temporary roofing elsewhere. The Local Authority has identified a preferred developer for the
	OCCUPANCY:	Vacant/not in use	building and discussions are now taking place to finalise a
	PRIORITY CATEGORY:	C (C)	Section 106 Agreement prior to Listed Building Consent and Planning Permission being granted.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1386028	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

© Historic England

© Historic England



1.1	SITE NAME:	Kennedy, 305, Walworth Road, Walworth SE17	Former Kennedy sausage shop, circa 1923. A well- preserved example of a 1920s shop. Considerable works
	DESIGNATION:	Listed Building grade II, CA	have been undertaken to bring the shop back into use. Whilst it is now operating as a restaurant, further repair are required to historic detailing and it is expected that these will be carried out under the Walworth Road
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	Heritage Action Zone scheme.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1392595	Contact: Catherine Jeater (LPA) 020 7525 5375



	SITE NAME:	Former office to Denmark Hill Station, Windsor Walk SE5	The former office to Denmark Hill Station dates from 1864-66. The building is in a poor condition following a fire.
	DESIGNATION:	Listed Building grade II, CA	Planning Permission has been granted to convert the building to a café but this has not yet been implemented.
	CONDITION:	Poor	, , , ,
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
- 0	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1386053	Contact: Catherine Jeater (LPA) 020 7525 5375

- state	SITE NAME:	Church of St Mary Magdalene, Bermondsey Street, Bermondsey SEI	The church was rebuilt in the late CI7 on the site of a former medieval church developed from the Chapel of the Convent of Bermondsey, first recorded in the late CI3.The
	DESIGNATION:	Listed Place of Worship grade II*, CA	lower stages of the C15 tower are incorporated. The structure is weak, not helped by remodelling in 1830 and the 1880s. Stucco finished throughout on brick under slate
	CONDITION:	Poor	roof with copper gutters within parapets. The roof structures have been heavily repaired historically but are
17311 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	PRIORITY CATEGORY:	C (C)	still under stress. This is likely the cause of falls of plaster
	OWNER TYPE:	Religious organisation	from ceilings. Leakage through the copper gutters is hard to trace.
© Historic England	LIST ENTRY NUMBER:	1376567	Contact: Ian Harper 020 7973 3786



RA-	SITE NAME:	The Cross and Star Church, Falmouth Road, Bermondsey SEI	Built as a Presbyterian chapel in 1888 with Queen Anne and Romanesque influences. It is now the London base for the Church of the Brotherhood of the Cross and Star. It is
	DESIGNATION:	Listed Place of Worship grade II	constructed of red brick and gauged brickwork with stone dressings under a slated roof. The complete gallery survives
11.5	CONDITION:	Poor	internally, and the stained glass is good quality. The external fabric is in urgent need of repair, including re-
	PRIORITY CATEGORY:	C (C)	roofing, and repairs to brickwork, rainwater goods and the
	OWNER TYPE:	Religious organisation	stained glass windows. The congregation is actively engaged in discussion with potential funders to develop a repair
	LIST ENTRY NUMBER:	1385523	project.
			Contact: Ian Harpor 020 7072 2706

Contact: lan Harper 020 7973 3786

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Augustine, Honor Oak Park, Camberwell, Southwark SE23	The church was completed in 1873 by William Oakley, in Kentish ragstone with ashlar details and slated roofs. Underpinning was carried out in two phases in 1993 and
	DESIGNATION:	Listed Place of Worship grade II	2010. Also in 2010 repairs were carried out to masonry and high-level roofs. The latest phase of stonework repairs
	CONDITION:	Poor	and tower re-roofing was completed in 2014, with funding from the National Lottery Heritage Fund and Historic
	PRIORITY CATEGORY:	C (C)	England. Monitoring of the structure continues and funding
	OWNER TYPE:	Religious organisation	is being sought for further repairs which will be required in the future.
	LIST ENTRY NUMBER:	1385617	Contact: Ian Harper 020 7973 3786
and			

© Historic England



	SITE NAME:	Church of St Peter, Lordship Lane, Camberwell SE22	Work started on this church, by Charles Barry Jnr, in 1873 on land gifted by Dulwich College for a new parish formed
	DESIGNATION:	Listed Place of Worship grade II, CA	from St Giles Camberwell. The tower and spire were completed in 1875 and the vestry enlarged in 1893. The Church of England closed the church in 1984 and sold it to
	CONDITION:	Very bad	Worth Abbey who then sold it to the Deeper Life Bible Church. External masonry is in Kentish ragstone with Bath
	PRIORITY CATEGORY:	A (A)	stone dressings: internally the walls are banded in cream
	OWNER TYPE:	Religious organisation	London stocks and red brick. Slated roofs of the nave and timber-framed spire are in bad condition. There is
	LIST ENTRY NUMBER:	1385670	settlement on the north side aisle.
			Contact: Ian Harper 020 7973 3786

© Historic England

SITE NAME:	Roman boat at N	New Guy's House, Bermondsey SEI			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1001979	
CONDITION:	Generally satisfac problems	ctory but with significant localised	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Drainage/dewate	ering	NEW ENTRY?:	No	
OWNER TYPE:	Health authority	Health authority		Elizabeth Whitbourn 07889 808145	
SITE NAME:	The Rose Theatr	re, Rose Court, Southwark SEI			
DESIGNATION:	Scheduled Monu	Scheduled Monument		1012707	
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Drainage/dewate	ering	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial com	Commercial company, multiple owners		Elizabeth Whitbourn 07889 808145	
	SITE NAME:	ME: Nunhead Cemetery (All Saints) SEI 5		An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the	
NA COL	DESIGNATION: Registered Park and Garden grade II*, 13 LBs, part in CA		cemetery skilfully exploits the undulating topography to create picturesque effects and vistas. Vegetation and sel sown saplings are disrupting historic monuments and		
THE SALE OF	CONDITION:	Generally unsatisfactory with	obscuring the legibility of the landscape. The Local		

© Historic England

	Drainage/dewate	ring	NEW ENTRY?:	No		
	Commercial com	pany, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145		
	SEI5		An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the			
	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, part in CA	create picturesqu	exploits the undulating topography to e effects and vistas. Vegetation and self- disrupting historic monuments and		
	CONDITION:	Generally unsatisfactory with major localised problems	obscuring the legibility of the landscape. The Local Authority is developing plans to restore the East Lod which is a longstanding building at risk, a programme memorial safety works is underway, and a comprehe tree survey is informing an updated Conservation Management Plan for the whole of the designed lands			
	VULNERABILITY:	High				
	TREND:	Declining				
	NEW ENTRY ?:	No	5	5		
	OWNER TYPE:	Local authority				
	LIST ENTRY NUMBER:	1000824	Contact: Christo	pher Laine 07780 545 979		

SITE NAME:	Nunhead Cemetery, Nunhead SE15		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Catherine Jeater (LPA) 020 7525 5375

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Walworth Road, Walworth		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Catherine Jeater (LPA) 020 7525 5375

SU	TΤ	ON

	SITE NAME:	Boundary walls to Beddington Place along east side of churchyard and along Church Lane, Church Road	Substantial length of C16 or C17 wall of red brick with battered coping and roll moulding. Sections have been buttressed. The brickwork needs substantial repairs, including extensive repointing, replacement of brickwork,
	DESIGNATION:	Listed Building grade II, CA	and repair of buttresses. Tree growth has threatened stability and vegetation is causing damage. The wall has
The second second second	CONDITION:	Poor	suffered extensive graffiti on some sections. A first phase of works has been completed with more planned once the
公司的规则	OCCUPANCY:	N/A	ground has settled following vegetation removal.
ALC: NO	PRIORITY CATEGORY:	C (C)	Applications for Planning Permission and Listed Building Consent for further repairs are being assessed.
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1357592	Contact: Dean James (LPA) 0208 770 5000

pilasters and brick quoins at intervals. Vegetation and				
DESIGNATION: Listed Building grade II, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation		SITE NAME:	Churchyard walls, Church Road	Circa C19 walls of dressed flint with rounded tops, with
CONDITION: Fair mortar failure has led to the loss of flints from others. The church has undertaken full repair of extensive sections of the flint wall and these are now in good condition. PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation		DESIGNATION:	Listed Building grade II, CA	mechanical damage caused some sections to collapse, and
OCCUPANCY: N/A the flint wall and these are now in good condition. PRIORITY CATEGORY: C (C) However, there remain some localised areas where more has deteriorated leading to the loss of flints, and brick sections require vegetation clearance, mortar and brickwork repair.		CONDITION:	Fair	mortar failure has led to the loss of flints from others. The
PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: LOCE (7)		OCCUPANCY:	N/A	the flint wall and these are now in good condition.
OWNER TYPE: Religious organisation sections require vegetation clearance, mortar and brickwork repair.		PRIORITY CATEGORY:	C (C)	
		OWNER TYPE:	Religious organisation	sections require vegetation clearance, mortar and
		LIST ENTRY NUMBER:	1065671	

© Historic England

©۲

	SITE NAME:	Garden walls at Beddington Place (Carew Manor Special School) to north of Orangery walls, Church Road	C17 to C18 garden walls. The east, south and part of the north walls to the east of Beddington Park Cottages are of brick with battered coping; the west wall is of a later date with plain capping. Damage has been largely caused by
and the state	DESIGNATION:	Listed Building grade II, CA	vegetation, and upper brick courses have been completely dislodged in some sections. The brickwork is in need of
AR DIA	CONDITION:	Very bad	substantial repairs, including extensive repointing and rebuilding of upper sections.
Contraction of the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
) Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1200792	Contact: Dean James (LPA) 0208 770 5000

all the second sec	SITE NAME:	Orangery wall to Beddington Place, Church Road, Beddington	Orangery wall of circa 1720. It has previously been subject to severe vandalism. The soft brickwork is susceptible to
	DESIGNATION:	Listed Building grade II, CA	erosion and there is invasive plant and shrub growth. There are currently no plans in place to address these issues.
	CONDITION:	Poor	
Constant in the second second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1065673	Contact: Dean James (LPA) 0208 770 5000

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Alexan	SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton	Early C18 grotto in Carshalton Park. The exterior of the grotto has symmetrical curved walls of brick, ramped up
	DESIGNATION:	Listed Building grade II, CA	gradually to a central peak. The grotto is vulnerable to vandalism and graffiti and is currently threatened by
	CONDITION:	Poor	significant vegetative growth. Survey work has been carried out to assess the extent of repairs needed but no plans
	OCCUPANCY:	N/A	have been brought forward.
	PRIORITY CATEGORY:	C (C)	
the we have a	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1065628	Contact: Dean James (LPA) 0208 770 5000
A A A A A A A A A A A A A A A A A A A	SITE NAME:	Parish Church of St Mary the	CI4 in origin, the church was much rebuilt with additions ir

	SITE NAME:	Parish Church of St Mary the Virgin, Church Road, Beddington	C19 by Joseph Clarke. The dormer windows were added in 1914 by HP Burke Downing. The interior has decorative
	DESIGNATION:	Listed Place of Worship grade II*, CA	Victorian wall paintings and there is a monument to Richard Carew (d.1520) which is suffering from cracking and friable stone. The tower exhibits cracks, open joints
CREWN CONTRACTOR AND A	CONDITION:	Poor	and past cementitious repairs. The congregation is in receipt of a grant from the National Lottery Heritage Fund
Startes	PRIORITY CATEGORY:	D (D)	for repairs to the tower and anticipate commencing work
	OWNER TYPE:	Religious organisation	in 2021.
© Historic England	LIST ENTRY NUMBER:	1065670	Contact: Tracey Craig 020 7973 3756

SITE NAME:	Sutton Town Centre High Street Crossroads, Sutto	on	
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Dean James (LPA) 0208 770 5000

TOWER HAMLETS

© London

	SITE NAME:	34, Mount Terrace, Whitechapel EI	Late C18/early C19 stock brick end of terrace house of three storeys with a basement, mansard roof and round
	DESIGNATION:	Listed Building grade II, CA	headed door with a fanlight. This was originally part of a development of two rows of 17 houses constructed for the
	CONDITION:	Very bad	City Corporation. The building is empty and is suffering from neglect with some structural cracking visible on the
	OCCUPANCY:	Vacant/not in use	front elevation. The ownership has recently changed and work to secure the building has been carried out. The Local Authority is liaising with the owner and is anticipatir
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Health authority	applications for Planning Permission and Listed Building Consent in due course.
on Borough of Tower Hamlets	LIST ENTRY NUMBER:	1065122	Contact: Andrew Hargreaves (LPA) 020 7364 5576



© London Borough of Tower Hamlets

SITE NAME:	Drinking fountain, Stepney Green El	Red and grey granite drinking fountain with a large red bowl, trefoil headed plaques and a small truncated spire.
DESIGNATION:	Listed Building grade II, CA	Erected in 1884 at Rutland Street School (now demolished) in memory of Leonard Montefiore, East End philanthropist,
CONDITION:	Poor	and moved to its current location in 1939. The fountain is not functioning and has missing architectural details from
OCCUPANCY:	N/A	the top of the spire. Funding has been secured for the
PRIORITY CATEGORY:	C (C)	repair of the fountain and the reinstatement of its water supply. This is part of a wider project to restore three
OWNER TYPE:	Local authority	drinking fountains in Tower Hamlets.
LIST ENTRY NUMBER:	1065062	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

107

SITE NAME:



SITE NAME:	One Lamp Standard in front of the Star of the East Public House, Commercial Road E14	One of the three C19 lamp standards on the pavement in front of the Star of the East Public House. A cast iron decorative lantern bearing the inn name with poor and
DESIGNATION:	Listed Building grade II, CA	defective paintwork. Two lamp standards were repaired separately in 2019 and their lanterns are now working. The
CONDITION:	Poor	Local Authority is working with the owner to secure funding to repair and reinstate the remaining lantern.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (D)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1065199	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© London Borough of Tower Hamlets




SITE NAME: Ragged School Museum, 46 and The Ragged School, now museum, was opened as a free school for poor children in the East End in 1877 by Dr 48, Copperfield Road E3 Barnardo, in converted warehouses on the Grand Union DESIGNATION: Listed Building grade II, CA Canal. The building remains underutilised due to the poor condition of the roof, originally slated but replaced with CONDITION: Poor asbestos-cement sheeting after a fire in the mid C20. There OCCUPANCY: Part occupied/part in use are also structural issues and damp problems. In 2020 the National Lottery Heritage Fund awarded a grant for a PRIORITY CATEGORY: F (C) repair project. Planning Permission and Listed Building Consent was granted in 2021 and work has begun on site OWNER TYPE: Charity (non-heritage) and is due to complete in spring 2022. LIST ENTRY NUMBER: 1065752 Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England



© Historic England



	at St Clements Hospital, Bow Road, Bow E3	the redundant St Clements Hospital. The freehold has been transferred to the Greater London Authority.
DESIGNATION:	Listed Building grade II, CA	Planning Permission and Listed Building Consent was granted for the conversion of the former hospital to
CONDITION:	Poor	housing, and works are now close to completion. The gates have been removed from site for conservation
OCCUPANCY:	N/A	repairs and should be reinstated in early 2022.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1065276	Contact: Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Clements Hospital, Bow Road, Bow E3	Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. Th
		freehold has been transferred to the Greater London

Front wall, gate piers and gates

SITE NAME:	St Clements Hospital, Bow Road, Bow E3	Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. The
DESIGNATION:	Listed Building grade II, CA	freehold has been transferred to the Greater London Authority. Planning Permission and Listed Building Consent
CONDITION:	Poor	was granted for the conversion of the former hospital to housing, and works are now close to completion, which is
OCCUPANCY:	Part occupied/part in use	expected in early 2022.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1251493	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England



1	SITE NAME:	2 bollards (between statue of Gladstone and St Mary's churchyard entrance), Bow Road, Bromley-By-Bow E3	Two C19 bollards which formed a group along with St Mary's Church, its gates and railings and the statue of WE Gladstone. One of the bollards has been removed. The Local Authority is working towards reinstatement of the
-	DESIGNATION:	Listed Building grade II, CA	missing bollard.
A.I.	CONDITION:	Poor	
-	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1262757	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Decorative gates and railings forming the front boundary to

- Conservation Area Listed Building CA LB
- I PA

ÍΙΑ


- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- Unitary Authority World Heritage Site WHS
- 108

LIST ENTRY NUMBER:

1402561

A-JAF	SITE NAME:	Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3	Underground gentlemen's public convenience, constructed by the Board of Works and opened in 1899. There are curved entrance steps designed to fit around the statue of
	DESIGNATION:	Listed Building grade II, CA	WE Gladstone. The decorative interior finish includes russet marble urinals. The public convenience has been
	CONDITION:	Very bad	disused for many years and the decorative iron gates have been damaged. The interior is also subject to vandalism.
Lifely and Annual Constant of	OCCUPANCY:	Vacant/not in use	The Local Authority is investigating options for the site.
trastic legitic - Constant of River	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1392968	Contact: Andrew Hargreaves (LPA) 020 7364 5576
1. A. A.	SITE NAME:	Former Bromley Hall School, Bromley Hall Road, London E14	Former school for physically disabled children, built in 1967-8 by the Greater London Council's Architects'
State of the second second	DESIGN HETION I	·	Department and extended in 1978-9. The building has a
Contraction of Contract, South Proc. 1997	DESIGNATION:	Listed Building grade II	
	CONDITION:	Listed Building grade II Poor	distinctive architectural form which reflects the local industrial vernacular. It has been vacant for several years
		00	distinctive architectural form which reflects the local industrial vernacular. It has been vacant for several years following changes in educational requirements. The Local Authority is considering options for the refurbishment and
	CONDITION:	Poor	distinctive architectural form which reflects the local industrial vernacular. It has been vacant for several years following changes in educational requirements. The Local
	CONDITION: OCCUPANCY:	Poor Vacant/not in use	distinctive architectural form which reflects the local industrial vernacular. It has been vacant for several years following changes in educational requirements. The Local Authority is considering options for the refurbishment and

© Historic England



© Historic England	SITE NAME:	Limehouse District Library, Commercial Road, Limehouse E14	Former Passmore Edwards Library. Built in 1900 by Messrs Clarkson Architects. The library is closed and the building vacant and boarded up. Planning Permission and Listed
	DESIGNATION:	Listed Building grade II, CA	Building Consent was granted to convert the building to student accommodation with associated educational and ancillary facilities. Works are due for completion at the enc of 2021.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357807	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	Former Caird & Rayner Ltd Warehouse, 777-783, Commercial Road E14	Former sail makers and ship chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. The building was fire damaged, resulting in the
	DESIGNATION:	Listed Building grade II, 2 CAs	loss of its roof covering. Urgent works were completed in April 2010. The Local Authority has approved Planning Permission and Listed Building Consent for the conversion of the building to office use as part of the wider development of the site. Works have now commenced or
© Historic England	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (B)	site and completion is expected in late 2022.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	385372	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

ര

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Andrew Hargreaves (LPA) 020 7364 5576

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

1065113

A T	SITE NAME:	Drinking fountain (on paver outside 31-74 Mile End Roa Mile End Road, Stepney E1
UNTTENT	DESIGNATION:	Listed Building grade II, CA
& have	CONDITION:	Very bad
Contraction of the	OCCUPANCY:	N/A
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Government or agency

Late C19 polished granite drinking fountain, with a short fountain (on pavement column on a plinth. The drinking fountain has an inscription I-74 Mile End Road), commemorating its erection by the Metropolitan Cattle Trough and Drinking Fountain Association. The bowl has been removed. Funding has been secured for the repair of the fountain and the reinstatement of its water supply. This is part of a wider project to restore three drinking fountains in Tower Hamlets.


Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England



	SITE NAME:	St Saviours Church, Northumbria Street, Poplar E14	Former church dating from 1873-4 to the design of Frederick J and Horace Francis. The building was severely
à	DESIGNATION:	Listed Building grade II	damaged by fire in May 2007 and is currently propped by scaffolding. Following detailed negotiations, Planning
R	CONDITION:	Very bad	Permission and Listed Building Consent was granted for residential conversion and all pre-commencement planning
1	OCCUPANCY:	Vacant/not in use	conditions have been discharged. Work began on site in
	PRIORITY CATEGORY:	F (F)	February 2020 with an estimated completion date in early 2022.
19	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1242275	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© London Borough of Tower Hamlets



Hamlets F2 a local builder. A	weavers' tenement house built c1735 by William Farme ocal builder. An early survival of a building type that onc
DESIGNATION: Listed Building grade II, CA structural problem	alfields. The building is derelict and has ems. It was recently braced to prevent
CONDITION: Very bad further moveme Planning Permis	ent and the building is wind and watertight. sion and Listed Building Consent for retail
OCCUPANCY: Vacant/not in use use have been g	granted and applications to discharge
PRIORITY CATEGORY: F (D) conditions are b the structural st	being discussed. Urgent repairs to secure tability of the front elevation are being
OWNER TYPE: Private carried out.	,
LIST ENTRY NUMBER: 1393497 Contact: Andre	ew Hargreaves (LPA) 020 7364 5576

© Historic England

© Historic England



LIST ENTRY NOMBER:	1393497	Contact: Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Tomb of Joseph Westwood, Southern Grove, Tower Hamlets Cemetery E3	A prominent funerary tomb dating from 1883, in the form of a Decorated style wayside cross. It is in poor condition due to general decay and the loss of parts of its low railings,
DESIGNATION:	Listed Building grade II, CA	tiles, finials and other detailing. The Local Authority commissioned a monument safety survey in 2019. The
CONDITION:	Poor	Friends of Tower Hamlets Cemetery Park, who manage the site on behalf of the Local Authority, are working on a
OCCUPANCY:	N/A	Conservation Management Plan, with funding from the
PRIORITY CATEGORY:	A (A)	National Lottery Heritage Fund. This will identify the conservation work and policies for its future upkeep and is
OWNER TYPE:	Local authority	due to be completed by summer 2022.
LIST ENTRY NUMBER:	1378758	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ŬA
- Unitary Authority World Heritage Site WHS

H

HERITAGE AT RISK 2021 / LONDO	on and south east	/ TOWER HAMLETS	
	SITE NAME:	St Pauls Mission Room and Infant Nursery, Wellclose Square EI	Gothic style structure built in 1874 to designs by Reuben Greatorex. The building is of stock brick with a red brick eaves cornice and red and blue brick bands. It has stone
	DESIGNATION:	Listed Building grade II, CA	dressings to the doors and windows, a steeply pitched tiled roof with cresting, and a stone banded chimney. The
	CONDITION:	Poor	building is empty and boarded up. The owner is considering options for re-use or conversion of the
	OCCUPANCY:	Vacant/not in use	building.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1242432	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Braithwaite Viaduct, Bishopsgate Goods Yard, Wheler Street / Brick Lane EI	Early railway viaduct built in 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within an extensive brick-vaulted goods yard circa 1880, partially demolished in 2003. Planning Permission and Listed
STEELA	DESIGNATION:	Listed Building grade II	Building Consent was granted in 2021 for a mixed-use
	CONDITION:	Poor	development which will include repair and reuse of the viaduct and adjacent historic arches.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Utility	
© Historic England	LIST ENTRY NUMBER:	1063895	Contact: Andrew Hargreaves (LPA) 020 7364 5576
AS A	SITE NAME:	Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI	Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected in 1860 but moved to its present position in 1879. Funding has been secured for th repair of the fountain and the reinstatement of its water
	DESIGNATION:	Listed Building grade II, CA	supply. This is part of a wider project to restore three
	CONDITION:	Poor	drinking fountains in Tower Hamlets.
	OCCUPANCY:	N/A	
A CONTRACTOR OF A	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1357512	Contact: Andrew Hargreaves (LPA) 020 7364 5576
13	SITE NAME:	Royal London Hospital - front block, Whitechapel Road, Whitechapel El	Fine C18 yellow brick hospital building fronting Whitechapel Road. The building, which became redund following development of new facilities to the rear, has
TEFEL	DESIGNATION:	Listed Building grade II, CA	been purchased by Tower Hamlets Council. Plans to convert the building into a Civic Centre are progressing, as
	CONDITION:	Fair	part of the new masterplan for Whitechapel. Planning Permission and Listed Building Consent have been granted
	OCCUPANCY:	Vacant/not in use	and works are underway with expected completion in
H GARRE	PRIORITY CATEGORY:	F (F)	2022.
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1065788	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	2, Wilkes Street, EI EI	Early C18 terraced house. Three storeys, double fronted,
	DESIGNATION:	Listed Building grade II, CA	with basement and attic in yellow stock brick with red dressings to segmental-arched windows. Wooden
	CONDITION:	Poor	doorcase and weavers' windows. The ownership has
	OCCUPANCY:	Vacant/not in use	recently changed and the Local Authority is liaising with the new owner and is anticipating applications for Planning
	PRIORITY CATEGORY:	C (C)	Permission and Listed Building Consent shortly.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1242278	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	LIST ENTITY INOUDER.	1272210	Contact. And ever harge eaves (LFA) 020 / 304 33/0

© Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Mary Stratford Bow, Bow Road, Poplar E3	St Mary's Bow is shrouded by trees on a traffic island on the AII. The tower and chancel were added circa 1490 to
	DESIGNATION:	Listed Place of Worship grade II*, CA	an early C14 nave. The south aisle was rebuilt in 1794; the upper tower in 1829 and then restored in the 1950s following war damage. There was a general restoration in
	CONDITION:	Poor	C19. Two phases of repairs are now complete to roo clock turret, and external masonry, funded by the Na
	PRIORITY CATEGORY:	D (D)	Lottery Heritage Fund. The church now urgently needs a
THE	OWNER TYPE:	Religious organisation	drainage system, tree management and suitable access from the highway. Discussions with authorities are ongoing.
	LIST ENTRY NUMBER:	1065273	Contact: Ian Harper 020 7973 3786

© Historic England

Sect.	446
La -	TRA
al a	P T T

Green, Cambridge Heath Road, and h Bethnal Green E2 Mund	The parish church of 1824 was designed by Sir John Soane and heavily restored and extended in the C19 by William Munday and GF Bodley. The church is built of London		
	DESIGNATION:	Listed Place of Worship grade I, CA	stock brick with artificial stone dressings and bell tower. Repairs to high-level stonework were grant aided by Historic England and the National Lottery Heritage Fund,
	CONDITION:	Poor	and completed in 2014. Funding is being sought for a final phase of repairs to the nave roof, the interior of the
	PRIORITY CATEGORY:	C (C)	narthex and the church steps.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065245	Contact: Ian Harper 020 7973 3786



©	Historic	England

© Historic England



© Historic England

X

Ô

	SITE NAME:	Calvary Charismatic Baptist	The church, hall and offices, arranged collegiately, were
	LIST ENTRY NUMBER:	1357808	Contact: Ian Harper 020 7973 3786
	OWNER TYPE:	Religious organisation	funding to develop the crypt and continue an on-going repair programme.
1.23	PRIORITY CATEGORY:	C (C)	parapet gutters. The congregation is actively seeking
-	CONDITION:	Poor	structure was carried out between 1983 and 1993. The classical interior is much damaged by water leakage from
	DESIGNATION:	Listed Place of Worship grade I, CA	and the western tower was used as a 'sea-mark' for naval purposes. The interior was restored by Philip Hardwick following a serious fire in 1851. Further work to the roof
	SITE NAME:	St Anne's Limehouse Parish Church, Commercial Road, Stepney E14	St Anne's Church was designed by Nicholas Hawksmoor in the English Baroque style. It was completed in 1730 and consecrated in 1733. The church is built of Portland stone
	LIST ENTRY NUMBER:	1065245	Contact: Ian Harper 020 7973 3786
	OWNER TYPE:	Religious organisation	
	PRIORITY CATEGORY:	C (C)	narthex and the church steps.

built in the 1950s as part of the live architectural phase of the 1951 Festival of Britain, which was the first stage of the post-war rebuilding of the heavily damaged Lansbury Estate. The church architects were Cecil Handisyde and D Rogers Stark and the consulting engineer Felix Samuely. Historic significance is being re-assessed. The roof, domed roof lights and exposed concrete frame were repaired in 2017 with a grant from Historic England. CCBC is in discussion about a further phase of repairs to complete the church and the tower.

Contact: lan Harper 020 7973 3786

	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	Church constructed of London stock brick with stone dressings, designed by G Austin and built between 1836 and 1839. Repairs to the roofs and stonework were
	DESIGNATION:	Listed Place of Worship grade II, CA	completed in 2007 with a grant from Historic England and the National Lottery Heritage Fund. Internal repairs are needed to the nave ceiling, windows and walls. External
	CONDITION:	Very bad	stonework repairs are needed to the west end. The congregation worships from a modern adjacent building
	PRIORITY CATEGORY:	C (C)	and is actively exploring options for funding the necessary
	OWNER TYPE:	Religious organisation	repairs to the former church to enable its use as a multi-´ purpose community facility.
© Historic England	LIST ENTRY NUMBER:	1065118	Contact: Ian Harper 020 7973 3786

Church (former Trinity Methodist Church), including attached hall and church rooms,

Religious organisation

E14

CA

Poor

C (C)

1376625

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

East India Dock Road, Poplar

Listed Place of Worship grade II,

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
 - RPG Registered Park and Garden Scheduled Monument
 - SM
 - UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Church of the English Martyrs, Prescott Street, Stepney El	A town church by EW Pugin with rich internal decoration, completed after his death in 1875 by his brothers. It
	DESIGNATION:	Listed Place of Worship grade II	replaced an earlier mission set up in 1864. The high altar was re-ordered in 1930 as a shrine to the English Martyrs.
	CONDITION:	Poor	Bomb damage in 1940 destroyed the pulpit. The nave roof has been re-slated and the dampness problem on the north
	PRIORITY CATEGORY:	C (C)	east side has been resolved, pending monitoring. The
	OWNER TYPE:	Religious organisation	remaining issues are stone decay to the belfry and repairs to rainwater disposal system. The church is investigating
	LIST ENTRY NUMBER:	1241734	sources of funding for repairs.
Factoria			Contact: lan Harper 020 7973 3786

© Historic England

	SITE NAME:	Sandys Row Synagogue, Sandys Row, Spitalfields EI	Former Huguenot chapel which was altered in the mid C19 into a synagogue. Major re-roofing and high- level brick
	DESIGNATION:	Listed Place of Worship grade II, CA	repairs were completed in 2011 with funding from the National Lottery Heritage Fund and Historic England. At the same time emergency works were carried out to
	CONDITION:	Poor	temporarily restrain the bowing narrow brick piers to the front elevation windows until funding for permanent repairs
	PRIORITY CATEGORY:	C (C)	can be found. The flat roofs over the western end of the
	OWNER TYPE:	Religious organisation	synagogue are also in need of attention and in 2020 Historic England awarded a Covid-19 Emergency Heritage
	LIST ENTRY NUMBER:	1260323	at Risk Response Fund grant for their repair.
			Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Priory and Hospital of St Mary Spital, Steward Stre	et El	
DESIGNATION:	Scheduled Monument, 11 LBs, part in CA	LIST ENTRY NUMBER:	1001982
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	London Hospital, Stepney El		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Anne's Church E14		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Tower Hamlets Cemetery, Bow E3		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wentworth Street, Bethnal Green EI		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / TOWER HAMLETS / WALTHAM FOREST

SITE NAME:	Whitechapel High Street, Aldgate EI		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

WALTHAM FOREST

	SITE NAME:	Chestnuts House, 398, Hoe Street E17	Substantial detached house of circa 1745-7 in stock red brick with red dressings. Elaborate stucco interiors survive
	DESIGNATION:	Listed Building grade II*	along with original panelling and cornices. The house fell out of use several years ago and has since been occupied
	CONDITION:	Poor	by live-in guardians. Emergency repairs to the roofs and rainwater goods have addressed the worst of deterioration
Ĥ	OCCUPANCY:	Occupied/in use	and water ingress, but extensive vegetation to the rear continues to threaten further damage. The Local Author continues to develop plans for the repair and re-use of
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	building, and is in discussion with Historic England.
ic England	LIST ENTRY NUMBER:	1191062	Contact: Verena McCaig 020 7973 3718

© Historic Eng

LABR

	SITE NAME:	Essex County Cricket Pavilion, Leyton High Road E10	Cricket pavilion, rendered and colour washed timber frame over a brick basement in the Vernacular Revival style, built
	DESIGNATION:	Listed Building grade II	in 1886 by Richard Creed for the Essex County Cricket Club. Part of the building is occupied by the Local
AUTOMA	CONDITION:	Poor	Authority as offices, alongside low-key community use. Roof tiles are missing, and pigeons are entering through
	OCCUPANCY:	Part occupied/part in use	broken windows. Temporary repairs, including internal
	PRIORITY CATEGORY:	C (New entry)	propping, have been carried out following a major internal water leak. A repair package is currently being prepared by
	OWNER TYPE:	Local authority	the Local Authority.
© Historic England	LIST ENTRY NUMBER:	1386803	Contact: Ron Presswell (LPA) 020 8496 6736

listoric England

11	
	"L

© London Borough of Waltham Forest

	SITE NAME:	Metal Railing to Chingford Mill Pumping Station, Lower Hall Lane E4	Metal railing with concrete plinth, 1890-95. Shallow curving plan in twelve sections; alternate uprights supported by curved brackets. The condition of the railings is poor and
6	DESIGNATION:	Listed Building grade II	numerous sections have been removed and replaced with temporary metal fencing. They were repainted in 2015 but
	CONDITION:	Poor	require further repair and replacement.
100	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1065575	Contact: Ron Presswell (LPA) 020 8496 6736



© Historic England

A STA	SITE NAME:	Wall to south east of St Mary's Churchyard, Church End E17	C18 walls, formerly belonging to a house, now demolished on the adjacent site. A dense covering of ivy is damaging
	DESIGNATION:	Listed Building grade II, part in CA	the brickwork, which is in need of repair. Efforts are being made to clarify ownership in order that necessary works can be discussed and eventually secured.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
A THE R	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357602	Contact: Ron Presswell (LPA) 020 8496 6736

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HER

		Walnut Tree House, 500, High Road EI0	Mid-C16 timber-framed property formerly used as a Conservative Club, but now a community centre. Works
and the second	DESIGNATION:	Listed Building grade II*	connected with a previously approved Listed Building Consent have been completed satisfactorily. Following
	CONDITION:	Fair	discussions with the Local Authority and Historic England,
	OCCUPANCY:	Occupied/in use	additional repairs are expected to be carried out, including restoration of the timber porch, for which Planning
	PRIORITY CATEGORY:	D (D)	Permission and Listed Building consent have been granted. However, in 2021 work was put on hold due to the
	OWNER TYPE:	Other not for profit group	pandemic.
© Historic England	LIST ENTRY NUMBER:	1065586	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	698a, High Road Leytonstone,	One of a surviving terrace of three Georgian houses,
E E		Leytonstone EII	probably late C18, for many years the home of the local
	DESIGNATION:	Listed Building grade II	British Legion branch. Planning Permission and Listed Building Consent have been secured for conversion into
	CONDITION:	Very bad	flats. The Local Authority is in discussion with the owner to ensure that the consented scheme is carried out.
155	OCCUPANCY:	Part occupied/part in use	ensure that the consented scheme is carried out.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© London Borough of Waltham Forest	LIST ENTRY NUMBER:	1357632	Contact: Ron Presswell (LPA) 020 8496 6736
12 A	SITE NAME:	Granada Cinema, 186 Hoe Street, Walthamstow E17	The cinema was built 1929-30 as the Granada Cinema the design of Cecil Masey with fine Art Deco and Moor style interiors by Theodore Komisarjevsky. The Local
	DESIGNATION:	Listed Building grade II*	Authority has purchased the building and is restoring and
	CONDITION:	Poor	redeveloping it as a cultural venue, in partnership with Soho Theatre. Enabling works have commenced on site
	OCCUPANCY:	Vacant/not in use	and Historic England has awarded a grant towards repair and restoration of the Hoe Street elevation, and is
	PRIORITY CATEGORY:	F(C)	considering further grant aid towards restoration of
	OWNER TYPE:	Local authority	internal features. The project is due to complete and the venue to open to the public in 2022.
© Historic England	LIST ENTRY NUMBER:	1065590	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Chapel to south of main hospital block, Langthorne Road El I	Closed chapel to a hospital (formerly a workhouse), 1840. The building is wind and weathertight but in need of moderate repair to bring it back into use.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
<u> 送到</u> - 111 - 333	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
© Historic England	LIST ENTRY NUMBER:	1357634	Contact: Ron Presswell (LPA) 020 8496 6736



	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1357634	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	Lodge south of main hospital block, Langthorne Road EI I	1840 lodge to a hospital (formerly a workhouse). Considerable ivy growth that was covering most of the
	DESIGNATION:	Listed Building grade II	building has largely been removed.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1293493	Contact: Ron Presswell (LPA) 020 8496 6736

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDONI AND SOLITH EAST / WALTHAM FOREST

HERITAGE AT RISK 2021 / LONDO	ON AND SOUTH EAST	/ WALTHAM FOREST	
	SITE NAME:	Chingford Mill Pumping Station, Lower Hall Lane E4	Pumping station built in 1895 for East London Water Works, in a variant of the style popularised by Norman
1 100	DESIGNATION:	Listed Building grade II	Shaw. The building is in two ownerships. Part of the building is being converted for residential use; part remains
	CONDITION:	Poor	for utility use. The roof to the tower section is in very poor condition and rainwater goods require repair. Enforcement
	OCCUPANCY:	Occupied/in use	action for unauthorised works is ongoing. The Local
	PRIORITY CATEGORY:	C (C)	Authority and Historic England are liaising with the owners to improve the condition and management of the buildings
	OWNER TYPE:	Mixed, multiple owners	and wider site.
© Historic England	LIST ENTRY NUMBER:	1250896	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Listed Building Consent for residential use were granted in 2007
	DESIGNATION:	Listed Building grade II	and subsequently renewed, subject to a Section 106 agreement. The building is in very poor condition, with
The Repairment	CONDITION:	Very bad	damage to rainwater goods, windows, and plasterwork. Enforcement action for unauthorised works is ongoing. The
	OCCUPANCY:	Vacant/not in use	Local Authority and Historic England are liaising with the
	PRIORITY CATEGORY:	C (C)	owners to identify and secure urgent remedial works.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1065574	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	133, Whipps Cross Road, Leytonstone EI I	One of six survivors from an original terrace of 12 'middle class' three-storey houses called Assembly Row, built in
	DESIGNATION:	Listed Building grade II, CA	1767. Render and brickwork on the flank wall have suffered from considerable water ingress and are in a parlous
	CONDITION:	Poor	condition. Following enforcement action, the roof coverings have been replaced and the front sash windows
	OCCUPANCY:	Occupied/in use	have been repaired. Historic England and the Local
	PRIORITY CATEGORY:	C (C)	Authority have advised the owner on further necessary repair works, and the Local Authority is taking
	OWNER TYPE:	Private	enforcement action, including for the unauthorised removal of two dormer windows.
© Historic England	LIST ENTRY NUMBER:	1357621	Contact: Ron Presswell (LPA) 020 8496 6736
	SITE NAME:	Church of St Andrew, Colworth Road, Leytonstone E11	Sir Arthur Blomfield was commissioned by the Cotton family to build the church in memory of William Cotton of Wallwood House; it was completed by 1893 in Kentish rag
	DESIGNATION:	Listed Place of Worship grade II, CA	with knapped flint walling and freestone dressings. There is an important collection of window glass by Margaret Chilton. The early C20 vestry has a fine timber roof but is
	CONDITION:	Very bad	poorly founded and its settlement is damaging the church structure. In 2020 Historic England awarded a Covid-19
	PRIORITY CATEGORY:	A (A)	Emergency Heritage at Risk Response Fund grant for
	OWNER TYPE:	Religious organisation	repairs to the stained glass and for investigations into the causes of subsidence.
© Historic England	LIST ENTRY NUMBER:	1391544	Contact: lan Harper 020 7973 3786
	SITE NAME:	St Michael and All Angels Church, Palmerston Road, Walthamstow E17	This church has an imposing interior augmented by stained glass windows by Hardman and the highest nave roof of any church in the Chelmsford Diocese. It was designed in the Cathia state build Diocella to a state in 1905 to in
	DESIGNATION:	Listed Place of Worship grade II	the Gothic style by JM Bignall and opened in 1885. It is constructed of London stock yellow brick with a mixture of
	CONDITION:	Poor	red brick and stonework dressings. The original cast iron rainwater goods are in very poor condition and
	PRIORITY CATEGORY:	C (C)	inadequately sized to cope with climate change. The
064	OWNER TYPE:	Religious organisation	regular wetting of the soft red bricks is causing them to decay internally and externally. In addition, the vestry roof
	LIST ENTRY NUMBER:	9 54	is felted over and needs renewal.
© Historic England			Contact: Ian Harper 020 7973 3786

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WALTHAM FOREST / WANDSWORTH

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

IERTAGE AT RISK 2021 / EOND	ON AND SOUTHEAST		
	SITE NAME:	Church of St Peter and St Paul, The Green, Chingford E4	The church, with tower and spire of 1844, is by Lewis Vulliamy; the chancel and north and south aisle chapels are
	DESIGNATION:	Listed Place of Worship grade II*, CA	by Sir Arthur Blomfield, dating from 1903. The Lady Chapel was extended and re-ordered in 1936 by NF Cachemaille- Day. Construction is in cream-coloured gault brick with
1 1 A	CONDITION:	Poor	flint chequer-board flushwork, and dressings in Bath stone. Slating is sound but the defective parapet gutters and
	PRIORITY CATEGORY:	D (D)	sumps have caused serious internal leaks. A first phase of
	OWNER TYPE:	Religious organisation	repairs has been funded by the National Lottery Heritage Fund. A second phase for the nave parapets and rainwater
	LIST ENTRY NUMBER:	1065582	goods is urgent needed.
) Historic England			Contact: Ian Harper 020 7973 3786
	SITE NAME:	Church of St Margaret of Antioch and attached railings, Woodhouse Road, Leyton EI I	A late C19 basilica style church by architect JT Newman, commenced in 1892, replacing an iron mission church. The Lady Chapel was added in 1910. There are fine decorations

Very bad

1390581

A (A)

Listed Place of Worship grade II

Religious organisation

rch by architect JT Newman, ing an iron mission church. The 910. There are fine decorations and wall paintings internally. Only the north transept and aisle roofs remain to be repaired but this work is urgent as the paintings and parquet floor are being damaged by inadequate rainwater goods and drainage. The contemporary railings and adjacent halls are also in need of repair. The congregation is actively exploring options for funding the repairs.

Contact: lan Harper 020 7973 3786

© Historic England

WANDSWORTH

© London Borough of Wand

1	SITE NAME:	Battersea Park Station, Battersea Park Road SW8	Italianate style station built circa 1865 for the London, Brighton and South Coast Railway. Alterations to the tra
	DESIGNATION:	Listed Building grade II, CA	service mean that the architecturally significant Platform 1 i redundant. Repair works are complete, but the building
-	CONDITION:	Fair	remains underused. A legal agreement with Network Rail for a scheme of works was secured in 2018. In 2019
	OCCUPANCY:	Part occupied/part in use	applications were approved for conversion of the former
	PRIORITY CATEGORY:	E (E)	station master's accommodation into offices, and this work is also complete. Discussions about the wider station site, a
Konstaller	OWNER TYPE:	Utility	new use for Platform I, disability access and improved facilities are underway.
dsworth	LIST ENTRY NUMBER:	1357652	Contact: Barry Sellers (LPA) 020 8871 7564

- An	SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII	Church school of 1866-67 designed by Benjamin Ferrey. The building is currently vacant but is wind and
	DESIGNATION:	Listed Building grade II, CA	weathertight. The owners carried out maintenance and repairs to the roof and rainwater goods and implemented
	CONDITION:	Poor	structural support to the north wall early in 2018. Discussions are ongoing between the Local Authority,
	OCCUPANCY:	Vacant/not in use	Historic England and the owners regarding the re-use,
	PRIORITY CATEGORY:	C (C)	extension, and alteration of the building. An outline programme of action is under discussion following further
	OWNER TYPE:	Religious organisation	investigative work carried out in 2021. The Local Authority is anticipating application proposals.
	LIST ENTRY NUMBER:	389 36	Contact: Barry Sellers (LPA) 020 8871 7564

© Historic England



SITE NAME:	Springfield Hospital (main building), Glenburnie Road SW17
DESIGNATION:	Listed Building grade II, RPG grade II
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Health authority
LIST ENTRY NUMBER:	1065553

Former psychiatric hospital built in 1840 in Tudor Gothic style as the Surrey County Asylum. Planning Permission and Listed Building Consent for redevelopment and demolition of curtilage listed buildings were granted in 2012 and the listed buildings' strategy was approved in 2017. The Hospital Trust appointed a partner in 2018 to progress a programme of works. Planning Permission and Listed Building Consent applications were approved in 2020 for the first phase of re-use, and restoration of the main building and Airing Courts. Further applications were submitted for the second phase in 2021.

Contact: Barry Sellers (LPA) 020 8871 7564

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

LIEDITACE AT DISK 2021		WANDSWORTH / WESTMINSTE	
TERITAGE AT RISK 2021	/ LONDON AND SOUTH EAST /		R, CITT OF

	SITE NAME:	Queenstown Road Station,
© London Borough of Wandsworth	LIST ENTRY NUMBER:	1184658
	OWNER TYPE:	Commercial company
	PRIORITY CATEGORY:	D (D)
	OCCUPANCY:	Vacant/not in use
	CONDITION:	Poor
	DESIGNATION:	Listed Building grade II, CA
- MIRINE STR	SITE NAME:	Former White Lion, 14-16, Putney High Street SW15
© Historic England	LIST ENTRY NUMBER:	1065545
@ Literatio England	OWNER TYPE:	Religious organisation
	PRIORITY CATEGORY:	A (A)
	OCCUPANCY:	N/A
	CONDITION:	Very bad
	DESIGNATION:	Listed Building grade II*, CA
	SITE NAME:	Temple in the grounds of Mount Clare, Minstead Gardens SW15
HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WANDSWORTH / WESTMINSTER, CITY		

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	SITE NAME:	Queenstown Road Station, Queenstown Road SW8	Station built in 1877. Repairs are needed to the doors, windows and floors of the disused areas of this unattended
	DESIGNATION:	Listed Building grade II, CA	station. The station is routinely inspected and the former station ticket office has been re-used as a cafe, and
TATION	CONDITION:	Poor	redecoration of the lobby area has been carried out. The owners have confirmed that funding is in place for repair
	OCCUPANCY:	Part occupied/part in use	works and further discussions are ongoing regarding
	PRIORITY CATEGORY:	D (D)	Network Rail's enhancement proposals for the station. An application for Planning Permission for revisions to
	OWNER TYPE:	Utility	proposals for a second entrance from Patcham Terrace was submitted in 2021.
lsworth	LIST ENTRY NUMBER:	1389413	Contact: Barry Sellers (LPA) 020 8871 7564

Listed Building grade II

19, Cavendish Avenue NW8

Listed Building grade II, CA

Vacant/not in use

Vacant/not in use

Fair

C (C)

Private

Poor

D (D)

Private

1066300

1357661

100, Tooting Bec Road SW17 Early C19 stucco lodge. Planning Permission and Listed Building Consent were granted in 2012 to use the building for retail and ancillary office space, together with a separate new building for use as a café and car sales. A Repairs Notice was served in 2015 and works to comply with the notice were completed in November 2017. An enforcement notice was served in 2018 in respect of hoardings around the site. Applications for Planning Permission and Listed Building Consent for new buildings, and car sales/gym use were refused in 2019. A revised scheme is still awaited.

The 'temple' dates from between 1762 and 1769. Some damage was caused as a result of heritage crime in 2017.

The site has been re-secured and temporary Planning Permission for perimeter fencing is subject to a renewal

application in 2021. The fence around the building has achieved protection of the building pending repair works, and the site is regularly monitored by Roehampton University. Discussions between the Local Authority and the university are still ongoing concerning the future of this building in the wider context of the Mount Clare site.

Former White Lion public house built in 1887. The building is unoccupied following its closure in 2015 and is in poor

condition, with access problems. Planning Permission and

Listed Building Consent, in line with the permissions granted in 2016, were renewed in April 2019 for extensions and alterations for hotel and public house use but have not yet been implemented. The building is secure

Contact: Elizabeth Whitbourn 07889 808145

and occupied by property guardians.

Contact: Barry Sellers (LPA) 020 8871 7564

Contact: Barry Sellers (LPA) 020 8871 7564

House dating from the mid C19, with a stuccoed facade and central Tuscan porch with a balcony above. The property is unoccupied and in a poor condition. The stucco is failing in places, plants have taken root at eaves level, and there are signs of water ingress internally. Planning Permission and Listed Building Consent were granted in November 2017 for the full repair of the building and alterations to provide a single family dwelling.

Contact: Alistair Taylor (LPA) 020 7641 2979

© Historic England

© London Borough of Wands

© London Borough of Wandsworth

WESTMINSTER, CITY OF

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is LB shown in brackets (otherwise. New Entry is noted).

NOTE

- Conservation Area Listed Building
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF

	SITE NAME:	90-93, Piccadilly WI	Corner block of shops and chambers dating from 1883.
	DESIGNATION:	Listed Building grade II, CA	Red brick with stucco ornament and dressings and slate roofs in an eclectic High Victorian design. Part of the
	CONDITION:	Poor	former private club complex with 94 and 95 Piccadilly. Planning Permission and Listed Building Consent were granted in March 2018 for a scheme including the adjace
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	listed buildings (94 and 95 Piccadilly). Works include the full repair of the buildings for hotel use, with seven residential
	OWNER TYPE:	Commercial company	units, and are currently being implemented.
	LIST ENTRY NUMBER:	1226747	Contact: Robert Ayton (LPA) 020 7641 2978

© Historic England



SITE NAME:	Snowdon Aviary London Zoo, Regents Park NW1	Aviary designed by Lord Snowdon and Cedric Price in 1962-5 as part of an expansion of London Zoo. The Aviar
DESIGNATION:	Listed Building grade II*, RPG grade I, CA	is an aluminium and steel structure on concrete foundations, accessed via a cantilevered concrete bridge. Funding has been secured from the National Lottery
CONDITION:	Poor	Heritage Fund for the full repair of the Aviary, and Planning Permission and Listed Building Consent were granted in
OCCUPANCY:	Part occupied/part in use	September 2017. Works will include the replacement of
PRIORITY CATEGORY:	D (D)	the aluminium mesh and alterations to the concrete bridge and entrance pods. Further investigative works are
OWNER TYPE:	Charity (non-heritage)	underway, partly funded by Historic England.
LIST ENTRY NUMBER:	1323695	Contact: Elizabeth Whitbourn 07889 808145

© Historic England



Terraced town house circa 1750-53. Some unauthorised SITE NAME: 21, Charles Street WI works have taken place. Planning Permission and Listed DESIGNATION: Listed Building grade II, CA Building Consent were granted in July 2008 for various works including demolition and rebuilding of the mews CONDITION: Poor building to the rear. The street elevation was cleaned and OCCUPANCY: Vacant/not in use repaired in 2011-12. PRIORITY CATEGORY: D (D) OWNER TYPE: Unknown LIST ENTRY NUMBER: Contact: Robert Ayton (LPA) 020 7641 2978 1357294

© Historic England

	SITE NAME:	112, Eaton Square SW1	Grand terraced house, circa 1825. The building is suffering
EM	DESIGNATION:	Listed Building grade II*, CA	from neglect, water ingress and a serious outbreak of dry rot. Discussions with the owner are ongoing. Planning
	CONDITION:	Poor	Permission and Listed Building Consent were granted in August 2017 for the full repair of the building as a single
HE IS	OCCUPANCY:	Vacant/not in use	family dwelling, but the works have not yet been
	PRIORITY CATEGORY:	D (D)	implemented.
	OWNER TYPE:	Private	
- 74	LIST ENTRY NUMBER:	1066851	Contact: Elizabeth Whitbourn 07889 808145
-1			

© Westminster City Council



SITE NAME:	94 and 100, Gloucester Place W1	Terraced houses built circa 1800 for the Portman Estate. Listed Building Consent was granted in July 2009 for the
DESIGNATION:	Listed Building grade II, CA	internal refurbishment and alterations to No. 100. Works have yet to be implemented.
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1066788	Contact: Susanna Miller (LPA) 020 7641 2459

© Westminster City Council

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site
- 119

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF

1	SITE NAME:	10-11, Lancaster Gate W2	Grand terrace of houses dating from 1865, attributed to
	DESIGNATION:	Listed Building grade II, CA	John Johnson. The building is three bays wide with four storeys plus attic and basement. It has fine classical
	CONDITION:	Very bad	detailing. The condition of the existing building is very poor, owing to water leakage and a lack of maintenance over
	OCCUPANCY:	Vacant/not in use	many years. The building has, however, been temporarily
	PRIORITY CATEGORY:	C (C)	secured following enforcement action, and discussions are ongoing with regards to its long-term use and repair.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1221694	Contact: Alistair Taylor (LPA) 020 7641 2979
1			

© Westminster City Council

-

TUPPER

	SITE NAME:	94, Piccadilly WI	Town Mansion of 1756-1760 by Matthew Brettingham for
	DESIGNATION:	Listed Building grade I, CA	Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Planning Permission
	CONDITION:	Poor	and Listed Building Consent were granted in March 2018 for a scheme including the adjacent listed buildings (90-93
	OCCUPANCY:	Vacant/not in use	and 95 Piccadilly). Works include the full repair of the
	PRIORITY CATEGORY:	F (F)	buildings for hotel use, with 7 residential units, and are currently being implemented.
	OWNER TYPE:	Commercial company	, , ,
	LIST ENTRY NUMBER:	1226748	Contact: Elizabeth Whitbourn 07889 808145

© Historic England

	SITE NAME:	95, Piccadilly WI	Town house dating from 1886, forming part of a larger site
	DESIGNATION:	Listed Building grade II, CA	with the Former Naval and Military Club. Planning Permission and Listed Building Consent were granted in
and the second s	CONDITION:	Poor	March 2018 for a scheme including the adjacent listed buildings (90-93 and 94 Piccadilly). Works include the full
	OCCUPANCY:	Vacant/not in use	repair of the buildings for hotel use, with seven residential
MARINE .	PRIORITY CATEGORY:	F (F)	units, and are currently being implemented.
	OWNER TYPE:	Commercial company	
and the second s	LIST ENTRY NUMBER:	1265696	Contact: Robert Ayton (LPA) 020 7641 2978

© Historic England

	SITE NAME:	Wharf side shelter and store to rear of builders' merchants, 22, Praed Street W2	Wharf side shelter and store circa 1840. Brick ground floor with timber first floor and large slated hipped roof. Part of the redevelopment scheme for Paddington Basin. The
	DESIGNATION:	Listed Building grade II	shelter is currently being stored off-site and will be re- erected as part of the final landscaping proposals.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1248366	Contact: Tom Burke (LPA) 020 7641 2357



© Historic England Archive

	LIST ENTRY NOMBER:	1248366	Contact: Tom Burke (LPA) 020 7641 2357
	SITE NAME:	140, Westbourne Terrace W2	Detached villa dating from 1843-8 in an Italianate style.
	DESIGNATION:	Listed Building grade II, CA	Occupied as a number of bedsits. Planning Permission and Listed Building Consent were refused in November 2011
	CONDITION:	Good	for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised
	OCCUPANCY:	Occupied/in use	works. This is being investigated as an enforcement matter.
	PRIORITY CATEGORY:	D (D)	Some repairs have, however, been carried out.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1267518	Contact: John Wilman (LPA) 020 7641 2561

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF			
I SOM	SITE NAME:	Church of the Annunciation, Bryanston Street, Marble Arch WI	Designed by Sir Walter Tapper and built 1912-13. Located on a corner site, the church is built up against on two sides which makes access difficult for roof maintenance. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	church has a problem with the ingress of rainwater and dampness has resulted in the ongoing detachment and falling of plaster and water staining to the vaulted ceilings.
	CONDITION:	Poor	There is also falling masonry externally. The rainwater goods to the north nave were replaced summer 2020.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1066358	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Peter, Eaton Square, Westminster SWI	A Classical Commissioner's church designed by Henry Hakewill, completed 1827 and enlarged 1875. It has a
	DESIGNATION:	Listed Place of Worship grade II*, CA	pedimented west portico, west end narthex carrying the tower and cupola, and rectangular nave with short transepts. The church was partly destroyed by fire in 1987
	CONDITION:	Poor	and the interior reordered, the nave being totally remodelled. The church has had a fall of plaster from the
	PRIORITY CATEGORY:	A (New entry)	portico ceiling, the buckled copper roofing to the portico
	OWNER TYPE:	Religious organisation	needs replacing, and past cementitious repairs to the tower are becoming detached and also falling.
	LIST ENTRY NUMBER:	1356980	Contact: Tracey Craig 020 7973 3756
© Paul Travis			, .
	SITE NAME:	Church of St Cyprian, Glentworth Street, Marylebone NW I	Designed by Ninian Comper and built 1903 in red brick with stone dressings and mainly slated roofs. It has a nave, aisles with large windows, small windows to the clerestory
	DESIGNATION:	Listed Place of Worship grade II*, CA	and a bellcote. The church has a white and gold colour scheme internally with finely detailed furnishings and stained glass also by Comper. The roofs are in need of
	CONDITION:	Poor	attention, particularly over the Lady Chapel, which has leaks.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1237476	Contact: Tracey Craig 020 7973 3756
À Č	SITE NAME:	Church of St Mark, Hamilton Terrace, Westminster NW8	Gothic church dating from 1846-7 by Thomas Cundy Senior with spire by Thomas Cundy Junior and chancel in 1878 by EB Ferrey. It has slate covered pitched roofs and
	DESIGNATION:	Listed Place of Worship grade II*, CA	Kentish ragstone walling with ashlar dressings. The nave roof was re-slated in 2013, with funding from Historic
Sale in the	CONDITION:	Poor	England and the National Lottery Heritage Fund. A further grant was awarded towards masonry repairs to the tower
	PRIORITY CATEGORY:	C (C)	and spire; these works were completed in 2017. The nave
	OWNER TYPE:	Religious organisation	parapets, the chancel roof and the baptistry remain in poor condition.
	LIST ENTRY NUMBER:	1066681	Contact: Tracey Craig 020 7973 3756
© Historic England			
	SITE NAME:	Church of St Augustine, Kilburn Park Road, Kilburn NW6	Designed by JL Pearson, built in 1877. The building has slated pitched roofs and red brick walling with Bath stone
A. M	DESIGNATION:	Listed Place of Worship grade I	dressings. Internally the walls are covered in wall paintings by Clayton & Bell. The south aisle roof was re-slated in
and the second sec	CONDITION:	Poor	2013, with funding from Historic England and the National Lottery Heritage Fund. A new heating system has more
the land	PRIORITY CATEGORY:	C (C)	recently been installed. Other roofs, particularly of the
	OWNER TYPE:	Religious organisation	nave, chancel and transepts remain in poor condition.

© Historic England

CONDITION:	Poor	2013, with funding from Historic England and the Lottery Heritage Fund. A new heating system h
PRIORITY CATEGORY:	C (C)	recently been installed. Other roofs, particularly
OWNER TYPE:	Religious organisation	nave, chancel and transepts remain in poor con
LIST ENTRY NUMBER:	1221320	Contact: Tracey Craig 020 7973 3756

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF / BRACKNELL FOREST (UA)

A THE	SITE NAME:	Buddhist Temple, Margaret Street, Westminster WI	Former Parish School and Church House to All Saints Margaret Street, dating from 1868-70 by William
	DESIGNATION:	Listed Place of Worship grade II*, CA	Butterfield. The building is in full-time occupation and use for worship, library and residential accommodation. The roofs and external elevations are in poor condition. Repa
	CONDITION:	Poor	were carried out in 2018 to the roofs, masonry and rainwater goods to the former Church House, grant aided
t - T - M M	PRIORITY CATEGORY:	C (C)	by the National Lottery Heritage Fund. Similar repairs a
A diality and the second	OWNER TYPE:	Religious organisation	required to the former School House.
	LIST ENTRY NUMBER:	1273611	Contact: Tracey Craig 020 7973 3756
England			

© Historic E

© Historic England



10-	Marylebone Road, Westminster WI remodelled in 1884 by Thomas Harris. Cori and tower surmounted by a domed cupola s	Built c1818, designed by Thomas Hardwick with chancel remodelled in 1884 by Thomas Harris. Corinthian portico and tower surmounted by a domed cupola supported by	
Pri ta	DESIGNATION:	Listed Place of Worship grade I, CA	golden caryatids. There are problems with the roof coverings, the timber roof structure and also to the stone in places. The lath and plaster ceilings and the fibrous
	CONDITION:	Poor	plaster ceilings are very fragile. In 2016 the church was awarded a grant from the National Lottery Heritage Fu
	PRIORITY CATEGORY:	D (D)	for their Changing Lives project, which will include the
	OWNER TYPE:	Religious organisation	repairs to the church fabric. Work commenced early 2021 and are due to complete summer 2022.
	LIST ENTRY NUMBER:	1239817	Contact: Tracey Craig 020 7973 3756

© Historic England

		1257017	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Mary Magdalene, Rowington Close, Paddington W2	Built 1878 by GE Street with crypt chapel of St Sepulchre by Sir Ninian Comper 1895. Roof repairs received funding from the National Lottery Heritage Fund and Historic
	DESIGNATION:	Listed Place of Worship grade I, CA	England in 2008. Further funding saw the replacement of electrics and drainage repairs in 2012. External fabric repairs with cleaning and conservation works to the
	CONDITION:	Poor	interior were grant-aided by the National Lottery Heritage Fund, completed in 2018, and a new contemporary
	PRIORITY CATEGORY:	C (C)	extension constructed in 2019. Historic England awarded a
	OWNER TYPE:	Religious organisation	Covid-19 emergency response grant to the St Sepulchre Chapel for investigations and project design.
	LIST ENTRY NUMBER:	1235288	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Gabriel, Warwick Square, Pimlico SWI	Church dating from 1851-3 by the architect Thomas Cundy II with his son Thomas Cundy III. The tower has been
	DESIGNATION:	Listed Place of Worship grade II*, CA	repaired, grant aided by the National Lottery Heritage Fund and Historic England. However, some roofs and masonry in other areas remain in poor condition. Work

i Ma	DESIGNATION:	Listed Place of Worship grade II*, CA	repaired, grant aided by the National Lottery Heritage Fund and Historic England. However, some roofs and masonry in other areas remain in poor condition. Work
Q	CONDITION:	Poor	was completed in March 2021 to convert an internal courtyard into a wc, provide step free access to the church, carry out improvements to rainwater goods an
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	below ground drainage, and repair the boundary wall.
	LIST ENTRY NUMBER:	1357369	Contact: Tracey Craig 020 7973 3756

© Historic England

BRACKNELL FOREST (UA)

		1.41.20
	Terms in	
		Ţ.
18821		

4)	
SITE NAME:	Newbold College (formerly Moor Close), Binfield
DESIGNATION:	Registered Park and Garden grade II*, 7 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)
LIST ENTRY NUMBER:	1000547

Moor Close estate, now the home of Newbold College, was Oliver Hill's first commission in an early C20 Arts and Crafts style. Divided into several sections the garden and its setting will be affected by development and infrastructure proposals within the Local Plan, some of which has now been approved. The garden's built fabric has deteriorated and after a condition survey and some limited site repairs further resources are needed to manage change so that the significance of design, structural fabric and setting may best be considered to restrict further loss of historic design integrity.

Contact: Kay Richardson 0207 973 3647

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial

use)

- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BRACKNELL FOREST (UA) / BRIGHTON AND HOVE, CITY OF (UA)

Mill and	 Ji	-
	ise.	

© Historic England

SITE NAME:	Broadmoor Hospital, Crowthorne	A mid-C19 asylum built to designs by Joshua Jebb with rare survival of large kitchen garden as the focus for therapeutic
DESIGNATION:	Registered Park and Garden grade II, LB grade II	work. Sited on a ridge, formal terraces descend to kitchen gardens and farm estate below. The ornamented farmland has survived with some loss of historic character. Major
CONDITION:	Extensive significant problems	redevelopment of the hospital completed in 2019 with site allocated in the 2013 local plan for comprehensive mixed
VULNERABILITY:	High	use development. Any application must be accompanied by
TREND:	Declining	a Conservation Management Plan and close liaison is necessary to minimise harm to the historic design integrity.
NEW ENTRY?:	No	
OWNER TYPE:	Health authority	
LIST ENTRY NUMBER:	1001401	Contact: Kay Richardson 0207 973 3647

BRIGHTON AND HOVE



E, CITY OF (UA)		
SITE NAME:	Madeira Terrace and Madeira Walk and Lift Tower and Related Buildings, Madeira Drive, Brighton	The 850 metres of cast iron arches known as Madeira Terrace is an icon feature of Brighton's eastern seafront. An important example of C19 engineering and evocative of the late Victorian heyday of the seaside. The terrace is in a
DESIGNATION:	Listed Building grade II*, part in RPG grade II, CA	very poor and deteriorating condition. Its structural stability is a serious concern causing the 170 plus bays to be closed off to the public. The restoration of the whole of
CONDITION:	Very bad	the terrace will require substantial funding. Brighton and Hove City Council has appointed a design team to develop
OCCUPANCY:	Vacant/not in use	options for the first phase of the restoration works.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	38 696	Contact: Alma Howell 0207 9733 627



-	SITE NAME:	53, Brunswick Square, Hove	Terraced house by A Wilds and CA Busby, 1825-27. Used
	DESIGNATION:	Listed Building grade I, CA	for multiple occupancy but largely vacant. The rear elevation and outbuildings are in poor condition and parts
TE	CONDITION:	Poor	of the building are not habitable. Urgent works have been carried to make the building weather and water tight but
	OCCUPANCY:	Part occupied/part in use	full repairs are still required and there is no long-term
	PRIORITY CATEGORY:	C (C)	solution in place.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1281017	Contact: Alma Howell 0207 9733 627

© Historic England

© Historic England



SITE NAME:	The West Pier, Kings Road, Brighton	Pier, 1864-66 by Eugenius Birch. Closed in 1975. Historic England has declared its view that the combination of
DESIGNATION:	Listed Building grade I, CA	significant damage and cost of repair make restoration from public funds uneconomic. In early 2013 the eastern side of
CONDITION:	Very bad	the structure collapsed following cold weather conditions, and in February 2014, further main supports on the eastern
OCCUPANCY:	N/A	side were washed away, splitting the former pavilion into
PRIORITY CATEGORY:	A (A)	two sections.
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1381655	Contact: Clare Charlesworth 0207 973 3640

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG
- Conservation Area Listed Building Local Planning Authority National Park
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Saltdean Lido, Marine Drive, Saltdean	Lido of 1938, by RWH Jones in Moderne style. Although the pool is open, the building remains largely closed and
	DESIGNATION:	Listed Building grade II*	requires extensive concrete repairs and general upgrading. The Saltdean Community Interest Company has a 60 year
	CONDITION:	Poor	lease and has submitted planning and listed building consent
	OCCUPANCY:	Part occupied/part in use	for its repair and reuse. Major funding has been awarded by the National Lottery Heritage Fund, Coastal Communities,
	PRIORITY CATEGORY:	D (D)	Social Investment in Business funds, and Brighton and Hove City Council. Discussions with Historic England to secure
AN THE KEN	OWNER TYPE:	Community interest group	further funding, beyond the completed investigatory work, continue.
lebecca Crook	LIST ENTRY NUMBER:	380905	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	Hippodrome, 52-58, Middle Street, Brighton	Originally an ice rink by Kerslake dating from 1896. Converted to Hippodrome in 1901 and again to variety
	DESIGNATION:	Listed Building grade II*, CA	theatre in 1902, both to designs of Frank Matcham. Vacant and in a very bad condition. The ornate plasterwork to the
THE MAN	CONDITION:	Very bad	auditorium is particularly at risk. Consent granted in November 2013 for conversion to a multi-screen cinema
	OCCUPANCY:	Vacant/not in use	was not implemented. A new private owner has acquired
	PRIORITY CATEGORY:	A (A)	the building and completed much needed urgent repair works. Historic England and Brighton & Hove City Council
	OWNER TYPE:	Commercial company	are engaged in pre-application discussions about further
listoric England	LIST ENTRY NUMBER:	1381793	repairs to the building and potential uses. Contact: Alma Howell 0207 9733 627
	SITE NAME:	Marlborough House, 54, Old Steine, Brighton	House built in 1765 and remodelled in 1786 by Robert Adam. Converted to an office, the building later became
	DESIGNATION:	Listed Building grade I, CA	vacant. Consent granted in 2015 for change of use to single family dwelling has not been implemented. Some repair and
the state of the state	CONDITION:	Poor	restoration work has been carried out including to lathe and plaster walls and ceilings. There have been more
	OCCUPANCY:	Vacant/not in use	recent discussions about potential new uses for the
	PRIORITY CATEGORY:	C (C)	building.
	OWNER TYPE:	Commercial company	
Historic England	LIST ENTRY NUMBER:	38067	Contact: Alma Howell 0207 9733 627
KX I	SITE NAME:	Church of St Patrick, Cambridge Road, Hove	Large C19 church constructed of ragstone. Problems with high level roofing and gutters, as well as stonework need
	DESIGNATION:	Listed Place of Worship grade II, CA	addressing. The future use of this church is uncertain and it is now closed. In use by the YMCA as a night shelter for the homeless.
	CONDITION:	Poor	
I all the	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1280980	Contact: David John 0207 973 3638
Historic England			
	SITE NAME:	Church of All Saints, Eaton Road, Hove	Large late Victorian sandstone ashlar church with a rich cathedral like interior in the suburbs of Hove near to the
	DESIGNATION:	Listed Place of Worship grade I, CA	seafront. Five bay nave, north and south aisles, chancel, chapel with apse and incomplete tower. Repairs to leaking roof over north aisle and organ carried out in summer
	CONDITION:	Poor	2013. Recent works (2019-20) include emergency stone
	PRIORITY CATEGORY:	Α (Α)	repairs to the window mullions and significant repairs to the upper levels of the north-east and south-east towers.

ist and south-east towers.

	DESIGNATION:	CA	chapel with apse and incomplete tow roof over north aisle and organ carrie
	CONDITION:	Poor	2013. Recent works (2019-20) includ repairs to the window mullions and s
	PRIORITY CATEGORY:	A (A)	the upper levels of the north-east
	OWNER TYPE:	Religious organisation	More repairs are still needed.
	LIST ENTRY NUMBER:	1187592	Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BRIGHTON AND HOVE, CITY OF (UA)

	SITE NAME:	Church of St Mary the Virgin, St James's Street, Kemp Town, Brighton	Late Victorian red brick building by William Emerson. Comprises a chancel with 5-sided apse, two vestries, transepts and four bay nave with north and south aisles and
	DESIGNATION:	Listed Place of Worship grade II*, CA	incomplete tower. Following on from major repairs to the North elevation (2016-17) and West front (2018-19) funded by the National Lottery Heritage Fund, recent work
	CONDITION:	Very bad	(2019-21) includes emergency repair of the south transept, repairs to brickwork, masonry, roofs, rainwater goods to
Test and Parks 4	PRIORITY CATEGORY:	A (A)	the south aisle funded by Covid-19 Emergency Heritage at
	OWNER TYPE:	Religious organisation	Risk Grants. Outstanding repairs remain to be done to the liturgical east end and other areas.
D Historic England	LIST ENTRY NUMBER:	1380884	Contact: David John 0207 973 3638



	SITE NAME:	Church of St Peter, St Peters Place, Brighton	Designed by Sir Charles Barry and built between 1824 and 1828. A National Lottery Heritage Fund and Historic
1	DESIGNATION:	Listed Place of Worship grade II*, CA	England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were completed. Further phases of repair to the tower have also
	CONDITION:	Poor	been completed with funding from the National Lottery Heritage Fund Grants for Places of Worship. One of the
	PRIORITY CATEGORY:	A (A)	intermediate pinnacles is in a precarious condition and
N	OWNER TYPE:	R TYPE: Religious organisation	needs securing. Further phases of work are planned for the building, including some possible redevelopment work.
	LIST ENTRY NUMBER:	1380903	Contact: David John 0207 973 3638

© Historic England

İ

©

	SITE NAME:	Church of St Paul, West Street, Brighton	A church designed by Richard Cromwell Carpenter in 1846-8 and built by George Cheeseman. The tower and
	DESIGNATION:	Listed Place of Worship grade II*	spire are by Richard Herbert Carpenter. The narthex, Fishermen's Institute (west end) and covered way are by
	CONDITION:	Poor	George Frederick Bodley. Large fragments of stone and flint have fallen from the tower, which is adjacent to a b
	PRIORITY CATEGORY:	A (A)	shopping street. Temporary protection has been provided.
	OWNER TYPE:	Religious organisation	Some other works have been carried out to other parts of the building.
	LIST ENTRY NUMBER:	1381098	Contact: David John 0207 973 3638

© Historic England

© Histori

NO CALA	SITE NAME:	The Royal Pavilion Gardens, Brighton	John Nash designed picturesque layout of serpentine walks and drives, flowery shrubberies and trees within open
	DESIGNATION:	Registered Park and Garden grade II, 3 LBs, CA	lawns of the royal estate. Restored in 1990 high levels of visitor use and recreational pressure affect the garden's condition and distinctiveness. Later insertions and
and share so the	CONDITION:	Extensive significant problems	temporary events conceal the estate's overall composition and identity. As highly socially valued urban green space but
	VULNERABILITY:	High	with little chance to understand the shared sense of place,
	TREND:	Declining	Royal Pavilion & Museums have been awarded National Lottery Heritage Funding in 2019 to conserve the
	NEW ENTRY?:	No	vulnerable Regency landscape.
ric England	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1000205	Contact: Kay Richardson 0207 973 3647

SITE NAME:	Benfield Barn		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	East Cliff		
DESIGNATION:	Conservation Area, 189 LBs, part in RPG grade II	NEW ENTRY?:	No
DESIGNATION: CONDITION:	Conservation Area, 189 LBs, part in RPG grade II Very bad	NEW ENTRY?: TREND:	No Deteriorating

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BRIGHTON AND HOVE, CITY OF (UA) / SOUTH DOWNS (NP) / BUCKINGHAMSHIRE (UA)

	, (),		
SITE NAME:	Old Town		
DESIGNATION:	Conservation Area, 114 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Queen's Park		
DESIGNATION:	Conservation Area, 34 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Sackville Gardens		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Valley Gardens		
DESIGNATION:	Conservation Area, 139 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SOUTH DOWNS (NP)			
SITE NAME:	Earthworks and lynchets near Eastwick Barn, Patch	am, Brighton and H	Hove, City of (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Stanmer, Brighton and Hove, City of (UA), Brighto	n and Hove, City o	of (UA)
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Michael Scammell (LPA) 01730 814810
	14		

BUCKINGHAMSHIRE (UA)



SITE NAME:	Walls of moated site at Grove Farm, Ashley Green	Remains of probable C15 walls to a strongly defended moated site. Walls have been overgrown with vegetation
DESIGNATION:	Scheduled Monument, 3 LBs	for many years but some have been cleared to reveal serious structural issues. A grant was offered by Historic
CONDITION:	Very bad	England to the owners to understand the extent and cost of the works needed to conserve the walls. The grant was
OCCUPANCY:	N/A	not accepted. Further proposals are awaited from the
PRIORITY CATEGORY:	A (A)	owner.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1006946	Contact: David John 0207 973 3638

© Hist ania Fueland

9	Historic	England	

OT IDEIX.	1006746	Contact: David

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

use).

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

Pin Nut: Barn at New Moner Farm, Broghten Lans, Broghten Lans, Bro	HERITAGE AT RISK 2021 / LONDO	on and south east	/ BUCKINGHAMSHIRE (UA)	
DODGRATION Listed Building grade IP Prime Prime OCCUMPNET: Vacant/hot in use Prime Prime OCCUMPNET: Vacant/hot in use Prime Prime Prime Prime OCCUMPNET: Vacant/hot in use Prime Prime Prim Prime		SITE NAME:	Broughton Lane, Broughton	queen posts hipped to the west end and half hipped to east. Barn clad in weatherboarding with a gabled C19 cart
Constraint Fair Constraint Vacant/not in use Performance Vacant/not in use Performance Private, multiple owners Performance 13 10584 Performance Scheduled Mounders, 21 Bs. Performance Vacant/not in use Private Vacy bad Contact: Rachel James 0207 973 3153 Private Line Notas Private Line Notas Private Line Notas <td></td> <td>DESIGNATION:</td> <td>Listed Building grade II*</td> <td></td>		DESIGNATION:	Listed Building grade II*	
GCLANNCE GENERATE Ligited GCLANNCE GENERATE Ligited GCLANNCE GENERATE LIGIT CONTROL IN LIGIT GENERATE LIGIT CONTROL IN LIGIT CONTR AND LIGIT C		CONDITION:	Eair grant aid. Timber structure now supported by full inte	grant aid. Timber structure now supported by full internal
Ofference Legend Definition of the second seco		OCCUPANCY:	Vacant/not in use	
Ofference Legend Definition of the second seco		PRIORITY CATEGORY:	C (C)	
INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET NUMBER: [3]0584 Contact: Rachel James 0207 973 3153 INTERNET: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 INTERNET: Lodging Rangel *counthouse" rach for George Public House, High Street, Great mission of the set of the contact and continuous brick, of the set of the core and agreement with the owner't to purchase it means Company has expressed interest in restoring the contact and continuous brick, of the set of the core and agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contact agreement with the owner't to purchase it means Company has expressed interest in restoring the contagreement with the owner't to purchase it meanot agreemen	Star Land	OWNER TYPE:	Private, multiple owners	
Site with dovecore at Church Farm, Edisorough Church Farm, Devecore at Church Farm, Edisorough Church Farm, Devecore at Church Farm, Edisorough Device of the set galaxies	© Historic England	LIST ENTRY NUMBER:	1310584	Contact: Rachel James 0207 973 3153
Belavarios Scheduled Monument, 2 LBs Red and vitreous brick, close a structures of reduction of the new queen structures of reduction of the continuous brick ledges below. Divectore at risk due to structural and reducting and provinting and continuous brick ledges below. Divectore at risk due to structural and reducting and provinting to the most. A project needs to be initiated to address these issues. With Particle Divector at risk due to structural and reducting and provinting to the most. A project needs to be initiated to address these issues. Contract: Rachel James 0207 973 3153 With Part Part Internet Networks in the structural and reducting and provinting to the most. A project needs to be initiated to address these issues. Contract: Rachel James 0207 973 3153 With Part Part Internet Networks in the structure in reducting and provinting to the most. A project needs to be initiated to address these issues. Contract: Rachel James 0207 973 3153 With Part Part Internet Interse in restructure in reducting and provinting to the most interse in restructure in reducting and associated with it, they have not been able to reach agreement with the structure in reducting and associated pub have been recently acquired. Werey bad Option Controls (C) Option Controls (C) Owner Part Part Part Part Part Part Part Par		SITE NAME:	site with dovecote at Church	Church Farm. Dovecote mid-C18, a small rectangular building with each gable with four entrance holes, the east
Power Figure Note:		DESIGNATION:	Scheduled Monument, 2 LBs	Red and vitreous brick, old tile roof with two queen strut
OCCUMANCY: Vacant/not in use below. Dovecte a trik due to structural cracking and proximity to the moat. A project needs to be initiated to address these issues. 0- Hence: Englied Active UP there: Private Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel Fletcher 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contac		CONDITION:	Poor	trusses, one altered. Contains about 350 nesting boxes with rectangular openings and continuous brick ledges
PHOME FOR INCOME A (A) PHOME FOR INCOME Private UST REFINE NUMBER 1006955 Contact: Rachel James 0207 973 3153 Image: Second Se		OCCUPANCY:	Vacant/not in use	below. Dovecote at risk due to structural cracking and
Pitterser: Engend Archive List EINTRY NUMBER: 1006955 Contact: Rachel James 0207 973 3153 Image: Strain Str		PRIORITY CATEGORY:	A (A)	
USTENTRY NUMBER: 1006955 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 STENAME: Lodging Range/ "courthouse" rear of the George Public House, High Street, Great Missenden Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 STENAME: Lodging Range/ "courthouse" rear of the George Public House, High Street, Great Missenden CIS timber framed range, probably built as a court house. Structural probably built as a court house. Image: Contact: Rachel James 0207 973 3153 Design Attool (Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Contact: Rachel Fletcher 0207 973 3153 Image: Contact: Rachel Fletcher 0207 973 3153 Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Contact: Rachel James 0207 973 3153 Imaten: The serule wild for contact in the serule wild for		OWNER TYPE:	Private	
Pream of the George Public House, High Street, Great Missenden Structural problems at one end which is propped with House, High Street, Great Missenden Delkowie Tright Deskowie High Street, Great Missenden Structural problems at one end which is propped with house ascrited with it, they have not been able to reach agreement with the owner to purchase it. The building and associated pub have been recently acquired. 0 Nerve Tright Vacant/not in use PRORTY CATEGORY: C (C) 0 WANIER TYPE: Commercial company List ENTRY NUMBER: L124795 0 WANIER TYPE: Contact: Rachel Fletcher 0207 973 3846 0 Wary have commercial company List ENTRY NUMBER: Large rectangular dovecote built from stone of Notley Abbey: Some moulded stones found in core of wall. High hipped root of of ultis with dorner at eaves on east side and gable lourves rear ridge on north and south. Significant historic subsidence, root files and bartens failing admitting rain into the building. A schedule of works is currently being prepared. 0 EVENNEY: Vacant/not in use PRORTY CATEGORY: Vacant/not in use Private 0 Designation: Listed Building grade I, RPG grade II*, CA 0 Structural Barbel (CONDITON: Very bad 0 Occurrency: Vacant/not in use PRORTY CATEGORY: Vacant/not in use PRORTY CATEGORY: Vacant/not in use <tr< td=""><td>© Historic England Archive</td><td>LIST ENTRY NUMBER:</td><td>1006955</td><td>Contact: Rachel James 0207 973 3153</td></tr<>	© Historic England Archive	LIST ENTRY NUMBER:	1006955	Contact: Rachel James 0207 973 3153
Beladixin Ions Listed Building grade IP, CA Construction Very bad Construction Construction Priority CATEGORY: C (C) Construction Ust ENTRY NUMBER: I 124795 Contact: Rachel Fletcher 0207 973 3846 Image: Statistic England Ste Ename: Devector to north east of Notely Farm, Chearsley Road, Long Crendon Large rectangular dovector built from stone of Notely Abbey. Some moulded stones found in core of wall. High hipped roof of old tiles with dormer at eaves on east side and gabel loures rear ridge on north and south. Significant historic subsidence, roof tiles and battens failing admitting rain into the building. A schedule of works is currently being prepared. Peliferrit England Ste Enser NuMeer: Very bad Ist ENTRY NUMBER: 1289102 Contact: Rachel James 0207 973 3153 Ist ENTRY NUMBER: Listed Building grade I, RPG grade II ¹ , CA Country house built 1852-4 by Sir Joseph Paxton and GH Stokes for Baron Mayer Amschel de Rothschild. Listed Building Consent and Planning Permission granted for consents to a hotel together with a major extension. Paining Or the implementation of these consenent stopped in 2009, Emergency works undertaken to cen		SITE NAME:	rear of the George Public House, High Street, Great	Structural problems at one end which is propped with scaffolding to prevent collapse. Although a Community Interest Company has expressed interest in restoring the
With You acquired. acquired.		DESIGNATION:	Listed Building grade II*, CA	able to reach agreement with the owner to purchase it.
OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company UST ENTRY NUMBER: 1124795 Contact: Rachel Fletcher 0207 973 3846 Image: Second Seco		CONDITION:	Very bad	
• Huseric England OWNER TYPE: Commercial company UST ENTRY NUMBER: 1124795 Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3846 Image: Contact: Rachel Fletcher 0207 973 3153 Image: Contact: Rachel Fletcher 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153 Image: Contact: Rachel James 0207 973 3153		OCCUPANCY:	Vacant/not in use	
UST ENTRY NUMBER: 1124795 Contact: Rachel Fletcher 0207 973 3846 Image: Stress of the stress of provide stress of outling of the stress of the stress of provide stress of uses is determined and provide stress of uses is determined and provide stress of uses in the stress of uses is determined and provide stress of uses in the stress of uses of uses in the stress within the stress of uses in the stress of uses of uses of uses in the stress of uses of uses in the stress of uses of uses of uses of uses in the stress of uses in the stress of uses of uses of uses used and gate and used the uses of uses used and gate uses of uses used and gate uses of uses used and gate uses of uses used used uses of uses used used uses of uses of uset used uset used uset used used used uses of uses of uset used us		PRIORITY CATEGORY:	C (C)	
With the second seco	© Historic England	OWNER TYPE:	Commercial company	
Wotley Farm, Chearsley Road, Long Crendon Abbey. Some moulded stones found in core of wall. High hipped roof of old tiles with dormer at eaves on east side and gabled lowres rear ridge on north and south. Significant historic subsidence, roof tiles and battens failing admitting rain into the building. A schedule of works is currently being prepared. e Hutoric England DESIGNATION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: I 289 102 Contact: Rachel James 0207 973 3153 STE NAME: Mentmore Towers, Mentmore pasion private Condition: Poor CONDITION: Poor CONDITION: Poor COUNTRY CATEGORY: B (B) OWNER TYPE: Plos (CUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Commercial company Conditions in very poor condition. An application for Listed Building Consent and Planning Permission for repairs has been granted. In 2018/19 Historic England grant aided research into the wider landscape.		LIST ENTRY NUMBER:	1124795	Contact: Rachel Fletcher 0207 973 3846
Wr George Harper. Image supplied Site NATION: Listed Building grade I, SM Significant historic subsidence, roof tiles and battens failing admitting rain into the building. A schedule of works is currently being prepared. Wr George Harper. Image supplied Very bad Conductor Significant historic subsidence, roof tiles and battens failing admitting rain into the building. A schedule of works is currently being prepared. Wr George Harper. Image supplied Very bad Contact: Rachel James 0207 973 3153	A.	SITE NAME:	Notley Farm, Chearsley Road,	Abbey. Some moulded stones found in core of wall. High hipped roof of old tiles with dormer at eaves on east side
• OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1289102 Contact: Rachel James 0207 973 3153 STE NAME: Mentmore Towers, Mentmore Country house built 1852-4 by Sir Joseph Paxton and GH stokes for Baron Mayer Amschel de Rothschild. Listed Building Consent and Planning Permission granted for conversion to a hotel together with a major extension. PlioRITY CATEGORY: B (B) Over OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OVNER TYPE: Conmercial company	The second second second	DESIGNATION:	Listed Building grade I, SM	Significant historic subsidence, roof tiles and battens failing
OCCUPANCY: Vacant/not in use PHORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1289102 Contact: Rachel James 0207 973 3153 STENAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building grade I, RPG order and lister Priorition: CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Commercial company UST ENTRY NUMBER: II17863		CONDITION:	Very bad	
OWNER TYPE: Private ust entry number: 1289102 Contact: Rachel James 0207 973 3153 Image: state of the implementation of the implementation of these consents stopped in 2009. Emergency works undertaken to central roof lantern. The service wing roof remains in very poor continuous of the implementation of these consents and Planning Permission for repairs has been granted. In 2018/19 Historic England grant aided research into the wider landscape. Image: work george Harper. Image supplied Ust ENTRY NUMBER: 1117863		OCCUPANCY:	Vacant/not in use	/ 01 1
• Historic England List ENTRY NUMBER: 1289102 Contact: Rachel James 0207 973 3153 File NAME: Listed Building grade I, RPG grade II*, CA Country house built 1852-4 by Sir Joseph Paxton and GH Stokes for Baron Mayer Amschel de Rothschild. Listed Building Consent and Planning Permission granted for conversion to a hotel together with a major extension. Planning for the implementation of these consents stopped in 2009. Emergency works undertaken to central roof lantern. The service wing roof remains in very poor condition. An application for Listed Building Consent and Planning Permission for repairs has been granted. In 2018/19 Historic England grant aided research into the wider landscape. e Mr George Harper. Image supplied List ENTRY NUMBER: 1117863	and the second se	PRIORITY CATEGORY:	A (A)	
UST ENTRY NUMBER: 1289102 Contact: Rachel James 0207 973 3153 INFERMINE Mentmore Towers, Mentmore Contact: Rachel James 0207 973 3153 INFERMINE Mentmore Towers, Mentmore Site NAME: Infermine Listed Building grade I, RPG Country house built 1852-4 by Sir Joseph Paxton and GH Infermine Listed Building grade I, RPG Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Listed Building grade I, RPG Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Condition: Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Condition: Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Mayer Amschel de Rothschild. Listed Infermine Poor Stokes for Baron Ma	Historic England	OWNER TYPE:	Private	
• Mr George Harper. Image supplied List entrry NUMBER: Listed Building grade I, RPG grade II*, CA Stokes for Baron Mayer Amschel de Rothschild. Listed Building Consent and Planning Permission granted for conversion to a hotel together with a major extension. • Mr George Harper. Image supplied List ENTRY NUMBER: II17863 Stokes for Baron Mayer Amschel de Rothschild. Listed Building Consent and Planning Permission granted for conversion to a hotel together with a major extension. • Mr George Harper. Image supplied List ENTRY NUMBER: II17863		LIST ENTRY NUMBER:	1289102	Contact: Rachel James 0207 973 3153
Image: State of the state	y was	SITE NAME:	,	Stokes for Baron Mayer Amschel de Rothschild. Listed
OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (B) OWNER TYPE: Commercial company OWN George Harper. Image supplied LIST ENTRY NUMBER:		DESIGNATION:		conversion to a hotel together with a major extension.
OCCUPANCY: Vacant/not in use lantern. The service wing roof remains in very poor condition. An application for Listed Building Consent and Planning Permission for repairs has been granted. In 2018/19 Historic England grant aided research into the wider landscape. © Mr George Harper. Image supplied LIST ENTRY NUMBER: 1117863		CONDITION:	Poor	Planning for the implementation of these consents stopped
Image: Supplied PRIORITY CATEGORY: B (B) Planning Permission for repairs has been granted. In 2018/19 Historic England grant aided research into the wider landscape. Image: Supplied LIST ENTRY NUMBER: 1117863 Contact: Rachel lames 0207 973 3153	alle a start	OCCUPANCY:	Vacant/not in use	lantern. The service wing roof remains in very poor
OWNER TYPE: Commercial company 2018/19 Historic England grant aided research into the wider landscape. © Mr George Harper. Image supplied LIST ENTRY NUMBER: 1117863		PRIORITY CATEGORY:	B (B)	condition. An application for Listed Building Consent and Planning Permission for repairs has been granted. In
© Mr George Harper. Image supplied LIST ENTRY NUMBER: 1117863	The loss of the second support advance of bases of biglind	OWNER TYPE:	Commercial company	2018/19 Historic England grant aided research into the
		LIST ENTRY NUMBER:	1117863	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA)

	SITE NAME:	The East Boycott Pavilion, Stowe Landscape Garden, Stowe	One of a pair of large stone pavilions, circa 1728, by James Gibbs, altered by Borra in 1754 to change the steep pyramidal roofs to domes with cupolas. It now
	DESIGNATION:	Listed Building grade I, RPG grade I, CA	incorporates domestic accommodation, but was previously an open-sided belvedere. With its western twin, these pavilions straddle the Oxford Avenue, at the south west of
	CONDITION:	Poor	The Course, which is the main approach to the house. Domed roof replacement needed and cupola reinstatment
	OCCUPANCY:	Part occupied/part in use	National Trust plan major repairs and removal of 1950s
	PRIORITY CATEGORY:	C (C)	interiors and conservation of original interior space in 2021-22.
) Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1289656	Contact: Rachel James 0207 973 3153
1	SITE NAME:	The Palladian Bridge, Stowe Landscape Garden, Stowe	Covered bridge built in 1738; attributed to James Gibbs, situated in the south east corner of the pleasure grounds.
Semila Inter	DESIGNATION:	Listed Building grade I, RPG grade I, CA	The bridge is viewed from the west across the Octagon Lake and from the north west and north across Hawkwell Fields. Steady decay of the roof covering, ceiling plaster an
	CONDITION:	Very bad	masonry. Holding repairs have been carried out, full
Colore and	OCCUPANCY:	N/A	conservation and repair is planned.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Charity (heritage)	
Historic England Archive	LIST ENTRY NUMBER:	1289750	Contact: Rachel James 0207 973 3153
	SITE NAME:	Aviary at Dropmore House,	Aviary, early C19, situated on south side of range of
	DESIGNATION:	Heathfield Road, Taplow Listed Building grade I, RPG grade II	buildings to west of the house. Previously vulnerable to heritage crime and longstanding lack of regular maintenance. Situated within late CI8 to early CI9
The second second	CONDITION:	Poor	gardens. Mansion converted into residential use. Restoration of the gardens in progress and structural
and the second s	OCCUPANCY:	N/A	repairs to the aviary by a specialist blacksmith now successfully carried out but marble inserts remain to be
	PRIORITY CATEGORY:	F (F)	completed.
	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1332401	Contact: Rachel James 0207 973 3153
1. M. M.	SITE NAME:	Church of St Martin, Dunton	Church, CI2 nave with south wall rebuilt late CI8, CI3
SAL PR	DESIGNATION:	Listed Place of Worship grade II*	chancel. CI5 west tower, all much restored late C18. Nav and tower are of large stone blocks, squared and coursed
	CONDITION:	Very bad	with brick repairs and dressings. Chancel is rendered. Slat
	PRIORITY CATEGORY:	A (A)	roof to nave, tiled roof to chancel. Tower of two stages has clasping buttresses, brick parapet and pointed single
	OWNER TYPE:	Religious organisation	openings to bell chamber. Serious cracking to north and south walls of the medieval chancel. Minor repairs and
	LIST ENTRY NUMBER:	1211972	investigations ongoing.
Historic England			Contact: Rachel James 0207 973 3153
	SITE NAME:	Church of All Saints, Church	Church with mid-C15 west tower of rubble stone.
		End, Hillesden	Remainder rebuilt after 1493 in ashlar, restored 1874-5 by
	DESIGNATION:	Listed Place of Worship grade I, CA	Sir George Gilbert Scott and again in 1960. The high level stonework was in very bad condition which put the churcl on the Heritage at Risk Register. Some repairs have been
		Poor	carried out under the National Lottery Heritage Fund

	DESIGNATION:	Listed Place of Worship grade I, CA	stonework was in very bad condition which put the church on the Heritage at Risk Register. Some repairs have been
3	CONDITION:	Poor	carried out under the National Lottery Heritage Fund Grants for Places of Worship scheme but further repairs to
La l	PRIORITY CATEGORY:	C (C)	the church are required.
1	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1288641	Contact: Rachel James 0207 973 3153

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOLITH EAST / RUCKINGHAMSHIRE (LIA)

HERITAGE AT RISK 2021 / LOND	on and south east	/ BUCKINGHAMSHIRE (UA)		
	SITE NAME:	Church of St Michael and All Angels, Hughenden Park, Hughenden	W Blomfield. Kn roofs. North we	CI4, almost totally rebuilt 1875 by Sir A apped flint with stone dressings and tiled st tower, nave, south porch, north aisle,
	DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA	north chapel now vestry, and chancel. In Decorate with arched traceried windows. Tower is of three s with set back buttresses, battlemented parapet and	
Bender strangering (all	CONDITION:	Poor	pyramidal roof.	Water ingress in the tower roof is causing
	PRIORITY CATEGORY:	A (A)	drawings comple	roof structure. Repair specification and ited, but work on hold. Temporary
1	OWNER TYPE:	Religious organisation	protection and r	epairs in place.
© Historic England	LIST ENTRY NUMBER:	1125743	Contact: Rachel	James 0207 973 3153
A sale	SITE NAME:	Church of All Saints, The Green, Hulcott	Church of C14 and C16, restored. Rubble limestone w tiled roof, C16 wooden bellcote with boarded sides an	
	DESIGNATION:	Listed Place of Worship grade II*, CA	shingled spire. Se Church use for s	erious structural problems in masonry. pecial services.
	CONDITION:	Very bad		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1281503	Contact: Rachel	James 0207 973 3153
© Historic England				
	SITE NAME:	Church of St Mary the Virgin, Church Lane, Ludgershall	Largely C14 church with C19 restorations. The nave, porch and north and south aisles were re-roofed, and decaying roof structure repaired. Repair work to the to roof, tower stonework, repointing, rainwater goods an drainage also now completed. Both phases were supported by the National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship scheme. The timber belfry structure has been repaired National Lottery Heritage Fund Grants for Places of Worship grant application was unsuccessful, but intern repairs to damaged plasterwork need to be addressed	
	DESIGNATION:	Listed Place of Worship grade I, CA		
	CONDITION:	Poor		
	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1124276		
© Historic England			Contact: Rachel	James 0207 973 3153
SITE NAME:	Desborough Cas	tle		
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1020863
CONDITION:	Generally unsatisf problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism		NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bell barrow 260n Saunderton	n WNW of Slough Glebe Farm, pa	rt of the Saundert	on Lee barrow cemetery, Bledlow-cum-
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1013953
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	pany	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 140 Bledlow-cum-Sau)m WNW of Slough Glebe Farm, F Inderton	part of the Saunder	ton Lee round barrow cemetery,
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1013954
CONDITION:	Extensive significa	nt problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	pany	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA)

SITE NAME:	Bowl barrow at Molin's Works, part of the Saunderton Lee round barrow cemetery, Bledlow-cum- Saunderton			
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1013955
CONDITION:	Generally unsatist problems	Generally unsatisfactory with major localised problems		Unknown
PRINCIPAL VULNERABILITY:	Permitted develo	pment	NEW ENTRY?:	No
OWNER TYPE:	Commercial com	pany	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows 450m north west of Slough Glebe Bledlow-cum-Saunderton		be Farm, part of th	e Saunderton Lee barrow cemetery,
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1013952
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	pany	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Large multivallate	e hillfort known as Cholesbury Car	mp, Cholesbury-cu	m-St. Leonards
DESIGNATION:	Scheduled Monur	ment, part in CA	LIST ENTRY NUMBER:	1015585
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY ?:	Yes
OWNER TYPE:	Mixed, multiple owners		CONTACT:	Chris Welch 0207 973 3633
SITE NAME:	Dam walls; part of Motte and bailey castle, moated s Church, Great and Little Kimble cum Marsh		site and Roman vil	la immediately east of All Saint's
DESIGNATION:	Scheduled Monument, part in RPG grade II		LIST ENTRY NUMBER:	1018007
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	·		NEW ENTRY ?:	No
OWNER TYPE:	· ·		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa north	h of Yewden Lodge, Hambleden		
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1014606
CONDITION:	Generally unsatist problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Halton House, Aston Clinton / Halton	the Aylesbury Va	riginal seven Rothschild country houses le with late C19 formal gardens and par
	DESIGNATION:	ATION: Registered Park and Garden grade II, 5 LBs, part in CA		ides. Sold to the Royal Air Force in 1918 the Officers' Mess to RAF Halton. used arm of the Grand Union Canal muc
	CONDITION:	Extensive significant problems	of the open parkland has been fragmented and lost to development of the camp with the historic fabric of the	
1 / 2	VULNERABILITY:	High	ornamental featu	res of the garden in poor condition.The
	TREND:	Stable		l structure survives managed by the ssion. A Conservation Management Plar
	NEW ENTRY ?:	No		to guide future proposals.
🛛 Historic England	OWNER TYPE: Mixed, multiple owners			
	OWNER TYPE:	Mixed, multiple owners		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA) / EASTBOURNE

	SITE NAME:	Mentmore Towers, Mentmore / Cheddington	Sir Joseph Paxton designed this largest of the Rothschild family houses in a prominent position in the Vale of
and the second second	DESIGNATION:	Registered Park and Garden grade II*, 10 LBs, 2 CAs	Aylesbury, with formal gardens and park to complement it and a contemporary Arts and Crafts estate village. Sold in 2000, permission was sought to convert the house into a
	CONDITION:	Generally satisfactory but with significant localised problems	hotel and conference centre. With the estate ownership fragmented, much of the park converted to golf, and new development proposals a Landscape & Conservation Area
A CAR	VULNERABILITY:	High	Appraisal funded by Historic England and completed in
- A - A	TREND:	Stable	2020 assesses the significance, fabric, character and setting of Mentmore to inform decisions.
) Historic England	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000319	Contact: Kay Richardson 0207 973 3647

EAST SUSSEX

	SITE NAME:	Eastbourne Redoubt, Eastbourne	A redoubt built as part of the Martello system, 1806. Main parts are in use as a museum. The aquarium building, which	
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	occupies casemates and the mast on the south west side in very poor condition. The surviving caponiers suffer fro water ingress. Moat walls are decaying. A Conservation Plan has been produced and proposals are being developed.	
hand the second	CONDITION:	Poor		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority		
© Historic England Archive	LIST ENTRY NUMBER:	1017358 and 1043662	Contact: Rebecca Lambert 0207 973 3630	
	SITE NAME:	Martello Tower No. 64, Eastbourne	Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.	
	DESIGNATION:	Scheduled Monument and Listed Building grade II		
(作) 二, 对意	CONDITION:	Poor		
	OCCUPANCY:	Vacant/not in use		
desident the	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1017355 and 1043661	Contact: Rebecca Lambert 0207 973 3630	
	SITE NAME:	Martello Tower No. 66, Langney Point, Eastbourne	Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical	
	DESIGNATION:	Scheduled Monument and Listed Building grade II	significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.	
	CONDITION:	Fair		
TANK THE PARTY OF	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1017356 and 1043660	Contact: Rebecca Lambert 0207 973 3630	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / EASTBOURNE / HASTINGS

	SITE NAME:	Eastbourne Pier, Grand Parade	The pier is 1,000ft long and 52ft wide on a substructure of
	DESIGNATION:	Listed Building grade II*, CA	iron screw piles, designed by Eugenius Birch and completed in 1872. The seaward Pavilion Theatre with 'camera
	CONDITION:	Very bad	obscura' and two games pavilions were designed and built in 1901 by Noel Ridley. The central windscreens were erected 1902-03 and the music pavilion added in 1925, designed by PD Stoneham. Later additions include the kiosks in 1971 and an entrance building in 1991. In July 2014
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	the landward arcade building was destroyed by fire. Historic England, the owners and Eastbourne Borough
	LIST ENTRY NUMBER:	1353116	Council have discussed how to reinstate.
England			Contact: David John 0207 973 3638

© Historic England


SITE NAME:	Shinewater Bronze Age settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1400780
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Maria Buczak 0207 973 3642

HASTINGS

© Historic England

•			
d	SITE NAME:	Chapel to the Former Convent of the Holy Child Jesus, Magdalen Road, St Leonards	Former convent chapel, partly designed by Augustus Welby Pugin and completed by his son Edward Welby Pugin. The chapel has a good High Victorian Gothic interior
	DESIGNATION:	Listed Building grade II*, CA	and is a rare example of a Roman Catholic Chapel retaining the nuns' choir. The convent complex is used as a language
	CONDITION:	Poor	school in the summer. Some of the more urgent repairs to the chapel have started to be addressed, but more work is
	OCCUPANCY:	Part occupied/part in use	still required, externally and internally.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1043478	Contact: David John 0207 973 3638

	SITE NAME:	Church of All Souls, Athelstan Road, Hastings	Former church built 1889. Designed by Sir Arthur Blomfield. Vacant since February 2008 and now closed for
	DESIGNATION:	Listed Building grade II*	worship. Its richly decorated interiors mean that it was included on the Victorian Society's top ten list of
	CONDITION:	Poor	endangered buildings in 2014. A new owner intends to use the building as a studio and for the display of art works with
	OCCUPANCY:	Vacant/not in use	some change to the interior fittings. Some holding repairs
	PRIORITY CATEGORY:	A (A)	are proposed for the south east chapel roof.
	OWNER TYPE:	Private	
tings Borough	LIST ENTRY NUMBER:	1293681	Contact: David John 0207 973 3638





Remains of Manor House, Ore Ruins of late medieval manor house surrounded by new SITE NAME: housing development, close to Old St Helens Church. The Place, Ore ruins are being damaged by heavy vegetation growth. DESIGNATION: Scheduled Monument, CA CONDITION. Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1002271 Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

ΗE

HERITAGE AT RISK 2021 / LONDO	on and south east	/ HASTINGS	
	SITE NAME:	Pelham Arcade, 1-12 and 12A, Pelham Place, Hastings	Semi-subterranean arcade of shops, developed as the first part of the Pelham scheme by Joseph Kay in 1823-5. Poor
	DESIGNATION:	Listed Building grade II*, CA	drainage from the carriage drive above the Arcade and structural failures in its formerly glazed lantern have
	CONDITION:	Poor	resulted in problems of damp, particularly to the rear. Investigation work to inform the road repairs, funded
	OCCUPANCY:	Part occupied/part in use	jointly by Historic England and Hastings Borough Council,
	PRIORITY CATEGORY:	D (E)	were completed in 2021. Historic England and Hastings Borough Council continue to explore funding opportunities
	OWNER TYPE:	Local authority, multiple owners	to support the package of repairs to the road and the arcade of shops below.
© Historic England	LIST ENTRY NUMBER:	1043389	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	Statue of Queen Anne south east of Holmhurst St Mary's School, The Ridge, Baldslow	Statue, 1711-12 in grounds of former convent (now sold separately). Longstanding lack of regular maintenance meant it was deteriorating rapidly through rainwater from overhanging trees and saline rain from the sea. It has also
K Contract	DESIGNATION:	Listed Building grade II*	been recently subject to heritage crime but has now been
	CONDITION:	Very bad	made secure. An application for residential development which would secure the repair of the statue and improve
	OCCUPANCY:	N/A	its setting has now been granted by the Local Planning
ALSE	PRIORITY CATEGORY:	B (B)	Authority. The developer has committed to carrying out repairs through a \$106 Agreement.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1192060	Contact: Alma Howell 0207 9733 627
	SITE NAME:	Church of St Leonard, Hastings	Church built in 1953-61 by Sir Giles and Adrian Gilbert
t	DESIGNATION:	Listed Place of Worship grade II, CA	Scott. Buff brick with cream stone dressings. Pantiled low pitched roof to eaves. Rectangular plan with altar against east wall and choir stalls in chancel. Nave with passage
	CONDITION:	Poor	aisles. Western tower, with entrance beneath. Simplified modernistic Gothic manner. Exterior dominated by fine
	PRIORITY CATEGORY:	C (C)	blocky Gothic west tower reached by a flight of steps
	OWNER TYPE:	Religious organisation	which has parabolic shape with late Gothic mouldings dying into the jambs. Congregation have moved out as there are
	LIST ENTRY NUMBER:	1376621	concerns about the surrounding low cliff that needs stabilising. Church now closed.
© Historic England			Contact: David John 0207 973 3638
			-
	SITE NAME:	Former United Reformed Church, Cambridge Road, Hastings	Built as a congregational church in 1885. Rainwater system very poor and needs replacing with more outlets, wider rainwater goods, more efficient drops. Movement cracks
	DESIGNATION:	Listed Place of Worship grade II, CA	are allowing rain penetration. Discussions are taking place with the new owners, a new religious group, who are carrying out emergency works and considering funding
	CONDITION:	Poor	options for full repairs.
	PRIORITY CATEGORY:	A (A)	
12	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1393646	Contact: David John 0207 973 3638
	SITE NAME:	Christ Church, London Road, St Leonards on Sea, Hastings	Late Victorian church designed by Blomfield with later additions in prominent location. Suffering from severe erosion due to vulnerable stonework and proximity to
	DESIGNATION:	Listed Place of Worship grade II*, CA	coast. Also rainwater goods in need of overhauling, window feramenta deteriorating and general deterioration
A Sell	CONDITION:	Poor	of fabric. Carrying out repairs in 2021 to the tower and spire with funding from the Heritage Stimulus Fund.
	PRIORITY CATEGORY:	D (New entry)	
and the second	OWNER TYPE:	Religious organisation	
© Thames Valley Drones	LIST ENTRY NUMBER:	1286965	Contact: David John 0207 973 3638
C manues railey Diones			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HASTINGS / LEWES

LIST ENTRY NUMBER:

1043430

	SITE NAME:	Church of St Thomas of Canterbury and the English Martyrs, Magdalen Road, Hastings	Built in 1889 by Charles Alban Buckler with an interior scheme by Nathaniel Westlake, 1908 and 1911 which is deteriorating due to water penetration caused by inappropriate external pointing, poor rainwater disposal
A PARA	DESIGNATION:	Listed Place of Worship grade II, CA	and the roof requiring repairs.
	CONDITION:	Poor	
A CONTRACTOR OF THE OWNER	PRIORITY CATEGORY:	C (New entry)	
© Historic England	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	39 83	Contact: David John 0207 973 3638
	SITE NAME:	Church of the Holy Trinity,	Victorian church designed by SS Teulon with stained glass
		Robertson Street, Hastings	windows by Clayton and Bell and Kempe. The stonework is displaying serious effects of erosion, particularly on the
	DESIGNATION:	Listed Place of Worship grade II*, CA	south, east and west elevations. The mullions and window tracery are particularly bad, allowing water to penetrate
Mar and Marce	CONDITION:	Poor	into the building. Awaiting the outcome of project development funding from the National Lottery Heritage
	PRIORITY CATEGORY:	D	Fund.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1043423	Contact: David John 0207 973 3638
© Historic England			
	SITE NAME:	Church of St Mary Magdalen, St Margaret's Road, St Leonards	Decorated-style church by Frederick Marrable, 1852, in a prominent position in St Leonards. It has a four-stage south
	DESIGNATION:	Listed Place of Worship grade II, CA	west tower built in 1872. Facing stonework and roofs in a fair condition but the tracery stonework is in a very poor condition. Historic England has given advice on repair and
14 Long / 14	CONDITION:	Poor	funding options. Repairs to the south aisle roof and drainage have recently been carried out.
HUNDER AND	PRIORITY CATEGORY:	A (A)	Gramage have recently been carried out.
	OWNER TYPE:	Religious organisation	

© Historic England

SITE NAME:	Hastings Town Centre		
DESIGNATION:	Conservation Area, 24 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jane Stephen (LPA) 01424 783273

LEWES

States -

	SITE NAME:	Newhaven Fort; Caponier, Fort Road, Newhaven	Caponier of Newhaven Fort. Victorian caponier is in very poor condition in places. Lunette battery was repaired with
Ser Ale	DESIGNATION:	Scheduled Monument	a Historic England grant by Lewes District Council in 2009. In 2017 National Lottery Heritage Funding was accepted to
	CONDITION:	Poor	develop a project for further repairs and interpretation at the fort. An application for the repairs fund is expected to
FRANKIN AND OF	OCCUPANCY:	Vacant/not in use	be made.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
toric England	LIST ENTRY NUMBER:	1002242	Contact: David John 0207 973 3638

© Histo

PR	OR	RITY	CA	TEC	GO	RIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: David John 0207 973 3638

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / ROTHER

ROTHER

© Historic England

© Historic England




	SITE NAME:	Martello Tower No. 28, Rye Harbour, Icklesham	Martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeological and
	DESIGNATION:	Scheduled Monument and Listed Building grade II	historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
100	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017353 and 1234372	Contact: David John 0207 973 3638



and the second se	SITE NAME:	Ruins of the former friary church [Grey Friars (Winchelsea Priory)], Friars Road, Winchelsea, Icklesham	Extensive ruins to full wall height of a monastic church c1310-20, now in the grounds of a C19 mansion. Ruins have significant plant growth with decay to stonework. Ir 2016 a quinquennial survey was carried out and		
- And	DESIGNATION:	Scheduled Monument and Listed Building grade I, CA	recommended various conservation works. At that time discussions took place with the owners regarding a programme of conservation works and maintenance		
	CONDITION:	Poor	however nothing has progressed since. There is a need to re-start a conversation about this; an updated survey is		
	OCCUPANCY:	N/A	likely to be required.		
	PRIORITY CATEGORY:	A (A)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1002301 and 1234450	Contact: Maria Buczak 0207 973 3642		





© Historic England Archive



			Contact. David John 0207 775 5050
Ser 1 and	SITE NAME:	Martello Tower No. 30, Winchelsea Road, Rye	Martello tower built 1806. The moat and glacis on the east side lost. Unconnected with destruction of the moat and
a state	DESIGNATION:	Scheduled Monument and Listed Building grade II	glacis, a small housing development was built adjacent to the east. The preservation of archaeological and historical significance will be the main consideration in assessing the
1000	CONDITION:	Poor	suitability of proposals to convert Martello towers for residential use.
the last	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
Â,	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017354 and 1262420	Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / ROTHER / SOUTH DOWNS (NP)

SITE NAME:	Church of St Barnabas, Sea Road, Bexhill	Late C19 and early C20 church in flint and red brick. Urgent repairs are required to re-cover the south aisle roof
DESIGNATION:	Listed Place of Worship grade II, CA	and the spire, including renewal of rainwater goods and repairs to stonework and window glass. The congregation was offered grant from the joint Historic England and
CONDITION:	Poor	National Lottery Heritage Fund for Places of Worship scheme in March 2012. However, it was not possible to
PRIORITY CATEGORY:	A (A)	proceed with the work. Discussions have taken place as to
OWNER TYPE:	Religious organisation	how a repair project might be taken forward.
LIST ENTRY NUMBER:	1044250	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Romano-British iron working site in Beauport Par	k, Battle	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002250
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

SOUTH DOWNS (NP)



F)			
-	SITE NAME:	Dovecote 160 metres north west of Coombe Place, Offham, Hamsey, Lewes	Early C19 dovecote within the grounds of Coombe Place. Ornate octagonal building of flint with dressings and quoins of red and grey brick. Water ingress and collapse of chalk
7	DESIGNATION:	Scheduled Monument, LB grade II	and brick nesting boxes inside is the cause of risk. Discussions have taken place with the owners as to how a repair project might be completed.
	CONDITION:	Poor	
ALC: NO	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1019248	Contact: David John 0207 973 3638



-	SITE NAME:	Icehouse at Coombe Place, Offham, Hamsey, Lewes	Late C18 ice house within the grounds of Coombe Place. The risk arises from heavy vegetation growth on the
	DESIGNATION:	Scheduled Monument	structure and partial collapse of the entrance tunnel vault. Discussions have taken place with the owners about how a
	CONDITION:	Poor	repair project can be completed.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
AL AL	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1019884	Contact: David John 0207 973 3638

© Historic England

© Historic England

SITE NAME:	Anglo-Saxon cemetery 275m north of Comps Farm	, Beddingham, Lew	ves
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021436
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Round barrow south of Ditchling Beacon, Ditchling,	, Lewes	
SITE NAME: DESIGNATION:	Round barrow south of Ditchling Beacon, Ditchling Scheduled Monument	LIST ENTRY NUMBER:	1002254
			1002254 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP) / WEALDEN

	· · · ·		
SITE NAME:	Bowl barrow forming part of a linear round barrow	v cemetery on Roo	kery Hill, Seaford, Lewes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009953
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Hillfort and a bowl barrow on Seaford Head, Seafo	rd, Lewes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014523
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows, the south easternmost pair of round barrow cemetery on Rookery Hill, Seaford,	a group of six bow Lewes	l barrows, forming part of a linear
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009951
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

SOUTH DOWNS (NP) / BRIGHTON AND HOVE, CITY OF (UA) / LEWES

	SITE NAME:	Stanmer Park, Ditchling / Falmer / Westmeston, Brighton and Hove, City of (UA), Lewes	Undulating C18 landscape park between city fringe and Sussex Downs surrounding a country house and incorporating Stanmer village. Bought by the Council
	Designation:	Registered Park and Garden grade II, 19 LBs, 4 SMs, part in CA	(1947) for public amenity, the parkland fabric is highly fragmented by A27 and woodland loss (1987) with furthe housing development approved in 2021. National Lottery Heritage Fund funded works to improve parking, access
	CONDITION:	Extensive significant problems	and convert the walled garden opening 2021. Next ste joint management and visioning within parkland, conservation plans being sought through Whole Estate with Highways England Designated Funds for access improvements.
	VULNERABILITY:	Medium	
© Historic England	TREND:	Stable	
	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1001447	Contact: Kay Richardson 0207 973 3647

WEALDEN



Church of CI3 built of stone rubble with tiled roof. Church of All Saints, Waldron, SITE NAME: Heathfield and Waldron Consists of chancel, aisled nave, north porch and west erpendicular epairs to the al Inspection ng problems asonry and roof which

© Historic England

DESIGNATION:	Listed Place of Worship grade I, CA	tower with higher stairs turret. Tower in the Pe style. South aisle dates from 1859-62. Urgent re tower have been completed. The Quinquennial
CONDITION:	Poor	carried out in 2019 identified significant on-going with old cement mortar repointing, eroded mas
PRIORITY CATEGORY:	C (C)	roof surfaces. The main issue is the south aisle r
OWNER TYPE:	Religious organisation	needs comprehensive repair.
LIST ENTRY NUMBER:	1284195	Contact: David John 0207 973 3638

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- Conservation Area Listed Building Local Planning Authority National Park LPA
- NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WEALDEN / WEST BERKSHIRE (UA)

	SITE NAME:	Church of St Andrew, The Tye, Alfriston, Wealden	C14 church; cruciform in plan with a central tower and spire, known as the Cathedral of the Downs. Knapped flint
	DESIGNATION:	Listed Place of Worship grade I, CA	walls and tiled roof. The spire has recently been repaired. However, the church walls are damp due to hard cementitious mortar trapping moisture. Some of the walls
	CONDITION:	Poor	have now been repointed and re-plastered in lime which is helping them to dry out. The south transept requires
	PRIORITY CATEGORY:	C (C)	similar repair work.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1043353	Contact: David John 0207 973 3638
© Historic England			

© Historic England



	SITE NAME:	Kidbrooke Park, Forest Row	CI8 park with extensive surviving early CI9 features				
	DESIGNATION:	Registered Park and Garden grade II, 2 LBs	including a designed water system attributed to Repton and later gardens. Sold and broken up after WWII, the house was converted to a school. Development has further				
	CONDITION:	Generally satisfactory but with significant localised problems	reduced the park and with increasing woodland cover fragmented historical design intentions such as designed views. Proposals for using the lower lake as a flood storage				
	VULNERABILITY:	Medium	facility have also been explored. A 2016 Parkland Plan for				
Sec.	TREND:	Declining	the school part-funded by Natural England explored options for restoration works for tree cover management				
1	NEW ENTRY ?:	No	and repair of parkland architecture.				
	OWNER TYPE:	Mixed, multiple owners					
	LIST ENTRY NUMBER:	1000305	Contact: Kay Richardson 0207 973 3647				

EAST SUSSEX / KENT

WEALDEN / TUNBRIDGE WELLS

SITE NAME:	High Rocks Camp (see also Tunbridge Wells, Kent), Frant			
DESIGNATION:	Scheduled Monument, SM LIST ENTRY NUMBER: 1002280			
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	

HAMPSHIRE

©

WEST BERKSHIRE (UA) / BASINGSTOKE AND DEANE

P Historic England	SITE NAME:	Sandleford Priory, Greenham / Newtown	A mid-late C18 landscape park with waterbodies laid out to designs by Lancelot Brown, surrounding a Gothick
	DESIGNATION:	Registered Park and Garden grade II, 2 LBs	house remodelled by James Wyatt. Once straddling the A339 the estate was sold into divided ownership, the house, gardens and core of the park being used as a scho
	CONDITION:	Extensive significant problems	The northern park has been largely developed (housing, waste disposal) leaving the core compromised as a design
	VULNERABILITY:	High	fragment which in turn is under-resourced in its
	TREND:	Declining	management. The setting of the house and park and gard is extremely vulnerable to housing and business
	NEW ENTRY ?:	No	development potential identified in the Local Plan.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000333	Contact: Kay Richardson 0207 973 3647

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

1157463

BASINGSTOKE AND DEANE

-14		
M.	T	III

SITE NAME: Barn at Manor Farm, Old Burghclere, Burghclere DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (D) OWNER TYPE: Commercial company

LIST ENTRY NUMBER:

Manorial barn, 1451, built for the Bishop of Winchester. Suffering from water ingress and failure of joints, the building needs comprehensive repair. Emergency repairs have been carried out. Full cost of repairs is very high. The owners have decided to undertake the repairs on a phased basis over 8 years. Works commenced in May 2017 to repair the 3 eastern bays of the barn. These works have been successfully completed. The next phase of repair was scheduled to commence in the summer of 2020 but due to Covid-19 these works have been postponed for one year.

Contact: Marion Brinton 0207 973 3631

© Historic England

SITE NAME:	Long barrow 600m south of Preston Grange, Pre	eston Candover	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013009
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Round barrow south west of Lower Farm, Presto	on Candover	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005541
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman site north west of Woodgarston Farm, V	Vootton St. Lawrence	e with Ramsdell
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001857
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
EAST HAMPSHIRE			
SITE NAME:	Walldown enclosures, Whitehill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017368

DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017368
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

EASTLEIGH

SITE NAME:	Promontory defined by an Iron Age linear earthwork, St Andrew's Castle and additional remains on Hamble Common, Hamble-le-Rice		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1008695
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Alex Bellisario 0207 973 3700

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

WHS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM ŬA

Unitary Authority World Heritage Site

FAREHAM

With the second seco	SITE NAME:	Brick Kiln, Chimney, Drying Sheds, Boiler and Engine House at Bursledon Brickworks south Section, Coal Park Lane, Swanwick	Steam driven brickworks complex in use from C19 until 1970's with what appears to be the earliest surviving Staffordshire type continuous kiln, with ten chambers. Now a museum, the buildings are mainly constructed of red brick with corrugated sheet roofs. At risk due to decay and
	DESIGNATION:	Listed Building grade II*	vulnerability of unsupported walls to roofless drying sheds and leaking roof above the brick kiln. National Lottery
	CONDITION:	Poor	Heritage Fund have grant-aided a Development Phase for repairing and converting the drying sheds but funding
	OCCUPANCY:	Vacant/not in use	required to implement the scheme.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1233725	Contact: Robert Williams 0207 973 3641



SITE NAME:	Fort Fareham, Newgate Lane, Fareham	Royal Commission fort built in 1861. The only one of three proposed 'Gosport Outer Line' forts built due to defence
DESIGNATION:	Scheduled Monument and Listed Building grade II, LB grade II	cuts. It was intended to be part of a further line of defence to the already completed 'Gosport Advanced Line' of Forts Elson, Brockhurst, Rowner, Grange and Gomer, built to
CONDITION:	Poor	defend Portsmouth Harbour. Unoccupied parts, including ramparts, suffering from decay and heritage crime. Interior
OCCUPANCY:	Part occupied/part in use	of Fort functioning as a business and industrial estate.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1001856 and 1094240	Contact: Rachel James 0207 973 3153

© Historic England

GOSPORT

© Historic England

	SITE NAME:	Gunboat Sheds and Workshops, Haslar Gunboat Yard	A row of ten gunboat sheds and three maintenance workshops, designed in 1856 by William Scamp of the
	DESIGNATION:	Listed Building grade I, CA	Admiralty Works Department as part of the Haslar Gunboat Yard for the housing and repair of British
	CONDITION:	Very bad	gunboats, and their successor craft, of the Royal Navy. The adjacent traverser system was used for their launch and
	OCCUPANCY:	Vacant/not in use	movement. The site ceased to be used in the mid-1970s
- n	PRIORITY CATEGORY:	C (C)	but remained in MOD ownership. Once vacant, condition deteriorated, with only minimum maintenance undertaken.
	OWNER TYPE:	Commercial company	Historic England granted aided a feasibility study in 2019 to help find an appropriate new use for the site.
	LIST ENTRY NUMBER:	43 90	Contact: Bachel James 0207 973 3153



© Historic England

AND DESCRIPTION OF THE OWNER	
	DESI
	CON
	000
1	PRIO

Contact: Rachel James 0207 973 3153 Mid C19 boundary walls incorporating corner SITE NAME: Gunboat Yard Boundary Walls, watchtowers, walkways and gates. Mainly built of red brick Watchtowers and Gates, Haslar Gunboat Yard, Gosport laid in Flemish bond with stone dressings and pyramidal slate roofs to watch towers. At risk due to animal Listed Building grade II*, part in burrowing, defective roofs, eroding brickwork and IGNATION: CA pointing, missing windows and doors and vegetation growth. A project needs to be initiated to address these NDITION: Poor issues. N/A CUPANCY: DRITY CATEGORY: C (C) OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: Contact: Rachel James 0207 973 3153 1431191

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / GOSPORT

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



SITE NAME:	No 2 Battery, Stokes Bay Road, Gosport	Batteries No.1 and 2 were built in the Stokes Bay area of Gosport, primarily to defend against a sea-borne attack,
DESIGNATION:	Listed Building grade II*	and are located at the north-west end of the Stokes Bay Lines. They were part of a system of ramparts, moats and
CONDITION:	Poor	batteries built in the 1860s. It has extensive problems of damp penetration and condensation affecting the building
OCCUPANCY:	Part occupied/part in use	fabric. The building is partly in use as a museum and
PRIORITY CATEGORY:	C (C)	opportunities to secure funding for repairs are being explored by the Trustees.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1276305	Contact: Rachel James 0207 973 3153

© Historic England

© Historic England

2.39	SITE NAME:	Former Guard House, Haslar Gunboat Yard, Haslar	Former Guard House to Gunboat Yard constructed in mid-19th century. Mainly built of red brick with limestone
	DESIGNATION:	Listed Building grade II*, CA	dressings beneath hipped slate roof. Vacant and at risk due to poor condition of roofs, rainwater disposal, leaning
A	CONDITION:	Very bad	chimney stack, windows, doors, floors and internal finishes. Historic England grant aided a Conservation Management
	OCCUPANCY:	Vacant/not in use	Plan and Feasibility Study. New uses are being explored.
	PRIORITY CATEGORY:	C (C)	
-	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1431192	Contact: Rachel James 0207 973 3153

May 2021.

Former Police Barracks, Haslar Gunboat Yard, Haslar

Listed Building grade II*, CA

Vacant/not in use

Charity (non-heritage)

Gilkicker Fort, Fort Road,

Scheduled Monument and Listed

Poor

E (C)

Poor

1434287

Gilkicker Point

Building grade II*

Former Police Barracks constructed at the entrance to

rainwater disposal, windows, doors, floors and internal

Contact: Rachel James 0207 973 3153

finishes. Historic England provided grant aid towards the repair of the external envelope and work commenced in

Artillery fort 1865-71 with later additions. Barrack block,

and conversion to residential units approved but scheme

has not yet been implemented. Security fencing and monitoring has been erected to try and control levels of

casemates and fixtures subject to vandalism, and casemates

and magazines are threatened by water penetration. Repair

Haslar Gunboat Yard in the mid C19. Mainly built of red brick with limestone dressings beneath a hipped slate roof.

Vacant and at risk due to extensive badger burrowing and very poor condition of roof structure, roof coverings,



© Historic England



© Historic England Archive



	CONDITION:	Poor	heritage crime, and vegetation management is in place for
101	OCCUPANCY:	Vacant/not in use	the outer banks.
	PRIORITY CATEGORY:	D (D)	
1 × 1	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1001789 and 1276716	Contact: Iain Bright 0207 9733 739
AN AN	SITE NAME:	Fort Elson, RNAD, Military Road, Gosport	Polygonal artillery fort of 1853-60. Damaging vegetation has taken hold of the site. Programmes of vegetation
	DESIGNATION:	Scheduled Monument	removal are intermittent. A management plan has been drafted but not agreed or implemented. The building
575 H	CONDITION:	Poor	cannot be occupied because it lies within a munitions storage area.
	OCCUPANCY:	Vacant/not in use	stol age al ea.
	PRIORITY CATEGORY:	A (A)	
her and a	OWNER TYPE:	Government or agency	

© Historic England

D

Е

use)

LIST ENTRY NUMBER:

PRIORITY CATEGORIES А

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid
- В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

1001841

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Rachel James 0207 973 3153

ABBREVIATIONS

WHS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / GOSPORT / HART

SITE NAME:	Fortifications S of Trinity Church		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001849
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Motte and bailey castle near Apple Dumpling Bridg	e, south of Rowner	•
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008694
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Gunboat Traverser System, Haslar Gunboat Yard		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001810
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Louise Forsyth 020 7973 3220
SITE NAME:	High Steet, Gosport		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Rob Harper (LPA) 02392 545456
SITE NAME:	Priddy's Hard		
DESIGNATION:	Conservation Area, 25 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Rob Harper (LPA) 02392 545456
SITE NAME:	Stoke Road, Gosport		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating

HART



SITE NAME:

D

Е

Walls to early C17 and early C19 formal walled gardens. Garden walls and gateways Some sections of the walls are in a poor condition and in need of repair. Site was sold in 2014 to a development north of Bramshill House, Bramshill company and proposals for development within the site the subject of a 2018 but the pair of the garden e of the planning

© Historic England

DESIGNATION:	Listed Building grade I, RPG grade I	and the conversion of the mansion were public inquiry which finished in February 2
CONDITION:	Fair	future of the site is still uncertain. The rep walls will be sought as a positive outcome
OCCUPANCY:	Part occupied/part in use	process.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1340026	Contact: Louise Forsyth 020 7973 3220

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HART / HAVANT / NEW FOREST

	SITE NAME:	Bramshill Park, Bramshill / Eversley / Mattingley	Rare early C17 gardens and contemporary house within a park of medieval origin created using the topography and
	DESIGNATION:	Registered Park and Garden grade I, 8 LBs, part in SM, part in CA	habitat, whose parkland architecture remains intact despite mid-C18 and later extensions, informalisations and some fragmentation of the wider park. Previously in institutional use with numerous college buildings built in the
the state of the state of the	CONDITION:	Extensive significant problems	core the estate was sold in 2014 and faces major change through development. With other changes in the wider
	VULNERABILITY:	High	park the significance, fabric, character, and any collective
	TREND:	Declining	experience is vulnerable to fragmentation and loss of integrity.
D Historic England	NEW ENTRY ?:	No	5 /
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000165	Contact: Kay Richardson 0207 973 3647
	SITE NAME:	Warbrook House, Eversley	Seminal in garden history terms, the gardens and house
	SITE NAME: DESIGNATION:	Warbrook House, Eversley Registered Park and Garden grade II*, LB grade I	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical
		Registered Park and Garden	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider
	DESIGNATION:	Registered Park and Garden grade II*, LB grade I	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider parkland has fragmented and deteriorated, and conversion to a hotel and conference centre created major local
	DESIGNATION:	Registered Park and Garden grade II*, LB grade I Extensive significant problems	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider parkland has fragmented and deteriorated, and conversion to a hotel and conference centre created major local change. Further visioning, surveys and land management
	DESIGNATION: CONDITION: VULNERABILITY:	Registered Park and Garden grade II*, LB grade I Extensive significant problems Medium	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider parkland has fragmented and deteriorated, and conversion to a hotel and conference centre created major local
Historic England	DESIGNATION: CONDITION: VULNERABILITY: TREND:	Registered Park and Garden grade II*, LB grade I Extensive significant problems Medium Stable	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. James' geometrical axes extend beyond the gardens but these, and the wider parkland has fragmented and deteriorated, and conversion to a hotel and conference centre created major local change. Further visioning, surveys and land management options within Countryside Stewardship are being

HAVANT

	SITE NAME:	St Faith's Church, West Street, Havant	Cruciform medieval church; flint and stone walls, clay tile roof. Tower with parapet. Following plaster falls an
	DESIGNATION:	Listed Place of Worship grade II*, CA	investigation of the roofs recommended a complete overhaul. Temporary repairs were undertaken. Fundraising has led to the PCC being able to undertake internal works
	CONDITION:	Poor	but external repairs still required.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1092120	Contact: Robert Williams 0207 973 3641
Historic England			

©Н

SITE NAME:	Coastguards		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Rachael McMurray (LPA) 02382 446546

NEW FOREST



SITE NAME:	Church of St Winfred, Salisbury Road, Totton and Eling
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1094352

Large church completed 1937 and designed by NF Cachemaille-Day. Unusual galleried square nave with monumental concrete font and Father Willis organ. Built of brick with mainly pantiled roofs. At risk due to defects to the brickwork, rainwater disposal system, steel-framed leaded windows and internal plaster. The pantiled roofs were repaired with a grant from the National Lottery Heritage Fund under their Grants for Places of Worship scheme. It is hoped that the remaining repairs will be carried out by a new incoming church plant congregation supported by the Diocese.

Contact: Robert Williams 0207 973 3641

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / NEW FOREST / NEW FOREST (NP)

	SITE NAME:	Church of St Katherine, Exbury, Exbury and Lepe, New Forest	Church remodelled in 1907 by JO Scott and Son, with coursed squared Ventnor Greensand facings and tiled roof.
	DESIGNATION:	Listed Place of Worship grade II, CA	The church forms part of a joint benefice and is located in a hamlet constructed to serve the neighbouring Rothschild house and garden. The main problem is the decay and
	CONDITION:	Poor	delamination of stonework. The congregation completed some stonework repairs to the tower in 2014. Further
	PRIORITY CATEGORY:	C (C)	funding required to complete the outstanding repairs to the
	OWNER TYPE:	Religious organisation	stonework.
	LIST ENTRY NUMBER:	1094359	Contact: Robert Williams 0207 973 3641

© Historic England

SITE NAME:	Bowl barrow 330m north of Grim's Ditch	n, near Tidpit Common, Mar	tin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011000
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long Barrow 800m north west of Paradis	e, Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012512
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Duck's Nest: a long barrow on Rockbour	ne Down, Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012920
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow 700m north west of Tenant	ry Farm, Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013002
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Rockbourne Down, Spring Pond enclosur	re, Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003453
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
NEW FOREST (NP)			
SITE NAME:	Bell barrow and two bowl barrows 180 n New Forest	netres south west of Stagbur	y Hill, Furzley Common, Bramshaw

ITE NAME:			

	New Forest		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016491
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / NEW FOREST (NP) / RUSHMOOR

SITE NAME:Rabbit warren and four bowl barrows on Stagbury HIL, Furzley Comment, Bramshaw, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016490CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Rispersod / Sopley, New ForestI012637DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016490CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New ForestDESIGNATION:DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No							
CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:Declining	CONDITION:Generally satisfactory but with significant localised problemsImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Rimgwood / Sopley, New ForestDesignation:DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	SITE NAME:	Rabbit warren and four bowl barrows on Stagbury Hill, Furzley Common, Bramshaw, New Forest					
CONDITION: problems Improving PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY?: No OWNER TYPE: Charity (heritage) CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New Forest DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012637 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	CONDITION: problems Principal vulnerability: Visitor erosion - limited/localised NEW ENTRY?: No OWNER TYPE: Charity (heritage) CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New Forest DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012637 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016490			
OWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:CONDITION:Generally unsatisfactory with major localised problemsTREND:Declining	OWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Rimwood / Sopley, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	CONDITION:		TREND:	Improving			
SITE NAME: Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New Forest DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems	SITE NAME: Bowl barrow 550m north west of Avon Tyrrell, Ringwood / Sopley, New Forest DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012637 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012637 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012637 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646			
CONDITION: Generally unsatisfactory with major localised TREND: Declining problems	CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	SITE NAME:	Bowl barrow 550m north west of Avon Tyrrell, Rin	gwood / Sopley, N	lew Forest			
problems	PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012637			
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No		CONDITION:		TREND:	Declining			
	OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 973 3646	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No			
OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 973 3646		OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646			

RUSHMOOR

	SITE NAME:	Building Q121 [24 foot wind tunnel] at former Royal Aircraft Establishment site, Hall Road, Farnborough	Wind tunnel built 1934-35. The external fabric of the building is generally in good condition and actively maintained. Tours are given by arrangement and low-key use for art exhibitions has been permitted (in association
	DESIGNATION:	Listed Building grade I	with the Farnborough Air Show) However the future use of the building remains uncertain, which is the reason for
	CONDITION:	Fair	the at-risk status. Study exploring Farnborough's aviation heritage being commissioned from consultants.
	OCCUPANCY:	Vacant/not in use	heritage being commissioned iron consultants.
	PRIORITY CATEGORY:	E (E)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1259589	Contact: Robert Williams 0207 973 3641
	SITE NAME:	Building R133 [Transonic wind tunnel] at former Royal Aircraft Establishment site, O'Gorman Avenue, Farnborough	Wind tunnel built in 1939 and modified in 1956. Externally the building is generally in good condition and actively maintained but some staining of concrete walls due to corroding reinforcement. Tours are given by appointment, but the forward of the building provide the state.
A PRILITAL TANK	DESIGNATION:	Listed Building grade I	but the future use of the building remains uncertain. Study exploring Farnborough's aviation heritage being
	CONDITION:	Fair	commissioned from consultants.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1259586	Contact: Robert Williams 0207 973 3641
	SITE NAME:	Church of the Holy Trinity, Albert Road, Aldershot	The first church to be built in the new town, by Sidney Stapley 1875-78, in the Early English style of Bargate stone
	DESIGNATION:	Listed Place of Worship grade II	with Bath stone dressings and a slate roof. The ashlar stonework is showing signs of decay and repairs required
an an	CONDITION:	Poor	to the roof and west porch.
	PRIORITY CATEGORY:	F (F)	
		D (k)	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

OWNER TYPE:

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Religious organisation

1092621

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Robert Williams 0207 973 3641

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

SOUTH DOWNS (NP)

r farm

© Historic

c England	SITE NAME:	Ruins of St Nicholas Chapel, Westbury, East Meon, East Hampshire	Small ruined medieval church of possibly C13 or later. Designated with associated earthwork remains of contemporary settlement. Standing ruins are suffering from
	DESIGNATION:	Scheduled Monument and Listed Building grade II	structural cracking and deferred maintenance. A project to see the ruins conserved, explained and maintained needs to be agreed and put into action.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1001942 and 1179009	Contact: Robert Williams 0207 973 3641



© Historic England

	LIST ENTRY NUMBER:	1001942 and 1179009	Contact: Robert Williams 0207 973 3641
	SITE NAME:	Brambridge House, Kiln Lane, Colden Common, Winchester	Country house, 1762 and 1872, converted to flats in the 1950s. Suffering from deferred maintenance due to
	DESIGNATION:	Listed Building grade II*	uncertainty about areas of responsibility amongst leaseholders. Some repairs have been carried out, but
	CONDITION:	Poor	more are needed.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1350494	Contact: Robert Williams 0207 973 3641

SITE NAME:	Bowl barrow on Chalton Down, 350m south east	of Manor Farm, Cla	anfield, East Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020511
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 620m north east of Warhill Cottage,	East Meon, East H	ampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019116
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Group of four bowl barrows 660m north of Warh	ill Cottage, East Me	on, East Hampshire
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019115
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 60m south east of the junction of the cemetery, Froxfield and Privett, East Hampshire	e A32 and Fawley L	ane, part of The Jumps round barrov
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019120
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site
- 146

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

CONDITION: Ex PRINCIPAL VULNERABILITY: Ar OWNER TYPE: Pr SITE NAME: TH DESIGNATION: Sc CONDITION: GE	cheduled Monument ktensive significant problems rable ploughing rivate hree disc barrows on Longmoor Common, 250m	LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	1017051 Declining No Alison McQuaid 0207 973 3646
PRINCIPAL VULNERABILITY: Ar OWNER TYPE: Pr SITE NAME: Th DESIGNATION: Sc CONDITION: Ge	rable ploughing rivate	NEW ENTRY?:	No
OWNER TYPE: Pr	ivate		
SITE NAME: TH DESIGNATION: Sc CONDITION: Ge		CONTACT:	Alison McOuaid 0207 973 3646
DESIGNATION: Sc	nree disc barrows on Longmoor Common, 250m		
	-	north west of the (church, Whitehill, East Hampshire
	heduled Monument	LIST ENTRY NUMBER:	1016843
pr	enerally satisfactory but with significant localised roblems	TREND:	Improving
PRINCIPAL VULNERABILITY: Br	racken	NEW ENTRY?:	No
OWNER TYPE: Go	overnment or agency	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME: RC	ound barrow cemetery, Roman road and hollow w ast Hampshire	vays 200m south w	vest of Woolmer Cottages, Whitehil
DESIGNATION: Sc	heduled Monument	LIST ENTRY NUMBER:	1020502
	xtensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Sc	rub/tree growth	NEW ENTRY ?:	No
OWNER TYPE: Pr	ivate	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME: St	Catherine's Hill hillfort, Winchester		
DESIGNATION: Sc	heduled Monument	LIST ENTRY NUMBER:	1016489
	enerally satisfactory but with minor localised roblems	TREND:	Declining
PRINCIPAL VULNERABILITY: SC	rub/tree growth	NEW ENTRY?:	No
OWNER TYPE: Ed	ducational (independent)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME: BO	oundary earthwork and barrow at Sheepbridge, W	/arnford / West M	eon, Winchester
designation: Sc	heduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003562
	enerally unsatisfactory with major localised roblems	TREND:	Declining
PRINCIPAL VULNERABILITY: Va	andalism	NEW ENTRY?:	Yes
OWNER TYPE: Pr	rivate	CONTACT:	Alex Bellisario 0207 973 3700
SITE NAME: Ea	aston, Winchester (District), Winchester		
DESIGNATION: Co	onservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION: At	t risk	TREND:	Deteriorating
VULNERABILITY: Ur	nknown	CONTACT:	Michael Scammell (LPA) 01730 814810
	ambledon, Winchester (District), Winchester		
	onservation Area, 82 LBs	NEW ENTRY?:	No
	t risk	TREND:	No significant change
VULNERABILITY: Ur	nknown	CONTACT:	Michael Scammell (LPA) 01730 814810
SITE NAME: Itc	chen Stoke, Winchester (District), Winchester		
	chen Stoke, Winchester (District), Winchester onservation Area, 16 LBs	NEW ENTRY?:	No
DESIGNATION: Co		NEW ENTRY?: TREND:	No Deteriorating

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP) / TEST VALLEY

DESIGNATION: Conservation Area, 9 LBs NEW ENTRY?: No CONDITION: At risk TREND: Deteriorating VULNERABILITY: Unknown CONTACT: Michael Scammell (LP, 814810) SITE NAME: Twyford, Winchester (District), Winchester Viscontact: Viscontact:	
VULNERABILITY: Unknown CONTACT: Michael Scammell (LP, 814810	
814810	
SITE NAME: Twyford, Winchester (District), Winchester	A) 01730
DESIGNATION: Conservation Area, 50 LBs NEW ENTRY?: No	
CONDITION: At risk TREND: Deteriorating	
VULNERABILITY: Unknown CONTACT: Michael Scammell (LP, 814810	A) 01730
TEST VALLEY	
SITE NAME: Long barrow 400m south east of Moody's Down Farm, Barton Stacey	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012515	
CONDITION: Extensive significant problems TREND: Declining	
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	
OWNER TYPE: Government or agency CONTACT: Alison McQuaid 0207	973 3646
SITE NAME: The Andyke, Bransbury, Barton Stacey	
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1015678	
CONDITION: Generally unsatisfactory with major localised TREND: Declining	
problems	
•	1072 2/1/
	7/3 3040
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207	773 3040
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton	773 3040
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton Scheduled Monument LIST ENTRY NUMBER: 1012998	773 3040
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton Estensive significant problems Ist ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining	773 3040
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill Houses Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private Long barrow 300m south east of Middlebarn Farm, Cibloton List entry Number:	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill Houses Broughton DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Arable ploughing NEW ENTRY?: No OWNER TYPE: Extensive significant problems CONTACT: Alison McQuaid 0207 OWNER TYPE: Frivate Long barrow 300m south east of Middlebarn Farm, Chilbolton Scheduled Monument UST ENTRY NUMBER: 1012517	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton DesignAttion: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Arable ploughing New ENTRY?: No OWNER TYPE: Extonsive 300m south east of Middlebarn Farm, CHIBOLTON: Scheduled Monument LIST ENTRY NUMBER: SITE NAME: Long barrow 300m south east of Middlebarn Farm, CHIBOLTON: Scheduled Monument LIST ENTRY NUMBER: SITE NAME: Long barrow 300m south east of Middlebarn Farm, CHIBOLTON: Scheduled Monument UST ENTRY NUMBER: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining	
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House. Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Long barrow 300m south east of Middlebarn Farm. CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm. I012517 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 ODESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1012517 DESIGNATION: Scheduled Monument IST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems NEW ENTRY: No	7 973 3646
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill Houss. Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Exton barrow 300m south east of Middlebarn Farm. UIST ENTRY NUMBER: 1012517 SITE NAME: Long barrow 300m south east of Middlebarn Farm. 1012517 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining RISTE NAME: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	7 973 3646
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill Houss. Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm. No SITE NAME: Long barrow 300m south east of Middlebarn Farm. I012517 CONDITION: Extensive significant problems TREND: Declining SITE NAME: Long barrow 300m south east of Middlebarn Farm. I012517 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Castle ploughing NEW ENTRY?: Alison McQuaid 0207 SITE NAME: Castle Hill, Chilworth CONTACT: A	7 973 3646
Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton Designation: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm, Chilbolton No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Castle Hill, Chilworth Scheduled Monument UST ENTRY NUMBER: 1012517 STET NAME: Castle Hill, Chilworth Scheduled Monument No <td>7 973 3646</td>	7 973 3646
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY?: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill Houss. Broughton Designation: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Private CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm. No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm. No OWNER TYPE: Scheduled Monument UST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 SITE NAME: Castle Hill, Chilworth LST ENTRY NUMBER: 1012517 CONDITION: Scheduled Monument UST ENTRY?: No SITE NAME: Castle Hill, Chilworth Scheduled Monument UST ENTRY NUMBER: 1001885<	7 973 3646
PRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Alison McQuaid 0207SITE NAME:Long barrow and two bowl barrows, 400m north of Chattis Hill House, BroughtonDesignAntion:Scheduled MonumentLIST ENTRY NUMBER:1012998CONDITION:Extensive significant problemsTREND:DecliningCONTACT:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateContact:Alison McQuaid 0207SITE NAME:Long barrow 300m south east of Middlebarn Farm, ChilboltonNoDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012517DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012517CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:Castle Hill, ChilworthCONTACT:Alison McQuaid 0207SITE NAME:Castle Hill, ChilworthCONTACT:Alison McQuaid 0207SITE NAME:Scheduled MonumentLIST ENTRY NUMBER:1001885ConDITION:Scheduled MonumentLIST ENTRY NUMBER:1001885ConDITION: <td>7 973 3646</td>	7 973 3646
RRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton Estensive Structure Broughton DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Extensive significant problems TREND: Declining CONTACT: Arable ploughing NeW ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 STEE NAME: Long barrow 300m south east of Middlebarn Farm, Chilbolton UST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems REW ENTRY: No OWNER TYPE: Castle Hill, Chilworth </td <td>7 973 3646</td>	7 973 3646
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House, Broughton Estensive Significant problems ID12998 CONDITION: Scheduled Monument LIST ENTRY NUMBER: ID12998 CONDITION: Extensive significant problems REND: Declining OWNER TYPE: Arable ploughing NEW ENTRY: No OWNER TYPE: Long barrow 300m south east of Middlebarn Farm, Chilbolton Strenter MumBer: ID12517 SITE NAME: Long barrow 300m south east of Middlebarn Farm, Chilbolton Declining DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: ID12517 CONDITION: Extensive significant problems REND: Declining OWNER TYPE: Arable ploughing NEW ENTRY: No CONDITION: Extensive significant problems REND: Declining STEE NAME: Castel Hill, Chilworth Strentery: No DESIGNATION: Scheduled Monumen	7 973 3646
RRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRYI: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 STE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House. Broughton DesignATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1012998 Declining RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYI: No OWNER TYPE: Cong barrow 300m south east of Middlebarn Farm, Chilbolton Scheduled Monument LIST ENTRY NUMBER: 1012517 OSIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012517 CONDITION: Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRYI: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 SITE NAME: Castle Hill, Chilworth Scheduled Monument UST ENTRY NUMBER: 1001885 CONDITION: Scheduled Monument UST ENTRY NUMBER: 1001885 Declining	7 973 3646
PRINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No OWNER TYPE: Private, multiple owners CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow and two bowl barrows, 400m north of Chattis Hill House. Broughton DesignATION: Scheduled Monument LIST ENTRY NUMBER: 1012998 CONDITION: Scheduled Monument LIST ENTRY NUMBER: 1012998 Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 SITE NAME: Long barrow 300m south east of Middlebarn Farm. Chilbolton Scheduled Monument UIST ENTRY NUMBER: 1012517 CONDITION: Scheduled Monument UIST ENTRY NUMBER: 1012517 CONDITION: Scheduled Monument UIST ENTRY NUMBER: 1012517 CONTACT: Arable ploughing NEW ENTRY: No OWNER TYPE: Castle Hill, Chilworth Contract: Alison McQuaid 0207 SITE NAME: Castle Hill, Chilworth Scheduled Monument UIST ENTRY NUMBER: 1001885 CONDITION: <	7 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / TEST VALLEY / WINCHESTER

SITE NAME:	Barrow cemeter	y 730m north of Hampshire Gap,	Grateley / Quarley			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1014817		
CONDITION:	Extensive significant problems		TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple	owners	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Andover-Redbrid	dge canal, Chalk Hill Lock, Horseb	ridge, Kings Sombo	orne		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1001794		
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No		
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	The Moat, Longs	tock				
DESIGNATION:	Scheduled Monument, CA		LIST ENTRY NUMBER:	1001940		
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Improving		
PRINCIPAL VULNERABILITY:	Scrub/tree growth		NEW ENTRY?:	No		
OWNER TYPE:	Commercial corr	ipany	CONTACT:	Alison McQuaid 0207 973 3646		
	SITE NAME:	Embley Park, Wellow		20 woodland and shrub garden of late C		
	Registered Park and Garden		origin, once the home of Florence Nightingale. After W			



© Historic England

	Commercial comp	bany	CONTACT:	Alison McQuaid 0207 973 3646
-	SITE NAME:	Embley Park, Wellow		0 woodland and shrub garden of late CI
1. N. N.	DESIGNATION:	Registered Park and Garden grade II, 8 LBs	origin, once the home of Florence Nightingale. After the estate was divided, the house and historic core becoming a school. A Conservation Management Pla	ided, the house and historic core I. A Conservation Management Plan
100	CONDITION:	Extensive significant problems		although the historic character is tional developement. The wider open
	VULNERABILITY:	High	and wooded park has multiple owners and accumul development pressures. A Heritage Impact Assessn was commissioned by Test Valley in 2016 in respon local plan proposals. The need to widen understance significance and conservation to sustain value remain	has multiple owners and accumulative
	TREND:	Stable		
	NEW ENTRY?:	No		Ils. The need to widen understanding of
	OWNER TYPE:	Mixed, multiple owners	significance and co	sustain value remains.
	LIST ENTRY NUMBER:	1000215	Contact: Kay Rich	ardson 0207 973 3647

WINCHESTER

the states		1	
and the second		State State	
	diffe		in the second

SITE NAME:	Ruins of Merdon Castle, Hursley	Circular Late Bronze Age or Early Iron Age earthwork with remains of Norman tower structure and length of curtain
DESIGNATION:	Scheduled Monument	surviving as flint core work, all in need of structural repair and consolidation. A development phase, including
CONDITION:	Poor	vegetation clearance and investigations works has been undertaken with the benefit of a Countryside Stewardship
OCCUPANCY:	N/A	grant and assistance from Historic England, Implementation
PRIORITY CATEGORY:	C (C)	of repairs and long-term management subject to availability of funding.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1019123	Contact: Robert Williams 0207 973 3641

© Historic England



SITE NAME:	Church of the Holy Trinity, North Walls, Winchester	Designed by Henry Woodyer and built 1853-1855. It has a continuous seven-bay clerestoried nave with north and
DESIGNATION:	Listed Place of Worship grade II*, CA	south aisles and chancel and fleche with spire and lunettes. The walls are of flint with limestone blocks and limestone dressings. Vestry on south east and enclosed porch on the
CONDITION:	Poor	west door dating from 1894. There are slipped and missing slates, the roof leaks and the rainwater goods do not
PRIORITY CATEGORY:	C (C)	function effectively, putting the church at risk.
OWNER TYPE:	PE: Religious organisation	
LIST ENTRY NUMBER:	1350718	Contact: Robert Williams 0207 973 3641

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WINCHESTER

DECIGNATION:Scheduled MonumentUTI DUTY NUMBER:100 (81 /4CONDITION:Extensive significant problems1940s:DecliningCONDITION:AubornersCONTACT:Alison McQuaid 0207 973 3646XITENAMERoman villa and earlier prehistoric settlement 400WEST of Lone Furt.XITENAMEScheduled MonumentIN INNERTAND:DoceliningXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMENorsebury Ring hillfort, MicheldeverVENAME:NoXITENAMEScheduled MonumentIN INNERTAND:DecliningXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEScheduled MonumentIN INNERTAND:NoXITENAMEConstractionINTEND:DecliningXITENAMEScheduled MonumentINTEND:NoXITENAMEConstractionINTEND:DecliningXITENAMEScheduled MonumentINTEND:NoXITENAMEConstraction Anna, 14 LBs, part in RPG gradel IPNoXITENAMEConservation Area, 13 LBsINNERTIF:NoXITENAMEConservation Area, 33 LBsINNERTIF:NoXITENAMEMediumConstractionINTEND:DeterioratingXITENAMEConservation Area,	SITE NAME:	'Banjo type' native settlement, Itchen Valley		
NRINCINAL VALIABINALITY: Arable ploughing NAW ENTRY: No COMMENT TYPE Private, multiple owners COMMACT: Alison MLQuaid 0207 973 3646 STER MARKE Roman villa and earlier prehistoric settlement 400m west of Lone Farm, Itchen, Itchen Valley Declining DESCRATORN Scheduled Monument UT ENTRY NUMBER No CONTROM Extensive significant problems TENTRY NUMBER No CONTROM Able ploughing Now DETRY: No CONTROM Extensive significant problems UT ENTRY NUMBER No CONTROM Able, multiple owners CONTROM Now DETRY: No CONTROM Extensive significant problems UP ENTRY NUMBER 1020317 CONTROM Extensive significant problems UP ENTRY NUMBER 10210317 CONTROM Extensive significant problems UP ENTRY NUMBER 1021109 CONTROM Able ploughing No 1021109 CONTROM Extensive significant problems UP ENTRY: No CONTROM Extensive significant problems UP ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001814
OWNERT TITE Private, multiple owners CONTACT: Alison McQuaid 0207 973 3646 STRTANPIC Roman villa and earlier prehistoric settlement 400m west of Lone Farm, Itchen, Itchen Valley DESIGNATION Scheduled Monument UST ENTRYNAMERSK ID12693 CONDITON Extensive significant problems TRING Declining Marcel Arable ploughing Nov WATERY No STRTANPIC Norsebury Ring hillfort, Micheldever USI STRTANPIC Declining DESIGNATION Scheduled Monument ISIT STRTANPIC Docelining CONTROP: Arable ploughing Nov BOTTRY: No CONTROP: Private CONTROP: No CONTROP: Private CONTROP: No CONTROP: Private CONTROP: Alison McQuaid 0207 973 3646 Scheduled Monument ISIT STRTANPIC Alison McQuaid 0207 973 3646 CONTROP: Private CONTROP: No CONTROP: Private Scheduled Monument ISIT STRTANPIC CONTROP: Religious organisation TRDP: No </td <td>CONDITION:</td> <td>Extensive significant problems</td> <td>TREND:</td> <td>Declining</td>	CONDITION:	Extensive significant problems	TREND:	Declining
Non- Roman villa and earlier prehistoric settlement 400m west of Lone Farm, Itchen, Itchen Valley DERCARTION: Scheduled Monument Ist EVITER VALUES: IO12693 CONDITION: Extensive significant problems TRINC: Declining RINCERAL VULUERABUTE: Arable ploughing NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Allson McQuaid 0207 973 3646 Strenger Strenger Scheduled Monument UST DISTRY NAMERS: IO20317 DESCRIPTION: Scheduled Monument UST DISTRY NAMERS: IO20317 OWNERTYPE: Arable ploughing NEW ENTRY: No OWNERTYPE: Arable ploughing NEW ENTRY: No OWNERTYPE: Origitar problems TRNC: Olision McQuaid 0207 973 3646 STEMAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wonston Declining DESCRIPTION: Scheduled Monument UST MIXAUMERS: IO21109 OWNERTYPE: Religious organisation CoNTACT: Allson McQuaid 0207 973 3646 STEMAME: Compton Street No No DESCRATION: </td <td>PRINCIPAL VULNERABILITY:</td> <td>Arable ploughing</td> <td>NEW ENTRY?:</td> <td>No</td>	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DEDERNATION:Scheduled MonumentUIT ENTRY NUMBER:[012693]CONDURTOR:Extensive significant problemsTREND:DecliningRENCIDAL VOLUMERATURY:Arable ploughingNON CQuaid 0207 973 3646OWNER TYPEMixed, multiple ownersCONTRET:Alloon MCQuaid 0207 973 3646STENAME:Norsebury Ring hilffort, MicheldeverUIT ENTRY NUMBER:1020317CONDITION:Extensive significant problemsTREND:DecliningCONDITION:Extensive significant problemsTREND:NoCONDITION:Extensive significant problemsNEW ENTRY:NoCONDITION:Extensive significant problemsINTEND:DecliningRENCOMULTYPEPrivateCONTACT:Allson McQuaid 0207 973 3646STENAME:Long barrow and bowl barrow 440m north west of Sanctury Farm, WonstonDecliningDESIGNATION:Extensive significant problemsINTEND:DecliningPRINCIPAL UNLERABULY:Arable ploughingNew ENTRY:NoCONDITION:Extensive significant problemsINTEND:DecliningPRINCIPAL UNLERABULY:Arable ploughingNew ENTRY:NoCONDITION:Extensive significant problemsINTEND:DecliningPRINCIPAL UNLERABULY:Arable ploughingNew ENTRY:NoCONDITION:Extensive significant problemsINTEND:DecliningVILLENAME:Compton StreetUNLENAME:NoDESIGNATION:Conservation Area, 14 LBs, part in RPG grade II*New ENTRY:NoCONDITIO	OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
CONDITION:Extensive significant problemsTREND:DecliningTREND:Arable ploughingNEW BYIRTY:NoOWNERT THE:Mixed, multiple ownersCONTACT:Alison McQuaid 0207 973 3646STET NAME:Norsebury Ring hilfort, MicheldeverUSCATTY: NUMBER1020317DEGRATION:Scheduled MonumentINEND:DecliningCONTACT:Abile ploughingNEW INTXY:NoOWNER THE:Constractury Farry: NUMBERAlison McQuaid 0207 973 3646STET NAME:Constractury Farry: NUMBERNoOWNER THE:Constractury Farry: NUMBERAlison McQuaid 0207 973 3646STET NAME:Constractury Garry: NonDecliningSTET NAME:Composition FaresNon Non NonSTET NAME:Composition FaresNon Non NonSTET NAME:Composition Area, 14 LBs, part in RPG gradel 14NEW DITAC:VAN BRAMEITY:HeadiumStefendule AreaStefendule AreaVAN BRAMEITY:NoDeclerinatingVAN BRAMEITY:NoDeclerinatingVAN BRAMEITY:NoDeclerinatingVAN BRAMEITY:NoDeclerinatingVAN BRAMEITY:NoNoVAN BRAMEITY:NoNoVAN BR	SITE NAME:	Roman villa and earlier prehistoric settlement 400r	n west of Lone Far	m, Itchen, Itchen Valley
PRINCIPAL VLINERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Alison McQuaid 0207 973 3646 SILE NAME: Norsebury Ring hillfort, Micheldever ID20317 DERIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020317 CONTROT: Extensive significant problems TREND: Declining RIENCREL VLINERABULY: Arable ploughing New ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STEENME: Long barrow and bowl barrow 440m north west of Sanctuary Farm.Wom StoOn DERIGNATION: Scheduled Monument List ENTRY: No CONTROT: Extensive significant problems TREND: Declining RIENDEL VLINERABUTY: Arable ploughing New ENTRY: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STEENME: Compton Street Declining DERIGNATION: Conservation Area, 14 LBs, part in RPG grade II* No VULNERABUTY: Hedium CONTACT: Historic Environment Team (LPA) VULNERABUTY: Hedium CONTACT: Historic Environment Team (LPA) VULNERABUTY: No CONTACT: Historic Enviro	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012693
OWNER TYPE Mixed, multiple owners CONTACT: Alison McQuaid 0207 973 3646 STET NAME: Norsebury Ring hillfort, Micheldever 1020317 DEBIGNATION: Scheduled Monument USTENTAY NUMBER: 1020317 CONTROT: Extensive significant problems TREND: Declining RINCERLY VULNERVAUUTY: Arable ploughing NEW DETTYP: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STE NAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wortson Declining DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021109 CONTROT: Arable ploughing NEW DETTYP: No DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021109 CONTROT: Arable ploughing NEW DETTYP: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STE NAME: Conservation Area, 14 LBs, part in RPG grade IIP NEW ENTRY: No CONTROT: Generoation Area, 33 LBs NEW ENTRY: No CONTROT: Historic Environment Team (LPA) OBEGRATION: Conservation Area, 125 LBs, SM NEW ENTRY: No CONTROT: Historic Environment Team (LPA)	CONDITION:	Extensive significant problems	TREND:	Declining
Norsebury Righilifore, Micheldever DERGRAMMONI Scheduled Monument INTENTION Scheduled Monument INTENTION CONDITION Extensive significant problems TREND Declining RENORMAL VILLINERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STEL NAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Volmes: 1021 109 DESIGNAMTONE Scheduled Monument LISTE NTRY: NUMBER: 1021 109 CONTROM Extensive significant problems INEND: Declining DESIGNAMTONE Scheduled Monument USTE NTRY: NUMBER: 1021 109 CONTROM Extensive significant problems INEND: Declining CONTROM Extensive significant problems INEND: No CONTROM Religious organisation CONTACT: No CONTROM: Conservation Area, 14 LBS, part in RPG grade II* No Decenorating VULNEABULTY: Medium CONTACT: No Decenorating CONTACT: H	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1020317 CONDITION: Extensive significant problems ITRUND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 Stite NAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wonston Declining DEBIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021109 DEBIGNATION: Extensive significant problems TRND: Declining RINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No CONVERT TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STEE NAME: Compton Street Scheduled Nourient TEBIG No CONDITION: Conservation Area, 14 LBS, part in RPG grade II* NEW ENTRY: No VULNERABILITY: Medium Conservation Area, 33 LBS NEW ENTRY: No CONDITION: Fair No Itstoric Environment Team (LPA) VULNERABILITY: Medium Conservation Area, 125 LBS, SM NEW ENTRY: No CONDITION: At risk TRIND: Conservation Area, 125 LBS, SM Improving VULNERABILITY: Unknown Co	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
CONDITION Extensive significant problems TRND: Declining RRINCRAL VULNEAMENT: Arable ploughing NEW ENTRY: No RRINCRAL VULNEAMENT: Arable ploughing NEW ENTRY: No STRENAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Worston Just Entry: Alison McQuaid 0207 973 3646 STRENAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Worston Declining DEBIGNATION: Scheduled Monument LST ENTRY NUMBER 1021109 CONDITION: Extensive significant problems TREND: Declining CONDITION: Arable ploughing NEW ENTRY: No CONDITION: Arable ploughing NEW ENTRY: No CONDITION: Arable ploughing NEW ENTRY: No CONTROT Street Extensive significant Problems Contract: No CONDITION: Very bad TREND: Deteriorating VULNERABUTY: Medium Contract: No CONDITION: Conservation Area, 33 LBs NEW ENTRY: No CONTROT <	SITE NAME:	Norsebury Ring hillfort, Micheldever		
PRINCIPAL VULNERVABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STRE NAME: Long barrow and bowl barrow 440m north west of Sanctuary Farm, Wonston Descining DEBEGRAATION: Scheduled Monument UST ENTRY NUMBER: 1021 109 CONDITION: Extensive significant problems TREND: Declining CONDITION: Extensive significant problems TREND: No CONNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STRE NAME: Compton Street No Desteriorating DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NeW ENTRY: No CONTACT: Historic Environment Team (LPA) 01962 840222 STRE NAME: Hursley No Deteriorating UNINERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 NEW ENTRY: No No STRE NAME: Conservation Area, 33 LBs NEW ENTRY: No STRE NAME: Needium ConTACT: Historic Environment Team (LPA) 01962 840222 NEW ENTRY: No No STRE NAME: Needium ConTACT: Historic Environment	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020317
CONTRETTIPE: Private CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Long barrow and bowl barrow 440m north west of Sanctuary Farnusmese 1021109 Designa ATION: Scheduled Monument LIST ENTRY NUMBERE 1021109 DESIGNATION: Extensive significant problems TEND: Declining RRINCIPAL VULIENABILITY: Arable ploughing NeW ENTRY: No CONTACT: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Compton Street No No DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Very bad No Deteriorating WULIERABULTY: Medium ConTACT: Historic Environment Team (LPA) 01962 840222 NEW ENTRY: No No CONDITION: Fair No No CONDITION: New Alresford New ENTRY: No CONDITION: Artisk No No CONDITION: Artisk <td>CONDITION:</td> <td>Extensive significant problems</td> <td>TREND:</td> <td>Declining</td>	CONDITION:	Extensive significant problems	TREND:	Declining
STRE NAME Long barrow and book barrow 440m north west of Sanctuary Farm. Worston Designation: Scheduled Monument List ENTRY NUMBER: 1021109 CONDITION: Extensive significant problems TREND: Declining RIPIN CIVIL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STRE NAME: Compton Street VILNERABILITY: No DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No VULNERABILITY: Very bad TREND: Deteriorating VULNERABILITY: Weldium Conservation Area, 33 LBs NEW ENTRY: No VULNERABILITY: Fair No Deteriorating UPA VULNERABILITY: Medium Conservation Area, 31 LBs NEW ENTRY: No VULNERABILITY: Medium Conservation Area, 125 LBs, SM NEW ENTRY: No VULNERABILITY: New Altresford TREND: Improving 01962 840222 VULNERABILITY: Unknown	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1021109 CONDITION: Extensive significant problems TREND: Declining RRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY NUMBER: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STE NAME: Compton Street Constract: Alison McQuaid 0207 973 3646 DESIGNATION: Consport Street NEW ENTRY: No DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium Contract: Historic Environment Team (LPA) 01962 840222 STE NAME: Hursley Deteriorating No UNERABILITY: Medium Contract: No STE NAME: Conservation Area, 33 LBs NEW ENTRY: No VULNERABILITY: Medium Contract: Historic Environment Team (LPA) 01962 840222 STE NAME: New Alresford TREND: Deteriorating CONDITION: Conservation Area, 125 LBs, SM NEW ENTRY: No CONTACT: Instroit Environment Team (LPA) 01962 840222 Historic Environment Team (LPA) 01962 840222 STE	OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
CONDITION: Extensive significant problems TREND: Declining RRINCIPAL VOLUBERABILITY: Arable ploughing NEW ENTRY: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 STEE NAME: Compton Street CONTACT: Alison McQuaid 0207 973 3646 DEBIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No VULNERABILITY: Medium Contract: Historic Environment Team (LPA) 01962 840222 VILNERABILITY: Hursley Deteriorating VILNERABILITY: Medium No VILNERABILITY: Medium Contract: No VILNERABILITY: Medium No No VILNERABILITY: New Alresford Improving VILNERABILITY: Conservation Area, 125 LBs, SM New ENTRY: No VILNERABILITY: Kinkown Contract: Historic Environment Team (LPA) 01962 840222 VILNERABILITY: Kinkown New ENTRY:	SITE NAME:	Long barrow and bowl barrow 440m north west o	of Sanctuary Farm, V	Vonston
RRINCIPAL VULNERABILITY: Arable ploughing New ENTRY: No OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 OWNER TYPE: Compton Street	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021109
Notice programs CONTACT: Alison McQuaid 0207 973 3646 OWNER TYPE: Religious organisation CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Compton Street NEW ENTRY: No DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONTACT: Wery bad TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: Hursley Seconservation Area, 33 LBs NEW ENTRY: No CONDITION: Conservation Area, 33 LBs NEW ENTRY: No CONDITION: Fair TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: New Alreeford Seconservation Area, 125 LBs, SM New ENTRY: No CONDITION: At risk TREND: Improving VULNERABILITY: Unknown Contract: Historic Environment Team (LPA) 01962 840222 Southwick Southwick Southwick Southact: <t< td=""><td>CONDITION:</td><td>Extensive significant problems</td><td>TREND:</td><td>Declining</td></t<>	CONDITION:	Extensive significant problems	TREND:	Declining
SITE NAME: Compton Street DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY?: No contonition: Very bad TREND: Deteriorating WULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) O1962 840222 SITE NAME: Hursley USENGINATION: Conservation Area, 33 LBs NEW ENTRY?: No CONDITION: Fair New ENTRY?: No CONDITION: Fair New ENTRY?: No Deteriorating WULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) O1962 840222 SITE NAME: New Alresford SITE NAME: New SITE NE	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
DESIGNATION: Conservation Area, 14 LBs, part in RPG grade II* NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium contact: Historic Environment Team (LPA) 01962 840222 STE NAME: Hursley No DESIGNATION: Conservation Area, 33 LBs NEW ENTRY: No CONDITION: Fair TREND: Deteriorating VULNERABILITY: Medium contact: Historic Environment Team (LPA) 01962 840222 VULNERABILITY: Medium contact: Deteriorating VULNERABILITY: Medium contact: Historic Environment Team (LPA) 01962 840222 STE NAME: New Alresford Improving CONDITION: Conservation Area, 125 LBs, SM NEW ENTRY: No CONDITION: At risk TREND: Improving VULNERABILITY: Unknown contact: Historic Environment Team (LPA) 01962 840222 STE NAME: Southwick Improving No CONTACT: Unknown contact: Historic Environment Team (LPA) VULNERABILITY: Southwick No	OWNER TYPE:	Religious organisation	CONTACT:	Alison McQuaid 0207 973 3646
CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: Hursley DESIGNATION: Conservation Area, 33 LBs NEW ENTRY?: No CONDITION: Fair TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 STE NAME: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 STE NAME: New Alresford Improving DESIGNATION: Conservation Area, 125 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Improving VULNERABILITY: Unknown CONTACT: Historic Environment Team (LPA) 01962 840222 STE NAME: Southwick Improving VULNERABILITY: Unknown CONTACT: No STE NAME: Southwick Improving VULNERABILITY: VINNEWER No	SITE NAME:	Compton Street		
VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: Hursley DESIGNATION: Conservation Area, 33 LBs NEW ENTRY: No CONDITION: Fair TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: New Alresford Improving SITE NAME: New Alresford Improving CONTACT: Historic Environment Team (LPA) 01962 840222 Improving VULNERABILITY: No Improving VULNERABILITY: Conservation Area, 125 LBs, SM NEW ENTRY: No CONDITION: At risk TREND: Improving VULNERABILITY: Unknown Contact: Historic Environment Team (LPA) 01962 840222 SITE NAME: Southwick Improving Improving SULNERABILITY: Unknown Conservation Area, 48 LBs, SM New ENTRY: No CONDITION: At risk TREND: Deteriorating VILNERABILITY: Unknown Conservation Area, 48 LBs, SM NEW ENTRY: No	DESIGNATION:	Conservation Area, 14 LBs, part in RPG grade II*	NEW ENTRY ?:	No
New Both Both International Conservation Area, 33 LBs New ENTRY: No DESIGNATION: Conservation Area, 33 LBs NEW ENTRY: No condition: Fair TREND: Deteriorating vulnerability: Medium Contact: Historic Environment Team (LPA) 01962 840222 stree NAME: New Alresford Contact: Historic Environment Team (LPA) 01962 840222 stree NAME: New Alresford New ENTRY: No condition: Conservation Area, 125 LBs, SM NEW ENTRY: No condition: At risk TREND: Improving vulnerability: Unknown contact: Historic Environment Team (LPA) 01962 840222 stre NAME: Southwick Improving No contact: Historic Environment Team (LPA) 01962 840222 New ENTRY: vulnerability: Unknown contact: Historic Environment Team (LPA) 01962 840222 stre NAME: Southwick Southwick Southwick contact: Trend: No No condition: At risk NEW ENTRY: No condition: At risk TREND: Deteriorating	CONDITION:	Very bad	TREND:	Deteriorating
DESIGNATION: Conservation Area, 33 LBs NEW ENTRY?: No CONDITION: Fair TREND: Deteriorating vulueRABILITY: Medium contact: Historic Environment Team (LPA) 01962 840222 SITE NAME: New Alresford stresseccccccccccccccccccccccccccccccccc	VULNERABILITY:	Medium	CONTACT:	
CONDITION: Fair TREND: Deteriorating VULNERABILITY: Medium CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: New Alresford VULNERABILITY: No DESIGNATION: Conservation Area, 125 LBs, SM NEW ENTRY: No CONDITION: At risk TREND: Improving VULNERABILITY: Unknown Conservation Area, 48 LBs, SM VULNERABILITY: DESIGNATION: Conservation Area, 48 LBs, SM New ENTRY: No CONDITION: At risk NEW ENTRY: No SULINERABILITY: Conservation Area, 48 LBs, SM NEW ENTRY: No CONDITION: At risk TREND: Deteriorating	SITE NAME:	Hursley		
vulnerability: Medium contact: Historic Environment Team (LPA) 01962 840222 stre name: New Alresford stress Designation: Conservation Area, 125 LBs, SM NEW ENTRY: No condition: At risk TREND: Improving vulnerability: Unknown contact: Historic Environment Team (LPA) 01962 840222 stre name: Southwick contact: Historic Environment Team (LPA) 01962 840222 stre name: Southwick contact: Historic Environment Team (LPA) 01962 840222 stre name: Southwick vulnerability: No unknown contact: Historic Environment Team (LPA) 01962 840222 unknown contact: Historic Environment Team (LPA) unknown contact: Historic Environment Team (LPA) unknown contact: Historic Environment Team (LPA)	DESIGNATION:	Conservation Area, 33 LBs	NEW ENTRY?:	No
New Alresford New Alresford DESIGNATION: Conservation Area, 125 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Improving vulnerability: Unknown contact: Historic Environment Team (LPA) 01962 840222 Sitte NAME: Southwick render render LDESIGNATION: Conservation Area, 48 LBs, SM NEW ENTRY?: No	CONDITION:	Fair	TREND:	Deteriorating
Designation: Conservation Area, 125 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Improving vulnerability: Unknown contact: Historic Environment Team (LPA) 01962 840222 stre NAME: Southwick New ENTRY?: No condition: Conservation Area, 48 LBs, SM New ENTRY?: No condition: At risk TREND: Deteriorating condition: Historic Environment Team (LPA) TREND: Deteriorating	VULNERABILITY:	Medium	CONTACT:	
CONDITION: At risk TREND: Improving VULNERABILITY: Unknown CONTACT: Historic Environment Team (LPA) 01962 840222 STEE NAME: Southwick VULNERABILITY: No DESIGNATION: Conservation Area, 48 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Deteriorating	SITE NAME:	New Alresford		
VULNERABILITY: Unknown CONTACT: Historic Environment Team (LPA) 01962 840222 SITE NAME: Southwick DESIGNATION: Conservation Area, 48 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Deteriorating VULNERABILITY: Unknown CONTACT: Historic Environment Team (LPA)	DESIGNATION:	Conservation Area, 125 LBs, SM	NEW ENTRY?:	No
Southwick Oligical and a strength of the strengt	CONDITION:	At risk	TREND:	Improving
DESIGNATION: Conservation Area, 48 LBs, SM NEW ENTRY?: No CONDITION: At risk TREND: Deteriorating VILINERABILITY: Linknown CONTACT: Historic Environment Team (LPA)	VULNERABILITY:	Unknown	CONTACT:	
CONDITION: At risk TREND: Deteriorating VILUNERABILITY: Lipkpowrp CONTACT: Historic Environment Team (LPA)	SITE NAME:	Southwick		
VILINERABILITY: Historic Environment Team (LPA)	DESIGNATION:	Conservation Area, 48 LBs, SM	NEW ENTRY?:	No
	CONDITION:	At risk	TREND:	Deteriorating
	VULNERABILITY:	Unknown	CONTACT:	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WINCHESTER / PORTSMOUTH, CITY OF (UA) / ISLE OF WIGHT (UA)

SITE NAME:	Sparsholt		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Sutton Scotney		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wickham		
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY ?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wonston		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222

PORTSMOUTH, CITY OF (UA) / WINCHESTER

	SITE NAME:	Fort Southwick, Portsdown Hill, Portsmouth, Southwick and Widley	1860s fort, part of the Palmerston Portsmouth defences. Parts of the monument are in poor condition. Following disposal by Defence Estates, the site is now operated by an
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I, SM	estate management company as a business park with a number of different companies operating from the site. The new owners have carried out some repairs but more are
De interes	CONDITION:	Fair	needed, together with a carefully planned maintenance regime.
	OCCUPANCY:	Part occupied/part in use	regime.
(mmm)	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1001808 and 1104368; 1167213	Contact: Rachel James 0207 973 3153

ISLE OF WIGHT (UA)

×		
	AMERICA	•
		1

© Historic England

	SITE NAME:	Hammerhead Crane, Thetis Road, West Cowes, Cowes	Giant cantilever crane, also called 'hammerhead' crane, built 1911. One of a handful of this type of crane now
	DESIGNATION:	Listed Building grade II*	surviving in the world, and witness to a major local industry. Disused and surrounded by a potential
	CONDITION:	non: Poor	development site. Historic England has been assisting the Local Authority with grant aid and technical advice.
	OCCUPANCY:	Vacant/not in use	Essential holding repairs to the legs and upper structure
	PRIORITY CATEGORY:	A (A)	have been undertaken under the auspices of an Urgent Works Notices. Historic England has grant-aided a
	OWNER TYPE:	Private	feasibility study and will be working with all stakeholders the site to secure the full repair of the crane.
L	LIST ENTRY NUMBER:	1390949	Contact: Robert Williams 0207 973 3641

NDITION:	Poor
CCUPANCY:	Vacant/not in use
IORITY CATEGORY:	A (A)
WNER TYPE:	Private
T ENTRY NUMBER:	1390949

g the ure ent ders on

Contact: Robert Williams 020/ 9/3 3641

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site



	(-)	
SITE NAME:	Northwood House, Ward Avenue, Cowes	Large house, 1837, with spectacular interiors. The long- term future of this partly used building is unresolved and
DESIGNATION:	Listed Building grade II*, CA	maintenance needs to be addressed in the short term. Some progress has been made and areas of the building
CONDITION:		have been brought back into use, but the comprehensive repair of the external envelope is still required. The
OCCUPANCY:	Part occupied/part in use	Trustees of Northwood House have been urged to
PRIORITY CATEGORY:	C (C)	appoint a conservation architect, compile a full package of repairs and improvements and to engage with the Nationa
OWNER TYPE:	Charity (heritage)	Lottery Heritage Fund. The cost of full repair is very high.
LIST ENTRY NUMBER:	1223779	Contact: Robert Williams 0207 973 3641


© Historic England Archive

© Historic England



SITE NAME:	Norris Castle Farm, the Bailiff's House, Two Cottages and Kitchen Garden Wall, Newbarn Road, East Cowes	Model Farm designed by James Wyatt around 1800. It includes farm buildings, Bailiff's house, cottages, walled garden and glass houses all contained within a rectangular plan surrounded by high castellated walls with corner
DESIGNATION:	Listed Building grade I, RPG grade I	towers. The walls are mainly built of rubble stonework with Welsh slate roofs to the buildings. At risk due to lack of long-term maintenance, leaking roofs and defective
CONDITION:	Very bad	rainwater disposal. Proposals for repair and sustainable re- use are awaited from the owner. Some emergency repairs
OCCUPANCY:	Vacant/not in use	carried out.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1223182	Contact: Robert Williams 0207 973 3641
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	HouseHouse, Two Cottages and Kitchen Garden Wall, Newbarn Road, East CowesDESIGNATION:Listed Building grade I, RPG grade ICONDITION:Very badOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Commercial company





© Isle of Wight Council



D

Е

LIST ENTRY NUMBER:

some structures and walling as part of a wider project. Building grade II*, LB grade II Further repairs are necessary to remove the remains from the Heritage at Risk Register. Historic England grant-aided an update of the condition survey, hydrological survey and temporary propping of the leaning east precinct wall which was in danger of collapse. Contact: Robert Williams 0207 973 3641 1012714 and 1234997

Cistercian foundation of 1131. The upstanding remains are

in an advanced state of decline due to longstanding lack of regular maintenance and vegetation growth. The National

Lottery Heritage Fund grant aided repairs to the barn,

Royal Commission coastal battery completed in 1864 with SITE NAME: Yaverland Battery, Sandown, later alterations. Mainly built of red brick with stone Sandown dressings. At risk due to vegetation growth and partial DESIGNATION: Scheduled Monument collapse of carnot wall. A plan for the long-term conservation of the monument needs to be developed with CONDITION: Poor the owner. N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1021443 Contact: Robert Williams 0207 973 3641 © Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ΪA

Unitary Authority World Heritage Site WHS

SITE NAME:	Bouldnor Battery, Shalfleet	Battery built in 1938 situated on the west coast of the Isle
DESIGNATION:	Scheduled Monument	of Wight to help protect the Solent. Buried components no longer accessible but survive. Mainly constructed from
CONDITION:	Very bad	reinforced concrete which is now spalling and decaying due to corrosion of the metal reinforcement. Historic England
OCCUPANCY:	Vacant/not in use	has grant-aided temporary propping and waterproofing of
PRIORITY CATEGORY:	C (C)	the roofs. An Options Appraisal, also grant-aided by Historic England, was completed in early 2020 and options
OWNER TYPE:	Government or agency	for the repair and possible re-use of the monument are being explored.
LIST ENTRY NUMBER:	1010011	Contact: Robert Williams 0207 973 3641
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:Scheduled MonumentCONDITION:Very badOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:C (C)OWNER TYPE:Government or agency

© Forestry Commission

-	SITE NAME:	Church of St Mary, Church Road, Cowes	Large church adjacent to Northwood Park. The west tower was designed by John Nash in 1816 and the rest of
	DESIGNATION:	Listed Place of Worship grade II*, CA	the church was rebuilt in 1867. Built of stone with colour banded slate roof. Historic England/National Lottery Heritage Fund grant-aided repairs to tower and north roof
ANTOTAN	CONDITION:	Poor	slopes but further repairs needed including to the south nave and aisle roofs, rainwater disposal, and addressing
	PRIORITY CATEGORY:	C (C)	structural movement to south west corner, which is
	OWNER TYPE:	Religious organisation	currently being monitored.
and	LIST ENTRY NUMBER:	1222748	Contact: Robert Williams 0207 973 3641

© Historic England

610-1	SITE NAME:	Church of St James, East Cowes	A C19 church by local Isle of Wight architect T Hellyer.
asta	DESIGNATION:	Listed Place of Worship grade II	Constructed in Romanesque style of stone rubble with slated roof. Incorporates tower of earlier 1830s church by
Real Property in	CONDITION:	Poor Johi	John Nash. Nash is buried in the church yard. Repairs, including to the rainwater goods and south transept rose window, have been completed but further works are
	PRIORITY CATEGORY:	C (C)	
A	OWNER TYPE:	Religious organisation	required to address the structural problems to the north vestry.
	LIST ENTRY NUMBER:	1222746	Contact: Robert Williams 0207 973 3641
City of the second s			

© Historic England

	SITE NAME:	Church of All Saints, Church Hill, Godshill	Mainly dating from the C14 with an unusual plan of double nave and arcade continuous to chancel. Early C16 south
-	DESIGNATION:	Listed Place of Worship grade I, CA	transept with crucifixion wall painting of similar date. Historic England/National Lottery Heritage Fund grant- aided repairs to rainwater goods, drainage and south west
	CONDITION:	Poor	corner, including west window to south nave, have been successfully completed. Further repairs required to the
	PRIORITY CATEGORY:	C (C)	stonework.
- 45 M	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1209229	Contact: Robert Williams 0207 973 3641

© Historic England



	SITE NAME:	Church of St Thomas, St Thomas's Square, Newport and Carisbrooke	Large church standing in central square. It was rebuilt on the site of an earlier church in 1854-6 by the architect SW Dawkes. The walls are mainly constructed of local and re-
	DESIGNATION:	Listed Place of Worship grade I, CA	used stone rubble with Caen stone dressings and Welsh slate roofs. Previous Historic England/National Lottery Heritage Fund grant-aided repairs to the stonework,
	CONDITION:	Poor	windows and roofs to the lady chapel, north aisle, upper tower stonework, chancel, vestry and south chapel.
le la	PRIORITY CATEGORY:	C (C)	However further repairs are necessary before the church
	OWNER TYPE:	Religious organisation	can be removed from the Heritage at Risk Register, including to the north aisle and tower.
	LIST ENTRY NUMBER:	1034494	Contact: Robert Williams 0207 973 3641

© Historic England

PR	NORITY CATEGORIES
Δ	Immodiato risk of further rapid

D

Е

- А Imme deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	St Mary's Roman Catholic Church, High Street, Ryde	Town centre church on compact site designed by Joseph Hansom in the Gothic style. It was mainly built 1846-8 of
	DESIGNATION:	Listed Place of Worship grade II, CA	rubble limestone with unusual angular pantile roofs. Listed Places of Worship Roof Repair Fund grant aided repairs to the roofs completed but funding required to make good
	CONDITION:	Poor	water damage to internal decorative scheme and finish
-	PRIORITY CATEGORY:	C (C)	
I ALM	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1216915	Contact: Robert Williams 0207 973 3641
gland			

© Historic Engla



© Historic England

	SITE NAME:	Church of St Saviour's on the Cliff, Queen's Road, Shanklin	Victorian church by Thomas Hellyer in the Early English style. Built of soft local limestone with tiled roof. The
	DESIGNATION:	Listed Place of Worship grade II	principal problem is the condition of the stonework which is badly spalled all over. The church is in a coastal location.
AND DECEMBER	CONDITION:	Poor	The windows at the west end are very fragile and are protected with Perspex to prevent them from being blown
A Manager	PRIORITY CATEGORY:	C (C)	out. Some repairs have been carried out, but more are
I III	OWNER TYPE:	Religious organisation	required. In February 2021 the hall roof suffered storm damage.
inntno A	LIST ENTRY NUMBER:	1212831	Contact: Robert Williams 0207 973 3641

© Historic England

	SITE NAME:	Church of St Paul's, Regent Street, Shanklin	Town centre church designed by CL Luck 1875-90, with west porch added 1911. Built of local Greensand stone
	DESIGNATION:	Listed Place of Worship grade II	with tiled roofs and slender tower with timber framed top storey and shingled roof. At risk due to timber decay to
	CONDITION:	Very bad	top of tower, decaying stonework, bulging window glazing, and slipped and missing shingles. Phase One repairs to the
	PRIORITY CATEGORY:	C (C)	main roofs, rainwater goods and high level stonework were
	OWNER TYPE:	Religious organisation	successfully completed in 2016 with the help of a grant from Historic England/National Lottery Heritage Fund.
	LIST ENTRY NUMBER:	1212881	Further phases of repair are now required.
			Contact: Robert Williams 0207 973 3641

© Historic England



SITE NAME:	Holy Trinity Church, Trinity Road, Ventnor	Victorian church in the Early English style by the architect CE Giles. Nave, aisles and chancel with slender tower and
DESIGNATION:	Listed Place of Worship grade II*, CA	spire at the south east corner. Built of soft local stone with concrete tiles on the roof. The main problem is the soft stone work which continues to decay. Some repairs have
CONDITION:	Poor	been carried out to the tower.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1343326	Contact: Robert Williams 0207 973 3641

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Medieval settlem and Ashey	ent 100m south east and 350m n	orth east of East As	hey Manor Farm, Brading / Havenstreet
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1015622
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barro	ws 180m WNW of Puck House,	Fishbourne	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1012715
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
P Historic England	SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: TREND: NEW ENTRY?: OWNER TYPE: LIST ENTRY NUMBER:	Swainston, "CalbourneRegistered Park and Garden grade II, 3 LBsGenerally unsatisfactory with major localised problemsHighDecliningNoMixed, multiple owners1000930	intersecting aven earlier fishponds Remnant garden woodland compa converted to ara historic character occured. The sou temple, is separa approach to furth recommended as	oodland garden, set in parkland, with ues and water features incorporating from a Bishopric manor, now a hotel, features lie in several ownerships and artments. Where parkland has been ble land or and light industrial use loss of r and designed landscape intentions has ithern portion of the estate, including a ted from the core by a road. A joint her action research has been s part of a parkland plan process in 2020 hardson 0207 973 3647
Historic England	SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: TREND: NEW ENTRY?: OWNER TYPE:	Norris Castle, East Cowes Registered Park and Garden grade I, 12 LBs, part in RPG grade II*, part in CA Generally unsatisfactory with major localised problems High Declining No Commercial company	Norris is an exemplar marine villa with castellated mode farm/walled garden from 1799 by James Wyatt for Lord Seymour as part of the early villa development on this coast. A single phase, intimate designed landscape that appropriates the topography and commanding views, it historical completeness of its parkland architecture surv mostly intact. Benign decay allowed the parkland featur to survive relative to historic structure and design intent whilst their condition slowly declined due to lack of management. Sold in 2015 and with major development proposals its future is uncertain.	
	LIST ENTRY NUMBER:	1000927	Contact: Kay Ric	hardson 0207 973 3647

SITE NAME:	Brading		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Oliver Boulter (LPA) 01983 823552
SITE NAME:	Carisbrooke, Newport		
SITE NAME: DESIGNATION:	Carisbrooke, Newport Conservation Area, 37 LBs, 3 SMs	NEW ENTRY?:	No
	· •	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 37 LBs, 3 SMs		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Cowes		
DESIGNATION:	Conservation Area, 73 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Oliver Boulter (LPA) 01983 823552
SITE NAME:	Godshill		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Oliver Boulter (LPA) 01983 823552
SITE NAME:	Newport		
DESIGNATION:	Conservation Area, 194 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (01983) 823552
SITE NAME:	Ryde		
DESIGNATION:	Conservation Area, 310 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (01983) 823552
SITE NAME:	Sandown		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating

KENT

ASHFORD

SITE NAME: Palace Farmhouse, Market The present farmhouse forms part of the north range of Place, Charing the former manor house of the Archbishops of Canterbury and includes part of the former chapel. The top floor is DESIGNATION: Listed Building grade I, SM, CA inaccessible and unoccupied. An options appraisal for the whole site has been carried out by Ashford Borough CONDITION: Poor Council with funding from Historic England. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) litt OWNER TYPE: Private 0207 072 2420 1070754 id lobr

© Historic England



© Historic England

	LIST ENTRY NUMBER:	1070756	Contact: David John 0207 973 3638
	SITE NAME:	Remains of Archbishops Palace, Market Place, Charing	Remains of palace built in C13 and C14. Farm complex converted from remains includes barn (east range of palace
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I; I grade II, 2 LBs, CA	courtyard) and outhouse (west range). The outhouse requires substantial maintenance repairs. Grant aided emergency works to north end of the barn have been carried out. An options appraisal for the whole site has
	CONDITION:	Very bad	been carried out by Ashford Borough Council with funding from Historic England. A further stage of repairs is being
	OCCUPANCY:	Part occupied/part in use	considered.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1011028 and 1185861; 1186008; 1362627	Contact: David John 0207 973 3638

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / ASHFORD / CANTERBURY



© Historic England

	SITE NAME:	Ruins of Church of St Mary, Pluckley Road, Little Chart	Possibly C13 church with tower built around 1500. Damaged during WWII by a VI flying bomb. Now ruinous
CONDITION OCCUPAI PRIORITY OWNER 1	DESIGNATION:	Scheduled Monument and Listed Building grade II	but with tower still standing to c.15m. High level stonework requires inspection, and the considerable growth of ivy and other vegetation needs controlling. The
	CONDITION:	Poor	grounds are well maintained and the site is open to the public. Vegetation clearance has been discussed with the
	OCCUPANCY:	N/A	owners.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1004208 and 1329709	Contact: David John 0207 973 3638

SITE NAME: Late medieval threshing barn, A late medieval barn that has for some time been suffering from water ingress and structural movement. All its roof Mersham Manor, Church Road, tiles have been removed without Listed Building Consent Mersham and replaced with protective sheeting. Historic England is DESIGNATION: Listed Building grade II* working with the Local Planning Authority and owners to secure the barn's long-term future. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company © Historic England LIST ENTRY NUMBER: 1233497 Contact: Alice Brockway 0207 973 3655

SITE NAME:	Castle Toll Saxon burgh and medieval fort, Newenden		
DESIGNATION:	Scheduled Monument	1013041	
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

CANTERBURY



© Historic England

Medieval ruinous structures of Christchurch Priory, which SITE NAME: Monuments in the precinct of have suffered from years of decline. Major backlog of Canterbury Cathedral, The repairs; work has started with Historic England grant to Precinct, Canterbury Llanfrancs dormitory and the city wall. Slow progress is Scheduled Monument and Listed being made. Detailed evaluation of the various assets is Buildings - 2 grade I; 1 grade II*, 22 LBs, CA, WHS DESIGNATION: being carried out in order to decide priorities. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: B (B)



SITE NAME:	Greyfriars Monastery, Stour Street, Canterbury	Boundary walls from Tudor house built on site of the and one part of the friary church. Friary built in 1267.
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs, CA	risk from deterioration and development pressures.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Other not for profit group	
LIST ENTRY NUMBER:	1005195 and 1242684	Contact: David John 0207 973 3638

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

D

Е

use)

OWNER TYPE:

LIST ENTRY NUMBER:

Religious organisation 1004195 and 1253715;

1085082; 1085079

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: David John 0207 973 3638

ABBREVIATIONS

Conservation Area Listed Building CA

- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CANTERBURY



© Historic England

SITE NAME:	Dovecote at Burnt House Farm, Chartham	Cleverly designed dovecote of three storeys built into a slope and dated to C18. Original design saw pigs kept on
DESIGNATION:	Scheduled Monument, LB grade II, CA	ground floor providing heating for poultry on middle floor and doves on third floor. In need of repair. New owner plans to undertake repairs as part of proposals for future
CONDITION:	Poor	low key use. Repairs carried out to the roof and doors. Further repairs required to the flooring and other features.
OCCUPANCY:	Vacant/not in use	runner repairs required to the hooring and other reatures.
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1018874	Contact: David John 0207 973 3638

SITE NAME: Horton Manor Chapel, Horton, Two cell C14 chapel, now roofless. Planning Permission and Scheduled Monument Consent for the conversion of Chartham the oast houses to residential use have been granted and Scheduled Monument and Listed the works completed. A proposal to also convert the DESIGNATION: Building grade II chapel is being developed. CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: F (F) OWNER TYPE: Private © Historic England LIST ENTRY NUMBER: 1005150 and 1085714 Contact: Paul Roberts 0207 973 3636



X	SITE NAME:	Barn at Hardres Court, Upper Hardres	Late CI5 to early CI6 aisled timber barn. Damaged by fi 1993. It would suit a variety of different forms of re-use
1	DESIGNATION:	ESIGNATION: Listed Building grade II*, CA exposed its impressive structural	which retain its characteristic open volume and leave exposed its impressive structural timbers.
	CONDITION:		
oco	OCCUPANCY:	Vacant/not in use	
1.0	PRIORITY CATEGORY:	C (C)	
OWN	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1085505	Contact: Alice Brockway 0207 973 3655

© Historic England Archive



SITE NAME:	Church of St Bartholomew, King Edward Avenue, Herne Bay	Early C20 church in Gothic style built to serve expandi population. Substantial church with yellow brick and terracotta detailing. Has some defective tiling especial
DESIGNATION:	Listed Place of Worship grade II	the south aisle roof and generally poor condition of guttering and downpipes around the building. There is
CONDITION:	Poor	evidence of water ingress with blown plaster to south aisle at high level and within the chancel at the north east
PRIORITY CATEGORY:	C (C)	corner. Deterioration of external brick work particularly on
OWNER TYPE:	Religious organisation	north side. South porch showing further signs of water ingress.
LIST ENTRY NUMBER: 1084977 Contact: Day	Contact: David John 0207 973 3638	

© Historic England



	SITE NAME:	Church of St Mary the Virgin, Church Lane, Chislet	Church with Norman nave and tower and later CI3 chancel and aisles. Cement render on both north and
	DESIGNATION:	Listed Place of Worship grade I, CA	south sides is defective and coming away. Coursed rubble walls contain loose material particularly on south side and deterioration of quoins to south side of tower. Substantial
	CONDITION:	Poor	ivy coverage to east end. Hoppers need unblocking and some guttering on north side is failing. The building has
	PRIORITY CATEGORY:	C (C)	been the victim of heritage crime.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1085653	Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious powy user (coplicable only obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CANTERBURY / DARTFORD

© Historic England	LIST ENTRY NUMBER:	1084972	Contact: David John 0207 973 3638
	OWNER TYPE:	Religious organisation	with further funding.
	PRIORITY CATEGORY:	C (C)	completed. A third phase has recently been completed
	CONDITION:	Very bad	phases of repairs, funded by the National Lottery Heritage Fund Grants for Places of Worship, have now been
	DESIGNATION:	Listed Place of Worship grade I, CA	level damp throughout. Roof tiles have slipped and rainwater goods are blocked and leaking. The building has been the victim of heritage crime. The first and second
FIII	SITE NAME:	Church of St Martin, Herne Street, Herne, Herne and Broomfield	A large church, predominantly of the C14, but with substantial C19 restoration. The church is suffering from severely deteriorating stonework at the west end and low

SITE NAME:	Enclosures west of Woodlands, Adisham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1004191
CONDITION: Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Rubury Butts bowl barrows, Nonington / Wome	enswold	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1427315
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	ER TYPE: Private CONTACT:		Maria Buczak 0207 973 3642
DARTFORD			
SITE NAME:	Palaeolithic sites near Baker's Hole		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003557
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman enclosure south east of Vagniacae, South	fleet	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004226
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Springhead Roman site, Southfleet		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005140
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

- C Slow decay; no solution agreed.

 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay: no solution agreed. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / DOVER

DOVER



SITE NAME:	Ruins of St James' Church, Dover	Ruins of former church in public park building but restored in the C19. The
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	destroyed in the Second World War kept as a commemorative monumen Dover. Emergency propping of some
CONDITION:	Poor	carried out by Dover District Counci has been published. There are plans t
OCCUPANCY:	Vacant/not in use	has been published. There are plans
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1005151	Contact: David John 0207 973 3638

Fort Burgoyne, Connaught

Barracks, Dover / Guston

1004224

ner church in public park, orginally a Norman restored in the C19. The church was virtually the Second World War. The ruins have been nmemorative monument to the people of rgency propping of some elements have been y Dover District Council. A condition report olished. There are plans to carry out repairs.

1860s polygonal-plan fort now part of a later barracks. The earth-covered terraced casemates are vacant and the

casemates) have been at risk from lack of maintenance and invasive ivy growth. The site is owned by The Land Trust

Substantial progress for brick work repair and vegetation control was made using Homes and Community Agency

funds. Further vegetation works and conversion of the former Officers Stables has also been undertaken.

structures on the ramparts (the brick-built Haxo

which is working on plans for its sustainable future.

Contact: Rebecca Lambert 0207 973 3630

© Historic England



	fortifications, Dover st		A multi-phase, post-medieval fortification, with extant structures largely dating from the Royal Commission period of military construction. Site is at risk in part due to lack of joined up management leading to lapsed maintenance, but also issues with funding. A masterplan ha
	Scheduled Monument and Listed Buildings - 2 grade II, part in CA		
	CONDITION:	_	been agreed but actions arising from this are slow to be taken forward.
	OCCUPANCY: Part occupied/part in use	taken for ward.	
and a	PRIORITY CATEGORY: C (C) OWNER TYPE: Mixed, multiple owners		
		Mixed, multiple owners	
	LIST ENTRY NUMBER:	1020298 and 1375598; 1375599	Contact: Paul Roberts 0207 973 3636

© Historic England



LIST ENTRY NUMBER:

© Historic England Archive



SITE NAME:	St Radegunds Abbey, Abbey Road, Hougham Without	C13 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II*; 1 grade II	ruinous state. The site is now a farm with roofed buildings used as barns and a farmhouse. These are in fair condition. Recent negotiations (2021) have looked at consolidation of
CONDITION:	Very bad	the ruins and explore funding streams.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005196 and 1070023; 1068889; 1356562; 1363382	Contact: David John 0207 973 3638

© Historic England Archive

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / DOVER

	OWNER TYPE: LIST ENTRY NUMBER:	Private 1051607	Contact: Alice Brockway 0207 973 3655
	OWNER TYPE:	Private	Contact: Alice Proclemer 0207 972 2455
© Historic England Archive		e (e)	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Vacant/not in use	
f - Con	CONDITION:	Very bad	from Historic England.
	DESIGNATION:	Listed Building grade I, RPG grade II	the park to the north and south. Derelict for many years and now in a ruinous state. Temporary scaffolding and a protective canopy have been completed with grant aid
	SITE NAME:	The Belvedere, Waldershare Park, Shepherdswell with Coldred	Belvedere, 1725 to 1770, probably by Colen Campbell for Sir Henry Furnese. Located at the southern end of the western side of an early C18 Wilderness and overlooking

Church of St Margaret, High Street, St. Margaret's At Cliffe



SITE NAME:	Church of St Martin, Church Hill, Great Mongeham	Church built of flint dating from C12 and later restored by Butterfield in C19. Kentish ragstone window tracery and
DESIGNATION:	Listed Place of Worship grade II*, CA	surrounds and quoins are deteriorating throughout the building. Investigation work looking at guttering and hoppers has been completed. Ground level water disposal
CONDITION: Poor	Poor	is poor and is encouraging plant growth. Possible structur movement at north east corner of north aisle. Slipped
PRIORITY CATEGORY:	C (C)	tower louvres and vegetative growth on tower and north
OWNER TYPE:	Religious organisation	aisle roof.
LIST ENTRY NUMBER:	1069782	Contact: David John 0207 973 3638

© Historic England



SITE NAME:

© Diocese of Canterbur

	SITE NAME:	Church of St Mary, Canterbury	Church dating to c1200 with C13 chancel, C14 tower and		
ıry					
	LIST ENTRY NUMBER:	1101743	Contact: David John 0207 973 3638		
I IS A	OWNER TYPE:	Religious organisation			
NUMBER OF T	PRIORITY CATEGORY:	C (New entry)	requiring attention.		
	CONDITION:	Poor	Some water ingress, stone repairs and repointing required. Also, some repairs to the west door roof and other areas		
	DESIGNATION:	Listed Place of Worship grade I, CA	Flint and rubble with red brick dressings and slate roof, with plain tiled roof to south side. Two stage west tower largely rebuilt; chancel, nave and aisles and north porch.		
		Street, St. Margaret's At Cline	Elist and multiple with and brief drassings and elete as of		

	SITE NAME:	Church of St Mary, Canterbury Road, Wingham	Church dating to c1200 with C13 chancel, C14 tower and C16 nave and aisle. Restored 1874-5 by Benjamin Ferrey,
	DESIGNATION:	Listed Place of Worship grade I, CA	particularly the chancel. Some repairs have been carried out to the tower gutter and stair turret. Further repairs are needed including stone work around the church, gutters
	CONDITION:	Poor	and soakaways, and the bases of the timber arcade columns are rotting.
	PRIORITY CATEGORY:	C (C)	countris a c rotang.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1070091	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Great Mongeham Anglo-Saxon cemetery, Great Mongeham / Sutton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003124
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
OWNER TYPE:	Frivate, multiple owners	connen	
SITE NAME:	Ring ditch and enclosure 200yds (180m) east of Par		-
	· · ·		-
SITE NAME:	Ring ditch and enclosure 200yds (180m) east of Par	sonage Farm, Press	ton
SITE NAME: DESIGNATION:	Ring ditch and enclosure 200yds (180m) east of Par Scheduled Monument	sonage Farm, Presi LIST ENTRY NUMBER:	ton 1003121

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Church of c1150 rebuilding of earlier building with late C12 tower. Restored in the C18 and 1864 by Ewan Christian.

CA LB

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument LPA NP RPG SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / DOVER / FOLKESTONE AND HYTHE

SITE NAME:	London Road, Dover, Dover		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480
SITE NAME:	Mongeham Road, Great Mongeham, Great Mongeh	am	
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480
SITE NAME:	Western Heights, Dover, Dover		
DESIGNATION:	Conservation Area, 2 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480

FOLKESTONE AND HYTHE

	SITE NAME:	The Leas Lift, including Waiting Rooms, Brake Houses and Railings, the Leas, Folkestone	The Listed grade II* Leas Lift, a cliff funicular railway built in 1885 to transport people between The Leas, the beach and promenade. It is not operational and a trust has been
	DESIGNATION:	Listed Building grade II*, CA	formed to carry out repairs to bring it back into use. Historic England is working closely with the trust as they
	CONDITION:	Poor	develop their proposal and seek funding to carry out the work.
PAT	OCCUPANCY:	Part occupied/part in use	
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1061185	Contact: Isabelle Ryan 0207 973 3637

	SITE NAME:	Martello Tower No. 4, The Leas, Folkestone	A good example of a Martello tower but now derelict and situated in the grounds of a private house. Tower is used in
	DESIGNATION:	Scheduled Monument	part for an art installation but a long term sustainable use not agreed and repair of fabric and removal of obscuring
	CONDITION:	Very bad	vegetation is necessary.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1019148	Contact: Rebecca Lambert 0207 973 3630

	SITE NAME:	Dymchurch Redoubt, Hythe Ranges, Hythe	The original fort of 1806 is a massive brick circular structure within a dry moat, and has C20 additions.
	DESIGNATION:	Scheduled Monument	Located on Ministry of Defence ranges, some parts have been brought back into use as a military training facility.
The Party of	CONDITION:	Poor	There is brickwork deterioration to both the original fort and later additions. A Conservation Management Plan was
FARRA I	OCCUPANCY:	Part occupied/part in use	prepared in 2005. Phased repairs are in progress. There is continuing erosion from the seaward side of the fort.
The same	PRIORITY CATEGORY:	E (E)	continuing erosion from the seaward side of the fort.
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1017352	Contact: David John 0207 973 3638

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Martello Tower No. 9, Shorncliffe Camp, Hythe / Sandgate	Martello tower, 1806. Derelict, disposed by Ministry of Defence to private owner. The preservation of archaeological and historical significance will be the main	
	DESIGNATION:	Scheduled Monument and Listed Building grade II	consideration in assessing the suitability of proposals to convert Martello towers for residential use.	
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant/not in use		
A BURGER LAND	PRIORITY CATEGORY:	C (C)		
Historic England	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1017226 and 1061167	Contact: Rebecca Lambert 0207 973 3630	
	SITE NAME:	Martello Tower No. 5, Sandgate	Martello tower situated in the grounds of a school and	
	DESIGNATION:	Scheduled Monument, part in CA	vacant but with potential for re-use by the school. The preservation of archaeological and historical significance wi be the main consideration in assessing the suitability of	
E PARA	CONDITION:	Fair	proposals to convert Martello towers for residential use.	
I A A	OCCUPANCY:	Vacant/not in use		
L	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Educational (state sector)		
) Historic England	LIST ENTRY NUMBER:	1017172	Contact: David John 0207 973 3638	
	SITE NAME:	Martello Tower no 6, Shorncliffe Camp, Sandgate	A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion	
	DESIGNATION:	Scheduled Monument and Listed Building grade II, part in CA	scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner	
A TOULS	CONDITION:	Poor	now under discussion.	
PULLY RE	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Private		
) Historic England	LIST ENTRY NUMBER:	1017173 and 1068919	Contact: Rebecca Lambert 0207 973 3630	
	SITE NAME:	Martello Tower no 7, Shorncliffe Camp, Sandgate	A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion	
	DESIGNATION:	Scheduled Monument and Listed Building grade II	scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner	
	CONDITION:	Poor	now under discussion.	
		1 661		

© Historic England Archive

LIST ENTRY NUMBER: 1017174 and 1068920 Contact: Rebecca Lambert 0207 973 3630 Church with origins in the CII, but of multiple subsequent SITE NAME: Church of St James, Elmsted phases. Although some repairs have been undertaken DESIGNATION: Listed Place of Worship grade I recently, including an overhaul of the roofs and internal redecoration, there are corroding rainwater goods, CONDITION: Poor blocked hoppers and gullies, and vegetation growth. The PRIORITY CATEGORY: C (C) building has been the victim of heritage crime. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1241752 Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

Vacant/not in use

D (D)

Private

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / FOLKESTONE AND HYTHE / MAIDSTONE



SITE NAME:	Church of St Mary, Stowting	
DESIGNATION:	Listed Place of Worship grade II*	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1061070	

Church of CI3. Chancel restored 1843-4 by Carpenter, rest 1876 and 1890. North aisle and tower added 1857-68 by Slater. Flint with stone dressings. Plain tile roof. Nave, south porch, chancel with north lean-to, north aisle with west tower. The roof is in poor condition and reason for inclusion in the Register.

Contact: David John 0207 973 3638

© Diocese of Canterbury

SITE NAME:	Motte and Bailey Castle 200m north west of Stowting Church, Stowting		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012099
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE: Private		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 150m north east of Red House Far	rm, Swingfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011765
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE: Mixed, multiple owners		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow at Minnis Beeches, Swingfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011766
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

MAIDSTONE

	SITE NAME:	II, Lower Stone Street, Maidstone	A large early C18 house of three storeys. Some repairs and redecoration have been carried out in recent years and it is
	DESIGNATION:	Listed Building grade II*	now partly occupied, but it continues to suffer from a lack of appropriate regular maintenance.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1086332	Contact: Alice Brockway 0207 973 3655

© Historic England



	SITE NAME:	Stone House, 28, Lower Stone Street, Maidstone	ormerly the Judge's lodging for Maidstone. Part of a ubstantial C15 or C16 townhouse refronted in the early
DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY OWNER TYPE:	Listed Building grade II*	C18. Water ingress caused major damp and structural problems to a flank wall. A permanent repair is agreed and	
	CONDITION:	Poor	work is now well advanced.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1224677	Contact: Alice Brockway 0207 973 3655

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MAIDSTONE

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:



SITE NAME:	The Dungeons at the Archbishop's Palace, Mill Street, Maidstone	Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems. Early discussions with the owners about repairs
DESIGNATION:	Listed Building grade II*	have taken place.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1086309	Contact: David John 0207 973 3638

© Historic England

© Historic England



	SITE NAME:	Boxley Abbey: Barn and Precinct Walls, including Gatehouse, Boxley, Boxley	Parts of a Cistercian abbey founded in 1143. Main threat is to a medieval roofed range [the abbey Hospitium] converted to a barn, but which now has other uses.
	DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs	Eastern end of barn repaired; western end requires repairs but now has a temporary roof of profiled steel sheeting. The extensive precinct walls are also in need of repair and
	CONDITION:	Poor	maintenance with collapsed sections and heavy plant growth. Discussions are ongoing with the owner and a
	OCCUPANCY:	Part occupied/part in use	scheme to address the walls is in preparation.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1012264 and 1086229	Contact: Liz Pollard 0207 973 3650

Former St Andrews Chapel,

Boarley Lane, Boxley Abbey,

Listed Building grade II*

Vacant/not in use

Charity (heritage)

Boxley

Poor

C (C)



© Historic England



LIST ENTRY NUMBER:	1185580	Contact: Liz Pollard 0207 973 3650	
SITE NAME:	Dovecotes at Leeds Priory, Lower Street, Leeds	Mid CI6, overgrown and roofless dovecotes from a p Dissolution mansion. The building is at risk from serie	
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	structural decay and extensive damaging vegetation growth. Possible proposal for enabling development.	
CONDITION:	Very bad		
OCCUPANCY:	Vacant/not in use		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Private		
LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275	Contact: Paul Roberts 0207 973 3636	

© Historic England Archive

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Former late C15 chapel, no longer used for worship, but

converted to a house early on in its history. Unoccupied

and in need of repair. Location affected by proximity of

Protection of Ancient Buildings as an exemplar in sensitive conservative repair and an opportunity for craft training

motorway. Now purchased by the Society for the

and working parties. Improved security, temporary

is under discussion.

propping, structural monitoring and ground clearance works carried out. A scheme for the repair of the building

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MAIDSTONE



SITE NAME:	Slype and associated remains at Leeds Priory, Lower Street, Leeds	The remains of a medieval building w brickwork additions and attached wa related to monastic water management
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	as "The Abbey" and more recently as " buildings are at risk of serious structura extensive damaging vegetation growth.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275	Contact: Paul Roberts 0207 973 3636

ns of a medieval building with post-medieval additions and attached walls. It was potentially monastic water management. Formerly known obey" and more recently as "The Slype". The re at risk of serious structural decay and lamaging vegetation growth.

© Historic England Archive



SITE NAME:	Church of All Saints, Mill Street, Maidstone	Large Perpendicular church of the late C14. Extensive high- level vegetation and erosion of stonework. Blocked and
DESIGNATION:	Listed Place of Worship grade I	damaged rainwater goods and drains have resulted in water ingress and internal dampness. Wall paintings in
CONDITION:	Poor	chancel are also suffering damage. Extensive roof repairs are necessary.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1225056	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Church of St Nicholas, Lower Street, Leeds	Medieval church built of ragstone and tufa with a broad Romanesque tower. Roofing and stonework are in poor
	DESIGNATION:	Listed Place of Worship grade I	condition. An application to the National Lottery Heritage Fund Grants for Places of Worship scheme was unsuccessful. However, some roof repairs have taken plac but more repairs, particularly to the stonework are needed.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1086125	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Church of St Mary the Virgin, Thurnham Lane, Thurnham	Church of CI2 to early CI7. North chapel of galleted stone, porches of small uneven blocks of stone, rest
	DESIGNATION:	Listed Place of Worship grade I	random flint and stone. Plain tile roofs. West tower, continuous nave and chancel with opposed north and
	CONDITION:	Poor	south porches at the west end. Rectangular north chapel towards east end of nave. Roofs over nave, chancel and
	PRIORITY CATEGORY:	C (New entry)	chapel require replacement and east wall of the chancel is
	OWNER TYPE:	Religious organisation	in a poor state; all contributing factors to the building's risk.
	LIST ENTRY NUMBER:	1086165	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Leeds Priory: Augustinian Priory of St Mary and St N of the C18 Meredith Mansion, Leeds	Nicholas with asso	ciated dovecotes and slype, and the site
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Paul Roberts 0207 973 3636

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MAIDSTONE / SEVENOAKS

SITE NAME:	Binbury motte and bailey castle, Thurnham		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Elmstone Hole, Grafty Green, Boughton Malherbe		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mike Parkinson (LPA) 01622 602335
SITE NAME:	Maidstone Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Paul Robertshaw 01622 602723

SEVENOAKS

	SITE NAME:	Remains of corner tower to former Archbishops Palace, Otford	Remains of gatehouse range to early C16 Archbishops Palace. Ruinous parts are in need of consolidation work. Following Urgent Repair Works in 2017, a local community
	DESIGNATION:	Scheduled Monument, LB grade II	group has leased the building and is looking at options for its repair and re-use. A report and scheme have been commissioned and funding is being sought.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
© Historic England Archive	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1005197	Contact: David John 0207 973 3638

SITE NAME:	Chapel, Maplesco	ombe, West Kingsdown		
DESIGNATION:	Scheduled Monu	ment, LB grade II	LIST ENTRY NUMBER:	1005134
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Combe Bank, Brasted / Sundridge with Ide Hill	A classical landscape garden and small park surrounding palladian villa associated with some of the greatest artist exponents of the early pictureque movement. Sold and divided up the house and gardens becaming a school in 1924. Numerous remant built features survive in varying	
	DESIGNATION:	Registered Park and Garden grade II*, 17 LBs		
	CONDITION:	Extensive significant problems	condition in the gardens which suffered considerable s damage in 1987. Bissected by the M25, development	
	VULNERABILITY:	High	proposals and fragmentation of ownership and	
	TREND:	Declining		threat. A partnership project to deliver anagement Plan is required.
	NEW ENTRY?:	No		<u> </u>
© Historic England	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000365	Contact: Liz Poll	ard 0207 973 3650

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

SEVENOAKS / TUNBRIDGE WELLS

	02 ((2220		
	SITE NAME:	Swaylands, Bidborough / Penshurst	Small landscape park with terraced gardens and pleasure grounds, including extensive rockwork developed in the
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs	late C19. Now split into several ownerships with the house converted into apartments development of residential facilities is fragmenting the park and inappropriate forms of
	CONDITION:	Generally unsatisfactory with major localised problems	management may precipitate loss of historic design integrity. Understanding the presentation of the lower lake and kitchen garden as part of the parkland landscape, which
	VULNERABILITY:	Medium	are in separate ownership, much neglected and subject to
	TREND:	Stable	change through development is also imperitive to ensure appropriate stewardship.
) Historic England	NEW ENTRY?:	No	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1001280	Contact: Kay Richardson 0207 973 3647

SWALE

したの

10 m ©۲

SITE NAME:	Murston Old Church, Murston, Sittingbourne	Originally a large church with three aisles and three chancels with a square tower and wooden turret, built
DESIGNATION:	Scheduled Monument	between 1375 and 1550; only the southern chapel remains. The rest of the church survives as buried archaeological
CONDITION:	Poor	remains. Building has been the victim to heritage crime. The owners are also looking at possible future uses for the
OCCUPANCY:	Vacant/not in use	site, including the provision of studios and a cafe in a new,
PRIORITY CATEGOR	^{Y:} C (C)	separate building at the edge of the site. A grant from Historic England to carry out repairs has now been
OWNER TYPE:	Charity (heritage)	accepted with work due to start later in 2021.
LIST ENTRY NUMBER	^{R:} 1011768	Contact: David John 0207 973 3638

Former Royal Dockyard Church

and attached wall and railings,

Listed Building grade II*, CA

Sheerness Dockyard

Vacant/not in use

Charity (heritage)

Very bad

C (C)

1273239

© Historic England



© Historic England



SITE NAME:	The Boat Store, Sheerness Dockyard	Boat store, built in 1859. Since the destruction of the Crystal Palace and the first South Kensington Museum, this
DESIGNATION:	Listed Building grade I	is the earliest surviving example of a multi-storey iron- frame and panel structure. Its condition is rapidly
CONDITION:	Very bad	deteriorating. Discussions with the Local Planning Authority and Port Company about its repair and reuse are on-going.
OCCUPANCY:	Vacant/not in use	and fore company about its repair and reuse are on going.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1273160	Contact: David John 0207 973 3638

Fund.

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid в deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Former St Paul's Parish Dockyard Church. Built in 1828, by

architect George Taylor, but partially rebuilt after a fire in

1884. Empty since 1970 and severely damaged by fire in

2001. The Sheerness Dockyard Preservation Trust has

planning consent to repair and convert it to a community facility and National Lottery Heritage Fund grant for this

has now been secured. Work on site is progressing well, which has been partly funded by the Heritage Stimulus

Contact: David John 0207 973 3638

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SWALE

HERITAGE AT RISK 2021 / LONDO	on and south east	/ SWALE	
	SITE NAME:	Sheerness Defences, Swale	Moated artillery fortifications from C17-C20. A major
City and	DESIGNATION:	Scheduled Monument and Listed Building grade II	complex defending the dockyard. A repair programme needs to be agreed and implemented.
	CONDITION:	Very bad	
	OCCUPANCY:	Part occupied/part in use	
and the	PRIORITY CATEGORY:	C (C)	
1	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1005145 and 1259029	Contact: David John 0207 973 3638
1140000	SITE NAME:	Former Working Mast House, 26, Jetty Road, Sheerness Dockyard	Large C19 industrial building used as part of a complex for constructing and storing masts and small boats. Used for storage as part of operational port.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1244509	Contact: David John 0207 973 3638
	SITE NAME:	Church of St Peter, Church Road, Oare	A predominantly Perpendicular church, much restored by Joseph Clarke in 1868. The church has had serious
	DESIGNATION:	Listed Place of Worship grade I	structural movement at its east end with disturbance to the flooring and serious cracking to the walls at the east end.
ARTEN	CONDITION:	Poor	This appears to have been partly resolved, but there is still evidence of movement that requires monitoring. Repairs
AT MALE	PRIORITY CATEGORY:	C (C)	are also required to the spire shingles.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1069126	Contact: David John 0207 973 3638
© Historic England			

	SITE NAME:	Church of St Peter and St Paul, Water Lane, Ospringe	A C13 church, with later accretions, all substantially restored in 1858-70 by EL Blackburne. Despite its apparent
	DESIGNATION:	Listed Place of Worship grade II*, CA	fair condition, the north and the south side of the church is suffering from serious internal damp as a result of multiple slipped tiles, blocked rainwater goods and extensive ivy
HALL &	CONDITION:	Poor	growth. There is probable structural movement in the chancel.
A TRA	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1343988	Contact: David John 0207 973 3638
Historic England			

© Historic England



SITE NAME: Church of St Giles, Church Originally C12 flint church with unconventional val	ey Sy stand
Road, Tonge gutter arrangement. Structural monitoring has esta	
DESIGNATION: Listed Place of Worship grade I that movement is generally stable. The state of the has been improved. The parish is applying for a grader light that movement is generally stable.	nt to
CONDITION: Poor conserve the medieval wall paintings and is about t the building re-wired.	> have
PRIORITY CATEGORY: C (C)	
OWNER TYPE: Religious organisation	
LIST ENTRY NUMBER: 1322821 Contact: David John 0207 973 3638	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SWALE / THANET

SITE NAME:	Cellar Hill and Greenstreet, Lynsted with King	down / Teynham	
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Milton Regis High Street		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Newington High Street, Newington		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Marine Town		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Mile Town		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Royal Naval Dockyard & Bluetown		
DESIGNATION:	Conservation Area, 13 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sittingbourne High Street		
DESIGNATION:	Conservation Area, 26 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Upchurch		
DESIGNATION:	Conservation Area, LB grade I	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Algar (LPA) 01795 417375

THANET



	SITE NAME:	Dreamland Cinema, Marine Terrace, Margate	Cinema, 1935. The first English cinema in the style based on the Titania Palast of Berlin, a style subsequently used
	DESIGNATION:	Listed Building grade II*	extensively by Odeon. The first major phases of a programme of repairs and reinstatement of architectural
	CONDITION:	Fair	features are now complete. Parts are now in use for the Dreamland Park and the remainder is proposed for a
	OCCUPANCY:	Part occupied/part in use	variety of entertainment uses.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1260315	Contact: Alice Brockway 0207 973 3655

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / THANET

	SITE NAME:	The Clock House, Royal Harbour, Ramsgate	The harbour clock house of 1817 designed by Benjamin Wyatt and George Louch and altered by John Rennie.
	DESIGNATION:	Listed Building grade II*	Located on the Ramsgate Meridian Line and originally designed to tell "Ramsgate time" being 5 minutes, 41
	CONDITION:	Poor	seconds ahead of Greenwich Mean Time. Partly in museum use. Covid-19 Emergency Heritage At Risk Response
	OCCUPANCY:	Part occupied/part in use	funding saw repairs to the roof and high level masonry
	PRIORITY CATEGORY:	C (C)	(2021), although a full scheme of repairs is still required. Plans need to be developed to see the building fully
A	OWNER TYPE:	Local authority	repaired and brought back into a sustainable use.
© Historic England	LIST ENTRY NUMBER:	1336325	Contact: David John 0207 973 3638

© Thanet District Council

Late medieval grain barn, on land formerly owned by St SITE NAME: Barn about 50 metres east of Ozengell Grange, Haine Road, Augustine's Abbey, Canterbury. In a very bad condition with missing roof tiles and structural issues. Discussions are Ramsgate on-going about how repairs may be organised. DESIGNATION: Listed Building grade II* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1336669 Contact: Alice Brockway 0207 973 3655

metre	SITE NAME:	Church of St Augustine of England, St Augustine's Road, Ramsgate	Constructed by AWN Pugin and containing his tomb. The site consists of a churchyard to the south and a cloister to the north with chapels, sacristy and ancillary
3.0	DESIGNATION:	Listed Place of Worship grade I	accommodation. The church comprises a nave, crossing with tower and confessional, chancel, south aisle and
	CONDITION:	Poor	chapel. A National Lottery Heritage Fund grant for Places of Worship addressed urgent repairs to roofs, gutters and
	PRIORITY CATEGORY:	C (C)	high level masonry in 2010 with further phases in 2011,
	OWNER TYPE:	Religious organisation	2012 and 2013. The first phases are now complete with further repairs still required to the north range.
toric England	LIST ENTRY NUMBER:	1281779	Contact: David John 0207 973 3638

© Historic England

STE NAME:Quex Park settlements, Birchington / Westgate-on-SetDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005137CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Anglo-Saxon cemetery, Dane Valley Road, Broadstatist and St. Peters1003601DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003601CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoOWNER TYPE:PrivateSettement one mile (1610m) east of village, Manty:NoSTE NAME:Scheduled MonumentLIST ENTRY NUMBER:1005135GONDITION:Scheduled MonumentLIST ENTRY NUMBER:1005135OWNER TYPE:PrivateSettement one mile (1610m) east of village, Manty:NoSTE NAME:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningScheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoONNERTYPE:PrivateScheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERA						
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Anglo-Saxon cemetery, Dane Valley Road, Broadstairs and St. PetersI003601DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003601CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorJoing Contact:DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135OWNER TYPE:Settlement one mile (1610m) east of village, ManstorJoing Contact:DecliningDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:NoPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY:No	SITE NAME:	Quex Park settlements, Birchington / Westgate-on-Sea				
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 SITE NAME: Anglo-Saxon cemetery, Dane Valley Road, Broadstairs and St. Peters Io03601 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1003601 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STE NAME: Settlement one mile (1610m) east of village, Manston Declining OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646 STE NAME: Settlement one mile (1610m) east of village, Manston UST ENTRY NUMBER: 1005135 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005135 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005137		
OWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Anglo-Saxon cemetery, Dane Valley Road, Broadstartand St. PetersDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003601CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646STTE NAME:Settlement one mile (1610m) east of village, ManstartIO051 35DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:10051 35CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?NoPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?No	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME:Anglo-Saxon cemetery, Dane Valley Road, Broadstairs and St. PetersDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003601CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorIST ENTRY NUMBER:1005135DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1003601CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorUIST ENTRY NUMBER:1005135DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorVIST ENTRY NUMBER:1005135DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	SITE NAME:	Anglo-Saxon cemetery, Dane Valley Road, Broadsta	airs and St. Peters			
PRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:NoOWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorLIST ENTRY NUMBER:1005 135DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005 135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003601		
OWNER TYPE:PrivateCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Settlement one mile (1610m) east of village, ManstorDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	CONDITION:	Extensive significant problems	TREND:	Declining		
SITE NAME: Settlement one mile (1610m) east of village, Manstor DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1005135 CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1005135CONDITION:Extensive significant problemsTREND:DecliningPRINCIPAL VULNERABILITY:Arable ploughingNEW ENTRY?:No	OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
CONDITION: Extensive significant problems TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	SITE NAME:	Settlement one mile (1610m) east of village, Mansto	on			
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005135		
	CONDITION:	Extensive significant problems	TREND:	Declining		
OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 3646	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
	OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / THANET / TONBRIDGE AND MALLING

SITE NAME:	Anglo-Saxon cemetery south of Ozengell Grange, Manston / Ramsgate				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004228		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Ramsgate				
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No		
CONDITION:	Poor	TREND:	Deteriorating		
VULNERABILITY:	Medium	CONTACT:	Josie Sinden 01843 577126		

TONBRIDGE AND MALLING

-	SITE NAME:	Church of All Saints, Snodland	Church with C12 origins restored and extended by
	DESIGNATION:	Listed Place of Worship grade I, CA	Blomfield in C19. Poor stonework repairs have been carried out in the past including rendering walling stones and dressings with a cement based mortar which is failing.
	CONDITION:	Poor	Areas of deeply eroded stonework and defective rainwater drainage system. High level stonework and plaster repairs
	PRIORITY CATEGORY:	D (D)	have been successfully completed using funds from the
	OWNER TYPE:	Religious organisation	National Lottery Heritage Fund Grants for Places of Worship scheme, but further phase of repairs required for
	LIST ENTRY NUMBER:	1347897	the lower level stonework and drainage.
C Historic England			Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Town Banks, Tonbridge		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1003599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Maria Buczak 0207 973 3642
SITE NAME:	Romano-British villa, Anglo-Saxon cemetery and	associated remains at	t Eccles, Aylesford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

А

- В
- C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but F Under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / TUNBRIDGE WELLS / KENT (OFF)

TUNBRIDGE WELLS



SITE NAME Providence Chapel, Stone Street, Cranbrook & Sissinghurst DESIGNATION: Listed Building grade II*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1084808

Baptist chapel, no longer used for worship. 1795 with early to mid C19 alterations. A temporary scaffold roof has been erected to limit water ingress. A feasibility study has been completed recommending its use by the community, and restoration led by a potential preservation trust. The current owner is considering this option but the building's condition is rapidly worsening. Some internal urgent works have recently been carried out by the owner.

Contact: David John 0207 973 3638

© Historic England Archive

SITE NAME:	Royal Tunbridge Wells		
DESIGNATION:	Conservation Area, 266 LBs, 2 RPGs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Mark Stephenson (LPA) 01892 526121

KENT / EAST SUSSEX

TUNBRIDGE WELLS / WEALDEN

SITE NAME:	High Rocks Camp (see also Wealden, East Sussex), Frant				
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1003816		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646		

SITE NAME:	Bayham Abbey, Frant / Lamberhurst	Late C19 mansion gardens with formal terraces and informal pleasure grounds set within a Humphry Repton
DESIGNATION:	Registered Park and Garden grade II, 8 LBs, SM	Red Book park focused on the abbey ruins, Now managed by English Heritage. Partly in East Sussex and Kent. The estate was divided in the 1970s with further fragmentation
CONDITION:	Generally unsatisfactory with major localised problems	of the site since. Mixed arable conversion has impacted the landscape fabric integrity supporting the composition of the parkland. A parkland plan exists in part around Bayham
VULNERABILITY:	Medium	Old Abbey (2012) and recommendation of a joint
TREND:	Declining	approach to further conservation priorities as part of a parkland plan process was made in 2020.
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000257	Contact: Kay Richardson 0207 973 3647
	DESIGNATION: CONDITION: VULNERABILITY: TREND: NEW ENTRY?: OWNER TYPE:	Lamberhurst DESIGNATION: Registered Park and Garden grade II, 8 LBs, SM CONDITION: Generally unsatisfactory with major localised problems VULNERABILITY: Medium TREND: Declining NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners

KENT (OFF)

-	1			
-	- 53		THE R	
-98		Ser.		
			194	The second
		1.1	A.	

© Pascoe Archaeology Services and

MSDS Marine

SITE NAME: Northumberland, Goodwin Sands Protected Wreck Site, part in DESIGNATION: PWS CONDITION: Extensive significant problems VULNERABILITY: Medium TREND: Declining PRIORITY CATEGORY: E (E) OWNER TYPE-Government or agency LIST ENTRY NUMBER: 1000058

Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. The first third rate ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships requested. The warship foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biological attack and may be subject to detachment and dispersal by tide and wave surge during winter storms.

Contact: Hefin Meara 07879 113318

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

WHS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / KENT (OFF) / MEDWAY (UA)

VULNERABILITY:

OWNER TYPE:

PRIORITY CATEGORY:

TREND:

High

E (E)

Declining

Government or agency

in the second seco	SITE NAME:	Restoration, Goodwin Sands	Although there is no definite evidence, this wreck of a
	DESIGNATION:	Protected Wreck Site, part in PWS	wooden warship is thought to be the remains of the Restoration, a Third Rate 70-gun warship built 1678 as par of Samuel Pepys' regeneration of the English navy. Along
	CONDITION:	Extensive significant problems	with the Northumberland and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of
	VULNERABILITY:	Medium	1703. The Goodwin Sands change morphology on a
	TREND:	Declining	seasonal basis leading to periodic exposure of the vessel's wooden hulls. Exposed timbers are weakened by biologica
	PRIORITY CATEGORY:	E (New entry)	attack and may be subject to detachment and dispers tide and wave surge during winter storms.
OUniversity of St Andrews and Wessex	OWNER TYPE:	Government or agency	tide and wave surge during winter storms.
Archaeology	LIST ENTRY NUMBER:	1000057	Contact: Hefin Meara 07879 113318
	SITE NAME:	London, The Nore	The London was a Second Rate 'Large Ship' built in
	DESIGNATION:	Protected Wreck Site	Chatham in 1654 during the Interregnum. The vessel is known to have participated in the First Dutch War (1652-
	CONDITION:	Extensive significant problems	4) and later formed part of an English Squadron sent to collect Charles II from the Netherlands and restore him to

© Historic Eng	back

	LIST ENTRY NUMBER:	1000088	Contact: Hefin Meara 07879 113318
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY:	SITE NAME:	Rooswijk, towards the north eastern end of the Kellett Gut	The VOC (Dutch East Company) ship Rooswijk was built in Amsterdam in 1737 but stranded on the Goodwin Sands
	DESIGNATION:	Protected Wreck Site	in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice
	CONDITION:	Generally unsatisfactory with major localised problems	of large-scale overseas commerce between the Netherlands and Asia during the C18. As with other sites in the Goodwins, archaeological material is at risk owing to
	VULNERABILITY:	High	mobile sediments causing periodic exposure. A large scale
1	TREND: Declining PRIORITY CATEGORY: E (E)	excavation was undertaken in 2017 and 2018, in a joint project with the Dutch Cultural Heritage Agency and othe	
		E (E)	stakeholders.
OWNER TYPE:	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1000085	Contact: Hefin Meara 07879 33 8

dive team

the throne. The London blew-up on passage from Chatham in March 1665. A series of artefacts have been

been undertaken in partnership with Cotswold

identified on the river bed and recovered to the surface. An excavation project, #LondonWreck1665, has recently

Archaeology, Southend Museums Service and the licensed

MEDWAY (UA)

© RCE

10Az	SITE NAME:	Brompton Lines, Chatham	Landward defences to dockyard at Chatham, subsequently
	DESIGNATION:	Scheduled Monument, part in CA	used in part as a pleasure ground for officers. Defences cross Ministry of Defence owned land, housing and Brompton Barracks. Section between Sallyport and Prince
	CONDITION:	Poor	of Wales bastion (including the Couvre Porte) are most in need of conservation.
	OCCUPANCY:	N/A	
Pares	PRIORITY CATEGORY:	C (C)	
• 340 ·	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1003364	Contact: Rebecca Lambert 0207 973 3630

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MEDWAY (UA)

	SITE NAME:	Fort Darnet	A Royal Commission fort circa 1860, in the Medway
T	DESIGNATION:	Scheduled Monument	Estuary. Constructed as part of the 1859 Royal Commission inspired refortification programme of the 1860s and 70s to protect Chatham dockyard. Partially
-	CONDITION:	Very bad	1860s and 70s to protect Chatham dockyard. Partially flooded.
	OCCUPANCY:	Vacant/not in use	nooded.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1019642	Contact: Rebecca Lambert 0207 973 3630

© Historic England Archive

	SITE NAME:	No. 8 machine shop, Dock Head Road, Chatham Dockyard	1840 former dry dock cover which was later used as a Machine Shop but is now disused. Cladding removed so
	DESIGNATION:	Listed Building grade II*	the cast iron members and joints are now corroding. Applications to repair and convert it for leisure uses were
	CONDITION:	Poor	approved by the Local Authority but not fully implemented. Recent applications for its conversion to a drive through
OCCUP	OCCUPANCY:	Vacant/not in use	cinema.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1267822	Contact: Alice Brockway 0207 973 3655

© Historic England

	SITE NAME:	351, High Street, Rochester	Brewery mansion. Early C18, refronted early C19 and with
	DESIGNATION:	Listed Building grade II*, CA	C20 alterations and additions as a shop to front. Painted brick, slate roofs. Last used as a shop in 1980s the fittings
	CONDITION:	Poor	or which have been removed. Later industrial buildings to he rear. Empty since closed as a shop; however a
	OCCUPANCY:	Vacant/not in use	programme of repairs is underway.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1320136	Contact: Alice Brockway 0207 973 3655

© Historic England

© Historic England

Surger State	SITE NAME:	Cliffe Fort, Cliffe and Cliffe	Fort c1860. Fort is now flooded. Much of it is stable due to	
	LIST ENTRY NUMBER:	1268218	Contact: David John 0207 973 3638	
	OWNER TYPE:	Religious organisation	back into use.	
	PRIORITY CATEGORY:	C (C)	Commissioners. Further funding will be required to complete the works to allow the building to be brought	
	OCCUPANCY:	Vacant/not in use	funded by Historic England and the Church	
	CONDITION:	Poor	Grant to carry out emergency works to the roof and interior rotting timber has now been completed, part	
	DESIGNATION:	Listed Building grade II*	by the Diocese of Rochester to bring this disused church back into use as a place of worship and for community use.	
	SITE NAME:	Former Church of St John the Divine, Railway Street, Chatham	Closed Italianate style church of 1820-21 by Sir Robert Smirke, 1863 apse by GM Hills. Plans are being developed	



AT A	SITE NAME:	Cliffe Fort, Cliffe and Cliffe Woods	Fort c1860. Fort is now flooded. Much of it is stable due to massive construction, but significant detail is vulnerable to
	DESIGNATION:	Scheduled Monument	decay. The building has been the victim of heritage crime. Remains of Brennan Torpedo Rail are also vulnerable to
	CONDITION:	Very bad	erosion. Historic England has carried out a detailed survey. Investigation is to be carried out as to the source of the
	OCCUPANCY:	Vacant/not in use	flood water.
7	PRIORITY CATEGORY:	C (C)	
1	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1003403	Contact: David John 0207 973 3638

© Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MEDWAY (UA)

HERITAGE AT RISK 2021 / LOND	JIN AIND SOUTH EAST	/ MEDVVAT (UA)	
	SITE NAME:	Cooling Castle, Cooling	A quadrangular castle with ruined fabric, some of which is
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I, LB grade II	in need of major repair.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	A (A)	
Part to be	OWNER TYPE:	Private	
) Historic England Archive	LIST ENTRY NUMBER:	1009018 and 1085771; 1085770	Contact: Rebecca Lambert 0207 973 3630
	SITE NAME:	Barn 30 yards south east of the manor, Upnor Road (south side), Frindsbury Extra	Very fine medieval barn, redundant for agricultural use an subject to major fire damage. The reconstruction of fire damaged bays and a programme of repair was completed
A VANNAME.	DESIGNATION:	Listed Building grade I, CA	in 2019. A planning application for the partial conversion the barn to a wedding venue was submitted in 2021.
	CONDITION:	Poor	, i i i i i i i i i i i i i i i i i i i
© Historic England	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
) Historic England	LIST ENTRY NUMBER:	1204320	Contact: Alice Brockway 0207 973 3655
All the second	SITE NAME:	Cockham Wood Fort, Hoo St. Werburgh	A rare C17 artillery fort. The brick lower battery is very decayed as it is washed by the tidal Medway. The higher
	DESIGNATION:	Scheduled Monument	earthwork batteries survive but in woodland, with the remains of a redoubt and commander's house.
-	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
Contraction of	PRIORITY CATEGORY:	A (A)	
No. Contraction	OWNER TYPE:	Private	
Historic England Archive	LIST ENTRY NUMBER:	1003362	Contact: Rebecca Lambert 0207 973 3630
	SITE NAME:	Fort Hoo, Hoo St. Werburgh	Sister fort to Fort Darnet circa 1860. Fort lies abandoned
a million of	DESIGNATION:	Scheduled Monument	on an island in the Medway.
1.63	CONDITION:	Poor	
and the second	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1019643	Contact: Rebecca Lambert 0207 973 3630

© Historic England Archive



SITE NAME:	Artillery Tower (Grain Tower), Isle of Grain	Artillery tower of 1855 with C20 additions. Forms part of the defences to Sheerness dockyard. Abandoned and
DESIGNATION:	Scheduled Monument and Listed Building grade II	surrounded by the sea at high tide.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1019955 and 1204520	Contact: Rebecca Lambert 0207 973 3630

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MEDWAY (UA) / MILTON KEYNES (UA)

SITE NAME:	Gillingham Green		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Halling		
DESIGNATION:	Conservation Area, 4 LBs, SM	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Railway Street		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721
SITE NAME:	Rainham		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
	FOOI		Deteriorating
VULNERABILITY:	High	CONTACT:	Martin McKay (LPA) 01634 331721

MILTON KEYNES (UA)



DESIGNATION:Listed Place of Worship grade I RPG grade IICONDITION:Very badPRIORITY CATEGORY:A (A)OWNER TYPE:Religious organisationLIST ENTRY NUMBER:1211931		SITE NAME:	Church of St Peter, Gayhurst Court, Gayhurst
PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation		DESIGNATION:	Listed Place of Worship grade I RPG grade II
OWNER TYPE: Religious organisation		CONDITION:	Very bad
I teligious of garlisation		PRIORITY CATEGORY:	A (A)
LIST ENTRY NUMBER: 2 93		OWNER TYPE:	Religious organisation
		LIST ENTRY NUMBER:	1211931

Renaissance design, built in 1728 for the Wrighte family. Only the crypt remains from the previous medieval church. Limestone with grey rusticated plinth with yellow ashlar above. Interior: ashlar stone above panelled dado, plaster ceilings. Nave walls of 5 bays with Corinthian pilasters. Two-stage west tower, arcaded cupola and ogee domed roof. Water penetrating cupola and tower resulting in timber decay of the structure. An application for a National Lottery Herítage Fund Grants for Places of Worship in 2017 was unsuccessful but these structural repair works remain urgent.

© Bryan Martin

Contact: Rachel James 0207 973 3153

SITE NAME:	Roman town of Magiovinium and Roman fort, Bletchley and Fenny Stratford			
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1006943			
CONDITION:	Extensive significant problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	St Martin's Chapel (site of), Emberton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021373	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company CONTACT:		Alison McQuaid 0207 973 3646	
SITE NAME:	Moated site 70m south of Long Plantation, Hanslop	e Park, Hanslope		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011303	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

LPA

- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MILTON KEYNES (UA) / CHERWELL

SITE NAME:	Wolverton, Wolverton and Greenleys / Stantonbury			
DESIGNATION:	Conservation Area, 17 LBs NEW ENTRY?: No			
CONDITION:	Fair	TREND:	Deteriorating significantly	
VULNERABILITY:	Low	CONTACT:	Simon Peart (LPA) 01908 252613	

OXFORDSHIRE

CHERWELL

	SITE NAME:	Ruins of Hampton Gay Manor House, Hampton Gay and Poyle	Ruins of late C16 manor house which burnt down in 1887. Ruin in very poor condition suffering from structural
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	problems and with substantial vegetation growth. A programme of consolidation works needs to be agreed and implemented and management as a ruin is required.
RAL	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1006334 and 1220230	Contact: Rachel James 0207 973 3153

	SITE NAME:	Defence and ancillary structures at RAF Bicester, Bicester, Launton	The most complete and strongly representative example of an RAF airbase from the interwar expansion, built as a bomber station as part of the 1920s Home Defence
	DESIGNATION:	Scheduled Monument, CA	Expansion Scheme. It is the scheduled monuments on the airfield site that are at risk from decay and vegetation.
© Historic England	CONDITION:	Poor	These comprise the southern bomb stores (pictured) and defensive structures. The owners have worked with
	OCCUPANCY:	Vacant/not in use	Historic England to address the issues. In 2016 and 2018
	PRIORITY CATEGORY:	F (F)	grant aided repairs to Scheduled airfield structures were completed. The Southern bomb stores condition and
	OWNER TYPE:	Commercial company	possible use are under consideration.
	LIST ENTRY NUMBER:	1021455	Contact: Rachel James 0207 973 3153

	SITE NAME:	Church of St Lawrence, Caversfield	Saxon, possibly C10, base to the west tower and bell stage rebuilt in the C13 with a saddleback roof covered in plain
	DESIGNATION:	Listed Place of Worship grade II*	clay tiles. Late C12 rebuilding of the chancel and nave; the chancel being remodelled in the C13. Henry Woodyer, in
	CONDITION:	Poor	1874, rebuilt the aisles, restored the chancel and added the north vestry. The nave and aisle roofs are very steep;
	PRIORITY CATEGORY:	C (C)	covered in thin, stone slates. Water ingress occurring and
	OWNER TYPE:	Religious organisation	repairs are needed. An application to the National Lottery Heritage Fund Grants for Places of Worship scheme in
	LIST ENTRY NUMBER:	1046533	2017 was unsuccessful.
			Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Ilbury Camp hillfort, Deddington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015167
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Islip Roman villa, 300m east of Hillside Farm, Islip		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015161
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CHERWELL / OXFORD / SOUTH OXFORDSHIRE


SITE NAME:	Banbury Grimsbury, North Oxfordshire, Ban	Banbury Grimsbury, North Oxfordshire, Banbury			
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No		
CONDITION:	Very bad	TREND:	Deteriorating significantly		
VULNERABILITY:	Low	CONTACT:	Jennifer Ballinger 01295 221885		
SITE NAME:	RAF Upper Heyford, Upper Heyford, Ardley, Upper Heyford / Ardley / Somerton				
DESIGNATION:	Conservation Area, 5 LBs, part in SM	NEW ENTRY ?:	No		
CONDITION:	Very bad	TREND:	Deteriorating		
VULNERABILITY:	Medium	CONTACT:	Jennifer Ballinger 01295 221885		

OXFORD

© Historic England



Swing bridge, near Rewley Road, Oxford Rewley Road Swing Bridge is a disused railway swing bridge SITE NAME: over Sheepwash Channel in west Oxford. The bridge was designed by Robert Stephenson and built in 1850-1. It was DESIGNATION Scheduled Monument reconstructed in 1890 and 1906, latterly using steel girders. The bridge closed to passenger traffic in 1951 and to goods CONDITION: Very bad in 1984. The bridge suffered from decay of the plating and paintwork protecting the 1850s mechanism and early OCCUPANCY: N/A fabric. Historic England provided grant aid towards PRIORITY CATEGORY: F (F) investigation work and the repair. Repair work started at the end of 2020 and is due to complete in the summer of OWNER TYPE: Charity (heritage) 2021. LIST ENTRY NUMBER: 1003651 Contact: Rachel James 0207 973 3153



© Historic England

	SITE NAME: Church of St Thomas the Martyr, St Thomas Street, Oxford		Church with chancel dating to late C12 and C15-16 nave west tower and north chapel. Roof covering in poor condition though structurally sound overall. The rainwat	
	DESIGNATION:	Listed Place of Worship grade II	goods are generally adequate apart from one gutter, and stonework is fair to poor. The church applied for a Listed	
	CONDITION:	Poor	Places of Worship Roof Repair Fund grant but was not successful. The repair of the roof coverings is still requi	
	PRIORITY CATEGORY:	C (C)	succession. The repair of the root coverings is suit required.	
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1047122	Contact: Rachel James 0207 973 3153	
and				

© Historic Englai

SOUTH OXFORDSHIRE

	SITE NAME:	Well house, Wick Farmhouse, Barton, Beckley and Stowood	Well house associated with Wick Farmhouse, late C17, in poor condition and not in use. Square plan ashlar structure
	DESIGNATION:	Listed Building grade II*	in Baroque style with stone benches lining walls. Well now filled in. Historic England has been in discussion with the
	CONDITION:	Poor	owner regarding maintenance and conservation repairs. We understand that quotations for the work were
	OCCUPANCY:	N/A	obtained. The structure sits within a larger unused
	PRIORITY CATEGORY:	D (D)	farmyard which forms part of larger planning discussions.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1047637	Contact: Rachel James 0207 973 3153

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2021 / LONDO	on and south east	/ SOUTH OXFORDSHIRE	
	SITE NAME:	Walled garden approximately 30 metres west of Manor Farmhouse, North Weston, Great Haseley	Walled garden with loggia, dating from early C18. Built of brick with limestone ashlar details and a plain tile roof to the loggia. The wall has a moulded brick coping. It was formerly part of the North Weston Manor which was
	DESIGNATION:	Listed Building grade II*	largely demolished in early C19. The wall tops are disintegrating; there are structural cracks and the loggia is
	CONDITION:	Very bad	propped to prevent collapse. A project to address the issues needs to be agreed.
	OCCUPANCY:	N/A	issues needs to be agreed.
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1369269	Contact: Rachel James 0207 973 3153
	SITE NAME:	Fernhouse, archway, gateway and walls, Mapledurham	Fern house, archway, gateway and walls of the walled garden to Mapledurham House. C17 and C18. The Fern
CONTRACT STREET	DESIGNATION:	Listed Building grade II*, CA	house is roofless and in need of repair. The condition of the walls and gateway varies. There have been discussions
	CONDITION:	Poor	regarding possible appropriate use and repair, including a proposal for reuse with heat provided by bio-mass heating.
	OCCUPANCY:	Vacant/not in use	No works have physically been undertaken.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1059520	Contact: Rachel James 0207 973 3153
	SITE NAME:	Remains of St Nicholas's College, Wallingford Castle, Wallingford	Remains of C13 St Nicholas's College, the King's Chapel built within the Castle, with C15 and C16 additions. The site has suffered from heritage crime and part is fenced off.
	DESIGNATION:	Scheduled Monument	Structures also in need of consolidation and a sustainable management plan. Historic England is working with the
	CONDITION:	Very bad	owners to see the site conserved, explained and maintained. Owners have commissioned survey work and
	OCCUPANCY:	N/A	have formed a heritage action group. Historic Éngland has
	PRIORITY CATEGORY:	A (C)	offered a two-stage grant for the repair and consolidation of the chapel remains.
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1006324	Contact: David Wilkinson 0207 973 3644
-	SITE NAME:	Church of All Saints, Church Street, North Moreton	Church, mainly flint and sandstone, with tiled roofs to nave and chancel, and sheet roof to south aisle. Mostly mid
	DESIGNATION:	Listed Place of Worship grade I, CA	CI3/CI4 but altered in CI5 and restored in CI9. The tower and chantry chapel have had works carried out to them. Two National Lottery Heritage Fund and Historic
A TEAT	CONDITION:	Poor	England Repair Grants for Places of Worship projects have been completed. Works are still needed to the South Aisle
	PRIORITY CATEGORY:	D (C)	roof. The outstanding important early C14 St Nicholas
	OWNER TYPE:	Religious organisation	stained glass window within the chantry chapel remains in urgent need of repair to the glazing and stonework and
	LIST ENTRY NUMBER:	8 258	funds need to be raised for this work.
© Historic England			Contact: Rachel James 0207 973 3153

SITE NAME:	Grim's Ditch; portion from Mongewell Park Lodge	to S of Nuffield ch	urch, Crowmarsh / Ipsden / Nuffield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006368
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Chris Welch 0207 973 3633

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH OXFORDSHIRE

SITE NAME:	North Stoke henge and ring ditch site, Crowma	rsh / South Stoke	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006335
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Dike Hills, Dorchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006364
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	Alison McQuaid 0207 973 3646	
SITE NAME:	Camp on Bozedown, Goring Heath / Whitchurc	h-on-Thames	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003704
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site at Northfield Farm, Little Witter	nham / Long Wittenha	m
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002925
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Defences to the Saxon town [within Bull and Ki	ne Croft], Wallingford	I
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006329
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	David Wilkinson 0207 973 3644
SITE NAME:	Long barrow 340m north west of Cooks Cottag	ges, Warborough	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016632
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Romano-British settlement 520m north west of	Cooks Cottages, Wa	rborough
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016630
	Extensive significant problems	TREND:	Declining
CONDITION:	8 1		
CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SOUTH OXFORDSHIRE	/ WOKINGHAM	(UA)	
	SITE NAME:	Fawley Court and Temple Island, Bix and Assendon / Fawley / Henley-on-Thames / Remenham	Early C18 garden and pleasure grounds surrounding a 1680s house set within a park landscaped by Lancelot Brown. Interacting with the adjacent River Thames, an eyecatcher stands on Temple Island downstream in
	DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, 2 CAs	Brown's principal vista. The gardens and wooded pleasure grounds have a number of parkland architectural elements linked by paths. Most of the estate and park are in separate
	CONDITION:	Generally unsatisfactory with major localised problems	ownership with previous development and inappropriate planting also impacting on the parkland structure and designed views There is a need to identify a partnership
	VULNERABILITY:	High	approach to deliver conservation management.
© Historic England	TREND:	Stable	
	NEW ENTRY?:	No	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1000390	Contact: Kay Richardson 0207 973 3647

VALE OF WHITE HORSE

	SITE NAME:	Milton Manor House, High Street, Milton	Manor house built circa 1670 in classical style with later attached flanking wings, (one of which includes a chapel),
	DESIGNATION:	Listed Building grade I, CA	kitchen and brewhouse range added circa 1776. North and south wings, and stable and carriage house roofs in poor
	CONDITION:	Poor	condition and cornice to main block in very poor cond The condition of the timberwork to the windows is al
	OCCUPANCY:	Occupied/in use	cause for great concern. Discussions between Historic
	PRIORITY CATEGORY:	A (A)	England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not
	OWNER TYPE:	Private	enacted.
© Historic England	LIST ENTRY NUMBER:	1048220	Contact: Rachel James 0207 973 3153
	SITE NAME:	Church of St Mary, Buckland	Cruciform plan with west tower. Early CI2 nave, Early
	DESIGNATION:	Listed Place of Worship grade I, CA	English (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; stone slate roofs, except to nave
	CONDITION:	Poor	and chancel; limestone ashlar flue. The limestone stone slate roofs to the north and south transept have been
	PRIORITY CATEGORY:	C (C)	repaired. Stonework repairs are required at high level on
	OWNER TYPE:	Religious organisation	the tower.

Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Castle mound at Fitzharris, Abingdon on Thames		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006311
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site south east of church, Appleford-on	-Thames / Long Wi	ittenham
SITE NAME: DESIGNATION:	Settlement site south east of church, Appleford-on Scheduled Monument	-Thames / Long Wi	ittenham 1004849
	·	J	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004849

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1181905

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / VALE OF WHITE HORSE / WEST BERKSHIRE (UA) / WEST OXFORDSHIRE

SITE NAME: Two round barrows 520m and 550m north of Lower Chance Farm, Blewbury				
	Two round barrows 520m and 550m north of Lower Chance Farm, Blewbury			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018716				
CONDITION: Generally unsatisfactory with major localised TREND: Declining				
PRINCIPAL VULNERABILITY: Animal burrowing - Badger - moderate NEW ENTRY?: No				
OWNER TYPE: Commercial company CONTACT: Alison McOuaid 0207 973	3646			
OWNER TYPE: Commercial company CONTACT: Alison McQuaid 0207 973				
SITE NAME: Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge				
SITE NAME: Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge				
SITE NAME: Yew Down round barrow 950m south west of Butterbush Reservoir, Lockinge DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018719				

WEST BERKSHIRE (UA) / VALE OF WHITE HORSE

SITE NAME:	Two bowl barrows 500m north east of Stancombe Farm, Lambourn / Letcombe Bassett			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012349	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	

WEST OXFORDSHIRE

©

	SITE NAME:	Church of St Nicholas, Kiddington Park, Kiddington with Asterleigh	A mostly C14 church with a C12 core, restored 1879 with addition of vestry. Constructed of coursed limestone rubble with stone slates to chancel. Roofs have been
	DESIGNATION:	Listed Place of Worship grade II*, RPG grade II	repaired under the National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship scheme, however there remains outstanding repair works
	CONDITION:	Poor	elsewhere in the building.
Fat the pl	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1198490	Contact: Rachel James 0207 973 3153

SITE NAME:	Waterman's Lodge bowl barrow, one of a pair Forest, Cornbury and Wychwood	of Bronze Age barrows	s on the western edge of Wychwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011221
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
	Pair of bowl barrows immediately south of Blindwell Wood, Crawley		
SITE NAME:	Pair of bowl barrows immediately south of Blir	ndwell Wood, Crawley	
SITE NAME: DESIGNATION:	Pair of bowl barrows immediately south of Blir Scheduled Monument	INTERNET INTRY NUMBER:	1015212
			1015212 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WEST OXFORDSHIRE / PORTSMOUTH, CITY OF (UA)

SITE NAME:	Linear earthworks east of Callow Hill Roman vil Glympton / Stonesfield / Wootton	la forming part of the	north Oxfordshire Grim's Ditch,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014751	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	145m section of the north Oxfordshire Grim's Ditch situated 200m west of Grimsdyke Farm, Kiddingtor with Asterleigh			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012905	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Medieval settlement and church of Asterleigh, Kiddington with Asterleigh			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020966	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Pump Copse earthwork, Kiddington with Asterl	eigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003242	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Rectangular enclosures 1100yds (1010m) north	west of Mount Owen	Farm, Lew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006348	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

PORTSMOUTH, CITY OF (UA)



SITE NAME: Fort Purbrook, Portsdown Hill Road, Portsmouth DESIGNATION: Listed Building grade II*, SM CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority in 2021/22. LIST ENTRY NUMBER: 1387127

Fort c1860 by Captain William Crossman of the Royal Engineers. It is one of a series of forts built for the defence of Portsmouth against landward attacks in the 1860s, and known as Palmerston's Follies as they were never used defensively. The fort is owned by Portsmouth City Council, and leased to a charitable trust as an outdoor activities centre. Problems related to the drainage of the ramparts and the maintenance of the moat's retaining walls put it at risk. Historic England has grant aided a conservation management plan and urgent repairs are due to commence

Contact: Rachel James 0207 973 3153

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

WHS

- CA
- LB LPA
- NP
- Conservation Area Listed Building Local Planning Authority National Park RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / PORTSMOUTH, CITY OF (UA)

1 Idenandun Hild Hild Barris	SITE NAME:	Hilsea Lines - Centre Bastion (excluding casemates referred to as Bastion 4), East Centre Curtain (Railway) west side (formerly known as Bastion no. 5), Hilsea	Earthwork defence dating from 1858-1869, with batterie magazines and barracks. The central section of the site, comprising three quarters of the Centre Bastion, and the west side of East Centre Curtain, where the railway ente Portsea Island (all formerly referred to broadly as Bastior no. 5) are continuing to suffer from heritage crime, a lack
	DESIGNATION:	Scheduled Monument, part in CA	regular maintenance largely and very limited access to the site. A Historic England grant has been used to explore repair strategies, mothballing, and re-purposing.
	CONDITION:	Poor	
Historic England	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1001861	Contact: Rachel James 0207 973 3153
	SITE NAME:	Former Royal Naval Academy (Buildings 1/14 and 1/116-9), HM Naval Base, Portsmouth	One of the oldest structures in the Dockyard, this buildir is a Georgian forerunner of the Britannia Royal Naval College at Dartmouth. This building has long been vacant
	DESIGNATION:	Listed Building grade II*, CA	Natural ventilation and background heating has been introduced and furnishings removed, reducing damp leve
	CONDITION:	Poor	Remedial works to roof coverings and parapet gutters h
	OCCUPANCY:	Vacant/not in use	reduced water ingress and the dry rot appears to be dyi back. The cupola has been repainted. Asbestos has bee
	PRIORITY CATEGORY:	C (A)	found in the roof and must be removed before full surve can be undertaken.
	OWNER TYPE:	Government or agency	
listoric England Archive	LIST ENTRY NUMBER:	1244573	Contact: Louise Forsyth 020 7973 3220
		Fort Widley, Portsmouth	A Royal Commission Fort c1860, intended to protect Portsmouth from attack from the rear. It is laid out in a
A day and the state	DESIGNATION:	Scheduled Monument, 2 LBs	massive polygonal trace plan, designed by Captain Willia Crossman of the Royal Engineers, surrounded on three
and the second sec	CONDITION:	Poor	sides by a dry moat with scarp and counterscarp in red
	OCCUPANCY:	Part occupied/part in use	brick with flint facings. There is a red brick barrack block the elevation facing the road. Like the adjacent Fort
	PRIORITY CATEGORY:	C (C)	Purbrook, Fort Widley is owned by Portsmouth City Council and leased to a charitable trust. Maintenance iss
Wen the .	OWNER TYPE:	Local authority	are now becoming repair problems. Historic England is
listoric England	LIST ENTRY NUMBER:	1001862	working with all parties to address these. Contact: Rachel James 0207 973 3153
	SITE NAME:	Horse Sand Fort, Solent	Horse Sand Fort is a circular 19th century Royal
	DESIGNATION:	Scheduled Monument	Commission sea fort lying in the Solent 3.6km south eas Southsea Castle. Horse Sand Fort was one of a chain of
Å	CONDITION:	Poor	four sea forts in the Solent recommended by the Royal
	OCCUPANCY:	Vacant/not in use	Commission on the Defence of the United Kingdom in 1860 and designed to protect Portsmouth dockyard fro
and a shore have been been a	PRIORITY CATEGORY:	C (C)	seaborne attack. The Fort also was armed during both
	OWNER TYPE:	Commercial company	World Wars. The Fort provides a visual reminder of the strategic importance of the Solent in the late 19th to ear
	LIST ENTRY NUMBER:	1018588	20th century. The Fort currently has no sustainable use aside from occasional visitor tours.
listoric England		1010000	Contact: Rebecca Lambert 0207 973 3630
	SITE NAME:	No.5 and No.6 Dock, Basin No.1, Portsmouth Dockyard	Docks 5 and 6 are part of a complex of late C18 and ea C19 ship building and repairing docks with associated q
	DESIGNATION:	Scheduled Monument and Listed Building grade I, part in CA	walls and mooring fixtures. The docks have stepped side with flights of steps and haulage slides; some retain later metal gates. Dock 6 is suffering from rotation, and mort
15 - Charles	CONDITION:	Poor	joints on the stonework treads on the north side have opened up; it is also vulnerable to water penetration act
	OCCUPANCY:	N/A	and the stonework is spalling. Dock 5 has recently been
	PRIORITY CATEGORY:	C (C)	flooded due to failure of the gates and is vulnerable to al growth and saturation of stonework with risk of
	OWNER TYPE:	Government or agency	accelerated decay.
Defence Estates	LIST ENTRY NUMBER:	1001852 and 1272267	Contact: lain Bright 0207 9733 739
IORITY CATEGORIES			ABBREVIATIONS
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric;	 D Slow decay; solution not yet implemented E Under repair or in fa repair, but no user in under threat of vaca 	d. (where applicable) end use o nir to good user identified; or functionally dentified; or redundant buildings with new	nd NOTE CA Conservation Area or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority v use New Entry is noted). NP National Park

- solution agreed but not yet implemented. C Slow decay; no solution agreed.
- obvious new user (applicable only to buildings capable of beneficial use).
- SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

185

HEF

HERITAGE AT RISK 2021 / LONDO	on and south east	/ PORTSMOUTH, CITY OF (UA)	
	SITE NAME:	Fort Cumberland, Fort Cumberland Road, Eastney	Coastal fort of 1746-1812 with later buildings and features. The casemates are suffering from water ingress and
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, 3 LBs	associated decay. In addition, there is localised deterioration of the Fort's defences, particularly the curtain and counterscarp. A programme of works to address some
A STOC	CONDITION:	Poor	of the most urgent issues has been completed and the causes of water ingress into the casemates are being
	OCCUPANCY:	Part occupied/part in use	investigated. With local partners, Historic England is
The second second	PRIORITY CATEGORY:	C (C)	considering options for the sustainable re-use of the vacant parts of the site, both in the long and short-term.
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1015700 and 1104273	Contact: Clare Charlesworth 0207 973 3640
	SITE NAME:	No. 25 Store, Yard Services Manager's Office, 1/118, Jago Road, HM Naval Base, Portsmouth	Two storey storehouse of 1782, with internal courtyard. In poor condition and vacant. Some evidence of water ingress and pigeon infestation. Some remedial works have been completed and further roof works are planned for this
	DESIGNATION:	Listed Building grade II*, CA	financial year. The Ministry of Defence is in discussion with a potential user of the building, to take occupation once
	CONDITION:	Fair	repairs are complete.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (C)	
© Historic England	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1244578	Contact: Louise Forsyth 020 7973 3220
	SITE NAME:	The Beneficial School, Kent Street, Portsea	Charity school of 1784 and 1836, now in use as a dance- drama school/theatre by the Groundlings Theatre Trust.
	DESIGNATION:	Listed Building grade II*, CA	An updated condition survey has been completed which has identified problems including with the roof structure
	CONDITION:	Poor	and windows. The governance of the building needs to be rationalised, so that a comprehensive funding package for
	OCCUPANCY:	Occupied/in use	the necessary repairs can be sought. Historic England, the
	PRIORITY CATEGORY:	C (C)	Theatres Trust and Groundlings have had positive meetings about the way forward. Repairs to some of the front
	OWNER TYPE:	Private	elevation windows have been successfully completed with the aid of a Covid 19 Emergency grant.
© Historic England	LIST ENTRY NUMBER:	1271859	Contact: Louise Forsyth 020 7973 3220
	SITE NAME:	Wymering Manor, Old Wymering Lane, Cosham	Manor house with medieval fabric and later work. Acquired by a Trust in 2013. A condition survey and an
	DESIGNATION:	Listed Building grade II*, CA	investigation into options for future sustainable uses have been completed with grant aid from Historic England and
	CONDITION:	Fair	the Architectural Heritage Fund. The house is in need of some structural repair, general renovation and a new use.
	OCCUPANCY:	Part occupied/part in use	some serveter an opan, general renovation and a new use.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1245180	Contact: Alison McQuaid 0207 973 3646
KR			
	SITE NAME:	2-8, The Parade, HM Naval Base, Portsmouth	Terrace of dockyard officers' lodgings, 1715-19. Partially converted to office use c1995, but now empty. Prone to wet rot and some structural movement. Structural and
	DESIGNATION:	Listed Building grade II*, CA	drainage problems persist between the main building and
	CONDITION:	Fair	the rear extensions. There is extensive decay in panelling and some plaster ceilings have collapsed. An extensive
	OCCUPANCY:	Vacant/not in use	programme of repair is underway and the roof has been reslated and the gutters re-lined with lead. Render and
	PRIORITY CATEGORY:	F (A)	window joinery repairs are also underway as well as the
	OWNER TYPE:	Government or agency	repair of the timber porches. Further works to the rear extensions are planned.

© Historic England

CONDITION:Fairthe rear extensions. There is extensive decay in panel and some plaster ceilings have collapsed. An extensive programme of repair is underway and the roof has b reslated and the gutters re-lined with lead. Render a window joinery repairs are also underway as well as repair of the timber porches. Further works to the re extensions are planned.UST ENTRY NUMBER:1272307Contact: Louise Forsyth 020 7973 3220		DESIGNATION:	Listed Building grade II*, CA	drainage problems persist between the main building
OCCUPANCY: Vacant/not in use programme of repair is underway and the roof has b PRIORITY CATEGORY: F (A) reslated and the gutters re-lined with lead. Render a OWNER TYPE: Government or agency repair of the timber porches. Further works to the restensions are planned.		CONDITION:	Fair	the rear extensions. There is extensive decay in pane
PRIORITY CATEGORY: F (A) OWNER TYPE: Government or agency LIST ENTRY NUMBER: 1272307	1	OCCUPANCY:	Vacant/not in use	programme of repair is underway and the roof has b
extensions are planned.		PRIORITY CATEGORY:	F (A)	
		OWNER TYPE:	Government or agency	
		LIST ENTRY NUMBER:	1272307	I

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	1	
and	1	11
		1-1-
0		-

© Historic England

SITE NAME:	Iron and Brass Foundry, 1/140, Victoria Road, HM Naval Base, Portsmouth	Iron foundry and smithery built 1857-1861, by Col GT Greene RE and Andrew Murray, Chief Engineer; extended 1878, with later alterations. The main part of the building
DESIGNATION:	Listed Building grade II*, CA	was converted to office use in 2003. The east wing (Building 1/136) remains unused and at risk. There were
CONDITION:	Fair	concerns over drainage and regular flooding of the building but this has been resolved. Roof repairs are due to be
OCCUPANCY:	Part occupied/part in use	undertaken in 2021/22.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1272310	Contact: Louise Forsyth 020 7973 3220

H MA	SITE NAME:	Church of St Mary, Fratton Road, Kingston	Church designed by Sir Arthur Blomfield and built of flint and Bath stone with plain tile roofs between 1887-9. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	church has received significant grant aid from Historic England and the National Lottery Heritage Fund in three phases and this has dealt with some of the roofs and tower.
	CONDITION:	Poor	Recent repairs to the building fabric have been carried of in connection with the Organ Project but further repairs
	PRIORITY CATEGORY:	C (C)	are required including to the roofs, south clerestory and
	OWNER TYPE:	Religious organisation	chancel windows.
	LIST ENTRY NUMBER:	1104279	Contact: Robert Williams 0207 973 3641
© Historic England			

4	1 mar	-	53	
Z	5-3	Å		
	1	-		
				100

1	SITE NAME:	Church of St Luke, Greetham Street, Portsmouth	Neo-Norman church by Thomas Hellyer of Ryde. Dated 1858-61. Built of flint and stone with a Welsh slate roof. At	
	DESIGNATION:	Listed Place of Worship grade II	risk due to extensive damp problems caused by water ingress resulting mainly from faulty and undersized	
	CONDITION:	Poor	rainwater goods. Cementitious repointing worsens the damp problems. Ambitious plans for redevelopment which	
	PRIORITY CATEGORY:	C (C)	will hopefully also address the outstanding repair issues.	
	OWNER TYPE:	Religious organisation		
1	LIST ENTRY NUMBER:	1104307	Contact: Robert Williams 0207 973 3641	

© Historic England

A TH	SITE NAME:	Church of St Cuthbert, Hayling Avenue, Portsmouth	1914-15. By E Stanley Hall. The original east end apse was destroyed by bombing, and the present east end wall is a
	DESIGNATION:	Listed Place of Worship grade II	post-war reconstruction. This has been remodelled in the last 10 years to provide community facilities and the
ALL AND	CONDITION:	Poor	present church sits in the western two bays of the former nave of the church only. The roofs over the worship space
and E all the	PRIORITY CATEGORY:	D (D)	and the bell tower are in poor condition. A National
	OWNER TYPE:	Religious organisation	Lottery Heritage Fund Grants for Places of Worship scheme grant was used to develop the project, but funding
	LIST ENTRY NUMBER:	1333225	for repairs has yet to be found.
			Contact: Robert Williams 0207 973 3641

© Historic England

READING (UA)



Е

SITE NAME:	Remains of Reading Abbey: a Cluniac and Benedictine monastery	
DESIGNATION:	Scheduled Monument, 14 LBs, part in RPG grade II, part in CA	
CONDITION:	Fair	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority, multiple owners	
LIST ENTRY NUMBER:	1007932	

Substantial standing remains of abbey established by Henry I in 1121. The National Lottery Heritage Fund grant-aided works to the ruins and gatehouse and these were completed and the ruins opened to the public in June 2018. A Historic England grant to Reading Borough Council to repair the refectory wall was also completed. A Historic England development grant to St James's church for the elements of the abbey ruins in their ownership was completed in 2019. The mill arch, in private ownership, is still in need of consolidation.

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site


HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / READING (UA) / SOUTHAMPTON, CITY OF (UA)

	SITE NAME:	Chazey Farm barn, The Warren, Reading	A very large seven bay red brick barn C17 or earlier. There is structural cracking and the gable currently has temporary
	DESIGNATION:	Listed Building grade I	shoring. The building forms part of a larger site proposal for a healthcare development. Ground works for the new
	CONDITION:	Very bad	development commenced in spring 2010. Following close working between the leaseholder, Local Planning Authority
	OCCUPANCY:	Vacant/not in use	and Historic England urgent work to prevent any further decay of the building commenced in 2020. Work will then
	PRIORITY CATEGORY:	B (B)	be required to restore the barn and find a viable use for it.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1113603	Contact: Rachel James 0207 973 3153

SITE NAME:	Russell Street / Castle Hill		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Mark Worringham 07855 126084

SOUTHAMPTON, CITY OF (UA)

listoric England	SITE NAME:	Former Chapel Mills, American Wharf, Elm Street, Southampton	Rare survival of former steam mill, 1781 and 1800, built to produce ship's biscuits for the Navy. Built of brick with mainly concrete tiled roofs. Now partly used as a sail loft
	DESIGNATION:	Listed Building grade II*	and part vacant, suffering from a backlog of maintenance Emergency repairs carried out and Planning Permission
	CONDITION:	Very bad	granted for repair and residential conversion but repairs to building not yet implemented.
	OCCUPANCY:	Part occupied/part in use	balang not yet implemented.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company, multiple owners	
	LIST ENTRY NUMBER:	1091968	Contact: Robert Williams 0207 973 3641





SITE NAME: St Denys Church, St Denys Road, St Denys DESIGNATION: Listed Place of Worship grade CONDITION: Poor PRIORITY CATEGORY: C (C)		Church designed by Sir George Gilbert Scott in 1868 and built of brick. At risk due to falls of ceiling plaster internally.	
	DESIGNATION:	Listed Place of Worship grade II	Historic England/National Lottery Heritage Fund grant- aided repairs to rainwater goods, east and west windows,
	CONDITION:	Poor	bell turret stonework and some areas of ceilings completed. A further phase of repairs is required.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1179120	Contact: Robert Williams 0207 973 3641

© Historic England

© His

SITE NAME:	Old Town North		
DESIGNATION:	Conservation Area, 15 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jon Willetts 023 8083 2479

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

LPA

Conservation Area Listed Building Local Planning Authority National Park NP RPG

- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

SURREY

© Histor

ELMBRIDGE

bric England Archive	SITE NAME:	Brooklands Motor Racing Circuit	The world's first purpose-built motor racing circuit, constructed in concrete in 1907. It was in use until 1939
	DESIGNATION:	Scheduled Monument and Listed Building grade II, part in CA	when aircraft production buildings took over part of the circuit. Historic England funded a Conservation Management Plan for the entire site which identified
	CONDITION:	Poor	various parts of the track to be at risk. Historic England is now working with owners and interested parties to ensure
	OCCUPANCY:	N/A	the necessary works take place and significant progress being made in reducing the risks to the track. However further action is required.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1020137 and 1272444	Contact: Iain Bright 0207 9733 739



A NAME	SITE NAME:	The Belvedere, Claremont Park, Esher	1717 by Sir John Vanbrugh. In need of repair to bring it
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I	back into use as a focal point of the Grade I Registered landscape of Claremont Park. A commitment to improving the immediate landscape surrounding the Belvedere was
	CONDITION:	Fair	sought as part of a planning application made by Claremont Fan Court School for long term development. Some of the
	OCCUPANCY:	Vacant/not in use	improvements have been implemented.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1005931 and 1030204	Contact: Alma Howell 0207 9733 627

© Historic England



SITE NAME:	Former kitchen garden walls to Claremont House, Claremont Park Road, Esher	Nationally significant garden walls of 1717 by Vanbrugh. Suffering from vegetation growth in wall tops, mortar loss and in need of general repair. Investigations for possible
DESIGNATION:	Listed Building grade II*, RPG grade I	repair techniques and materials completed with one of the owners. Some repairs have taken place as an exemplar but more are needed. A full survey of the walls is being
CONDITION:	Poor	undertaken to understand the overall condition and the extent and cost of repairs needed.
OCCUPANCY:	N/A	extent and cost of repairs needed.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1377465	Contact: David John 0207 973 3638

© Historic England

DESIGNATION: Conservation Area, 5 LBs, part in SM	NEW ENTRY?: No	
	INU	
CONDITION: Poor	TREND: Impr	roving
VULNERABILITY: Low	CONTACT: Jon I	Kilner 01372 474824

EPSOM AND EWELL

SITE NAME:	Epsom Town Centre, Epsom		
DESIGNATION:	Conservation Area, 39 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Anthony Evans (LPA) 01372 732394
SITE NAME:	Ewell Village		
SITE NAME: DESIGNATION:	Ewell Village Conservation Area, 77 LBs, 2 SMs	NEW ENTRY?:	No
	5	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 77 LBs, 2 SMs		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / EPSOM AND EWELL / GUILDFORD / MOLE VALLEY

SITE NAME:	Horton, Epsom		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Anthony Evans (LPA) 01372 732394

GUILDFORD

	SITE NAME:	West Horsley Place, Epsom Road, West Horsley	Country house, C15 timber-framed hall and domestic wing, refronted in brick in the C17 with C18 alterations
	DESIGNATION:	Listed Building grade I	and internal features. The house has suffered from defer of maintenance under private ownership and now stand
	CONDITION:	Poor	need of a major renovation of the frame, brickwork and roof as well as all decorative finishes. A recently created
	OCCUPANCY:	Part occupied/part in use	Trust has taken on the building which is now being used conjunction with Grange Park Opera, operating from th grounds. Further uses being explored. Immediate struct
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	remediations have been addressed and a phased programme of repairs is in progress.
© Historic England	LIST ENTRY NUMBER:	88949	Contact: Alma Howell 0207 9733 627



	SITE NAME:	Church of St Luke, Burpham Lane, Burpham	Church designed by Henry Woodyer in 1859. Built of Bargate stone with tiled roofs. At risk due to defective roof
	DESIGNATION:	Listed Place of Worship grade II	tiling and rainwater disposal goods.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1029301	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Clandon Park, West Clandon	Gardens and pleasure grounds within a landscaped park by
	DESIGNATION:	Registered Park and Garden grade II, 8 LBs, part in CA	Lancelot Brown. Gutted by fire in 2015 the house and garden are owned by the National Trust while the park is privately owned. Management without a plan for guidance
	CONDITION:	Extensive significant problems	has lead to lack of suitable conservation priorities around
	VULNERABILITY:	High	the park, damaging its overall integrity and its character further vulnerable to development proposals. With
	TREND:	Declining	separate plans drawn up for restoration in the house an garden, and management of the park, a coordinated approach to park use and appropriate management is needed to secure this landscape's future.
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	needed to secure unis nandscape's luture.
	LIST ENTRY NUMBER:	1001171	Contact: Kay Richardson 0207 973 3647

MOLE VALLEY

© Historic England



Lime kilns at Betchworth SITE NAME: Quarry, Betchworth DESIGNATION: Scheduled Monument, 3 LBs CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) Commercial company, multiple OWNER TYPE: owners LIST ENTRY NUMBER: 1021346

An important group of C19 and C20 brick built lime kilns. Three of the structures (the Dietsch, remains of the six Flare kilns and remaining Hoffman kiln) are at risk due to a longstanding lack of regular maintenance. A condition survey of the structures has been completed and estimated cost of the repairs produced. Sources of funds to implement the repairs now need to be identified.

Contact: lain Bright 0207 9733 739

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MOLE VALLEY

With the second se	SITE NAME:	Brockham Lime Kilns, Brockham	The site includes a disused eastern battery of eight kilns and a western battery of two. The eastern battery, originally
	DESIGNATION:	Scheduled Monument and Listed Building grade II	built in 1870, comprises four pairs of linked flare kilns. The northern two pairs were modified to the Brockham patent, as was the western battery. Now also an important bat
	CONDITION:	Very bad	habitat. Parts of the kilns remain in a very bad condition and supported by scaffold. Funds need to be raised which will allow the identified repairs to take place and improve interpretation for visitors.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1021322 and 1230730	Contact: David John 0207 973 3638

Ø Historic England	SITE NAME:	Ruins of Betchworth Castle, Reigate Road, Brockham	Late C17 ruined house built on site of medieval castle. Consolidation works to ruins completed 2013. A section of
	DESIGNATION:	Scheduled Monument and Listed Building grade II	the terrace retaining wall was rebuilt in 2014, but a long section of the terrace is still held up only by tree roots and temporary geotextile fabric shoring. This will fail once the
	CONDITION:	Fair	tree roots rot or if strong winds blow over any of the trees
	OCCUPANCY:	N/A	on the terrace edge. This and on-going management/ maintenance needs to be addressed before the monument
	PRIORITY CATEGORY:	F (F)	can be removed from the Register. The owner is trying secure funding to assure the long term future of the ruir
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017996 and 1378073	Contact: David John 0207 973 3638

	SITE NAME:	Church of St John the Baptist, Church Lane, Okewood Hill, Abinger	Church dating from C13, virtually doubled in size in 1879 by the architect Basil Champneys. Rendered rubble stone walls with slab roofs and shingled spire to low timber
	DESIGNATION:	Listed Place of Worship grade II*	tower. At risk due to defective rainwater goods and roofs. A phase of repairs has been completed under the National
	CONDITION:	Poor	Lottery Heritage Fund Grants for Places of Worship scheme, however further repairs are required and funds
	PRIORITY CATEGORY:	C (C)	are needed for these.
Array Constant	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1028844	Contact: David John 0207 973 3638
© Historic England			

SITE NAME:	Anstiebury Camp: a large multivallate hillfort sout	Anstiebury Camp: a large multivallate hillfort south east of Crockers Farm, Capel				
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1007891			
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining			
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No			
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646			
SITE NAME:	Bell barrow in Deerleap Wood, Wotton					
SITE NAME: DESIGNATION:	Bell barrow in Deerleap Wood, Wotton Scheduled Monument	LIST ENTRY NUMBER:	1007878			
	• ·	LIST ENTRY NUMBER:	1007878 Declining			
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised					
DESIGNATION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems	TREND:	Declining			

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

191

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / MOLE VALLEY / REIGATE AND BANSTEAD / RUNNYMEDE / SPELTHORNE

Ø Historic England	SITE NAME:	Ashtead Park, Ashtead	A C17 park, developed with successive owners throughout
	DESIGNATION:	Registered Park and Garden grade II, 20 LBs, part in SM, part in CA	the C18 and C19 the well wooded open parkland estate was broken up and sold in the 1920s with the historic landscape split into two principle ownerships, the house, gardens and southern park a school, and the northern park
	CONDITION:	Generally satisfactory but with significant localised problems	with ponds managed as open access land now a nature reserve. The school has improved its management of the landscape amongst proposals for further facilities following
	VULNERABILITY:	Medium	a Conservation Management Plan since 2010. A joint heritage-led approach should support the park's historic character and balance its cultural services .
	TREND:	Improving	
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001490	Contact: Kay Richardson 0207 973 3647

REIGATE AND BANSTEAD

	SITE NAME:	Alderstead (Merstham) Fort, Shepherd's Hill, Reigate	C19 mobilisation centre, one of 13 constructed on the North Downs for the defence of London. The scheduling
	DESIGNATION:	Scheduled Monument	comprises the infantry fort and detached tool store. Tree growth and poor drainage are causing problems and the fort has no current use or management. Discussions need
	CONDITION:	Poor	fort has no current use or management. Discussions need to take place with the owners to agree a project to enable
	OCCUPANCY:	Vacant/not in use	the site to be conserved and maintained.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1018073	Contact: Iain Bright 0207 9733 739

RUNNYMEDE

-			
© Historic England	SITE NAME:	Woburn Farm, Addlestone	An Arcadian 'ferme ornée' designed by Philip Southcote
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs	from 1734-5, highly influential in the history of garden design but rather ephemeral in nature. Now in divided ownership and varying uses very little of the landscape laid
	CONDITION:	Extensive significant problems	out by Southcote remains today apart from the wooded banks of the Bourne stream that was part of Southcote's
	VULNERABILITY:	High	circuit around the farm. Isolated parkland architecture
	TREND:	Declining	features sit within highly frangmented settings. With such high levels of loss of historic design intention and character
	NEW ENTRY?:	No	the overall integrity of the registered area need reassessing.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000342	Contact: Kay Richardson 0207 973 3647

SPELTHORNE

	SITE NAME:	Church of St Mary Magdalene, Squires Bridge Road, Sunbury	A medieval church with an C18 tower. Constructed of ragstone, chalk, conglomerate and brown brick with a clay
	DESIGNATION:	Listed Place of Worship grade I	tiled roof. The tiled roofs are in a poor condition, especially on the north slopes although there is no evidence of water
	CONDITION:	Poor	penetration at the moment. The interior walls have been painted with a non-micro porous paint which is causing
	PRIORITY CATEGORY:	C (C)	decay of the carved stone details.
	OWNER TYPE:	Religious organisation	
TO BALL	LIST ENTRY NUMBER:	1377699	Contact: David John 0207 973 3638

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / TANDRIDGE / WAVERLEY / WOKING

TANDRIDGE

IT A DIAD GE			
	SITE NAME:	Ruins at Bletchingley Castle, Bletchingley	Norman ringwork and bailey, with the remains of a rare stone built Norman house. The ruins were previously
	DESIGNATION:	Scheduled Monument	excavated. Some trees are growing close to the fragile masonry of the house, which is overgrown with vegetation
	CONDITION:	Very bad	and in need of consolidation. The condition of the ruins of the house put the site at risk. It is hoped that a project can
	OCCUPANCY:	N/A	be developed to conserve the ruins.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	1013374	Contact: David John 0207 973 3638

©۲

SITE NAME:		Church of St Mary the Virgin, Church Lane, Oxted	Large church of medieval origins constructed from a mixture of sandstone, Reigate, Kentish rag and ironstone.
	DESIGNATION:	Listed Place of Worship grade I	At risk due to deterioration of the stonework and render. The National Lottery Heritage Fund's Grants for Places of
à an	CONDITION:	Poor	Worship grant-aided repairs to the chancel and aisles completed in 2018 but further repairs, including to the
	PRIORITY CATEGORY:	C (C)	tower, are required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1189608	Contact: David John 0207 973 3638

© Historic England

WAVERLEY

	SITE NAME:	Church of St Peter and St Paul, The Street, Ewhurst	C12 church with nave, C13 transepts, C15 porch. Chancel largely rebuilt 1838 after the central tower collapse. Weald
	DESIGNATION:	Listed Place of Worship grade I, CA	sandstone rubble and dressed sandstone blocks on buttresses. Stone slab roofs with short, wood-shingled broach spire to tower. Cruciform plan. Water ingress
	CONDITION:	Poor	through the roof of the chancel has led to the ceiling plaster falling. National Lottery Heritage Fund Grants for
	PRIORITY CATEGORY:	B (B)	Places of Worship scheme repairs to the chancel, south
	OWNER TYPE:	Religious organisation	transept and south nave slopes were completed in 2019, but the remaining roofs are in urgent need of repair.
	LIST ENTRY NUMBER:	1190455	Contact: David John 0207 973 3638
) Historic England			

SITE NAME:	Four bowl barrows 30m south east of Tilford Barrows: part of The Barrows round barrow cemetery, Tilford			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007883	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

WOKING



© Historic England

SITE NAME:	Brookwood Cemetery, Brookwood
DESIGNATION:	Registered Park and Garden grade I, 18 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001265

A commercial garden cemetery of immense scale founded in 1852 for London's dead, uniquely served by its own railway. Still active with tombs and monuments for many denominations, faiths, nationalities and groups within a picturesque landscape design. C20 military and woodland sections only heighten the site's significance. Acquired by the Local Authority after longstanding lack of overall management. A Conservation Framework was funded by Historic England in 2014 to scope the huge visioning and management task required. Master plan, experience and business plans completed in 2020.

Contact: Kay Richardson 0207 973 3647

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WOKING / WEST BERKSHIRE (UA)

SITE NAME:	Brookwood Cemetery		
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Tom Simpson 01483 743871

WEST BERKSHIRE (UA)			
	SITE NAME:	Former Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton	Former chapel. C12 and later. Structure is generally sound, with main repair programme completed. Planning Permission and Scheduled Monument Consent granted for
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	sympathetic conversion to office use not implemented. The vegetation is being managed. The chapel is part of the adjacent Manor Farmhouse leasehold demise.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
D Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1005378 and 1303413	Contact: Rachel James 0207 973 3153
	SITE NAME:	Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead Marshall	Early C18 brick gate piers and attached walling. Formerly in the gardens of a C17 house which burnt down in 1718. The piers suffer from open joints to the brickwork and capitals and a corroding pintle which has caused the brickwork to bulge. A programme of repairs needs to be agreed with the owners and the works undertaken.
	DESIGNATION:	Listed Building grade II*, RPG grade II	
	CONDITION:	Poor	
∋ Historic England	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1117222	Contact: Rachel James 0207 973 3153
	SITE NAME:	Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall	Gate piers to house which burnt down in 1718. The piers remain in the north west corner of the park. Some of the bricks have eroded; there is vegetation growth to the tops
	DESIGNATION:	Listed Building grade I, RPG grade II	severely cracked stone and fractures through brickwork and a shell niche. A programme of repairs needs to be agreed and taken forward by the owners.

© Historic England

Contact: Rachel James 0207 973 3153

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Poor

N/A

C (C)

Private

1136042

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

A man	SITE NAME:	Three pairs of gate piers and walls around gardens and terrace at Home Farm, Park Lane, Hampstead Marshall	Two late C17 walled gardens (one with raised terrace) and three pairs of gate piers located in the north west corner of the park. Formerly the gardens to the C17 house which burnt down in 1718. Now forming the boundary walls to
Marial Maria	DESIGNATION:	Listed Building grade I, RPG grade II	various private properties. Some sections have open joints. One of the gate piers has vegetation growth to the cornice and there is a large crack in one of the decorative urns,
State State	CONDITION:	Very bad	which puts the significance of the structure at risk. Repairs
WATER PRODUCT	OCCUPANCY:	N/A	to this section need to take place.
	PRIORITY CATEGORY:	C (C)	
listoric England	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1136034	Contact: Rachel James 0207 973 3153
TT NO	SITE NAME:	Church of All Saints, Station Road, East Garston	Church, C12 with C13/C14 work. Central tower, nave, chancel, transepts, south aisle, south porch and a Lady Chapel. Walls are of flint with brick banding and limestone
O ANTA	DESIGNATION:	Listed Place of Worship grade II*	dressings. Roofs with Welsh slate coverings except the
A Park St	CONDITION:	Poor	porch. C19 works to the nave roof, and a west window installed, also work to the Lady Chapel, chancel, the south
	PRIORITY CATEGORY:	C (C)	arcade and windows. The pyramidal Welsh slate roof and
	OWNER TYPE:	Religious organisation	parapet gutters to the tower roof are in need of repair. An application under the National Lottery Heritage Fund
	LIST ENTRY NUMBER:	1321874	Grants for Places of Worship was unsuccessful and these works are still needed.
Historic England			Contact: Rachel James 0207 973 3153
	SITE NAME:	Church of St James, Leckhampstead	Church designed by the architect Samuel Teulon and consecrated in 1860. External walls of flint and brick, and
	DESIGNATION:	Listed Place of Worship grade II*	internal walls of polychrome brick. The steeply pitched plain clay tile roofs were last repaired/renewed in the
	CONDITION:	Very bad	1940s. The clay tiles are delaminating, slipped or missing. Water ingress to the roof structure and roofing battens is
	PRIORITY CATEGORY:	A (A)	occurring. Structural tying to the roof is now needed to
	OWNER TYPE:	Religious organisation	brace the roof due to roof spread. An application for a National Lottery Heritage Fund Grants for Places of
	LIST ENTRY NUMBER:	1313057	Worship was unsuccessful. The church is still fundraising for these roof works.
Historic England			Contact: Rachel James 0207 973 3153
	SITE NAME:	Church of St Gregory, Welford	Church 1852-5 by T Talbot Bury, the Norman tower taken
	DESIGNATION:	Listed Place of Worship grade II*	down and re-built late C19. Flint, with stone dressings and clay plain tiled roofs. Tower, nave, aisles, chancel and south
	CONDITION:	Poor	porch. Four bay nave and aisles, arcade of two centred arches. Three bay chancel with stone vaulted roof, Slipped
	PRIORITY CATEGORY:	C (C)	and deteriorated roof tiles to the nave, aisles and porch in
	OWNER TYPE:	Religious organisation	need of repair to avoid water ingress. An application made to the National Lottery Heritage Fund Grants for Places of
	LIST ENTRY NUMBER:	1117225	Worship scheme in 2017 was unsuccessful and the works continue to be necessary.
Historic England			Contact: Rachel James 0207 973 3153

SITE NAME:	Long barrow on Sheep Down, 1km north of East Ilsley, East Ilsley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013056
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WEST BERKSHIRE (UA)

SITE NAME:	Membury Camp (see also Wiltshire Unitary Autho		ority), Lambourn / F	Ramsbury
DESIGNATION:	Scheduled Monument, SM		LIST ENTRY NUMBER:	1003818
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Woodland management		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Moated site and	three fishponds at Ufton Nervet, l	Jfton Nervet	
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1013176
CONDITION:	Generally satisfac problems	tory but with minor localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Daniel Bashford 07824 103 102
SITE NAME:	Remains of St Jol	hn the Baptist church at Ufton Gre	een Farm, Ufton Ne	ervet
DESIGNATION:	Scheduled Monu	ment, LB grade II	LIST ENTRY NUMBER:	1006967
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
1 H	SITE NAME:	Aldermaston Court, Aldermaston	The remaining portion of Aldermaston Park, a mid-late C19 landscape with remains of C17/C18 pleasure grou and wooded deer park including veteran trees of histor value. Sold into commercial use with an office complex juxtaposed between the house and lake, planning	
A BAR	DESIGNATION:	Registered Park and Garden grade II, 12 LBs, part in CA		
	CONDITION:	Generally unsatisfactory with major localised problems	discussions for a	ins for more offices. Sold in 2014 sustainable long term future for the 19 further loss of historic design integrity
	VULNERABILITY:	High	and establishing a	a conservation management approach to
	TREND:	Declining	the landscape an	d its cultural service are required.
Historic England	NEW ENTRY?:	No		
	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000530	Contact: Kay Ric	hardson 0207 973 3647
	SITE NAME:	Shaw House, Newbury / Shaw	C16 or early C17 garden laid out by the Dolman fam a complex of early C18 water gardens by the Duke of Chandos. Bought by Berkshire County Council in 194 National Lottery Heritage Fund and Historic England in 2005 restored the house as a conference centre ar	
		cum Donnington		
	DESIGNATION:	Registered Park and Garden grade II, 6 LBs, 2 CAs		
	CONDITION:	Extensive significant problems		on which opened to the public in 2008. Th an academy school, fragmented land
A Contraction of the second se	VULNERABILITY:	Medium	management and	poor public realm affects views and
	TREND:	Declining	funded by Histor	onents. A Conservation Management Plan ric England to understand and sustain
and the second se	NEW ENTRY ?:	No	significance and r	manage change is now complete.

© Historic England

Contact: Liz Pollard 0207 973 3650

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

1001446

Local authority, multiple owners

OWNER TYPE:

LIST ENTRY NUMBER:

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

WEST SUSSEX

ADUR

••••			
	SITE NAME:	Church of St Mary De Haura, Church Lane, Shoreham by Sea	Norman church built of Caen stone, containing a tall crossing tower with transepts to north and south, and a
	DESIGNATION:	Listed Place of Worship grade I, CA	large aisled chancel to the east. It is a mixture of Romanesque and Transitional architecture. At risk due to the need for stone, roof and gutter repairs. Some urgent
	CONDITION:	Poor	works have been completed, including stone and mortar repairs to the lower stages of the tower with the benefit of
	PRIORITY CATEGORY:	C (C)	a grant from the Covid-19 Emergency Heriage at Risk
	OWNER TYPE:	Religious organisation	Response Scheme, but further repairs are required.
	LIST ENTRY NUMBER:	1192780	Contact: Robert Williams 0207 973 3641

© Historic England

DESIGNATION: Conservation Area NEW ENTRY?: No CONDITION: Very bad TREND: Improving significantly VULNERABILITY: Medium CONTACT: Colette Blackett (LPA) 01273 263242	SITE NAME:	Southlands		
	DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
VULNERABILITY: Medium CONTACT: Colette Blackett (LPA) 01273 263242	CONDITION:	Very bad	TREND:	Improving significantly
	VULNERABILITY:	Medium	CONTACT:	Colette Blackett (LPA) 01273 263242

ARUN

	SITE NAME:	Blake's Cottage, Blake's Road, Felpham	Thatched brick and flint cottage dating from C17 with later alterations and extensions. It was the home of the poet,
	DESIGNATION:	Listed Building grade II*, CA	artist and visionary William Blake and his wife Catherine from 1800-1803, and where he wrote the words to the
	CONDITION:	Poor	hymn 'Jerusalem'. Purchased by a trust in 2015 since when the building has remained vacant. At risk due to decay and
	OCCUPANCY:	Vacant/not in use	failure of part of the roof structure and thatch, and
	PRIORITY CATEGORY:	C (New entry)	structural problems to the masonry. Now in need of sympathetic repair and maintenance.
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1353792	Contact: Robert Williams 0207 973 3641

© 2021 Google



SITE NAME:	Littlehampton Fort, Littlehampton	C19 fort. The fort is partly covered in ivy which poses the main threat to the structure. Other parts of the fort are
DESIGNATION:	Scheduled Monument	engulfed by sand dunes which have Site of Special Scientific Interest status. A project to remove the ivy from the fort
CONDITION:	Poor	walls and ditches is in progress. This work is being undertaken by a local interest group in partnership with the
OCCUPANCY:	N/A	owner and will help to inform understanding of the risks to
PRIORITY CATEGORY:	A (C)	the monument and guide a long-term strategy for its management.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1005809	Contact: Rebecca Lambert 0207 973 3630

© Historic England Archive



SITE NAME:	Church of St Mary the Virgin, Church Street, Littlehampton	A large imposing geometric red brick church located in the town centre of Littlehampton. Originally constructed in
DESIGNATION:	Listed Place of Worship grade II, CA	1826 by George Draper on the site of a medieval church and then transformed in 1935 by WH Randoll Blacking. It has an impressive galleried interior. The interior of the
CONDITION:	Very bad	tower, aisles and galleries above are in poor condition with water damage, structural problems in the tower, erosion of
PRIORITY CATEGORY:	A (A)	stone around the windows and loss of plaster on walls of
OWNER TYPE:	Religious organisation	the gallery. Further investigations and a comprehensive programme of repairs are now urgently necessary.
LIST ENTRY NUMBER:	1353769	Contact: Robert Williams 0207 973 3641

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CHICHESTER

CHICHESTER

©

a Juni	SITE NAME:	Bell Tower of the Cathedral, Chichester	Grade I listed freestanding bell tower, adjacent to Chichester Cathedral. Circa early C15, probably the work
	DESIGNATION:	Listed Building grade I, CA	of William Wynford who also designed the cloisters, with Perpendicular style openings. The external surfaces of the
	CONDITION:	Very bad	stonework are degrading, and structural movement is evidenced by cracks in the buttresses. The Cathedral
	OCCUPANCY:	Part occupied/part in use	Restoration and Development Trust aspire to see the fabric repaired and new, sustainable uses found for some of
	PRIORITY CATEGORY:	C (C)	tabric repaired and new, sustainable uses found for some of the under-utilised internal spaces.
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1026825	Contact: Robert Williams 0207 973 3641



© Historic England

	SITE NAME:	Former Church of the Assumption, Church Farm Lane, East Wittering	Medieval church, restored 1875-6. Not used for worship for some years. Some repairs have been made but future new uses have not been agreed.	
	DESIGNATION:	Listed Building grade II*		
Internet	CONDITION:	Fair		
ot	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
6	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1354484	Contact: Alma Howell 0207 9733 627	

SITE NAME:	A Romano-Celtic temple, Iron Age shrine and assoc Funtington	ciated remains 250	m north west of Ratham Mill,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018354
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section extending 200yds (180m) east	t from Chapel Lane	e, Funtington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005880
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	YPE: Private c		Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section extending 400yds (370m) wes	t from Chapel Lan	e, Funtington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005881
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / CHICHESTER / HORSHAM

	SITE NAME:	Lavington Park, Duncton / East Lavington, Chichester	Late C18 and C19 garden at the foot of the South Downs on the site of a late C16 house and garden set within a park
A CONTRACT OF A	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	of C18 origin largely planted in the C19 further altered in the C20. The house with extensive panoramic views north is now a school. School and enabling development within
A. C. S. States	CONDITION:	Generally satisfactory but with significant localised problems	the park has led loss of historic character and designed landscape intentions. A heritage led estate plan by the school was discussed with The South Downs NPA in 2017
No Contraction	VULNERABILITY:	Medium	to improve conservation management as the historic and
	TREND:	Stable	aesthetic value of the site is vulnerable to futher planned change and development.
© Historic England	NEW ENTRY?:	No	
	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1001213	Contact: Kay Richardson 0207 973 3647

SITE NAME:	Graylingwell, Chichester, Chichester		
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Improving significantly
VULNERABILITY:	High	CONTACT:	Lone Le Vay (LPA) 01243 534688

HORSHAM

© Historic England

X III Y	SITE NAME:	Ruins of Sedgwick Castle, Moated site, Nuthurst	Ruinous moated medieval castle. The exposed parts of this structure are in a very poor state of repair and continue to
N. N. V.N.	DESIGNATION:	Scheduled Monument, RPG grade II	deteriorate. A conservation strategy has been agreed but needs to be implemented to enable the monument to be conserved and maintained.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
1	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1009579	Contact: Alison McQuaid 0207 973 3646

1 martin	SITE NAME:	Church of St Peter, Station Road, Cowfold	Large medieval village church built of Wealden sandstone with stone roofs. At risk due to defective roofing to the
	DESIGNATION:	Listed Place of Worship grade I, CA	chancel and internal plaster ceilings. Previous Historic England/National Lottery Heritage Fund grant-funded repairs successfully completed but a final phase now required in order to remove the church from the Heritage
	CONDITION:	Poor	required in order to remove the church from the Heritage at Register.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1354161	Contact: Robert Williams 0207 973 3641

© Historic England

2
A
And the second se
No. of Concession, Name
Contraction of the Contraction o
A REAL PROPERTY AND A REAL PROPERTY.
- C. C. S.
a design of the second set of
and the second se
and the second
Contract States (B) - Ventering States of Contraction
AND A DECEMBER OF AND A DECEMBER OF
A DATE OF A DESCRIPTION OF A DESCRIPTION OF A DESCRIPTION
And the second s
Contraction of the second s

	SITE NAME:	Church of St Peter, Upper Beeding	Medieval church built of a mixture of ashlar and rubble stone with areas of flint. The roofs have stone slab on the
CONDITION: Poor PRIORITY CATEGORY: C (C)	DESIGNATION:	Listed Place of Worship grade II*	outer slopes and tiled inner slopes. The church is at risk due to defects to the roofs, rainwater disposal and
	CONDITION:	Poor	stonework. Historic England/National Lottery Heritage Fund grant-aided repairs to the tower and valley gutter,
	PRIORITY CATEGORY:	C (C)	and repairs have been carried out to the chancel roof and
	Religious organisation	gable walls. However further repairs are required to the rainwater drainage and the window behind the organ.	
		1027214	Contact: Robert Williams 0207 973 3641

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / HORSHAM / MID SUSSEX / SOUTH DOWNS (NP)

		. ,	
SITE NAME:	Bowl barrow on Black Hill, Colgate		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011596
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Alfoldean Roman site, Slinfold		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005838
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Billingshurst		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Horsham District Council (LPA)

MID SUSSEX

1	SITE NAME:	Church of Holy Trinity, Church Street, Cuckfield	Church mainly constructed in the CI3 and CI4, comprising nave, chancel, aisles, chapels, vestry, north and south
	DESIGNATION:	Listed Place of Worship grade I, CA	porches, and W tower with shingled broach spire. Walls of sandstone rubble with some areas of rough squared ashlar and render. Significant CI9 painted decorative scheme to
	CONDITION:	Poor	nave and chancel ceilings by Kempe. At risk due to falls high level cementicious pointing and decaying stonewor
	PRIORITY CATEGORY:	D (D)	tower; leaking, corroded and blocked cast iron rainwater
	OWNER TYPE:	Religious organisation	goods and slipping roof slabs,
	LIST ENTRY NUMBER:	1191625	Contact: Robert Williams 0207 973 3641

© Historic England

SITE NAME:	Motte and bailey castle 240m east of Dean's Mill, Lindfield Rural		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011776
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Fairfields, Burgess Hill, Burgess Hill		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Angela Heyward (LPA) 01444 477385

SOUTH DOWNS (NP)

PRIORITY CATEGORIES			ABBREVIATIONS
	LIST ENTRY NUMBER:	1232485	Contact: Alma Howell 0207 9733 627
© Historic England	OWNER TYPE:	Commercial company	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Vacant/not in use	Historic England has provided advice to the owner on addressing these issues.
	CONDITION:	Poor	
	DESIGNATION:	Listed Building grade II*, RPG grade II	is in use, but the chapel remains vacant. Most of the repairs have been completed but lack of maintenance is leading to water penetration and damage of original building fabric.
	SITE NAME:	The chapel at the former King Edward VII Hospital, Easebourne, Chichester	L-shaped former chapel for tuberculosis patients by Charles Holden, 1903-6. Later mortuary wing has been demolished and replaced with a new swimming pool which

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

BREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)



	SITE NAME:	Dam wall to North Park Furnace, Fernhurst / Linchmere, Chichester	The furnace is one of the most complete charcoal fired blast furnaces surviving from the Wealden iron industry but was at risk due to danger of collapse and damage to buried
	DESIGNATION:	Scheduled Monument	archaeology by excessive water flows through sluices. A comprehensive package of private and publicly funded
	CONDITION:	Poor	repairs commenced in May2021 and should be completed by the end of December 2021.
	OCCUPANCY:	N/A	
A STATE	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1021403	Contact: Robert Williams 0207 973 3641

© Historic England



© Historic England Archive

	SITE NAME:	Amberley Limeworks; entrance buildings, Kiln 2 and Office, Houghton Bridge, Amberley / Houghton, Horsham	C19 lime works including kilns and associated buildings. Historic England grant aided repairs to the Locomotive Shed, Blacksmith's Shop and part of the Loading Shed are now complete. However, the ingress of rainwater,
	DESIGNATION:	Scheduled Monument	vegetation growth and decay have led to structural weaknesses to the rest of the Loading Shed, the Southern
	CONDITION:	Poor	Lime Kilns and Kiln No. 2. The De Witt Kilns were added to the Register following the collapse of part of the parapet
	OCCUPANCY:	Part occupied/part in use	wall in 2021. Secured Covid-19 Emergency Heritage at Risk
	PRIORITY CATEGORY:	C (C)	Response funding in 2021.
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1005810	Contact: Robert Williams 0207 973 3641



© Historic England



19Ma	SITE NAME:	Castle Goring, Arundel Road , Worthing	Large house. Built by the poet Shelley's grandfather, Sir Bysshe Shelley, about 1797-8. The house was in very poor
ATT -	DESIGNATION:	Listed Building grade I	condition for many years. In 2013 the house was sold to a private individual who is now using it as a private residence
	CONDITION:	Fair	and wedding/conference venue. Čonsent for change of use was granted and repairs to the roof, stairs and structural
	OCCUPANCY:	Part occupied/part in use	timbers were carried out but further repairs remain
	PRIORITY CATEGORY:	F (F)	necessary, including to the glass dome.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1025839	Contact: Robert Williams 0207 973 3641

ilt in I 380. The pel to the east are in
n is at risk due to spalling vindow, defective roofs and lding repairs were carried
the north aisle. re required, including
e required, including
641
r 1 r

© Historic England

SITE NAME:	Flint mine and a bowl barrow on Church Hill, 400m south west of Findon Place, Findon, Arun				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015238		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

SITE NAME:	Duncton Common round barrow cemetery, Duncton / Petworth, Chichester				
DESIGNATION:	ATION: Scheduled Monument LIST ENTRY NUMBER: [C		1009329		
CONDITION:	ITION: Generally satisfactory but with significant localised TREND: Declir problems		Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	E NAME: Remains of iron works and gun foundry at North Park Furnace, Fernhurst / Linchmere, Chichester				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021403		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Flooding - Local	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Robert Williams 0207 973 3641		
SITE NAME:	Devil's Ditch, section extending 900yds (820m), Ly	e Wood, West Sto	ke, Funtington, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005882		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No		
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Linear boundary on Stoke Down, 800m north of West Stoke House, Funtington, Chichester				
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER:		1018564		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	AL VULNERABILITY: Scrub/tree growth N		No		
WNER TYPE: Private		CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Flint mine on Stoke Down, immediately north of St	oke Clump, Funtin	gton / Lavant, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018563		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow 500m WNW of Barnett's Bridge, Gra	affham, Chichester			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009910		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow on Gallows Hill, 150m east of Millbor	ough House, Graff	ham, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009905		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

SITE NAME:	E NAME: Two bowl barrows on Gallows Hill, 200m east of Millborough House, Graffham, Chichester				
DESIGNATION:	NATION: Scheduled Monument LIST ENTRY NUMBER: 1009906				
CONDITION:	TION: Generally unsatisfactory with major localised TREND: problems		Unknown		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow 350m WNW of Barnett's Bridge, Graffham / Lodsworth, Chichester				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009916		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bexley Bushes earthworks, Lavant, Chichester				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005892		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant, Chich				
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005877		
CONDITION:	N: Generally unsatisfactory with major localised TREM problems		Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	ER TYPE: Local authority		Alison McQuaid 0207 973 3646		
SITE NAME:	Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant, Chichester				
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005878		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow on Gallows Hill, 300m east of Millbo	rough House, Lods	worth, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009908		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow on Fitzhall Rough, 330m ENE of Fitzh Stedham with Iping, Chichester	nall: part of Fitzhall	Rough round barrow cemetery,		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008503		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?: No			
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP) / WORTHING / WINDSOR AND MAIDENHEAD (UA)

SITE NAME:	Motte and bailey castle in Pulborough Park, Pulborough, Horsham				
DESIGNATION:	Scheduled Monument LIST ENTRY N		1BER: 1017547		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No		
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bowl barrow 950m south west of Grey Friars Fa Hill, Storrington and Sullington, Horsham	rm: part of a disperse	ed round barrow cemetery on Kithurs		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015711		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Greatham, Horsham (District), Parham, Horshar	n			
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No		
CONDITION:	Very bad	TREND:	Deteriorating		
VULNERABILITY: Medium		CONTACT:	Michael Scammell (LPA) 01730 814810		

WORTHING



© Historic England

WINDSOR AND MAIDENHEAD (UA)

	SITE NAME:	Royal Mausoleum, The Home Park, Windsor	Mausoleum of Queen Victoria and Prince Albert, 1862-71. Damp problems put external and internal historic fabric at
	DESIGNATION:	Listed Building grade I, 2 RPGs	risk, including internal paintings. Original rainwater drainage was inadequate and poorly designed. Consented
	CONDITION:	Fair	programme of repairs was completed in 2019 to make the exterior weather-tight and prevent moisture from entering
	OCCUPANCY:	N/A	the building via the raised perimeter paving. Since 2009 an
	PRIORITY CATEGORY:	F (F)	environmental monitoring regime confirms high level drying out. Regular monitoring continues. It will be some years
	OWNER TYPE:	Crown	before the building is dry enough to accommodate interior conservation work.
Historic England	LIST ENTRY NUMBER:	778	Contact: Jane Sidell 020 7973 3738

©Н

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

		/ WINDSOR AND MAIDENHEAD (UA) / W	. ,		
	SITE NAME:	Noah's Boathouse, Stonehouse Lane (Off), Cookham	monolithic reinfo	ucas for his father. Constructed of prced concrete with a flat roof. An early	
	DESIGNATION:	Listed Building grade II*	and pioneering example of Modern Movement archite by one of the major figures in the movement. The bui floods regularly and is derelict. The roof is leaking and concrete is spalling. A project to address the issues ne to be agreed.		
THE REAL IN LA	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	A (A)			
	OWNER TYPE:	Private			
© Historic England	LIST ENTRY NUMBER:	1323741	Contact: Rachel Fletcher 0207 973 3846		
	SITE NAME:	The Cock Pitt, 47-49, High Street, Eton	C15 timber framed building, with approvals for conve to residential use retaining commercial units at groun		
	DESIGNATION:	Listed Building grade II*, CA	suffered financial	nmenced on site, but the developer difficulties and as a result work stopped	
	CONDITION:	Poor		ng partially stripped and in deteriorating gent Works Notice to secure the building	
	OCCUPANCY:	Vacant/not in use	was served in 20	20, which was complied with by the	
	PRIORITY CATEGORY:	A (New entry)	owner. The prop	perty is currently for sale.	
	OWNER TYPE:	Commercial company			
© Historic England	LIST ENTRY NUMBER:	1290036	Contact: Rachel	James 0207 973 3153	
SITE NAME:	Beenham's Heath	, Waltham St. Lawrence			
DESIGNATION:	Conservation Are	ea, 8 LBs	NEW ENTRY?:	No	
CONDITION:	Poor		TREND:	No significant change	
VULNERABILITY:	Medium		CONTACT:	Roderick McDonald 07969 504 872	
WOKINGHAM (UA)					
	SITE NAME:	Ruins of St Bartholomews Church (Arborfield), Arborfield and Newland	CI3 and built in t CI8 brick rebuild	arish church, now a roofless ruin. Originally flint and stone, with substantial probable ding. One wall partially standing, with other	
	DESIGNATION:	Scheduled Monument, LB grade II	there is a risk of	r brick segments. Very overgrown and further collapse. A project to see the ruins ined and maintained still needs to be	
Ban-gr I	CONDITION:	Very bad	agreed and imple	emented.	
	OCCUPANCY:	N/A			
Carlo A	PRIORITY CATEGORY:	A (A)			
© Historic England	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1006975	Contact: Rachel	James 0207 973 3153	
	SITE NAME:	Former Infirmary Stables, Arborfield Garrison, Barkham	redundant by vir	rse hospital' built 1911-12. The building is tue of changes in army practices (reduced	
	DESIGNATION:	Scheduled Monument		A sustainable future needs to be found and en. Planning Permission has been granted	
	CONDITION:	Fair	for the developm	nent of Arborfield Garrison and this will	
	OCCUPANCY:	Vacant/not in use	clear asbestos fro	ment to repair the stables. Works to om the site and re- roofing of the stables	
	PRIORITY CATEGORY:	E (E)	with matching ce	ment diamond tiles were carried out in	
	OWNER TYPE:	Commercial company	2017 and have been completed. An end use for the building is being considered and long term management/maintenance agreed.		
© Historic England	LIST ENTRY NUMBER:	1006949			
WI INSTOLIC EUSIAND			Contact: Rachel James 0207 973 3153		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2021 / LONDON AND SOUTH EAST / WOKINGHAM (UA)

OWNER TYPE:

LIST ENTRY NUMBER:

······································						
SITE NAME:	TE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil					
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006965		
CONDITION:	Extensive significant problems		TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No		
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Cropmark comp	blex south west of St Patrick's Aver	nue, Sonning			
DESIGNATION:	Scheduled Monu	iment	LIST ENTRY NUMBER:	1006964		
CONDITION:	Extensive signific	ant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No		
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Cropmark site east of Broadmoor Lane, Sonning					
DESIGNATION:	Scheduled Monu	iment	LIST ENTRY NUMBER:	1006963		
CONDITION:	Generally satisfact problems	ctory but with significant localised	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	3	NEW ENTRY?:	No		
OWNER TYPE:	Educational (stat	e sector)	CONTACT:	Alison McQuaid 0207 973 3646		
and the second of	SITE NAME:	Bearwood College, Arborfield and Newland / Barkham / Winnersh	This C19 landscape park and woodland surrounds Victorian country house on formal terraces overloo picturesque lake with early designs by Gilpin and a Pulhamite garden. Subject to resent alterations wit gardens and pleasure grounds a private school and charitable trust, the wider park a golf course and R FC's training site, the parkland features are varying condition. A Conservation Management Plan and li			
Mo a line have been	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs				
	CONDITION:	Extensive significant problems				
	VULNERABILITY:	High	group agreed fur	ided proposals for tree management and		
The second s	TREND:	Stable		n works in 2018 with Historic England proposals can be progressed.		
© Historic England	NEW ENTRY?:	No				

Mixed, multiple owners

1000414

Contact: Kay Richardson 0207 973 3647

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

This document is one in a series of regional registers produced as part of Historic England's national Heritage at Risk programme. The registers for other regions and previous Heritage at Risk publications can be found at historicengland.org.uk/advice/heritage-at-risk/ registers-and-publications/ More information about Historic England's Heritage at Risk programme can be found at historicengland.org.uk/advice/heritage-at-risk/

Heritage at Risk Published November 2021 4th Floor, Cannon Bridge House 25 Dowgate Hill London EC4R 2YA © Copyright Historic England 2021 Product code: HE0061



London&SouthEast Register 2021