# Heritage at **Risk**



London & South East Register 2023

# Contents

The Register	IV	Hastings	125
Criteria	IV	Lewes Rother	28  28
Key statistics	VII	South Downs (NP)	120
		Wealden	3
Key to the Entries	VIII	Hampshire	133
Entries on the Register by local planning	Х	, Basingstoke and Deane	133
authority		East Hampshire	133
Greater London	I	Eastleigh	133
Barking and Dagenham	I	Fareham	134
Barnet	2	Gosport	134
Bexley	4	Hart	136
Brent	4	Havant	137
Bromley	6	New Forest	137
Camden	11	New Forest (NP)	138
City of London	17	Rushmoor	139
Croydon	17	Test Valley	142
Ealing	20	Winchester	143
Enfield	22	Isle of Wight (UA)	145
Greenwich	26		
Hackney	28	Kent	150
Hammersmith and Fulham	35	Ashford	150
Haringey	38	Canterbury	151
Harrow	41	Dartford	153
Havering	44	Dover	153
Hillingdon	46	Folkestone and Hythe	156
Hounslow	54	Maidstone	158
Islington	59	Sevenoaks	161
Kensington and Chelsea	64	Swale	162
Kingston upon Thames	73	Thanet	164
Lambeth	74	Tonbridge and Malling	165
Lewisham	78	Tunbridge Wells	166
London Legacy (MDC)	82	Kent (off)	167
Merton	83	Medway (UA)	168
Newham	87		
Redbridge	89	Milton Keynes (UA)	171
Richmond upon Thames	91	Oxfordshire	171
Southwark	94	Cherwell	171
Sutton	101	Oxford	173
Tower Hamlets	102	South Oxfordshire	173
Waltham Forest	108	Vale of White Horse	176
Wandsworth		West Oxfordshire	177
Westminster, City of	112	Portsmouth, City of (UA)	178
Bracknell Forest (UA)	116		
Brighton and Hove, City of (UA)	116	Reading (UA)	181
South Downs (NP)	119	Southampton, City of (UA)	182
Buckinghamshire (UA)	120	Surrey	183
East Sussex	124	Elmbridge	183
Eastbourne	124	Epsom and Ewell Guildford	183 184

Mole Valley	184
Reigate and Banstead	186
Runnymede	186
Spelthorne	186
Tandridge	186
Waverley	187
Woking	187
West Berkshire (UA)	188
West Sussex	190
Adur	190
Arun	190
Chichester	9
Horsham	192
Mid Sussex	193
South Downs (NP)	194
Worthing	196
Windsor and Maidenhead (UA)	197
Wokingham (UA)	197

# THE REGISTER

The Heritage at Risk Register includes historic buildings and sites that are at risk of loss through neglect, decay or development, or are vulnerable to becoming so. It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful publications and guidance is available on our <u>website</u>.

# Criteria for inclusion on the Register

# **RISK ASSESSMENTS**

Heritage assets included on the Register are assessed according to the nature of the site. This can be through on-site checks and/or desk-based assessments. The risk assessment methodologies outlined below are based on the different factors which can threaten the different types of heritage assets and lead to them becoming at risk.

# **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be listed on the National Heritage List for England; and in secular (non-worship) use. And be either:

- a grade I or II\* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'partoccupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future.

A few buildings remain on the Register in good condition whilst solutions are being implemented as a reminder of the need for monitoring, and to ensure that repair and re-use are seen through to completion.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

# PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II\* or grade II on the National Heritage List for England and be used as a public place of worship at least six times a year.

The method used to assess whether a place of worship is at risk is essentially the same as that used to assess other historic buildings or structures (as outlined above), with one important difference: the criterion as to whether a building is occupied is not used as by their nature, places of worship are in use. Places of worship will be assessed as at risk and added to the Register if their condition is assessed to be very bad or poor.

It is often the case that only part of a church building, e.g. the tower or one of the aisles, is in very bad or poor condition, and it then becomes a matter of professional judgement whether this puts the whole building at risk. Usually if a major or a very significant element of a church is considered to be at risk then the judgement is made that the whole building is at risk and it is included in the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even to good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

# ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be designated as scheduled monuments on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'. The trend will also be recorded as 'improving', 'stable', 'declining' or 'unknown'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

# PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be designated as grade I, grade II\* or grade II on the National Heritage List for England. Parks and gardens are assessed in terms of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

# BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register. Each battlefield is assessed against four key criteria:

- Landscape readability is it possible to understand the context of the battle?
- Landscape features are hedgerows, walls and trees which had a significant impact on the battle still in place?
- Archaeological integrity is the archaeology of the battle being disturbed?
- Ambiance are activities such as development having a negative impact on the setting of the site?

Current condition, future vulnerability and trend are all taken into account.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

# WRECK SITES

To be considered for inclusion on the Register, wrecks must be designated as protected wreck sites on the National Heritage List for England.

Wreck sites are assessed based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability.

Wrecks are considered to be at risk if there is a significant likelihood of loss or further loss of historical, archaeological or artistic significance from it within the foreseeable future.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern or are believed to no longer be at risk.

Conservation areas that are deteriorating or are in very bad or poor condition and not expected to

change significantly in the next three years are defined as being at risk.

Categories for condition, vulnerability and trend are included for each conservation area on the Heritage at Risk Register.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. Conservation areas identified as at risk in 2009 but not reassessed since using the revised methodology are included on the Register but with limited information.

Conservation area entries are removed from the Register once issues have been identified, plans put in place to address them, and positive progress is being made.

# Key Heritage at Risk Statistics for London & South East 2023

There are 1,053 entries on the HAR Register for 2023 in London & South East, 42 fewer than on the previous Register for 2022.

## **BUILDINGS AND STRUCTURES**

- Of the 22,519 grade I and II\* listed buildings and structures (excluding places of worship) in England, 765 (3.4%) are on the Register. Of the 5,927 listed secular buildings and structures (of grade I and II\*) in London & South East 133 (2.2%) are on the Register.
- Of the 16,782 grade II secular buildings in London 343 (2.0%) are on the Register.
- In addition to this, of the 2,859 scheduled monuments in London & South East, 70 (2.4%) are on the Register assessed as structural scheduled monuments (i.e. using the buildings or structures methodology).
- 39 building or structure entries (of all grades and including structural scheduled monuments) have been removed from the previous London & South East Register (2022) for positive reasons and 12 have been added.

## PLACES OF WORSHIP

- Of the 14,797 listed places of worship (of all grades) in England, 943 (6.4%) are on the Register. Of the 3,087 listed places of worship in London & South East 180 (5.8%) are on the Register.
- 8 places of worship entries have been removed from the previous London & South East Register (2022) for positive reasons and 9 have been added.

## ARCHAEOLOGY

- Of the 19,954 scheduled monuments in England, 1,916 (9.6%) are on the Register assessed as archaeology. Of the 2,859 scheduled monuments in London & South East, 151 (5.3%) are on the Register assessed as archaeology.
- I7 archaeology entries have been removed from the previous London & South East Register (2022) for positive reasons, and 4 have been added.

## PARKS AND GARDENS

- Of the 1,701 registered parks and gardens in England 104 (6.1%) are on the Register. Of the 549 registered parks and gardens in London & South East, 38 (6.9%) are on the Register.
- No parks and gardens entries have been removed for positive reasons and one has been added to the previous London & South East Register (2022).

### BATTLEFIELDS

• Of the 47 registered battlefields in England, 3 (6.4%) are on the Register. None of the seven registered battlefields in London & South East are on the Register.

## WRECK SITES

• Of the 57 protected wreck sites around England's coast, 4 (7.0%) are on the Register. Of the 4 on the Register, 3 are off the coast of Kent in the London & South East region and the other is in the in the Thames Estuary (East of England region).

### **CONSERVATION AREAS**

- Of the 9,907 conservation areas in England, 483 (4.9%) are on the Register. Of the 3,151 conservation areas London & South East 135 (4.3%) are on the Register.
- 2 conservation areas have been removed from the previous London & South East Register (2022) for positive reasons and none have been added.

## HISTORIC ENGLAND FUNDING

• £1.42 million in grant was spent on 23 entries on the London & South East Register during 2022/23. (This figure includes funding for Heritage Action Zones and for Partnership Schemes in Conservation Areas. It does not include regional capacity building grants or funding for High Street Heritage Action Zones.)

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of both buried and structural remains.

# Key to the entries

The Register includes the following risk assessment types:

- Building or structure (for grade I and II\* listed Buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship (for grade I, II\* and II listed buildings)
- Archaeology (for scheduled monuments earthworks and buried archaeology)
- Park and garden (for Registered parks and gardens)
- Battlefield (for Registered battlefields)
- Wreck site (for Protected wreck sites)
- Conservation area (for conservation areas)

(Please note not all assessment types appear in each of the regional registers.)

# ORDER OF ENTRIES

Please refer to the 'Contents' page to see the order that the Planning Authorities are presented in.

Please note that Unitary Authorities are ordered under their own names and may not appear in the same section as the other planning authorities in their ceremonial (or former) county.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

# DESIGNATION/LISTING

The principal designation/listing type is noted for each entry:

- Listed Building (LB) grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\*
   or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Any other listing types that also apply to the site are also noted (e.g. location within a World Heritage Site (WHS); where a LB or SM is sited within a CA or RPG; or where a CA contains many LBs or SMs).

If an entry is dual designated on the National Heritage List for England (i.e. it is both a listed building and a scheduled monument) the two designations will be joined with an 'and' (e.g. 'Scheduled Monument and Listed Building grade I').

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

# CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

# OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use.

Occupancy (or use) is noted as follows:

- vacant (or not in use)
- part occupied (part in use)
- occupied (in use)
- unknown
- not applicable (for structural scheduled monuments)

# VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as 'high', 'medium' or 'low'.

# PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

The priority category for the previous year for the entry is given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

# TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

# OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

# CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

- CA Conservation Area
- HE Historic England
- NLHF National Lottery Heritage Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- PWS Protected Wreck Site
- RB Registered Battlefield
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

# Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON							Г
Barking and Dagenham	4	0		0	0	0	I
Barnet	4	4	-	0	0	0	
Bexley	3	0	0	0	0	0	0
Brent	7	3	0	0	0	0	0
Bromley	18	I	3	I	0	0	l
Camden	16	14	0	0	0	0	0
City of London	0	2	0	0	0	0	0
Croydon	6	5	I	0	0	0	I
Ealing	7	I	2	0	0	0	5
Enfield	11	2	I	4	0	0	2
Greenwich	8	2	0		0	0	3
Hackney	20		0		0	0	2
Hammersmith and Fulham	11	1	0			0	
Haringey	11	5	0			0	5
Harrow	9		5		0	0	0
Havering	8		2			0	1
Hillingdon	30		3			0	9
Hounslow	19		2		0	0	2
Islington	12		0			0	9
	30		0		0	0	
Kensington and Chelsea	4		0			0	3
Kingston upon Thames							
Lambeth	15		0			0	3
Lewisham	17	2	0			0	1
London Legacy (MDC)	4		0			0	2
Merton	13	0	I		0	0	6
Newham	3	0	0			0	0
Redbridge	3	2	0		0	0	3
Richmond upon Thames	4		0			0	I
Southwark	25	4	2		0	0	2
Sutton	5		0			0	I
Tower Hamlets	17	8	I	0		0	5
Waltham Forest	10		0			0	0
Wandsworth	7			0	0	0	0
Westminster, City of		8	0	0	0	0	0
BRACKNELL FOREST (UA)		1					
Bracknell Forest (UA)	0	0	0	2	0	0	0
BRIGHTON AND HOVE, CI	TY OF (UA)	1		1		1	
Brighton and Hove, City of	6	5	0		0	0	5
					-		
SOUTH DOWNS (NP)	-	-	-	-	-		
South Downs (NP)	0	0	0	0	0	0	
BUCKINGHAMSHIRE (UA)					_		
Buckinghamshire (UA)	8	6	8	2	. 0	0	0
EAST SUSSEX		1		1		1	
Eastbourne	5		I	0		0	0
Hastings	5		0			0	I
Lewes	1	0	0			0	0
Rother	4		1	0	0	0	0
South Downs (NP)	2	I	5	0	0	0	0
South Downs (NP) / Brighton and Hove, City of (UA) / Lewes <sup>†</sup>	0	0	0	I	0	0	0
Wealden	4	2	0	1	0	0	0
Wealden / Tunbridge							
Wells <sup>†</sup>	0	0	I	0	0	0	0

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HAMPSHIRE							
West Berkshire (UA) / Basingstoke and Deane <sup>†</sup>	0	0	0	1	0	0	0
Basingstoke and Deane	1	0	0	0	0	0	0
East Hampshire	0	0	I	0	0	0	0
Eastleigh	0	0	I	0	0	0	0
Fareham	2	0	0	0	0	0	0
Gosport	6	0	3	0	0	0	3
Hart	1	0	0	2	0	0	0
Havant	0	I	0	0	0	0	I
New Forest	0	I	5	0	0	0	0
New Forest (NP)	0	I	3	0	0	0	0
Rushmoor	2	I	0	0	0	0	0
South Downs (NP)	1	0	8	0	0	0	5
Test Valley	0	0	8	I	0	0	0
Winchester	0	I	3	0	0	0	8
Portsmouth, City of (UA) / Winchester <sup>†</sup>	1	0	0	0	0	0	0
ISLE OF WIGHT (UA)							
Isle of Wight (UA)	8	9	2	2	0	0	7
KENT							
Ashford	4	0	1	0	0	0	0
Canterbury	5	3	4	0	0	0	0
Dartford	0	0	2	0	0	0	0
Dover	5	4	2	0	0	0	3
Folkestone and Hythe	7	2	4	0	0	0	0
Maidstone	6	3	2	0	0	0	I
Sevenoaks	I	0	I	1	0	0	0
Sevenoaks / Tunbridge Wells <sup>†</sup>	0	0	0	I	0	0	0
Swale	3	4	0	0	0	0	8
Thanet	3	2	4	0	0	0	I
Tonbridge and Malling	0	I	3	0	0	0	0
Tunbridge Wells	2	0	0	0	0	0	1
Tunbridge Wells / Wealden <sup>†</sup>	0	0	I	I	0	0	0
KENT (OFF)	1	1		1			
Kent (off)	0	0	0	0	0	3	0
MEDWAY (UA)	•		1	1			
Medway (UA)	11	1	0	0	0	0	4
MILTON KEYNES (UA)			1	1			
Milton Keynes (UA)	0		3	0	0	0	
OXFORDSHIRE	-	-		-			
Cherwell	2	2	2	0	0	0	2
Oxford	1	2	0				0
South Oxfordshire	3	1	9	0			0
South Oxfordshire / Wokingham (UA) <sup>†</sup>	0	0	0	I	0	0	0
Vale of White Horse	1	1	4	0	0	0	0
West Berkshire (UA) / Vale of White Horse <sup>†</sup>		0	I	0		0	0
West Oxfordshire	0	1	7	0	0	0	0
PORTSMOUTH, CITY OF (U		•	,	0	Ŭ	0	0
Portsmouth, City of (UA)	12	3	0	0	0	0	0
READING (UA)	12		0		0	0	0
				1		1	

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
SOUTHAMPTON, CITY OF	(UA)						
Southampton, City of (UA)	2		0	0	0	0	
SURREY				-		1	
Elmbridge	3	0	0	0	0	0	1
Epsom and Ewell	0	0	0	0	0	0	2
Guildford	I	1	0	1	0	0	0
Mole Valley	3	1	2	1	0	0	0
Reigate and Banstead	I	0	0	0	0	0	0
Runnymede	0	0	0	1	0	0	0
Spelthorne	0	1	0	0	0	0	0
Tandridge	I	1	0	0	0	0	0
Waverley	0	1	1	0	0	0	0
Woking	0	0	0		0	0	
WEST BERKSHIRE (UA)						-	
West Berkshire (UA)	4	2	3	2	0	0	0
WEST SUSSEX		1					
Adur	0	I	0	0	0	0	I
Arun	2	I	0	0	0	0	0
Chichester	2	0	3	I	0	0	
Horsham	2	3	2	0	0	0	I
Mid Sussex	0	I	I	0	0	0	I
South Downs (NP)	3	I	11	0	0	0	
Worthing	0		0	0	0	0	0
WINDSOR AND MAIDENH	EAD (UA)						
Windsor and Maidenhead (UA)	3	0	0	0	0	0	1
WOKINGHAM (UA)							
Wokingham (UA)	2	0	3	I	0	0	0
TOTAL	546	180	151	38	0	3	135

<sup>†</sup> Sites that cross local planning authority boundaries

SITE NAME:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

#### **GREATER LONDON**

#### BARKING AND DAGENHAM

No. Star	SITE NAME:	The Old Vicarage, Crown Street, Dagenham	House, dated 1665, and remodelled in the C19. The building is currently partly occupied and has been at risk of
	DESIGNATION:	Listed Building grade II, CA	vandalism. Planning Permission has been granted for residential conversion into flats. The Local Authority is
	CONDITION:	Poor	awaiting the submission of conditions relating to the consented scheme.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
gland	LIST ENTRY NUMBER:	1064411	Contact: Alex Philpott (LPA) 07925 357065

© Historic Engl



SITE NAME:	The Marks Stones, Whalebone Lane North, Chadwell Heath	Boundary marker of the Liberty of Havering-atte-Bower, set up in 1642. There are two stones; one inscribed 'Marks
DESIGNATION:	Listed Building grade II	Stone' and one inscribed 'Marks Stone Sept 1642'. One stone is broken and in safekeeping, the other remains in its
CONDITION:	Very bad	original position. The stones are to be repaired by the quarry operators once restoration of the area is complete.
OCCUPANCY:	N/A	A feasibility report, with funding from the National Lottery
PRIORITY CATEGORY:	C (D)	Heritage Fund in 2015, explored the potential of the site. Discussions between the Local Authority, the Crown
OWNER TYPE:	Crown	Estate and Historic England about the site's use and maintenance have not progressed.
LIST ENTRY NUMBER:	1079887	Contact: Alex Philpott (LPA) 07925 357065

© Historic England



© Historic England Archive



SITE NAME:	The Warren Stone, Whalebone Lane North, Chadwell Heath	Boundary stone erected in 1642. The stone marked the boundary of Hainault Forest, along with the Marks Stones
DESIGNATION:	Listed Building grade II	and the Forest Bounds Stone. The stone is in storage at Warren Farm during ongoing quarrying operations. The
CONDITION:	Poor	stone will be reinstated in its original position once quarrying is finished and land levels have been restored. A
OCCUPANCY:	N/A	feasibility report, with funding from the National Lottery
PRIORITY CATEGORY:	C (D)	Heritage Fund in 2015, explored the potential of the site. Discussions between the Local Authority, the Crown
OWNER TYPE:	Crown	Estate and Historic England about the site's use and maintenance have not progressed.
LIST ENTRY NUMBER:	84884	Contact: Alex Philpott (LPA) 07925 357065

The remains of a World War II anti-aircraft battery, with pits for eight guns in two groups of four, with other structures. The buildings are in an isolated spot and have been subject to vandalism. The former quarry is being restored, including the land levels around the gun site, and when complete there will be a five-year aftercare plan. A feasibility report, with funding from the National Lottery Heritage Fund in 2015, explored the potential of the site. Discussions between the Local Authority, the Crown Estate and Historic England about the site's use and maintenance have not progressed.

Contact: Alex Philpott (LPA) 07925 357065

© Historic England

SITE NAME:	Barking Abbey		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1003581
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738

Chadwell Heath anti-aircraft gun site, Whalebone Lane

North (off), Chadwell Heath

Listed Building grade II, CA

Poor

N/A

C (C)

Crown

1079855

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site
- WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BARKING AND DAGENHAM / BARNET

SITE NAME:	Chadwell Heath Anti-Aircraft Gun Site, Marks Gate				
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No		
CONDITION:	Very bad	TREND:	No significant change		
VULNERABILITY:	Medium	CONTACT:	Alex Philpott (LPA) 07925 357065		

#### BARNET

	SITE NAME:	College Farm - main building, Fitzalan Road N3	Stables, teashop and dairy, built in 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy
- t	DESIGNATION:	Listed Building grade II, CA	farm of the Express Dairy Company. The site is owned by the College Farm Trust. The building is in a deteriorating
	CONDITION:	Fair	condition and discussions have failed to progress regarding the future use of the site and necessary repairs.
	OCCUPANCY:	Occupied/in use	the future use of the site and necessary repairs.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
oric England	LIST ENTRY NUMBER:	1359127	Contact: Jonathan Hardy (LPA) 020 8359 4655

© Histori

C.	SITE NAME:	College Farm Dairy, Fitzalan Road N3	Dairy built in 1883 to the design of Frederick Chancellor, with an ornate timber lantern roof and decorative tilework
and the second s	DESIGNATION:	Listed Building grade II, CA	to the interior. The site is owned by the College Farm Trust. The building is in a deteriorating condition and
1-1	CONDITION:	Fair	discussions have failed to progress regarding the future use of the site and necessary repairs.
Annt A	OCCUPANCY:	Vacant/not in use	of the site and necessary repairs.
Str. C	PRIORITY CATEGORY:	C (C)	
The second second	OWNER TYPE:	Charity (heritage)	
land	LIST ENTRY NUMBER:	1064789	Contact: Jonathan Hardy (LPA) 020 8359 4655

© Historic Engla

	1			
	Harly			
	F	-	-	
- 19		- te	1	

SITE NAME:

DESIGNATION:

OCCUPANCY:

OWNER TYPE-

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



© Historic England

	CONDITION:	Fair	failed to progress regarding the future use of the site and necessary repairs.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1359128	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Railway Hotel including sign in front and former off-sales	The Railway Hotel dates from 1931 and was designed by AE Sewell for the brewers, Truman Hanbury Buxton. It is a
		building to west, Station Road, Edgware	large three-storey half-timbered roadhouse, no longer in use as a public house and damaged by a fire in 2016. The
	DESIGNATION:	0	use as a public house and damaged by a fire in 2016. The listing includes the former off-sales building and the gibbet
	DESIGNATION: CONDITION:	Edgware	use as a public house and damaged by a fire in 2016. The

C (C)

Private

1096066

Part occupied/part in use

Silo, Fitzalan Road, College

Listed Building grade II, CA

Farm N3

Contact: Jonathan Hardy (LPA) 020 8359 4655

use of the surrounding site.

Silo built in 1883 to the design of Frederick Chancellor as

part of the Express Dairy Company's pioneering model farm. The site is owned by the College Farm Trust. The

building is in a deteriorating condition and discussions have failed to progress regarding the future use of the site and

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- NP RPG
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Jude, Central Square, Hampstead Garden Suburb NW11	Designed by Sir Edwin Lutyens, St Jude's was consecrated in 1911 with the west end completed in 1935. There are frescoes throughout by Walter Starmer, dating from 19
	DESIGNATION:	Listed Place of Worship grade I, CA	30. The church has damp issues; there is cracking evident internally and some areas of the frescoes are suffering from salt damage. The heating system requires overhauling. The
	CONDITION:	Poor	weathervane was reinstated in 2021 and the lead spire repaired, damaged when the weathervane fell. A Historic
	PRIORITY CATEGORY:	C (C)	England Heritage at Risk grant was awarded for emergency
TC- WERE	OWNER TYPE:	Religious organisation	repointing of open joints in the brick tower at the same time.
Historic England	LIST ENTRY NUMBER:	1294714	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Parish Church of St Mary, Church End, Hendon NW4	St Mary's dates to the mid C13, with a C15 north aisle, C16 north chapel and nave, and south aisle added
	DESIGNATION:	Listed Place of Worship grade II*, CA	alongside existing by Temple Moore in 1915. The font is C12. North chapel glass by Kempe, altar screen by Bodley, and altar hangings by Comper. There are various defects in
	CONDITION:	Poor	the roofs and gutters; structural movement particularly to the south and west; hard renders on the external walls; and
	PRIORITY CATEGORY:	D (C)	issues with drainage at and below ground level. These

© Historic England

Сŀ



© Historic England

OWNER TYPE:	Religious organisation	particularly evident on plasterwork internally, and where			
LIST ENTRY NUMBER:	1359029	water is damaging wall paintings.			
		Contact: Tracey Craig 020 7973 3756			
SITE NAME:	All Saints Church, Durham Road, East Finchley N2	This is a prominent suburban church of high quality designed by JEK and JP Cutts and built in 1892. The chancel			
DESIGNATION:	Listed Place of Worship grade II	with transepts was built in 1911, with parish room on nor side. There is a fine hammer-beam roof over the nave. A			
CONDITION:	Fair	part of a re-ordering by Bruno Hooker in the late 1980s the rood screen was moved to the west end and the			
PRIORITY CATEGORY:	F (F)	adjacent hall (c1935) demolished. The plain tiled roofs			
OWNER TYPE:	Religious organisation	were repaired in 2019, funded by the National Lottery Heritage Fund. The cracking in brick masonry at the east			
LIST ENTRY NUMBER:	1396401	end is still under investigation.			
		Contact: Ian Harper 07974 979620			

issues are having a detrimental effect on the fabric,

	SITE NAME:	Church of All Saints, Oakleigh Road, Friern Barnet N20	Built in 1883, designed by Joseph Clark in Early English style, with tiled pitched roofs and flint faced walling with ashlar
	DESIGNATION:	Listed Place of Worship grade II	dressings. It has a tall tower and stone spire. The structure has suffered from general erosion of stonework and has
	CONDITION:	Poor	extensive cementitious repairs, which are failing. There are areas of bulging and missing flints. Repairs to the spire and
	PRIORITY CATEGORY:	C (C)	tower grant-aided by the National Lottery Heritage Fund
	OWNER TYPE:	Religious organisation	were completed in 2019. Further repairs to roofs and masonry are required, particularly to the west end, the east
	LIST ENTRY NUMBER:	1064881	end vestry and to the south porch.
c England			Contact: Tracey Craig 020 7973 3756

#### © Historic England

SITE NAME:	Brockley Hill Romano-British pottery and settleme	nt	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	College Farm, Finchley N3		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA LB

- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BEXLEY / BRENT

#### BEXLEY




© London Borough of Bexley

C16 red brick garden wall which was part rebuilt in C18, enclosing Hall Place and its formal gardens. A section of the SITE NAME Section of garden wall to the north of Hall Place, Bourne wall between the gatehouse and a brick pier has a severe Road, Bexley, DA5 lean and in places has collapsed and requires structural Listed Building grade I, part in repair. There is also severe erosion of brickwork and DESIGNATION: RPG grade II mortar pointing parallel with the A223 Bourne Road. Discussions between the Local Authority and Historic CONDITION: Poor England regarding a potential solution have failed to OCCUPANCY. N/A progress. PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1064250 Contact: Simon Buteux 07973 498013



SITE NAME:	Crossness Pumping Station, Belvedere Road SE28	Opened 1865; the engineer was Joseph Bazalgette. The building retains important cast iron interior fittings and four
DESIGNATION:	Listed Building grade I, CA	colossal beam engines by James Watt and Co. Opened to the public in 2016 as a heritage attraction following
CONDITION:	Good	restoration funded by the National Lottery Heritage Fund, Historic England and others. Run by the Crossness Engines
OCCUPANCY:	Occupied/in use	Trust, who have restored one of the engines to working
PRIORITY CATEGORY:	C (C)	order. Concerns about structural issues have limited public access. Listed Building Consent has been obtained for
OWNER TYPE:	Charity (heritage)	repairs to localised cracks to the cast iron in the Engine House.
LIST ENTRY NUMBER:	1064241	Contact: Simon Buteux 07973 498013

© Historic England





D

Е

use)

SITE NAME:	Former Savoy Cinema, Burnt Oak Broadway, Edgware	The Savoy Cinema was built for the independent circuit Goide & Glassman and was designed by cinema architect
DESIGNATION:	Listed Building grade II	George Coles. It opened on 29th June 1936 with Bobby Breen in "Rainbow on the River". It is an impressive cinema
CONDITION:	Poor	with all of its internal Moderne fittings intact. It operated as a bingo hall from the 1960s but closed in 2014. The
OCCUPANCY:	Vacant/not in use	building remains empty and in a declining state with
PRIORITY CATEGORY:	D (D)	crumbling plasterwork. Applications for Planning Permission and Listed Building Consent to re-purpose and
OWNER TYPE:	Commercial company	restore the building were approved in March 2021.
LIST ENTRY NUMBER:	1384932	Contact: Mark Price (LPA) 020 8937 5236

© London Borough of Brent



СНА	SITE NAME:	Goetze Grave, Paddington Cemetery, Willesden Lane NW6 NW6	Pink granite Celtic cross on a two-stage base set within a kerb of granite surrounded by railings. Circa 1911, by Kelly, monumental masons, incorporating figural elements
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	ascribed to Sir Alfred Gilbert. Commemorates James Goetze and his wife Rosina and is the only listed memorial in the cemetery. It is vulnerable to heritage crime and one
	CONDITION:	Fair	of the allegorical cowled figures is missing. Discussions are underway regarding the necessary repair works.
	OCCUPANCY:	N/A	underway regarding the necessary repair works.
A	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389534	Contact: Mark Price (LPA) 020 8937 5236

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABB	REVIAT	IONS
~ .	~	

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA
- Unitary Authority World Heritage Site ŴĤS

	SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6	Built in 1863 as St James's Episcopal Chapel. It is a prefabricated structure of corrugated iron with boarded
	DESIGNATION:	Listed Building grade II, CA	roof covered in corrugated asbestos. Since 1920 it has been the home of the Willesden & St Marylebone Cadet
	CONDITION:	Poor	Corps, which converted the interior to resemble a boat, in itself of historic interest. In 2020 Historic England awarded
	OCCUPANCY:	Part occupied/part in use	a Covid-19 Emergency Heritage at Risk Response Fund grant for high priority repairs. Discussions and an optic
	PRIORITY CATEGORY:	C (C)	appraisal, funded by Historic England, are ongoing, prior to
	OWNER TYPE:	Other not for profit group	seeking funding for full repair.
oric England	LIST ENTRY NUMBER:	1271962	Contact: Mark Price (LPA) 020 8937 5236

© Histor



SITE NAME:	Old Oxgate Farm, Coles Green Road, Cricklewood NW2	C16 and C17 timber-framed building suffering from subsidence to the brick plinth and structural failure of bean ends to the ground floor due to damp penetration. A condition assessment was produced in 2016, with funding from Historic England, and priority works identified in that survey to safeguard the building were completed in 2017.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	Funding for repair of the front façade has been secured
PRIORITY CATEGORY:	A (A)	through a Section 106 agreement but this has not yet been implemented. The building was sold in 2020 and
OWNER TYPE:	Private	discussions have taken place between the Local Authority and the new owner.
LIST ENTRY NUMBER:	1078875	Contact: Simon Buteux 07973 498013

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© London Borough of Brent

© Historic England

© Historic England

	LIST ENTRY NUMBER:	1078875	Contact: Simon Buteux 07973 498013
the second	SITE NAME:	Summerhouse, Kingsbury Manor, 288, Kingsbury Road	Summerhouse, circa 1899, by William West Neve, who designed the adjoining Kingsbury Manor for Mary Blair,
1 Ale	DESIGNATION:	Listed Building grade II	Duchess of Sutherland. Built in the Arts and Crafts style, timber-framed with patterned brick nogging on a brick
	CONDITION:	Poor	plinth edged with stone, and a hipped thatched roof. The thatched roof is deteriorating and the building is in need of
	OCCUPANCY:	N/A	repair. The Local Authority and the leaseholder have begun
1° Kan	PRIORITY CATEGORY:	C (C)	discussions to develop a strategy for the summerhouse's repair and re-use.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1322049	Contact: Mark Price (LPA) 020 8937 5236

Wembley Hill Lodge, 114, Wembley Hill Road, Brent HA9

The Chapels at Paddington

Cemetery, Willesden Lane

Listed Building grade II, RPG

Listed Building grade II

Vacant/not in use

Very bad

B (B)

Private

1359001

grade II, CA

Vacant/not in use

Local authority

Very bad

1359002

F (B)

Early C19 orné style cottage which was formerly a lodge to Wembley Park. Single storey and attic with gable to the front. Featuring twin chimneys and thatched catslide roof. The detached property was severely damaged by a fire in 2013. A new owner secured Planning and Listed Building Consent in 2021, which includes reinstatement of the lodge.

Contact: Mark Price (LPA) 020 8937 5236

Mid-C19 twin Anglican and Nonconformist chapels connected by a pair of carriage-porches and a central bell tower. Designed by Thomas Little in 1855 as part of a new cemetery. The vacant buildings are isolated within the cemetery and too dangerous to use. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for holding repairs to the walls, roof and rainwater goods, with the purpose of allowing the Heras fencing surrounding the building to be removed. Additional work to finalise this, funded by the Council, started on site in April 2023.

Contact: Mark Price (LPA) 020 8937 5236

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM

ÍΙΑ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BRENT / BROMLEY

	SITE NAME:	New Parish Church of St Andrew, Church Lane,	Built 1847 in Wells Street in London's West End, designed by Guy Daukes. It fell into disuse and in 1933 was dismantled and rebuilt in Kingsbury. The interior was reconstructed in its entirety apart from the north and south galleries and has works commissioned from many leading C19 architects and artists. Holding works have been carried out to the spire, which has suffered from rust jacking. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for project development for the roof and spire and holding
	DESIGNATION:	Kingsbury NW9 Listed Place of Worship grade	
	DESIGNATION:	II*, CA	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	repairs to gutters to prevent the ingress of water.
© John Scott	LIST ENTRY NUMBER:	1078874	Contact: Tracey Craig 020 7973 3756



	SITE NAME:	Church of St Andrew, High Road, Willesden Green NW10	Designed by James Brooks and built in 1885. Brooks also designed the adjacent grade II vicarage. The church suffers
	DESIGNATION:	Listed Place of Worship grade II*, CA	from cracking, some severe, mainly at the eastern end. Potentially loose stones internally have been pinned to secure them and the church is undergoing monitoring and
	CONDITION:	Poor	various investigations in order to ascertain the cause of movement which is resulting in the cracking. In 2020
	PRIORITY CATEGORY:	C (C)	Historic England awarded a Covid-19 Emergency Heritage
	OWNER TYPE:	Religious organisation	at Risk Response Fund grant to address a number of maintenance issues to the church fabric. Still to address is
	LIST ENTRY NUMBER:	1078881	movement at the east end.
			$C_{2}$ is the set $T_{2}$ is a set $C_{2}$ is $0.20, 70.72, 2.75/$

© Historic England



			Contact: Tracey Craig 020 7973 3756
多大	SITE NAME:	St Michael's Church, St Michael's Road, Cricklewood NW2	Designed by John Samuel Alder and built in 1910 in stone with tiled pitched roofs and flat roofs to the aisles, which are felted. In the northwest corner is the base of a tower
	DESIGNATION:	Listed Place of Worship grade II	which was never built. The church generally is in poor condition with movement resulting in cracking, and faulty
P	CONDITION:	Very bad	rainwater goods allowing water ingress with much staining internally. The west end window is supported by a
4	PRIORITY CATEGORY:	A (A)	framework of scaffolding poles.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1262125	Contact: Tracey Craig 020 7973 3756

© Historic England

#### BROMLEY

© Historic England

	SITE NAME:	Base of the Southern Crystal Palace Water Tower, SE 19	Base, trenches and pipework of the southern Crystal Palace water tower. Built for the Crystal Palace Company
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	by Fox, Henderson and Company to designs by Isambard Kingdom Brunel between 1854 and 1856. The tower itself was demolished in 1940-1941. The structure comprises a
	CONDITION:	Poor	thick, tapering, ring of brickwork, beneath which is a subterranean area enclosed within the circular mass
	OCCUPANCY:	N/A	concrete foundation. The brickwork has a coating of
	PRIORITY CATEGORY:	C (C)	cement render which has fallen off in places so that it is now vulnerable to further weather and vegetative damage.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1469984	Contact: Simon Went (LPA) 020 8464 3115



No. of the second s	SITE NAME:	The Ice House and Ha-Ha Wall at Bromley Palace Park, Kentish Way	e house and ha-ha wall to Bromley Old Palace. Ice house robably dating from the late C18 and remodelled in the arly C19 as a garden shelter. Despite previous repairs,
	DESIGNATION:	Listed Building grade II	and a fence constructed to protect the rear chamber, further substantial works are required, and it has been
OCCUPANCY: N	Very bad	subject to extensive vandalism. The ha-ha has been cleared of vegetation, but also requires repair. The Local Authority	
	OCCUPANCY:	N/A	has commissioned surveys and is considering suitable
	C (C)	approaches to repair.	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1393912	Contact: Simon Went (LPA) 020 8464 3115

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



SITE NAME:	Victorian Folly of 'Medieval Ruins' in Bromley Palace Park, Rafford Way	Folly with Norman-style detailing, probably of mid-1860s and by the important firm of garden contractors, Pulham. The structure had been cleared of ivy and other woody
DESIGNATION:	Listed Building grade II	vegetation, which was seriously damaging the stonework and lime render, but this has now regrown and is causing
CONDITION:	Very bad	further damage. Recently sold as part of a development site, Historic England and the Local Authority have made
OCCUPANCY:	N/A	contact with the new owners and it is expected that
PRIORITY CATEGORY:	A (A)	appropriate conservation works will be undertaken.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1186785	Contact: Simon Went (LPA) 020 8464 3115

Pedestrian subway under Crystal Palace Parade, Crystal

Listed Building grade II\*, part in

Palace SEI9

RPG grade II\*

Local authority

1385457

Poor

N/A

F (F)

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

A large C15 semi-fortified manor house built by Sir Henry Heydon. The square plan has castellated octagonal turrets located at each corner. The once-open courtyard has been roofed in and contains a central stair. The house was leased and occupied by a private school. The building suffered from storm damage and a lack of maintenance, but a collapsed tower has now been rebuilt and repairs were undertaken prior to the sale of the property.

Contact: Verena McCaig 020 7973 3718

The Subway was designed by Charles Barry Junior and

opened in 1865. It provided a direct link from his High-Level Station (demolished 1961) into the Crystal Palace via

a ticketing hall and the spectacular diaper brickwork of the

subway vaulting. Historic England is providing grant aid for

Authority's Strategic Investment Pot, with support from the

Friends of Crystal Palace Subway. Repairs commenced in


summer 2022 and are due to complete in late autumn

Contact: lan Harper 07974 979620

an extensive repair project, including a new roof for the ticketing hall, funded primarily by the Greater London

© Historic England





© Historic England



SITE NAME:	Prehistoric animal sculptures, geological formations and lead mine on islands in lake, Crystal Palace Park SE19	Sculptures of prehistoric animals with associated geological strata, constructed 1852 to 1855 for The Crystal Palace Company forming a unique display of prehistoric life as then understood, but now deteriorating significantly.
DESIGNATION:	Listed Building grade I, RPG grade II*, CA	Historic England is leading a project drawing on specialists to record and investigate underlying issues, working with key stakeholders including the Local Authority and Friends
CONDITION:	Very bad	of Crystal Palace Dinosaurs, to develop conservation recommendations. The Local Authority has been awarded
OCCUPANCY:	N/A	a Stage I pass for a National Lottery Heritage Fund grant
PRIORITY CATEGORY:	A (A)	to develop repair approaches.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1067798	Contact: Verena McCaig 020 7973 3718
SITE NAME:	Upper and Lower Terraces, Crystal Palace Park SE19	Terraces designed by Sir Joseph Paxton and situated to the east of the site of the Crystal Palace (re-erected here in
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	1852-4 and burnt down in 1936), at the top of Crystal Palace Park. The terraces are in a very poor condition and suffering from erosion, with fenced-off balustrading.
CONDITION:	Poor	Discussions are ongoing to determine an approach to further conservation works as part of the wider strategic
OCCUPANCY:	N/A	Regeneration Plan for the park. The Local Authority has
PRIORITY CATEGORY:	C (C)	identified funding for restoration of the terraces, which are to be included in the first stage of delivery of the
OWNER TYPE:	Local authority	Regeneration Plan.

2023.

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

1064352

- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Simon Went (LPA) 020 8464 3115

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Building 10 (Junior Ranks Mess, former Airmen's Institute), West Camp, Main Road, A233 (east side), Biggin Hill	Former Airmen's Institute and recreation centre of c1926 design and built in 1930. It was one of the principal barracks buildings at Biggin Hill, the internationally renowned historic fighter base. The building has been
	DESIGNATION:	Listed Building grade II, CA	vacant since the RAF withdrew from Biggin Hill in 1993. Repairs have been undertaken to the roof. Having met wit
LA SECTION D	CONDITION:	Poor	the owner and other stakeholders, the Local Authority an Historic England are discussing ways in which they can
	OCCUPANCY:	Vacant/not in use	assist in identifying new uses for the building.
	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1416723	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	North and south railings, Crystal Palace Parade, Crystal Palace Park SE19	Decorative cast iron railings on gault brick plinths with stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in
	DESIGNATION:	Listed Building grade II, RPG grade II*	1936) from Crystal Palace Parade. There is damage to some cast iron panels and the dwarf wall, and a long section of curved railing is missing from the north section.
the contraction	CONDITION:	Poor	A condition survey of the railings was completed in 2015, with funding from Historic England. Discussions are
All All All	OCCUPANCY:	N/A	ongoing to secure their full repair as part of the park's
	PRIORITY CATEGORY:	C (C)	wider regeneration plan.
Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1393659	Contact: Simon Went (LPA) 020 8464 3115
1 13	SITE NAME:	91, High Street, St Mary Cray	CI6 dwelling with crown post roof. The building is in a ve
~	DESIGNATION:	Listed Building grade II, CA	poor condition and a flank wall is at risk of collapse. Listed Building Consent has been granted for repairs to the
	CONDITION:	Very bad	structure, and applications for Planning Permission and
	OCCUPANCY:	Vacant/not in use	Listed Building Consent have been approved for works in connection with development for residential use.
	PRIORITY CATEGORY:	В (В)	However, no works have yet been carried out. The Local Authority is considering enforcement action.
	OWNER TYPE:	Private	Autionty is considering enior cement action.
	LIST ENTRY NUMBER:	1298993	Contact: Simon Went (LPA) 020 8464 3115
Historic England			
	SITE NAME:	The Royal Bell Hotel, 173-177, High Street, Bromley	The Royal Bell Hotel is part of a range of buildings rebuilt 1898 on the site of an earlier hostelry of 1666. It has beer vacant for some years and is in need of repair to halt its
P P A	DESIGNATION:	Listed Building grade II, CA	decline. Following a change of owner, Planning Permission
	CONDITION:	Poor	and Listed Building Consent have been granted to bring the hotel back into use, with enabling development on the
	OCCUPANCY:	Vacant/not in use	stable yard. Works are progressing on site.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
Historic England	LIST ENTRY NUMBER:	1054095	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	Building 12 (Candidates' Club, Former Sergeants' Mess), West Camp, Main Road, A233 (east side), Biggin Hill	Sergeants' mess, dating from 1932, built by the Air Ministry's Directorate of Works and Buildings. The buildir has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993
	DESIGNATION:	Listed Building grade II, CA	The Local Authority is considering action to secure works Having met with the owner and other stakeholders, the
	CONDITION:	Poor	Local Authority and Historic England are discussing ways
Lotter Lang	OCCUPANCY:	Vacant/not in use	which they can assist in identifying new uses for the building.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
London Borough of Bromley			
London Borough of Bromley	LIST ENTRY NUMBER:	1391606	Contact: Simon Went (LPA) 020 8464 3115
London Borough of Bromley	LIST ENTRY NUMBER:	1391606	Contact: Simon Went (LPA) 020 8464 3115

- solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use).

- redundant buildings with new use agreed but not yet implemented.
- New Entry is noted).
- LPA
   Local Planning Authority

   NP
   National Park

   RPG
   Registered Park and Garden

   SM
   Scheduled Monument

   UA
   Unitary Authority

   WHS
   World Heritage Site

8

HERITAGE AT RISK 2023 / LONDO	on and south east	/ BROMLEY	
	SITE NAME:	Building 15, Hawkinge Block, West Camp, Main Road, A233 (east side), Biggin Hill	Barrack block dated 1934, built by the Air Ministry's Directorate of Works and Buildings. The building has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. The
	DESIGNATION:	Listed Building grade II, CA	Local Authority is considering action to secure works.
	CONDITION:	Poor	Having met with the owner and other stakeholders, the Local Authority and Historic England are discussing ways in
	OCCUPANCY:	Vacant/not in use	which they can assist in identifying new uses for the
	PRIORITY CATEGORY:	C (C)	building.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1391604	Contact: Simon Went (LPA) 020 8464 3115
2	SITE NAME:	Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill	Office block dated 1931, formerly the station headquarters building. The building has been vacant since the RAF withdrew from Biggin Hill, the internationally renowned
CITILIC SA	DESIGNATION:	Listed Building grade II, CA	historic fighter base, in 1993. The Local Authority is considering action to secure works. Having met with the
	CONDITION:	Poor	owner and other stakeholders, the Local Authority and
	OCCUPANCY:	Vacant/not in use	Historic England are discussing ways in which they can assist in identifying new uses for the building.
	PRIORITY CATEGORY:	С (С)	,
	OWNER TYPE:	Commercial company	
© London Borough of Bromley	LIST ENTRY NUMBER:	1391587	Contact: Simon Want (I BA) 020 84(4 2115
	LIST ENTRY NOPIBER:	1391287	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	Buildings I-5 (Airmen's barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill	Group of five airmen's barracks blocks, dating from 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill, the internationally renowned historic fighter base, in 1993. Roof repairs have been carried out to
	DESIGNATION:	Listed Building grade II, CA	one block but urgent repairs are required to the roofs and rainwater goods of the remaining blocks. The Local
	CONDITION:	Very bad	Authority is considering action to secure these works.
	OCCUPANCY:	Vacant/not in use	Having met with the owner and other stakeholders, the Local Authority and Historic England are discussing ways in
	PRIORITY CATEGORY:	A (A)	which they can assist in identifying new uses for the buildings.
© Historic England	OWNER TYPE:	Commercial company	bullangs.
	LIST ENTRY NUMBER:	1391589	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	Ice house to Sundridge Park, Plaistow Lane, Bromley	Ice house circa 1800, in the south west corner of a late C18 landscape park designed by Humphry Repton, now a
	DESIGNATION:	Listed Building grade II, RPG grade II	golf course. The ice house has previously been subject to vandalism despite strenuous efforts by the owners to prevent access. A local archaeological group has identified
	CONDITION:	Very bad	its exact location and plans to visit to reassess its condition
	OCCUPANCY:	N/A	although internal access is difficult.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1254001	Contact: Simon M(ant /LDA) 020 94/42115
	LIST ENTRY NOPIBER:	1254001	Contact: Simon Went (LPA) 020 8464 3115
	SITE NAME:	Pulhamite fernery, Stockwell Close, Bromley Palace Park	Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy
and the second	DESIGNATION:	Listed Building grade II	coal merchant. The fernery is at the northern end of the
	CONDITION:	Poor	ornamental lake and is in need of repair. The Local Authority has commissioned surveys and is considering
	OCCUPANCY:	N/A	suitable approaches to repair.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1392584	Contact: Simon Went (LPA) 020 8464 3115

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Pulhamite waterfall, Stockwell Close, Bromley Palace Park	Pulhamite rockwork garden feature constructed circa 1865 as part of the improvements to the gardens of Bromley
	DESIGNATION:	Listed Building grade II	Palace that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end,
	CONDITION:	Poor	adjacent to an ice house, probably of late C18, and is in need of repair. Vegetation clearance takes place
	OCCUPANCY:	N/A	periodically, but structural works are needed. The Local Authority has commissioned surveys and is considering suitable approaches to repair.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1392583	Contact: Simon Went (LPA) 020 8464 3115

	SITE NAME:	Church of St John the Evangelist, High Street, Penge SE20	The church was designed by John Nash and Edwin Nash of Bermondsey in the Early English style and completed in 1849. It is built of ragstone with Bath stone dressings,
	DESIGNATION:	Listed Place of Worship grade II, CA	including the spire. The church suffers from water ingress at roof and lower levels, and dampness at lower levels. High level repairs were completed in 2013 at the east end,
at a	CONDITION:	Poor	grant-aided by Historic England and the National Lottery
	PRIORITY CATEGORY:	C (C)	Heritage Fund. Further repairs are required to the west end but await the outcome of discussions between Historic
	OWNER TYPE:	Religious organisation	England and the church regarding a development scheme.
Historic England	LIST ENTRY NUMBER:	1186832	Contact: Ian Harper 07974 979620

SITE NAME:	Iron Age settlement and Roman villa at Warbank, Keston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002024
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Scadbury Manor moated site and fishponds		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1409786
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Romano-British masonry building and Saxon cemet	ery, Fordcroft, Or	pington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001973
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable

PRINCIPAL VULNERABILITY:

OWNER TYPE:

©⊢



© Historic England Archive

	Vandalism		NEW ENTRY?:	No
	Local authority, n	nultiple owners	CONTACT:	Jane Sidell 020 7973 3738
a second states	SITE NAME:	Crystal Palace Park SE19		e grounds designed by Sir Joseph Paxton
	DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, part in CA	as a setting for the Crystal Palace, burnt down in 1936 park is in variable condition with related listed structur also at risk. An approved regeneration plan is being implemented alongside a new sustainable governance management model. A Stage I grant has been secured from the National Lottery Heritage Fund by the Local	
	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY:	Medium	Authority to develop projects to repair and conserv prehistoric animal sculptures and geological illustrati make improvements to park infrastructure.	elop projects to repair and conserve the
うな	TREND:	Stable		
A.	NEW ENTRY?:	No		•
	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000373	Contact: Christopher Laine 020 7973 3473	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Biggin Hill RAF		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Simon Went (LPA) 020 8464 3115

#### CAMDEN

-

1

	SITE NAME:	39, Tottenham Street WIT WI	Late C18 terraced house with a later shop, of four storeys
	DESIGNATION:	Listed Building grade II, CA	with a basement and constructed of darkened stock brick with upper parts refaced. The property was used for a
	CONDITION:	Poor	community purpose on the ground floor with flats above but has been vacant for several years. Following roof leaks
	OCCUPANCY:	Vacant/not in use	temporary remedial works have taken place to keep the
	PRIORITY CATEGORY:	C (D)	building watertight and structurally safe. In 2018 permission was granted for the change of the ground floor unit to a
	OWNER TYPE:	Local authority	commercial unit with separate flats above; however the consents for this scheme have now expired.
	LIST ENTRY NUMBER:	1379039	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

	SITE NAME:	Former Hampstead Police Station, Rosslyn Hill NW3 NW3	Former police station and courthouse including stable and harness room, railings and lamps. Built in 1913 by J Dixon Butler, surveyor to the Metropolitan Police. The building
	DESIGNATION:	Listed Building grade II, CA	has been empty since 2013 and is now secure after illega entry in 2014 and 2020. Applications for a proposed new use as a school were refused by the Local Authority in 2019 and were dismissed at appeal in 2020. In 2021 the building was sold and in 2022 applications were submitte
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	to the local authority for the conversion of the stables to residential. Some unauthorised work to the stables' roof is
	OWNER TYPE:	Commercial company	being investigated.
	LIST ENTRY NUMBER:	1130397	Contact: Jane Wylie (LPA) 020 7974 8737



© London Borough of Camden

		1150577	Contact. Jane vvyne (ELA) 020 777 10757
	SITE NAME:	Wall to the south of St George's Gardens, Handel Street, WCI WCI	C18 red brick graveyard wall with stone copings to the piers. The burial ground was closed in 1854 and reopened as public gardens in the late C19. The wall is lined with
	DESIGNATION:	Listed Building grade II, part in RPG grade II*, CA	gravestones formerly located within the burial ground. Some sections of wall have been repaired but there are structural problems on this southern section. Discussions
	CONDITION:	Very bad	are underway with the owners of the wall regarding the necessary repairs.
	OCCUPANCY:	N/A	
Contraction of the	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1378729	Contact: Jane Wylie (LPA) 020 7974 8737



1	SITE NAME:	Cattle trough to south east of the Roundhouse, Chalk Farm Road NWI	Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist Charles Kingsley. Some
and	DESIGNATION:	Listed Building grade II, CA	repairs have been carried out but investigation into the stability of the trough on the plinth is required. It is
	CONDITION:	Fair	vulnerable given its location adjacent to the bus lane and bus stop.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1258104	Contact: Jane Wylie (LPA) 020 7974 8737

© Historic England

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site



SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NWI	Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but the drinking
DESIGNATION:	Listed Building grade II, CA	fountain remains prone to littering and damage. Options for repair are being explored with partner organisations.
CONDITION:	Fair	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1258105	Contact: Jane Wylie (LPA) 020 7974 8737

© Historic England

© Historic England



	SITE NAME:	26, Denmark Street WC2	Early C18 terraced house; windows altered in C20. The
	LIST ENTRY NUMBER:	1242917	Contact: Jane Wylie (LPA) 020 7974 8737
	OWNER TYPE:	Health authority	
	PRIORITY CATEGORY:	F (F)	have started on site and are progressing.
	OCCUPANCY:	Part occupied/part in use	the rear of the listed building have been approved. Works
	CONDITION:	Fair	Applications for refurbishment and alterations to provide residential accommodation and mixed-use development to
	DESIGNATION:	Listed Building grade II, CA	live-in guardians and site staff in the adjoining unlisted buildings. The buildings are weathertight and secure.
	SITE NAME:	Former Strand Union Workhouse (Middlesex Hospital Annex), 44, Cleveland Street WI	Former Strand Union Workhouse, dating from 1778, with an austere symmetrical brick building facing Cleveland Street behind later high brick walls. Vacated by University College London Hospital and in temporary occupation by

	SITE NAME:	26, Denmark Street WC2	Early C18 terraced house; windows altered in C20. The
	DESIGNATION:	Listed Building grade II, CA	windows, parapets and gutters are in poor condition. Listed Building Consent and Planning Permission have been
	CONDITION:	Poor	granted as part of a wider scheme which includes residential use on the upper floors and repairs to the roof
	OCCUPANCY:	Vacant/not in use	and front parapet. Repair works are continuing on site w the front façade being refurbished and tied back into the building.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	5
12 BAR CAT	LIST ENTRY NUMBER:	1271982	Contact: Alan Wito (LPA) 020 7974 6392
© Historic England			

_		SITE NAME:	3, Endsleigh Street	One in a terrace of four houses, dating from circa 1825,
		DESIGNATION:	Listed Building grade II, CA	built by Thomas Cubitt and constructed from multi- coloured stock brick. It comprises four storeys and a
		CONDITION:	Good	basement with a round-arched doorway and first floor casements with continuous cast iron balconies. Planning
		OCCUPANCY:	Occupied/in use	Permission and Listed Building Consent were granted in
		PRIORITY CATEGORY:	F (E)	2018 to convert the ground floor to a gallery and the works have been completed. Whilst the building is
和		OWNER TYPE:	Private	occupied and in good condition there are a number of outstanding matters which are being dealt with.
		LIST ENTRY NUMBER:	1078298	Contact: Catherine Bond (LPA) 020 7974 2669

© London Borough of Camden



SITE NAME:	43, Fitzroy Street	One of a terrace of four houses, dating from the late C18,
DESIGNATION:	Listed Building grade II, CA	constructed from darkened multi-coloured stock brick with some stucco dressings. It comprises four storeys and a
CONDITION:	Poor	basement. The property is partially occupied and in a deteriorating condition. The Local Authority has contacted
OCCUPANCY:	Part occupied/part in use	the owner to discuss the building's condition.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1322184	Contact: Jane Wylie (LPA) 020 7974 8737

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	34 and 39, Great James Street	Two in a terrace of 14 houses, dating from 1720-24, all of
	DESIGNATION:	Listed Building grade II*, CA	four storeys with basements and constructed from brown brick. Both properties are currently empty. Listed Building
	CONDITION:	Poor	Consent and Planning Permission were granted in 2018 for
	OCCUPANCY:	Vacant/not in use	refurbishment and a rear extension at 39, and in 2019 for 34 Great James Street. Works have started on 34 and 39
	PRIORITY CATEGORY:	F (F)	Great James Street.
H HI KOLALINA	OWNER TYPE:	Commercial company, multiple owners	
© Historic England	LIST ENTRY NUMBER:	1113203	Contact: Simon Buteux 07973 498013
	SITE NAME:	Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6	Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. The original sculptures are missing from the completed scheme.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
ALT V ALTA	OCCUPANCY:	N/A	
A CAR	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379028	Contact: Jane Wylie (LPA) 020 7974 8737
	SITE NAME:	Drinking fountain on north west corner, Lincoln's Inn Fields	Stone gabled drinking fountain with a semi-circular basin on a half pedestal. Erected in 1861, restored circa 1992, and
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	inscribed "The Fear of the Lord is a Fountain of Life". An early public drinking fountain erected at the time when the St Giles's parish wells were polluted and when Lincoln's Inn
	CONDITION:	Poor	Fields was being restored and renovated. The fountain is
	OCCUPANCY:	N/A	not functioning and has a plaque missing. The Local Authority replaced the rear maintenance panel in 2019 and
	PRIORITY CATEGORY:	C (C)	is working towards a repair scheme.
-hout e	OWNER TYPE:	Local authority	
© Historic England		/	
0	LIST ENTRY NUMBER:	1379337	Contact: Alan Wito (LPA) 020 7974 6392
	LIST ENTRY NUMBER:	1379337 Heath House, North End Way NW3	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following
		Heath House, North End Way	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water
	SITE NAME:	Heath House, North End Way NW3	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was
	SITE NAME: DESIGNATION:	Heath House, North End Way NW3 Listed Building grade II*, CA	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the
	SITE NAME: DESIGNATION: CONDITION:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C)	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight.
© London Borough of Camden	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C)	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company III3183 Section of boundary wall to St Stephen's Church, Rosslyn Hill	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OW/NER TYPE: LIST ENTRY NUMBER: SITE NAME:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company III3183 Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved an application for further remedial works to part of the
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UST ENTRY NUMBER: SITE NAME: DESIGNATION:	Heath House, North End Way         NW3         Listed Building grade II*, CA         Poor         Vacant/not in use         C (C)         Commercial company         1113183         Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3         Listed Building grade II, CA	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Heath House, North End Way         NW3         Listed Building grade II*, CA         Poor         Vacant/not in use         C (C)         Commercial company         III3183         Section of boundary wall to St stephen's Church, Rosslyn Hill NVV3         Listed Building grade II, CA         Poor	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved an application for further remedial works to part of the
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company III3183 Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3 Listed Building grade II, CA Poor	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved an application for further remedial works to part of the
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY:	Heath House, North End Way NW3 Listed Building grade II*, CA Poor Vacant/not in use C (C) Commercial company III3183 Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3 Listed Building grade II, CA Poor N/A D (D)	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The owner is pursuing a scheme which was granted consent in 2008 to restore the building as a single dwelling, which has been partially implemented. In 2021 the building was protected by scaffolding, monoflex wrapping and a temporary roof and an internal inspection in December 2021 showed it to be secure, wind and watertight. Contact: Simon Buteux 07973 498013 Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by the entrances, but other areas on Rosslyn Hill and fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved an application for further remedial works to part of the

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	St Stephen's Church, Rosslyn Hill NW3	Former church, built 1869-71 to the design of SS Teulon, i an early French Gothic style. The London Diocesan Fund has leased the church to St Stephen's Restoration and Preservation Trust for use by Hampstead Hill School and as a community lifelong learning centre. Repair works to the south slope of the nave roof, grant-aided by Historic England, were completed in March 2016. Further repairs are needed to the other roofs and the tower.
	DESIGNATION:	Listed Building grade I, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© Historic England Archive	LIST ENTRY NUMBER:	1130394	Contact: Ian Harper 07974 979620




SITE NAME:	Toll Gate House, Spaniards Road, Highgate NW3	Late C18 toll house, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic
DESIGNATION:	Listed Building grade II, part in CA	bottleneck on a busy road and has suffered impact damage from heavy vehicles. A bollard was erected in late 2008 to provide protection from traffic. Roof and guttering repair
CONDITION:	Good	works have been undertaken and the property is regularly inspected. It is now in good condition; but remains
OCCUPANCY:	Vacant/not in use	unoccupied.
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1378793	Contact: Alan Wito (LPA) 020 7974 6392



© Historic England

© Historic England



	SITE NAME:	Church of St Michael, Camden Road, Camden NWI	The nave and aisles were built in 1881, designed by GF Bodley and T Garner; the chancel was added in 1894 and
	DESIGNATION:	Listed Place of Worship grade II*	the vestries in 1908. The church has undergone structural and stonework repair, re-roofing and drainage works. New
	CONDITION:	Fair	electrical and lighting installations were completed in 2016, grant-aided by the National Lottery Heritage Fund. In 2020
	PRIORITY CATEGORY:	C (C)	Historic England awarded a Covid-19 Emergency Heritage
	OWNER TYPE:	Religious organisation	at Risk grant which, with additional fundraising, saw the repair of the nave painted ceiling where water damage had
	LIST ENTRY NUMBER:	1244156	resulted in flaking paint. Interior fabric remains in need of attention.

© Historic England



SI

D

C

PF

0

LIS

D

Е

		, C
ITE NAME:	Church of the Holy Trinity with St Barnabas, Clarence Way, Kentish Town NWI	Built in 1849-50 in a C14 Gothic style to the design of Thomas H Wyatt and David Brandon. The building was bomb damaged during World War II. The tower roof was
DESIGNATION:	Listed Place of Worship grade II	re-covered and the roofs re-slated with a grant from the National Lottery Heritage Fund and Historic England. The
CONDITION:	Poor	church was awarded a subsequent grant from the National Lottery Heritage Fund for repairs to the tower stonework
RIORITY CATEGORY:	C (C)	and this was completed in summer 2015. The western end
OWNER TYPE:	Religious organisation	of the south aisle has suffered from structural movement and in part there is shoring in place externally and
IST ENTRY NUMBER:	1356761	scaffolding internally.
		Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Tracey Craig 020 7973 3756

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2023 / LONDO	on and south east	/ CAMDEN	
	SITE NAME:	Church of the Holy Cross, Cromer Street, Camden Town WCI	Church in the Early English style built in 1885 by Joseph Peacock, with internal features by Charles Nicholson circa 1913. Built of yellow stock brick under clay tiled roofs;
	DESIGNATION:	Listed Place of Worship grade II, CA	stone dressings inside and out with red brick banding inside. An unusual two-storey narthex houses the organ gallery. There is settlement of the foundations at the
	CONDITION:	Very bad	northeast corner causing structural cracking to the vestry and adjacent walls of the church. Other repairs are needed
	PRIORITY CATEGORY:	A (A)	to the east end roofing, north side guttering and brickwork.
	OWNER TYPE:	Religious organisation	The congregation and Diocese are actively exploring possible sources of funding.
© Historic England	LIST ENTRY NUMBER:	1067375	Contact: Ian Harper 07974 979620
	SITE NAME:	Church of St Mary Brookfield, Dartmouth Park Road, Hampstead NW5	The church was built in the late C19 by W Butterfield with the chancel added by WC Street in 1881. Construction is of stock brick with red brick bands, diaper work and stone
	DESIGNATION:	Listed Place of Worship grade II*, CA	dressings under a slated roof. The church has a fine interior. There is severe spalling to brickwork internally to chancel walls and weathering of stone dressings at high
0	CONDITION:	Poor	level externally, caused by previous failure of parapet gutters and rainwater goods at the east end. The parish is
	PRIORITY CATEGORY:	C (C)	preparing a project to carry out the necessary repairs and
	OWNER TYPE:	Religious organisation	is investigating sources of funding.
© Historic England	LIST ENTRY NUMBER:	1067389	Contact: Ian Harper 07974 979620
<u>a</u>	SITE NAME:	Church of St Mary the Virgin, Eversholt Street, Somers Town NWI	Built in 1824-7, designed by H and HW Inwood in Gothic style with the apse added in 1888 by Ewan Christian, who also removed the side galleries. The church has slate
11.5.11	DESIGNATION:	Listed Place of Worship grade II	pitched roofs and brick walling with stone dressings. There is a central tower at the west end. Inspection by roped
	CONDITION:	Poor	access and a drone has shown that the roofs are in poor condition along with the gutters, flashings and rainwater
	PRIORITY CATEGORY:	C (C)	goods. Water staining is evident internally, along with
	OWNER TYPE:	Religious organisation	dampness at low level. Areas of the stone window surrounds are decayed and there are some failing past
O Historic Fordund	LIST ENTRY NUMBER:	1342049	cementitious repairs.
© Historic England			Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Christ Apostolic Church (formerly Church of St John), Highgate Road, Kentish Town NW5	Church built on the site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. High level repairs to the west end, grant-aided by the
	DESIGNATION:	Listed Place of Worship grade II	National Lottery Heritage Fund and Historic England, were completed in 2011. The Diocese commissioned a full
	CONDITION:	Very bad	dilapidations report in 2020 and is in discussion with the church. Some stained-glass windows have been sent to a
	PRIORITY CATEGORY:	A (A)	studio for repair. The church is seeking funding for this and
	OWNER TYPE:	Religious organisation	other necessary internal and external repairs.
© Historic England Archive	LIST ENTRY NUMBER:	3790 3	Contact: Ian Harper 07974 979620
6 Aug 2 Star	SITE NAME:	St Andrew's Cathedral (former Church of St Barnabas), Kentish Town Road, Hampstead NWI	This church was constructed in the style of a three-aisled basilica (without a dome) by Ewan Christian in 1884-85. It has been in use by the Greek Orthodox Church since 1957 and basers 51 Andrews Cathedral in 1970. All internal
	DESIGNATION:	Listed Place of Worship grade II, CA	and became St Andrew's Cathedral in 1970. All internal walls and ceilings have been decorated in the traditional Byzantine style, and large areas have been repainted where
	CONDITION:	Poor	damaged by dampness. Externally the tabled guttering to the aisles and apse needs renewal.
	PRIORITY CATEGORY:	C (C)	···· ···· ····
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1379241	Contact: Ian Harper 07974 979620

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Mary Magdalene, Munster Square, Camden Town NWI	The church, designed by RC Carpenter and completed in 1852, was described in the Ecclesiologist as the 'most artistically correct new church in London'. Even so, it was
	DESIGNATION:	Listed Place of Worship grade II*, CA	altered in 1866-67, and in 1883-84 the north aisle and crypt were added. Built of ragstone with Welsh slate ro on Baltic fir collar-braced trusses. The interior is richly decorated with marbles and frescoes. The condition of frescoes is poor as a result of damp caused by leaks in t
	CONDITION:	Poor	
	PRIORITY CATEGORY:	A (A)	roof and defective rainwater goods. Externally there is
	OWNER TYPE:	Religious organisation	localised decay to the stonework.
D Historic England	LIST ENTRY NUMBER:	1113157	Contact: Ian Harper 07974 979620



ALL ALL	SITE NAME:	St Pancras Old Church, Pancras Road, Camden NWI	Church dating from the CI3 and enlarged in the mid CI9 by AD Gough and RL Roumieu, retaining CI3 and CI5
	DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA	fabric and wall memorials. Restored by AW Blomfield in the late C19 and by Erith and Terry in 1980. The church has cracks externally and internally along with blown
	CONDITION:	Fair	plaster. A deep and narrow C19 gully around the building was modified in 2015 along with new drainage, with a grant
	PRIORITY CATEGORY:	D (C)	from the National Lottery Heritage Fund. Emergency
	OWNER TYPE:	Religious organisation	repairs to the most unstable areas were completed in March 2021, grant aided with a Historic England Heritage
	LIST ENTRY NUMBER:	1113246	at Risk repair grant.

© Historic England

A CAN

©



Contact: Tracey Craig 020 7973 3756 Designed by Frederick and Horace Francis in 1856 with the SITE NAME: Church of St Mary, Priory Road, Camden NW6 spire added in 1872. The church is built of Kentish ragstone with Bath stone dressings and slate roofs. Stonework Listed Place of Worship grade II, repairs to the north and south transept gables and east end DESIGNATION: of the nave were carried out in 2008, grant-aided by CA Historic England. Repairs to the west elevation of the nave CONDITION Poor and north aisle are also complete, jointly funded by the PRIORITY CATEGORY: National Lottery Heritage Fund and Historic England. C (C) Further repairs are required to the tower and spire OWNER TYPE: Religious organisation stonework. LIST ENTRY NUMBER: 1139083 Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England



Church of St George the Built 1706 by Arthur Tooley with major re-modelling 1869 SITE NAME: by SS Teulon who altered the exterior, added a chancel, Martyr, Queen Square, Holborn and removed most of the galleries. The roof is in poor WCI condition and this, along with defects in the rainwater Listed Place of Worship grade goods, may have contributed to falls of plaster which DESIGNATION: II\*, CA necessitated the church to close. Emergency stabilisation works were carried out in 2019 which permitted worship CONDITION: Poor in the church again. In 2020 Historic England awarded a PRIORITY CATEGORY: Covid-19 Emergency Heritage at Risk Response Fund grant C (C) to undertake a condition survey of the ceiling, prepare a OWNER TYPE: Religious organisation schedule of work and a cost plan. LIST ENTRY NUMBER: 1245485 Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Church of St Pancras, Upper Woburn Place, Camden NWI	Designed by H and HW Inwood, built in 1822 and restored in 1953. The earliest Greek Revival church in
	DESIGNATION:	Listed Place of Worship grade I, CA	London. The west end has an lonic portico to a vestibule with tower above. The north and south facades each have a tribune with a portico supported by four caryatids with a
	CONDITION:	Poor	sarcophagus behind. Repairs to the west portico roof a surrounding stone parapets were completed in early 20
	PRIORITY CATEGORY:	C (C)	with funding from the National Lottery Heritage Fund. The
	OWNER TYPE:	Religious organisation	condition of the tower, front portico and caryatids has been investigated and all are in need of repair.
	LIST ENTRY NUMBER:	1379062	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- ÍΙΑ
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CAMDEN / CITY OF LONDON / CROYDON

	SITE NAME:	Church of St Martin, Vicars Road, Gospel Oak, Camden NW5	Designed by Edward Buckton Lamb and built1864-6. The choir vestry added in 1928 is now subdivided for wider community use. Repairs to the tower stonework and
	DESIGNATION:	Listed Place of Worship grade I	restoration of the pinnacles were completed in 2014, grant-aided by the National Lottery Heritage Fund. The
	CONDITION:	Poor	church has a history of subsidence and has been underpinned in part but there is cracking to the choir
	PRIORITY CATEGORY:	C (C)	vestry and more recently in the southeast corner. The west
	OWNER TYPE:	Religious organisation	end window to the choir vestry was repaired in 2020. The church is undergoing continual structural monitoring.
	LIST ENTRY NUMBER:	1379098	Contact: Tracey Craig 020 7973 3756

© Historic England

© Histori

#### **CITY OF LONDON**

	SITE NAME:	Church of St Mary Woolnoth, King William Street, City of London EC3	This square-plan church was built between 1716 and 1727 by Nicholas Hawksmoor on a tight site between Lombard Street and King William Street. In 1875-6 William
	DESIGNATION:	Listed Place of Worship grade I, CA	Butterfield raised the chancel floor and removed the galleries, setting the carved fronts against the walls. The church is dominated by a baroque tower: this has
	CONDITION:	Poor	settlement cracks which are currently being monitored. Elsewhere asphalt roofing needs to be repaired. In 2020
	PRIORITY CATEGORY:	C (C)	Historic England awarded a Covid-19 Emergency Heritage
	OWNER TYPE:	Religious organisation	at Risk Response Fund grant for investigations and a costed dilapidations report to inform a repairs programme.
ric England	LIST ENTRY NUMBER:	1064620	Contact: lan Harper 07974 979620

	SITE NAME:	Church of St Margaret, Lothbury, City of London EC2	Designed by Sir Christopher Wren, the church was built between 1686 and 1695. The form is a simple rectangle
	DESIGNATION:	Listed Place of Worship grade I, CA	orientated north-south with a vestry to the east and a tower to the west. The south elevation is faced in Portland stone; the others are rendered brick with stone quoins.
	CONDITION:	Poor	Internal fittings are contemporary. The spire was fully repaired in 2018-2019 with a grant from the National
	PRIORITY CATEGORY:	C (C)	Lottery Heritage Fund. However, further settlement of the
	OWNER TYPE:	Religious organisation	nave floor is causing concern and is being monitored, along with the tower which leans towards the street.
	LIST ENTRY NUMBER:	1064634	Contact: Ian Harper 07974 979620
© Historic England			

# CROYDON

-			
	SITE NAME:	Kennedy's, 18a, High Street, South Norwood SE25	Built in 1926 for Kennedy, a chain of South London butchers, now closed. The refurbishment of the upper
	DESIGNATION:	Listed Building grade II, CA	floors and conversion of the rear of the ground floor for residential use began in early 2020 and was completed in
	CONDITION:	Fair	2021. Discussions with the Local Authority are ongoing regarding the future use and repair of the shop front. The
ST attor	OCCUPANCY: PRIORITY CATEGORY:	Vacant/not in use	Local Authority's enforcement team has a live case regarding unauthorised works to the building's front elevation.
SIG 7 -		E (F)	
	OWNER TYPE:	Private	
: England	LIST ENTRY NUMBER:	1392596	Contact: Nicolette Duckham (LPA) 020 8726 6000

© Historic E



SITE NAME:	Leslie Arms public house, 62, Lower Addiscombe Road, Addiscombe	Public house circa 1900 in Arts and Crafts style. The ground floor of the building has been vacant for many years and its condition is deteriorating, particularly the interiors.
DESIGNATION:	Listed Building grade II	The upper floors have now been converted to flats. In 2017 and 2019 repairs were carried out, including to the
CONDITION:	Poor	front parapet wall, and rubbish was cleared from the front of the building. Planning Permission was granted in
OCCUPANCY:	Part occupied/part in use	February 2023 for a new rear extension with community
PRIORITY CATEGORY:	B (A)	space and 2 additional residential units. Work has not started on site.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1272418	Contact: Nicolette Duckham (LPA) 020 8726 6000

#### PRIORITY CATEGORIES

© London Borough of Croydon

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Segas offices, 32, Park Lane, Croydon	Gas company showroom and office, built 1939-41 in Moderne style. The building is in need of maintenance and
The second	DESIGNATION:	Listed Building grade II, CA	is vacant. Approved soft strip works and temporary use of the ground floor as a marketing suite are being
	CONDITION:	Poor	implemented, and discussions are ongoing regarding the long-term use of the building as part of the wider Queen's
	OCCUPANCY:	Vacant/not in use	Square development (St George's Walk). The Mid
	PRIORITY CATEGORY:	C (C)	Croydon Masterplan and Opportunity Area Planning Framework emphasise the need for a new use to be for
	OWNER TYPE:	Commercial company	for the building.
© Historic England	LIST ENTRY NUMBER:	1262041	Contact: Nicolette Duckham (LPA) 020 8726 6000



	SITE NAME:	Former lodge to Croydon Airport Terminal, Purley Way, Croydon	Single storey lodge to Airport House, built circa 1928. In spring 2019 works were completed on repairs to the roof, walls and interior to ensure it is secure and watertight. The
	DESIGNATION:	Listed Building grade II	building is vacant and discussions are ongoing between the owner and the Local Authority, with advice from Historic
	CONDITION:	Fair	England, regarding the building's use and a second phase of work to include further internal works and repair of the
	OCCUPANCY:	Vacant/not in use	Crittal windows.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1079299	Contact: Nicolette Duckham (LPA) 020 8726 6000



	OWNER TYPE:	Commercial company	
© London Borough of Croydon	LIST ENTRY NUMBER:	1079299	Contact: Nicolette Duckham (LPA) 020 8726 6000
<b>*</b>	SITE NAME:	Surrey Street Pumping Station, Surrey Street, Croydon	Pumping station, built in four phases from 1851. The building is secure and watertight; but remains vacant.
Alte	DESIGNATION:	Listed Building grade II, CA	Located within the Old Town Masterplan area, its future use has been identified as key to the regeneration of
	CONDITION:	Fair	Croydon's Old Town. Discussions with the Local Authority are ongoing regarding the future use and repair of the
1 sille	OCCUPANCY:	Vacant/not in use	pumping station and regeneration of the surrounding area.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1079248	Contact: Nicolette Duckham (LPA) 020 8726 6000

	SITE NAME:	2, Woodside Green, South Norwood SE25	Early C18 timber-framed house with brick gable ends and catslide roof to the rear. The building is unoccupied and in
	DESIGNATION:	Listed Building grade II	poor condition following fire damage in 1991. Planning Permission and Listed Building Consent for residential use
THE REAL PROPERTY OF	CONDITION:	Poor	were granted in 2015. The Local Authority and Historic England advised on the condition of the building and repair
Party and and and	OCCUPANCY:	Vacant/not in use	works. The chimneys have been rebuilt, wall timbers
	PRIORITY CATEGORY:	F (F)	repaired, and the roof was in the process of being reinstated to make the building wind and weathertight.
And the second se	OWNER TYPE:	Private	However repair and reinstatement have been delayed because of the contractor's availability.
ngland	LIST ENTRY NUMBER:	1079280	Contact: Nicolette Duckham (LPA) 020 8726 6000

© Historic Engl



			Contact. Nicolette Duckham (ELA) 020 0720 0000
	SITE NAME:	Church of St Mark, Albert Road, South Norwood SE25	Designed by GH Lewis of Linden and Lewis, the nave was built in 1852 and the rest completed by 1890. The church
	DESIGNATION:	Listed Place of Worship grade II, CA	has slate pitched roofs and Kentish ragstone walling. Stonework repairs were completed in 2013, grant-aided by Historic England and the National Lottery Heritage Fund.
	CONDITION:	Poor	The chancel and south slopes of the nave and aisle were re-roofed in 2016 with funding secured from the Listed
	PRIORITY CATEGORY:	C (C)	Places of Worship Roof Repair Fund. The north slopes of
	OWNER TYPE:	Religious organisation	the nave and aisle roofs remain in need of repair.
	LIST ENTRY NUMBER:	1323688	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Old Tithe Barn, Purley Way, Waddon	C18 former barn, now in use as a place of worship. The barn is an unusual structure of two parallel ranges with an
	DESIGNATION:	Listed Place of Worship grade II	M-shaped roof. The timber frame is clad in light brickwork with steeply pitched tiled roofs and wooden louvres at the
	CONDITION:	Fair	end of each range. Some repairs have been undertaken to make the building watertight, however further work is
	PRIORITY CATEGORY:	C (C)	required to the roof and to clear the rainwater goods.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1079247	Contact: Tracey Craig 020 7973 3756

© Historic England

	SITE NAME:	Church of St Andrew, Southbridge Road, Croydon	Church dating from 1857 by Benjamin Ferrey, with aisles added in 1879; chancel rebuilt and Lady Chapel added in
	DESIGNATION:	Listed Place of Worship grade II	1891, designed by HB Walton. The church has been re- ordered internally. The unusual bellcote feature has been
	CONDITION:	Fair	dismantled due to its poor structural condition and needs to be reinstated. Works are also required to the roofs,
	PRIORITY CATEGORY:	C (C)	rainwater goods, stonework and windows.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1079305	Contact: Tracey Craig 020 7973 3756

© Historic England

JAC YEAL

SITE NAME:	Church of St Augustine, St Augustine's Avenue, South Croydon	Designed by John Oldrid Scott and built in 1884. Re- ordered in 1989 to provide hall accommodation. The church has clay tiled roofs, with flint walling. Roof repairs to
DESIGNATION:	Listed Place of Worship grade II*	the south transept and south chapel, along with associated overhauling of rainwater goods and stone and flint repairs,
CONDITION:	Poor	were completed in 2015 grant-aided jointly by the National Lottery Heritage Fund and Historic England. Further repairs
PRIORITY CATEGORY:	F (C)	are needed to the north aisle roof, rainwater goods and
OWNER TYPE:	Religious organisation	tower stonework.
LIST ENTRY NUMBER:	1079301	Contact: Tracey Craig 020 7973 3756
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Augustine's Avenue, South CroydonDESIGNATION:Listed Place of Worship grade II*CONDITION:PoorPRIORITY CATEGORY:F (C)OWNER TYPE:Religious organisation

Upper Norwood SE19       The church is located on a hill of shrinkable clay an been subject to ongoing differential movement for years which has resulted in substantial cracking, mathematic the south side of the building. Underpinning, stitching in the south aisle was completed in 2017, gaided by the National Lottery Heritage Fund. Fund through Grants for Programmes of Major Works enterprise         OWNER TYPE:       Religious organisation				
DESIGNATION:       Listed Place of Worship grade II*, CA       years which has resulted in substantial cracking, may the south side of the building. Underpinning, stitchi most severe cracks and securing the brick and stor vaulting in the south aisle was completed in 2017, g aided by the National Lottery Heritage Fund. Fund through Grants for Programmes of Major Works er the structural repair of the inner south aisle east w		SITE NAME:	Church of St John, Sylvan Road, Upper Norwood SE19	Built in 1882, designed by John Loughborough Pearson. The church is located on a hill of shrinkable clay and has
PRIORITY CATEGORY:       C (C)         OWNER TYPE:       Religious organisation    validing in the south aisle was completed in 2017, g aided by the National Lottery Heritage Fund. Fund through Grants for Programmes of Major Works e the structural repair of the inner south aisle east w	- AND	DESIGNATION:		years which has resulted in substantial cracking, mainly to the south side of the building. Underpinning, stitching of the
PRIORITY CATEGORY:       C (C)         OWNER TYPE:       Religious organisation		CONDITION:	Poor	most severe cracks and securing the brick and stone
owner IYPE: Religious organisation the structural repair of the inner south aisle east w		PRIORITY CATEGORY:	C (C)	aided by the National Lottery Heritage Fund. Funding
LIST ENTRY NUMBER: 1079275 Contact: Tracey Craig 020 7973 3756		OWNER TYPE:	Religious organisation	through Grants for Programmes of Major Works enabled the structural repair of the inner south aisle east window.
Contact. Tracey Chaig 020 7775 5750	NAME -	LIST ENTRY NUMBER:	1079275	Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England

SITE NAME:	Three of four World War II fighter pens at the former airfield of RAF Kenley		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021242
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	South Norwood, South Norwood, Croydon SE25		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Nicolette Duckham (LPA) 020 8726 6000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Good

C (C)

1079410

Good

C (C)

Fair

F (F)

Private

1079330

1358760

Local authority

Vacant/not in use

Hanwell Community Centre,

Listed Building grade II, CA

Part occupied/part in use

Norwood Hall, Norwood

Listed Building grade II, CA


Part occupied/part in use

Green Road, Southall

Cuckoo Avenue, Hanwell W7

Local authority

EALING



under consideration.

over one of the wings.

Contact: Planning Officer (LPA) 020 8825 5000

Administration block of the former London District

Schools, 1856. The Local Authority carried out major

Management of the building has reverted to the Local Authority. Planning Permission and Listed Building Consent

development centre with a new café, dance studio and community facilities. A long-term business plan has been

formulated to support the new school which has taken

Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and

includes substantial grounds, outbuildings and a walled

garden. The building was used as a horticultural college for several years but is now used as a community centre by the

present owner. Works are ongoing to restore the house

and a new school complex has been built in the grounds.

Contact: Planning Officer (LPA) 020 8825 5000

have been granted for conversion to a learning and

Contact: Planning Officer (LPA) 020 8825 5000

repairs in 2010 and the building is now in good condition.

© Historic England

© London Borough of Ealing

© Historic England

SITE NAME:	Two chapels at South Ealing Cemetery, South Ealing Road W5	The two chapels are linked by a porte cochère with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are too
DESIGNATION:	Listed Building grade II	dangerous to use. An options appraisal and condition survey of the building, funded by the National Lottery
CONDITION:	Poor	Heritage Fund, was completed in 2020. Historic England (April 2023) grant aided proposals for urgent repairs and
OCCUPANCY:	Vacant/not in use	enabling works to help the building accommodate a
PRIORITY CATEGORY:	A (A)	meanwhile use. Planning Permission and Listed Building Consent applications are currently under consideration
OWNER TYPE:	Local authority	(March 2023).
LIST ENTRY NUMBER:	1380227	Contact: Planning Officer (LPA) 020 8825 5000

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site ŴĤS

	SITE NAME:	Twyford Abbey, Twyford Abbey Road NW10 NW10	Gothic country house built 1807-9 by William Atkinson; brick and cement fronted with a crenelated parapet, last
and the second	DESIGNATION:	Listed Building grade II	used as a nursing home. In 2017 some urgent stabilisation works were carried out to the roof and floors, however
	CONDITION:	Poor	more work is needed to get the building wind and weathertight. Consents granted in 2017 for an educational
	OCCUPANCY:	Vacant/not in use	use did not progress and the new owners have been
Constant of	PRIORITY CATEGORY:	B (A)	granted Planning Permission (February 2023) for residential use of the house and site together with a public open
	OWNER TYPE:	Commercial company	space.
toric England	LIST ENTRY NUMBER:	1079383	Contact: Planning Officer (LPA) 020 8825 5000

© Histor



SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall	Former mental asylum of 1829 by William Alderson; extended in 1854-57. Part of the original complex has been
DESIGNATION:	Listed Building grade II	restored for continuing healthcare use. Applications for the conversion of the listed wards to private residential use
CONDITION:	Fair	were approved in 2013 and the site is now partially refurbished. The chapel, ballroom and remaining wards are
OCCUPANCY:	Part occupied/part in use	still vacant but work on these is now in progress.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Health authority	
LIST ENTRY NUMBER:	1079364	Contact: Planning Officer (LPA) 020 8825 5000

© Historic England Archive



Desi	SITE NAME:	Christ the Saviour Church, New Broadway, Ealing W5	Designed by Sir George Gilbert Scott and built 1852. Some additions by G F Bodley. The church was awarded a
	DESIGNATION:	Listed Place of Worship grade II*, CA	grant from the National Lottery Heritage Fund for repair works to the tower; these works were completed in early 2016. The nave and aisle roofs are in need of re-covering.
	CONDITION:	Poor	Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant in 2020 to carry out a
	PRIORITY CATEGORY:	C (C)	condition survey of high-level roofs and gutters along with
	OWNER TYPE:	Religious organisation	some permanent and holding repairs to slates, gutters and rainwater goods.
	LIST ENTRY NUMBER:	1079392	Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Hanwell flight of locks and brick boundary wall of St Bernard's Hospital		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Moated site at Down Barns Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Acton Town Centre, Acton W3		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / EALING / ENFIELD

SITE NAME:	Cuckoo Estate, Hanwell W7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Ealing Town Centre, Ealing W5		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Haven Green, Ealing W5		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000
SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area, 7 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Planning Officer (LPA) 020 8825 5000

#### **ENFIELD**



© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Holly Hill Farmhouse, The SITE NAME: Ridgeway DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1188655

Road

Very bad

A (A)

Private

1079477

North Lodge, Whitewebbs

Listed Building grade II

Vacant/not in use

Mid C19 villa of London stock brick, formerly a farmhouse, with later additions and outbuildings to the rear. The house has been vacant for many years and has suffered from the effects of water ingress, blocked rainwater goods, vegetative growth, broken windows and rotten joinery. The building is now secured, and Historic England and the Local Authority have identified urgent works needed to arrest further decline whilst a decision is made on the future use of the building.

#### Contact: Christine White (LPA) 020 8379 3852

Contact: Christine White (LPA) 020 8379 3852

Small Victorian Gothic stuccoed cottage of one storey and an attic, with a steep-pitched roof of fishscale tiles with barge-boarded gable ends. The building has been empty and neglected for many years and part of the building was subject to unauthorised demolition works for which the Local Authority undertook enforcement action and extensive works to secure and protect the building. Change of ownership is likely to secure the future of the site and discussions are at an early stage with the Local Authority and Historic England.

© Historic England

10	SITE NAME:	Southgate House, High Street NI4	Late C18 house with early C19 extension in similar style, with an elliptical entrance hall. Formerly used as a college, it
	DESIGNATION:	Listed Building grade II*	is now vacant whilst a new use is secured. Water ingress, now halted, has led to outbreaks of dry rot, and vegetation
OC PRIC	CONDITION:	Very bad	growth has hampered ventilation and drainage to the building. Some remedial works were carried out prior to
	OCCUPANCY:	Part occupied/part in use	the sale of the building to a religious organisation. The
	PRIORITY CATEGORY:	A (C)	Local Authority and Historic England are working with the new owner to bring forward a suitable programme of
	OWNER TYPE:	Local authority	urgent repairs needed to stabilise the building.
	LIST ENTRY NUMBER:	1079541	Contact: Verena McCaig 020 7973 3718

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS



© Historic England

© Historia

© Historic England

SITE NAME:	Broomfield House, Broomfield Park, Broomfield Lane N13	C16 house with late C18 additions, situated in a public park. The building is severely fire damaged, although
DESIGNATION:	Listed Building grade II*, RPG grade II	significant parts of the interior are in safe storage. Additional scaffolding works were carried out in 2016 funded by Historic England and the Local Authority.
CONDITION:	Very bad	Following extensive discussions and commissioned reports, further work is being carried out to help inform a decision
OCCUPANCY:	Vacant/not in use	on the future of the building.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1078934	Contact: Verena McCaig 020 7973 3718

ic England	SITE NAME:	Stable block in Broomfield Park, Broomfield Lane N13	Early C18 stable block to Broomfield House. The building is vacant. Internal propping works have been undertaken to
	DESIGNATION:	Listed Building grade II*, RPG grade II	stabilise the floors, and further works carried out following subsequent fire and water damage. Following extensive discussions and commissioned reports, further work is
	CONDITION:	Very bad	being carried out to help inform a decision on the future of the building.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1188544	Contact: Verena McCaig 020 7973 3718



	SITE NAME:	Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road	1870-1 Gothic Revival cemetery chapel. The chapel is in poor condition and in need of an appropriate use. Repairs are required to arrest deterioration of damaged	
	DESIGNATION:	Listed Building grade II	stonework. Minor repairs are planned imminently, and the Local Authority has commenced discussions regarding potential future use of the building.	
	CONDITION:	Poor		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1079458	Contact: Christine White (LPA) 020 8379 3852	

	SITE NAME:	Former Edmonton Girls' Charity School, Church Street, Edmonton N9	Single-storey building, with a central arched doorway to the street and sash windows to either side. Above the doorway is a statuette of a female pupil. Historic England and the Local Authority are working with the current owners and London Historic Buildings Trust to secure a repair project. Potential new users have been identified and initial project development funding secured from the Architectural Heritage Fund and National Lottery Heritage Fund. In the meantime, live-in guardians continue to safeguard the property.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1079547	Contact: Christine White (LPA) 020 8379 3852

Former teacher's accommodation to the adjoining Charity 24, Church Street, Edmonton School. C18 cottage of red brick with renewed pantile N9 roof. Historic England and the Local Authority are working Listed Building grade II, 2 CAs with the current owners and London Historic Buildings Trust to secure a repair project. Potential new users have Poor been identified and initial project development funding Occupied/in use secured from the Architectural Heritage Fund and National Lottery Heritage Fund. In the meantime, live-in guardians C (C) continue to safeguard the property. Religious organisation 1079546 Contact: Christine White (LPA) 020 8379 3852

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

States - States	SITE NAME:	Trent Park House terrace,	Brick and stone terrace reconstructed in the 1920s. The
Contraction of the second seco	SHE MARIE.	Cockfosters Road, Trent Park	terrace is in very poor condition, with temporary propping in place. Vegetation clearance and further propping works were undertaken after additional surveys were carried out in 2015. Full repair and conservation are expected to take place as part of the planned redevelopment of the wider site, which is in progress.
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	
To Market	CONDITION:	Very bad	
All and a second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
and the second s	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1078931	Contact: Christine White (LPA) 020 8379 3852
	SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield	Former Enfield Electricity Works dating from 1906, architect unknown. The building is partially occupied. Extensive works have been undertaken to stabilise the building and make it watertight. However, further works are required to the exterior tilework and masonry to
	DESIGNATION:	Listed Building grade II	
1	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	prevent water ingress and further damage. Future operational options are under consideration for the site
Linamin 11 -	PRIORITY CATEGORY:	С (С)	which will inform its future repair and re-use.
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1389537	Contact: Christine White (LPA) 020 8379 3852
© Historic England		1507557	Contact. Christine White (E17) 020 0577 5052
	SITE NAME:	Barn at Whitewebbs Farm, Whitewebbs Road	Simple, timber-framed barn probably dating from the late C17. Works have been undertaken to prop the building to secure the structure. Planning Permission and Listed Building Consent have been granted for residential conversion. The Local Authority are in discussion with new owners.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
© London Borough of Enfield	LIST ENTRY NUMBER:	1079480	Contact: Christine White (LPA) 020 8379 3852
	SITE NAME:	All Saints Church, Church	C12 in origin, largely rebuilt in the C15 and clad in brick in 1772. Restored in 1855 and 1871 by Ewan Christian and in 1889 by William Gillbee Scott. The church has a Kentish ragstone medieval tower, 1772 brick-faced east and north sides, and stone south and west sides. The church was awarded a grant from the National Lottery Heritage Fund for repair works to the tower which were completed in early 2016. The nave and aisle roofs are in need of re- covering. A fall of stone internally necessitated general investigations and temporary holding repairs until a scheme of work can be prepared.
	DESIGNATION:	Street, Edmonton N9 Listed Place of Worship grade II*, CA	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:		
Colin Kerr (Architect)	LIST ENTITY INOPIDER:	1079548	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Andrew, Church Walk, Enfield	The church and tower have C12 origins, were extended in C15 and C16 (Sir Thomas Lovell), repaired in C18, and restored in C19 (including all new roofs) by variously Lochner, St Anbyn and Scott. It is built of rubble masonry including brick and flint with stone quoins and window dressings. There are fine C15 and C16 monuments but these are deteriorating due to dampness caused by poor
	DESIGNATION:	Listed Place of Worship grade II*, CA	
500 500 - 10 - 10 - 10 - 10 - 10 - 10 -	CONDITION:	Very bad	
		1	

© Historic England

Very bad these are deteriorating due to dampness caused by poor drainage. The leaking tower roof has caused by pool failure in the belfry. Holding repairs are in place and the PRIORITY CATEGORY: A (A) Religious organisation Parish is seeking funding for a comprehensive development and repair project. LIST ENTRY NUMBER: 1079549

Contact: Ian Harper 07974 979620

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG SM
  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Site of Elsynge H	all, Forty Hall		
DESIGNATION:	Scheduled Monument, part in RPG grade II, CA		LIST ENTRY NUMBER:	1002040
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY ?:	No
OWNER TYPE:	ER TYPE: Local authority, multiple ov		CONTACT:	Jane Sidell 020 7973 3738
1/ - Norman I	SITE NAME:	Broomfield Park N13	Early C18 formal gardens associated with Broomfield	
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA	of formal lakes a for use as a publi	ng a walled enclosure focussed on a series nd set within a landscape park. Converted ic park in the early C20 with input from
	CONDITION:	Generally satisfactory but with significant localised problems	bad condition, th	n. The house and stable block are in very ne lakes are in poor condition, and areas o I has been lost to development. Work is
ti : - ine stel	VULNERABILITY:	Medium	being carried out	t to inform a decision on the future of the
and the second design of the s	TREND:	Declining	buildings and stakeholder discussions regarding practic implementation of a Conservation Management Plan for the park are at an early stage.	
© Historic England Archive	NEW ENTRY ?:	No		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1000517	Contact: Christo	pher Laine 020 7973 3473
	SITE NAME: DESIGNATION:	Grovelands Park N14 Registered Park and Garden grade II*, 5 LBs, part in CA	Late C18 landscape park and lake by Humphry Repton, extended in the mid-C19 and laid out as a public park in the early C20 by Thomas Mawson. The mansion and immediate grounds are now a private hospital. The divic ownership of the park between the Local Authority, Thames Water and the hospital has led to differential management regimes. The sports area is in very bad condition with intrusive fencing and redundant structure A Conservation Management Plan requires completion discussions are needed in order to then secure its	
6 Martin	CONDITION:	Generally satisfactory but with significant localised problems		
a staticity	VULNERABILITY:	Medium		
SI MARTALDON	TREND:	Declining		
	NEW ENTRY ?:	No	implementation.	
) Historic England Archive	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000395	Contact: Christo	opher Laine 020 7973 3473
	SITE NAME:	Trent Park	Late CIR landes	ape park further developed in the early
and	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, part in CA	C20 by Sir Philip their approved s the historic lands	Sassoon. Developers are implementing cheme for improvements to the core of scape around the mansion house. There
	CONDITION:	Generally satisfactory but with significant localised problems	owned and mana	t issues in the surrounding parkland, aged by the Local Authority as a country s continue towards improving the inter-
STATE STATES	VULNERABILITY:	Medium	relationship betv	veen the wider park and the historic core.
All Part		Incomessing	A strategy is being developed to produce a Conserva Management Plan to deliver improved management of	ng developed to produce a Conservation
Bell March	TREND:	Improving	Management Pla	n to deliver improved management of the

© Historic England Archive



1000484 Contact: Christopher Laine 020 7973 3473 SITE NAME: Mid-to-late C18 pleasure grounds overlaying C17 formal Forty Hall gardens focussed on Forty Hall, built 1629-36 for Sir Registered Park and Garden Nicholas Rainton, and set within a C18 landscape park DESIGNATION: grade II, 5 LBs, part in SM, CA developed over a CI6 royal palace and associated water gardens. Owned and managed by the Local Authority as a Generally satisfactory but with CONDITION: country park, with the Home Farm and ferme ornée to the significant localised problems west (outside of the registered area) leased to a VULNERABILITY: High horticultural college. A strategy to address lapsed woodland and grassland management, restore the Declining character and legibility of the designed landscape, and improve the condition of individual features is being NEW ENTRY?: No developed. OWNER TYPE: Local authority

Contact: Christopher Laine 020 7973 3473

parkland, woodland and historic water bodies.

#### PRIORITY CATEGORIES

© Historic England Archive

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

LIST ENTRY NUMBER:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

No

1001357

Mixed, multiple owners

obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ENFIELD / GREENWICH

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

SITE NAME: Church Street, Edmonton N9	
DESIGNATION: Conservation Area, 8 LBs NEW ENTRY?: No	
CONDITION: Very bad TREND: No significant char	ige
VULNERABILITY: Low CONTACT: Christine White (I	.PA) 020 8379 3852
SITE NAME: Fore Street, Edmonton N18	
SITE NAME: Fore Street, Edmonton N18	

Gazebo in the grounds of Shrewsbury House, Bushmoor

Listed Building grade II, CA

Crescent SEI8

Vacant/not in use

Local authority

Poor

D (C)

# GREENWICH

© Historic England



	SITE NAME:	Garden House to south east of Rush Grove House, Rush Grove Street SE18	Late C18 or early C19 octagonal building with pointed slate roof of moderate pitch. The walls are set back to provide an open loggia with round wooden arches set in trellis.
The second	DESIGNATION:	Listed Building grade II, CA	Extensive loss of tiles from the roof has led to considerable water ingress. The building is suffering from a prolonged
Design of	CONDITION:	Very bad	lack of maintenance and is deteriorating rapidly. Efforts to contact the owners have not yet been successful and the
	OCCUPANCY:	N/A	Local Authority is considering taking enforcement action.
A STATE	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1289930	Contact: Conservation Team (LPA) 020 8921 5355





© Historic	England



LIST ENTRY NUMBER:	1409363	Contact: Conservation Team (LPA) 020 8921 5355
SITE NAME:	Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Large conservatory built in 1889 in a classical style, with domed glass roofs and surmounted by a figure of Mercury. The wider site has been sold for new educational use. The
DESIGNATION:	Listed Building grade II	building was deteriorating due to blocked rainwater goods and lack of maintenance. The owner has now carried out
CONDITION:	Fair	urgent works and comprehensive roof repairs to improve the building's condition and ensure it is watertight. Joinery
OCCUPANCY:	Part occupied/part in use	repairs to all three glasshouses are now complete and lead
PRIORITY CATEGORY:	E (C)	to the main dome has been completely replaced. Discussions are continuing to secure the future
OWNER TYPE:	Educational (state sector)	management and use of the building.
LIST ENTRY NUMBER:	1079082	Contact: Conservation Team (LPA) 020 8921 5355

Brick gazebo with a hipped tile roof, and round-headed

subsidiary features in the grounds of the grade II listed early C20 country house, Shrewsbury House. Whilst joinery and

brickwork appear to be largely intact, the significant loss of tiles from the roof and inadequate or missing rainwater

goods are contributing to its serious decline. A temporary

and a condition survey undertaken to inform a programme

roof was erected summer 2022 to prevent water ingress

of repairs. Consents were given for works to include the

replacement of the roof covering

multi-pane windows and entrance, one of several

D

Е

	SITE NAME:	Garden House to north west of Charlton House, Charlton Road, Charlton SE7	Small red brick garden house with undercroft and high pyramidal swept roof, dating from the mid to late C17 and attributed to Inigo Jones. In the 1930s the building was
	DESIGNATION:	Listed Building grade I, CA	adapted for use as public toilets, and it was for many years redundant once they ceased in use. The Royal Greenwich
	CONDITION:	Fair	Heritage Trust commissioned a condition survey and heritage assessment which informed a recently completed
	OCCUPANCY:	Vacant/not in use	development project funded by Historic England. This
	PRIORITY CATEGORY:	F (F)	project was designed to make the building secure and weathertight and to facilitate a meanwhile use. The Trust is
	OWNER TYPE:	Charity (heritage)	considering next steps.
	LIST ENTRY NUMBER:	1291892	Contact: Verena McCaig 020 7973 3718

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / GREENWICH

	S
- A HI	D
	C
	C
	Ρ
	C

A STATE	SITE NAME:	95A, Eltham High Street, Eltham SE9	C17 or earlier stable building with three diagonal chimney shafts. Although the building has been made weathertight,
DESIGNATION:	Listed Building grade II	it is showing signs of a lack of maintenance. It is currently in residential use. The building was the subject of pre-	
and the second	CONDITION:	Poor	application discussions in early 2022 for its repair, refurbishment and alteration. However, a full application
OCCUPANCY:	OCCUPANCY:	Occupied/in use	has not been received.
The survey	PRIORITY CATEGORY:	C (C)	
01	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1219821	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England

© Historic England



SITE NAME:	Forecourt railings and gates to Red Barracks, and Gate Lodge, Frances Street, Woolwich SE18	Railings, entrance gateway and lodge to the former Red Barracks (1858-60 but now demolished). Structural repairs and repointing to the small watch tower to the north were
DESIGNATION:	Listed Building grade II	completed in 2013. The railings, piers, and gate piers are generally in good condition. The gate lodge is in very poor
CONDITION:	Very bad	ondition, although the Local Authority has removed debris and most of the vegetation threatening the building.
OCCUPANCY:	Vacant/not in use	However, the main structure is derelict and continues to
PRIORITY CATEGORY:	C (C)	deteriorate. The Local Authority and Historic England are in discussion regarding potential approaches to secure its
OWNER TYPE:	Local authority	repair and new use.
LIST ENTRY NUMBER:	1358950	Contact: Conservation Team (LPA) 020 8921 5355



© Historic England

	LIST ENTRY NUMBER:	1358950	Contact: Conservation Team (LPA) 020 8921 5355
	SITE NAME:	The Rotunda, Green Hill, Woolwich Common SE18	24-sided polygon, single-storey building designed by John Nash. Concave conoid roof. First erected in the grounds of
	DESIGNATION:	Listed Building grade II*, CA	Carlton House in 1814 for (premature) celebration of Allied victory in the Napoleonic Wars. The Rotunda
	CONDITION:	Very bad	housed the reserve collection of the 'Firepower' museum but is now vacant. The roof covering is leaking, and
	OCCUPANCY:	Vacant/not in use	extensive propping works and investigations have been
	PRIORITY CATEGORY:	A (A)	undertaken to stabilise the structural roof timbers prior to discussions commencing to secure the long-term future of
	OWNER TYPE:	Government or agency	the building.
	LIST ENTRY NUMBER:	1078987	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	24, Royal Hill, Greenwich SE10	Early C18 small urban house of central chimneystack plan,		
The state	DESIGNATION:	Listed Building grade II, CA	the smallest known example of the 1703 Moxon Plan. The building has been vacant for some years and is in poor		
	CONDITION:	Poor	condition. A scheme for restoration and conversion was agreed in 2011-2012 but, although works were started,		
BO I	OCCUPANCY:	Vacant/not in use	they were halted for some years. Following discussions		
	PRIORITY CATEGORY:	D (D)	with the Local Authority and Historic England, the own re-commenced internal works, but this has been spora		
	OWNER TYPE:	Private			
and the second	LIST ENTRY NUMBER:	1391248	Contact: Conservation Team (LPA) 020 8921 5355		

© Royal Borough of Greenwich



D

Е

SITE NAME:	Church of St Saviours, Middle Park Avenue, Eltham SE9	This vast church of purple brick and shallow concrete roofs was built in 1932 to the designs of Cachemaille-Day and is
DESIGNATION:	Listed Place of Worship grade II	largely unaltered since then. The RIBA gold medal was awarded for the design in 1933. The vicarage was built ir 1960. The church has always suffered from having intern rainwater pipes and from poor access for high-level maintenance. Roof coverings were repaired in late C20 I are now in need of renewal. Windows to the Lady Chap are decayed and high-level plasterwork partially removed
CONDITION:	Poor	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1212904	The church is seeking funding for emergency repairs and health and safety works.

Contact: Ian Harper 07974 979620

© Photo © Stephen Craven (cc-bysa/2.0)

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

Woolwich SEI8

Religious organisation

Poor

C (C)

1212426



This church in the Gothic style was completed by AW Roman Catholic Church of St Pugin in 1843. It is listed together with detached school Peter, Woolwich New Road, buildings on the south side, completed a decade later by EW Pugin. The external masonry and roofing of the Listed Place of Worship grade II church, along with internal plastered ceilings, were repaired in 2017 with a grant from the National Lottery Heritage Fund. The condition of the adjacent two-storey school buildings is poor; the upper hall is closed due to structural problems and roof leaks. The congregation is now seeking funding to repair the school buildings to bring them back into use.

© Historic England



Contact: lan Harper 07974 979620 Man-made training landscape established in the early C19 SITE NAME: **Repository Woods SE7** for pupils of the Royal Military Repository at Woolwich to Registered Park and Garden practice and display artillery exercises on purpose-built DESIGNATION: grade II, part in SM, part in CA earthworks and ponds. With formal planting and paths, it also offered publicly accessible pleasure grounds and Generally unsatisfactory with CONDITION: military showcase, and the setting for the adjacent major localised problems Rotunda. Military use continues and an angling club uses VUI NERABII ITY: High the main pond. Active management of the site has lapsed and key structures and features are being lost to woodland TREND: Declining succession. There is no Conservation Management Plan and the site's future is uncertain. NEW ENTRY ?: Yes OWNER TYPE: Government or agency LIST ENTRY NUMBER: 1001717 Contact: Christopher Laine 020 7973 3473

© Historic England Archive

SITE NAME:	Charlton Village SE7		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Conservation Team (LPA) 020 8921 5355
SITE NAME:	Thames Barrier and Bowater Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Conservation Team (LPA) 020 8921 5355
SITE NAME:	Woolwich Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Conservation Team (LPA) 020 8921 5355

# HACKNEY

© Historic England



D

Е

SITE NAME:	25 and 27, Hackney Grove E8 E8
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1226756

Early C19 pair of three-storey townhouses. They have been vacant since about 2016. Although Planning Permission and Listed Building Consent were granted in 2017 for works in connection with conversion for use as a school, the scheme has not been implemented and the buildings have fallen into disrepair. The building was illegally occupied, causing damage to historic fabric. A lack of maintenance has caused the roof and rainwater goods to fail and water is now penetrating the building. The Local Authority is in discussion with the owners to secure urgent repairs.

Contact: Adam Dyer ( LPA) 07543 509082

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	98 and 98a, Clapton Common (also known as I-4 Belz Terrace) E5	Regency stucco-fronted villa of 1825 with central portico entrance and pairs of curved bay windows, facing onto the nearby common. It was used as a home for destitute
	DESIGNATION:	Listed Building grade II, CA	children in C19 and converted into flats in 1928, becoming a school in about 1985. There are longstanding unlawful
	CONDITION:	Very bad	works and the building suffered a fire in 2017. Planning Permission and Listed Building Consent were granted for
0 7	OCCUPANCY:	Vacant/not in use	repairs and extensions as a school in 2018, and works hav
La commence file	PRIORITY CATEGORY:	C (C)	commenced. However, the building is still deteriorating, and the Local Authority has since taken enforcement
	OWNER TYPE:	Religious organisation	action.
© Historic England	LIST ENTRY NUMBER:	1226457	Contact: Adam Dyer ( LPA) 07543 509082




5 10	SITE NAME:	175, Stoke Newington Church Street N16	Mid C18 two-storey building of brown brick with red brick dressings, cornice band and parapet, and sash windows,
	DESIGNATION:	Listed Building grade II, CA	with mid-late C19 projecting ground floor shop. The roof is leaking and there are structural issues in evidence, although
	CONDITION:	Poor	the building is propped in places. The building is generally a very poor condition and there are areas of dry rot. Planning Permission and Listed Building Consent were granted in January 2020 for a scheme to repair the buildin and bring it back into use as a shop and office, with mode
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (D)	
	OWNER TYPE:	Private	extensions to the roof and rear. However, this has not been implemented.
	LIST ENTRY NUMBER:	1235427	Contact: Adam Dyer ( LPA) 07543 509082



© London Borough of Hackney

SITE NAME:	179, Stoke Newington Church Street N16	The western half of a mid C18 house, converted to shops in C19. The building, including an unusual C19 extension to
DESIGNATION:	Listed Building grade II, CA	the rear side, was in use as a Chinese restaurant at ground floor level with staff accommodation above. Planning
CONDITION:	Poor	Permission was granted for conversion and extension to the rear to form a shop and flats in 2018, but the scheme
OCCUPANCY:	Vacant/not in use	has yet to be implemented. There are both structural and
PRIORITY CATEGORY:		asbestos issues. The building has been vacant for several years and is in poor condition.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1235521	Contact: Adam Dyer ( LPA) 07543 509082





	SITE NAME:	Cleeve Workshops, Calvert Avenue E2	Row of workshops built 1895-8 to the design of Reginalc Minton Taylor of London County Council as part of the
	DESIGNATION:	Listed Building grade II, CA	Boundary Estate. All the workshops are in use and some repair and security works have taken place. Listed Building
Th	CONDITION:	Fair	Consent was previously granted in 2019 for their refurbishment, and partially implemented. The Local Authority has taken enforcement action against multiple
The	OCCUPANCY:	Occupied/in use	
-	PRIORITY CATEGORY:	D (D)	incidences of unlawful works. Planning Permission and Listed Building Consent applications for a revised repair
3	OWNER TYPE:	Private	and refurbishment scheme are under consideration.
	LIST ENTRY NUMBER:	1264906	Contact: Adam Dyer ( LPA) 07543 509082

© London Borough of Hackney

PRIORITY	CATEGORIES
----------	------------

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious powy user (coplicable only obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	7, Clapton Square E5	Early C19 terraced house. Listed Building Consent was
	DESIGNATION:	Listed Building grade II, CA	granted for the restoration and conversion of the building to accommodate three flats. However, the building
	CONDITION:	Fair	suffered from inappropriate and unauthorised works and the Local Authority took enforcement action. The
	OCCUPANCY:	Occupied/in use	property was sold in autumn 2019 and the new owner has
	PRIORITY CATEGORY:	F (F)	submitted applications for Planning Permission and Listed Building Consent to rectify the unauthorised works, and
	OWNER TYPE:	Private	these are now being considered.
-db-	LIST ENTRY NUMBER:	1226411	Contact: Adam Dyer ( LPA) 07543 509082

© London Borough of Hackney



4	SITE NAME:	Forecourt wall and railings, 25, Hackney Grove E8	Early C18 brick wall with square pier at end and contemporary wrought iron railings with spearhead
	DESIGNATION:	Listed Building grade II, CA	standards and urn finials. The building to which they relate is vacant and not being maintained. Repairs are required.
TH	CONDITION:	Poor	
1	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1265682	Contact: Adam Dyer ( LPA) 07543 509082

© Historic England



Anglican school and house for nuns built in 1898 to the SITE NAME: Sisters' House and School to St design of James Brooks. This completed the collegiate Columba's Church, Kingsland Road NI assemblage of his church and vicarage (both separately on the Heritage at Risk register) completed in 1869. Leased to DESIGNATION: Listed Building grade II\*, CA a Christian group. Full condition surveys have been carried out funded by Covid19 Emergency Héritage at Risk CONDITION: Very bad Response Fund grants and the Diocese of London. Urgent repairs are required to the roofs, brickwork and railings. OCCUPANCY: Part occupied/part in use Discussions are on-going regarding future appropriate uses PRIORITY CATEGORY: A (A) and sources of funding. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1265691 Contact: lan Harper 07974 979620

SITE NAME: St Columba's Vicarage and link Gothic Revival vicarage built 1873-4 to the design of James Brooks. The vicarage forms part of a larger group of listed to church, Kingsland Road E2 buildings by the same architect, including the church and DESIGNATION: Listed Building grade I, CA Sisters' House. A condition survey in 2018 and more recent drone and drainage surveys funded by Covid19 CONDITION: Very bad Heritage at Risk emergency grants and the Diocese of OCCUPANCY. Part occupied/part in use London have highlighted the seriousness of the condition. Discussions in 2019 led to an application for Listed Building PRIORITY CATEGORY: A (A) Consent in early 2020 for repairs and development. These discussions are on-going and architects have been OWNER TYPE: Religious organisation appointed. Funding is being sought. LIST ENTRY NUMBER: 1265658 © Historic England Archive Contact: lan Harper 07974 979620 SITE NAME C18 terraced house with a shop on the ground floor and EQ2 Kingsland Da 

	SITE NAME:	592, Kingsland Road E8	Croterraced house with a shop on the ground hoor and
	DESIGNATION:	Listed Building grade II, CA	vacant upper floors. Listed Building Consent was granted in 2008 and again in 2018 for rebuilding the upper parts of the
	CONDITION:	Poor	north and east wall following structural problems. These works were completed in March 2020. However, the roof
	OCCUPANCY:	Part occupied/part in use	is still in poor condition with signs of water ingress and
	PRIORITY CATEGORY:	C (C)	unlawful sub-divisions throughout the property, and the Local Authority is continuing with enforcement action.
-	OWNER TYPE:	Private	· · ·
	LIST ENTRY NUMBER:	1226776	Contact: Adam Dyer ( LPA) 07543 509082

© London Borough of Hackney

5H0E9

D

Е

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



© London Borough of Hackney

© Historic England Archive

k	SITE NAME:	Portico to former London Orphan Asylum, Linscott Road E5	The remaining part of the London Orphan Asylum, circa 1823 by WS Inman. The rest of the building was demolished in 1975 and the portico was derelict until 2003.
	DESIGNATION:	Listed Building grade II	It now consists of an entrance portico with colonnades. Behind the entrance is a computer centre by Brady
	CONDITION:	Fair	Mallalieu from 2005 on the site of the former chapel. The building was associated with the nearby Clapton Girls
	OCCUPANCY:	Part occupied/part in use	Academy until 2017. Planning Permission and Listed
	PRIORITY CATEGORY:	D (D)	Building Consent were granted in 2021 for a scheme to extend and convert the building into a medical surgery, but
	OWNER TYPE:	Local authority	the scheme has not yet been implemented.
	LIST ENTRY NUMBER:	1265630	Contact: Adam Dyer ( LPA) 07543 509082

New Lansdowne Club, 195,

Listed Building grade II\*, CA

Part occupied/part in use

Mare Street E8

Fair

F (F)

Private

1265590

Substantial detached house, dating from 1699. Planning Permission and Listed Building Consent were granted in 2018, subject to a Section 106 agreement, to convert the house to offices, with enabling residential development to the rear. Consent for change of use to a single dwelling with community use with public access in the basement has now been approved and further applications for alterations are expected. Major repairs are largely complete, and all enforcement issues resolved.

Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5	Disinfecting station built in 1900 by Gordon and Gunton for Hackney Borough Council. The building is in very poor
	DESIGNATION:	Listed Building grade II	condition following years of water ingress. A number of surveys and reports have been undertaken in order to
	CONDITION:	Very bad	better understand the building's significance and condition. Asbestos and stored items have been cleared. Emergency
	OCCUPANCY:	Vacant/not in use	repairs and mothballing works have largely been completed, including propping to unstable areas. The Local Authority is in discussions with internal and external
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	stakeholders regarding its restoration and to identify and secure a new use.
© London Borough of Hackney	LIST ENTRY NUMBER:	1253493	Contact: Adam Dyer ( LPA) 07543 509082

SITE NAME:	Rossendale Street (east side) E5 suffered from flooding. Planning Pern	Air raid shelter built in 1938. The building has previously suffered from flooding. Planning Permission and Listed
DESIGNATION:	Listed Building grade II	Building Consent were granted in 2004 for the retention of the air raid shelter as a museum and the construction of
CONDITION:	Fair	flats above. These works are largely complete and the flats occupied. However, the ownership of the Air Raid
OCCUPANCY:	Vacant/not in use	Precaution Centre is uncertain, and the space is currently
PRIORITY CATEGORY:	E (E)	used for storage.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1235876	Contact: Adam Dyer ( LPA) 07543 509082

© London Borough of Hackney



D

Е

EIST EINTRE ROTBER.	1255070	Contact: Adam Dyer ( Li A) 07545 507002
SITE NAME:	Walls and gates to Bishopsgate Goods Station, Shoreditch High Street El	Late C19 walls to the demolished goods station. The gates were repaired some years ago and are now in situ beneath the hoarding. The repair of the listed wall forms part of a
DESIGNATION:	Listed Building grade II	large redevelopment proposal for the entire Bishopsgate Goodsyard site, which was approved by the Mayor of
CONDITION:	Poor	London in 2020. Works have yet to commence on site.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1235316	Contact: Adam Dyer ( LPA) 07543 509082

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:

DESIGNATION:

CONDITION:

LIST ENTRY NUMBER:

	SITE NAME:	187, Shoreditch High Street EI	Early C18 terraced house with an altered facade. The roof,
	DESIGNATION:	Listed Building grade II, CA	front elevation and windows have been restored and the building is now weathertight. A new shopfront has also
	CONDITION:	Fair	been fitted. The future use of the building forms part of a wider development scheme currently being implemented.
	OCCUPANCY:	Vacant/not in use	wider development scheme currently being implementer
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1235320	Contact: Adam Dyer ( LPA) 07543 509082
and the second s			

Mortuary Chapel, Stoke

Park Cemetery NI6

grade II, CA

1235838

Fair

Newington High Street, Abney

Listed Building grade II, RPG

© London Borough of Hackney



SITE NAME:	Shrubland Road Evangelical Church, Shrubland Road E8	A rare and complete example of a temporary iron mission church built in 1858. The building is now clad in corrugated
DESIGNATION:	Listed Building grade II, CA	asbestos sheeting. The building is in use occasionally as a church. The property is currently advertised for sale.
CONDITION:	Fair	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1245303	Contact: Adam Dyer ( LPA) 07543 509082

Gothic Revival cemetery chapel, dating from 1839. The

A first phase of repairs to the roof, spire and high-level stonework was completed in 2017, with funding from

has been awarded significant funding from the National Lottery Heritage Fund for a project to improve the

cemetery landscape. This includes a second phase of

Contact: Adam Dyer (LPA) 07543 509082

chapel is situated in the centre of the early C19 cemetery.

Hackney Council and Historic England. The Local Authority

© Historic England



© Historic England



OCCUPANCY: repairs to the chapel including underpinning and new Part occupied/part in use windows, enabling it to be used for community uses and PRIORITY CATEGORY: F (F) events. Works are on-going on site. OWNER TYPE: Local authority LIST ENTRY NUMBER: 1265023 Contact: Adam Dyer (LPA) 07543 509082 Public baths and swimming pool, dating from 1904. The SITE NAME: Haggerston Baths, Whiston Road E2 building is vacant and in a state of disrepair. Following a competitive bidding process and public consultation, the DESIGNATION: Listed Building grade II Local Authority selected a developer in 2017 to repair the building and bring it back into use. Planning Permission and CONDITION: Poor Listed Building Consent have been granted for a scheme OCCUPANCY: involving restoration and re-purposing as community space, Vacant/not in use workshops, café, gym and other uses, with demolition of PRIORITY CATEGORY: D (D) part of the building and erection of a new six-storey office building. Works have yet to commence. OWNER TYPE: Local authority

© Historic England



	SITE NAME:	Church of St Andrew, Bethune Road, Stoke Newington N16	The church was built in 1883-4 by Sir Arthur Blomfield in the Early English style, using Kentish ragstone with Bath stone dressings. Although plain externally, the interior is richly decorated. Two phases of repairs are complete,
	DESIGNATION:	Listed Place of Worship grade II*	
	CONDITION:	Poor	funded by the National Lottery Heritage Fund. The nave and aisle roofs are repaired and also external masonry and
	PRIORITY CATEGORY:	F (F)	windows to clerestory and west wall. A third and final
	OWNER TYPE:	Religious organisation	phase of roofing repair is required to the transepts and chancel roofs and related masonry.
AW	LIST ENTRY NUMBER:	1264896	Contact: Ian Harper 07974 979620

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM

ΪA Unitary Authority World Heritage Site WHS

T	SITE NAME:	Church of St Chad, Dunloe Street, Hackney E2	Church by Victorian Gothicist architect James Brooks, completed in 1869 to provide for rapidly expanding but
1	DESIGNATION:	Listed Place of Worship grade I	poor suburbs. The adjacent vicarage dates from 1874. The church is high and lofty, with plain detailing in red brick and
5 C AN	CONDITION:	Poor	contrasting with Bath stone dressings under slated roofs. The vicarage, transept roofs and north nave brickwork
	PRIORITY CATEGORY:	A (A)	were repaired in the late C20. More repairs are needed to
THA	OWNER TYPE:	Religious organisation	brickwork and rainwater goods, and the timber bellcote above the crossing is in urgent need of assessment and
A Carton	LIST ENTRY NUMBER:	1265793	repair. The church is actively seeking funding.
			Contact: Ian Harper 07974 979620

© Historic England

n n



DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	SITE NAME:	Christ Apostolic Church (formerly St Columba), Kingsland Road, Hackney E2	The parish church was built in the Gothic Revival style in 1868-9 by James Brooks and the mortuary chapel was added in 1904-5 by E Geldart. It forms an enclosed
	DESIGNATION:	Listed Place of Worship grade I, CA	courtyard with the vicarage and Sisters' House, listed separately. Construction is in red brick with Bath stone dressings. A drone survey has confirmed serious decay i the high-level lantern above the central tower and the rainwater goods; a drainage survey was funded in 2020
	CONDITION:	Poor	
	A (A)	Covid-19 Emergency Heritage at Risk Response Fund	
	OWNER TYPE:	Religious organisation	grant. The Diocese and the congregation are discussing future management of the church and the site.
	LIST ENTRY NUMBER:	1226862	Contact: Ian Harper 07974 979620

© Historic England



Only the crypt (c1777), the tower and belfry (1827) SITE NAME: Church of St Thomas, Old Hill Street, Clapton Common N16 survived World War II bomb damage in December 1940. The church was re-opened in October 1958 to designs by Listed Place of Worship grade II, NF Cachemaille-Day; he incorporated the apse from DESIGNATION: CA William Burges's remodelling in 1873 and the 1921 World War I memorial. The asphalt finish of the reinforced CONDITION: Poor concrete roof slab has been much repaired over previous decades, raising concerns about the structural integrity of PRIORITY CATEGORY: A (A) the roof. The congregation is seeking funding for a repair OWNER TYPE: Religious organisation project and has commissioned a development appraisal. LIST ENTRY NUMBER: 1265859 Contact: lan Harper 07974 979620

© Historic England

	SITE NAME:	Church of St John the Baptist, Pitfield Street, Hackney NI	St John the Baptist, a Commissioners' church funded under the 1818 Act, was completed in 1826 by Francis Edwards,
	DESIGNATION:	Listed Place of Worship grade II*	a pupil of Sir John Soane. Built of stock bricks contained within limestone dressings under a slated roof, the spacious
	CONDITION:	Poor	interior has galleries on three sides and a fine early C20 painted ceiling by J A Reeve. The tower and galleried
	PRIORITY CATEGORY:	C (C)	cupola at the west end have structural problems due to the rusting of embedded cramps. These are causing jacking in the masonry above roof level, which needs to be
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1235285	addressed.
			Contact: Ian Harper 07974 979620

© Historic England



SITE NAME:	Church of the Ark of the Covenant, Rookwood Road, Stoke Newington N16	The church, located at the north end of Clapton Common in Hackney, was designed by Joseph Morris and Sons for the Agapemonite Church and finished in 1895. Carvings or
DESIGNATION:	Listed Place of Worship grade II*	the west tower were by A G Walker, and the window glass was designed by Walter Crane. The building passed
CONDITION:	Poor	to the Catholic Church 1956 -2007, and then to the Georgians. External elevations are in squared rubble
PRIORITY CATEGORY:	A (A)	ragstone; at some time hard cement pointing has led to
OWNER TYPE:	Religious organisation	stone decay. The plain clay roof tiles are slipping off and have caused plaster falls in the nave.
LIST ENTRY NUMBER:	1235310	Contact: Ian Harper 07974 979620

© Historic England

# PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ŬA
- Unitary Authority World Heritage Site WHS



SITE NAME: St Barnabas was built as a Mission church between 1910 Church of St Barnabas, and 1911 by Professor Sir Charles Reilly. Constructed in Shacklewell Row, Hackney E8 mass brickwork it was roofed in concrete vaults on steel Listed Place of Worship grade reinforcement, finished in asphalt and set behind parapets. DESIGNATION: II\*, CA The roof was repaired with a grant from the National Lottery Heritage Fund and Historic England in 2014 but the CONDITION: Poor design of the rainwater disposal system cannot discharge PRIORITY CATEGORY: storm water sufficiently and the condition is poor again, A (A) with leaking parapet gutters causing damage to the OWNER TYPE: Religious organisation structure. Uncontrolled tree growth along boundaries is also damaging the church. LIST ENTRY NUMBER: 1265135

© Historic England



© Historic England Archive

			Contact: Ian Harper 07974 979620
	SITE NAME:	Church of St Leonard, Shoreditch High Street, Shoreditch EI	Built 1740 to the design of George Dance the Elder. Constructed in brick with a Portland stone facade and dressings, and slate roofs. The roofs to the north and south
	DESIGNATION:	Listed Place of Worship grade I, CA	aisles and the flat roofs either side of the tower have been repaired with funding from the National Lottery Heritage Fund and Historic England. The nave roof was re-slated in
	CONDITION:	Poor	2017 with funding from the Listed Places of Worship Roof Repair Fund. Repairs were completed in 2019 to the
	PRIORITY CATEGORY:	A (A)	tower, pediment, columns and portico roofs, and
	OWNER TYPE:	Religious organisation	temporary repairs were made to the spire, grant-aided by the National Lottery Heritage Fund.
	LIST ENTRY NUMBER:	1235382	Contact: Tracey Craig 020 7973 3756



The old parish church of St Mary dates from 1563. It was SITE NAME: Old Church of St Mary, Stoke restored in 1827-29 by Charles Barry who added the Newington Church Street, clerestory, the spire and the outer north aisle, Stoke Newington N16 subsequently lost in WWII. The exposed soft brick of the Listed Place of Worship grade north wall is weathering badly. In 2017 the south aisle roof DESIGNATION: II\*, CA was repaired with a grant from the Listed Places of Worship Roof Repair Fund. Further work is needed to deal CONDITION: Poor with dampness and investigate and monitor worsening PRIORITY CATEGORY: A (A) structural movement of the ceiling. In 2020 Historic England awarded a Covid-19 Emergency Heritage at Risk OWNER TYPE: Religious organisation Response Fund grant for repairs to the tower windows. LIST ENTRY NUMBER: 1235419 Contact: lan Harper 07974 979620

The Church of St Michael and All Angels was designed by SITE NAME: Church of St Michael and All IEK Cutts and completed in 1884. It was listed at grade II Angels N16 on 15 December 2021. Although typical of his many robust Listed Place of Worship grade II, Gothic Revival church designs, this one employed cast DESIGNATION: CA concrete to imitate stone for all the window and other dressings, including the tracery of the East window. The CONDITION: Poor church has suffered structural movement in the past and PRIORITY CATEGORY: the chancel arch and west porch were underpinned in 1994 C(C)and 1997 respectively. Of major concern is the instability of OWNER TYPE: Religious organisation the west wall, and this will need careful monitoring and assessment. LIST ENTRY NUMBER: 1476310 Contact: lan Harper 07974 979620

© Historic England

© Historic England



SITE NAME:	Church of St Matthias, Wordsworth Road, Stoke Newington N16	The church was completed in 1851 to an innovative design by William Butterfield in free Gothic style. Stock brick with Bath stone dressings. Repairs to the nave roof and
DESIGNATION:	Listed Place of Worship grade I	rainwater goods were completed in May 2015 with funding from the National Lottery Heritage Fund and Historic
CONDITION:	Poor	England. Another phase of work is required to the aisle roofs, as well as the roof, belfry louvers and masonry of the
PRIORITY CATEGORY:	C (C)	tower. The church is seeking funding for project
OWNER TYPE:	Religious organisation	development and repair.
LIST ENTRY NUMBER:	1265031	Contact: Ian Harper 07974 979620

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HACKNEY / HAMMERSMITH AND FULHAM

	SITE NAME:	Abney Park Cemetery N16	Laid out as an arboretum cemetery in 1840 from the
	DESIGNATION:	Registered Park and Garden grade II, 18 LBs, part in CA	gardens of two C17 houses, Abney Park is one of London's most important Nonconformist cemeteries. Features of the historic designed landscape survive but are in poor
	CONDITION:	Generally satisfactory but with minor localised problems	condition and, in places, illegible. A Development Board is using a Conservation Management Plan to guide future management and maintenance, and volunteers continue to
	VULNERABILITY:	Low	carry out improvements. The Local Authority, with
	TREND:	Improving	partners, is implementing a major restoration project with grant funding from the National Lottery Heritage Fund and
	NEW ENTRY?:	No	the National Lottery Community Fund.
ngland Archive	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1000789	Contact: Christopher Laine 020 7973 3473

SITE NAME:	Mare Street, Hackney Central E8		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Adam Dyer ( LPA) 07543 509082
SITE NAME:	Sun Street, City of London EC2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Adam Dyer ( LPA) 07543 509082
	2011		

# HAMMERSMITH AND FULHAM

	SITE NAME:	Draped woman sculpture, North Verbena Gardens W6	Cast concrete sculpture, circa 1959 by Karel Vogel, situated in an open space off the Great West Road. It was
	DESIGNATION:	Listed Building grade II, CA	an early commission of the London County Council's Patronage of the Arts scheme, unusually commissioned
	CONDITION:	Poor	provide visual amenity in compensation for a major road scheme. The cast concrete is cracking, damaged by rusting
	OCCUPANCY:	N/A	structural iron elements, and past repairs are both unsight
ALE DESCRIPTION	PRIORITY CATEGORY:	C (C)	and failing. A condition survey has been carried out, funded by local amenity groups. Local Authority funding is in place
	OWNER TYPE:	Local authority	to undertake further investigations prior to planning for full repair.
storic England	LIST ENTRY NUMBER:	1431422	Contact: Adam O'Neill (LPA) 020 8753 3318

© Hist

© Historic En



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER

© Historic England



SITE NAME:	Number 2 Gasholder, Former Fulham Gas Works, Imperial Road SW6	Gasholder dating fro oldest surviving gash single lift wrought irc
DESIGNATION:	Listed Building grade II*, CA	standards in tripod fo Gas Works site has b
CONDITION:	Very bad	Planning Permission f with a \$106 Agreeme
OCCUPANCY:	N/A	investigatory works.
PRIORITY CATEGORY:	C (C)	the results will help in purposing of the gash
OWNER TYPE:	Commercial company	developer, Local Aut
LIST ENTRY NUMBER:	1261959	Contact: Verena Mc

Reception House, Hammersmith Cemetery,

Poor

N/A

C (C)

1436663

Local authority

Margravine Road W6

Listed Building grade II, CA

om 1830, and considered to be the nolder in the world. It consists of a on holder, with cast iron guide form and wrought iron framework. The been decommissioned. Outline for redevelopment has been obtained, nent to secure protective and Preliminary works are underway, and inform the future restoration and resholder on site in consultation with the thority and Historic England.

Caig 020 7973 3718

Single-storey octagonal brick building with a slate roof, circa 1869, probably by George Saunders, built to provide temporary resting places for bodies prior to burial. The rainwater goods are inadequate and failing, leading to deterioration of stone dressings, brickwork and mortars. The Friends of Margravine Cemetery funded a costed condition survey. The Local Authority has commissioned consultants to advise on repair and conservation works, and is working with the Friends of Margravine Cemetery and Historic England to identify appropriate funding sources.

Contact: Adam O'Neill (LPA) 020 8753 3318

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no
  - obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
  - Local Planning Authority National Park NP
  - RPG
  - Registered Park and Garden Scheduled Monument SM

UÁ

Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HAMMERSMITH AND FULHAM

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Harwath Mausoleum, St

Thomas Of Canterbury

Listed Building grade II, CA

Circular garden building,

Hammersmith Road

Vacant/not in use

Local authority

Listed Building grade II

boundary wall and railings, formerly to St Paul's School,

Churchyard SW6

Poor

N/A

C (C)

Unknown

1463196

Very bad

C (C)

the state	SIT
	DE
	СС
	00
THE HE AND	PR
a line	0\

SITE NAME:	Refreshment Room, Ravenscourt Park W6	Former stable block of C18 Ravenscourt Park House, partially demolished and converted into a refreshment
DESIGNATION:	Listed Building grade II, CA	room late C19. Recently used as a park tea room, it has been vacant since the end of 2019. The roof is failing,
CONDITION:	Fair	exacerbated by heritage crime and subsequent water ingress, and needs replacing, along with rainwater goods.
OCCUPANCY:	Vacant/not in use	One floor is inaccessible owing to previous layout
PRIORITY CATEGORY:	E (E)	interventions. The Local Authority has undertaken extensive external repairs to the building in preparation for
OWNER TYPE:	Local authority	return to use as a tea-room.
LIST ENTRY NUMBER:	1358588	Contact: Adam O'Neill (LPA) 020 8753 3318

© Historic England

© Historic England



	SITE NAME:	Tomb of Abraham Smith, Hammersmith Cemetery, Margravine Road W6	White marble monument with a tall, enriched cross surmounting a rubble-carved base circa 1923, by CJ Jordan & Son, Acton, dedicated to a gold prospector. The surface
	DESIGNATION:	Listed Building grade II, CA	of the marble is suffering considerable decay and soiling, leading to a loss of detail, and the monument is also leaning
	CONDITION:	Poor	significantly. A full condition survey has been undertaken to inform future repair works and advice sought from a
	OCCUPANCY:	N/A	structural engineer; consent has been obtained from the
	PRIORITY CATEGORY:	C (C)	Diocese for further investigations. The Local Authority, Historic England and Friends of Margravine Cemetery are
	OWNER TYPE:	Unknown	exploring funding options.
	LIST ENTRY NUMBER:	1072616	Contact: Adam O'Neill (LPA) 020 8753 3318

Neoclassical stone mausoleum dating from 1918 with

interior designer who assisted in the design of the Eiffel Tower and interiors of RMS Titanic and RMS Olympic. It

was built by Simon Harwath, a Slovenian immigrant who

helped manage their businesses. The decorative ceiling and plaques are damaged, likely from water ingress through the

Circular red brick building and boundary wall, with railings

Paul's School, 1881-85 by Alfred Waterhouse, now part of St Paul's Open Space. The building is disused and subject to

Authority commissioned a condition survey for the building and has submitted applications for consent for its repair

and re-use for garden storage. Conservation repairs to the adjacent wall following damage from a car collision are

and terracotta finials to brick piers, all formerly part of St

vandalism, with missing roof tiles and damp. The Local

complete. Repairs to the railings are being investigated.

became a West End hotelier, for his wife Mathilde who

roof. Further investigation is required to determine an

Contact: Adam O'Neill (LPA) 020 8753 3318

appropriate conservation approach.

elaborate exterior and intact interior fittings. It was designed by Arthur Henry Durand FRIBA, architect and



© London Borough of Hammersmith and Fulham



© London Borough of Hammersmith and Fulham



	LIST ENTRY NUMBER:	1079820	Contact: Adam O'Neill (LPA) 020 8753 3318		
	SITE NAME:	Former Hope and Anchor public house, 20 Macbeth Street, Hammersmith W6	Public house in neo-Georgian style dating from 1936. Built for Truman's as part of a housing estate. The building is an unusual survival with two exceptionally intact 1930s bar		
	DESIGNATION:	Listed Building grade II, CA	interiors. The public house business closed in 2012. The ground floor is used for occasional filming and the upper		
	CONDITION:	Good	floors are occupied and in residential use. Original external signage and some internal ironmongery in the bar areas		
	OCCUPANCY:	Part occupied/part in use	have been removed.		
	PRIORITY CATEGORY:	E (E)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	39279	Contact: Adam O'Neill (LPA) 020 8753 3318		

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

WHS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
  - Unitary Authority World Heritage Site

	SITE NAME:	Tomb of Frederick Harold Young, Hammersmith Cemetery, Margravine Road W6	Mausoleum dating from 1884. The parapet to the west elevation is missing and there is some broken and missing glass. There are structural defects to the floor. The Local Authority has commissioned a structural report and
	DESIGNATION:	Listed Building grade II, CA	architectural consultants to prepare a fully detailed schedule of repairs and conservation works, with funding
	CONDITION:	Very bad	from Historic England. The Local Authority is also working with the Friends of Margravine Cemetery and Historic
	OCCUPANCY:	N/A	England to identify appropriate funding sources to enable
AND STATISTICS	PRIORITY CATEGORY:	A (A)	full repair and conservation works to be carried out.
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1072617	Contact: Adam O'Neill (LPA) 020 8753 3318
	SITE NAME:	Tomb of Samuel Jones, Queen Caroline Street, St Paul's Churchyard W6	Table tomb over a brick and stone plinth dating from the end of the C18. There is evidence of severe mechanical damage and erosion as well as rusting of the remaining
. Miller 12	DESIGNATION:	Listed Building grade II, CA	railings. Invasive vegetation and dumped rubbish continue to be a problem. A suitable proposal is awaited from the
	CONDITION:	Very bad	church to secure the repair of the monument and improve its setting.
A CARLON	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1246022	Contact: Adam O'Neill (LPA) 020 8753 3318
-	SITE NAME:	Former Royal Masonic Hospital, Ravenscourt Park, Hammersmith W6	Hospital, 1933, by Thomas Tait, funded by the Freemasons. The building has been vacant since the closure of the NHS facility in 2006. Walls within the landscaped
	DESIGNATION:	Listed Building grade II*, CA	garden were demolished in anticipation of implementation of an approved scheme for hospital use but works then
a la	CONDITION:	Fair	stalled. New owners are exploring options for a residential
			led conversion of the building.
Contraction of the second second	OCCUPANCY:	Vacant/not in use	C C
	OCCUPANCY: PRIORITY CATEGORY:	Vacant/not in use E (E)	
© Historic England	PRIORITY CATEGORY:	E (E)	Contact: Verena McCaig 020 7973 3718
© Historic England	PRIORITY CATEGORY: OWNER TYPE:	E (E) Commercial company	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	E (E) Commercial company 1192740 Church of St John, North End	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	E (E) Commercial company 1192740 Church of St John, North End Road, Walham Green SW6 Listed Place of Worship grade II,	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the Listed Places of Worship Roof Repair Fund. The church
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	E (E) Commercial company 1192740 Church of St John, North End Road, Walham Green SW6 Listed Place of Worship grade II, CA	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the Listed Places of Worship Roof Repair Fund. The church interior and electrics remain in poor condition and a new drainage system is required. Work recently completed on
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	E (E) Commercial company 1192740 Church of St John, North End Road, Walham Green SW6 Listed Place of Worship grade II, CA Poor	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the Listed Places of Worship Roof Repair Fund. The church interior and electrics remain in poor condition and a new drainage system is required. Work recently completed on replacing and upgrading of all the hoppers, overflows and
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY:	E (E) Commercial company 1192740 Church of St John, North End Road, Walham Green SW6 Listed Place of Worship grade II, CA Poor D (C)	Contact: Verena McCaig 020 7973 3718 Church built in 1827, designed by George Ledwell Taylor. Stonework repairs to the tower and re-roofing of the aisles were completed in 2016, grant-aided by Historic England and the National Lottery Heritage Fund. The nave and chancel were re-roofed in 2017 with funding from the Listed Places of Worship Roof Repair Fund. The church interior and electrics remain in poor condition and a new drainage system is required. Work recently completed on

SITE NAME:	St Mary's, Kensal Green NW10		
DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Adam O'Neill (LPA) 020 8753 3318

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE

DESI

CON

000

PRIC

ow LIST

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

#### HARINGEY



SITE NAME:	37, North Road, Highgate N6 N6	Early C19 house of two storeys and basement, part of two pairs linked by recessed porches. The building is built of red
DESIGNATION:	Listed Building grade II, CA	brick, with cement detailing including pilaster strips, entablature and cornice. The condition of the property and
CONDITION:	Poor	front garden is deteriorating. In 2022 the Council took enforcement action and issued a s215 notice in relation to
OCCUPANCY:	Unknown	the surrounding site and are actively (April 2023)
PRIORITY CATEGORY:	A (C)	considering further enforcement action to secure the full repair of the building.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	893	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© London Borough of Haringey



ENAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N10 N10	Ente thea was
IGNATION:	Listed Building grade II, part in RPG grade II, CA	terr com buile
NDITION:	Poor	part large
CUPANCY:	Part occupied/part in use	The
ORITY CATEGORY:	C (C)	fund repa
/NER TYPE:	Charity (heritage)	
ENTRY NUMBER:	1268256	Cor

ertainment complex including exhibition halls and atre, built 1868-75. From 1935 part of Alexandra Palace s leased to the BBC. Repairs to the loggia on the south race (western end) and south-east roofs were npleted in 2013. Repairs to the eastern part of the lding, including the theatre, were completed in 2018, as t of a National Lottery Heritage Fund project. However, e parts of the building remain in a derelict condition. e north-east office building, where Historic England has ded project development, is of particular concern; a air scheme is planned.

ntact: Elisabetta Tonazzi (LPA) 020 8489 4497

1	SITE NAME:	N8 N8 Dudock's seminal to	Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important
	DESIGNATION:	Listed Building grade II*, CA	influence on subsequent British town hall design. The building was in a poor condition, particularly the Assembly
OCCUP PRIORI OWNE	CONDITION:	Poor	Hall to the rear. The Local Authority has transferred ownership to Far East Consortium International Ltd. This
	OCCUPANCY:	Part occupied/part in use	includes an agreement to guarantee continued public
	PRIORITY CATEGORY:	F (F)	access to, and use of, parts of the building. The town hall will also accommodate a hotel, with new residential
	OWNER TYPE:	Local authority	development to the rear. Works to the interior and exterior are slowly progressing (April 2023).
	LIST ENTRY NUMBER:	1263688	Contact: Simon Buteux 07973 498013

arts café.

© Historic England



© London Borough of Haringey



SITE NAME:	7, Bruce Grove, Tottenham NI7 NI7
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1188605

Former public toilets, Bruce

Grove, Tottenham NI7 NI7

Listed Building grade II, CA

Vacant/not in use

Local authority

1259316

Poor

F (F)

commissioned a structural survey in 2018 and has secured funding for repair and renovation of the building. The ironwork has been restored and works are progressing on site, relevant demolitions have occurred, cleaning and repair trials have been agreed. Planning and Listed Building Consent applications were approved in 2022 and work is steadily progressing to refurbish the toilets as a community

Public toilet circa 1920, with fine external ironwork. The

building is currently empty. The Local Authority

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

One of a pair of early C19 houses. The building is vacant and has suffered substantial internal collapse. A scheme of refurbishment and conversion to flats was approved. A proposal to amend the approved scheme in order to optimise the configuration of the second and top floors is under discussion. The building was sold to a new owner in 2020. The Council took enforcement action in 2021 to obtain access and carry out a condition survey and are now (April 2023) considering further enforcement action.

Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

#### PRIORITY CATEGORIES

© London Borough of Haringey

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG SM
- ΪA
- Unitary Authority World Heritage Site WHS



SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17 N17	C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as the brickwork is deteriorating. An initial programme of repairs has been
DESIGNATION:	Listed Building grade II, CA	undertaken, but further works are needed. Comprehensive repair works are in preparation (April 2023) and a Listed
CONDITION:	Poor	Building Consent application is anticipated in summer 2023. Works are to be carried out as soon as possible.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1294666	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© London Borough of Haringey



1	SITE NAME:	662, High Road, Tottenham N17 N17	Early C18 building of three storeys, in stock brick with stone coped parapet, lower than the neighbouring
	DESIGNATION:	Listed Building grade II, CA	properties with which it has group value. The building was badly fire damaged during the 2011 riots. The upper floors
	CONDITION:	Fair	and roof of the building have been renovated and repaired. Listed Building Consent was granted in 2019 for
	OCCUPANCY:	Vacant/not in use	renovations to the ground floor of the building with
	PRIORITY CATEGORY:	F (F)	restoration of the shop frontage, and works are due to start on site.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1358832	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497

© Historic England



	SITE NAME:	Retaining wall along Highgate Hill (The Bank), Highgate Hill, Highgate N6 N6	Early C19 retaining wall along Highgate Hill between the street pavement and higher paved walk. Some repairs were carried out in 2010/11. Temporary measures were
	DESIGNATION:	Listed Building grade II, CA	implemented in January 2018 to safeguard the wall. A repair and enhancement project informed by specialist
	CONDITION:	Poor	conservation architects was approved in January 2023 and the remedial works are anticipated to start in summer 2023.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
© London Borough of Haringey	LIST ENTRY NUMBER:	1079237	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497



	LIST ENTRY NOMBER:	10/9237	Contact: Elisadetta Tonazzi (LPA) 020 8489 4497	
野	SITE NAME:	South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17 N17	Red brick wall of probable early C17 date in Flemish bond, with tall sloped coping and plinth. The wall is ramped gently up at intervals towards the west. It is now seriously deteriorating with open decayed pointing, loose and unstable brickwork, previous re-pointing damage, and	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Poor	extensive ivy/creeper and frost damage. A programme of urgent repairs has been undertaken, but further repairs are	
	OCCUPANCY:	N/A	required.	
	PRIORITY CATEGORY:	A (A)		
NN	OWNER TYPE:	Local authority		
y	LIST ENTRY NUMBER:	1079218	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497	

# PRIORITY CATEGORIES

© London Borough of Haringey

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Porters and Walters Almshouses, St Leonard's Almshouses, Nightingale Road, Wood Green N22 N22	Four two-storey almshouses, circa 1904, which form a group with a commemorative stone and front railings. The buildings have suffered from a lack of proper maintenance over a number of years and there was a partial collapse of the boundary upplies 2019. Listed Building Consent has
	DESIGNATION:	Listed Building grade II, CA	the boundary wall in 2018. Listed Building Consent has been granted for partial demolition and rebuilding, and
MAN BOD	CONDITION:	Poor	work is in progress.
	OCCUPANCY:	Occupied/in use	
The second second	PRIORITY CATEGORY:	F (F)	
) London Borough of Haringey	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1079222	Contact: Elisabetta Tonazzi (LPA) 020 8489 4497
	SITE NAME:	Church of St Augustine, Archway Road, Hornsey N6	The Art Workers Guild background of the three architect involved in this late C19 church is very apparent. JF Seddir
	DESIGNATION:	Listed Place of Worship grade II, CA	started the work, was succeeded by his pupil Henry Wilson (west nave and Lady Chapel) and Harold Gibbons who in 1916 completed the Arts and Crafts facade with its
	CONDITION:	Fair	Calvary. The London stock brickwork is dressed in Bath
	PRIORITY CATEGORY:	F (F)	stone and red brick under a plain tiled roof. Internal fitting are of a high quality. The tower roof was repaired in 2017
	OWNER TYPE:	Religious organisation	and the Calvary Statuary in 2018, with grants from the National Lottery Heritage Fund. There remain repairs
	LIST ENTRY NUMBER:	1358860	needed to roofs and gutters.
) Historic England			Contact: Ian Harper 07974 979620
A REAL PROPERTY AND A REAL	SITE NAME:	Former Gaumont Palace cinema, Broadway, Wood Green N22	The former Gaumont Cinema was built in 1934, designed by architects William Edward Trent and Ernest F Tulley. It is constructed with a steel frame clad in brick. The entranc
	DESIGNATION:	Listed Place of Worship grade II*	In 2018 a piece of the high-level cornice fell to the grou Access scaffolding was erected for inspection and emergency repairs. In 2020 it was discovered that the
	CONDITION:	Poor	
B AR DOMINION CENTRE	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	steels supporting the high-level upper and lower cornices were extensively corroded. A repair solution is now being
	LIST ENTRY NUMBER:	1263635	sought.
Donald Insall Associates			Contact: Tracey Craig 020 7973 3756
utilita.	SITE NAME:	Parish Church of All Hallows, Church Lane, Tottenham N17	This medieval church incorporates a C14 tower with C18 battlements. The north aisle was rebuilt in 1855. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	chancel, east end extensions and raised clerestories were by William Butterfield in 1875-7. In 2017 the roofs and valley gutters were repaired with a grant from the Listed
	CONDITION:	Poor	Places of Worship Roof Repair Fund. Much C14 and C15 architectural fabric survives internally but is suffering from
	PRIORITY CATEGORY:	C (C)	dampness and requires repair. In 2020 Historic England
	OWNER TYPE:	Religious organisation	awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for repairs to the vestry roof. The felted tower
	LIST ENTRY NUMBER:	1188633	roof is ponding and a big risk.
) Historic England			Contact: Ian Harper 07974 979620
200 5	SITE NAME:	Church of St Bartholomew, Craven Park Road, Tottenham NI5	Arts and Crafts parish church designed by WD Caroe, completed in 1904. Plain tiled roofs and mass soft red-bric walls contain a finely carpentered roof and original interior furnishings including come by Cibhons from St
	DESIGNATION:	Listed Place of Worship grade II*	furnishings including some by Gibbons from St Bartholomew by the Bank. Vicarage on north side of the
A PRIME A	CONDITION:	Very bad	church also by Ćaroe. The roof batten fixings to the boards are failing in some areas, especially to chancel and
	PRIORITY CATEGORY:	A (A)	Lady Chapel roofs, causing the battens and tiles to creep
	OWNER TYPE:	Religious organisation	down the roof with resultant leakage. This condition need to be addressed urgently in order to prevent roof decay.
			6 / ···································

Contact: Ian Harper 07974 979620

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

1079264

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HARINGEY / HARROW

	SITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The former Tottenham Palace Theatre was built in 1908 by Wylson Long as a variety theatre. The building is now in use for worship. It is suffering from water ingress, which is
	DESIGNATION:	Listed Place of Worship grade II, CA	causing significant damage to both the structure and interior plaster work. Some repairs were carried out to the front roofs in 2015, but considerable further work is
The second se	CONDITION:	Very bad	required. Discussions between the Local Authority and the congregation are ongoing to secure necessary urgent
	PRIORITY CATEGORY:	A (A)	works.
	OWNER TYPE:	Religious organisation	
) Historic England	LIST ENTRY NUMBER:	1249660	Contact: Ian Harper 07974 979620

SITE NAME:	Bruce Grove NI7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY: Low		CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Clyde Circus N15		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Hornsey Water Works and Filter Beds, Hornsey	N8	
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY: Medium		CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	North Tottenham High Road N17		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497
SITE NAME:	Scotland Green N17		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY: Medium		CONTACT:	Elisabetta Tonazzi (LPA) 020 8489 4497

HARROW

© Historic England

6 7

© I



	SITE NAME:	Former White Hart Hotel, High Street, Edgware HA8	C17 three-storey stuccoed building with a hipped tile roof and wooden eaves cornice. It is closed and no longer in
T.	DESIGNATION:	Listed Building grade II	use. The upper floors are in a poor condition after unauthorised works and there are holes in the walls and
	CONDITION:	Poor	ceilings. A new leaseholder took over in 2020. Further unauthorised works were carried out during Covid-19
	OCCUPANCY:	Vacant/not in use	Lockdown. The Local Planning Authority halted these and
1.1	PRIORITY CATEGORY:	C (C)	carried out enforcement action and are awaiting an appeal decision relating to this. Further unlawful works were
	OWNER TYPE:	Commercial company	undertaken in 2022 and 2023. The Local Planning Authority is carrying out enforcement action.
	LIST ENTRY NUMBER:	1079726	Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

# A Immediate risk of further rapid deterioration or loss of fabric; no

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE A

	SITE NAME:	Kenton Lane Farmhouse, Kenton Lane HA3	Two-storey former farmhouse built circa 1808, to the designs of William Loudon and Robert Abraham in Flemish bond red brick with a hipped slate roof. Listed Building Consent and Planning Permission were approved in 2013 for conversion to residential with an adjacent housing scheme. The new homes are complete but works to the listed buildings have not been carried out and they were damaged by illegal entry in 2019. Some urgent works were undertaken by the owner in 2022 and the site is secure,
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
Barthere Barres Cont	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	wind and weathertight. The Local Planning Authority is
) Historic England	LIST ENTRY NUMBER:	1253950	carrying out enforcement action. Contact: Lucy Haile (LPA) 020 8736 6101
ł	SITE NAME:	Kenton Lane former farm buildings, Kenton Lane HA3	Former farm buildings built circa 1808, to designs of William Loudon and Robert Abraham in Flemish bond
	DESIGNATION:	Listed Building grade II	brick. The vacant buildings are three sides of a courtyard. Listed Building Consent and Planning Permission were
	CONDITION:	Poor	approved in 2013 for conversion to residential, with an adjacent housing scheme. The new homes are complete but works to the listed buildings have not been carried or and they were damaged by illegal entry in 2019. Some urgent works were undertaken by the owner in 2022 and the site is secure, wind and weathertight. The Local Planning Authority is carrying out enforcement action.
	OCCUPANCY:	Vacant/not in use	
The T	PRIORITY CATEGORY:	A (A)	
the manufactures	OWNER TYPE:	Commercial company	
) Historic England	LIST ENTRY NUMBER:	1253952	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Old Pye House, West Street, HAI 3EL	The C15 two-storey building was part of a larger hall building. It has a slate roof, timber-framed walls and gable
	DESIGNATION:	Listed Building grade II, CA	ends with a central tie beam, and a plain kingpost. The south front is C18 or early C19 red brick. Unoccupied and
	CONDITION:	Poor	in poor condition, the original first floor was removed
	OCCUPANCY:	Vacant/not in use	when it was used as a plastics factory. Internal scaffolding has now been installed, a modern extension and yew tree
	PRIORITY CATEGORY:	A (A)	have been removed, and the ground level lowered inside the building. Discussions about proposals, including
	OWNER TYPE:	Private	external scaffolding, are taking place between the owner
) Historic England	LIST ENTRY NUMBER:	35865	and the Local Authority. Contact: Lucy Haile (LPA) 020 8736 6101
• • · · · · · · · · · · · · · · · · · ·	SITE NAME:	Wall to west and north of Springbok House, Wood Lane	C19 wall, 11 foot high, with stone copings, recessed in the centre to pass through the porte-cochère. The wall forms
	DESIGNATION:	Listed Building grade II, CA	curved forecourt and screening to Springbok House, now the Hussaini Shia Islamic Centre. A leaning section of the
The subscription of the second s			wall was deemed a dengeneus structure by the Local



© London Borough of Harrow

	LIST ENTRY NUMBER:	1358651	and the Local Authonity.		
		1338631	Contact: Lucy Haile (LPA) 020 8736 6101		
	SITE NAME:	Wall to west and north of Springbok House, Wood Lane	C19 wall, 11 foot high, with stone copings, recessed in the centre to pass through the porte-cochère. The wall forms a		
	DESIGNATION:	Listed Building grade II, CA	curved forecourt and screening to Springbok House, now the Hussaini Shia Islamic Centre. A leaning section of the		
	CONDITION:	Poor	wall was deemed a dangerous structure by the Local Authority and was taken down in 2018 for safety reasons.		
	OCCUPANCY:	N/A	The wall has been rebuilt without Planning Permission or		
	PRIORITY CATEGORY:	C (C)	Listed Building Consent in 2022/2023. The Local Authority is in discussion with the owner.		
	OWNER TYPE:	Charity (non-heritage)			
	LIST ENTRY NUMBER:	1358673	Contact: Lucy Haile (LPA) 020 8736 6101		

Gate pier at entrance to

Commercial company

grade II, CA

Very bad

N/A

A (A)

1079736

Canons Drive, Edgware HA8

Listed Building grade II, RPG

One of the two decorated early C18 gate piers, belonging to and contemporary with Canons (now demolished), collapsed in a storm in early 2022 due to a tree fall. The Local Authority is in discussion with the owner regarding repair and reinstatement and an application for Listed Building Consent was submitted in September 2022 and is under consideration.

Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

© London Borough of Harrow

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


# ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument

- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Brick Kiln to south east of the Kiln, Common Road, Stanmore	Lower part of a C18 brick kiln conical chimney, of which the upper part no longer exists. In urgent need of structural
	DESIGNATION:	Listed Building grade II	stabilisation and repair. The Local Authority is in discussion with the new owner and applications for Planning
	CONDITION:	Very bad	Permission and Listed Building Consent were submitted in April 2023 and are under consideration.
	OCCUPANCY:	N/A	The second are under consideration.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
gh of Harrow	LIST ENTRY NUMBER:	1079710	Contact: Lucy Haile (LPA) 020 8736 6101

	SITE NAME:	Pinner Park Farmhouse, George V Avenue, Pinner	The building dates from circa 1750. It is two storeys with three bays plus hipped wing. The windows to the main
	DESIGNATION:	Listed Building grade II	house are altered. The building appears in good condition externally but the interior requires attention. There has
	CONDITION:	Poor	been some damage from water penetration and the building is partly vacant. Listed Building Consent was
	OCCUPANCY:	Part occupied/part in use	approved in 2018 to replace an existing steel beam and
	PRIORITY CATEGORY:	C (C)	repair the central valley gutter, and in 2019 this work was completed.
	OWNER TYPE:	Local authority	
igh of Harrow	LIST ENTRY NUMBER:	1079715	Contact: Lucy Haile (LPA) 020 8736 6101



	SITE NAME:	Old Stanmore Church, Church Road, Stanmore	The now roofless ruined church of St John the Evangelist was built in 1632, attributed to Nicholas Stone. The wall
	DESIGNATION:	Listed Place of Worship grade II*, CA	heads have exposed brickwork allowing rainwater ingress. This is resulting in the erosion of mortar and bricks and in supporting deleterious plant growth. There is decayed
	CONDITION:	Poor	mortar, brick, stone and timber elsewhere around the building along with some vertical cracking in the walling.
	PRIORITY CATEGORY:	C (C)	The church is occasionally used for worship.
	OWNER TYPE:	Religious organisation	
China and	LIST ENTRY NUMBER:	1079747	Contact: Tracey Craig 020 7973 3756

© Historic England

© London Borough

© London Boroug

SITE NAME:Grim's Ditch: section extending 1500yds (1370m)					
DESIGNATION:     CA     ESTENTION FOR TOULOGE     TOULOGE       CONDITION:     Generally satisfactory but with significant localised problems     TREND:     Declining       PRINCIPAL VULNERABILITY:     Scrub/tree growth     NEW ENTRY?:     No	SITE NAME:	Grim's Ditch: section extending 1500yds (1370m) north east from Oxhey Lane			
PRINCIPAL VULNERABILITY:     Scrub/tree growth     NEW ENTRY?:     No	DESIGNATION:	<b>U U U</b>	LIST ENTRY NUMBER:	1002044	
	CONDITION:		TREND:	Declining	
OWNER TYPE: Local authority, multiple owners CONTACT: Jane Sidell 020 7973 3738	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority, multiple owners	CONTACT:	Jane Sidell 020 7973 3738	

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HARROW / HAVERING

SITE NAME:	Grim's Ditch: section north of Blythwood House		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002007
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Linear earthworks in Pear Wood, west of Watling	Street	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001996
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Pinner deer park, Pinner Park Farm		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1019135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Grim's Ditch: four linear sections between Uxbridg	e Road and Oxhey	' Lane
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
	SITE NAME Pantlas Priors	A CIA actata an	arged and improved in the late CIR Sin



HAVERING

ING			
	SITE NAME:	The Rom Skatepark	Built in 1978, The Rom Skatepark was designed by Adrian
	DESIGNATION:	Listed Building grade II	Rolt of G-Force and in 2014 became the first skatepark in England to receive national listed status. Following a fire in
	CONDITION:	Poor	2018 the park lost its (unlisted) indoor facilities which ultimately led to its closure in September 2019. The park
	OCCUPANCY:	Vacant/not in use	has re-opened but requires concrete and drainage repairs.
	PRIORITY CATEGORY:	C (C)	Historic England has provided advice to owners on surveys required to identify appropriate approaches to repair.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1419328	Contact: Cara Collier (LPA) 0170 8434083

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



© Historic England

© Historic England

SITE NAME:	Garden walls to former North Ockendon Hall, Church Lane, North Ockendon	C16 and later garden walls to Ockendon Hall (now demolished). These extensive walls are slowly deteriorating although the owners are making efforts to prevent further
DESIGNATION:	Listed Building grade II, CA	damage from vegetation.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1300500	Contact: Cara Collier (LPA) 0170 8434083

×	SITE NAME:	Outbuilding to the rear of The Old Anchor, Harwood Hall Lane	ilding to the rear of The nchor, Harwood Hall clink of the rear wing of The Old Anchor, a C18 timber-framed house. The building is currently used as a workshop. It is need of roof and brickwork repairs, new rainwater good
	DESIGNATION:	Listed Building grade II, CA	and renewal of the timber lintels. The Local Authority and
	CONDITION:	Very bad	Historic England are monitoring the condition of the building and have discussed essential repairs with the
	OCCUPANCY:	Part occupied/part in use	owner.
1	PRIORITY CATEGORY:	C (C)	
- PERS	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079891	Contact: Cara Collier (LPA) 0170 8434083

High House Farmhouse,

Listed Building grade II\*, CA

Part occupied/part in use

Two brick barns and garden

walls to south of Bretons

House, Rainham Road,

Listed Building grade II

Part occupied/part in use

Ockendon Road

Very bad

A (A)

Private

1079867

Hornchurch

Very bad

1183600

© Historic England



© Historic England



	· ··· · · · · · · · · · · · · · · · ·	
PRIORITY CATEGORY:	A (A)	assets and plans for the wider site are being developed. However, immediate repairs are required.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1300053	Contact: Cara Collier (LPA) 0170 8434083
SITE NAME:	Garden walls at Cranham Hall, The Chase, Cranham	C16 walls to an earlier house on the site of Cranham Hall. The wall is in need of extensive repairs. Previous localised
DESIGNATION:	Listed Building grade II, CA	repairs are inappropriate and uncontrolled tree and other plant growth is causing further damage and deterioration.
CONDITION:	Very bad	The Local Authority and Historic England are in discussion to determine an appropriate approach to securing repairs.
OCCUPANCY:	N/A	to determine an appropriate approach to securing repairs.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	

© London Borough of Havering

Contact: Cara Collier (LPA) 0170 8434083

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

LIST ENTRY NUMBER:

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

# ABBREVIATIONS

Three-storey house of brick and timber frame circa 1700 with an older timber-framed wing. The timber frame to the

three-storey section is under stress, the porch is propped

by scaffold and there is significant water damage from the roof. A number of the rooms are uninhabitable. Much of

the extensive vegetation growth on the exterior of the

discussions with the owners.

Contact: Verena McCaig 020 7973 3718

building has been removed and some surveys have been carried out but the building requires urgent repairs to

prevent further decay and possible localised collapse. The Local Authority and Historic England are continuing

Two Tudor barns set around a cobbled courtyard close to

the C16 garden walls, all associated with Bretons House.

deteriorating, with some earlier unsympathetic alterations

repair, particularly to the roof and walls, and suffers from vandalism. The garden walls also require extensive repair,

One barn is watertight and in partial use although

although sections have been robustly propped. A

and additions. The other barn is in need of extensive

Conservation Statement has been prepared for these

Conservation Area Listed Building

- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site WHS

	SITE NAME:	Mill Cottage, The Dell, High Street, Hornchurch	Single-storey timber-framed range, now one dwelling, dating from the C17. The building is in very bad condition
	DESIGNATION:	Listed Building grade II, CA	and continuing to deteriorate. The roof has undergone extensive temporary repair but continues to present major
	CONDITION:	Very bad	maintenance problems.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079898	Contact: Cara Collier (LPA) 0170 8434083

	SITE NAME:	Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s
	DESIGNATION:	Listed Building grade II	for Sir James Esdaile, Lord Mayor of London 1777-78. Erection of fencing on the bridge has seriously damaged the
	CONDITION:	Very bad	structure. Extensive vegetation growth is further threatening its stability. Some structural repairs have been
	OCCUPANCY:	N/A carried out in the past but further works are urgently	carried out in the past but further works are urgently
and the second second	PRIORITY CATEGORY:	A (A)	required.
	OWNER TYPE:	Local authority	
gland	LIST ENTRY NUMBER:	1323729	Contact: Cara Collier (LPA) 0170 8434083

SITE NAME:	Upminster Tithe Barn, Hall Lane, Upminster RM14		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001991
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Rain entry	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Dagnam Park Farm moated site, Noak Hill, Romfor	ď	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001988
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Romford		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Planning Service (LPA) 01708 433100

# HILLINGDON

© Historic England

© Historic Engla



SITE NAME:	Granaries at Knightscote Farm, Harefield UB9	A pair of early to mi with timber frames,
DESIGNATION:	Listed Building grade II	roofs. These are exa building type in Mide
CONDITION:	Very bad	granary re-uses a CI roof with clasped pu
OCCUPANCY:	N/A	collapsed.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1376634	Contact: Ian Thynne

nid C19 weatherboarded granaries, each , standing on staddle stones, with tiled amples of a once-common agricultural Idlesex, but now rare. The northern Cl8 six-panel door and has a queen strut purlins. The southern granary has now

© Historic England

ne (LPA) 01895 558326

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERI

HERITAGE AT RISK 2023 / LONDO	on and south east	/ HILLINGDON	
-	SITE NAME:	Manor Farmhouse, High Street, Harmondsworth UB7	Mid C19 stock brick villa with hipped slated roofs and gauged brick near-flat arches to sash windows with glazing
	DESIGNATION:	Listed Building grade II, CA	bars. Permission had been granted to convert the building to two dwellings. Whilst awaiting discharge of conditions
	CONDITION:	Poor	for the application the building suffered lead theft and was
	OCCUPANCY:	Vacant/not in use	illegally used as a cannabis farm. Damage includes internal brickwork and water ingress from the roof. The Local
	PRIORITY CATEGORY:	C (New entry)	Authority is discussing the site with the owner.
	OWNER TYPE:	Commercial company	
© London Borough of Hillingdon	LIST ENTRY NUMBER:	1358367	Contact: Ian Thynne (LPA) 01895 558326
	SITE NAME:	Wall and gate piers at St Martin's churchyard entrance, Church Road, Hillingdon UB7	Restored C16 red brick churchyard entrance wall and gate piers, with wrought iron gates, at St Martin's Church. Lower parts of C16 red brick, with the upper part rebuilt
Partial Church	DESIGNATION:	Listed Building grade II, CA	probably in the C19. A survey of the churchyard walls was carried out in 2021, with funding from Historic England,
	CONDITION:	Very bad	and funding will be sought to enable the necessary repair works to be carried out. In January 2023 a short section of
	OCCUPANCY:	N/A	wall collapsed close to the main access path to the south
	PRIORITY CATEGORY:	A (A)	entrance door to the church. Discussions are in progress (Feb 2023) regarding its repair.
	OWNER TYPE:	Religious organisation	
© MRDA	LIST ENTRY NUMBER:	1080275	Contact: Ian Thynne (LPA) 01895 558326
	SITE NAME:	Wall running south from the Old Gatehouse west along Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
A CONTRACTOR	DESIGNATION:	Listed Building grade II*, CA	remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and
	CONDITION:	Poor	discussions are underway with the owners of the wall
in the second	OCCUPANCY:	N/A	regarding the necessary repairs.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1358326	Contact: Simon Buteux 07973 498013
the second second	SITE NAME:	Walls around St Martin's churchyard, north side, Church Road, Hillingdon UB7	Red brick boundary and retaining wall for St Martin's churchyard. C16 red brick walls, with tall sloped coping, along the east and north sides of the churchyard and the
L'ALLER AND A	DESIGNATION:	Listed Building grade II*, CA	northern part of the west side. At the south end of the east side there is a square pier with stone cornice and ball
	CONDITION:	Very bad	finials. A survey of the churchyard walls has been carried
Etal and the	OCCUPANCY:	N/A	out, with funding from Historic England, and funding will be sought to enable the necessary repair works to be carried
2 ANDES	PRIORITY CATEGORY:	A (A)	out.
or have the			

© Historic England



LIST ENTRY NUMBER:	1286366	Contact: Simon Buteux 07973 498013
SITE NAME:	Walls around St Martin's churchyard, south side, Church Road, Hillingdon UB7	Red brick boundary and retaining wall along the south part of the west side and the south side of St Martin's churchyard. Lower parts of C16 red brick, with the upper
DESIGNATION:	Listed Building grade II, CA	part rebuilt probably in the C19. A survey of the churchyard walls has been carried out, with funding from
CONDITION:	Very bad	Historic England, and funding will be sought to enable the necessary repair works to be carried out.
OCCUPANCY:	N/A	necessary repair works to be carried out.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1080276	Contact: Ian Thynne (LPA) 01895 558326

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

OWNER TYPE:

D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Religious organisation

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Lych gate to south of Church of St Mary, Church Walk, Hayes	Circa C16 timber lych gate with tiled roof. The timber supports and base are in a very poor state of repair and
	DESIGNATION:	Listed Building grade II, CA	tiles are slipping from the roof. No repairs are planned.
10 MA	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
- A	OWNER TYPE:	Religious organisation	
nd	LIST ENTRY NUMBER:	1080234	Contact: Ian Thynne (LPA) 01895 558326

© Historic England



Late C17 or early C18 weatherboarded barn with tiled SITE NAME: Barn to the west of Weekly House, Bath Road, roof and Queen post truss at the west end. Weekly House, the boundary wall and the barn form a group. The Harmondsworth barn is in a dilapidated state. DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1286544 Contact: Ian Thynne (LPA) 01895 558326



© London Borough of Hillingd



© London Borough of Hilling



© London Borough of Hillingdon

	SITE NAME:	Former King Henry public house and stables, 456, Bath Road, Longford	Converted to a house, the rear of the building is the former King Henry public house. The front part of the property has been rebuilt, using old material, after a fire. All
	DESIGNATION:	Listed Building grade II	the walls have exposed timber framing with brick filling. The roofs are tiled. The adjacent stables are also of interest
	CONDITION:	Poor	with an early diamond mullioned window. The buildings are in poor condition but have been secured by the owner.
12.44	OCCUPANCY:	Vacant/not in use	They have been included in larger development proposals.
A Car	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
gdon	LIST ENTRY NUMBER:	1080296	Contact: Ian Thynne (LPA) 01895 558326

	SITE NAME:	Enterprise House, Blyth Road, Hayes	1912 factory building by the Trussed Concrete Steel Company for HMV. It has an unusual design with a high-
	DESIGNATION:	Listed Building grade II, CA	level water tank and is an important local landmark. Proposals for conversion to residential use were agreed
1000	CONDITION:	Poor	and works started on the consented scheme in 2021. Repairs to the façade were completed in November 2022
	OCCUPANCY:	Vacant/not in use	and works to the interior will continue in 2023.
	PRIORITY CATEGORY:	F (F)	
A. Cart	OWNER TYPE:	Commercial company	
ngdon	LIST ENTRY NUMBER:	1244861	Contact: Ian Thynne (LPA) 01895 558326

	SITE NAME:	Langley Farm Barn, Breakspear Road North, Harefield	C16 barn in private ownership at Langley Farm. The three- bay barn is timber-framed and weatherboarded with a tiled
	DESIGNATION:	Listed Building grade II, CA	roof. It has lost parts of the brick plinth to the north east elevation. Listed Building Consent and Planning Permission
	CONDITION:	Very bad	have been granted for residential use and work has started on site.
	OCCUPANCY:	N/A	
A PARTY	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
n	LIST ENTRY NUMBER:	1080261	Contact: Ian Thynne (LPA) 01895 558326

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

48

#### H

HERITAGE AT RISK 2023 / LONDO	on and south east	/ HILLINGDON		
	SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield	C17 red brick garden walls in need of extensive repairs. Some works have already been undertaken to a good standard. Planning Permission and Listed Building Consent	
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	applications were approved in 2021 for work which will include repairs to the walls.	
	CONDITION:	Fair		
	OCCUPANCY:	N/A		
S. S. Barris	PRIORITY CATEGORY:	B (B)		
© Historic England	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1080272	Contact: Ian Thynne (LPA) 01895 558326	
	SITE NAME:	Wall in front of numbers 30 to 36 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment h been prepared, with funding from Historic England, and discussions are underway with the owners of the wall represent the processory repaired.	
	DESIGNATION:	Listed Building grade II, CA		
and the state of the	CONDITION:	Poor		
A CALLER	OCCUPANCY:	N/A	regarding the necessary repairs.	
A CARLEN CONTRACTOR	PRIORITY CATEGORY:	C (C)		
- Man ad the	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1080277	Contact: Ian Thynne (LPA) 01895 558326	
	SITE NAME:	Wall in front of numbers 40 to 50 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the	
	DESIGNATION:	Listed Building grade II, CA	remainder is in poor condition. A condition assessment has been prepared, with funding from Historic England, and	
	CONDITION:	Poor	discussions are underway with the owners of the wall	
	OCCUPANCY:	N/A	regarding the necessary repairs.	
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1358327	Contact: Ian Thynne (LPA) 01895 558326	
	SITE NAME:	Walls in front of numbers 52-58	C16 red brick wall of varied height, breached in places to	



100.00	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1358327	Contact: Ian Thynne (LPA) 01895 558326
-	SITE NAME:	Walls in front of numbers 52-58 (even) and along west end of property, Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has
	DESIGNATION:	Listed Building grade II, CA	been prepared, with funding from Historic England, and discussions are underway with the owners of the wall
-	CONDITION:	Poor	regarding the necessary repairs.
	OCCUPANCY:	N/A	
1	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1286348	Contact: Ian Thynne (LPA) 01895 558326

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.


 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Walls to east and south of garden of number 28 (Coombe House), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition. A condition assessment has
	DESIGNATION:	Listed Building grade II*, CA	been prepared, with funding from Historic England, and discussions are underway with the owners of the wall
	CONDITION:	Poor	regarding the necessary repairs.
	OCCUPANCY:	N/A	
-	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193014	Contact: Simon Buteux 07973 498013



SITE NAME: World War II Bofors gun tower 1940s reinforced concrete gun tower platform with red brick infill walls and external access stair. The associated and ancillary building, Ruislip ancillary building is also brick with a flat reinforced concrete HA4 roof. It has previously been used as storage for the DESIGNATION: Listed Building grade II adjacent football ground. The structure is not weathertight, and the openings and rear roof require securing and repair. CONDITION: Very bad There is severe vegetation growth on the ancillary building. OCCUPANCY. Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation © Historic England LIST ENTRY NUMBER: 1414202 Contact: Ian Thynne (LPA) 01895 558326

	SITE NAME:	The Dower House, 393, High Street, Harlington	Two-storey house with C18 brick front to an older timber- framed structure, with large rebuilt C16 chimney. The
	DESIGNATION:	Listed Building grade II	house is four bays wide, built of brown brick with red brick quoins and window dressings. The building suffered severe
	CONDITION:	Very bad	fire damage in May 2011. In May 2018 the Council took enforcement action to ensure that the building was made
	OCCUPANCY:	Vacant/not in use	wind and weathertight, and it has a temporary roof. The house was sold in 2020 and initial pre-application discussions have taken place with the Council regarding
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	repair and future uses.
rough of Hillingdon	LIST ENTRY NUMBER:	1080196	Contact: Ian Thynne (LPA) 01895 558326



# PRIORITY CATEGORIES

© London Borough of Hillingdon

© London Boro

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

F

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT KISK 2023 / LOINDC				
	SITE NAME:	The stable block, north east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	One of two stable buildings of early C18 date. The stable building has had work completed to the roof and interior and is being used for staff offices. Some further repairs to the exterior are required.	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Fair		
32	OCCUPANCY:	Occupied/in use		
C. There is a	PRIORITY CATEGORY:	C (C)		
© London Borough of Hillingdon	OWNER TYPE:	Health authority		
	LIST ENTRY NUMBER:	1285329	Contact: Ian Thynne (LPA) 01895 558326	
	SITE NAME:	The stable block, south east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	One of two stable buildings of early C18 date. The stable building is currently being used in the short-term for clinical storage and staff accommodation. A long-term use needs to be identified.	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Poor		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
© Historic England	OWNER TYPE:	Health authority		
	LIST ENTRY NUMBER:	1358396	Contact: Ian Thynne (LPA) 01895 558326	
the state of the s	SITE NAME:	Former Nurses Home in grounds of Hillingdon Hospital, Pield Heath Road, Hillingdon	Early C19 house in the grounds of Hillingdon Hospital, currently used as offices, but generally in poor condition. Planning Permission and Listed Building Consent were	
C G IIm In III	DESIGNATION:	Listed Building grade II	approved summer 2022 to repair the building and refurbish the modern extensions so it can continue as part of the	
	CONDITION:	Poor	hospital complex. A longer-term strategy for its use is under discussion.	
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	D (C)		
© London Borough of Hillingdon	OWNER TYPE:	Health authority		
	LIST ENTRY NUMBER:	1080153	Contact: Ian Thynne (LPA) 01895 558326	
	SITE NAME:	Harefield Grove, Rickmansworth Road, Harefield	Probably early C19 country house of three storeys. Stuce with stone cornice and parapet concealing a fairly low-	
E F I I W	DESIGNATION:	Listed Building grade II	pitched hipped slate roof. The building has a two-storey modern courtyard wing for office use with an atrium link. It	
	CONDITION:	Fair	has been vacant for a number of years and is deteriorating. Listed Building Consent and Planning Permission have been	
	OCCUPANCY:	Vacant/not in use	granted for residential use but work has not yet started.	
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Private		
© Antonio Cruz, Comer Homes Group	LIST ENTRY NUMBER:	8  48	Contact: Ian Thynne (LPA) 01895 558326	
in the	SITE NAME:	Mount Vernon Hospital, Rickmansworth Road, Northwood	1902-4 by FL Wheeler in Edwardian Free Style. Built as a hospital for the treatment of tuberculosis patients, and as a branch hospital of the original Mount Vernon hospital in	
un di la	DESIGNATION:	Listed Building grade II	Hampstead (built 1879-80). The building is noted for its advanced plan, including isolation wards and facilities such	
	CONDITION:	Poor	as an X-ray room and dental unit. It is still in use by the hospital, but in a poor state of repair and under pressure	
Summer Part & 49%	OCCUPANCY:	Occupied/in use	from the redevelopment of the site.	
- Contraction	PRIORITY CATEGORY:	C (C)		
© London Borough of Hillington	OWNER TYPE:	Health authority		
© London Borough of Hillingdon	LIST ENTRY NUMBER:	1080083	Contact: Ian Thynne (LPA) 01895 558326	
<ul> <li>PRIORITY CATEGORIES</li> <li>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.</li> <li>C Slow decay; no solution agreed.</li> </ul>	<ul> <li>D Slow decay; solution not yet implemented</li> <li>E Under repair or in fa repair, but no user ic under threat of vacar obvious new user (a) to buildings capable of use).</li> </ul>	I. (where applicable) end use o ir to good dentified; or functionally redundant buildings with new ney with no agreed but not yet implemen pplicable only	or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority v use New Entry is noted). NP National Park	

51



2.00% (B)	SITE NAME:	Cellars of former Cranford House, Roseville Road, Cranford	Brick vaulted cellars to Cranford House circa 1722 (demolished). The cellars are suffering from structural weakening and their condition is deteriorating. The
18194111411111	DESIGNATION:	Listed Building grade II, CA	National Lottery Heritage Fund awarded the Local Authority a grant which included funds towards repair of
	CONDITION:	Fair	the cellars. Planning Permission and Listed Building Consent applications were approved in 2020. Work on the wider
	OCCUPANCY:	Vacant/not in use	project is due finish at the end of 2025 and works to the
	PRIORITY CATEGORY:	F (F)	cellars and stables are underway with an anticipated completion date in summer 2023.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1285115	Contact: Ian Thynne (LPA) 01895 558326

© Historic England



SITE NAME:	Roseville Road, Cranford manage	Stables to Cranford House circa 1720, owned and managed by the London Borough of Hillingdon. The east
DESIGNATION:	Listed Building grade II, CA	block is in very poor condition and the site is in need of a long-term use. The National Lottery Heritage Fund,
CONDITION:	Fair	National Highways and Heritage of London Trust have awarded the Local Authority grants which include funds
OCCUPANCY:	Vacant/not in use	towards repair of the stables. Planning Permission and
PRIORITY CATEGORY:	F (F)	Listed Building Consent applications were approved in 2021. Work on the wider project is due finish at the end of
OWNER TYPE:	Local authority	2025 and works to the cellars and stables are underway with an anticipated completion date in summer 2023.
LIST ENTRY NUMBER:	1080157	Contact: Ian Thynne (LPA) 01895 558326

© Historic England



© London Borough of Hillingdon

© London Borough of Hillir

Orchestrelle Factory of 1909-11. Reinforced concrete SITE NAME: Benlow Works, Silverdale Road, Hayes frame, with brick exterior. Four storeys with a 19-bay elevation. The entrance bay has a semi-circular stepped DESIGNATION: Listed Building grade II brick architrave to the doorway and segmental arched metal casements flanked by rusticated pilasters slightly set CONDITION Very bad forward and breaking the parapet. Temporary repairs have OCCUPANCY: Part occupied/part in use been undertaken so that the building is weathertight. Discussions have been held with the owner, but no PRIORITY CATEGORY: C (C) solution is agreed for future use as yet. OWNER TYPE: Private LIST ENTRY NUMBER: 1080121 Contact: Ian Thynne (LPA) 01895 558326

	SITE NAME:	Gatehouse at Hillingdon- Uxbridge Cemetery, Uxbridge Road	Mid-C19 gatehouse by Benjamin Ferry, with an adjacent stock brick boundary wall. The gatehouse is constructed of rubble with stone dressings, tiled roof and five bays with a
Y	DESIGNATION:	Listed Building grade II	wide central entrance under the arch. It is in a deterioration condition and vacant, and the wall has partially collapsed.
	CONDITION:	Poor	condition survey has been completed and the extent of repairs required agreed, but not yet implemented.
	OCCUPANCY:	Vacant/not in use	repairs required agreed, but not yet implemented.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
lingdon	LIST ENTRY NUMBER:	1358415	Contact: Ian Thynne (LPA) 01895 558326

	SITE NAME:	Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge	Two barns dating from the C16. Listed Building Consent and Planning Permission were granted for a residential scheme incorporating re-use of the salvaged historic
	DESIGNATION:	Listed Building grade II	timbers. The barns were re-erected on site in 2021, however the works were not undertaken in accordance
	CONDITION:	Fair	with the approved drawings and the Local Authority is currently in discussion with the owner.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1284866	Contact: Ian Thynne (LPA) 01895 558326

# PRIORITY CATEGORIES

© London Borough of Hillingdon

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site
- 52

	SITE NAME:	Church of St Mary, High Street, Harmondsworth	St Mary's has fabric from the C12 to the C16 including a fine C12 stone doorway. It has a tall square tower c1500
	DESIGNATION:	Listed Place of Worship grade II*, CA	on top of which is a cupola and weathervane supported on four cast iron columns. The church is largely constructed in flint with stone dressings; the upper stages of the tower are
- La V	CONDITION:	Fair	in brick. The roofs are tiled. Much of the dressed stone, including quoins and the copings to the battlemented
	PRIORITY CATEGORY:	C (C)	parapet, has been refaced in a cementitious render. The
	OWNER TYPE:	Religious organisation	refacings are failing in places, exposing the substructure. There is cracking around the western end, particularly
	LIST ENTRY NUMBER:	1080201	severe in the tower.
ngland			Contact: Tracey Craig 020 7973 3756

© Historic Eng



		Contact: Tracey Craig 020 7973 3756
SITE NAME:	Church of St John, Royal Lane, Hillingdon	C13 chancel arch and C14 nave and aisles. Tower rebuilt 1629. In 1848 Sir G Gilbert Scott refurbished the building
DESIGNATION:	Listed Place of Worship grade II*, CA	and added transepts and chancel. The tower is surmounted by a wooden cupola which is in poor condition with decay, splits and unsympathetic past repairs. Clay tiles are
CONDITION:	Poor	beginning to fail, valley gutters are poor and patched, and rainwater goods are also in need of attention. The flint
PRIORITY CATEGORY:	C (C)	walling has some loss of pointing. In 2020 Historic England
OWNER TYPE:	Religious organisation	awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for a timber survey of the cupola and also some
LIST ENTRY NUMBER:	1080160	stabilisation works.
		Contact: Tracey Craig 020 7973 3756

© Alex Veal

SITE NAME:	Moated site, west bank of River Pinn, near Ickenha	m (1/2 mile (800m)	north west of church)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002001
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Park Pale, Ruislip		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021402
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Manor Farm moat, Ickenham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1002006
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Bulls Bridge, Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION: Very bad			
CONDITION:	Very bad	TREND:	Deteriorating significantly

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2023	S / LONDON AND SOUTH EAST / HILLINGDON / HOUNSLOW
-----------------------	---------------------------------------------------

SITE NAME:	Cranford Park, Cranford		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Harmondsworth Village, Heathrow Village	25	
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Northwood Town Centre, Green Lane, N	Jorthwood	
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Planning Team (LPA) 01895 250230
SITE NAME:	Old Uxbridge/ Windsor Street, Uxbridge		
DESIGNATION:	Conservation Area, 43 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	lan Thynne (LPA) 01895 558326
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Planning Team (LPA) 01895 250230

# HOUNSLOW



SITE NAME:	Roman Bridge, Jersey Road, Osterley Park	Rusticated and stone-faced bridge with one segmental arch and flanking pairs of rusticated Doric half columns, dating
DESIGNATION:	Listed Building grade II*, RPG grade II*, part in CA	from 1780, by Robert Adam. The bridge is severed from the historic park by the M4 and straddles the borough boundary between Ealing and Hounslow. It is in need of
CONDITION:	Very bad	considerable repair and consolidation, and is subject to heritage crime. Vegetation, potential collapse, and
OCCUPANCY:	N/A	redundancy are key threats to address.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1079401	Contact: Verena McCaig 020 7973 3718

© Historic England

# PRIORITY CATEGORIES

# Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	21, Chiswick High Road W4	Stucco-fronted early C19 three-storey house which has
The serve	DESIGNATION:	Listed Building grade II	been empty for some time. It is in a state of considerable disrepair, including vegetation growth affecting the
	CONDITION:	Poor	stonework and balcony. No suitable scheme for repair and re-use of the building has yet been presented. The Local
	OCCUPANCY:	Part occupied/part in use	Authority and Historic England are considering appropriate
	PRIORITY CATEGORY:	A (A)	action to secure necessary repairs.
	OWNER TYPE:	Private	
Frank .	LIST ENTRY NUMBER:	1189230	Contact: Sean Doran (LPA) 020 8583 4941

© Historic England

© Historic England



	SITE NAME:	Brentford Fountain, Western International Market, Hayes Road	Drinking Fountain of 1877 in grey granite, with railings and lamp standards. Originally located in Brentford and a prominent local landmark, it was moved to its current
	DESIGNATION:	Listed Building grade II	location on the edge of an industrial estate in 1974. The lamp standards are badly damaged or missing and its setting
	CONDITION:	Poor	means that it is subject to anti-social behaviour, fly-tipping, and significant littering. There is interest from a local group,
	OCCUPANCY:	N/A	Brentford Voice, in securing its future and a proposal from
	PRIORITY CATEGORY:	C (C)	a developer to move the fountain back into Brentford with full public access. Discussions are at a very early stage.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1096071	Contact: Sean Doran (LPA) 020 8583 4941



© London Borough of Hounslow

1	SITE NAME:	Gate piers within Osterley Park, Jersey Road	Pair of gate piers with contemporaneous railings designed by Robert Adam. The railings are in need of repair.	
Ţ	DESIGNATION:	Listed Building grade II, part in RPG grade II*, CA		
1	CONDITION:	Poor		
	OCCUPANCY:	N/A		
A. C.	PRIORITY CATEGORY:	C (C)		
24	OWNER TYPE:	Charity (heritage)		
	LIST ENTRY NUMBER:	1391000	Contact: Sean Doran (LPA) 020 8583 4941	

C18 brick wall and gateway, with impost bands, iron gate SITE NAME: Kitchen garden wall, including carved door and wrought iron and carved wooden door. Reputedly built by Princess gate, Gunnersbury Park, Gunnersbury Avenue W3 Amelia out of the profits from gambling. A large section of the wall is evidently unstable and requires extensive repair, and other sections also require repair; significant vegetation Listed Building grade II, RPG DESIGNATION: removal has been carried out. Funding is being sought to grade II\*, CA enable repairs to be undertaken to the western section to allow this area to be used. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) © Historic England OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1080336 Contact: Sean Doran (LPA) 020 8583 4941



	SITE NAME:	Pair of chapels at Isleworth Cemetery, Park Road	Pair of cemetery chapels with central porte cochère built in 1879. They were last used for a service in 1970 and
	DESIGNATION:	Listed Building grade II, CA	subsequently used as a council store and suffered considerable dereliction. Hounslow Men's Shed have
	CONDITION:	Poor	secured a lease on the chapels and carried out preliminary works to enable their use for workshops, along with the
	OCCUPANCY:	Occupied/in use	nearby mortuary buildings. Works have also been carried
	PRIORITY CATEGORY:	F (F)	out to conserve and protect the windows and minor repairs are ongoing, but high-level stonework still requires
	OWNER TYPE:	Local authority	repair and the group are seeking funding to carry this out.
	LIST ENTRY NUMBER:	1272433	Contact: Sean Doran (LPA) 020 8583 4941

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

55

	SITE NAME:	The Keep (Armoury) to Hounslow Cavalry Barracks, Beavers Lane, Hounslow	Built in 1875, consisting of three storeys with four-storey staircase towers at each end and in the centre of the southwest front. Many windows retain heavy cast iron
	DESIGNATION:	Listed Building grade II, CA	shutters with firing loops and massive bolts to the interior. The building has been unused for some years and the top
Fill Provide State	CONDITION:	Very bad	storeys are now inaccessible. This is as a result of rainwater penetration from the rooftop parapet and blockages in the
	OCCUPANCY:	Vacant/not in use	flat roof drainage rainwater pipes. There are currently no
	PRIORITY CATEGORY:	C (C)	specific plans for repairs, but discussions are continuing concerning the future of the wider site.
	OWNER TYPE:	Government or agency	0
© Historic England	LIST ENTRY NUMBER:	1240633	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	Feltham House, Elmwood Avenue, Feltham	Built in the mid-C18 in stock brick and modelled on other Palladian villas, extended in the late C18 with the addition
	DESIGNATION:	Listed Building grade II, CA	of side wings. The interior has been modernised but retains C18 decorations of interest, which may partly be
	CONDITION:	Very bad	attributable to James Wyatt who lived at Hanworth. The building has been unused for several years, and there is
	OCCUPANCY:	Vacant/not in use	extensive rot damage in the principal storey and rainwater
	PRIORITY CATEGORY:	A (A)	penetration. Some ceilings have collapsed and extensive repairs are urgently required. Discussions are pending to
	OWNER TYPE:	Government or agency	secure its repair and re-use as part of plans for the wider
© Historic England	LIST ENTRY NUMBER:	1189466	site. Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	Archway near east entrance lodge, Gunnersbury Park, Gunnersbury Avenue W3	Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park. Urgent repairs to secure the structural stability of the arch
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	were undertaken in 2012, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is
The Transit State	CONDITION:	Poor	being considered as part of studies evaluating future us for the Small Mansion.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1080332	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	Boundary wall at Gunnersbury Park, Gunnersbury Avenue W3	Part of the boundary wall to the garden of the original Gunnersbury House, built 1658-63 by John Webb for Sir
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	John Maynard. Repairs have been carried out to a large section with funding from the National Lottery Heritage Fund. Further extensive sections require repair.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
and the second second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Community interest group	
© Historic England	LIST ENTRY NUMBER:	1322060	Contact: Sean Doran (LPA) 020 8583 4941
N	SITE NAME:	East Lodge to Gunnersbury	Entrance lodge circa 1837. All that remains are small
		Park (Junnershury Avenue VV3	
	DESIGNATION:	Park, Gunnersbury Avenue W3 Listed Building grade II, RPG	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic
		Listed Building grade II, RPG grade II*, CA	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by
	CONDITION:	Listed Building grade II, RPG grade II*, CA Very bad	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating
	CONDITION: OCCUPANCY:	Listed Building grade II, RPG grade II*, CA Very bad N/A	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this
	CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II, RPG grade II*, CA Very bad N/A C (C)	secure the structural stability of the remaining elements of the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating
© Historic England	CONDITION: OCCUPANCY:	Listed Building grade II, RPG grade II*, CA Very bad N/A	the lodge have been completed, grant-aided by Historic England. Vegetation clearance was undertaken by volunteers but repairs are still required. The future of this structure is being considered as part of studies evaluating

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### 

HERITAGE AT RISK 2023 / LONDO	on and south east	/ HOUNSLOW	
ANKAR &	SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue W3	Stable block dating from 1835, on the eastern edge of Gunnersbury Park. The building has suffered considerable
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	dereliction. The Local Authority, Historic England, Gunnersbury Estate 2026 Community Interest Company and other key stakeholders secured major funding,
	CONDITION:	Poor	including from National Highways and Historic England. Extensive works to replace the roof to make it watertight
	OCCUPANCY:	Vacant/not in use	are complete. A feasibility study has tested potential future
	PRIORITY CATEGORY:	F (F)	viable and sustainable uses, with further public consultation planned. Fundraising is commencing for the next phase of
	OWNER TYPE:	Local authority	works towards re-use.
© Historic England	LIST ENTRY NUMBER:	3583 6	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Gothic Boathouse, Gunnersbury Park, Gunnersbury Avenue	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly
11 Juniary	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	funded by Historic England. Extensive further repairs are required and a new use needs to be secured. Discussions are continuing between stakeholders in order to set out
The second s	CONDITION:	Very bad	timescales for a future project, and potential new funding sources are being explored. Works to control the
	OCCUPANCY:	Vacant/not in use	vegetation are planned in the meantime.
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Community interest group	
	LIST ENTRY NUMBER:	1189588	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	The Small Mansion - Gunnersbury House, Gunnersbury Park, Gunnersbury Avenue W3	Built circa 1802, the smaller of two houses on the site of Gunnersbury House which was demolished circa 1801. The mansion had been deteriorating rapidly. The Local Authority, Historic England, Gunnersbury Estate 2026
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Community Interest Company and other key stakeholders secured major funding, including from National Highways and Historic England, for extensive works to the roof,
	CONDITION:	Poor	balustrades, windows and rainwater goods, now complete. A feasibility study tested potential future viable and
And And And And	OCCUPANCY:	Vacant/not in use	sustainable uses, with public consultation planned. Further
© Historic England	PRIORITY CATEGORY:	F (F)	fundraising approaches are being considered.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1080330	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	West Lodge to Gunnersbury Park, Gunnersbury Avenue	Lodge building dating from 1875 in the manner of a gatehouse, located at the south entrance to the park, partly
	DESIGNATION:	Listed Building grade II, RPG grade II*	in residential use. Historic England awarded a grant towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway. The Local Authority is
	CONDITION:	Poor	actively considering options for its full repair and re-use.
	OCCUPANCY:	Part occupied/part in use	
Harris Contraction of the local data	PRIORITY CATEGORY:	C (C)	

© Historic England

Contact: Sean Doran (LPA) 020 8583 4941

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

Local authority

1389619

OWNER TYPE:

LIST ENTRY NUMBER:

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2023 / LONDO	on and south east	/ HOUNSLOW	
	SITE NAME:	West stable block in Gunnersbury Park, Gunnersbury Avenue W3	Early C19 stables situated within Gunnersbury Park. Works to stabilise and repair the shell of the building were completed in 2014. The Local Authority, Historic England,
CHITCH	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Gunnersbury Estate 2026 Community Interest Company and other key stakeholders commissioned a feasibility study to test potential future viable and sustainable uses,
The ac	CONDITION:	Poor	with further public consultation planned. Fundraising is commencing for the next phase of works towards re-use.
Carl Mark	OCCUPANCY:	Vacant/not in use	commencing for the next phase of works towards re-use.
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1096950	Contact: Sean Doran (LPA) 020 8583 4941
N.	SITE NAME:	St Lawrence's Church (former), High Street, Brentford	C15 church tower, with nave dating from 1764 by Thomas Hardwick and later Victorian additions. The building, no
Ada A	DESIGNATION:	Listed Building grade II*, CA	longer in use as a church, has been empty since the 1960s and stripped of its fittings. Extensive stonework repairs
	CONDITION:	Poor	have been carried out, along with works to the roof and
	OCCUPANCY:	Vacant/not in use	rainwater goods. Listed Building Consent and Planning Permission have been secured for conversion to retail and
	PRIORITY CATEGORY:	C (C)	leisure facilities, and further discussions are taking place.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1080302	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	The Hermitage, 17, Upper Sutton Lane, Heston	Late C15 timber-framed house with later additions. It was badly damaged by fire in 2003 and suffered further
CARL CAR	DESIGNATION:	Listed Building grade II	deterioration following theft of the temporary protective roof. The site has been placed in the Local Authority's
	CONDITION:	Very bad	emerging Local Plan which might allow limited housing as
Configuration of	OCCUPANCY:	Vacant/not in use	enabling development.
California (	PRIORITY CATEGORY:	A (A)	
A state of the sta	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1260544	Contact: Sean Doran (LPA) 020 8583 4941
	SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth	Country house built after 1828 with an extension circa 1860. The building has suffered significant deterioration.
	DESIGNATION:	Listed Building grade II, CA	Urgent works were undertaken to stabilise the building and a series of condition reports produced with
	CONDITION:	Very bad	recommendations for repair. The owners and the Local Authority are working together to develop a scheme to
	OCCUPANCY:	Vacant/not in use	bring the house back into full repair and re-use for
And the state of t	PRIORITY CATEGORY:	A (A)	residential and community use under a partial enabling development scheme. The proposal has been approved by
	OWNER TYPE:	Commercial company	the Local Authority and final details are under discussion,
© Historic England	LIST ENTRY NUMBER:	1240343	pending a decision by the Greater London Authority. Contact: Sean Doran (LPA) 020 8583 4941
M H H L I D'A	SITE NAME:	Church of All Saints, Uxbridge Road, Hanworth	Constructed in the 1950s, designed by NF Cachemaille- Day. Built in brick with reinforced concrete dressings and
	DESIGNATION:	Listed Place of Worship grade II	roofs covered in asphalt. It has a tall square nave with lower side aisles and a semi-domical sanctuary. Over the
	CONDITION:	Poor	nave is a large circular lantern with twenty-four stained
	PRIORITY CATEGORY:	A (A)	glass panels between slender concrete mullions surmounted by a tall cross finial. Some mullions are
	OWNER TYPE:	Religious organisation	suffering from cracking and spalling of the concrete. There is concern over the stability of several of the glass panels,
	LIST ENTRY NUMBER:	1241073	some of the glass is cracked and past repairs have been
© Bob Wilson			carried out in non-matching glass.
			Contact: Tracey Craig 020 7973 3756

# PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HOUNSLOW / ISLINGTON

DESIGNATION:

CONDITION:

VULNERABILITY:

LIST ENTRY NUMBER:

SITE NAME:	Double ditched	enclosure beside A30 road 500yd	ls (460m) west of Ea	st Bedfont parish church
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1002043
CONDITION:	Extensive signific	Extensive significant problems		Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	g	NEW ENTRY?:	No
OWNER TYPE:	Commercial company		CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	Romano-British site 1000yds (910m) west of East Bedfont parish church			
DESIGNATION:	Scheduled Monu	Scheduled Monument		1002042
CONDITION:	Extensive signific	Extensive significant problems		Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	g	NEW ENTRY ?:	No
OWNER TYPE:	Commercial cor	Commercial company, multiple owners		Jane Sidell 020 7973 3738
-1	SITE NAME:	Gunnersbury Park W5		< developed in the CI8 by Princess Amelia
U. S. C.	DESIGNATION:	Registered Park and Garden		y Baron Lionel de Rothschild. It became a 25. Long periods of underinvestment

grade II\*, 22 LBs, part in CA

Generally satisfactory but with

Local authority, multiple owners

significant localised problems

Medium

No

Improving

1000808



TREND: NEW ENTRY ?: © Historic England Archive OWNER TYPE: public park in 1925. Long periods of underinvestment affected the condition of buildings and landscape features. An updated masterplan, funded by Historic England, is informing priorities for the next phases of works, with further public consultation planned. Key stakeholders, including the Local Authorities and the Gunnersbury Museum and Park Development Trust, are exploring further fundraising opportunities.

Contact: Christopher Laine 020 7973 3473

SITE NAME:	Grand Union Canal and Boston Manor, Brentford		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Sean Doran (LPA) 020 8583 4941
SITE NAME:	Gunnersbury Park, Brentford W3		
SITE NAME: DESIGNATION:	Gunnersbury Park, Brentford W3 Conservation Area, 21 LBs, part in RPG grade II*	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No Improving

# ISLINGTON



© Historic England

	SITE NAME:	Part of Former House of Detention, below Kingsway College Clerkenwell Centre, Sans Walk EC1	Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. Previous water ingress issues have been addressed but it remains vacant.
and the second	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1025279	Contact: Rachel Godden (LPA) 020 7527 5967

# PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

- aug	S
	C
	C
	C
ALANA	F
	~

A - Henry	SITE NAME:	Railings and gates to Islington Tennis Centre and King George's Field, Market Road N7	Cast iron railings and gates with elaborate piers and finials, probably designed by JB Bunning, 1854. Some cast iron finials have failed, and several have been removed and
	DESIGNATION:	Listed Building grade II	placed into store for safety reasons. A condition survey has been carried out to inform their future conservation and
	CONDITION:	Poor	funding now needs to be identified.
2	OCCUPANCY:	N/A	
- Car	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	9568	Contact: Trystan Lever (LPA) 020 7527 5826


© Historic England

SITE NAME:	Holy Trinity Church, Cloudesley Square NI	Grade II* church, built 1826-9 to the design of Sir Charles Barry. Repairs to the roof and parapets were funded by the
DESIGNATION:	Listed Building grade II*, CA	National Lottery Heritage Fund and Historic England in 2006-7. The Diocese of London closed the church and set
CONDITION:	Very bad	up the multi-functional Cloudesley Centre to provide for a sustainable future. The aisle roofs were repaired in 2020
OCCUPANCY:	Vacant/not in use	and the nave plaster and lath ceiling was renewed in 2021.
 PRIORITY CATEGORY:	A (A)	funded by Historic England and the Diocese. Negotiations are in hand with funders for the completion of external
OWNER TYPE:	Religious organisation	fabric repairs and provision of internal facilities.
LIST ENTRY NUMBER:	1195557	Contact: Ian Harper 07974 979620

SITE		
CO OC PRI		SITE
oc PRI		DES
PRI	DESN	со
	I HE THE DESIGNATION	oc
ow		PRI
	AT TITLE	OV

© Historic England

© Historic England



	SITE NAME:	Soley Mews Chapel (former), Lloyd Baker Street WCI	Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. The building is of stock brick with tracery windows in stone, slate roof, late Decorated Gothic style. It now appears to be occupied and in fair condition following its conversion t residential use. However, the Local Authority and Historic
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	England need to reassess the condition of the whole
	PRIORITY CATEGORY:	F (F)	building in order to be assured of its current status.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1195670	Contact: Lucy Morrow (LPA) 020 7527 3733

© Historic England



State of Sta	SITE NAME:	Islington War Memorial Arch, Manor Gardens N7	War memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the archway
	DESIGNATION:	Listed Building grade II	around which the new building has been constructed. There are drainage and damp problems, causing
	CONDITION:	Fair	incremental decay and affecting the legibility of the names of those who are commemorated on the memorial. The
V	OCCUPANCY:	N/A	Local Authority has been working closely with consultants
	PRIORITY CATEGORY:	C (C)	and stakeholders to better understand the issues with the asset and identify appropriate solutions.
	OWNER TYPE:	Commercial company	
-	LIST ENTRY NUMBER:	1392555	Contact: Rachel Godden (LPA) 020 7527 5967

© Historic England

PRIORITY C	ATEGORIES
------------	-----------

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLINGTON

LIST ENTRY NUMBER:



Railings, walls, gate piers and gates to Caledonian Park, Market Road N7	Railings, walls and gates to Caledonian Market built in 1854 (market demolished). There are major failures to the cast iron, with severe cracking in places. As part of the Cally
Listed Building grade II	Clock Tower Project, funded by the National Lottery Heritage Fund and the Local Authority, some localised
Very bad	repairs are being prioritised and preparatory modelling undertaken. Significant further funding is required in order
N/A	to reinstate all the decorative features and effect suitable
C (C)	repairs and the Local Authority are developing a phased strategy for this long-term project.
Local authority	
1208009	Contact: Trystan Lever (LPA) 020 7527 5826

© Historic England

© Historic England

© Historic England



SITE NAME:	Finsbury Health Centre, Pine Street ECI	Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. Whilst some urgent works
DESIGNATION:	Listed Building grade I, CA	have been carried out, including removal of asbestos, further repairs are still required, particularly to the roof,
CONDITION:	Poor	external walls and windows. Assessment reports and proposals for priority repairs have been prepared and
OCCUPANCY:	Occupied/in use	discussions are taking place with the Local Authority and
PRIORITY CATEGORY:	C (C)	Historic England to secure repair.
OWNER TYPE:	Health authority	
LIST ENTRY NUMBER:	1297993	Contact: Verena McCaig 020 7973 3718



	SITE NAME:	Finsbury Town Hall, Rosebery Avenue ECI	Town hall, built in 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style, with a public hall on
	DESIGNATION:	Listed Building grade II*, CA	the first floor with elaborate plasterwork in Belle Epoque manner. The building is now in use as dance studios with
	CONDITION:	Poor	the main halls available for public use. The owners have undertaken some repairs, but further external works are
	OCCUPANCY:	Occupied/in use	urgently necessary.
191	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1293112	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	St Paul's Church, St Paul's Road NI	St Paul's Church was built in 1826-28 to the design of Sir Charles Barry in an early Gothic Revival style. It was
	DESIGNATION:	Listed Building grade II*, CA	declared redundant in 1980 when the parish united with St Jude in Mildmay Park. The building was leased to St Paul's
	CONDITION:	Poor	Steiner Project in 1995 for use as a school. Repairs have been undertaken, most recently to the aisle roofs, and the
	OCCUPANCY:	Part occupied/part in use	tower and nave ceiling are now the priority. Some safet
	PRIORITY CATEGORY:	C (C)	works have been carried out and an up-dated Conservation Management Plan commissioned. Funding is
	OWNER TYPE:	Charity (non-heritage)	being sought for development and repair.
storic England	LIST ENTRY NUMBER:	1208912	Contact: Ian Harper 07974 979620

© Histo

© Historic England



SITE NAME:	Railings, Thornhill Square NI	Cast iron railings, circa 1852, to the perimeter of the
DESIGNATION:	Listed Building grade II, CA	central garden square, with foliated spear-head finials set in a moulded plinth on brickwork. Parts of the railings are
CONDITION:	Poor	misaligned, degraded and cracked, with missing elements. Historic England part-funded pilot repairs in 2010, and a
OCCUPANCY:	N/A	specialist measured survey and costed condition survey in
PRIORITY CATEGORY:	C (C)	2017. In 2018 a project to repair the enclosed gardens was not able to proceed after funding was withdrawn.
OWNER TYPE:	Local authority	Interested parties are in early talks with the Local Authority about another possible initiative to secure the necessary
LIST ENTRY NUMBER:	1297982	repairs.

Contact: Fabrizio Matillana (LPA) 020 7527 2000

## PRIORITY CATEGORIES

## Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

use).

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HER

HERITAGE AT RISK 2023 / LONDO	on and south east	/ ISLINGTON	
	SITE NAME:	Railings, Wilmington Square WCI	Cast iron railings of 1819-1841, in very poor condition. Urgent works have previously been carried out, but
	DESIGNATION:	Listed Building grade II, CA	currently no funding has been identified for a full repair programme.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
A A A A A A A A A A A A A A A A A A A	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1 195789	Contact: Lucy Morrow (LPA) 020 7527 3733
	SITE NAME:	Church of St Andrew, Bridgeman Road, Islington NI	St Andrews was designed by Francis Newman and John Johnson as part of a development laid out by Joseph Kay,
	DESIGNATION:	Listed Place of Worship grade II, CA	surveyor, for the Thornhill family. The church was completed in 1854. It is built of Kentish ragstone with Bath stone used for the architectural dressings and the spire.
	CONDITION:	Very bad	The church was temporarily closed in July 2019 due to falling stone from the spire. There is serious settlement in
	PRIORITY CATEGORY:	A (A)	the northeast vestry and chancel. In 2020 Historic England
	OWNER TYPE:	Religious organisation	awarded a Covid-19 Emergency Heritage at Risk Response Fund grant for the preparation of specifications for a full
	LIST ENTRY NUMBER:	9548	programme of repairs.
© Historic England			Contact: Ian Harper 07974 979620
	SITE NAME:	Church of St James and attached railings, Clerkenwell Close, Islington EC1	The church was built by architect James Carr between 1788 and 1792 for a Methodist congregation; it was re- ordered in 1882 by Reginald Blomfield for a Church of
	DESIGNATION:	Listed Place of Worship grade II*, CA	England congregation. The steeple was rebuilt in 1849, and in 1900 the vaulted crypt was deepened. The nave parapet gutters and the roofs were repaired in 2018, funded by the
	CONDITION:	Poor	Listed Places of Worship Roof Repair Fund. There are cracks on the west front and decayed iron windows. In
	PRIORITY CATEGORY:	C (C)	2020 Historic England awarded a Covid-19 Emergency
	OWNER TYPE:	Religious organisation	Heritage at Risk Response Fund grant towards repairs to the tower and nave roof.
© Historic England	LIST ENTRY NUMBER:	1207786	Contact: Ian Harper 07974 979620
	SITE NAME:	Union Chapel, Compton Terrace NI	A Congregational chapel, schools and offices by James Cubit, built in 1886-87 with the tower finished in 1889.
	DESIGNATION:	Listed Place of Worship grade I, CA	Three phases of repairs to the tower and high-level roofs were funded by the National Lottery Heritage Fund and Historic England in the 2000s. In 2015 the church carried
ker and a	CONDITION:	Fair	out repairs to the lower level roofs, funded by the Listed Places of Worship Roof Repair Fund. In 2020 Historic
	PRIORITY CATEGORY:	D (D)	England awarded a Covid-19 Emergency Heritage at Risk
	OWNER TYPE:	Religious organisation	Response Fund grant for various repairs to address water penetration into the buildings.
	LIST ENTRY NUMBER:	1208365	Contact: Ian Harper 07974 979620
© Historic England			
mmmmmmmmmm	SITE NAME:	Former Mecca Bingo, 161-169, Essex Road NI	Built as the Carlton Cinema in 1930 by George Coles, previously a bingo hall and now used as a place of worship
	DESIGNATION:	Listed Place of Worship grade II*	by Resurrection Manifestations. The Egyptian-style facade is decorated with multi-coloured faience while the rest is
	CONDITION:	Poor	yellow stock brick under a slated roof. The church has temporary consent for use of the building and for division
	PRIORITY CATEGORY:	C (C)	of the main auditorium. A first phase of renovation and
	OWNER TYPE:	Religious organisation	repair was completed in 2013, but there is evidence of damage to the faience tiles. Proposals for repair and re-use
			and being even and in discussion with the Local Authenity

© Historic England

LIST ENTRY NUMBER: 1292870

are being explored in discussion with the Local Authority and Historic England.

Contact: Ian Harper 07974 979620

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site
- 62

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLINGTON

and and a	SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19	The Passionists (a Roman Catholic re acquired the site in 1858 and built a r
	DESIGNATION:	Listed Place of Worship grade II*, CA	The chapel was rebuilt in 1887-9 by A Romanesque style. Some localised ro carried out in 2015 with a grant from
EAS.	CONDITION:	Poor	Worship Roof Repair Fund. The inter repainted. There are still parts of the
	PRIORITY CATEGORY:	C (C)	poor condition and a comprehensive
	OWNER TYPE:	Religious organisation	needed.
	LIST ENTRY NUMBER:	1279729	Contact: Ian Harper 07974 979620
© lim Linwood			

onists (a Roman Catholic religious order) the site in 1858 and built a monastery and chapel. el was rebuilt in 1887-9 by Albert Vicars in a Neoque style. Some localised roof repairs were ut in 2015 with a grant from the Listed Places of Roof Repair Fund. The interior has been There are still parts of the external fabric in dition and a comprehensive repair programme is

© Jim Linwood

© Historic England	SITE NAME:	Hope Church (former Church of St Mary Magdalene) and attached railings, Holloway Road, Islington N7	Closed Church of England church re-opened as Hope Church in 2013; built 1812-14 by William Wickings as the Chapel of Ease to St Mary's Islington. The church is built of London stock bricks with Portland stone dressings. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	east end tower has settled structurally, and the north and south porches have settled and pulled away from the aisles. The west end and west porch have also settled. The crypt
	CONDITION:	Very bad	is at risk of flooding due to high underground water levels currently controlled by permanent pumping. The Diocese
	PRIORITY CATEGORY:	C (C)	of London is arranging for the north and south porches to
	OWNER TYPE:	Religious organisation	be supported.
- 0	LIST ENTRY NUMBER:	1195637	Contact: Ian Harper 07974 979620





© Historic England

	SITE NAME:	Church of St Silas, Penton Street, Islington NI	Built in 1860, designed by SS Teulon, completed in 1863 by EP Loftus Brock and chancel added in 1884 by W White.
	DESIGNATION:	Listed Place of Worship grade II, CA	The roofs were re-slated in 2010, the south slope with photovoltaic tiles matching the slates in size and colour. Structural repairs to cracks at the west end were
	CONDITION:	Poor	completed in 2016, grant-aided by the National Lottery Heritage Fund. Stone repairs were carried out in 2018 to
	PRIORITY CATEGORY:	D (C)	the north aisle. Repairs were completed to the north
	OWNER TYPE:	Religious organisation	clerestory stonework and windows in 2020. The equivalent work is required to the south elevation although one
	LIST ENTRY NUMBER:	1208241	window in urgent need was repaired June 2022.
ngland			Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Angel NI		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	Bunhill Fields, Finsbury Square EC2		
DESIGNATION:	Conservation Area, 95 LBs, RPG grade I	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
			8
VULNERABILITY:	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

ŬA

- CA LB
- I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- Unitary Authority World Heritage Site WHS

SITE NAME:	Chapel Market NI		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	Clerkenwell EC1		
DESIGNATION:	Conservation Area, 95 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	Holborn Union Infirmary		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	Moorfields EC1		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	St John's Grove N19		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
SITE NAME:	St Lukes ECI		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
	Medium	CONTACT:	Fabrizio Matillana (LPA) 020 7527 2000
VULNERABILITY:			
	Tollington Park N4		
SITE NAME:	<b>Tollington Park N4</b> Conservation Area, 5 LBs	NEW ENTRY?:	No
VULNERABILITY: SITE NAME: DESIGNATION: CONDITION:	-	NEW ENTRY?: TREND:	No No significant change

## KENSINGTON AND CHELSEA

	SITE NAME:	Entrance Arch From Courtfield Gardens, Gaspar Mews SW5	Stucco carriage arch, c1870, with foot arches on either side. The central arch has plain piers, a central channelled
	DESIGNATION:	Listed Building grade II, CA	arch with vermiculated keystone, and pediment. The stucco has deteriorated, and resultant water penetration is
	CONDITION:	Poor	damaging the structure. A sapling has disrupted one side arch, causing loss of stucco and brickwork and extensive
	OCCUPANCY:	N/A	cracking. No owner can be traced, and the Local Authority
	PRIORITY CATEGORY:	B (B)	has undertaken to fund the works. These have yet to commence.
	OWNER TYPE:	Unknown	
ıd	LIST ENTRY NUMBER:	1190812	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

## PRIORITY CATEGORIES

- C Slow decay; no solution agreed.
- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Slow decay: no solution agreed.
   D Slow decay; solution agreed but F not yet implemented.
   C Slow decay: no solution agreed.
   D Slow decay; solution agreed but F not yet implemented.
   D Slow decay; solution agreed but not yet implemented.
   D Slow decay; solution agreed but F not yet implemented.
   D Slow decay; solution agreed but not yet implemented.
   D Slow decay; solution agreed but not yet implemented.
   D Slow decay; solution agreed but not yet implemented. use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- 64

	SITE NAME:	Mausoleum of Joseph Hudson, Harrow Road, Kensal Green Cemetery W10	Opulent classical mausoleum of Portland stone dating from circa 1850. Invasive vegetation and saplings are severely damaging the roof, and the joints in the stonework are
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	separating, allowing water ingress. A condition survey and urgent works are required to this monument to halt further extensive damage.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
listoric England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389190	Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

© His

	SITE NAME:	Tomb of Mary, Lady Montgomerie, Kensal Green Cemetery, Harrow Road W10	Massive sarcophagus of Carrara marble on a grey granite base with a frieze of paterae and fleurs de lys. It is now completely submerged under ivy. Ash saplings further threaten its structural stability.
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	38924	Contact: Sarah Buckingham (LPA) 07970 944 428

	SITE NAME:	Tomb of Thomas Hardwick and Philip Hardwick, Kensal Green Cemetery, Harrow Road W10	Pair of sandstone slab tombs, circa 1870, with marble cross commemorating the architectural dynasty of Thomas, Philip and Philip Charles Hardwick. Philip (1792-1870) was
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	designer of the Euston Arch. The slabs have been subject to considerable subsidence causing the marble cross to lean significantly and progressively.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
the second second second	PRIORITY CATEGORY:	A (A)	
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246086	Contact: Sarah Buckingham (LPA) 07970 944 428

31, Brompton Square, South Kensington SW3

Listed Building grade II, CA

Vacant/not in use

I, Campden Hill W8

Vacant/not in use

F

Listed Building grade II, CA

Poor

F (F)

Poor

F (D)

Private

1391138

Private

1080723



© Historic England

© Historic England

©Н



er rapid	D	Slow decay; so

Е

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Immediate risk of further rapid deterioration or loss of fabric; no А

PRIORITY CATEGORIES

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

House dating from 1824-39, part of Brompton Square. A

extensions. Works on site are ongoing.

Contact: Sarah Buckingham (LPA) 07970 944 428

Contact: Sarah Buckingham (LPA) 07970 944 428

Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country

house in an urban setting. The building is in poor condition. Listed Building Consent and Planning Permission have been

granted for works in association with repair of the building

for use as a family home, and works are underway on site.

series of Planning Permissions and Listed Building Consents have been granted for internal alterations and rear

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10	High brick boundary wall to Harrow Road, a 100-metre section of which collapsed in 2006. Further bays were
	DESIGNATION:	Listed Building grade II, part in RPG grade I, part in CA	subsequently reduced in height due to safety concerns. Historic England awarded a grant towards the first phase of rebuilding the collapsed section which involves piling,
	CONDITION:	Very bad	casting a ground beam and rebuilding the wall as original. Repair works have been completed to ten bays in total,
	OCCUPANCY:	N/A	funded by Historic England and the General Cemetery
	PRIORITY CATEGORY:	C (C)	Company. However, considerable further funding is required to complete essential works to the entire wall.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1191000	Contact: Sarah Buckingham (LPA) 07970 944 428

SITE NAME: Mausoleum of Andrew Ducrow, Mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson, with later Harrow Road, Kensal Green embellishments following Ducrow's own interment. The Cemetery WI0 mausoleum is in poor condition with loss of sculptural Listed Building grade II\*, RPG grade I, CA elements and ironwork, general erosion and vegetation DESIGNATION: causing damage at roof level. A comprehensive condition survey was produced in 2013, funded by Historic England. CONDITION: Poor This monument has been prioritised for conservation; OCCUPANCY: N/A however, no sources of funding have been identified. PRIORITY CATEGORY: C (C) © Historic England OWNER TYPE: Unknown LIST ENTRY NUMBER: 1358179 Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Mausolea of Isabella Gregory and Hall, Harrow Road, Kensal Green Cemetery NW10	Two mausolea dating to the early 1830s, amongst the very earliest in the cemetery, one to Isabella Gregory and the other to Hall. Overgrown vegetation obscures the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition of much of the Gregory mausoleum but spalled stone due to corroding iron cramps is evident. A comprehensive condition survey of the Gregory tomb was
	CONDITION:	Very bad	produced in 2013, funded by Historic England. The Hall mausoleum has been cleared of vegetation but now
and the second second	OCCUPANCY:	N/A	requires a full condition survey.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1227650	Contact: Sarah Buckingham (LPA) 07970 944 428



SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10	1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco central chapel of a Greek Doric tetra style, with (now roofless) pavilions
DESIGNATION:	Listed Building grade I, RPG grade I, CA	containing marble memorial sculptures. There are large catacombs below. The building is no longer in use and is suffering from water ingress. An options appraisal and
CONDITION:	Very bad	updated condition survey have been carried out. Discussions on the future of the building, in conjunction
OCCUPANCY:	Vacant/not in use	with key stakeholders, are progressing.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1 1 9 0 9 9 5	Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic England

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10	Built by John Griffith in 1833 to display tablets and monuments, with brick vaulted catacombs underneath. It is currently in poor condition, with damaged stone and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	plasterwork, encroaching vegetation, and subject to anti- social behaviour. The restoration of a sample bay has been completed, part funded by Historic England, but
	CONDITION:	Poor	considerable further funding is required to complete the works. The freeholder, the General Cemetery Company,
	OCCUPANCY:	N/A	has undertaken considerable vegetation clearance in the
Card Martin	PRIORITY CATEGORY:	C (C)	surrounding area to minimise damage and anti-social behaviour.
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080629	Contact: Sarah Buckingham (LPA) 07970 944 428
States Lates	SITE NAME:	Tomb of Admiral Henry Collins Deacon, Harrow Road, Kensal Green Cemetery W10	Mid-C19 sculptural monument in Portland stone with cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	monument on its base and a significant lean. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
A later	CONDITION:	Poor	accordingly.
	OCCUPANCY:	N/A	
P Maria ana	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389226	Contact: Sarah Buckingham (LPA) 07970 944 428
aut of	SITE NAME:	Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery W10	Marble memorial with sculpture of an anchor and cros a tall pedestal, commemorating the arctic explorer Sir Ross (1777-1856). There is a significant lean to the sou
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England.
	designation:	Listed Building grade II, RPG	and risk from invasive plants. A comprehensive condition
		Listed Building grade II, RPG grade I, CA	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England.
	CONDITION:	Listed Building grade II, RPG grade I, CA Very bad	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England.
© Historic England	CONDITION: OCCUPANCY:	Listed Building grade II, RPG grade I, CA Very bad N/A	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England.
© Historic England	CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C)	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England.
With the second seco	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut
With the second seco	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown 1389215 Tomb of Alexander Bruce, Harrow Road, Kensal Green	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
• Historic England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown 1389215 Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
Image: Second system	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown 1389215 Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
Image: Second	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown 1389215 Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
• Historic England         • Mistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UIST ENTRY NUMBER: SITE NAME: SITE NAME: CONDITION: CONDITION:	Listed Building grade II, RPG grade I, CA Very bad N/A C (C) Unknown 1389215 Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG grade I, CA Poor N/A	and risk from invasive plants. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly. Contact: Sarah Buckingham (LPA) 07970 944 428 Two stage monument dating from 1850, consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised

Contact: Sarah Buckingham (LPA) 07970 944 428

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1389188

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Tomb of Alfred Cooke, Harrow Road, Kensal Green Cemetery W10	A limestone tomb by Thomas Milnes from the mid C19, with a statue of a horse and infant on a pedestal. The sculpture is very badly damaged. A comprehensive
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
Contraction of the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389167	Contact: Sarah Buckingham (LPA) 07970 944 428




a state	SITE NAME:	Tomb of Colonel Gideon Gorrequer, Harrow Road, Kensal Green Cemetery NW10	Elaborate military monument dating from 1841 to Colonel Gorrequer, ADC (aide-de-camp) to the Governor of St Helena during Napoleon's banishment. There is evidence
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	of erosion at foundation level and architectural elements are threatened by ivy growth. Fixings have been lost from the stone plaque on the front of the pedestal. A
	CONDITION:	Poor	comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
	OCCUPANCY:	N/A	accordingly.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389244	Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

© Historic England





	LIST ENTRY NUMBER:	1246079	Contact: Sarah Buckingham (LPA) 07970 944 428
	SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10	Portland stone mausoleum dating from the mid C19. There is erosion at foundation level, and spalling stone due to rusting cramps. The entrance has been secured temporarily
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	to minimise any risk from heritage crime. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
- And	OCCUPANCY:	N/A	
1	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389242	Contact: Sarah Buckingham (LPA) 07970 944 428

## © Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM UA WHS

Unitary Authority World Heritage Site

The second secon	SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10	Portland stone sarcophagus with effigy of a sleeping child in Carrara marble from around 1840. There is a slight lean to the north east, erosion of foundations and invasive
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	vegetation growth. The effigy of the child has been removed for safekeeping. A comprehensive condition survey was produced in 2013, funded by Historic England.
	CONDITION:	Poor	Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389182	Contact: Sarah Buckingham (LPA) 07970 944 428

	SITE NAME:	Tomb of James Poole, Harrow Road, Kensal Green Cemetery W10	Sla ha ele
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	Tł fea in
	CONDITION:	Very bad	ha ha
	OCCUPANCY:	N/A	110
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	


1271534

LIST ENTRY NUMBER:

late chest tomb from the mid C19. Structural settlement as led to compression and shearing of some slate lements. This structural movement needs to be arrested. he tomb has also suffered from the loss of decorative eatures. A comprehensive condition survey was produced n 2013, funded by Historic England. While this monument as been prioritised for conservation, no sources of funding ave been identified.

Contact: Sarah Buckingham (LPA) 07970 944 428

© Histor





	SITE NAME:	Tomb of John Lucas, Harrow Road, Kensal Green Cemetery W10	Tall grey Cornish granite obelisk with Carrara marble bas- relief dating from the end of the C19. The landing stone is broken and sinking into the vault and the monument is
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	leaning significantly. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389238	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ŬA
- Unitary Authority World Heritage Site WHS

A.	SITE NAME:	Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10	Monumental tomb from 1856 comprising a carved coffin under an open aedicule with twelve Corinthian columns which are surmounted by four angels, each with an arm
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	held aloft to support a central wreath, now missing. The monument is in poor condition due to the loss of sculptural elements, sinking on the west side, widespread erosion and
	CONDITION:	Poor	dirt accretions. A comprehensive condition survey was produced in 2013, funded by Historic England. While th
	OCCUPANCY:	N/A	monument has been prioritised for conservation, no
	PRIORITY CATEGORY:	C (C)	sources of funding have been identified.
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1293490	Contact: Verena McCaig 020 7973 3718



	SITE NAME:	Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10	Portland stone altar tomb on a stepped granite base, from circa 1830. The tomb is in poor condition due to erosion and loss of detailing, corrosion of ironwork and heavy
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	overgrowth which has exacerbated the disruption of stone. Railings are missing and bollards have fallen. A comprehensive condition survey was produced in 2013,
	CONDITION:	Poor	funded by Historic England. Works are being prioritised accordingly.
	OCCUPANCY:	N/A	accol dingly.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389237	Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

© Historic England

©Н



Tall Greek grave stele style headstone dating from the end of the C19. Now laid flat and very vulnerable to dirt and SITE NAME: Tomb of Sir Charles Newton, Harrow Road, Kensal Green Cemetery W10 organic growth. There is some erosion and cracking. A comprehensive condition survey was produced in 2013, Listed Building grade II, RPG funded by Historic England. Works are being prioritised DESIGNATION: grade I, CA accordingly. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1389225 Contact: Sarah Buckingham (LPA) 07970 944 428



Large neoclassical chest tomb by JB Papworth dating from SITE NAME: Tomb of the Earl of Galloway, Harrow Road, Kensal Green 1838. There is damage to the kerb stone, widening of Cemetery WI0 joints, invasive plant growth causing extensive disruption and some collapse on the east face. A comprehensive Listed Building grade II, RPG condition survey was produced in 2013, funded by Historic DESIGNATION: grade I, CA England. Urgent works are required to this monument to halt further extensive damage from plant growth. While CONDITION: Very bad this monument has been prioritised for conservation, no OCCUPANCY: N/A sources of funding have been identified. PRIORITY CATEGORY: A(A)OWNER TYPE: Unknown LIST ENTRY NUMBER: 1389178 Contact: Sarah Buckingham (LPA) 07970 944 428

© Historic England

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	LIST ENTRY NUMBER:	1389246	Contact: Sarah Buckingham (LPA) 07970 944 428
) Historic England	OWNER TYPE:	Unknown	
	PRIORITY CATEGORY:	A (A)	
	OCCUPANCY:	N/A	are being prioritised accordingly.
	CONDITION:	Very bad	risk of wind damage. A comprehensive condition survey was produced in 2013, funded by Historic England. Works
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	deterioration of the inscription, and heavy lean of the monument towards the west. Arboreal ivy has almost obscured the monument entirely and now presents a high
	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery NW10	Carrara marble pedestal surmounted by a draped urn with a relief of a dog at its base, dating from 1874. The tomb is in poor condition due to erosion of its carving,



٥I

		Harrow Road, Kensal Green Cemetery W10	from the mid C19. The corrosion of iron cramps is causing spalling of the stone. The ground is eroded around the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
La fre	CONDITION:	Poor	accordingly.
ALL ALL	OCCUPANCY:	N/A	
-	PRIORITY CATEGORY:	C (C)	
d	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246083	Contact: Sarah Buckingham (LPA) 07970 944 428



© Historic England

© Historic England



SITE NAME:	Enclosing walls to Moravian Burial Ground, King's Road SW10	The historic brick walls enclosing the Moravian Bur Ground once enclosed a garden in Sir Thomas Mor estate, and are mostly of Tudor origin, with later ad
DESIGNATION:	Listed Building grade II, part in CA	Historic repairs have used damaging cementitious r for pointing. Other problems relate to structural in and brick decay. A pilot repair project, grant-aided
CONDITION:	Poor	Historic England, was carried out on three sections walls and finished in April 2017. This will be used to
OCCUPANCY:	N/A	the strategy for the repair of the remaining walls. T
PRIORITY CATE	GORY: C (C)	owners are exploring possible sources of funding.
OWNER TYPE:	Religious organisation	
LIST ENTRY NU	MBER: 1224734	Contact: Sarah Buckingham (LPA) 07970 944 428

Holland House, Kensington

Listed Building grade I, RPG

High Street W8

Occupied/in use

Local authority

grade II, CA

Fair

F (F)

1267135

ric brick walls enclosing the Moravian Burial once enclosed a garden in Sir Thomas More's nd are mostly of Tudor origin, with later additions. repairs have used damaging cementitious mortars ing. Other problems relate to structural instability decay. A pilot repair project, grant-aided by England, was carried out on three sections of the finished in April 2017. This will be used to inform egy for the repair of the remaining walls. The are exploring possible sources of funding.

Remains of a large C17 mansion of considerable architectural and historic importance damaged during

and the courtyard used for summer opera events. The

stonework to the north. The east wing has undergone

is required to review risk factors.

Contact: Verena McCaig 020 7973 3718

World War II. The east wing is occupied as a youth hostel

Local Authority has carried out major works on both wings to repair defective rainwater goods, balustrading and

repairs to the windows and repointing. Further inspection

© Historic England



SITE NAME:	All Saints Church, Clydesdale Road, Kensington W11	Designed by William White and completed in 1861, although the spire was never realised. The sanctuary has
DESIGNATION:	Listed Place of Worship grade II*, CA	paintings by Henry Holiday. The slates are suffering from nail sickness and the gutters have many patch repairs. Rainwater leaks are ongoing. There is cracking through the
CONDITION:	Poor	stonework at the west end of the north aisle and in the south transept. Repairs are necessary to the tower
PRIORITY CATEGORY:	C (C)	stonework and to the uneven floor internally. In 2020
OWNER TYPE:	Religious organisation	Historic England awarded a Covid-19 Emergency Heritage at Risk Response Fund grant to undertake a temporary
LIST ENTRY NUMBER:	1080701	repair to the crack in the south transept.
		Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS
---------------

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

	SITE NAME:	Church of St John the Baptist, Holland Road, Kensington W14	Early English style church dating from 1874-1911 by J Brooks and JS Atkins architects. The church has slate
	DESIGNATION:	Listed Place of Worship grade I, CA	pitched roofs, coursed rubble walling with Bath stone dressings and a large rose window at the west end. Extensive repairs to the roofs, high level masonry and
State of the	CONDITION:	Fair	rainwater goods were completed in early 2015, grant aid by the National Lottery Heritage Fund and Historic England. Works to repair the west end roofs and masor
In Mark	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	grant aided by the National Lottery Heritage Fund, were completed in 2017. Further roof repairs are required.
	LIST ENTRY NUMBER:	1080593	Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England



	SITE NAME:	Church of St Michael and All Angels, Ladbroke Grove, Kensington W10	Designed by J and JS Edmeston, built in 1871. Rhineland Romanesque style in London stock brick with terracotta, red Mansfield and Forest of Dean stone dressings, and clay
	DESIGNATION:	Listed Place of Worship grade II, CA	roof tiles. The roofs and rainwater disposal system are in poor condition with water damage evident internally. Some stone and brickwork is also in need of repair.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
-	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1226579	Contact: Tracey Craig 020 7973 3756



© Historic England



© Historic England

	SITE NAME:	Church of St Augustine, Queen's Gate, Kensington SW7	Completed in 1876, designed by William Butterfield in Gothic style. Constructed in Gault brick with stone and red
	DESIGNATION:	Listed Place of Worship grade II*, CA	brick banding, areas of patterned diaper work to parapets and gables, and decorative carved stone panels. There is rich polychromatic decoration internally. Re-slating of the
	CONDITION:	Poor	north slope of the nave and the north aisle was complet in 2011 with funding from Historic England and the National Lottery Heritage Fund. The south side is in nee
A Jam	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	of similar work, along with brick and stone repairs, particularly to the west elevation where mortar re-facings
	LIST ENTRY NUMBER:	1226161	of brickwork are failing.
			Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Kensal Green (All Souls) Cemetery W10	London's first metropolitan cemetery, designed by John William Griffith in 1833. The cemetery contains a large
	DESIGNATION:	Registered Park and Garden grade I, 159 LBs, 2 CAs	number of listed monuments and key buildings also at risk. The Management Plan from 2004 needs revision, but changes to forward planning and operations are having a
	CONDITION:	Generally unsatisfactory with major localised problems	positive impact on tree and vegetation management and other conservation issues. Discussions are taking place between key stakeholders to identify funding opportunit for further investment in key structures and infrastructur
10	VULNERABILITY:	Medium	
	TREND:	Stable	
	NEW ENTRY?:	No	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1000817	Contact: Christopher Laine 020 7973 3473

SITE NAME:	Kensal Green Cemetery, Queen's Park W10		
DESIGNATION:	Conservation Area, 154 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Sarah Buckingham (LPA) 07970 944 428

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / KINGSTON UPON THAMES

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

LIST ENTRY NUMBER:

#### **KINGSTON UPON THAMES**

	SITE NAME:	Garden and boundary walls to Cimero, Thatchers and Wansbeck, Traps Lane	C17 dark red brick walls about seven feet high with tapered flange and offsets, which run along the frontage of houses along Traps Lane and enclosing the garden of
Salary Contest	DESIGNATION:	Listed Building grade II, CA	'Cimero'. The structure of the wall has been compromise by failing pointing and vegetative growth. Part of the wall
	CONDITION:	Poor	collapsed in spring 2020 and repair to this stretch is complete, following the granting of Listed Building Consent.
and the second	OCCUPANCY:	N/A	Vegetation was removed by the Local Authority on the Traps Lane side. A separate section of the wall, between Thatcher's Cottage and Spanish Lodge, has been
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Mixed, multiple owners	buttressed. Further repairs are needed.
© Historic England	LIST ENTRY NUMBER:	1299858	Contact: Rebecca Eng (LPA) 020 8547 5000

Kingston Telephone Exchange,

Ashdown Road, Kingston upon

Listed Building grade II

Commercial company

1080100

Thames

Fair



SITE NAME:	Mortuary Chapels, Bonner Hill Road	Symmetrical Gothic-style twin chapels either side of a carriageway through the cemetery. The slate roofs are
DESIGNATION:	Listed Building grade II	steeply pitched with a central stone spire and open octagonal lantern. The west chapel is still used for
CONDITION:	Poor	memorial purposes. There is general spalling to stonework, and vegetation growing at high level. The east chapel is
OCCUPANCY:	Part occupied/part in use	closed owing to structural movement, and propping is in
PRIORITY CATEGORY:	D (D)	place. The Local Authority has carried out condition and structural surveys. Listed Building Consent has been
OWNER TYPE:	Local authority	secured to carry out structural repairs and works are due to commence in summer 2023.
LIST ENTRY NUMBER:	1358433	Contact: Rebecca Eng (LPA) 020 8547 5000

© Historic England



© Historic England



CONDITION:	Fair	fit-out works for office use near completion. Marketing for	
OCCUPANCY:	Vacant/not in use	a new end user will commence early summer 2023.	
PRIORITY CATEGORY:	F (F)		
OWNER TYPE:	Commercial company		
LIST ENTRY NUMBER:	1080059	Contact: Rebecca Eng (LPA) 020 8547 5000	
		years. Planning Permission has been granted for a wide	
SITE NAME:	Former Head Post Office, 42, Eden Street, Kingston upon Thames	stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider	
SITE NAME: DESIGNATION:	Eden Street, Kingston upon	stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this	
	Eden Street, Kingston upon Thames	stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this building, and works are substantially completed. Part of the building is now being used as a marketing suite for the	
DESIGNATION:	Eden Street, Kingston upon Thames Listed Building grade II	stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this building, and works are substantially completed. Part of the building is now being used as a marketing suite for the overall development and will likely eventually be for restaurant use. The upper levels are to be let to a tenant	
designation: condition:	Eden Street, Kingston upon Thames Listed Building grade II Fair	stone dressings. The building has been vacant for many years. Planning Permission has been granted for a wider redevelopment, including the repair and re-use of this building, and works are substantially completed. Part of the building is now being used as a marketing suite for the overall development and will likely eventually be for	

© Historic England



	SITE NAME:	Church of St Matthew, St Matthew's Avenue, Surbiton	Designed by CL Luck in Gothic style and built in 1875. It has a square tower crowned with a tall octagonal stone spire.
-	DESIGNATION:	Listed Place of Worship grade II	The spire and tower suffered from erosion of stone and pointing, and rusting of embedded ironwork had resulted in
	CONDITION:	Poor	cracking of stone. The mullions to the belfry openings had to be strapped temporarily due to loss of stone. Repairs to
10 A V	PRIORITY CATEGORY:	C (C)	the tower, spire and belfry openings were completed in
Signal and	OWNER TYPE:	Religious organisation	2019, grant aided by the National Lottery Heritage Fund. Priority maintenance works to some roofs and stonework
	LIST ENTRY NUMBER:	1184929	were carried out in 2021 but permanent repairs to the roofs are still required.
_			

Contact: Tracey Craig 020 7973 3756

Contact: Rebecca Eng (LPA) 020 8547 5000

Purpose built telephone exchange, built in 1907 and

opened in 1908. Arts and Crafts style with an asymmetrical

plan. The building has been vacant for many years. Planning

Permission has been granted for a wider redevelopment,

including the repair and re-use of this building, and works are at an advanced stage, with shell repairs completed and

#### PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / KINGSTON UPON THAMES / LAMBETH

SITE NAME:	Coombe Wood		
DESIGNATION:	Conservation Area, 8 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000
SITE NAME:	Fairfield / Knights Park, Kingston Town		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000
SITE NAME:	Grove Crescent, Kingston Town		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rebecca Eng (LPA) 020 8547 5000

## LAMBETH

© I ond

IDETTT			
	Road SE5 9RF SE5 TI Bailey with c	A large symmetrical building of 7 sections built in 1912 by TJ Bailey with complex roofs including spirelets, dressings	
in a	DESIGNATION:	Listed Building grade II, CA	of red brick, stone and terracotta, varied windows and wall enrichment. It became the Kennington Boys' School and
	CONDITION:	Very bad	later the Charles Edward Brooke Girls' School before becoming vacant following the relocation of the school.
	OCCUPANCY: V	Vacant/not in use	The Local Authority commissioned a condition survey in
	PRIORITY CATEGORY:	C (C)	March 2016. Water ingress has caused significant internal damage and works to make the building wind and
	OWNER TYPE:	Local authority	weathertight are to commence in 2023. No future user has been identified.
idon Borough of Lambeth	LIST ENTRY NUMBER:	1184669	Contact: Douglas Black (LPA) 020 7926 4065



			Contact. Douglas Diack (LI A) 020 7720 4005
	SITE NAME:	Mausoleum of George Dodd, Norwood Road, West Norwood Memorial Park SE27	Mausoleum, circa 1865, by Thomas Allom. Built of white marble in an Italian Gothic style, with a rectangular plan of three bays defined by pinnacle buttresses. In 2019 the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for People programme which secured funding for the repair of priority
-	CONDITION:	Very bad	monuments. Work on the wider project is currently progressing. The vegetation has been removed (spring
	OCCUPANCY:	N/A	2023), however the mausoleum is in a very poor state of
	PRIORITY CATEGORY:	A (F)	repair, and discussions are in progress regarding repairs and potential funding sources.
	OWNER TYPE:	Unknown	

1325944

© Historic England



DESIGNATION: List CONDITION: Poor OCCUPANCY: Par PRIORITY CATEGORY: C (	Streatham Hill Theatre, 110, Streatham Hill SW2 SW2	Constructed by WGR Spague and WH Barton in 1928. Steel framed construction clad in brick with the frontage	
	DESIGNATION:	Listed Building grade II, CA	clad in Doulton Carrara terracotta. An unusually lavish example, with a significant amount of survival, despite a
	CONDITION:	Poor	direct hit during World War II after which the interior was repaired to the original design. It remained in use as a
	OCCUPANCY:	Part occupied/part in use	theatre until 1962 and then as a bingo hall until 2017, b
	PRIORITY CATEGORY:	C (C)	now much of the building is no longer in use. There is flooding in the basement subways causing deterioration of
	OWNER TYPE:	Religious organisation	the fabric and other areas show signs of water ingress.
	LIST ENTRY NUMBER:	1244564	Contact: Nicola Xuereb (LPA) 0207 926 1217

© Historic England

#### PRIORITY CATEGORIES

## Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

Contact: Douglas Black (LPA) 020 7926 4065

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

74

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LAMBETH

LIST ENTRY NUMBER:



SITE NAME: Gates, piers and railings at Western Block of Number 39 (Beaufoy School Technical Block), Black Prince Road, Vauxhall SEI I DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1183436

Wrought iron railings in a scalloped pattern on a granite plinth and three pairs of wrought iron gates, circa 1907. Currently in poor condition, suffering from deterioration and pigeon damage. Discussions are underway regarding the necessary repair works and funding sources.


Contact: Douglas Black (LPA) 020 7926 4065

© Historic England



SITE NAME:	Dorchester Court, Herne Hill SE24	Eight blocks with 96 flats around a central landscaped courtyard, dating from 1933-4 by Leslie H Kemp and
DESIGNATION:	Listed Building grade II	Frederick E Tasker. There are structural problems with the balconies and general external deterioration. A Listed
CONDITION:	Poor	Building Consent application for the extension and refurbishment of the blocks is pending determination.
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1390780	Contact: Douglas Black (LPA) 020 7926 4065

© Historic England



1358299

Mid-C19 ragstone walls and ironwork in a partial state of collapse. Planning Permission and Listed Building Consent have been granted for their repair and restoration. Work is now complete on the Garden Museum, grant-aided by the National Lottery Heritage Fund, and discussions are ongoing to identify a scheme and funding for the repair of the walls, railings and gates.

Contact: Douglas Black (LPA) 020 7926 4065



D

Е

SITE NAME:	Augustus Ralli Mortuary Chapel, Norwood Road, West Norwood Memorial Park SE27	Doric temple mortuary chapel circa 1872, attributed to J Oldrid Scott, within the Greek Burial Ground and known as St Stephen's Chapel. The chapel was in poor condition
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	due to subsidence, collapsed steps and internal water damage. In 2019 the National Lottery Heritage Fund awarded the Local Authority a grant under the Parks for
CONDITION:	Fair	People programme which secured funding for the repair of priority monuments. Work on the wider project is
OCCUPANCY:	N/A	currently progressing and memorial repairs are nearly
PRIORITY CATEGORY:	F (F)	complete with an anticipated completion date in summer 2023.
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1064989	Contact: Simon Buteux 07973 498013

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

of

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LAMBETH



SITE NAME: Catacombs beneath the Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II\*, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER:

Catacombs circa 1837; cemetery laid out circa 1837 by Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs. Moisture surveys are ongoing; levels appear to be stabilising/reducing. Discussions are ongoing regarding potential funding sources and long-term use.

© Historic England



© London Borough of Lambeth

1263192 Contact: Douglas Black (LPA) 020 7926 4065 SITE NAME Cross decorated with blue and buff ceramic tiles by Tomb of Ibbotson Family, Norwood Road, West Doulton of Lambeth on a pedestal with grave slab dating from 1904. Tiles are missing and cementitious repairs are causing further damage. In 2019 the National Lottery Norwood Memorial Park SE27 Listed Building grade II, RPG Heritage Fund awarded the Local Authority a grant under DESIGNATION: grade II\*, CA the Parks for People programme which secured funding for the repair of priority monuments. Work on the wider CONDITION: Poor project is currently progressing and memorial repairs are OCCUPANCY: N/A nearly complete with an anticipated completion date in summer 2023. PRIORITY CATEGORY: F (F) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1250687 Contact: Douglas Black (LPA) 020 7926 4065



© Historic England



Ionic temple mausoleum dating from the late C19 within SITE NAME: Tomb of XE Balli Family, Norwood Road, West the Greek Burial Ground. There is evidence of movement Norwood Memorial Park SE27 to the entablature and collapse of the steps. In 2019 the National Lottery Heritage Fund awarded the Local Listed Building grade II, RPG DESIGNATION: Authority a grant under the Parks for People programme grade II\*, CA which secured funding for the repair of priority monuments. Work on the wider project is currently CONDITION: Fair progressing and memorial repairs are nearly complete with N/A OCCUPANCY: an anticipated completion date in summer 2023. PRIORITY CATEGORY: F (F) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1120820 Contact: Douglas Black (LPA) 020 7926 4065



SITE NAME: Monument to George Abell, St Chest tomb of circa 1826 commemorating George and Leonard's churchyard, Elizabeth Abell. The slab of Portland limestone with a Streatham High Road, curved edged top has broken and the plinth is in a bad condition. A condition survey has been prepared, with Streatham SWI6 support from Historic England, and funding is now being DESIGNATION: Listed Building grade II, CA sought to secure the necessary repair works. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1323730 Contact: Douglas Black (LPA) 020 7926 4065

#### © London Borough of Lambeth

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site WHS

## 

HERITAGE AT RISK 2023 / LONDO	on and south east	/ LAMBETH	
	SITE NAME:	Monument to Joseph Hay, St Leonards churchyard, Streatham High Road, Streatham SW16	Coade stone chest tomb in railed enclosure, dated 1808 by Coade and Sealy. The railings are broken and in a poor state of repair. A condition survey has been prepared, with support from Historic England, and funding is now being
	DESIGNATION:	Listed Building grade II, CA	sought to secure the necessary repair works.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1323732	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa 1808 by Coade and Sealy. The Coade stone is in an advanced state of decay. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to
	DESIGNATION:	Listed Building grade II, CA	secure the necessary repair works.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	32373	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Wall on the south side of St John with All Saints' churchyard, Waterloo Road SEI	Early C19 stock brick walls, spalled with cracked brickwork. Some of the finials are broken or missing. A structural survey has been carried out and the Local
	DESIGNATION:	Listed Building grade II, CA	Authority is investigating potential funding sources for repairs.
	CONDITION:	Poor	
拉《学校学生》	OCCUPANCY:	N/A	
Contract of the	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1068687	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	The Clapham Orangery, Worsopp Drive SW4	Orangery built in 1793 to the design of William Burgh, in a Palladian style. It stood in the grounds of Thornton House,
No.	DESIGNATION:	Listed Building grade II	demolished in the 1940s. Now standing in the middle of a housing estate. Discussions regarding maintenance of the
	CONDITION:	Fair	roof and rainwater goods have commenced.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
the sector of th	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1068843	Contact: Douglas Black (LPA) 020 7926 4065
© Historic England		1000015	Contact. Douglas black (El 11) 020 7720 1005
	SITE NAME:	Church of St Leonard, Streatham High Road, Streatham SW16	Designed by J Parkin, built 1841, chancel added 1862 by Benjamin Ferrey. The lower tower and spiral stair date from mid C14. The church was burnt out in 1975; repaired
	DESIGNATION:	Listed Place of Worship grade II, CA	and re-ordered by Douglas Feast. The aisle and nave roofs have been re-slated and the flat roofs either side of the tower re-covered along with stucco repairs to the north
	CONDITION:	Poor	side in 2015 and the south side in 2018, both with funding from the National Lottery Heritage Fund. Works to
	PRIORITY CATEGORY:	C (C)	underpin and repair the north porch were completed in
	OWNER TYPE:	Religious organisation	2019. Historic England awarded a Covid-19 response grant to repair the stained-glass windows.
© Historic England	LIST ENTRY NUMBER:	1100267	Contact: Tracey Craig 020 7973 3756

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LAMBETH / LEWISHAM

SITE NAME:	Leigham Court Estate, Streatham SW2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065
SITE NAME:	Vassall Road, Brixton SW9		
DESIGNATION:	Conservation Area, 43 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065
SITE NAME:	West Norwood SE27		
DESIGNATION:	Conservation Area, 75 LBs, part in RPG grade II*	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Douglas Black (LPA) 020 7926 4065

## LEWISHAM

	SITE NAME:	Livesey Hall War Memorial, Perry Hill SE26 SE26	War Memorial, designed by Sydney March, Kent; unveiled in 1920. Lifesize female figure of an angel in bronze with
	DESIGNATION:	Listed Building grade II	arms outstretched upwards and wings spread out horizontally. Bronze plaques commemorate the employed
	CONDITION:	Poor	of the South Suburban Gas Company who lost their lives in World War I and World War II. It is vulnerable to heritage
	OCCUPANCY:	N/A	crime and two of the plaques are missing. Discussions ar
	PRIORITY CATEGORY:	A (New entry)	underway (March 2023) regarding the necessary repair works.
	OWNER TYPE:	Commercial company	
nd	LIST ENTRY NUMBER:	1253111	Contact: Joanna Ecclestone (LPA) 020 7974 2078

© Historic England

-

© London Borough of Lewisham

	SITE NAME:	Olympia Convoy's Wharf, Prince Street SE8	Cast and wrought iron slip covers of 1845-47 by Messrs George Baker and Sons in the former Deptford Royal
A	DESIGNATION:	ATION: Listed Building grade II and portions to the	Dockyard. The arched iron construction of two main spans and perimeter cantilevered aisles is clad in corrugated iron
	CONDITION:		to the roof and sides. The iron frame is heavily corroded in certain areas and previous ad hoc repairs are temporarily
OCCUPANCY:	Vacant/not in use	providing support. Used previously for storage through to	
1-01	PRIORITY CATEGORY:	IER TYPE: Commercial company	the late C20, it is now empty. Outline planning permissior was granted in 2015 for the redevelopment of the wider Convoys Wharf site and a proposal for re-use of this building is expected in 2023.
Sea. W	OWNER TYPE:		
	LIST ENTRY NUMBER:	1213012	Contact: Joanna Ecclestone (LPA) 020 8314 9912



© Historic England

	SITE NAME:	Holland and Company's Distillery, 14 and 16, Deptford Bridge SE8	Former offices of the Holland and Company's Distillery, dating from the late C18. On the ground floor at the east end is a double door and a carriage entrance, framed in late
	DESIGNATION:	Listed Building grade II	C19 stonework with dentil cornice and an inscription in the small pediment over: "Established 1779. Holland and Co's
	CONDITION:	Poor	Distillery and Bonded Store". The building has been empty for a number of years and is deteriorating. The Local
	OCCUPANCY:	Vacant/not in use	Authority has written to the owner to discuss the building's
	PRIORITY CATEGORY:	C (C)	condition.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080000	Contact: Joanna Ecclestone (LPA) 020 8314 9912

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

# Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## CA LB

- LPA NP RPG SM

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LEWISHAM



SITE NAME:	Beckenham Place, Foxgrove Road, Beckenham Place Park	Mansion built c1773 and situated within former park land. The National Lottery Heritage Fund completed a project in
DESIGNATION:	Listed Building grade II*, CA	2019 for the wider park, which restored the setting of the mansion and the listed stableyard. The mansion currently
CONDITION:	Fair	accommodates several meanwhile uses whilst the Local Authority investigates funding options for its full repair, and
OCCUPANCY:	Part occupied/part in use	long-term use. Historic England awarded the Local
PRIORITY CATEGORY:	C (C)	Authority a Covid-19 Emergency grant for priority roof repairs, which were completed in 2021. A Listed Building
OWNER TYPE:	Local authority	Consent application for extensive window repairs is under consideration (March 2023).
LIST ENTRY NUMBER:	1BFR: 1359317	Contact: Simon Buteux 07973 498013

© Historic England



© Historic England

© Historic England

	CONDITION:	Poor	and to dry rot stabilised the building although some water ingress persists. The Local Authority secured a restoration
	OCCUPANCY:	Vacant/not in use	partner in 2017 and an application for full repair of the
	PRIORITY CATEGORY:	C (C)	building along with development in the grounds was submitted in 2022. Planning Permission and Listed Building
	OWNER TYPE:	Local authority	Consent, subject to a s106 agreement, is under consideration.
	LIST ENTRY NUMBER:	39 8	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	SITE NAME:	Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old Churchyard SEI3	A stone chest tomb from the middle of the C18 commemorates Captain Limeburner of the Royal Navy and his wife. The south side has lost its central panel and the
-	DESIGNATION:	Listed Building grade II, CA	angle balusters are displaced. A condition survey has been prepared, with funding from Historic England, and funding
合作的	CONDITION:	Very bad	for repair and restoration works has been secured through a Section 106 agreement.
-	OCCUPANCY:	N/A	a section rob agreement.
	PRIORITY CATEGORY:	A (A)	
The	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392002	Contact: Joanna Ecclestone (LPA) 020 8314 9912

LIST ENTRY NUMBER:	1392002	Contact: Joanna Ecclestone (LPA) 020 8314 9912
SITE NAME:	Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard SE13	An elaborate Rococo tomb of 1769 in Portland stone and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints from
DESIGNATION:	Listed Building grade II*, CA	vegetation growth, and some collapse. A condition survey has been prepared, with funding from Historic England, and
CONDITION:	Very bad	funding for repair and restoration works has been secured through a Section 106 agreement.
OCCUPANCY:	N/A	un ough a section roo agreement.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1391993	Contact: Simon Buteux 07973 498013

© Historic England



	SITE NAME:	Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE13	Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head, dating from 1752. The
	DESIGNATION:	Listed Building grade II, CA	monument has lost its railings, back plates and inscription panels, and vegetation growth is causing further damage. A
	CONDITION:	Poor	condition survey has been prepared, with funding from Historic England, and funding for repair and restoration
1	OCCUPANCY:	N/A	works has been secured through a Section 106 agreement.
	PRIORITY CATEGORY:	A (A)	
and the	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1391998	Contact: Joanna Ecclestone (LPA) 020 8314 9912

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

use).

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### 

HERITAGE AT RISK 2023 / LONDO	on and south east	/ LEWISHAM	
	SITE NAME:	Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SEI3	Raised ledger stone of 1727. Ground subsidence has caused some sinking and movement to the ledger, which is now set at an angle. A condition survey has been prepared,
The last	DESIGNATION:	Listed Building grade II, CA	with funding from Historic England, and funding for repair and restoration works has been secured through a Section
22 Totals	CONDITION:	Poor	106 agreement.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392012	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	SITE NAME:	Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SEI3	Stone chest tomb erected in 1767. The tomb is badly damaged by vegetation growth through open joints. A condition survey has been prepared, with funding from
	DESIGNATION:	Listed Building grade II, CA	Historic England, and funding for repair and restoration works has been secured through a Section 106 agreement.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392013	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	SITE NAME:	Tomb of Lord Dacre, Lee Terrace, St Margaret's Old Churchyard SEI3	This composite urn monument to Lord Dacre dates from 1794. All the elements now lie disassembled on the ground. The monument needs urgent attention to avoid
A Partie	DESIGNATION:	Listed Building grade II, CA	further damage or loss of its components. A condition survey has been prepared, with funding from Historic
	CONDITION:	Very bad	England, and funding for repair and restoration works has
	OCCUPANCY:	N/A	been secured through a Section 106 agreement.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392008	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	SITE NAME:	Tomb of Rev. Thomas Negus, Lee Terrace, St Margaret's Old Churchyard SEI3	Chest tomb of 1765, badly damaged from vegetation which has infiltrated through open joints and cracked the ledger slab. One angle baluster has been lost and there is a risk of
P.L. TINK	DESIGNATION:	Listed Building grade II, CA	further collapse. A condition survey has been prepared, with funding from Historic England, and funding for repair
A CALLARD COM	CONDITION:	Very bad	and restoration works has been secured through a Section 106 agreement.
Nor I CO	OCCUPANCY:	N/A	
the second	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	3920	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	SITE NAME:	Tomb of Thomas Butler, Lee Terrace, St Margaret's Old Churchyard SEI3	Chest tomb of 1733. The panels on both sides and on one end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition
	DESIGNATION:	Listed Building grade II, CA	survey has been prepared, with funding from Historic England, and funding for repair and restoration works has
	CONDITION:	Very bad	been secured through a Section 106 agreement.
and the	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392003	Contact: Joanna Ecclestone (LPA) 020 8314 9912

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LEWISHAM



© Historic England

© Historic England

	SITE NAME:	Tomb of Tredway, Lee Terrace, St Margaret's Old Churchyard SEI3	A composite monument formed by a mid/late C18 chest tomb surmounted by an early C19 sarcophagus. The end panel of the upper part is broken. A condition survey has
	DESIGNATION:	Listed Building grade II, CA	been prepared, with funding from Historic England, and funding for repair and restoration works has been secured
	CONDITION:	Poor	through a Section 106 agreement.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392010	Contact: Joanna Ecclestone (LPA) 020 8314 9912



	SITE NAME:	Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE13	Coade stone chest tomb from the late C18. The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. The tomb is in need of
120	DESIGNATION:	Listed Building grade II, CA	attention to avoid serious structural damage. A condition survey has been prepared, with funding from Historic
Desi.	CONDITION:	Poor	England, and funding for repair and restoration works has been secured through a Section 106 agreement.
1 all	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
A CONTRACTOR	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392001	Contact: Joanna Ecclestone (LPA) 020 8314 9912

SITE NAME:	Rileys (former Temperance Billiard Hall), 233-241, Lewisham High Street SE13	A temperance billiard hall built 1909-10, originally incorporating a café, lounge and shops facing Lewisham High Street. Listed as a well-surviving example of an
DESIGNATION:	Listed Building grade II	uncommon building type. The building had been empty t a number of years and was showing signs of neglect.
CONDITION:	Poor	Planning Permission and Listed Building Consent were granted in 2017 for conversion to a church, with associated
OCCUPANCY:	Vacant/not in use	changes to restore and change parts of the building. All
PRIORITY CATEGORY:	F (F)	structural refurbishment and reconstruction and part of the internal works were completed in 2021, with the final
OWNER TYPE:	Religious organisation	remaining works due to start in 2023.
LIST ENTRY NUMBER:	1392397	Contact: Joanna Ecclestone (LPA) 020 8314 9912
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Billiard Hall), 233-241, Lewisham High Street SE13DESIGNATION:Listed Building grade IICONDITION:PoorOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:F (F)OWNER TYPE:Religious organisation

	SITE NAME:	Baring Hall Hotel and Stable Block, Baring Road, SE12 SE12	Public house and stable block designed by Ernest Newton 1881-1882, with later additions. The pub is a prominent
BARING HALL	DESIGNATION:	Listed Building grade II	landmark in the centre of Grove Park. It was occupied at ground and basement only and in use as a pub but was
	CONDITION:	Poor	closed and broken into during Lockdown. The stable block is unoccupied and derelict but is now secure, although not
	OCCUPANCY:	Vacant/not in use	weathertight (March 2023). Listed Building Consent was
Dinka	PRIORITY CATEGORY:	A (A)	granted in 2021 for works to protect and preserve the building and urgent works were carried out in March 2023
	OWNER TYPE:	Commercial company	making the main building secure, wind and weathertight. The owner is marketing the building.
st	LIST ENTRY NUMBER:	45645	Contact: Joanna Ecclestone (LPA) 020 8314 9912

© Baring Hall Trust



I de la competencia de la comp	SITE NAME:	Church of St Swithun, Hither Green Lane, Lewisham SEI3	This church was completed in 1893 to the designs of Ernest Newton, with an extension in 1905. A small mission church
	DESIGNATION:	Listed Place of Worship grade II	of 1884 survives at the east end. Built of red Wrotham brick, Bath stone is used for windows and dressings, and
	CONDITION:	Poor	Portland stone for copings, all under slated roofs. A programme of repairs to windows and masonry at the
	PRIORITY CATEGORY:	C (C)	west end was completed in 2015, grant aided by the
	OWNER TYPE:	Religious organisation	National Lottery Heritage Fund and Historic England. Further repairs are required.
E1 25	LIST ENTRY NUMBER:	1192516	Contact: Ian Harper 07974 979620

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site
- 81

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LEWISHAM / LONDON LEGACY (MDC)

	SITE NAME:	Church of St Mary the Virgin, Lewisham High Street, Lewisham SEI 3	This unusual Georgian church, raised over a crypt, was completed in 1774 by George Gibson Jr; it replaced a medieval church and incorporated the original tower. The
1- Carlos	DESIGNATION:	Listed Place of Worship grade II*, CA	nave was re-modelled and the chancel added in 1882 by William Blomfield. The chancel was re-ordered in 1995-96. A nave re-roofing and drainage project was completed in
	CONDITION:	Poor	2016 with a grant from the National Lottery Heritage Fund. The congregation is actively exploring options for funding
	PRIORITY CATEGORY:	C (C)	for a second phase of roofing repairs to the tower and
	OWNER TYPE:	Religious organisation	chancel.
© Historic England	LIST ENTRY NUMBER:	1193297	Contact: Ian Harper 07974 979620

SITE NAME:	Deptford High Street SE8		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Joanna Ecclestone (LPA) 020 8314 9912

## LONDON LEGACY (MDC)

``	/		
	SITE NAME:	Abbey Mills Pumping Station (Station C) with associated Valve House, Abbey Lane E15	Pumping station 1910-14, white stock brick with terracotta and moulded stone dressings. The internal pumping floor is sunk deep below ground level. Works are planned to
	DESIGNATION:	Listed Building grade II, CA	ensure that the building remains wind and watertight. Listed Building Consent has been granted and these works
The second	CONDITION:	Poor	are now out to tender with a view to commencement summer 2023. There are no long-term proposals for the
	OCCUPANCY:	Vacant/not in use	re-use of the building at this stage, although options are
Con Alter	PRIORITY CATEGORY:	D (C)	being discussed.
	OWNER TYPE:	Utility	
land	LIST ENTRY NUMBER:	1392550	Contact: Planning Officer (LPA) 020 3288 8820

Bases of pair of chimneystacks

at Abbey Mills Pumping Station,

Listed Building grade II, CA

Abbey Lane EI5

Very bad

N/A

B (A)

Utility

1357995

© Historic Engla

	A Mar	3.4. di 14
F		
	44	
1		
	20	

© Historic England



	SITE NAME:	Ancillary Pump House at Abbey Mills Pumping Station (Station B), Abbey Road E15	Pump house circa 1868, probably by Bazalgette and Cooper, built in a similar style to the main pumping station. There is some evidence of water ingress and the design of
日本	DESIGNATION:	Listed Building grade II, CA	the exterior downpipes makes them vulnerable to plant growth and blockages. Listed Building Consent has been
1	CONDITION:	Poor	granted and repair works are now out to tender with a view to commencement summer 2023. The building is
14 M	OCCUPANCY:	Vacant/not in use	vacant and has no identified use although options are being
1	PRIORITY CATEGORY:	D (C)	discussed.
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357994	Contact: Planning Officer (LPA) 020 3288 8820

© Historic England

D

Е

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Immediate risk of further rapid deterioration or loss of fabric; no А

PRIORITY CATEGORIES

- solution agreed. Immediate risk of further rapid В
- deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

Two chimney bases built in 1865 by Sir Joseph Bazalgette. Elaborate pedimented porches to battered brick plinths

crowned by stone bases of octagonal stacks (demolished).

The brick and stonework have been severely damaged by

invasive plant growth, although this is now being monitored and removed regularly. The stonework porches have

suffered partial collapse. A survey has been carried out and

remedial works are planned. Listed Building Consent has

expected to commence summer 2023.

Contact: Planning Officer (LPA) 020 3288 8820

been granted and these works are now out to tender and

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / LONDON LEGACY (MDC) / MERTON



SITE NAME:	Tide Mill (known as the House Mill), Three Mill Lane E3
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1080970

Tide Mill dating from 1776 and last used in 1941. Much of the building fabric has been repaired, but work is needed to the undershot water wheels and surviving machinery, and to find a solution to significantly increased flooding at ground floor level. The House Mill Trust continues to work towards a sustainable strategy for repair of machinery, along with improvements to education and community facilities. Extensive repairs and decorative works to the roof, external doors, and windows have been completed.


Contact: Verena McCaig 020 7973 3718

© Historic England

SITE NAME:	Sugar House Lane, Stratford E15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574
SITE NAME:	Three Mills, Stratford/Bow EI5		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574

#### MERTON

	SITE NAME:	west of easternmost block, 9, 11, 15 and 17, Windsor Avenue the former Merton Priory, constructed from flint ar rubble stone. The walls have been subjected to ext	Fragments of medieval and probably later precinct wall of the former Merton Priory, constructed from flint and rubble stone. The walls have been subjected to extensive damage and loss through unauthorised works and the Local
	DESIGNATION:	Listed Building grade II, CA	Authority are considering appropriate enforcement action.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1194014	Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England



		1200007	
	SITE NAME:	Tomb of Thomas Stanly, St Peter and St Paul's Churchyard, Church Road, Mitcham	Table tomb over large podium erected in the early C18. The podium is severely damaged by vegetation. A condition survey has been carried out, funded by Historic
	DESIGNATION:	Listed Building grade II, CA	England, but no funding has been identified to enable the necessary works to be carried out.
and I	CONDITION:	Very bad	
100	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080949	Contact: Jill Tyndale (LPA) 020 8545 3041

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS
---------------

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ

ŴĤS

Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MERTON

HERITAGE AT RISK 2023 / LONDO	JN AND SOUTH EAST	/ MERTON	
	SITE NAME:	Portion of wall on the west side of River Pickle between Merton High Street and Merantun Way, High Street, Wimbledon Village SW19	Formerly part of the precinct wall to Merton Priory, consisting of medieval flint and rubblestone. Sections of the wall are in poor condition and have collapsed due to vegetation growth. The National Trust has developed a plan towards its conservation and long-term maintenance,
	DESIGNATION:	Listed Building grade II, part in CA	with improved public access, in conjunction with Historic England, the Local Authority, Merton Local History Society and Merton Priory Trust. In 2020 Historic England awarde
	CONDITION:	Very bad	a Covid-19 Emergency Heritage at Risk Response Fund
	OCCUPANCY:	N/A	grant for emergency stabilisation work. Permanent repair works have now commenced.
© Historic England	PRIORITY CATEGORY:	F (A)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1358009	Contact: Jill Tyndale (LPA) 020 8545 3041
	SITE NAME:	Burn Bullock Public House, 315, London Road	Former public house, previously the Kings Head Hotel, with C16 interior and exterior features and C18 front, it
	DESIGNATION:	Listed Building grade II, CA	had been illegally occupied as a House in Multiple Occupation and has suffered associated deterioration.
	CONDITION:	Very bad	Essential repairs had been carried out to make the building weatherproof and it was decorated externally. No
	OCCUPANCY:	Part occupied/part in use	applications for development and re-use of the building
	PRIORITY CATEGORY:	C (C)	have been submitted, although early discussions have taken place and a building archaeology study undertaken. The
	OWNER TYPE:	Commercial company	Local Authority are taking enforcement action to secure its repair.
© Historic England	LIST ENTRY NUMBER:	9339	Contact: Jill Tyndale (LPA) 020 8545 3041
	SITE NAME:	Ravensbury Mill (North Wing), 245, Morden Road, Morden	C18 and C19 snuff mill powered by water. The north wing is subject to a Section 106 agreement. There is slow
	DESIGNATION:	Listed Building grade II, CA	progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the north
	CONDITION:	Fair	wing by Wandle Industrial Museum. Discussions are ongoing to resolve these outstanding issues.
	OCCUPANCY:	Part occupied/part in use	
And a state of the	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1080857	Contact: Jill Tyndale (LPA) 020 8545 3041
	SITE NAME:	Mausoleum of Sir Joseph William Bazalgette, St Mary's Churchyard, St Mary's Road, Wimbledon SW19	Portland stone mausoleum from the end of the C19. Bazalgette was the designer of the main London trunk sewer system and the builder of the Victoria and Albert Embankments in the 1860s. The ironwork requires repair
Personal State	DESIGNATION:	Listed Building grade II, CA	and the gates are missing. Water ingress is causing gradual collapse of the internal brickwork to the roof. Charity
	CONDITION:	Poor	Habitats & Heritage and the church have begun to explore possibilities for developing a project and seeking funding to
	OCCUPANCY:	N/A	enable the necessary works to be carried out.
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080887	Contact: Jill Tyndale (LPA) 020 8545 3041

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MERTON

	SITE NAME:	Tomb of Gerard De Visme 10 Feet to north of west tower of Chapel in Churchyard of St Mary, St Mary's Road, Wimbledon SW19	Stone tomb of Gerard de Visme, who died in 1797, consisting of a square plan, rusticated pyramid with corner acroteria to the base. An acroterion has fallen due to movement in the stone blocks, and another is dislodged. Slow deterioration continues. A condition survey has been
	DESIGNATION:	Listed Building grade II, CA	carried out, funded by Historic England. Charity Habitats & Heritage and the church have begun to explore possibilities
	CONDITION:	Poor	for developing a project and seeking funding to enable th necessary works to be carried out.
1 - Charles	OCCUPANCY:	N/A	necessary works to be carried out.
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080883	Contact: Jill Tyndale (LPA) 020 8545 3041

	SITE NAME:	Tomb of Bankes, St Mary's Churchyard, St Mary's Road, Wimbledon SW19	Table tomb from the mid CI8 with inset panels and baluster profiled corners. The tomb is suffering from continued waste dumping activity and the stonework is
	DESIGNATION:	Listed Building grade II, CA	cracking. It has been previously subject to poor quality repairs. A condition survey has been carried out, funded by
A REAL	CONDITION:	Poor	Historic England, but no funding has been identified to enable the necessary works to be carried out.
	OCCUPANCY:	N/A	chable the necessary works to be carried out.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
© Historic England	LIST ENTRY NUMBER:	1080888	Contact: Jill Tyndale (LPA) 020 8545 3041

	SITE NAME:	Tomb of Elizabeth Johnson, St Mary's Churchyard, St Mary's Road, Wimbledon SW19	Table tomb, tapered to the base, erected around 1800. The side panels have collapsed and vegetation has rooted in the monument and on its pedestal. A condition survey
	DESIGNATION:	Listed Building grade II, CA	has been carried out, funded by Historic England, but no funding has been identified to enable the necessary works
	CONDITION:	Poor	to be carried out.
Sol Der	OCCUPANCY:	N/A	
A BEACH	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1193775	Contact: Jill Tyndale (LPA) 020 8545 3041



-	SITE NAME:	Tomb of John Lawson, St Mary's Churchyard, St Mary's Road, Wimbledon SW19	Table tomb on a stepped podium, dating from circa 1704. There is evidence of joints widening and the plinth collapsing. A condition survey has been carried out, funded
	DESIGNATION:	Listed Building grade II, CA	by Historic England, but no funding has been identified to enable the necessary works to be carried out.
des.	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A.	PRIORITY CATEGORY:	C (C)	
and.	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080886	Contact: Jill Tyndale (LPA) 020 8545 3041

© Historic England

©



	SITE NAME:	Base of windmill at Mill House, Windmill Road	Brick with timber framing comprising the base of a hollow- post windmill. It is located within the car park of the Mill	
	DESIGNATION:	Listed Building grade II	House public house with its timber superstructure exposed to the elements. The owners have undertaken works to	
	CONDITION:	Fair	preserve the timbers which have now been reinstated. The structure remains at risk without a protective cover.	
	OCCUPANCY:	N/A	Repairs are now required to the supporting walls.	
	PRIORITY CATEGORY:	C (C)		
TRANS SALVAN	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1194005	Contact: Jill Tyndale (LPA) 020 8545 3041	

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MERTON

SITE NAME

	SITE NAME:	Wall to rear of flats, 27-33 (consecutive), Windsor Avenue, Colliers Wood SW19	Fragment of medieval, and probably later, precinct wall of the former Merton Priory. Constructed from flint and rubble stone, it is being damaged by vegetation growing out
	DESIGNATION:	Listed Building grade II, CA	of the wall structure.
	CONDITION:	Very bad	
·西亚州和国家。2	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1080856	Contact: Jill Tyndale (LPA) 020 8545 3041

SITE NAME:	Merton Priory (site of), Merantun Way, Colliers Wood SW19			
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001976	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY ?:	No	
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Jane Sidell 020 7973 3738	



© Historic England Archive

	DESIGNATION:	Registered Park and Garden grade II*, 2 CAs	dev
	CONDITION:	Generally unsatisfactory with major localised problems	with own
	VULNERABILITY:	High	resu exis histe add
	TREND:	Declining	
	NEW ENTRY?:	No	dev
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000852	Cor

Wimbledon Park SW19

A remnant of the C18 landscape by Lancelot Brown for the 1st Earl Spencer's manor house at Wimbledon, itself veloped from a CI6 estate. The Local Authority nages Brown's lake and land to the east as a public park h an emphasis on sport, with land to the west in private nership as golf and sports clubs. Divided ownership ults in differential landscape management. A masterplan sts for the public park, but a shared vision for the whole toric landscape is needed. Recent works on site have dressed lake safety. Proposals exist for major new velopment within the golf course.

ntact: Christopher Laine 020 7973 3473

SITE NAME:	Bathgate Road SW19		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Drax Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	The Broadway		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:			
VOLINEIVADILITT.	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	High Upper Morden	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
		CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Upper Morden		

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MERTON / NEWHAM

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

SITE NAME:	Wimbledon Chase		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	CONDITION: Very bad		No significant change
VULNERABILITY: Medium		CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Wimbledon Hill Road		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	ill Tyndale (LPA) 020 8545 3041

## NEWHAM

© Historic England



	SITE NAME:	Police Station, with walls and gatepiers to side, High Street South, E6	Red brick police station with Portland stone dressings and bands, and a slate roof. 1904, by John Dixon Butler for the Metropolitan Police. The building has been vacant since
	DESIGNATION:	Listed Building grade II, CA	2013. Repairs have been carried out to the roof. Applications for Planning Permission and Listed Building
	CONDITION:	Poor	Consent have been approved for works in relation to re- use of the building for educational purposes and works
	OCCUPANCY:	Vacant/not in use	have started on site.
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1253087	Contact: Ben Hull (LPA) 020 3373 9574



© Historic England



-			
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357997	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Dukes Head public house, 593, Barking Road, East Ham E6	Impressive corner public house dating from 1900. The ground and first floor function rooms are being used for
	DESIGNATION:	Listed Building grade II	weddings and parties, and currently a place of worship. The flats on the upper floors are occupied. Restoration works
	CONDITION:	Fair	were undertaken following fire damage. There is some unauthorised signage, and repairs needed to the cornice
F	OCCUPANCY:	Part occupied/part in use	and string courses. Planning consents were secured in
	PRIORITY CATEGORY:	D (D)	spring 2021 for conversion and extension for residential and community uses. It is believed that works will
	OWNER TYPE:	Commercial company	commence imminently after determination of Approval of Detail applications currently being assessed.
	LIST ENTRY NUMBER:	1392558	

West Ham Pumping Station

Listed Building grade II

Part occupied/part in use

Fair

C (C)

Engine House, Abbey Road E15

© Historic England

Three-storey C18 public house, yellow brick with red brick SITE NAME: Coach and Horses public house, arches and reveals. The interior has been extensively damaged. Planning Permission and Listed Building Consent 100, High Street, Plaistow E13 Listed Building grade II have been granted for conversion of the building into residential units. These consents have now lapsed. CONDITION: Poor Unauthorised works have taken place and the Local OCCUPANCY: Authority has issued a stop notice to prevent further Vacant/not in use unauthorised works taking place. PRIORITY CATEGORY: C (D) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1080959 Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Engine house, built in 1897, containing original Lilleshall

with high level vegetation growth to roofs and rainwater goods and graffiti damaging industrial heritage features.

there are no specific plans identified as yet.

Contact: Ben Hull (LPA) 020 3373 9574

Company beam engines. The building is currently in use as

a training facility. Parts of the building are in poor condition,

Discussions are ongoing regarding the future of this site but

## ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA

WHS

- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA
  - Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / NEWHAM



Chimney dating from 1887 to 1889, designed by Joseph SITE NAME: Chimney to Beckton Sewage Bazalgette, as part of the improvements to the northern Works, Jenkins Lane, Beckton E6 outfall of the London drainage network. The chimney was dismantled, with Listed Building Consent, and is in storage, DESIGNATION: Listed Building grade II pending re-erection following completion of tunnelling works. Regular surveys are carried out to review its CONDITION: Poor condition and maintenance works are being undertaken OCCUPANCY: based on these findings. Pre-application discussions have N/A taken place with the owner regarding the re-erection of the PRIORITY CATEGORY: D (D) chimney and an application is expected imminently. OWNER TYPE: Utility LIST ENTRY NUMBER: 1393160 Contact: Ben Hull (LPA) 020 3373 9574

© Historic England



	SITE NAME:	Silo D, North Woolwich Road, Canning Town E16	Grain silo, 1920, built of reinforced concrete. Vegetation threatening the building has been mostly cleared but pigeon
	DESIGNATION:	Listed Building grade II	ingress is an issue. Planning Permission has been granted for the first phase of development of the Silvertown site. Silo D
	CONDITION:	Poor	is envisioned as a landmark building within the new masterplan and discussions are ongoing as to how the
	OCCUPANCY:	N/A	building might be re-used. Works are required to maint
	PRIORITY CATEGORY:	C (C)	it while these future uses are explored. A condition survey including recommendations for repairs and timescales for
	OWNER TYPE:	Commercial company	implementation has been approved as a condition of the consented masterplan.
	LIST ENTRY NUMBER:	1245030	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England



© Historic England

	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	C (C) Commercial company 1245030	it while these future uses are explored. A condition survey including recommendations for repairs and timescales for implementation has been approved as a condition of the consented masterplan. Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	North Woolwich Station including turntable and platform lamp standards, Pier Road, North Woolwich E16	Former railway station, 1847. Extensive works are needed to the roof, and the rear canopy has been dismantled following partial collapse. Essential remedial works were carried out prior to sale of the building. New owners have submitted applications for Planning Pormission and Listed
	DESIGNATION:	Listed Building grade II	submitted applications for Planning Permission and Listed Building Consent for repair and conversion of the building
	CONDITION:	Poor	into a place of worship. The applications have been refused as the proposals were considered to harm the heritage
	OCCUPANCY:	Part occupied/part in use	significance of the building.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1376229	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Earl of Essex public house, 616, Romford Road, Newham E12	Impressive Edwardian public house by Henry Poston and WE Trent, dating from 1902, on a prominent corner site.
	DESIGNATION:	Listed Building grade II	The ground floor has been empty and boarded up and the upper floors occupied. Repairs are needed, particularly to
TAT I TATAP	CONDITION:	Fair	external architectural details. Planning Permission and Listed Building Consent have been granted for the
	OCCUPANCY:	Part occupied/part in use	refurbishment and extension of the building for use as a
0061793	PRIORITY CATEGORY:	F (F)	public house and restaurant, with residential accommodation on upper floors. Works have commenced
	OWNER TYPE:	Commercial company	on site.
gland	LIST ENTRY NUMBER:	1357990	Contact: Ben Hull (LPA) 020 3373 9574

© Historic Engl



	SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16	Restaurant built in 1883 to the design of Vigers and Wagstaffe in a free Classical style. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Poor	repairs undertaken. Planning Permission and Listed Building Consent have been granted for restoration and use as a
	OCCUPANCY:	Vacant/not in use	restaurant as part of the wider Royals Business Park
	PRIORITY CATEGORY:	C (D)	development of Albert Dock. However, this scheme will no longer go ahead, and no revised plans have been
	OWNER TYPE:	Commercial company	brought forward.
	LIST ENTRY NUMBER:	38020	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HER

RITAGE AT RISK 2023 / LOND	on and south east	/ NEWHAM / REDBRIDGE	
	SITE NAME:	Central offices at Custom House, Royal Albert Dock E16	Offices, built in 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Poor	repairs undertaken. Planning Permission and Listed Building
	OCCUPANCY:	Vacant/not in use	Consent were granted for restoration and use as a club and art gallery as part of the wider Royals Business Park
	PRIORITY CATEGORY:	C (D)	development of Albert Dock. However, this scheme will no longer go ahead, and no revised plans have been
	OWNER TYPE:	Commercial company	brought forward.
Historic England	LIST ENTRY NUMBER:	1376228	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Spotted Dog public house, 212, Upton Lane E7	Weatherboarded C15 timber-framed public house. The property has been vacant for some years. Urgent repairs
ALL SUPPORT	DESIGNATION:	Listed Building grade II	were carried out to stabilise the building and consents secured for its repair and re-use as pub, restaurant and
	CONDITION:	Very bad	hotel; however, this scheme has not been implemented, and no further plans have come forward. There are
	OCCUPANCY:	Vacant/not in use	concerns regarding the current condition of the building
-1	PRIORITY CATEGORY:	C (D)	and associated use of the adjacent car park for vehicle storage. Attempts are being made to access the site to
	OWNER TYPE:	Commercial company	determine its current condition and establish a plan with the owner to secure and restore the building.
Historic England	LIST ENTRY NUMBER:	1191297	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	West Ham Court House, West Ham Lane EI5	The first Court House of 1884, to the design of Lewis Angell, was extended symmetrically in 1905 to provide a
	DESIGNATION:	Listed Building grade II, CA	second courtroom. Having been vacated it suffered from theft, vandalism and decay over many years, as well as from
	CONDITION:	Very bad	fire damage in 2014, resulting in the loss of much of the historic interior. In 2019 the Local Authority undertook
	OCCUPANCY:	Vacant/not in use	works to stabilise the surviving walls and to protect the
	PRIORITY CATEGORY:	C (C)	site. This was completed in early 2020 with partial grant funding from Historic England. The Local Authority is
for the	OWNER TYPE:	Local authority	committed to exploring its long-term future, in discussion with Historic England.
Historic England	LIST ENTRY NUMBER:	1080974	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Northern block and courtyard walls of Alice Billings House, Stratford E15	A block of firemen's accommodation built for the West Ham Fire Brigade c1905-06; a rare example of the incorporation of a practice hose/drying tower separate
	DESIGNATION:	Listed Building grade II, part in CA	from the fire station building. It has been vacant and deteriorating since the 1980s. Funding was awarded through Newham Council's Active Spaces programme in
	CONDITION:	Poor	2021 to Creative Land Trust to convert the building into
			studios to be let at affordable rents to creatives, with

© Historic England

©Н

©Ні

©Ні

REDBRIDGE

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Vacant/not in use

Local authority

C (C)

1443788

1271968

Shop with circa 1900 interior, featuring striking glazed 831, High Road, Ilford decorative wall tiling and Minton floor tiling. The tiles have Listed Building grade II been severely damaged by nailed studwork and plasterboard to the wall, and cement screeding of the floor. Poor The building requires major tile repairs and replacements to restore the interior, and unauthorised works need to be Part occupied/part in use addressed. Pre-application discussions have taken place C (C) with Historic England and the Local Authority with a view to reinstatement of the tiles and refurbishment of the Private building. A suitable scheme is awaited.

Contact: Suzanne Lansley (LPA) 020 8708 6690

teaching areas and a community café, with further funding from the Levelling Up Fund. Detailed plans for the project

are now in development.

Contact: Ben Hull (LPA) 020 3373 9574

© London Borough of Redbridge

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- NP
- Local Planning Authority National Park RPG
  - Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / REDBRIDGE

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



	SITE NAME:	The Grotto, Wanstead Park EII	Ruined grotto boathouse of circa 1762. It consists of a honeycomb rockwork facade of segmental plan with
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	several arches at lake level, and window openings above. The area is fenced off from public access. The grotto is managed as a ruin, but its stability is threatened by mortar
	CONDITION:	Poor	failure, loss of rockwork, and self-sown vegetation. The owner, the City of London, has carried out repairs and
	OCCUPANCY:	DCCUPANCY: N/A clearance, an Plan to identi	clearance, and commissioned a Conservation Managemen
	PRIORITY CATEGORY:		Plan to identify the most appropriate approach to securi the grotto's long-term future. Investigations into its
	OWNER TYPE:	Local authority	structural integrity are also planned.
	LIST ENTRY NUMBER:	1183624	Contact: Suzanne Lansley (LPA) 020 8708 6690

© Historic England

© Historic England



	SITE NAME:	Garden Temple in garden of Temple House, 14, The Avenue, Wanstead E11	Garden temple, circa 1730-40, with lonic pedimented portico. The structure once formed part of the Wanstead Grove Estate. Extensive repairs to the roof and one of the
	DESIGNATION:	Listed Building grade II*, CA	columns have been carried out, grant-aided by Historic England. Further repairs are needed to the remaining
	CONDITION:	Poor	columns, which are showing signs of significant decay, as well as the decorative finishes. Structural and condition
	OCCUPANCY:	N/A	surveys were prepared in 2016 to inform these repairs,
	PRIORITY CATEGORY:	A (A)	with funding from Historic England. The Local Authority and Historic England are jointly considering options to
	OWNER TYPE:	Private	secure full repair of the structure.
	LIST ENTRY NUMBER:	1357974	Contact: Verena McCaig 020 7973 3718

© Historic England



around the monument to Sir Josiah Child. The west end Listed Place of Worship grade I, supports a Doric portico, hipped slate roof and a timber RPG grade II\*, CA clock tower with open belfry and cupola. The interior has been redecorated and retains all original furnishings. The Poor Portland stone masonry is spalling due to rusting cramps. PRIORITY CATEGORY: Two elevations, including the clock turret, were repaired in D (D) 2018, funded by the National Lottery Heritage Fund. Religious organisation Funding is being sought for the repair of the two remaining elevations. LIST ENTRY NUMBER: 1081008 Contact: lan Harper 07974 979620 Gothic-style church built as a chapel of ease to St Mary the Christ Church, Wanstead Place, Wanstead EII

Virgin and still sharing the parish. It was built between 1861 and 1867, to the designs of George Gilbert Scott; construction is of ragstone with ashlar dressings under slated roofs. The valley gutters were renewed in 2013. A specialist survey in the same year identified masonry at belfry level in a dangerous condition. Some emergency repairs have been done but the condition is worsening and there is a risk of falls of stone. The tower is in need of a comprehensive repair programme. The parish is investigating sources of funding.

This church of 1790 was designed by architect Thomas

Hardwick in the neoclassical style. The chancel is designed

© Historic England



SITE NAME Wanstead Park EI2 Registered Park and Garden DESIGNATION: grade II\*, 7 LBs, 2 CAs CONDITION: Extensive significant problems VULNERABILITY: High TREND: Stable NEW ENTRY ?: No OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1000194

Church of St Mary, Overton

Listed Place of Worship grade

Religious organisation

II\*, CA

Poor

B (B)

1081017

Drive, Wanstead EII

Contact: lan Harper 07974 979620

Remains of an important landscape dating from the late CI7 to the early CI9 and associated with George London and Humphry Repton, further developed in the late C19 by the City of London as a public park. The central area was converted to a private golf course in the early C20. Features of the historic designed landscape survive but are in poor condition. A Parkland Plan has been prepared to inform decision making and forward planning. Possible sources of funding for implementation are being explored, with emerging projects focusing on the historic lakes, the grotto, and landscape management.

Contact: Christopher Laine 020 7973 3473

### PRIORITY CATEGORIES

© Historic England Archive

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## ABBREVIATIONS

ΪA

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / REDBRIDGE / RICHMOND UPON THAMES

SITE NAME:	Mayfield, Ilford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Wanstead Park EI I		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690
SITE NAME:	Woodford Bridge, Bridge, Chigwell		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Suzanne Lansley (LPA) 020 8708 6690

## **RICHMOND UPON THAMES**

© Historic England	SITE NAME:	Boathouse and deep-water dock, riverside landing stage, steps, balustrade and gates, Thames Eyot, Cross Deep, Twickenham	Built in the 1870s as part of Frederick Chancellor's remodelling of the house and grounds of Poulett Lodge for William Punchard. The boathouse and dock are disused and falling into disrepair, with encroaching vegetation threatening the masonry. The balustrade is structurally
	DESIGNATION:	Listed Building grade II, CA	compromised and shows evidence of cracking and leaning. This also affects the landing stage and gates. Discussions
	CONDITION:	Poor	towards a solution are at an early stage with the owners.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1400159	Contact: Nicolette Duckham (LPA) 020 8891 7335

	SITE NAME:	Building number 14, Platts Eyot, Hampton	Late C19 office building in stock brick with an ogee-shaped cupola, formerly with a wooden balcony. It possibly once
A PART	DESIGNATION:	Listed Building grade II, CA	housed electric works and a boathouse to the ground floor. Long-term solutions for this building are being
	CONDITION:	Fair	discussed as part of the expected overall strategy for Platts Eyot island. Some limited damage was caused by fire in
	OCCUPANCY:	Part occupied/part in use	2021. The Local Authority are seeking to secure the
	PRIORITY CATEGORY:	C (C)	reinstatement of the first-floor balcony which was unlawfully removed.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1254430	Contact: Lauren Way (LPA) 020 8891 7928

© Historic England



SITE NAME:	Loggia in the grounds of Thames Eyot, Cross Deep, Twickenham	Stone loggia of nine Doric columns, probably C18, situated in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The roof has suffered partial
DESIGNATION:	Listed Building grade II, CA	collapse and structural movement has caused distortion to the colonnade. An options appraisal was completed in
CONDITION:	Very bad	2011 but not taken forward. The loggia has now been propped with scaffolding under a time-limited Listed
OCCUPANCY:	N/A	Building Consent and this should prevent major loss of
PRIORITY CATEGORY:	C (C)	fabric whilst the freeholders develop a permanent scheme. A Listed Building Consent application for further structural
OWNER TYPE:	Private, multiple owners	investigation has been approved.
LIST ENTRY NUMBER:	1401819	Contact: Lauren Way (LPA) 020 8891 7928

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

91

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / RICHMOND UPON THAMES

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

1	SITE NAME:	Norfolk House, 8, Montpelier Row	C18 plain brown brick house with red window arches and many remaining original internal features. Vacant for some			
	DESIGNATION:	Listed Building grade II*, CA	years, a major water leak has caused considerable damage to the rear sections of the house, leading to problems with			
	CONDITION:	Very bad	rot and damp. Initial works have been carried out to the rear section of the roof through enforcement action by the			
	OCCUPANCY:	Vacant/not in use	Local Authority, but further works are needed, particularly			
	PRIORITY CATEGORY:	A (C)	to windows and rainwater goods. The Local Authority are continuing to make efforts to secure the future of the			
	OWNER TYPE:	Private	property.			
	LIST ENTRY NUMBER:	1065390	Contact: Verena McCaig 020 7973 3718			

© Historic England



SITE NAME:	Grotto or shell house in grounds of Thames Eyot, Cross Deep, Twickenham	Later C18 or early C19 grotto or shell house, altered in the mid C19, now in the grounds of Thames Eyot, a block of 1930s flats on the bank of the Thames. The grotto is
DESIGNATION:	Listed Building grade II*, CA	A decorated in a precise geometric pattern to resemble a coffered vault which is separated by a deep horizontal b from the more randomly decorated vertical walls. Considerable amounts of the shellwork have been lost of the
CONDITION:	Poor	
OCCUPANCY:	N/A	damaged and it is in need of conservation to prevent
PRIORITY CATEGORY:	C (C)	further deterioration. Historic England has provided advice to the owner and Local Authority.
OWNER TYPE:	Private, multiple owners	
LIST ENTRY NUMBER:	1080812	Contact: Verena McCaig 020 7973 3718

considered.

Church of England Cemetery Chapel, Grove Road, Richmond

Listed Building grade II

Part occupied/part in use

Charity (heritage)

Commercial company

1254429

Cemetery

Very bad

A (A)

1261361

Cemetery chapel built in 1875 by Sir Arthur Blomfield.

structural problems meant it had to be vacated. The

separation of the gable wall from the roof. It has been propped and is being monitored by structural engineers.

explored and the long-term future of the asset being

Contact: Lauren Way (LPA) 020 8891 7928

building is suffering from ground movement and

Formerly leased out by the locally-based charity Habitats and Heritage, it had operated as a nursery until major

subsidence, causing major cracks above windows and the

Approaches to temporary or permanent repairs are being

© Historic England



© Historic England



© Historic England



	SITE NAME:	lvy Hall Hotel (known as Hobart Hall Hotel), 43-47 (odd), Petersham Road	Early C18 three-storey house in L-shaped plan with a river frontage, with mid to late C18 wing of four storeys with bays and C20 link. Whilst last used as a hotel, the building
	DESIGNATION:	Listed Building grade II, CA	has been largely unoccupied for over ten years and is in very bad condition. Urgent works have been carried out
	CONDITION:	Very bad	and the building is now temporarily wind and weathertight. The Local Authority is in discussion with the owners to
	OCCUPANCY:	Part occupied/part in use	secure its repair and re-use, but no suitable scheme has yet
	PRIORITY CATEGORY:	A (A)	been brought forward. A pre-application scheme has been submitted for conversion for residential use.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1357738	Contact: Lauren Way (LPA) 020 8891 7928
y switt	SITE NAME:	Boathouse 5 (easternmost 13 bays), Platts Eyot, Hampton	Timber-framed boathouse built in 1917 by Augustine Alban Hamilton Scott for the Thorneycroft firm to build torpedo
ax.	DESIGNATION:	Listed Building grade II, CA	boats for the Admiralty. A full measured survey of the remaining structure has been completed, but it is in very
× C	CONDITION:	Very bad	bad condition with a large area of collapse. Solutions for this structure, including the rebuilding of the Belfast trusses,
A.	OCCUPANCY:	Vacant/not in use	will be discussed as part of the expected overall strategy
	PRIORITY CATEGORY:	A (A)	for Platts Eyot.

© Historic England

Contact: Lauren Way (LPA) 020 8891 7928

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

D

Е

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB
- I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA

Unitary Authority World Heritage Site WHS

#### Н

LIST ENTRY NUMBER:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

1263475

Poor

D (D)

Private

1387232

Vacant/not in use

HERITAGE AT RISK 2023 / LONDO	on and south east	/ RICHMOND UPON THAMES	
STR. STR.	SITE NAME:	Boathouse 2, Platts Eyot, Hampton	Timber-framed boathouse clad in corrugated zinc with a Belfast truss roof. It was constructed in 1916 by Augustine
	DESIGNATION:	Listed Building grade II, CA	Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May
Part of the second seco	CONDITION:	Very bad	2021, a significant fire took place on the island which has destroyed a large extent of Boathouse 2. The cause of the
	OCCUPANCY:	N/A	fire has been established as accidental. Prior to the fire,
	PRIORITY CATEGORY:	A (A)	condition surveys were being carried out. Historic England and the Local Authority are discussing the future of the
	OWNER TYPE:	Commercial company	building with the owner.
© Historic England	LIST ENTRY NUMBER:	1254428	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME:	Boathouse 4, Platts Eyot, Hampton	Timber-framed boathouse clad in corrugated zinc with a Belfast truss roof. It was constructed in 1916 by Augustine
FILE	DESIGNATION:	Listed Building grade II, CA	Alban Hamilton Scott for the Thorneycroft firm to build fast launches carrying torpedoes for the Admiralty. In May
JA IN TO	CONDITION:	Very bad	2021, a significant fire took place on the island which has destroyed a large extent of Boathouse 4. The cause of the
	OCCUPANCY:	Vacant/not in use	fire has been established as accidental. Prior to the fire,
	PRIORITY CATEGORY:	A (A)	condition surveys were being carried out. Historic England and the Local Authority are discussing the future of the
Contraction of the second seco	OWNER TYPE:	Commercial company	building with the owner.
© Historic England	LIST ENTRY NUMBER:	1261295	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME:	Wick House, Richmond Hill, Richmond	Designed by Sir William Chambers circa 1772 for Sir Joshua Reynolds. Planning Permission has been granted to
A CALLER S	DESIGNATION:	Listed Building grade II, CA	convert the building from a nurses' home to a single residence. Agreed stabilisation works have taken place to
	CONDITION:	Very bad	address significant cracks in the later Victorian wing. Further applications for Planning Permission and Listed
	OCCUPANCY:	Vacant/not in use	Building Consent have been approved but no work has
	PRIORITY CATEGORY:	D (D)	taken place on site. Protection measures have been put in place to prevent damage from any falling masonry adjacent
	OWNER TYPE:	Private	to Petersham Woods, and the building has been made more secure.
		10/0/75	more secure.

© Historic England

© Historic England

*	

	SITE NAME:	Doughty House, 142, RichmondC18 house with C19 alterations, including the addition an art gallery, made by the Cook family. Planning	
	DESIGNATION:	Listed Building grade II, CA	Permission and Listed Building Consent have been granted to retain the main property as a single dwelling and to
	CONDITION:	Very bad	convert the gallery (listed separately) to ancillary accommodation, along with re-instating Doughty Cottage
	OCCUPANCY:	Vacant/not in use	as the link between the house and gallery. An application
	PRIORITY CATEGORY:	D (D)	for further work has been approved, including an alternative access arrangement, but limited work has taken
	OWNER TYPE:	Private	place on site, largely to implement a current consent prior to expiry.
	LIST ENTRY NUMBER:	1249955	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME: DESIGNATION:	The Gallery at Doughty House, 142, Richmond Hill, Richmond	Gallery built c1880 for Sir Francis Cook, extended 1915 by Brewer Smith, comprising eleven bays in giant lonic order
		Listed Building grade II, CA	with balustrade, the lower order containing door and window openings between Doric pilasters. Works are

cis Cook, extended 1915 by en bays in giant lonic order er containing door and window openings between Doric pilasters. Works are needed to the roof, balustrade and rainwater goods. An application for further work has been approved, including an alternative access arrangement, but limited work has taken place on site, largely to implement a current consent prior to expiry.

Contact: Lauren Way (LPA) 020 8891 7928

Contact: Lauren Way (LPA) 020 8891 7928

© Historic England	

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / RICHMOND UPON THAMES / SOUTHWARK

	SITE NAME:	Air Raid Shelter, St Leonard's Court, St Leonard's Road, East Sheen SW14	Air raid shelter, probably built in 1938 to serve St Leonard's Court which was built in 1934-38 by local builder Mr FG Fox. It was designed to hold 48 people; at
La l	DESIGNATION:	Listed Building grade II	the time there were 83 flats. Locally-based charity Habitats and Heritage commissioned a structural survey leading to
	CONDITION:	Fair	minor works. The owners are considering the future of the building.
1	OCCUPANCY:	N/A	building.
- and	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private, multiple owners	
D Historic England	LIST ENTRY NUMBER:	1395422	Contact: Lauren Way (LPA) 020 8891 7928


SITE NAME:	Platt's Eyot, Hampton		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lauren Way (LPA) 020 8891 7928

## SOUTHWARK

ĥ

C

	SITE NAME:	Office, Licensed Victuallers Almshouses, 12a, Asylum Road SE15	Annexe to the offices of the Licensed Victuallers' Almshouses, 1913-14 by FE Harford, in a restrained Baroque style. There are significant structural cracks to the
	DESIGNATION:	Listed Building grade II, CA	front and side elevations and failing stonework at upper levels. The Local Authority has carried out remedial works
	CONDITION:	Very bad	to the pediment and flat roof. They have also commissioned investigatory works, including structural
	OCCUPANCY:	Vacant/not in use	monitoring, and a suitable approach to securing the future
	PRIORITY CATEGORY:	C (C)	of the building is being considered.
	OWNER TYPE:	Local authority	
storic England	LIST ENTRY NUMBER:	1376536	Contact: Catherine Jeater (LPA) 020 7525 5375





© Historic England



Iron railings to the Licensed Victuallers' Almshouse SITE NAME: Railings and gates to Caroline complex, dating largely to circa 1830-40. Sections of the Gardens, Asylum Road SEI5 ironwork are in a poor state of repair with some elements DESIGNATION: Listed Building grade II, CA cracked or missing. Some backstays and a pair of gates have been removed to storage. The Local Authority is pro-CONDITION: Poor actively seeking funding to carry out full conservation. OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1376543 Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

## Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTHWARK



© Historic England

© Historic England

© Historic En

SITE NAME:	Licensed Victuallers Almshouses: Chapel, Asylum Road SE15	Former almshouse chapel, dating from 1827-31. The building is leased by the Local Authority to a local artists' group. The building needs significant roof repairs and fabric
DESIGNATION:	Listed Building grade II, CA	consolidation. The Local Authority is pro-actively seeking funding to carry out full conservation and repair, working
CONDITION:	Poor	with the leaseholders.
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1376538	Contact: Catherine Jeater (LPA) 020 7525 5375

	SITE NAME:	Chest tomb, St Mary Magdalene Churchyard, Bermondsey Street SEI	Chest tomb from 1815 with original railings. Overgrowth has caused damage to the stone and ironwork. Historic England has funded a condition survey and specification for
	DESIGNATION:	Listed Building grade II, SM, CA	works to the tomb, but no funding has been identified that would enable the works to be carried out.
	CONDITION:	Poor	
1000	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
1	LIST ENTRY NUMBER:	1376573	Contact: Gemma Williams (LPA) 020 7525 5000

	SITE NAME:	Table tomb, St Mary Magdalene Churchyard, Bermondsey Street SEI	Unusual C18 table tomb under a stone canopy with tapered, fluted columns. There is some deterioration to the stone elements and railings. Historic England has
	DESIGNATION:	Listed Building grade II, CA	funded a condition survey and specification for works to the tomb, but no funding has been identified that would
	CONDITION:	Fair	enable the works to be carried out.
	OCCUPANCY:	N/A	
Western	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
England	LIST ENTRY NUMBER:	1376578	Contact: Gemma Williams (LPA) 020 7525 5000

	SITE NAME:	Tomb of John Sargeant, St Mary Magdalene Churchyard, Bermondsey Street SEI	C18 stone chest tomb. The monument has been damaged by erosion and cementitious repairs in the past. Historic England has funded a condition survey and specification for
	DESIGNATION:	Listed Building grade II, CA	works to the tomb, but no funding has been identified that would enable the works to be carried out.
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1376580	Contact: Gemma Williams (LPA) 020 7525 5000

SITE NAME:	Presbyterian Chapel, 109, Borough Road SEI	2006 for facade retention.		Former Presbyterian chapel 2006 for facade retention. S
DESIGNATION:	Listed Building grade II, CA	secured Planning Permission for a scheme to convert the		
CONDITION:	Very bad	community use. Major work Covid-19 pandemic when th		
OCCUPANCY:	Vacant/not in use	changes have resulted in the		
PRIORITY CATEGORY:	A (F)	The Council and Historic En owners, London South Bank		
OWNER TYPE:	Educational (state sector)			
LIST ENTRY NUMBER:	1378375	Contact: Gemma Williams (		

el, 1846. Consent was granted in South Bank University has since n and Listed Building Consent e building for student and ks were underway before the he scheme was halted. Funding e need to review the scheme. ingland are in discussion with the ik University.

(LPA) 020 7525 5000

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park

  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Monument to Charles Waters, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1910 to Charles Waters. Marble group of a seated woman with book/bible in her lap embracing a small child on a battered plinth. The monument, which was leaning, has been returned to an upright position and made
	DESIGNATION:	Listed Building grade II	structurally stable. However, the figures have been damaged through cleaning processes and have been
	CONDITION:	Poor	assessed for further repair. A scheme for stonework
T	OCCUPANCY:	N/A	stabilisation has been agreed but has yet to be carried out.
	PRIORITY CATEGORY:	D (D)	
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1385530	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	Monument to Rebekah Horniman, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1895 to Rebekah, wife of FS Horniman. Its prominent bronze tablet depicting a figure of an angel is missing, presumed stolen. There are no current plans for its restoration.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
122-23	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1385533	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	38, Glengall Road, Peckham SEI5	Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. The Ionic entrance
- ALANINA	DESIGNATION:	Listed Building grade II, CA	porch is in very bad condition, cracking is evident, and the roof is not watertight to the rear. The house was sold in
	CONDITION:	Very bad	August 2022 and the Local Authority and Historic England
	OCCUPANCY:	Occupied/in use	are considering approaches to secure stabilisation and repair of the building.
	PRIORITY CATEGORY:	A (A)	
Frank and the second second	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1385563	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	55, Great Suffolk Street SEI	Unaltered mid-C19 warehouse. The building is in a poor
1 1 1 1	DESIGNATION:	Listed Building grade II	condition having been vacant for a number of years. Applications for Listed Building Consent and Planning
1 3 440	CONDITION:	Poor	Permission have been secured for change of use from warehouse use to a commercial scheme including café and
	OCCUPANCY:	Vacant/not in use	restaurant use. Emergency works have been undertaken
	PRIORITY CATEGORY:	D (D)	and, now that consents have been granted subject to a Section 106 Agreement, works are expected to start
	OWNER TYPE:	Private	imminently.
Distoric England	LIST ENTRY NUMBER:	393 23	Contact: Gemma Williams (LPA) 020 7525 5000
ANNI (M	SITE NAME:	East Lodge to Nunhead	One of a pair of gate lodges dating from 1840, by James
	DESIGNATION:	Cemetery, Linden Grove SE15 Listed Building grade II, RPG grade II*, CA	Bunstone Bunning, adjacent to the main entrance gates. The lodge is in a ruinous condition. Enabling works have been carried out to stabilise the structure. Listed Building
A ANTIMAL	CONDITION:	Very bad	Consent and Planning Permission have been granted for ful restoration for café and community facilities and works are
	OCCUPANCY:	Vacant/not in use	expected to commence in 2023 funded by the National Lottery Heritage Fund and others. Further fundraising is
	PRIORITY CATEGORY:		being undertaken.
	INONITI CATEGORI:	D (D)	

© Historic England

	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	been carried out to stabilise the structure. Listed Buildin Consent and Planning Permission have been granted for
	CONDITION:	Very bad	restoration for café and community facilities and works expected to commence in 2023 funded by the National
	OCCUPANCY:	Vacant/not in use	Lottery Heritage Fund and others. Further fundraising is
	PRIORITY CATEGORY:	D (D)	being undertaken.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1385647	Contact: Gemma Williams (LPA) 020 7525 5000

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2023 / LONDO	on and south east	/ SOUTHWARK	
	SITE NAME:	Tomb of Maria Proom, Nunhead Cemetery, Linden Grove SEI5	Visually prominent monument of 1872 in pink and grey granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure presents a
ALALA	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	praying figure carried on a tall column and plinth, and an angel statue at its base which was perhaps originally unrelated to the monument. The railings around it are
	CONDITION:	Fair	missing. A condition survey has been produced which
	OCCUPANCY:	N/A	indicates that there are no major concerns at present but monitoring needs to be undertaken to check for any
and the second of the	PRIORITY CATEGORY:	C (C)	movement owing to nearby ground conditions.
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1385651	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	St Peter's Church Hall, 522, Lordship Lane, East Dulwich SE22	Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is
A Star Mar 200	DESIGNATION:	Listed Building grade II, CA	suffering from structural movement and lack of maintenance. Historic England has provided advice on
	CONDITION:	Very bad	urgent repairs required; however, these have not been
	OCCUPANCY:	, Vacant/not in use	carried out. The Local Authority and Historic England are discussing possible action to secure the repair and
	PRIORITY CATEGORY:	A (A)	conservation of the building.
A MARCHER DE MARK	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	38567	Contact: Gemma Williams (LPA) 020 7525 5000
		1505071	
	SITE NAME:	The Kentish Drovers public house, 720, Old Kent Road, Peckham SE15	Mid-C19 public house, now partly in use as a restaurant. The Local Authority commissioned a specialist survey of the damaged tiled mural and full conservation works
	DESIGNATION:	Listed Building grade II	commenced in 2020 using Section 106 funding. Works are ongoing.
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385740	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	112, Peckham Park Road, Peckham SE15	One of a group of four pairs of early C19 houses. The house is in a poor state of repair, in particular the exterior,
	DESIGNATION:	Listed Building grade II	and continues to deteriorate.
	CONDITION:	Very bad	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1385765	Contact: Gemma Williams (LPA) 020 7525 5000
	SITE NAME:	40, Queens Road, Peckham SE15	Early-C19 terraced building. The building is in poor condition and has suffered from extensive unauthorised
	DESIGNATION:	Listed Building grade II	works.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1385796	Contact: Gemma Williams (LPA) 020 7525 5000

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTHWARK

SITE NAME:

DESIGNATION:

	SITE NAME:	Former Clare College Mission Church, Southwark Park SEI6	Former mission church of circa 1900 and 1911-1912, by John W Simpson and Maxwell Ayrton, built for Clare
	DESIGNATION:	Listed Building grade II	College, Cambridge in Italianate style. The walls are ferro- concrete with shallow pitched tiled roofs. Following
	CONDITION:	Poor	refurbishment, the building is used as gallery space by the Bermondsey Artists' Group. There are further repairs
	OCCUPANCY:	Occupied/in use	required to external walls and tile detail, and investigations
	PRIORITY CATEGORY:	C (C)	necessary into structural movement. The Local Authority and Historic England are helping to advise the Group.
11	OWNER TYPE:	Local authority	
land	LIST ENTRY NUMBER:	1385919	Contact: Gemma Williams (LPA) 020 7525 5000

	SITE NAME:	Number I and attached railings, I, Stamford Street SEI	Mid-C19 red brick building that occupies a prominent position looking towards Blackfriars Bridge. Works to
	DESIGNATION:	Listed Building grade II	convert the building to offices were completed but the building does not appear to have been occupied and is now
	CONDITION:	Fair	deteriorating. An application for Listed Building Consent has been secured for extensive repairs and repointing to
	OCCUPANCY:	Vacant/not in use	the flank wall, which is the last phase in the repair of the
	PRIORITY CATEGORY:	D (D)	building. These works have yet to commence.
	OWNER TYPE:	Commercial company	
1	LIST ENTRY NUMBER:	1385933	Contact: Gemma Williams (LPA) 020 7525 5000

Peckham Rye Station, Station

Listed Building grade II, 2 CAs

Way, Peckham SEI5

© Historic England

© Historic England

© Historic Engla

	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Fair Part occupied/part in use C (C) Utility 1392389	is largely vacant and in a poor state of repair. Works to restore the staircase are complete, funded by the Railway Heritage Trust, the Local Authority and Network Rail following local campaigns. Further works have been carried out to the roof and consent has been given for a suitable scheme which will provide full level access; funding is being sought for this. Contact: Gemma Williams (LPA) 020 7525 5000
X	SITE NAME:	Beltwood House, 41, Sydenham Hill, Camberwell SE26	Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. The house was remodelled in
	DESIGNATION:	Listed Building grade II, CA	the neoclassical style circa 1895. The building was suffering from the effects of water ingress and the curtilage buildings
	CONDITION:	Fair	were in a very poor state of repair. Consents were granted
	CONDITION: OCCUPANCY:	Fair Vacant/not in use	for conversion to flats, with development in the surrounding gardens. While works are near completion,
			for conversion to flats, with development in the
	OCCUPANCY:	Vacant/not in use	for conversion to flats, with development in the surrounding gardens. While works are near completion,

© Historic England



SITE NAME:	Southwark Municipal Offices and attached railings, Walworth Road SE17	Built as a vestry hall circa 1863-64, then later used as a town hall and more recently as municipal offices for Southwark Council. The building was severely damaged by
DESIGNATION:	Listed Building grade II, CA	fire in 2013. It was then stabilised and remedial works undertaken, including construction of a new roof and
CONDITION:	Poor	provision of temporary roofing elsewhere. New leaseholders have now taken possession of the building and
OCCUPANCY:	Vacant/not in use	have secured Planning Permission and Listed Building
PRIORITY CATEGORY:	F (F)	Consent for conversion of the building into community centre, start-up office space and café. Works on site are at
OWNER TYPE:	Commercial company	an advanced stage.
LIST ENTRY NUMBER:	1386028	Contact: Catherine Jeater (LPA) 020 7525 5375

© Historic England

PR	IORIT	Y	CA	Т	EG	C	DRI	ES	
						-	-		

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

The station is an H-shaped building, built in 1864-65 by

East Coast Railway. The northern wing has been

Charles Henry Driver for the London, Brighton and South

refurbished and brought back into use. The southern wing

- CA LB
- LPA NP RPG
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTHWARK

SITE NAME:	Former library, public baths and wash-house, Wells Way SE5	Former library and public baths and wash house, in adjacent linked buildings designed by Maurice Adams,
DESIGNATION:	Listed Building grade II	1902. The baths and wash house now house a boxing club, but other parts of the buildings are vacant owing to
CONDITION:	Fair	their declining condition. The buildings require significant upgrading of fabric and services to ensure new uses can be
OCCUPANCY:	Part occupied/part in use	found.
PRIORITY CATEGORY:	C (New entry)	
 OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1386038	Contact: Gemma Williams (LPA) 020 7525 5000

© Historic England



1	SITE NAME:	Former office to Denmark Hill Station, Windsor Walk SE5	The former office to Denmark Hill Station dates from 1864-66. The building is in a poor condition following a fire.
	DESIGNATION:	Listed Building grade II, CA	Planning Permission has been granted to convert the building to a café, but this has not yet been implemented.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
I	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1386053	Contact: Gemma Williams (LPA) 020 7525 5000

Church of St Mary Magdalene,

Listed Place of Worship grade

Bermondsey Street,

Religious organisation

Southwark SE23

Religious organisation

Poor

C (C)

1385617

Bermondsey SEI

II\*, CA

Poor

C (C)

CONDITION:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

PRIORITY CATEGORY:

PRIORITY CATEGORY:

SITE NAME: DESIGNATION:

© Historic England

© Historic England



	0 0	
LIST ENTRY NUMBER:	1376567	Contact: Ian Harper 07974 979620
SITE NAME:	The Cross and Star Church, Falmouth Road, Bermondsey SEI	Built as a Presbyterian chapel in 1888 with Queen Anne and Romanesque influences. It is now the London base for the Church of the Brotherhood of the Cross and Star. It is
DESIGNATION:	Listed Place of Worship grade II	constructed of red brick and gauged brickwork with stone dressings under a slated roof. The complete gallery survives
CONDITION:	Poor	internally, and the stained glass is good quality. The external fabric is in urgent need of repair, including re-
PRIORITY CATEGORY:	C (C)	roofing, and repairs to brickwork, rainwater goods and the
OWNER TYPE:	Religious organisation	stained-glass windows. The congregation is actively engaged in discussion with potential funders to develop a
LIST ENTRY NUMBER:	1385523	repair project.

to trace.

Contact: lan Harper 07974 979620

The church was completed in 1873 by William Oakley, in Church of St Augustine, Honor Kentish ragstone with ashlar details and slated roofs. Oak Park, Camberwell, Underpinning was carried out in two phases in 1993 and 2010. Also in 2010 repairs were carried out to masonry Listed Place of Worship grade II and high-level roofs. The latest phase of stonework repairs and tower re-roofing was completed in 2014, with funding from the National Lottery Heritage Fund and Historic England. Monitoring of the structure continues and funding is being sought for further repairs which will be required in the future.

The church was rebuilt in the late C17 on the site of a

former medieval church developed from the Chapel of the

Convent of Bermondsey, first recorded in the late CI3. The lower stages of the CI5 tower are incorporated. The

structure is weak, not helped by remodelling in 1830 and

structures have been heavily repaired historically but are

still under stress. This is likely the cause of falls of plaster from ceilings. Leakage through the copper gutters is hard

the 1880s. Stucco finished throughout on brick under slate roof with copper gutters within parapets. The roof

© Historic England

© Historic England

OWNER TYPE: LIST ENTRY NUMBER:

D

Е

Contact: lan Harper 07974 979620

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTHWARK

CONDITION:

TREND:

VULNERABILITY:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:



SITE NAME: Church of St Peter, Lordship Lane, Camberwell SE22 Listed Place of Worship grade II, DESIGNATION: CA CONDITION: Very bad PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1385670

Work started on this church, by Charles Barry Jnr, in 1873 on land gifted by Dulwich College for a new parish formed from St Giles Camberwell. The tower and spire were completed in 1875 and the vestry enlarged in 1893. The Church of England closed the church in 1984 and sold it to Worth Abbey, who then sold it to the Deeper Life Bible Church. External masonry is in Kentish ragstone with Bath stone dressings; internally the walls are banded in cream London stocks and red brick. Slated roofs of the nave and timber-framed spire are in bad condition. There is settlement on the north side aisle.

Contact: lan Harper 07974 979620

obscuring the legibility of the landscape. The Local

the whole of the designed landscape.

Contact: Christopher Laine 020 7973 3473

Authority is fundraising to restore the East Lodge, which is

safety works is underway, and a comprehensive tree survey

is informing an updated Conservation Management Plan for

a longstanding building at risk, a programme of memorial

© Histo	oric En	gland
---------	---------	-------

SITE NAME:	Roman boat at N	lew Guy's House, Bermondsey SEI		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1001979
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewate	ering	NEW ENTRY?:	No
OWNER TYPE:	Health authority		CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	The Rose Theatr	re, Rose Court, Southwark SEI		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1012707
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewate	ering	NEW ENTRY?:	No
OWNER TYPE:	Commercial com	npany, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
	SITE NAME:	Nunhead Cemetery (All Saints) SEI5	An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the	
there is the	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, part in CA	create picturesqu	v exploits the undulating topography to ue effects and vistas. Vegetation and self- e disrupting historic monuments and

Generally unsatisfactory with

major localised problems

High

No

Declining

1000824

Local authority

© Historic England Archive

SITE NAME:	Nunhead Cemetery, Nunhead SE15		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Catherine Jeater (LPA) 020 7525 5375
SITE NAME:	Walworth Road, Walworth		
SITE NAME: DESIGNATION:	Walworth Road, Walworth Conservation Area, 6 LBs	NEW ENTRY?:	No
	,	NEW ENTRY?: TREND:	No Improving
DESIGNATION:	Conservation Area, 6 LBs		

#### PRIORITY CATEGORIES

# Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM UÁ
- Unitary Authority World Heritage Site WHS

## SUTTON

SUTTON			
Philipping and an an	SITE NAME:	Boundary walls to Beddington Place along east side of churchyard and along Church Lane, Church Road	Substantial length of C16 or C17 wall of red brick with battered coping and roll moulding. Sections have been buttressed. Sections of the wall and buttresses had suffere structural damage from tree growth and also from
COMPANY IN	DESIGNATION:	Listed Building grade II, CA	extensive graffiti. Sections of the wall have now been repaired and rebuilt to secure its long-term structural
	CONDITION:	Good	performance, with works commissioned by the Local
	OCCUPANCY:	N/A	Authority.
	PRIORITY CATEGORY:	F (F)	
) London Borough of Sutton	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1357592	Contact: Dean James (LPA) 020 8770 5000
	SITE NAME:	Churchyard walls, Church Road	Circa C19 walls of dressed flint with rounded tops, with
	DESIGNATION:	Listed Building grade II, CA	pilasters and brick quoins at intervals. Vegetation and mechanical damage caused some sections to collapse, and
Partie parties	CONDITION:	Fair	mortar failure has led to the loss of flints from others. The
AND AND	OCCUPANCY:	N/A	church has undertaken full repair of extensive sections of the flint wall and these are now in good condition.
18192	PRIORITY CATEGORY:	C (C)	However, there remain some localised areas where morta has deteriorated leading to the loss of flints, and brick
	OWNER TYPE:	Religious organisation	sections require vegetation clearance, mortar and
States and so the	LIST ENTRY NUMBER:	1065671	brickwork repair.
Historic England			Contact: Dean James (LPA) 020 8770 5000
	SITE NAME:	Garden walls at Beddington Place (Carew Manor Special School) to north of Orangery walls, Church Road	C17 to C18 garden walls. The east, south and part of the north walls to the east of Beddington Park Cottages are o brick with battered coping; the west wall is of a later date with plain capping. Damage has been largely caused by
A VI A	DESIGNATION:	Listed Building grade II, CA	vegetation, upper brick courses have been completely dislodged in some sections, and a section of wall has now
	CONDITION:	Very bad	collapsed. The brickwork is in need of substantial repairs,
	OCCUPANCY:	N/A	including extensive repointing and rebuilding.
	PRIORITY CATEGORY:	A (A)	
) Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1200792	Contact: Dean James (LPA) 020 8770 5000
aller.	SITE NAME:	Orangery wall to Beddington Place, Church Road, Beddington	Orangery wall of circa 1720. It has previously been sub to severe vandalism. The soft brickwork is susceptible
A K	DESIGNATION:	Listed Building grade II, CA	erosion and there is invasive plant and shrub growth. Then are currently no plans in place to address these issues.
TEN and	CONDITION:	Poor	are currently no plans in place to address these issues.
The man and the	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1065673	Contact: Dean James (LPA) 020 8770 5000
) Historic England		1005075	Contact. Dearryanies (El A) 020 0770 3000
Alter	SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton	Early C18 grotto in Carshalton Park. The exterior of the grotto has symmetrical curved walls of brick, ramped up grodually to a control peak. The grotto is vulnerable to
	DESIGNATION:	Listed Building grade II, CA	gradually to a central peak. The grotto is vulnerable to vandalism and graffiti and is currently threatened by
n and a second sec	CONDITION:	Poor	significant vegetative growth. Survey work has been carrie out to assess the extent of repairs needed but no plans
	OCCUPANCY:	N/A	have been brought forward.
	PRIORITY CATEGORY:	C (C)	
the second second	OWNER TYPE:	Local authority	
) Historic England	LIST ENTRY NUMBER:	1065628	Contact: Dean James (LPA) 020 8770 5000
RIORITY CATEGORIES			ABBREVIATIONS
<ul> <li>Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.</li> <li>Slow decay; no solution agreed.</li> </ul>	<ul> <li>D Slow decay; solution not yet implemented</li> <li>E Under repair or in fa repair, but no user id under threat of vaca obvious new user (a to buildings capable use).</li> </ul>	d. (where applicable) end use o user identified; or functionally dentified; or redundant buildings with new nocy with no agreed but not yet implemen pplicable only	or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority y use New Entry is noted). NP National Park

- solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Slow decay; no solution agreed.

- Under repair or in fair to good repair, but no user identified, or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- New Entry is noted).

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SUTTON / TOWER HAMLETS

ALVER A	SITE NAME:	Parish Church of St Mary the Virgin, Church Road, Beddington	C14 in origin, the church was much rebuilt with additions in C19 by Joseph Clarke. The dormer windows were added in 1914 by HP Burke Downing. The interior has decorative
	DESIGNATION:	Listed Place of Worship grade II*, CA	Victorian wall paintings and there is a monument to Richard Carew (d.1520) which is suffering from cracking and friable stone. The congregation received a grant from
	CONDITION:	Poor	the National Lottery Heritage Fund for repairing the tov roof, cracks in the tower along with open joints and pas
	PRIORITY CATEGORY:	C (C)	cementitious repairs. These are now complete. Work still
	OWNER TYPE:	Religious organisation	required to other church roofs and the masonry and monuments to the Carew Chapel.
© Historic England	LIST ENTRY NUMBER:	1065670	Contact: Tracey Craig 020 7973 3756

SITE NAME:	Sutton Town Centre High Street Crossro	Sutton Town Centre High Street Crossroads, Sutton		
DESIGNATION:	Conservation Area, 11 LBs, SM	NEW ENTRY ?:	No	
CONDITION:	Fair	TREND:	No significant change	
VULNERABILITY:	Medium	CONTACT:	Dean James (LPA) 020 8770 5000	

#### TOWER HAMLETS

©

1	SITE NAME:	34, Mount Terrace, Whitechapel, EI EI	Late C18/early C19 stock brick end-of-terrace house of three storeys with a basement, mansard roof and round-
1	DESIGNATION:	Listed Building grade II, CA	headed door with a fanlight. This was originally part of a development of two rows of 17 houses constructed for the
	CONDITION:	Very bad	City Corporation. The building is empty and is suffering from neglect with some structural cracking on the front
<b>A</b> f	OCCUPANCY:	Vacant/not in use	elevation. Planning Permission and Listed Building Consent
-	PRIORITY CATEGORY:	F (A)	were granted in 2021 and repair works are in progress.
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1065122	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England



© London Borough of Tower Hamlets

SITE NAME:	One Lamp Standard in front of the Star of the East Public House, Commercial Road E14	One of the three C19 lamp standards on the pavement in front of the Star of the East Public House. A cast iron decorative lantern bearing the inn name with poor and
DESIGNATION:	Listed Building grade II, CA	defective paintwork. Two lamp standards were repaired separately in 2019 and their lanterns are now working. The
CONDITION:	Poor	Local Authority is working with the owner to secure funding to repair and reinstate the remaining lantern.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1065199	Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England

1 20 3	SITE NAME:	The former London Chest Hospital, Bonner Road, Bethnal Green E2	The former London Chest Hospital, a specialist hospital built in 1851-5 to the design of FW Ordish. Built to a late- C17 style, the frontage incorporates sculpture, attributed
	DESIGNATION:	Listed Building grade II, CA	to the workshop of George Myers. The redundant hospital has been vacant some time and has some water ingress at
-	CONDITION:	Poor	roof level. Works to make the building wind and watertight are planned for the summer of 2023. The Council is in
I	OCCUPANCY:	Vacant/not in use	discussion with the owner regarding the future of the
	PRIORITY CATEGORY:	A (New entry)	building.
ii.	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1433870	Contact: Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TOWER HAMLETS


	SITE NAME:	Front wall, gate piers and gates at St Clements Hospital, Bow Road, Bow E3	Decorative gates and railings forming the front boundary to the redundant St Clements Hospital. The freehold has been transferred to the Greater London Authority.
	DESIGNATION:	Listed Building grade II, CA	Planning Permission and Listed Building Consent were granted for the conversion of the former hospital to housing, and works are now close to completion. The gates have now been repaired and will be reinstated as par
	CONDITION:	Fair	
	OCCUPANCY:	N/A	of the final stage of works, which is expected in mid 2023.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1065276	Contact: Andrew Hargreaves (LPA) 020 7364 5576



-	SITE NAME:	St Clements Hospital, Bow Road, Bow E3	Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. The
	DESIGNATION:	Listed Building grade II, CA	freehold has been transferred to the Greater London Authority. Planning Permission and Listed Building Consent
11	CONDITION:	Fair	were granted for the conversion of the former hospital to housing, and works are now close to completion, which is
11	OCCUPANCY:	Part occupied/part in use	expected in mid 2023.
18	PRIORITY CATEGORY:	F (F)	
ten.	OWNER TYPE:	Government or agency	
ets	LIST ENTRY NUMBER:	1251493	Contact: Andrew Hargreaves (LPA) 020 7364 5576



© Historic England



	SITE NAME:	Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3	Underground gentlemen's public convenience, constructed by the Board of Works and opened in 1899. There are curved entrance steps designed to fit around the statue of
	DESIGNATION:	Listed Building grade II, CA	WE Gladstone. The decorative interior finish includes russet marble urinals. The public convenience has been disused for many years and the decorative iron gates have been damaged. The interior is also subject to vandalism. Additional damage to the plinth and railings was caused by
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	a vehicle in Nov 2022. The Local Authority is investigating options for the site.
	OWNER TYPE:	Local authority	
© London Borough of Tower Hamlets	LIST ENTRY NUMBER:	1392968	Contact: Andrew Hargreaves (LPA) 020 7364 5576



SITE NAME:	Former Bromley Hall School, Bromley Hall Road, London E14	Former school for physically disabled children, built in 1967-8 by the Greater London Council's Architects'
DESIGNATION:	Listed Building grade II	Department and extended in 1978-9. The building has a distinctive architectural form which reflects the local
CONDITION:	Poor	industrial vernacular. It has been vacant for several years following changes in educational requirements. The Local
OCCUPANCY:	Vacant/not in use	Authority is considering options for the refurbishment and
PRIORITY CATEGORY:	C (C)	re-use of the building.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1402561	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### 

HERITAGE AT RISK 2023 / LONDO	on and south east	TOWER HAMLETS	
	SITE NAME:	How Memorial Gateway, Bromley High Street E3	Gabled Gothic stone arch with double buttresses at each side, circa 1893. Formerly an entrance to St Mary's
	DESIGNATION:	Listed Building grade II	Churchyard and once the site of St. Leonard's Priory. The gateway is suffering from stonework decay. Volunteers
	CONDITION:	Poor	from Bow Church have been working to tidy up the former churchyard open space, having received a Community
	OCCUPANCY:	N/A	Gardens Grant. Repair works to the gateway are
	PRIORITY CATEGORY:	D (C)	anticipated to start summer 2023, dependent on availability of grant funding.
4	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1065281	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Former Caird & Rayner Ltd Warehouse, 777-783, Commercial Road E14	Former sail makers and ship chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. The building was fire damaged, resulting in the
	DESIGNATION:	Listed Building grade II, 2 CAs	loss of its roof covering. Urgent works were completed in April 2010. The Local Authority approved Planning
	CONDITION:	Very bad	Permission and Listed Building Consent for the conversion of the building to office use as part of the wider
	OCCUPANCY:	Vacant/not in use	development of the site. Works are in progress on site and
	PRIORITY CATEGORY:	F (F)	completion is expected in summer 2024.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1385372	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Drinking fountain (on pavement outside 31-74 Mile End Road), Mile End Road, Stepney E1	Late C19 polished granite drinking fountain, with a short column on a plinth. The drinking fountain has an inscriptio commemorating its erection by the Metropolitan Cattle
UTTLE THE BACK	DESIGNATION:	Listed Building grade II, CA	Trough and Drinking Fountain Association. The bowl has been removed.
	CONDITION:	Very bad	
KING	OCCUPANCY:	N/A	
The card	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© London Borough of Tower Hamlets	LIST ENTRY NUMBER:	1065113	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	19, Princelet Street, Spitalfields El	Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. The building
	DESIGNATION:	Listed Building grade II*, CA	combines a well-preserved Spitalfields Huguenot merchant's house with weaving garrets, and a rare surviving
	CONDITION:	Poor	small synagogue. The owner is working towards a suitable programme of repairs.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1260421	Contact: Simon Buteux 07973 498013
	SITE NAME:	113, Redchurch Street, Tower Hamlets E2	A weavers' tenement house built c1735 by William Farmer, a local builder. An early survival of a building type that once
	DESIGNATION:	Listed Building grade II, CA	dominated Spitalfields. The building is derelict and has structural problems. It was recently braced to prevent
CTILLE - T	CONDITION:	Very bad	further movement and the building is wind and watertight.
	OCCUPANCY:	Vacant/not in use	Planning Permission and Listed Building Consent for retail use have been granted. Repairs in progress (April 2023).
	PRIORITY CATEGORY:	F (F)	

© Historic England

	Hamlets EZ	a local builder. All early survival of a building type that one
DESIGNATION:	Listed Building grade II, CA	dominated Spitalfields. The building is derelict and has structural problems. It was recently braced to prevent
CONDITION:	Very bad	further movement and the building is wind and watertight Planning Permission and Listed Building Consent for retail
OCCUPANCY:	Vacant/not in use	use have been granted. Repairs in progress (April 2023).
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1393497	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

The second	SITE NAME:	Tomb of Joseph Westwood,	A prominent funerary monument dating from 1883, in the	
t.		Southern Grove, Tower Hamlets Cemetery E3	form of a Decorated style wayside cross. It is in poor condition due to the loss of parts of its low railings, tiles,	
	DESIGNATION:	Listed Building grade II, CA	finials and other detailing. The Local Authority commissioned a monument safety survey in 2019. The	
	CONDITION:	Poor	Friends of Tower Hamlets Cemetery Park, who manage	
	OCCUPANCY:	N/A	the site for the Local Authority, have completed a Conservation Management Plan, with funding from the	
TER REAL FAILAN	PRIORITY CATEGORY:	A (A)	National Lottery Heritage Fund. This Identifies the tomb as a priority for future grant funding (April 2023).	
	OWNER TYPE:	Local authority		
© Historic England	LIST ENTRY NUMBER:	1378758	Contact: Andrew Hargreaves (LPA) 020 7364 5576	
	SITE NAME:	St Pauls Mission Room and Infant Nursery, Wellclose Square El	Gothic style structure built in 1874 to designs by Reuben Greatorex. The building is of stock brick with a red brick eaves cornice and red and blue brick bands. It has stone	
AA 3	DESIGNATION:	Listed Building grade II, CA	dressings to the doors and windows, a steeply pitched tiled roof with cresting, and a stone banded chimney. The	
	CONDITION:	Poor	building is empty and boarded up and has recently been	
	OCCUPANCY:	Vacant/not in use	sold (April 2023).	
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:			
© Historic England		Charity (non-heritage)		
	LIST ENTRY NUMBER:	1242432	Contact: Andrew Hargreaves (LPA) 020 7364 5576	
	SITE NAME:	Braithwaite Viaduct, Bishopsgate Goods Yard, Wheler Street / Brick Lane EI	Early railway viaduct built in 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within an extensive brick-vaulted goods yard circa 1880, partially demolished in 2003. Planning Permission and Listed	
STATE F/14	DESIGNATION:	Listed Building grade II	Building Consent was granted in 2021 for a mixed-use	
	CONDITION:	Poor	development which will include repair and reuse of the viaduct and adjacent historic arches.	
	OCCUPANCY:	N/A	viaduce and adjacent historic arches.	
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Utility		
© Historic England	LIST ENTRY NUMBER:	1063895	Contact: Andrew Hargreaves (LPA) 020 7364 5576	
	SITE NAME:	2, Wilkes Street, EI EI	Early C18 terraced house. Three storeys, double fronted,	
	DESIGNATION:	Listed Building grade II, CA	with basement and attic in yellow stock brick with red dressings to segmental-arched windows. Wooden	
	CONDITION:	Poor	doorcase and weavers' windows. Planning Permission and Listed Building Consent were granted in 2021 for external	
	OCCUPANCY:	Vacant/not in use	repairs. Works to the window shutters and door surround	
	PRIORITY CATEGORY:	F (F)	to the front of the building are near completion, with roof works anticipated in the summer of 2023. Further	
	OWNER TYPE:	Private	applications for works to the basement and internal joinery	
	LIST ENTRY NUMBER:	1242278	are expected in late 2023.	
© Historic England Archive			Contact: Andrew Hargreaves (LPA) 020 7364 5576	
	SITE NAME:	Church of St Mary Stratford Bow, Bow Road, Poplar E3	St Mary's Bow is shrouded by trees on a traffic island on the AII. The tower and chancel were added circa 1490 to an early CI4 nave. The south aisle was rebuilt in 1794; the	
	DESIGNATION:	Listed Place of Worship grade II*, CA	upper tower in 1829 and then restored in the 1950s following war damage. There was a general restoration in	
and the second	CONDITION:	Poor	C19. Two phases of repairs are now complete to roofs, clock turret, and external masonry, funded by the National	
	PRIORITY CATEGORY:	D (D)	Lottery Heritage Fund. The church now urgently needs a	
THE THE	OWNER TYPE:	Religious organisation	drainage system, tree management and suitable access from the highway. Discussions with authorities are ongoing	
THE PROPERTY AND A DESCRIPTION OF THE PR	LIST ENTRY NUMBER:	1065273	Contact: Ian Harper 07974 979620	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TOWER HAMLETS

A Star	SITE NAME:	St Paul's Church, Burdett Road, Stepney E3	Designed by architect Robert Maguire, the church was consecrated on the 30th April 1960. The church is based
-364	DESIGNATION:	Listed Place of Worship grade II*	on a rectangular plan centred on the altar, with projections to the northwest and southeast for the porch and the
	CONDITION:	Poor	baptistry, and an adjacent vicarage. Following renewal of the lantern ceiling panels in 2015 and 2016, funded by the
	PRIORITY CATEGORY:	A (A)	National Lottery Heritage Fund, the church was taken off
	OWNER TYPE:	Religious organisation	the register. Now the porch roof and the aisle roofs are leaking, and the concrete structures are at risk.
	LIST ENTRY NUMBER:	1241881	Contact: Ian Harper 07974 979620

© Historic England

© Historic England

© Historic England



	SITE NAME:	Church of St John on Bethnal Green, Cambridge Heath Road, Bethnal Green E2	The parish church of 1824 was designed by Sir John Soane and heavily restored and extended in the C19 by William Munday and GF Bodley. The church is built of London
	DESIGNATION:	Listed Place of Worship grade I, CA	stock brick with artificial stone dressings and bell tower. Repairs to high-level stonework, complete in 2014, were grant aided by Historic England and the National Lottery
	CONDITION:	Poor	Heritage Fund. Funding is being sought for a final phase of repairs to the nave roof, the interior of the narthex and the
	PRIORITY CATEGORY:	C (C)	church steps.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065245	Contact: Ian Harper 07974 979620

SITE NAME: The prominent Commissioner's church was designed in an Church of St George in the East, Cannon Street Road, idiosyncratic style by Hawksmoor and completed in 1729. Faced in fine Portland ashlar on brick cores, the interior Stepney EI was gutted during WW2 with only the landmark tower and Listed Place of Worship grade I, walls surviving. In 1964 a new church was built within the DESIGNATION: CA walls and flats were created above the aisles, accessed through the former gallery stair towers. The aisle roofs are CONDITION: Poor leaking and the exposed exterior walls are suffering from B (New entry) PRIORITY CATEGORY: rain ingress. The church is seeking funding for a full repair and development project. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1357779 Contact: lan Harper 07974 979620

St Anne's Limehouse Parish St Anne's Church was designed by Nicholas Hawksmoor in SITE NAME: the English Baroque style. It was completed in 1730 and consecrated in 1733. The church is faced with Portland Church, Commercial Road, Stepney EI4 stone over brickwork, and the western tower was used as Listed Place of Worship grade I, a 'sea-mark' for naval purposes. The interior was restored DESIGNATION CA by Philip Hardwick following a serious fire in 1851. Further work to the roof structure was carried out between 1983 CONDITION: Poor and 1993. The classical interior is much damaged by PRIORITY CATEGORY: historic water leakage from parapet gutters. The church C (C) has ambitious plans to develop the crypt, provide level OWNER TYPE-Religious organisation access and continue with repairs.

© Historic Engla



© Historic Engla

gland	LIST ENTRY NUMBER:	1357808	Contact: Ian Harper 07974 979620
	SITE NAME:	Calvary Charismatic Baptist Church (former Trinity Methodist Church), including attached hall and church rooms, East India Dock Road, Poplar E14	The church, hall and offices, arranged collegiately, were built in the 1950s as part of the live architectural phase of the 1951 Festival of Britain, which was the first stage of the post-war rebuilding of the heavily damaged Lansbury Estate. The church architects were Cecil Handisyde and D Rogers Stark and the consulting engineer Felix Samuely.
	DESIGNATION:	Listed Place of Worship grade II*, CA	Historic significance is being re-assessed. The roof, domed roof lights and exposed concrete frame were repaired in 2017 with a grant from Historic England. CCBC is in
gland	CONDITION:	Poor	discussion about a further phase of repairs to the church and the tower.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1376625	Contact: Ian Harper 07974 979620

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TOWER HAMLETS

A ANA	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	Church constructed of London stock brick with stone dressings, designed by G Austin and built between 1836 and 1839. Repairs to the roofs and stonework were
	DESIGNATION:	Listed Place of Worship grade II, CA	completed in 2007 with a grant from Historic England and the National Lottery Heritage Fund. Internal repairs are needed to the nave ceiling, windows and walls. External
	CONDITION:	Very bad	stonework repairs are needed to the west end. The congregation worships from a modern adjacent building
	PRIORITY CATEGORY:	C (C)	and is actively exploring options for funding the necessary repairs to the former church to enable its use as a multi-
Name of Contract of Contract of Contract	OWNER TYPE:	Religious organisation	repairs to the former church to enable its use as a multi- purpose community facility.
Historic England	LIST ENTRY NUMBER:	1065118	Contact: Ian Harper 07974 979620



SITE NAME:	St Peter's Church, St Peter's Close, Bethnal Green E2	St Peter with St Thomas was designed by Lewis Vulliamy and completed in 1841 in a neo-Norman style. Vestries
DESIGNATION:	Listed Place of Worship grade II, CA	were added to the east end in early C20. The church is built of flint facework on brick cores with dressings in Bath stone and terracotta. Services are being held in a marquee
CONDITION:	Very bad	in the churchyard while funds are raised to replace the ceiling panels. These have decayed and fallen, causing
PRIORITY CATEGORY:	A (New entry)	asbestos contamination. Trees in the churchyard are
OWNER TYPE:	Religious organisation	damaging the railings. The church is actively engaged with raising funds to deal with the asbestos problem.
LIST ENTRY NUMBER:	1357877	Contact: Ian Harper 07974 979620

© Historic England

C

Ŷ

©⊦

SITE NAME:	Priory and Hospital of St Mary Spital, Steward Stre	et El	
DESIGNATION:	Scheduled Monument, 11 LBs, part in CA	LIST ENTRY NUMBER:	1001982
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Jane Sidell 020 7973 3738
SITE NAME:	London Hospital, Stepney El		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Anne's Church E14		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Tower Hamlets Cemetery, Bow E3		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wentworth Street, Bethnal Green EI		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TOWER HAMLETS / WALTHAM FOREST

SITE NAME:	Whitechapel High Street, Aldgate El		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

WALTHAM	FOREST
Internet III	

	SITE NAME:	Chestnuts House, 398, Hoe Street E17	Substantial detached house of circa 1745-7 in stock red brick with red dressings. Elaborate stucco interiors survive
	DESIGNATION:	Listed Building grade II*	along with original panelling and cornices. The house fell out of use several years ago and has since been occupied
	CONDITION:	Poor	by live-in guardians. Emergency repairs to the roofs and rainwater goods have addressed the worst of deterioration
	OCCUPANCY:	Occupied/in use	and water ingress with further recent investment in the
	PRIORITY CATEGORY:	C (C)	building through the Public Sector Decarbonisation Scheme. The Local Authority continues to develop plans
	OWNER TYPE:	Local authority	for the repair and re-use of the building through funding from the Levelling Up Fund.
ic England	LIST ENTRY NUMBER:	1191062	Contact: Verena McCaig 020 7973 3718

© Historic

	SITE NAME:	Essex County Cricket Pavilion, Leyton High Road E10	Cricket pavilion, rendered and colour washed timber frame over a brick basement in the Vernacular Revival style, built
A	DESIGNATION:	Listed Building grade II	in 1886 by Richard Creed for the Essex County Cricket Club. The building currently has low-key community uses.
Annual	CONDITION:	Fair	Urgent works were carried out in 2021 to make the building water-tight and repair damaged elements, with
	OCCUPANCY:	Part occupied/part in use	additional works carried out through the Public Sector
	PRIORITY CATEGORY:	C (C)	Decarbonisation Scheme. The Council is now taking forward proposals for re-use of the building for leisure
	OWNER TYPE:	Local authority	purposes, progressing opportunities to fund full restoration and secure new long-term occupiers.
storic England	LIST ENTRY NUMBER:	1386803	Contact: Mike Fox (LPA) 020 8496 3000

© Histo



© London Borough of Waltham Forest

	SITE NAME:	Metal Railing to Chingford Mill Pumping Station, Lower Hall Lane E4	Metal railing with concrete plinth, 1890-95. Shallow curving plan in twelve sections; alternate uprights supported by curved brackets. The condition of the railings is poor and
	DESIGNATION:	Listed Building grade II	numerous sections have been removed and replaced with temporary metal fencing. They were repainted in 2015 but
	CONDITION:	Poor	require further repair and replacement.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
t	LIST ENTRY NUMBER:	1065575	Contact: Mike Fox (LPA) 020 8496 3000



© Historic England

are the	SITE NAME:	Wall to south east of St Mary's Churchyard, Church End E17	C18 walls, formerly belonging to a house, now demolished, on the adjacent site. A dense covering of ivy is damaging	
	DESIGNATION:	Listed Building grade II, part in CA	the brickwork, which is in need of repair. A section has collapsed. Efforts are being made to clarify ownership in order that necessary works can be discussed and eventually secured.	
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
a series	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1357602	Contact: Mike Fox (LPA) 020 8496 3000	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB Listed Building LPA Local Planning Autho NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WALTHAM FOREST




© London Borough of Waltham Forest

SITE NAME:	698a, High Road Leytonstone, Leytonstone EI I	One of a surviving terrace of three Georgian houses, probably late C18, for many years the home of the local
DESIGNATION:	Listed Building grade II	British Legion branch. Planning Permission and Listed Building Consent have been secured for conversion into
CONDITION:	Very bad	flats. The Local Authority is in discussion with the owner to ensure that the consented scheme is carried out.
OCCUPANCY:	Part occupied/part in use	choire that the consented sentine is carried out.
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1357632	Contact: Mike Fox (LPA) 020 8496 3000



© Historic England

	SITE NAME:	Chapel to south of main hospital block, Langthorne Road EII	Closed chapel to a hospital (formerly a workhouse), 1840. The building is wind and weathertight but in need of moderate repair to bring it back into use.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1357634	Contact: Mike Fox (LPA) 020 8496 3000



	SITE NAME:	Chingford Mill Pumping Station, Lower Hall Lane E4	Pumping station built in 1895 for East London Water Works, in a variant of the style popularised by Norman
	DESIGNATION:	Listed Building grade II	Shaw. The building is in two ownerships. Part of the building is being converted for residential use; part remains for utility use. The roof to the tower section is in very poo
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	condition and rainwater goods require repair. Enforcement action for unauthorised works is ongoing. The Local
	PRIORITY CATEGORY:	C (C)	Authority and Historic England are liaising with the owners to improve the condition and management of the buildings
	OWNER TYPE:	Mixed, multiple owners	and wider site.
© Historic England	LIST ENTRY NUMBER:	1250896	Contact: Mike Fox (LPA) 020 8496 3000
and a	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Listed Building Consent for residential use were granted in 2007
			and subsequently renewed, subject to a Section 106



© Historic England	LIST ENTRY NUMBER:	1250896	Contact: Mike Fox (LPA) 020 8496 3000
the second	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Liste Building Consent for residential use were granted in 2007
MAKE	DESIGNATION:	Listed Building grade II	and subsequently renewed, subject to a Section 106 agreement. Repairs have been carried out and the building
A	CONDITION:	Fair	is now occupied. The Local Authority and Historic England are monitoring the building to review the level of current
	OCCUPANCY:	Occupied/in use	risk and ensure that unauthorised works are remedied or
	PRIORITY CATEGORY:	C (C)	regularised.
	OWNER TYPE:	Commercial company	
© London Borough of Waltham Forest	LIST ENTRY NUMBER:	1065574	Contact: Mike Fox (LPA) 020 8496 3000

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious powy user (coplicable only obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WALTHAM FOREST

	SITE NAME:	133, Whipps Cross Road, Leytonstone EI I	One of six survivors from an original terrace of 12 'middle- class' three-storey houses called Assembly Row, built in		
	DESIGNATION:	Listed Building grade II, CA	1767. Render and brickwork on the flank wall have suffered from considerable water ingress and are in a parlous		
	CONDITION:	Poor	condition. Following enforcement action, the roof coverings have been replaced and the front sash windows		
	OCCUPANCY:	Occupied/in use	have been repaired. Historic England and the Local		
	PRIORITY CATEGORY:	C (C)	Authority have advised the owner on further necessary repair works, and the Local Authority is taking		
	OWNER TYPE:	Private	enforcement action, including for the unauthorised removal of two dormer windows.		
ham Forest	LIST ENTRY NUMBER:	1357621	Contact: Mike Fox (LPA) 020 8496 3000		



© London Borough of Walth

© Historic England

©

SITE NAME:	Church of St Andrew, Colworth Road, Leytonstone E11	Sir Arthur Blomfield was commissioned by the Cotton family to build the church in memory of William Cotton of Wallwood House; it was completed by 1893 in Kentish rag
DESIGNATION:	Listed Place of Worship grade II, CA	with knapped flint walling and freestone dressings. There is an important collection of window glass by Margaret Chilton. The early C20 vestry has a fine timber roof but is
CONDITION:	Very bad	poorly founded and its settlement is damaging the chur structure. In 2020 Historic England awarded a Covid-19
PRIORITY CATEGORY:	A (A)	Emergency Heritage at Risk Response Fund grant for
OWNER TYPE:	Religious organisation	repairs to the stained glass and for investigations into the causes of subsidence.
LIST ENTRY NUMBER:	1391544	Contact: Ian Harper 07974 979620

		SITE NAME:	St Michael and All Angels Church, Palmerston Road, Walthamstow E17	This church has an imposing interior augmented by stained glass windows by Hardman and the highest nave roof of any church in the Chelmsford Diocese. It was designed in the Gothic style by JM Bignall and opened in 1885. It is constructed of London stock yellow brick with a mixture of
		DESIGNATION:	Listed Place of Worship grade II	
		CONDITION:	Poor	red brick and stonework dressings. The original cast iron rainwater goods are in very poor condition and
La Line Line II	Side (	PRIORITY CATEGORY:	C (C)	inadequately sized to cope with climate change. The
00		OWNER TYPE:	Religious organisation	regular wetting of the soft red bricks is causing them to decay internally and externally. In addition, the vestry roof
	1	LIST ENTRY NUMBER:	1191154	is felted over and needs renewal.
Historic England				Contact: Ian Harper 07974 979620
	Channel of	SITE NAME:	Church of St Peter and St Paul, The Green, Chingford E4	The church, with tower and spire of 1844, is by Lewis Vulliamy; the chancel and north and south aisle chapels are

by Sir Arthur Blomfield, in 1903. The Lady Chapel was Listed Place of Worship grade extended and re-ordered in 1936 by NF Cachemaille-Day. Construction is in cream-coloured brick with decorative flint flushwork dressed in Bath stone. The slating is sound but the defective parapet gutters and sumps have caused serious internal leaks. A first phase of repairs was funded by the National Lottery Heritage Fund. Funds are sought for a second phase for the nave parapets, rainwater goods, and reordering access.

Contact: Ian Harper 07974 979620

SITE NAME: A late C19 basilica style church by architect JT Newman, Church of St Margaret of Antioch and attached railings, commenced in 1892, replacing an iron mission church. The Lady Chapel was added in 1910. There are fine decorations Woodhouse Road, Leyton EII and wall paintings internally. Only the north transept and aisle roofs remain to be repaired but this work is urgent as DESIGNATION: Listed Place of Worship grade II the paintings and parquet floor are being damaged by CONDITION: Very bad inadequate rainwater goods and drainage. The PRIORITY CATEGORY: contemporary railings and adjacent halls are also in need of A (A) repair. The congregation is actively exploring options for Religious organisation OWNER TYPE: funding the repairs. LIST ENTRY NUMBER: 1390581 Contact: lan Harper 07974 979620

© Historic England

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

II\*, CA

Poor

C (C)

1065582

Religious organisation

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WANDSWORTH

SITE NAME:

OWNER TYPE:

LIST ENTRY NUMBER:

#### WANDSWORTH

	SITE NAME:	Battersea Park Station, Battersea Park Road SW8	Italianate style station built circa 1865 for the London, Brighton and South Coast Railway. Alterations to the train
	DESIGNATION:	Listed Building grade II, CA	service mean that the architecturally significant Platform redundant. Repair works are complete, but the building.
	CONDITION:	Fair	specifically Platform I, remains underused. A legal agreement with Network Rail for a scheme of works was
	OCCUPANCY:	Part occupied/part in use	secured in 2018. In 2019 the former station master's
	PRIORITY CATEGORY:	E (E)	accommodation was converted into offices. Discussions about the wider station site, including an additional
	OWNER TYPE:	Utility	entrance, a new use for Platform 1, disability access and improved facilities are underway.
ondon Borough of Wandsworth	LIST ENTRY NUMBER:	1357652	Contact: David Andrews (LPA) 020 8871 6631



A.	SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII	Church school of 1866-67 designed by Benjamin Ferrey. The building is currently vacant but is wind and
P	DESIGNATION:	Listed Building grade II, CA	weathertight. The previous owners carried out maintenance and repairs to the roof and rainwater goods
	CONDITION:	Poor	and implemented structural support to the north wall early in 2018. The building has recently (Spring 2023) been sold
	OCCUPANCY:	Vacant/not in use	and discussions are in progress between the Local
-	PRIORITY CATEGORY:	C (C)	Authority and the new owner. Applications for Planning Permission and Listed Building Consent have been
	OWNER TYPE:	Commercial company	submitted for alterations and repairs (March 2023).
	LIST ENTRY NUMBER:	1389136	Contact: Lauren Way (LPA) 020 8891 7928

Former psychiatric hospital built in 1840 in Tudor Gothic

style as the Surrey County Asylum. The Hospital Trust appointed a partner in 2018 to progress a programme of

© Historic England

© Lor



© Historic England



		SW17	appointed a partner in 2018 to progress a programme of
	DESIGNATION:	Listed Building grade II, RPG grade II	works. Planning Permission and Listed Building Consent applications were approved in 2020 for the first phase of re-use, and restoration of the main building and Airing
	CONDITION:	Poor	Courts. Further applications were submitted and approved for the second phase in 2022 and 2023 and works of re-
	OCCUPANCY:	Part occupied/part in use	use, restoration and repair are currently (March 2023) in
	PRIORITY CATEGORY:	F (F)	progress.
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1065553	Contact: Lauren Way (LPA) 020 8891 7928
	SITE NAME:	Temple in the grounds of Mount Clare, Minstead Gardens SW15	The 'temple' dates from between 1762 and 1769. Some damage was caused as a result of heritage crime in 2017. The site has been re-secured by perimeter fencing which
	SITE NAME: DESIGNATION:	Mount Clare, Minstead Gardens	damage was caused as a result of heritage crime in 2017. The site has been re-secured by perimeter fencing which has temporary Planning Permission (renewed in 2021) and
		Mount Clare, Minstead Gardens SW15	damage was caused as a result of heritage crime in 2017. The site has been re-secured by perimeter fencing which has temporary Planning Permission (renewed in 2021) and is regularly monitored by Roehampton University. Some tree damage to the fence and roof occurred in 2022 and a
	DESIGNATION:	Mount Clare, Minstead Gardens SW15 Listed Building grade II*, CA	damage was caused as a result of heritage crime in 2017. The site has been re-secured by perimeter fencing which has temporary Planning Permission (renewed in 2021) and is regularly monitored by Roehampton University. Some tree damage to the fence and roof occurred in 2022 and a schedule of conservation repair works is being prepared. Discussions between the Local Authority and the university
	DESIGNATION: CONDITION:	Mount Clare, Minstead Gardens SW15 Listed Building grade II*, CA Very bad	damage was caused as a result of heritage crime in 2017. The site has been re-secured by perimeter fencing which has temporary Planning Permission (renewed in 2021) and is regularly monitored by Roehampton University. Some tree damage to the fence and roof occurred in 2022 and a schedule of conservation repair works is being prepared.

Springfield Hospital (main building), Glenburnie Road

Religious organisation

1065545

SW17

© Historic England



SITE NAME:	Former White Lion, 14-16, Putney High Street SW15	Former White Lion public house, built in 1887. The building is unoccupied following its closure in 2015 and is in
DESIGNATION:	Listed Building grade II, CA	poor condition, with access problems. Planning Permission and Listed Building Consent, in line with the permissions
CONDITION:	Poor	granted in 2016, were renewed in April 2019 for extensions and alterations for hotel and public house use
OCCUPANCY:	Vacant/not in use	but have not yet been implemented and have now lapsed.
PRIORITY CATEGORY:	C (D)	The building is secure and occupied by property guardians (March 2023).
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1184658	Contact: Lauren Way (LPA) 020 8891 7928

© London Borough of Wandsworth

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

proposed repair works is being sought.

Contact: Simon Buteux 07973 498013

#### ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument

- SM UA WHS
  - Unitary Authority World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WANDSWORTH / WESTMINSTER, CITY OF

101	1
ALEFE	
LSWB QUEENS ROAD STATION	

SITE NAME:	Queenstown Road Station, Queenstown Road SW8	Station built in 1877. Repairs are needed to the doors, windows and floors of the disused areas of this unattended
DESIGNATION:	Listed Building grade II, CA	station. The former station ticket office has been re-used as a café, and redecoration of the lobby area is complete. The
CONDITION:	Poor	owners have confirmed that funding is in place for repair works and discussions are ongoing regarding Network
OCCUPANCY:	Part occupied/part in use	Rail's enhancement proposals for the station. An
PRIORITY CATEGORY:	F (D)	application for Listed Building Consent for proposals for a second entrance from Patcham Terrace was approved in
OWNER TYPE:	Utility	2022 and the works to implement the second entrance are currently (March 2023) under way.
LIST ENTRY NUMBER:	3894 3	Contact: Lauren Way (LPA) 020 8891 7928

© London Borough of Wandsworth

	SITE NAME:	100, Tooting Bec Road SW17	Early C19 stucco lodge. Planning Permission and Listed
Iller Y	DESIGNATION:	Listed Building grade II	Building Consent were granted in 2012 to use the building for retail and office space, together with a new building for
	CONDITION:	Fair	use as a café and car sales. A Repairs Notice was served in 2015 and these works were completed in 2017. An
	OCCUPANCY:	Vacant/not in use	enforcement notice was served in 2018 in respect of
	PRIORITY CATEGORY:	C (C)	hoardings around the site. Applications for Planning Permission and Listed Building Consent for new buildings,
	OWNER TYPE:	Private	and car sales/gym use were refused in 2019. A revised scheme is awaited, and discussions are in progress between
	LIST ENTRY NUMBER:	1357661	the Local Authority and the owner.
© London Borough of Wandsworth			Contact: David Andrews (LPA) 020 8871 6631

Contact: David Andrews (LPA) 020 8871 6631

#### WESTMINSTER, CITY OF

	SITE NAME:	19, Cavendish Avenue NW8	House dating from the mid C19, with a stuccoed facade
	DESIGNATION:	Listed Building grade II, CA	and central Tuscan porch with a balcony above. The property is unoccupied and in a poor condition. The stucco
	CONDITION:	Poor	is failing in places, plants have taken root at eaves level, and there are signs of water ingress internally. Planning
	OCCUPANCY:	Vacant/not in use	Permission and Listed Building Consent were granted i
	PRIORITY CATEGORY:	F (F)	November 2017 for the full repair of the building and alterations to provide a single family dwelling. Work has
	OWNER TYPE:	Private	now started on site.
	LIST ENTRY NUMBER:	1066300	Contact: John Wilman (LPA) 07866 037008

© Historic England

	SITE NAME:	90-93, Piccadilly WI	Corner block of shops and chambers dating from 1883.
	DESIGNATION:	Listed Building grade II, CA	Red brick with stucco ornament and dressings and slate roofs in an eclectic High Victorian design. Part of the
	CONDITION:	Poor	former private club complex with 94 and 95 Piccadilly. Planning Permission and Listed Building Consent were granted in March 2018 for a scheme including the adjacer
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	listed buildings (94 and 95 Piccadilly). Works include the full repair of the buildings for hotel use, with seven residential
	OWNER TYPE:	Commercial company	units, and are currently being implemented.
	LIST ENTRY NUMBER:	1226747	Contact: Matthew Pendleton (LPA) 07866 039923

© Historic England



Hospital building dating from 1889-90 by WC Habershon Former Samaritans Hospital for Women, 161 Marylebone Road and F Fawkner. Bold classical style building with a NWI NWI symmetrical front incorporating a giant pilaster order and faced in red brick and terracotta with a slate roof. Vacant DESIGNATION: Listed Building grade II, CA and in need of internal repair and conservation and with plant growth on the external elevations. Discussions are Very bad ongoing with regards to its long-term use and repair. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (C) OWNER TYPE: Health authority LIST ENTRY NUMBER: 1239818 Contact: Alistair Taylor (LPA) 07866037603

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

CONDITION:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF

	SITE NAME:	21, Charles Street WI	Terraced town house circa 1750-53. Some unauthorised
	DESIGNATION:	Listed Building grade II, CA	works have taken place. Planning Permission and Listed Building Consent were granted in July 2008 for various
	CONDITION:	Poor	works including demolition and rebuilding of the mews building to the rear. The street elevation was cleaned and
	OCCUPANCY:	Vacant/not in use	repaired in 2011-12.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357294	Contact: Matthew Pendleton (LPA) 07866 039923

© Historic England

	SITE NAME:	112, Eaton Square SW1	Grand terraced house, circa 1825. The building is suffering
	DESIGNATION:	Listed Building grade II*, CA	from neglect, water ingress and a serious outbreak of dry rot. Discussions with the owner are ongoing. Planning
	CONDITION:	Poor	Permission and Listed Building Consent were granted in August 2017 for the full repair of the building as a single
	OCCUPANCY:	Vacant/not in use	family dwelling, but the works have not yet been
	PRIORITY CATEGORY:	D (D)	implemented.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1066851	Contact: Simon Buteux 07973 498013

© Westminster City Council

	SITE NAME:	94 and 100, Gloucester Place WI	Terraced houses built circa 1800 for the Portman Estate. Listed Building Consent was granted in July 2009 for the
	DESIGNATION:	Listed Building grade II, CA	internal refurbishment and alterations to No. 100. Works have yet to be implemented.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Westminster City Council	LIST ENTRY NUMBER:	1066788	Contact: Susanna Miller (LPA) 07866 039239

	SITE NAME:	10-11, Lancaster Gate W2	Grand terrace of houses dating from 1865, attributed to
	DESIGNATION:	Listed Building grade II, CA	John Johnson. The building is three bays wide with four storeys plus attic and basement. It has fine classical
	CONDITION:	Very bad	detailing. The condition of the existing building is very poor, owing to water leakage and a lack of maintenance over
	OCCUPANCY:	Vacant/not in use	many years. The building has, however, been temporar
	PRIORITY CATEGORY:	C (C)	secured following enforcement action, and discussions are ongoing with regards to its long-term use and repair.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1221694	Contact: Alistair Taylor (LPA) 07866037603

© Westminster City Council

	SITE NAME:	94, Piccadilly WI	Town Mansion of 1756-1760 by Matthew Brettingham for
	DESIGNATION:	Listed Building grade I, CA	Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Planning Permission
	CONDITION:	Poor	and Listed Building Consent were granted in March 2018 for a scheme including the adjacent listed buildings (90-93
	OCCUPANCY:	Vacant/not in use	and 95 Piccadilly). Works include the full repair of the
	PRIORITY CATEGORY:	F (F)	buildings for hotel use, with 7 residential units, and are currently being implemented.
	OWNER TYPE:	Commercial company	, , ,
7	LIST ENTRY NUMBER:	1226748	Contact: Simon Buteux 07973 498013

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF

	SITE NAME:	95, Piccadilly WI	Town house dating from 1886, forming part of a larger site
	DESIGNATION:	Listed Building grade II, CA	with the Former Naval and Military Club. Planning Permission and Listed Building Consent were granted in
	CONDITION:	Poor	March 2018 for a scheme including the adjacent listed buildings (90-93 and 94 Piccadilly). Works include the full
	OCCUPANCY:	Vacant/not in use	repair of the buildings for hotel use, with seven residential
	PRIORITY CATEGORY:	F (F)	units, and are currently being implemented.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1265696	Contact: Matthew Pendleton (LPA) 07866 039923

© Historic England

© Historic England



SITE NAME:	Wharf side shelter and store to rear of builders' merchants, 22, Praed Street W2 W2	Wharf side shelter and store circa 1840. Brick ground floor with timber first floor and large slated hipped roof. Part of the redevelopment scheme for Paddington Basin. The	
DESIGNATION:	Listed Building grade II	shelter is currently being stored off-site and will be re- erected as part of the final landscaping proposals.	
CONDITION:	Fair		
OCCUPANCY:	Vacant/not in use		
PRIORITY CATEGORY:	D (D)		
OWNER TYPE:	Charity (heritage)		
LIST ENTRY NUMBER:	1248366	Contact: Andrew Barber (LPA) 07866 037397	

	SITE NAME:	140, Westbourne Terrace W2	Detached villa dating from 1843-8 in an Italianate style.
	DESIGNATION:	Listed Building grade II, CA	Occupied as a number of bedsits. Planning Permission and Listed Building Consent were refused in November 2011
	CONDITION:	Fair	for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised
inner mar	OCCUPANCY:	Occupied/in use	works. This is being investigated as an enforcement matter.
	PRIORITY CATEGORY:	D (D)	Some repairs have, however, been carried out.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1267518	Contact: John Wilman (LPA) 07866 037008

Designed by Sir Walter Tapper and built 1912-13. Located SITE NAME: Church of the Annunciation, on a corner site, the church is built up against on two sides Bryanston Street, Marble Arch which makes access difficult for roof maintenance. The Ŵ church has a problem with the ingress of rainwater and Listed Place of Worship grade dampness has resulted in the ongoing detachment and falling of plaster and water staining to the vaulted ceilings. DESIGNATION: II\*, CA There is also falling masonry externally. The rainwater CONDITION: Poor goods to the north nave were replaced summer 2020. PRIORITY CATEGORY: C (C) OWNER TYPE Religious organisation © Historic England



	OWNER TIPE:	Religious organisation			
	LIST ENTRY NUMBER:	1066358	Contact: Tracey Craig 020 7973 3756		
	SITE NAME:	Church of St Peter, Eaton Square, Westminster SWI	A Classical Commissioner's church designed by Henry Hakewill, completed 1827 and enlarged 1875. It has a		
	DESIGNATION:	Listed Place of Worship grade II*, CA	pedimented west portico, west end narthex carrying the tower and cupola, and rectangular nave with short transepts. The church was partly destroyed by fire in 19		
The s	CONDITION:	Poor	and the interior reordered, the nave being totally remodelled. The church has had a fall of plaster from the		
	PRIORITY CATEGORY:	A (A)	portico ceiling, the buckled copper roofing to the portico		
	OWNER TYPE:	Religious organisation	needs replacing, and past cementitious repairs to the tower are becoming detached and also falling.		
	LIST ENTRY NUMBER:	1356980	Contact: Tracey Craig 020 7973 3756		

© Paul Travis

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Church of St Cyprian,	Designed by Ninian Comper and built 1903 in red brick
		Glentworth Street, Marylebone NWI	with stone dressings and mainly slated roofs. It has a nave, aisles with large windows, small windows to the clerestory, and a bellcote. The church has a white and gold colour
	DESIGNATION:	Listed Place of Worship grade II*, CA	scheme internally with finely detailed furnishings and stained glass, also by Comper. The roofs are in need of
	CONDITION:	Poor	attention, particularly over the Lady Chapel, which has leaks.
	PRIORITY CATEGORY:	C (C)	
and the second	OWNER TYPE:	Religious organisation	
) Historic England	LIST ENTRY NUMBER:	1237476	Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Mark, Hamilton Terrace, Westminster NW8	Gothic church dating from 1847 by Thomas Cundy Senior with spire by Thomas Cundy Junior and chancel in 1878 by EB Farroy. The page rest was re-stated in 2013, with
A A A A A A A A A A A A A A A A A A A	DESIGNATION:	Listed Place of Worship grade II*, CA	EB Ferrey. The nave roof was re-slated in 2013, with funding from Historic England and the National Lottery Heritage Fund. A further grant was awarded towards
STATE IN STATE	CONDITION:	Very bad	masonry repairs to the tower and spire; these works were
	PRIORITY CATEGORY:	C (C)	completed in 2017. On 26th January 2023 St Mark's suffered a devastating fire which has left the church gutted.
	OWNER TYPE:	Religious organisation	Shoring has been erected to make the building safe for inspection and salvage. Discussions are starting on a
	LIST ENTRY NUMBER:	1066681	strategy for the long term.
D Historic England			Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of St Augustine, Kilburn Park Road, Kilburn NW6	Designed by JL Pearson, built in 1877. The building has slated pitched roofs and red brick walling with Bath stone
No. 14	DESIGNATION:	Listed Place of Worship grade I	dressings. Internally the walls are covered in wall paintings by Clayton & Bell. The south aisle roof was re-slated in
	CONDITION:	Poor	2013, with funding from Historic England and the National Lottery Heritage Fund. A new heating system has more
and the little	PRIORITY CATEGORY:	C (C)	recently been installed. The church received funding
	OWNER TYPE:	Religious organisation	through the Grants for Programmes of Major Works for the repair of roofs to the nave, chancel, transepts, the lead
	LIST ENTRY NUMBER:	1221320	fleche and some masonry, completed June 2022.
D Historic England			Contact: Tracey Craig 020 7973 3756
AL PRIME	SITE NAME:	Buddhist Temple, Margaret Street, Westminster WI	Former Parish School and Church House to All Saints Margaret Street, dating from 1868-70 by William
	DESIGNATION:	Listed Place of Worship grade II*, CA	Butterfield. The building is in full-time occupation and used for worship, library and residential accommodation. The roofs and external elevations are in poor condition. Repair
	CONDITION:	Poor	were carried out in 2018 to the roofs, masonry and
I I THE MAN	PRIORITY CATEGORY:	C (C)	rainwater goods of the former Church House, grant aided by the National Lottery Heritage Fund. Similar repairs are
HI HA STATE	OWNER TYPE:	Religious organisation	required to the former School House.
D Historic England	LIST ENTRY NUMBER:	1273611	Contact: Tracey Craig 020 7973 3756
N. ĝ	SITE NAME:	Church of St Clement Danes, Strand, Westminster WC2	St Clement Danes is a 1681 rebuild by Sir Christopher Wren of an earlier church. Portland stone. At the west end
	DESIGNATION:	Listed Place of Worship grade I, CA	is a tower with steeple added by James Gibbs in 1719, consisting of three octagonal diminishing stages surmounted by a dome. The church was gutted in World
	CONDITION:	Poor	War II and restored in the 1950s by Antony Lloyd for the
A States	PRIORITY CATEGORY:	C (New entry)	RAF as their church in London. Recent inspections have found serious problems with the stone to the steeple,
	OWNER TYPE:	Religious organisation	which is fractured and eroded, neccessitating wire
X	LIST ENTRY NUMBER:	1237099	strapping and netting to hold it together. Also problems with the lead roofs, which are beginning to fail.
© Historic England	LIST LITTLE HOULDEN.		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WESTMINSTER, CITY OF / BRACKNELL FOREST (UA) / BRIGHTON AND HOVE, CITY OF (UA)

	SITE NAME:	Church of St Gabriel, Warwick Square, Pimlico SWI	Church dating from 1851-3 by the architect Thomas Cundy II with his son Thomas Cundy III. The tower has been
	DESIGNATION:	Listed Place of Worship grade II*, CA	repaired, grant aided by the National Lottery Heritage Fund and Historic England. Work was completed in March 2021 to convert an internal courtyard into a WC, provide
	CONDITION:	Fair	step free access to the church, carry out improvements to rainwater goods and below ground drainage, and repair th boundary wall. The church was awarded funds from the Grants for Programmes of Major Works for masonry repairs and internal plaster and decorations, completed in
	PRIORITY CATEGORY:	F (F)	
Anne	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1357369	June 2022.
Historic England			Contact: Tracey Craig 020 7973 3756

© Historic England

#### **BRACKNELL FOREST (UA)**

	SITE NAME:	Newbold College (formerly Moor Close), Binfield	Moor Close estate, now the home of Newbold College, was Oliver Hill's first commission in an early C20 Arts and
	DESIGNATION:	Registered Park and Garden grade II*, 7 LBs	Crafts style. Divided into several sections the garden and its setting will be affected by development and infrastructure proposals within the Local Plan, some of which has now
	CONDITION:	Extensive significant problems	been approved.The garden's built fabric has deteriorated and after a condition survey and some limited site repairs
	VULNERABILITY: High	High	further resources are needed to manage change so that the significance of design, structural fabric and setting may best be considered to restrict further loss of historic design
Contraction of the second	TREND:	Declining	
	NEW ENTRY?:	No	integrity.
© Historic England	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1000547	Contact: Kay Richardson 0207 973 3647

Mar Al	SITE NAME:	Broadmoor Hospital, Crowthorne	A mid-C19 asylum designed by Joshua Jebb with rare survival of large kitchen garden as the focus for therapeutic work. Sited on a ridge the cascading walled gardens and institutional farm are highliy significant. The setting of ornamented farmland is vulnerable. Development of the
	DESIGNATION:	Registered Park and Garden grade II, LB grade II	
a second de la second	CONDITION:	Extensive significant problems	new hospital is complete with the original complex allocated for comprehensive mixed use/residential
	VULNERABILITY:	High	development. A pre-development Conservation Management Plan is required and close liaison is welcome to minimise further harm to the historic design integrity ar
	TREND:	Declining	
	NEW ENTRY ?:	No	explore significance for sustainabile living here.
© Historic England	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1001401	Contact: Kay Richardson 0207 973 3647

#### BRIGHTON AND HOVE, CITY OF (UA)



© Historic England

	SITE NAME:	Madeira Terrace and Madeira Walk and Lift Tower and Related Buildings, Madeira Drive, Brighton	The 850 metres of cast iron arches known as Madeira Terrace is an iconic feature of Brighton's eastern seafront. An important example of C19 engineering, and evocative of the late Victorian heyday of the seaside. The terrace is in
	DESIGNATION:	Listed Building grade II*, part in RPG grade II, CA	a very poor and deteriorating condition. Its structural stability is a serious concern causing the 170 plus bays to be closed off to the public. The restoration of the whole of
	CONDITION:	Very bad	the terrace will require substantial funding. Listed Building Consent and Planning Permission have been granted for
No.	OCCUPANCY:	Vacant/not in use	the repair, restoration and re-use of the first phase of 40
	PRIORITY CATEGORY:	C (C)	arches.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1381696	Contact: Alma Howell 0207 9733 627

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park

  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BRIGHTON AND HOVE, CITY OF (UA)

	SITE NAME:	53, Brunswick Square, Hove	Terraced house by A Wilds and CA Busby, 1825-27. Used
	DESIGNATION:	Listed Building grade I, CA	for multiple occupancy but largely vacant. The rear elevation and outbuildings are in poor condition and parts
	CONDITION:	Poor	of the building are not habitable. Urgent works have been carried to make the building weather and water tight but
	OCCUPANCY:	Part occupied/part in use	full repairs are still required and there is no long-term
	PRIORITY CATEGORY:	C (C)	solution currently in place.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1281017	Contact: Alma Howell 0207 9733 627

© Historic England



-	SITE NAME:	The West Pier, Kings Road, Brighton	Pier, 1864-66 by Eugenius Birch. Closed in 1975. Historic England has declared its view that the combination of
5.	DESIGNATION:	Listed Building grade I, CA	significant damage and cost of repair make restoration from public funds uneconomic. In early 2013 the eastern side of
	CONDITION: Ver	Very bad	the structure collapsed following cold weather conditions, and in February 2014, further main supports on the eastern
2	OCCUPANCY:	N/A side	side were washed away, splitting the former pavilion into
	PRIORITY CATEGORY:	A (A)	two sections.
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1381655	Contact: Clare Charlesworth 0207 973 3640

© Historic England



© Historic England

© Historic England



SITE NAME:	Saltdean Lido, Marine Drive, Saltdean	Lido of 1938, by RWH Jones in Moderne style. The building is currently undergoing an extensive programme of	
	DESIGNATION:	Listed Building grade II*	concrete repairs and general upgrading. The Saltdean Community Interest Company is leading the major repair
	CONDITION:	Fair	scheme having secured substantial funding from the National Lottery Heritage Fund, Coastal Communities,
	OCCUPANCY:	Part occupied/part in use	Social Investment in Business funds, Brighton and Hove
	PRIORITY CATEGORY:	F (F)	City Council, and Historic England.
	OWNER TYPE:	Community interest group	
	LIST ENTRY NUMBER:	1380905	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	Hippodrome, 52-58, Middle Street, Brighton	Originally an ice rink by Kerslake dating from 1896. Converted to a circus theatre in 1901 to designs by the
	DESIGNATION:	Listed Building grade II*, CA	leading theatre architect Frank Matcham and then to a variety theatre in 1902 by Bertie Crewe. Currently vacant
	CONDITION:	Fair	but a new private owner has acquired the building and

ıt but a new private owner has acquired the building and completed much needed urgent repair works including providing a new roof to arrest water ingress. Listed Building Consent and Planning Applications are under consideration by the Local Authority for use of the Hippodrome as a multi-entertainment venue with apart-hotel units in the service yard.

Contact: Alma Howell 0207 9733 627

House built in 1765 and remodelled in 1786 by Robert Adam. Converted to an office, the building later became vacant. Consent granted in 2015 for change of use to single family dwelling has not been implemented. Some repairs and restoration work has been carried out including to lathe and plaster walls and ceilings. There have been more recent discussions about potential new uses for the building but these have not progressed.

© Historic England

Marlborough House, 54, Old SITE NAME: Steine, Brighton DESIGNATION: Listed Building grade I, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1380671 Contact: Alma Howell 0207 9733 627

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

A (A)

1381793

Vacant/not in use

Commercial company

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UÁ Unitary Authority World Heritage Site WHS

of

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BRIGHTON AND HOVE, CITY OF (UA)

	SITE NAME:	Church of St Patrick, Cambridge Road, Hove	Large C19 church constructed of ragstone. Problems with high level roofing and gutters, as well as stonework need
	DESIGNATION:	Listed Place of Worship grade II, CA	addressing. The future use of this church is uncertain and it is now closed. In use by the YMCA as a night shelter for the homeless.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1280980	Contact: David John 0207 973 3638

© Historic England



	SITE NAME:	Church of All Saints, Eaton Road, Hove	Large late Victorian sandstone ashlar church with a rich cathedral like interior in the suburbs of Hove near to the
	DESIGNATION:	Listed Place of Worship grade I, CA	seafront. Five bay nave, north and south aisles, chancel, chapel with apse and incomplete tower. Repairs to leaking roof over north aisle and organ carried out in summer
	CONDITION:	Poor	2013. Further works, undertaken in 2019-20 included emergency stone repairs to the window mullions and
	PRIORITY CATEGORY:	A (A)	significant repairs to the upper levels of the north-east and
	OWNER TYPE:	Religious organisation	south-east towers. More repairs are still needed.
	LIST ENTRY NUMBER:	1187592	Contact: David John 0207 973 3638

© Historic England



© Historic England



	SITE NAME:	Church of St Mary the Virgin, St James's Street, Kemp Town, Brighton	Late Victorian red brick building by William Emerson. Comprises a chancel with 5-sided apse, two vestries, transepts and four bay nave with north and south aisles and
1	DESIGNATION:	Listed Place of Worship grade II*, CA	incomplete tower. Major repairs to the North elevation (2016-17) and West front (2018-19) were funded by the National Lottery Heritage Fund. Work undertaken in
1	CONDITION:	Very bad	2019-21 included emergency repair of the south transept, repairs to brickwork, masonry, roofs, rainwater goods to
1.1.1.2	PRIORITY CATEGORY:	A (A)	the south aisle, funded by Covid-19 Emergency Heritage at
-	OWNER TYPE:	Religious organisation	Risk Grants. Outstanding repairs remain to be done to the liturgical east end and other areas.
	LIST ENTRY NUMBER:	1380884	Contact: David John 0207 973 3638
	SITE NAME:		
	SHE MARE.	Church of St Peter, St Peters Place, Brighton	Designed by Sir Charles Barry and built between 1824 and 1828. A National Lottery Heritage Fund and Historic
1	DESIGNATION:	,	1828. A National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were
4		Place, Brighton Listed Place of Worship grade	1828. A National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were completed. Further phases of repair to the tower have also been completed with funding from the National Lottery
	DESIGNATION:	Place, Brighton Listed Place of Worship grade II*, CA	1828. A National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were completed. Further phases of repair to the tower have also been completed with funding from the National Lottery Heritage Fund Grants for Places of Worship. One of the intermediate pinnacles is in a precarious condition and has
	DESIGNATION: CONDITION:	Place, Brighton Listed Place of Worship grade II*, CA Poor	1828. A National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship grant for repairs to the lower tower roof, nave and aisle roofs were completed. Further phases of repair to the tower have also been completed with funding from the National Lottery Heritage Fund Grants for Places of Worship. One of the

© Historic England



SITE NAME:	Church of St Paul, West Street, Brighton	A church designed by Richard Cromwell Carpenter in 1846-8 and built by George Cheeseman. The tower and
DESIGNATION:	Listed Place of Worship grade II*	spire are by Richard Herbert Carpenter. The narthex, Fishermen's Institute (west end) and covered way are by
CONDITION:	Poor	George Frederick Bodley. Large fragments of stone and flint have fallen from the tower, which is adjacent to a busy
PRIORITY CATEGORY:	A (A)	shopping street. Temporary protection has been provided.
OWNER TYPE:	Religious organisation	Some other works have been carried out to other parts of the building.
LIST ENTRY NUMBER:	1381098	Contact: David John 0207 973 3638

© Historic England

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: David John 0207 973 3638

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BRIGHTON AND HOVE, CITY OF (UA) / SOUTH DOWNS (NP)

		( )	
MALO XULLA	SITE NAME:	The Royal Pavilion Gardens, Brighton	John Nash designed picturesque layout of serpentine walks and drives, flowery shrubberies and trees within open
	DESIGNATION:	Registered Park and Garden grade II, 3 LBs, CA	lawns of the private seaside royal estate. Restored in 1990 high levels of visitor use, event pressures, crime and anti- social behaviour affect the garden condition and safety.
and and a second	CONDITION:	Extensive significant problems	Later insertions and temporary uses conceal the garden's overall composition and identity. As highly socially valued
	VULNERABILITY:	High	urban green space but with little chance to understand its
	TREND:	Stable	historical values an enhanced conservation planning process is being consulted upon to inform a National
	NEW ENTRY?:	No	Lottery Heritage Fund bid.
© Historic England	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1000205	Contact: Kay Richardson 0207 973 3647

SITE NAME:	Benfield Barn		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION: Very bad		TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	East Cliff		
DESIGNATION:	Conservation Area, 189 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Old Town		
DESIGNATION:     Conservation Area, 114 LBs       CONDITION:     Very bad		NEW ENTRY?:	No
		TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Sackville Gardens		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152
SITE NAME:	Valley Gardens		
DESIGNATION:	Conservation Area, 139 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Tim Jefferies (LPA) 01273 293152

#### SOUTH DOWNS (NP)

SITE NAME:	Stanmer, Brighton and Hove, City of (UA), Brighton and Hove, City of (UA)		
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Planning Performance and Technical Team (LPA) 01730 814810

#### PRIORITY CATEGORIES

# А

- В
- C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but F Under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial use use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA)

LIST ENTRY NUMBER:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

#### **BUCKINGHAMSHIRE (UA)**



)			
SITE NAME:	Walls of moated site at Grove Farm, Ashley Green	Remains moated s for many serious s England t of the wo not accep updated owner.	
DESIGNATION:	Scheduled Monument, 3 LBs		
CONDITION:	Very bad		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Private		

1006946

of probable C15 walls to a strongly defended site. Walls have been overgrown with vegetation years but some have been cleared to reveal structural issues. A grant was offered by Historic to the owners to understand the extent and cost orks needed to conserve the walls. The grant was epted. The scheduling description for the site was in 2017. Further proposals are awaited from the

also having a door with rectangular barred fanlight. Red and

vitreous brick, old tile roof with two queen strut trusses, one altered. Contains about 350 nesting boxes with

rectangular openings and continuous brick ledges below.

Dovecote at risk due to structural cracking, water ingress through the roof and proximity to the moat. A project

needs to be initiated to address these issues.

Contact: Rachel James 0207 973 3153

Contact: David John 0207 973 3638

© Historic England

© Historic Eng

	SITE NAME:	Barn at New Manor Farm, Broughton Lane, Broughton Hamlet	Five bay aisled barn, late C12 and later. Roof of early C18 queen posts hipped to the west end and half hipped to east. Barn clad in weatherboarding with a gabled C19 cart
	DESIGNATION:	Listed Building grade II*	entrance to the centre of the north elevation. A historic building analysis has been carried out with Historic England
<u>k</u> —	CONDITION:	Fair	grant aid. Timber structure now supported by full internal birdcage scaffold and robust weatherproof roofing erected
	OCCUPANCY:	Vacant/not in use	early 2019. A longer term conservation plan is required as
	PRIORITY CATEGORY:	C (C)	part of any wider site development.
	OWNER TYPE:	Private, multiple owners	
ngland	LIST ENTRY NUMBER:	1310584	Contact: Rachel James 0207 973 3153
	SITE NAME:	Barn and fishpond and moated site with dovecote at Church Farm, Edlesborough	Barn and fishpond and moated site with dovecote at Church Farm. Dovecote mid-C18, a small rectangular building, each gable with four entrance holes, the east gable

© Historic England



SITE NAME:	Lodging Range/ "courthouse" rear of the George Public House, High Street, Great Missenden	C15 timber framed range, probably built as a court house. Structural problems at one end which is propped with scaffolding to prevent collapse. The building and associated pub are within private ownership with no known plans for
DESIGNATION:	Listed Building grade II*, CA	repair and reuse.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1124795	Contact: Andy Scott 02079733749

Scheduled Monument, 2 LBs


Vacant/not in use

Poor

A (A)

Private

1006955



#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS
---------------

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site ŴĤS





#### HE

HERITAGE AT RISK 2023 / LONDO	on and south east	/ BUCKINGHAMSHIRE (UA)	
y y	SITE NAME:	Mentmore Towers, Mentmore	Country house built 1852-4 by Sir Joseph Paxton and GH
	DESIGNATION:	Listed Building grade I, RPG grade II*, CA	Stokes for Baron Mayer Amschel de Rothschild. An application for Listed Building Consent and Planning Permission for external and internal alterations including
	CONDITION:	Poor	repairs was granted in 2014. The programme of repairs identified within the consents has not been undertaken and
	OCCUPANCY:	Vacant/not in use	there is a longstanding lack of regular maintenance. The
The second second	PRIORITY CATEGORY:	A (A)	service wing roof is in very poor condition and the deterioration of the main house is accelerating with areas
The face of the set more support internet of inspired toplard	OWNER TYPE:	Commercial company	of water ingress into the main hall and adjacent reception rooms.
Mr George Harper. Image supplied ourtesy of Images of England	LIST ENTRY NUMBER:	1117863	Contact: Rachel James 0207 973 3153
	SITE NAME:	The East Boycott Pavilion, Stowe Landscape Garden, Stowe	One of a pair of large stone pavilions, circa 1728, by James Gibbs, altered by Borra in 1754 to change the steep pyramidal roofs to domes with cupolas. It now
	DESIGNATION:	Listed Building grade I, RPG grade I, CA	incorporates domestic accommodation but was previously an open-sided belvedere. With its western twin, these pavilions straddle the Oxford Avenue, at the south west of
	CONDITION:	Poor	The Course, which is the main approach to the house. Domed roof replacement needed and cupola
	OCCUPANCY:	Part occupied/part in use	reinstatement. The National Trust plan major repairs,
	PRIORITY CATEGORY:	C (C)	removal of 1950s interiors and conservation of original interior space.
Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1289656	Contact: Rachel James 0207 973 3153
- mile	SITE NAME:	The Palladian Bridge, Stowe Landscape Garden, Stowe	Covered bridge built in 1738; attributed to James Gibbs, situated in the south east corner of the pleasure grounds.
Section 1	DESIGNATION:	Listed Building grade I, RPG grade I, CA	The bridge is viewed from the west across the Octagon Lake and from the north west and north across Hawkwell Fields. Steady decay of the roof covering, ceiling plaster and
	CONDITION:	Very bad	masonry. Holding repairs have been carried out, full conservation and repair is planned.
	OCCUPANCY:	N/A	conscivation and repair is planned.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Charity (heritage)	
∋ Historic England Archive	LIST ENTRY NUMBER:	1289750	Contact: Rachel James 0207 973 3153
1 Mar	SITE NAME:	Church of St Martin, Dunton	Church, CI2 nave with south wall rebuilt late CI8, CI3
in the	DESIGNATION:	Listed Place of Worship grade II*	chancel. Cl5 west tower, all much restored late C18. Nave and tower are of large stone blocks, squared and coursed
	CONDITION:	Poor	with brick repairs and dressings. Chancel is rendered. Slate

© Historic England

© col

. © |

と言

©

DESIGNATION:	Listed Place of Worship grade II*	chancel. Cl5 west tower, all much restored late C18. Nave and tower are of large stone blocks, squared and coursed
CONDITION:	Poor	with brick repairs and dressings. Chancel is rendered. Slate roof to nave, tiled roof to chancel. Tower of two stages
PRIORITY CATEGORY:	C (A)	has clasping buttresses, brick parapet and pointed single
OWNER TYPE:	Religious organisation	openings to bell chamber. There is serious cracking to north and south walls of the medieval chancel which is
LIST ENTRY NUMBER:	1211972	being monitored. Gutters have been repaired and improvements made to the underground drainage.
		Contact: Rachel James 0207 973 3153

Baptist chapel dated 1809. Square, two-storey building of SITE NAME: Haddenham Baptist Church, rendered witchert. Backlog of maintenance issues, including Stockwell, Haddenham failing slate roof coverings with dry rot to roof structure, Listed Place of Worship grade II, poor below ground drainage and widespread cracking to the render. Failure of render to the south west corner is of DESIGNATION: CA particular concern. Fundraising and grant applications are CONDITION: Poor underway. PRIORITY CATEGORY: B (New entry) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1159647 Contact: Rachel James 0207 973 3153

© Historic England

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA)

	SITE NAME:	Church of All Saints, Church End, Hillesden	Church with mid-C15 west tower of rubble stone. Remainder rebuilt after 1493 in ashlar, restored 1874-5 by
	DESIGNATION:	Listed Place of Worship grade I, CA	Sir George Gilbert Scott and again in 1960. The high level stonework was in very bad condition which put the church on the Heritage at Risk Register. Some repairs have been
	CONDITION:	Poor	carried out under the National Lottery Heritage Fund Grants for Places of Worship scheme but further repairs
	PRIORITY CATEGORY:	C (C)	the church are required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1288641	Contact: Rachel James 0207 973 3153
nd			

© Historic England



3	SITE NAME:	Church of All Saints, The Green, Hulcott	Church of C14 and C16, restored. Rubble limestone with tiled roof, C16 wooden bellcote with boarded sides and
	DESIGNATION:	Listed Place of Worship grade II*, CA	shingled spire. Serious structural problems in masonry. Church in use for special services. The most urgent of the repairs have been carried out with the benefit of the
	CONDITION:	Very bad	Covid-19 Emergency Heritage at Risk Response Scheme. Ongoing monitoring and recording of movement should
	PRIORITY CATEGORY:	A (A)	continue and further repairs are required.
	OWNER TYPE:	Religious organisation	
5	LIST ENTRY NUMBER:	1281503	Contact: Rachel James 0207 973 3153

© Historic England



X	SITE NAME:	Church of St Mary the Virgin, Church Lane, Ludgershall	Largely C14 church with C19 restorations. The nave, porch and north and south aisles were re-roofed, and the
DESIGNATION:	DESIGNATION:	Listed Place of Worship grade I, CA	decaying roof structure repaired. Repair work to the to roof, tower stonework, repointing, rainwater goods ar drainage also now completed. Both phases were supported by the National Lottery Heritage Fund and Historic England Repair Grants for Places of Worship
	CONDITION: PRIORITY CATEGORY:	Poor	
		F (F)	scheme. The timber belfry structure has been repaired. A
	OWNER TYPE:	Religious organisation	National Lottery Heritage Fund Grants for Places of Worship grant application was unsuccessful, but internal
2	LIST ENTRY NUMBER:	1124276	repairs to damaged plasterwork need to be addressed.
			Contact: Pachal Jamas 0207 972 2152

© Historic England



		Contact: Rachel James 0207 973 3153
SITE NAME:	Church of All Saints, Church Street, Wing	aisle, chancel and crypt surviving from this period. The west tower, clerestory and south porch are from the C The church was restored in C19 and early C20. Constructed of coursed limestone and greensand rubbl with dressed stone parapets. At risk due to the deteriorating stone of the tower. Works were carried in 2021 with the benefit of the Covid-19 Emergency Heritage at Risk Response fund to inform a repair and
DESIGNATION:	Listed Place of Worship grade I, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (New entry)	in 2021 with the benefit of the Covid-19 Emergency
OWNER TYPE:	Religious organisation	Heritage at Risk Response fund to inform a repair and conservation strategy that does not rely on extensive
LIST ENTRY NUMBER:	1320141	masonry renewal. A full programme of repair is required.
		Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME: Desborough Castle DESIGNATION Scheduled Monument LIST ENTRY NUMBER: 1020863 Generally unsatisfactory with major localised CONDITION TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY? Vandalism No OWNER TYPE: CONTACT: Alison McQuaid 0207 973 3646 Local authority Bell barrow 260m WNW of Slough Glebe Farm, part of the Saunderton Lee barrow cemetery, Bledlow-cum-SITE NAME: Saunderton LIST ENTRY NUMBER: DESIGNATION 1013953 Scheduled Monument CONDITION: TREND: Extensive significant problems Declining PRINCIPAL VULNERABILITY: NEW ENTRY ?: Arable ploughing No

# PRIORITY CATEGORIES

OWNER TYPE:

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.

С Slow decay; no solution agreed. Slow decay; solution agreed but F not yet implemented.

Commercial company

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

CONTACT:

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

Alison McQuaid 0207 973 3646

Conservation Area Listed Building CA

LB LPA

Local Planning Authority National Park NP

- RPG
- Registered Park and Garden Scheduled Monument SM

UA WHS

Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / BUCKINGHAMSHIRE (UA)

SITE NAME:	Bowl barrow 140m WNW of Slough Glebe Farn Bledlow-cum-Saunderton	n, part of the Saunder	ton Lee round barrow cemetery,
DESIGNATION:	Scheduled Monument	1013954	
CONDITION:	Extensive significant problems	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow at Molin's Works, part of the Saun Saunderton	derton Lee round bar	row cemetery, Bledlow-cum-
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Permitted development	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows 450m north west of Slough 0 Bledlow-cum-Saunderton	Glebe Farm, part of th	ne Saunderton Lee barrow cemetery
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013952
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	St Rumbold's Well, Buckingham		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 101720		1017204
CONDITION:	Extensive significant problems TREND: Declining		Declining
PRINCIPAL VULNERABILITY:	CIPAL VULNERABILITY: Natural erosion - localised/limited NEW ENTRY?: Y		Yes
OWNER TYPE: Private CONT		CONTACT:	David Wilkinson 0207 973 3644
SITE NAME:	Dam walls; part of Motte and bailey castle, moat Church, Great and Little Kimble cum Marsh	ed site and Roman vil	la immediately east of All Saint's
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1018007
CONDITION:	Generally unsatisfactory with major localised		Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa north of Yewden Lodge, Hambleden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014606
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems		
PRINCIPAL VULNERABILITY:	TY: Arable ploughing NEW ENTRY?: No		
OWNER TYPE: Private CONTACT: Alison McQuaid 0207 973 364			Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERIT

Declining

1000319

Mixed, multiple owners

No

TREND:

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

HERITAGE AT RISK 2023 / LONDO	on and south east	/ BUCKINGHAMSHIRE (UA) / EASTBOURN	E
	SITE NAME:	Halton House, Aston Clinton / Halton	Another of the original seven Rothschild country houses in the Aylesbury Vale with late C19 formal gardens and park
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs, part in CA	with woodland rides. Sold to the Royal Air Force in 1918 the estate is allocated for residential development in the Local Plan. Bisected by the Grand Union Canal much of the
	CONDITION:	Extensive significant problems	open parkland was fragmented and lost to development of the camp with the historic fabric of park and garden
1 /	VULNERABILITY:	High	features in poor condition. The overlooking designed
and the state	TREND:	Stable	woodland survives managed by Forestry England. Discussions regarding masterplan development have been
	NEW ENTRY?:	No	set out by Aylesbury Vale District Council.
© Historic England	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000601	Contact: Kay Richardson 0207 973 3647
	SITE NAME:	Mentmore Towers, Mentmore / Cheddington	Sir Joseph Paxton designed this largest of the Rothschild family houses in a prominent position in the Vale of
	DESIGNATION:	Registered Park and Garden grade II*, 10 LBs, 2 CAs	Aylesbury, with formal gardens and park to complement it and a contemporary Arts and Crafts estate village. Sold in 2000, permission was sought to convert the house into a
	CONDITION:	Generally satisfactory but with significant localised problems	hotel and conference centre. With the estate ownership fragmented, much of the park converted to golf, and new development proposals a Landscape & Conservation Area
	VULNERABILITY:	High	Appraisal funded by Historic England and completed in

- I

© Historic	England
------------	---------

EAST SUSSEX	

# EASTBOURNE

	SITE NAME:	Langney Priory, Langney Rise	The oldest portion of this house is the chapel, refectory and dormitory built by the Cluniac's before 1121 as part of
	DESIGNATION:	Listed Building grade II*	the Grange of St Pancras Priory at Lewes. There are later
	CONDITION:	Poor	additions of various dates and materials. It is now in use as a house. There is damage to the roof caused by storms and
	OCCUPANCY:	Part occupied/part in use	water penetration. There is also structural movement.
	PRIORITY CATEGORY:	C (C)	
La Contro Charter 200	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1043639	Contact: David John 0207 973 3638

© Historic England



© Historic England Archive

SITE NAME:	Eastbourne Redoubt, Eastbourne	A redoubt built as part of the Martello system, 1806. Main parts are in use as a museum. The aquarium building, which
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	occupies casemates and the mast on the south west side, is in very poor condition. The surviving caponiers suffer from water ingress. Moat walls are decaying. A Conservation
CONDITION:	Poor	Plan has been produced and proposals are being developed.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1017358 and 1043662	Contact: Rebecca Lambert 0207 973 3630

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

2020 assesses the significance, fabric, character and setting

of Mentmore to inform decisions.

Contact: Kay Richardson 0207 973 3647

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / EASTBOURNE / HASTINGS

and the section
Salaha Pering and
Maria All
(1) (1) (1) (1)
and the second
The second se
And the second se

© Historic England

© Historic England

SITE NAME:	Martello Tower No. 66	Martello tower, 1806. On the beach near the harbour
LIST ENTRY NOMBER:	1017355 and 1043661	Contact: Rebecca Lambert 0207 973 3630
LIST ENTRY NUMBER:		Compared Balances Lowel and 0207 072 2/20
OWNER TYPE:	Commercial company	
PRIORITY CATEGORY:	C (C)	
OCCUPANCY:	Vacant/not in use	
CONDITION:	Poor	the owner to find a sustainable conservation solution for the Martello.
DESIGNATION:	Scheduled Monument and Listed Building grade II	and historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with
SITE NAME:	Martello Tower No. 64, Eastbourne	Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological



d	SITE NAME:	Martello Tower No. 66, Langney Point, Eastbourne	Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical
	DESIGNATION:	Scheduled Monument and Listed Building grade II	significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with the owner
	CONDITION:	Fair	to find a sustainable conservation solution for the Martello.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017356 and 1043660	Contact: Rebecca Lambert 0207 973 3630

	SITE NAME:	Eastbourne Pier, Grand Parade	The pier is 1,000ft long and 52ft wide on a substructure of
	DESIGNATION:	Listed Building grade II*, CA	iron screw piles, designed by Eugenius Birch and completed in 1872. The seaward Pavilion Theatre with 'camera
Hillmonia A	CONDITION:	Very bad	obscura' and two games pavilions were designed and built in 1901 by Noel Ridley. The central windscreens were erected 1902-03 and the music pavilion added in 1925, designed by PD Stoneham. Later additions include the kiosks in 1971 and an entrance building in 1991. In July 201
	OCCUPANCY:	Part occupied/part in use	
and a still	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	the landward arcade building was destroyed by fire. Historic England, the owners and Eastbourne Borough
	LIST ENTRY NUMBER:	353  6	Council have discussed how to reinstate.
istoric England			Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Shinewater Bronze Age settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1400780
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

#### HASTINGS

SI
D
C
0
PF
0

SITE NAME:	Chapel to the Former Convent of the Holy Child Jesus, Magdalen Road, St Leonards	Former convent chapel, partly designed by Augustus Welby Pugin and completed by his son Edward Welby Pugin. The chapel has a good High Victorian Gothic interior
DESIGNATION:	Listed Building grade II*, CA	and is a rare example of a Roman Catholic Chapel retaining the nuns' choir. Some of the more urgent repairs to the
CONDITION:	Poor	chapel have started to be addressed, but more work is still required, externally and internally.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1043478	Contact: David John 0207 973 3638

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HASTINGS

SITE NAME:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Very bad

1192060

Charity (non-heritage)

N/A

B (B)

	SITE NAME:	Church of All Souls, Athelstan Road, Hastings	Former church built 1889. Designed by Sir Arthur Blomfield. Vacant since February 2008 and now closed for
	DESIGNATION:	Listed Building grade II*	worship. Its richly decorated interiors mean that it was included on the Victorian Society's top ten list of
	CONDITION:	Poor	endangered buildings in 2014. A new owner intends to use the building as a studio and for the display of art works with
	OCCUPANCY:	Vacant/not in use	some change to the interior fittings. Some holding repa
	PRIORITY CATEGORY:	A (A)	are proposed for the south east chapel roof.
	OWNER TYPE:	Private	
n, Hastings Borough	LIST ENTRY NUMBER:	1293681	Contact: David John 0207 973 3638

Pelham Arcade, 1-12 and 12A,

© Judith Warren, Council



SITE NAME:	Remains of Manor House, Ore Place, Ore	Ruins of late medieval manor house surrounded by new housing development, close to Old St Helens Church. The	
DESIGNATION:	Scheduled Monument, CA ruins are being damaged by heavy vegetation growth		
CONDITION:	Very bad		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Local authority		
LIST ENTRY NUMBER:	1002271	Contact: David John 0207 973 3638	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Place, OreDESIGNATION:Scheduled Monument, CACONDITION:Very badOCCUPANCY:N/APRIORITY CATEGORY:A (A)OWNER TYPE:Local authority	

© Historic England



© Historic England

© Historic England



Pelham Place, Hastings part of the Pelham scheme by Joseph Kay in 1823-5. Poor drainage from the carriage drive above the Arcade and DESIGNATION: Listed Building grade II\*, CA structural failures in its formerly glazed lantern have resulted in problems of damp, particularly to the rear. CONDITION: Poor Investigation work to inform the road repairs, funded OCCUPANCY: Part occupied/part in use jointly by Historic England and Hastings Borough Council, were completed in 2021. Historic England and Hastings PRIORITY CATEGORY: D (D) Borough Council continue to explore funding opportunities to support the package of repairs to the road and the OWNER TYPE: Local authority, multiple owners arcade of shops below. LIST ENTRY NUMBER: 1043389 Contact: Liz Pollard 0207 973 3650 Statue, 1711-12 in grounds of former convent (now sold SITE NAME: Statue of Queen Anne south separately). Longstanding lack of regular maintenance east of Holmhurst St Mary's meant it was deteriorating rapidly through rainwater from School, The Ridge, Baldslow overhanging trees and saline rain from the sea. It has also DESIGNATION: Listed Building grade II\* been subject to heritage crime but has now been made

secure. An application for residential development which would also secure the repair of the statue and improve its setting has been granted by the Local Planning Authority. The developer has committed to carrying out repairs through a S106 Agreement.

Semi-subterranean arcade of shops, developed as the first

Contact: Alma Howell 0207 9733 627

ian Gilbert Pantiled low altar against h passage th. Simplified ated by fine t of steps nouldings dying ut as there are : needs

Contact: David John 0207 973 3638

	SITE NAME:	Church of St Leonard, Hastings	Church built in 1953-61 by Sir Giles and Adria
1	DESIGNATION: CONDITION: PRIORITY CATEGORY:	Listed Place of Worship grade II, 2 CAs	Scott. Buff brick with cream stone dressings. F pitched roof to eaves. Rectangular plan with a east wall and choir stalls in chancel. Nave with
		Poor	aisles. Western tower, with entrance beneath
		C (C)	modernistic Gothic manner. Exterior dominat blocky Gothic west tower reached by a flight
	OWNER TYPE:	Religious organisation which has parabolic shape with into the jambs. Congregation h	which has parabolic shape with late Gothic me into the jambs. Congregation have moved out
	LIST ENTRY NUMBER:	1376621	concerns about the surrounding low cliff that stabilising. Church now closed.
100			stabilising. Church now closed.

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

	SITE NAME:	Former United Reformed Church, Cambridge Road, Hastings	Built as a congregational church in 1885. Rainwater system very poor and needs replacing with more outlets, wider rainwater goods, more efficient drops. Movement cracks
	DESIGNATION:	Listed Place of Worship grade II, CA	are allowing rain penetration. Discussions are taking place with the new owners, a new religious group, who are carrying out emergency works and considering funding
	CONDITION:	Poor	options for full repairs.
	PRIORITY CATEGORY:	A (A)	
12	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1393646	Contact: David John 0207 973 3638
And Minere	SITE NAME:	Christ Church, London Road, St Leonards on Sea, Hastings	Late Victorian church designed by Blomfield with later additions in prominent location. Suffering from severe
	DESIGNATION:	Listed Place of Worship grade II*, CA	erosion due to vulnerable stonework and proximity to coast. Also rainwater goods in need of overhauling, window ferramenta deteriorating and general deterioration
	CONDITION:	Poor	of fabric. Repairs were carried out in 2021 to the tower and spire with funding from the Heritage Stimulus Fund.
A COMPANY AND A COMPANY	PRIORITY CATEGORY:	D (D)	and spire with funding if off the field age sufficies fund.
and and the	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1286965	Contact: David John 0207 973 3638
© Thames Valley Drones			
	SITE NAME:	Church of St Thomas of Canterbury and the English Martyrs, Magdalen Road, Hastings	Built in 1889 by Charles Alban Buckler with an interior scheme by Nathaniel Westlake, 1908 and 1911 which is deteriorating due to water penetration caused by inappropriate external pointing, poor rainwater disposal
	DESIGNATION:	Listed Place of Worship grade II, CA	and the roof requiring repairs. Some roof repairs have recently (2023) been carried out.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Religious organisation	
C	LIST ENTRY NUMBER:	1391831	Contact: David John 0207 973 3638

	SITE NAME:	Church of the Holy Trinity, Robertson Street, Hastings	Victorian church designed by SS Teulon with stained glass windows by Clayton and Bell and Kempe. The stonework
	DESIGNATION:	Listed Place of Worship grade II*, CA	is displaying serious effects of erosion, particularly on the south, east and west elevations. The mullions and windo tracery are particularly bad, allowing water to penetrate into the building. There is a cost plan for implementing repairs.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1043423	Contact: David John 0207 973 3638
and			

© Historic England



			,
	SITE NAME:	Church of St Mary Magdalen, St Margaret's Road, St Leonards	Decorated-style church by Frederick Marrable, 1852, in a prominent position in St Leonards. It has a four-stage south
	DESIGNATION:	Listed Place of Worship grade II, CA	west tower built in 1872. Facing stonework and roofs in a fair condition but the tracery stonework is in a very poor condition. Historic England has given advice on repair and
	CONDITION:	Poor	funding options. Repairs to the south aisle roof and drainage have recently been carried out.
	PRIORITY CATEGORY:	A (A)	dramage nave recently been carried out.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1043430	Contact: David John 0207 973 3638

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HASTINGS / LEWES / ROTHER

SITE NAME:	Hastings Town Centre		
DESIGNATION:	Conservation Area, 24 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jane Stephen (LPA) 01424 783273

#### LEWES

No. of Concession, Name

©

©

1 set v

THE REAL

©

	SITE NAME:	Newhaven Fort; Caponier, Fort Road, Newhaven	Caponier of Newhaven Fort. Victorian caponier is in very poor condition in places. Lunette battery was repaired with
	DESIGNATION:	Scheduled Monument	a Historic England grant by Lewes District Council in 2009. In 2017 National Lottery Heritage Funding was accepted to
	CONDITION:	Poor	develop a project for further repairs and interpretation at the fort. An application for the repairs fund is expected to
	OCCUPANCY:	Vacant/not in use	be made.
and the second se	PRIORITY CATEGORY:	C (C)	
A SHORE SHOW	OWNER TYPE:	Local authority	
D Historic England	LIST ENTRY NUMBER:	1002242	Contact: David John 0207 973 3638

## ROTHER

NOT TER			
	SITE NAME:	Martello Tower No. 28, Rye Harbour, Icklesham	Martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeological and
	DESIGNATION:	Scheduled Monument and Listed Building grade II	historical significance will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential use. Historic England is working with
	CONDITION:	Very bad	the owner of the site to try and achieve a sustainable solution to the long-term conservation of the Martello.
© Historic England	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017353 and 1234372	Contact: Rebecca Lambert 0207 973 3630

© Historic England	SITE NAME:	Ruins of the former friary church [Grey Friars (Winchelsea Priory)], Friars Road, Winchelsea, Icklesham	Extensive ruins to full wall height of a monastic church c1310-20, now in the grounds of a C19 mansion. Ruins have significant plant growth with decay to stonework. In 2016 a quinquennial survey was carried out and
	DESIGNATION:	Scheduled Monument and Listed Building grade I, CA	recommended various conservation works. At that time discussions took place with the owners regarding a programme of conservation works and maintenance
	CONDITION:	Poor	however nothing has progressed. Since, damage from animal burrowing has occured which is causing significa damage to the buried remains, requiring immediate
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	attention to control.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1002301 and 1234450	Contact: Rebecca Lambert 0207 973 3630



	LIST ENTRY NUMBER:	1002301 and 1234450	Contact: Rebecca Lambert 0207 973 3630
CONDITION OCCUPANC PRIORITY CA	SITE NAME:	Austin Friars Chapel, Conduit Hill, Rye	Remains of an Augustinian friary chapel dating from the 1380s. The chapel building underwent alteration in the
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	early C20. The window tracery is suffering from decay and the roof was leaking. Repairs to the roof and damp proofing were completed with funding from Historic
	CONDITION:	Poor	England.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1002296 and 1352789	Contact: David John 0207 973 3638

© Historic England Archive

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ROTHER / SOUTH DOWNS (NP)

1	
A Local	a state
	100
	181 M

SITE NAME:	Martello Tower No. 30, Winchelsea Road, Rye	Martello tower built 1806. The moat and glacis on the east side lost. Unconnected with destruction of the moat and
DESIGNATION:	Scheduled Monument and Listed Building grade II	glacis, a small housing development was built adjacent to the east. The preservation of archaeological and historical significance will be the main consideration in assessing the
CONDITION:	Poor	suitability of proposals to convert Martello towers for residential use.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1017354 and 1262420	Contact: David John 0207 973 3638

© Historic England




	SITE NAME:	Church of St Barnabas, Sea Road, Bexhill, Bexhill-on-Sea	Late C19 and early C20 church in flint and red brick. Urgent repairs are required to re-cover the south aisle roof
	DESIGNATION:	Listed Place of Worship grade II, CA	and the spire, including renewal of rainwater goods and repairs to stonework and window glass. The congregation was offered grant from the joint Historic England and
	CONDITION:	Poor	National Lottery Heritage Fund for Places of Worship scheme in March 2012. However, it was not possible to
	PRIORITY CATEGORY:	A (A)	proceed with the work. Discussions have taken place as to
-	OWNER TYPE:	Religious organisation	how a repair project might be taken forward, with other plans, which are now being pursued.
-	LIST ENTRY NUMBER:	1044250	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Romano-British iron working site in Beauport Park, Battle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002250
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

# SOUTH DOWNS (NP)

· · · ·			
A	SITE NAME:	Dovecote 160 metres north west of Coombe Place, Offham, Hamsey, Lewes	Early C19 dovecote within the grounds of Coombe Place. Ornate octagonal building of flint with dressings and quoins of red and grey brick. Water ingress and collapse of chalk
Historic England	DESIGNATION:	Scheduled Monument, LB grade II	and brick nesting boxes inside is the cause of risk. Discussions have taken place with the owners as to how a repair project might be completed.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1019248	Contact: David John 0207 973 3638



© Historic England

@⊦

Е

PRIORITY CATEGORIES А

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

	SITE NAME:	Church of St Michael and All Angels, Plumpton, Lewes	Small parish church with large square tower to the west. Dates to the C12 with a C13 chancel and contains rare
	DESIGNATION:	Listed Place of Worship grade I	surviving Norman wall paintings. The lack of an eaves gutter to the tower, combined with inappropriate cement
	CONDITION:	Poor	renders in several areas, and ground drainage, is causing internal damp and putting the wallpaintings at risk. A
	PRIORITY CATEGORY:	F (New entry)	programme of repairs was undertaken with a Listed Places
	OWNER TYPE:	Religious organisation	of Worship Roof Repair Fund grant, which was awarded in 2015.
	LIST ENTRY NUMBER:	1238266	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Anglo-Saxon cemetery 275m north of Comps Farm	n, Beddingham, Lew	ves
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021436
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
site name:	Round barrow south of Ditchling Beacon, Ditchling	g, Lewes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002254
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow forming part of a linear round barrow	v cemetery on Roo	kery Hill, Seaford, Lewes
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009953
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Hillfort and a bowl barrow on Seaford Head, Seafo	ord, Lewes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014523
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Two bowl barrows, the south easternmost pair of round barrow cemetery on Rookery Hill, Seaford,	a group of six bow Lewes	l barrows, forming part of a linear
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009951
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### SOUTH DOWNS (NP) / BRIGHTON AND HOVE, CITY OF (UA) / LEWES

	SITE NAME:	Stanmer Park, Ditchling / Falmer / Westmeston, Brighton and Hove, City of (UA), Lewes	Undulating C18 landscape park and downland agricultural estate on city fringe surrounding a country house and incorporating Stanmer village. Bought by the Council		
/ 是	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, 4 SMs, part in CA	(1947) for public amenity, the parkland fabric is highly fragmented by A27 with further housing development being constructed. Building upon successful improvements completed to the parkland core the 2023 City Downland		
RE PROS	CONDITION:	Generally satisfactory but with significant localised problems	Estate Plan envisions Stanmer as gateway to the South Downs within an ambitious carbon neutral target. Plannin of future woodland management and Highways England Designated Funds access improvements being undertake		
	VULNERABILITY:	Medium			
© Historic England Archive	TREND:	Improving			
	NEW ENTRY?:	No			
	OWNER TYPE:	Local authority, multiple owners			
	LIST ENTRY NUMBER:	1001447	Contact: Kay Richardson 0207 973 3647		

#### WEALDEN

	SITE NAME:	Cross-In-Hand Windmill, Mill Lane, Heathfield and Waldron	A remarkably complete post mill dating originally to the early 19th century. No longer in working order, with the
	DESIGNATION:	Listed Building grade II*	sails and tail removed. At risk due to deteriorating condition including internal and external timber work, and
	CONDITION:	Very bad	longstanding lack of regular maintenance. Condition survey and a comprehensive programme of repairs are needed
	OCCUPANCY:	Vacant/not in use	
STR	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1183064	Contact: Liz Pollard 0207 973 3650

© Historic England

© Historic England

SITE NAME:	Gibraltar Tower, Heathfield Park, Heathfield, Heathfield and Waldron	Ornamental tower within grade II registered Heathfield Park. Has been subject to repeated heritage crime leading to loss of windows, staircase and internal decorative
DESIGNATION:	Listed Building grade II*, RPG grade II	scheme. This, combined with deteriorating roof covering, means that the building is not wind or watertight and continues to decline. Heritage crime prevention measures
CONDITION:	Very bad	are in place. The Tower requires a full condition survey to understand the extent and costs of conservation work
OCCUPANCY:	Vacant/not in use	required. A temporary roof covering is needed as priority. Early stage discussions about a future use for the building
PRIORITY CATEGORY:	A (New entry)	Early stage discussions about a future use for the building are on-going.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1194199	Contact: Liz Pollard 0207 973 3650



© Historic England

	SITE NAME:	The Mint House, Village Street, Pevensey	C16 timber framed hall with one of the largest C16 kitchen ranges known to survive in East Sussex. Water penetration
OWNER TYPE:	DESIGNATION:	Listed Building grade II*, CA	is causing wet rot and deterioration of timber frame. Structural movement resulting in failure of first floor wall
	CONDITION:	Very bad	plate causing slumping of the jetty. Loss of plaster and wall paintings in some areas.Unstable chimney now removed
	OCCUPANCY:	Vacant/not in use	and funding sought for reinstatement. Further investigations
	PRIORITY CATEGORY:	A (A)	and a comprehensive programme of repairs are now urgently necessary. Friends of the Mint House continues to
	OWNER TYPE:	Private	explore means to purchase and repair the building, and develop community engagement.
	LIST ENTRY NUMBER:	1284471	Contact: Liz Pollard 0207 973 3650

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WEALDEN

	SITE NAME:	Polegate Windmill, Park Croft, Willingdon and Jevington	Four-storey, brick tower windmill dating to 1817 for milling oats. The original machinery was restored in 1967. At risk	
	DESIGNATION:	Listed Building grade II*	due to water ingress from the cap and tower walls causing concerning deterioration of the substantial timber beams	
	CONDITION:	Very bad	on all floors which support the mill stones and internal mechanism. As a result the beams are propped. Evidence	
	OCCUPANCY:	Part occupied/part in use	of rot throughout the tower. Gallery also requires repair	
	PRIORITY CATEGORY:	A (New entry)	and the ground floor external bitumen coating is contributing to damp conditions. A comprehensive	
	OWNER TYPE:	Charity (heritage)	condition survey is required and improved	
© Historic England		1043086	weathertightness is a priority. Contact: Liz Pollard 0207 973 3650	
	SITE NAME:	Church of All Saints, Waldron, Heathfield and Waldron	Church of C13 built of stone rubble with tiled roof. Consists of chancel, aisled nave, north porch and west	
	DESIGNATION:	Listed Place of Worship grade I, CA	tower with higher stairs turret. Tower in the Perpendicu style. South aisle dates from 1859-62. Urgent repairs to tower have been completed. The Quinquennial Inspectio	
	CONDITION:	Poor	carried out in 2019 identified significant on-going problems with old cement mortar repointing, eroded masonry and	
	PRIORITY CATEGORY:	C (C)	roof surfaces. The main issue is the south aisle roof which	
	OWNER TYPE:	Religious organisation	needs comprehensive repair.	
	LIST ENTRY NUMBER:	1284195	Contact: David John 0207 973 3638	
© Historic England				
	SITE NAME:	Church of St Andrew, The Tye, Alfriston, Wealden	CI4 church; cruciform in plan with a central tower and spire, known as the Cathedral of the Downs. Knapped flint	
	DESIGNATION:	Listed Place of Worship grade I, CA	walls and tiled roof. The spire has recently been repaired. However, the church walls are damp due to hard cementitious mortar trapping moisture. Some of the walls	
	CONDITION:	Poor	have now been repointed and re-plastered in lime which is helping them to dry out. The south transept requires	
	PRIORITY CATEGORY:	C (C)	similar repair work.	
	OWNER TYPE:	Religious organisation		
Carlos and the state	LIST ENTRY NUMBER:	1043353	Contact: David John 0207 973 3638	
© Historic England			·	
		Kidhara dan Davida Farmant David	C19 park with sumining early C19 features including a	

	SITE NAME:	Kidbrooke Park, Forest Row	C18 park with surviving early C19 features, including a
	DESIGNATION:	Registered Park and Garden grade II, 2 LBs	designed water system attributed to Repton and later gardens. Sold and broken up after WWII, the house became a Steiner Waldorf school which has its own unique
	CONDITION:	Generally satisfactory but with significant localised problems	significance. Edge development reduced the park, and ornamental features need repair and maintenance. New imaginative opportunities for embedding the landscape
	VULNERABILITY:	Medium	within pupils' curriculum, through the school's values, an Parkland Plan (part-funded by Natural England) are emerging along with developing sustainable school uses
	TREND:	Stable	
	NEW ENTRY?:	No	parkland buildings.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000305	Contact: Kay Richardson 0207 973 3647

#### EAST SUSSEX / KENT

© Historic England

#### WEALDEN / TUNBRIDGE WELLS

SITE NAME:	High Rocks Camp (see also Tunbridge Wells, Kent), Frant			
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1002280	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WEST BERKSHIRE (UA) / BASINGSTOKE AND DEANE / EAST HAMPSHIRE / EASTLEIGH

#### HAMPSHIRE

の言語

© Historic

#### WEST BERKSHIRE (UA) / BASINGSTOKE AND DEANE

e Ergland	SITE NAME:	Sandleford Priory, Greenham / Newtown	A mid-late C18 landscape park with waterbodies laid out to designs by Lancelot Brown, surrounding a Gothick
	DESIGNATION:	Registered Park and Garden grade II, 2 LBs	house remodelled by James Wyatt. Once straddling the A339 the estate was sold into divided ownership, the house, gardens and core of the park being used as a school.
	CONDITION:	Extensive significant problems	The northern park has been largely developed (housing, waste disposal) leaving the core compromised as a design
	VULNERABILITY:	High	fragment which in turn is under-resourced in its
	TREND:	Declining	management. The setting of the house and park and garden is extremely vulnerable to housing and business
	NEW ENTRY?:	No	development potential identified in the Local Plan.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000333	Contact: Kay Richardson 0207 973 3647

BASINGSTOKE AND DEANE				
	SITE NAME:	Barn at Manor Farm, Old Burghclere, Burghclere	Manorial barn, 1451, built for the Bishop of Winchester. Suffering from water ingress and failure of joints, the	
	DESIGNATION:	Listed Building grade I	building needs comprehensive repair. The owners have decided to undertake the repairs on a phased basis over	
	CONDITION:	Poor	several years. Works commenced in May 2017 to repair the 3 eastern bays of the barn. These works have been	
	OCCUPANCY:	N/A	successfully completed. The next phase of repair is now	
	PRIORITY CATEGORY:	F (D)	underway having started in February 2023 after a delay due to Covid. These repairs are supported by a Farming in	
	OWNER TYPE:	Commercial company	to Covid. These repairs are supported by a Farming in Protected Landscapes grant and should be completed in March 2024.	
© Historic England	LIST ENTRY NUMBER:	1157463	Contact: Marion Brinton 0207 973 3631	

#### EAST HAMPSHIRE

SITE NAME:	Walldown enclosures, Whitehill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017368
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

#### EASTLEIGH

SITE NAME:	Promontory defined by an Iron Age linear earthwork, St Andrew's Castle and additional remains on Hamble Common, Hamble-le-Rice		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1008695
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alex Bellisario 0207 973 3700

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
  - Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### FAREHAM

	SITE NAME:	Brick Kiln, Chimney, Drying Sheds, Boiler and Engine House at Bursledon Brickworks south Section, Coal Park Lane, Swanwick	Steam driven brickworks complex in use from C19 until 1970's with what appears to be the earliest surviving Staffordshire type continuous kiln. Now a museum. A failing asbestos roof over the significant brick kiln was replaced 2022-2023 through a Historic England Repair
	DESIGNATION:	Listed Building grade II*	grant. The brickworks complex remains at risk due to the vulnerability of the unsupported walls to roofless drying
	CONDITION:	Poor	sheds. National Lottery Heritage Fund have grant-aided a
	OCCUPANCY:	Part occupied/part in use	Development Phase for repairing and converting the drying sheds. An enabling development scheme should fund
© Historic England	PRIORITY CATEGORY:	C (C)	further repair works, to be completed 2024-2025.
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1233725	Contact: Elspeth Faulkner 07557 521610

Stren M	SITE NAME:	Fort Fareham, Newgate Lane, Fareham	Royal Commission fort built in 1861. The only one of three proposed 'Gosport Outer Line' forts built due to defence
-	DESIGNATION:	Scheduled Monument and Listed Building grade II, LB grade II	cuts. It was intended to be part of a further line of defence to the already completed 'Gosport Advanced Line' of Forts Elson, Brockhurst, Rowner, Grange and Gomer, built to
	CONDITION:	Poor	defend Portsmouth Harbour. Suffering from decay and heritage crime in parts. Interior of fort functioning as a
	OCCUPANCY:	Part occupied/part in use	business and industrial estate.
	PRIORITY CATEGORY:	A (A)	
All and a second second	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001856 and 1094240	Contact: Rachel James 0207 973 3153

© Historic England

## GOSPORT

© Historic England

	SITE NAME:	Gunboat Sheds and Workshops, Haslar Gunboat Yard	A row of ten gunboat sheds and three maintenance workshops, designed in 1856 by William Scamp of the
	DESIGNATION:	Listed Building grade I, CA	Admiralty Works Department as part of the Haslar Gunboat Yard for the housing and repair of British
	CONDITION:	Very bad	gunboats, and their successor craft, of the Royal Navy. The adjacent traverser system was used for their launch and
	OCCUPANCY:	Vacant/not in use	movement. The site ceased to be used in the mid-1970s
	PRIORITY CATEGORY:	C (C)	but remained in MOD ownership. Once vacant, its condition deteriorated, with only minimum maintenance
	OWNER TYPE:	Commercial company	undertaken. Historic England grant aided a feasibility study in 2019 to help find an appropriate new use for the site.
	LIST ENTRY NUMBER:	1431190	Contact: Rachel James 0207 973 3153



© Historic England

	SITE NAME:	Gunboat Yard Boundary Walls, Watchtowers and Gates, Haslar Gunboat Yard, Gosport	Mid C19 boundary w watchtowers, walkw laid in Flemish bond
	DESIGNATION:	Listed Building grade II*, part in CA	slate roofs to watch burrowing, defective pointing, missing win
	CONDITION:	Poor	growth. Contact w established who wi
	OCCUPANCY:	N/A	to develop heritage s
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	43  9	Contact: Rachel Jam

walls incorporating corner ways and gates. Mainly built of red brick with stone dressings and pyramidal towers. At risk due to animal e roofs, eroding brickwork and ndows and doors and vegetation th a local construction college has been I supervise brickwork repairs at the site skiİls.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / GOSPORT



Batteries No.1 and 2 were built in the Stokes Bay area of SITE NAME: No 2 Battery, Stokes Bay Road, Gosport, primarily to defend against a sea-borne attack, Gosport and are located at the north-west end of the Stokes Bay DESIGNATION: Listed Building grade II\* Lines. They were part of a system of ramparts, moats and batteries built in the 1860s. It has extensive problems of CONDITION: Poor damp penetration and condensation affecting the building OCCUPANCY: Part occupied/part in use fabric. The building is partly in use as a museum. The Trustees have secured funding including through Arts PRIORITY CATEGORY: D (C) Council England, Historic England and National Lottery Heritage Fund and they are developing a repair scheme OWNER TYPE: Local authority which will start in September 2023. LIST ENTRY NUMBER: 1276305 Contact: Rachel James 0207 973 3153

© Historic England

© Historic England

103	SITE NAME:	Former Guard House, Haslar Gunboat Yard, Haslar	Former Guard House to Gunboat Yard constructed in mid-19th century. Mainly built of red brick with limestone
	DESIGNATION:	Listed Building grade II*, CA	dressings beneath hipped slate roof. Vacant and at risk due to poor condition of roofs, rainwater disposal, leaning
-	CONDITION:	Very bad	chimney stack, windows, doors, floors and internal finishes. Historic England grant aided a Conservation Management
	OCCUPANCY:	Vacant/not in use	Plan and Feasibility Study. New uses are being explored.
- 71	PRIORITY CATEGORY:	C (C)	
- 1	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	43  92	Contact: Rachel James 0207 973 3153



© Historic England Archive

© His

Artillery fort 1865-71 with later additions. The fort been SITE NAME: Gilkicker Fort, Fort Road, Gilkicker Point subject to heritage crime in parts, and casemates and magazines are threatened by water penetration. Repair and Scheduled Monument and Listed conversion to residential units has planning approval and DESIGNATION: Building grade II\* the scheme is in very early stages. Security fencing and a construction presence on site will aim to control levels of CONDITION Poor heritage crime. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: F (D) OWNER TYPE: Private LIST ENTRY NUMBER: 1001789 and 1276716 Contact: lain Bright 0207 9733 739

A CONTRACTOR	SITE NAME:	Fort Elson, RNAD, Military Road, Gosport	Polygonal artillery fort of 1853-60. Damaging vegetation has taken hold of the site. Programmes of vegetation
	DESIGNATION:	Scheduled Monument	removal are intermittent. A management plan has been drafted but not agreed or implemented. The building
Their !	CONDITION:	Poor	cannot be occupied because it lies within a munitions storage area.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	Υ: A (A)	
	OWNER TYPE:	Government or agency	
listoric England	LIST ENTRY NUMBER:	1001841	Contact: Rachel James 0207 973 3153

SITE NAME: Fortifications S of Trinity Church DESIGNATION Scheduled Monument LIST ENTRY NUMBER 1001849 Generally satisfactory but with significant localised CONDITION: TREND: Improving problems PRINCIPAL VULNERABILITY: NEW ENTRY? No Scrub/tree growth Alison McQuaid 0207 973 3646 OWNER TYPE: CONTACT: Local authority

#### PRIORITY CATEGORIES

## Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / GOSPORT / HART

SITE NAMEMotte and balley castle near Apple Dumpling Bridge, south of RowerDISIGNATIONEScheduled MonumentUST ENTRY NURBER1008694CONDITIONEGenerally unsatisfactory with major localised problemsTREND:DeckningRINCIPAL VULNERABUTY:Scrub/tree growthNeW ENTRY:NoOWNER TYPELocal authorityCONTACT:Alison McQuaid 0207 973 3646SITE NAMEGunboat Traverser System, Haslar Gunboat YardUST ENTRY NURBER1001810CONDITION:Scheduled Monument, part in CAUST ENTRY NURBER1001810CONDITION:Generally satisfactory but with significant localised problemsINEND:DeciningRINCIPAL VULNERABUTY:Development requiring planning permissionNew ENTRY:NoOWNER TYPECommercial companyCONTACT:NoCONDITION:PoorTREND:DeterioratingVULNERABUTY:HighContract:Richard Whittington (LPA) corazy 2032/S45552SITE NAME:Friddy's HardScherard States, part in SMNeW ENTRY:NoCONDITION:Very badNEW ENTRY:NoSITE NAME:Scherard States, part in SMNeW ENTRY:NoCONDITION:Very badNEW ENTRY:NoCONDITION:Very badStele Sates, part in SMNoCONDITION:Very badNEW ENTRY:NoSITE NAME:Scherard States, part in SMNeW ENTRY:NoCONDITION:Very badNEW ENTRY:NoSITE NAME:Scherard States, part in SM<				
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPELocal authorityCONTACT:Alison McQuaid 0207 973 3646STRE NAME:Gunboat Traverser System, Haslar Gunboat YardDESIGNATION:Scheduled Monument, part in CALIST ENTRY NUMBER:1001810CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningOWNER TYPE:Development requiring planning permissionNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Louise Forsyth 020 7973 3220STE NAME:High Steet, GosportLouise Forsyth 020 7973 3220DESIGNATION:Conservation Area, 16 LBsNEW ENTRY:NoCONDITION:PoorTREND:DeterioratingVULNERABILITY:HighContract:Richard Whittington (LPA) (02392)545552STE NAME:Priddy's HardNEW ENTRY:NoCONDITION:Very badTREND:Deteriorating significantlyVULNERABILITY:HighContract:Richard Whittington (LPA) (02392)545552STE NAME:Stoke Road, GosportSteek Road, GosportSTE NAME:Conservation Area, 2 LBsNEW ENTRY:NoSTE NAME:PoorTREND:Deteriorating (02392)545552STE NAME:Conservation Area, 2 LBsNEW ENTRY:NoSTE NAME:PoorTREND:DeterioratingSTE NAME:Conservation Area,	SITE NAME:	Motte and bailey castle near Apple Dumpling Bridg	e, south of Rowner	ŕ
Continue         problems         Note of the set of the s	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008694
OWNER TYPE:Local authorityCONTACT:Alison McQuaid 0207 973 3646SITE NAME:Gunboat Traverser System, Haslar Gunboat YardDESIGNATION:Scheduled Monument, part in CALIST ENTRY NUMBER:1001810CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningCONTACT:Development requiring planning permissionNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Louise Forsyth 020 7973 3220SITE NAME:High Steet, GosportUSE Forsyth 020 7973 3220SITE NAME:Conservation Area, 16 LBsNEW ENTRY:NoCONDITION:PoorTREND:DeterioratingVULNERABILITY:HighContractRichard Whittington (LPA) (02392)545552SITE NAME:PoirSchervation Area, 25 LBs, part in SMNEW ENTRY:NoCONDITION:Very badTREND:Deteriorating significantlyVULNERABILITY:HighContract:Richard Whittington (LPA) (02392)545552VILNERABILITY:HighContract:NoCONDITION:Very badTREND:Deteriorating significantlyVILNERABILITY:HighContract:Richard Whittington (LPA) (02392)545552SITE NAME:Stek Road, GosportStek Road, GosportSITE NAME:Stek Road, GosportNoSITE NAME:Conservation Area, 2 LBsNEW ENTRY:NoCONDITION:PoorRIEND:DeterioratingSIGNATION:Conservation Area, 2 LBsNEW ENTRY: <td>CONDITION:</td> <td></td> <td>TREND:</td> <td>Declining</td>	CONDITION:		TREND:	Declining
SITE NAME:       Gunboat Traverser System, Haslar Gunboat Yard         DESIGNATION:       Scheduled Monument, part in CA       LIST ENTRY NUMBER:       1001810         CONDITION:       Generally satisfactory but with significant localised problems       TREND:       Declining         DENICIPAL VULNERABILITY:       Development requiring planning permission       NEW ENTRY:       No         OWINER TYPE:       Commercial company       CONTACT:       Louise Forsyth 020 7973 3220         SITE NAME:       High Steet, Gosport       Euclining         DESIGNATION:       Conservation Area, 16 LBS       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       High       Conservation Area, 16 LBS       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       High       Contract:       Richard Whittington (LPA) (2392)54552         STE NAME:       Priddy's Hard       Scher Nations:       No         CONDITION:       Very bad       TREND:       Deteriorating significantly         VULNERABILITY:       High       Contract:       Richard Whittington (LPA) (2392)54552         STE NAME:       Stoke Road, Gosport       Stretin Arme:       No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION:Scheduled Monument, part in CAUST ENTRY NUMBER:1001810coNDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABULTY:Development requiring planning permissionNEW ENTRY:NoOWNER TYPE:Commercial companyCONTACT:Louise Forsyth 020 7973 3220SITE NAME:High Steet, GosportContract:NoCONDITION:Conservation Area, 16 LBsNEW ENTRY:NoCONDITION:PoorTREND:DeterioratingvulnerabultY:HighContract:Richard Whittington (LPA) (02392) S45552SITE NAME:Friddy's HardVULNERABULTY:NoCONDITION:Conservation Area, 25 LBs, part in SMNEW ENTRY:NoCONDITION:Very badTREND:Deteriorating significantlyVULNERABULTY:HighContract:Richard Whittington (LPA) (02392) S45552SITE NAME:Stoke Road, GosportVery badTREND:SITE NAME:Stoke Road, GosportVery badNoVULNERABULTY:Gonservation Area, 2 LBsNEW ENTRY:NoCONDITION:PoorNoNoCONDITION:PoorNEW ENTRY:NoSITE NAME:Stoke Road, GosportVery badNew ENTRY:DESIGNATION:Conservation Area, 2 LBsNEW ENTRY:NoCONDITION:PoorNEW ENTRY:NoCONDITION:PoorNEW ENTRY:NoCONDITION:PoorNEW ENTRY:No <td>OWNER TYPE:</td> <td>Local authority</td> <td>CONTACT:</td> <td>Alison McQuaid 0207 973 3646</td>	OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Development requiring planning permissionNEW ENTRY!NoOWNER TYPE:Commercial companyCONTACT:Louise Forsyth 020 7973 3220SITE NAME:High Steet, GosportSteen Conservation Area, 16 LBsNEW ENTRY!NoCONDITION:PoorTREND:DeterioratingCONDITION:PoorTREND:DeterioratingVULNERABILITY:HighCONTACT:Richard Whittington (LPA) (02392)545552SITE NAME:Priddy's HardNEW ENTRY!:NoCONDITION:Conservation Area, 25 LBs, part in SMNEW ENTRY!:NoCONDITION:Very badTREND:Deteriorating significantly (02392)545552SITE NAME:Stok Road, GosportStokard Whittington (LPA) (02392)545552SITE NAME:Stok Road, GosportStokard Stokard Stokard (02392)545552SITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoSITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoSITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoSITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoCONDITION:PoorTREND:DeterioratingSITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoCONDITION:PoorTREND:DeterioratingSITE NAME:Conservation Area, 2 LBsNEW ENTRY!:NoCONDITION:PoorTREND: <td< td=""><td>SITE NAME:</td><td>Gunboat Traverser System, Haslar Gunboat Yard</td><td></td><td></td></td<>	SITE NAME:	Gunboat Traverser System, Haslar Gunboat Yard		
Conditional         problems         France         Index.         Declining           PRINCIPAL VULNERABILITY:         Development requiring planning permission         NEW ENTRY?:         No           OWNER TYPE:         Commercial company         CONTACT:         Louise Forsyth 020 7973 3220           SITE NAME:         High Steet, Gosport         Contact:         No           DESIGNATION:         Conservation Area, 16 LBs         NEW ENTRY?:         No           CONDITION:         Poor         TREND:         Deteriorating           VULNERABILITY:         High         Conservation Area, 25 LBs, part in SM         NEW ENTRY?:         No           SITE NAME:         Priddy's Hard         Conservation Area, 25 LBs, part in SM         NEW ENTRY?:         No           CONDITION:         Very bad         TREND:         Deteriorating significantly           VULNERABILITY:         High         Conservation Area, 25 LBs, part in SM         NEW ENTRY?:         No           CONDITION:         Very bad         TREND:         Deteriorating significantly           VULNERABILITY:         High         Conservation Area, 2 LBs         NEW ENTRY?:         No           SITE NAME:         Stoke Road, Gosport         Stoke Road, Gosport         Stokeroad, Gosport         Stokeroad, Gosport <td>DESIGNATION:</td> <td>Scheduled Monument, part in CA</td> <td>LIST ENTRY NUMBER:</td> <td>1001810</td>	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001810
OWNER TYPE:Commercial companyCONTACT:Louise Forsyth 020 7973 3220sitte NAME:High Steet, GosportDESIGNATION:Conservation Area, 16 LBsNEW ENTRY?:NoCONDITION:PoorTREND:DeterioratingvULNERABILITY:Highcontact:Richard Whittington (LPA) (02392)545552SITE NAME:Priddy's HardDESIGNATION:Conservation Area, 25 LBs, part in SMNEW ENTRY?:NoCONDITION:Very badTREND:Deteriorating significantlyvULNERABILITY:Highcontact:Richard Whittington (LPA) (02392)545552SITE NAME:Stoke Road, GosportTEEND:Deteriorating significantlyVULNERABILITY:Conservation Area, 2 LBsNEW ENTRY?:NoSITE NAME:Conservation Area, 2 LBsNEW ENTRY?:NoSITE NAME:PoorTREND:Deteriorating significantlyULNERABILITY:Highcontact:Richard Whittington (LPA) (2392)545552VULNERABILITY:HighConservation Area, 2 LBsNEW ENTRY?:VULNERABILITY:HighContact:Richard Whittington (LPA)VULNERABILITY:HighContact:Richard Whittington (LPA)	CONDITION:		TREND:	Declining
site NAME:       High Steet, Gosport         DESIGNATION:       Conservation Area, 16 LBs       NEW ENTRY?:       No         cONDITION:       Poor       TREND:       Deteriorating         vULNERABILITY:       High       Conservation Area, 25 LBs, part in SM       NEW ENTRY?:       No         site NAME:       Priddy's Hard       Conservation Area, 25 LBs, part in SM       NEW ENTRY?:       No         condition:       Conservation Area, 25 LBs, part in SM       NEW ENTRY?:       No         condition:       Very bad       TREND:       Deteriorating significantly         vulnerabilitY:       High       contact:       Richard Whittington (LPA) (02392)545552         site NAME:       Priddy's Hard       NEW ENTRY?:       No         condition:       Conservation Area, 25 LBs, part in SM       NEW ENTRY?:       No         vulnerabilitY:       High       Contact::       Richard Whittington (LPA) (02392)545552         site NAME:       Stoke Road, Gosport       Stoke Road, Gosport       Stoke Road, Gosport         site NAME:       Stoke Road, Gosport       No       No         condition:       Conservation Area, 2 LBs       NEW ENTRY?:       No         condition:       Poor       Netwentry?:       No         condi	PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
DESIGNATION:       Conservation Area, 16 LBs       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         vULNERABILITY:       High       contact:       Richard Whittington (LPA) (02392)545552         stre NAME:       Priddy's Hard       strende       strende         DESIGNATION:       Conservation Area, 25 LBs, part in SM       NEW ENTRY:       No         condition:       Very bad       TREND:       Deteriorating significantly         vULNERABILITY:       High       contact:       Richard Whittington (LPA) (02392)545552         vulnerability:       Conservation Area, 25 LBs, part in SM       NEW ENTRY:       No         condition:       Conservation Area, 25 LBs, part in SM       NEW ENTRY:       No         condition:       Conservation Area, 25 LBs, part in SM       NEW ENTRY:       No         condition:       Very bad       trend       contact:       Richard Whittington (LPA) (02392)545552         stre NAME:       Stoke Road, Gosport       strende       strende       contact:       Richard Whittington (LPA)         stre NAME:       Conservation Area, 2 LBs       NEW ENTRY:       No       contact in ginating         vulnee Abilition:       Poor       Richard Conting       contact in ginating	OWNER TYPE:	Commercial company	CONTACT:	Louise Forsyth 020 7973 3220
CONDITION:PoorTREND:DeterioratingvULNERABILITY:HighCONTACT:Richard Whittington (LPA) (02392)545552site NAME:Priddy's HardDESIGNATION:Conservation Area, 25 LBs, part in SMNEW ENTRY:NoCONDITION:Very badTREND:Deteriorating significantlyvULNERABILITY:HighCONTACT:Richard Whittington (LPA) (02392)545552SITE NAME:Stoke Road, GosportJESIGNATION:Conservation Area, 2 LBsNEW ENTRY:NoCONDITION:PoorTREND:DeterioratingULINERABILITY:LickOotTREND:No	SITE NAME:	High Steet, Gosport		
VULNERABILITY:       High       CONTACT:       Richard Whittington (LPA) (02392)545552         SITE NAME:       Priddy's Hard	DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
Nome     Priddy's Hard     New ENTRY?     No       DESIGNATION:     Conservation Area, 25 LBs, part in SM     NEW ENTRY?     No       CONDITION:     Very bad     TREND:     Deteriorating significantly       vULNERABILITY:     High     CONTACT:     Richard Whittington (LPA) (02392)545552       SITE NAME:     Stoke Road, Gosport     NEW ENTRY?:     No       DESIGNATION:     Conservation Area, 2 LBs     NEW ENTRY?:     No       ULINERABILITY:     Poor     TREND:     Deteriorating       VULINERABILITY:     High     CONTACT:     Richard Whittington (LPA)	CONDITION:	Poor	TREND:	Deteriorating
DESIGNATION:       Conservation Area, 25 LBs, part in SM       NEW ENTRY?:       No         CONDITION:       Very bad       TREND:       Deteriorating significantly         vulnerabilitry:       High       contact:       Richard Whittington (LPA) (0392)545552         STEE NAME:       Stoke Road, Gosport       VULNERABILITY:       No         DESIGNATION:       Conservation Area, 2 LBs       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Lick       CONTACT:       Richard Whittington (LPA)	VULNERABILITY:	High	CONTACT:	Richard Whittington (LPA) (02392)545552
CONDITION:     Very bad     TREND:     Deteriorating significantly       vulnerabilitY:     High     contact:     Richard Whittington (LPA) (02392)545552       site NAME:     Stoke Road, Gosport     vulnerabilitY:     No       DESIGNATION:     Conservation Area, 2 LBs     NEW ENTRY:     No       condition:     Poor     TREND:     Deteriorating contacting       vulnerabilitY:     Lick     contact:     Richard Whittington (LPA)	SITE NAME:	Priddy's Hard		
VULNERABILITY:     High     CONTACT:     Richard Whittington (LPA) (02392)545552       SITE NAME:     Stoke Road, Gosport	DESIGNATION:	Conservation Area, 25 LBs, part in SM	NEW ENTRY?:	No
VIENEBABILITY:     High     CONTACT:     (02392)545552       New ENTRY?:     Stoke Road, Gosport       DESIGNATION:     Conservation Area, 2 LBs     NEW ENTRY?:     No       CONDITION:     Poor     TREND:     Deteriorating       VIENEBABILITY:     Lick     CONTACT:     Richard Whittington (LPA)	CONDITION:	Very bad	TREND:	Deteriorating significantly
DESIGNATION:     Conservation Area, 2 LBs     NEW ENTRY?:     No       CONDITION:     Poor     TREND:     Deteriorating       VILINERABILITY:     Lick     CONTACT:     Richard Whittington (LPA)	VULNERABILITY:	High	CONTACT:	Richard Whittington (LPA) (02392)545552
CONDITION:     Poor     TREND:     Deteriorating       VILINERABILITY:     Litzle     CONTACT:     Richard Whittington (LPA)	SITE NAME:	Stoke Road, Gosport		
VIII NERABILITY: Lick CONTACT: Richard Whittington (LPA)	DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
	CONDITION:	Poor	TREND:	Deteriorating
	VULNERABILITY:	High	CONTACT:	

#### HART



D

Е

SITE NAME:	Garden walls and gateways north of Bramshill House, Bramshill
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1340026

Walls to early C17 and early C19 formal walled gardens. Some sections of the walls are in a poor condition and in need of repair. Site was sold in 2014 to a development company and proposals for development within the site and the conversion of the mansion were the subject of a public inquiry which finished in February 2018 but the future of the site is still uncertain. The repair of the garden walls will be sought as a positive outcome of the planning process.

© Historic England

Contact: Louise Forsyth 020 7973 3220

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS

Unitary Authority World Heritage Site

#### HERI

HERITAGE AT RISK 2023 / LOND	ON AND SOUTH EAST	/ HART / HAVAINT / INEVV FOREST	
	SITE NAME:	Warbrook House, Eversley	Seminal in garden history terms, the gardens and house
	DESIGNATION:	Registered Park and Garden grade II*, LB grade I	were designed c1724 by the architect John James whose home it was, utilising the formal geometric principles he translated from Dezallier d'Argenville. Geometrical axes
	CONDITION:	Generally unsatisfactory with major localised problems	extend beyond the gardens but these, and the wider parkland has fragmented, and conversion to a hotel and conference centre created major local change. An aerial
and the second sec	VULNERABILITY:	Medium	survey of the park undertaken by Historic England to
	TREND:	Stable	inform a Parkland Plan and ideas for restoration of key features with land and flood management options are being
	NEW ENTRY?:	No	discussed in partnership with Natural England.
© Historic England	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000249	Contact: Kay Richardson 0207 973 3647
	SITE NAME:	Bramshill Park, Mattingley / Bramshill / Eversley	Rare early C17 gardens and 'prodigy' house for royal visits within a park of medieval origin created for entertaining
	SITE NAME: DESIGNATION:	Bramshill Park, Mattingley / Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in CA	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many
		Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many college buildings built in the core the estate was sold in 2014 and faces discussions for its future. With other
	DESIGNATION:	Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in CA	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many college buildings built in the core the estate was sold in 2014 and faces discussions for its future. With other changes and ownerships in the wider park, the park and garden is vulnerable to fragmentation and loss of integrity
	designation: Condition:	Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in CA Extensive significant problems	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many college buildings built in the core the estate was sold in 2014 and faces discussions for its future. With other changes and ownerships in the wider park, the park and
© Historic England	DESIGNATION: CONDITION: VULNERABILITY:	Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in CA Extensive significant problems High	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many college buildings built in the core the estate was sold in 2014 and faces discussions for its future. With other changes and ownerships in the wider park, the park and garden is vulnerable to fragmentation and loss of integrity and a co-ordinated Conservation Management Plan
© Historic England	DESIGNATION: CONDITION: VULNERABILITY: TREND:	Bramshill / Eversley Registered Park and Garden grade I, 8 LBs, part in SM, part in CA Extensive significant problems High Declining	within a park of medieval origin created for entertaining and recreation, whose key parkland features remains intact despite later C18 informalisations and some fragmentation of the wider park. Previously in institutional use with many college buildings built in the core the estate was sold in 2014 and faces discussions for its future. With other changes and ownerships in the wider park, the park and garden is vulnerable to fragmentation and loss of integrity and a co-ordinated Conservation Management Plan

#### HAVANT

© Histori

	SITE NAME:	St Faith's Church, West Street, Havant	Cruciform medieval church; flint and stone walls, clay tile roof. Tower with parapet. Following plaster falls an
	DESIGNATION:	Listed Place of Worship grade II*, CA	investigation of the roofs recommended a complete overhaul. Temporary repairs were undertaken. Fundraising has led to the congregation being able to undertake
	CONDITION:	Poor	internal works but external repairs still required.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1092120	Contact: Rachel James 0207 973 3153
ric England			

SITE NAME:	Coastguards		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Rachael McMurray (LPA) 02382 446546

#### NEW FOREST

	Hitter The State	11	10
--	------------------	----	----

SITE NAME:	Church of St Winfred, Salisbury Road, Totton and Eling
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1094352

Large church completed 1937 and designed by NF Cachemaille-Day. Unusual galleried square nave with monumental concrete font and Father Willis organ. Built of brick with mainly pantiled roofs. At risk due to defects to the brickwork, rainwater disposal system, deteriorating windows and internal plaster. The pantiled roofs were repaired with a grant from the National Lottery Heritage Fund under their Grants for Places of Worship scheme. It is hoped that the remaining repairs will be carried out by a new incoming church plant congregation supported by the Diocese.

Contact: Rachel James 0207 973 3153

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / NEW FOREST / NEW FOREST (NP)

		, ,	
SITE NAME:	Bowl barrow 330m north of Grim's Ditch, r	near Tidpit Common, Mar	tin
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011000
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
site name:	Long Barrow 800m north west of Paradise,	Martin	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012512
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Duck's Nest: a long barrow on Rockbourne	Down, Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012920
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow 700m north west of Tenantry	Farm, Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013002
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Rockbourne Down, Spring Pond enclosure,	Rockbourne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003453
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### NEW FOREST (NP)

( )			
And Factor	SITE NAME:	Church of St Katherine, Exbury, Exbury and Lepe, New Forest	Church remodelled in 1907 by JO Scott and Son, with coursed squared Ventnor Greensand facings and tiled roof.
	DESIGNATION:	Listed Place of Worship grade II, CA	The church forms part of a joint benefice and is located in a hamlet constructed to serve the neighbouring Rothschild house and garden. The main problem is the decay and
	CONDITION:	Poor	delamination of stonework. The congregation complete some stonework repairs to the tower in 2014. Further
	PRIORITY CATEGORY:	C (C)	funding required to complete the outstanding repairs to the
	OWNER TYPE:	Religious organisation	stonework.
	LIST ENTRY NUMBER:	1094359	Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Bell barrow and two bowl barrows 180 metres south west of Stagbury Hill, Furzley Common, Bramshaw, New Forest		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016491
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY ?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / NEW FOREST (NP) / RUSHMOOR

SITE NAME:Rabbit warren and four bowl barrows on Stagbur J-LIF Larzley CommercialBramshaw, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1016490CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, SVFNIRgwood, FNIRG1012637DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNew ENTRY:NoOWNER TYPE:Private, multiple ownersCONTACT:Alison McQuaid 0207 973 3646					
CONDITION:Generally satisfactory but with significant localised problemsTREND:ImprovingPRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Sopter / Ringwood, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	SITE NAME:	Rabbit warren and four bowl barrows on Stagbury	Hill, Furzley Comm	non, Bramshaw, New Forest	
PRINCIPAL VULNERABILITY:Visitor erosion - limited/localisedNEW ENTRY?:NoOWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Sopley / Ringwood, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016490	
OWNER TYPE:Charity (heritage)CONTACT:Alison McQuaid 0207 973 3646SITE NAME:Bowl barrow 550m north west of Avon Tyrrell, Sopley / Ringwood, New ForestDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1012637CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:No	CONDITION:		TREND:	Improving	
SITE NAME:       Bowl barrow 550m north west of Avon Tyrrell, Sopley / Ringwood, New Forest         DESIGNATION:       Scheduled Monument       LIST ENTRY NUMBER:       1012637         CONDITION:       Generally unsatisfactory with major localised problems       TREND:       Declining         PRINCIPAL VULNERABILITY:       Animal burrowing - extensive       NEW ENTRY?:       No	PRINCIPAL VULNERABILITY:	Visitor erosion - limited/localised	NEW ENTRY?:	No	
DESIGNATION:       Scheduled Monument       LIST ENTRY NUMBER:       1012637         CONDITION:       Generally unsatisfactory with major localised problems       TREND:       Declining         PRINCIPAL VULNERABILITY:       Animal burrowing - extensive       NEW ENTRY:       No	OWNER TYPE:	Charity (heritage)	CONTACT:	Alison McQuaid 0207 973 3646	
CONDITION:     Generally unsatisfactory with major localised problems     TREND:     Declining       PRINCIPAL VULNERABILITY:     Animal burrowing - extensive     NEW ENTRY:     No		Bowl barrow 550m north west of Avon Tyrrell, Sopley / Ringwood, New Forest			
PRINCIPAL VULNERABILITY:     Animal burrowing - extensive     NEW ENTRY:     No	SITE NAME:	Bowl barrow 550m north west of Avon Tyrrell, So	pley / Ringwood, N	lew Forest	
			. , -		
OWNER TYPE:Private, multiple ownersCONTACT:Alison McQuaid 0207 973 3646	DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1012637	
	DESIGNATION: CONDITION:	Scheduled Monument Generally unsatisfactory with major localised problems	LIST ENTRY NUMBER: TREND:	1012637 Declining	

#### RUSHMOOR

Resiniteen				
	SITE NAME:	Building Q121 [24 foot wind tunnel] at former Royal Aircraft Establishment site, Hall Road, Farnborough	Wind tunnel built 1934-35. The external fabric of the building is generally in good condition and actively maintained. Tours are given by arrangement and low-key use for art exhibitions has been permitted (in association	
	DESIGNATION:	Listed Building grade I	with the Farnborough Air Show) However the future use of the building remains uncertain, which is the reason for	
	CONDITION:	Fair	the at-risk status. Study exploring Farnborough's aviation heritage being commissioned from consultants.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
© Historic England	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1259589	Contact: Rachel James 0207 973 3153	
	SITE NAME:	Building R133 [Transonic wind tunnel] at former Royal Aircraft Establishment site, O'Gorman Avenue, Farnborough	Wind tunnel built in 1939 and modified in 1956. Extern the building is generally in good condition and actively maintained but some staining of concrete walls due to corroding reinforcement. Tours are given by appointm	
ALL DATES IN THE REAL OF	DESIGNATION:	Listed Building grade I	but the future use of the building remains uncertain. Study exploring Farnborough's aviation heritage being	
	CONDITION:	Fair	commissioned from consultants.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
© Historic England	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1259586	Contact: Rachel James 0207 973 3153	
	SITE NAME:	Church of the Holy Trinity, Albert Road, Aldershot	The first church to be built in the new town, by Sidney Stapley 1875-78, in the Early English style of Bargate stone	
	DESIGNATION:	Listed Place of Worship grade II	with Bath stone dressings and a slate roof. The ashlar stonework is showing signs of decay and repairs required	
an an	CONDITION:	Poor	to the roof and west porch.	
	PRIORITY CATEGORY:	F (F)		

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

OWNER TYPE:

LIST ENTRY NUMBER:

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Religious organisation

1092621

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Rachel James 0207 973 3153

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

#### SOUTH DOWNS (NP)

The second second	
一、 直接 6. 加爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾爾	
the stand of a sub-	
	and the second
A CARLON OF THE OWNER WITH	And the second second
and the second	
DOD AND AND AND	Same A
	State of the second second
and the second se	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	S. STREAMS
	- A State State A
	and the second
	The second states
A REAL PROPERTY OF THE PARTY OF	and the second second
and the second second	
and the second second second second	ANY COLUMN
and the second second second second	
Contraction of the second second second	
	Add Strengtheres
IP SOIL A REALING	A CONTRACTOR OF

#### SITE NAME: Ruins of St Nicholas Chapel, Westbury, East Meon, East Hampshire Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Commercial company

1001942 and 1179009

Small ruined medieval church of possibly C13 or later. Designated with associated earthwork remains of contemporary settlement. Standing ruins are suffering from structural cracking and deferred maintenance. A project to see the ruins conserved, explained and maintained needs to be agreed and put into action.

© Historic England

Contact: Rachel James 0207 973 3153

SITE NAME:	Bowl barrow 620m north east of Warhill Cottage,	East Meon, East H	ampshire	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019116	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Group of four bowl barrows 660m north of Warh	ill Cottage, East Me	on, East Hampshire	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019115	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Bowl barrow 100m south east of Lower Bordean Farm, Langrish, East Hampshire			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017051	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Three disc barrows on Longmoor Common, 250m	north west of the	church, Whitehill, East Hampshire	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016843	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY ?:	No	
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646	
site name:	Round barrow cemetery, Roman road and hollow East Hampshire	ways 200m south v	vest of Woolmer Cottages, Whitehill,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020502	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM

UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

SITE NAME:	St Catherine's Hill hillfort, Winchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016489
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (independent)	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman villa in Bottom Copse, Soberton, Winche	ster	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001848
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Boundary earthwork and barrow at Sheepbridge,	West Meon / Warn	ford, Winchester
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1003562
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alex Bellisario 0207 973 3700
SITE NAME:	Easton, Winchester (District), Itchen Valley, Win	chester	
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Planning Performance and Technica Team (LPA) 01730 814810
SITE NAME:	Hambledon, Winchester (District), Hambledon, V	Winchester	
DESIGNATION:	Conservation Area, 82 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Planning Performance and Technica Team (LPA) 01730 814810
SITE NAME:	Itchen Stoke, Winchester (District), Itchen Stoke	and Ovington, Wind	hester
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Planning Performance and Technica Team (LPA) 01730 814810
SITE NAME:	Martyr Worthy, Winchester (District), Itchen Va	lley, Winchester	
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Planning Performance and Technica Team (LPA) 01730 814810
SITE NAME:	Twyford, Winchester (District), Twyford, Winch	ester	
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Planning Performance and Technica Team (LPA) 01730 814810

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TEST VALLEY

HERITAGE AT RISK 2023 / LOI	NDOIN AIND SOUTH EAST / TEST VALLET		
TEST VALLEY			
SITE NAME:	Long barrow 400m south east of Moody's Down F	arm, Barton Stacey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012515
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	The Andyke, Bransbury, Barton Stacey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015678
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow 300m south east of Middlebarn Farm	, Chilbolton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012517
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Castle Hill, Chilworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001885
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 780m NNE of Hampshire Gap, Grate	eley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014816
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Barrow cemetery 730m north of Hampshire Gap,	Grateley / Quarley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014817
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Andover-Redbridge canal, Chalk Hill Lock, Horseb	ridge, Kings Sombo	rne
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001794
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

142

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TEST VALLEY / WINCHESTER

SITE NAME:	The Moat, Longs	tock		
DESIGNATION:	Scheduled Monur	ment, CA	LIST ENTRY NUMBER:	1001940
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree grow	th	NEW ENTRY ?:	No
OWNER TYPE:	Commercial com	ipany	CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Embley Park, Wellow	C19 and early C20 woodland and shrub garden of late C origin, once the home of Florence Nightingale. After WV the estate was divided, the house and historic core becoming a school. A Conservation Management Plan covers the school although the historic character is vulnerable to additional development. The wider open	
ALL DESCRIPTION OF THE OWNER	DESIGNATION:	Registered Park and Garden grade II, 8 LBs		
	CONDITION:	Extensive significant problems		
	VULNERABILITY:	High	and wooded park has multiple owners and accumulat	k has multiple owners and accumulative
	TREND:	Stable	development pressures. A Heritage Impact Assessm was commissioned by Test Valley in 2016 in respons	
	NEW ENTRY?:	No	local plan proposals. The need to widen understand significance and conservation to sustain value remain	sals. The need to widen understanding of
© Historic England	OWNER TYPE:	Mixed, multiple owners	significance and c	conservation to sustain value remains.
	LIST ENTRY NUMBER:	1000215	Contact: Kay Ric	hardson 0207 973 3647

#### WINCHESTER

e Felad	SITE NAME:	Church of the Holy Trinity, North Walls, Winchester	Designed by Henry Woodyer and built 1853-1855. It continuous seven-bay clerestoried nave with north an
	DESIGNATION:	Listed Place of Worship grade II*, CA	south aisles and chancel and fleche with spire and lunettes The walls are of flint with limestone blocks and limestone dressings. Vestry on south east and enclosed porch on the
	CONDITION:	Poor	west door dating from 1894. There are slipped and mis slates, the roof leaks and the rainwater goods do not function effectively, putting the church at risk.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1350718	Contact: Rachel James 0207 973 3153

#### © Historic England

SITE NAME:	Roman villa and earlier prehistoric settlement 400r	n west of Lone Far	m, Itchen, Itchen Valley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012693
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Norsebury Ring hillfort, Micheldever		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020317
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Long barrow and bowl barrow 440m north west o	f Sanctuary Farm, V	Vonston
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021109
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Alison McQuaid 0207 973 3646

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WINCHESTER

SITE NAME:	Compton Street, Compton and Shawford		
DESIGNATION:	Conservation Area, 14 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Hursley		
DESIGNATION:	Conservation Area, 33 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	New Alresford, Old Alresford / New Alresford		
DESIGNATION:	Conservation Area, 125 LBs, SM	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Southwick, Southwick and Widley		
DESIGNATION:	Conservation Area, 48 LBs, SM	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Sparsholt		
DESIGNATION:	Conservation Area, 13 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Sutton Scotney, Wonston		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Deteriorating
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wickham, Wickham and Knowle		
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222
SITE NAME:	Wonston		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	No significant change
VULNERABILITY:	Unknown	CONTACT:	Historic Environment Team (LPA) 01962 840222

#### PRIORITY CATEGORIES

- implemented. C Slow decay; no solution agreed.

 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solu use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### PORTSMOUTH, CITY OF (UA) / WINCHESTER



. ,		
SITE NAME:	Fort Southwick, Portsdown Hill, Portsmouth, Southwick and Widley	1860s fort, part of the Palmerston Portsmouth defences. Parts of the monument are in poor condition. Following disposal by Defence Estates, the site is now operated by ar
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I, SM	estate management company as a business park with a number of different companies operating from the site. The new owners have carried out some repairs but more are
CONDITION:	Fair	needed, together with a carefully planned maintenance regime.
OCCUPANCY:	Part occupied/part in use	regime.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1001808 and 1104368; 1167213	Contact: Rachel James 0207 973 3153

© Historic England

#### ISLE OF WIGHT (UA)

. ,			
	SITE NAME:	Hammerhead Crane, Thetis Road, West Cowes, Cowes	Giant cantilever crane, also called 'hammerhead' crane, built 1911. One of a handful of this type of crane now
	DESIGNATION:	Listed Building grade II*	surviving in the world, and witness to a major local industry. Disused and surrounded by a potential
	CONDITION:	Poor	development site. Historic England has been assisting th Local Authority with grant aid and technical advice. Essential holding repairs to the legs and upper structure have been undertaken under the auspices of an Urgent Works Notice. Historic England has grant-aided a feasib
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	study and will be working with all stakeholders on the site to secure the full repair of the crane.
ic England	LIST ENTRY NUMBER:	1390949	Contact: Rachel James 0207 973 3153

Northwood House, Ward

Listed Building grade II\*, CA

Part occupied/part in use

Avenue, Cowes

Fair

C (C)

1223182

© Historic

	SITE NAME:
	DESIGNATION:
PERSONAL TREELED & F	CONDITION:
A DESCRIPTION OF A DESC	OCCUPANCY:
	PRIORITY CATEGORY:
and the states	OWNER TYPE:

© Historic	England	Archive



© Historic England

STREET.	OWNER TYPE:	Charity (heritage)	Lottery Heritage Fund. The cost of full repair is very high.
	LIST ENTRY NUMBER:	1223779	Contact: Rachel James 0207 973 3153
1	SITE NAME:	Norris Castle Farm, the Bailiff's House, Two Cottages and Kitchen Garden Wall, Newbarn Road, East Cowes	Model Farm designed by James Wyatt around 1800. It includes farm buildings, Bailiff's house, cottages, walled garden and glass houses all contained within a rectangular plan surrounded by high castellated walls with corner
	DESIGNATION:	Listed Building grade I, RPG grade I	towers. The walls are mainly built of rubble stonework with Welsh slate roofs to the buildings. At risk due to lack of long-term maintenance, leaking roofs and defective
Steller,	CONDITION:	Very bad	rainwater disposal. Proposals for repair and sustainable re- use are awaited from the owner. Some emergency repairs
1.	OCCUPANCY:	Vacant/not in use	carried out.
ALC: NOTE:	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	

Contact: Rachel James 0207 973 3153

Large house, 1837, with spectacular interiors. The long-

term future of this partly used building is unresolved and maintenance needs to be addressed in the short term.

Some progress has been made and areas of the building have been brought back into use, but the comprehensive

appoint a conservation architect, compile a full package of

repairs and improvements and to engage with the National

repair of the external envelope is still required. The

Trustees of Northwood House have been urged to

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOLITH EAST / ISLE OF WIGHT (LIA)

HERITAGE AT RISK 2023 / LONDO	ON AND SOUTH EAST	/ ISLE OF WIGHT (UA)	
-	SITE NAME:	Norris Castle, Newbarn Road, East Cowes	Mock castle of 1799 by James Wyatt on a spectacular site overlooking the Solent. Constructed with galletted stone
	DESIGNATION:	Listed Building grade I, RPG grade I	facings to the walls and slate roofs behind parapets. At risk due to backlog of maintenance, heritage crime and deterioration of significant historic fabric including to roofs,
	CONDITION:	Very bad	walls, windows and interiors. Historic England is working with representatives of the owners to address repairs in
	OCCUPANCY:	Vacant/not in use	both the short and long term.
-	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© Isle of Wight Council	LIST ENTRY NUMBER:	1267468	Contact: Rachel James 0207 973 3153
	SITE NAME:	The Guildhall, High Street, Newport and Carisbrooke	Former Guildhall, now museum, in the centre of Newport. Designed by John Nash and constructed 1814-6, with clock
	DESIGNATION:	Listed Building grade II*, CA	tower added in 1887 for Queen Victoria's Golden Jubilee. Slate roofs, rendered walls and stone columns and
	CONDITION:	Very bad	dressings to tower. At risk due to deferred maintenance
	OCCUPANCY:	Part occupied/part in use	and defects to roofs, render, stonework and rainwater disposal.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
a Uistaria Fardand	LIST ENTRY NUMBER:	1278563	Contact: Rachel James 0207 973 3153
© Historic England		12/0303	
	SITE NAME:	Remains of Old Quarr Abbey, Fishbourne Park Road, Binstead, Ryde / Fishbourne	Cistercian foundation of 1131. The upstanding remains are in an advanced state of decline due to longstanding lack of regular maintenance and vegetation growth. The National
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II	Lottery Heritage Fund grant aided repairs to the barn, some structures and walling as part of a wider project. Further repairs are necessary to remove the remains from
	CONDITION:	Poor	the Heritage at Risk Register. Historic England grant-aided an update of the condition survey, hydrological survey and
	OCCUPANCY:	Part occupied/part in use	temporary propping of the leaning east precinct wall which
	PRIORITY CATEGORY:	A (A)	was in danger of collapse.
D Historic England	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1012714 and 1234997	Contact: Rachel James 0207 973 3153
	SITE NAME:	Yaverland Battery, Sandown, Sandown	Royal Commission coastal battery completed in 1864 with later alterations. Mainly built of red brick with stone
A B	DESIGNATION:	Scheduled Monument	dressings. At risk due to vegetation growth and partial collapse of carnot wall. A plan for the long-term
	CONDITION:	Poor	conservation of the monument needs to be developed with
	OCCUPANCY:	N/A	the owner.
The second second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1021443	Contact: Rachel James 0207 973 3153
	SITE NAME:	Bouldnor Battery, Shalfleet	Battery built in 1938 situated on the west coast of the Isle
Than Miller average	DESIGNATION:	Scheduled Monument	of Wight to help protect the Solent. Buried components no
THE REAL PROPERTY OF	CONDITION:		longer accessible but survive. Mainly constructed from reinforced concrete which is now spalling and decaying due
	OCCUPANCY:	Very bad Vacant/not in use	to corrosion of the internal reinforcement. Historic England
			has grant-aided temporary propping and waterproofing of the roofs. An Options Appraisal, also grant-aided by
	PRIORITY CATEGORY:	C (C)	Historic England, was completed in early 2020 and options for the repair and possible re-use of the monument are
	OWNER TYPE:	Government or agency	being explored.
© Forestry Commission	LIST ENTRY NUMBER:	1010011	Contact: Rachel James 0207 973 3153
,			

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLE OF WIGHT (UA)

	SITE NAME:	Church of St Mary, Church Road, Cowes	Large church adjacent to Northwood Park. The west tower was designed by John Nash in 1816 and the rest of
	DESIGNATION:	Listed Place of Worship grade II*, CA	the church was rebuilt in 1867. Built of stone with colour banded slate roof. Historic England/National Lottery Heritage Fund grant-aided repairs to tower and north roof
AN IN INT	CONDITION:	Poor	slopes but further repairs needed including to the south nave and aisle roofs, rainwater disposal, and addressing
1/2/2	PRIORITY CATEGORY:	C (C)	structural movement to south west corner, which is
	OWNER TYPE:	Religious organisation	currently being monitored.
	LIST ENTRY NUMBER:	1222748	Contact: Rachel James 0207 973 3153
ngland			

© Historic Eng



© Historic England

Market Market	SITE NAME:	Church of All Saints, Church Hill, Godshill	Mainly dating from the CI4 with an unusual plan of double nave and arcade continuous to chancel. Early CI6 south
	DESIGNATION:	Listed Place of Worship grade I, CA	transept with crucifixion wall painting of similar date. Historic England/National Lottery Heritage Fund grant- aided repairs to rainwater goods, drainage and south west
	CONDITION:	Poor	corner, including west window to south nave, have been successfully completed. Further repairs required to the
	PRIORITY CATEGORY:	C (C)	stonework.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1209229	Contact: Rachel James 0207 973 3153
© Historic England			

SITE NAME: Spacious Gothic style church to the south of Newport Church of St John the Baptist, town centre. It was designed by R G Wetten and mainly Drake Road, Newport., constructed 1835-7 of rubblestone with ashlar buttresses Newport and Carisbrooke and turrets and Roman cement window surrounds, DESIGNATION: Listed Place of Worship grade II mouldings and corbels. Slate roof behind tall parapets. At risk due to deterioration of the historic fabric including the CONDITION: Poor stonework and window surrounds. PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1278820 Contact: Rachel James 0207 973 3153

© Historic England



Town centre church on compact site designed by Joseph SITE NAME: St Mary's Roman Catholic Church, High Street, Ryde Hansom in the Gothic style. It was mainly built 1846-8 of rubble limestone with unusual angular pantile roofs. Listed Listed Place of Worship grade Places of Worship Roof Repair Fund grant aided repairs to DESIGNATION: II\*, CA the roofs and Covid 19 Emergency Grant funded report on internal decorative scheme, but conservation work to this CONDITION: Poor is required. PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1216915 Contact: Rachel James 0207 973 3153

© Historic England

D

Е

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLE OF WIGHT (UA)

15	SITE NAME:	Church of St John, Carter Street, Sandown	A Victorian church in the Early English style; by the architect CL Luck. Walls of soft local stone, roof has
II.	DESIGNATION:	Listed Place of Worship grade II	concrete tiles. Nave and chancel, south aisle with south porch. Shingled spirelet. The main problem is the eroding
H EN EN TER	CONDITION:	Poor	stonework but also the roof over the clergy vestry leaks and there has been a partial collapse of the ceiling. A
AND AND I LOT	PRIORITY CATEGORY:	C (C)	programme of repairs is required to address these issues.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1034282	Contact: Rachel James 0207 973 3153

© Historic England

11 11 1

	SITE NAME:	Church of St Saviour's on the Cliff, Queen's Road, Shanklin	Victorian church by Thomas Hellyer in the Early English style. Built of soft local limestone with tiled roof. The
	DESIGNATION:	Listed Place of Worship grade II	principal problem is the condition of the stonework which is badly spalled all over. The church is in a coastal location.
100	CONDITION:	Poor	The windows at the west end are very fragile and are protected with Perspex to prevent them from being blown
	PRIORITY CATEGORY:	C (C)	out. Some repairs have been carried out, but more are
	OWNER TYPE:	Religious organisation	required. In February 2021 the hall roof suffered storm damage.
In En	LIST ENTRY NUMBER:	1212831	Contact: Rachel James 0207 973 3153

© Historic England

	SITE NAME:	Church of St Paul's, Regent Street, Shanklin	Town centre church designed by CL Luck 1875-90, with west porch added 1911. Built of local Greensand stone
	DESIGNATION:	Listed Place of Worship grade II	with tiled roofs and slender tower with timber framed top storey and shingled roof. At risk due to timber decay to
	CONDITION:	Very bad	top of tower, decaying stonework, bulging window gla and slipped and missing shingles. Phase One repairs to
	PRIORITY CATEGORY:	C (C)	main roofs, rainwater goods and high level stonework were
	OWNER TYPE:	Religious organisation	successfully completed in 2016 with the help of a grar from Historic England/National Lottery Heritage Fun
	LIST ENTRY NUMBER:	1212881	Further phases of repair are now required.
			Contact: Rachel James 0207 973 3153

© Historic England

	SITE NAME:	Holy Trinity Church, Trinity Road, Ventnor	Victorian church in the Early English style by the architect CE Giles. Nave, aisles and chancel with slender tower and
	DESIGNATION:	Listed Place of Worship grade II*, CA	spire at the south east corner. Built of soft local stone with concrete tiles on the roof. The main problem is the soft stone work which continues to decay. Some repairs have
	CONDITION:	Poor	been carried out to the tower.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
nd	LIST ENTRY NUMBER:	1343326	Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Medieval settlement 100m south east and 350m north east of East Ashey Manor Farm, Brading / Havenstreet and Ashey			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015622	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLE OF WIGHT (UA)

SITE NAME:	Two bowl barrows 110m north-east of Heatherdown, Totland				
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1010619	
CONDITION:	Generally unsatisf problems	Generally unsatisfactory with major localised problems		Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - extensive		NEW ENTRY?:	No	
OWNER TYPE:	Charity (heritage)		CONTACT:	Alison McQuaid 0207 973 3646	
	SITE NAME: Swainston, Calbourne, Newtown and Porchfield		intersecting aven	Mid-late C18 woodland garden, set in parkland, with intersecting avenues and water features incorporating earlier fishponds from a Bishopric manor, now a hotel.	
	DESIGNATION:	Registered Park and Garden grade II, 3 LBs	Remnant garden woodland compa	Remnant garden features lie in several ownerships and woodland compartments. Where parkland has been	
	CONDITION:	Generally unsatisfactory with major localised problems	converted to arable land or and light industrial use loss historic character and designed landscape intentions h occured. The southern portion of the estate, including		
and the second se	VULNERABILITY:	High	temple, is separa	ted from the core by a road. A	
Container Container	TREND:	Declining	recommended as	kland/conservation management plan is s spart of any Countryside Stewardship	
D Historic England	NEW ENTRY ?:	No	process.		
	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1000930	Contact: Kay Ric	hardson 0207 973 3647	
	SITE NAME:	Norris Castle. East Cowes	Norris is an exer	nplar marine villa with castellated model	
			farm/walled garden from 1799 by James Wyatt for Seymour as part of the early villa development on Solent. A particularly fine and unusual example of the historical completeness of its key parkland fea parkland architecture and setting survives mostly i Benign neglect allowed the parkland features to su relative to the Castle and farm that slowly decline		
	DESIGNATION:	Registered Park and Garden grade I, 12 LBs, part in RPG grade II*, part in CA			
	CONDITION:	Generally unsatisfactory with major localised problems			
	VULNERABILITY:	BILITY: High lack of management. With major dev		ent. With major development proposals	
	TREND: Declining		2022 a contextual report has been published to better understand the significance.		
© Historic England	NEW ENTRY?: No				
	OWNER TYPE: Commercial company				
	LIST ENTRY NUMBER: 1000927		Contact: Kay Ric	hardson 0207 973 3647	
SITE NAME:	Brading				
DESIGNATION:	Conservation Are	ea. 52 LBs	NEW ENTRY?:	No	
CONDITION:	Fair		TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	Lee Byrne (LPA) 01983 823552	
SITE NAME:	Carisbrooke, Ne	wport and Carisbrooke		, , ,	
SITE NAME: DESIGNATION:		•	NEW ENTRY?:	No	
	Conservation Are	•	NEW ENTRY?: TREND:	No	
DESIGNATION:		•			
DESIGNATION: CONDITION:	Conservation Are Poor	•	TREND:	No Deteriorating	
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium	ea, 37 LBs, 3 SMs	TREND:	No Deteriorating	
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	Conservation Are Poor Medium Cowes	ea, 37 LBs, 3 SMs	TREND: CONTACT:	No Deteriorating Lee Byrne (LPA) 01983 823552	
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION:	Conservation Are Poor Medium Cowes Conservation Are	ea, 37 LBs, 3 SMs	TREND: CONTACT: NEW ENTRY?:	No Deteriorating Lee Byrne (LPA) 01983 823552 No	
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION:	Conservation Are Poor Medium Cowes Conservation Are Poor	ea, 37 LBs, 3 SMs	TREND: CONTACT: NEW ENTRY?: TREND:	No Deteriorating Lee Byrne (LPA) 01983 823552 No Deteriorating	
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium Cowes Conservation Are Poor Medium	ea, 37 LBs, 3 SMs	TREND: CONTACT: NEW ENTRY?: TREND:	No Deteriorating Lee Byrne (LPA) 01983 823552 No Deteriorating	
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	Conservation Are Poor Medium Cowes Conservation Are Poor Medium Godshill	ea, 37 LBs, 3 SMs	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT:	No Deteriorating Lee Byrne (LPA) 01983 823552 No Deteriorating Lee Byrne (LPA) 01983 823552	

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ISLE OF WIGHT (UA) / ASHFORD

SITE NAME:	Newport, Newport and Carisbrooke			
DESIGNATION:	Conservation Area, 194 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552	
SITE NAME:	Ryde			
DESIGNATION:	Conservation Area, 310 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552	
SITE NAME:	Sandown			
DESIGNATION:	Conservation Area	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Lee Byrne (LPA) 01983 823552	

#### KENT


#### ASHFORD

© Historic Englar

	SITE NAME:	Palace Farmhouse, Market Place, Charing	The present farmhouse forms part of the north range of the former manor house of the Archbishops of Canterbury
	DESIGNATION:	Listed Building grade I, SM, CA	and includes part of the former chapel. The top floor is inaccessible and unoccupied. An options appraisal for the
	CONDITION:	Poor	whole site has been carried out with funding from Historic England.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
land	LIST ENTRY NUMBER:	1070756	Contact: David John 0207 973 3638



© Historic England





SITE NAME: Ruins of Church of St Mary, Possibly C13 church with tower built around 1500. Damaged during WWII by a VI flying bomb. Now ruinous Pluckley Road, Little Chart but with tower still standing to c.15m. High level Scheduled Monument and Listed stonework requires inspection, and the considerable DESIGNATION: Building grade II growth of ivy and other vegetation needs controlling. The grounds are well maintained and the site is open to the CONDITION Poor public. Vegetation clearance has been discussed with the OCCUPANCY: N/A owners. PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1004208 and 1329709 Contact: David John 0207 973 3638

© Historic England

D

Е

#### PRIORITY CATEGORIES

# Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good


repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM UÁ
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ASHFORD / CANTERBURY



SITE NAME:	Castle Toll Saxon burgh and medieval fort, Newenden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013041
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

CANTERBURY

- CAR	SITE NAME:	Monuments in the precinct of Canterbury Cathedral, The Precinct, Canterbury	Medieval ruinous structures of Christchurch Priory, which have suffered from years of decline. Major backlog of repairs; work has started with Historic England grant to
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I; 1 grade II*, 22 LBs, CA, WHS	Llanfrancs dormitory and the city wall. Slow progress is being made. Detailed evaluation of the various assets is being carried out in order to decide priorities.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
© Historic England	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1004195 and 1253715; 1085082; 1085079	Contact: David John 0207 973 3638

eric England	SITE NAME:	Greyfriars Monastery, Stour Street, Canterbury	Friary built in 1267 with chapel surviving over the river. Boundary walls from a Tudor house built on the site of the
	DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs, CA	friary are at risk from deterioration.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1005195 and 1242684	Contact: David John 0207 973 3638



© Histor

SITE NAME:	Dovecote at Burnt House Farm, Chartham	Cleverly designed dovecote of three storeys built into a slope and dated to C18. Original design saw pigs kept on
DESIGNATION:	Scheduled Monument, LB grade II, CA	ground floor providing heating for poultry on middle floor and doves on third floor. In need of repair. New owner plans to undertake repairs as part of proposals for future
CONDITION:	Poor	low-key use. Repairs carried out to the roof and doors. Further repairs required to the flooring.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1018874	Contact: David John 0207 973 3638

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CANTERBURY


	SITE NAME:	Horton Manor Chapel, Horton, Chartham	Two cell C14 chapel, now roofless. Planning Permission and Scheduled Monument Consent for the conversion of		
	DESIGNATION:	Scheduled Monument and Listed Building grade II	the oast houses to residential use have been granted and the works completed.		
	CONDITION: Poor				
	OCCUPANCY:	Part occupied/part in use			
	PRIORITY CATEGORY:	F (F)			
Active States	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1005150 and 1085714	Contact: Rebecca Lambert 0207 973 3630		



	SITE NAME:	Barn at Hardres Court, Upper Hardres	Late Cl5 to early Cl6 aisled timber barn. Damaged by fire in 1993. It would suit a variety of different forms of re-use
	DESIGNATION:	Listed Building grade II*, CA	which retain its characteristic open volume and leave exposed its impressive structural timbers.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1085505	Contact: Alice Brockway 0207 973 3655

© Historic England Archive


© Historic England



© Historic England

	SITE NAME:	Church of St Mary the Virgin, Church Lane, Chislet	Church with Norman nave and tower and later C13 chancel and aisles. Cement render on both north and
	DESIGNATION:	Listed Place of Worship grade I, CA	south sides is defective and coming away. Coursed rubble walls contain loose material particularly on south side and deterioration of quoins to south side of tower. Substantial
	CONDITION:	Poor	ivy coverage to east end. Hoppers need unblocking and some guttering on north side is failing. The building has
	PRIORITY CATEGORY:	C (C)	been the victim of heritage crime.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1085653	Contact: David John 0207 973 3638
nd			

© Historic England



5	SITE NAME:	Church of St Martin, Herne Street, Herne, Herne and Broomfield	A large church, predominantly of the C14, but with substantial C19 restoration. Roof tiles have slipped and there are other roof defects and rainwater goods are
and	DESIGNATION:	Listed Place of Worship grade I, CA	blocked and leaking. Also, there are issues with internal plasterwork. The building has been the victim of heritage crime. Several phases of repairs to the tower, chancel roof
	CONDITION:	Poor	and west front, funded by the National Lottery Heritage Fund Grants for Places of Worship and others have now
	PRIORITY CATEGORY:	B (C)	been completed.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1084972	Contact: David John 0207 973 3638

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CANTERBURY / DARTFORD / DOVER

SITE NAME:	Dane John Mound and Roman and medieval remain	ns in Dane John Ga	rden
DESIGNATION:	Scheduled Monument, 4 LBs, part in RPG grade II, CA	LIST ENTRY NUMBER:	1003780
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Enclosures west of Woodlands, Adisham		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1004191
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Anglo-Saxon cemetery on Hanging Hill, Bridge, im Bridge	mediately south we	st of Watling Street, Bishopsbourne
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021421
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	Yes
OWNER TYPE:	Private	CONTACT:	Rebecca Lambert 0207 973 3630
SITE NAME:	Rubury Butts bowl barrows, Womenswold / Noni	ngton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1427315
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Rebecca Lambert 0207 973 3630
DARTFORD			
SITE NAME:	Palaeolithic sites near Baker's Hole		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003557
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Roman enclosure south east of Vagniacae, Southfle	et	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004226
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
DOVER			
	SITE NAME: The Western Heights	The fortifications	of the Western Heights are a specta



	SITE NAME:	The Western Heights fortifications, Dover	The fortifications of the Western Heights are a spectacular complex of earthworks and structures that are the largest
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, part in CA	and most elaborate example of 19th century fortification in England. Various issues contribute to risk, including fragmented ownership and lack of co-ordinated
	CONDITION:	Poor	management; poor condition leading to a huge conservation deficit; lack of sustainable uses; poor
	OCCUPANCY:	Part occupied/part in use	connectivity to town centre; poor visitor infrastructure;
	PRIORITY CATEGORY:	C (C)	poor permeability and way finding; unmanaged vegetation that obscures historic form and views; and heritage crime.
	OWNER TYPE:	Mixed, multiple owners	_
	LIST ENTRY NUMBER:	1020298 and 1375598; 1375599	Contact: Paul Roberts 0207 973 3636

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS	

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 153

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / DOVER

	SITE NAME:	Fort Burgoyne, Connaught Barracks, Dover / Guston	1860s polygonal-plan fort now part of a later barracks. The earth-covered terraced casemates are vacant and the
	DESIGNATION:	Scheduled Monument	structures on the ramparts (the brick-built Haxo casemates) have been at risk from lack of maintenance and
	CONDITION:	Fair	invasive ivý growth. The site is owned by The Land Trust which is working on plans for its sustainable future.
	OCCUPANCY:	Vacant/not in use	Substantial progress for brick work repair and vegetation
	PRIORITY CATEGORY:	E (E)	control was made using Homes and Community Agency funds. Further vegetation works and conversion of the former Officers Stables has also been undertaken.
	OWNER TYPE:	Charity (non-heritage)	former Officers Stables has also been undertaken.
© Historic England Archive	LIST ENTRY NUMBER:	1004224	Contact: Liam Delaney 07387 533 659



© Historic England Archive

	SITE NAME:	St Radegunds Abbey, Abbey Road, Hougham Without	C13 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a
	DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II*; 1 grade II	ruinous state. The site is now a farm with roofed buildings used as barns and a farmhouse. These are in fair condition. Recent negotiations have looked at consolidation of the
	CONDITION:	Very bad	ruins and explore funding streams and options.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1005196 and 1070023; 1068889; 1356562; 1363382	Contact: David John 0207 973 3638

	SITE NAME:	Church of St George, Ham, Northbourne	Former church converted to a house. Saxon structure with C13 fenestration, restored in 1879-80. Wooden bell turret
ATTEN AN	DESIGNATION:	Listed Building grade II*	with shingle spire; chancel, nave and south porch. Severe fire which has destroyed most of the roof.
200 / / M	CONDITION:	Very bad	
THAN	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Private	
s	LIST ENTRY NUMBER:	1264237	Contact: David John 0207 973 3638

The Belvedere, Waldershare Park, Shepherdswell with

Listed Building grade I, RPG

Coldred

grade II

Very bad

C (C)

Vacant/not in use



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

© Historic England Archive

© Mark Pays



	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1051607	Contact: Alice Brockway 0207 973 3655		
	SITE NAME:	Church of St Martin, Church Hill, Great Mongeham	Church built of flint dating from C12 and later restored by Butterfield in C19. Kentish ragstone window tracery and		
	DESIGNATION:	Listed Place of Worship grade II*, CA	surrounds and quoins are deteriorating throughout the building. Investigation work looking at guttering and hoppers has been completed. Ground level water disposal		
	CONDITION:	Poor	is poor and is encouraging plant growth. Possible structural movement at north east corner of north aisle. Slipped		
	PRIORITY CATEGORY:	C (C)	tower louvres and vegetative growth on tower and north		
	OWNER TYPE:	Religious organisation	aisle roof.		
100	LIST ENTRY NUMBER:	1069782	Contact: David John 0207 973 3638		

© Historic England

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

Belvedere, 1725 to 1770, probably by Colen Campbell for Sir Henry Furnese. Located at the southern end of the

western side of an early CI8 Wilderness and overlooking the park to the north and south. Derelict for many years

and now in a ruinous state. Temporary scaffolding and a

protective canopy have been completed with grant aid

from Historic England.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / DOVER

	SITE NAME:	Church of St Mildred, Court Lane, Preston	The church dates from the C13 and was extended in the C14. It was remodelled by William White. It has a west
	DESIGNATION:	Listed Place of Worship grade I, CA	tower with nave having a roof that continues over the aisles with triangular dormers, and a chancel. The walls are cold and saturated at low level. Some of the eaves require
	CONDITION:	Poor	gutters, also the ground gutters are not draining away which is causing damp in the walls and floors. There is
	PRIORITY CATEGORY:	D (New entry)	a high water table. There is also condensation within the
	OWNER TYPE:	Religious organisation	church, and it is difficult to heat.
	LIST ENTRY NUMBER:	1376652	Contact: David John 0207 973 3638
oric England			

© Histor ng

A FURFATENTER	SITE NAME:	Church of St Margaret, High Street, St. Margaret's At Cliffe	Church of c1150 rebuilding of earlier building with late C12 tower. Restored in the C18 and 1864 by Ewan Christian.
	DESIGNATION:	Listed Place of Worship grade I, CA	Flint and rubble with red brick dressings and slate roof, with plain tiled roof to south side. Two stage west tower largely rebuilt; chancel, nave and aisles and north porch.
	CONDITION:	Poor	Some water ingress. Repairs are now (2023) being carried out to the tower and its roof.
A Streemen	PRIORITY CATEGORY:	F (C)	
rese of Canterbury	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1101743	Contact: David John 0207 973 3638

© Diocese of Canterbury

	SITE NAME:	Church of St Mary, Canterbury Road, Wingham	Church dating to c1200 with C13 chancel, C14 tower and C16 nave and aisle. Restored 1874-5 by Benjamin Ferrey,
	DESIGNATION:	Listed Place of Worship grade I, CA	particularly the chancel. Some repairs have been carried out to the tower gutter and stair turret. Further repairs are needed including stone work around the church, gutters
	CONDITION:	Poor	and soakaways, and the bases of the timber arcade columns are rotting.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
<b>x</b>	LIST ENTRY NUMBER:	1070091	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Ring ditch and enclosure 200yds (180m) east of Parsonage Farm, Preston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003121	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE: Mixed, multiple owners		CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Great Mongeham Anglo-Saxon cemetery, Sut	tton / Great Mongeham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003124	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE: Private, multiple owners		CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	London Road, Dover, Dover			
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	No significant change	
VULNERABILITY:	Medium	CONTACT:	G Simone Senior Heritage Officer (LPA) 01304 872480	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / DOVER / FOLKESTONE AND HYTHE

SITE NAME:	Mongeham Road, Great Mongeham, Great Mongeham			
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	No significant change	
VULNERABILITY:	VULNERABILITY: Medium		G Simone Senior Heritage Officer (LPA) 01304 872480	
SITE NAME:	Western Heights, Dover, Dover			
SITE NAME: DESIGNATION:	Western Heights, Dover, Dover Conservation Area, 2 LBs, 2 SMs	NEW ENTRY?:	No	
	0	NEW ENTRY?: TREND:	No Improving	
DESIGNATION:	Conservation Area, 2 LBs, 2 SMs			

#### FOLKESTONE AND HYTHE

© Historic England	SITE NAME:	The Leas Lift, including Waiting Rooms, Brake Houses and Railings, the Leas, Folkestone	The Listed grade II* Leas Lift, is a cliff funicular railway built in 1885 to transport people between The Leas, the beach and promenade. It is not operational and a Community
	DESIGNATION:	Listed Building grade II*, CA	Interest Company (CIC) has been formed to carry out repairs to bring it back into use. Historic England is
	CONDITION:	Poor	working closely with the CIC as they develop their proposals and conservation management plan, and
	OCCUPANCY:	Part occupied/part in use	continue to explore funding to deliver a repair scheme.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Community interest group	
	LIST ENTRY NUMBER:	1061185	Contact: Liz Pollard 0207 973 3650

Martello Tower No. 4, The

Leas, Folkestone

Ranges, Hythe

Poor

E (E)


Scheduled Monument

Part occupied/part in use

Government or agency

Scheduled Monument





SITE NAME:

DESIGNATION:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:



© Historic England

© Historic England



	LIST ENTRY NUMBER:	1017352	Contact: David John 0207 973 3638	
	SITE NAME:	Martello Tower No. 9, Shorncliffe Camp, Hythe / Sandgate	Martello tower, 1806. Derelict, disposed by Ministry of Defence to private owner. The preservation of archaeological and historical significance will be the main	
	DESIGNATION:	Scheduled Monument and Listed Building grade II		
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1017226 and 1061167	Contact: Rebecca Lambert 0207 973 3630	
			ABBREVIATIONS	

improved.

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Е
  - Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

A good example of a Martello tower but now derelict and

situated in the grounds of a private house. Tower is used in

part for an art installation but a long term sustainable use is

not agreed and repair of fabric and removal of obscuring

Contact: Rebecca Lambert 0207 973 3630

The original fort of 1806 is a massive brick circular structure within a dry moat, and has C20 additions.

Located on Ministry of Defence ranges, some parts have

and later additions. A Conservation Management Plan was

prepared in 2005. The seaward defences have now been

been brought back into use as a military training facility. There is brickwork deterioration to both the original fort

vegetation is necessary.

#### ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park CA LB LPA

- NP
- Registered Park and Garden Scheduled Monument RPG SM
- UÁ
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / FOLKESTONE AND HYTHE

	SITE NAME:	Martello Tower No. 5, Sandgate	Martello tower situated in the grounds of a school and
	DESIGNATION:	Scheduled Monument, part in CA	vacant but with potential for re-use by the school. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of
	CONDITION:	Fair	proposals to convert Martello towers for residential use.
	OCCUPANCY:	Vacant/not in use	
ZAX E	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Educational (state sector)	
**************************************	LIST ENTRY NUMBER:	1017172	Contact: David John 0207 973 3638

© Historic England



SITE NAME:	Martello Tower no 6, Shorncliffe Camp, Sandgate	A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion
DESIGNATION:	Scheduled Monument and Listed Building grade II, part in CA	scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner
CONDITION:	Poor	now under discussion.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1017173 and 1068919	Contact: Rebecca Lambert 0207 973 3630



© Historic England Archive

Net	SITE NAME:	Martello Tower no 7, Shorncliffe Camp, Sandgate	A Martello tower sold by the Ministry of Defence to a private owner who proposed a repair and conversion
All I	DESIGNATION:	Scheduled Monument and Listed Building grade II	scheme, including residential use. Permissions now lapsed with no works having started, including for agreed enabling development. Alternative solution under a different owner
100	CONDITION:	Poor	now under discussion.
	OCCUPANCY:	Vacant/not in use	
2.40	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1017174 and 1068920	Contact: Rebecca Lambert 0207 973 3630

	SITE NAME:	Church of St James, Elmsted	Church with origins in the CII, but of multiple subsequent
	DESIGNATION:	Listed Place of Worship grade I	phases. Although some repairs have been undertaken recently, including an overhaul of the roofs and internal
a state and a	CONDITION:	Poor	redecoration, there are corroding rainwater goods, blocked hoppers and gullies, and vegetation growth. The
· 百合户	PRIORITY CATEGORY:	C (C)	building has been the victim of heritage crime.
	OWNER TYPE:	Religious organisation	
<u>》题题</u> 图	LIST ENTRY NUMBER:	1241752	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Church of St Mary, Stowting	Church of C13. Chancel restored 1843-4 by Carpenter,
	DESIGNATION:	Listed Place of Worship grade II*	rest 1876 and 1890. North aisle and tower added 1857-68 by Slater. Flint with stone dressings. Plain tile roof. Nave,
	CONDITION:	Poor	south porch, chancel with north lean-to, north aisle with west tower. The roof is in poor condition and reason for inclusion in the Register.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1061070	Contact: David John 0207 973 3638

© Diocese of Canterbury

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / FOLKESTONE AND HYTHE / MAIDSTONE

SITE NAME:	Roman villa, Folkestone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005158
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Motte and Bailey Castle 200m north west of Stown	ing Church, Stowti	ng
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012099
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow 150m north east of Red House Farm	, Swingfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011765
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bowl barrow at Minnis Beeches, Swingfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011766
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

#### MAIDSTONE

	SITE NAME:	II, Lower Stone Street, Maidstone	A large early C18 house of three storeys. Some repairs and redecoration have been carried out in recent years and it is
	DESIGNATION:	Listed Building grade II*	now partly occupied, but it continues to suffer from a lack of appropriate regular maintenance.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
1 Carlos	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1086332	Contact: Alice Brockway 0207 973 3655



SITE NAME:	The Dungeons at the Archbishop's Palace, Mill Street, Maidstone	Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems. Early discussions with the owners about repairs
DESIGNATION:	Listed Building grade II*	have taken place.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1086309	Contact: David John 0207 973 3638

© Historic England

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### ----

HERITAGE AT RISK 2023 / LONDO	on and south east	/ MAIDSTONE	
A An	SITE NAME:	Boxley Abbey: Barn and Precinct Walls, including Gatehouse, Boxley, Boxley	Parts of a Cistercian abbey founded in 1143. Main threat is to medieval roofed range converted to a barn (grade 1 listed) and extensive precinct walls. Eastern end of the barn
	DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs	has been repaired with Historic England and Natural England grant-funding. The western end of the barn is under profiled steel sheeting; it requires a full scheme of
ALC: ST	CONDITION:	Poor	repairs and a sustainable use found for the entire building supported by a regular maintenance programme. Precinct
T. Marrie Lass	OCCUPANCY:	Vacant/not in use	walls require a comprehensive condition survey to inform a
ALC: ALC: AND ALC: AN	PRIORITY CATEGORY:	C (C)	repair scheme and address the collapsed sections and heavy plant growth.
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1012264 and 1086229	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	Former St Andrews Chapel, Boarley Lane, Boxley Abbey, Boxley	Former late C15 chapel, no longer used for worship, but converted to a house early on in its history. Unoccupied and in need of repair. Location affected by proximity of
	DESIGNATION:	Listed Building grade II*	motorway. Purchased by the Society for the Protection of Ancient Buildings as an exemplar in sensitive conservative
	CONDITION:	Poor	repair and craft skills training. Improved security, temporary propping, structural monitoring, ground
	OCCUPANCY:	Vacant/not in use	clearance and survey work carried out. A scheme for the
	PRIORITY CATEGORY:	F (D)	repair of the building is underway with financial support from the Architectural Heritage Fund, The Pilgrim Trust
	OWNER TYPE:	Charity (heritage)	and Historic England.
© Historic England	LIST ENTRY NUMBER:	1185580	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	Dovecotes at Leeds Priory, Lower Street, Leeds	Mid C16, overgrown and roofless dovecotes from a post- Dissolution mansion. The building is at risk from serious
	DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	structural decay and extensive damaging vegetation growth. Possible proposal for enabling development.
	CONDITION:	Very bad	
A REAL ROOM	OCCUPANCY:	Vacant/not in use	
The state of the state of the	PRIORITY CATEGORY:	A (A)	
Allistation of Appleing	OWNER TYPE:	Private	
© Historic England Archive	LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275	Contact: Rebecca Lambert 0207 973 3630
Contraction of the second	SITE NAME:	Slype and associated remains at Leeds Priory, Lower Street, Leeds	The remains of a medieval building with post-medieval brickwork additions and attached walls. It was potentially related to monastic water management. Formerly known
	DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	as "The Abbey" and more recently as "The Slype". The buildings are at risk of serious structural decay and extensive damaging vegetation growth.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	

© Historic England Archive

	Leeds	related to monastic water management. For
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	as "The Abbey" and more recently as "The S buildings are at risk of serious structural dec extensive damaging vegetation growth.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275	Contact: Rebecca Lambert 0207 973 3630

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MAIDSTONE

	SITE NAME:	Church of All Saints, Mill Street, Maidstone	Large Perpendicular church of the late CI4. Extensive high- level vegetation and erosion of stonework. Blocked and
	DESIGNATION:	Listed Place of Worship grade I	damaged rainwater goods and drains have resulted in water ingress and internal dampness. Wall paintings in chancel are also suffering damage. Extensive roof repairs are necessary.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1225056	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Church of St Nicholas, Lower Street, Leeds	Medieval church built of ragstone and tufa with a broad Romanesque tower. Roofing and stonework are in poor
	DESIGNATION:	Listed Place of Worship grade I	condition. An application to the National Lottery Heritag
	CONDITION:	Poor	unsuccessful. However, some roof repairs have taken place but more repairs, particularly to the stonework are
	PRIORITY CATEGORY:	C (C)	needed.
	OWNER TYPE:	Religious organisation	
- 161	LIST ENTRY NUMBER:	1086125	Contact: David John 0207 973 3638

© Historic England

	SITE NAME:	Church of St Mary the Virgin, Thurnham Lane, Thurnham	Church of C12 to early C17. North chapel of galleted stone, porches of small univer blocks of stone, rest
	DESIGNATION:	Listed Place of Worship grade I	random flint and stone. Plain tile roofs. West tower, continuous nave and chancel with opposed north and
	CONDITION:	Poor	south porches at the west end. Rectangular north chape towards east end of nave. Roofs over nave, chancel and chapel require replacement and east wall of the chancel
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	in a poor state; all contributing factors to the building's risk.
	LIST ENTRY NUMBER:	1086165	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Leeds Priory: Augustinian Priory of St Mary and St N of the C18 Meredith Mansion, Leeds	Nicholas with asso	ciated dovecotes and slype, and the site
DESIGNATION:	Scheduled Monument and Listed Buildings - 4 grade II, 4 LBs	LIST ENTRY NUMBER:	1011027 and 1185691; 1336305; 1086132; 1344275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Rebecca Lambert 0207 973 3630
SITE NAME:	Binbury motte and bailey castle, Thurnham		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1010713
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Maidstone Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Paul Robertshaw (LPA) 01622 602723

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### **SEVENOAKS**



SITE NAME:	Remains of corner tower to former Archbishops Palace, Otford
DESIGNATION:	Scheduled Monument, LB grade II
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005197

Remains of gatehouse range to early C16 Archbishops Palace. Ruinous parts need consolidation work. Following Urgent Repair Works in 2017, a local community group has leased the building and is looking at options for its repair and re-use. A report and scheme have been commissioned and an initial phase of repairs have been carried out with funding from various sources. Further work is still required, and options are being pursued.

© Historic England Archive

Contact: David John 0207 973 3	8638

SITE NAME:	Chapel, Maplesco	ombe, West Kingsdown		
DESIGNATION:	Scheduled Monu	Scheduled Monument, LB grade II		1005134
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree grow	rth	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Combe Bank, Brasted / Sundridge with Ide Hill	A classical landscape garden and small park surrounding palladian villa associated with some of the greatest artist exponents of the early pictureque movement. Sold and divided up the house and gardens becaming a school in 1924. Numerous remant built features survive in varying condition in the gardens which suffered considerable ste damage in 1987. Bissected by the M25, development,	
	DESIGNATION:	Registered Park and Garden grade II*, 17 LBs		
	CONDITION:	Extensive significant problems		
	VULNERABILITY:	High	fragmentation of ownership and management is a th	ownership and management is a threat. A
	TREND:	Declining		ect to deliver a Conservation Management to help understanding and management of

© Historic England



© Historic

Contact: Kay Richardson 0207 973 3647

the park and garden's significance.

#### SEVENOAKS / TUNBRIDGE WELLS

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

No

1000365

Mixed, multiple owners

	GE TTELES		
tic England	SITE NAME:	Swaylands, Bidborough / Penshurst	Small landscape park with terraced gardens and pleasure grounds, including extensive rockwork developed in the
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs	late CI9. Now split into several ownerships with the house converted into apartments, development of residential facilities is fragmenting the park and inappropriate forms of
	CONDITION:	Generally unsatisfactory with major localised problems	management may precipitate loss of historic design integrity. Understanding the presentation of the lower lake and kitchen garden as part of the parkland landscape, which
	VULNERABILITY:	Medium	are in separate ownership, much neglected and subject to
	TREND:	Stable	change through development, is also imperitive to ensure appropriate stewardship.
	NEW ENTRY?:	No	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1001280	Contact: Kay Richardson 0207 973 3647

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SWALE

**SWALE** 

	SITE NAME:	The Boat Store, Sheerness	Boat store, built in 1859. Since the destruction of the
	SHE NAME:	Dockyard, Sheerness	Crystal Palace and the first South Kensington Museum, this
	DESIGNATION:	Listed Building grade I	is the earliest surviving example of a multi-storey iron- frame and panel structure. Its condition is rapidly
	CONDITION:	Very bad	deteriorating. Discussions with the Local Planning Authority and Port Company about its repair and reuse are on-going.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1273160	Contact: David John 0207 973 3638



© Historic England Archive

Moated artillery fortifications from C17-C20. A major SITE NAME: Sheerness Defences, Swale, complex defending the dockyard. A repair programme Sheerness needs to be agreed and implemented. Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1005145 and 1259029 Contact: David John 0207 973 3638

Former Working Mast House,

26, Jetty Road, Sheerness

Dockyard, Sheerness

Vacant/not in use

Poor

C (C)

1061036

Listed Building grade II\*



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England Archive



OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1244509 Contact: David John 0207 973 3638 SITE NAME: Parish Church of the Holy HolyTrinity is a large medieval church with Saxon Trinity, North Street, Milton herringbone masonry. There are issues with damp walls and staining of plasterwork as well as slipped tiles and Regis, Sittingbourne. stonework. Some repairs have been carried out to the DESIGNATION: Listed Place of Worship grade I tower and north windows of the nave. CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

vacant.

© Historic England

	SITE NAME:	Church of St Peter, Church Road, Oare	A predominantly Perpendicular church, much restored b Joseph Clarke in 1868. The church has had serious structural movement at its east end with disturbance to t flooring and serious cracking to the walls at the east end. This appears to have been partly resolved, but there is st evidence of movement that requires monitoring. Repairs
	DESIGNATION:	Listed Place of Worship grade I	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	are also required to the spire shingles.
	OWNER TYPE:	Religious organisation	
SA ELS	LIST ENTRY NUMBER:	1069126	Contact: David John 0207 973 3638

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: David John 0207 973 3638

#### ABBREVIATIONS

WHS

Large C19 industrial building used as part of a complex for

constructing and storing masts and small boats. Used in the

past for storage within the commercial port, it is now

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ

Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SWALE

	SITE NAME:	Church of St Peter and St Paul, Water Lane, Ospringe	A C13 church, with later accretions, all substantially restored in 1858-70 by EL Blackburne. Despite its apparent
× 1	DESIGNATION:	Listed Place of Worship grade II*, CA	fair condition, the north and the south side of the church is suffering from serious internal damp as a result of multiple slipped tiles, blocked rainwater goods and extensive ivy
	CONDITION:	Poor	growth. There is probable structural movement in the chancel.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1343988	Contact: David John 0207 973 3638
© Historic England			



	SITE NAME:	Church of St Giles, Church Road, Tonge	Originally C12 flint church with unconventional valley gutter arrangement. Structural monitoring has established
	DESIGNATION:	Listed Place of Worship grade I	that movement is generally stable. The state of the fabric has been improved. The congregation is applying for a grant to conserve the medieval wall paintings and is about
	CONDITION:	Poor	grant to conserve the medieval wall paintings and is about to have the building re-wired.
	PRIORITY CATEGORY:	C (C)	to have the building re wired.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1322821	Contact: David John 0207 973 3638

© Historic England

SITE NAME:	Cellar Hill and Greenstreet, Lynsted with	Kingsdown / Teynham	
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Milton Regis High Street		
DESIGNATION:	Conservation Area, 37 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Newington High Street, Newington		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Marine Town, Sheerness		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Mile Town, Sheerness		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Sheerness: Royal Naval Dockyard & Blue	town, Sheerness	
DESIGNATION:	Conservation Area, 13 LBs	NEW ENTRY ?:	No
		TREND:	Deteriorating
CONDITION:	Very bad	Interveb.	Deteriorating

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SWALE / THANET

SITE NAME:	Sittingbourne High Street		
DESIGNATION:	Conservation Area, 26 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Simon Algar (LPA) 01795 417375
SITE NAME:	Upchurch		
DESIGNATION:	Conservation Area, LB grade I	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
	1001	THEIRE.	Deteriorating

#### THANET



	SITE NAME:	Dreamland Cinema, Marine Terrace, Margate	Cinema, 1935. The first English cinema in the style based on the Titania Palast of Berlin, a style subsequently used
	DESIGNATION:	Listed Building grade II*	extensively by Odeon. The first major phases of a programme of repairs and reinstatement of architectural
	CONDITION:	Fair	features are now complete. Parts are now in use for the Dreamland Park and the remainder is proposed for a
	OCCUPANCY:	Part occupied/part in use	variety of entertainment uses.
	PRIORITY CATEGORY: E (E)		
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1260315	Contact: Alice Brockway 0207 973 3655

© Historic England



© Historic England



© Thanet District Council

Contact: Liz Pollard 0207 973 3650 Late medieval grain barn on land formerly owned by St SITE NAME: Barn about 50 metres east of Augustine's Abbey, Canterbury. In a very bad condition Ozengell Grange, Haine Road, with missing roof tiles and structural issues. Discussions are Ramsgate on-going about how repairs may be organised. DESIGNATION: Listed Building grade II\* CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1336669

The Clock House, Royal

Listed Building grade II\*

Part occupied/part in use

Harbour, Ramsgate

Very bad

C (C)

1336325

Local authority

Contact: Alice Brockway 0207 973 3655

heritage crime have been strengthened.

The harbour clock house of 1817 designed by Benjamin

on the Ramsgate Meridian Line. Covid-19 Emergency

required to address the tower's worsening structural

Wyatt and George Louch. Altered by John Rennie. Located

Heritage At Risk Response funding saw repairs to the roof

issues. Issues with damp need to be addressed. Forms part of the Levelling Up Fund programme. Plans need to be

and high-level masonry (2021). A full scheme of repairs is

developed to see the building fully repaired and brought back into a sustainable use. Measures to prevent further



	SITE NAME:	Church of St George, Broad Street, Ramsgate	Prominent church with octagonal top to tower. Although some repairs to the upper tower and roofs, the building is
	DESIGNATION:	Listed Place of Worship grade I	at risk due to continuing problems from heritage crime, as well as external stone erosion and damage to internal
	CONDITION:	Poor	plaster from water ingress.
No.	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1085430	Contact: David John 0207 973 3638

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UÁ Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / THANET / TONBRIDGE AND MALLING

and the	SITE NAME:	Church of St Augustine of England, St Augustine's Road, Ramsgate	Constructed by AWN Pugin and containing his tomb. The site consists of a churchyard to the south and a cloister to the north with chapels, sacristy and ancillary
. 801	DESIGNATION:	Listed Place of Worship grade I	accommodation. The church comprises a nave, crossing with tower and confessional, chancel, south aisle and
Con R.	CONDITION:	Poor	chapel. A National Lottery Heritage Fund grant for Places of Worship addressed urgent repairs to roofs, gutters and
	PRIORITY CATEGORY:	C (C)	high-level masonry in 2010 with further phases in 2011,
	OWNER TYPE:	Religious organisation	2012 and 2013. The north range was repaired with a Culture Recovery Fund grant in 2022. Further works are
	LIST ENTRY NUMBER:	1281779	still required which are being identified.
oric England			Contact: David John 0207 973 3638

© Histor

SITE NAME:	Quex Park settlements, Birchington / Westgate-on-Sea		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005137
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Anglo-Saxon cemetery, Dane Valley Road	, Broadstairs and St. Peters	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003601
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement one mile (1610m) east of villag	ge, Manston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005135
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Anglo-Saxon cemetery south of Ozengell	Grange, Manston / Ramsgate	e
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004228
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Ramsgate		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Josie Sinden (LPA) 01843 577126

#### TONBRIDGE AND MALLING

	SITE NAME:	Church of All Saints, Snodland	Church with C12 origins restored and extended by
	DESIGNATION:	Listed Place of Worship grade I, CA	Blomfield in C19. Poor stonework repairs have been carried out in the past including rendering walling stones and dressings with a cement based mortar which is failing.
	CONDITION:	Poor	Areas of deeply eroded stonework and defective rainwater drainage system. High level stonework and plaster repairs
	PRIORITY CATEGORY:	D (D)	have been successfully completed using funds from the
	OWNER TYPE:	Religious organisation	National Lottery Heritage Fund Grants for Places of Worship scheme, but further phase of repairs required for
	LIST ENTRY NUMBER:	1347897	the lower level stonework and drainage.

Contact: David John 0207 973 3638

© Historic England

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

n

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS


- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TONBRIDGE AND MALLING / TUNBRIDGE WELLS

SITE NAME:	Town Banks, Tonbridge		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1003599
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Liam Delaney 07387 533 659
SITE NAME:	Romano-British villa, Anglo-Saxon cemetery and	associated remains a	t Eccles, Aylesford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011770
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

#### TUNBRIDGE WELLS



Loota.	SITE NAME:	Bedgebury Park, Stable Courts and Garden Terraces, Goudhurst	Country house, formerly a school, with a core of 1688 with C18 stables adjoining. The house was altered in c1838 and 1854-1855. Originally red brick now clads in sandstone
	DESIGNATION:	Listed Building grade II*	ashlar with a slate roof. French style roofs with large- shallow H-plan. Entrance front of three storeys with two
	CONDITION:	Poor	attic storeys. The house has consent for conversion to residential which has been partially implemented. It is
TITTT	OCCUPANCY:	Vacant/not in use	furnished but not currently occupied. Some roof repairs
C Incorder The	PRIORITY CATEGORY:	C (New entry)	have been carried out, but there are issues with gutters and water ingress which has caused problems internally to part
	OWNER TYPE:	Private	of the property.
© Historic England	LIST ENTRY NUMBER:	1084710	Contact: David John 0207 973 3638

SITE NAME:	Royal Tunbridge Wells, Frant / Rusthall		
DESIGNATION:	Conservation Area, 266 LBs, 2 RPGs	NEW ENTRY?:	No
CONDITION:	At risk	TREND:	Improving
VULNERABILITY:	Unknown	CONTACT:	Mark Stephenson (LPA) 01892 526121

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TUNBRIDGE WELLS / KENT (OFF)

#### KENT / EAST SUSSEX

#### TUNBRIDGE WELLS / WEALDEN

SITE NAME:	High Rocks Camp (see also Wealden, East Sussex), Frant			
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1003816	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	




© Historic England

Extensive significa	int problems	TREND:	Declining		
Arable ploughing		NEW ENTRY?:	No		
Private, multiple o	owners	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Bayham Abbey, Frant / Lamberhurst	informal pleasure	Late C19 mansion gardens with formal terraces and informal pleasure grounds set within a Humphry Repton		
DESIGNATION:	Registered Park and Garden grade II, 8 LBs, SM	by English Herita	ocused on the abbey ruins. Now managed ge. Partly in East Sussex and Kent. The ed in the 1970s with further fragmentation		
CONDITION:	Generally unsatisfactory with major localised problems	landscape fabric	Mixed arable conversion has impacted the integrity supporting the composition of the land plan exists in part around Bayham		
VULNERABILITY:	Medium	Old Abbey (201)	2) and recommendation of a joint		
TREND:	Stable		urkland plan process have been made rside Stewardship advice.		
NEW ENTRY ?:	No	,	·		
OWNER TYPE:	Mixed, multiple owners				
LIST ENTRY NUMBER: 1000257		Contact: Kay Ric	hardson 0207 973 3647		

KENT (OFF)

· · ·			
	SITE NAME:	Northumberland, Goodwin Sands	Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. The first third rate
	DESIGNATION:	Protected Wreck Site, part in PWS	ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships requested. The warship foundered on
	CONDITION:	Extensive significant problems	Goodwin Sands during the 'Great Storm' of 1703. The site has continued to experience significant exposure due to
	VULNERABILITY:	Medium	sediment migration and associated threats. The licensee
CHER STR	TREND:	Declining	and Historic England are in the process of formulating a plan to mitigate these risks.
	PRIORITY CATEGORY:	E (E)	
© Pascoe Archaeology Services and MSDS Marine	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1000058	Contact: Hefin Meara 07879 113318



SITE NAME:	Restoration, Goodwin Sands	Although there is no definite evidence, this wreck of a
DESIGNATION: CONDITION: VULNERABILITY:	Protected Wreck Site, part in PWS	wooden warship is thought to be the remains of the Restoration, a Third Rate 70-gun warship built 1678 as part of Samuel Pepys' regeneration of the English navy. Along
	Extensive significant problems	with the Northumberland and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of
	Medium	1703.Site currently at its most exposed. Historic England
TREND:	Declining	nded project undertaken 2021 to record site and work ontinues.
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1000057	Contact: Hefin Meara 07879   33 8

© University of St Andrews and Wessex Archaeology

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

t

#### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / KENT (OFF) / MEDWAY (UA)

		···=··· (•··) / ··== ···· (•··)	
	SITE NAME:	Rooswijk, towards the north eastern end of the Kellett Gut	The VOC (Dutch East Company) ship Rooswijk was built in Amsterdam in 1737 but stranded on the Goodwin Sands
an Car	DESIGNATION:	Protected Wreck Site	in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice
	CONDITION:	Generally unsatisfactory with major localised problems	of large-scale overseas commerce between the Netherlands and Asia during the C18. the Goodwins, The site was visited in 2022 and new areas of the wreck site are
	VULNERABILITY:	High	being exposed due to the movement of sediment. The site
Carl and	TREND:	Declining	appears to have been impacted by fishing activity and this incursion has been reported to Kent Police.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1000085	Contact: Hefin Meara 07879     33   8

MEDWAY (UA)

© RCE

© Histor

( )			
	SITE NAME:	Brompton Lines, Chatham	Landward defences to dockyard at Chatham, subsequently used in part as a pleasure ground for officers. Defences cross Ministry of Defence owned land, housing and Brompton Barracks. Section between Sallyport and Prince of Wales bastion (including the Couvre Porte) are most in need of conservation.
	DESIGNATION:	Scheduled Monument, part in CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
oric England	LIST ENTRY NUMBER:	1003364	Contact: Rebecca Lambert 0207 973 3630

٩.	ale.	
	-	
Car		
	Mannan	

A Royal Commission fort circa 1860, in the Medway SITE NAME: Fort Darnet Estuary. Constructed as part of the 1859 Royal DESIGNATION: Scheduled Monument Commission inspired refortification programme of the 1860s and 70s to protect Chatham dockyard. Partially CONDITION: Very bad flooded. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1019642 Contact: Rebecca Lambert 0207 973 3630

© Historic England Archive

	SITE NAME:	No. 8 machine shop, Dock Head Road, Chatham Dockyard	1840 former dry dock cover which was later used as a Machine Shop but is now disused. Cladding removed so the cast iron members and joints are now corroding. Applications to repair and convert it for leisure uses were approved by the Local Authority but not fully implemented. An updated application for its conversion to a retail use has not yet been determined.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Government or agency	
land	LIST ENTRY NUMBER:	1267822	Contact: Alice Brockway 0207 973 3655

© Historic Engla



		1207022	Contact. Alice Brockway 0207 775 5055	
	SITE NAME:	351, High Street, Rochester	Brewery mansion. Early C18, refronted early C19 and with	
	DESIGNATION:	Listed Building grade II*, CA	C20 alterations and additions as a shop to front. Painted brick, slate roofs. Last used as a shop in 1980s the fittings	
	CONDITION:	Poor	for which have been removed. Later industrial buildings to the rear. Empty since closed as a shop; however a	
	OCCUPANCY:	Vacant/not in use	programme of repairs is underway.	
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1320136	Contact: Alice Brockway 0207 973 3655	

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MEDWAY (UA)


	SITE NAME:	Cliffe Explosives Works, Cliffe and Cliffe Woods	Extensive remains of former explosive works dating from around 1890 with rapid expansion during First World War
	DESIGNATION:	Scheduled Monument	and in use until the 1920's. Constructed of re-inforced concrete but with severe deterioration and collapse. No
	CONDITION:	Poor	public access.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1428315	Contact: David John 0207 973 3638

© Historic England

CT Star	SITE NAME:	Cliffe Fort, Cliffe and Cliffe Woods	Fort c1860. Fort is now flooded. Much of it is stable due to massive construction, but significant detail is vulnerable to
Contraction of the local division of the loc	DESIGNATION:	Scheduled Monument	decay. The building has been the victim of heritage crime. Remains of Brennan Torpedo Rail are also vulnerable to
	CONDITION:	Very bad	erosion. Historic England has carried out a detailed survey. Investigation is to be carried out as to the source of the
	OCCUPANCY:	Vacant/not in use	flood water.
	PRIORITY CATEGORY:	C (C)	
10 mg	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1003403	Contact: David John 0207 973 3638



© Historic England Archive



Distance	SITE NAME:	Barn 30 yards south east of the manor, Upnor Road (south side), Frindsbury Extra	Medieval barn, redundant for agricultural use and subject to major fire damage. The reconstruction of fire damaged bays and a programme of repair was completed in 2019. A
A VALVER	DESIGNATION:	Listed Building grade I, CA	planning application for the partial conversion of the barn to a wedding venue was approved in 2021.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1204320	Contact: Alice Brockway 0207 973 3655



	LIST ENTRY NUMBER:	1204320	Contact: Alice Brockway 0207 973 3655
	SITE NAME:	Cockham Wood Fort, Hoo St. Werburgh	A rare C17 artillery fort. The brick lower battery is very decayed as it is washed by the tidal Medway. The higher
	DESIGNATION:	Scheduled Monument	earthwork batteries survive but in woodland, with the remains of a redoubt and commander's house.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
9	LIST ENTRY NUMBER:	1003362	Contact: Rebecca Lambert 0207 973 3630

© Historic England Archive

PRIORITY CATEGOR	RIES
------------------	------

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious now user (applicable only obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MEDWAY (UA)

N.	SITE NAME:	Fort Hoo, Hoo St. Werburgh	Sister fort to Fort Darnet circa 1860. Fort lies abandone		
	DESIGNATION:	Scheduled Monument	on an island in the Medway.		
	CONDITION:	Poor			
	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Commercial company			
	LIST ENTRY NUMBER:	1019643	Contact: Rebecca Lambert 0207 973 3630		

© Historic England Archive

	SITE NAME:	Coastal artillery defence structures on the Isle of Grain, including the Artillery Tower (Grain Tower), Isle of Grain	19th and 20th century gun emplacements and related structures, and artillery tower of 1855 with C20 additions The tower is abandoned and surrounded by the sea at hig tide. All structures suffer from vandalism and decaying fabric.	
	DESIGNATION:	Scheduled Monument and Listed Building grade II		
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant/not in use		
England	PRIORITY CATEGORY:	C (C)		
C England	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1019955 and 1204520	Contact: Rebecca Lambert 0207 973 3630	
	SITE NAME:	Church of St John the Divine, Railway Street, Chatham	Italianate style church of 1820-21 by Sir Robert Smirke, 1863 apse by GM Hills. It reopened in April 2021 having	
N	DESIGNATION:	Listed Place of Worship grade II*	been closed for around 25 years. Grant to carry out emergency works to the roof and interior rotting timber	
10100	CONDITION:	Fair	has now been completed, part funded by Historic England and the Church Commissioners. Further works have been	
illi, 🚟	PRIORITY CATEGORY:	F (New entry - re-assessed)	carried out to bring the building back into community use,	
	OWNER TYPE:	Religious organisation	including as a church, but there are still further works to b done.	
	LIST ENTRY NUMBER:	1268218	Contact: David John 0207 973 3638	

© Historic England

© Histor

SITE NAME:	Gillingham Green		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Ross Crayford (LPA) 01634 336655
SITE NAME:	Halling		
DESIGNATION:	Conservation Area, 4 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Ross Crayford (LPA) 01634 336655
SITE NAME:	Railway Street		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Ross Crayford (LPA) 01634 336655
	-		, , ,
SITE NAME:	Rainham		
SITE NAME: DESIGNATION:	Rainham Conservation Area, 12 LBs	NEW ENTRY?:	No
		NEW ENTRY?: TREND:	No
DESIGNATION:	Conservation Area, 12 LBs		

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

```
implemented.
C Slow decay; no solution agreed.
```

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### MILTON KEYNES (UA)

1	
AT IT	
	States -
1 1 11	- Bar
Salar Maria	

SITE NAME:	Church of St Peter, Gayhurst Court, Gayhurst
DESIGNATION:	Listed Place of Worship grade I, RPG grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1211931

Renaissance design, built in 1728 for the Wrighte family. Only the crypt remains from the previous medieval church. Limestone with grey rusticated plinth with yellow ashlar above. Interior: ashlar stone above panelled dado, plaster ceilings. Nave walls of 5 bays with Corinthian pilasters. Two-stage west tower, arcaded cupola and ogee domed roof. Water penetrating cupola and tower resulting in timber decay of the structure. An application for a National Lottery Heritage Fund Grants for Places of Worship in 2017 was unsuccessful but these structural repair works remain urgent.

Contact: Rachel James 0207 973 3153

© Bryan Martin

SITE NAME:	St Martin's Chapel (site of), Emberton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021373
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Moated site 70m south of Long Plantation, Ha	inslope Park, Hanslope	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011303
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Moated site 410m south east of Maukins, Har	dmead	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018726
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Wolverton, Wolverton and Greenleys / Stant	onbury	
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Simon Peart (LPA) 01908 252613

### **OXFORDSHIRE**

### CHERWELL

© Historic England



SITE NAME:	Ruins of Hampton Gay Manor House, Hampton Gay and Poyle	Rı Tl
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	pr pr w
CONDITION:	Very bad	sc
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	F (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1006334 and 1220230	С

Ruin of a late CI6 manor house which burnt down in 1887. he ruin is in very poor condition, suffering from structural roblems and with substantial vegetation growth. A repair roject to consolidate and stabilise the ruin is underway vith the benefit of an Environmental Land Management cheme.

Contact: Rachel James 0207 973 3153

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CHERWELL

	SITE NAME:	Defence and ancillary structures at RAF Bicester, Bicester, Launton	The most complete and strongly representative example of an RAF airbase from the interwar expansion, built as a bomber station as part of the 1920s Home Defence
	DESIGNATION:	Scheduled Monument, CA	Expansion Scheme. In 2016 and 2018 grant aided repairs to
		,	scheduled airfield structures were completed and further repairs to the Watch Office have been completed with the
© Historic England	CONDITION:	Poor	benefit of the Covid-19 Emergency Heritage at Risk
	OCCUPANCY:	Vacant/not in use	Response Scheme. Repairs are required to the southern bomb stores and a use for it identified.
	PRIORITY CATEGORY:	F (F)	bomb stores and a use for it identified.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1021455	Contact: Rachel James 0207 973 3153

	SITE NAME:	Church of St Mary, Horse Fair, Banbury	St Mary's Church Banbury is a late C18 classical church with a distinctive tower by S P Cockerell with additions by
	DESIGNATION:	Listed Place of Worship grade I, CA	C R Cockerell 1818-22. Listed Places of Worship Roof Repairs Grant in 2015 implemented in early 2016. Urgent repairs to the east end funded by the National Lottery
	CONDITION:	Poor	Heritage Fund Grant for Places of Worship have been completed. 2021 Covid 19 Recovery Fund Grant has been
	PRIORITY CATEGORY:	D (D)	used to address problems with the rainwater goods.
	OWNER TYPE:	Religious organisation	Further funding for high level stone repairs is still required.
	LIST ENTRY NUMBER:	1369519	Contact: Rachel James 0207 973 3153
© Historic England			-

	SITE NAME:	Church of St Lawrence, Caversfield	Saxon, possibly C10, base to the west tower and bell stage rebuilt in the C13 with a saddleback roof covered in plain
	DESIGNATION:	Listed Place of Worship grade II*	clay tiles. Late C12 rebuilding of the chancel and nave; the chancel being remodelled in the C13. Henry Woodyer, in
	CONDITION:	Poor	1874, rebuilt the aisles, restored the chancel and added north vestry. The nave and aisle roofs are very steep; covered in thin, stone slates. Water ingress occurring ar repairs are needed. An application to the National Lotte Heritage Fund Grants for Places of Worship scheme in
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1046533	2017 was unsuccessful.
oric England			Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Ilbury Camp hillfort, Deddington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015167
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Islip Roman villa, 300m east of Hillside Farm, Islip		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015161
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Banbury Grimsbury, North Oxfordshire, Banbury		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Emma Harrison (LPA) 01295 221846

### PRIORITY CATEGORIES

### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CHERWELL / OXFORD / SOUTH OXFORDSHIRE

SITE NAME:	RAF Upper Heyford, Upper Heyford, Ardley, Heyford Park / Ardley / Somerton / Upper Heyford				
DESIGNATION:	Conservation Area, 5 LBs, part in SM	NEW ENTRY?:	No		
CONDITION:	Very bad	TREND:	Deteriorating		
VULNERABILITY:	Medium	CONTACT:	Emma Harrison (LPA) 01295 221846		

### OXFORD

E C P	SITE NAME:	Minchery Farmhouse, Littlemore	C15 dormitory range of Littlemore Priory reconstructed c.1600. Later farmhouse, pub and country club. Limestone
	DESIGNATION:	Listed Building grade II*	rubble with squared dressings; old plain-tile roof with stone and brick ridge stacks. Single range running north-south
	CONDITION:	Poor	with stair tower on west. 2 storeys plus attics. Vacant since 2013, the building has suffered from heritage crime and
	OCCUPANCY:	Vacant/not in use	longstanding lack of maintenance. No solutions for its
	PRIORITY CATEGORY:	C (New entry)	future currently in place.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1047672	Contact: Rachel James 0207 973 3153

© Historic England



	SITE NAME:	Church of St Thomas the Martyr, St Thomas Street, Oxford	Church with chancel dating to late C12 and C15-16 nave, west tower and north chapel. Roof covering is in poor condition though structurally sound overall. The rainwater
	DESIGNATION:	Listed Place of Worship grade II	goods are generally adequate apart from one gutter, and the stonework is fair to poor. The south elevation of the
1	CONDITION:	Poor	chancel roof and the eastern part of the south nave roof have been reslated but further repairs are required to the
2	PRIORITY CATEGORY:	CATEGORY: D (A)	north elevation.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1047122	Contact: Rachel James 0207 973 3153

© Historic England

Blackbird Leys, Blackbird Leys a timber hyperbolic paraboloid roof designed by the engineer Hugh Tottenham. It comprises a spacious heart-				
Designation:       Listed Place of Worship grade II       shaped worship space with sacristy, small square campanile, narthex and toilets. The timber boarded roof was originally covered in aluminium sheet which was later replaced with a membrane: this now leaks leading to localised failure of the main roof structure. There are		SITE NAME:	Church Of The Holy Family, Blackbird Leys, Blackbird Leys	Innovative church designed by Colin Shewring 1964-5, with a timber hyperbolic paraboloid roof designed by the
CONDITION:Very badcampanile, narthex and toilets. The timber boarded roof was originally covered in aluminium sheet which was later replaced with a membrane: this now leaks leading to localised failure of the main roof structure. There are		DESIGNATION:	Listed Place of Worship grade II	shaped worship space with sacristy, small square
PRIORITY CATEGORY: A (A) replaced with a membrane: this now leaks leading to localised failure of the main roof structure. There are		CONDITION:	Very bad	
		PRIORITY CATEGORY:	A (A)	replaced with a membrane: this now leaks leading to
		OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER: 1464513 Contact: Rachel James 0207 973 3153		LIST ENTRY NUMBER:	1464513	Contact: Rachel James 0207 973 3153

© Historic England

# SOUTH OXFORDSHIRE



© Historic England

	SITE NAME:	Well house, Wick Farmhouse, Barton, Beckley and Stowood	Well house associated with Wick Farmhouse, late C17, in poor condition and not in use. Square plan, ashlar structure		
	DESIGNATION:	Listed Building grade II*	in Baroque style with stone benches lining the walls. Well now filled in. A schedule of repairs has been developed and		
	CONDITION:	Poor	which will be implemented as part of the wider redevelopment of the site.		
11	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1047637	Contact: Rachel James 0207 973 3153		

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2023 / LONDO	on and south east	/ SOUTH OXFORDSHIRE		
A CONTRACT	SITE NAME:	Walled garden approximately 30 metres west of Manor Farmhouse, North Weston, Great Haseley	brick with limest the loggia. The v	vith loggia, dating from early C18. Built of one ashlar details and a plain tile roof to vall has a moulded brick coping. It was the North Weston Manor which was
	DESIGNATION:	Listed Building grade II*	largely demolish	ed in the early C19. The wall tops are ere are structural cracks and the loggia is
ALL DAY	CONDITION:	Very bad	propped to prev	rent collapse. The owner has
and and and a	OCCUPANCY:	N/A		heritage statement and propped areas of ent collapse. A project to address all the
The second second	PRIORITY CATEGORY:	A (A)	issues needs to b	be agreed.
© Historic England	OWNER TYPE:			
	LIST ENTRY NUMBER:	1369269	Contact: Rachel	James 0207 973 3153
	SITE NAME:	Fernhouse, archway, gateway and walls, Mapledurham	garden to Maple	way, gateway and walls of the walled durham House, C17 and C18. The Fern
Constant and a second	DESIGNATION:	Listed Building grade II*, CA	the walls and gat	and in need of repair. The condition of wway varies. There have been discussions
	CONDITION:	Poor	regarding possib	le appropriate use and repair, including a se with heat provided by bio-mass heating.
	OCCUPANCY:	Vacant/not in use	No works have	physically been undertaken.
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1059520	Contact: Rachel	James 0207 973 3153
	SITE NAME:	Church of All Saints, Church Street, North Moreton	Church, mainly flint and sandstone, with tiled roofs to and chancel, and sheet roof to south aisle. Mostly mid C13/C14 but altered in C15 and restored in C19. Th tower and chantry chapel have had works carried our them. Two National Lottery Heritage Fund and Histo England Repair Grants for Places of Worship projects been completed. Works are still needed to the south roof. The outstanding important early C14 St Nichola stained glass window within the chantry chapel remai urgent need of repair to the glazing and stonework ar	
	DESIGNATION:	Listed Place of Worship grade I, CA		
A TAT	CONDITION:	Poor		
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Religious organisation		
© Historic England	LIST ENTRY NUMBER:	1181258		e raised for this work.
	Contact: Rachel James 0207 973 3153			
SITE NAME:	North Stoke henge and ring ditch site, Crowmarsh / South Stoke			
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1006335
CONDITION:	Extensive significa	int problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple o	wners	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Dike Hills, Dorch	nester		
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1006364
CONDITION:	Extensive significa	int problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing	g - Rabbit - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site a	t Northfield Farm, Long Wittenhar	n / Little Wittenha	um
DESIGNATION:	Scheduled Monur	nent	LIST ENTRY NUMBER:	1002925
CONDITION:	Extensive significa	int problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Commercial com	pany	CONTACT:	Alison McQuaid 0207 973 3646

### PRIORITY CATEGORIES

### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTH OXFORDSHIRE

SITE NAME:	Grim's Ditch; portion from Mongewell Park Loo	lge to S of Nuffield ch	urch, Nuffield / Crowmarsh / Ipsden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006368		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	Animal burrowing - moderate NEW ENTRY?: No			
OWNER TYPE:	Mixed, multiple owners	Alison McQuaid 0207 973 3646			
SITE NAME:	Defences to the Saxon town [within Bull and Kine Croft], Wallingford				
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1006329		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Local authority CONTACT: David Wilkinson 020				
SITE NAME:	Motte of Wallingford Castle, Wallingford				
DESIGNATION:	Scheduled Monument, 3 LBs, CA	LIST ENTRY NUMBER:	1006324		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	David Wilkinson 0207 973 3644		
SITE NAME:	Long barrow 340m north west of Cooks Cottages, Warborough				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016632		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Romano-British settlement 520m north west of	Cooks Cottages, Wa	rborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016630		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Camp on Bozedown, Whitchurch-on-Thames /	Goring Heath			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003704		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646		

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SOUTH OXFORDSHIRE	IRE / WOKINGHAM (UA)						
Ø Historic England	SITE NAME:	Fawley Court and Temple Island, Henley-on-Thames / Remenham / Bix and Assendon / Fawley	Early C18 garden and pleasure grounds surrounding a 1680s house set within a park landscaped by Lancelot Brown. Interacting with the adjacent River Thames, an eyecatcher stands on Temple Island downstream in				
	DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, 2 CAs	Brown's principal vista. The gardens and wooded pleasure grounds have a number of parkland architectural elements linked by paths. Most of the estate and park are in separate				
	CONDITION:	Generally unsatisfactory with major localised problems	ownership with previous development and planting impacting on the parkland structure and designed views There is a need to identify a partnership approach to				
	VULNERABILITY:	Medium	deliver conservation management.				
	TREND:	Declining					
	NEW ENTRY?:	No					
	OWNER TYPE:	Private, multiple owners					
	LIST ENTRY NUMBER:	1000390	Contact: Kay Richardson 0207 973 3647				

# VALE OF WHITE HORSE

Image: Construction of the condition of the timberwork to the windows is also occupancy:       Occupancy:       Occupied/in use         PRIORITY CATEGORY:       A (A)       Owner TYPE:       Private         Instruction of the timberwork to the windows is also cause for great concern. Discussions between Historic England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.		-		
DESIGNATION:       Listed Building grade I, CA       south wings, and stable and carriage house roofs in poor condition and cornice to main block in very poor condition         CONDITION:       Poor       Occupied/in use       FiloRATY CATEGORY:       A (A)         PRIORITY CATEGORY:       A (A)       OWNER TYPE:       Private       England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.         WINER TYPE:       Private       Io48220       Contact: Rachel James 0207 973 3153         SITE NAME:       Church of St Mary, Buckland       Cruciform plan with west tower. Early C12 nave, Early English (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; limestone stone state roofs, except to nave and chancel; limestone ashlar flue. The stone slate roofs to the north and south transept have		SITE NAME:		attached flanking wings, (one of which includes a chapel),
CONDITION:       Poor       condition and cornice to main block in very poor condition         OCCUPANCY:       Occupied/in use       condition and cornice to main block in very poor condition         PRIORITY CATEGORY:       A (A)       private       condition and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.         WINER TYPE:       Private       1048220       Contact: Rachel James 0207 973 3153         SITE NAME:       Church of St Mary, Buckland       Cruciform plan with west tower. Early Cl2 nave, Early condition in the condition in the condition of the impervant condition of the timberwork to the windows is also cause for great concern. Discussions between Historic England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.         WINER TYPE:       Private         UST ENTRY NUMBER:       1048220         SITE NAME:       Church of St Mary, Buckland         DESIGNATION:       Listed Place of Worship grade I, CA         CONDITION:       Poor         CONDITION:       Poor		DESIGNATION:	Listed Building grade I, CA	kitchen and brewhouse range added circa 1//6. North and south wings, and stable and carriage house roofs in poor
OCCUPANCY:       Occupied/in use       cause for great concern. Discussions between Historic England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not enacted.         WNER TYPE:       Private       1048220         ISTE INAME:       Church of St Mary, Buckland       Contact: Rachel James 0207 973 3153         SITE NAME:       Listed Place of Worship grade I, CA       Cruciform plan with west tower. Early C12 nave, Earl		CONDITION:	Poor	condition and cornice to main block in very poor condition
PHORITY CATEGORY:       A (A)       prioritise and cost the repairs need but this was not enacted.         OWNER TYPE:       Private       Contact: Rachel James 0207 973 3153         ISTE NAME:       Church of St Mary, Buckland       Cruciform plan with west tower. Early C12 nave, Early English (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar flue. The stone slate roofs to the north and south transept have		OCCUPANCY:	Occupied/in use	cause for great concern. Discussions between Historic
OWNER TYPE:       Private       enacted.         IJST ENTRY NUMBER:       1048220       Contact: Rachel James 0207 973 3153         SITE NAME:       Church of St Mary, Buckland       Cruciform plan with west tower. Early C12 nave, Early         ISITE NAME:       Listed Place of Worship grade I,       Cruciform plan with uset tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, immestone ashlar walling; limestone stone slate roofs, except to nave and chancel; limestone ashlar flue. The stone slate roofs to the north and south transept have		PRIORITY CATEGORY:	A (A)	England and the owners led to a grant being offered to prioritise and cost the repairs need but this was not
SITE NAME:       Church of St Mary, Buckland         DESIGNATION:       Listed Place of Worship grade I, CA         CONDITION:       Poor         CONDITION:       Poor		OWNER TYPE:	Private	
DESIGNATION:Listed Place of Worship grade I, CAEnglish (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; limestone stone slate roofs, except to nave and chancel; limestone ashlar flue. The stone slate roofs to the north and south transept have	© Historic England	LIST ENTRY NUMBER:	1048220	Contact: Rachel James 0207 973 3153
DESIGNATION:Listed Place of Worship grade I, CAEnglish (c1240) transepts, tower and chancel; church rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; limestone stone slate roofs, except to nave and chancel; limestone ashlar flue. The stone slate roofs to the north and south transept have				
DESIGNATION:       Listed Place of Worship grade I, CA       rebuilt with late C18 windows. Coursed limestone rubble, limestone ashlar walling; limestone stone slate roofs, except to nave and chancel; limestone ashlar flue. The stone slate roofs to the north and south transept have		SITE NAME:	Church of St Mary, Buckland	
stone slate roofs to the north and south transept have		DESIGNATION:		rebuilt with late C18 windows. Coursed limestone rubble,
		CONDITION:	Poor	except to nave and chancel; limestone ashlar flue. The
			P(C)	

© Historic England

11-

OWNER TYPE:

LIST ENTRY NUMBER:

SITE NAME:	Castle mound at Fitzharris, Abingdon on Thames		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006311
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Settlement site south east of church, Appleford-on-	Thames / Long W	ittenham
SITE NAME: DESIGNATION:	Settlement site south east of church, Appleford-on- Scheduled Monument	Thames / Long W	ittenham 1004849
		0	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004849

Religious organisation

1181905

### PRIORITY CATEGORIES

### Immediate risk of further rapid deterioration or loss of fabric; no А

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Work to recover chancel, tower, vestry and carry out stone repairs to the tower are due to take place spring -autumn 2023.

Contact: Rachel James 0207 973 3153

# ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

176

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / VALE OF WHITE HORSE / WEST BERKSHIRE (UA) / WEST OXFORDSHIRE

SITE NAME:	Two round barrows 520m and 550m north of Lower Chance Farm, Blewbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018716
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY?:	No
	<b>C</b>	CONTACT:	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646
OWNER TYPE: 	Yew Down round barrow 950m south west of Butt		• 
	. ,		• 
SITE NAME:	Yew Down round barrow 950m south west of Butt	terbush Reservoir,	Lockinge
SITE NAME: DESIGNATION:	Yew Down round barrow 950m south west of Butt Scheduled Monument	cerbush Reservoir, LIST ENTRY NUMBER:	Lockinge 1018719

# WEST BERKSHIRE (UA) / VALE OF WHITE HORSE

SITE NAME:	Two bowl barrows 500m north east of Stancombe Farm, Letcombe Bassett / Lambourn		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012349
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646

### WEST OXFORDSHIRE

©

1	SITE NAME:	Church of St Nicholas, Kiddington Park, Kiddington with Asterleigh	A mostly C14 church with a C12 core, restored 1879 with addition of a vestry. Constructed of coursed limestone rubble with stone slates to chancel. The floors are in poor
	DESIGNATION:	Listed Place of Worship grade II*, RPG grade II	condition and there are problems with damp. A phased programme of repairs is being developed. The first phase will tackle the blocked drainage and high external ground
	CONDITION:	Poor	levels.
de l'	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
D Historic England	LIST ENTRY NUMBER:	98490	Contact: Rachel James 0207 973 3153

SITE NAME:	Waterman's Lodge bowl barrow, one of a pair Forest, Cornbury and Wychwood	of Bronze Age barrows	s on the western edge of Wychwood
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011221
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Pair of bowl barrows immediately south of Blir	ndwell Wood, Crawley	
SITE NAME: DESIGNATION:	Pair of bowl barrows immediately south of Blir Scheduled Monument	INCLUSION Crawley	1015212
			1015212 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

### PRIORITY CATEGORIES

### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WEST OXFORDSHIRE / PORTSMOUTH, CITY OF (UA)

SITE NAME:	Linear earthworks east of Callow Hill Roman villa forming part of the north Oxfordshire Grim's Ditch, Glympton / Stonesfield / Wootton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014751	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	145m section of the north Oxfordshire Grim's I with Asterleigh	145m section of the north Oxfordshire Grim's Ditch situated 200m west of Grimsdyke Farm, Kiddington with Asterleigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012905	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Medieval settlement and church of Asterleigh, Kiddington with Asterleigh			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020966	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Pump Copse earthwork, Kiddington with Asterl	eigh		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003242	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Rectangular enclosures 1100yds (1010m) north	west of Mount Owen	Farm, Lew	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006348	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

# PORTSMOUTH, CITY OF (UA)



SITE NAME: Fort Purbrook, Portsdown Hill Road, Portsmouth DESIGNATION: Listed Building grade II\*, SM CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1387127

Fort c1860 by Captain William Crossman of the Royal Engineers. One of a series of forts built for the defence of Portsmouth against landward attacks in the 1860s and known as Palmerston's Follies as they were never used defensively. Used by a charitable trust as an outdoor activities centre. The wrought iron bridges have been repaired with funding from the Heritage Stimulus Fund and a structural survey and vegetation management plan through the Countryside Stewardship Scheme. Problems related to the drainage of the ramparts and maintenance of the moat's retaining walls put it at risk.

Contact: Rachel James 0207 973 3153

© Historic England

D

Е

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB I PA
- NP
- RPG Registered Park and Garden Scheduled Monument
- SM

ŬA WHS

# HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / PORTSMOUTH, CITY OF (UA)

And and a second	SITE NAME:	Hilsea Lines - Centre Bastion (excluding casemates referred to as Bastion 4), East Centre Curtain (Railway) west side (formerly known as Bastion no. 5), Hilsea	Earthwork defence dating from 1858-1869, with batteries, magazines and barracks. The central section of the site, comprising three quarters of the Centre Bastion, and the west side of East Centre Curtain, where the railway enters Portsea Island (all formerly referred to broadly as Bastion no. 5) are continuing to suffer from heritage crime, a lack of
	DESIGNATION:	Scheduled Monument, part in CA	regular maintenance and very limited access to the site. Opportunities to manage the monument, improve access and interpretation, and reduce heritage crime through the
	CONDITION:	Poor	creation of a linear park are being explored by Portsmouth City Council.
© Historic England	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1001861	Contact: Rachel James 0207 973 3153
A A	SITE NAME:	Former Royal Naval Academy (Buildings 1/14 and 1/116-9), HM Naval Base, Portsmouth	One of the oldest structures in the Dockyard, this building is a Georgian forerunner of the Britannia Royal Naval College at Dartmouth. This building has long been vacant.
	DESIGNATION:	Listed Building grade II*, CA	Natural ventilation and background heating has been introduced and furnishings removed, reducing damp levels
	CONDITION:	Poor	Remedial works to roof coverings and parapet gutters have reduced water ingress and the dry rot appears to be dying
	OCCUPANCY:	Vacant/not in use	back. The cupola has been repainted. Asbestos has been
	PRIORITY CATEGORY:	C (C)	found in the roof and must be removed before full survey can be undertaken.
	OWNER TYPE:	Government or agency	
9 Historic England Archive	LIST ENTRY NUMBER:	1244573	Contact: Louise Forsyth 020 7973 3220
	SITE NAME:	Fort Widley, Portsmouth	Fort c1860 by Captain William Crossman of the Royal Engineers. It is one of a series of forts built for the defende
the state of the s	DESIGNATION:	Scheduled Monument, 2 LBs	of Portsmouth against landward attacks in the 1860s and
	CONDITION:	Poor	known as Palmerston's Follies as they were never used defensively. It is laid out in a massive polygonal trace plan
	OCCUPANCY:	Part occupied/part in use	and surrounded on three sides by a dry moat. The fort is
THE REAL PROPERTY AND A DECK	PRIORITY CATEGORY:	C (C)	run by a charitable trust as an outdoor activities centre. Maintenance issues are now becoming repair problems. <i>A</i>
and the second second	OWNER TYPE:	Local authority	structural survey of the counterscarp wall and a vegetatio management plan has been funded through Countryside
	LIST ENTRY NUMBER:	1001862	Stewardship.
) Historic England			Contact: Rachel James 0207 973 3153
	SITE NAME:	Horse Sand Fort, Solent	Horse Sand Fort is a circular 19th century Royal Commission sea fort lying in the Solent 3.6km south east
	DESIGNATION:	Scheduled Monument	Southsea Castle. Horse Sand Fort was one of a chain of
A	CONDITION:	Poor	four sea forts in the Solent recommended by the Royal Commission on the Defence of the United Kingdom in
manere and a solid	OCCUPANCY:	Vacant/not in use	1860 and designed to protect Portsmouth dockyard from
onestes admentioned becalit editories	PRIORITY CATEGORY:	C (C)	seaborne attack. The Fort also was armed during both World Wars. The Fort provides a visual reminder of the
	OWNER TYPE:	Commercial company	strategic importance of the Solent in the late 19th to earli 20th century. The Fort currently has no sustainable use
	LIST ENTRY NUMBER:	1018588	aside from occasional visitor tours.
) Historic England			Contact: Rebecca Lambert 0207 973 3630
	SITE NAME:	No.5 and No.6 Dock, Basin No.1, Portsmouth Dockyard	Docks 5 and 6 are part of a complex of late C18 and early C19 ship building and repairing docks with associated qua
	DESIGNATION:	Scheduled Monument and Listed Building grade I, part in CA	walls and mooring fixtures. The docks have stepped sides with flights of steps and haulage slides; some retain later gates. Dock 6 is suffering from rotation, and mortar joints
	CONDITION:	Poor	on the stonework treads on the north side have opened up; it is also vulnerable to water penetration action and th
in the second	OCCUPANCY:	N/A	stonework is spalling. Dock 5 has recently been flooded
	PRIORITY CATEGORY:	C (C)	due to failure of the gates and is vulnerable to algal growt and saturation of stonework with risk of accelerated deca
	OWNER TYPE:	Government or agency	
Defence Estates	LIST ENTRY NUMBER:	1001852 and 1272267	Contact: Iain Bright 0207 9733 739
<ul> <li>PRIORITY CATEGORIES</li> <li>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>3 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet</li> </ul>	<ul> <li>D Slow decay; solution not yet implemented</li> <li>E Under repair or in fare</li> <li>repair, but no user in</li> <li>under threat of vaca</li> <li>obvious new user (a</li> </ul>	<ul> <li>d. (where applicable) end use of ir to good gentified; or redundant buildings with new ncy with no agreed but not yet implemen</li> </ul>	or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority y use New Entry is noted). NP National Park

- solution agreed but not yet implemented. C Slow decay; no solution agreed.
- obvious new user (applicable only to buildings capable of beneficial use).

- SMScheduled MonumentUAUnitary AuthorityWHSWorld Heritage Site
- 179

### HERI

HERITAGE AT RISK 2023 / LONDO	on and south east	/ PORTSMOUTH, CITY OF (UA)	
	SITE NAME:	Fort Cumberland, Fort Cumberland Road, Eastney	Coastal fort of 1746-1812 with later buildings and features. The casemates are suffering from water ingress and
	DESIGNATION:	Scheduled Monument and Listed Building grade II*, 3 LBs	associated decay. In addition, there is localised deterioration of the Fort's defences, particularly the curtain and counterscarp. A programme of works to address some
	CONDITION:	Poor	of the most urgent issues has been completed and the causes of water ingress into the casemates are being
	OCCUPANCY:	Part occupied/part in use	investigated. With local partners, Historic England is
The second	PRIORITY CATEGORY:	C (C)	considering options for the sustainable re-use of the vacant parts of the site, both in the long and short-term.
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1015700 and 1104273	Contact: Clare Charlesworth 0207 973 3640
	SITE NAME:	No. 25 Store, Yard Services Manager's Office, 1/118, Jago Road, HM Naval Base, Portsmouth	Two storey storehouse of 1782, with internal courtyard. In poor condition and vacant. Some evidence of water ingress and pigeon infestation. Some remedial works have been completed and further roof works are planned. The Ministry of Defence is in discussion with a potential user of
	DESIGNATION:	Listed Building grade II*, CA	the building, to take occupation once repairs are complete.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
© Historic England	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1244578	Contact: Louise Forsyth 020 7973 3220
	SITE NAME:	The Beneficial School, Kent Street, Portsea	Charity school of 1784 and 1836, now in use as a dance- drama school/theatre by the Groundlings Theatre Trust.
	DESIGNATION:	Listed Building grade II*, CA	An updated condition survey has been completed which has identified problems including with the roof structure
	CONDITION:	Poor	and windows. Some repairs to the front elevation have
m · 🌧 m '	OCCUPANCY:	Occupied/in use	been successfully completed with the aid of a Covid 19 Emergency grant funding. Historic England, Theatres Trust,
	PRIORITY CATEGORY:	C (C)	National Lottery Heritage Fund and Architectural Heritage Fund continue to offer guidance to the tenant and owner
	OWNER TYPE:	Private	to secure repairs, maintenance and management of the
© Llistenia Fasland	LIST ENTRY NUMBER:	1271859	building.
© Historic England		12/103/	Contact: Rachel James 0207 973 3153
	SITE NAME:	Wymering Manor, Old Wymering Lane, Cosham	Manor house with medieval fabric and later work. Acquired by a Trust in 2013. A condition survey and an
	DESIGNATION:	Listed Building grade II*, CA	investigation into options for future sustainable uses have been completed with grant aid from Historic England and
	CONDITION:	Fair	the Architectural Heritage Fund. The house is in need of
	OCCUPANCY:	Part occupied/part in use	some structural repair, general renovation and a new use.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1245180	Contact: Liz Pollard 0207 973 3650
	SITE NAME:	2-8, The Parade, HM Naval Base, Portsmouth	Terrace of dockyard officers' lodgings, 1715-19. Partially converted to office use c1995, but now empty. Prone to wat rand some structural movement. Structural and
	DESIGNATION:	Listed Building grade II*, CA	wet rot and some structural movement. Structural and drainage problems persist between the main building and
	CONDITION:	Fair	the rear extensions. There is extensive decay in panelling and some plaster ceilings have collapsed. An extensive
	OCCUPANCY:	Vacant/not in use	programme of repair is underway and the roof has been
	PRIORITY CATEGORY:	F (F)	reslated and the gutters repaired. Render and window joinery repairs are also underway as well as the repair of
	OWNER TYPE:	Government or agency	the timber porches. Further works to the rear extensions

© Historic England

DESIGNATION:	Listed Building grade II*, CA	wet rot and some structural movement. Structural and drainage problems persist between the main building and
CONDITION:	Fair	the rear extensions. There is extensive decay in panelling and some plaster ceilings have collapsed. An extensive
OCCUPANCY:	Vacant/not in use	programme of repair is underway and the roof has been
PRIORITY CATEGORY:	F (F)	reslated and the gutters repaired. Render and window joinery repairs are also underway as well as the repair of
OWNER TYPE:	Government or agency	the timber porches. Further works to the rear extensions are planned.
LIST ENTRY NUMBER:	1272307	Contact: Louise Forsyth 020 7973 3220

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

-----

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

206		
FOR .		
0	414	


SITE NAME:	Iron and Brass Foundry, 1/140, Victoria Road, HM Naval Base, Portsmouth	Iron foundry and smithery built 1857-1861, by Col GT Greene RE and Andrew Murray, Chief Engineer; extended 1878, with later alterations. The main part of the building
DESIGNATION:	Listed Building grade II*, CA	was converted to office use in 2003. The east wing (Building 1/136) remains unused and at risk. There were
CONDITION:	Fair	concerns over drainage and regular flooding of the building but this has been resolved. Roof repairs are due to be
OCCUPANCY:	Part occupied/part in use	undertaken.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1272310	Contact: Louise Forsyth 020 7973 3220

© Historic England



Weat	SITE NAME:	Church of St Mary, Fratton Road, Kingston	Church designed by Sir Arthur Blomfield and built of flint and Bath stone with plain tile roofs between 1887-9. The
KA	DESIGNATION:	Listed Place of Worship grade II*, CA	church has received significant grant aid from Historic England and the National Lottery Heritage Fund in three phases and this has dealt with some of the roofs and tower.
6A	CONDITION:	Poor	Recent repairs to the building fabric have been carried o in connection with the Organ Project but further repairs
PRIORITY CATEGORY: C (C)	C (C)	are required including to the roofs, south clerestory and	
	OWNER TYPE:	ER TYPE: Religious organisation chan	chancel windows.
	LIST ENTRY NUMBER:	1104279	Contact: Rachel James 0207 973 3153

© Historic England



© Historic England

	SITE NAME:	Church of St Cuthbert, Hayling Avenue, Portsmouth	1914-15. By E Stanley Hall. The original east end apse was destroyed by bombing, and the present east end wall is a
	DESIGNATION:	Listed Place of Worship grade II	post-war reconstruction. This has been remodelled in the last 10 years to provide community facilities and the
	CONDITION:	Poor	present church sits in the western two bays of the former nave of the church only. The roofs over the worship space
	PRIORITY CATEGORY:	D (D)	and the bell tower are in poor condition. A National
	OWNER TYPE:	Religious organisation	Lottery Heritage Fund Grants for Places of Worship scheme grant was used to develop the project, but funding
	LIST ENTRY NUMBER:	1333225	for repairs has yet to be found.
			Contact: Rachel James 0207 973 3153

© Historic England

### **READING (UA)**



SITE NAME:	Remains of Reading Abbey: a Cluniac and Benedictine monastery
DESIGNATION:	Scheduled Monument, 14 LBs, part in RPG grade II, part in CA
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1007932

Substantial standing remains of abbey established by Henry I in 1121. The majority of the ruins including the gatehouse, refectory wall and elements within the ownership of St James's church have been repaired. The mill arch, C12 to CI3, is the surviving western wall of the Abbey Mill. The original flint rubble wall faces have been much repaired with inset areas of chalk ashlar and brickwork. There are areas of re-pointing in hard cement mortar and open joints. Implementation of repairs and long-term management is required.

© Historic England

Contact:	Rachel	lames	0207	973	3153
Contact.	INACHEI	annes	0207	115	J   J J

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UÁ
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / READING (UA) / SOUTHAMPTON, CITY OF (UA)

	SITE NAME:	Chazey Farm barn, The Warren, Reading	A very large seven bay red brick barn C17 or earlier. There is structural cracking and the gable currently has temporary
	DESIGNATION:	Listed Building grade I	shoring. The building forms part of a larger site proposal for a healthcare development. Ground works for the new
	CONDITION:	Very bad	development commenced in spring 2010. Following close working between the leaseholder, Local Planning Authority
	OCCUPANCY:	Vacant/not in use	and Historic England urgent work to prevent any furthe
	PRIORITY CATEGORY:	B (B)	decay of the building commenced in 2020. Work will then be required to restore the barn and find a viable use for it.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1113603	Contact: Rachel James 0207 973 3153

SITE NAME:	Russell Street / Castle Hill		
DESIGNATION:	Conservation Area, 52 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Mark Worringham (LPA) 07855 126084

# SOUTHAMPTON, CITY OF (UA)

· · · · · · · · · · · · · · · · · · ·	<b>\</b>		
	SITE NAME:	Former Chapel Mills, American Wharf, Elm Street, Southampton	Rare survival of former steam mill, 1781 and 1800, built to produce ship's biscuits for the Navy. Built of brick with mainly concrete tiled roofs. Now partly used as a sail loft
	DESIGNATION:	Listed Building grade II*	[East] and part vacant [West], suffering from longstanding lack of regular maintenance. Eastern part re-roofed in 2022
	CONDITION:	Poor	including gutter repairs, and internal structural repairs to timber posts and beams. Planning Permission granted for
	OCCUPANCY:	Vacant/not in use	repair and residential conversion of Western part, but
	PRIORITY CATEGORY:	D (D)	permanent repairs not yet implemented.
	OWNER TYPE:	Commercial company, multiple owners	
	LIST ENTRY NUMBER:	1091968	Contact: Rachel James 0207 973 3153

THE T	SITE NAME:	Red Lion Public House, 55, High Street, Southampton	C15 hall house now commercial premises, suffering from water ingress and deferred maintenance and therefore
	DESIGNATION:	Listed Building grade II*	considered to be at risk. Condition survey undertaken and programme of repairs identified. Repairs need to take place
	CONDITION:	Poor	to prevent deterioration.
OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
d	LIST ENTRY NUMBER:	1092055	Contact: Rachel James 0207 973 3153



A	SITE NAME:	St Denys Church, St Denys Road, St Denys	Church designed by Sir George Gilbert Scott in 1868 ar built of brick. At risk due to falls of ceiling plaster interr	
Val	DESIGNATION:	Listed Place of Worship grade II	Historic England/National Lottery Heritage Fund grant- aided repairs to rainwater goods, east and west windows,	
8	CONDITION:	Poor	bell turret stonework and some areas of ceilings completed. A further phase of repairs is required.	
	PRIORITY CATEGORY:	C (C)	completed. A duriner phase of repairs is required.	
6	OWNER TYPE:	Religious organisation		
1	LIST ENTRY NUMBER:	1179120	Contact: Rachel James 0207 973 3153	

© Historic England

© Historic England

© Histo

SITE NAME:	Old Town North		
DESIGNATION:	Conservation Area, 15 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jon Willetts (LPA) 023 8083 2479

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA LB LPA NP RPG SM

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### SURREY

© Histo

### ELMBRIDGE

MM	SITE NAME:	The Belvedere, Claremont Park, Esher	Eye-catcher and viewpoint in the form of a mock castle, 1717 by Sir John Vanbrugh. In need of repair to bring it
storic England Archive	LIST ENTRY NUMBER:	1020137 and 1272 <del>444</del>	Contact: Iain Bright 0207 9733 739
	OWNER TYPE:	Mixed, multiple owners	
	PRIORITY CATEGORY:	F (F)	being made in reducing the risks to the track. However, further action is required.
	OCCUPANCY:	N/A	the necessary works take place and significant progress is
	CONDITION:	Poor	various parts of the track to be at risk. Historic England is now working with owners and interested parties to ensure
	DESIGNATION:	Scheduled Monument and Listed Building grade II, part in CA	when aircraft production buildings took over part of the circuit. Historic England funded a Conservation Management Plan for the entire site which identified
	SITE NAME:	Brooklands Motor Racing Circuit	The world's first purpose-built motor racing circuit, constructed in concrete in 1907. It was in use until 1939
IDIGE			



	SITE NAME:	The Belvedere, Claremont Park, Esher	Eye-catcher and viewpoint in the form of a mock castle, 1717 by Sir John Vanbrugh. In need of repair to bring it
A MARIE	DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I	back into use as a focal point of the Grade I Registered landscape of Claremont Park. A commitment to improving the immediate landscape surrounding the Belvedere was
	CONDITION:	Fair	sought as part of a planning application made by Claremont Fan Court School for long term development. Some of the
	OCCUPANCY:	Vacant/not in use	improvements have been implemented.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1005931 and 1030204	Contact: Alma Howell 0207 9733 627



	SITE NAME:	Former kitchen garden walls to Claremont House, Claremont Park Road, Esher	Nationally significant garden walls of 1717 by Vanbrugh. Suffering from vegetation growth in wall tops, mortar loss and in need of general repair. Investigations for possible
	DESIGNATION:	Listed Building grade II*, RPG grade I	repair techniques and materials completed with one of the owners. Some repairs have taken place as an exemplar but more are needed. A full survey of the walls is being
	CONDITION:	Poor	undertaken to understand the overall condition and the extent and cost of repairs needed.
	OCCUPANCY:	N/A	extent and cost of repairs needed.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1377465	Contact: David John 0207 973 3638

© Historic England	

© Historic England

SITE NAME:	Brooklands		
DESIGNATION:	Conservation Area, 5 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jon Kilner (LPA) 01372 474824

EPSOM AND EWELL

SITE NAME:	Epsom Town Centre, Epsom		
DESIGNATION:	Conservation Area, 39 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Epsom & Ewell Borough Council (LPA) 01372 732394
SITE NAME:	Horton, Epsom		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lance Penman (LPA) 01372732000

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### ABBREVIATIONS

CA LB LPA NP RPG SM

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / GUILDFORD / MOLE VALLEY

### **GUILDFORD**



SITE NAME:	West Horsley Place, Epsom Road, West Horsley	Country house, C15 timber-framed hall and domestic wing, refronted in brick in the C17 with C18 alterations
DESIGNATION:	Listed Building grade I	and internal features. The house has suffered from deferral of maintenance under private ownership and now stands in
CONDITION:	Poor	need of a major renovation of the frame, brickwork and roof as well as all decorative finishes. A recently created
OCCUPANCY:	Part occupied/part in use	Trust has taken on the building which is now being used in
PRIORITY CATEGORY:	F (F)	conjunction with Grange Park Opera, operating from the grounds. Further uses being explored. Immediate structural
OWNER TYPE:	Charity (heritage)	remediations have been addressed and a phased programme of repairs is in progress.
LIST ENTRY NUMBER 1188949	Contact: Alma Howell 0207 9733 627	

© Historic England



	SITE NAME:	Church of St Luke, Burpham Lane, Burpham	Church designed by Henry Woodyer in 1859. Built of Bargate stone with tiled roofs. At risk due to defective roof
	DESIGNATION:	Listed Place of Worship grade II	tiling and rainwater disposal goods.
A	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
1.12.1	LIST ENTRY NUMBER:	1029301	Contact: David John 0207 973 3638

© Historic England

ric Ergland	SITE NAME:	Clandon Park, West Clandon	Gardens and pleasure grounds within a landscaped park by
	DESIGNATION:	Registered Park and Garden grade II, 8 LBs, part in CA	Lancelot Brown. Gutted by fire in 2015 the house and garden are owned by the National Trust while the park is privately owned. Management without a plan for guidance
	CONDITION:	Extensive significant problems	has lead to lack of suitable conservation priorities around the park, damaging its overall integrity and its character further vulnerable to development proposals. With separate plans being drawn up for restoration in the hous and garden and management of the park, a coordinated
	VULNERABILITY:	High	
	TREND:	Declining	
	NEW ENTRY?:	No	approach to park use and appropriate management is needed to secure this landscape's future.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001171	Contact: Kay Richardson 0207 973 3647

### MOLE VALLEY

© Historic



SITE NAME:	Lime kilns at Betchworth Quarry, Betchworth	An important group of C19 and C20 brick built lime kilns. Three of the structures (the Dietsch, remains of the six
DESIGNATION:		Flare kilns and remaining Hoffman kiln) are at risk due to a longstanding lack of regular maintenance. A condition
CONDITION:	Poor	survey of the structures has been completed and estimated cost of the repairs produced. Sources of funds to
OCCUPANCY:	N/A	implement the repairs now need to be identified.
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Commercial company, multiple owners	
LIST ENTRY NUMBER:	1021346	Contact: Iain Bright 0207 9733 739

© Historic England



SITE NAME:	Brockham Lime Kilns, Brockham	The site includes a disused eastern battery of eight kilns and a western battery of two. The eastern battery, originally
DESIGNATION:	Scheduled Monument and Listed Building grade II Very bad	built in 1870, comprises four pairs of linked flare kilns. The northern two pairs were modified to the Brockham patent, as was the western battery. Now also an important bat habitat. Parts of the kilns remain in a very bad condition and supported by scaffold. Funds need to be raised which
CONDITION:		
OCCUPANCY: PRIORITY CATEGORY:	N/A	will allow the identified repairs to take place and improve
	A (A)	interpretation for visitors.
OWNER TYPE:	Charity (non-heritage)	
LIST ENTRY NUMBER:	1021322 and 1230730	Contact: David John 0207 973 3638

### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MOLE VALLEY



© Historic England

SITE NAME:Ruins of Betchworth Castle, Reigate Road, BrockhamLate C17 ruined house built on site of medieval castle. Consolidation works to ruins completed 2013. A section of the terrace retaining wall was rebuilt in 2014, but a long section of the terrace is still held up only by tree roots and temporary geotextile fabric shoring. This will fail once the tree roots rot or if strong winds blow over any of the trees on the terrace edge. This and on-going management/ maintenance needs to be addressed before the monument can be removed from the Register. The owner is trying to secure funding to assure the long term future of the ruins.INTE ENTRY NUMBER:1017996 and 1378073Contact: David John 0207 973 3638				
DESIGNATION:Scheduled Monument and Listed Building grade IIsection of the terrace is still held up only by tree roots and temporary geotextile fabric shoring. This will fail once the tree roots rot or if strong winds blow over any of the trees on the terrace edge. This and on-going management/ maintenance needs to be addressed before the monument can be removed from the Register. The owner is trying to secure funding to assure the long term future of the ruins.PRIORITY CATEGORY:Private	1 - 5	SITE NAME:		Consolidation works to ruins completed 2013. A section
CONDITION:Fairtree roots rot or if strong winds blow over any of the trees on the terrace edge. This and on-going management/ maintenance needs to be addressed before the monument can be removed from the Register. The owner is trying to secure funding to assure the long term future of the ruins.OWNER TYPE:Private	-	DESIGNATION: Scheduled Monument and Listed section Building grade II temp	section of the terrace is still held up only by tree roots and	
OCCUPANCY:       N/A       maintenance needs to be addressed before the monument can be removed from the Register. The owner is trying to secure funding to assure the long term future of the ruins.         OWNER TYPE:       Private	A STATE	CONDITION:	Fair tree roots rot or if strong winds blow over any	tree roots rot or if strong winds blow over any of the trees
PRIORITY CATEGORY:       F (F)       secure funding to assure the long term future of the ruins.         OWNER TYPE:       Private	PRIORITY CATEGO	OCCUPANCY:	N/A	maintenance needs to be addressed before the monument
Thrace		PRIORITY CATEGORY:	F (F)	
LIST ENTRY NUMBER: 1017996 and 1378073 Contact: David John 0207 973 3638		OWNER TYPE:	Private	
		LIST ENTRY NUMBER:	1017996 and 1378073	Contact: David John 0207 973 3638

	SITE NAME:	Church of St John the Baptist, Church Lane, Okewood Hill, Abinger	Church dating from C13, virtually doubled in size in 1879 by the architect Basil Champneys. Rendered rubble stone walls with slab roofs and shingled spire to low timber
	DESIGNATION:	Listed Place of Worship grade II*	tower. At risk due to defective rainwater goods and roofs. A phase of repairs has been completed under the National
	CONDITION:	Poor	Lottery Heritage Fund Grants for Places of Worship scheme, however further repairs are required and funds
	PRIORITY CATEGORY:	C (C)	are needed for these.
Alex Control	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1028844	Contact: David John 0207 973 3638
© Historic England			

SITE NAME: Anstiebury Camp: a large multivallate hillfort south east of Crockers Farm, Capel LIST ENTRY NUMBER: DESIGNATION: 1007891 Scheduled Monument, part in CA Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY ?: No OWNER TYPE: CONTACT: Alison McQuaid 0207 973 3646 Mixed, multiple owners SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: ut



© Historic England

	Bell barrow in Deerleap Wood, Wotton					
	Scheduled Monun	nent	LIST ENTRY NUMBER:	1007878		
	Generally unsatisf problems	actory with major localised	TREND:	Declining		
ſ:	Scrub/tree growt	h	NEW ENTRY?:	No		
	Private		CONTACT:	Alison McQuaid 0207 973 3646		
	SITE NAME:	Ashtead Park, Ashtead	A C17 park, developed with successive owners throughor the C18 and C19 the well wooded open parkland estate was broken up and sold in the 1920s with the historic landscape split into two principle ownerships, the house, gardens and southern park a school, and the northern pa with ponds managed as open access land now a nature reserve. The school has improved its management of the landscape amongst proposals for further facilities followir a Conservation Management Plan since 2010. A joint heritage-led approach should support the park's significance and balance its ecosystem services.			
	DESIGNATION:	Registered Park and Garden grade II, 20 LBs, part in SM, part in CA				
	CONDITION:	Generally satisfactory but with significant localised problems				
240	VULNERABILITY:	Medium				
Star Star	TREND:	Improving				
	NEW ENTRY?:	No				
	OWNER TYPE:	Mixed, multiple owners				
	LIST ENTRY NUMBER:	1001490	Contact: Kay Ricl	hardson 0207 973 3647		

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

# Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

### CA LB

LPA

- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / REIGATE AND BANSTEAD / RUNNYMEDE / SPELTHORNE / TANDRIDGE

REIGATE AND BANSTEA	D		
No Maria	SITE NAME:	Alderstead (Merstham) Fort, Shepherd's Hill, Reigate	C19 mobilisation centre, one of 13 constructed on the North Downs for the defence of London. The scheduling
	DESIGNATION:	Scheduled Monument	comprises the infantry fort and detached tool store. Tree growth and poor drainage are causing problems and the
A Line	CONDITION:	Poor	fort has no current use or management. Discussions need to take place with the owners to agree a project to enable
	OCCUPANCY:	Vacant/not in use	the site to be conserved and maintained.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1018073	Contact: Iain Bright 0207 9733 739

# RUNNYMEDE

Historic England	SITE NAME:	Woburn Farm, Addlestone	An Arcadian 'ferme ornée' designed by Philip Southcote
	DESIGNATION:	Registered Park and Garden grade II, 5 LBs	from 1734-5, highly influential in the history of garden design but rather ephemeral in nature. Now in divided ownership and varying uses so very little of the landscape
	CONDITION:	Extensive significant problems	laid out by Southcote remains today apart from the wooded banks of the Bourne stream that was part of
	VULNERABILITY:	High	Southcote's circuit around the farm. Isolated parkland
	TREND:	Declining	architecture features sit within highly frangmented settings. With such high levels of loss of historic design intention and
	NEW ENTRY?:	No	character the overall integrity of the registered area needs reassessing.
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000342	Contact: Kay Richardson 0207 973 3647

# SPELTHORNE

©

	SITE NAME:	Church of St Mary Magdalene, Squires Bridge Road, Littleton	A medieval church with an C18 tower. Constructed of ragstone, chalk, conglomerate and brown brick with a clay
2 martin	DESIGNATION:	Listed Place of Worship grade I	tiled roof. The tiled roofs are in a poor condition, especially on the north slopes although there is no evidence of water
T	CONDITION:	Poor	penetration at the moment. The interior walls have been painted with a non-micro porous paint which is causing
	PRIORITY CATEGORY:	C (C)	decay of the carved stone details.
U-F-	OWNER TYPE:	Religious organisation	
ANN B-	LIST ENTRY NUMBER:	1377699	Contact: David John 0207 973 3638

© Historic England

### TANDRIDGE

	SITE NAME:	Ruins at Bletchingley Castle, Bletchingley	Norman ringwork and bailey, with the remains of a rare stone built Norman house. The ruins were previously
State 1	DESIGNATION:	Scheduled Monument	excavated. Some trees are growing close to the fragile masonry of the house, which is overgrown with vegetation
	CONDITION:	Very bad	and in need of consolidation. The condition of the ruins of the house put the site at risk. It is hoped that a project can
	OCCUPANCY:	N/A	be developed to conserve the ruins.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1013374	Contact: David John 0207 973 3638

© Historic England

	D	Slow
deterioration or loss of fabric; no		not y
solution agreed	E	Inde

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

PRIORITY CATEGORIES

А

- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / TANDRIDGE / WAVERLEY / WOKING

	SITE NAME:	Church of St Mary the Virgin, Church Lane, Oxted	Large church of medieval origins constructed from a mixture of sandstone, Reigate, Kentish rag and ironstone.
	DESIGNATION:	Listed Place of Worship grade I	At risk due to deterioration of the stonework and render. The National Lottery Heritage Fund's Grants for Places of
in and address I. D.	CONDITION:	Poor	Worship grant-aided repairs to the chancel and aisles completed in 2018 but further repairs, including to the
	PRIORITY CATEGORY:	C (C)	tower, are required. Works are due to commence on the
Stress Provent	OWNER TYPE:	Religious organisation	tower in 2023.
	LIST ENTRY NUMBER:	89608	Contact: David John 0207 973 3638

© Historic England

# WAVERLEY

	SITE NAME:	Church of St Peter and St Paul, The Street, Ewhurst	C12 church with nave, C13 transepts, C15 porch. Chancel largely rebuilt1838 after the central tower collapsed.
	DESIGNATION:	Listed Place of Worship grade I, CA	Wealden sandstone rubble and dressed sandstone blocks on buttresses. Stone slab roofs with short, wood-shingled broach spire to tower. Cruciform plan. Water ingress
	CONDITION:	Poor	through the roof of the chancel has led to the ceiling plaster falling. National Lottery Heritage Fund Grants for
	PRIORITY CATEGORY:	B (B)	Places of Worship scheme repairs to the chancel, south
	OWNER TYPE:	Religious organisation	transept and south nave slopes were completed in 2019, but the remaining roofs are in urgent need of repair.
	LIST ENTRY NUMBER:	1190455	Contact: David John 0207 973 3638
© Historic England			

C

SITE NAME:	Four bowl barrows 30m south east of Tilford Ba	rrows: part of The Ba	arrows round barrow cemetery, Tilford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007883
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

# WOKING

	SITE NAME:	Brookwood Cemetery, Brookwood	A commercial garden cemetery of immense scale founded in 1852 for London's dead with its own railway. Still active
	DESIGNATION:	Registered Park and Garden grade I, 18 LBs, part in CA	with tombs and monuments for many denominations, faiths, nationalities and groups, C20 military and woodland sections heighten the site's significance. Acquired by the
	CONDITION:	Generally satisfactory but with significant localised problems	Local Authority after longterm lack of overall management, repairs to signficant structures, improved landscape infrastructure/management is welcome positive
	VULNERABILITY:	Medium	enhancement. With an ambitious future plan outlined in a
	TREND:	Improving	masterplan in 2020 support for the commitment to bring greater resilience to the cemetery is ongoing.
© Historic England	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1001265	Contact: Kay Richardson 0207 973 3647

SITE NAME:	Brookwood Cemetery, Pirbright				
DESIGNATION:	Conservation Area, 18 LBs, part in RPG grade I	NEW ENTRY?:	No		
CONDITION:	Very bad	TREND:	Improving		
VULNERABILITY:	Medium	CONTACT:	Tom Simpson (LPA) 01483 743871		

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

WEST BERKSHIRE (UA)       STENAME:       Former Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton       Former chapel, C12 and later. Structure is generally with main repair programme completed. Planning programing completed. Planning programme compregramme	d for I. The
<ul> <li></li></ul>	I. The
CONDITION:       Fair         CCUPANCT:       Vacant/not in use         PHORTPY CATEGOR:       E (E)         OWNERTTPE       Commercial company         UST ENTRY NUMBER:       1005378 and 1303413         Contact:       Rachel James 0207 973 3153         INTENTRY NUMBER:       1005378 and 1303413         Contact:       Rachel James 0207 973 3153         INTENTRY NUMBER:       Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane, Hampstead Marshall         DESIGNATION:       Estention:         Paire of gate Diers and approximately 2 metres of wall to east and west of piers on edge of Park Lane, Hampstead Marshall       Sarped II         DESIGNATION:       Estent Building grade II*, RPG grade II       Sarped II         OCUMANCY:       N/A       Poor         OCUMANCY:       N/A       Private         UST ENTRY NUMBER:       II17222       Contact: Rachel James 0207 973 3153         STENAME:       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall       Sate piers to house which burnt down in 1718. The remain in the north west corner of the park. Some of severely cracked some and fractures through brick and a shell niche. A programme of repairs needs to agreed and taken forward by the owners.         EVENTRY NUMBER:       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampst	
PRICENTY CATEGORY:         E (E)           OWNER TYPE:         Commercial company           UST ENTRY NUMBER:         1005378 and 1303413         Contact: Rachel James 0207 973 3153           STENAME:         Pair of gate piers and approximately 2 metres of or east and west of piers on east of west of entrance to church yard, Park Lane, Hampstead Marshall         East ONATION:         East of entrance to Home Farm, Park Lane, Hampstead Marshall         Contact: Rachel James 0207 973 3153           UST ENTRY NUMBER:         ITT222         Contact: Rachel James 0207 973 3153         East of entrance to Home Farm, Park Lane, Hampstead Marshall         Fare piers to house which burnt down in 1718, The every cracked stone and fractures	
e Hittoric England       OWNER TYPE:       Commercial company         UST ENTRY NUMBER:       1005378 and 1303413       Contact: Rachel James 0207 973 3153         Image: Strep NAME:       Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead Marshall       Early C18 brick gate piers and attached walling. For the gardens of a C17 house which burnt down in 17 house which burnt down house to pieres house which burnt down house to pieres house which burnt down h	
UST ENTRY NUMBER:         1005378 and 1303413         Contact: Rachel James 0207 973 3153           INSTENTRY NUMBER:         1005378 and 1303413         Contact: Rachel James 0207 973 3153           INSTENTRY NUMBER:         Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead Marshall         Early C18 brick gate piers and attached walling. For the gardens of a C17 house which burnt down in 17 the piers suffer from open joints to the brickwork acapitals and a corroding pintle which has caused the brickwork to bulge. A programme of repairs needs are dell conditions:           INFERTION:         Listed Building grade II*, RPG grade II         Contact: Rachel James 0207 973 3153           INFERTION:         Listed Building grade II*, RPG grade II         Contact: Rachel James 0207 973 3153           INFERTION:         Listed Building grade II*, RPG grade II         Contact: Rachel James 0207 973 3153           INFERTIFY:         N/A         Private         Contact: Rachel James 0207 973 3153           INFERTIFY:         N/A         Private         Contact: Rachel James 0207 973 3153           INFERTIFY:         Private         Contact: Rachel James 0207 973 3153           INFERTIFY:         Private         Contact: Rachel James 0207 973 3153           INFERTIFY:         Private         Contact: Rachel James 0207 973 3153           INFERING:         Brit of gate piers 204 metres	
WITH STREAM       Pair of gate piers and approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead Marshall       Early C18 brick gate piers and attached walling. For the gardens of a C17 house which burnt down in 17 he piers suffer from open joints to the brickwork a greed with the owners and the works undertaken. Warshall            e Hittoric England           DESIGNATION:         Listed Building grade II*, RPG grade II         CONDITION:         Poor         OCCUPANCY:         N/A         RIORITY CATEGORY:         C (C)         OWNER TYPE:         Private         LIST ENTRY NUMBER:         II17222         Contact: Rachel James 0207 973 3153             STE NAME:         STE NAME:         Stre NAME:         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Listed Building grade I, RPG         grade II         Stre NAME:         Stre NA	
approximately 2 metres of wall to east and west of piers on edge of Park Lane 162 metres west of entrance to church yard, Park Lane, Hampstead Marshall       the gardens of a C17 house which burnt down in 17 the piers suffer from open joints to the brickwork as capitals and a corroding pintle which has caused the brickwork to bulge. A programme of repairs needs: agreed with the owners and the works undertaken.            PeisGNATION:          Listed Building grade II*, RPG grade II            CONDITION:          Poor            OCCUPANCY:          N/A            Private          III17222            SITE NAME:          Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall            SITE NAME:          Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall            DESIGNATION:          Dister Building grade I, RPG grade II            DESIGNATION:          Dati of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall            DESIGNATION:          Disted Building grade I, RPG grade II            DESIGNATION:          Poor OccupancY:            CONDITION:          Poor OccupancY:            CONDITION:          Poor OccupancY:            CONDITION:          Poor OccupancY:            CONDITION:          Poor OccupancY:	
Image: Bission Ref.       grade II         Image: Bission Ref.       grade II         Image: Bission Ref.       Poor         Image: CONDITION:       Poor         Image: OCUPANCY:       N/A         Image: Priority CATEGORY:       C (C)         Image: OCUPANCY:       Private         Image: Distribution Ref.       Private         Image: Distribution Ref.       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall         Image: Distribution Ref.       STE NAME:         Image: Distribution Ref.       Listed Building grade I, RPG grade II         Image: CONDITION:       Poor         Image: OcupAncy:       N/A         Image: Distribution Ref.       Poor         Image: Distribution Ref.	9
<ul> <li>Historic England</li> <li>OCCUPANCY:</li> <li>N/A</li> </ul> <ul> <li>PRIORITY CATEGORY:</li> <li>C (C)</li> <li>OWNER TYPE:</li> <li>Private</li> <li>LIST ENTRY NUMBER:</li> <li>III 17222</li> </ul> <ul> <li>STE NAME:</li> <li>Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshal</li> <li>DESIGNATION:</li> <li>Listed Building grade I, RPG grade II</li> <li>CONDITION:</li> <li>Poor</li> <li>OCCUPANCY:</li> <li>N/A</li> <li>PRORITY CATEGORY:</li> <li>C (C)</li> </ul>	
OCCUPANCY:       N/A         PRIORITY CATEGORY:       C (C)         OWNER TYPE:       Private         LIST ENTRY NUMBER:       III7222         Contact: Rachel James 0207 973 3153         STE NAME:       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall         DESIGNATION:       Listed Building grade I, RPG grade I         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY CATEGORY:       C (C)	
OWNER TYPE:       Private         LIST ENTRY NUMBER:       1117222       Contact: Rachel James 0207 973 3153         STE NAME:       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall       Gate piers to house which burnt down in 1718. The remain in the north west corner of the park. Some of grade II         DESIGNATION:       Listed Building grade I, RPG grade II       Gate piers to house which burnt down entrance to Home Farm, Park Lane, Hampstead Marshall         CONDITION:       Poor       Poor         COUPANCY:       N/A         PRORITY CATEGORY:       C (C)	
LIST ENTRY NUMBER:       III7222       Contact: Rachel James 0207 973 3153         Image: Step in s	
SITE NAME:       Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hampstead Marshall       Gate piers to house which burnt down in 1718. The remain in the north west corner of the park. Some of park Lane, Hampstead Marshall         DESIGNATION:       Listed Building grade I, RPG grade II         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY CATEGORY:       C (C)	
east of entrance to Home Farm, Park Lane, Hampstead Marshall       remain in the north west corner of the park. Some of bricks have eroded; there is vegetation growth to the severely cracked stone and fractures through brickw and a shell niche. A programme of repairs needs to agreed and taken forward by the owners.         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY CATEGORY:       C (C)	
DESIGNATION:       Listed Building grade I, RPG grade II       and a shell niche. A programme of repairs needs to agreed and taken forward by the owners.         CONDITION:       Poor         OCCUPANCY:       N/A         PRIORITY CATEGORY:       C (C)	Some of the h to the tops; brickwork
CONDITION:     Poor       OCCUPANCY:     N/A       PRIORITY CATEGORY:     C (C)	
PRIORITY CATEGORY: C (C)	
© Historic England OWNER TYPE: Private	
LIST ENTRY NUMBER: 1136042 Contact: Rachel James 0207 973 3153	
SITE NAME: Three pairs of gate piers and walls around gardens and terrace at Home Farm, Park Lane, Hampstead Marshall Two late C17 walled gardens (one with raised terra three pairs of gate piers located in the north west co the park. Formerly the gardens to the C17 house w burnt down in 1718. Now forming the boundary wa	her of th to
DESIGNATION: Listed Building grade I, RPG grade II RPG grade II RPG	rnice
CONDITION: Very bad which puts the significance of the structure at risk. R	airs
OCCUPANCY: N/A to this section need to take place.	
© Historic England PRIORITY CATEGORY: C (C)	
OWNER TYPE: Private, multiple owners	
LIST ENTRY NUMBER: 1136034 Contact: Rachel James 0207 973 3153	

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WEST BERKSHIRE (UA)

	SITE NAME:	Church of All Saints, Station Road, East Garston	Church, Cl2 with Cl3/Cl4 work. Central tower, nave, chancel, transepts, south aisle, south porch and a Lady
DESIGNATION:       Listed Place of Worship grade II*       dressings. Roofs with porch. C19 works to installed, also work to installed, also wore work to installed, also work to installed, also wor	DESIGNATION:	Listed Place of Worship grade II*	Chapel. Walls are of flint with brick banding and limestone dressings. Roofs with Welsh slate coverings except the
	porch. C19 works to the nave roof, and a west window installed, also work to the Lady Chapel, chancel, the south		
	arcade and windows. Following porch repairs in 2019/20,		
	repairs to the tower are planned comprising masonry repair, re-pointing, repairs to upper windows and louvres.		
	LIST ENTRY NUMBER:	1321874	The pyramidal Welsh slate roof and parapet gutters to the tower roof also require repair.

### Contact: Rachel James 0207 973 3153

T.S.T.	SITE NAME:	Church of St Gregory, Welford	Church 1852-5 by T Talbot Bury, the Norman tower taken
DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:	Listed Place of Worship grade II*	down and re-built late C19. Flint, with stone dressings and clay plain tiled roofs. Tower, nave, aisles, chancel and south
	CONDITION:	Poor	porch. Four bay nave and aisles, arcade of two centred arches. Three bay chancel with stone vaulted roof. Slipped
	C (C)	and deteriorated roof tiles to the nave, aisles and porch in	
	OWNER TYPE:	Religious organisation	need of repair to avoid water ingress. Rainwater goods in poor condition. An application made to the National
m	LIST ENTRY NUMBER:	1117225	Lottery Heritage Fund Grants for Places of Worship scheme in 2017 was unsuccessful and the works continue
1 1			to be necessary.

© Historic England

© Historic England

Contact: Rachel James 0207 973 3153

SITE NAME:	Mombury Camp (soo also Wiltshiro Unitary Aut	hority) Lambourn / E	Pamshury
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
DESIGNATION:	Scheduled Monument	Scheduled Monument LIST ENTRY NUMBER:	
SITE NAME:	Long barrow on Sheep Down, 1km north of East Ilsley, East Ilsley		

SITE NAME:	Membury Camp (see also wildshire Unitary Authority), Lambourn / Ramsbury		
DESIGNATION:	Scheduled Monument, SM	LIST ENTRY NUMBER:	1003818
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Woodland management	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646

SITE NAME:	Moated site and three fishponds at Ufton Nervet, Ufton Nervet		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013176
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Daniel Bashford 07824 103 102

Aldermaston Court,

Registered Park and Garden

Generally unsatisfactory with

grade II, 12 LBs, part in CA

major localised problems

Mixed, multiple owners

Aldermaston

High

No

Declining

1000530



SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: TREND: NEW ENTRY ?: © Historic England

OWNER TYPE:

D

Е

LIST ENTRY NUMBER:

The remaining portion of Aldermaston Park, a mid-late CI9 landscape with remains of CI7/CI8 pleasure grounds, medieval deer park wood-pasture with many veteran or ancient trees of evidential value. Converted to commercial use with an office complex juxtaposed between the house and lake, planning permission remains for more offices. Sold in 2014 discussions for a sustainable long term future for the buildings are required by applying a conservation management plan process to the park and garden and caring for all the veteran trees and key parkland features that remain.

Contact: Kay Richardson 0207 973 3647

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WEST BERKSHIRE (UA) / ADUR / ARUN

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

	SITE NAME:	Shaw House, Newbury / Shaw cum Donnington	C16 or early C17 garden laid out by the Dolman family and a complex of early C18 water gardens by the Duke of
	DESIGNATION:	Registered Park and Garden grade II, 6 LBs, 2 CAs	Chandos. Bought by Berkshire County Council in 1946, National Lottery Heritage Fund and Historic England grants in 2005 restored the house as a conference centre and
Contraction of the second	CONDITION:	Generally unsatisfactory with major localised problems	heritage attraction which opened to the public in 2008. The development of an academy school, fragmented land management and poor public realm affects views and
Historic England	VULNERABILITY:	Low	landscape components. A Conservation Area Management
	TREND:	Stable	Plan funded by Historic England to understand and sustain significance and manage change is now complete.
	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1001446	Contact: Kay Richardson 0207 973 3647

### WEST SUSSEX

### ADUR

© Hi

E CL. Plints

Norman church built of Caen stone, containing a tall Church of St Mary De Haura, crossing tower with transepts to north and south, and a Church Lane, Shoreham by Sea large aisled chancel to the east. It is a mixture of Listed Place of Worship grade I, Romanesque and Transitional architecture. At risk due to CA the need for stone, roof and gutter repairs. Some urgent works have been completed, including stone and mortar Poor repairs to the lower stages of the tower with the benefit of PRIORITY CATEGORY: C (C) a grant from the Covid-19 Emergency Heritage at Risk Response Scheme. Most recently (2021) there have been Religious organisation roof repairs to the south transept and stone repairs, but further repairs are required. LIST ENTRY NUMBER: 1192780

Contact: Liz Pollard 0207 973 3650

© Historic England

SITE NAME:	Southlands		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	Colette Blackett (LPA) 01273 263242

### ARUN

	SITE NAME:	Blake's Cottage, Blake's Road, Felpham	Thatched brick and flint cottage dating from C17 with later alterations and extensions. It was the home of the poet,
	DESIGNATION:	Listed Building grade II*, CA	artist and visionary William Blake and his wife Catherine from 1800-1803, and where he wrote the words to the
	CONDITION:	Poor	hymn 'Jerusalem'. Purchased by The Blake Cottage Trust in 2015 since when the building has remained vacant. At risk
	OCCUPANCY:	Vacant/not in use	due to decay and failure of part of the roof structure and
	PRIORITY CATEGORY:	A (C)	thatch, and structural problems to the masonry. Urgently requires temporary roof covering to protect the vulnerable
	OWNER TYPE:	Charity (heritage)	thatch and roof structure below while funds are sought for sympathetic repairs.
	LIST ENTRY NUMBER:	1353792	Contact: Liz Pollard 0207 973 3650

© Historic England



D

Е

use)

SITE NAME:	Littlehampton Fort, Littlehampton	C19 fe main t
DESIGNATION:	Scheduled Monument	engulf Intere
CONDITION:	Poor	walls a under
OCCUPANCY:	N/A	owne
PRIORITY CATEGORY:	A (A)	the m manag
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1005809	Conta

fort. The fort is partly covered in ivy which poses the threat to the structure. Other parts of the fort are lfed by sand dunes which have Site of Special Scientific est status. A project to remove the ivy from the fort and ditches is in progress. This work is being rtaken by a local interest group in partnership with the er and will help to inform understanding of the risks to nonument and guide a long-term strategy for its agement.

act: Rebecca Lambert 0207 973 3630

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

WHS

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
  - Unitary Authority World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / ARUN / CHICHESTER

	SITE NAME:	Church of St Mary the Virgin, Church Street, Littlehampton	A large imposing geometric red brick church located in the town centre of Littlehampton. Originally constructed in
	DESIGNATION:	Listed Place of Worship grade II, CA	1826 by George Draper on the site of a medieval churc and then transformed in 1935 by WH Randoll Blacking. has an impressive galleried interior. The interior of the
	CONDITION:	Very bad	tower, aisles and galleries above are in poor condition with water damage, structural problems in the tower, erosion of
	PRIORITY CATEGORY:	A (A)	stone around the windows and loss of plaster on walls of
	OWNER TYPE:	Religious organisation	the gallery. Further investigations and a comprehensive programme of repairs are now urgently necessary.
	LIST ENTRY NUMBER:	1353769	Contact: Liz Pollard 0207 973 3650

© Historic England

# CHICHESTER

	SITE NAME:	Bell Tower of the Cathedral, Chichester	Grade I listed freestanding bell tower, adjacent to Chichester Cathedral. Circa early C15, probably the work
	DESIGNATION:	Listed Building grade I, CA	of William Wynford who also designed the cloisters, with Perpendicular style openings. The external surfaces of the
	CONDITION:	Very bad	stonework are degrading, and structural movement is evidenced by cracks in the buttresses. The Cathedral
	OCCUPANCY:	Part occupied/part in use	Restoration and Development Trust aspire to see the
	PRIORITY CATEGORY:	C (C)	fabric repaired and new, sustainable uses found for some of the under-utilised internal spaces.
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1026825	Contact: Liz Pollard 0207 973 3650

© Historic England

SITE NAME:	SITE NAME:	Former Church of the Assumption, Church Farm Lane, East Wittering	Medieval church, restored 1875-6. Not used for worship for some years. Some repairs have been carried out but future new uses have not been agreed.
	DESIGNATION:	Listed Building grade II*	
CONDITION:	CONDITION:	Fair	
i int	OCCUPANCY: Va	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1354484	Contact: Alma Howell 0207 9733 627

SITE NAME:	A Romano-Celtic temple, Iron Age shrine and associated remains 250m north west of Ratham Mill, Funtington			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018354	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Devil's Ditch, section extending 200yds (180m)	east from Chapel Lane	e, Funtington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005880	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Devil's Ditch, section extending 400yds (370m)	west from Chapel Lan	ie, Funtington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005881	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / CHICHESTER / HORSHAM

© Historic England	SITE NAME:	Lavington Park, Duncton / East Lavington, Chichester	Late C18 and C19 garden at the foot of the South Downs on the site of a late C16 house and garden set within a park
	DESIGNATION:	Registered Park and Garden grade II, 7 LBs	of C18 origin, largely planted in the C19 and further altered in the C20. The house with extensive panoramic views north is now a school. School buildings and enabling
	CONDITION:	Generally satisfactory but with significant localised problems	development within the park has eroded historic character and designed landscape intentions. A heritage led estate plan by the school was discussed with The South Downs
	VULNERABILITY:	Medium	NPA in 2017 to improve conservation management as historic and aesthetic value of the site is vulnerable to futher change and development.
	TREND:	Stable	
	NEW ENTRY ?:	No	
	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1001213	Contact: Kay Richardson 0207 973 3647

SITE NAME:	Graylingwell, Chichester, Chichester		
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Improving significantly
VULNERABILITY:	High	CONTACT:	Conservation and Design (LPA) 01243 785166

# HORSHAM

© Historic England

1000

C



Ruins of Sedgwick Castle, Moated site, Nuthurst Ruinous moated medieval castle. The exposed parts of this SITE NAME: structure are in a very poor state of repair and continue to deteriorate. A conservation strategy has been agreed but Scheduled Monument, RPG needs to be implemented to enable the monument to be DESIGNATION: grade II conserved and maintained. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C)

III

OWNER TYPE:	Private, multiple owners				
LIST ENTRY NUMBER:	1009579	Contact: Alison McQuaid 0207 973 3646			
SITE NAME:	Kings Windmill, Shipley	Four-storey smock mill on a two-storey brick base of 1879.			
DESIGNATION:	Listed Building grade II*, CA	Upper storeys faced with weather- boarding. Attached one storey engine house of 1880. The mill was bought in 1906			
CONDITION:	Poor	by the author Hilaire Belloc, who owned it until his death in 1953. The owners continue a programme of repainting			
OCCUPANCY:	Part occupied/part in use	and minor repairs but a more comprehensive repair			
PRIORITY CATEGORY:	C (New entry)	scheme is required. The cap no longer turns and the shutters have been removed from the sweeps to prevent			
OWNER TYPE:	Private	high winds putting stress on the structure. The fan tail has been removed and there has been some water ingress			
LIST ENTRY NUMBER:	1180806	through the cap.			

© Historic England



義	SITE NAME:	Church of St Peter, Station Road, Cowfold	Large medieval village church built of Wealden sandstone with stone roofs. At risk due to defective roofing to the
A.	DESIGNATION:	Listed Place of Worship grade I, CA	chancel and internal plaster ceilings. Previous Historic England/National Lottery Heritage Fund grant-funded repairs successfully completed but a final phase now
13	CONDITION:	Poor	required in order to remove the church from the Heritage at Register. The weathervane was repaired in 2021.
	PRIORITY CATEGORY:	C (C)	at Register. The weathervalle was repaired in 2021.
1 Par	OWNER TYPE:	Religious organisation	
EU.	LIST ENTRY NUMBER:	1354161	Contact: Liz Pollard 0207 973 3650

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Rachel James 0207 973 3153

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / HORSHAM / MID SUSSEX

	SITE NAME:	Church of St Peter, Upper Beeding	Medieval church built of a mixture of ashlar and rubble stone with areas of flint. The roofs have stone slab on the
	DESIGNATION:	Listed Place of Worship grade II*	outer slopes and tiled inner slopes. The church is at risk due to defects to the roofs, rainwater disposal and
	CONDITION:	Poor	stonework. Historic England/National Lottery Heritage Fund grant-aided repairs to the tower and valley gutter,
	PRIORITY CATEGORY:	C (C)	and repairs have been carried out to the chancel roof and
	OWNER TYPE:	Religious organisation	gable walls. However further repairs are required to the rainwater drainage and the window behind the organ.
	LIST ENTRY NUMBER:	1027214	There has been some work to the dangerous church walls recently (2021).
			recently (2021).

© Historic England



SITE NAME:	Church of All Saints, Steyning Road, Buncton, Wiston	Water penetration and damp are contributing to this medieval church's declining condition. The worsening
DESIGNATION:	Listed Place of Worship grade I	condition of the stone slab roof dating to the early $\tilde{C20}$ phase of restoration is leading to water ingress,
CONDITION:	Poor	deterioration roof the structure and the ceiling below. Built principally of flint, the hard cement-based pointing is
PRIORITY CATEGORY:	C (New entry)	contributing to internal damp problems with rotting
OWNER TYPE:	Religious organisation	internal wood fittings and algal growth. Consequently, the medieval wall paintings are vulnerable to deterioration. The
LIST ENTRY NUMBER:	1354113	growing congregation hopes to develop a repair project.
		Contact: Liz Pollard 0207 973 3650

Contact: Liz Pollard 0207 973 3650

© Historic England

SITE NAME:	Bowl barrow on Black Hill, Colgate		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011596
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Alfoldean Roman site, Slinfold		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005838
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Billingshurst		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sean Rix (LPA) Horsham District Council 01403 215100

# MID SUSSEX



D

Е

use).

SITE NAME:	Church of Holy Trinity, Church Street, Cuckfield	
DESIGNATION:	Listed Place of Worship grade I, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1191625	

Church mainly constructed in the C13 and C14, comprising nave, chancel, aisles, chapels, vestry, north and south porches, and West tower with shingled broach spire. Walls of sandstone rubble with some areas of rough squared ashlar and render. Significant C19 painted decorative scheme to nave and chancel ceilings by Kempe. At risk due to falls of high level cementicious pointing and decaying stonework to tower; leaking, corroded and blocked rainwater goods and slipping roof slabs,

Contact: Liz Pollard 0207 973 3650

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / MID SUSSEX / SOUTH DOWNS (NP)

SITE NAME:	Motte and bailey castle 240m east of Dean's Mill,	Motte and bailey castle 240m east of Dean's Mill, Lindfield Rural			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011776		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646		
SITE NAME:	Fairfields, Burgess Hill, Burgess Hill				
DESIGNATION:	Conservation Area	NEW ENTRY?:	No		
CONDITION:	Very bad	TREND:	No significant change		
VULNERABILITY:	Medium	CONTACT:	Angela Heyward (LPA) 01444 477385		

Amberley Limeworks; entrance

buildings, Kiln 2 and Office, Houghton Bridge, Houghton /

Amberley, Horsham

Scheduled Monument

Charity (heritage)

Part occupied/part in use

Poor

C (C)

1005810

# SOUTH DOWNS (NP)



	SITE NAME:	The chapel at the former King Edward VII Hospital, Easebourne, Chichester	L-shaped former chapel for tuberculosis patients by Charles Holden, 1903-6. Later mortuary wing has been demolished and replaced with a new swimming pool which
	DESIGNATION:	Listed Building grade II*, RPG grade II	is in use, but the chapel remains vacant. Most of the repairs have been completed but lack of maintenance is leading to water penetration and damage of original building fabric.
	CONDITION:	Fair	Historic England has provided advice to the owner on addressing these issues.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1232485	Contact: Alma Howell 0207 9733 627





SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic	England	Archive
------------	---------	---------



© Historic England

ALL	SITE NAME:	Castle Goring, Arundel Road , Worthing	Large house. Built by the poet Shelley's grandfather, Sir Bysshe Shelley, about 1797-8. The house was in very poor
	DESIGNATION:	Listed Building grade I	condition for many years. In 2013 the house was sold to a private individual who is now using it as a private residence
	CONDITION:	Fair	and wedding/conference venue. Consent for change of use was granted and repairs to the roof, stairs and structural
	OCCUPANCY:	Part occupied/part in use	timbers were carried out but further repairs remain
	PRIORITY CATEGORY:	F (F)	necessary, including to the glass dome.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1025839	Contact: Liz Pollard 0207 973 3650

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

C19 lime works including kilns and associated buildings.

now complete. However, the ingress of rainwater, vegetation growth and decay have led to structural

for repairs to the Loading Shed.

Contact: Liz Pollard 0207 973 3650

Historic England grant aided repairs to the Locomotive Shed, Blacksmith's Shop and part of the Loading Shed are

weaknesses to the rest of the Loading Shed, the Southern Lime Kilns and Kiln No. 2. The De Witt Kilns were added

to the Register following the collapse of part of the parapet

wall in 2021. Secured Arts Council England funding in 2022

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP)

A	SITE NAME:	Church of St Nicholas, London Road, Arundel, Arun	Church of England town church, re-built in 1380. The adjacent Fitzalan Chapel and Lady Chapel to the east are in
	DESIGNATION:	Listed Place of Worship grade I, CA	Roman Catholic use. The church is at risk due to spalling stonework, decay to the west window, defective roofs and drainage. In 2020 emergency holding repairs were carried
	CONDITION:	Poor	out to the west window, with further discussions to consider its full repair. There were also emergency repairs
	PRIORITY CATEGORY:	C (C)	to the north aisle. However further permanent repairs are
	OWNER TYPE:	Religious organisation	required, including to the south aisle.
	LIST ENTRY NUMBER:	1027914	Contact: Liz Pollard 0207 973 3650

© Historic England

SITE NAME:	Flint mine and a bowl barrow on Church Hill, 400	Om south west of Fin	don Place, Findon, Arun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015238
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section extending 900yds (820m), L	ye Wood, West Sto	ke, Funtington, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005882
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE: Private, multiple owners CONTACT:		Alison McQuaid 0207 973 3646	
SITE NAME:	Linear boundary on Stoke Down, 800m north of	West Stoke House,	Funtington, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018564
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Flint mine on Stoke Down, immediately north of	Stoke Clump, Funtin	gton / Lavant, Chichester
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018563
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Bexley Bushes earthworks, Lavant, Chichester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005892
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Devil's Ditch, section 230yds (210m) long from C	hichester main road	to Pook Lane, Lavant, Chichester
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005877
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Alison McQuaid 0207 973 3646

### PRIORITY CATEGORIES

# А

В

C Slow decay; no solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Slow decay; solution agreed but deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user)

 use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / SOUTH DOWNS (NP) / WORTHING

SITE NAME:	Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant, Chichester			
DESIGNATION:	Scheduled Monument, part in RPG grade I	LIST ENTRY NUMBER:	1005878	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Duncton Common round barrow cemetery, Petwo	orth / Duncton, Ch	ichester	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009329	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Bowl barrow on Fitzhall Rough, 330m ENE of Fitzh Stedham with Iping, Chichester	all: part of Fitzhall	Rough round barrow cemetery,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008503	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Motte and bailey castle in Pulborough Park, Pulbor	ough, Horsham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017547	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Bowl barrow 950m south west of Grey Friars Farr Hill, Storrington and Sullington, Horsham	n: part of a disperse	ed round barrow cemetery on Kithurs	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015711	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Alison McQuaid 0207 973 3646	
SITE NAME:	Greatham, Horsham (District), Parham, Horsham			
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Planning Performance and Technical Team (LPA) 01730 814810	

# WORTHING

N		
	SI	
m	mu	
1	are a	ALC: NO.

Holy Trinity Church, Shelley SITE NAME: Road, Worthing DESIGNATION: Listed Place of Worship grade II CONDITION Poor Worthing. PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1393419

Large church, brick with stone dressings. Designed by Henry Coe and Stephen Robinson and built 1882-88. At risk due to eroding high level brick and stonework to the tower and decaying timber shingling to spire. Included in current discussions as part of a wider review of churches in

Contact: Liz Pollard 0207 973 3650

© Historic England

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS

# WINDSOR AND MAIDENHEAD (UA)

S

Г

C

C

Р

C L



HEAD (UA)		
SITE NAME:	Royal Mausoleum, The Home Park, Windsor	Mausoleum of Queen Victoria and Prince Albert, 1862-71. Damp problems put external and internal historic fabric at
DESIGNATION:	Listed Building grade I, 2 RPGs	risk, including internal paintings. Original rainwater drainage was inadequate and poorly designed. Consented
CONDITION:	Fair	programme of repairs was completed in 2019 to make the exterior weather-tight and prevent moisture from entering
OCCUPANCY:	N/A	the building via the raised perimeter paving. Since 2009 an
PRIORITY CATEGORY:	F (F)	environmental monitoring regime confirms high level drying out. Regular monitoring continues. It will be some years
OWNER TYPE:	Crown	before the building is dry enough to accommodate interior conservation work.
LIST ENTRY NUMBER:	778	Contact: Jane Sidell 020 7973 3738

© Historic England



SITE NAME:	Noah's Boathouse, Stonehouse Lane (Off), Cookham	1930 by Colin Lucas for his father. Constructed of monolithic reinforced concrete with a flat roof. An early	
DESIGNATION:	Listed Building grade II*	and pioneering example of Modern Movement architecture by one of the major figures in the movement. The building	
CONDITION:	Poor	floods regularly and is derelict. The roof is leaking and the concrete is spalling. A project to address the issues needs	
OCCUPANCY:	N/A	to be agreed.	
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Private		
LIST ENTRY NUMBER:	1323741	Contact: Rachel Fletcher 0207 973 3846	

© Historic England

© |

	SITE NAME:	The Cock Pitt, 47-49, High Street, Eton	C15 timber framed building, with approvals for conversion to residential use retaining commercial units at ground
	DESIGNATION:	Listed Building grade II*, CA	floor. Works commenced on site, but the developer suffered financial difficulties and as a result work stopped
	CONDITION:	Poor	leaving the building partially stripped and in deteriorating condition. An Urgent Works Notice to secure the building
	OCCUPANCY:	Vacant/not in use	was served in 2020 which was complied with by the
	PRIORITY CATEGORY:	C (A)	owner. A Repairs Notice was served in 2021. The property has changed hands and a schedule of repairs is
	OWNER TYPE:	Commercial company	being déveloped.
) Historic England	LIST ENTRY NUMBER:	1290036	Contact: Rachel James 0207 973 3153

SITE NAME:	Beenham's Heath, Waltham St. Lawrence		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Roderick McDonald (LPA) 07969 504 872

### WOKINGHAM (UA)



SITE NAME: Ruins of St Bartholomews Church (Arborfield), Arborfield and Newland Scheduled Monument, LB grade DESIGNATION: Ш CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1006975

Previously the parish church, now a roofless ruin. Originally CI3 and built in flint and stone, with substantial probable C18 brick rebuilding. One wall partially standing, with other fragments of later brick segments. Very overgrown and there is a risk of further collapse. A project to see the ruins conserved, explained and maintained still needs to be agreed and implemented.

© Historic England

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA

WHS

### HERITAGE AT RISK 2023 / LONDON AND SOUTH EAST / WOKINGHAM (UA)



SITE NAME: Former Infirmary Stables, Arborfield Garrison, Barkham DESIGNATION: Scheduled Monument CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1006949

A specialised 'horse hospital' built 1911-12. The building became redundant by virtue of changes in army practices (reduced cavalry activity). Planning Permission for the development of Arborfield Garrison included a requirement to repair the stables. Works to clear asbestos from the site and repair the external envelope have been completed. An end use for the building is being considered and long-term management/maintenance plan agreed.

Contact: Rachel James 0207 973 3153

© Historic England

SITE NAME:	Ring ditch cropmark east of St Patrick's Avenue, Charvil			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006965
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Cropmark complex south west of St Patrick's Avenue, Sonning			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006964
CONDITION:	Extensive significant problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646
SITE NAME:	Cropmark site east of Broadmoor Lane, Sonning			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1006963
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY ?:	No
OWNER TYPE:	Educational (state sector)		CONTACT:	Alison McQuaid 0207 973 3646
	SITE NAME:	Bearwood College, Barkham / Winnersh / Arborfield and Newland	This C19 landscape park and woodland surrounds a Victorian country house on formal terraces overlooking a picturesque lake with early designs by Gilpin and a Pulhamite garden. Subject to recent alterations with the gardens and pleasure grounds a private school and charitable trust, the wider park a golf course and Reading FC's training site, the parkland features are varying in condition. Funded proposals for tree management and Pulhamite garden repairs were coordinated through a	
	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs		
	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY:	Medium	conservation ma	conservation management plan and liaison group in 2018
© Historic England	TREND:	Stable	With works now being progressed advice is ongoing.	

Contact: Kay Richardson 0207 973 3647

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

NEW ENTRY ?:

OWNER TYPE:

LIST ENTRY NUMBER:

No

1000414

Mixed, multiple owners

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA WHS

This document is one in a series of regional registers produced as part of Historic England's national Heritage at Risk programme. The registers for other regions and previous Heritage at Risk publications can be found at historicengland.org.uk/advice/heritage-at-risk/ registers-and-publications/ More information about Historic England's Heritage at Risk programme can be found at historicengland.org.uk/advice/heritage-at-risk/

Heritage at Risk Published November 2023 4th Floor, Cannon Bridge House 25 Dowgate Hill London EC4R 2YA © Copyright Historic England 2023 Product code: HE0081



London & South East Register 2023