





HERITAGE AT RISK REGISTER 2009 / SOUTH EAST

Contents

HERITAGE AT RISK	2
Buildings at Risk	6
Monuments at Risk	8
Parks and Gardens at Risk	10
Battlefields at Risk	12
Shipwrecks at Risk	13
Conservation Areas at Risk	14
The 2009 Conservation Areas Survey	16
Publications and guidance	20
THE REGISTER 2009	21
Contents	21
The register – content and assessment criteria	22
Key to the entries	24
Heritage at Risk entries	26

HERITAGE AT RISK IN THE SOUTH EAST

- Registered Battlefields at Risk
- Listed Buildings at Risk
- Scheduled Monuments at Risk
- Registered Parks and Gardens at Risk
- Protected Wrecks at Risk
- Local Planning Authority



HERITAGE AT RISK

We are all justly proud of England's historic buildings, monuments, parks, gardens and designed landscapes, battlefields and shipwrecks. But too many of them are suffering from neglect, decay and pressure from development. Heritage at Risk is a national project to identify these endangered places and then help secure their future.

In 2008 English Heritage published its first register of Heritage at Risk – a region-by-region list of all the Grade I and II* listed

buildings (and Grade II listed buildings in London), structural scheduled monuments, registered battlefields and protected wreck sites in England known to be 'at risk'. A year later, this second updated regional edition of the register has been enlarged to include details of all scheduled monuments (archaeological sites) and registered parks and gardens, as well as conservation areas designated by local authorities that are also reported to be at certain or potential risk.

The South East region is a rich and varied landscape of historic towns and cities, rural villages, coastal resorts and outstanding countryside. This quality of the historic environment is fundamental to its appeal as a place to live and work. Understanding the condition of this remarkable heritage resource is therefore vital if we are to sustain it in the long-term for future generations.

ETTANDING ESTIMATED OUTSTANDING CONSERVATION DEFICIT FOR BUILDINGS AT RISK ALONE

In total, the expanded South East register of Heritage at Risk in 2009 contains some 582 heritage assets, featuring not only Grade I and II* listed buildings, protected historic wreck sites and registered battlefields, but for the first time detail on registered parks and gardens, scheduled monuments and conservation areas. Identifying those assets that are at risk and monitoring their condition will help us to plan and prioritise our expertise, resources and grant investment effectively in order to secure sustainable solutions for their futures.

In its first ten years, the Buildings at Risk register proved a useful focus for this and helped direct our investment priorities. The register was effective in highlighting need. Working with owners and partners and providing substantial grant-aid, we have now secured the future of a total of 109 buildings from the original register of 1999. In 2008/9 alone, we succeeded in removing 10 entries and offered grants totalling £417k towards ten different Heritage at Risk projects. We will continue to use the register as the principal guide for our investment strategy in the future, focusing our funds and expertise towards those assets and owners with the greatest need for our help.

But this will be ever-more challenging in the future with the additional number of assets now on the register, the varying nature and scale of risk to each asset type, and the current economic climate - for entries on the Buildings at Risk register alone, there is an estimated conservation deficit of £72.3m. Each asset type will require a different approach. Many parks and gardens, for example, are in multiple ownership and unlike buildings they often lack an obvious commercial benefit to warrant investment. Similarly, the local authorities that designate conservation areas and have responsibility for their management are under increasing budgetary pressures; in particular, conservation staff are being reduced in many councils. This will inevitably have an impact on the quality and character of conservation areas in the future.

Resolving these cases will not be easy but we are committed to working with partners to deliver lasting solutions that will contribute to making quality places for the benefit of the entire region.

Andrew Brown, Planning and Development Regional Director, South East

Contact: Simon Goodhugh, Business Manager, English Heritage South East Region, Eastgate Court, 195-205 High Street, Guildford, GUI 3EH Telephone: 01483 252037 Fax: 01483 252021 Email: simon.goodhugh@english-heritage.org.uk

Heritage at Risk 2009

The 2009 register for England includes 5,094 nationally designated sites that are at risk, along with 727 locally designated conservation areas at risk. These sites are important and irreplaceable elements of our historic environment and help contribute to local and national character. By assessing their condition and identifying which are most at risk, we can define the scale of the problem and plan and prioritise the resources needed to bring them back into good repair – and, where appropriate, into practical use – for the benefit of present and future generations.

This year more than 400 heritage assets have been added to the South East Heritage at Risk register. These include one additional protected wreck site, 140 conservation areas, 270 scheduled monuments, and 24 registered parks and gardens. Alongside this the region still has I registered battlefield at risk, 6 other protected wreck sites at risk and some I67 entries on the Buildings at Risk register. With nearly 600 individual elements of the historic environment of the South East now officially 'at risk' the statistics paint a disturbing picture.

THE NATIONAL PICTURE

The table on the opposite page sets out the number and percentage of nationally designated assets that have been identified as 'at risk'. The significant variations in the proportions at risk reflect important differences not only in the physical character of the historic assets, but also differences in the way in which they are used. Buildings generally have an economic value to their owners, particularly when capable of adaptive use. The percentage of Grade I and II* listed buildings at risk (3.1%) is thus lower than for the other asset types.

By contrast, assets that have far less economic benefit have higher percentages at risk. Archaeological monuments have little direct economic benefit and, as a result, often suffer from neglect, and a far higher percentage, 17.9%, is at risk. The main threats to historic landscapes, parks, gardens and battlefields come from either neglect or from unsympathetic development -6% of parks and gardens and 16.3% of battlefields are currently at risk. The main threats facing wreck sites are from the forces of the sea and natural decay, and wreck sites have the highest proportion at risk (19.6%) of all asset types. The relatively low proportion of listed buildings at risk is also the result of work that has been put in by individuals and agencies over many years to identify them and then secure their future. English Heritage began assessing the condition of listed buildings in the 1980s, publishing the first annual register of Buildings at Risk in London in 1991, and the first national register of Grade I and II* listed buildings and structural scheduled monuments at risk in 1998.

The registers have enabled English Heritage and its partners in local authorities, building preservation trusts and funding bodies, as well as owners, to understand the extent of the problem and to prioritise action and resources. As a result, the proportion of England's highest-graded (I and II*) listed buildings at risk has fallen steadily from 3.8% in the baseline year of 1999 to 3.1% this year. Of the Grade I and II* listed building and structural scheduled monument entries on the baseline register, 48% have now been removed.

While the condition of the nation's Grade I and II* listed buildings has improved, this year's Heritage at Risk registers show that England's other nationally designated heritage assets face much greater levels of risk, and highlight the scale of the challenge and the resources needed, both at a national and local level.

Working with property owners and our partners, we aim to achieve similar progress in reducing risk to other heritage assets. This will be challenging in the current economic climate, given the high proportion of heritage sites that do not, even in more prosperous times, generate an income. Their importance as part of our heritage is nevertheless immeasurable, and their urgent needs must not be ignored.


Inclusion of sites on this register does not imply criticism of their owners, many of whom are actively trying to secure their future. While we have tried to ensure that the information included is accurate, we will correct any errors or omissions brought to our attention. We welcome further information and corrections.

Further information on heritage at risk is given on page 20, and on our website: **www.englishheritage.org.uk/risk**. An interactive database providing detailed information on all heritage sites at risk nationally can also be found on our website.

SOURCE OF RISK TO SCHEDULED MONUMENTS IN THE SOUTH EAST

SOURCE OF RISK	NUMBER	PERCENTAGE
Arable ploughing / clipping	150	56
Scrub / tree growth	38	4
Animal burrowing	26	10
Deterioration – in need of management	16	6
Plant growth	15	6
Collapse / subsidence	7	3
Other*	5	2
Coastal erosion	3	1
Development requiring planning permission	3	1
Forestry	2	
Stock erosion	3	1
Vandalism	2	1

* 'Other' category includes Flooding (0.4%), Natural erosion (0.4%), Rain entry (0.4%), Vehicle damage / erosion (0.4%) and Visitor erosion (0.4%)




NUMBER AND PERCENTAGE OF HERITAGE ASSETS AT RISK NATIONALLY AND IN THE SOUTH EAST


ASSET TYPE	ENGLAND 2009			SOUTH EAST 2009		
	NO. OF ASSETS	NO. OF ASSETS AT RISK	% AT RISK	NO. OF ASSETS	NO. OF ASSETS AT RISK	% AT RISK
GRADE I AND II* LISTED BUILDING ENTRIES	30,776	969	3.1%	5,561	104	1.9%
GRADE II LISTED BUILDING ENTRIES IN LONDON	16,561	401	2.4%	N/A	N/A	N/A
SCHEDULED MONUMENTS	19,719	3,535	17.9%	2,627	270	10.3%
REGISTERED PARKS AND GARDENS	1,600	96	6.0%	366	24	6.6%
REGISTERED BATTLEFIELDS	43	7	16.3%	366	24	6.6%
PROTECTED WRECK SITES	46	9	19.6%	366	24	6.6%

The number of assets at risk in the South East is 406 (England, 5,017) and the total number of entries on the South East register is 442 (England, 5,094). The difference is due to a small number of scheduled monuments with structural elements which are not also listed Grade I or II* and which are assessed as and included on the register as buildings at risk.





PERCENTAGE OF REGISTERED PARKS AND GARDENS AT RISK BY GRADE At risk Not at risk



WESTENHANGER BARN, KENT

Westenhanger Barn, dating from the 16th century, is an extravagantly designed building adjacent to a 14th-century castle – Kent's forgotten great country house of the Tudor period. This unusual and massive barn was part of the service buildings but has a magnificent hammer-beam roof.

The barn has featured on the Buildings at Risk register since 1999 and, following consolidation into single ownership with the castle in 2003, is now part of a major programme of conservation works throughout the site. Work to repair the barn itself finally began in 2007 following technical advice and a grant of £500,000 from English Heritage.

Progress on conserving the barn progresses well and is due to complete in autumn 2009. After careful conservation of the roof timbers work on the daunting task of re-laying the thousands of clay peg tiles on its roof slopes is under way.

6



BUILDINGS AT RISK

Of England's 30,776 outstandingly important Grade I and II* listed buildings, 969 (3.1%) are at risk through neglect and decay (or vulnerable to becoming so). This year, the future of 69 buildings on the national register has been secured, while 64 newly identified buildings have been added. Of the entries on the original 1999 baseline register, 48% (685) have now been removed, but the rate of removal is slowing as we and our partners strive to resolve

the more intractable cases.

In the past year, English Heritage offered £9.5 million to 113 buildings at risk: £8.5 million to 102 Grade I and II* listed buildings, £248,000 to Grade II buildings in London and £721,000 to places of worship (under the scheme we fund jointly with Heritage Lottery Fund). Since 1998/99, we have offered £54.4 million in grants to Grade I and II* listed buildings at risk.

There are 167 Grade I and II* listed buildings or structural scheduled monuments at risk entries on the Heritage at Risk register 2009, just two fewer than in 2008. This figure represents 13.6% of the total number of entries on the national register, the highest percentage in any region. Proportionally, the South East also has the highest number of structural scheduled monuments on its Buildings at Risk register when compared with the other regions, which reflects the large number of important former defence sites we have in the region.

This year a total of 10 entries were removed from the register, but this was offset by 9 new entries being added (plus one entry being reassigned to the Scheduled Monuments at Risk category). Of the 10 removed, 8 were on the original Buildings at Risk register of 1999, meaning that in the last eleven years we have secured the future of 109 of the original 233 entries on the baseline register – more than any of the other regions. With 47% of entries now removed, the region is approaching the half-way mark. However, it also means that it is the most intractable and challenging cases that remain on the register, where sustainable solutions are hardest to find.

We are, however, still making significant progress with some of those intractable cases. The Tudor Shurland Hall in Kent, for example, was on the 1999 register and with an English Heritage grant of £300K the Spitalfields Trust has made remarkable progress with the repair of the gatehouse so that it can be re-occupied as a house. Our experience in the last eleven years has taught us that whilst our grant-aid is often a crucial tool in brokering solutions, money is not always the vital ingredient to securing success for these cases. The key steps are often taken through developing successful partnerships with owners, local authorities and other partners. This will become ever more important as competition for our grants is spread across a much larger Heritage at Risk register.



OLD SHOREHAM TOLL BRIDGE, WEST SUSSEX

This historic bridge links Shorehamby-Sea to Lancing and Worthing by spanning the River Adur tidal estuary. In 1968 it became a public bridleway having previously formed part of the heavily used A27 road.

The ravages of time and weather gradually took their own toll on the bridge. Thanks to the Old Shoreham Community Trust, funds, including a grant from the Heritage Lottery Fund, were raised to repair the bridge. Work was completed during 2008, allowing the bridge to be removed from the Heritage at Risk register this year.

MONUMENTS AT RISK

Since the launch of Monuments at Risk, almost 900 scheduled monuments have been removed from the 'at risk' category, representing a reduction of around 20% nationally. Since 2008 a rigorous checking and updating exercise has been undertaken by the regional teams. While this work identified some inconsistencies (not least the inclusion of scheduled monuments containing structural elements more suitable for the Buildings at Risk register),

this reduction is irrespective of these changes. By any measure the improvement represents a remarkable achievement and demonstrates the validity of the Heritage at Risk initiative.

These impressive results should not make us complacent; highlighting the risk in order to begin a dialogue with owners of monuments is only the first stage of what can be a long process. While small changes in management can often do much to improve condition, securing the future of a significant proportion of monuments will require further study, partnership working and resources. This cannot be achieved overnight.

The Heritage at Risk register 2009 contains for the first time a full listing of the 270 scheduled monuments at risk in the region, representing 10.3% of the region's 2,627 scheduled monuments. They include prehistoric burial mounds and hillforts, Roman towns, villas and forts, medieval settlements, castles and abbeys and post-medieval fortifications and industrial structures. The vast majority of at risk scheduled monuments are in private ownership, with just 6% owned by central government or its agencies and 4% by local authorities. The most common form (54%) of at risk scheduled monument is an ancient earthwork.

These monuments are all vulnerable to a wide range of damaging human activities and natural processes, arable farming being the predominant threat with 56% at risk from this. Scrub and tree-growth are a threat to a further 14%, and extensive animal burrowing to a further 10%. All but 8 of the scheduled monuments at risk are considered to be in a state of active decline.

With many other important sites classified as at medium risk through our survey work, it is clear that more than half of all monuments need urgent action to prevent deterioration, loss or damage. English Heritage will be dedicating some of its grant aid in 2009/10 to developing solutions for scheduled monuments at risk. This itself will pose new challenges, not least because we must recognise the increasing pressure on our agricultural land to produce not only food but also energy crops as we square up to the challenges of climate change.

SEVEN BARROWS, LAMBOURN, WEST BERKSHIRE

This well-preserved Bronze Age cemetery is both a scheduled monument and a Site of Special Scientific Interest was recently reduced from high to low risk. The site is managed as a nature reserve by the Berkshire, Buckinghamshire and Oxfordshire Wildlife Trusts.

Rabbits had caused substantial disturbance of archaeological remains and the chalk grassland was in an unfavourable condition so English Heritage, English Nature and West Berkshire Council worked together to protect the archaeological remains and promote biodiversity through the installation of stock and rabbit fences and the introduction of Dexter cattle for conservation grazing.



LEWES PRIORY, EAST SUSSEX

Established in the late II th century, Lewes Priory was the first Cluniac foundation in Britain. The ruins are exceptionally significant but at risk because of the serious decay of the stonework. A solution, however, has now been agreed. The Lewes Priory Trust has received grants from English Heritage and the Heritage Lottery Fund for conservation and the provision of free access and interpretation and it is anticipated that Lewes Priory Park will eventually create a long-lasting and sustainable heritage benefit for the town.

NEWBOLD COLLEGE, BRACKNELL, BERKSHIRE

Moor Close estate, now the home of Newbold College, includes an Edwardian mansion that was the first house and garden to be designed by Oliver Hill in an early 20th-century Arts and Crafts style. The intricate gardens comprise fragile fabric with interesting architectural features and decoration. A condition survey has been completed with a grant from English Heritage. Some restoration work has been undertaken but other parts of the garden have continued to deteriorate; restoration is expensive because of the architectural nature of the garden. Unfortunately a recent pre-application to the Heritage Lottery Fund was unsuccessful as the College is unable to fulfil the public access criteria.



There are only 1,600 parks and gardens registered for their historic interest, so each is very special. Diverse in style and size, they reflect the fashions and aspirations of past generations. These art forms are one of the foundations to our national passion for gardens and gardening. But all is not rosy and some are threatened by development pressures or are neglected and decaying.

For the first time, English Heritage is publishing a list of those that are vulnerable as part of its Heritage at Risk register. Some 6% of sites are considered to be at risk and most of these are

deteriorating. The pattern of parks and gardens at risk is similar across the country. With the aid of the Heritage at Risk register, English Heritage is able to take stock of the pressures and challenges to the historic interest of these sites, and direct advice and grants towards those whose historic significance is most at risk.

For the first time, the Heritage at Risk register 2009 contains full listings of the 24 registered parks and gardens considered to be at risk in the South East, 6.6% of the total number of registered landscapes in the region. This is a significantly higher number than any other region, and represents one quarter of the 96 sites considered at risk nationally. Of the South East sites at risk:

- 16 of the 24 are registered Grade II, 7 are Grade II*, one is Grade I (Brookwood Cemetery)
- 19 of the 24 sites are considered to be actively deteriorating

- Only 7 have a full or partial conservation management plan
- The principal risks to these landscapes are from development and/or neglect.

English Heritage will be dedicating some of its grant aid in 2009/10 to working with owners and partners to develop solutions for registered parks and gardens at risk. This may be in the form of direct grant-aid for improvement works, or to help site owners to invest in a conservation management plan as the first step to managing the risks.



CLAREMONT LANDSCAPE GARDEN, SURREY

Claremont is a beautiful Grade I garden, the creation and development of which involved many of the great names in garden history, including Sir John Vanbrugh, Charles Bridgeman, William Kent and 'Capability' Brown. In 1726 it was described as 'the noblest of any in Europe'. A recent conservation management plan now proposes the re-establishment of a physical link between the pleasure grounds, now in the care of the National Trust, and other parts of the park that are in separate ownership.

BATTLEFIELDS AT DR I SK

The Register of Historic Battlefields contains 43 sites that have been selected as the most important, identifiable military engagements on English soil. These were often the turning points of English history – places where people risked their lives fighting for a cause. Not all regions have registered battlefields which are classified as 'at risk' in the national 2009 register, but as the case study below illustrates, such sites are vulnerable to loss because

they can cover large areas of ground and their extents are rarely obvious. They often appear little different to other parts of the country, with their interest lying in their landscape, their archaeology and as a place of commemoration. Furthermore, while inclusion on the Register affords special consideration for the battlefield in the planning process, it does not protect against threats that do not require planning permission.

TOWTON BATTLEFIELD, NORTH YORKSHIRE

High, bleak, arable land near Tadcaster was the scene of a ten-hour battle on 29 March 1461 during the Wars of the Roses. Fought in a snow storm, the battle is said to have claimed 28,000 lives. Artefacts and arrowheads from the battle have been consistently targeted by metal detectorists, some unauthorised and working independently of any agreed archaeological survey. At least one episode of deep ploughing may have disturbed a possible mass grave. Today, the Towton Battlefield Society has a strong and active membership that seeks to protect the battlefield and promote research and education. © Glenn Foard



REGISTERED BATTLEFIELDS AT RISK IN ENGLAND

- I Newburn Ford (1640)
- 2 Boroughbridge (1322)
- 3 Stamford Bridge (1066)
- **4** Towton (1461)
- 5 Adwalton Moor (1643)
- 6 Newbury I (1643)
- **7** Langport (1645)



SHIPWRECKS AT RISK

Not every region's 2009 Heritage at Risk register features a shipwreck at risk, but in the English territorial sea as a whole the density of shipwreck remains is among the highest in the world. Our 46 protected sites represent a tiny proportion – just 1 in 706 – of the 32,476 pre-1945 casualties known to lie in the territorial sea. Wrecks are vulnerable to both environmental and human impacts. Because they are in remote locations, their management

can be challenging – and changes to their condition are difficult to anticipate. In 2009 English Heritage audited all designated wreck sites to better understand their condition and vulnerability. As a result, nine sites were deemed to be most at risk and are included on the national Heritage at Risk register – an example is *Swash Channel* off the Dorset coast (below).



SWASH CHANNEL WRECK, DORSET

In October 2004, archaeological assessment work in advance of channel deepening in Poole Harbour led to the discovery of this previously unrecorded wreck. A recovered fragment of Rhenish stoneware and the general form of the surviving structure of the vessel both suggest an early 17th-century ship, probably an armed vessel. Because of its national significance, the wreck was designated in December 2004. However, it is unstable and subject to dramatic shifts in exposure. Monitoring by Bournemouth University showed that 300mm of sediment had been lost across the site in just two years, resulting in the exposure of further sections of the ship to the destructive force of the sea. The vessel is now deemed to be at risk and English Heritage is working with Bournemouth University to implement a management plan to mitigate the loss. © Bournemouth University



PROTECTED WRECK SITES AT RISK IN ENGLAND

- I The Royal Anne (Lizard Point, Cornwall)
- 2 Swash Channel wreck site (Poole Bay, Dorset)
- 3 HM Submarine AI (Eastern Solent)
- 4 The Hazardous (Bracklesham Bay)
- 5 The Northumberland (Goodwin Sands, Kent)
- 6 The Restoration (Goodwin Sands, Kent)
- 7 The Stirling Castle (Goodwin Sands, Kent)
- 8 The Rooswijk (Goodwin Sands, Kent)
- 9 The London (Thames Estuary)

VALLEY GARDENS CONSERVATION AREA, BRIGHTON

The Valley Gardens conservation area includes some of the earliest buildings from Brighton's fashionable Regency period, including some of the town's most important listed buildings and open spaces. The area features on the register because of the effects of heavy traffic, redevelopment proposals and the significant number of vacant and poorly maintained properties. Brighton and Hove City Council is prioritising the area for proactive enforcement action to secure repairs to historic buildings and hopes to make a bid for a grant-aided partnership scheme in the future.

6350

CONSERVATION AREAS AT REAS AT REAS AT

For 40 years conservation areas have been helping to preserve the special character of the nation's best-loved places – not only at the heart of our historic cities and market towns but in the suburban neighbourhoods, former industrial quarters and rural villages that together give this country its irreplaceable distinctiveness. They can encompass many elements of the historic environment: buildings; spaces; designed landscapes and archaeological remains. In this sense, they are unique designations and their value lies in the experience of the area as a whole, as opposed to being simply a collection of separate buildings.

Conservation areas were introduced by the 1967 Civic Amenities Act as 'areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance' (s.79). Since then, more than 9,300 have been designated by local authorities across England. This means that we all visit, work in or live in conservation areas on a regular basis: they are part of our everyday life and represent what we value most about our surroundings.

Their designation is about recognising the significance of an area – what gives it its special character – and then about managing its future. Designation is not intended to prevent change or adaptation but simply to ensure that any proposals for change are properly considered. In many conservation areas the balance is working well, but we know that in some others ill-considered change is putting their special architectural or historic interest at serious risk.

Across England as a whole, about half of all conservation areas are rural, mainly covering the centres of villages and small towns, while about a quarter are urban and the remainder primarily suburban in character.

The South East region has more than 2,000 conservation areas, ranging from the historic core of Oxford to the villages of the South Downs; from the seaside resorts like Hastings to the former defence estates around Gosport.

By their nature, conservation areas will be among the best environments in the country and they project a positive image to visitors and inward investors. The majority of England's city, town and village centres are designated as conservation areas. Good conservationarea management can lead to better shopping areas, parks and gardens and residential neighbourhoods.

Our conservation areas protect many of the region's quality places to live and work. They mark out areas cherished for their special local character and bring economic and social benefits to communities, as well as safeguarding and enhancing their environmental qualities. They can be a powerful focus for local renewal, as has happened at Ryde on the Isle of Wight.



RYDE CONSERVATION AREA

Central Ryde was originally designated as a conservation area in 1969 and is considered to be the Isle of Wight's finest Regency period town. The town, however, has declined during the last 30 years as a result of neglect, economic stagnation and poorly completed alterations. The Isle of Wight Council is now taking action to address these issues with a Townscape Heritage Initiative scheme established to secure repair and reuse of historic buildings and to improve the public realm in the area. So far the scheme has successfully improved 36,000sq feet of public realm, including winning the 2008 Isle of Wight Society Conservation Award for the St Thomas' Churchyard Enhancement project.

The 2009 Conservation Areas Survey

As the starting point to our Conservation Areas at Risk campaign we asked every local authority in England to complete a questionnaire about the condition of each of the conservation areas in its district. This is the first survey of its kind ever carried out. More than 70% of local authorities took part and the results are providing us with some very important information.

The good news is that most of our conservation areas are in a relatively stable state. From the responses received, we now know that the condition of more than 70% of them has not changed significantly over the last three years. Rather less encouraging, however, is the fact that only 15% of conservation areas have actually seen a positive improvement in their condition since 2006.

In the South East region our survey has identified that 140 out of 1,224 sampled conservation areas are at risk -11% of the total, and just under the national average of 15%. Among the most commonly identified problems were development pressures and traffic issues. These can combine with other smaller scale issues, such as a prevalence of street clutter, to substantially erode the quality and character of the areas.

HOW DO WE REDUCE THE RISKS TO CONSERVATION AREAS?

As a result of our national survey we now have clear evidence that a conservation area is more likely to improve if the local authority has a dedicated conservation officer or an elected member who has been appointed as a heritage champion to promote the historic environment within the council.

Looking after conservation areas is a responsibility we all share – those of us who visit them to work or for enjoyment, those of us who own homes and businesses in them, those of us whose job it is to manage the spaces between the buildings and make decisions about their future.

Armed with the kind of robust information provided by this year's survey we and our regional partners will from now on be able to direct resources and investment much more accurately towards those conservation areas at greatest risk, and those with the greatest potential to improve the quality of life and economic prospects of people in the villages, towns and cities of which they are such crucially important components.

In the South East our priorities are to encourage local authorities to maintain or increase their conservation staffing levels during this period of financial constraint so that conservation areas are put at no further or greater risk. We will make sure that our own limited resources are targeted at those areas most in need of our help and expertise. At the same time, we will work with local partners to address in particular the risks to conservation areas in our seaside towns. Prolonged under-investment has been a key factor in their decline and we will work to ensure that local heritage fulfils its potential in regenerating these communities.

CONSERVATION AREA CENSUS DATA RECEIVED FROM LOCAL PLANNING AUTHORITIES (LPAs)


 LPAs who had already completed the census by December 2008

 LPAs who completed the census when it was reopened in March 2009

 LPAs who are in the process of completing the census*

LPAs who have not completed the census

*Includes LPAs formed as part of the April 2009 boundary changes. Eight of these newly created LPAs merged authorities who had completed the census with others who had not.



CONSERVATION AREAS AT RISK THE SOUTH EAST 2009

Adur

Kingston Buci Shoreham-by-Sea

Ashford

Ashford Queens Road Wye

Brighton and Hove, City of (UA)

Benfield Barn East Cliff Montpelier and Clifton Hill North Laine Old Hove Ovingdean Patcham Portslade Old Village Queen Regency Square Rottingdean Sackville Gardens Valley Gardens West Hill Willett Estate

Canterbury

Eddington Highland Court Martyrs Field, Canterbury New Dover Road, Canterbury Nunnery Field, Canterbury Reculver Seaview Chalet Park Womenswold

Chichester

Chichester East Marden Graylingwell Kirdford Selsey Tangmere Walderton West Itchenor West Wittering

Chiltern

Old Town and town centre, Chesham

Dartford

Dartford town centre

Eastbourne Upperton Gardens

.....

Elmbridge Brooklands Thames Ditton

Epsom and Ewell

Adelphi Road, Linton Church Street, Worple Road Epsom town centre Ewell Village Stamford Green The Manor, Horton Hospital, Long Grove Hospital, St.Ebba Woodcote, Chalk Lane

Fareham

Titchfield Abbey

Gosport

Daedalus Haslar Rowner Stoke Road

Isle of Wight (UA)

Brading Carisbrooke Cowes Godshill Newport Ryde St John

Maidstone

Lenham Elmstone Hole Wateringbury Station

Mid Sussex

Ardingly Burgess Hill, Fairfields Burgess Hill, St. Johns East Grinstead Handcross Haywards Heath, Franklands Village Horsted Keynes Hurstpierpoint The Heath, Haywards Heath

Mole Valley

Buckland Coldharbour Dorking Leatherhead

New Forest (NP)

Bucklers Hard Forest Central, North and South Forest North East Forest South East Western Escarpment

Portsmouth, City of (UA)

HM Naval Base and St. George St. David

Reigate and Banstead Walton on the Hill

Sevenoaks

Brasted High Street Chiddingstone Edenbridge Halstead Kippington and Oakhill Road, Sevenoaks Otford Riverhead Seal Sevenoaks High Street Shoreham High Street Shoreham High Street South Darenth Sundridge The Vine, Sevenoaks Vine Court, Sevenoaks

Shepway

Dungeness Lydd Sandgate High Street

South Bucks

Burnham Gerrards Cross Common Iver Stoke Green Taplow Riverside Uxbridge Lock

Tunbridge Wells

Royal Tunbridge Wells

Waverley Peperhare

Peperharow

West Oxfordshire

Aston Bampton Great Tew Stonesfield Taynton Witney and Cogges

Winchester

Abbotts Worthy Avington Bishops Waltham Cheriton Compton Street Corhampton and Meonstoke Droxford Easton Exton Hambledon Hursley Itchen Stoke Kings Worthy Littleton Martyr Worthy New Alresford Southwick Sparsholt Sutton Scotney Twyford West Meon Wickham Winchester Wonston

Windsor and Maidenhead (UA) Beenham Maidenhead town centre

Worthing Goring

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk. This will be challenging with the additional assets now on the register and the varying nature of risk to each asset type. Each asset type and individual case will require a different approach and solution.

There are, however, approaches that are important for all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners.

Advice and understanding are essential. Historic Environment Records, maintained by local authorities, provide a repository of information on local historic assets. They underpin the work of local-authority historic-environment services and can help improve the protection, conservation and management of heritage assets.

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website **www.helm.org.uk**.

Maintenance of heritage assets is essential to help prevent sites becoming 'at risk', and those that are already at risk from decaying further and the escalation of cost of their repair and consolidation. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide property protection through residential occupation are low-cost approaches that can maintain buildings until a permanent solution can be found.

LISTED BUILDINGS

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities and owners. English Heritage's involvement in cases is determined by the importance of the building and the complexity of the issues. English Heritage can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant-aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexities are such that direct involvement is the best way of securing its long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local 'at-risk' register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some councils have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs a grant scheme to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works and Repairs Notices.

Building preservation trusts can be the key to saving buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including Save Britain's Heritage, the Society for the Protection of Ancient Buildings, The Victorian Society and the Georgian Group.

SCHEDULED MONUMENTS

Although a significant proportion of scheduled monuments remain at risk, in many cases the problems can be reduced by either small changes to land management or better-informed decision-making. This is reinforced by the success in reducing the number of monuments at risk since the release of the interim figures in 2008, which shows how the simple act of disseminating information and advice can go a long way towards improving condition. English Heritage provides on-line advice to the owners and managers of sites via the Historic Environment Local Management web site www.helm.org.uk; through its Historic Environment Field Advisers and through the network of local authority Historic Environment Countryside Advisers that we have co-sponsored with local authority partners.

While many owners and managers of scheduled monuments address their long-term care on a voluntary basis, some monuments do require significant resources in order to stabilise their condition, to carry out repairs, or to change the way in which the land on and around them is used. English Heritage therefore works closely with the Heritage Lottery Fund to identify important sites deserving grant-aid and in partnership with Natural England who delivers the Environmental Stewardship agri-environment scheme on behalf of Defra.

The English Heritage National Monuments Record and local authority Historic Environment Records have increased the information available to land managers and we are continuing to develop their services, most recently through the Selected Heritage Inventory for Natural England (SHINE) project, through which owners will be able to view online information on scheduled monuments and other archaeological features on their holdings.

In all cases – whether for rural or urban monuments – close co-operation with owners and land managers is the key to making further progress.

PARKS AND GARDENS

The registered status of parks and gardens is a material consideration in the determination of planning applications. The new PPS 15 and its companion guidance will therefore help planning authorities to assess and mitigate the impact of development on our irreplaceable heritage of designed landscapes.

English Heritage can engage only with the highestpriority proposals for change and we shall be reviewing our priorities for casework as a result of this year's Heritage at Risk register findings. We shall also continue to support the professional training courses and apprenticeship schemes that are vital to the long-term conservation of England's historic parks and gardens.

English Heritage encourages the development of conservation management plans for registered historic parks and gardens, especially those in complicated multiple ownership. We are also keen for bursars and estate teams to use management plans to help conserve important but fragile landscapes in the care of schools, hospitals, hotels and other institutional owners.

Following our recent review of the grading of registered cemeteries we are committed to helping communities to raise awareness of the importance of their historic burial grounds. Towards this end, a new advice note on the conservation of memorials will also be published this summer as a successor to our more general guidance on the conservation of historic cemeteries, *Paradise Preserved*.

BATTLEFIELDS

The limited level of statutory protection that registered battlefields receive means that there is relatively modest direct impact that English Heritage can have on their future. English Heritage will work with owners to develop management plans for registered sites, and in appropriate cases, assist with funding management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect the battlefield archaeology and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can help reduce the risk to battlefields by designating registered battlefields as conservation areas, providing further protection and making sure that registered battlefields are explicitly taken into account in Local Development Frameworks. Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have now been identified, and in terms of high-priority sites practical requirements have been identified in conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to pass them on to future generations in as good a condition as reasonably possible. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage's Maritime Archaeology Team (maritime@english-heritage.org.uk) and from **www.helm.org.uk**.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk:

- Buildings at Risk: A New Strategy (1998)
- Conservation Areas at Risk (2009) public campaign booklet
- Conservation Areas at Risk (2009) campaign leaflet for local authorities
- Monuments at Risk (2008) summary of scheduled monuments at risk in each of our nine regions: East Midlands, East of England, London, North-East, North-West, South-East, South-West, West Midlands, Yorkshire and the Humber
- Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous helpful guidance documents now available on our website: www.english-heritage.org.uk/helm

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Enabling Development and the Conservation of Significant Places (2008)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Stopping the Rot: A Step by Step Guide to Serving Urgent Works and Repairs Notices (1998)

The Disposal of Historic Assets: Guidance Note for Government Departments and Non-Departmental Public Bodies (1999)

Further copies of this register and those for the other eight English regions are available free of charge from:

English Heritage Customer Services Department, PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

REGISTER 2009

The register – content and assessment criteria	22
Key to the entries	24
Heritage at Risk entries	26
Bracknell Forest (UA)	26
Brighton and Hove, Ćity of (UA)	26
Buckinghamshire	27
East Sussex	31
Hampshire	35
Isle of Wight (UA)	46
Kent	48
Medway (UA)	60
Milton Keynes (UA)	62
Oxfordshire	63
Portsmouth, City of (UA)	71
Reading (UA)	73
Southampton, City of (UA)	73
Surrey	73
West Berkshire (UA)	76
West Sussex	79
Windsor and Maidenhead (UA)	86
Wokingham (UA)	86
Conservation Areas at Risk	88

The register: content and criteria

DESIGNATION

All of the historic environment matters – but there are some elements which warrant extra protection through the planning system. Ever since 1882, when the first Act protecting archaeology was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Around 20,000 archaeological sites are scheduled, which introduces tight management controls, and some 1600 designed landscapes are registered, as are 43 battlefields.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the DCMS who makes the decisions. Understanding and appreciation develop constantly, which makes keeping the designation base up to date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness, and better communication of what makes something special. This register includes the following heritage assets at risk:

- Grade I and II* listed buildings and structural scheduled monuments
- scheduled monuments (archaeological sites)
- registered parks and gardens (including cemeteries)
- registered battlefields (where applicable)
- protected wreck sites (where applicable)
- conservation areas.

LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed Grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this register reflect how buildings are grouped and recorded on the statutory list. Structures can occasionally be both listed and scheduled as monuments.

Criteria for inclusion on this register

Buildings included on this register are listed Grade I and II*, and some are structural scheduled monuments. Buildings are assessed for inclusion on the register on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'partoccupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the 'at risk' register when fully repaired/consolidated, their future secured, and where appropriate, occupied.

Priority for action

Once a building is identified as at risk or vulnerable and included on the register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

SCHEDULED MONUMENTS Definition

Scheduled monuments are our most valued archaeological sites and landscapes, England's 19,719 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They span more than 6,000 years of human activity, from prehistoric burial mounds to 20th-century military and industrial remains. For the millennia before written history scheduled monuments are the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

Criteria for inclusion on this register

Once damaged or destroyed, scheduled monuments and the information they contain cannot be replaced. In 2008 English Heritage surveyed the condition of each of the nation's scheduled monuments. This has allowed the identification of national and regional priorities for action. All the monuments included in this regional register have been identified as being 'at risk'. Put simply, this means that on the basis of their current condition and vulnerability they are susceptible to significant loss to their fabric in the near future. They are then further sub-divided in terms of the severity of the threat that they face, ranging from those in 'optimal' condition (the best that can be achieved) to others whose 'extensive significant problems' are likely to be more difficult to resolve.

HISTORIC PARKS AND GARDENS Definition

There are I,600 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes, which can be Grade I, II* or II, include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their beauty, diversity and historical importance but in contrast to the number of listed historic buildings this is a very small group of assets.

Inclusion on the register of parks and gardens brings no additional statutory controls, but it is a material consideration in the determination of planning applications. Local authorities are required to consult English Heritage on applications affecting sites registered as Grade I or II* and the Garden History Society on sites of all grades.

Criteria for inclusion on this register

The identification of sites at risk begins with a desk-top appraisal of the condition and vulnerability of each registered park and garden. This allows them to be provisionally categorised as at low, medium or high risk. These rankings are then checked by our regional expert advisers and adjusted to reflect steps already taken by owners to address problems.

Sites assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. They are generally not protected by conservation management plans or conservation area status. The original function of these landscapes has often changed; divided ownership may also have resulted in the loss of the cohesive character of the place. Unless the entry gives information on the state of repair of the site as a whole, it should not be assumed that the surroundings are themselves at risk.

CONSERVATION AREAS Definition

Conservation areas are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. Designated by local authorities, for more than 40 years they have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,300 in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on this register

In the first survey of its kind ever undertaken, English Heritage in 2008 asked every local authority in England to fill out a census form for each of its conservation areas. Responses were received for approximately 60% of conservation areas, highlighting current threats and trends. Based on the local authority's own assessment, those which have deteriorated over the last three years, or are expected to do so over the next three years, are defined as being at risk – I in 7, or about 14% of the total in the survey.

This is the first step in building up a comprehensive national picture of the condition of England's conservation areas. At present, the survey is incomplete, so the results need to be treated with caution. However, understanding the emerging trends will help English Heritage and local authorities to address those at greatest risk, and to mobilise local groups to reinforce their support for the historic environment in communities across the country.

BATTLEFIELDS Definition

English Heritage's register of historic battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause; reputations were made or lost, history was set and people died. The outcome of these battles was influenced by where they were fought and traces of the events of the day will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields are sensitive and appropriate.

Criteria for inclusion on this register

Of the 43 registered battlefields, 7 are deemed to be at risk of loss of historic significance and are included on this register. The identified risks and threats come from:

- development pressure for example, because they lie on urban fringes or are subject to development pressures within the site
- arable cultivation
- unregulated metal-detecting.

One major impact or a combination of several factors can be enough to raise the risk at a particular site. Of the seven sites deemed to be most at risk, five are in decline and two are stable.

WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea – just I in 706. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community.

The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference. Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

Criteria for inclusion on this register

In 2009 English Heritage audited all designated wreck sites to better understand their current condition and vulnerability, the way they are being managed, and what needs to be done to ensure that their significance is maintained for present and future generations. As a result, nine sites were deemed to be at risk.

Key to the entries

ORDER

Entries are grouped and ordered alphabetically first by county or unitary authority, and then by local planning authority (unitary authority/national park/district or borough).

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural monuments
- scheduled monuments
- registered parks and gardens
- registered battlefields
- protected wreck sites are listed at the end of the county or unitary authority off which they are located.

Within each asset type, sites are ordered alphabetically by parish and site name.

Conservation areas at risk are listed together on page 88.

DESIGNATION

The lead designation is noted for each entry, and includes:

- Listed Building (LB) Grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) Grade I, II* or II
- Registered Battlefield
- Protected Wreck Site
- Conservation Area (CA)
- World Heritage Site (WHS).

For buildings and registered parks and gardens, other designations that apply to each site are also noted. Their location within a conservation area or World Heritage Site is noted where applicable.

Given the difference in each asset type and also the varying nature of the risks to which they are exposed, there will inevitably be differences in how risk is assessed and how the information is categorised.

CONDITION

For buildings at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens and wreck sites) one overall condition category is recorded. The category may relate only to the one part of the site or monument that is at risk and not the whole site:

- extensive significant problems (i.e. under plough, collapse)
- generally unsatisfactory with major localised problems

- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal (ie the best we can realistically expect to achieve)
- significant decline
- unknown.

'Unknown' is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established.

OCCUPANCY

For buildings that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable.

VULNERABILITY

Principal Vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration
- scrub / tree growth
- visitor erosion.

For registered parks and gardens, vulnerability is noted as high, medium and low.

PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

If the priority category has changed since the 2008 register, the previous category is given in brackets.

TREND

Trend for scheduled monuments, registered parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown.

OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed. We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LA	Local Authority
LB/LBs	Listed Building/s
NP	National Park
RPG	Registered Park and Garden
SM/SMs	Scheduled Monument/s
UA	Unitary Authority
WHS	World Heritage Site
	-

DDACK IELL EODEE			
BRACKNELL FOREST	(UA)		
	SITE NAME: DESIGNATION CONDITION:	Grotto in Grounds of Ascot Place, Pigeon House Lane, Ascot, Winkfield	Exceptionally fine grotto of circa 1750 with numerous chambers decorated with stalactites, finished with mineral ores, and zig-zag bonding which was the 'trademark' of Josiah Lane and his father. External repairs completed and structure now sound and weather tight. Work on interior repairs and flood prevention measures ongoing.
ALL YN M			
AVE AAA		Not applicable	
MAR INV	PRIORITY:	E (E)	
	OWNERSHIP:	Company	Contact: Kathryn Davies 01483 252028
SITE NAME:	Newbold	College (formerly Moor Close), Binfield	Moor Close estate, now the home of Newbold College, includes an Edwardian mansion which was Oliver Hill's
DESIGNATION:	Registere	d Park and Garden Grade II*, also 7 LBs	first house and garden design in an early C20 Arts & Crafts
CONDITION:	Extensive	significant problems	style. The intricately designed gardens comprise fragile fabric
VULNERABILITY:	Low		which is deteriorating and in need of renovation. A condition survey has been completed with grant from English Heritage;
TREND:	Deteriora	ating	further resources and action are urgently needed. A recent
OWNERSHIP :	Corporat	e, single owner	pre-application to the Heritage Lottery Fund was unsuccessful.
	,		Contact: Charlotte McLean 01483 252076
SITE NAME:	Broadmo	or Hospital, Crowthorne	A mid CI9 asylum, built for the criminally insane to designs by Joshua Jebb.There are extensive contemporary gardens
DESIGNATION:	Registere	d Park and Garden Grade II, also I LB	and ornamented farmland. The site remains in use as a
CONDITION:	Extensive	significant problems	secure psychiatric hospital but its historic layout is not
VULNERABILITY:	High		addressed in its grounds management.
TREND:	Deteriora	ating	
OWNERSHIP :		e, single owner	Contact: Charlotte McLean 01483 252076
BRIGHTON AND HO	VE, CITY		
BRIGHTON AND HO	SITE NAME:	OF (UA) The West Pier, Kings Road, Brighton	Pier, 1864-66 by Eugenius Birch. Closed in 1975. English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public
BRIGHTON AND HO	SITE NAME:	The West Pier, Kings Road, Brighton	English Heritage has declared its view that the
BRIGHTON AND HO	SITE NAME: DESIGNATION	The West Pier, Kings Road, Brighton & Listed Building Grade I, CA	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public
BRIGHTON AND HO	SITE NAME: DESIGNATION CONDITION:	The West Pier, Kings Road, Brighton & Listed Building Grade I, CA Very bad	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public
BRIGHTON AND HO	SITE NAME: DESIGNATION CONDITION: OCCUPANCY	The West Pier, Kings Road, Brighton A: Listed Building Grade I, CA Very bad Not applicable	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public
BRIGHTON AND HO	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY:	The West Pier, Kings Road, Brighton A: Listed Building Grade I, CA Very bad I: Not applicable A (A)	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic.
BRIGHTON AND HO	SITE NAME: DESIGNATION CONDITION: OCCUPANCY	The West Pier, Kings Road, Brighton A: Listed Building Grade I, CA Very bad I: Not applicable A (A)	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY:	The West Pier, Kings Road, Brighton A: Listed Building Grade I, CA Very bad I: Not applicable A (A)	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic.
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	The West Pier, Kings Road, Brighton A: Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine,	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	The West Pier, Kings Road, Brighton Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Listed Building Grade I, CA	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: DESIGNATION CONDITION:	The West Pier, Kings Road, Brighton Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Listed Building Grade I, CA	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: DESIGNATION CONDITION:	The West Pier, Kings Road, Brighton Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Listed Building Grade I, CA Poor Part occupied	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	The West Pier, Kings Road, Brighton 4: Listed Building Grade I, CA Very bad a: Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton 4: Listed Building Grade I, CA Poor : Part occupied C (New)	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY:	The West Pier, Kings Road, Brighton 4: Listed Building Grade I, CA Very bad a: Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton 4: Listed Building Grade I, CA Poor : Part occupied C (New)	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak.
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	The West Pier, Kings Road, Brighton Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Listed Building Grade I, CA Poor Part occupied C (New) Private The stables at Stanmer House, Stanmer Park,	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak. Contact: Tom Foxall 01483 252035 Stables probably C18. Much altered and largely empty
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	The West Pier, Kings Road, Brighton Listed Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Listed Building Grade I, CA Poor Part occupied C (New) Private The stables at Stanmer House, Stanmer Park, Brighton	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak. Contact: Tom Foxall 01483 252035 Stables probably C18. Much altered and largely empty
	SITE NAME: DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP SITE NAME:	The West Pier, Kings Road, Brighton Isted Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Isted Building Grade I, CA Poor Part occupied C (New) Private The stables at Stanmer House, Stanmer Park, Brighton Isted Building Grade II*, CA Poor	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak. Contact: Tom Foxall 01483 252035 Stables probably C18. Much altered and largely empty
	SITE NAME: DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: SITE NAME: CONDITION: OCCUPANCY	The West Pier, Kings Road, Brighton Isted Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton Isted Building Grade I, CA Poor Private The stables at Stanmer House, Stanmer Park, Brighton Isted Building Grade II*, CA Poor Part occupied	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak. Contact: Tom Foxall 01483 252035 Stables probably C18. Much altered and largely empty
	SITE NAME: DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP SITE NAME:	The West Pier, Kings Road, Brighton Isted Building Grade I, CA Very bad Not applicable A (A) Trust Marlborough House, 54 Old Steine, Brighton and Hove, Brighton * Listed Building Grade I, CA Poor Part occupied C (New) Private The stables at Stanmer House, Stanmer Park, Brighton * Listed Building Grade II*, CA Poor Part occupied C (New) Private	English Heritage has declared its view that the combination of significant recent damage and cost of repair make restoration from public funds uneconomic. Contact: Tom Foxall 01483 252035 House, now office. Built 1765, remodelled in 1786 by Robert Adam. Not structurally sound, secure or weathertight and with a dry rot outbreak. Contact: Tom Foxall 01483 252035 Stables probably C18. Much altered and largely empty

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

No. 14, 14 Brunswick Square, East Sussex, How Brunswick Square, East Sussex, How Brunswick Square, but not complete, in our complete,	GHTON AND HOVE (UA) / AYLESBURY VALE
Consumer Very bad Occumence Part Occupied Province B (A) Ownershie Contact: Tom Foxall Steiner Stanner Park, Stanner Distortione Registered Park and Garden Grade II, also part in CA, Jo LB, 3 SNs Conditione Extensive significant problems Provide autrix High Deteriorating Provide autrix Ownershie Local Authority single owner EVECKINGHAMSHIRE Barn, late C12 and la tempory or Co- out. Slow decay no a late tempory or Co- out. Slow decay no a la	25-7. Mews to the rear of I4, circa 1825. Repair works underway,
Image: Section of the principal of the principal result. Section of the principal of the princip	
Image: Property is a (A) Contact: Tom Foxall Image: Company Contact: Tom Foxall Image: Company Contact: Tom Foxall Image: Company Stammer is an C18 est informal pleasure gri proposals for conserv- reconditioned manage incoordinated manage proposals for conserv- reconditioned manage incoordinated manage proposals for conserv- reconditioned manage incoordinated manage proposals for conserv- reconditioned manage proposals for conserv- proposals for conserv- proposals for conserv- proposal for conserv- proposals for conserv- proposals for conserv- proposals for conserv- proconserver for proposals for conserv- pronoser	
Conversion Conversion Conversion Contact: Tom Foxall Stammer Fark, Stammer Stammer is an C16 est informal pleasure gri 1947 as a public ane also part in CA 19 LBs, 3 SMs Stammer is an C16 est informal pleasure gri 1947 as a public ane uncoordinated manage bistoric estate building proposals for conserv- rationalisation of acc rationalisation of acc at emporary roof co out. Stow deay, no acc rational listed Building Grade II* concurse Very Vale, Dorton Barn, late C12 and la at emporary roof co out. Stow deay, no acc rationalisation rationalisted Building Grade II* concurse Very bad cocurse Very bad cocurse Very bad cocurse Very bad cocurse Very bad cocurse Very bad cocurse Private Barn, late C12, data I (2 Contact: Kathryn Da contact: Kathryn Da STE NAME Ashfold School (Dorton House), Deron Early C17, data I (2 Contact: Sathryn Da cocurse Very bad cocurse Very bad cocurse Very bad cocurse Very bad cocurate Very bad cocurse Very bad cocurse Very Bat cocurse V	
Stanmer Park, Stanmer Stanmer is an C18 estimation of the provided informal pleasure grain formal pleasure grain please formal pleasure grain provide and the provide grain formal pleasure grain provide grain formal please forman pleaser formal please formal please formal pleas form	
Discovence Registered Park and Garden Grade II, also part in CA, 19 LBs, 3 SMs informal pleasure gra uncoordinated mang historic estate buildin proposals for conserver rationalisation of acc learning CONDITION Extensive significant problems proposals for conserver rationalisation of acc learning Deteriorating Deteriorating contact: Charlotte N CONDITION Local Authority, single owner Contact: Charlotte N BUCKINGHAMSHIRE STEINME Barn at New Manor Farm, Broughton Lane, Distron with Broughton Barn, late Cl2 and la a temporary roof co- occumence: Vacant PUCOTION C (C) Contact: Kathryn Da OWNERSHIRE Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no On the point of coll Local council has un connorme. Very bad OWNERSHIRE Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no On the point of coll Local council has un councerse. OWNERSHIRE Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no On the point of coll Local council has un councerse. OWNERSHIRE Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no On the point of coll Local council has un councerse. OWNERSHIRE Dinton Castle, Aylesbury Vale, Dinton Folly, Cl7, dated 162 Contact: Kathryn Da STEINME Ashfold School (Dorton House), Dorcon Early Cl7, dated 162 Contact: Kathryn Da	01483 252035
Description Registered Park and Garden Grade II, also part in CA, 19 LBs, 3 SMs IP47 as a public ame uccondinated mang bitoric estate building proposals for conserv proposals for conserv leadership to implen eadership to implen readership to implen advership to implen readership to implen readership to implen advership to implen readership to implent readership to implent	estate village set in a landscape park with
also part in CA, 19 LBs, 3 SMs uncoordinated manage intervice state building proposals for conserv vuluersatury: High TEND. Deteriorating OWNERSHP: Local Authority, single owner BUCKINGHAMSHIRE AYLESBURY VALE STE NAME Barn at New Manor Farm, Broughton Lane, Bietron with Broughton Desourtons. Listed Building Grade II* Contact: Kathryn Da STE NAME Dinton Castle, Aylesbury Vale, Dinton Castle, Aylesbury Cast STE NAME STE NAME Ashfold School (Dorton House), Desourtons. Listed Building Grade I STE NAME STE NAME Ashfold School (Dorton House), Desourtons. Listed Building Grade I Contact: Kathryn Da STE NAME STE N	rounds. Brighton Borough bought it in nenity but it has now declined due to
Condition Extensive significant problems Photon estate building fracte life WILNERMARTY: High Instruction estate building fracte life Instruction estate building fracte life CONVERSENT: Local Authority, single owner Contact: Charlotte N BUCKINGHAMSHIRE STEINAME Barn, late Cl2 and la a temporary roof co-out. Slow decay no charlow builde Building Grade life CONVERSENT: Contact: Vacant Barn, late Cl2 and la a temporary roof co-out. Slow decay no charlow builde Building Grade life CONVERSENT: Vacantes: Vacantes: Vacantes: PROFIN: C (C) Contact: Kathryn Da STEINAME: Dinton Castle, Alyesbury Vale, Dinton Contact: Kathryn Da STEINAME: Dinton Deservarrow Listed Building Grade life CONDITION: Very bad Contact: Kathryn Da STEINAME: Ashfold School (Dorton House), Dortains extense Contact: Kathryn Da STEINAME: Mathrmore Contact: Kathryn Da STEINAME: Ashfold School (Dorton House), Dortains extense Contact: Kathryn Da STEINAME: Mathrmore Contact: Kathryn Da Contact: STEINAME: <t< td=""><td>agement, under-resourcing and redundant</td></t<>	agement, under-resourcing and redundant
VULNERABLITY: High Proprior is connected by a finalisation of a conserver of a c	lings. A Stewardship plan (2003) made
THENC: Deteriorating leadership to implem needed. Part of the preded. Part of the contact: Charlotte N CONVERSION BUCKINGHAMSHIRE AULESBURY VALE SITE NAME: Barn at New Manor Farm, Broughton Lane, Broughton Lane, Broughton Lane, Contact: Kathryn Da Descention: Listed Building Grade II* Contact: Kathryn Da SITE NAME: Dinton Castle, Aylesbury Vale, Dinton Contact: Kathryn Da SITE NAME: SITE NAME: Dinton Castle, Aylesbury Vale, Dinton Contact: Kathryn Da Contact: Kathryn Da SITE NAME: Ashfold School (Dorton House), Dorton Discon Cocupied ONNERSEN SITE NAME: Ashfold School (Dorton House), Dorton Discon Cocupied Contact: Kathryn Da Contact: Kathryn Da SITE NAME: SITE NAME: SITE NAME:	rving and enhancing the landscape includin ccess but progress is limited. Focussed
OWNERSHIP: Local Authority, single owner needed, Part of the Contact: Charlotte N BUCKINGHAMSHIRE E AYLESBURY VALE SITE NAME Barn at New Manor Farm, Broughton Lane, Bierton with Broughton Barn, late Cl2 and la a temporary roof co out. Slow decay no 1 Inscrementation Dissonance, Listed Building Grade II* Contact: Kathryn Da CONDITION Poor Contact: Kathryn Da SITE NAME Dinton Castle, Alesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no' On the point of coll Condition Diston Castle, Alesbury Vale, Dinton Contact: Kathryn Da Condition Diston Castle, Alesbury Vale, Dinton Contact: Kathryn Da Concurrex: Not applicable Poorton Diesonance: Not applicable Poorton Diotron Poor Contact: Kathryn Da Concurrex: Not applicable Contact: Kathryn Da Concurrex: Not applicable Contact: Cathryn Da Concurrex: Contact: Common Coccupied Contact: Cathryn Da Concurrex: Contact: Cathryn Da Contact: Kathryn Da Concurrex: Cocupied Contact: Cathryn Da Concurrex: Cocupied	ement a revised management plan is
Contact: Charlotte N BUCKINGHAMSHIRE AYLESBURY VALE STE NAME: Barn at New Manor Farm, Broughton Lane, Bierton with Broughton Discontrow Listed Building Grade II* controw Poor occupation Vacant record record recor	e park is also in the district of Lewes.
AYLESBURY VALE SITE NAME Barn at New Manor Farm, Broughton Lane, Berton with Broughton Barn, late C12 and la a temporary roof could Slow decay no shas been carried out Slow decay no shas the principal rooms. SITE NAME Mentmore SITE NAME SITE NAME Mentmore Slow no shas tecent been carried out Slow no shas tecent be carried out Slow no shas tecent be carried out Slow no shas tecent be principal rooms.	McLean 01483 252076
SITE NAME Barn at New Manor Farm, Broughton Lane, Bierton with Broughton Barn, late C12 and la a temporary roof co- out. Slow decay: no s- has been carried out DESIGNATION: Foor Contact: Kathryn Da COMDITION: Poor Contact: Kathryn Da OWNERSHEP: Private Contact: Kathryn Da SITE NAME: Dinton Castle, Alyesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no Dinton DISGONATION: Listed Building Grade II* Contact: Kathryn Da CONDITION: Very bad Contact: Kathryn Da COURNACC: Not applicable Contact: Kathryn Da DISTON: Poor Contact: Kathryn Da COURNACC: Occupied Contact: Kathryn Da DISTON: Poor Contact: Corrow and under sta COURNACC: Occupied Poor COCUPANCY: Occupied Poor COCUPANCY: Occupied Private	
Broughton Lane, Bierton with Broughton a temporary roof con- out. Slow decay: no s- has been carried out Descriverow Poor OCCUPANCE: Vacant PRORIT: C (C) OWNERSHIP: Private SITE NAME: Dinton Castle, Algesbury Vale, Dinton Disconverow: Vacant PRORIT:: C (C) OWNERSHIP: Private CONDITION: Very bad OCCUPANCE: Not applicable PRORIT:: A (A) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton CONDITION: Poor OCCUPIED Private Descriver: C(C) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton Descriver: C(C) OCUPIED Poor OCCUPIED Poor	
Image: Stree Name Listed Building Grade II* has been carried out Image: Stree Name Concornors Poor Concornors Image: Stree Name Dinton Castle, Aylesbury Vale, Dinton Castle, Allesburg, Contact: Kathryn Da Foly, 1796, built as ey gothić structure, noi Contact: Kathryn Da Image: Stre Name Ashfold School (Dorton House), Dorton Early C17, datel IG2 Contact: Kathryn Da Image: Stre Name Mentmore Towers, Mentmore Building vacant for a permission granted for amajor extension. P consents has recent been carried out buil damaging the interio the principal rooms.	later. Propped with scaffolding and with overing. Urgent works have been carried o solution. A historic building analysis
CONDITION: Poor OCCUPANCY: Vacant PRORITY: C (C) OWNERSHIE: Private Contact: Kathryn Da Contact: Contact: Contact: Kathryn Da Contact: Contact: Contact: Kathryn Da Contact: Contac	ut with English Heritage grant aid.
OCCUPANCE: Vacant PRORITY: C (C) OWNERSHIE Private Contact: Kathryn Da STE NAME: Dinton Castle, Aylesbury Vale, Dinton Folly, I796, built as ey 'gothic' structure, no On the point of coll Local council has une OCCUPANCE: Very bad Occupance: Not applicable PRORITY: A (A) Occupance: Contact: Kathryn Da OCCUPANCY: Not applicable Private Contact: Kathryn Da OCCUPANCY: Norton Poor Occupied for many y and the condition of The fine plaster ceilin and this is already or Occupancy: Occupance: Contact: Kathryn Da OCCUPANCY: Occupancy: Occupancy: Contact: Kathryn Da OCCUPANCY: Occupancy: Occupancy: Contact: Kathryn Da OCCUPANCY: Occupancy: Occupancy Contact: Kathryn Da	
PRIORITY:: C (C) OWNERSHIP: Private Contact: Kathryn Da STE INAME: Dinton Castle, Aylesbury Vale, Dinton DESIGNATION:: Listed Building Grade II* CONDITION: Very bad Occurrance: Not applicable PRIORITY:: A (A) OWNERSHIP: Private OWNERSHIP: Private Contact: Kathryn Da Occurrance: Not applicable PRIORITY:: A (A) OWNERSHIP: Private Contact: Kathryn Da STE NAME: Ashfold School (Dorton House), Dorton DESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupied PRIORITY:: C (C) OWNERSHIP: Private Contact: Contact: Kathryn Da STE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* CONDITION: Fair OCCUPANCY: Vacant	
OWNERSHIP: Private Contact: Kathryn Da Image: Stre NAME Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gethic' structure, no' On the point of coll Local council has une conditione Image: Stre NAME Distorn Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gethic' structure, no' On the point of coll Local council has une conditione Image: Stre NAME Very bad Contact: Kathryn Da Image: Stre NAME Stre NAME A(A) Image: Stre NAME Ashfold School (Dorton House), Dorton Contact: Kathryn Da Image: Stre NAME Stre NAME Ashfold School (Dorton House), Dorton Early CI7, dated I62 Contains extremely in roms and under streenely occupied for many y and the condition of The fine plaster cellin and this is already or Or Condentact: Kathryn Da Image: Stre NAME Mentmore Towers, Mentmore Building vacant for a permission granted fa amjor extension. P consents has recent been carried out bu' damaging the interio the principal rooms.	
SITE NAME Dinton Castle, Aylesbury Vale, Dinton Folly, 1796, built as ey gothic' structure, no On the point of coll Local council has une DESIGNATION: Listed Building Grade II* CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: A (A) OWNERSHIP: Private SITE NAME Ashfold School (Dorton House), Dorton SITE NAME Ashfold School (Dorton House), Dorton DESIGNATION: Listed Building Grade I OWNERSHIP: Private DESIGNATION: Listed Building Grade I OCCUPANCY: Occupied PRIORITY: C (C) OWNERSHIP: Private OCCUPANCY: Contact: Kathryn Da SITE NAME Mentmore Towers, Mentmore SITE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* condition granted fa amajor extension.P OCCUPANCY: Vacant	000000000000000000000000000000000000
Aylesbury Vale, Dinton 'gothic' structure, no On the point of coll Local council has und DESIGNATION: Listed Building Grade II* CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: A (A) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton DESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupied PRORITY: C (C) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton DESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupied PRORITY: C (C) OWNERSHIP: Private OUTON: Poor OCCUPANCY: Occupied PRORITY: C (C) OWNERSHIP: Private SITE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* CONDITION: Fair OCCUPANCY: Vacant	Javies 01403 232020
Designation: Listed Building Grade II* CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: A (A) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton Designation: Listed Building Grade I CONDITION: Poor OCCUPANCY: OCCUPIED PRIORITY: C (C) OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Ashfold School (Dorton House), Dorton Designation: Listed Building Grade I CONDITION: Poor OCCUPANCY: OCCUPIED PRIORITY: C (C) OWNERSHIP: Private SITE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* CONDITION: Fair OCCUPANCY: Vacant	eyecatcher for Dinton Hall. Octagonal ow with major structural cracking. Ilapse as the lintels rot behind arches.
CONDITION: Very bad OCCUPANCY: Not applicable PRORITY: A (A) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton Early C17, dated 162. Contains extremely - rooms and under state DESIGNATION: Listed Building Grade I coupled for many y and the condition of The fine plaster ceilin and this is already of OCCUPANCY: Occupied PRIORITY: C (C) OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Mentmore Towers, Mentmore Building vacant for a major extension. P. consents has recently besignation: DESIGNATION: Listed Building Grade I, RPG II* Contact: Kathryn Da CONDITION: Fair OCCUPANCY: Vacant	ndertaken urgent repairs.
OCCUPANCY: Not applicable PRIORITY: A (A) OWNERSHIP: Private SITE NAME: Ashfold School (Dorton House), Dorton BESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupancy DESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupancy PRIORITY: C (C) OWNERSHIP: Private Contact: Kathryn Da Building vacant for a permission granted fa major extremely or consents has recently or co	
PRIORITY: A (A) OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Ashfold School (Dorton House), Dorton DESIGNATION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupied PRIORITY: C (C) OWNERSHIP: Private CONDITION: Listed Building Grade I CONDITION: Poor OCCUPANCY: Occupied PRIORITY: C (C) OWNERSHIP: Private CONDITION: Early C17, dated I62: CONDITION: Poor OCCUPANCY: Occupied PRIORITY: C (C) OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* Consents has recent been carried out build damaging the interio CONDITION: Fair OCCUPANCY: Vacant	
OWNERSHIP: Private Contact: Kathryn Da Image: Stre NAME: Ashfold School (Dorton House), Dorton Early C17, dated 162. Contains extremely rooms and under sta occupied for many y and the condition of The fine plaster ceilin and this is already or PRIORITY: C (C) Image: OWNERSHIP: Private Contact: Kathryn Da Image: Stre NAME: Ashfold School (Dorton House), Dorton Early C17, dated 162. Contains extremely rooms and under sta occupied for many y and the condition of The fine plaster ceilin and this is already or PRIORITY: C (C) Image: OWNERSHIP: Private Contact: Kathryn Da Image: Stre NAME: Mentmore Towers, Mentmore Building vacant for a permission granted fa a major extension. P consents has recent been carried out but damaging the interio the principal rooms.	
SITE NAME Ashfold School (Dorton House), Dorton Early C17, dated 162: Contains extremely rooms and under state occupied for many y and the condition of The fine plaster ceilin and this is already of PRIORITY: C (C) OCCUPANCY: Occupied Contact: Kathryn Da SITE NAME: Mentmore Towers, Mentmore Building vacant for a permission granted fa a major extension. P consents has recently been carried out build amaging the interio the principal rooms.	avies 01483 252028
Dorton Contains extremely rooms and under state occupied for many y and the condition of the fine plaster ceiling occupied for many y and the condition of The fine plaster ceiling and this is already occupied PRIORITY: C (C) OWNERSHIP: Private SITE NAME: Mentmore Towers, Mentmore DESIGNATION: Listed Building Grade I, RPG II* Contact: Listed Building Grade I, RPG II* CONDITION: Fair OCCUPANCY: Vacant	
Designation: Listed Building Grade I and the condition of The fine plaster ceilin and this is already of Coupling OCCUPANCY: Occupied and this is already of Coupling PRORITY: C (C) Ownership: OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Mentmore Towers, Mentmore Building vacant for a permission granted fa major extension. P CONDITION: Listed Building Grade I, RPG II* consents has recently been carried out but damaging the interio occupancy: Vacant Vacant Vacant	26 on staircase soffit, altered 1784. / elaborate C17 plaster ceilings in severa :taircase soffits.The building has been
CONDITION: Poor The fine plaster ceiling and this is already or coupled PRIORITY: C (C) Occupied PRIORITY: C (C) Occupied SITE NAME: Mentmore Towers, Mentmore Conserts has recently been carried out but damaging the interior of the principal rooms.	years as a school. The roofs, stonework
OCCUPANCY: Occupied and this is already of PRIORITY: C (C) Contact: Kathryn Da OWNERSHIP: Private Contact: Kathryn Da SITE NAME: Mentmore Towers, Mentmore Building vacant for a permission granted fa a major extension. P consents has recently been carried out but damaging the interio the principal rooms.	of the lintels all give cause for concern. lings are vulnerable to water damage
SITE NAME Mentmore Towers, Mentmore Building vacant for a permission granted fa a major extension. P consents has recently been carried out but damaging the interio the principal rooms.	
OWNERSHIP: Private Contact: Kathryn Da Image: Stre NAME: Mentmore Towers, Mentmore Building vacant for a permission granted fa a major extension. P consents has recently been carried out building Grade I, RPG II* Building vacant for a permission granted fa a major extension. P consents has recently been carried out building drade I, RPG II* CONDITION: Fair Consents has recently been carried out building drade I, RPG II* OCCUPANCY: Vacant Vacant	
Mentmore permission granted f a major extension. P DESIGNATION: Listed Building Grade I, RPG II* consents has recently been carried out building the interior occupancy: Vacant	Davies 01483 252028
DESIGNATION: Listed Building Grade I, RPG II* a major extension. P consents has recently been carried out but damaging the interio CONDITION: Fair damaging the interio OCCUPANCY: Vacant the principal rooms.	a number of years. LBC and planning I for conversion to a hotel together with
Designation: Listed Building Grade I, RPG II* been carried out but condition: Fair damaging the interio occupancy: Vacant the principal rooms.	Planning for the implementation of these
CONDITION: Fair damaging the interio occupancy: Vacant the principal rooms.	tly stopped, some emergency work has ut roof repairs are outstanding. Leaks an
occupancy: Vacant the principal rooms.	ior including decorative plasterwork in
The second se	
PRIORITY: A (A)	
	Davies 01483 252028

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

PRIORITY

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

A	site name:	The West Boycott Pavilion, Stowe Landscape Garden, Stowe	One of pair of large stone pavilions, circa 1728, by James Gibbs, incorporating domestic accommodation. Situated on one side of the Oxford Avenue, at the south-west of The Course which is the main approach to the house.
	DESIGNATION	Listed Building Grade I, RPG Grade I, CA	Work is needed to masonry. The pleasure grounds are
	CONDITION:	Poor	in the process of restoration.
AND A DESCRIPTION OF A	OCCUPANCY:	Part occupied	
	PRIORITY:	D (D)	
	OWNERSHIP:	Trust	Contact: Kathryn Davies 01483 252028

SITE NAME:	Buckinghamshire Grim's Ditch: 875m long se	ction between L	eylands Farm and Shire Lane, Buckland
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	A small multivallate hillfort on Southend Hill	, Cheddington	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	A slight univallate hillfort 600m south east o	f Home Farm, M	aids Moreton
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Halton House, Halton		d country house with late CI9 formal gardens and
DESIGNATION:	Registered Park and Garden Grade II,		roodland rides. The estate was used by the Army (1, when many trees were cut down, and was sold to
	also part in CA, 5 LBs		1918. Halton House is now the Officers' Mess. Some
CONDITION:	Extensive significant problems	of the ornar	nental features of the garden are in poor condition, e pavilion in the Italian garden which is derelict. New
VULNERABILITY:	High	developmer	nts being discussed include a car park extension. There
TREND:	Deteriorating	is no Ćonse	rvation Management Plan for the gardens.
OWNERSHIP :	Corporate, single owner	Contact: C	harlotte McLean 01483 252076
SITE NAME:	Mentmore Towers, Mentmore	Sir Joseph Mentmore	Paxton designed the park and gardens for Towers.The house and gardens were sold in
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 10		permission granted in 2005 to convert to an hotel.
			It golf course has since been bought by the developer
CONDITION:	Extensive significant problems		
CONDITION: VULNERABILITY:	Extensive significant problems High	thus reuniti	ng most of the site. The permission has not yet
		thus reuniti	

SOUTH BUCKS

want la	SITE NAME:	Aviary at Dropmore House, Heathfield Road, Taplow	Aviary, early CI9, situated on south side of the range of buildings to west of the house. Vandalised and neglected for some years. Situated within late CI8 to early CI9 gardens in a ruinous condition. The woodland to the north and west
	DESIGNATION	Listed Building Grade I, RPG II	in a poor condition. The park to south and east is in good condition. Planning permission/conditional LBC granted for
ILZIN MANAGER ANNA ANY A	CONDITION:	Very bad	condition. Planning permission/conditional LBC granted for repair and conversion of mansion including Aviary.
and the second second	OCCUPANCY:	Not applicable	repair and conversion of mansion including / wary.
	PRIORITY:	B (B)	
	OWNERSHIP:	Private	Contact: Kathryn Davies 01483 252028

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

```
HERITAGE AT RISK 2009 / WYCOMBE
```

SITE NAME:	Bell barrow 260m WNW of Slough Glebe Farm, p	oart of the S	Saunderton Lee barrow cemetery,
	Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bledlow Cross, Bledlow cum Saunderton		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow I40m WNW of Slough Glebe Farm, Bledlow cum Saunderton	part of the	Saunderton Lee round barrow cemetery,
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow at Molin's Works, part of the Saunder	rton Lee ro	und barrow cemetery, Bledlow cum Saunderto
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			minor localised problems
RINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Roman villa east of Lodge Hill Farm, Bledlow cur	n Saunderto	n
designation:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Two bowl barrows 450m north west of Slough G Bledlow cum Saunderton	ilebe Farm, j	part of the Saunderton Lee barrow cemetery
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Roman villa north of Yewden Lodge, Hambleden		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
		convinci.	
SITE NAME:	Fawley Court and Temple Island, High Wycombe		urt's early CI8 garden and pleasure grounds 1680s' house set within a park landscaped by
DESIGNATION:	Registered Park and Garden Grade II*, also CA, 17 LBs	Lancelot Br	rown, the island Temple forming part of Brown
CONDITION:	Generally unsatisfactory with major localised problems		sta. Most of the park and estate are in separate
/ULNERABILITY:	High		from the gardens. Landscape management has npathetic and poorly resourced and, since beir
rrend:	Deteriorating	put on the	market in 2008, Fawley Court's future is
	Corporate, multiple owners	currently u	ncertain.
DWNERSHIP :			

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. agreed

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

EAST SUSSEX					
EASTBOURNE					
	SITE NAME: Eastbourne Redoubt, Eastbourne		A redoubt built as part of the Martello system. 1806. Main parts are in use as a museum. The aquarium building which occupies casemates and the mast on the south we side, is in very poor condition. The surviving caponieres suffer from water ingress. Moat walls are decaying.		
-	CONDITION:	E Listed Building Grade II, SM, CA	suiter norn water ingress. Tioat waits are decaying.		
		Part occupied C (C)			
	PRIORITY:	Local authority	Contact: Paul Roberts 01483 252032		
(91)	OVVINERSHIP:	Local authority	Contact. Faul Nobel is 01403 232032		
	SITE NAME:	Martello Tower No.64, Eastbourne	Martello tower, 1806. On the beach with a housing development nearby. The preservation of archaeological and historical significance will be the main consideration in assessing the suitability of proposals to convert		
		: Listed Building Grade II, SM	Martello towers for residential use.		
A Company of the State	CONDITION:				
	OCCUPANCY:				
a mail and a second	PRIORITY:	C (C)			
	OWNERSHIP:	Company	Contact: Paul Roberts 01483 252032		
1	SITE NAME:	Martello Tower No.66, Langney Point, Eastbourne	Martello tower, 1806. On the beach near the harbour entrance. The preservation of archaeological and historical significance will be the main consideration in assessing the		
The state of the second	DESIGNATION	:: Listed Building Grade II, SM	suitability of proposals to convert Martello towers for residential use.		
and the state	CONDITION:				
and the second second	OCCUPANCY:	Vacant			
The second second	PRIORITY:	С (С)			
And a star	OWNERSHIP:	Company	Contact: Paul Roberts 01483 252032		
HASTINGS					
	SITE NAME:	Statue of Queen Anne south east of Holmhurst St Mary's School, The Ridge, Baldslow, Hastings	Statue, 1711-12 in grounds of former convent (now sold separately). The statue is not being maintained.		
100 A 19 A	DESIGNATION	: Listed Building Grade II*			
CONTRACTOR OF A	CONDITION:				
States and a		Not applicable			
La L	PRIORITY:	C (C)			
	OWNERSHIP:		Contact:Tom Foxall 01483 252035		
	SITE NAME:	Remains of Manor House, Ore Place, Ore, Hastings	Ruins of late medieval manor house surrounded by new housing development.		
CON CONTRACT	DESIGNATION	: Scheduled Monument			
	CONDITION:				
1 Part		Not applicable			
and the second se	PRIORITY:	D (D)			
the state of the state		Local authority	Contact: Paul Roberts 01483 252032		
the second					
and a	SITE NAME:	Church of St Helen, Elphinstone Road, St Helens, Hastings	funded a feasibilty study, which has resulted in an approach		
		Elphinstone Road, St Helens, Hastings	grant given in past for repair of the tower. English Heritage funded a feasibilty study, which has resulted in an approact to Heritage Lottery Fund for a conservation, learning and		
	DESIGNATION	Elphinstone Road, St Helens, Hastings Listed Building Grade II, SM	grant given in past for repair of the tower. English Heritage funded a feasibilty study, which has resulted in an approad		
	DESIGNATION CONDITION:	Elphinstone Road, St Helens, Hastings Listed Building Grade II, SM Very bad	grant given in past for repair of the tower. English Heritage funded a feasibilty study, which has resulted in an approact to Heritage Lottery Fund for a conservation, learning and		
	DESIGNATION CONDITION: OCCUPANCY:	Elphinstone Road, St Helens, Hastings Listed Building Grade II, SM Very bad Not applicable	grant given in past for repair of the tower. English Heritage funded a feasibilty study, which has resulted in an approact to Heritage Lottery Fund for a conservation, learning and		
	DESIGNATION CONDITION:	Elphinstone Road, St Helens, Hastings Listed Building Grade II, SM Very bad Not applicable C (C)	grant given in past for repair of the tower. English Heritage funded a feasibilty study, which has resulted in an approach to Heritage Lottery Fund for a conservation, learning and		

Note: If the priority category has changed since the 2008 register, the previous category is given in brackets.

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

LEWES					
	SITE NAME: Lewes Priory Cockshut Ro Lewes		the care of are fenced	a Trust and open to off because of a ris	077. Much of the ruin is in o the public, but the ruins k to public safety.The area now privately owned and
million - worker	designation: Listed Building	g Grade I, SM, CA		ntained as a 'wild ga	
STATE OF	CONDITION: Poor				
and the first	OCCUPANCY: Not applicable PRIORITY: D (D)	9			
	PRIORITY: D (D) OWNERSHIP: Local authorit	у	Contact: Pa	ul Roberts 01483 2	252032
		,			
N'S IN	SITE NAME: Newhaven Fo Caponier and Fort Road, N DESIGNATION: Scheduled Mc	l Lunette Battery, ewhaven	Pry, Victorian gun battery and caponier of Newhaven Fo Both structures are overgrown with vegetation and brickwork has not been maintained and is in poor cor		
State of the second second second	condition: Poor				
	occupancy: Vacant				
	PRIORITY: $F(D)$				
	ownership: Local authorit	Contact: Paul Roberts 01483 252032			
SITE NAME:	Fore Hill round barrow,	Beddingham			
DESIGNATION:	Scheduled Monument		CONDITION:	Extensive significa i.e. under plough	'
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining	, collapse
OWNERSHIP:	Private		CONTACT:	Simon Goodhug	h 01483 252037
SITE NAME:	Round barrow south of	Ditchling Beacon, Ditch	ling		
DESIGNATION:	Scheduled Monument		CONDITION:	Extensive signification i.e. under plough	
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining	, collapse
OWNERSHIP:	Private		CONTACT:	Simon Goodhug	h 01483 252037
SITE NAME:	Bowl barrow on Front I	Hill, lford			
DESIGNATION:	Scheduled Monument		CONDITION:	Generally unsatis	factory
			Condition	with major locali	,
PRINCIPAL VULNERABILITY:	Arable clipping		TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhug	h 01483 252037
SITE NAME:	Lewes Town Wall, sectio	on called The Green Wall	, Lewes		
DESIGNATION:	Scheduled Monument		CONDITION:	Generally unsatis	factory
				with major locali	
PRINCIPAL VULNERABILITY:	Scrub / tree growth		TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhug	h 01483 252037
SITE NAME:	Multiple ring-ditch at M	ount Pleasant, Denton, N	lewhaven		
DESIGNATION:	Scheduled Monument		CONDITION:	Extensive significa	
	Arable players -			i.e. under plough	, collapse
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private		TREND: CONTACT:	Declining Simon Goodhug	n 01483 252037
Grandensen.	rivate		CONTACT:	Simon Gooding	1 01 103 232037
SITE NAME:	Bowl barrow forming pa	art of a linear round bar	row cemetery	y on Rookery Hill,	Seaford
DESIGNATION:	Scheduled Monument		CONDITION:	Generally satisfact significant localise	,
PRINCIPAL VULNERABILITY:	Arable clipping		TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhug	h 01483 252037
PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.	C Slow decay; no solution agreed. D Slow decay; solution agreed but not yet implemented.	but no use of vacancy	air or in fair to good repair, r identified; or under threat with no obvious new user only to buildings capable Il use).	F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	round ba	rrow cemetery on Rookery Hill, Seaf	ord	six bowl barrows, forming part of a linear		
DESIGNATION:	Scheduled	d Monument	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable cli	pping	TREND:	Declining		
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037		
ROTHER						
6	SITE NAME:	Martello Tower No. 55, Normans Bay, Bexhill	Martello tower built 1806. The preservation of archae and historical significance will be the main considera assessing the suitability of proposals to convert Mar towers for residential use.			
1	DESIGNATION	: Listed Building Grade II, SM				
Contraction of the local division of the loc	CONDITION:	-				
No. of States and	OCCUPANCY:	Vacant				
	PRIORITY:	D (D)				
the second	OWNERSHIP:	· · /	Contact: Pa	ul Roberts 01483 252032		
and the second	OWNERSHIP:	TTIVALE				
	SITE NAME:	Martello Tower No. 28, Rye Harbour, Icklesham	A derelict martello tower built 1806. Situated on the edge of a caravan park. The preservation of archaeol and historical significance will be the main considerat			
	DESIGNATION	: Listed Building Grade II, SM	in assessing the suitability of proposals to convert Ma towers for residential use.			
PERIOD PERIOD	CONDITION:	Poor				
	OCCUPANCY:	Vacant				
State of the local division of the local div	PRIORITY:	С (С)				
	OWNERSHIP:	()	Contact: Pa	ul Roberts 01483 252032		
	SITE NAME:	Grey Friars (Winchelsea Priory), Friars Road,Winchelsea, Icklesham	Ruins of a r of a CI9 m	nonastic church circa 1310-20, in the grounds ansion.		
	DESIGNATION	: Listed Building Grade I, SM, CA				
	CONDITION:	Poor				
Conden-Laster De	OCCUPANCY:	Not applicable				
	PRIORITY:	D (D)				
Company Pring & St.	OWNERSHIP:	Private	Contact: Pa	ul Roberts 01483 252032		
A.	SITE NAME:	Grey Friars Boundary Wall, Friars Road, Winchelsea, Icklesham		oundary wall to the Grey Friars mansion I from multiple collapses and further re likely.		
C UN PERSONAL PROPERTY.	DESIGNATION	: Scheduled Monument, CA				
A H State of the	CONDITION:	Very bad				
	OCCUPANCY:	Not applicable				
Charles Street	PRIORITY:	B (B)				
and the second	OWNERSHIP:		Contact: Pa	ul Roberts 01483 252032		
	SITE NAME:	Austin Friars Chapel, Conduit Hill, Rye	The south s	Remains of a friary chapel dating from about 1380. The south side of the Chapel is overgrown with vegetation and the window tracery is suffering		
SALANCE STREET	DESIGNATION	: Listed Building Grade II, SM, CA	ii oiri decay.			
	CONDITION:	Poor				
·····································						
	OCCUPANCY:	Occupied				
	OCCUPANCY: PRIORITY:	Occupied C (C)				

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

	SITE NAME:	Martello Tower No.30, Winchelsea Road, Rye	Martello tower built 1806. Nearly derelict. The moat on the east side has been destroyed and is now the site of new houses. The preservation of archaeological and historical significance will be the main consideration in assessing the
	DESIGNATION	Listed Building Grade II, SM	suitability of proposals to convert Martello towers for
	CONDITION:	Poor	residential use.
	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNERSHIP:	Private	Contact: Paul Roberts 01483 252032

SITE NAME:	Bowl barrow in Petley Wood, Battle		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Romano-British iron working site in Beaupor	rt Park, Battle	
SITE NAME: DESIGNATION:	Romano-British iron working site in Beaupor Scheduled Monument	rt Park, Battle	Extensive significant problems i.e. under plough, collapse
			0
DESIGNATION:	Scheduled Monument	CONDITION:	i.e. under plough, collapse

WEALDEN

Iron working site C17-C19. Lake drained and dam in very poor condition. Pippingford Blast Furnace, Pippingford Park, SITE NAME: Hartfield DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: Not applicable D (D) PRIORITY: OWNERSHIP: Private Contact: Paul Roberts 01483 252032

h	SITE NAME: Argos Hill Windmill, Argos Hill, Mayfield Designation: Listed Building Grade II* CONDITION: Poor		Post mill su	Post mill suffering from lack of maintenance and scaffolded.		
Caner Aspir Land	OCCUPANCY					
	PRIORITY: D (D) OWNERSHIP: Local authority					
			Contact: To	Contact: Tom Foxall 01483 252035		
SITE NAME:	Bramblet	ye House, Forest Row				
DESIGNATION:	Schedule	d Monument	CONDITION:	Generally satisfactory but with		
				significant localised problems		
PRINCIPAL VULNERABILITY:	Deteriora	ation – in need of management	TREND:	Declining		
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Far Black	lands iron bloomery, Forest Row				
DESIGNATION:	Schedule	d Monument	CONDITION:	Extensive significant problems		
				i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable pl	oughing	TREND:	Declining		
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

С Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

Е

SITE NAME:	High Rocks Camp, Frant (part in Kent)				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Kidbrooke Park, Forest Row	Kidbrooke i C19 landsca	is an CI8 park with extensive surviving early aping attributed to Humphry Repton and later		
DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs	formal and woodland gardens. The estate was sold in 193 then further subdivided. The house became a Steiner schoo which has since sold perimeter land for development and built school facilities in the grounds. This fragile landscape highly vulnerable to continuing development pressure and			
CONDITION:	Extensive significant problems				
VULNERABILITY:	Medium				
TREND:	Unknown				
OWNERSHIP :	Mixed, multiple owners	lack of a conservation strategy.			
		Contact: Cł	narlotte McLean 01483 252076		

HAMPSHIRE					
BASINGSTOKE AND	DEANE				
-	SITE NAME:	Barn at Manor Farm, Old Burghclere, Burghclere	Manorial barn, 1451, built for the Bishop of Winches Suffering from water ingress and failure of joints, the building needs comprehensive repair.		
		Listed Building Grade I			
And Address of the second	CONDITION: Poor				
Statistics of the local distance of the loca	occupancy: Not applicable				
g and the second second	PRIORITY:	C (New)			
	OWNERSHIP:	Private	Contact: D	avid Brock 01483 252044	
	SITE NAME:	London Lodge, Highclere Park, Highclere	Ceremonial archway and attached accommodation, 1793. Only emergency repairs have been carried out and negotiations continue to allow it to be occupied.		
	DESIGNATION	Listed Building Grade II*, RPG Grade I	1		
	CONDITION:	-			
	OCCUPANCY:	cant			
All Collins and All State	priority: C (C)				
	OWNERSHIP:	Private	Contact: David Brock 01483 252044		
SITE NAME:	A cross dyke and bowl barrow on the northern spur of Beacon Hill, Burghclere				
DESIGNATION:	Schedulec	Monument	CONDITION:	Generally unsatisfactory	
				with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037	
SITE NAME:	Long barrow 600m south of Preston Grange, Candovers				
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems	
				i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037	
SITE NAME:	A bell bar	row and a saucer barrow 315m ESE of th	ne unfinished	hillfort on Ladle Hill, Ecchinswell and Sydmonton	
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems	
				i.e. under plough, collapse	

PRINCIPAL VULNERABILITY:

OWNERSHIP:

Arable ploughing

Private

LA LB/LBs NP Local Authority Listed Building/s National Park

Declining

Simon Goodhugh 01483 252037

TREND:

CONTACT:

HERITAGE AT RISK 2009 / BASINGSTOKE AND DEANE / EAST HAMPSHIRE

SITE NAME:	Windmill mound at Farleigh House,	Farleigh Wallop	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	The western of two rectangular enclo	sures on Great Litchfield [Down, SSW of Ladle Hill, Litchfield and Woodc
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barrow 250m south east of W	illesley Warren Farm, Ov	erton
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Round barrow south west of Lower	Farm, Preston Candover	r
Designation:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
EAST HAMPSHIRE			
SITE NAME:	Bowl barrow on Chalton Down, 350	Om south east of Manor I	Farm, Clanfield
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 620m north east of W	′arhill Cottage, East Meor	n
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Group of four bowl barrows 660m	north of Warhill Cottage	e, East Meon
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:		junction of the A32 and	Fawley Lane, part of The Jumps round
	Bowl barrow 60m south east of the barrow cemetery, Froxfield Scheduled Monument	junction of the A32 and	Fawley Lane, part of The Jumps round Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	barrow cemetery, Froxfield		Extensive significant problems

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Bowl barrow 100m south east of Lov	wer Bordean Farm, Langr	rish
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
	A 11 1 1		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 240m south of Trinity	House, Medstead	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Three bowl barrows on Chalton Do	wn, 860m east of Nethe	rley Farm, Rowlands Castle
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 250m west of the junct barrow cemetery, West Tisted	tion of the A32 and Fawl	ey Lane, part of The Jumps round
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 330m south west of th barrow cemetery, West Tisted	e junction of the A32 an	d Fawley Lane, part of The Jumps round
		e junction of the A32 an	Extensive significant problems
DESIGNATION:	barrow cemetery, West Tisted		
DESIGNATION: PRINCIPAL VULNERABILITY:	barrow cemetery, West Tisted Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWINERSHIP: SITE NAME:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 • south west of Woolmer Cottages, White Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: 5ITE NAME: DESIGNATION:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman roa Scheduled Monument	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 • south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse
PESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman roa	CONDITION: TREND: CONTACT: d and hollow ways 200m	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 • south west of Woolmer Cottages, White Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: STTE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DWNERSHIP: DWNERSHIP: DWNERSHIP: DWNERSHIP:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: DESIGNATION: DESIGNATION:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private Three disc barrows on Longmoor C	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: OWNERSHIP:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument Plant growth Private Plant growth Plant growth Plant growth	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280 Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: DESIGNATI	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman roat Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument Plant growth Private Walldown enclosures, Whitehill	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION: TREND: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280 Declining Simon Goodhugh 01483 252037
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: SITE NAME: SITE NAME: SITE NAME:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument Plant growth Plant growth Government or Agency	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280 Declining Simon Goodhugh 01483 252037 Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman road Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument Plant growth Plant growth Government or Agency Walldown enclosures, Whitehill Scheduled Monument	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION: TREND: CONDITION: CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280 Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	barrow cemetery, West Tisted Scheduled Monument Arable ploughing Private Round barrow cemetery, Roman roat Scheduled Monument Plant growth Private Three disc barrows on Longmoor C Scheduled Monument Plant growth Private Walldown enclosures, Whitehill	CONDITION: TREND: CONTACT: d and hollow ways 200m CONDITION: TREND: CONTACT: ommon, 250m north we CONDITION: TREND: CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 a south west of Woolmer Cottages, White Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 st of the church, Whitehill Generally satisfactory but with significant localised problems 30280 Declining Simon Goodhugh 01483 252037 Generally unsatisfactory

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

1-	SITE NAME:	Barn at Fernhill Farm, Mill Lane, Titchfield	Tithe barn, probably C15, formally part of Titchfield Abbe Has been damaged by casual vandalism and needs repair and a new use.
/ management	DESIGNATION	: Listed Building Grade I, SM, CA	
	CONDITION:	-	
PART 1 1 1 1	OCCUPANCY:	Vacant	
	PRIORITY:	C (New)	
		Company	Contact: Richard Massey 01483 252046
	Ovvideronin.	company	
Mary	SITE NAME:	Fort Fareham, Newgate Lane, Fareham	Mid C19 fort forming part of a series of fortifications bui to defend Portsmouth Harbour. Unoccupied parts sufferi from decay and vandalism. Site now owned by various
THE REAL PROPERTY OF	DESIGNATION	: Listed Building Grade II, SM	private companies.
A	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	A (A)	
No.		Company	Contact: Richard Massey 01483 252046
	SITE NAME:	Mill Street, Titchfield, Fareham	Stables to Titchfield Abbey. The Abbey was founded in 12 and converted to a private residence in 1537. The stables are overgrown with vegetation and have some structural problems. A repair programme is under discussion with
Call The Call	DESIGNATION	Scheduled Monument, CA	the new owner.
	CONDITION:	Fair	
A DECLARIE	OCCUPANCY: Not applicable	Not applicable	
	PRIORITY:	D (D)	
	OWNERSHIP:	Private	Contact: Richard Massey 01483 252046
GOSPORT			
	SITE NAME:	Fort Elson, RNAD, Military Road, Gosport	Polygonal artillery fort. 1853-60. Work has been undertak to check vegetation which is causing the masonry to fail. The fort is within a secure armaments depot so not availab for disposal. A management plan is being developed by
ALL THE COLOR	DESIGNATION	Scheduled Monument	Defence Estates with discussion with English Heritage
CONTRACTOR OF THE	CONDITION:	Poor	to agree a management regime. The building cannot be
10 mm 444 202	OCCUPANCY:	Vacant	occupied because of its location.
E ANY DE VIEL TO DEPENDENT	PRIORITY:	C (C)	
L C.J. C. HELL, BOOK P. MICH TWO (1981)			
NUMERICAL PROPERTY		Government	Contact: Alan Johnson 020 7973 3174
NIN THE REAL		Government	Contact: Alan Johnson 020 7973 3174
		Government Fortifications north of Mumby Road, Mumby Road, Gosport	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major
	OWNERSHIP:	Fortifications north of Mumby Road, Mumby Road,	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks.
	OWNERSHIP:	Fortifications north of Mumby Road, Mumby Road, Gosport : Scheduled Monument, CA	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks.
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks.
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks.
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C) Government	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C)	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775 Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin,
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C) Government Railway Station Old Terminal, Spring Garden Lane,	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775 Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin, now with consent for a housing scheme, on which
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C) Government Railway Station Old Terminal, Spring Garden Lane, Gosport Listed Building Grade II*, CA	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775 Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin,
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C) Government Railway Station Old Terminal, Spring Garden Lane, Gosport Listed Building Grade II*, CA Fair	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775 Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin, now with consent for a housing scheme, on which
	OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Fortifications north of Mumby Road, Mumby Road, Gosport Scheduled Monument, CA Fair Not applicable C (C) Government Railway Station Old Terminal, Spring Garden Lane, Gosport Listed Building Grade II*, CA Fair	A 600m length of the western fortifications of Gosport dating from circa 1770. Discussions on redesign of securit fencing in 2006 but no action. Excluded from major redevelopment scheme covering adjoining barracks. There is no foreseeable future use for the site. Contact: Rory O'Donnell 020 7973 3775 Railway station circa 1842, by Sir William Tite, for the London and South Western Railway Company. Damaged by bombing. Stable but unexploited ruin, now with consent for a housing scheme, on which

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

<u> 11 ii .</u>	SITE NAME:	Gilkicker Fort, Fort Road, Gilkicker Point, Gosport	good order, by water pe	t 1865-71. Owner has put barrack block into but casemates and magazines are threatened netration. Repair and conversion to residentia
The state of the s	DESIGNATION	Listed Building Grade II*, SM	developmer	it being considered.
THE CARLESSEE	CONDITION:	-		
THE REAL PROPERTY OF	OCCUPANCY:			
a Brook	PRIORITY:	D (D)		
		Local authority	Contact: Ric	hard Massey 01483 252046
	SITE NAME:	Workshops, Boilerhouse & Engine Room, Haslar Gunboat Yard, HMS Dolphin, Gosport	concern. The repair and a	boiler house and offices, mid C19, cause e buildings are already in a poor state of re deteriorating. Parts are no longer stable
	DESIGNATION	Scheduled Monument, CA	current use.	ections of the workshops roof). There is no
	CONDITION:	Poor	current use.	
	OCCUPANCY:	Vacant		
	PRIORITY:	A (A)		
	OWNERSHIP:	Company	Contact: Ric	hard Massey 01483 252046
± ±	SITE NAME:	Guardrooms to Haslar Gunboat Yard, Haslar Road, HMS Dolphin, Dolphin 3, Gosport	Unoccupied known as bu Dolphin, Do	and in need of more permanent repair. Also uildings 85 and 139, The Old Gatehouses, HM Iphin 3.
CALCULATION OF THE OWNER.	DESIGNATION	Scheduled Monument, CA		
	CONDITION:	Poor		
- 1 - 3/11	OCCUPANCY:	Vacant		
	PRIORITY:	С (С)		
	OWNERSHIP:	Government	Contact: Ala	n Johnson 020 7973 3174
ART				
AKI	SITE NAME:	Garden walls and associated structures,	Malls to ear	ly CI7 and CI8 formal walled gardens
		Bramshill House, Bramshill	surrounding of medieval Some sectio	the house, which is situated within a park origin, landscaped in the CI7, CI8 and CI9. ons of the walls are in a poor condition and
- AND AN	DESIGNATION	Listed Building Grade I, RPG II*	a section of	the wall to west of the house collapsed in eme for repair is in preparation for all the wa
BALL -	CONDITION:		2003. A SCH	errie for repair is in preparation for all the wa
122	OCCUPANCY:	Not applicable		
11.30	PRIORITY:	D (D)		
A.R. I.	OWNERSHIP:	Government	Contact: Eliz	rabeth Moore 020 7973 3803
	SITE NAME:	High Bridge, Bramshill House, Bramshill	lake formed on the main	an-style, arched bridge crossing Broad Water, along the course of the River Hart. Bridge is south-west to north-east axis across the par
AGAIN AND AND AND AND AND AND AND AND AND AN			willen has h	adjeval origins and was landscaped in the CI
	DESIGNATION	Listed Building Grade I, RPG II*	CI8 and CI	nedieval origins and was landscaped in the Cl 9. Repair scheme implemented in 2000/01 bi
a Provide States of States	DESIGNATION CONDITION:	-		nedieval origins and was landscaped in the Cl 9. Repair scheme implemented in 2000/01 bi 5 remain outstanding.
	CONDITION:	-		9. Repair scheme implemented in 2000/01 bi
	CONDITION:	Fair	some works	9. Repair scheme implemented in 2000/01 bi s remain outstanding.
	CONDITION: OCCUPANCY: PRIORITY:	Fair Not applicable	some works	9. Repair scheme implemented in 2000/01 b
E NAME:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP:	Fair Not applicable D (D)	some works Contact: Eliz	9. Repair scheme implemented in 2000/01 bi s remain outstanding.
TE NAME: ESIGNATION:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba	Fair Not applicable D (D) Government	some works Contact: Eliz	9. Repair scheme implemented in 2000/01 bi s remain outstanding. cabeth Moore 020 7973 3803 Generally unsatisfactory
SIGNATION:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot,	Contact: Eliz Crondall CONDITION:	9. Repair scheme implemented in 2000/01 bi s remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems
SIGNATION: INCIPAL VULNERABILITY:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tr	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth	Contact: Eliz Crondall CONDITION: TREND:	9. Repair scheme implemented in 2000/01 bi s remain outstanding. rabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining
SIGNATION: INCIPAL VULNERABILITY:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tr	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot,	Contact: Eliz Crondall CONDITION:	9. Repair scheme implemented in 2000/01 bi s remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tro Governme Bramshill	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa	Generally unsatisfactory with major localised problems Declining
ISIGNATION: INCIPAL VULNERABILITY: WNERSHIP:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tra Governme Bramshill Registerec also part i	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill d Park and Garden Grade II*, n CA, 8 LBs	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa within a par the CI7 and The site bed	9. Repair scheme implemented in 2000/01 bi s remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 rk comprises early C17 formal walled garden k of medieval origin which was landscaped in d mid C18 and later deformalised and enlarge came the Police Staff College in 1952, the
SIGNATION: NCIPAL VULNERABILITY: VNERSHIP: E NAME:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tra Governme Bramshill Registerec also part i	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill d Park and Garden Grade II*,	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa within a par the CI7 and The site bed farmland be	9. Repair scheme implemented in 2000/01 bi s remain outstanding. sabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 rk comprises early C17 formal walled garden k of medieval origin which was landscaped in d mid C18 and later deformalised and enlarge ame the Police Staff College in 1952, the ing sold and put under commercial forestry.
SIGNATION: NCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: DNDITION:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulec Scrub / tra Governme Bramshill Registerec also part i	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill d Park and Garden Grade II*, n CA, 8 LBs	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa within a par the CI7 and The site bed farmland be The site's his College's red	9. Repair scheme implemented in 2000/01 bits remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 rk comprises early C17 formal walled garden k of medieval origin which was landscaped in d mid C18 and later deformalised and enlarge iame the Police Staff College in 1952, the ing sold and put under commercial forestry, storic importance is highly vulnerable to the quirement for future building and to
SIGNATION: NCIPAL VULNERABILITY: VNERSHIP: E NAME: SIGNATION:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: CONNERSHIP: CONNERSHIP: CONNERSHIP: CONNERSHIP: CONNERSHIP: CONNERSHIP: CONDITION: CONDI	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill d Park and Garden Grade II*, n CA, 8 LBs	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa within a par the CI7 and The site bed farmland be The site's his College's red	9. Repair scheme implemented in 2000/01 bits remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 rk comprises early CI7 formal walled garden k of medieval origin which was landscaped in d mid C18 and later deformalised and enlarge tame the Police Staff College in 1952, the ing sold and put under commercial forestry, storic importance is highly vulnerable to the
SIGNATION: NCIPAL VULNERABILITY: vnership: E NAME: SIGNATION: INDITION: LNERABILITY:	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: Round ba Schedulect Scrub / tro Governme Bramshill Registerect also part i Extensive High Stable	Fair Not applicable D (D) Government rrow cemetery at Heath Brow, Ewshot, I Monument ee growth ent or Agency Park, Bramshill d Park and Garden Grade II*, n CA, 8 LBs	Contact: Eliz Crondall CONDITION: TREND: CONTACT: Bramshill Pa within a par the CI7 and The site bed farmland be The site's his College's req unsympathe	9. Repair scheme implemented in 2000/01 bis remain outstanding. tabeth Moore 020 7973 3803 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 rk comprises early C17 formal walled garden k of medieval origin which was landscaped ir d mid C18 and later deformalised and enlarge iame the Police Staff College in 1952, the ing sold and put under commercial forestry. storic importance is highly vulnerable to the quirement for future building and to

site name:	Warbrook House, Eversley
DESIGNATION:	Registered Park and Garden Grade II*, also I LB
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Deteriorating
OWNERSHIP :	Corporate, single owner

Warbrook's gardens with their axial vistas were designed c1724 by the architect John James – whose home it was. Major change occurred in the mid C20 with the conversion of the house to business use and the addition of new buildings and service areas. James' axes extend beyond the gardens but these, and the parkland, are perceived as without beneficial use and have deteriorated. A conservation strategy is urgently needed.

Contact: Charlotte McLean 01483 252076

NEW FOREST (NP)

NEVV FOREST (NI			
SITE NAME:	Bell barrow and two bowl barrows 180	m south west of Stagbu	ry Hill, Furzley Common, Bramshaw, New Fo
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Rabbit warren and four bowl barrows	on Stagbury Hill, Furzl	ey Common, Bramshaw, New Forest
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Studley Castle royal hunting lodge, Bra	amshaw, New Forest	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Twin bowl barrow on Furzley Commo	on, 810m SSW of Stagb	ury Hill, Bramshaw, New Forest
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 320m west of Ober Ho	use, Brockenhurst, New	/ Forest
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Hillfort 400m south of Home Farm, D	enny Lodge, New Fore	st
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
	Covernment of Agency	CONIACI.	
	Medieval hunting lodge in Churchplace	e Inclosure, Denny Lod	ge, New Forest
SITE NAME:			
SITE NAME: DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
		CONDITION: TREND:	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	I hree bowl barrows 420m south west barrow cemetery, Denny Lodge, New		orming part of the Beaulieu Heath round
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 360m west of Pitts Cops Fawley, New Forest	e farm forming part of	f Beaulieu Heath round barrow cemetery,
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Frankenbury hillfort, Godshill, New Fo	rest	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 400m south west of Rob	in Hood Farm, Minstea	ad, New Forest
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 550m north west of Avo	n Tyrrell, Ringwood, No	ew Forest
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
			a
NEW FOREST			
No. of Concession, Name	SITE NAME: Beaulieu Abbey,	Arcade of	Chapter House and associated walls, part of

	SITE NAME:	Beaulieu Abbey, Beaulieu	Arcade of Chapter House and associated walls, part of CI3 Abbey Arcade in danger of collapse and wall suffering from vegetation growth. Condition report completed.
1/2	DESIGNATION:	Scheduled Monument, CA	
1990	CONDITION:	Very bad	
	OCCUPANCY:	Not applicable	
	PRIORITY:	B (D)	
	OWNERSHIP:	Company	Contact: Richard Massey 01483 252046



_			
		Tide Mill, High Street, Beaulieu	Early C18, one of the few remaining tide mills. Repairs were largely complete before a fire (March 2006) which destroyed much of the roof.
	DESIGNATION:	Listed Building Grade II*, CA	
1994 1	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
10	PRIORITY:	C (C)	
	OWNERSHIP:	Trust	Contact: David Brock 01483 252044

Giant's Grave: a long barrow 400m north west of Down Farm, Breamore SITE NAME: Scheduled Monument Generally unsatisfactory DESIGNATION: CONDITION: with major localised problems Declining Extensive animal burrowing PRINCIPAL VULNERABILITY: TREND: Private Simon Goodhugh 01483 252037 OWNERSHIP: CONTACT: ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund Note: If the priority category has changed since the 2008 register, the previous category is given in brackets. WHS World Heritage Site

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / NEW FOREST / RUSHMOOR

SITE NAME:	Bowl barr	row 630m north of Hardley Bridge, Hyt	he and Dibd	en
DESIGNATION:	Schedulec	l Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tr	ee growth	TREND:	Declining
OWNERSHIP:	Governme	ent or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barı	row 330m north of Grim's Ditch, near T	idpit Comm	on, Martin
DESIGNATION:	Schedulec	l Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
OWNERSHIP:	Local Autl	nority	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long Barr	row 800m north west of Paradise, Marti	n	
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	bughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Duck's N	est: a long barrow on Rockbourne Dow	n, Rockbour	ne
DESIGNATION:		1 Monument	CONDITION:	Extensive significant problems
DESIGINALION:	JCHEQUIEC	i i fondment	CONDITION:	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:		rrow: a long barrow 880m west of Dow	n Farm, Roc	
DESIGNATION:		l Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:		animal burrowing	TREND:	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barr	row 700m north west of Tenantry Farm	, Rockbourn	e
DESIGNATION:	Schedulec	l Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	bughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
RUSHMOOR				
a	SITE NAME:	Building Q121 at Royal Defence Agency (24 foot wind tunnel), Hall Road, Farnborough	currently ur	el built 1934-35.The future use of the building is ncertain, but the owner is exploring imaginative r re-use. Repairs are complete.
	DESIGNATION	Listed Building Grade I		
	CONDITION:	Fair		
ALL AND AL	OCCUPANCY:	Vacant		
ALL DE LIGHT OF THE OWNER.	PRIORITY:	F (F)		
	OWNERSHIP:	Company	Contact: Da	avid Brock 01483 252044
	SITE NAME:	Building RI33 at Royal Defence Agency	of the build	el built 1939 and modified in 1956. The future us ing is currently uncertain, but being actively
		Farnborough	explored by	the owners. Repairs are now complete.
	DESIGNATION		explored by	the owners. Repairs are now complete.
1.1 Suprimum	DESIGNATION	Farnborough Listed Building Grade I	explored by	The owners. Repairs are now complete.
· · · · · · · · · · · · · · · · · · ·		Farnborough Listed Building Grade I Fair	explored by	the owners. Repairs are now complete.
	CONDITION:	Farnborough Listed Building Grade I Fair	explored by	The owners. Repairs are now complete.

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

TEST VALLEY			
SITE NAME:	Ashley Wood camp, Ashley		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barrow 400m south east of Mc	oody's Down Farm, Bartc	on Stacey
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barrow 400m west of Moody's	Down Farm, Barton Sta	сеу
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barrow and two bowl barrows	, 400m north of Chattis	Hill House, Broughton
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Two bowl barrows 90m south of Hill	l Lodge: part of a group o	of round barrows on Broughton Hill, Broughton
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Long barrow 300m south east of Mi	ddlebarn Farm, Chilbolto	n
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Castle Hill, Chilworth		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Barrow cemetery 730m north of Ha	mpshire Gap, Grately	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / TEST VALLEY

TE NAME:	Bowl barrow 780m NNE of Hampshir	e Gap, Grately	
ESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
TE NAME:	Andover-Redbridge canal, Chalk Hill Lo	ock, Horsebridge, King	s Somborne
ESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
TE NAME:	Long barrow 50m north east of Down	n Farm, Nether Wallop	
ESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
TE NAME:	Bowl barrow 250m south of Martin's (Clump, Over Wallop	
esignation:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
	Extensive animal burrowing	TREND:	Declining
RINCIPAL VULNERABILITY: WINERSHIP: TE NAME:	Government or Agency Flint mines, linear boundary and two b	CONTACT:	Simon Goodhugh 01483 252037
WNERSHIP:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument	CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems
WNERSHIP: TE NAME: ESIGNATION:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing	CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable
WNERSHIP: TE NAME:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument	CONTACT: nowl barrows at Martin CONDITION:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing	CONTACT: wowl barrows at Martin CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency	CONTACT: wowl barrows at Martin CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037
WNERSHIP: TE NAME: ESIGNATION: NINCIPAL VULNERABILITY: WNERSHIP: TE NAME:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro	CONTACT: wowl barrows at Martin CONDITION: TREND: CONTACT: ww, 250m south of Martin	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument	CONTACT: www.barrows at Martin CONDITION: TREND: CONTACT: ww,250m south of Martin CONDITION:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: w, 250m south of Martin CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing Government or Agency	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: w, 250m south of Martin CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: TE NAME:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing Government or Agency Long Barrow 350m south east of Nutt	CONTACT: www.barrows at Martin CONDITION: TREND: CONTACT: ww.250m south of Martin CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONTACT:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: WNERSHIP: TE NAME: ESIGNATION: TE NAME: ESIGNATION:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing Government or Agency Long Barrow 350m south east of Nutt Scheduled Monument	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: W, 250m south of Martin CONDITION: TREND: CONTACT: Dane, Penton Grafton CONDITION:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing Government or Agency Long Barrow 350m south east of Nutt Scheduled Monument Arable ploughing	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: W, 250m south of Martin CONDITION: TREND: CONTACT: Dane, Penton Grafton CONDITION: TREND: CONDITION:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: ESIGNATION:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barro Scheduled Monument Extensive animal burrowing Government or Agency Long Barrow 350m south east of Nutt Scheduled Monument Arable ploughing Private	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: W, 250m south of Martin CONDITION: TREND: CONTACT: Dane, Penton Grafton CONDITION: TREND: CONDITION:	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: WNERSHIP: TE NAME: ESIGNATION: RINCIPAL VULNERABILITY: WNERSHIP: TE NAME: ESIGNATION: TE NAME: TE NAME: TE NAME: TE NAME:	Government or Agency Flint mines, linear boundary and two b Scheduled Monument Moderate animal burrowing Government or Agency Long barrow and adjoining bowl barrow Scheduled Monument Extensive animal burrowing Government or Agency Long Barrow 350m south east of Nutt Scheduled Monument Arable ploughing Private Roman villa 500yds (460m) south west	CONTACT: Powl barrows at Martin CONDITION: TREND: CONTACT: W, 250m south of Martin CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: CONDITION: TREND: CONDITION: C	Simon Goodhugh 01483 252037 's Clump, Porton Down, Over Wallop Generally satisfactory but with significant localised problems Stable Simon Goodhugh 01483 252037 tin's Clump, Over Wallop Generally satisfactory but with significant localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 enton Grafton Extensive significant problems

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Embley Park, Wallow	Embley Park is a C19 and early C20 woodland and shrub garden of late C18 origin, once the home of
DESIGNATION:	Registered Park and Garden Grade II, also 8 LBs	Florence Nightingale, After WWII the estate was divided.
CONDITION:	Extensive significant problems	the house becoming a school. The school has since
VULNERABILITY:	High	reunited some of the park but the rest is divided between more than a dozen owners. This, with inevitable diverse
TREND:	Unknown	use and maintenance, make it difficult to conserve the
OWNERSHIP :	Mixed, multiple owners	fabric and design holistically.

Contact: Charlotte McLean 01483 252076

WINCHESTER			
	SITE NAME:	Brambridge House, Kiln Lane, Colden Common	Country house, 1762 and 1872, suffering from deferred maintenance. Some repairs have been carried out but more are needed.
	DESIGNATION	:: Listed Building Grade II*	
	CONDITION:	-	
	OCCUPANCY:	Occupied	
A STREET, BURNING THE REAL	PRIORITY:	D (F)	
Conception of the local diversion of the loca	OWNERSHIP:	Company	Contact: David Brock 01483 252044
	SITE NAME:	Merdon Castle, Hursley	Norman ringwork with a standing gatehouse surviving as core work. Overgrown and in need of consolidation. English Heritage is in discussion with owner about clearance and consolidation.
	DESIGNATION	: Scheduled Monument	cical ance and consolidation.
	CONDITION:	Poor	
	OCCUPANCY:	Not applicable	
	PRIORITY:	D (D)	
And I wanted	OWNERSHIP:	Company	Contact: Richard Massey 01483 252046
AP 3	SITE NAME:	St Peters Church (ruin), Lainston House, Lainston Park, Sparsholt	CI2 ruinous chapel, located circa I50m south-west of Lainston House. The ruin was used as a romantic folly in CI8 pleasure grounds in which it stands. Requires consolidation. Discussions have taken place and some
	DESIGNATION	:: Listed Building Grade II, SM, RPG II*	masonry repairs were carried out in 2005 but lintels
	CONDITION:		especially, give continued cause for concern.
A DECK	OCCUPANCY:	Not applicable	
	PRIORITY:	F (F)	
	OWNERSHIP:	Company	Contact: Richard Massey 01483 252046
	SITE NAME:	Walled garden to Lainston House, Lainston Park, Sparsholt	Hexagonal walled fruit or kitchen garden, c5.3ha, c100m west of the house. Probably C18. Striking polygonal layout. Axial vista from main entrance of house, across forecourt
	DESIGNATION	:: Listed Building Grade II*, RPG II*	and into walled garden. In use as hotel car park around the sides and planted in the centre. Some fruit trees remains
	CONDITION:	Fair	on the walls. In need of basic repairs. The gardens around
	OCCUPANCY:	Not applicable	the house are in good condition, but the park is in arable use.
	PRIORITY:	D (D)	
	OWNERSHIP:	Company	Contact: David Brock 01483 252044
and the second			
A ANT OF	SITE NAME:	King Johns House, Warnford Park, Warnford	Ruinous CI3 hall house. A feature within the CI8 pleasure grounds of Warnford Park, within which it is situated. Stop gap repairs have been
	DESIGNATION	: Listed Building Grade I, SM, RPG II	carried out. Requires further consolidation.
Stonessen of the file	CONDITION:	Poor	
THE PARTY IN	OCCUPANCY:	Not applicable	
	PRIORITY:	B (C)	
	OWNERSHIP:		Contact: Richard Massey 01483 252046

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / WINCHESTER / ISLE OF WIGHT (UA)

SITE NAME:	Two bow	l barrows north of Hoe Farm, Bish	ops Waltham	
DESIGNATION:	Schedulec	d Monument	CONDITION:	Generally unsatisfactory with major localised problems
RINCIPAL VULNERABILITY:	Scrub / tr	ee growth	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Four rour	nd barrows in 'Hump Field' south o	of Stakes Lane, Co	orhampton and Meonstoke
Designation:	Schedulec	Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Long barr	row 640m south east of Stock's Fa	rm, Corhampton	and Meonstoke
DESIGNATION:	-	Monument	CONDITION:	Generally unsatisfactory
	Schedulee		CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Iron Age f	ield system, banjo enclosure and R	omano-British vill	a, 500m east of Woodham Farm, Kings Worth
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:		ry Ring hillfort, Micheldever		
DESIGNATION:	Schedulec	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNERSHIP:	Private	2021.11.12	CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Long barr	row and bowl barrow 440m north	west of Sanctuar	y Farm, Wonston
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SLE OF WIGHT (UA))			
	SITE NAME:	Northwood House, Ward Avenue, Cowes	The origina The long-te	e, 1837, with spectacular interiors. I service wings have been mainly repaired. erm future of this partly-used building is
		: Listed Building Grade II*, CA		and maintenance to be addressed in erm. The cost of full repair is very high.
the second	CONDITION:	Fair		
	CONDITION: OCCUPANCY:	Fair Part occupied		
	CONDITION: OCCUPANCY: PRIORITY:	Fair Part occupied C (C)		
	CONDITION: OCCUPANCY:	Fair Part occupied C (C)		avid Brock 01483 252044
	CONDITION: OCCUPANCY: PRIORITY:	Fair Part occupied C (C)	Giant Canti built 1911. C surviving, an	avid Brock 01483 252044 ilever Crane, also called 'hammerhead' crane, Dne of a handful of this type of crane now id witness to a major local industry. Now disuse
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Fair Part occupied C (C) Trust Hammerhead Crane, Thetis Road, West Cowes,	Giant Canti built 1911. C surviving, an	avid Brock 01483 252044 ilever Crane, also called 'hammerhead' crane, Dne of a handful of this type of crane now
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Fair Part occupied C (C) Trust Hammerhead Crane, Thetis Road, West Cowes, Cowes Listed Building Grade II*	Giant Canti built 1911. C surviving, an	avid Brock 01483 252044 ilever Crane, also called 'hammerhead' crane, Dne of a handful of this type of crane now id witness to a major local industry. Now disuse
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Fair Part occupied C (C) Trust Hammerhead Crane, Thetis Road, West Cowes, Cowes Listed Building Grade II*	Giant Canti built 1911. C surviving, an	avid Brock 01483 252044 ilever Crane, also called 'hammerhead' crane, Dne of a handful of this type of crane now id witness to a major local industry. Now disuse
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Fair Part occupied C (C) Trust Hammerhead Crane, Thetis Road, West Cowes, Cowes Listed Building Grade II* Poor	Giant Canti built 1911. C surviving, an	avid Brock 01483 252044 ilever Crane, also called 'hammerhead' crane, Dne of a handful of this type of crane now id witness to a major local industry. Now disuse

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

		Golden Hill Fort, Military Road, Freshwater	The forme	t of I863 built as a hexagon around a courtyard r use as industrial units has ceased and domestic is now being carried out.
and the second second second	DESIGNATION:	Listed Building Grade I		-
	CONDITION:	•		
THE THERE IS NOT	OCCUPANCY:	Vacant		
Martin Mark . Tell	PRIORITY:	F (E)		
and the second second	OWNERSHIP:	Company	Contact: D	avid Brock 01483 252044
- Sette		Remains of Old Quarr Abbey, Fishbourne Park Road, Binstead, Ryde	of decline o English Her	oundation of 1131. In an advanced state due to neglect and vegetation growth. itage has carried out a photographic
2 to to the los	DESIGNATION:	Listed Building Grade II, SM		a condition survey. Discussions are e on a repair programme.
	CONDITION:		taking place	e off a repair programme.
CONTRACT A PROPERTY	OCCUPANCY:	Not applicable		
The the second second		A (A)		
A LOT MAL		Religious organisation	Contact: Ri	chard Massey 01483 252046
SITE NAME:	Medieval	ettlement 100m south east and 35	Om porth east o	f Fast Ashey Manor Farm Brading
				, .
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tre	ee growth	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barr	ow known as 'Black Barrow': 670n	NNE of Longst	one Farmhouse, Brighstone
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
	Extensive	animal burrowing	TRENED	Declining
PRINCIPAL VULNERABILITY:	Private	animai burrowing	TREND:	Simon Goodhugh 01483 252037
OWNERSHIP:	TTIVALE		CONTACT:	
SITE NAME:	Bowl barr	ow on Newbarn Down:1.1km sou	th west of Rowr	idge, Brighstone
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate	stock erosion	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Two bowl	barrows 250m south west of Call	ourne Bottom, I	Brighstone
DESIGNATION:		Monument	CONDITION:	Generally unsatisfactory
	Scheduled	Tionament	CONDITION.	with major localised problems
PRINCIPAL VULNERABILITY:	Extensive a	animal burrowing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
			north of lighthe	use on St Catherine's Hill, Chale
SITE NAME:	Bowl harr	ow on St Catherine's Down 680m		
			-	
SITE NAME: DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION:	Scheduled Extensive a		-	Generally unsatisfactory with major localised problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Extensive a Private A Bronze a	Monument animal burrowing Age barrow and Anglo-Saxon cem	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining
	Scheduled Extensive a Private A Bronze a Isle of Wig	Monument animal burrowing Age barrow and Anglo-Saxon cem	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	Scheduled Extensive a Private A Bronze a Isle of Wig	Monument animal burrowing Age barrow and Anglo-Saxon cem ght Monument	CONDITION: TREND: CONTACT: etery on Bowcon	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 mbe Down, 575m south east of Apesdown, Extensive significant problems

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / ISLE OF WIGHT (UA) / ASHFORD

SITE NAME:	Carisbrooke Romano-British villa, Isle of Wight		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Two bowl barrows 180m WNW of Puck House,	Fishbourne,	Isle of Wight
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Moated site 100m north east of Wolverton Manc	or, Shorwell	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Unknown
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Three bowl barrows 540m east of Week Farm: p	art of a rou	nd barrow cemetery on Week Down, Ventno
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
site name:	Swainston, Clabourne	Swainston's	s mid/late C18 woodland pleasure grounds, set
	Swainston, Clabourne Registered Park and Garden Grade II, also 3 LBs	parkland, w a stream in	ere designed with intersecting avenues, pools an corporating earlier fishponds. The reconstructed
DESIGNATION:		parkland, w a stream ind house and	ere designed with intersecting avenues, pools an corporating earlier fishponds. The reconstructed refurbished gardens is now a hotel, but some
DESIGNATION: CONDITION:	Registered Park and Garden Grade II, also 3 LBs	parkland, w a stream in house and key feature	ere designed with intersecting avenues, pools an corporating earlier fishponds. The reconstructed refurbished gardens is now a hotel, but some s lie in the remainder of the estate which is in
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: TREND:	Registered Park and Garden Grade II, also 3 LBs Generally unsatisfactory with major localised problems	parkland, w a stream ind house and key feature separate, d low value o	ere designed with intersecting avenues, pools an corporating earlier fishponds. The reconstructed refurbished gardens is now a hotel, but some

KENT ASHFORD

ASITIOND			
	1	Remains of Archbishops Palace, Market Place, Charing	Remains of palace built in CI3 and CI4. Farm complex converted from remains includes gatehouse, barn (east range of palace courtyard), outhouse (west range) and Palace Farmhouse (north range). Temporary support
		Listed Building Grade I, SM, CA	has been given to the structurally unsound barn with
all an mail	CONDITION:	Very bad	English Heritage grant aid. Survey carried out by the
A CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWN	OCCUPANCY:	Not applicable	Royal Commission on the Historic Monuments of England.
	PRIORITY:	A (A)	
Charles and the second	OWNERSHIP:	Private	Contact: Judith Roebuck 01483 252048
	SITE NAME:	Ruins of Church of St Mary, Pluckley Road, Little Chart	War damaged church, circa 1500, now ruinous with tower still standing. Local authority has repaired ruined walls of nave and chancel with English Heritage grant.
	DESIGNATION	Listed Building Grade II, SM	
	CONDITION:	Poor	
	OCCUPANCY:	Not applicable	
	PRIORITY:	D (D)	
	OWNERSHIP:	Local authority	Contact: Judith Roebuck 01483 252048

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

				HERITAGE AT RISK 2009 / ASHFORD / CANTERBU
	SITE NAME:	Wye Undercroft, Bridge Street, Wye with Hinxhill	CI3 underc	roft in front garden of new house.
Land I	DECICNIATION	: Listed Building Grade II, SM, CA		
hi Hallan	CONDITION:	-		
E. A Printer				
		Not applicable		
And The Market of Colors	PRIORITY:	D (D)		
	OWNERSHIP:	Private	Contact: jud	dith Roebuck 01483 252048
SITE NAME:	Castle To	II Saxon burgh and medieval fort, Newe	enden	
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
CANTERBURY				
	site name:	Greyfriars Monastery, Stour Street, Canterbury		valls from Tudor house built on site of the fria rt of the friary church. Friary built in 1267.
	DESIGNATION	: Listed Building Grade I, SM, CA		
11 2		Very bad		
100		Not applicable		
States All Side	PRIORITY:	A (A)		
5.1	OWNERSHIP:	Housing Association	Contact: Judith Roebuck 01483 252048	
S AUDA	SITE NAME:	Monuments in the precinct of Canterbury Cathedral, The Precinct, Canterbury	Very important medieval ruinous structures of Christchurch Priory, which have suffered from years of decline, Major backlog of repairs, work has started	
	DESIGNATION	: Listed Building Grade I, WHS, SM, CA	with English	Heritage grant to Llanfrancs dormitory y wall. Slow progress is being made.
的 同时间隔离 把上		Very bad	and the Cit	y wall. Slow progress is being made.
ARE STREET		Not applicable		
	PRIORITY:	B (B)		
		Religious organisation	Contact: luc	dith Roebuck 01483 252048
	Ownerdrin .	Tionglous of gambation	contact. juc	
	SITE NAME:	Horton Manor Chapel, Horton, Chartham	Two cell me Located on	edieval (CI4) chapel now roofless. a farm. Repair schedule prepared.
L. C. C.	DESIGNATION	: Listed Building Grade II, SM		
A Second Second		Very bad		
		Not applicable		
版: 全人 1988年2	PRIORITY:	C (C)		
A HINDRY	OWNERSHIP:		Contact: Juc	dith Roebuck 01483 252048
	SITE NAME:	Barn at Hardres Court, Upper Hardres	Late CI5 to Damaged b	early Cl6 aisled timber barn. y fire in 1993.
		: Listed Building Grade II*, CA		
	CONDITION:	-		
and the second of the	OCCUPANCY:			
Service USS				
and a school had	PRIORITY:	C (C)	Card	
	OWNERSHIP:	Private	Contact: lor	m Foxall 01483 252035
ITE NAME:	Bowl barı	row 350m south west of Upper Digges	Farm, Adisha	am
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining PRINCIPAL VULNERABILITY: Private Simon Coordburgh 01/483 252037	DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
Chartersum Private Private Simon Coodburgh 01483 252037	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / CANTERBURY / DARTFORD / DOVER

SITE NAME:

SITE NAME:	Enclosures west of Woodlands, Adisham		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

DARTFORD

SITE NAME:	Roman enclosure south east of Vagnia	Roman enclosure south east of Vagniacae, Southfleet				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems			
			i.e. under plough, collapse			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037			
SITE NAME:	Springhead Roman site, Southfleet					
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems			
			i.e. under plough, collapse			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037			

The Western Heights fortifications,

Castle Hill,

DESIGNATION: Scheduled Monument, CA

Dover

DOVER

MAR

CONDITION: Poor steadily deteriorating due to long-term neglect and vandalism. OCCUPANCY: Part occupied C (C) PRIORITY: OWNERSHIP: Government Contact: Alan Johnson 020 7973 3174 Fort Burgoyne, 1860s polygonal-plan fort now part of a later barracks. SITE NAME: The earth-covered terraced casemates are vacant. Connaught Barracks, Structures on the ramparts (the brick-built Haxo Guston Casemates) are at risk from lack of maintenance and DESIGNATION: Scheduled Monument invasive ivy growth. The site is now owned by Homes Fair CONDITION: and Community Agency. OCCUPANCY: Vacant C (C) OWNERSHIP: Housing Association Contact: Judith Roebuck 01483 252048



SITE NAME:		St Radegunds Abbey, Abbey Road, Hougham Without	A significant CI3 monastic site with standing remains of the church and claustral buildings. Heavily overgrown and fabric in a ruinous state. The site is now a farm with	
		Listed Building Grade II*, SM	buildings used as barns and a farmhouse. These are in fair condition.	
	CONDITION:	Very bad		
	OCCUPANCY:	Not applicable		
	PRIORITY:	A (A)		
	OWNERSHIP:	Private	Contact: Judith Roebuck 01483 252048	
	SITE NAME:	The Belvedere, Waldershare Park, Shepherdswell with Coldred	Belvedere: 1725-7 by Lord Burlington or Colin Campbell for Sir Henry Furnese located at the southern end of the western side of an early C18 Wilderness, overlooking the	



te name:	The Belvedere, Waldershare Park, Shepherdswell with Coldred
ESIGNATION:	Listed Building Grade I, RPG II
ONDITION:	Very bad
CCUPANCY:	Vacant
RIORITY:	C (C)
WNERSHIP:	Private

Belvedere: I725-7 by Lord Burlington or Colin Campbell for Sir Henry Furnese located at the southern end of the western side of an early CI8 Wilderness, overlooking the park to the north and south. Derelict for many years and now in a ruinous state. The Wilderness lies to the south of the house; mostly cleared and planted with larch in the I950s. The rides and scattered mature oaks and sweet chestnuts survive.

The extensive Western Heights fortifications are in multiple

ownership and parts are at risk, including the western

outworks (on land managed by the Home Office) and

Heritage: the north entrance, north-centre bastion and adjoining detached bastion. The areas at risk are robust but

parts of the site that lie within the guardianship of English

Contact: Tom Foxall 01483 252035

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. L Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

site name:	Sandown	Castle, Deal		
DESIGNATION:	Schedulec	Monument	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Coastal er	rosion	TREND:	Declining
OWNERSHIP:	Local Aut	nority	CONTACT:	Simon Goodhugh 01483 252037
JITE NAME:	Great Mc	ngeham Anglo-Saxon cemetery, Grea	t Mongeham	
DESIGNATION:	Schedulec	l Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	bughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	St Radegi	ınd's Abbey, Poulton, Hougham Witho	ut	
DESIGNATION:	Schedulec	I Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Collapse		TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Ring ditch	n and enclosure 200yds (180m) east c	of Parsonage Fa	ırm, Preston
DESIGNATION:	Schedulec	l Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Four ring ditches on ridge of Sutton Hill, Sut		n	
DESIGNATION:		1 Monument	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plo	ughing	TREND:	i.e. under plough, collapse Declining
OWNERSHIP:	Private	Jagning	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Romano-	Celtic temple and Iron Age site south	of Worth.Wo	rth
DESIGNATION:		I Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
GRAVESHAM				
GRAVESHAM	SITE NAME:	The Dairy, Cobham Hall, Cobham	Unusual Ge years ago a	orgian model dairy, part repaired several nd awaiting completion of works.
GRAVESHAM		Cobham Hall,	Unusual Ge years ago a	eorgian model dairy, part repaired several nd awaiting completion of works.
GRAVESHAM		Cobham Hall, Cobham Listed Building Grade II*, RPG II*	Unusual Ge years ago a	eorgian model dairy, part repaired several nd awaiting completion of works.
GRAVESHAM	DESIGNATION	Cobham Hall, Cobham : Listed Building Grade II*, RPG II* Fair	Unusual Ge years ago a	eorgian model dairy, part repaired several nd awaiting completion of works.
GRAVESHAM	DESIGNATION CONDITION:	Cobham Hall, Cobham : Listed Building Grade II*, RPG II* Fair	years ago a	nd awaiting completion of works.
GRAVESHAM	DESIGNATION CONDITION: OCCUPANCY:	Cobham Hall, Cobham Listed Building Grade II*, RPG II* Fair Vacant E (E)	years ago a	eorgian model dairy, part repaired several nd awaiting completion of works. m Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	Cobham Hall, Cobham Listed Building Grade II*, RPG II* Fair Vacant E (E)	years ago a Contact: Tor	nd awaiting completion of works. m Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	Cobham Hall, Cobham Listed Building Grade II*, RPG II* Fair Vacant E (E)	years ago a Contact: Tou Cistercian a medieval rc	nd awaiting completion of works. m Foxall 01483 252035 bbey founded in 1146. Main threat is to a
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Cobham Hall, Cobham Listed Building Grade II*, RPG II* Fair Vacant E (E) Trust Boxley Abbey Barn, Boxley Abbey,	years ago a Contact: Tou Cistercian a medieval rc	nd awaiting completion of works. m Foxall 01483 252035 bbey founded in 1146. Main threat is to a pofed range used formerly as a barn, but whicl
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Cobham Hall, Cobham Listed Building Grade II*, RPG II* Fair Vacant E (E) Trust Boxley Abbey Barn, Boxley Abbey, Boxley Listed Building Grade I, SM, CA	years ago a Contact: Tou Cistercian a medieval rc	nd awaiting completion of works. m Foxall 01483 252035 bbey founded in 1146. Main threat is to a pofed range used formerly as a barn, but whic
GRAVESHAM	DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION	Cobham Hall, Cobham Hall, Cobham Grade II*, RPG II* Fair Vacant E (E) Trust Boxley Abbey Barn, Boxley Abbey, Barn, Boxley Abbey, Barn, Boxley Abbey, Barn, Boxley Abbey Composition Compos	years ago a Contact: Tou Cistercian a medieval rc	nd awaiting completion of works. m Foxall 01483 252035 bbey founded in 1146. Main threat is to a pofed range used formerly as a barn, but whic
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Cobham Hall, Cobham Hall, Cobham Grade II*, RPG II* Fair Vacant E (E) Trust Boxley Abbey Barn, Boxley Abbey, Boxley Abbey Barn, Boxley Abbey, Boxley Abbey, Boxley Abbey, Boxley Abbey, Boxley Abbey Barn, Boxley Barn, Boxley Abbey Barn, Boxl	years ago a Contact: Tou Cistercian a medieval ro is now vaca	nd awaiting completion of works. m Foxall 01483 252035 bbey founded in 1146. Main threat is to a pofed range used formerly as a barn, but whicl

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

 RPG
 Registered Park and Garden
 WHS
 World Heritage Site

 SM/SMs
 Scheduled Monument/s
 UA
 Unitary Authority

MI	SITE NAME:	St Andrews Chapel, Boarley Lane, Boxley Abbey, Boxley	Late CI5 chapel. Currently unoccupied and subject to vandalism. Location affected by proximity of motorway.
Alles Start	DESIGNATION	Listed Building Grade II*	
	CONDITION:	-	
	OCCUPANCY	Vacant	
ALL ALL	PRIORITY:	E (E)	
	OWNERSHIP:	Private	Contact:Tom Foxall 01483 252035
/0.	SITE NAME:	Dovecotes at Leeds Priory, Lower Street, Leeds	Mid CI6 overgrown and roofless dovecotes from a post-dissolution mansion. Site purchased for possible new houses.
	DESIGNATION	I: Listed Building Grade II, SM	
All the second second	CONDITION:	Very bad	
	OCCUPANCY	Vacant	
A STATE OF THE OWNER	PRIORITY:	B (B)	
	OWNERSHIP:	Trust	Contact: Judith Roebuck 01483 252048
	site name:	Slype and associated remains at Leeds Priory, Lower Street, Leeds	A slype (covered passage) and associated remains of medieval priory. Site purchased for possible new houses.
	DESIGNATION	: Listed Building Grade II, SM	
	CONDITION:	Very bad	
NU RUNCE	OCCUPANCY	Not applicable	
	PRIORITY:	C (C)	
	OWNERSHIP:	Trust	Contact: Judith Roebuck 01483 252048
	SITE NAME:	II Lower Stone Street, Maidstone	Early C18 house.Vacant for some years.
	DESIGNATION	Listed Building Grade II*, CA	
	CONDITION:	-	
	OCCUPANCY	Vacant	
	PRIORITY:	E (E)	
	OWNERSHIP:	Company	Contact:Tom Foxall 01483 252035
	site name:	Ruined gateway, College of All Saints, Mill Street, Maidstone	Ruined gatehouse to medieval college. Structural cracking evident. Monitoring by structural engineer will inform application for English Heritage grant consideration.
		Listed Building Grade II, SM, CA	
	CONDITION:		
語言には言語	OCCUPANCY	Not applicable	
	PRIORITY:	D (D)	
	OWNERSHIP:	Local authority	Contact: Judith Roebuck 01483 252048
A CONTRACTOR OF A CONTRACTOR OFTA CONTRACTOR O			
	SITE NAME:	The Dungeons at the Archbishop's Palace, Mill Street, Maidstone	Partially ruined stone building of medieval date. Previous alterations and lack of repair are contributing to structural problems.
	DESIGNATION	Archbishop's Palace, Mill Street, Maidstone Listed Building Grade II*, CA	Previous alterations and lack of repair are contributing
		Archbishop's Palace, Mill Street, Maidstone Listed Building Grade II*, CA	Previous alterations and lack of repair are contributing
	DESIGNATION	Archbishop's Palace, Mill Street, Maidstone t Listed Building Grade II*, CA Poor Vacant	Previous alterations and lack of repair are contributing
	DESIGNATION CONDITION: OCCUPANCY PRIORITY:	Archbishop's Palace, Mill Street, Maidstone & Listed Building Grade II*, CA Poor	Previous alterations and lack of repair are contributing

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Interve More Prove Networks House And Base Prove House Pr					HERITAGE AT RISK 2009 / MAIDSTONE / SEVENOAKS
baseware listed Building Grade IP, PPG II covering Pair incovering Pair	1	SITE NAME:	Mote Park,	House, 1793 Currently ur	3-1801. Recently used as an old people's home. Inder repair for conversion to retirement housing.
Eventual Probability Contract: Tom Food1 01483 252035 stranse: Leads Priory Augusthian Priory of St Mary and St Nicholas with associated dovecotes and stype, and the site of the 18th century Meredith manion. Leads Scheduleet Monument: contract: Tom Food1 01483 252035 stranse: Leads Priory Augusthian Priory of St Mary and St Nicholas with associated dovecotes and stype, and the site of the 18th century Meredith manion. Leads contract: Tom Food1 01483 252037 stranse: Scheduleet Monument: contract: Dow Decling contrasts contrasts with major localised problems missaw with major localised problems stranse Scheduleet Monument: contrast stranse Scheduleet Monument: contrast Generally unstificatory with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems missaw with major localised problems	NO REPERE				
December 2007 December 2007 December 2007 Contract: Form Foxall 01483 252035 STIT NAME Leeds Priory: Augustinin Priory of St Mary and St Nicholas with associated dovecotes and skype, and the site of the Bib century Meredium manison, Leeds Status and the site of the Bib century Meredium manison, Leeds Status and the site of the Bib century Meredium manison, Leeds Contract: Tom Foxall 01483 252037 Status and the site of the Bib century Meredium manison, Leeds Extensive significant problems is: under plough, cellspan Status and the site of the Bib century Meredium manison, Leeds Contract: Control of Status and Status			· · · · · · · · · · · · · · · · · · ·		
Processor F (C) consistence: Contact: Tom Foxall 01483 252035 ummark Leeds Priory: Augustinian Priory of St Mary and St Nicholas with associated devectors and stype, and the size of the life the entrury Meredith manion. Leeds Contact: Tom Foxall 01483 252037 ummark Scheduled Monument consumous Extensive significant problems is under plogin-collapse ummark Collapse mass. Declining ummark Binbury motte and bailey caste, Thumham Contact: Simon Goodhigh 01483 252037 ummark Binbury motte and bailey caste, Thumham Contact: With major localised problems ummark Scheduled Monument consumous Scheduled Monument ummark Scheduled Monument consumous Simon Goodhigh 01483 252037 StVENOAKS Stream Marcreal Park, Obelisk, Riverhead mass. Declining ummark Marcreal Park, Obelisk, Riverhead mass. Declining consumous ummark D (D) consumous Scheduled Monument consumous ummark D (D) consumous Scheduled Monument consumous ummark D (D) consume <					
Ownerse Local authomy Contact: Tom Foxall 01483 252035 ait. Name: Leeds Priory: Augustinian Priory of St Mary and St Nicholas with associated dovecoes and signe. and the site of the IBM century Meredith manison. Leeds Extensive significant problems i.e. under plough collapse Data Annote: Contact: Tom Foxall 01483 252037 Extensive significant problems i.e. under plough collapse Marken: Binbury mote and balley castle, Thurnham Contact: Marken Declining Smith Balley Castle, Thurnham Statewin: Scheduled Monument Contact: Marken Declining Smith Balley Castle, Thurnham Statewin: Scheduled Monument Contact: Marken Declining Smith Balley Castle, Thurnham Statewin: Scheduled Monument Contact: Judith Roebuck 01483 252037 Smith Balley Castle, Thurnham Statewin: Scheduled Monument Contact: Judith Roebuck 01483 252037 Smith Balley Castley Scheduled Marken Declining Statewin: D (D) Contact: Judith Roebuck 01483 252037 Smith Balley Castley Declining Tit Marken Chapel, Maplescombe, West Kingdown Smith Balley Castley Declining Contact: Judith Roebuck 01483 252037 Tit Marken Scheduled Monument Smith Balley Castley Declining Smith Balley Castley Declining					
Instrume Leeds Priory: Augustinian Priory of St. Mary and St. Nicholas tasocitated devectors and stype, and the size of the 18th century Meredith mansion. Leeds DEGRAMON Scheduled Monument control Extensive significant problems is under plough collapse PRACEMENT Collapse mm Declining provement Private control Extensive significant problems is under plough collapse transver Binbury motte and bailey castle, Thurnham Control Generally unsatifactory with major localed problems transver Scheduled Monument control Generally unsatifactory with major localed problems Transver Scheduled Monument control Simon Goodhigo 01483 252037 SEVENCAKS Transver Montreal Park Obelisk, Montreal Park, Northead On C18 monument to the Canadam Wars in need or consvers Declining converses Declining Montreal Park, Northead On C18 monument to the Canadam Wars in need or consvers Declining converses Declining Montreal Park, Northead On C18 monument to the Canadam Wars in need or consvers Declining converses Declining Montreal Park, Northead On C18 monument to the Canadam Wars in need or consvers Traver Chapel, Maplescombe, West Kingdown					
and the site of the IBth century Meredith mansion, Leeds max Description Scheduled Monument controls Le under plough, collapse Prescription Private controls Le under plough, collapse Description Private controls Extensive significant problems Le under plough, collapse Description Private controls Generally unsatisfactory with major localised problems Description Scheduled Monument controls Generally unsatisfactory with major localised problems Private Controls Scheduled Monument smoon Goodingh 01483 252037 Strevensuse Private controls Simon Goodingh 01483 252037 Strevensuse Private controls Simon Goodingh 01483 252037 Strevensuse Private control Simon Goodingh 01483 252037 Strevensuse Private control Simon Goodingh 01483 252037 Strevensuse Private control Simon Goodingh 01483 252037 Strevensus Strevensus Scheduled Monument controls Simon Goodingh 01483 252048 Strevensus Scheduled		OWNERSHIP:	Local authority	Contact: Ioi	m Foxall 01483 252035
Ise under plugh, collapse tree men Declining conversion Private conversion Simon Goodhugh 01483 252037 version Binbury motte and balley castle, Thurnham conversion Generally unsatisfactory with major localised problems version Scheduled Monument conversion Generally unsatisfactory with major localised problems version Structure Structure Structure Structure Structure Structure Montreal Park Obelisk, Montreal Park Obelisk, Montreal Park, Riverhead An CIB monument to the Ganadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorals grant accepted March 2007. Structure Control Control Control Control control Control Declining Control Control control Robread Monument Control Control Control control Scheduled Monument conversion Generally unsatisfactory with major localied problems structure Scheduled Monument conversion Generally unsatisfactory with major localied problems structure Scheduled Monument conversion Generally	SITE NAME:				vith associated dovecotes and slype,
Conversion Private Conversion Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 Simon Goodhugh 01483 252037 SEVENOAKS Strue Feeders Vision Goodhugh 01483 252037 Simon Goodhugh 01483 252037 SEVENOAKS Strue Montreal Park, Niverhead An CIB monument to the Canadian Wars In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. SEVENOAKS Strue Montreal Park, Niverhead An CIB monument to the Canadian Wars In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Strue Chapel, Maplescombe, West Kingsdown Decourse: Contact: Judith Roebuck 01483 252048 Strue Chapel, Maplescombe, West Kingsdown Decourse: Contact: Scheduled Monument converse: Contact: Scheduled Monument converse: Strue K Chapel, Maplescombe, West Kingsdown Decourse: Strue March 2007. Strue Chapel, Maplescombe, West Kingsdown Decourse: Strue K Strue J tree growth Trave: Declining Sympand, including extensive rockwork developed in the lat Instruation Strue K: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure rearmedy withrealle with major	DESIGNATION:	Scheduled	l Monument	CONDITION:	
STREAME: Binbury mote and bailey castle, Thurnham Descivation Scheduled Monument Containers Generally unsatisfactory with major localised problems PROCENT VALUES Strub / tree growth TREAM Decklining Concernse Private Controls / tree growth TREAME SEVENOAKS Strub / tree growth Tree growth An CIB monument to the Canadian Wars In need or prains to payle to prevent loss of historic detail. War Memonals grant accepted March 2007. SEVENOAKS Struberead Processes: Values An CIB monument to the Canadian Wars In need or prains to payle to prevent loss of historic detail. War Memonals grant accepted March 2007. Strub Nerse D(D) concesses: Poor concesses: Poor concesses: Poor concesses: Contact: Judith Roebuck 01483 252048 Strub Nerse Scheduled Monument concesses: Scheduled Monument Contact: Judith Roebuck 01483 252048 Strub / tree growth Tree mark Contact: Judith Roebuck 01483 252037 Strub / tree growth Tree mark Declining growth, including extension rodowork developed in the lat Contact: Output the growth and Garden Grade II, also 2 LBS contacts Strub / tree growth Tree mark Swaylands, Penshurst Swaylands is important for it terraced gardens and pleasure grownts, including extension rodowork developed in the lat	PRINCIPAL VULNERABILITY:	Collapse		TREND:	Declining
Decisionmone Scheduled Monument consistence Generally unsatisfactory with major localised problems merced vulueewattm Scrub / tree growth merce Declining SEVENOAKS Stream Montreal Park, Obelisk, Monreal Park, Riverhead Simon Goodhugh 01483 252037 SEVENOAKS Stream Montreal Park, Riverhead An CIB monument to the Canadian Wars. In need or epairs to plaques to prevent loss of histionic detail. War Memorials grant accepted March 2007. Stream Doci Contact: Judith Roebuck 01483 252048 Mine Landow Contact: Judith Roebuck 01483 252048 Mine Landow Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument concurse: Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument Contact: Judith Roebuck 01483 252048 Mine Landow Scheduled Monument Contact: Judith Roebuck 01483 252037 Mine Landow Scheduled Monument Scheduled Monument Contact: Landow Scrub / tree growth max Mine Landow Scrub / tree growth max Mine Landow <td>OWNERSHIP:</td> <td>Private</td> <td></td> <td>CONTACT:</td> <td>Simon Goodhugh 01483 252037</td>	OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
Visit major localised problems Prescret Universe Scrub / tree growth THE NO. Declining SEVENICARS Simo Goodhigh 01483 252037 Simo Goodhigh 01483 252037 SEVENICARS Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Simo Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Simo Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Document Concurse: Judith Roebuck 01483 252048 Streament D (D) Output Prevente Scheduled Monument Concurse: Scheduled Monument Sevente Scrub / tree growth Treac <td>SITE NAME:</td> <td>Binbury n</td> <td>notte and bailey castle, Thurnham</td> <td></td> <td></td>	SITE NAME:	Binbury n	notte and bailey castle, Thurnham		
Visit major localised problems Prescret Universe Scrub / tree growth THE NO. Declining SEVENICARS Simo Goodhigh 01483 252037 Simo Goodhigh 01483 252037 SEVENICARS Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Simo Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Simo Montreal Park, Biverhead An CIB monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Document Concurse: Judith Roebuck 01483 252048 Streament D (D) Output Prevente Scheduled Monument Concurse: Scheduled Monument Sevente Scrub / tree growth Treac <td>DESIGNATION:</td> <td>Scheduled</td> <td>Monument</td> <td>CONDITION</td> <td>Generally unsatisfactory</td>	DESIGNATION:	Scheduled	Monument	CONDITION	Generally unsatisfactory
Penchasukukanan Scrub / tree growth menc Declining Connects Simon Goodhugh 01483 252037 SEVENOAKS Montreal Park Obelisk, Riverhead An C18 monument to the Canadian Wars. In need of registre to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Poor Connects An C18 monument to the Canadian Wars. In need of registre to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevence Poor Connects Contact: Judith Roebuck 01483 252048 Stream D (D) Contact: Judith Roebuck 01483 252048 Stream Chapel, Maplescombe, West Kingsdown Contact: Judith Roebuck 01483 252037 Descurrence Scrub / tree growth mence Declining Stream Scrub / tree growth mence Declining Stream Scrub / tree growth mence Declining Stream Stream Stream Declining Stream Swaylands, Penshurst Simon Goodhugh 01483 252037 Stream Registered Park and Garden Grade II, also 2 LBS Simon Goodhugh 01483 252037 Stream Registered Park and Garden Grade II, also 12 LBS<		Schedulet		CONDITION.	
OWNERSIDE Private Counset Simon Goodhugh 01483 252037 SEVENOAKS STENME Montreal Park, Montreal Park, Montreal Park, Montreal Park, Riverhead An C18 monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. SEVENOAKS Descoursow Scheduled Monument countrols Countrols An C18 monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Sevennoe: Doc Document Countrols Contact: Judith Roebuck 01483 252048 Strenver: Chapel, Maplescombe, West Kingsdown Countrols Generally unsatisfactory with major localised problems Periode Scheduled Monument Countrols Generally unsatisfactory with major localised problems Periode Strenver: Strendy Area and pleasure growth Trende and brows Periode Swaylands, Penshurst Simon Goodhugh 01483 252037 Strenver: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure growth stafactory with major localised problems ValueRawure: High Contact: Charlotte McLean 01483 252076 Strenver: Combe Bank, Sundridge Combe Bank garden Grade II, also 17		Scrub / +n	e growth	TREND	
SEVENOAKS Site Methic Montreal Park Obelisk, Montreal Park, Riverhead An CI8 monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail, War Memorials grant accepted March 2007. Secondaria March 2007 Descurptions Scheduled Monument concorners Poor occurption Poor occurptin Poor occurption Poor occurption Poor occu					0
STEENAME Montreal Park, Montreal Park, Riverhead An C18 monument to the Canadian Wars. In need of repairs to plaques to prevent loss of historic detail. War Memonals grant accepted March 2007. Desenvences Processor Scheduled Monument covortion. Poor occurance: Not applicable meiors: D (D) overessere: Unknown Contact: Judith Roebuck 01483 252048 Strie NAME: Chapel, Maplescombe, West Kingsdown Contact: Judith Roebuck 01483 252048 Descention: Scheduled Monument Contact: Judith Roebuck 01483 252048 Stre NAME: Chapel, Maplescombe, West Kingsdown Descention: Scheduled Monument Contact: Judith Roebuck 01483 252037 Stre NAME: Scheduled Monument Contact: Judith Roebuck 01483 252037 PRINCPAL VULKERABUTY: Scrub / tree growth TEND. PRINCPAL VULKERABUTY: Scrub / tree growth TEND. Stre NAME: Swaylands, Penshurst Swaylands is important for its terraced garders and pleasure grounds, including extensive rockwork developed in the late Contact. Unknown in 2006 to convert the solution threaded in a duftion of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the strensive significant problems Stre NAME: Deteriorating <	OWNERSHIP:	Frivate		CONTACT:	
Montreal Park, Niverhead of repairs to plaques to prevent loss of historic detail. War Memorials grant accepted March 2007. Descurators: Roor occumence: Not applicable PRORITY: D (D) ownershie Unknown Contact: Judith Roebuck 01483 252048 Site NM*6: Chapel, Maplescombe, West Kingsdown Contact: Judith Roebuck 01483 252048 Descuratione Scheduled Monument contact: Judith Roebuck 01483 252048 Site NM*6: Scheduled Monument contact: Judith Roebuck 01483 252037 OWNERSHP Scheduled Monument contact: Simon Goodhugh 01483 252037 Site NM*6: Swaylands, Penshurst Simon Goodhugh 01483 252037 Site NM*6: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the latt sold to a developer Work began in 2006 for convert the sold to a developer Work began in 2006 for convert the sold to a country house. The property was recently unatargatury: VILNERABUTY: High mervo: Deteriorating extensive significant problems Site NM*8: Combe Bank, Sundridge Combe Bank's Sundridge Desconsition: Registered Park and Garden Grade II* also 17 LBs Extensive significant problems Combe Bank's Sundridge Site NM*8: Combe Bank's Sundridge Combe Bank's Sundridge Combe Bank's apple and garden Grade II* also 17 LBs	SEVENOAKS				
CONDITION: POOR OCCUPANCY: Not applicable PROMITY: O PRINCIPAL VIEWERSHER: Unknown Contact: Judith Roebuck 01483 252048 STE NAME: Chapel, Maplescombe, West Kingsdown Contact: Judith Roebuck 01483 252048 DEGRATION Schedule Monument Control (Signature) DEGRATION Schub / tree growth TREND: Declining OWNERSHER: Private Control (Signature) Signature) STE NAME: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the late (Diagounda country house. The property was recently sold to a developer Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. Contact: Charlotte McLean 01483 252076 STE NAME: Combe Bank, Sundridge OWNERSHIP: Private, multiple owners Stensive significant problems Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The partensite for develop it as a burial ground are unresolved. The gardens suffered considered bestorm the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The partensite f		SITE NAME:	Montreal Park,	of repairs to	o plaques to prevent loss of historic detail.
Image: Second and the second secon					
PRIORITY: D (D) OWNERSHER: Contact: Judith Roebuck 01483 252048 SITE NAME: Chapel, Maplescombe, West Kingsdown Contact: Judith Roebuck 01483 252048 DISIGNATION: Scheduled Monument Contact: Judith Roebuck 01483 252037 PRINCIPAL VULNERABLITY: Scrub / tree growth TREND: Declining OWNERSHER: Private Contact: Judith Roebuck 01483 252037 STE NAME: Swaylands, Penshurst Declining DESIGNATION: Registered Park and Garden Grade II, also 2 LBs Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat DESIGNATION: Generally unsatisfactory with major localised problems Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat CONDITION: Generally unsatisfactory with major localised problems Swaylands is important for its terraced gardens and pleasure grounds, including the addition of two now wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. CONTICK: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 120s and 1740s. After WW1 the estate was sold and trided up. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground thided up. The parkland became derelict after constructi					
OWNERSHIP: Unknown Contact: Judith Roebuck 01483 252048 SITE NAME: Chapel, Maplescombe, West Kingsdown CONDITION: Generally unsatisfactory with major localised problems DESIGNATION Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILTY: Scrub / tree growth TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 STE NAME: Swaylands, Penshurst Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat C19 around a country house. The property was recently sold to a developer Work began in 2006 to convert the house into 22 ag partments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. Contact: Charlotte McLean 01483 252076 Sitte NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WW1 the estate was sold and divided up. The house and gardens becoming a shonol in 1924. The parkland became derelict after construction of the 1425; recent attempts to develop it as a burial ground are unsolved. The garden suffer donside store in suffered estorm suffered suffered suffered become suffered became derelict after construction of the 1425; recent attempts to develop it as a burial ground are unsoled. The garden suffe	PICAL LAND				
SITE NAME Chapel, Maplescombe, West Kingsdown DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining OWNERSHIP: Private CONTROL Swaylands, Penshurst DISIGNATION: Registered Park and Garden Grade II, also 2 LBs Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat C19 around a country house. The property was recently sold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project thas stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Private, multiple owners Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of two private, multiple owners SITE NAME Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After developed in a subrial ground are unresolved. The gardens subred considerable storm the 1720s and 1740s. After developed in the 1720s and 1740s. After developed and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the 1720s and 1740s. After developed in the 1250 recent attempts to develop it as a brial ground are unresolved. The gardens suf			()		
Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining OWNERSHIP: Private CONTRACT: Simon Goodhugh 01483 252037 STTE NAME: Swaylands, Penshurst Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the late C19 around a country house. The property was recently sold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two rewings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. CONDITION: Deteriorating Combe Bank, Sundridge DESIGNATION: Extensive significant problems Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.		OWNERSHIP:	Unknown	Contact: Juc	dith Roebuck 01483 252048
PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Swaylands, Penshurst Swaylands, Penshurst Swaylands, including extensive rockwork developed in the lat CONTRON: SITE NAME: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat CONTRON: CONTRON: Generally unsatisfactory with major localised problems VULNERABUTY: High Deteriorating extremely vulnerable with an uncertain future. Contact: Charlotte McLean 01483 252076 SITE NAME: Combe Bank, Sundridge SITE NAME: Combe Bank, Sundridge SITE NAME: Combe Bank, Sundridge CONDITION: Registered Park and Garden Grade II*, also 17 LBs CONDITION: Extensive significant problems VULNERABUTY: High DESCINATION: Extensive significant problems VULNERABUTY: High DESCINATION: Extensive significant problems VULNERABUTY: High Deteriorating Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s	SITE NAME:	Chapel, M	aplescombe, West Kingsdown		
PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Swaylands, Penshurst Swaylands, Penshurst Swaylands, is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat C19 around a country house. The property was recently to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. CONDITION: Combe Bank, Sundridge Contact: Charlotte McLean 01483 252076 SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	DESIGNATION:	Scheduled	l Monument	CONDITION:	
OWNERSHIP: Private CONTRCT: Simon Goodhugh 01483 252037 SITE NAME: Swaylands, Penshurst Swaylands, Penshurst Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat C19 around a country house. The property was recently sold to a developer: Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The backand derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.		Causela / Au			
SITE NAME: Swaylands, Penshurst Swaylands is important for its terraced gardens and pleasure grounds, including extensive rockwork developed in the lat C19 around a country house. The property was recently sold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The parkland became derelict after construction of two the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.			ee growth		5
DESIGNATION: Registered Park and Garden Grade II, also 2 LBs grounds, including extensive rockwork developed in the lat CONDITION: Generally unsatisfactory with major localised problems sold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Private, multiple owners Combe Bank, Sundridge SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm drage in the lat C20 and need resources and specialist guidance to repair them.	OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
DESIGNATION: Registered Park and Garden Grade II, also 2 LBs C19 around a country house. The property was recently sold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Private, multiple owners Combe Bank, Sundridge SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After VWVI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	SITE NAME:	Swaylands	s, Penshurst		
CONDITION:Generally unsatisfactory with major localised problemssold to a developer. Work began in 2006 to convert the house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future.OWNERSHIP :Private, multiple ownersCombe Bank, SundridgeSITE NAME:Combe Bank, SundridgeCombe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	DESIGNATION:	Registered	l Park and Garden Grade II, also 2 LBs		
VULNERABILITY: High house into 28 apartments, including the addition of two new wings, and to restore the grounds as well. The project has stalled due to financial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Private, multiple owners Combe Bank, Sundridge SITE NAME: Combe Bank, Sundridge Combe Bank, Sundridge Designation: Registered Park and Garden Grade II*, also 17 LBs Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After VWVI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	CONDITION:	Generally (unsatisfactory with major localised problems	sold to a de	eveloper. Work began in 2006 to convert the
TREND: Deteriorating how Wings, and to Fisancial difficulties leaving this landscape extremely vulnerable with an uncertain future. OWNERSHIP: Private, multiple owners contact: Charlotte McLean 01483 252076 SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.			, , , , , , , , , , , , , , , , , , , ,		
OWNERSHIP: Private, multiple owners extremely vulnerable with an uncertain future. SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.		-	ting		
SITE NAME: Combe Bank, Sundridge Combe Bank's gardens and pleasure grounds date from the 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.			-		
DESIGNATION:Registered Park and Garden Grade II*, also 17 LBsthe 1720s and 1740s. After WWI the estate was sold and divided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	Conclose .	i i ivace, i ii		Contact: Ch	narlotte McLean 01483 252076
DESIGNATION:Registered Park and Garden Grade II*, also 17 LBsdivided up. The house and gardens becoming a school in 1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.	SITE NAME:	Combe B	ank, Sundridge		
CONDITION:Extensive significant problems1924. The parkland became derelict after construction of the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them.		Registeres	Park and Garden Grade II* also 17 De		
VULNERABILITY: High the M25; recent attempts to develop it as a burial ground are unresolved. The gardens suffered considerable storm damage in the late C20 and need resources and specialist guidance to repair them. OWNERSHIP: Mixed, multiple owners guidance to repair them.		0			
TREND: Deteriorating damage in the late C20 and need resources and specialist OWNERSHIP: Mixed, multiple owners guidance to repair them.			significant problems	the M25; re	cent attempts to develop it as a burial ground
OWNERSHIP : Mixed, multiple owners guidance to repair them.		-		are unresoly	ved. The gardens suffered considerable storm
	TREND:		0		
Contact: Charlotte McLean 01483 252076	OWNERSHIP :	Mixed, mi	litiple owners	guidarice (O	
				Contact: Ch	narlotte McLean 01483 252076

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / SHEPWAY **SHEPWAY** A very good example of a Martello tower. Situated in Martello Tower No.5, SITE NAME: Folkestone the grounds of a school and vacant but with potential for re-use by the school. The preservation of archaeological and historical significance will be the main consideration DESIGNATION: Scheduled Monument in assessing the suitability of proposals to convert Martello towers for residential use. CONDITION: Fair OCCUPANCY: Vacant E (E) OWNERSHIP: Local authority Contact: Judith Roebuck 01483 252048 Martello Tower No.4, A good example of a Martello tower built 1806. SITE NAME: Derelict and situated in the grounds of a private house. The Leas. The preservation of archaeological and historical Folkestone significance will be the main consideration in assessing DESIGNATION: Scheduled Monument, CA the suitability of proposals to convert Martello towers CONDITION: Very bad for residential use. OCCUPANCY: Vacant C(C)PRIORITY: Contact: Judith Roebuck 01483 252048 Private OWNERSHIP: SITE NAME: Martello Towers Nos. 6 and 7, Martello towers, 1806. Derelict recently sold by Ministry Shorncliffe Camp, Of Defence to private owner. (Photograph shows tower 6). The preservation of archaeological and historical significance Folkestone will be the main consideration in assessing the suitability of proposals to convert Martello towers for residential DESIGNATION: Listed Building Grade II, SM CONDITION POOR or other use. OCCUPANCY: Vacant PRIORITY: C(C)OWNERSHIP: Private Contact: Judith Roebuck 01483 252048 Martello Tower No.9, Martello tower, 1806. Derelict, disposed by Ministry Of SITE NAME: Defence to private owner. The preservation of archaeological Shorncliffe Camp, and historical significance will be the main consideration in Sandgate, Folkestone assessing the suitability of proposals to convert Martello DESIGNATION: Listed Building Grade II, SM towers for residential use. CONDITION: Very bad OCCUPANCY: Vacant C (C) OWNERSHIP: Private Contact: Judith Roebuck 01483 252048 Dymchurch Redoubt, An early CI9 fortification built as part of the Martello SITE NAME: system. Located on Ministry of Defence, parts have recently Hythe Ranges, been brought back into use. Deterioration in parts of Hythe brickwork and to later additions. Some repairs to rainwater DESIGNATION: Scheduled Monument goods and renewal of asphalt have been carried out. CONDITION: Poor A conservation plan has been completed. OCCUPANCY: Part occupied PRIORITY: D (D) ownership: Government Contact: Alan Johnson 020 7973 3174 (east) grant aided

SITE NAME:	Barns at Westenhanger Castle, Stone Street, Westenhanger, Stanford	Service buildings to castle. Circa 1600. Main barn had a failing temporary roof. Repairs, g by English Heritage, are well advanced.
DESIGNATION	: Listed Building Grade I, SM	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	F (F)	
OWNERSHIP:	Private	Contact: Peter Kendall 01483 252038

SITE NAME:	Romano-British building	south of Burch's Rough,	Lympne		
DESIGNATION:	Scheduled Monument		CONDITION:	Extensive significa	ant problems
				i.e. under plough,	collapse
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh	ח 01483 252037
PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.	C Slow decay, no solution agreed. D Slow decay, solution agreed but not yet implemented.	but no user of vacancy	ir or in fair to good repair, identified; or under threat with no obvious new user only to buildings capable l use).	F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Motte an	d Bailey Castle 200m north west of S	Stowting Churcl	h, Stowting
DESIGNATION:	Scheduled	d Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	animal burrowing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barı	row I50m north east of Red House I	Farm, Swingfield	
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barı	row at Minnis Beeches, Swingfield		
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
7KINCIPAL VULNEKABILITY:	Private		CONTACT:	Simon Goodhugh 01483 252037
JVVINERSHIP:	TTIVALE		CONTACT:	
SWALE				
	SITE NAME:	The ruins of Shurland Hall, Leysdown Road, Eastchurch	Gatehouse has negotia	tier house with long history of neglect. built during reign of Henry VIII. English Heritag ted with the Spitalfield Trust a rescue project n English Heritage grant was offered. Works are
STREET, STREET	DESIGNATION	: Listed Building Grade II*, SM	well advanc	ed and attention is turning to the other ruins.
	CONDITION:	-		C C
	OCCUPANCY:	Vacant		
	PRIORITY:	F (F)		
Mary Contraction	OWNERSHIP:	()	Contact: Pe	ter Kendall 01483 252038
	SITE NAME:	Medieval Stables at Abbey Farm, Abbey Fields, Faversham	Very small r of repair.	medieval farm building in a very poor state
	DESIGNATION	: Listed Building Grade II*, CA		
And a state of the state		Very bad		
and the second	OCCUPANCY:			
7	PRIORITY:	D (D)		
and the second second	OWNERSHIP:	Private	Contact: Tor	m Foxall 01483 252035
	SITE NAME:	Provender, Provender Lane, Norton	Fine mediev of substanti	val and later house, for which a programme al repairs is well underway.
	DESIGNATION	: Listed Building Grade II*		
AN DUMENT	CONDITION:	-		
THE REAL PROPERTY AND INCOME.		Occupied		
	PRIORITY:	D (D)		
and the second of the second of the second se	OWNERSHIP:	. ,	Contact: Tor	m Foxall 01483 252035
and the second second				
	SITE NAME:	Former Medway Ports Authority Offices (Dockyard House), Sheerness Docks, Sheerness	House, 1830	D. Vacant with a growing maintenance problem
		Offices (Dockyard House),	House, 1830). Vacant with a growing maintenance problem
		Offices (Dockyard House), Sheerness Docks, Sheerness Listed Building Grade II*, CA	House, 1830). Vacant with a growing maintenance problem
	DESIGNATION	Offices (Dockyard House), Sheerness Docks, Sheerness Listed Building Grade II*, CA Fair	House, 1830). Vacant with a growing maintenance problem
	DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	Offices (Dockyard House), Sheerness Docks, Sheerness Listed Building Grade II*, CA Fair	House, 1830	D. Vacant with a growing maintenance problem

	SITE NAME:	Coach Houses, Naval Terrace, Sheerness Docks, Sheerness	Coach houses ancillary to Nos I-8 Naval Terrace. 1830. Some are now restored, but others continue to suffer from a lack of repairs and maintenance.
	DESIGNATION	Listed Building Grade II*, CA	
	CONDITION:	Very bad	
States and States and	OCCUPANCY	Part occupied	
And the second second second	PRIORITY:	B (A)	
	OWNERSHIP:	Private	Contact: Tom Foxall 01483 252035
and the second second	SITE NAME:	I-15 (consec) Regency Close, Sheerness Docks, Sheerness	Row of houses built 1830. Largely vacant.
	DESIGNATION	: Listed Building Grade II*, CA	
	CONDITION:	Fair	
and the second se	OCCUPANCY	Part occupied	
	PRIORITY:	С (С)	
	OWNERSHIP:	Company	Contact: Tom Foxall 01483 252035
	SITE NAME:	Former Royal Dockyard Church and attached wall and railings, Sheerness Dockyard, Sheerness	Former St Paul's Parish Dockyard Church. Built originally in 1828, Architect George Taylor, but destroyed by fire and rebuilt in 1884 incorporating the old clock tower. Empty since 1970 and damaged by fire in 2001,
		N: Listed Building Grade II*, CA	now scaffolded. Consent received for conversion
		Very bad	to apartments.
	OCCUPANCY		
	PRIORITY:	B (C)	
	OWNERSHIP:	Private	Contact: Tom Foxall 01483 252035
1	SITE NAME:	The Boat Store (No.78), Sheerness Dockyard, Sheerness	Boat store. Built 1859. Since the destruction of the Crystal Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and
		Sheerness Dockyard,	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with
		Sheerness Dockyard, Sheerness A: Listed Building Grade I	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and
	DESIGNATION CONDITION:	Sheerness Dockyard, Sheerness A: Listed Building Grade I	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with
	DESIGNATION CONDITION:	Sheerness Dockyard, Sheerness & Listed Building Grade I Fair	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with
	DESIGNATION CONDITION: OCCUPANCY PRIORITY:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with
	DESIGNATION CONDITION: OCCUPANCY PRIORITY:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C)	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing.
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard,	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II*	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II*	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied	Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C)	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375-1550; only the southern chapel remains. The rest
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C) Company Murston Old Church,	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP:	Sheerness Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C) Company	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375-1550; only the southern chapel remains. The rest
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, C (C) Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C) Company Murston Old Church, Sittingbourne Scheduled Monument Poor	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375-1550; only the southern chapel remains. The rest
	DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION: OCCUPANCY PRIORITY: OWNERSHIP: SITE NAME:	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, C (C) Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C) Company Murston Old Church, Sittingbourne Scheduled Monument Poor	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375-1550; only the southern chapel remains. The rest
	DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME DESIGNATION OCCUPANCY PRIORITY: OWNERSHIP SITE NAME SITE NAME	Sheerness Dockyard, Sheerness Listed Building Grade I Fair Part occupied C (C) Company Former Working Mast House, 26 Jetty Road, Sheerness Dockyard, Sheerness Listed Building Grade II* Poor Part occupied C (C) Company Murston Old Church, Sittingbourne Scheduled Monument Poor Vacant A (A)	 Palace and the first South Kensington Museum this is the earliest surviving example of a multi-storey iron-frame and panel structure. In minor use for storage. Discussions with Local Planning Authority and port company continuing. Contact: Tom Foxall 01483 252035 Large C19 industrial building. Contact: Tom Foxall 01483 252035 Originally a large church with three aisles and three chancels with a square tower and wooden turret, built between 1375-1550; only the southern chapel remains. The rest

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

				HERITAGE AT RISK 2009 / SWALE / THANET
	SITE NAME:	51 High Street, Sittingbourne	A Regency suffering frc Potentially f	front to a probable C18 house.Vacant and m vandalism and a lack of maintenance. for sale.
	DESIGNATION	: Listed Building Grade II*, CA		
	CONDITION:			
1222	OCCUPANCY:			
	PRIORITY:	D (New)		
	OWNERSHIP:	Company	Contact: Ioi	m Foxall 01483 252035
A	SITE NAME:	Sheerness Defences, Swale		illery fortifications from C17-C20. mplex defending the dockyard.
	DESIGNATION	: Scheduled Monument, CA		
ALL AND ALL AN		Very bad		
		Not applicable		
and a state of the	PRIORITY:	C (C) Company	Contact: Po	ter Kendall 01483 252038
The second se	OWNERSHIP:	Company	Contact: re	ter Kendali 01463 232036
THANET				
A .	SITE NAME:	The Shell Grotto, Grotto Hill, Margate		rotto. Extensive shell designs to walls and ceilings, nich are loose or have detached completely.
A COMPANY AND INCOME		: Listed Building Grade I		
意味の問題的	CONDITION:			
		Not applicable		
and the second sec	PRIORITY: OWNERSHIP:	D (C) Private	Contact [.] To	m Foxall 01483 252035
	Ovviveligi III .	Thvate	Contact. Ior	
	SITE NAME:	Dreamland Cinema, Marine Terrace, Margate	on the Titar	35.The first English cinema in the style based nia Palast of Berlin; a style subsequently used by Odeon.Vacant and with a backlog of repairs.
- Eller		: Listed Building Grade II*		
	CONDITION:			
A DESCRIPTION OF THE OWNER OWNER OF THE OWNER	OCCUPANCY: PRIORITY:	C (New)		
Antoine State Sector of the	-	Company	Contact: Tor	m Foxall 01483 252035
		1 /		
	SITE NAME:	Barn about 50m east of Ozengell Grange, Haine Road, Ramsgate		e medieval grain barn, on land formerly ot Augustine's Abbey, Canterbury.
		E Listed Building Grade II*		
		Very bad		
	OCCUPANCY: PRIORITY:	C (C)		
	OWNERSHIP:		Contact: Tor	m Foxall 01483 252035
SITE NAME:	Ring ditch	nes and enclosures 500yds (450m) I	ESE of College Fa	ırm, Acol
DESIGNATION:				
	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo		CONDITION: TREND:	i.e. under plough, collapse Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:				i.e. under plough, collapse
	Arable plo Private		TREND: CONTACT:	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
OWNERSHIP:	Arable plo Private Group of	oughing	TREND: CONTACT:	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
OWNERSHIP:	Arable plo Private Group of	oughing ring ditches 400yds (360m) north	TREND: CONTACT: west of Great Br	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 ooks End Farm, Birchington
OWNERSHIP:	Arable plo Private Group of	oughing Tring ditches 400yds (360m) north d Monument	TREND: CONTACT: west of Great Br	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 ooks End Farm, Birchington Extensive significant problems

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / THANET / TONBRIDGE AND MALLING

SITE NAME:	Anglo-Saxon cemetery, Dane Valley F	Road, Broadstairs and St	Peters
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Double ring ditch and two enclosure	es 400yds (360m) north	west of Danes Court, Broadstairs and St F
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Anglo-Saxon cemetery south of Oze	engell Grange, Margate a	nd Ramsgate
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Quex Park settlements, Margate and	Ramsgate	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
site name:	Settlement one mile (1610m) east o	f village, Margate and Rar	nsgate
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Enclosure and ring ditches 200yds (1	80m) ENE of Minster La	uundry, Minster
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
TONBRIDGE AND	MALLING		
	SITE NAME: Hadlow Tower,	Tower of a	n otherwise demolished late C18/early C19

Tower of an otherwise demolished late C18/early C19 country house. The service buildings around base have Hadlow Tower, SITE NAME: High Street, been converted into housing. Hadlow DESIGNATION: Listed Building Grade I, CA CONDITION: Poor OCCUPANCY: Occupied C (C) PRIORITY: OWNERSHIP: Private Contact: Tom Foxall 01483 252035

DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse	SITE NAME:	Romano-British villa, Anglo-Saxon cemete	ery and associated re	emains at Eccles, Aylesford
i.e. under plough, collapse	DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining	'RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037	OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

В D Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

С Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Е

SITE NAME:	Chapel of St Blaise, Offham		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Town banks, Tonbridge		
SITE NAME: DESIGNATION:	Town banks, Tonbridge Scheduled Monument	CONDITION:	Generally unsatisfactory
		CONDITION:	Generally unsatisfactory with major localised problems
		CONDITION: TREND:	, , , ,

TUNBRIDGE WELLS

10	1		1	SITE NAME:	Provid Stone Cranbi
1 8		885	-	DESIGNATION:	Listed
100				CONDITION:	Poor
11	15			OCCUPANCY:	Vacant
	1000			PRIORITY:	C(C)
			1	OWNERSHIP:	Private

 NAME:
 Providence Chapel, Stone Street, Cranbrook
 Strict Baptist chapel. 1795 with early to mid C19 alterations.

 IGNATION:
 Listed Building Grade II*, CA

 NDITION:
 Poor

 CUPANCY:
 Vacant

 V C (C)

 NERSHIP:
 Private

 Contact: Tom Foxall 01483 252035

	GwinerGriff. Trivate	Contact. Ior	
SITE NAME:	High Rocks Camp,Tunbridge Wells	(part in East Sussex)	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Somerhill, Capel	Somerhill is	an early CI9 terraced garden probably laid out

SITE NAME:	Somerhill, Capel	Somerhill is an early C19 terraced garden probably laid out by William Sawrey Gilpin with surrounding, later C19, ornamental
DESIGNATION: CONDITION:	Registered Park and Garden Grade II, also 4	LBs gardens, all set within parkland. The site is now divided
	Extensive significant problems	between a school, an estate and several smaller, private
VULNERABILITY:	Medium	owners all operating diverse management regimes which compromise the designed landscape's integrity. The school's
TREND:	Unknown	conservation plan for the gardens could form the basis for
OWNERSHIP :	Mixed, multiple owners	an approach to a strategy for the whole site.
		Contact: Charlotte McLean 01483 252076
SITE NAME:	Bayham Abbey, Lamberhurst	Bayham Abbey's designed landscape comprises late C19 mansion gardens with formal terraces and informal pleasure ground all
DESIGNATION:	Registered Park and Garden Grade II,	set within a Humphry Repton park focussed on the abbey ruins.
	also 7 LBs, I SM	The property was divided and sold in the 1970s then further
		fragmented since. English Heritage looks after the abbey ruins

	also / LBs, I SM	fragmented since. English Heritage looks after the abbey ruins
CONDITION:	Extensive significant problems	but fragmentation of ownership has severely compromised this
VULNERABILITY:	Medium	significant picturesque landscape. Co-ordinated action is needed
TREND:	Deteriorating	to conserve this historic landscape. Part of the park is in East Sussex and the district of Wealden.
OWNERSHIP :	Mixed, multiple owners	Sussex and the district of Wealden.
		Contact: Charlotte McLean 01483 252076

LA Local Authority LB/LBs Listed Building/s NP National Park

OFF KENT The London was a Second Rate 'Large Ship' built in Chatham SITE NAME: London, Thames Estuary in 1654 during the Interregnum. She is known to have participated in the First Dutch War (1652-4) and later formed part of an English Squadron sent to collect Charles DESIGNATION: Protected Wreck Site Il from the Netherlands and restore him to his throne. The London blew-up on passage from Chatham in March Extensive significant problems CONDITION 1665. A series of artefacts have been identified on the river Natural decline TREND: bed and recovered to the surface. In addition an abundance OWNERSHIP-Government of loose material on the bottom has been noted in a Wessex Archaeology and the remarkably well preserved state. This suggests that the PHOTO site has been recently disturbed. Port of London Authority Contact: Simon Goodhugh 01483 252037 Wessex-Archaeology Third rate 70-gun warship built 1678 as part of Samuel Pepys' SITE NAME: Northumberland. INCOLOR INCOLS Goodwin Sands regeneration of the English navy. The first third rate ship to be built under contract, after it was realised that the naval dockyards could not cope with the construction of the number of ships DESIGNATION: Protected Wreck Site requested. She foundered on Goodwin Sands during the CONDITION: Extensive significant problems 'Great Storm' of 1703. The Goodwin Sands change morphology on a seasonal basis leading to periodic exposure of the vessel's Significant decline TREND: wooden hulls. Exposed timbers are weakened by biological OWNERSHIP-Government attack and may be subject to detachment and dispersal by © Wessex Archaeology PHOTO: tide and wave surge during winter storms. Contact: Simon Goodhugh 01483 252037 Although there is no definite evidence, this wreck of a wooden Restoration. SITE NAME: Goodwin Sands warship is thought to be the remains of the Restoration, a third rate 70-gun warship built 1678 as part of Samuel Pepys regeneration of the English navy. Along with the Northumberland DESIGNATION: Protected Wreck Site and Stirling Castle, she foundered on Goodwin Sands during the 'Great Storm' of 1703. The Goodwin Sands change morphology CONDITION: Extensive significant problems on a seasonal basis leading to periodic exposure of the vessel's Significant decline TREND: wooden hulls. Exposed timbers are weakened by biological OWNERSHIP: Government attack and may be subject to detachment and dispersal by tide © University of St Andrews and wave surge during winter storms. PHOTO: and Wessex Archaeology Contact: Simon Goodhugh 01483 252037 The VOC (Dutch East Company) ship Rooswijk was built SITE NAME: Rooswiik. in Amsterdam in 1737 but stranded on the Goodwin Sands Goodwin Sands, in 1739 while en route from the Texel to the East Indies. The site represents archaeological evidence for the practice DESIGNATION: Protected Wreck Site of large-scale overseas commerce between the Netherlands CONDITION: Generally unsatisfactory and Asia during the eighteenth century. As with other sites in the Goodwins, archaeological material is at risk owing to with major localised problems mobile sediments causing periodic exposure. Natural decline TREND: Contact: Simon Goodhugh 01483 252037 OWNERSHIP Private Stirling Castle, One of twenty, third rate 70-gun warships, built 1678 at SITE NAME: Deptford as part of Samuel Pepys' regeneration of the Goodwin Sands English navy. Like the Northumberland and the Restoration she was rebuilt at Chatham in 1699. All three ships foundered DESIGNATION: Protected Wreck Site on the Goodwin Sands during the 'Great Storm' of 1703. CONDITION: Extensive significant problems Significant decline TREND: Trust OWNERSHIP-© Seadive Contact: Simon Goodhugh 01483 252037 PHOTO: MEDWAY (UA) The Chapel of St Bartholomew, Hospital Chapel since CI2. Now vacant, SITE NAME: High Street, but potentially for sale. Chatham DESIGNATION: Listed Building Grade II*, CA CONDITION: Fair OCCUPANCY: Vacant D (D) PRIORITY: OWNERSHIP: Private Contact: Tom Foxall 01483 252035 PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

ummediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.

Slow decay; solution agreed but not yet implemented. L Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

	SITE NAME:	Cliffe Fort, Cliffe	Fort circa 1860. Fabric is derelict but stable due to massive construction. Remains of Brennan Torpedo Rail, said to be the best surviving example, are vulnerable. Surrounded by
A State of the second	DESIGNATION:	Scheduled Monument	gravel pits.
	CONDITION:		
The second line	OCCUPANCY:	,	
	PRIORITY:	C (C)	
and the second sec	OWNERSHIP:	Company	Contact: Peter Kendall 01483 252038
		. ,	
. 6	SITE NAME:	Cooling Castle, Cooling	A quadrangular castle with ruined fabric and in need of major repair. Includes CI4 gatehouse repaired with English Heritage grant.
E	DESIGNATION:	Listed Building Grade I, SM	
	CONDITION:	Very bad	
and the second second	OCCUPANCY:	Part occupied	
	PRIORITY:	A (A)	
	OWNERSHIP:	Private	Contact: Peter Kendall 01483 252038
	SITE NAME:	Barn 30 yards south east of the manor, Upnor Road (south side), Frindsbury Extra	Very fine medieval barn, more or less redundant for agricultural use. Subject to fire damage.
1.111.1.1.1	DESIGNATION:	Listed Building Grade I, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNERSHIP:	Private	Contact:Tom Foxall 01483 252035
	SITE NAME:	Brompton Lines, Gillingham	Landward defences to dockyard at Chatham, subsequently used in part as a pleasure ground for officers. Now cross
			Ministry of Defence owned land, housing and Brompton
()]]制建设()	DESIGNATION:	Scheduled Monument, CA	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner.
	DESIGNATION:	Scheduled Monument, CA	Ministry of Defence owned land, housing and Brompton
	CONDITION:	Scheduled Monument, CA	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained
	CONDITION:	Scheduled Monument, CA Poor	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained
	CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument, CA Poor Not applicable	Ministry of Defence owned land, housing and Brompton Barracks, Lower lines site now released to new owner. Discussions continue about management of retained MOD parts.
	CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument, CA Poor Not applicable D (D)	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained
	CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument, CA Poor Not applicable D (D)	Ministry of Defence owned land, housing and Brompton Barracks, Lower lines site now released to new owner. Discussions continue about management of retained MOD parts.
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet,	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860,
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860,
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860,
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION: CONDITION:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant	Ministry of Defence owned land, housing and Brompton Barracks, Lower lines site now released to new owner. Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860,
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: SITE NAME: CONDITION: OCCUPANCY:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A)	Ministry of Defence owned land, housing and Brompton Barracks, Lower lines site now released to new owner. Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860,
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: SITE NAME: CONDITION: OCCUPANCY: PRIORITY:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A)	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides.
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides.
	CONDITION: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham Listed Building Grade II*	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides. Contact: Peter Kendall 01483 252038
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham Listed Building Grade II*	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides. Contact: Peter Kendall 01483 252038
	CONDITION: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME: SITE NAME:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham Listed Building Grade II* Poor	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner: Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides. Contact: Peter Kendall 01483 252038
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: SITE NAME: CONDITION:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham Listed Building Grade II* Poor	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides. Contact: Peter Kendall 01483 252038
	CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: SITE NAME: CONDITION: CONDITION:	Scheduled Monument, CA Poor Not applicable D (D) Government Fort Darnet, Gillingham Scheduled Monument Very bad Vacant A (A) Private No. 8 Machine Shop, Dock Head Road, Chatham Dockyard, Gillingham Listed Building Grade II* Poor Vacant C (C)	Ministry of Defence owned land, housing and Brompton Barracks. Lower lines site now released to new owner. Discussions continue about management of retained MOD parts. Contact: Peter Kendall 01483 252038 A Royal Commission fort circa 1860, in the Medway Estuary, washed by high tides. Contact: Peter Kendall 01483 252038

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

Barris .	SITE NAME:	Cockham Wood Fort, Hoo St Werburgh	A rare CI7 artillery fort. The brick lower battery is decayed as it is washed by the tidal Medway. The hi earthwork batteries survive but in woodland, with t remains of a redoubt and commander's house.	gher
100 - Constant	DESIGNATION	Scheduled Monument	remains of a redoubt and commander's nouse.	
	CONDITION:	Very bad		
EA .	OCCUPANCY:	Vacant		
The state of the state of the	PRIORITY:	A (A)		
	OWNERSHIP:	· · ·	Contact: Peter Kendall 01483 252038	
	SITE NAME:	Fort Hoo, Hoo St Werburgh	Sister fort to Fort Darnet circa 1860. Fort lies aband on an island in the Medway.	Joned
	DESIGNATION	: Scheduled Monument		
THE REAL PROPERTY.	CONDITION:	Poor		
The Contest of the State	OCCUPANCY:	Vacant		
	PRIORITY:	a (a)		
the states of		Company	Contact: Peter Kendall 01483 252038	
Manager & Date & a rear way way of	Ownershir.	Company	Contact, reter Kendair of 105 252550	
-	SITE NAME:	Artillery Tower (Grain Tower), Isle of Grain	Artillery tower: Late 1840's to early 1850's. Forms pa of the defences to Sheerness dockyard. Abandoned surrounded by the sea at high tide.	
and the second second	DESIGNATION	: Listed Building Grade II, SM		
		Very bad		
State and State	OCCUPANCY:	,		
the second s	PRIORITY:	C (C)		
Concession of the local division of the loca	OWNERSHIP:		Contact: Peter Kendall 01483 252038	
	OWNERSHIP:	Trivate	Contact. Peter Kendali of 105 252050	
	SITE NAME:	Brompton Lines (Fort Amherst), Rochester	Part of the major C18 landward defence to the doc at Chatham. Open periodically to the public. Grants English Heritage and local authority have conserved	s from
The second	DESIGNATION	: Scheduled Monument, CA	part but significant areas still derelict.	
	CONDITION:	Poor		
654	OCCUPANCY:	Vacant		
Miller march	PRIORITY:	B (B)		
	OWNERSHIP:	()	Contact: Peter Kendall 01483 252038	
THEFT	SITE NAME:	351 High Street, Rochester	Early CI8 town house, last used as a shop in 1980s. Empty since then, but a programme of repairs is currently under discussion.	
	DESIGNATION	: Listed Building Grade II*, CA	·	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	CONDITION:	Poor		
INTEL SPOTTON	OCCUPANCY:	Vacant		
10001 11 2003 311	PRIORITY:	E (E)		
HAR I FRANK	OWNERSHIP:	Company	Contact:Tom Foxall 01483 252035	
Sec. 1				
The second se	SITE NAME:	Priors Gate, The Precinct,	Medieval gatehouse, 1344, forming the south entran to the precincts of the Cathedral. Signs of structura	ce I
The second second		Rochester	movement. Recording undertaken.	1
AA. STAR				
		Listed Building Grade I, SM, CA		
	CONDITION:			
Spe	OCCUPANCY:			
A PARTY AND A	PRIORITY:	C (C)		
11 100	OWNERSHIP:	Trust	Contact: Peter Kendall 01483 252038	
MILTON KEYNES (UA	۹)			
SITE NAME:	Roman to	own of Magiovinium and Roman fort,	Bletchley and Fenny Stratford	
DESIGNATION:	Scheduled	Monument	CONDITION: Extensive significant problems	
			i.e. under plough, collapse	

			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Wood Farm moat, Clifton Reynes		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	St Martin's Church (site of), Emberton		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Roman villa 300m south east of Newton	Lodge Farm, Newto	n Blossomville
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Roman site at Olney, Olney		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME: DESIGNATION:	Group of ring ditches and enclosures at Scheduled Monument	Tyringham, Tyringham condition:	and Filgrave Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	i.e. under plough, collapse Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
OXFORDSHIRE		CONIACI.	
CHERWELL			
M	SITE NAME: Hampton Gay Manor House, Hampton Gay, Hampton Gay and Poyle DESIGNATION: Listed Building Grade II, SM CONDITION: Very bad	Manor hou Now a roo	se, late C16. Burnt down in 1887. fless ruin.
	occupancy: Not applicable		
	PRIORITY: A (A)		
Style and and The	ownership: Private	Contact: Cl	nris Welch 01483 252027
		Contact of	
SITE NAME:	llbury Camp hillfort, Deddington		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Islip Roman villa, 300m east of Hillside Fa	ırm, İslip	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
		condition.	

DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s Unitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / CHERWELL / OXFORD / SOUTH OXFORDSHIRE

site name:	RAF Bicester: World War II airfield, Laughton		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Government or Agency	CONTACT:	Simon Goodhugh 01483 252037
OXFORD			

ES?	SITE NAME:	Osney Abbey, Mill Street, Oxford	Only surviving building of Augustinian Priory, founded 1129. Rubble and timber framed building, probably C15, with C16 roof. Attached wall with C15 archway. Currently included in discussions over the wider Osney Mill site.
the state of the s	DESIGNATION	: Listed Building Grade II, SM	
Contraction of the local division of the loc	CONDITION:	Fair	
	OCCUPANCY	Part occupied	
	PRIORITY:	С (С)	
	OWNERSHIP:	Company	Contact: Chris Welch 01483 252027

site name:	Seacourt medieval settlement 760m west of Manor Farm, Binsey, Oxford		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Swing bridge, LNWR Station, Oxford	d	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Local Authority	CONTACT:	Simon Goodhugh 01483 252037

SOUTH OXFORDSHIRE

-		Bix Old Church, Bix, Bix and Assendon	Ruins of church of St James. Norman chancel with later additions. Very overgrown. Roofless, with considerable collapse at west end. Further collapse likely. English Heritage management agreement with PCC for limited landscape
æ	DESIGNATION:	Listed Building Grade II, SM	maintenance (expired 2001).
	CONDITION: Very bad	Very bad	
	OCCUPANCY:	Not applicable	
	PRIORITY:	A (A)	
58	OWNERSHIP:	Religious organisation	Contact: Chris Welch 01483 252027

SITE NAME:	Gothic Temple, Shotover Park, Forest Hill with Shotover	The Gothic Temple within the Grade I Shotover Park was designed as a garden temple or boathouse c1740, by William Townsend of Oxford (?) for General James Tyrrell
DESIGNATION	Listed Building Grade II*, RPG Grade I	in Gothick style. The temple lies at the eastern end of the main axis of the early CI8 layout of the formal garden.
CONDITION:	Poor	Front repaired 10 years ago but rear structure in need
OCCUPANCY:	Not applicable	of repairs to roof and rainwater goods. Conservation
PRIORITY:	С (С)	Mngt Plan underway – 2009.
OWNERSHIP:	Private	Contact: Kathryn Davies 01483 252028



SITE NAME: Walled garden approx 30m west of manor, North Weston, Great Haseley DESIGNATION: Listed Building Grade II* CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: A (New) OWNERSHIP: Private

Walled garden with loggia dating from early CI8. Built of brick with limestone ashlar details and a plain tile roof to the loggia. The wall has a moulded brick coping. It was formerly part of the North Weston Manor which was largely demolished in early CI9. The wall tops are disintegrating; there are structural cracks and the loggia is propped to prevent collapse.

Contact: Kathryn Davies 01483 252028

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

rapid Immediate ris bric; deterioration

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C

Slow decay; no solution agreed. D Slow decay; solution agreed but not yet implemented. L Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

	gatewa The St	ouse, archway, ay and walls, treet, Mapledurham	The fernho	archway, gateway and walls. C17 and C18. use is roofless, although recent consolidation lace to the parapet.
	designation: Listed	Building Grade II*, CA		
ANN	condition: Poor	3		
	OCCUPANCY: Vacant			
	PRIORITY: C (C)			
(III) III / Are and Maderal	ownership: Private		Contact: Ka	thryn Davies 01483 252028
	OWNERSHIP: FTIVale		Contact. Na	un yn Davies 01463 232026
SITE NAME:	North Stoke henge and ring ditch site, Crowmarsh			
DESIGNATION:	Scheduled Monur	ment	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Dike Hills, Dorch	nester		
	Scheduled Monur	mont		Extensive significant problems
DESIGNATION:	Scheduled Monul	nent	CONDITION:	0
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Extensive animal	burrowing	TREND:	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Ring ditches, cursus, enclosures and settlement site, Dorchester			
DESIGNATION:	Scheduled Monur	ment	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
	Sottlomont site a	t Northfield Farm, Long W	littophom	
SITE NAME:		-		
DESIGNATION:	Scheduled Monur	nent	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Site of Roman ki	Ins, Marsh Baldon		
DESIGNATION:	Scheduled Monu	ment	CONDITION:	Generally satisfactory but with
				significant localised problems
RINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Stable
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Church Piece ce	metery site, Warborough		
DESIGNATION:	Scheduled Monu	ment	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing		TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	Long barrow 140	m north west of Cooks Co	ottages, Warborou	gh
	Scheduled Monur	ment	CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Fiolidi			ie under plauch collapse
				i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private		TREND: CONTACT:	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / SOUTH OXFORDSHIRE / VALE OF WHITE HORSE

SITE NAME:	Long barrow 340m north west of Cooks Cottages, Warborough				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Romano-British settlement 520m no	orth west of Cooks Cott	ages, Warborough		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Thomley deserted medieval village, V	Vaterperry with Thomley	/		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Camp on Bozedown,Whitchurch or	Thames			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
VALE OF WHITE H					
	Sutton Wick settlement site, Abingd	on			
	-				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:			
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Settlement site south east of church	, Appleford-on-Thames			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Settlement site, Drayton				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	East Hendred Down bowl barrow, E	ast Hendred			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
	Arable plaughing	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	IREND:	Decining		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

HERITAGE AT RISK 2009 / VALE OF WHITE HORSE / WEST OXFORDSHIRE

SITE NAME:	Wyke monastic grange and section o	f 18th century turnpike roa	ad, 780m south of Tudor Farm, Great Farin		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
	Private	CONTACT:	Simon Goodhugh 01483 252037		
DWNERSHIP:	I TIVALC	CONTACT:			
SITE NAME:	Yew Down round barrow 950m sou	ith west of Butterbush Re	eservoir, Lockinge		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
ITE NAME:	Settlement site north of Cow Lane,	Marcham			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Settlement site east of Goose Acre	Farm, Radley			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
	Arable ploughing		Declining		
PRINCIPAL VULNERABILITY:	Private	TREND:	Simon Goodhugh 01483 252037		
OWNERSHIP:	I IIVale	CONTACT:			
SITE NAME:	Disc barrow 700m north east of Se	venbarrows House: part o	of the Seven Barrows cemetery, Sparsholt		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
ITE NAME:	Roman villa east of Cornhill Farm,V	Vest Challow			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
WEST OXFORDSH	IIRE				
SITE NAME:	Iron Age settlement centring 500m south west of Black Bourton, Alvescot				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Asthall Barrow: an Anglo-Saxon buri	al mound 100m SSW of B	Barrow Farm, Asthal		
	Scheduled Monument	CONDITION:	Generally unsatisfactory		
DESIGNATION		CONDITION:			
DESIGNATION:			with major localised brodiems		
DESIGNATION: PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	with major localised problems Declining		

Area LA ge LB/LE ery Fund NP

LA LB/LBs NP Local Authority Listed Building/s National Park

HERITAGE AT RISK 2009 / WEST OXFORDSHIRE

	Pair of confluent bowl barrows 200m	SSW of Bockett's Corr	er on Leigh Hale Plain, Asthal	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems	
			i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037	
ITE NAME:	Ring ditches, Aston, Cote, Shifford and	I Chimney		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems	
			i.e. under plough, collapse	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037	
ITE NAME:	Interrupted ditch system, Broadwell			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems	
			i.e. under plough, collapse	
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037	
SITE NAME:	Bowl barrow 525m north of Barter's	Hill Farm, Chadlington		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems	
		Contonion	i.e. under plough, collapse	
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037	
	Besbury Lane bowl barrow, 450m north east of Conduit Farm, Churchill			
SITE NAME:	besbury Lane bowl barrow, 450m nor	th east of Conduit Farr	n, Churchill	
	Scheduled Monument	th east of Conduit Farr		
	-		Generally unsatisfactory	
DESIGNATION:	Scheduled Monument		Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY:	-	CONDITION:	Generally unsatisfactory with major localised problems Declining	
SITE NAME: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Scheduled Monument Extensive animal burrowing	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037	
DESIGNATION: PRINCIPAL VULNERABILITY: DWINERSHIP: SITE NAME:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m	CONDITION: TREND: CONTACT: north west of High Loc	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037	
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Scheduled Monument Extensive animal burrowing Private	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems	
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME: DESIGNATION:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument	CONDITION: TREND: CONTACT: north west of High Loc	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: GITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m	CONDITION: TREND: CONTACT: north west of High Loc CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing	CONDITION: TREND: CONTACT: north west of High Loo CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037	
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: DWN	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT: north west of High Loo CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037	
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME: ITE NAME:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m	CONDITION: TREND: CONTACT: north west of High Loo CONDITION: TREND: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: SITE NAME: DESIGNATION:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m	CONDITION: TREND: CONTACT: north west of High Loo CONDITION: TREND: CONTACT: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument	CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: STTE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing	CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: DWNERSHIP:	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 sham	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: DES	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument	CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 sham Extensive significant problems i.e. under plough, collapse	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: PRINCIPAL VULNERABILITY: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: DES	Scheduled Monument Extensive animal burrowing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private One of a pair of bowl barrows 370m Scheduled Monument Arable ploughing Private Scheduled Monument Sites discovered by aerial photography	CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 dge, Cornbury and Wychwood Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 sham	

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Oaklands Farm Roman villa, Fawler		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Linear earthworks east of Callow Hill Rom	man villa forming part o	of the north Oxfordshire Grim's Ditch, Glympto
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Ring ditches, Grafton and Radcot		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Beaconsfield Farm Roman villa, Great Te	2W	
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITY: OWNERSHIP:	Arable ploughing Private	TREND: CONTACT:	Declining Simon Goodhugh 01483 252037
		CONTACT:	Simon Goodhugh 01483 252037
OWNERSHIP: SITE NAME:	Private 145m section of the north Oxfordshire Kiddington with Asterleigh	CONTACT: Grim's Ditch situated	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm,
OWNERSHIP:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing	CONTACT: Grim's Ditch situated	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument	CONTACT: Grim's Ditch situated CONDITION:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037
OWNERSHIP: SITE NAME: DESIGNATION:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wit	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 h Asterleigh Generally unsatisfactory
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wit	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 hAsterleigh Generally unsatisfactory with major localised problems
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: OWNERSHIP:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wit CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 hAsterleigh Generally unsatisfactory with major localised problems Declining
OWNERSHIP: STE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: STE NAME: PRINCIPAL VULNERABILITY: OWNERSHIP: STE NAME:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wit CONDITION: TREND: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 hAsterleigh Generally unsatisfactory with major localised problems Declining
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION:	Private 145m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Pump Copse earthwork, Kiddington with	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wit rleigh, CONDITION: TREND: CONTACT: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 Asterleigh Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Pump Copse earthwork, Kiddington with Scheduled Monument	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington witt CONDITION: TREND: CONTACT: CONTACT: CONTACT:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 Asterleigh Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: OWNERSHIP: OWNERSHIP:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Pump Copse earthwork, Kiddington with Scheduled Monument Arable ploughing	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wite CONDITION: trenD: CONDITION: CONDITION:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 h Asterleigh Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION: SITE NAME: SITE NAME: SITE NAME:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Pump Copse earthwork, Kiddington with Scheduled Monument Arable ploughing Private	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: rleigh, Kiddington wite CONDITION: trenD: CONDITION: CONDITION:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 Asterleigh Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Extensive significant problems
OWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME: DESIGNATION:	Private I45m section of the north Oxfordshire Kiddington with Asterleigh Scheduled Monument Arable ploughing Private Medieval settlement and church of Aster Scheduled Monument Arable ploughing Private Pump Copse earthwork, Kiddington with Scheduled Monument Arable ploughing Private Enclosures and trackways, Langford	CONTACT: Grim's Ditch situated CONDITION: TREND: CONTACT: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION:	Simon Goodhugh 01483 252037 200m west of Grimsdyke Farm, Extensive significant problems i.e. under plough, collapse Stable Simon Goodhugh 01483 252037 Asterleigh Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / WEST OXFORDSHIRE

SITE NAME:	Site of 19th century pottery factory north west of Leafield, Leafield				
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
ITE NAME:	Rectangular enclosures 1100yds (1010	0m) north west of Mour	nt Owen Farm, Lew		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
	Scheddied Fiondment	CONDITION.	i.e. under plough, collapse		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
ITE NAME:	Enclosures I500m south east of Little	e Faringdon. Little Faring	don		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
	Arable ploughing		i.e. under plough, collapse Declining		
PRINCIPAL VULNERABILITY:	Private	TREND: CONTACT:	Simon Goodhugh 01483 252037		
2001 NETAFIF.	TTVate	CONTACT:			
SITE NAME:	Settlement 700m north east of Lechl	ade, Little Faringdon			
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems		
			i.e. under plough, collapse		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
DWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Skew Plantation bowl barrow, Sarsde	n			
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory		
		CONDITION.	with major localised problems		
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037		
SITE NAME:	Bowl barrow 270m east of Spelsbury	down Farm barns, Spels	bury		
	Bowl barrow 270m east of Spelsbury Scheduled Monument	rdown Farm barns, Spels	Extensive significant problems		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument Arable ploughing	CONDITION: TREND:	Extensive significant problems i.e. under plough, collapse Declining		
DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse		
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME:	Scheduled Monument Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037		
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME:	Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037		
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: DITE NAME: DESIGNATION:	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spels	CONDITION: TREND: CONTACT: sburydown Farm barns,	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems		
DESIGNATION: RINCIPAL VULNERABILITY: DWNERSHIP: ITE NAME: DESIGNATION: RINCIPAL VULNERABILITY:	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spels Scheduled Monument	CONDITION: TREND: CONTACT: sburydown Farm barns, CONDITION:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems i.e. under plough, collapse		
DESIGNATION: PRINCIPAL VULNERABILITY: DWINERSHIP:	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spel: Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT: sburydown Farm barns, CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems i.e. under plough, collapse Declining		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: D	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spels Scheduled Monument Arable ploughing Private Ditchley Park Roman villa and part o	CONDITION: TREND: CONTACT: sburydown Farm barns, CONDITION: TREND: CONTACT: f an associated field syst	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 em 450m ENE of Lodge Farm, Spelsbury		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: D	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spel: Scheduled Monument Arable ploughing Private	CONDITION: TREND: CONTACT: sburydown Farm barns, CONDITION: TREND: CONTACT:	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 em 450m ENE of Lodge Farm, Spelsbury Extensive significant problems		
DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: DWNERSHIP:	Scheduled Monument Arable ploughing Private Bowl barrow 80m south east of Spels Scheduled Monument Arable ploughing Private Ditchley Park Roman villa and part o	CONDITION: TREND: CONTACT: sburydown Farm barns, CONDITION: TREND: CONTACT: f an associated field syst	Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 Spelsbury Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 em 450m ENE of Lodge Farm, Spelsbury		

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	on the D	itchley Estate, Spelsbury	tch running into t	the northern edge of Shilcott Wood
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable pl	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Complex	of rectangular enclosures, ring dite	ches and tracks, S	tandlake
DESIGNATION:		d Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
RINCIPAL VULNERABILITY:	Arable pl	ougning	TREND:	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Callow H	lill Roman villa, Stonesfield		
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable pl	oughing	TREND	Declining
	Private	ougning	TREND:	8
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	90m sect	ion of the north Oxfordshire Grim	n's Ditch 350m sc	outh of Grim's Dyke Farm,Wootton
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable pl	oughing	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
PORTSMOUTH, CITY	′ OF (UA))		
	SITE NAME:	The Beneficial School, Kent Street, Portsea	Charity school, 1784 and 1836. Now empty and seek a new use.	
- 0-		Listed Building Grade II*, CA		
	CONDITION:	•		
	OCCUPANCY			
- 승규는 비				
3	PRIORITY:	C (New)	Country at D	
	OWNERSHIP:	Local authority	Contact: D	avid Brock 01483 252044
P-1	SITE NAME:	Fort Southwick, moat and ramparts, Portsdown Hill, Portsmouth	Fort circa 1860s. Part of Palmerston's Portsmouth defen In poor condition in parts. Fort is now in private owner following disposal by Defence Estate, and has benefited from a recent programme of repair and consolidation.	
States of the owner of the owner	DESIGNATION	: Listed Building Grade I, SM		
and the second s	CONDITION:	Fair		
A Holes	OCCUPANCY	Part occupied		
A Martin and a state	PRIORITY:	F (F)		
a summer	OWNERSHIP:		Contact: Richard Massey 01483 252046	
	SITE NAME:	Fort Cumberland,	Coastal for	t of 1746-1812 with later buildings and features
12	L. L. F. W. H. La	Fort Cumberland Road, Eastney, Portsmouth	Some repairs have been carried out, and the numbe buildings being used by the Centre for Archaeology a	
15 marth	DESIGNATION	Listed Building Grade II*, SM		increased. The Guardhouse, a stand alone
ALCORDON STORE	CONDITION:	_		vith the Fort Cumberland complex and the ing element of the 1747 Demaretz Fort,
THE REAL PROPERTY OF		Part occupied		from water ingress and associated decay.
1 2	OCCUPANCY		is suffering from water ingress and associated de	
014312				
Q123	OCCUPANCY PRIORITY: OWNERSHIP:	F (F) English Heritage	Contact: D:	chard Massey 01483 252046

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / PORTSMOUTH, CITY OF (UA)

1 Same	SITE NAME:	Hilsea Lines – Bastion No. 5, Hilsea, Portsmouth	Earthwork defence dating from 1858-1869, with batteries, magazines and barracks. Bastion No 5 is continuing to suffer from vandalism and neglect.
a state of the sta	DESIGNATION	: Scheduled Monument, CA	
L. Martin and State	CONDITION:	Poor	
14 (14) (16(K3)) (1	OCCUPANCY:	Not applicable	
and a second	PRIORITY:	A (A)	
		Local authority	Contact: Richard Massey 01483 252046
	office of the		
	SITE NAME:	No. 25 Store, Yard Services Manager's Office, I/118 Jago Road, HM Naval Base, Portsmouth	1782. Two storied storehouse with internal courtyard. In fair condition but vacant. Future use uncertain.
	DESIGNATION	: Listed Building Grade II*, CA	
- 4 Ulm	CONDITION:	-	
H - 2500	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
HER BEITROU		Government	Contact: Alan Johnson 020 7973 3174
CHARTER MANAGE	Office of the		
	SITE NAME:	2-8 The Parade, HM Naval Base, Portsmouth	Part of terrace of dockyard officers' lodgings, 1715-19, with attached service buildings and walled gardens. Converted to office use circa 1990, ceased this use in
	DESIGNATION	: Listed Building Grade II*, CA	1995. Prone to wet rot and some structural movement. Future use uncertain. Nos $I - 9$ (adjacent) are in use.
	CONDITION:	Poor	
NRG	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
- The second sec	OWNERSHIP:	Government	Contact: Rory O'Donnell 020 7973 3775
No. 1		Iron and Brass Foundry, I/140 Victoria Road, HM Naval Base, Portsmouth E Listed Building Grade II*, CA	1854 foundry for the Naval Base. West three storey wing converted to offices. Middle section is used for storage. East wing (Building I/136) is unoccupied and at risk.
HILL STORE STORE	CONDITION:	Fair	
APPLATE A	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
Tana P			
	OWNERSHIP:	Government	Contact: Alan Johnson 020 7973 3174
	OWNERSHIP: SITE NAME:	Government No. 6 Dock, Basin No. I,	Naval dock circa 1690, immediately adjacent to the
B.M.	SITE NAME:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars.
	SITE NAME: DESIGNATION	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth :: Listed Building Grade I, SM, CA	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening
	SITE NAME:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth :: Listed Building Grade I, SM, CA	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the
	SITE NAME: DESIGNATION CONDITION:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth :: Listed Building Grade I, SM, CA	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the
	SITE NAME: DESIGNATION CONDITION:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth E Listed Building Grade I, SM, CA Poor	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth Listed Building Grade I, SM, CA Poor Not applicable	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth Listed Building Grade I, SM, CA Poor Not applicable C (C)	Naval dock circa I690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the Basin No. I complex.
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OW/NERSHIP: SITE NAME:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth Listed Building Grade I, SM, CA Poor Not applicable C (C) Government Horse Sand Fort, Solent,	Naval dock circa I690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the Basin No. I complex. Contact: Rory O'Donnell 020 7973 3775 CI9 sea fort in state of dereliction. Now owned by private
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OW/NERSHIP: SITE NAME:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth E Listed Building Grade I, SM, CA Poor Not applicable C (C) Government Horse Sand Fort, Solent, Portsmouth E Scheduled Monument	Naval dock circa I690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the Basin No. I complex. Contact: Rory O'Donnell 020 7973 3775 CI9 sea fort in state of dereliction. Now owned by private
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth E Listed Building Grade I, SM, CA Poor Not applicable C (C) Government Horse Sand Fort, Solent, Portsmouth E Scheduled Monument Poor	Naval dock circa 1690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the Basin No. I complex. Contact: Rory O'Donnell 020 7973 3775 C19 sea fort in state of dereliction. Now owned by private
	SITE NAME: DESIGNATION CONDITION: OCCUPANCY: PRIORITY: OWNERSHIP: SITE NAME: DESIGNATION CONDITION:	No. 6 Dock, Basin No. I, Portsmouth Dockyard, Portsmouth E Listed Building Grade I, SM, CA Poor Not applicable C (C) Government Horse Sand Fort, Solent, Portsmouth E Scheduled Monument Poor	Naval dock circa I690, immediately adjacent to the Block Mills. Suffering from rotation, and thus the opening up of mortar joints in the north side stonework altars. Underpinning may be the only solution. Part of the Basin No. I complex. Contact: Rory O'Donnell 020 7973 3775 CI9 sea fort in state of dereliction. Now owned by private

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

	HERITAGE			
	SITE NAME:	Spitbank Fort, Solent, Portsmouth	C19 Solent In need of r	sea fort. Used as a tourist attraction. epair.
CONTRACTOR OF THE OWNER.	DESIGNATION	Scheduled Monument		
A REAL PROPERTY AND A REAL	CONDITION:			
and the second se		Occupied		
	PRIORITY:	C (D)		
	OWNERSHIP:		Contact: Ric	hard Massey 01483 252046
				,
READING (UA)				
A	SITE NAME:	Chazey Farm Barn, The Warren, Reading	Structural ci shoring.The	e 7 bay red brick barn CI7 or earlier. racking and gable currently has temporary building forms part of a larger site proposal
ANTIHAR	DECICNIATION	Listed Building Grade I		care development. Work was due to in Spring 2009.
ALC: HIS			commence	
Difference in		Very bad		
	OCCUPANCY:			
an bie lander	PRIORITY:	A (A)	Contact: Kat	they on Davies 01492 252029
Contraction of the State of the State	OWNERSHIP:	Company	CONTACT: NA	thryn Davies 01483 252028
SITE NAME:	Reading A	bbey: a Cluniac and Benedictine mon	astery and Civi	il War earthwork, Reading
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:	Deteriora	tion – in need of management	TREND:	Declining
OWNERSHIP:	Local Aut		CONTACT:	Simon Goodhugh 01483 252037
				5
SOUTHAMPTON, CIT	ry of (U	A)		
	SITE NAME:	Chapel Mills, American Wharf, Elm Street, Southampton	biscuits for t	am mill, 1781 and 1800, built to produce ship's the Navy. Now used as storage and suffering f maintenance, but negotiations on more active
	DESIGNATION	Listed Building Grade II*		80
目出 十二十一十一十	CONDITION:	-		
	OCCUPANCY:	Occupied		
And a state of the	PRIORITY:	C (C)		
	OWNERSHIP:	Company	Contact: Da	vid Brock 01483 252044
	SITE NAME:	Red Lion public house, 55 High Street, Southampton	CI5 hall hou from water	use now commercial premises, suffering ingress and deferred maintenance.
	DESIGNATION	: Listed Building Grade II*		
	DESIGNATION	-		
	CONDITION:	-		
	CONDITION:	Poor		
	CONDITION: OCCUPANCY:	Poor Part occupied C (New)	Contact: Da	wid Brock 01483 252044
	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (New)	Contact: Da	vid Brock 01483 252044
SURREY	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (New)	Contact: Da	wid Brock 01483 252044
SURREY ELMBRIDGE	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (New)	Contact: Da	vid Brock 01483 252044
	CONDITION: OCCUPANCY: PRIORITY:	Poor Part occupied C (New)	Garden wal	ls, 1717 by Vanbrugh. Unusually monumental. om vegetation and mortar loss and in need
	CONDITION: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME:	Poor Part occupied C (New) Private Former Kitchen Garden walls to Claremont House, Claremont Park Road, Esher	Garden wal Suffering frc of general n	ls, 1717 by Vanbrugh. Unusually monumental. om vegetation and mortar loss and in need
	CONDITION: OCCUPANCY: PRIORITY: OWINERSHIP: SITE NAME:	Poor Part occupied C (New) Private Former Kitchen Garden walls to Claremont House, Claremont Park Road, Esher : Listed Building Grade II*, RPG Grade	Garden wal Suffering frc of general n	ls, 1717 by Vanbrugh. Unusually monumental. om vegetation and mortar loss and in need

Contact: Andy White 01483 252047

PRIORITY:

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

OCCUPANCY: Not applicable

OWNERSHIP: Private

C (New)

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / ELMBRIDGE / EPSOM AND EWELL / GUILDFORD

	Cla Est		1717 by Sir J back into us	Iohn Vanbrugh. In ne se as a focal point c	e form of a mock castle, eed of repair to bring it of the Grade I landscape
2 1 1 1 1 1 X		ed Building Grade II*, SM, RPG Grade I			
	condition: Fail				
Low Str 9- States	occupancy: Vac				
	PRIORITY: C (· ,			
	ownership: Ch	arity	Contact: Da	wid Brock 01483 25	52044
EPSOM AND EWELL					
A	Ch	ling School at The Durdans, Ialk Lane, som	for Lord Ro	osebery. Last used as use which could pr	designed by George Devey s part of a stable, but a ovide for full restoration
	designation: List	ted Building Grade II*, CA			
	condition: Fail	r			
A PROPERTY	occupancy: No	ot applicable			
	PRIORITY: C ((C)			
	OWNERSHIP: Priv	vate	Contact: Da	wid Brock 01483 25	52044
GUILDFORD					
	site name: Th	e Watts Gallery,	Gallery buil	t in 1904 as a memo	orial to the painter
9	Do	own Lane, ompton	G F Watts. I	In need of major re	
	designation: List	ted Building Grade II*			
Harrison of Fall	condition: Poo	or			
Contraction (12) (12)	occupancy: Oc	ccupied			
1 300 0000000	PRIORITY: D	(D)			
	ownership: Tru	ıst	Contact: Da	wid Brock 01483 25	52044
A	Ne	ins of Newark Priory, wark Lane, bley	Beatrice de 1538-39 by I	Saudes, for Augusti Henry VIII. Extensive	de Calva and his wife nian Canons. Dissolved in remains of monastic churcl
BAUG	designation: List	ted Building Grade I, SM	Consolidation Current disc	on is required to pr cussion with owner	event gradual decay. over repairs.
	occupancy: No	ot applicable			
	priority: C ((C)			
	OWNERSHIP: Priv	vate	Contact: Ric	chard Massey 01483	3 252046
ITE NAME:	Hillbury hillfo	ort, Puttenham			
DESIGNATION:	Scheduled Mc	onument	CONDITION:	Generally unsatist	,
	Carrie (traca a			with major localis	sed problems
RINCIPAL VULNERABILITY:	Scrub / tree g	growth	TREND:		01402 252027
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh	1 01483 252037
ITE NAME:	Large univalla	te hillfort at Felday, Shere			
DESIGNATION:	Scheduled Mo	onument	CONDITION:	Generally unsatist	factory
			CONDITION.	with major localis	,
RINCIPAL VULNERABILITY:	Scrub / tree g	rowth	TREND:	Declining	
DWNERSHIP:	Private	, on an	CONTACT:	Simon Goodhugh	n 01483 252037
ITE NAME:	Clandon Park	c,West Clandon			on's landscape park c1776-8 owned by the National Trus
DESIGNATION:	Registered Pa also part in C	rk and Garden Grade II, A. 8 I Bs	but the park managed wit	is privately owned. I th many trees lost to	t is currently unsympathetic decay, thus affecting the
CONDITION:		ificant problems	overall integ	rity of the design and	d the setting of the house.
ULNERABILITY:	High				or business use of farm n to a conservation and
REND:	Deteriorating			t strategy is needed.	
	Mixed, multipl		Ű	arlotte McLean 014	483 252076
DWNERSHIP :	T incea, maialpi		Contact. Cl		105 2520/0
NORITY (FOR BUILDINGS)	B Immediate risk of furthe	C er rapid Slow decay; no solution agreed.	E Linder room	ir or in fair to good repair,	F Repair scheme in progress and

MOLE VALLEY				
TAJ	SITE NAME:	Ruins of Betchworth Castle, Reigate Road, Betchworth	Consolidatio	ined house built on site of medieval castle. on required. Emergency works required me areas are in danger of imminent collapse.
man and a fill working	DESIGNATION	Listed Building Grade II, SM		
	CONDITION:	Poor		
	OCCUPANCY:	Not applicable		
and the second second	PRIORITY:	B (B)		
	OWNERSHIP:	Local authority	Contact: Ric	hard Massey 01483 252046
Summer Mile	SITE NAME:	Brockham Lime Works, Brockham	a western b built in 1870	s include an eastern battery of eight kilns and attery of two.The eastern battery, originally , comprises four pairs of linked flare kilns. rn two pairs were modified to the Brockham
A Company of the second		Listed Building Grade II, SM	patent, as w	as the western battery, and comprises the type
111111 Martine		Very bad		type of kiln. The kilns are in a very poor state of uffer from water ingress and vegetation growth.
		Not applicable A (A)	ropair and s	
	PRIORITY: OWNERSHIP:	()	Contact: Ric	hard Massey 01483 252046
	Ovviderorim.	ii dot	Contact. Nic	
SITE NAME:	Lime kiln:	s at Betchworth Quarry, Betchworth		
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deteriora	tion – in need of management	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Anstiebur	y Camp: a large multivallate hillfort s	south east of Cr	ockers Farm, Capel
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory
				with major localised problems
PRINCIPAL VULNERABILITY:		ee growth	TREND:	
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bell barro	ow in Deerleap Wood, Wotton		
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tr	ee growth	TREND:	Declining
OWNERSHIP:	Private	0	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Ashtead I	Park, Ashtead/Headley	Begun as a (C17 park, Ashtead was developed during
DESIGNATION:	0	d Park and Garden Grade II, 8 LBs, I SM	estate was s	d CI9 by successive owners. In the 1920s the sold as 51 lots. The historic estate is now in rships making co-ordination of conservation
CONDITION:	,	significant problems	action almo	st impossible. The main house and surrounds
VULNERABILITY:	High		are a schoo housing and	I, the road frontages have been developed for northern part of the park is managed as
TREND:	Deteriora	ting	public open	
OWNERSHIP :		ultiple owners	Contact: Ch	arlotte McLean 01483 252076
REIGATE AND BANST	FEAD			
	site name:	Alderstead (Merstham) Fort, Shepherd's Hill, Reigate	North Dow comprises tl	ation centre, one of I3 constructed on the rns for the defence of London. The scheduling he infantry fort and detached tool store. In and poor drainage are causing problems
Stor Barrie	DESIGNATION	Scheduled Monument		t has no current use.
	CONDITION:			
	OCCUPANCY:			
	PRIORITY:	C (C)		
	OWNERSHIP:	Private	Contact: Ric	hard Massey 01483 252046

Note: If the priority category has changed since the 2008 register, the previous category is given in brackets.

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

75

RUNNYMEDE				
SITE NAME:	Bronze Ag	ge settlement, west of Runnymede Brid	ge, Runnymed	de
DESIGNATION:	Scheduled	Monument	CONDITION:	Generally satisfactory but with
				significant localised problems
PRINCIPAL VULNERABILITY:	Scrub / tr	ee growth	TREND:	Declining
OWNERSHIP:		ent or Agency	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Woburn	Farm, Addlestone	Woburn Far	rm is an Arcadian landscaped <i>ferme ornée</i> Philip Southcote from 1734/5 and it was high
DESIGNATION:	Registered	d Park and Garden Grade II, also 5 LBs	influential as	a landscape design. The site is now in divided
CONDITION:	-	significant problems	in public and	d private ownership, including a school, some
VULNERABILITY:	Medium	5		dences and an area owned by the local planni
TREND:	Deteriora	ting	authority ov	vned but leased for various uses.
OWNERSHIP :		ultiple owners	Contact: Ch	arlotte McLean 01483 252076
TANDRIDGE				
da le	SITE NAME:	Bletchingly Castle, Bletchingley	too close to consolidatio developmer	gwork and bailey. Some trees are growing the fragile masonry which is in need of n. Owners have previously had plans for nt approved. A Conservation Management Pla
AND DEV. AND	DESIGNATION	Scheduled Monument	has also bee	en approved and work now needs to start.
	CONDITION:	Very bad		
Service and service	OCCUPANCY:	Not applicable		
	PRIORITY:	D (D)		
and the state	OWNERSHIP:	Private	Contact: Ric	hard Massey 01483 252046
WAVERLEY				
SITE NAME:	Chiddingf	old Roman villa, Chiddingfold		
DESIGNATION:	Scheduled	Monument	CONDITION:	Extensive significant problems
	A 11 1			i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Four bow	l barrows 30m south east of Tilford Ba	rrows: part of	f The Barrows round barrow cemetery, Tilfo
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tr	ee growth	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
	Thvate		contract.	
WOKING				
SITE NAME:	Brookwo	od Cemetery, Brookwood	The largest London's de	cemetery in England, founded in 1852 to hou ead, served by its own railway line and laid ou
DESIGNATION:	Registered	Park and Garden Grade I, also CA, 18 LBs	and planted	to JC Loudon's principles. It remains a working
CONDITION:	Extensive	significant problems	cemetery ar	nd is owned by a limited company. The scale of
VULNERABILITY:	High		with an ung	e and restoration work required is immense ent and immediate need for a conservation,
TREND:	Deteriora	ting		unding strategy with priorities.
OWNERSHIP :		e, single owner		arlotte McLean 01483 252076
	14)			
WEST BERKSHIRE (U		Chapel of St Languard	Chanal Cla	and later Structure is generally accord with
Asa	SITE NAME:	Chapel of St Leonard, east of Manor Farmhouse, Brimpton Road, Brimpton	repair progr Scheduled N	and later. Structure is generally sound, with amme completed. Planning permission and Monument Consent granted for sympathetic to office use.
4		Listed Building Grade II*, SM		
1111月1日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日	CONDITION:	Good		
	OCCUPANCY:	Vacant		
indertained the state	PRIORITY:	E (E)		
	OWNERSHIP:	Private	Contact: Ch	ris Welch 01483 252027
	_			
RIORITY (FOR BUILDINGS)				

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

1412	SITE NAME:	Pair of gate piers 103 metres south	Gate piers	HERITAGE AT RISK 2009 / WEST BERKSHIRE (L (built before 1718) to C17 house, burnt down
		of east end of church, Park Lane, Hamstead Marshall	in 1718.The	gate piers remain in the north-west corner o one cornice eroded in places with open joints
	DESIGNATION	: Listed Building Grade I, RPG II	and weed g	rowth.The landscape is generally in good
		Very bad	condition, b	ut other pairs of gate piers and CI7 walled also at risk.
		Not applicable	Sal dens al e	
salarity far all	PRIORITY:	A (C)		
an ann an	OWNERSHIP:		Contact: Ka	thryn Davies 01483 252028
± ±	SITE NAME:	Pair of gate piers 204 metres east of entrance to Home Farm, Park Lane, Hamstead Marshall	in 1718.The the park. Sc	(built before 1718) to C17 house, burnt down gate piers remain in the north west corner o ome of the bricks have eroded. The landscape
	DESIGNATION	: Listed Building Grade I, RPG II		good condition, but three other pairs of gate ne CI7 walled garden are also at risk.
Contraction of the local division of the loc	CONDITION:	Poor	piero una u	
	OCCUPANCY:	Not applicable		
Contraction and Research	PRIORITY:	С (С)		
	OWNERSHIP:	Private	Contact: Ka	thryn Davies 01483 252028
	SITE NAME:	Pair of gate piers 210 metres south of church tower, Park Lane, Hamstead Marshall	in 1718.The the park.Th	(built before 1718) to C17 house, burnt down gate piers remain in the north west corner o le landscape is generally in good condition, but
81 16 En 100	DESIGNATION	Listed Building Grade I, RPG II		airs of gate piers and the CI7 walled gardens risk.The stonework is in poor condition and a
	CONDITION:	Poor		ornice has fallen away.
	OCCUPANCY:	Not applicable		
	PRIORITY:	C (C)		
	OWNERSHIP:		Contact: Ka	thryn Davies 01483 252028
	SITE NAME:	Pair of gate piers 30 metres south of east end of church, Park Lane, Hamstead Marshall	in 1718.The of the park.	(built before 1718) to C17 house, burnt down gate piers remain in the north west corner Bricks and pointing have eroded and the ston
4 4 C	DESIGNATION	Listed Building Grade I, RPG II	cornices are	e damaged. Shrubs are growing from the joints f the base and the pier corner has fallen away.
		Very bad	The landsca	upe is generally in good condition, but other
	OCCUPANCY:	Not applicable	pairs of gate	e piers and the CI7 walled gardens are also
	PRIORITY:	A (C)	at risk.	
	OWNERSHIP:	Private	Contact: Ka	thryn Davies 01483 252028
	SITE NAME:	Three pairs of gate piers and walls around gardens and terrace at Home Farm, Park Lane, Hamstead Marshall	and three p corner of th	I7 walled gardens (one with raised terrace) pairs of gate piers located in the north west he park. Formerly the gardens to the CI7 hous
and some over the second second	DESIGNATION	Listed Building Grade I, RPG II		n in 1718. Used by the C19 as kitchen gardens
		Very bad		ad Lodge. The walls are in joint ownership. ons have open joints. One of the gate piers
		Not applicable		rowth to the cornice. Parts are being repaired
Constraints and	PRIORITY:	C (C)	0	0 1
	OWNERSHIP:		Contact: Ka	thryn Davies 01483 252028
ITE NAME:	Long barr	row at Combe Gibbet, Gallows Down, C	Combe	
Designation:	-	l Monument	CONDITION:	Generally satisfactory but with
				significant localised problems
RINCIPAL VULNERABILITY:	Extensive	vehicle damage/erosion	TREND:	Declining
DWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
ITE NAME:	East IIsley	Down round barrows, East Ilsley		
DESIGNATION:	Schedulec	Monument	CONDITION:	Extensive significant problems
JESIGINATION.				i.e. under plough, collapse
	A no-l-l	aughing.		Declining
RINCIPAL VULNERABILITY:	Arable plo Private	bughing	TREND:	Declining Simon Goodhugh 01483 252037

Note: If the priority category has changed since the 2008 register, the previous category is given in brackets.

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG SM/SMs Scheduled Monument/s UNitary Authority

WHS World Heritage Site

77

HERITAGE AT RISK 2009 / WEST BERKSHIRE (UA)

SITE NAME:	Long barrow on Sheep Down, Ikm north of East	IIsley, East II	sley
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 30m north of Bitham Lane, Inkpen		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
		CONDITION.	i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Membury Camp, Lambourn		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems
	Ample playshing		i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Two bowl barrows 500m north east of Stancomb	e Farm, Lam	bourn
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
Ownershir.	Thvate	CONTACT.	
SITE NAME:	Remains of St John the Baptist church at Ufton G	Green Farm,	Ufton Nervet
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Aldermaston Court, Aldermaston	The landsca	ape comprises an important mid/late CI9 Iayou
		but with re	mains of CI7/CI8 pleasure grounds relating to
DESIGNATION:	Registered Park and Garden Grade II, also CA, 10 LBs		manor house. Following WWII the house was sold te use then converted into a hotel and conference
CONDITION:	Generally unsatisfactory with major localised problems		were built in the grounds. The main part of the
VULNERABILITY:	Medium	former par	k is not registered. The conservation challenge
TREND:	Deteriorating		he management of this designed landscape.
OWNERSHIP:	Corporate, multiple owners	Contact: Cl	harlotte McLean 01483 252076
SITE NAME:	Sandleford Priory, Greenham		Priory is a mid/late CI8 landscape for which rown prepared designs, surrounding a Gothick
DESIGNATION:	Registered Park and Garden Grade II, also 2 LBs	house remo	odelled by James Wyatt. In 1947 the estate was
CONDITION:	Extensive significant problems	sold into di	ivided ownership, the house, gardens and core
VULNERABILITY:	High		t being used as a school. Other ownerships have to development (housing, waste disposal) leavir
TREND:	Deteriorating		ompromised as a design fragment which in turn
OWNERSHIP:	Mixed, multiple owners		sourced in its management.
		Contact: Cl	harlotte McLean 01483 252076
SITE NAME:	Shaw House, Newbury	This site cc	onsists of rare earthworks of a late CI6 or early
	,		n laid out by the Dolman family and a complex
	Registered Park and Garden Grade II, also CA, 6 LBs	Shaw Hours	8 water gardens by the Duke of Chandos. se, now restored with HLF and EH grant, as a
DESIGNATION:	Extensive significant problems		rity education centre, needs help and additiona
CONDITION:			
	Medium	funding to I	restore all the garden areas and to integrate
CONDITION:	Medium Deteriorating Local Authority, single owner	funding to I	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

			HERITAGE A	T RISK 2009 / WEST BERKSHIRE (UA) / ADUR / ARUN
	SITE NAME: DESIGNATION: TREND: OWNERSHIP:	First Battle of Newbury, Enborne / Newbury / Spee Registered Battlefield Stable Private	of the 1640s army attem had its path Royalist for defensive p The battle Parliamenta	ttle of Newbury took place during the Civil Wars s, on 20 September 1643. A large Parliamentarian ppting to march from Gloucester to the capital blocked by King Charles's equally strong ce. Fighting centred on the Parliamentarians' osition on Round Hill, west of Newbury. was indecisive, but did not prevent the irians from marching on towards London. mon Goodhugh 01483 252037
WEST SUSSEX				
ADUR				
	site name:	Shoreham Old Fort, Old Fort Road, Shoreham by Sea	Fort is vuln	ith later coastguards observation post. erable to vandalism and the elements. eginning to deteriorate badly.
	DESIGNATION:	Scheduled Monument		
CONTRACTOR OF STREET,	CONDITION:	Poor		
and the second s	OCCUPANCY:			
Contraction of the second	PRIORITY:	C (C)		
Contract Institute	OWNERSHIP:	Company	Contact: Rid	chard Massey 01483 252046
ARUN				
	SITE NAME:	Maison Dieu, Mill Road, Arundel	The monur owners, div	ains of the former hospital of the Holy Trinity. nent is in two distinct parts, with different ided by a road. One part is in fair condition v C, whilst the other is in a very bad condition
No. of Column States	DESIGNATION:	Listed Building Grade II, SM, CA	and Priority	
	CONDITION:	Very bad		
	OCCUPANCY:	Not applicable		
Particular	PRIORITY:	A (A)		
States and States	OWNERSHIP:	Private	Contact: Rid	chard Massey 01483 252046
	SITE NAME:	Littlehampton Fort, Littlehampton	main threat	he fort is partly covered in ivy which poses the to the building. Part of the fort is engulfed by which have 'Site of Special Scientific Interest' status.
A TANK A PARTY AND	DESIGNATION:	Scheduled Monument		
	CONDITION:	Poor		
Contraction of the	OCCUPANCY:	Not applicable		
	PRIORITY:	C (C)		
	OWNERSHIP:	Private	Contact: Rid	chard Massey 01483 252046
SITE NAME:	Romano-I	British villa and traces of Iron Age	e occupation 500m	WSW of New Barn, Angmering
DESIGNATION:	Scheduled	Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Flint mine	and a bowl barrow on Church H	Hill, 400m south we	est of Findon Place, Findon
	Scheduled	Monument	CONDITION:	Extensive significant problems
DESIGNATION:				
DESIGNATION:				i.e. under plough, collapse
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable plc Private	bughing	TREND:	i.e. under plough, collapse Declining Simon Goodhugh 01483 252037

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

WHS World Heritage Site

HERITAGE AT RISK 2009 / ARUN / CHICHESTER

SITE NAME:	Seven sections of Stane Street Roman road betw and two bowl barrows, Slindon	veen Eartham	n and Bignor, a prehistoric linear boundary
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Stable
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

CHICHESTER

	SITE NAME The Chapel at the former King Edward VII Hospital, Easebourne	Remarkable L-shaped chapel for tuberculosis patients by Charles Holden, 1903-6. In need of roof repairs as part of scheme to convert the hospital. Currently in receivership.
North Providence	DESIGNATION: Listed Building Grade II*, RPG II	
A STATE OF THE OWNER	CONDITION: Poor	
	occupancy: Vacant	
Contraction in the local division of the loc	priority: B (B)	
	OWNERSHIP: Company	Contact: David Brock 01483 252044
ALC	SITE NAME Former Church of the Assumption Church Farm Lane, East Wittering	on, Church, Medieval, restored 1875-6. Redundant for some years. Repairs have now been made but future use is not yet agreed.
11 200 000	DESIGNATION: Listed Building Grade II*	
States States and the	condition: Fair	
TANK IN THE	occupancy: Vacant	
L PARKE AND AND	priority: C (C)	
	ownership: Private	Contact: David Brock 01483 252044
	SITE NAME North Park Furnace, Linchmere	The furnace is one of the best preserved charcoal fired blast furnaces surviving from the Wealden iron industry. Built in 1614, it was in sporadic use until 1777, the last to be
PHR Manuel	designation: Scheduled Monument	operated in the western weald. It comprises an impressive
//	CONDITION: Poor	set of dam earthworks with pond, the remains of the blast furnace, wheel pit, casting pit and sluices. The dam is
1 1	occupancy: Vacant	unstable and the monument is at risk of erosion.
	priority: C (C)	
2 March	ownership: Trust	Contact: Richard Massey 01483 252046
	SITE NAME Ruined Church of St Mary,	CI3 parish church. In ruinous condition and under dense
C. Wante	Treyford	cracked and probably unstable. Repair and consolidation
L MALLA	Ireytord DESIGNATION: Listed Building Grade II*, SM	growth of ivy and other vegetation. Some walls are severel cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared.
在通知		cracked and probably unstable. Repair and consolidation
A MARK	DESIGNATION: Listed Building Grade II*, SM	cracked and probably unstable. Repair and consolidation
	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad	cracked and probably unstable. Repair and consolidation
	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable	growth of ivy and other vegetation. Some walls are severel cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared. Contact: Richard Massey 01483 252046
SITE NAME:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B)	cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared.
SITE NAME: DESIGNATION:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private	CONDITION: Generally satisfactory but with
DESIGNATION:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor Scheduled Monument	Contact: Richard Massey 01483 252046
DESIGNATION: PRINCIPAL VULNERABILITY:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor	CONDITION: Generally satisfactory but with
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor Scheduled Monument Rain entry	cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared. Contact: Richard Massey 01483 252046 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONTACT: Simon Goodhugh 01483 252037
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor Scheduled Monument Rain entry Private Bowl barrow 480m south of Irongates Lodge	cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared. Contact: Richard Massey 01483 252046 Contact: Richard Massey 01483 252046 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONTACT: Simon Goodhugh 01483 252037
DESIGNATION: PRINCIPAL VULNERABILITY:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor Scheduled Monument Rain entry Private	cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared. Contact: Richard Massey 01483 252046 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONTACT: Simon Goodhugh 01483 252037 ge, Compton CONDITION: Generally unsatisfactory
DESIGNATION: PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	DESIGNATION: Listed Building Grade II*, SM CONDITION: Very bad OCCUPANCY: Not applicable PRIORITY: B (B) OWNERSHIP: Private Bignor Roman villa, Bignor Scheduled Monument Rain entry Private Bowl barrow 480m south of Irongates Lodge	cracked and probably unstable. Repair and consolidation needed but vegetation has now been cleared. Contact: Richard Massey 01483 252046 Contact: Richard Massey 01483 252046 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining CONTACT: Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

 B d Immediate risk of further rapid ; deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Duncton Common round barrow ceme	tery, Duncton	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally satisfactory but with
			significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Field system in Lamb Lea, East Dean		
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
site name:	Bowl barrow on Lavington Common, 13	0m SSW of Main Woo	od Cottage, East Lavington
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow on Lavington Common, 15	0m SSE of Main Woo	d Cottage, East Lavington
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow on Lavington Common, 50	0m north west of W	esterland Lodge, East Lavington
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow on Lavington Common, 55	0m north of Wester	land Stud, East Lavington
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Declining
OWNERSHIP:	FTIVALE	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Four bowl barrows on Lavington Comm	on, north of Lower B	Barn. East Lavington
	Four both barrows on Langton Comm	,	,
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument Plant growth		Generally unsatisfactory with major localised problems Declining
	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scheduled Monument Plant growth	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
PRINCIPAL VULNERABILITY: OWNERSHIP:	Scheduled Monument Plant growth Private Harting Beacon: a hilltop enclosure, Ang	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
PRINCIPAL VULNERABILITY: OWNERSHIP: SITE NAME:	Scheduled Monument Plant growth Private Harting Beacon: a hilltop enclosure, Ang and Pen Hills, Elsted and Treyford	CONDITION: TREND: CONTACT:	Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 and and telegraph station on Beacon Generally satisfactory but with

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / CHICHESTER

'E NAME:	A Romano-Celtic temple, Iron Age sh	rine and associated rema	ins 250m north west of Ratham Mill, Fu
SIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
INCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
'E NAME:	Devil's Ditch, section extending 200y	rds (180m) east from Ch	apel Lane, Funtington
SIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
INCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
'E NAME:	Devil's Ditch, section extending 400y	rds (370m) west from Cl	napel Lane, Funtington
SIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
INCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
'E NAME:	Devil's Ditch, section extending 900y	rds (820m), Lye Wood, W	/est Stoke, Funtington
SIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
		Condition.	with major localised problems
INCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
		INEIND.	
WNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
WNERSHIP:	Flint mine on Stoke Down, immediat	ely north of Stoke Clum	p, Funtington
WNERSHIP:			
WNERSHIP:	Flint mine on Stoke Down, immediat	ely north of Stoke Clum	p, Funtington Extensive significant problems
VINERSHIP: TE NAME: SIGNATION:	Flint mine on Stoke Down, immediat Scheduled Monument	ely north of Stoke Clum	p, Funtington Extensive significant problems i.e. under plough, collapse
VINERSHIP: TE NAME: SIGNATION: INCIPAL VULNERABILITY:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing	condition: Trend: Contact:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
VINERSHIP: TE NAME: SIGNATION: INCIPAL VULNERABILITY: WNERSHIP:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private	condition: Trend: Contact:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037
VINERSHIP: TE NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: TE NAME:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80	condition: TREND: CONTACT: Om north of West Stoke	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory
VINERSHIP: TE NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: TE NAME: SIGNATION:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument	ely north of Stoke Clum CONDITION: TREND: CONTACT: Om north of West Stoke CONDITION:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: TE NAME: SIGNATION: INCIPAL VULNERABILITY:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scrub / tree growth	ely north of Stoke Clum CONDITION: TREND: CONTACT: Om north of West Stoke CONDITION: TREND: CONTACT:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scrub / tree growth Private	ely north of Stoke Clum CONDITION: TREND: CONTACT: Om north of West Stoke CONDITION: TREND: CONTACT:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory
VINERSHIP: TE NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: TE NAME: VINERSHIP: VINERSHIP: TE NAME: TE NAME:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument	ely north of Stoke Clum CONDITION: TREND: CONTACT: Om north of West Stoke CONDITION: TREND: CONTACT: TREND: CONTACT: TREND: CONTACT:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: E NAME: SIGNATION:	Flint mine on Stoke Down, immediat Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scheduled Monument Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet	ely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONTACT: *** Bridge, Graffham CONDITION:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: E NAME: SIGNATION: INCIPAL VULNERABILITY:	Flint mine on Stoke Down, immediate Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument Forestry	ely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONTACT: t's Bridge, Graffham CONDITION: TREND:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: E NAME: SIGNATION: INCIPAL VULNERABILITY:	Flint mine on Stoke Down, immediate Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument Forestry Private Bowl barrow 350m WNW of Barnet Bowl barrow 500m WNW of Barnet	ely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONTACT: t's Bridge, Graffham CONDITION: TREND: CONDITION:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: WINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: INCIPAL VULNERABILITY: VINERSHIP: INCIPAL VULNERABILITY:	Flint mine on Stoke Down, immediate Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument Forestry Private	ely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONTACT: t's Bridge, Graffham CONDITION: TREND: CONDITION:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: INCIPAL VULNERABILITY	Flint mine on Stoke Down, immediate Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument Forestry Private Bowl barrow 500m WNW of Barnet Scheduled Monument	eely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONDITION: t's Bridge, Graffham CONDITION: t's Bridge, Graffham	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining
VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: SIGNATION: INCIPAL VULNERABILITY: VINERSHIP: E NAME: E NAME	Flint mine on Stoke Down, immediate Scheduled Monument Arable ploughing Private Linear boundary on Stoke Down, 80 Scheduled Monument Scheduled Monument Scrub / tree growth Private Bowl barrow 350m WNW of Barnet Scheduled Monument Forestry Private Bowl barrow 350m WNW of Barnet Bowl barrow 500m WNW of Barnet	ely north of Stoke Clum CONDITION: TREND: CONTACT: 0m north of West Stoke CONDITION: TREND: CONTACT: t's Bridge, Graffham CONDITION: TREND: CONDITION: TREND: CONTACT: TREND: CONDITION:	p, Funtington Extensive significant problems i.e. under plough, collapse Declining Simon Goodhugh 01483 252037 House, Funtington Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS) A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

isionance Scheduled Monument control of the growth spectra control of Generally unsatisfactory with major localised problems control of the growth control of the gro	Bowl barrow on Gallows Hill, 150m ea	st of Millborough Hous	se, Graffham
Serve AUGUARDATION Serve A Serve A Theory of the growth Theory of the growth Theory of the growth Theory of the growth Serve A Serve A <th>Scheduled Monument</th> <th>CONDITION:</th> <th>Generally unsatisfactory</th>	Scheduled Monument	CONDITION:	Generally unsatisfactory
Weeksee Private counter Simon Goodhugh 01483 252037 In seven Two bowl barrows on Gallows Hill, 200m east of Millborough House, Graffham Generally unsatisfactory with major localied problems Interview Development Countral of Count			with major localised problems
Devide Monument Constract Generally unsatisfactory with major localised problems Inscrimunation Scheduled Monument Constract Generally unsatisfactory with major localised problems Inscrimunation Forestry Uses Declining Inscrimunation Scheduled Monument Constract Simon Goodhugh 01483 252037	Scrub / tree growth	TREND:	Declining
Scheduled Monument Consumery with major localised problems RECENTIONERABLERY FORMATIONE RECENTIONERABLERY FORMATIONE RECENTIONERABLERY FORMATIONE RECENTIO	Private	CONTACT:	Simon Goodhugh 01483 252037
Instrument Device for stry THE NO Device for stry INCOME VALUESTATURE Forestry THE NO Decklining INCOME VALUESTATURE Forestry THE NO Decklining INCOME VALUESTATURE Forestry THE NO Decklining INCOME VALUESTATURE Scheduled Monument Consumers Generally unsatisfactory with major localised problems INCOME VALUESTATURE Scheduled Monument Consumers Decklining INCOME VALUESTATURE Scheduled Monument Consumers Simon Goodhugh 01483 252037 INCOME VALUESTATURE Private Consumers Simon Goodhugh 01483 252037 INCOME VALUESTATURE Scheduled Monument Consumers Generally unsatisfactory with major localised problems INCOME VALUESTATURE Arable ploughing THE NOVE Simon Goodhugh 01483 252037 INCOME VALUESTATURE Peril's Ditch, section extending 530yds (480m) west from Lavart Lodge, Lavant INCOME VALUESTATURE Arable ploughing THE NOVE INCOME VALUESTATURE Arable ploughing THE NOVE Declining INCOME VALUESTATURE Arable ploughing	Two bowl barrows on Gallows Hill, 20	00m east of Millborough	n House, Graffham
Processory Descent Forestry memory Declining Development Boxide descent Simon Goodhugh 01483 252037 att sample Boxide descent/boxids, Laxant Simon Goodhugh 01483 252037 att sample Boxide descent/boxids, Laxant Generally unsatisfactory with major localised problems memory Constraint Strub / tree growth meta Declining memory Constraint Devil's Ditch, section 230yds (210m) long from Chickester min road to Pook Lane, Lavant messaria Devil's Ditch, section 230yds (210m) long from Chickester min road to Pook Lane, Lavant messaria Devil's Ditch, section 230yds (210m) long from Chickester min road to Pook Lane, Lavant messaria Devil's Ditch, section extending 530yds (480m) Generally unsatisfactory with major localised problems messaria Devil's Ditch, section extending 530yds (480m) Simon Goodhugh 01483 252037 messaria Devil's Ditch, section extending 960yds (870m) Generally unsatisfactory with major localised problems messaria Scheduled Monument Conamoni Generally unsatisfactory with major localised problems messaria Scheduled Monument Conamoni Generally unsatisfactory with major localised problems	Scheduled Monument	CONDITION:	
Windlesine Private covincr: Simon Goodhugh 01483 252037 Intervation Scheduled Monument covernore: Generally unsatisfactory with major localised problems Intervation Scheduled Monument covernore: Generally unsatisfactory with major localised problems Intervation Scheduled Monument covernore: Generally unsatisfactory with major localised problems Intervate: Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant covernore: Generally unsatisfactory with major localised problems Intervate: Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant covernore: Generally unsatisfactory with major localised problems Intervate: Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant covernore: Simon Goodhugh 01483 252037 Intervate: Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant covernore: Simon Goodhugh 01483 252037 Intervate: Devil's Ditch, section extending 540yds (870m) south of Lavant House, Lavant covernore: Generally unsatisfactory with major localised problems Intervate: Devil's Ditch, section extending 540yds (870m) south of Lavant House, Lavant covernore: S	Forestry	TREND:	
Scheduled Monument cokoniose Generally unsatisfiatory with major localised problems Invested units with major localised problems Declining Invested units with major localised problems Declining Invested units with major localised problems Cokoniose Generally unsatisfiatory with major localised problems International Columnation Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant Scheduled Monument cokoniose Generally unsatisfiatory with major localised problems International Columnation Arable ploughing Trends Declining International Columnation Cokoniose Generally unsatisfiatory with major localised problems International Columnation Cokoniose Generally unsatisfiatory with major	*	CONTACT:	0
with major localised problems BN GRW VULKERABLETY: Scrub / tree growth THERD: Declining WHAREAULY: Scrub / tree growth THERD: Declining THE NAME: Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant VERSINATION Scheduled Monument cononcal Generally unsatisfactory with major localised problems NENDERAULTY: Arable ploughing TREND: Simon Goodhugh 01483 252037 THE NAME: Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant VERSINTON Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTON Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTON Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTON Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTONE Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTONE Scheduled Monument cononcal Generally unsatisfactory with major localised problems VERSINTONE Scheduled Monument	Bexley Bushes earthworks, Lavant		
Private Constraint Declining International Constraint Private Constraint Declining International Constraint Declining Constraint Constraint International Constraint Scheduled Monument Constraint Constraint Rescreta With Reservations Scheduled Monument Constraints Constraints Rescreta With Reservations Arable ploughing TREND Declining Rescreta With Reservations Arable ploughing TREND Declining Rescreta With Reservations Decili Ditch, section extending 530yds (480m) Westraint Constraints Rescreta With Reservations Scheduled Monument Constraints Constraints Constraints Rescreta With Reservations Arable ploughing TREND Constraints Constraints Rescreta With Reservations Arable ploughing Constraints </td <td>Scheduled Monument</td> <td>CONDITION:</td> <td></td>	Scheduled Monument	CONDITION:	
Private Private Simon Goodhugh 01483 252037 Inter NAME: Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant Descountorin Scheduled Monument convince: Generally unsatisfactory with major localised problems MINIORAL VULNEWABLITY: Arable ploughing HEND Declining WINIORAL VULNEWABLITY: Arable ploughing HEND Convince: BIRCORUL VULNEWABLITY: Arable ploughing HEND Declining WINIORAL VULNEWABLITY: Scheduled Monument Convort Simon Goodhugh 01483 252037 WINIORAL VULNEWABLITY: Scheduled Monument Convort Simon Goodhugh 01483 252037			
Arran Meter Devil's Ditch, section 230yds (210m) long from Chichester main road to Pook Lane, Lavant beside Monument conomow Generally unsatisfactory with major localised problems BRICENAL VLAREMARTY: Arable ploughing mexo: Decilinig BRICENAL VLAREMARTY: Arable ploughing mexo: Decilinig British Stationty converse: Stimulation Statisfactory with major localised problems Bevil's Ditch, section extending 530yds (480m) west from Lavant Color Nork Beside Monument converse: Deciling Beside Monument converse: Deciling Beside Monument converse: Deciling Beside Monument converse: Simon Goodhugh 01483 252037 Beside Monument converse: Simon Goodhugh 0148	-	TREND:	5
Scheduled Monument CONDITION Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Arable ploughing TREND Declining WAREBAULTION CONTINUE Simon Goodhugh 01483 252037 WITE NAME Devil's Ditch, section extending 530yds (480m) west from Lavant Construct: RINCIPAL VULNERABLITY: Arable ploughing TREND Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Arable ploughing TREND: Declining RINCIPAL VULNERABLITY: Arable ploughing TREND: Declining WAREBAULTY: Arable ploughing TREND: Declining WAREBAULTY: Arable ploughing TREND: Declining WAREBAULTY: Arable ploughing TREND: Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABLITY: <td>Private</td> <td>CONTACT:</td> <td>Simon Goodhugh 01483 252037</td>	Private	CONTACT:	Simon Goodhugh 01483 252037
with major localised problems with major localised problems<	Devil's Ditch, section 230yds (210m) l	ong from Chichester m	ain road to Pook Lane, Lavant
Prescription Arable ploughing TREND: Declining SWNDERSHIP: Local Authonity CONTACE: Simon Goodhugh 01483 252037 SWNDERSHIP: Local Authonity CONTACE: Simon Goodhugh 01483 252037 THE NAME: Devil's Ditch, section extending 530yds (480m) Scheduled Monument Contorions: Generally unsatisfactory with major localised problems Prescription Arable ploughing TREND: Declining Declining Previous Private Contorions: Generally unsatisfactory with major localised problems Previous Private Contorions: Generally unsatisfactory with major localised problems Previous Scheduled Monument Contorions: Generally unsatisfactory with major localised problems Previous Scheduled Monument Contorions: Generally unsatisfactory with major localised problems Previous Scheduled Monument Contorions: Generally unsatisfactory with major localised problems Previous Scheduled Monument Contorions: Generally unsatisfactory with major localised problems Previous Scheduled Monument Contorios: Generally unsatisfactory with major localised problems Previous	Scheduled Monument	CONDITION:	, , , ,
WINNERSHIP: Local Authority CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant ESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERVAUUTY: Arable ploughing TREND: Declining WINERSHIP: Private CONDITION: Generally unsatisfactory with major localised problems WINERSHIP: Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant ESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERVAUUTY: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERVAUUTY: Scrub / tree growth TREND: Declining WINERSHIP: Scrub / tree growth TREND: Condition: WINERSHIP: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems WINERSHIP: Private Condition: Generally unsatisfactory with major localised problems WINERSHIP: Private Condition: Generally unsatisfactory with major localised problems			
TTE NAME: Devil's Ditch, section extending 530yds (480m) west from Lavant Lodge, Lavant esignation: Scheduled Monument contonion: Generally unsatisfactory with major localised problems anxcinal volumenatury: Arable ploughing memo: Declining www.esishue: Private contract: Simon Goodhugh 01483 252037 TTE NAME: Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant esignation: Scheduled Monument contonion: Generally unsatisfactory with major localised problems anxcinal volumenatury: Scrub / tree growth memo: Declining www.esishue: Private contract: Simon Goodhugh 01483 252037 TTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth esignation: Scheduled Monument contone: Generally unsatisfactory with major localised problems and private contract: Simon Goodhugh 01483 252037 TTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth esignation: Scheduled Monument contone: Generally unsatisfactory with major localised problems and private contract: Simon Goodhugh 01483 252037 TTE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping esignation: Scheduled Monument contone: Extensive significant problems and contone: Scheduled Monument contone: Scheduled Monument contone: Scheduled Monument contone: Scheduled Monument contone: Scheduled Monum			0
Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Arable ploughing TRIND: Declining Devil's Ditch, section extending 960yds (870m) south of Lavart Simon Goodhugh 01483 252037 International Conditional Condite Conditional Conditional Conditiona Conditio	Local Authority	CONTACT:	Simon Goodhugh 01483 252037
With major localised problems WRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Devil's Ditch, section extending 960yds (870m) south of Lavart Generally unsatisfactory with major localised problems Streinvarie: Devil's Ditch, section extending 960yds (870m) south of Lavart Generally unsatisfactory with major localised problems Streinvarie: Scheduled Monument control Revo Generally unsatisfactory with major localised problems WINNERSHIP: Scrub / tree growth TREND: Declining WINNERSHIP: Private control Revo Simon Goodhugh 01483 252037 WINNERSHIP: Private control Revo Generally unsatisfactory with major localised problems WINNERSHIP: Plant growth TREND: Declining DevineshiP: Private control Revo Simon Goodhugh 01483 252037 WINNERSHIP: Private control Revo Simon Goodhugh 01483 252037	Devil's Ditch, section extending 530yd	s (480m) west from Lav	vant Lodge, Lavant
RENCIPAL VOLUMERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 WILL CONTACT: Devil's Ditch, section extending 960yds (870m) >>uth of Lavart House, Lavant Desisionanon: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems VILL CONTACT: Scrub / tree growth TREND: Declining Sortub / tree growth TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 WILL CONTACT: Simon Goodhugh 01483 252037 Declining Sortub / tree growth TREND: Declining Sortub /	Scheduled Monument	CONDITION:	
Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining Devil's Ditch, section extending 960yds (870m) south of Lavant House, Lavant Declining RINCIPAL VULNERABILITY: Scheduled Monument CONTACT: Simon Goodhugh 01483 252037 Devil's Ditch, section extending 960yds (870m) TREND: Declining WILE FRAME: Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Plant growth TREND: Declining WILE FRAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Designation: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining			
Intername: Devil's Ditch, section extending 960yds (870m) south of Lavart House, Lavant Designation: Scheduled Monument condition: Generally unsatisfactory with major localised problems RRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining DWNERSHIP: Private control: Simon Goodhugh 01483 252037 UTTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborugh House, Lodsworth TREND: Designation: Scheduled Monument condition: Generally unsatisfactory with major localised problems UTTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborugh House, Lodsworth Generally unsatisfactory with major localised problems RRINCIPAL VULNERABILITY: Plant growth TREND: Declining WITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Simon Goodhugh 01483 252037 WITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping WITE NAME: Scheduled Monument Condition: Extensive significant problems WITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Extensive significant problems <tr< td=""><td></td><td></td><td>0</td></tr<>			0
Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining DWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough House-Lodsworth CONDITION: Generally unsatisfactory with major localised problems Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining DWNERSHIP: Private CONDITION: Generally unsatisfactory with major localised problems Private Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems Private CONDITION: Simon Goodhugh 01483 252037 UTE NAME: Private CONTACT: Simon Goodhugh 01483 252037 UTE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining <td>Private</td> <td>CONTACT:</td> <td>Simon Goodhugh 01483 252037</td>	Private	CONTACT:	Simon Goodhugh 01483 252037
RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining WINDERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough Houses Lodsworth VERSIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINDERSHIP: Private CONDITION: Generally unsatisfactory with major localised problems WINDERSHIP: Plant growth TREND: Declining WINDERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 WITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with lping Simon Goodhugh 01483 252037 WITE NAME: Scheduled Monument CONTACT: Simon Goodhugh 01483 252037 WITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with lping VERSIONATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining <td>Devil's Ditch, section extending 960yd</td> <td>s (870m) south of Lava</td> <td>nt House, Lavant</td>	Devil's Ditch, section extending 960yd	s (870m) south of Lava	nt House, Lavant
RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining DWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 WITE NAME: Bowl barrow on Gallows Hill, 300m east of Millborugh Houses, Lodsworth Image: Control of Cont	Scheduled Monument	CONDITION:	, , ,
WINERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth VESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 TITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzball: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Scheduled Monument CONDITION: RESIGNATION: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	Comula / trace graduith		
ITTE NAME: Bowl barrow on Gallows Hill, 300m east of Millborough House, Lodsworth ESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	-		
Designation: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems RINCIPAL VULNERABILITY: Plant growth TREND: Declining WWNERSHIP: Private contact: Simon Goodhugh 01483 252037 TTE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Scheduled Monument condition: VESIGNATION: Scheduled Monument condition: Extensive significant problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	i fivale	CONTACT:	
RINCIPAL VULNERABILITY: Plant growth TREND: Declining WINERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 ITTE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping VESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining			
DWN RERSHIP: Private contact: Simon Goodhugh 01483 252037 AITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	Bowl barrow on Gallows Hill, 300m ea	ast of Millborough Hou	
ITE NAME: Bowl barrow on Fitzhall Rough, 330m ENE of Fitzhall: part of Fitzhall Rough round barrow cemetery, Stedham with Iping DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining			se, Lodsworth Generally unsatisfactory
Stedham with Iping CONDITION: Extensive significant problems DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	Scheduled Monument	CONDITION:	se, Lodsworth Generally unsatisfactory with major localised problems
Designation: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse RINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	Scheduled Monument Plant growth	CONDITION: TREND:	se, Lodsworth Generally unsatisfactory with major localised problems Declining
PRINCIPAL VULNERABILITY: Scrub / tree growth TREND: Declining	Scheduled Monument Plant growth Private Bowl barrow on Fitzhall Rough, 330m	CONDITION: TREND: CONTACT:	se, Lodsworth Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037
	Scheduled Monument Plant growth Private Bowl barrow on Fitzhall Rough, 330m Stedham with Iping	CONDITION: TREND: CONTACT: ENE of Fitzhall: part of	se, Lodsworth Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Fitzhall Rough round barrow cemetery, Extensive significant problems
	Scheduled Monument Plant growth Private Bowl barrow on Fitzhall Rough, 330m Stedham with Iping Scheduled Monument	CONDITION: TREND: CONTACT: ENE of Fitzhall: part of CONDITION:	se, Lodsworth Generally unsatisfactory with major localised problems Declining Simon Goodhugh 01483 252037 Fitzhall Rough round barrow cemetery, Extensive significant problems i.e. under plough, collapse
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNERSHIP: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:		Scrub / tree growth Private Two bowl barrows on Gallows Hill, 20 Scheduled Monument Forestry Private Bexley Bushes earthworks, Lavant Scheduled Monument Scrub / tree growth Private Devil's Ditch, section 230yds (210m) M Scheduled Monument Arable ploughing Local Authority Devil's Ditch, section extending 530yd Scheduled Monument Arable ploughing Private Devil's Ditch, section extending 530yd Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument	Scrub / tree growth TREND: Private CONTACT: Two bowl barrows on Gallows Hill, 200m east of Millborough Scheduled Monument CONDITION: Forestry TREND: Private CONTACT: Bexley Bushes earthworks, Lavant Scheduled Monument CONDITION: Scrub / tree growth TREND: Private CONTACT: Devil's Ditch, section 230yds (210m) long from Chichester m Scheduled Monument CONDITION: CONDITION: Arable ploughing TREND: Local Authority CONTACT: Devil's Ditch, section extending 530yds (480m) west from Lava Scheduled Monument CONDITION: CONDITION: Arable ploughing TREND: Local Authority CONTACT: Devil's Ditch, section extending 530yds (480m) west from Lava Scheduled Monument CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: TREND: TREND: CONDITION: TREND

LA LB/LBs NP Local Authority Listed Building/s National Park

RPG Registered Park and Garden SM/SMs Scheduled Monument/s Unitary Authority

HERITAGE AT RISK 2009 / CHICHESTER / HORSHAM

SITE NAME:	Round ba	arrow south of Burton Down, Sutton		
DESIGNATION:	Scheduled	d Monument	CONDITION:	Extensive significant problems
				i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Scrub / tr	ree growth	TREND:	Declining
OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Lavington	Park, East Lavington		Park is a late CI8 and CI9 garden, laid out on
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs Extensive significant problems			a former late CI6 house and garden and furthe he C20, set within a park largely planted in the
CONDITION:			CI9 but of	CI8 origin. The property is now a school. The
VULNERABILITY:				has suffered from neglect and development
TREND:	Deteriora	iting	which shou	conservation plan is currently being prepared Id help to guide any future development in a
OWNERSHIP :		e, single owner	positive dire	ection and thus improve its trajectory.
	,		Contact: Cł	narlotte McLean 01483 252076
HORSHAM				
Marilia 10 me à	SITE NAME:	Amberley Limeworks,	CI9 Limew	orks including kilns and associated buildings.
		Houghton Bridge,	Vegetation	growth, the ingress of rain, inadequate
		Amberley		te in the past and industrial processes have
		: Scheduled Monument		bus structural weaknesses in the kilns and buildings. Site owned by West Sussex County
	CONDITION:		Council but	t leased to Amberely Museum Trust.
A REAL PROPERTY AND A REAL		Not applicable		
		11		
Carl and the second	PRIORITY:	C (C)	Contort, Di	shard Massay 01482 252044
	OWNERSHIP:	Trust	Contact: Ri	chard Massey 01483 252046
	SITE NAME:	St Marys House, The Street,		CI5 as a home for the Wardens of the Bridge the monks of Sele Priory at Upper Beeding.
All All		Bramber	Repairs are	necessary in the medium term but funding
	DECICNIATION	Listed Building Grade I, CA	from either	private or public sources remains uncertain.
	CONDITION:	-		
12 Statements				
14- 24 . Harrison and	PRIORITY: OWNERSHIP:	C (C)	Contact: D	avid Brock 01483 252044
	OWNERSHIP:	rivale	Contact: Da	avid dfock 01463 232044
JANK L	SITE NAME:	Chapter House & remains of kitchen,	Remains of	an Augustinian monastery founded during
MANDASSING.		Hardham Priory, Coldwaltham		/ Sir William Dawtry.The Chapter House is urgent repair.The upstanding remains of the
TI DO			kitchen are	in imminent danger of collapse. First stage
MAN		I: Listed Building Grade I, SM		roject underway.
	CONDITION:			
	OCCUPANCY			
	PRIORITY:	B (B)		L LN4 01 402 2520 4 4
	OWNERSHIP:	Private	Contact: Ri	chard Massey 01483 252046
HEL CH	SITE NAME:	Sedgwick Castle,		edieval castle. Ruinous. The exposed parts of th
Carlo Andread A		Moated site, Nuthurst	ongoing with new owners. A conservation strat previously been prepared but will need to be u	re in a very poor state of repair. Discussions ar
				been prepared but will need to be updated.
		Reprint Scheduled Monument		· · ·
	CONDITION:			
		Not applicable		
	PRIORITY:	B (B)	C	
	OWNERSHIP:	Private	Contact: Ri	chard Massey 01483 252046
SITE NAME:	Bowl bar	row on Black Hill, Colgate		
DESIGNATION:	Scheduled	d Monument	CONDITION:	Generally unsatisfactory

DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

site name:	Motte and bailey castle in Pulborou	gh Park, Pulborough	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Alfoldean Roman site, Slinfold		
DESIGNATION:	Scheduled Monument	CONDITION:	Extensive significant problems i.e. under plough, collapse
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 230m north east of T Sullington Warren, Storrington and		orming part of a round barrow cemetery o
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
			U. A A A A A A A A A A A A A A A A A A A
SITE NAME:	Bowl barrow 950m south west of 0 Kithurst Hill, Storrington and Sulling		dispersed round barrow cemetery on
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Bowl barrow 440m south east of C	Chanctonbury Ring hillfort,	Wiston
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
SITE NAME:	Cross dyke and platform barrow 46	60m south east of Chancto	onbury Ring hillfort, Wiston
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
MID SUSSEX			
SITE NAME:	Motte and bailey castle 240m east of	of Dean's Mill, Lindfield Ru	
DESIGNATION:	Scheduled Monument	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub / tree growth	TREND:	Declining
OWNERSHIP:	Private	CONTACT:	Simon Goodhugh 01483 252037
WORTHING			
	SITE NAME: Castle Goring, Arundel Road, Worthing	ndel Road, Shelley, about 1797-8. Currently let to a	
ALCON ENGL	DESIGNATION: Listed Building Grade I		
E VINANE.	CONDITION: Very bad		
	occupancy: Part occupied		
A REAL PROPERTY OF A REAL PROPER	PRIORITY: A (A)		
AND REAL PROPERTY AND REAL PROPERTY.			
	OWNERSHIP: Private	Contact: Da	avid Brock 01483 252044

Note: If the priority category has changed since the 2008 register, the previous category is given in brackets.

ABBREVIATIONS CA Conservation Area EH English Heritage HLF Heritage Lottery Fund

LA Local Authority LB/LBs Listed Building/s NP National Park

RPG
SM/SMsRegistered Park and GardenUAScheduled Monument/s
Unitary Authority

WHS World Heritage Site

85

HERITAGE AT RISK 2009 / WORTHING / OFF WEST SUSSEX / WINDSOR AND MAIDENHEAD (UA) / WOKINGHAM (UA)

	CONDITION:	Occupied F (F)	Early example of leisure complex, built 1911 as a roller skating rink and developed as a cinema in 1923. In need of extensive repair. The Worthing Dome and Regeneration Trust has secured Heritage Lottery Fund and English Heritage funding for repair and enhancement as a cinema, which is now nearly complete.
OFF WEST SUSSEX			
-	SITE NAME:	Hazardous, Bracklesham Bay,	A 54-gun Fourth Rate Ship of the Line, captured from the French in 1703 and refitted for the Royal Navy. Grounded on a reef in Bracklesham Bay during storm in 1706 while acting as escort for convoy en route from Chesapeake Bay, Virginia, to the
at		Protected Wreck Site	Thames Estuary. Urgent investigation occurred after seabed
and the second s		Extensive significant problems	levels dropped in 1984. Subsequent accretion and erosion have been recorded, including loss of exposed timbers in early
	TREND:	Significant decline	1990s. In 2006, changes to sediment patterns caused new areas
A President March		Government	of scouring. Recent studies have quantified environmental threats which are being used to mitigate further loss.
- 16 BERRY - 2500	PHOTO:	© Hazardous Project	which are being used to mitigate for the loss.
			Contact: Simon Goodhugh 01483 252037
	SITE NAME:	Submarine HMS/mAI, Eastern Solent	Built by Vickers in 1903, the A1 is the first British designed and built submarine used by the Royal Navy. She sank for the second time in 1911 while operating under automatic pilder as a submarized target The site has been rubiset to
	DESIGNATION	Protected Wreck Site	pilot as a submerged target. The site has been subject to unauthorised access and a chain of shellfish pots was fixed
VOID	CONDITION:	Extensive significant problems	by an unknown diver to the vessels' pressure hull causing
A DESCRIPTION OF THE PARTY OF T	TREND:	Significant decline	abrasive damage.
- 20	OWNERSHIP:	Private	
and the second			Contact: Simon Goodhugh 01483 252037
WINDSOR AND MAI	DENHEA	D (UA)	
	SITE NAME:	Noahs Boathouse, Stonehouse Lane (Off), Cookham	1930, by Colin Lucas for his father, constructed of monolithic reinforced concrete with a flat roof. An early and pioneering example of Modern Movement architecture by one of the major figures in the movement. The building floods regularly
	DESIGNATION	: Listed Building Grade II*	and is derelict. The roof is leaking and the concrete is spalling.
	CONDITION:	-	
and the second	OCCUPANCY:	Not applicable	
Control of the second second	PRIORITY:	A (A)	
Contract of the Contract of the	OWNERSHIP:	Private	Contact: Kathryn Davies 01483 252028

site name:	Royal Mausoleum, The Home Park, Windsor	Mausoleum; internal decoration decaying through damp. Possible need to replace the copper roof, modify the rainwater discharge, and undertake fabric repairs,
DESIGNATION	Listed Building Grade I, RPG Grade I	especially to the interior.
CONDITION:	Poor	
OCCUPANCY:	Not applicable	
PRIORITY:	С (С)	
OWNERSHIP:	Crown	Contact: Elizabeth Moore 020 7973 3803

WOKINGHAM (UA)



SITE NAME:	Site of St Bartholomews Church, Arborfield, Arborfield and Newland
DESIGNATION:	Listed Building Grade II, SM
CONDITION:	Very bad
OCCUPANCY:	Not applicable
PRIORITY:	A (A)
OWNERSHIP:	Religious organisation

Old parish church, now a roofless ruin. Originally CI3 in flint and stone, with substantial probable CI8 brick rebuilding. One wall partially standing, with fragments of later brick segments. Very overgrown. Risk of further collapse.

Contact: Chris Welch 01483 252027

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

В D Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

С Slow decay; no solution agreed.

D Slow decay, solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

E

Descrivation: Scheduled Monument continone Extensive significant problems i.e. under plough, collapse PreixCenus VLANERVABURY: Arable ploughing TERIA: Declining conversitie: Private conversitie: Declining stre NAME: Cropmark enclosure and pits north east of St Patrick's Avenue; Charvil conversitie: Conversitie: stre NAME: Scheduled Monument conversitie: Extensive significant problems i.e. under plough, collapse PreixCenus VLANERVABURY: Arable ploughing TERIA Declining conversitie: Ring ditch cropmark east of St Patrick's Avenue; Charvil Declining conversitie: Scheduled Monument conversitie: Extensive significant problems i.e. under plough, collapse stre NAME: Scheduled Monument conversitie: Extensive significant problems i.e. under plough, collapse stre NAME: Scheduled Monument conversitie: Extensive significant problems i.e. under plough, collapse stre NAME: Scheduled Monument conversitie: Extensive significant problems i.e. under plough, collapse stre NAME: Cropmark site east of Broadmoor Lane, Sonning protate <	+	Arborfield Garrison, Arborfield, Finchampstead		A specialised 'horse hospital' built 1911-12. The building is redundant by virtue of changes in Army practices (i.e. reduced cavalry activity).	
Construct Yacant Proverts Contract: Chris Welch 01483 252027 Streamer Comment Contact: Chris Welch 01483 252027 Streamer Cropmark complex south west of St Patrick's Avenue, Charvil Descursion Scheduled Monument contract: Chris Welch 01483 252037 Immonent Arable ploughing merens Extensive significant problems i.e. under plough, collapse Immonent Contract: Simon Goodhugh 01483 252037 Immonent Contract: Simon Goodhugh 01483 252037 Immonent Contract: Streamer Immonent Contrac	A CAN DE MAINE				
Procent: A (A) OWNERSHE Government Contact: Chris Weich 01483 252027 Streame: Cropmark complex south west of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse Prescent: Scheduled Monument controls Extensive significant problems i.e. under plough, collapse Prescent: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Scheduled Monument controls Stheduled Monument controls Extensive significant problems i.e. under plough, collapse Prescent: Prescent: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse Prescent: Ring ditch cropmark east of St Patrick's Avenue, Charvil Declining Scheduled Monument controls Extensive significant problems i.e. under plough, collapse Prescent: Ring ditch cropmark east of St Patrick's Avenue, Charvil Declining Controls Extensive significant problems i.e. under plough, collapse Prescent: Cropmark site east of St Patrick's Avenue, Charvil Declining Ownerseare Private Controls Extensive significant problems i.e. under plough, collapse Prestate Cropmark site east of		CONDITION: Very	bad		
Constant Contract: Chris Welch 01483 252027 UTE NAME: Cropmark complex south west of St Patrick's Avenue, Charvil Description Scheduled Monument Constract: Simon Goodhugh, collapse Prencenu XLAREMAULTY: Arable ploughing THE NAME: Constract: Simon Goodhugh, collapse Scheduled Monument Constract: Simon Goodhugh, collapse Constract: Simon Goodhugh, collapse Scheduled Monument Constract: Simon Goodhugh, collapse Description Scheduled Monument Constract: Simon Goodhugh, collapse Instrume: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse Instrume: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse Instrume: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse Instrume: Ring dick cropmark east of St Patrick's Avenue, Charvil Constract: Simon Goodhugh 01483 252037 Instrume: Cropmark site east of Broadmoor Lane, Sonning Declining Instrume: Cropmark site east of Broadmoor Lane, Sonning Generally satisfactory but with significant localised problems Instrume: <th< th=""><th></th><th>OCCUPANCY: Vaca</th><th>nt</th><th></th><th></th></th<>		OCCUPANCY: Vaca	nt		
STRENAME: Cropmark complex south west of St Patrick's Avenue, Charvil Descentione Scheduled Monument constrone Extensive significant problems i.e. under plough, collapse PRINCER, VULNEMARITY: Arable ploughing THEND Declining Streame: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Streame Descention: Scheduled Monument constrone Extensive significant problems i.e. under plough, collapse PRINCEN_VULNEMARITY: Arable ploughing THEND Declining OWNERSHE: Ring ditch cropmark east of St Patrick's Avenue, Charvil Streame Streame: Scheduled Monument constrone Extensive significant problems i.e. under plough, collapse TRENAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Streame Streame: Private constrone Extensive significant problems i.e. under plough, collapse TRENAME: Scheduled Monument constrone Extensive significant problems i.e. under plough, collapse Streame: Cropmark site east of Broadmoor Lane, Sonning Extensive significant localised problems Streame: Scheduled Monument constrone Generally satisfactory but with significant localised problems	The second second	PRIORITY: A (A)		
Backwannow Scheduled Monument Cowomow Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABURY: Arable ploughing TREND. Declining OWNERSHIP: Private Cowince: Simon Goodhugh 01483 252037 Stre NAME: Cropmark enclosure and pits north east of St Patrick's Avenue. Charvil Extensive significant problems i.e. under plough, collapse Scheduled Monument Cowince: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABURY: Arable ploughing TREND. Declining OWNERSHIP: Private Cowince: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABURY: Arable ploughing TREND. Declining Stre NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABURY: Arable ploughing TREND. Declining OWNERSHIP: Private Cowince: Simon Goodhugh 01483 252037 OWNERSHIP: Cropmark site east of Broadmoor Lane, Sonning Extensive significant localised problems in: under plough, collapse Stre NAME: Cropmark site east of Broadmoor Lane, Sonning Generally satisfactory but with significant localised problems TREND: Scheduled Monument Cowince: Scheduled Monument	and the second of	OWNERSHIP: GOVE	ernment	Contact: Ch	nris Welch 01483 252027
i.e. under plough, collapse i.e. under plough, collapse Declining Converses THENDE C	SITE NAME:	Cropmark com	plex south west of St Patrick's Av	enue, Charvi	1
OWNERSHIP Private Contract: Simon Goodhugh 01483 252037 STRENAME: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP Private Contract: Simon Goodhugh 01483 252037 STRENAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Declining DESIGNATION: Scheduled Monument Contract: Simon Goodhugh 01483 252037 STRENAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Declining DESIGNATION: Scheduled Monument Contract: Simon Goodhugh 01483 252037 STRENAME: Cropmark site east of Broadmoor Lane, Sonning Declining Declining STRENAME: Scheduled Monument Contract: Simon Goodhugh 01483 252037	DESIGNATION:	Scheduled Mon	ument	CONDITION:	
STRE NAME: Cropmark enclosure and pits north east of St Patrick's Avenue, Charvil DESCRANTORE Scheduled Monument CONDITIONE Extensive significant problems i.e. under plough, collapse PRINCEPAL VULNERABUTY: Arable ploughing TRENC Declining CONDITIONE Simon Goodhugh 01483 252037 STEE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil DESCRANTORE Scheduled Monument CONDITIONE Extensive significant problems i.e. under plough, collapse STEE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse PRINCEPAL VULNERABUTY: Arable ploughing TRENC Declining OWNERSHIP Private CONDITIONE Simon Goodhugh 01483 252037 STE NAME: Cropmark site east of Broadmoor Lane, Sonning Simon Goodhugh 01483 252037 STE NAME: Scheduled Monument CONDITIONE Generally satisfactory but with significant localised problems PRINCEPAL VULNERABUTY: Arable ploughing TRENC Declining CONDITIONE Scheduled Monument CONDITIONE Generally satisfactory but with significant localised problems	PRINCIPAL VULNERABILITY:	Arable ploughin	g	TREND:	Declining
Descrivation:Scheduled MonumentCONDITION:Extensive significant problems i.e. under plough, collapsePRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningOWNERSHER:PrivateCONTROCT:Simon Goodhugh 01483 252037UNITERABLITI:Ring ditch cropmark east of St Patrick's Avenue, CharvilScheduled MonumentCONDITION:Descrivation:Scheduled MonumentCONDITION:Extensive significant problems i.e. under plough, collapsePRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningPRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningPRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningPRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningPRINCIPAL VULNERABILIT:Arable ploughingTREND:DecliningDESCRIVATION:Scheduled MonumentCONDITION:Generally satisfactory but with significant localised problemsPRINCIPAL VULNERABILITY:Arable ploughingTREND:DecliningOWNERSHER:PrivateCONTROCT:Simon Goodhugh 01483 252037TREND:Scheduled MonumentCONTROCT:Simon Goodhugh 01483 252037TREND:Bearwood C	OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
PRINCIPAL VULNERABUTY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 STE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Scheduled Monument CONTACT: Simon Goodhugh 01483 252037 DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABUTY: Arable ploughing TREND: Declining OWNERSHIP: Private Contract: Simon Goodhugh 01483 252037 STE NAME: Cropmark site east of Broadmoor Lane, Sonning Simon Goodhugh 01483 252037 STE NAME: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABUTY: Arable ploughing TREND: Declining OWNERSHIP: Private Condition: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABUTY: Arable ploughing TREND: Declining OWNERSHIP: Private Condition: Generally satisfactory but with significant localised problems STE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19	SITE NAME:	Cropmark encl	osure and pits north east of St Pa	trick's Avenu	ie, Charvil
OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABLITY: Arable ploughing TREND: Declining OWNERSHIP: Private Contract: Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Declining SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Contract: Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Contract: Simon Goodhugh 01483 252037 SITE NAME: Scheduled Monument Contract: Simon Goodhugh 01483 252037 SITE NAME: Scheduled Monument Contract: Simon Goodhugh 01483 252037 SITE NAME: Scheduled Monument Contract: Simon Goodhugh 01483 252037 SITE NAME: Registered Park and Garden Grade II*, also part in CA, 3 LBs, Declining CONDITION: Generally unsatisfactory with major localised problems Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Savrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and maagement of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and s	DESIGNATION:	Scheduled Mon	ument	CONDITION:	
SITE NAME: Ring ditch cropmark east of St Patrick's Avenue, Charvil DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 STE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Ging and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of management of the g	PRINCIPAL VULNERABILITY:	Arable ploughin	g	TREND:	Declining
DESIGNATION: Scheduled Monument CONDITION: Extensive significant problems i.e. under plough, collapse PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private Construct: Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Construct: Simon Goodhugh 01483 252037 SITE NAME: Scheduled Monument Construct: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private Construct: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after VWU but subsequent and current development and management of the gardens and woodland, puls lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	OWNERSHIP:	Private		CONTACT:	Simon Goodhugh 01483 252037
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Generally satisfactory but with significant localised problems DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	SITE NAME:	Ring ditch crop	mark east of St Patrick's Avenue, (Charvil	
OWNERSHIP: Private Contract: Simon Goodhugh 01483 252037 SITE NAME: Cropmark site east of Broadmoor Lane, Sonning Condition: Generally satisfactory but with significant localised problems DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future and facer WIV but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	DESIGNATION:	Scheduled Mon	ument	CONDITION:	
SITE NAME: Cropmark site east of Broadmoor Lane, Sonning DESIGNATION: Scheduled Monument CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	PRINCIPAL VULNERABILITY:	Arable ploughin	g	TREND:	Declining
DESIGNATION:Scheduled MonumentCONDITION:Generally satisfactory but with significant localised problemsPRINCIPAL VULNERABILITY:Arable ploughingTREND:DecliningOWNERSHIP:Privatecontact:Simon Goodhugh 01483 252037SITE NAME:Bearwood College, Aborfield and NewlandNow a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	OWNERSHIP:	Private	-	CONTACT:	Simon Goodhugh 01483 252037
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival or the historic landscape.	SITE NAME:	Cropmark site	east of Broadmoor Lane, Sonning		
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	DESIGNATION:	Scheduled Mon	ument	CONDITION:	Generally satisfactory but with
OWNERSHIP: Private CONTACT: Simon Goodhugh 01483 252037 SITE NAME: Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.					significant localised problems
Bearwood College, Aborfield and Newland Now a school and separate golf course, this C19 landscape park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	PRINCIPAL VULNERABILITY:	Arable ploughin	g	TREND:	Declining
DESIGNATION:Registered Park and Garden Grade II*, also part in CA, 3 LBs,park and woodland surrounds a Victorian country house standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	OWNERSHIP:			CONTACT:	Simon Goodhugh 01483 252037
DESIGNATION:Registered Park and Garden Grade II*, also part in CA, 3 LBs,standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future after WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.	SITE NAME:	Bearwood Coll	ege, Aborfield and Newland		
CONDITION:Generally unsatisfactory with major localised problemsafter WWI but subsequent and current development and management of the gardens and woodland, plus lack of specialist guidance and resources, challenges the integrity and survival of the historic landscape.VULNERABILITY:Deteriorating	DESIGNATION:	0		standing on formal terraces, with gardens by William Sawrey Gilpin and Pulham. The school helped secure its future	
VULNERABILITY: High specialist guidance and resources, challenges the integrity and survival of the historic landscape.	CONDITION:				
TREND: Deteriorating and survival of the historic landscape.	VULNERABILITY:	,			
	TREND:	-			
	OWNERSHIP :	Corporate, mult	tiple owners		

LA LB/LBs NP Local Authority Listed Building/s National Park

CONSERVATION AREAS AT RISK

ADUR

Kingston Buci Shoreham-by-Sea

ASHFORD

Ashford Queens Road Wye

BRIGHTON AND HOVE, CITY OF (UA)

Benfield Barn East Cliff Montpelier and Clifton Hill North Laine Old Hove Ovingdean Patcham Portslade Old Village Queen Regency Square Rottingdean Sackville Gardens Valley Gardens West Hill Willett Estate

CANTERBURY

Eddington Highland Court Martyrs Field, Canterbury New Dover Road, Canterbury Nunnery Field, Canterbury Reculver Seaview Chalet Park Womenswold

CHICHESTER

Chichester East Marden Graylingwell Kirdford Selsey Tangmere Walderton West Itchenor West Wittering

CHILTERN

Old Town and town centre, Chesham

DARTFORD

Dartford town centre

EASTBOURNE

Upperton Gardens

ELMBRIDGE

Brooklands Thames Ditton

EPSOM AND EWELL

Adelphi Road, Linton Church Street, Worple Road Epsom town centre Ewell Village Stamford Green The Manor, Horton Hospital, Long Grove Hospital, St.Ebba Woodcote, Chalk Lane

FAREHAM

Titchfield Abbey

GOSPORT

Daedalus Haslar Rowner Stoke Road

ISLE OF WIGHT (UA)

Brading Carisbrooke Cowes Godshill Newport Ryde St John

MAIDSTONE

Lenham Elmstone Hole Wateringbury Station

MID SUSSEX

Ardingly Burgess Hill, Fairfields Burgess Hill, St. Johns East Grinstead Handcross Haywards Heath, Franklands Village Horsted Keynes Hurstpierpoint The Heath, Haywards Heath

MOLE VALLEY

Buckland Coldharbour Dorking Leatherhead

NEW FOREST (NP)

Bucklers Hard Forest Central, North and South Forest North East Forest South East Western Escarpment

PORTSMOUTH, CITY OF (UA)

HM Naval Base and St. George St. David

REIGATE AND BANSTEAD

Walton on the Hill

SEVENOAKS

Brasted High Street Chiddingstone Edenbridge Halstead Kippington and Oakhill Road, Sevenoaks Otford Riverhead Seal Sevenoaks High Street Shoreham High Street South Darenth Sundridge The Vine, Sevenoaks Vine Court, Sevenoaks

SHEPWAY

Dungeness Lydd Sandgate High Street

SOUTH BUCKS

Burnham Gerrards Cross Common Iver Stoke Green Taplow Riverside Uxbridge Lock

TUNBRIDGE WELLS

Royal Tunbridge Wells

WAVERLEY

Peperharow

HERITAGE AT RISK 2009 / CONSERVATION AREAS AT RISK

WEST OXFORDSHIRE

Aston Bampton Great Tew Stonesfield Taynton Witney and Cogges

WINCHESTER

Abbotts Worthy Avington Bishops Waltham Cheriton Compton Street Corhampton and Meonstoke Droxford Easton Exton Hambledon Hursley Itchen Stoke Kings Worthy Littleton Martyr Worthy New Alresford Southwick Sparsholt Sutton Scotney Twyford West Meon Wickham Winchester Wonston

WINDSOR AND MAIDENHEAD (UA)

Beenham Maidenhead town centre

WORTHING

Goring



This document is one of a series of publications produced as part of English Heritage's new national Heritage at Risk campaign. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

For copies of this document, or if you would like it in a different format, please contact our Customer Services department. Tel: 0870 333 1181; Fax: 01793 414926; Textphone: 01793 414878; E-mail: customers@english-heritage.org.uk







Proud to be supporting English Heritage in its campaign to save the nation's historic environment.



HERITAGE AT RISK Published June 2009 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2009

PRODUCTION Editors: Clare Parfitt, Rowan Whimster Design: Evolve Design (London) Print:The Colourhouse Recycled Paper: Revive 100 Uncoated / 75 Matt