# Heritage at **Risk**



London Register 2015

# Contents

The RegisterVContent and criteriaVCriteria for inclusion on the RegisterIReducing the risksXKey statisticsXIPublications and guidanceXKey to the entriesXVEntries on the Register by local planning authorityXIGreater LondonXBarking and Dagenham Barnet Bexley BrentICity of LondonICroydon2Enfield2Greenwich3Hackney3Hammersmith and Fulham4Harrow Havering4
Criteria for inclusion on the RegisterI.Reducing the risksXKey statisticsXIPublications and guidanceXKey to the entriesXVEntries on the Register by local planning authorityXIGreater LondonBarking and Dagenham Barnet Bexley BrentBromley CamdenICity of LondonICroydon22Enfield22Greenwich33Hackney33Haringey4Harrow4Havering4
Reducing the risks       XI         Reducing the risks       XI         Publications and guidance       XI         Publications and guidance       XV         Entries on the entries       XV         Entries on the Register by local planning authority       XI <i>Greater London</i> Barking and Dagenham         Barnet       Bexley         Brent       Bromley         Camden       I         City of London       I         Croydon       22         Enfield       22         Greenwich       33         Hackney       33         Harrow       4         Havering       4
Key statisticsXIPublications and guidanceXPublications and guidanceXKey to the entriesXVEntries on the Register by local planning authorityXIGreater LondonBarking and Dagenham Barnet Bexley Brent CamdenICity of LondonICroydon2Ealing2Enfield2Greenwich3Hackney3Harmow4Harrow4Havering4
Publications and guidance X Key to the entries XV Entries on the Register by local planning XI authority Greater London Barking and Dagenham Barnet Bexley Brent Bromley Camden I City of London I Croydon 2 Ealing 2 Enfield 2 Greenwich 3 Hackney 3 Hammersmith and Fulham 4 Harrow 4 Havering 4
Key to the entriesXVEntries on the Register by local planning authorityXIGreater LondonBarking and Dagenham Barnet Bexley Brent Bromley CamdenICity of LondonICroydon2Ealing2Enfield2Greenwich3Hackney3Harrow4Havering4
Function of the Register by local planning XI authority Creater London Barking and Dagenham Barnet Barnet Bexley Brent Bromley Camden I City of London I Croydon 2 Ealing 2 Enfield 2 Greenwich 3 Hackney 3 Hammersmith and Fulham 4 Haringey 4 Harrow 4 Havering 4
authority Greater London Barking and Dagenham Barnet Bexley Brent Bromley Camden City of London Croydon Ealing Enfield Greenwich Hackney Hammersmith and Fulham Harrow Havering 4
Barking and DagenhamBarnetBexleyBrentBromleyCamdenCity of LondonCroydon2Ealing2Enfield2Greenwich3Hackney3Harnow4Harrow4Havering
BarnetBexleyBrentBromleyCamdenCity of LondonCroydon2Ealing2Enfield2Greenwich3Hackney3Hammersmith and Fulham4Harrow4Havering4
Hillingdon5Hounslow5Islington6Kensington and Chelsea7Kingston upon Thames8Lambeth8Lewisham9Merton9Newham9Redbridge10Richmond upon Thames10Southwark10Sutton11Tower Hamlets11Waltham Forest12Wandsworth12Westminster, City of12

# Heritage at Risk



London Summary 2015



or the first time, we've compared all sites on the Heritage at Risk Register – from houses to hillforts – to help us better understand which types of site are most commonly at risk. There are things that make each region special and, once lost, will mean a sense of our region's character is lost too. Comparing London to the national Register shows that 80.2% of all commemorative monuments and 57.6% of all public buildings are in our region. There are 670 entries on the London 2015 Heritage at Risk Register, making up 12.2% of the national total of 5,478 entries. The Register provides an annual snapshot of historic sites known to be at risk from neglect, decay or inappropriate development. Our local HAR team, led by Rebecca Barrett, continues to work with owners, funders and other stakeholders to find the right solutions for sites on the Register.

### Nigel Barker Planning Director, London



Tackling heritage at risk is a real challenge – it requires imaginative solutions, strong partnerships and a great deal of determination. Given these challenges, we're delighted that 35 historic buildings and sites in London have been

removed from the 2014 Heritage at Risk Register. This is thanks to so many individuals, from volunteers to local authority staff, private owners to commercial developers.

One of our biggest achievements is the sensitive repair of Harmondsworth Barn in Hillingdon. Once described by Sir John Betjeman as the "Cathedral of Middlesex", the barn is an exceptional medieval building. After years of legal negotiations it is now cared for by English Heritage, and is well worth a visit.

The continuing support of the Heritage Lottery Fund has also been critical this year. The early 17th century stables at Eastcote House, which now host a range of community activities; and Raleigh Hall, now a heritage centre for the Black Cultural Archives in the heart of Brixton, are just two beneficiaries. Both sites have been removed from the Heritage at Risk Register.

Once again we're grateful to volunteers across London who helped us champion the historic environment.


Volunteers in Hounslow, for example, worked tirelessly through the winter months to assess the condition of all Grade II listed buildings in the borough. Their work will help focus resources on those buildings most in need of attention.

Despite our successes there are still significant challenges. 33 historic buildings and sites have been added to the Heritage at Risk Register this year. They range from an 18th century tithe barn to a 1920s factory building designed by Wallis, Gilbert and Partners. Another two cemetery monuments have also been added taking our tally to 93. **Cemeteries** therefore remain a priority for us.

Over the coming year we will continue to provide support and advice where we can, recognising that resources across the heritage sector are increasingly stretched. We will encourage local authorities to use the **legal tools** available to them to protect heritage assets, and will help find sustainable solutions to the numerous **public buildings** on our Register, many of which are no longer in use. We will also strive to protect **town centre conservation areas**, where the challenge is to accommodate significant growth in a positive way. We look forward to working with our partners to meet these challenges.

#### **Rebecca Barrett** Principal Adviser, Heritage at Risk

**Cover image:** The six sphinxes that flank the terrace steps in **Crystal Palace Park** date from the mid-19th century. They were part of Sir Joseph Paxton's vision to create an ambitious landscape setting for the 'crystal palace'. In 1936 the 'palace' burnt down and years of under investment followed. The London Borough of Bromley and the Mayor of London have now committed £2.4 million to improve the Grade II\* registered park. As part of this, the sphinxes will be conserved.



# Garrison Church of St George Greenwich



# Background and history

St George's Church was built in 1863 to serve the Royal Artillery Barracks in Woolwich. It was an ambitious building, designed by Thomas Henry Wyatt in an Italianate style. Most impressive was the richly decorated interior, with mosaics, inlaid marble

and tiled inscriptions around the apse. The centrepiece was the mosaic of George and the Dragon, flanked by marble tablets commemorating artillery men awarded the Victoria Cross.

Sadly, much of the building was destroyed by a V2 flying bomb in 1944. Fortunately the apse with its rich decoration survived.

#### Is it at risk?

Now a roofless ruin, these decorative finishes have been exposed to the elements for 70 years. A temporary tin roof provided limited protection. As a result St George's was added to the Heritage at Risk Register in 2000.

#### What's the current situation?

In 2011 the site was acquired by Heritage of London Trust Operations (HOLT Ops). With funding from Historic England the mosaics have been meticulously conserved. The tiles were carefully cleaned and loose elements re-secured. The tops of the walls were also repaired to prevent water ingress. The mosaics are now protected by a permanent roof, funded by the Heritage Lottery Fund.

Despite this progress, there are still significant challenges. The decorative marble and tiles in the apse require urgent attention and further funding is needed. Historic England will continue to work closely with HOLT Ops and the Friends Group to secure these repairs, ensuring that St George's continues to serve the local community as a place of commemoration for years to come.

# Harmondsworth Barn Hillingdon

### **Background and history**

Built in 1427, Harmondsworth Barn is a medieval timberframed building of huge proportions. It ranks alongside the Houses of Parliament and Westminster Abbey given its exceptional architectural and historic importance.

For almost 600 years the barn remained in agricultural use. But in 2006 it was bought as a speculative investment and its condition deteriorated. Roof tiles started to slip and plants took root in the brick and stone plinth.

### Is it at risk?

The barn was added to the Heritage at Risk Register in 2008.

Following lengthy negotiations the building was sold to English Heritage. Work started immediately on an ambitious restoration project. The vast roof was re-tiled with handmade clay peg tiles. Structural repairs were carried out to the timber frame and the rare medieval weatherboarding was sensitively conserved. Throughout the project there were opportunities for training in traditional building skills. With repairs complete,



Harmondsworth Barn was removed from the Heritage at Risk Register this year.

### What's the current situation?

The barn is managed on a day-to-day basis by an active Friends Group. Open days allow visitors to appreciate its sheer scale and outstanding medieval carpentry.

# Historic England Angel Awards

The Historic England Angel Awards were founded in 2011, co-funded by the Andrew Lloyd Webber Foundation. They celebrate local people's extraordinary efforts to save historic buildings and places. Over the past five years, the Angel Awards have showcased inspirational friends groups, communities, worshippers, owners and craftspeople.

From 2016, we'll be looking for projects that champion the historic environment in many ways. These could include:

- community action projects
- heritage research, survey or education projects
- heritage professionals
- lifetime achievements
- and of course, rescues of heritage sites

Shortlisted Angels will continue to be put to the vote in the ever-popular People's Favourite Award.

Look out for news at www.HistoricEngland.org.uk/ AngelAwards

## For more information contact:

Rebecca Barrett, Historic England London 1 Waterhouse Square, 138-142 Holborn, London, EC1N 2ST Telephone: 020 7973 3700 Email: London@HistoricEngland.org.uk Twitter: @HE\_LondonAdvice For a different format of this document contact our customer services department on:

Telephone: 0370 333 0608 Textphone: 0800 015 0516 Email: customers@HistoricEngland.org.uk Product code: 51992

Find out what's at risk by searching or downloading the online Heritage at Risk Register at: HistoricEngland.org.uk/har

# THE REGISTER Content and criteria

# DESIGNATION Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the <u>National</u> <u>Heritage List for England</u> (NHLE), an online searchable database of designated assets. Since I 882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

# LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Culture Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II\* and II. Grade I buildings are of outstanding interest, and II\* are particularly

important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are over 376,000 listed entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

# SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,850 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not designated. Instead, they are managed through the planning system and other regimes.

# REGISTERED PARKS AND GARDENS

There are 1,635 designed landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II\*, and the Gardens Trust on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

# **REGISTERED BATTLEFIELDS**

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

# PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

# CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For almost 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,853 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

# Criteria for inclusion on the Register

# **RISK ASSESSMENTS**

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of designation. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

# **BUILDINGS AND STRUCTURES**

To be considered for inclusion on the Register, buildings or structures must be:

- designated and included on the National Heritage List for England
- a grade I or II\* listed building
- a grade II listed building in London
- a structural scheduled monument with upstanding remains
- in secular (non-worship) use

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

# PLACES OF WORSHIP

To be considered for inclusion on the Register places of worship must be designated and listed grade I, II\* or II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

# ARCHAEOLOGY

To be considered for inclusion on the Register archaeological sites must be designated as scheduled monuments and included on the National Heritage List for England. Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it ranging from 'extensive significant problems', to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

# PARKS AND GARDENS

To be considered for inclusion on the Register parks and gardens must be designated as grade I, II\* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

# BATTLEFIELDS

To be considered for inclusion on the Register battlefields must be designated and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings
- pressures of particular use within the site e.g. arable cultivation
- damage e.g. unregulated metal detecting

Battlefields are removed from the Register either when damaging activities cease, are managed, or when threats recede due to effective planning.

## WRECK SITES

To be considered for inclusion on the Register wrecks must be designated and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

## **CONSERVATION AREAS**

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Reducing the risks

One of the primary aims of the Historic England Corporate Plan 2015-2018 is reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grants to help remove heritage from the Register

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website,

www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

# **BUILDINGS AND STRUCTURES**

Our nine regional teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. Historic England can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk for all asset types and Section 17 Management Agreements which are smaller grants for scheduled monuments. More information on funding can be found on the <u>Historic England</u> website.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with Civic Voice and voluntary groups to enable the compilation of local heritage at risk registers. We are also working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our Heritage at Risk Solicitor can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and fund their regional support officers to work across the country. They help BPTs and other not-for-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The <u>United Kingdom Association of Preservation Trusts</u> also provides information about support officers and BPTs. Guidance and case studies are available on the <u>Historic England</u> website.

# PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Cooperatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the <u>Grants for Places</u> of <u>Worship</u> scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. Historic England's architects and surveyors, based in our regional Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants. The Government's Listed Places of Worship Roof Repair Fund offers grants to help make listed places of worship weathertight, safe and open for use.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. <u>New Work in Historic Places of Worship</u> helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part funded by Historic England, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

# ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,832 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This is especially important under the New Environmental Land Management Scheme (NELMS) which commenced in 2015. Natural England shared our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015, which was achieved with 35% being removed. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project will provide updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in over 130 entries being removed from the 2014 Register.

Analysis of entries on the Register shows that prehistoric barrows are one of the most 'at risk' types of archaeological site on the Register. Unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

# PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

## BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II\*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

# WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems. In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival.

Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from <u>Historic England</u>.

# CONSERVATION AREAS

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management. Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them as well as those of us whose job it is to manage them or make decisions about their future.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

# Key statistics

# **BUILDINGS AND STRUCTURES**

- Nationally, 3.9% of grade I and II\* listed buildings (excluding places of worship) are on the Register. In London the percentage is also 3.9% (64 listed secular buildings).
- 2.6% (428) of London's grade II listed secular buildings are on the Register.
- 28 building or structure entries have been removed from the 2014 London Register because their futures have been secured, and 25 have been added.
- 96% of buildings or structures on the London baseline 1991 Register have been removed because their futures have been secured.

# PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In London, 9.5% (76) are on the Register.
- 3 places of worship have been removed from the London Register following repair work, and 6 have been added.

# ARCHAEOLOGY

- 2,701 (13.6%) of England's 19,850 scheduled monuments are on the Register.
   31 (19.6%) of London's 158 scheduled monuments are on the Register.
- I archaeology entry has been removed from the 2014 London Register for a positive reason, and I has been added.
- 32.4% of archaeology entries (12) on the London baseline 2009 Register have been removed for positive reasons, compared with the national figure of 38.6%.

• Nationally, damage from arable cultivation is the greatest cause of risk affecting 39% of archaeological entries on the Register. In London the proportion is 10%. The greatest risk, to 32% of entries on the London Register is from unrestricted plant, scrub and tree growth. The national figure for plant, scrub and tree growth is 27%.

## PARKS AND GARDENS

- 94 (5.8%) of England's 1,633 registered parks and gardens are on the Register. Of the 150 registered parks and gardens in London, 9 (6.0%) are on the Register.
- I park and garden entry has been removed from the 2014 London Register for a positive reason, and none have been added.

# BATTLEFIELDS

• Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. The only registered battlefield in London is not on the Register.

# WRECK SITES

• Of the 49 protected wreck sites around England's coast, 4 (8.2%) are on the Register. London has no protected wreck sites.

# CONSERVATION AREAS

- 8,298 of England's 9,853 conservation areas have been surveyed by local authorities and 505 (6.1%) are on the Register. Of the 1,015 conservation areas in London, 954 have been surveyed and 62 (6.5%) are on the Register.
- 2 conservation areas have been removed from the 2014 London Register for positive reasons, and 4 have been added.

# HISTORIC ENGLAND FUNDING

• £557,000 in grant was spent on 22 entries on the London Register during 2014/15.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

# Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – Historic England Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

Historic England's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2015 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2015 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.HistoricEngland.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

## HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit

http://www.HistoricEngland.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally. Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.HistoricEngland.org.uk .

Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address: http://list.HistoricEngland.org.uk.

# CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: <u>http://www.historicengland.org.uk/publications</u>

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological Sites on Arable Land (2004) Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Repair Grants for Heritage at Risk (2015)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2007)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

# Key to the entries

This Register includes the following risk assessment types

- Building or structure (grade I, II\* and II listed buildings and structural scheduled monuments)
- Place of worship (grade I, II\* and II listed buildings)
- Archaeology (scheduled monuments – earthworks and buried archaeology)
- Park and garden
   (Registered parks and gardens)
- Conservation area
   (Conservation areas)

# ORDER

Entries are grouped and ordered alphabetically by London borough. Within each borough, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by street and site name. Conservation areas are ordered by site name only. Parks and gardens are integrated by locality.

# DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I, II\* or II
- Listed Place of Worship grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II\* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

# CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

# OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

# VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

## PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

2014 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

## TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

# OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

# CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas and grade II listed buildings, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- HE Historic England
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

# Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON							1
Barking and Dagenham	5	1	1	0	0	0	1
Barnet	10	1	1	0	0	0	2
Bexley	2	1	0	0	0	0	0
Brent	2	0	0	0	0	0	0
Bromley	19	2	3		0	0	1
Camden	30	12	0	0	0	0	0
City of London	I	2	3	0	0	0	0
Croydon	8	5	3	0	0	0	1
Ealing	9	1	4	0	0	0	5
Enfield	9	2	1	2	0	0	2
Greenwich	15	1	0	0	0	0	0
Hackney	28	5	0	I	0	0	3
Hammersmith and Fulham	8	2	0	0	0	0	1
Haringey	14	3	0	0	0	0	5
Harrow	9	1	5	I	0	0	0
Havering	10	0	1	0	0	0	1
Hillingdon	26	0	2	0	0	0	11
Hounslow	23	1	2	I	0	0	2
Islington	16	8	0	0	0	0	11
Kensington and Chelsea	42	4	0	I	0	0	1
Kingston upon Thames	3	0	0	0	0	0	0
Lambeth	40	2	0	0	0	0	0
Lewisham	17	2	0	0	0	0	1
Merton	14	0	2	0	0	0	2
Newham	17	1	0	0	0	0	2
Redbridge	3	0	0	I	0	0	3
Richmond upon Thames	10	1	0	0	0	0	1
Southwark	34	2	2	I	0	0	1
Sutton	5	0	0	0	0	0	0
Tower Hamlets	22	7	1	0	0	0	5
Waltham Forest	10	3	0	0	0	0	0
Wandsworth	16	0	0	0	0	0	0
Westminster, City of	15	6	0	0	0	0	0
		1		1			
TOTAL	492	76	31	9	0	0	62

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

#### **GREATER LONDON**

#### BARKING AND DAGENHAM

KKING AND DAGEN			
	SITE NAME:	The Old Vicarage, Crown Street, Dagenham	House, dated 1665, and remodelled in the C19. The building is currently partly occupied and has been at risk of
	DESIGNATION:	Listed Building grade II, CA	vandalism. Planning Permission was granted in March 2013 for residential conversion into flats.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (F)	
	OWNER TYPE:	Commercial company	
toric England	LIST ENTRY NUMBER:	1064411	Contact: Daniel Pope (LPA) 020 8227 3929

The Marks Stones, Whalebone

The Warren Stone, Whalebone Lane North, Chadwell Heath

Listed Building grade II

Lane North, Chadwell Heath

Listed Building grade II

Very bad

D (New entry)

N/A

Crown

Poor

N/A

Crown

D (New entry)

1079887



© Hist

	SITE NAME:	Magistrates Court, East Street, Barking	Built in 1893 in the manner of the Flemish Renaissance. The building was in use as a magistrates' court but has been
	DESIGNATION:	Listed Building grade II, CA	empty since 2011. Planning Permission has been granted for residential conversion with commercial use on the
	CONDITION:	Good	ground floor and a contemporary extension. Works are currently underway and are due to be completed in
	OCCUPANCY:	Vacant/not in use	autumn 2015.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Government or agency	
d	LIST ENTRY NUMBER:	1359304	Contact: Daniel Pope (LPA) 020 8227 3929

© London Borough of Barking and Dagenham



© London Borough of Barking and Dagenham



© Historic England Archive



		1104004			
	LIST ENTRY NUMBER:	1184884	Contact: Daniel Pope (LPA) 020 8227 3929		
	SITE NAME:	Chadwell Heath anti-aircraft gun site, Whalebone Lane North (off), Chadwell Heath	The substantial remains of a World War II anti-aircraft battery with pits for eight guns in two groups of four and associated structures. The buildings are in an isolated spot		
200	DESIGNATION:	Listed Building grade II, CA	surrounded by a quarry and are subject to vandalism. The quarry is now being restored, including the land levels		
44	CONDITION:	Poor	around the gun site. Its future is being discussed with the Local Authority, the landowners (the Crown Estate) and		
	OCCUPANCY:	N/A	Historic England. A Heritage Lottery Fund start-up grant		
	PRIORITY CATEGORY:	C (C)	has been awarded to investigate the potential of the site with community involvement.		
P	OWNER TYPE:	Crown			
	LIST ENTRY NUMBER:	1079855	Contact: Daniel Pope (LPA) 020 8227 3929		

© London Borough of Barking and Dagenham

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

Boundary marker of the Liberty of Havering-atte-Bower, originally set up in 1642. There are two stones; one 12

inches high inscribed 'Marks Stone' and one 30 inches high

inscribed 'Marks Stone Sept 1642'. One stone is broken and in safekeeping, the other remains in its original

position. The stones are to be repaired by quarry

operators once restoration of the area is complete. A Heritage Lottery Fund start-up grant has been awarded to

investigate the potential of the site with community involvement. This entry previously appeared on the

Register under its old List Entry Number 1359307.

Boundary stone erected in 1642. The stone marked the

Warren Farm during ongoing quarrying operations. The stone will be reinstated in its original position by the quarry

finished and land levels have been restored. A Heritage

Lottery Fund start-up grant has been awarded to

investigate the potential of the site with community involvement. This entry previously appeared on the Register under its old List Entry Number 1064419.

operators as part of a planning condition once quarrying is

boundary of Hainault Forest, along with the Marks Stones and the Forest Bounds Stone. The stone is in storage at

Contact: Daniel Pope (LPA) 020 8227 3929

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ΪA
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / BARKING AND DAGENHAM / BARNET SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

II\*, CA

C (C)

Very bad

1359302

Religious organisation



Most of this medieval church was rebuilt in 1800 in the Church of St Peter and St Paul, Strawberry Hill Gothic style, using red brick quoins and Crown Street, Dagenham dressings to frame both ashlar and random ragstone Listed Place of Worship grade panels. The wide-span nave has a fine open-truss roof. The chancel and north chapel are medieval, finished with render over ragstone. The interior of the church has been reordered. The tower roof and sound lantern are in very poor condition and access is difficult. A programme of masonry repairs is required. The church is also considering an extension to provide toilets and a kitchen.

Contact: lan Harper 020 7973 3786

© Historic England

SITE NAME:	Barking Abbey		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003581
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Chadwell Heath Anti-Aircraft Gun Site, Marks Gat	e	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Daniel Pope (LPA) 020 8227 3910

#### BARNET

© Historic England



	SITE NAME:	Tomb of John Jones, Church End, St Mary's Churchyard, Hendon NW4	Tall pedestal over base with carved fielded panels, datin from the early C18. The panels have been dismantled, exposing damaged brickwork.	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1375647	Contact: Jonathan Hardy (LPA) 020 8359 4655	



	LIST EN TRY NUMBER:	13/564/	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Tomb of Susannah Frye, Church End, St Mary's Churchyard, Hendon NW4	Chest tomb with inset angle balusters, a curved cover with carvings of funerary and heraldic imagery. The tomb has a collapsed end panel.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
C.	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1375651	Contact: Jonathan Hardy (LPA) 020 8359 4655

© Historic England

PRIORITY CATEGORIES

implemented.

А

В

С

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid deterioration or loss of fabric;

Slow decay; no solution agreed.

solution agreed but not yet

D	Slow decay; solution agreed but	F

Е

not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

Contraction of the second	SITE NAME:	The Bothy, East End Road, Finchley N3	Garden compound in the grounds of Avenue House, comprising summer house, living accommodation and
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	storage. Completed in 1882. The building is currently vacant although permission for re-use by a charity has beer granted. Proposals for the restoration of the Bothy are in
	CONDITION:	Fair	progress, with funding from the Heritage Lottery Fund.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
Historic England	LIST ENTRY NUMBER:	1387534	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	The Water Tower, East End Road, Finchley N3	Water tower, circa 1880, built of massed concrete. The structure has been neglected for many years. The
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	overgrown ivy, which may have contributed to the large cracks in the concrete, has been removed. Restoration of the water tower is now underway, as part of a wider
	CONDITION:	Very bad	project at Avenue House, with funding from the Heritage Lottery Fund.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Charity (heritage)	
Historic England	LIST ENTRY NUMBER:	1387524	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	College Farm - main building, Fitzalan Road N3	Stables, teashop and dairy, built in 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy
1	DESIGNATION:	Listed Building grade II, CA	farm of the Express Dairy Company. The site has been acquired by the College Farm Trust.
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
Historic England	LIST ENTRY NUMBER:	1359127	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	College Farm Dairy, Fitzalan Road N3	Dairy built in 1883 to the design of Frederick Chancellor, with an ornate timber lantern roof and decorative tilework
	DESIGNATION		to the interior. The condition of the building is



DESIGNATION: Listed Building grade II, CA deteriorating. The site has been acquired by the College Farm Trust. See also entry for College Farm main building. CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1064789 Contact: Jonathan Hardy (LPA) 020 8359 4655

© Historic England

© Historic England



	SITE NAME:	Silo, Fitzalan Road, College Farm N3	Silo built in 1883 to the design of Frederick Chancellor as part of the Express Dairy Company's pioneering model
	DESIGNATION:	Listed Building grade II, CA	farm. The condition of the building is deteriorating. The site has been acquired by the College Farm Trust. See also
	CONDITION:	Fair	entry for College Farm main building.
	OCCUPANCY:	N/A	
HILLIN	PRIORITY CATEGORY:	C (C)	
IS.	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1359128	Contact: Jonathan Hardy (LPA) 020 8359 4655

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 / LONDON / BARNET

© Historic

SITE NAME:	Monument to Major John Cartwright, St Mary at Finchley Churchyard, Hendon Lane N3	Monument erected in 1835 to Major John Cartwright by public subscription. Built of yellow oolitic limestone, with a square tapering obelisk and armorial and portrait roundels.
DESIGNATION:	Listed Building grade II, CA	The monument has been dismantled due to its dangerous condition and plans for restoration are under discussion.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1246062	Contact: Jonathan Hardy (LPA) 020 8359 4655
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Cartwright, St Mary at Finchley Churchyard, Hendon Lane N3DESIGNATION:Listed Building grade II, CACONDITION:PoorOCCUPANCY:N/APRIORITY CATEGORY:A (A)OWNER TYPE:Local authority

SITE NAME: Railway Hotel including sign in The Railway Hotel dates from 1931 and was designed by AE Sewell for the brewers, Truman Hanbury Buxton. It is a front and former off-sales large, prominent, three storey half-timbered roadhouse building to west, Station Road, and one of the best examples of its type in the country. It Edgware has been closed as a public house for over six years. The DESIGNATION: Listed Building grade II listing includes the former off-sales building to the west and the gibbet sign on the frontage. A scheme to restore and CONDITION: Fair extend the building for hotel use has been approved although not implemented. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (D) © Historic England OWNER TYPE: Private LIST ENTRY NUMBER: 1096066 Contact: Jonathan Hardy (LPA) 020 8359 4655



	SITE NAME:	Church of St Jude, Central Square, Hendon NWI I	Designed by Sir Edwin Lutyens, St Jude's was consecrated in 1911 with the west end finally completed in 1935. There
	DESIGNATION:	Listed Place of Worship grade I, CA	are frescoes throughout by Walter Starmer, dating from 1919-30. Built in grey and red brick with stone dressings and clay tiled roofs. It has a tall open tower and spire. The
	CONDITION:	Poor	church has damp issues, including the crypt which is prone to flooding. There is cracking evident internally and some areas of the frescoes are suffering from salt damage.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	Localised repairs are required to the brickwork and the roofs. The heating system requires overhauling.
	LIST ENTRY NUMBER:	1294714	Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Brockley Hill Romano-British pottery and settlement		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	College Farm, Finchley N3		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / BARNET / BEXLEY / BRENT

SITE NAME:	Hampstead Garden Suburb - The Bishops Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655

#### BEXLEY

	SITE NAME:	Crossness Pumping Station, Belvedere Road SE28	Opened 4 April 1865; the engineer was Joseph Bazalgette. The building retains important cast iron interior fittings and
	DESIGNATION:	Listed Building grade I, CA	four colossal beam engines by James Watt and Co. The Crossness Engines Trust is restoring the building, with
	CONDITION:	Good	funding from the Heritage Lottery Fund. Work is expected to finish in 2015.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
storic England	LIST ENTRY NUMBER:	1064241	Contact: Elizabeth Whitbourn 07889 808145

© Historic England

	SITE NAME:	Chapel House, 497, Blackfen Road, Sidcup	An eye-catcher as part of the layout of Danson Park, circa 1761 and attributed to Lancelot 'Capability' Brown. The
	DESIGNATION:	Listed Building grade II	Chapel House is now separated from the park by the A2 trunk road and modern houses. Some render repairs have
	CONDITION:	Fair	been carried out. The building forms part of a larger extant redevelopment scheme, which if implemented will result in
	OCCUPANCY:	Part occupied/part in use	the building being refurbished and brought back into
	PRIORITY CATEGORY:	D (D)	sustainable use.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1064248	Contact: Gordon Fraser (LPA) 020 3045 5789

© Historic England



SITE NAME:	Parish Church of St Paulinus, Perry Street, Bexley	St Paulinus dates from the CII when the church was in the form of a simple two-cell building on the footprint of the
DESIGNATION:	Listed Place of Worship grade II*, CA	current north nave. By 1220 a parallel nave was added on the south side, later arcaded. A western tower was added in the 1430s. An eastern chapel houses fine C17
CONDITION:	Poor	monuments and the marble reredos in the chancel dates from the C19 restoration. The church has been awarded a
PRIORITY CATEGORY:	D (C)	Heritage Lottery Fund grant to repair the flint walling, the
OWNER TYPE:	Religious organisation	tower stonework and the drainage system, which has caused much dampness in the lower walls.
LIST ENTRY NUMBER:	1359434	Contact: Ian Harper 020 7973 3786

© Historic England

BRENT			
	SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6	Built in 1863 as St James's Episcopal Chapel. It is a prefabricated structure of corrugated iron with boarded
	DESIGNATION:	Listed Building grade II, CA	roof covered in corrugated asbestos. A planning application has been submitted for a new residential building alongside
	CONDITION:	Poor	and conservation works to the hall.
ATT	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
8	OWNER TYPE:	Other not for profit group	
© Historic England	LIST ENTRY NUMBER:	1271962	Contact: Mark Price (LPA) 0208 937 5236

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 / LONDON / BRENT / BROMLEY

	SITE NAME: Old C Road,	Old Oxgate Farm, Coles Green Road, Cricklewood NW2	C16 and C17 timber-framed building suffering from subsidence to the brick plinth and structural failure of beam
	DESIGNATION:	Listed Building grade II*	ends to the ground floor due to damp penetration. The owner carried out urgent works in 2013 and is exploring
	CONDITION:	Poor	possible solutions for full repair.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1078875	Contact: Elizabeth Whitbourn 07889 808145

© Historic England

#### BROMLEY

© Historic England	7	SITE NAME:	Crystal Palace Park SE19	C19 pleasure grounds designed by Sir Joseph Paxton as a
		DESIGNATION:	Registered Park and Garden grade II*, 7 LBs, part in CA	setting for the Crystal Palace (re-erected here 1852-4 and burnt down in 1936). The park is in variable condition and the grade II listed terraces, pedestrian subway and railings
	and the second second	CONDITION:	Generally satisfactory but with significant localised problems	are also at risk. The Mayor of London and Bromley Council have committed £2.4 million towards the implementation of six priority projects in the park. Works will begin in
		VULNERABILITY:	Medium	2015, including the conservation of the sphinxes and
	ALL CANADA	TREND:	Improving	improvements to the central axis, which is a key elemen the historic designed landscape.
		NEW ENTRY?:	No	
	OWNER TYPE:	Local authority		
		LIST ENTRY NUMBER:	1000373	Contact: Zosia Mellor 020 7973 3473



	and the second s
© Historic England	

	LIST ENTRY NUMBER:	1000373	Contact: Zosia Mellor 020 7973 3473
1	SITE NAME:	Pedestrian subway under Crystal Palace Parade, Crystal Palace SE19	Pedestrian subway circa 1854. A condition survey and investigative works have been carried out, grant-aided by Historic England. Discussions are now underway to secure
	DESIGNATION:	Listed Building grade II, RPG grade II*	necessary repairs to the structure and to think about its temporary and long-term use.
	CONDITION:	Poor	
4	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1385457	Contact: Kevin Munnelly (LPA) 020 8313 4582



© Historic England

SITE NAME:	North and south railings, Crystal Palace Parade, Crystal Palace Park SE19	Decorative cast iron railings on gault brick plinths with stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in	
DESIGNATION:	Listed Building grade II, RPG grade II*	1936) from Crystal Palace Parade. There is damage to some cast iron panels and the dwarf wall. A condition survey of the railings has been commissioned, with fur	
CONDITION:	Poor	from Historic England.	
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	C (C)		
OWNER TYPE:	Local authority		
LIST ENTRY NUMBER:	1393659	Contact: Kevin Munnelly (LPA) 020 8313 4582	

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / BROMLEY

LI

SITE NAME:

DESIGNATION:

CONDITION:

LIST ENTRY NUMBER:



© Historic England Archive

書

© Historic England

SITE NAME:	Upper and Lower Terraces, Crystal Palace Park SE19	Terraces designed by Sir Joseph Paxton and situated to the east of the site of Crystal Palace (re-erected here in 1852-4
DESIGNATION:	Listed Building grade II, RPG grade II*, CA	and burnt down in 1936), on the west of Crystal Palace Park. The terraces are in a ruinous condition and suffering from erosion. A condition survey of the sphinxes and south
CONDITION:	Poor	terrace steps was undertaken in 2013, grant-aided by Historic England. Funding has now been secured from the Local Authority and the Mayor of London to conserve the
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	D (C)	six sphinxes. Works are due to start in 2015.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1064352	Contact: Kevin Munnelly (LPA) 020 8313 4582

Offices, cutting shop, tool room and storage factory. Completed in 1937 to the designs of Wallis Gilbert and Partners for Richard Klinger Ltd, founded in Austria in

Crittal window frames are intact, but the interior is dilapidated. The current owner is marketing the property

and it is understood that there is interest.

Contact: Kevin Munnelly (LPA) 020 8313 4582

1893. The building has been vacant for many years. The

-	SITE NAME:	Downe Court Manor, Cudham Road, Downe	Modest red brick house of 1690. The building is currently vacant and starting to show the effects of long term
	DESIGNATION:	Listed Building grade II	neglect. Roof and joinery repairs have been undertaken to arrest the decline of the building.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
A State of the second second	OWNER TYPE:	Private	
nd	LIST ENTRY NUMBER:	1064357	Contact: Kevin Munnelly (LPA) 020 8313 4582

Frontage building to Richard Klinger Factory, Edgington Way,

Listed Building grade II

Sidcup

Poor

Private

1359319



© Lo	ndon	Boroug	h of	Brom	ıley
------	------	--------	------	------	------



OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1387704 Contact: Kevin Munnelly (LPA) 020 8313 4582 SITE NAME: Pair of mid-C19 stuccoed houses suffering from structural 20-22, Hamlet Road, Crystal problems. Some urgent works have been undertaken, Palace SEI9 including the removal of a tree from the front garden and DESIGNATION: Listed Building grade II, CA the erection of additional scaffolding. Discussions are ongoing with regards to further remedial works required to CONDITION: Poor stabilise the buildings, as well as a longer-term OCCUPANCY: Vacant/not in use development scheme. PRIORITY CATEGORY: A (A)

© Historic England



			, , , ,
	SITE NAME:	91, High Street, St Mary Cray	C16 dwelling with crown post roof. The building is in a very
	DESIGNATION:	Listed Building grade II, CA	poor condition and at risk of collapse. Listed Building Consent has been granted for the restoration of the
	CONDITION:	Very bad	property for residential use.
TT of	OCCUPANCY:	Vacant/not in use	
IT ST	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1298993	Contact: Kevin Munnelly (LPA) 020 8313 4582

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

use)

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / BROMLEY

	SITE NAME:	The Royal Bell Hotel, 173-177, High Street, Bromley	This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is vacant and
8 8 8 8 8 8 8 8	DESIGNATION:	Listed Building grade II, CA	boarded up. Discussions are ongoing regarding its future re-use.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (E)	
A THE A THE	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1054095	Contact: Kevin Munnelly (LPA) 020 8313 4582



1	SITE NAME:	Former Officers' Mess, RAF Biggin Hill, Main Road, Biggin Hill	Officers' mess, circa 1935. Partially occupied but suffering neglect due to the cost of repairs and maintenance. Some works have been carried out. Planning Permission and
3	DESIGNATION:	Listed Building grade II, CA	Listed Building Consent have been granted for conversion to a hotel.
PIN THE	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
加限	PRIORITY CATEGORY:	D (D)	
1	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1416723	Contact: Robert Buckley (LPA) 020 8461 7532

© Historic England



© London Borough of Bromley

	SITE NAME:	Building 12 (Candidates' Club, Former Sergeants' Mess), West Camp, Main Road, A233 (east side), Biggin Hill	Sergeants' mess, dating from 1932. Built by the Air Ministry's Directorate of Works and Buildings, but vacant since the RAF withdrew from Biggin Hill in 1993. The Local Authority is actively looking at options and is working with
	DESIGNATION:	Listed Building grade II, CA	Historic England and the owners to explore possible new uses.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
in the second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1391606	Contact: Kevin Munnelly (LPA) 020 8313 4582

	West Camp, Main Road, A233 (east side), Biggin Hill Directorate of Works and RAF withdrew from Biggin Authority is actively looking	Barrack block dated 1934. Built by the Air Ministry's Directorate of Works and Buildings, but vacant since the RAF withdrew from Biggin Hill in 1993. The Local	
	DESIGNATION:	Listed Building grade II, CA	Authority is actively looking at options and working with Historic England and the owners to explore possible new
	CONDITION:	Poor	uses.
	OCCUPANCY:	Vacant/not in use	
-	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© London Borough of Bromley	LIST ENTRY NUMBER:	1391604	Contact: Kevin Munnelly (LPA) 020 8313 4582



All g	SITE NAME:	Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill	Office block dated 1931, formerly the station headquarters building. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. The Local Authority is
-Aug	DESIGNATION:	Listed Building grade II, CA	actively looking at options and working with Historic England and the owners to explore possible new uses.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1391587	Contact: Kevin Munnelly (LPA) 020 8313 4582

#### PRIORITY CATEGORIES

© London Borough of Bromley

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Buildings I-5 (Airmen's barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill	Group of five airmen's barracks blocks, dating from 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill in 1993. The Local Authority is actively looking at options and working with Historic England and
	DESIGNATION:	Listed Building grade II, CA	the owners to explore possible new uses.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
- A - A - Containing	PRIORITY CATEGORY:	E (E)	
) London Borough of Bromley	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1391589	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	lce house to Sundridge Park, Plaistow Lane, Bromley	Ice house circa 1800, in the south west corner of a late C18 landscape park designed by Humphry Repton, now a
	DESIGNATION:	Listed Building grade II, RPG grade II	golf course. The ice house is subject to continuous vandalism despite strenuous efforts by the owners to prevent access. Discussions about its future have so far
273 3000	CONDITION:	Very bad	failed to find a suitable solution.
	OCCUPANCY:	N/A	
A MARINE AND A MARINE	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
) Historic England	LIST ENTRY NUMBER:	1254001	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	The Convent of the Holy Trinity, Plaistow Lane, Bromley	House built by John Hulls around 1708 and since 1888 used as a convent and school. The building is currently
	DESIGNATION:	Listed Building grade II	vacant and covered in order to protect it against the elements. Planning Permission and Listed Building Consen
	CONDITION:	Fair	have been granted to convert the building into flats
	OCCUPANCY:	Vacant/not in use	works are underway.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
) London Borough of Bromley	LIST ENTRY NUMBER:	1186782	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	lce house to Old Palace, Stockwell Close, Bromley Palace Park	Ice house to Bromley Old Palace, located in the gardens of the Palace at the southern end of the ornamental lake nea the waterfall. Probably late C18, remodelled in the early
	DESIGNATION:	Listed Building grade II	C19 as a garden shelter, possibly used as a stopping-off
	DESIGNATION: CONDITION:		C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have
		Listed Building grade II	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the
	CONDITION:	Listed Building grade II Poor	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and
	CONDITION: OCCUPANCY:	Listed Building grade II Poor N/A	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the
Pistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II Poor N/A C (D)	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the
Pistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Listed Building grade II Poor N/A C (D) Local authority	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palac
Historic England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Listed Building grade II Poor N/A C (D) Local authority 1281268 Pulhamite fernery, Stockwell	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace that had been acquired by Coles Child, a wealthy coal
Pistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Listed Building grade II Poor N/A C (D) Local authority 1281268 Pulhamite fernery, Stockwell Close, Bromley Palace Park	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 a part of the improvements to the gardens of Bromley Palac
Historic England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Listed Building grade II Poor N/A C (D) Local authority 1281268 Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building grade II	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 a part of the improvements to the gardens of Bromley Pala that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the
Fistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Listed Building grade II Poor N/A C (D) Local authority 1281268 Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building grade II Poor	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 a part of the improvements to the gardens of Bromley Pala that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the
Pistoric England	CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Listed Building grade II Poor N/A C (D) Local authority 1281268 Pulhamite fernery, Stockwell Close, Bromley Palace Park Listed Building grade II Poor N/A	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a perambulation of the grounds. Considerable repairs have been undertaken but further vegetation clearance and stabilisation works are needed to the roof above the chamber itself. Contact: Kevin Munnelly (LPA) 020 8313 4582 Pulhamite rock-work garden feature constructed c1865 a part of the improvements to the gardens of Bromley Pala that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Pulhamite waterfall, Stockwell Close, Bromley Palace Park	Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palac
	DESIGNATION:	Listed Building grade II	that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end, adjacent to
	CONDITION:	Poor	a probably late C18 ice house, and is in need of repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
Start 11	OWNER TYPE:	Local authority	
D Historic England	LIST ENTRY NUMBER:	1392583	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Old Town Hall, Tweedy Road,	Former Town Hall building built in 1906 and used as premises for Bromley College until 2006/07. The building
	DESIGNATION:	Bromley Listed Building grade II, CA	is partially vacant and awaiting a suitable use. The building Authority is working with a development partner to bring

and the second second	DESIGNATION:	Liste
A	CONDITION:	Fair
	OCCUPANCY:	Part
	PRIORITY CATEGORY:	E (E)
	OWNER TYPE:	Loca
© Historic England	LIST ENTRY NUMBER:	1299

SITE NAME:	Old Town Hall, Tweedy Road, Bromley	Former I own Hall building built in 1906 and used as premises for Bromley College until 2006/07. The building
DESIGNATION:	Listed Building grade II, CA	is partially vacant and awaiting a suitable use. The Local Authority is working with a development partner to bring
CONDITION:	Fair	forward a proposal to convert the building to a hotel. Planning and Listed Building Consent applications have now
OCCUPANCY:	Part occupied/part in use	been submitted (spring 2015).
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1299012	Contact: Kevin Munnelly (LPA) 020 8313 4582



© Historic England

© Historic England



St Mary Cray Drick and stone dressings and tiled root. The spire of the	SITE NAME:	Church of St Mary, High Street, St Mary Cray	Church built between the C13 and C15 in flint rubble with brick and stone dressings and tiled roof. The spire of the
DESIGNATION: Listed Place of Worship grade II*, CA tower is tiled in cedar wood shingles which have curled badly and are slipping off the roof. The church is also suffering from dampness and it is suspected that the drain	DESIGNATION:		tower is tiled in cedar wood shingles which have curled badly and are slipping off the roof. The church is also suffering from dampness and it is suspected that the drains
CONDITION: Poor are in need of attention. The congregation is actively exploring options for funding to repair the spire roof,	CONDITION:	Poor	are in need of attention. The congregation is actively
PRIORITY CATEGORY: C (New entry) associated stonework and rainwater goods.	PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE: Religious organisation	OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER: 1045813 Contact: Ian Harper 020 7973 3786	LIST ENTRY NUMBER:	1045813	Contact: Ian Harper 020 7973 3786

	SITE NAME:	Church of St John the Evangelist, High Street, Penge SE20	Church by John Nash and Edwin Nash of Bermondsey in the Early English style, completed in 1849. Built of ragstone with Bath stone dressings, including spire. The church is
	DESIGNATION:	Listed Place of Worship grade II, CA	suffering from water ingress at roof and lower levels, and dampness at lower levels. High level repairs to the east end were completed in 2013, grant-aided by Historic England
	CONDITION:	Poor	and the Heritage Lottery Fund. A second phase of repairs is required to the west end and the congregation is
	PRIORITY CATEGORY:	C (C)	currently exploring ways to fund these works.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1186832	Contact: Ian Harper 020 7973 3786

SITE NAME:	Iron Age settlement and Roman villa at Warbank, Keston			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002024	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
		CONTACT		
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145	
OWNER TYPE: SITE NAME:	Private, multiple owners Scadbury Manor moated site and fishponds	CONTACT:	Elizabeth VVnitbourn 07889 808145	
	· •	LIST ENTRY NUMBER:	1409786	
SITE NAME:	Scadbury Manor moated site and fishponds			
SITE NAME: DESIGNATION:	Scadbury Manor moated site and fishponds Scheduled Monument, CA	LIST ENTRY NUMBER:	1409786	

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / BROMLEY / CAMDEN

SITE NAME:	Romano-British masonry building and Saxon cemetery, Fordcroft, Orpington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001973
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Biggin Hill RAF		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Kevin Munnelly (LPA) 020 8313 4582

#### CAMDEN

© Historic England



Late C19 granite cattle trough. Placed by the Metropolitan SITE NAME: Cattle trough to south east of the Roundhouse, Chalk Farm Cattle Trough and Drinking Fountain Association in Road NW1 memory of the Christian Socialist Charles Kingsley. Some repairs have been carried out but investigation into the DESIGNATION: Listed Building grade II, CA security of the trough on the plinth is required. It is vulnerable given its location adjacent to the bus lane and CONDITION: Poor bus stop. OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER 1258104 Contact: Alan \A/ita (I PA) 020 7974 6392



	LIST ENTRY NORBER.	1238104	Contact: Alan VVIto (LPA) 020 7974 6392
SITE NAME: DESIGNATION:	SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NWI	Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but the drinking fountain remains prone to littering and damage. Options for repair are being explored with the relevant partner
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	organisations.
OCCUPANCY:	N/A		
1	PRIORITY CATEGORY:	C (C)	
N. Roberton	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1258105	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England



	SITE NAME:	Stanley Sidings: stables (inc. stables A, B, C, D), Chalk Farm Road NWI	Important complex of industrial stabling built 1883-1895 for the Camden Goods Yard of the London and North Western Railway. Some repairs have been carried out to
DESIGNATION:	Listed Building grade II, CA	the Tack Room, including the renewal of the roof. Applications for remedial works to the Provender Store,	
	CONDITION:	Fair	which was fire damaged in 2014, are currently being considered by the Local Authority.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
10	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1258101	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



SITE NAME:	Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3	Stone stele from the mid-C19 with flanking angels holding a cross and an inscription. The monument is leaning heavily, but propping has secured it temporarily. Listed Building
DESIGNATION:	Listed Building grade II, CA	Consent has been granted for structural repairs.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	В (В)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1067360	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

	SITE NAME:	Former Strand Union Workhouse (Middlesex Hospital Annex), 44, Cleveland Street W1	Former Strand Union Workhouse, dating from 1778, wi an austere symmetrical brick building facing Cleveland Street behind later high brick walls. Vacated by Universit College London Hospital and in temporary occupation b live-in guardians and site staff in the adjoining unlisted buildings. The buildings are weathertight and secure;
FE E E III	DESIGNATION:	Listed Building grade II, CA	
MILL I	CONDITION:	Fair	negotiations regarding the redevelopment of the site are ongoing.
	OCCUPANCY:	Part occupied/part in use	ongoing.
	PRIORITY CATEGORY:	E (E)	
toric England	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1242917	Contact: Alan Wito (LPA) 020 7974 6392
E	SITE NAME:	26, Denmark Street WC2	Early C18 terraced house; windows altered in the C20.
RAA E	SITE NAME: DESIGNATION:	26, Denmark Street WC2 Listed Building grade II, CA	There is a bar on the ground floor. The windows, parapets and gutters are still in poor condition. Listed Building
iii H		,	There is a bar on the ground floor. The windows, parapets and gutters are still in poor condition. Listed Building Consent and Planning Permission have been granted as
	DESIGNATION:	Listed Building grade II, CA	There is a bar on the ground floor. The windows, parapets and gutters are still in poor condition. Listed Building
	DESIGNATION: CONDITION:	Listed Building grade II, CA Poor	There is a bar on the ground floor. The windows, parapets and gutters are still in poor condition. Listed Building Consent and Planning Permission have been granted as part of a wider scheme which includes residential use on

© Historic England

© Historic

© His

	SITE NAME:	The Elms (formerly Elm Lodge), Fitzroy Park N6	Detached house built 1838-40 to the design of George Basevi. A listed building enforcement notice was served in 2012 following unauthorised works during refurbishment. The Local Authority is in receipt of Planning and Listed
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	Building Consent applications for remedial works, but these are not yet determined.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
THE REAL PROPERTY AND A DECIMAL OF THE REAL PROPERTY AND A DECIMAL PROPERTY AND A DECIMAL OF THE REAL PROPERTY AND A DECIMAL PROPERTY AND A DEC	OWNER TYPE:	Commercial company	
ic England	LIST ENTRY NUMBER:	1078355	Contact: Alan Wito (LPA) 020 7974 6392

One of a terrace of four houses, dating from the late C18, constructed from darkened multi-coloured stock brick with some stucco dressings. Comprising four storeys and basements. The property is partially occupied and in a deteriorating condition.

Contact: Alan Wito (LPA) 020 7974 6392

Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

1271982

43, Fitzroy Street WI

Poor

A (A)

Private

1322184

Listed Building grade II, CA

Part occupied/part in use

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	39, Great James Street WCI	One of a terrace of 14 houses, dating from 1720-24,
	DESIGNATION:	Listed Building grade II*, CA	comprising four storeys and basement, constructed from brown brick. The property is currently empty. Listed
	CONDITION:	Poor	Building Consent and Planning Permission were granted in 2011 for refurbishment and a rear extension. The
	OCCUPANCY:	Vacant/not in use	consented scheme has not been implemented and no
	PRIORITY CATEGORY:	B (B)	repairs have been undertaken.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1113203	Contact: Elizabeth Whitbourn 07889 808145

© Historic England



SITE NAME:	Ladies and gentlemen's public conveniences, Guilford Place WC1	Disused late C19 public lavatory sited on a traffic island. Enriched railings and gates with overthrows and lanterns. Options for future use are currently being explored
DESIGNATION:	Listed Building grade II, CA	through a marketing exercise (summer 2015).
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Educational (state sector)	
LIST ENTRY NUMBER:	1245849	Contact: Alan Wito (LPA) 020 7974 6392

	LIST ENTRY NUMBER:	1245849	Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	66, Guilford Street WCI	One of a terrace of houses built circa 1793-99 by James
	DESIGNATION:	Listed Building grade II, CA	Burton. Planning Permission and Listed Building Consent have been granted for change of use to a backpackers'
	CONDITION:	Fair	hostel. The works have not yet started.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1245858	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

summer of

m late	SITE NAME:	67, Guilford Street WCI	Part of a terrace of houses built circa 1793-99 by James
	DESIGNATION:	Listed Building grade II, CA	Burton. Planning Permission and Listed Building Consent have been granted for change of use to a backpackers'
	CONDITION:	Fair	hostel. The works have not yet started.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1245860	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

a fair and	SITE NAME:	82, Guilford Street WCI	Terraced house built circa 1793-99 by James Burton.
	DESIGNATION:	Listed Building grade II, CA	Consent was granted in 2012 for internal works and change of use to residential. The consented scheme is
	CONDITION:	Fair	currently being implemented and is due for completion in 2016.
	OCCUPANCY:	Vacant/not in use	2010.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1271620	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



1	SITE NAME:	Drinking fountain in St James Gardens, Hampstead Road NWI	Drinking fountain likely to date from the 1880s. Constructed from cast iron, the design closely resembles a pattern illustrated in Macfarlane's catalogue of circa 1880.
and a contract	DESIGNATION:	Listed Building grade II	The fountain has been temporarily removed from its plinth due to fire damage, and is being stored by the Local
	CONDITION:	Very bad	Authority with a view to its future repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1378714	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden



	SITE NAME:	I, Hawley Road NWI	Early C19 detached villa. Repairs to render and joinery on
	DESIGNATION:	Listed Building grade II	the front facade are complete and the building is now weathertight. Planning Permission and Listed Building
	CONDITION:	Fair	Consent have been granted for various internal and external works to adapt the building for educational use.
	OCCUPANCY:	Vacant/not in use	These works are in connection with the use of the building
	PRIORITY CATEGORY:	D (D)	as part of a new primary school to be built on an adjacent site. Works are due to start in 2015.
1	OWNER TYPE:	Private	
122	LIST ENTRY NUMBER:	1378820	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden



© Historic England

© Historic England

ちに	SITE NAME:	Fountain and pond in the Italianate Garden, Witanhurst, Highgate West Hill N6	Fountain set in a circular pond forming a central feature of the Italianate Garden, built circa 1913, probably to the design of Harold Peto for Sir Arthur Crosfield. Repairs to	
ALL.	DESIGNATION:	Listed Building grade II, CA	the fountain are underway.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1379027	Contact: Alan Wito (LPA) 020 7974 6392	

	SITE NAME: Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6		Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. Two are now missing; the remaining two are in storage. Repairs are underway.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
(ie)	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379028	Contact: Alan Wito (LPA) 020 7974 6392



	SITE NAME:	Italianate Garden in grounds of Witanhurst, Highgate West Hill N6	Italianate Garden comprising walls, steps, gateway, sunken pond and pergola. Built circa 1913, probably designed by Harold Peto for Sir Arthur Crosfield. Repair works are
	DESIGNATION:	Listed Building grade II, CA	nearly complete.
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
A COLOR	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379032	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2015 / LOND			
	SITE NAME:	Railings and bollards to terraced paths, Holly Hill NW3	C19 railings and bollards to terraced paths. Cast iron standards and rail with terminal bollards of cannon type
	DESIGNATION:	Listed Building grade II, CA	inscribed "St. Johns/Hampstead/B. Griffin and J. Kelly Surveyors 1828". Sections of the ironwork are missing or ir
and	CONDITION:	Poor	a poor state of repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1379076	Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	l and 2, Lincoln's Inn Fields WC2	Two early C18 terraced houses, converted to one in the C19. The building is protected by occupation. The Local
	DESIGNATION:	Listed Building grade II, CA	Authority has granted Planning Permission and Listed Building Consent for the conversion and extension of the
	CONDITION:	Fair	properties to create a single family dwelling. Works have not yet commenced.
	OCCUPANCY:	Part occupied/part in use	hot yet conmenced.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1379323	Contact: Alan Wito (LPA) 020 7974 6392
	SITE NAME:	25, Mornington Crescent NWI	House forming part of a crescent, built circa 1821-23 by I
	SITE NAME: DESIGNATION:	<b>25, Mornington Crescent NWI</b> Listed Building grade II, CA	Bryant for the Southampton Estate. Planning Permission
		-	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and
	DESIGNATION:	Listed Building grade II, CA	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for
	DESIGNATION: CONDITION:	Listed Building grade II, CA Fair	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be
	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building grade II, CA Fair Part occupied/part in use	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II, CA Fair Part occupied/part in use F (F)	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be
ø Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015.
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015. Contact: Alan Wito (LPA) 020 7974 6392 Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company 1113140 Heath House, North End Way	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015. Contact: Alan Wito (LPA) 020 7974 6392 Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company 1113140 Heath House, North End Way NW3	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015. Contact: Alan Wito (LPA) 020 7974 6392 Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The building is currently protected by a
• Aistoric England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company 1113140 Heath House, North End Way NW3 Listed Building grade II*, CA	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015. Contact: Alan Wito (LPA) 020 7974 6392 Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The building is currently protected by a temporary roof and monoflex wrapping. Discussions are ongoing with the Local Authority regarding the long-term
• Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Listed Building grade II, CA Fair Part occupied/part in use F (F) Commercial company 1113140 Heath House, North End Way NW3 Listed Building grade II*, CA Poor	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for conversion to four flats and works of repair and reinstatement. Works are in progress and should be completed in 2015. Contact: Alan Wito (LPA) 020 7974 6392 Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have been removed. The building is currently protected by a temporary roof and monoflex wrapping. Discussions are

© Historic England



and an allow	SITE NAME:	69, Oakley Square and attached railings NWI	One of a terrace of 13 houses, dating from c1845-59. Constructed from yellow stock brick with stucco dressings;
	DESIGNATION:	Listed Building grade II, CA	four storeys and basements, two windows each with prostyle porticoes. Although built as a single family
	CONDITION:	Fair	dwelling, the building was subsequently used as a women's short-stay hostel. Planning Permission and Listed Building
	OCCUPANCY:	Part occupied/part in use	Consent have been granted for the conversion of the
	PRIORITY CATEGORY:	D (D)	building to four residential units.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1322081	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

Contact: Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

OWNER TYPE:

LIST ENTRY NUMBER:

D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Commercial company

1113183

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	The 'Lighthouse' block, 295-297 (odd), Pentonville Road WC1	'Flat iron' block of shops with offices over, circa 1875, prominently situated at the junction of Gray's Inn Road and
	DESIGNATION:	Listed Building grade II, CA	Pentonville Road. The site also includes 378-380 (even) Gray's Inn Road. A tall lead clad tower at the apex gives the building its 'lighthouse' identity. A scheme has been approved for refurbishment for office and retail use. Work have started and are programmed for completion in 2015.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	3 9	Contact: Alan Wito (LPA) 020 7974 6392



© Historic England

4	SITE NAME:	Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3	Brick and stone boundary wall along Hampstead Green, dating from 1869. Repairs are complete to the wall and piers by entrances, but other areas on Rosslyn Hill and
CO OC PRIM	DESIGNATION:	Listed Building grade II, CA	fronting Hampstead Green need repairs to the stone copings and repointing. The Local Authority has approved
	CONDITION:	Poor	an application for further remedial works to part of the wall.
	OCCUPANCY:	N/A	YY GIL
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1130395	Contact: Alan Wito (LPA) 020 7974 6392



	SITE NAME:	Baptist Church House, 2-6 (even), Southampton Row WCI	Former Baptist Chapel, offices and shop built 1901-3 to the design of Arthur Keen, architect for the Baptist Union of Great Britain and Ireland. 'Wrenaissance' style with Flemish-inspired shaped gables and eclectic baroque and Arts and Crafts details. Planning Permission and Listed Building Consent were granted for restoration and conversion to a hotel. Details have been agreed with Historic England and works have commenced.
	DESIGNATION:	Listed Building grade II*, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1378782	Contact: Alan Wito (LPA) 020 7974 6392

	SITE NAME:	Toll Gate House, Spaniards Road, Highgate NW3	Late C18 toll house, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic
	DESIGNATION:	Listed Building grade II	bottleneck on a busy road and has suffered impact damage from heavy vehicles. A bollard was erected in late 2008 to
	CONDITION:	Good	provide protection from traffic. Roof and guttering repair works have been undertaken and the property is now in
	OCCUPANCY:	Vacant/not in use	good condition, but remains unoccupied.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
nd Archive	LIST ENTRY NUMBER:	1378793	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England



	LIST ENTRY NUMBER:	1378793	Contact: Alan Wito (LPA) 020 7974 6392
2	SITE NAME:	108, St Pancras Way, Kentish Town NWI	End of terrace house dating from the mid-1820s, with an early C19 shop front. The building was squatted
	DESIGNATION:	Listed Building grade II, CA	intermittently and was in a poor condition. Temporary roof repairs were carried out in early 2012. A Repairs Notice
	CONDITION:	Fair	was served in 2014 and the implementation of extant consents and remedial works in accordance with the notice
1	OCCUPANCY:	Vacant/not in use	are in progress and due for completion in September 2015.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1245848	Contact: Alan Wito (LPA) 020 7974 6392

© London Borough of Camden

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	65, Swinton Street WCI	Terraced house circa 1775, with a late C19 shop front.
DESIGNATION:	Listed Building grade II, CA	Currently unoccupied and deteriorating. The building is in very poor condition, with much of the interior removed.
CONDITION:	Very bad	Consents were granted in 2012 for conversion to a hotel and works are due for completion in 2016.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (B)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1378960	Contact: Alan Wito (LPA) 020 7974 6392

© Historic England



SITE NAME:	Eastern coal drops at Kings Cross Goods Yard, York Way NI	Coal drops built in 1851-2, probably to the design of Lewis Cubitt, to carry high level track for the transport of coal into storage bins. Part of a system of distributing coal from
DESIGNATION:	Listed Building grade II, CA	the North East and Yorkshire to the London market. Proposals for a mixed use scheme are being negotiated.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (E)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1379214	Contact: Alan Wito (LPA) 020 7974 6392



	SITE NAME:	St George's Cathedral (formerly Christ Church), Albany Street, Camden Town NWI	Former parish church. Antiochian Orthodox Cathedral since 1989. Designed by Sir James Pennethorne, built in 1837 in neo-Grecian style to serve Nash's development
	DESIGNATION:	Listed Place of Worship grade II*, CA	east of Regents Park, with later alterations. Grey stock brick with Roman cement and stone dressings. There is vegetation growth on the spire. The Roman cement
	CONDITION:	Poor	mouldings and past repairs in cementitious mortar are failing in places. Cracking is evident, particularly on the
	PRIORITY CATEGORY:	A (A)	principal south elevation.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1378620	Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Church of St Michael, Camden Road, Camden Town NWI	The nave and aisles were built in 1881 designed by GF Bodley and T Garner, the chancel was added in 1894 and
	DESIGNATION:	Listed Place of Worship grade II*	the vestries in 1908. Bodley's altar, reredos, stone chapel vaulting and screen survive. The church has undergone structural and stonework repair, re-roofing and drainage works. The electrical fittings have been disconnected due to their hazardous condition. The church has been awarded a first round pass from the Heritage Lottery Fun for works including a new electrical installation and lightin
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1244156	Repair works are due to start in summer 2015.
			Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England



	SITE NAME:	Church of the Holy Trinity with St Barnabas, Clarence Way NW1	Built 1849-50 in a C14 Gothic style to the design of Thomas H Wyatt and David Brandon. The building was bomb damaged during World War II and is now suffering
	DESIGNATION:	Listed Place of Worship grade II	from structural movement. The tower roof was re-covered and the roofs re-slated with a grant from the Heritage
	CONDITION:	Poor	Lottery Fund and Historic England. The church has been awarded a subsequent grant from the Heritage Lottery
	PRIORITY CATEGORY:	F (B)	Fund for repairs to the tower stonework. Works are
	OWNER TYPE:	Religious organisation	currently underway and due to complete in summer 2015.
	LIST ENTRY NUMBER:	1356761	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

17

	SITE NAME:	Church of the Holy Cross, Cromer Street, Camden Town	The church was built in the Early English style in 1885 by Joseph Peacock with additional internal features by Charles
ACRN		WCI	Nicholson c1913. Built of yellow stock brick under clay
A MANDE	DESIGNATION:	Listed Place of Worship grade II, CA	tiled roofs; stone dressings inside and out with red brick banding inside. The church has an unusual two-storey narthex with bellcote. There is settlement of the
	CONDITION:	Very bad	foundations at the north-east corner causing structural cracking to the vestry and associated walls of the church
	PRIORITY CATEGORY:	A (A)	itself. The east end roofing and north side guttering are in
	OWNER TYPE:	Religious organisation	need of repair.
) Historic England	LIST ENTRY NUMBER:	1067375	Contact: Ian Harper 020 7973 3786
A. A. H.	SITE NAME:	Christ Apostolic Church	Church built on the site of the Kentish Town Chapel of
		(formerly Church of St John), Highgate Road, Kentish Town NW5	1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. High level repairs to the west end, grant-aided by the
	DESIGNATION:	Listed Place of Worship grade II	Heritage Lottery Fund and Historic England, are complete. Further works are required to the roofs, high level
	CONDITION:	Poor	stonework, boundary wall and gates. The church suffered
	PRIORITY CATEGORY:	C (C)	storm damage in December 2013 and repairs to the affected area are underway.
	OWNER TYPE:	Religious organisation	
Historic England Archive	LIST ENTRY NUMBER:	1379013	Contact: Ian Harper 020 7973 3786
	SITE NAME:	St Andrew's Cathedral (former Church of St Barnabas), Kentish Town Road, Hampstead NWI	This church was constructed in the style of a three-ais basilica (without a dome) by Ewan Christian in 1884-8 has been in use by the Greek Orthodox Church since
	DESIGNATION:	Listed Place of Worship grade II, CA	1957, and became St Andrew's Cathedral in 1970. All internal walls and ceilings have been decorated in the traditional Byzantine style, and large areas have now been
AA AA	CONDITION:	Poor	repaired where damaged by dampness. Externally the
	PRIORITY CATEGORY:	C (A)	tabled guttering to the aisles and apse needs renewal.
	OWNER TYPE:	Religious organisation	
Historic England	LIST ENTRY NUMBER:	1379241	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Church of St Mary Magdalene, Munster Square, Camden Town NWI	The church, designed by RC Carpenter and completed in 1852, was described in the Ecclesiologist as the 'most artistically correct new church in London'. Even so, it was
	designation:	Listed Place of Worship grade II*, CA	altered in 1866-67, and in 1883-84 the north aisle and crypt were added. Built of ragstone with Welsh slate roofs on Baltic fir collar-braced trusses. The interior is richly
	CONDITION:	Poor	decorated with marbles and frescoes. The condition of the
	PRIORITY CATEGORY:	A (A)	frescos is deteriorating as a result of damp caused by leaks in the roof and defective rainwater goods. Externally there
24 0	OWNER TYPE:	Religious organisation	is localised decay to the stonework.



LIST ENTRY NUMBER:	1113157	Contact: Ian Harper 020 7973 3786
SITE NAME:	St Pancras Old Church, Pancras Road, Camden Town NWI	Church dating from the C13 and enlarged in the C19, but retaining C13 and C15 fabric and some very fine wall
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II, CA	memorials. The church exhibits cracking externally and internally. Monitoring is showing movement to be progressive and not just seasonal. A contributing cause is
CONDITION:	Poor	considered to be the very deep and narrow C19 gully which runs around the building. The church has been
PRIORITY CATEGORY:	D (D)	awarded a Heritage Lottery Fund grant to address this and
OWNER TYPE:	Religious organisation	to improve drainage. Works are due to commence in summer 2015.
LIST ENTRY NUMBER:	1113246	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

18

#### HERITAGE AT RISK 2015 / LONDON / CAMDEN / CITY OF LONDON

	SITE NAME:	Church of St Mary and attached walls, piers and gates, Priory Road, Hampstead NW6	Designed by Frederick and Horace Francis in 1856 with spire added in 1872. Kentish ragstone with Bath stone dressings and slate roofs. Stonework repairs to the north
	DESIGNATION:	Listed Place of Worship grade II, CA	and south transept gables and east end of the nave were carried out in 2008, grant-aided by Historic England. A Heritage Lottery Fund/Historic England grant was awarded
	CONDITION:	Fair	in 2013 for stone repairs to the west elevation of the nave and north aisle, and work is now complete. Repairs are still required to the tower and spire stonework.
in the second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1139083	Contact: Tracey Craig 020 7973 3756



	SITE NAME:	The Danish Church, St Katherines Precinct NWI	Designed by Ambrose Poynter and built in 1826 originally for the Royal Hospital of St Katherine, comprising a chapel,
	DESIGNATION:	Listed Place of Worship grade II*, CA	school, dwellings for the brothers and sisters and a Master's House (demolished). The chapel has been occupied by the Danish Church since 1952. The buildings
	CONDITION:	Poor	in the precinct are built of brick with stone dressings, the front western part of the chapel being faced in stone. The
m	PRIORITY CATEGORY:	C (New entry)	stonework is now suffering from rusting cramps causing the
0	OWNER TYPE:	Religious organisation	stone to spall and past re-facings in cementitious render are becoming detached.
Ind.	LIST ENTRY NUMBER:	1245872	Contact: Tracey Craig 020 7973 3756

© Historic England

© Historic England



SITE NAME:	Church of St Pancras, Upper Woburn Place, Camden Town NWI	Designed by H and HW Inwood, built in 1822 and restored in 1953. The earliest Greek Revival church in London. The west end has an lonic portico to a vestibule
DESIGNATION:	Listed Place of Worship grade I, CA	with tower above. The north and south facades each have a tribune with a portico supported by four caryatids with a sarcophagus behind. The church has been awarded a grant
CONDITION:	Poor from the	from the Heritage Lottery Fund for repairs to the west portico roof and surrounding stone parapets. Works are
PRIORITY CATEGORY:	D (D)	due to start in summer 2015. The condition of the tower
OWNER TYPE:	Religious organisation	and caryatids has also been investigated.
LIST ENTRY NUMBER:	1379062	Contact: Tracey Craig 020 7973 3756

**	OWNER TYPE:	Religious organisation	and caryatids has also been investigated.
	LIST ENTRY NUMBER:	1379062	Contact: Tracey Craig 020 7973 3756
National States	SITE NAME:	Church of St Martin, Vicars Road, Gospel Oak, Camden NW5	Church of 1864-6 by Edward Buckton Lamb. The choir vestry, added in 1928, is now subdivided for community use. Eclectic Gothic style with Kentish ragstone walls, Bath
ar with	DESIGNATION:	Listed Place of Worship grade I	stone dressings and tiled roofs, with fine interior. The church has a history of subsidence and more recent
	CONDITION:	Fair	cracking to the former choir vestry is likely to require underpinning. Urgent repairs to the tower stonework and
	PRIORITY CATEGORY:	С (В)	restoration of the pinnacles were completed in 2014,
	OWNER TYPE:	Religious organisation	grant-aided by the Heritage Lottery Fund. A further phase of repairs is required to address subsidence of the west
	LIST ENTRY NUMBER:	1379098	end, as well as repairs to window tracery.

© Historic England

#### **CITY OF LONDON**

# in

	SITE NAME:	St Mary Somerset Tower, Upper Thames Street EC4	Redundant church built between 1686-94 by Wren. The body of the church was destroyed in 1871. Permission has
	DESIGNATION:	Listed Building grade I	been granted for an extension to convert the building to residential use.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
A LE LE LE LE LE LE LE LE LE LE LE LE LE L	PRIORITY CATEGORY:	F (F)	
nann	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358904	Contact: Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

© Historic England Archive

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Tracey Craig 020 7973 3756

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / CITY OF LONDON / CROYDON

	SITE NAME:	Church of St Bride, Fleet Street, City of London EC4	Wren church of 1671-8 on the site of an earlier church, the medieval crypts of which were excavated after World War
	DESIGNATION:	Listed Place of Worship grade I, CA	II. The church has the tallest of all Wren spires which is unique in form. Repairs to the spire were completed in 2014. The condition of the nave parapets, the aisle roofs
	CONDITION:	Poor	and the clerestory walls and windows remains poor. In March 2015 the church was awarded a grant from the Listed Places of Worship Roof Repair Fund.
- A Street	PRIORITY CATEGORY:	C (C)	
Lalas	OWNER TYPE:	Religious organisation	
and the second se	LIST ENTRY NUMBER:	1064657	Contact: Ian Harper 020 7973 3786
England			

© Historic Er

© Historic England

C di	SITE NAME:	Church of St Margaret, Lothbury, City of London EC2	Designed by Sir Christopher Wren, built 1686-1695. The form is a simple rectangle orientated north-south with a
1	DESIGNATION:	Listed Place of Worship grade I, CA	vestry to the east and a tower to the west end. The south elevation is faced in Portland stone while the others are rendered with stone dressings. The four-stage tower is
	CONDITION:	Poor	topped with a cupola and obelisk. The church has fine contemporary fittings. There are cracks externally between
+	PRIORITY CATEGORY:	A (A)	the tower and the body of the church, which are being
	OWNER TYPE:	Religious organisation	monitored. The floor of the nave is also undulating as a result of differential settlement. The congregation is
	LIST ENTRY NUMBER:	1064634	exploring options for funding.
nd			Contact: Ian Harper 020 7973 3786

London Wall: remains of Roman and medieval wall from west end of All Hallows Church to 38 Camomile SITE NAME Street EC2 DESIGNATION Scheduled Monument, 2 CAs LIST ENTRY NUMBER: 1002050 Generally satisfactory but with significant localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY NEW ENTRY?: Deterioration - in need of management No CONTACT: OWNER TYPE: Elizabeth Whitbourn 07889 808145 Local authority, multiple owners London Wall: section of Roman and Medieval wall at St Alphage garden, incorporating remains of St Alphage's SITE NAME: Church EC2 DESIGNATION LIST ENTRY NUMBER 1018886 Scheduled Monument Generally satisfactory but with significant localised CONDITION: TREND: Declining problems NEW ENTRY? PRINCIPAL VULNERABILITY Deterioration - in need of management No OWNER TYPE: CONTACT: Elizabeth Whitbourn 07889 808145 Local authority SITE NAME: Roman wall in basement of 90 Gracechurch Street EC3 LIST ENTRY NUMBER: DESIGNATION 1002035 Scheduled Monument, CA Generally satisfactory but with significant localised CONDITION: TREND: Improving problems PRINCIPAL VULNERABILITY: NEW ENTRY? No Deterioration - in need of management OWNER TYPE: CONTACT Local authority Elizabeth Whitbourn 07889 808145

#### CROYDON



	SITE NAME:	lce house, Geoffrey Harris House, Coombe Road
	DESIGNATION:	Listed Building grade II
	CONDITION:	Poor
	OCCUPANCY:	N/A
and a set	PRIORITY CATEGORY:	F(C)
	OWNER TYPE:	Educational (independent)
	LIST ENTRY NUMBER:	1031615

C18 ice house to Coombe House, now Geoffrey Harris House. Disused and partly overgrown, with some loose brickwork and deteriorating pointing. The ice house is under new ownership in the grounds of The Cedars school located in Geoffrey Harris House. Work is currently in progress to remove vegetation and to carry out sympathetic repairs to the brickwork.

Contact: Vincent Lacovara (LPA) 020 8726 6000 ext

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use)

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

6205 I

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015



	SITE NAME:	Former Kennedys Butchers,	Built in 1926 for Kennedys, a chain of South London
		18a, High Street, South Norwood SE25	butchers, now closed. It is hoped the ground floor shop can be brought back into use. Conversion of the upper
	DESIGNATION:	Listed Building grade II, CA	floors was proposed in 2011-2012, however this work does not appear to have been carried out. Unauthorised
	CONDITION:	Poor	works to the building's front elevation are being pursued b the Council's Enforcement Team.
	OCCUPANCY:	Vacant/not in use	the Council's Emorcement ream.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
London Borough of Croydon	LIST ENTRY NUMBER:	1392596	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Lesley Arms public house, 62, Lower Addiscombe Road, Addiscombe	Public house circa 1900 in Arts and Crafts style. The building has been vacant for many years and its condition is deteriorating, particularly the interiors. The upper floors
	DESIGNATION:	Listed Building grade II	have now been converted to flats. Discussions with the Local Authority on the future use of the ground floor took
	CONDITION:	Poor	place in 2012 but no progress has been made.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (C)	
	OWNER TYPE:	Commercial company	
London Borough of Croydon	LIST ENTRY NUMBER:	1272418	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Segas offices, 32, Park Lane, Croydon	Gas company showroom and office, built 1939-41 in Moderne style. The building is in sound condition but
	DESIGNATION:	Listed Building grade II, CA	vacant. The Mid Croydon Masterplan and Opportunity Area Planning Framework emphasise the need for a new
	CONDITION:	Fair	use to be found for the building. Discussions are ongoing with the property owner regarding possible new uses.
	OCCUPANCY:	Vacant/not in use	·····
	PRIORITY CATEGORY:	E (C)	
	OWNER TYPE:	Commercial company	
London Borough of Croydon	LIST ENTRY NUMBER:	1262041	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Former lodge to Croydon Airport Terminal, Purley Way, Croydon	Single storey lodge to Airport House, built c1928. The building has fallen into a state of disrepair through a lack of maintenance and possibly vandalism. There are damaged
- Para	DESIGNATION:	Listed Building grade II	windows and masonry, and overgrown vegetation. The building is part used for storage and part by the Croydon
NE A	CONDITION:	Poor	Airport Society. Discussions with the Local Authority are ongoing and Historic England is advising on appropriate
	OCCUPANCY:	Part occupied/part in use	repairs, which are due to be carried out in 2015.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	

© London Borough of Croydon



	LIST ENTRY NUMBER:	1079299	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Old Tithe Barn, Waddon, 520, Purley Way	C18 former barn, more recently used as offices. The barn is an unusual structure of two parallel ranges with an M-
	DESIGNATION:	Listed Building grade II	shaped roof. The timber frame is clad in light brickwork with a steeply pitched tiled roof and wooden louvres at the
	CONDITION:	Poor	end of each range. The building has been unoccupied since 2007 and its condition is deteriorating. Discussions have
	OCCUPANCY:	Vacant/not in use	taken place with the Local Authority regarding its future
	PRIORITY CATEGORY:	C (New entry)	use.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079247	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Surrey Street Pumping Station, Surrey Street, Croydon	Pumping station, built in four phases from 1851. Some exterior repairs have been carried out, however, the	
	DESIGNATION:	Listed Building grade II, CA	building is vacant. Located within the Old Town Masterplar area, its future use has been identified as key to the	
	CONDITION:	Fair	regeneration of Croydon's Old Town. Local people,	
	OCCUPANCY:	Vacant/not in use	including the Portas Town Team, have expressed a desire for it to be publicly accessible.	
	PRIORITY CATEGORY:	E (C)		
	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1079248	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051	
	SITE NAME:	2, Woodside Green, South Norwood SE25	Early C18 timber-framed house with brick gable ends and catslide roof to the rear. The building is unoccupied and very poor condition internally and externally following extensive fire damage in 1991 and subsequent neglect. T condition of the building is being monitored by the Local Authority. Historic England is advising on necessary surver work and discussions are underway with the Local	
	DESIGNATION:	Listed Building grade II		
	CONDITION:	Very bad		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	A (B)	Authority regarding its future use.	
	OWNER TYPE:	Private		
© Historic England	LIST ENTRY NUMBER:	1079280	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051	
	SITE NAME:	Church of St Mark, Albert Road, Croydon SE25	Designed by GH Lewis of Linden and Lewis, the nave was built in 1852 and the rest completed by 1890. Slate pitched	
	DESIGNATION:	Listed Place of Worship grade II, CA	roofs, Kentish ragstone walling. Stonework repairs were recently completed, grant-aided by Historic England and the Heritage Lottery Fund. Some associated and temporary	
	CONDITION:	Poor	roof repairs have been carried out, but the roofs generally need re-slating. Funding has been secured from the Listed	
			need re-stating, runding has been secured from the Listed	

	DESIGNATION:	Listed Place of Worship grade II, CA	roofs, Kentish ragstone walling. Stonework repairs were recently completed, grant-aided by Historic England and the Heritage Lottery Fund. Some associated and temporary
11	CONDITION:	Poor	roof repairs have been carried out, but the roofs generally need re-slating. Funding has been secured from the Listed
12	PRIORITY CATEGORY:	C (C)	Places of Worship Roof Repair Fund for some of these
	OWNER TYPE:	Religious organisation	works.
	LIST ENTRY NUMBER:	1323688	Contact: Tracey Craig 020 7973 3756

1	SITE NAME:	Church of St Mark, Church Road, Croydon	Built in 1910, designed by Fellowes-Prynne. The clay tiled south aisle mono-pitched roof and the double-pitched ro		
	DESIGNATION:	Listed Place of Worship grade II	over the adjacent memorial chapel are in poor condition, along with associated flashings and valley gutter linings. This is resulting in rainwater ingress. Stonework and pointing are also in need of attention in places. The church has been awarded a grant from the Heritage Lottery Fund for re-		
TIME	CONDITION:	Poor			
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Religious organisation	roofing and masonry repairs. Works are due to start in summer 2015.		
and the second se	LIST ENTRY NUMBER:	1079317	Contact: Tracey Craig 020 7973 3756		

© Historic England

© Historic England

	SITE NAME:	Church of St Andrew, Southbridge Road, Croydon	Church dating from 1857 by Benjamin Ferrey, with aisles added in 1879, chancel rebuilt and Lady Chapel added in
	DESIGNATION:	Listed Place of Worship grade II	1891 designed by HB Walton. The church has been reordered internally. The unusual bellcote feature has been
11	CONDITION:	Fair	dismantled due to its poor structural condition and needs to be reinstated. Works are required to the rainwater
A A AALAAA	PRIORITY CATEGORY:	C (C)	goods and stonework.
	OWNER TYPE:	Religious organisation	
A ROBERT A	LIST ENTRY NUMBER:	1079305	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / CROYDON

•	SITE NAME:	Church of St Augustine, St Augustine's Avenue, Croydon	Designed by John Oldrid Scott, built in 1884. Reordered 1989 to provide hall accommodation. The church has c			
1	DESIGNATION:	Listed Place of Worship grade II*	tiled roofs, with flint walling. A Heritage Lottery Fund/Historic England grant was awarded in 2012 for roof			
	CONDITION:	Fair	repairs to the south transept and south chapel, along with associated overhauling of rainwater goods and stone and			
	PRIORITY CATEGORY:	C (D)	flint repairs. These works are now complete. Further			
T	OWNER TYPE:	Religious organisation	repairs are needed to the north aisle roof and tower stonework.			
	LIST ENTRY NUMBER:	1079301	Contact: Tracey Craig 020 7973 3756			

© Historic England

MAR I	SITE NAME:	Church of St John, Upper Norwood, Sylvan Road, Croydon SE19	Built in 1882, designed by John Loughborough Pearson. The church is located on the crest of a hill on shrinkable clay and has been subject to ongoing differential movement
	DESIGNATION:	Listed Place of Worship grade II*, CA	for many years. There has been regular monitoring and ground investigations were carried out in 2013. Substantial cracking is occurring mainly to the south side of the building
· · · ·	CONDITION:	Poor	and internally netting has been erected at high level in the
	PRIORITY CATEGORY:	B (A)	south aisle to collect any fragments of falling masonry. The church has been awarded a first round pass from the
	OWNER TYPE:	Religious organisation	Heritage Lottery Fund for works to underpin the south side of the church.
© Historic England	LIST ENTRY NUMBER:	1079275	Contact: Tracey Craig 020 7973 3756

SITE NAME:	Group of four World War II fighter pens at the for	rmer airfield of RAI	F Kenley
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021242
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Group of seven World War II fighter pens at the f	ormer airfield of RA	AF Kenley
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021243
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Surrey Iron Railway embankment, approximately I	30m south west of	Lion Green Road, Coulsdon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021441
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	South Norwood, South Norwood, Croydon SE25		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Sarah Freeman (LPA) 020 8726 6000 ext 62251

#### PRIORITY CATEGORIES

### А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; solution agreed but Under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user. use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

EALING



SITE NAME:	Stable Block at Brent Lodge Park, Church Road, Hanwell W7	Late C19 two storey building, built of yellow stock brick. Urgent works to the slate hipped roof and underpinning were undertaken to control water ingress and stabilise the
DESIGNATION:	Listed Building grade II, CA	building. The Local Authority has recently carried out a marketing exercise in order to find a viable use for the
CONDITION:	Good	building which will ensure its ongoing maintenance.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1079410	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

© Historic England



	SITE NAME:	Crossways, 134, Church Road, Hanwell W7	C18 or earlier house. The house is vacant and has been deteriorating for some time. Discussions are ongoing with
	DESIGNATION:	Listed Building grade II, CA	the present owners regarding necessary urgent works, as well as the full repair of the house. The building continues
Sectors.	CONDITION:	Very bad	to be shored up with scaffolding supporting a tin roof. The Local Authority is considering further statutory action,
	OCCUPANCY:	Vacant/not in use	including a Repairs Notice.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
_	LIST ENTRY NUMBER:	1358740	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

formulated.

Administration block of the former London District

Schools, 1856. The Local Authority carried out major repairs in 2010 and the building is now in good condition.

Management of the building has reverted to the Local Authority and an options survey has been carried out to

inform future uses, as well as a planned programme of maintenance. A long-term business plan is also being

Contact: Rosemarie Wakelin (LPA) 020 8825 6600

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

© London Borough of Ealing



LIST ENTRY NUMBER: 1358760 Contact: Rosemarie Wakelin (LPA) 020 8825 6600 Circa 1875-77 with important station canopies and SITE NAME Hanwell Station, main up side building and down side island ironwork especially on the central platform. It is the least altered example remaining of the general station rebuilding platform, Station Road, Hanwell of the 1870s when the track numbers were quadrupled. w7 The timber platform structures have been repaired, DESIGNATION: Listed Building grade II, CA however, the buildings remain underused. A project is underway to secure step-free access to the station CONDITION: Fair platforms as part of the Crossrail development and OCCUPANCY: N/A planning applications are anticipated before 2016. PRIORITY CATEGORY: C (C)

Hanwell Community Centre, Cuckoo Avenue, Hanwell W7

Listed Building grade II, CA

Part occupied/part in use

Good

E (E)

Utility

1358787

Local authority

© Historic England



	SITE NAME:	Norwood Hall, Norwood Green Road, Southall	Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and
- ANA	DESIGNATION:	Listed Building grade II, CA	includes substantial grounds, outbuildings and a walled garden. The building was used as a horticultural college for
	CONDITION:	Fair	several years but is now used as a community centre by the present owner. Works are ongoing to restore the house
	OCCUPANCY:	Part occupied/part in use	and a new school complex has been built in the grounds.
1	PRIORITY CATEGORY:	category: F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079330	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UÁ
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / EALING




N N N N N N	SITE NAME:	Two chapels at South Ealing Cemetery, South Ealing Road W5	The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now
17 B	DESIGNATION:	Listed Building grade II	considered too dangerous to use. Funding for emergency repairs is being sought and a long term solution being
A PARTY OF	CONDITION:	Very bad	explored.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1380227	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

© London Borough of Ealing



	SITE NAME:	Southall Manor House, The Green, Southall	Substantial timber-framed manor house dating from 1587, with later extensions and alterations. Works have been
1	DESIGNATION:	Listed Building grade II*	carried out to upgrade the property internally to a minimum standard to accommodate temporary tenants.
	CONDITION:	Fair	An options appraisal has been prepared to support the use of the building as a training hub for local chefs and further
	OCCUPANCY:	Part occupied/part in use	design work is underway to determine the impact on the
	PRIORITY CATEGORY:	E (E)	original fabric of the building and possibilities for extension.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079419	Contact: Elizabeth Whitbourn 07889 808145

© Historic England



	SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall	Former mental asylum (1829) by William Alderson; extended in 1854-57. Part of the original complex has been
	DESIGNATION:	Listed Building grade II	restored for continuing healthcare use. Applications for the conversion of the listed wards to private residential use
	CONDITION:	Fair	were approved in 2013. The site is now partially refurbished, but the chapel, ballroom and remaining wards
<b>D</b>	OCCUPANCY:	Part occupied/part in use	are still vacant and awaiting conversion.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Health authority	
coric England Archive	LIST ENTRY NUMBER:	1079364	Contact: Rosemarie Wakelin (LPA) 020 8825 6600



			(,
	SITE NAME:	Church of St Peter, Mount Park Road W5	Church in free Gothic style by JD Sedding and H Wilson dating from 1889 to 1892. Stock brick with stone dressings.
	DESIGNATION:	Listed Place of Worship grade II*, CA	There are two west end towers with spirelets. Turrets, the extension of the nave piers, extend up through the nave roof and have connecting arches. Recent repairs have
a sur		Fair	included the roofs to the main slopes, turrets and towers; the timber shingles to the tower spirelets; and stonework
		C (F)	repairs with funding from the Heritage Lottery Fund and
	OWNER TYPE:	Religious organisation	Historic England. The west end window and masonry remain in need of repair.
	LIST ENTRY NUMBER:	1079390	Contact: Tracey Craig 020 7973 3756

© Historic England

© Histo

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / EALING

Constrained         Generally satisfactory but with significant localised problems         TERMS         Declining           SenderAl VolUNERABUTY:         Scrub/tree growth         New DNTRY:         No           Charity (non-heritage)         CONTACT:         Elizabet Whitbourn 07889 808145           SEREMARD:         Charity (non-heritage)         CONTACT:         Elizabet Whitbourn 07889 808145           SEREMARD:         Scheduled Monument         List ENTRY NUMBER         1001971           CONTACT:         Elizabet Mitbourn 07889 808145         SenderMathon:         No           SEREMARD:         Scheduled Monument         List ENTRY NUMBER         1001971           CONTACT:         Elizabet Mitbourn 07889 808145         SenderMathon:         Scheduled Monument, CA         UST ENTRY NUMBER         1002020           CONTACT:         Elizabet Mitbourn 07889 808145         TREND:         Declining           SENDERATON:         Scheduled Monument, CA         UST ENTRY NUMBER         1002020           CONTACT:         Elizabet Mitbourn 07889 808145         SenderMathon:         Scheduled Monument; CA         UST ENTRY NUMBER         1002020           CONTACT:         Scheduled Monument; CA         UST ENTRY NUMBER         1002020         Scheduled Monument; CA         UST ENTRY NUMBER         1002020	SITE NAME:	Hanwell flight of locks and brick boundary wall of S	it Bernard's Hospit	al
problemsproblemsnoticemippioningBinderNat, VolubbalitySarub/tree growthNow ChrittineNoBinderNat, VolubbalitySarub/tree growthNow ChrittineNoBinderNat, VolubbalityScheduled MonumentList Entry Nutree1005552ExcessionGenerally satisfactory but with significant localised problemsInstanceDecliningBinderNat, VolubbalityScheduled MonumentList Entry NutreeNoConstantionGenerally satisfactory but with significant localised problemsInstanceDecliningBinderNat, VolubbalityScheduled MonumentCONTACT:Elizabeth Whitbourn 07889 808145BinderNat, VolubbalityDrainage/dewateringNoW Differ:NoBinderNat, VolubbalityDrainage/dewateringNoW Differ:NoBinderNat, VolubbalityDrainage/dewateringNoW Differ:NoBinderNat, VolubbalityDrainage/dewateringNoW Differ:NoBinderNat, VolubbalityDecliningTraco:DecliningBinderNat, VolubbalityDecliningTraco:DecliningBinderNat, VolubbalityScheduled Monument, CAIsi INING NutreeNoBinderNat, VolubbalityDecliningTraco:Declining <th>DESIGNATION:</th> <th>Scheduled Monument, part in CA</th> <th>LIST ENTRY NUMBER:</th> <th>1001963</th>	DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001963
DWNRETTR:     Mixed, multiple owners     CONTACT:     Elizabeth Whitbourn 07889 808145       ATTEMATE:     Moated site at Down Barns Farm     USTEXERY NUMBER     1005552       DESEMATION:     Scheduled Monument     USTEXERY NUMBER     1005552       DESEMATION:     Scheduled Monument     No     Declining       DESEMATION:     Scheduled Monument     USTEXERY NUMBER     ID01971       DESEMATION:     Scheduled Monument     USTEXERY NUMBER     ID01971       DESEMATION:     Scheduled Monument     USTEXERY NUMBER     ID01971       DESEMATION:     Delanage/dewatering     No     No       DESEMATION:     Delanage/dewatering     No     No       DESEMATION:     Delanage/dewatering     No     No       DESEMATION:     Scheduled Monument, CA     USTEXERY NUMBER     ID02200       DESEMATION:     Scheduled Monument, CA     USTEXERY NUMBER     ID02200       DESEMATION:     Generally statificatory but with significant localised problems     TEND:     Declining       DESEMATION:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       DESEMATION:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       DESEMATION:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       DESE	CONDITION:		TREND:	Improving
Strandbe         Moated site at Down Barns Farm           Strandbe         Scheduled Monument         INTERNET         1005552           Concornics         Generally satisfactory but with significant localised problems         TREND:         Declining           Strandbe         Scheduled Monument         No         Elizabeth Whitbourn 07889 808 145           OWNER TYPE         Charity (non-heritage)         CONTACT:         Elizabeth Whitbourn 07889 808 145           DESCRATOR         Scheduled Monument         INTERNATE:         No           DESCRATOR         Scheduled Monument         INTERNATE:         Unknown           Strandberns         Generally satifactory but with significant localised problems         TREND:         Unknown           Strandberns         Windmill Endge         INTERND:         Elizabeth Whitbourn 07889 808 145           Strandberns         Windmill Endge         INTERND:         Declining           Descrator         Scheduled Monument, CA         USTERNTR NURRE:         No           Strandberns         Scheduled Monument, CA         USTERNTR NURRE:         Declining           Strandberns         Generally satisfactory but with significant localised problems         Track:         Declining           Strandberns         Generally satisfactory but with significant localised problems <t< td=""><td>PRINCIPAL VULNERABILITY:</td><td>Scrub/tree growth</td><td>NEW ENTRY?:</td><td>No</td></t<>	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Designation         Scheduled Monument         List Drift Number         1005552           conditions         Generally satisfactory but with significant localised problems         mexp:         Declining           maxber         Scrub/tree growth         New ENTRY:         No           constraints         Scrub/tree growth         New ENTRY:         Elizabeth Whitbourn 07889 808145           constraints         Scheduled Monument         Est ENTRY NUMBER         Unknown           constraints         Scheduled Monument         Est ENTRY NUMBER         Unknown           constraints         Scheduled Monument         Est ENTRY NUMBER         Unknown           constraints         Scheduled Monument         Est ENTRY NUMBER         No           constraints         Private         Constraints         Elizabeth Whitbourn 07889 808145           est entry         Private         Constraints         Elizabeth Whitbourn 07889 808145           est entry         Private         Constraints         Interp         Interp           este entry         Scheduled Monument, CA         Est Entry Number         Interp         Interp           constraints         Generally satisfactory but with significant localised problems         mexp         No           contortent         Generally satisfactory but with	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
Constraint         Generally statisfactory but with significant localised problems         TRED:         Deckning           SREACEAL MARKABURY:         Scrub/tree growth         NN         CONTACT:         Elizabeth Whitbourn 07899 808145           STET MARK:         Moated site at Sudbury golf course, Wembley         UNINGAME         UNINGAME         UNINGAME           Stendel Monument         LIST DITTY MARKE:         Moated site at Sudbury golf course, Wembley         UNINGAME         UNINGAME           Stender Mountent         LIST DITTY MARKE:         Dol 1971         UNINGAME           Stender Mountent         Data age / dewatering         New Marken         No           STERMARK:         Windmill Bridge         UNINGAME         UNINGAME           Stendel Monument, CA         LIST ENTRY MARKE:         Dockning           Stendelman         Scheduled Monument, CA         LIST ENTRY MARKE:         No           Stendelman         Controon         Generally satisfactory but with significant localised problems         TREND:         Dockning           Stender MARKE         Windmill Bridge         Controon         Rever NTACT:         Rever NTACT:           Stender MARKE         Conservation Area, 9 LBs         New INTACT:         No           Stender MARKE         Conservation Area, 9 LBs         New INTACT: <td>SITE NAME:</td> <td>Moated site at Down Barns Farm</td> <td></td> <td></td>	SITE NAME:	Moated site at Down Barns Farm		
problemsproblemsproblemsproblemsproblemsSenub/tree growthNew KNTRY:NoSenub/tree growthCharity (non-heritage)CNTACT:Elizabeth Whitbourn 07889 808145SENEANTACNScheduled MonumentINTERIARYU01971SeneantacyScheduled MonumentINTERIARYU01971ConstructGenerally satisfactory but with significant localised problemsInter:UnknownDrange/dewateringNew ENTRY:NoOWNER TYPE:PrivateContract:Elizabeth Whitbourn 07889 808145SeneantacyWindmill BridgeContract:Elizabeth Whitbourn 07889 808145SeneantacyScheduled Monument, CAINTERNATIONEIO0200SeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONENoSeneantacyScheduled Monument, CAINTERNATIONEDecliningSeneantacyScheduled Monument, CAINTERNATIONENoSeneantacyScheduled Monument, CAINTERNATIONENoSeneantacyScheduled Monument, CAINTERNATIONENoSeneantacyScheduled Monument, CAINTERNATIONENoSeneantacySc	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005552
DWMRR TMPR:     Charity (non-heritage)     CONTACT:     Elizabeth Whitbourn 07889 808145       STRE NAME:     Moated site at Sudbury golf course, Wembley     IDENON:     DOI 1971       DENONATION:     Scheduled Monument     UST RYTRY NUMBER     IDD1971       CONTACT:     Brainage/dewatering     INEND:     Unknown       DENONATION:     Private     CONTACT:     Elizabeth Whitbourn 07889 808145       STRE NAME:     Private     CONTACT:     Elizabeth Whitbourn 07889 808145       STRE NAME:     Windmill Bridge     Elizabeth Whitbourn 07889 808145       STRE NAME:     Scheduled Monument, CA     UST RYTRY NUMBER     IDD200       CONDITION:     Scheduled Monument, CA     UST RYTRY NUMBER     Declining       CONDITION:     Operant 2 statisfactory but with significant localised problems     INEND:     Declining       STRE NAME:     Acton Town Centre, Acton W3     No     ISSENSATION:     No       CONDITION:     Poor     INEND:     Deterioration     Rosemarie Wakelin (LPA) 020 8822       STRE NAME:     Conservation Area, 9 LBs     No     ISSENSATION:     No       CONDITION:     Poor     INEND:     Deteriorating       MULERABULTY:     Low     CONTACT:     Rosemarie Wakelin (LPA) 020 8822       STRE NAME:     Conservation Area, LB grade II     New ENTR	CONDITION:		TREND:	Declining
STRE NAME: Moated size at Sudbury golf course, Wembley STRE NAME: Scheduled Monument LIST INTRY NUMBER: 1001971 CONDITION: Scheduled Monument (LIST INTRY NUMBER: 1001971 TRENO: Unknown Problems Singer Advance Problems Scheduled Monument, CA CONTACT: Elizabeth Whitbourn 07889 808145 STRE NAME: Windmill Bridge ESEGNATION: Scheduled Monument, CA LIST INTRY NUMBER: 1002020 CONTACT: Elizabeth Whitbourn 07889 808145 StrE NAME: Windmill Bridge ESEGNATION: Scheduled Monument, CA LIST INTRY NUMBER: 1002020 CONTACT: Elizabeth Whitbourn 07889 808145 StrE NAME: Minill Bridge ESEGNATION: Scheduled Monument, CA LIST INTRY NUMBER: 1002020 CONTACT: Elizabeth Whitbourn 07889 808145 StrE NAME: Mo CONTACT: No CONTACT: No CONTACT: Elizabeth Whitbourn 07889 808145 StrE NAME: Conservation - in need of management NEW ENTRY: No CONTACT: Elizabeth Whitbourn 07889 808145 StrE NAME: Conservation - in need of management NEW ENTRY: No CONTACT: Rosemarie Wakelin (LPA) 020 8822 StrE NAME: Conservation Area, 9 LBs NEW ENTRY: No CONTACT: Rosemarie Wakelin (LPA) 020 8822 StrE NAME: Conservation Area, 9 LBs NEW ENTRY: No CONTACT: Rosemarie Wakelin (LPA) 020 8822 StrE NAME: Conservation Area, LB grade II NEW ENTRY: No CONTACT: Rosemarie Wakelin (LPA) 020 8822 StrE NAME: Ealing Town Centre, Ealing WS StrE NAME: Ealing Town Centre, Ealing WS StrE NAME: Conservation Area, 6 LBs NEW ENTRY: No CONTACT: Rosemarie Wakelin (LPA) 020 8822 StrE NAME: Hanvell VIIge Green, Hanvell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No StrE NAME: Hanvell VIIge Green, Hanvell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No Deteriorating significantly StrE NAME: Hanvell VIIge Green, Hanvell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No Deteriorating significantly StrE NAME: Hanvell VIIge Green, Hanvell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No Deteriorating significantly StrE NAME: Hanvell VIIge Green, Hanvell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No Deteriorating signific	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
DESIGNATION:     Scheduled Monument     UKT FNTRY NUMBER:     1001971       CONDITION:     Generally satisfactory but with significant localised problems     INEND:     Unknown       DEMINICAL UNIVERABILITY:     Drainage/dewatering     Nev ENTRY:     No       DOWNER TYFE:     Private     CONTACT:     Elizabeth Whitbourn 07889 808145       DESIGNATION:     Scheduled Monument, CA     UST ENTRY NUMBER     1002020       CONTACT:     Elizabeth Whitbourn 07889 808145     Declining       REINCRAN UNIVERABILITY:     Deterioration - in need of management     No       DESIGNATION:     Generally satisfactory but with significant localised problems     TREND     Declining       CONNERTYFE:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       SATE NAME:     Acton Town Centre, Acton W3     Deteriorating       CONDITION:     Poor     TREND     Deteriorating       VULNERABILITY:     Low     Conservation Area, 9 LBs     Nev ENTRY:     No       STETENAME:     Cuckoo Estate, Hanwell W7     Soconation:     Rosemarie Wakelin (LPA) 020 8822       GONTACT:     Elizabeth Whitbourn Area, 6 LBs     NEV ENTRY:     No       STETENAME:     Ealing Town Centre, Ealing W5     Soconating       STETENAME:     Ealing Town Centre, Ealing W5     Soconating       STETENA	OWNER TYPE:	Charity (non-heritage)	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION:         Generally satisfactory but with significant localised problems         TRENED:         Unknown           RIBNACIEAL VULNERABLITY:         Drainage/dewatering         NEW EXITEX:         No           RIBNACIEAL VULNERABLITY:         Private         CONTACT:         Elizabeth Whitbourn 07889 808145           STEE NAME:         Windmill Bridge         E         Ideateth Whitbourn 07889 808145           DEGINARTION:         Scheduled Monument, CA         UST ENTRY NUMBER         1002020           CONDITION:         Generally satisfactory but with significant localised problems         TRENC.         Declining           RIBNACIEAL VULNERABLITY:         Deterioration - in need of management         Now WINTERT:         No           OWNER TYPE:         Government or agency         CONTACT:         Elizabeth Whitbourn 07889 808145           STEE NAME:         Acton Town Centre, Acton V3         Deterioration         Scheduled Norus           DEGINARTION:         Conservation Area, 9 LBS         New ENTRY:         No           STEE NAME:         Cuckoo Estate, Hanwell W7         Scheduled II (LPA) 020 8822           STEE NAME:         Cuckoo Estate, Hanwell W7         Rosemarie Wakelin (LPA) 020 8822           STEE NAME:         Ealing Town Centre, Ealing W5         Rosemarie Wakelin (LPA) 020 8822           STEE NAME:	SITE NAME:	Moated site at Sudbury golf course, Wembley		
Construction         problems         Construction         Distributiin           PRENCIPAL VULNERABULTY:         Drainage/dewatering         New PRTRY:         No           OWNER TYPE:         Private         CONTACT:         Elizabeth Whitbourn 07889 808145           STET NAME:         Windmill Bridge         Elizabeth Whitbourn 07889 808145           STET NAME:         Scheduled Monument, CA         UST ENTRY NUMMERE         1002020           CONTON:         Generally satisfactory but with significant localised problems         TREND:         Declining           STET NAME:         Government or agency         CONTACT:         Elizabeth Whitbourn 07889 808145           STET NAME:         Acton Town Centre, Acton W3         Deterioration         Elizabeth Whitbourn 07889 808145           STET NAME:         Conservation Area, 9 LBS         NEW ENTRY:         No         No           STET NAME:         Conservation Area, 9 LBS         NEW ENTRY:         No         No           STET NAME:         Low         Conservation Area, 10 LB grade II         NEW ENTRY:         No           STET NAME:         Cuckoo Estate, Hanwell W7         Deteriorating         Rosemarie Wakelin (LPA) 020 8822           STET NAME:         Ealing Town Centre, Ealing W5         No         Ealing Town Centre, Ealing W5	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001971
DVINUER TYPE:     Private     CONTACT:     Elizabeth Whitbourn 07889 808145       STE NAME:     Windmill Bridge     INSTENTRY NUMBER     1002020       DESEGNATION:     Scheduled Monument, CA     UST ENTRY NUMBER     1002020       CONDITION:     Generally satisfactory but with significant localised problems     TREND:     Declining       RRINCRACK VULNERABILITY:     Deterioration - In need of management     NEW ENTRY:     No       OWNER TYPE:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       STE NAME:     Acton Town Centre, Acton W3     Elizabeth Whitbourn 07889 808145       STE NAME:     Conservation Area, 9 LBs     NEW ENTRY:     No       CONDITION:     Poor     TREND:     Deteriorating       VILINERABILITY:     Low     Contract:     Rosemarie Wakelin (LPA) 020 882: 6600       STE NAME:     Cuckoo Estate, Hanwell W7     No     Contract:     Rosemarie Wakelin (LPA) 020 882: 6600       STE NAME:     Ealing Town Centre, Ealing W5     Sternarding     No     Sternarding       STE NAME:     Ealing Town Centre, Ealing W5     Deteriorating     Sternarding       STE NAME:     Ealing Town Centre, Ealing W5     Deteriorating       STE NAME:     Ealing Town Centre, Ealing W5     Deteriorating       STE NAME:     Ealing Town Centre, Ealing W5 <td< td=""><td>CONDITION:</td><td></td><td>TREND:</td><td>Unknown</td></td<>	CONDITION:		TREND:	Unknown
STE NAME Windmill Bridge Stelevine Manual Market Ma	PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
Designation:         Scheduled Monument, CA         LIST ENTRY NUMBER         1002020           CONDITION:         Generally satisfactory but with significant localised problems         TREND:         Declining           RRINCHAL WULMERABILITY:         Deterioration - in need of management         NEW ENTRY:         No           OWNER TYPE:         Government or agency         CONTACT:         Elizabeth Whitbourn 07889 808145           STE NAME:         Acton Town Centre, Acton W3         Elizabeth Whitbourn 07889 808145           STE NAME:         Acton Town Centre, Acton W3         Deteriorating           CONDITION:         Poor         TREND:         Deteriorating           VULMERABILITY:         Low         CONTACT:         Rosemarie Wakelin (LPA) 020 8822 6600           STE NAME:         Cuckoo Estate, Hanwell W7         No         Sternamie           STE NAME:         Conservation Area, 1B grade II         NEW ENTRY:         No           CONDITION:         Poor         TREND:         Deteriorating           VULMERABILITY:         Medium         ConTract:         Rosemarie Wakelin (LPA) 020 8822 6600           STE NAME:         Ealing Town Centre, Ealing W5         No         Sternamie Wakelin (LPA) 020 8822 6600           VULMERABILITY:         Low         ConTract:         Rosemarie Wakelin (LPA)	OWNER TYPE:	Private	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION:       Generally satisfactory but with significant localised       TREND:       Declining         RRINCIPAL VOLUBERABILITY:       Deterioration - in need of management       NEW ENTRY:       No         OWNER TYPE:       Government or agency       CONTACT:       Elizabeth Whitbourn 07889 808145         SITE NAME:       Acton Town Centre, Acton W3       Elizabeth Whitbourn 07889 808145         DESIGNATION:       Conservation Area, 9 LBs       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         CONDITION:       Poor       Resemarie Wakelin (LPA) 020 8823         SITE NAME:       Cuckoo Estate, Hanwell W7       No         SITE NAME:       Cuckoo Estate, Hanwell W7       No         SITE NAME:       Poor       REND:       Deteriorating         CONDITION:       Poor       REND:       Deteriorating         VULNERABILITY:       Medium       Conservation Area, 6 LBs       NEW ENTRY:       No         SITE NAME:       Ealing Town Centre, Ealing W5       No       Contract:       Rosemarie Wakelin (LPA) 020 8823         SITE NAME:       Law       Conservation Area, 6 LBs       NEW ENTRY:       No         SITE NAME:       Low       Contract:       Rosemarie Wakelin (LPA) 020 8823 <tr< td=""><td>SITE NAME:</td><td>Windmill Bridge</td><td></td><td></td></tr<>	SITE NAME:	Windmill Bridge		
Bancholski, Boroblems     problems     Nature     Deterioration       RINCIPAL VULNERABILITY:     Deterioration - in need of management     NeW ENTRY?:     No       SWINER TYPE:     Government or agency     CONTACT:     Elizabeth Whitbourn 07889 808145       MITE NAME:     Acton Town Centre, Acton W3     Elizabeth Whitbourn 07889 808145       DESIGNATION:     Conservation Area, 9 LBs     NEW ENTRY?:     No       CONDITION:     Poor     TREND:     Deteriorating       CONTACT:     Rosemarie Wakelin (LPA) 020 882     6600       CONDITION:     Poor     REND:     Deteriorating       CONDITION:     Conservation Area, LB grade II     NEW ENTRY?:     No       CONDITION:     Poor     Resemarie Wakelin (LPA) 020 882       CONDITION:     Poor     REND:     Deteriorating       CONDITION:     Poor     RenD:     Deteriorating       CONDITION:     Poor     RenD:     Deteriorating       CONDITION:     Poor     RenD:     Deteriorating       CONDITION:     Conservation Area, 6 LBs     NEW ENTRY?:     No       CONDITION:     Poor     RenD:     Deteriorating       CONDITION:     Poor     REND:     Deteriorating       CONDITION:     Poor     REND:     Deteriorating       CONDI	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002020
CONTRETTYPE:       Government or agency       CONTACT:       Elizabeth Whitbourn 07889 808145         STRE NAME:       Acton Town Centre, Acton W3	CONDITION:		TREND:	Declining
SITE NAME: Acton Town Centre, Acton W3 DESIGNATION: Conservation Area, 9 LBs NEW ENTRY: No CONDITION: Poor TREND: Deteriorating VULNERABILITY: Low CONTACT: Rosemarie Wakelin (LPA) 020 882. 6600 SITE NAME: Cuckoo Estate, Hanwell W7 Conservation Area, LB grade II NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No SITE NAME: Ealing Town Centre, Ealing W5 DESIGNATION: Conservation Area, 6 LBs NEW ENTRY: No CONDITION: Poor TREND: Deteriorating VULNERABILITY: Low Conservation Area, 6 LBs NEW ENTRY: No SITE NAME: Ealing Town Centre, Ealing W5 DESIGNATION: Conservation Area, 6 LBs NEW ENTRY: No SITE NAME: Hanwell Village Green, Hanwell W7 DESIGNATION: Conservation Area, 3 LBs NEW ENTRY: No CONDITION: NO CONDITION: Conservation Area, 3 LBs NEW ENTRY: No CONDITION: NEW ENTRY: No CONDITION: Conservation Area, 3 LBs NEW ENTRY: No CONDITION: NO CONDITION: Conservation Area, 3 LBs NEW ENTRY: No CONDITION: NEW	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
Designation:       Conservation Area, 9 LBs       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Low       contract:       Rosemarie Wakelin (LPA) 020 882.         SITE NAME:       Cuckoo Estate, Hanwell W7       set entry:       No         CONDITION:       Conservation Area, LB grade II       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         CONDITION:       Poor       TREND:       Deteriorating         CONDITION:       Poor       Rosemarie Wakelin (LPA) 020 882.         CONDITION:       Poor       TREND:       Deteriorating         CONDITION:       Poor       Rosemarie Wakelin (LPA) 020 882.         SITE NAME:       Ealing Town Centre, Ealing W5       Rosemarie Wakelin (LPA) 020 882.         CONDITION:       Poor       TREND:       Deteriorating         DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY:       No         CONTACT:       Rosemarie Wakelin (LPA) 020 882.       6600         VULNERABILITY:       Low       Contract:       Rosemarie Wakelin (LPA) 020 882.         SITE NAME:       Hanwell Village Green, Hanwell W7       Sosemarie Wakelin (LPA) 020 882.         CONDITION	OWNER TYPE:	Government or agency	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Cuckoo Estate, Hanwell W7       No         STE NAME:       Conservation Area, LB grade II       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Medium       conservation Area, LB grade II       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Medium       conservation Area, 6 LBs       NEW ENTRY?:       No         STE NAME:       Ealing Town Centre, Ealing W5       Deteriorating       Rosemarie Wakelin (LPA) 020 8823 6600         VULNERABILITY:       Poor       TREND:       Deteriorating         STE NAME:       Ealing Town Centre, Ealing W5       No         STE NAME:       Poor       TREND:       Deteriorating         VULNERABILITY:       Low       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Hanwell Village Green, Hanwell W7       No       Rosemarie Wakelin (LPA) 020 8821 6600         STE NAME:       Conservation Area, 3 LBs       NEW ENTRY?:       No         CONTACT:	SITE NAME:	Acton Town Centre, Acton W3		
VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 8823 6600         SITE NAME:       Cuckoo Estate, Hanwell W7       No         DESIGNATION:       Conservation Area, LB grade II       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         CONDITION:       Medium       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Ealing Town Centre, Ealing W5       Deteriorating         DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY:       No         CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Low       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Ealing Town Centre, Ealing W5       Deteriorating         VULNERABILITY:       Low       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Hanwell Village Green, Hanwell W7       Steriorating       Steriorating         STE NAME:       Hanwell Village Green, Hanwell W7       Steriorating significantly         DESIGNATION:       Conservation Area, 3 LBs       <	DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONSISTENTION:     Cuckoo Estate, Hanwell W7       DESIGNATION:     Conservation Area, LB grade II       NEW ENTRY?:     No       CONDITION:     Poor       WULNERABILITY:     Medium       Conservation Area, 6 LBs     NEW ENTRY?:       No     Contact:       Rosemarie Wakelin (LPA) 020 882!       6600	CONDITION:	Poor	TREND:	, i i i i i i i i i i i i i i i i i i i
DESIGNATION:       Conservation Area, LB grade II       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         WULNERABILITY:       Medium       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         SITE NAME:       Ealing Town Centre, Ealing W5       seconservation Area, 6 LBs       NEW ENTRY?:       No         DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY?:       No       Seconservation Grade	VULNERABILITY:	Low	CONTACT:	
CONDITION:       Poor       TREND:       Deteriorating         vuluerabilitY:       Medium       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         SITE NAME:       Ealing Town Centre, Ealing W5          DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         vuluerabilitY:       Low       contact:       Rosemarie Wakelin (LPA) 020 8823 6600         STE NAME:       Hanwell Village Green, Hanwell W7       Deteriorating         DESIGNATION:       Conservation Area, 3 LBs       NEW ENTRY?:       No         CONDITION:       Optimal       TREND:       Deteriorating significantly	SITE NAME:	Cuckoo Estate, Hanwell W7		
AVULNERABILITY:       Medium       CONTACT:       Rosemarie Wakelin (LPA) 020 882!         SITE NAME:       Ealing Town Centre, Ealing W5       Soveration Area, 6 LBs       NEW ENTRY?:       No         CONDITION:       Conservation Area, 6 LBs       NEW ENTRY?:       No       Deteriorating         VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 882!         SITE NAME:       Hanwell Village Green, Hanwell W7       Contact:       Rosemarie Wakelin (LPA) 020 882!         SITE NAME:       Hanwell Village Green, Hanwell W7       No       Soveration Area, 3 LBs       NEW ENTRY?:       No         CONDITION:       Optimal       TREND:       Deteriorating significantly         Mull NERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 882!	DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
Note Revealed in the initial sector is a sector is a sector initial sector is a secto	CONDITION:	Poor	TREND:	Deteriorating
DESIGNATION:       Conservation Area, 6 LBs       NEW ENTRY?:       No         CONDITION:       Poor       TREND:       Deteriorating         vulnerABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 8821 6600         SITE NAME:       Hanwell Village Green, Hanwell W7       Site NAME:       New ENTRY?:       No         DESIGNATION:       Conservation Area, 3 LBs       NEW ENTRY?:       No         CONDITION:       Optimal       TREND:       Deteriorating significantly         VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 8821	VULNERABILITY:	Medium	CONTACT:	
CONDITION:       Poor       TREND:       Deteriorating         VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 8825 6600         SITE NAME:       Hanwell Village Green, Hanwell W7       V         Designation:       Conservation Area, 3 LBs       NEW ENTRY:       No         CONDITION:       Optimal       TREND:       Deteriorating significantly	SITE NAME:	Ealing Town Centre, Ealing W5		
VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 882. 6600         SITE NAME:       Hanwell Village Green, Hanwell W7         DESIGNATION:       Conservation Area, 3 LBs       NEW ENTRY?:       No         CONDITION:       Optimal       TREND:       Deteriorating significantly         VULNERABILITY:       Low       CONTACT:       Rosemarie Wakelin (LPA) 020 882.	DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY?:	No
Conservation Area, 3 LBs     NEW ENTRY?:     No       Condition:     Optimal     TREND:     Deteriorating significantly       KULINERABILITY:     Low     CONTACT:     Rosemarie Wakelin (LPA) 020 882.	CONDITION:	Poor	TREND:	Deteriorating
DESIGNATION:     Conservation Area, 3 LBs     NEW ENTRY?:     No       CONDITION:     Optimal     TREND:     Deteriorating significantly       VUI NERABILITY:     Low     CONTACT:     Rosemarie Wakelin (LPA) 020 882.	VULNERABILITY:	Low	CONTACT:	
CONDITION: Optimal TREND: Deteriorating significantly	SITE NAME:	Hanwell Village Green, Hanwell W7		
VUINFRABILITY: Low CONTACT: Rosemarie Wakelin (LPA) 020 882	DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
	CONDITION:	Optimal	TREND:	Deteriorating significantly
	/ULNERABILITY:	Low	CONTACT:	

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / EALING / ENFIELD

SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600


#### **ENFIELD**

© Historic England

© Historic England



SITE NAME: Broomfield House, Broomfield CI6 house with late CI8 additions, situated in a public Park, Broomfield Lane NI3 park. The building is severely fire damaged, although significant parts of the interior are in safe storage. A Listed Building grade II\*, RPG structural survey was undertaken in 2014, which included a DESIGNATION grade II thorough inspection of the scaffolding. A Conservation Management Plan and Options Appraisal are currently CONDITION: Very bad being prepared to help inform a way forward. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1078934 Contact: Verena McCaig 020 7973 3718 Early C18 stable block to Broomfield House. The building Stable block in Broomfield Park, SITE NAME: is currently empty, although weathertight and secure. A Broomfield Lane NI3 structural survey was undertaken in early 2015 and a Listed Building grade II\*, RPG Conservation Management Plan and Options Appraisal are DESIGNATION: grade II currently being prepared. These reports will help to inform a way forward. CONDITION: Poor OCCUPANCY Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1188544 Contact: Verena McCaig 020 7973 3718





SITE NAME: Former Edmonton Girls' Single storey building, with a central arched doorway to the street and sash windows to either side. Above the Charity School, Church Street, doorway is a statuette of a female pupil. The condition of Edmonton N9 the building is slowly deteriorating and the former use is DESIGNATION: Listed Building grade II, CA unable to provide adequate income for its upkeep. An Historic England funded Conservation Management Plan, CONDITION: Poor condition survey and options appraisal have been OCCUPANCY: Vacant/not in use produced. Discussions have begun with potential new users. PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1079547 Contact: Christine White (LPA) 020 8379 3865

© Historic England

D

Е

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA

WHS

Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / ENFIELD

	SITE NAME:	24, Church Street, Edmonton	Former teacher's accommodation to the adjoining Charity
	DESIGNATION:	Listed Building grade II, CA	School. C18 cottage of red brick with renewed pantiled roof. A Conservation Management Plan, condition survey
	CONDITION:	Poor	and options appraisal have been produced, funded by Historic England. Discussions have begun with potential
	OCCUPANCY:	Vacant/not in use	new users.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
and a	LIST ENTRY NUMBER:	1079546	Contact: Christine White (LPA) 020 8379 3865


© Historic England

© Historic England

© Historic England

	SITE NAME:	Trent Park	Late C18 landscape park further developed in the early
and the second	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, CA	C20 by Sir Philip Sassoon. The central mansion house, gardens and pleasure grounds have been vacated and their future use is uncertain. The surrounding parkland is
	CONDITION:	Generally satisfactory but with significant localised problems	managed by the London Borough of Enfield as a country park. The terrace to the mansion house is also at risk.
	VULNERABILITY:	High	
47.44	TREND:	Declining	
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000484	Contact: Zosia Mellor 020 7973 3473





	LIST ENTRY NOMBER:	1078931	Contact: Christine White (LPA) 020 8379 3865
	SITE NAME:	Truro House and stable block, 176, Green Lanes N13	Early to mid-C19 detached villa with C19 stable block. A residential scheme was agreed in 2009 and is being
and the second second	DESIGNATION:	Listed Building grade II	implemented, and repairs are underway to the house.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
t d	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1079521	Contact: Christine White (LPA) 020 8379 3865

© London Borough of Enfield



and and	SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield	Former Enfield Electricity Works dating from 1906, architect unknown. The building is partially occupied.		
	DESIGNATION:	Listed Building grade II	Urgent works were undertaken in 2014/15. Future operational requirements are under consideration and		
	CONDITION:	Fair	investigative works proposed to explore options for repair and re-use.		
	OCCUPANCY:	Part occupied/part in use			
	PRIORITY CATEGORY:	E (E)			
	OWNER TYPE:	Utility			
	LIST ENTRY NUMBER:	1389537	Contact: Christine White (LPA) 020 8379 3865		

© London Borough of Enfield

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT	RISK 2015	/ LONDON /	ENFIELD

HERITAGE AT RISK 2015 / LONDO	ON / ENFIELD			
	SITE NAME:	Barn at Whitewebbs Farm, Whitewebbs Road	CI7. Works to ι	ramed barn probably dating from the late upgrade temporary support to the
	DESIGNATION:	Listed Building grade II	undertaken, in di	protect it from the elements have been scussion with the Local Authority and
	CONDITION:	Very bad	Historic England. Consents have been granted for residential conversion.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	B (B)		
And Adda to	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	1079480	Contact: Christir	ne White (LPA) 020 8379 3865
n ;	SITE NAME:	All Saints Church, Church Street N9	1772. Restored i	gely rebuilt in the C15 and clad in brick in n 1855 and 1871 by Ewan Christian and in ert Scott. The church has a Kentish
	DESIGNATION:	Listed Place of Worship grade II*, CA	ragstone mediev sides, and stone	al tower, 1772 brick-faced east and north south and west sides. The tower
	CONDITION:	Poor	fenced off due to	very poor condition and the area below is the risk of falling stone. The nave and
	PRIORITY CATEGORY:	F (B)	aisle roofs need i	recovering. The church has been awarded Heritage Lottery Fund for repair works to
	OWNER TYPE:	Religious organisation	the tower. Work	s are currently underway and due to
© Colin Kerr (Architect)	LIST ENTRY NUMBER:	1079548	complete in summer 2015.	
			Contact: Tracey	Craig 020 7973 3756
	SITE NAME:	New Covenant Church (formerly The Charles Lamb Halls), Church Street, Edmonton N9	The Charles Lamb Halls were built in a collegiate Tudou style by local philanthropist Charles Lamb in 1908. The buildings are faced in stone under plain tile roofs and no occupied by the New Covenant Church, Edmonton. Repairs to high level stonework and other external fabr are due to start in July 2015 with funding from the Herit Lottery Fund. A second phase of work is required to re	
	DESIGNATION:	Listed Place of Worship grade II, CA		
	CONDITION:	Poor	the roofs, stonew north side.	work, rainwater goods and drains on the
	PRIORITY CATEGORY:	D (D)		
© Hook Mason Architects	OWNER TYPE:	Religious organisation	Contact: Ian Harper 020 7973 3786	
	LIST ENTRY NUMBER:	1078914		
	SITE NAME:	Grovelands Park N14	Late C18 landscape park and lake by Humphry Reptor extended in the mid-C19 and laid out as a public park the early C20 by Thomas Mawson. The mansion is no private hospital. The management is fragmented due to	
Contraction of the local division of the loc	DESIGNATION:	Registered Park and Garden grade II*, 4 LBs		
	CONDITION:	Generally satisfactory but with minor localised problems	separate owners commissioned a	hips. The London Borough of Enfield has Conservation Management Plan.
	VULNERABILITY:	Medium		
	TREND:	Declining		
© Historic England	NEW ENTRY?:	No		
C Filotorie England	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000395	Contact: Zosia N	1ellor 020 7973 3473
SITE NAME:	Site of Elsynge Ha	all, Forty Hall		
DESIGNATION:	Scheduled Monument, part in RPG grade II, CA		LIST ENTRY NUMBER:	1002040
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - I	imited/localised	NEW ENTRY ?:	Yes

#### PRIORITY CATEGORIES

OWNER TYPE:

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

Local authority, multiple owners

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

CONTACT:

#### ABBREVIATIONS

Elizabeth Whitbourn 07889 808145

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / ENFIELD / GREENWICH

SITE NAME:	Church Street, Edmonton N9		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY: Low		CONTACT:	Christine White (LPA) 020 8379 3865
SITE NAME:	Fore Street, Edmonton N18		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Christine White (LPA) 020 8379 3865

#### GREENWICH



SITE NAME:	Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Large conservatory with domed glass roofs, surmounted by a figure of Mercury. Built in 1889 in a classical style. Previously suffering from long-term neglect and major
DESIGNATION:	Listed Building grade II	deterioration of the fabric. Restoration of the East House has been completed. A Stage 2 Heritage Lottery Fund
CONDITION:	Fair	application was in advanced stages of preparation. However, those plans have been halted and the owner is
OCCUPANCY:	Occupied/in use	now marketing the wider site, including the Winter
PRIORITY CATEGORY:	C (F)	Garden, for sale. The Local Authority and Historic England are involved in discussions to secure the future of the site.
OWNER TYPE:	Educational (state sector)	
LIST ENTRY NUMBER:	1079082	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England



	LIST ENTRY NOMBER:	1079082	Contact: Conservation Team (LPA) 020 8921 5355
	SITE NAME:	Lock and swing bridge, Broadwater Estate SE28	The Royal Arsenal Canal was built 1812-14 to bring supplies into the arsenal. The swing bridge was built circa
	DESIGNATION:	Listed Building grade II	1876 to carry railway tracks across the canal. Some work was carried out to the bridge in the early 1980s but since then the lock and bridge have both lain derelict.
i,	CONDITION:	Poor N/A	
1	OCCUPANCY:		
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1213695	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England



© Historic England



SITE NAME:	Garden House to north west of Charlton House, Charlton Road, Charlton SE7	Small red brick garden house with undercroft. High pyramidal swept roof. Mid to late C17 and attributed to Inigo Jones. Previously used as a public lavatory, but now
DESIGNATION:	Listed Building grade I, CA	vacant. The building is in need of repair, maintenance and beneficial use. The borough-wide Royal Greenwich
CONDITION:	Poor	Heritage Trust is commissioning a condition survey as part of a wider programme of surveys for Charlton House, and
OCCUPANCY:	Vacant/not in use	Historic England and the Local Authority will be working
PRIORITY CATEGORY:	C (C)	with them to support progress towards the repair and reuse of the Garden House.
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1291892	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Enderby House, 100, Christchurch Way, Greenwich SE10	Early to mid-C19 wharf-side building of Samuel Enderby, largest whalers and sealers in Britain and pioneers of Atlantic exploration. Unusual octagonal room giving onto a
	DESIGNATION:	Listed Building grade II	projecting bay, allowing views of approaching vessels. A scheme has been agreed in principle, subject to a Section
	CONDITION:	Very bad	106 agreement, but is currently unresolved. Historic England and the Local Authority have been advising the
	OCCUPANCY:	Vacant/not in use	developers on urgent works required to maintain the
	PRIORITY CATEGORY:	B (D)	building in a sound condition whilst it awaits future repair.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1079026	Contact: Conservation Team (LPA) 020 8921 5355

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

30

#### HERITAGE AT RISK 2015 / LONDON / GREENWICH

「「ある」の

©Η

	SITE NAME:	Old brick wall between gardens in front of Nos. 34 and 36, Court Yard, Eltham SE9	Brick wall with sloped coping of C16 appearance. In poor condition with some structural problems caused by overgrowth of vegetation. This vegetation needs to be
	DESIGNATION:	Listed Building grade II*, SM, CA	removed, allowing for repair and repointing.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
9 Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1358957	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	95A, Eltham High Street, Eltham SE9	C17 or earlier stable building with three diagonal chimney shafts. Although the building has been made weathertight,
	DESIGNATION:	Listed Building grade II	it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, the most appropriate future use
	CONDITION:	Poor	would be commercial/office use. Currently in residential use and subject to enforcement action.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1219821	Contact: Conservation Team (LPA) 020 8921 5355

	SITE NAME:	Royal Military Academy, Academy Road, Woolwich SE18	Military college built in 1805 to the designs of James Wyatt. Planning Permission has been granted for residential
	DESIGNATION:	Listed Building grade II*, CA	conversion. Works began in spring 2008 and are continuing in phases.
	CONDITION:	Fair	
1001 1000 1	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1358936	Contact: Verena McCaig 020 7973 3718

14	SITE NAME:	Forecourt railings and gates to Red Barracks, and Gate Lodge, Frances Street, Woolwich SE18	Railings and entrance gateway to the former Red Barracks (1858-60 but now demolished). Structural repairs and repointing to the small watch tower to the north were
THE PARTY OF	DESIGNATION:	Listed Building grade II	completed in 2013. The railings, piers, and gate piers are generally in good condition. The gate lodges, however, are
	CONDITION:	Very bad	in particularly poor condition and are in need of major repair and identification of a new use.
A DE LA CALENCE	OCCUPANCY:	Vacant/not in use	repair and identification of a new use.
© Historic England	PRIORITY CATEGORY:	A (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358950	Contact: Conservation Team (LPA) 020 8921 5355



	SITE NAME:	Garrison Church of St George, Grand Depot Road, Royal Artillery Barracks, Woolwich SE18	Former Italianate church of 1863, a roofless ruin after bomb damage in 1944. Valuable mosaics survive in the apse, including one commemorating members of the Royal Artillery awarded the Victoria Cross. The new permanent
	DESIGNATION:	Listed Building grade II	protective roof funded by the Heritage Lottery Fund has now been erected. The first phase of fabric repairs,
	CONDITION:	Poor	including the apse wall-heads, mosaics, and entrance gates are also complete, grant-aided by Historic England.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1078985	Contact: Conservation Team (LPA) 020 8921 5355

#### PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK	2015 / LONDON /	GREENWICH
	ZOIS / LOINDOIN /	GIVELINGTICIT

LIST ENTRY NUMBER:	Government or agency 1078987	uses. Contact: Verena McCaig 020 7973 3718
OWNER THE.	Government or agency	<b>o o i i</b>
OWNER TYPE:	C	identified. Discussions are ongoing to identify potential new
PRIORITY CATEGORY:	C (C)	Building Consent has been granted for investigative works and some repairs, although funding has not yet been
OCCUPANCY:	Vacant/not in use	concerns about the condition of internal timbers. Listed
CONDITION:	Poor	the reserve collection of the 'Firepower' museum but is now vacant. The roof covering is failing and there are
DESIGNATION:	Listed Building grade II*, CA	Carlton House in 1814 for (premature) celebration of Allied victory in the Napoleonic wars. The Rotunda housed
SITE NAME:	The Rotunda, Greenhill, Woolwich Common SE18	24-sided polygon, single storey building designed by John Nash. Concave conoid roof; first erected in the grounds of
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Woolwich Common SE18         DESIGNATION:       Listed Building grade II*, CA         CONDITION:       Poor         OCCUPANCY:       Vacant/not in use         PRIORITY CATEGORY:       C (C)



Riverside Guard Rooms, Royal Arsenal, Plumstead Road,

Listed Building grade II, CA

Part occupied/part in use

Royal Laboratory to Royal

Arsenal, Plumstead Road,

Listed Building grade II, CA

Woolwich SE18

Vacant/not in use

Commercial company

Commercial company

Woolwich SEI8

Poor

C (E)

Fair

F (F)

1078955



SITE NAME:

DESIGNATION:

CONDITION

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England

©Н



© Royal Borough of Greenwich



		1 /	
	LIST ENTRY NUMBER:	1211082	Contact: Conservation Team (LPA) 020 8921 5355
	SITE NAME:	24, Royal Hill SE10	Early C18 small urban house of central chimneystack plan,
	DESIGNATION:	Listed Building grade II, CA	the smallest known example of the 1703 Moxon Plan. The building has been vacant for some years and is in poor
	CONDITION:	Poor	condition. A scheme for restoration and conversion was agreed in 2011-2012 but has not yet implemented.
	OCCUPANCY:	Vacant/not in use	agreed in 2011 2012 but has not yet implemented.
INCO	PRIORITY CATEGORY:	D (D)	
UN08	OWNER TYPE:	Private	
1	LIST ENTRY NUMBER:	1391248	Contact: Conservation Team (LPA) 020 8921 5355

well underway.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

Royal Arsenal's guardrooms, 1814. The Royal Arsenal site

is owned by Berkeley Homes who are progressing repairs.

roofs renewed, but there are clear signs of major structural movement and a need for extensive repointing. Whilst one

of the guardrooms is currently used for temporary storage,

Royal Arsenal's laboratory, two buildings originally built in

scheme for restoration and conversion to residential use is

1696, reconstructed in 1802 after fire. Both buildings are

within the area covered by the Arsenal Masterplan. A

Planning Permission has been granted for the Arsenal Masterplan. Shell repairs have been carried out and the

Contact: Conservation Team (LPA) 020 8921 5355

no long-term use has been identified.

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2015 / LONDON / GREENWICH / HACKNEY



© Historic England Archive

			A shumsh designed by AVA/NI Dugin linked to a visamera to
	LIST ENTRY NUMBER:	1289024	Contact: Conservation Team (LPA) 020 8921 5355
	OWNER TYPE:	Commercial company	
	PRIORITY CATEGORY:	A (C)	application for the building's demolition was withdrawn by the developer in 2015.
	OCCUPANCY:	Vacant/not in use	condition, although significant features survive. An
	CONDITION:	Very bad	temporary roof since 2008. Much of the late C18 roof structure has been lost and the interior is in poor
1000	DESIGNATION:	Listed Building grade II, CA	whole site has been approved by the Local Authority. The building has been protected by sheeted scaffold and a
	SITE NAME:	Officers' Quarters, Royal Arsenal (building 11), Seymour Street, Woolwich SE18	Officers' block for the Royal Military Academy 1717-20. The Royal Arsenal site is owned by Berkeley Homes who are discussing options for its re-use. A masterplan for the

AL	SITE NAME:	Roman Catholic Church of St Peter, Woolwich New Road, Woolwich SE18	A church designed by AWN Pugin linked to a vicarage to the north and completed in 1843. Built of multi-coloured stock brick with stone dressings in the Decorated style. At
	DESIGNATION:	Listed Place of Worship grade II	a later date the nave was extended to create a chancel and halls were built to the south to house a church school. The
	CONDITION:	Poor	church has problems with roof leakage and falling plaster from the ceilings. The church has appointed an architect to
	PRIORITY CATEGORY:	A (New entry)	oversee the necessary repairs and to prepare a masterplan
	OWNER TYPE:	Religious organisation	to ensure the sustainability of the site.
land	LIST ENTRY NUMBER:	1212426	Contact: Ian Harper 020 7973 3786

© Historic England

#### HACKNEY

1	SITE NAME:	Cleeve Workshops, Calvert Avenue E2	Row of workshops, built 1895-8 to the design of Reginald Minton Taylor of the London County Council as part of the Boundary Estate. Some are in use but all require repair. The owners have had pre-application discussions with the Local Authority.
Long Long Strategy	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1264906	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	7, Clapton Square E5	Early C19 terraced house. The Local Authority has taken enforcement action against unauthorised works and is now
	DESIGNATION:	Listed Building grade II, CA	enforcement action against unauthorised works and is now considering an Urgent Works Notice. The property
1	CONDITION:	Poor	remains in a poor state of repair.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226411	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England

	SITE NAME:	55 and 59, Clapton Terrace E5	Terraced houses, mid to late C18. Suffering from disrepair
	DESIGNATION:	Listed Building grade II, CA	and under use.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
D	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226416	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England Archive

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Marlow House, 160, Dalston Lane E8	Early to mid-C18 house. Listed Building Consent was granted for conversion to residential use in 2011. Work
	DESIGNATION:	Listed Building grade II, CA	are yet to commence.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© Historic England Archive	LIST ENTRY NUMBER:	1226591	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	St Columba's Vicarage and link to church, Kingsland Road E2	Gothic Revival vicarage built 1873-4 to the design of James Brooks. The lantern joinery and leadwork were repaired in
	DESIGNATION:	Listed Building grade I, CA	2011 and localised reslating carried out. Further repair works are still required.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England Archive	LIST ENTRY NUMBER:	1265658	Contact: Rebecca Barrett 020 7973 3716

SITE NAME:	320, Kingsland Road E8	Early C19 terraced house suffering from under use and lack
DESIGNATION:	Listed Building grade II, CA	of maintenance. An enforcement notice was served in May 2013.
CONDITION:	Fair	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1226848	Contact: Conservation Officer (LPA) 020 8356 6408

© London Borough of Hackney

	SITE NAME:	592, Kingsland Road E8	C18 terraced house with a shop on the ground floor. The
	DESIGNATION:	Listed Building grade II, CA	upper floors are disused. Listed Building Consent was granted in 2008 for rebuilding the upper parts of the north
	CONDITION:	Poor	and east wall following structural problems.
	OCCUPANCY:	Part occupied/part in use	
H	PRIORITY CATEGORY:	D (D)	
AMERICAN N	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226776	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England Archive

	SITE NAME:	The Griffin, Leonard Street EC2	Public house circa 1889. The building is suffering from a
	DESIGNATION:	Listed Building grade II, CA	lack of maintenance. Listed Building Consent was granted for conversion of the upper floors in 2012. Works have
	CONDITION:	Poor	started and are due to finish in late 2015.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Private	
वाहा ता ता ता ह	LIST ENTRY NUMBER:	1389397	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England

PRIORITY CATEGORI	S
-------------------	---

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Gas House to west of reservoir, Lordship Road, Stoke Newington N16	Single storey, four bay, stock brick building with moulded brick cornice and parapet. The building no longer has an operational use in connection with the reservoir. A grant
	DESIGNATION:	Listed Building grade II, CA	has been secured from the Heritage Lottery Fund to use the building as a nature reserve visitor centre, and works
	CONDITION: Poor	Poor	are underway.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	CATEGORY: F (D)	
	OWNER TYPE:	Utility	
oric England	LIST ENTRY NUMBER:	1265631	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	Bishop Wood's Almshouses, Lower Clapton Road E5	ate C17 almshouses restored in the late C19. The small chapel and almshouses are all vacant and in a deteriorating
	DESIGNATION:	Listed Building grade II, CA	condition. Discussions are ongoing between the owner and Local Authority to explore options for repair and reuse.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
<u>(</u> _)	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226891	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England

© Histor



	SITE NAME:	New Lansdowne Club, 195, Mare Street E8	Substantial detached house, dating from 1715. The property was bought by new owners in May 2013. Listed
	DESIGNATION:	Listed Building grade II*, CA	Building Consent has been granted for the full refurbishment of the property, including the removal of a
	CONDITION:	Poor	later rear extension. Works are yet to start on site.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1265590	Contact: Rebecca Barrett 020 7973 3716
	SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5	Disinfecting station, built in 1900. Located within a site used as an animal warden's base and as the Local
. 1	DESIGNATION:	Listed Building grade II	Authority's cleansing depot. Proposals are being developed to make the building watertight pending a feasibility study
	CONDITION	Poor	for new uses.

		Station, I millerus Road ES	
	DESIGNATION:	Listed Building grade II	Authority's cleansing depot. Proposals are being develor to make the building watertight pending a feasibility stu
	CONDITION:	Poor	for new uses.
LATER ATTAL	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
England Archive	LIST ENTRY NUMBER:	1253493	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England Archive

D

Е

use).

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Court House and Police Station, Old Street ECI	Former magistrates' court and police station. Listed Building Consent and Planning Permission were granted in
	DESIGNATION:	Listed Building grade II, CA	2012 for conversion into a hotel. Works have commenced on site and the project is due to complete in 2015.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1376533	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	Air Raid Precaution Centre, Rossendale Street (east side) E5	Air raid shelter built in 1938. The building has previously suffered from flooding. It was "adopted" as a monument by
N P P N	DESIGNATION:	Listed Building grade II	a local school, Horizon School in Stoke Newington. Planning Permission and Listed Building Consent were
	CONDITION:	Fair	granted in 2004 for the retention of the air raid shelter a museum and construction of flats above. Works are
- NO	OCCUPANCY:	Vacant/not in use	nearing completion.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
© Historic England Archive	LIST ENTRY NUMBER:	1235876	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	Walls and gates to Bishopsgate Goods Station, Shoreditch High Street El	Late C19 walls to the demolished goods station. The gates were recently repaired and have been re-erected on site. The future use of the structure is currently being discussed
	DESIGNATION:	Listed Building grade II	as part of the wider redevelopment of the Goods Yard. Planning and Listed Building Consent applications are under
	CONDITION:	Poor	consideration.
the state of the s	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
© Historic England Archive	LIST ENTRY NUMBER:	1235316	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	187, Shoreditch High Street EI	Early C18 terraced house with altered facade. The building
BBIE	DESIGNATION:	Listed Building grade II	is vacant and in a deteriorating condition. A temporary metal covering to the roof is providing protection against
LLF	CONDITION:	Very bad	water ingress. Listed Building Consent and Planning Permission have been granted for the conversion of the
FFF	OCCUPANCY:	Vacant/not in use	ground floor to a retail unit, with residential above. Works
	PRIORITY CATEGORY:	B (B)	are expected to start in 2015.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1235320	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	196, Shoreditch High Street EI	Early C18 building. Stabilisation and repair works are
	DESIGNATION:	Listed Building grade II	complete and all floors now have existing or prospective occupiers. Works are due to start in 2015 to convert the
	CONDITION:	Good	ground floor into a restaurant.
FEFFF	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1235410	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

36



	SITE NAME:	Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street E1	C19 churchyard walls and stone coped brick piers that occur at intervals along the walls. The railings and gates around the forecourt to St Leonard's Church were
	DESIGNATION:	Listed Building grade II, CA	repaired in 2010 with funding from Historic England. Like- for-like repairs are now complete to the eastern boundary
	CONDITION:	Fair	wall. Minor repairs to other parts of the wall are still required.
	OCCUPANCY:	N/A	required.
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1235318	Contact: Conservation Officer (LPA) 020 8356 6408

-	SITE NAME:	Shrubland Road Evangelical Church, Shrubland Road E8	A rare and complete example of a temporary iron mission church built in 1858. The building is in need of some repair
	DESIGNATION:	Listed Building grade II, CA	and discussions are ongoing with the owner.
	CONDITION:	Poor	
M	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1245303	Contact: Conservation Officer (LPA) 020 8356 6408



© Historic England

© Historic England

	SITE NAME:	White Lodge, Springfield Park E5	Early to mid-C19 villa. The building is part occupied with a café on the ground floor. Listed Building Consent was
	DESIGNATION:	Listed Building grade II, RPG grade II	granted in November 2011 for the repair and use of the upper floor for community uses. The Local Authority has now submitted an application to the Heritage Lottery Fund
	CONDITION:	Fair	for repairs to the villa and landscaping works to the wider park.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
Re-	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1235414	Contact: Conservation Officer (LPA) 020 8356 6408

	SITE NAME:	91, Stoke Newington Church Street N16Mid-C18 house of three storeys with pedimented front. Although at least partially occupied, the building is falling into disrepair.1Listed Building grade II, CA	
	DESIGNATION:	Listed Building grade II, CA	into disrepair.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
d	LIST ENTRY NUMBER:	1265044	Contact: Conservation Officer (LPA) 020 8356 6408

© Historic England



SITE NAME:	Abney Park Cemetery N16	Laid out as an arboretum cemetery in 1840 from the
DESIGNATION:	Registered Park and Garden grade II, 16 LBs, CA	gardens of two C17 houses. Abney Park is one of London's most important Nonconformist cemeteries. Features of the historic designed landscape survive but are in poor
CONDITION:	Extensive significant problems	condition and, in places, illegible. Two of the monuments and the Mortuary Chapel are also at risk. A programme of
VULNERABILITY:	High	works was carried out in 2013/14 to address health and
TREND:	Declining	safety concerns. Discussions are now underway regarding the strategic direction for future improvements, which will
NEW ENTRY ?:	No	include repair works to the grade II listed Mortuary Chapel.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1000789	Contact: Zosia Mellor 020 7973 3473

© Historic England

- PRIORITY CATEGORIES А
- Immediate risk of further rapid deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site
- 37

	SITE NAME:	Monument to Joanna Vassa, Stoke Newington High Street, Abney Park Cemetery N16	A four-sided stone pedestal with lotus bud cornice surmounted by an urn commemorating the death of the daughter of black abolitionist Olaudah Equiano in 1857.		
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	Previous repairs have failed and there is widespread erosion. Discussions are ongoing to agree a schedule of repairs and to explore possible sources of funding.		
	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
© Historic England	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	39285	Contact: Conservation Officer (LPA) 020 8356 6408		
	SITE NAME:	Monument to John Swan, Stoke Newington High Street, Abney Park Cemetery N16	A white marble draped urn over pedestal from around 1869. The surface is badly damaged by erosion, dirt and organic growth. The adjacent pedestal, which was leaning		
	SITE NAME: DESIGNATION:	Newington High Street, Abney	1869. The surface is badly damaged by erosion, dirt and		
		Newington High Street, Abney Park Cemetery N16 Listed Building grade II, RPG	1869. The surface is badly damaged by erosion, dirt and organic growth. The adjacent pedestal, which was leaning against the monument to John Swan, has been moved. Discussions are ongoing to agree a schedule of repairs and		
	DESIGNATION:	Newington High Street, Abney Park Cemetery N16 Listed Building grade II, RPG grade II, CA	1869. The surface is badly damaged by erosion, dirt and organic growth. The adjacent pedestal, which was leaning against the monument to John Swan, has been moved. Discussions are ongoing to agree a schedule of repairs and		
	DESIGNATION: CONDITION:	Newington High Street, Abney Park Cemetery N16 Listed Building grade II, RPG grade II, CA Poor	1869. The surface is badly damaged by erosion, dirt and organic growth. The adjacent pedestal, which was leaning against the monument to John Swan, has been moved. Discussions are ongoing to agree a schedule of repairs and		
© Historic England	DESIGNATION: CONDITION: OCCUPANCY:	Newington High Street, Abney Park Cemetery N16 Listed Building grade II, RPG grade II, CA Poor N/A	1869. The surface is badly damaged by erosion, dirt and organic growth. The adjacent pedestal, which was leaning against the monument to John Swan, has been moved. Discussions are ongoing to agree a schedule of repairs and		



© Historic England



© Historic England

10-	SITE NAME:	Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16	Gothic Revival cemetery chapel, dating from 1839 and now ruinous. The chapel is situated in the centre of the early C19 cemetery and is a feature of views along the main		
-	DESIGNATION:	Listed Building grade II, RPG grade II, CA	avenues. A condition survey was completed in 2012 and a further structural survey was carried out in early 2015. The chapel is currently fenced off and discussions are ongoing		
	CONDITION:	Very bad	to explore future uses and possible sources of funding.		
E AN	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	A (A)			
	OWNER TYPE:	Local authority			
	LIST ENTRY NUMBER:	1265023	Contact: Conservation Officer (LPA) 020 8356 6408		
JAN P		• • • • • • • • • • • •			
The sea	SITE NAME:	9, Victorian Grove N16	Early to mid-C19 semi-detached house of stock brick. T ground floor has a distinctive bow window, with decora		
8 1 1	DESIGNATION:	Listed Building grade II	cast iron balcony railings and curved canopy above. The		
12.24	CONDITION:	Poor	building is currently vacant and has been stripped of many internal features. An application has been submitted to		
high A	OCCUPANCY:	Vacant/not in use	reinstate these features and to retain the building in		
-	PRIORITY CATEGORY:	C (New entry)	residential use.		
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1235551	Contact: Conservation Officer (LPA) 020 8356 6408		

SITE NAME: Mid-C19 Tudor style building, probably originally a school. Premises of Testi and Sons The building is currently vacant and repairs are required to the roof and stonework. Planning and Listed Building Millwrights, Waterworks Lane E5 Consent applications have been submitted for the DESIGNATION: Listed Building grade II, CA conversion of the building into two residential units. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (D) OWNER TYPE: Commercial company © Historic England Archive LIST ENTRY NUMBER: 1264991 Contact: Conservation Officer (LPA) 020 8356 6408

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Haggerston Baths, Whiston Road E2	Public baths and swimming pool, dating from 1904. The building is now vacant and in a state of disrepair. The Lo	
	DESIGNATION:	Listed Building grade II	Authority has sought expressions of interest for the building to bring it back into viable use (June 2015).	
	CONDITION:	Poor		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority		
© Historic England Archive	LIST ENTRY NUMBER:	1235838	Contact: Conservation Officer (LPA) 020 8356 6408	

	SITE NAME:	Church of St Andrew, Bethune Road, Stoke Newington N16	Church built 1883-4 by Sir Arthur Blomfield in the Early English style. Kentish ragstone with Bath stone dressings.
	DESIGNATION:	Listed Place of Worship grade II*	Although plain externally, the interior is richly decorated. The interior is now deteriorating due to dampness and
	CONDITION:	Poor	water ingress. The church has been awarded a first round pass from the Heritage Lottery Fund and has started the
	PRIORITY CATEGORY:	B (B)	development phase of the project.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1264896	Contact: Ian Harper 020 7973 3786
AT THE STORE			

© Historic England Archive

	SITE NAME:	Church of St John of Jerusalem, Lauriston Road E9	Church by EC Hakewill of 1845-8 in the Early English style. The church has a cruciform plan with west tower in Kentish
	DESIGNATION:	Listed Place of Worship grade II*, CA	ragstone, limestone dressings and slate roofs. Repair works to the roofs and high level stonework, grant-aided by Historic England and the Heritage Lottery Fund, are now
	CONDITION:	Fair	complete. However, there is still another phase of maso repair work to be carried out. In March 2015 the church
	PRIORITY CATEGORY:	C (C)	was awarded a grant from the Listed Places of Worship
	OWNER TYPE:	Religious organisation	Roof Repair Fund.
	LIST ENTRY NUMBER:	1226409	Contact: Ian Harper 020 7973 3786

© Historic England



SITE NAME:	Old Church of St Mary, Stoke Newington Church Street, Stoke Newington N16	The old parish church of Stoke Newington dates from 1563. The church was restored in 1827-29 by Charles Barry who raised new roofs on a clerestory and added the
DESIGNATION:	Listed Place of Worship grade II*, CA	spire and an outer north aisle, which was not rebuilt after World War II damage. Consequently the soft red bricks, now exposed to the weather on the north side, are
CONDITION:	Poor	deteriorating badly. Much of the external fabric needs repairs, including the tower, cracked renders and open
PRIORITY CATEGORY:	C (C)	joints to copings. The churchyard is heavily overgrown,
OWNER TYPE:	Religious organisation	with the monuments suffering accordingly.
LIST ENTRY NUMBER:	1235419	Contact: Ian Harper 020 7973 3786

© Historic England



	SITE NAME:	Church of St Leonard, Shoreditch High Street El	Church built between 1736 and 1740 to the design of George Dance the Elder. Built in brick with a Portland		
2.4	DESIGNATION:	Listed Place of Worship grade I, CA	stone front facade and dressings, with slate roofs. The roofs to the nave, north and south aisles, and the flat roofs either side of the tower have been repaired with funding		
2	CONDITION:	Poor	from the Heritage Lottery Fund and Historic England. Further works are required to the tower, spire and		
	PRIORITY CATEGORY:	C (C)	portico, as well as the interior.		
	OWNER TYPE:	Religious organisation			
ŝ	LIST ENTRY NUMBER:	1235382	Contact: Tracey Craig 020 7973 3756		

© Historic England Archive

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 39

#### HERITAGE AT RISK 2015 / LONDON / HACKNEY / HAMMERSMITH AND FULHAM



SITE NAME:	Church of St Matthias, Wordsworth Road, Stoke Newington N16	The church by Williar Bath ston
DESIGNATION:	Listed Place of Worship grade I	rainwater from the
CONDITION:	Poor	Another and the re
PRIORITY CATEGORY:	C (D)	need of r
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	I 26503 I	Contact:

ch was completed in 1851 to an innovative design m Butterfield in free Gothic style. Stock brick with ne dressings. Repairs to the nave roof and r goods were completed in May 2015 with funding Heritage Lottery Fund and Historic England. phase of roof repairs is required to the aisle roofs, poofs and masonry of the upper tower are also in repair.

lan Harper 020 7973 3786

Contact: Adam O'Neill (LPA) 020 8753 3318

© Historic England

SITE NAME:	Dalston Lane (West), Dalston E8		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739
SITE NAME:	Mare Street, Hackney Central E8		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739
SITE NAME:	Sun Street, City of London EC2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739

#### HAMMERSMITH AND FULHAM




SITE NAME:	34, Black Lion Lane, St Peter's Square W6	Cottage, early to mid-C19. Stuccoed and painted brick. Listed Building Consent has been granted for the
DESIGNATION:	Listed Building grade II, CA	restoration of the building and works are now at an advanced stage.
CONDITION:	Fair	-
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	E (E)	
OWNER TYPE:	Private	
OWNER TYPE:	Private	

© Historic England



© Historic England



#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

LIST ENTRY NUMBER:

1287039

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

ŬA

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / HAMMERSMITH AND FULHAM



© Historic England

Fulham

Fulham

©۲

The second	SITE NAME:	Vault of Campbell Family, Harrow Road, St Mary's Roman Catholic Cemetery NW10	Mausoleum by CHB Quennell in Byzantine style, erected in 1904. There is severe damage to the brickwork bands and internal marble cladding, and vegetation is growing through
	DESIGNATION:	Listed Building grade II, CA	the roof. There is also evidence of anti-social activity. Historic England has funded a condition survey to identify
	CONDITION:	Very bad	necessary repairs. Discussions have begun to identify possible funding sources that would enable these works to
	OCCUPANCY:	N/A	be carried out.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1079822	Contact: Adam O'Neill (LPA) 020 8753 3318

SITE NAME: Hope and Anchor public house, Public house in neo-Georgian style dating from 1936. Built for Truman's as part of a housing estate. The building is an Macbeth Street, Hammersmith unusual survival with two exceptionally intact 1930s bar W6 interiors. The public house business closed in 2012. There DESIGNATION: Listed Building grade II, CA is no identified future use for the bar area, although it is occasionally used as a film location. The upper floors are CONDITION: Fair currently occupied and in residential use. Discussions with OCCUPANCY: Part occupied/part in use the owner are ongoing. PRIORITY CATEGORY: E (E) OWNER TYPE-Private © London Borough of Hammersmith and LIST ENTRY NUMBER: 1392791 Contact: Adam O'Neill (LPA) 020 8753 3318



SITE NAME: Tomb of Frederick Harold Mausoleum dating from 1884. The parapet to the west elevation is missing and there is some broken or missing Young, Margravine Road, glass. The flashing was stolen in 2012. The interior has not been inspected. Discussions are ongoing to identify funding Hammersmith Cemetery W6 DESIGNATION: Listed Building grade II, CA for repair works. CONDITION: Poor OCCUPANCY. N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown © London Borough of Hammersmith and LIST ENTRY NUMBER: 1072617 Contact: Adam O'Neill (LPA) 020 8753 3318

	SITE NAME:	Tomb of Samuel Jones, Queen Caroline Street, St Paul's Churchyard W6	Table tomb over a brick and stone plinth dating from the end of the C18. There is evidence of severe mechanical damage and erosion as well as rusting of the remaining
	DESIGNATION:	Listed Building grade II, CA	railings. There was also invasive vegetation, which the church was asked to remove in 2014. A planning
Historic England	CONDITION:	Very bad	application has been submitted to relocate the tomb with the churchyard in connection with its restoration. The tomb is currently behind a protective hoarding. Discussion
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	are ongoing to identify funding for repair works and relocation.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1246022	Contact: Adam O'Neill (LPA) 020 8753 3318

Nurses' home, 1938 by Burnet, Tait and Lorne. The SITE NAME: Ashlar Court, Former Royal Masonic Hospital Nurses building had been vacant since the cessation of an unauthorised budget hotel use in 2009. Works for Home, Ravenscourt Gardens conversion to residential use are at an advanced stage W6 towards completion and most units are now occupied. пп DESIGNATION: Listed Building grade II, CA Outstanding conditions attached to the Listed Building Consent are yet to be discharged. CONDITION: Good OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: F (F) OWNER TYPE: © Historic England Private LIST ENTRY NUMBER: 1269052 Contact: Adam O'Neill (LPA) 020 8753 3318

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. D Under repair or in fair to good

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use F agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG SM
- ΪA

Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / HAMMERSMITH AND FULHAM / HARINGEY

-	SITE NAME:	Former Royal Masonic Hospital, Ravenscourt Park, Hammersmith W6	Hospital, 1933 by Thomas Tait, funded by the Freemasons. The building has been vacant since the closure of the NHS facility in 2006. Listed Building Consent was granted in
	DESIGNATION:	Listed Building grade II*, CA	2008 for refurbishment in connection with a cancer treatment hospital proposal. Some works, including the
ESA MA IL-	CONDITION:	Fair	dismantling of the garden walls and sundial, have been
	OCCUPANCY:	Vacant/not in use	undertaken, but conversion work has stalled. Parapet repairs were undertaken in 2011/12. New proposals for a
A CONTRACT CONTRACTOR STATES	PRIORITY CATEGORY:	E (E)	potential hospital use are awaited.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1192740	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Church of St Peter, Black Lion Lane, Hammersmith W6	Built in 1829, designed by Edward Lapidge. Rectangular plan with a pedimented entrance portico with tower above
	DESIGNATION:	Listed Place of Worship grade II*, CA	surmounted by a copula. Built in brick with stone dressings and a slate pitched roof behind a parapet. The external envelope is in good condition having being re-roofed.
	CONDITION:	Poor	Internally the plaster ceilings are of concern exhibiting
	PRIORITY CATEGORY:	C (New entry)	deflection and cracking and two areas have had timber propping installed to mitigate against collapse. The
	OWNER TYPE:	Religious organisation	congregation is actively exploring possible sources of funding.
	LIST ENTRY NUMBER:	1079843	Contact: Tracey Craig 020 7973 3756
© Historic England			
the man	SITE NAME:	Church of St John, North End Road, Walham Green SW6	Church built in 1827 designed by George Ledwell Taylor. Most roof slopes have artificial slates which are in poor
1-2-1	DESIGNATION:	Listed Place of Worship grade II, CA	condition. Walling is brick with Bath stone dressings. The tower suffers from rusting buried iron, causing damage to the stone. The tower openings have large perforated stone
1. 1	CONDITION:	Poor	panels rather than louvres and there are concerns over their structural stability due to spalling. A Heritage Lottery
	PRIORITY CATEGORY:	F (D)	Fund/Historic England grant has been awarded for re-
	OWNER TYPE:	Religious organisation	covering the aisle roofs and tower repairs. Work is currently underway and is due to complete in summer
	LIST ENTRY NUMBER:	1079751	2015.
© Historic England			Contact: Tracey Craig 020 7973 3756
SITE NAME:	St Mary's, Kensal	Green NW10	
	Ser lary s, icelisal	GICCHINTTO	

DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Adam O'Neill (LPA) 020 8753 3318

#### HARINGEY

	SITE NAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N10	Entertainment complex including exhibition hall, music hall and theatre, built 1868-73. First ever television centre,
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	1935. Urgent repairs to the loggia on the south terrace and south east roofs were completed in 2013, part funded by Historic England. Funding has now been secured from the
State Annes	CONDITION:	Poor	Heritage Lottery Fund to restore the eastern part of the building, including the theatre and former BBC Studios.
	OCCUPANCY:	Part occupied/part in use	Discussions regarding other parts of the building not
	PRIORITY CATEGORY:	D (C)	included in the Heritage Lottery Fund bid are ongoing.
© Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1268256	Contact: Nairita Chakraborty (LPA) 020 8489 2841

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Hornsey Town Hall, Broadway N8	Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important
	DESIGNATION:	Listed Building grade II*, CA	influence in subsequent British town hall design. The building is vacant and in a poor condition. Discussions
	CONDITION:	Poor	regarding the future use and repair of the building are ongoing, following the withdrawal of a bid to the Heritage
	OCCUPANCY:	Vacant/not in use	Lottery Fund for a theatre and drama school.
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1263688	Contact: Rebecca Barrett 020 7973 3716

7, Bruce Grove, Tottenham

Listed Building grade II, CA

NI7

Very bad

Vacant/not in use



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

Public toilet circa 1920, with fine external ironwork. Empty Public toilets, Bruce Grove, Tottenham NI7 and deteriorating. The ironwork has been restored as part of a partnership scheme between the Local Authority and Listed Building grade II, CA Historic England and a feasibility study has been undertaken. Discussions regarding future use are ongoing. Poor Vacant/not in use C (C) Local authority LIST ENTRY NUMBER: 1259316 Contact: Nairita Chakraborty (LPA) 020 8489 2841

works are carried out.



© London Borough of Hari

© London Borough of Haringey



© London Borough of Hari



	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
aringey	LIST ENTRY NUMBER:	1188605	Contact: Nairita Chakraborty (LPA) 020 8489 2841
	SITE NAME:	South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17	Probably early C17 red brick wall in Flemish bond, with tall sloped coping and plinth. The wall is ramped gently up at intervals towards the west. It is now seriously deteriorating
	DESIGNATION:	Listed Building grade II, CA	with open decayed pointing, loose and unstable brickwork, previous re-pointing damage, and extensive ivy/creeper
	CONDITION:	Poor	and frost damage. A programme of urgent repairs has been undertaken, but further repairs are required.
	OCCUPANCY:	N/A	under taken, but fui ther repairs are required.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
aringey	LIST ENTRY NUMBER:	1079218	Contact: Nairita Chakraborty (LPA) 020 8489 2841
	SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17	C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as the brickwork is
	DESIGNATION:	Listed Building grade II, CA	deteriorating. An initial programme of repairs has been undertaken, but further works are needed.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	

© London Borough of Haringey

Contact: Nairita Chakraborty (LPA) 020 8489 2841

One of a pair of early C19 houses. The building is vacant

and has suffered substantial internal collapse. A scheme of refurbishment and conversion to flats has been approved,

but not yet implemented. The Local Authority is also considering statutory action to ensure that essential repair

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

LIST ENTRY NUMBER:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

1294666

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

HERITAGE AT	RISK 2015 /		HARINGEY
	1031 20137	LONDON	

© Historic Engla

© Historic Er

	SITE NAME:	Drinking fountain and cattle trough, High Road, Wood Green N22	Cattle trough and drinking fountain, 1901. Elaborate Roman baroque style stone fountain head with grey granite trough. Some repair works have been carried out, but
	DESIGNATION:	Listed Building grade II, CA	further works are still required. The Local Authority is actively exploring options for funding.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
NSP Bas	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
land	LIST ENTRY NUMBER:	1249717	Contact: Nairita Chakraborty (LPA) 020 8489 2841

	SITE NAME:	662, High Road, Tottenham N17	Early C18 building of three storeys, in stock brick with stone coped parapet, lower than the neighbouring
	DESIGNATION:	Listed Building grade II, CA	properties with which it has group value. The building was badly fire damaged during the 2011 riots. Listed Building
	CONDITION:	Very bad	Consent has been granted for the repair and refurbishment of the building with office use at ground floor level and
	OCCUPANCY:	Vacant/not in use	residential above, including a mansard extension at root
	PRIORITY CATEGORY:	F (B)	level. Works have commenced but are not yet complete.
11Huns	OWNER TYPE:	Commercial company	
England	LIST ENTRY NUMBER:	1358832	Contact: Nairita Chakraborty (LPA) 020 8489 2841

	SITE NAME:	Warmington House, 744, High Road, Tottenham N17	Early C19 house last used as offices and now partly in use for storage. The building is to be restored as part of the
	DESIGNATION:	Listed Building grade II, CA	proposed Tottenham Hotspur Football Club stadium redevelopment proposal.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© London Borough of Haringey	LIST ENTRY NUMBER:	1358833	Contact: Nairita Chakraborty (LPA) 020 8489 2841

.1	SITE NAME:	Percy House, 796, High Road, Tottenham N17	Mid-C18 house with late C17 forecourt walls and railings. The Heritage Lottery Fund has awarded Tottenham
	DESIGNATION:	Listed Building grade II*, CA	Hotspur Foundation a grant for the restoration of Percy House to provide an employment, enterprise and skills
	CONDITION:	Fair	hub.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
Statistics of the local division of the loca	OWNER TYPE:	Commercial company	
© London Borough of Haringey	LIST ENTRY NUMBER:	1079242	Contact: Rebecca Barrett 020 7973 3716

	SITE NAME:	810, High Road, Tottenham N17	Fine house built circa 1715 as part of a symmetrical pair. The exterior was restored by a building preservation trust.
	DESIGNATION:	Listed Building grade II*, CA	The trust has secured agreement to undertake the internal refurbishment and re-use of the building as part of
	CONDITION:	Fair	Tottenham Hotspur Football Club's redevelopment proposals.
i i i i i i i i i i i i i i i i i i i	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
© London Borough of Haringey	LIST ENTRY NUMBER:	1358835	Contact: Rebecca Barrett 020 7973 3716

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

© Londo

٥I



田田	SITE NAME:	62, Monument Way, Tottenham NI7	Late C18 three storey detached house, also known as 62 High Cross Road. Seriously affected by water penetration
H	DESIGNATION:	Listed Building grade II	into the structure and interior. Consent for conversion into flats was granted in August 2012, but has not yet been
	CONDITION:	Poor	implemented.
<b>*</b>	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
on Borough of Haringey	LIST ENTRY NUMBER:	1079226	Contact: Nairita Chakraborty (LPA) 020 8489 2841

	SITE NAME:	Porters and Walters Almshouses, St Leonard's Almshouses, Nightingale Road, Wood Green N22	Four two storey almshouses, circa 1904, which form a group with a commemorative stone and front railings. The buildings have suffered from a lack of proper maintenance over a number of years.
	DESIGNATION:	Listed Building grade II, CA	
© London Borough of Haringey	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Trust	
	LIST ENTRY NUMBER:	1079222	Contact: Nairita Chakraborty (LPA) 020 8489 2841

LIST ENTRY NUMBER:	1358860	Heritage Lottery Fund grant has been offered for the repair of the tower roof. Contact: Ian Harper 020 7973 3786
	5 5	
o menter men	Religious of garlisation	Heritage Lottery Fund grant has been offered for the repair
OWNER TYPE	Religious organisation	dressings under a plain tiled roof. Internal fittings are of a high quality. The original roof is in need of repair. A Heritage Lottery Fund grant has been offered for the repair
PRIORITY CATEGORY:	D (C)	
CONDITION:	Poor	facade with its Calvary carved in Portland stone. The church is in London stock with Bath stone and soft red
DESIGNATION:	Listed Place of Worship grade II, CA	started the work and was succeeded by his pupil Henry Wilson (west nave and Lady Chapel) and J Harold Gibbons, who in 1916 completed the Arts and Crafts
SITE NAME:	Church of St Augustine, Archway Road, Hornsey N6	The Art Workers Guild background of the three architects involved in this late C19 church is very apparent. JF Sedding
	DESIGNATION: CONDITION: PRIORITY CATEGORY:	Archway Road, Hornsey N6         DESIGNATION:       Listed Place of Worship grade II, CA         CONDITION:       Poor

	SITE NAME:	Parish Church of All Hallows, Church Lane, Tottenham N17	This medieval chu battlements. The
	DESIGNATION:	Listed Place of Worship grade II*, CA	chancel and east e other internal alte 1875-7. Although
	CONDITION:	Poor	internally. The ro
	PRIORITY CATEGORY:	C (C)	funding. Internally
that is	OWNER TYPE:	Religious organisation	stonework, partic important monum
A REAL PROPERTY OF	LIST ENTRY NUMBER:	1188633	poor condition.
			Contact: Jan Harr

north aisle was rebuilt in 1855. The end extensions, raised clerestories and terations were by William Butterfield in h altered, the CI4 and CI5 fabric survives oofs and valley gutters are in need of repair actively exploring possible sources of y there is localised decay to the icularly at the west end. There are mental tombs in the churchyard, also in

Contact: lan Harper 020 7973 3786

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / HARINGEY / HARROW

	SITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The former Tottenham Palace was built in 1908 by Wylson Long as a variety theatre. The building is now in use for worship. It is suffering from water ingress, which is causing
	DESIGNATION:	Listed Place of Worship grade II, CA	significant damage to both the structure and interior plaster work. Repair works have commenced and are due for completion in 2015.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
© London Borough of Haringey	LIST ENTRY NUMBER:	1249660	Contact: Ian Harper 020 7973 3786

SITE NAME:	Bruce Grove NI7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Clyde Circus N15		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Noel Park N22		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	North Tottenham High Road N17		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Scotland Green NI7		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841

HARROW



SITE NAME:	Brick Kiln to south east of the Kiln, Common Road, Stanmore	Lower part of an C18 brick kiln conical chimney of which the upper part no longer exists. In urgent need of structural
DESIGNATION:	Listed Building grade II	stabilisation and repair.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1079710	Contact: Lucy Haile (LPA) 020 8736 6101

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / HARROW

8 Parts	SITE NAME:	Pinner Park Farmhouse, George V Avenue, Pinner	The building dates from circa 1750. It is two storeys with three bays plus hipped wing. The windows to the main
1	DESIGNATION:	Listed Building grade II	house are altered. The building appears in good condition externally but the interior requires attention. There has
	CONDITION:	Poor	been damage from water penetration from the central valley gutter and the building is partly vacant.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
16.	OWNER TYPE:	Local authority	
Borough of Harrow	LIST ENTRY NUMBER:	1079715	Contact: Lucy Haile (LPA) 020 8736 6101

Garden wall to Bernays

Stanmore

Poor

N/A

D (D)

1079749

Local authority

Gardens, Old Church Lane,

Listed Building grade II, CA



© London Borough of Harrow

© London B

-	SITE NAME:	Cannons Farm Barn, Hereford Gardens, Pinner	C17 barn with three bays and a narrow central bay. The Local Authority approved the change of use of the building,
-	DESIGNATION:	Listed Building grade II	as well as its repair and restoration. Works have been carried out and the building is now in use. However,
	CONDITION:	Good	unauthorised boundary treatments need addressing.
-	OCCUPANCY:	Occupied/in use	
-	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079725	Contact: Lucy Haile (LPA) 020 8736 6101



PRIORITY CATEGORY: OWNER TYPE: © London Borough of Harrow

SITE NAME:

DESIGNATION:

CONDITION

OCCUPANCY:

LIST ENTRY NUMBER:

C19 wall with buttresses. A high number of bricks are significantly decayed and the wall is in need of repointing. Listed Building Consent and Planning Permission were granted in April 2013 for the restoration of the wall. Funding is being sought.

Contact: Lucy Haile (LPA) 020 8736 6101

	SITE NAME:	Headstone Manor, Pinner View, Harrow	Manor house dating from the C14 with C16, C17 and C1 fabric, surrounded by a moat. Believed to be the earliest surviving timber-framed building in Middlesex, and the oldest complete water-filled moat in Greater London. The Local Authority has secured a grant from the Heritage Lottery Fund to restore the building, part of a wider masterplan to provide Harrow's heritage centre and
	DESIGNATION:	Listed Building grade I, SM	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (C)	community museum.
	OWNER TYPE:	Local authority	
© London Borough of Harrow	LIST ENTRY NUMBER:	1285855	Contact: Elizabeth Whitbourn 07889 808145



L	SITE NAME:	Harrow Magistrates Court, Rosslyn Crescent, Wealdstone	The Jasper Foundation has acquired the building with the intention of carrying out repairs and finding a new use.
	DESIGNATION:	Listed Building grade II	Unauthorised works have been carried out, including the removal of original fixtures and fittings. A listed building
	CONDITION:	Poor	enforcement case is open and the outcome of an appeal against refusal of Listed Building Consent is awaited.
	OCCUPANCY:	Occupied/in use	against relation of Elocal Danaling Conserve is awared.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1390755	Contact: Lucy Haile (LPA) 020 8736 6101

© London Borough of Harrow

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / HARROW



SITE NAME:	Boundary wall fronting road from Nos 118-128, Stanmore Hill (east side), Stanmore	C18 brick wall with buttresses with chamfered bases. Many bricks at the base have weathered away and parts require repointing. The Local Authority is discussing repairs with
DESIGNATION:	Listed Building grade II, CA	the owners.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1194205	Contact: Lucy Haile (LPA) 020 8736 6101

© London Borough of Harrow



© London Borough of Harrow

	SITE NAME:	Boundary wall fronting road (Hill House), 173, Stanmore Hill (West Side), Stanmore	This brick wall originates from the C18 or early C19. It is 10 foot high, built of red brick with chamfered pilaster buttresses. Many sections of the wall have weathered away	
	DESIGNATION:	Listed Building grade II, CA	and parts require repointing. The owner is aware of the issue.	
	CONDITION:	Poor		
97	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Other not for profit group		
	LIST ENTRY NUMBER:	1079648	Contact: Lucy Haile (LPA) 020 8736 6101	

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© London Borough of Harrow



The now roofless ruined church of St John the Evangelist SITE NAME: Old Stanmore Church, Church was built in 1632, attributed to Nicholas Stone. The wall Road, Stanmore heads have exposed brickwork allowing rainwater ingress. Listed Place of Worship grade This is resulting in the erosion of mortar and bricks and DESIGNATION: II\*, CA supporting deleterious plant growth. There is decayed mortar, brick, stone and timber elsewhere around the CONDITION: Poor building along with some vertical cracking in the walling. PRIORITY CATEGORY: The church is occasionally used for worship. C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1079747 Contact: Tracey Craig 020 7973 3756

The Rayners public house, 23,

Village Way East

Vacant/not in use

Good

E (E)

Private

1392310

Listed Building grade II

© Historic England

© Historic England



SITE NAME:	Bentley Priory	
DESIGNATION:	Registered Park and Garden grade II, LB grade II*	
CONDITION:	Generally satisfactory but with significant localised problems	
VULNERABILITY:	Medium	
TREND:	Improving	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1001440	

A CI6 estate enlarged and improved in the late CI8. Sir Uvedale Price and William Gilpin influenced the design in the early C19. Royal Air Force Fighter Command occupied the mansion from 1936 and it played a central role during World War II. The mansion has been converted to a museum with residential units and additional housing in the grounds. A Conservation Management Plan has been prepared to guide landscape restoration, including works to the Italian Gardens. Natural England is preparing a Parkland Management Plan for land owned and managed by the LPA, with input from the Friends group.

A virtually unaltered 1930s public house retaining its

been empty since 2006. Listed Building Consent was

the building is being sought.

Contact: Lucy Haile (LPA) 020 8736 6101

internal plan form and original fittings. The building has

granted for the repair, renovation and reuse of the building and outline Planning Permission granted for surrounding

development that will help to secure funding for its future.

The works of repair have largely been implemented though

the curtilage listed wall awaits work and a new occupier for

Contact: Zosia Mellor 020 7973 3473

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG SM
- ΪA
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / HARROW / HAVERING

SITE NAME:	Grim's Ditch: four linear sections between Uxbridg	e Road and Oxhey	Lane
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: section extending 1500yds (1370m) n	orth east from Ox	hey Lane
DESIGNATION:	Scheduled Monument, part in RPG grade II, part in CA	LIST ENTRY NUMBER:	1002044
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: section north of Blythwood House		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002007
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Linear earthworks in Pear Wood, west of Watling S	Street	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001996
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
	-		
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
OWNER TYPE:	Local authority Pinner deer park, Pinner Park Farm	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	,	CONTACT:	Elizabeth Whitbourn 07889 808145
	Pinner deer park, Pinner Park Farm		
SITE NAME: DESIGNATION:	Pinner deer park, Pinner Park Farm Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1019135

### HAVERING



	SITE NAME:	Stable block, Rainham Hall, Broadway, Rainham	Stables and coach house dating from the C18. Works are underway to restore the stable block to provide a National
	DESIGNATION:	Listed Building grade II*, CA	Trust cafe and community/learning space, grant-aided by the Heritage Lottery Fund. Works are due to be
	CONDITION:	Fair	completed in summer 2015.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
_	LIST ENTRY NUMBER:	1183554	Contact: Verena McCaig 020 7973 3718

© Historic England

OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1183554	Contact: Verena McCaig 020 79

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / HAVERING



CI6 and later garden walls to Ockendon Hall (now Garden walls to former North SITE NAME: demolished). Slowly deteriorating. Ockendon Hall, Church Lane, North Ockendon DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1300500 Contact: Heritage Officer (LPA) 01708 432606

© London Borough of Havering



	SITE NAME:	Bridge in Parklands Park, Corbets Tey Road, Upminster	C18 bridge, attributed to James Paine; in the former landscaped park to Gaynes House (demolished), and now
C F	DESIGNATION:	Listed Building grade II, CA	a public park. Listed Building Consent has been granted for the full repair of the bridge. Work started in spring 2015
	CONDITION:	Poor	and is expected to be completed in late summer.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079928	Contact: Heritage Officer (LPA) 01708 432606

© Historic England



SITE NAME: Outbuilding to the rear of The C19 timber-framed outbuildings which continue the line of Old Anchor, Harwood Hall the rear wing of The Old Anchor, a C18 timber-framed house. The building is in need of re-roofing and the Lane brickwork is seriously decayed and in need of repair, along DESIGNATION: Listed Building grade II, CA with the renewal of the timber lintels. The Local Authority and Historic England are in discussion with the owners CONDITION: Poor regarding options for repair. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1079891 Contact: Heritage Officer (LPA) 01708 432606

J A	SITE NAME:	Mill Cottage, The Dell, High Street, Hornchurch	Single storey timber-framed range, dating from the C17. Now one dwelling. The building is in poor condition and
Alter	DESIGNATION:	Listed Building grade II, CA	continuing to deteriorate. A survey is needed to establish the extent of works required and the Local Authority has
	CONDITION:	Poor	discussed this with the owner.
SAUK SA	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
of Havering	LIST ENTRY NUMBER:	1079898	Contact: Heritage Officer (LPA) 01708 432606

© London Borough o



High House Farmhouse, SITE NAME: Ockendon Road DESIGNATION: Listed Building grade II\*, CA CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1079867

F

Three storey house of brick and timber frame c1700 with older timber-framed wing. The timber frame to the three storey section is under stress, the porch is propped by scaffold and there is significant water damage from the roof. Many of the rooms are uninhabitable. There is extensive vegetation growth on the exterior of the building which is accelerating decay and needs to be removed as soon as possible. The Local Authority and Historic England are in discussion with the owners regarding options for repair.

Contact: Verena McCaig 020 7973 3718

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е


repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS
- 50

#### HERITAGE AT RISK 2015 / LONDON / HAVERING



A ALINE	SITE NAME:	Upminster Windmill, St Mary's Lane, Upminster	Smock mill 1803, retaining original machinery. The building preservation trust (Friends of Upminster Windmill), in
2 mars	DESIGNATION:	Listed Building grade II*	conjunction with the Local Authority, has been awarded a grant from the Heritage Lottery Fund. The project include the full restoration of the mill, and the provision of a workshop and visitors' centre on the site. Regular public access will be provided. Works are planned to start on the education centre in August 2015, and restoration works will commence on the mill in early 2016.
1 1994	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
THE THE	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
gland	LIST ENTRY NUMBER:	1079878	Contact: Verena McCaig 020 7973 3718

© Historic Engl



© London Borough of Havering

© Histo

SITE NAME: Garden walls at Cranham Hall, CI6 walls to an earlier house on the site of Cranham Hall. In need of extensive repairs. Uncontrolled plant growth is The Chase, Cranham causing further deterioration. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: Contact: Heritage Officer (LPA) 01708 432606 1183600

	SITE NAME:	Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	Footbridge and eye-catcher, circa 1765, probably by James Paine who laid out the estate of Gaynes Park in the 1760s
	DESIGNATION:	Listed Building grade II	for Sir James Esdaile, Lord Mayor of London 1777-78. Some structural repairs have been carried out in the past,
	CONDITION:	Poor	and an application for funding for further repair works is being prepared.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Local authority	
oric England	LIST ENTRY NUMBER:	1323729	Contact: Heritage Officer (LPA) 01708 432606

SITE NAME: Dagnam Park Farm moated site, Noak Hill, Romford DESIGNATION: LIST ENTRY NUMBER: 1001988 Scheduled Monument Generally satisfactory but with significant localised CONDITION: TREND: Stable problems PRINCIPAL VULNERABILITY: NEW ENTRY? Vandalism No OWNER TYPE: CONTACT: Elizabeth Whitbourn 07889 808145 Local authority SITE NAME: Romford DESIGNATION: Conservation Area, 4 LBs NEW ENTRY? No CONDITION: TREND: Very bad Improving VULNERABILITY: CONTACT: Planning Service (LPA) 01708 433100 Low

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.

С Slow decay; no solution agreed. Slow decay; solution agreed but F not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

#### ABBREVIATIONS

Conservation Area Listed Building

- LB I PA
- Local Planning Authority National Park NP
- RPG

Registered Park and Garden Scheduled Monument

SM

UA Unitary Authority WHS World Heritage Site

#### HILLINGDON




	SITE NAME:	Barn to the west of Weekly House, Bath Road, Harmondsworth	Late C17 or early C18 weatherboarded barn with tiled roof. Queen post truss at west end. Weekly House, the boundary wall and the barn form a group. The barn is in
	DESIGNATION:	Listed Building grade II, CA	dilapidated state.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1286544	Contact: Alisha Lad (LPA) 01895 556000

© London Borough of Hillingdon



	SITE NAME:	Former King Henry public house and stables, 456, Bath Road, Longford	Converted to a house, the rear of the building is the former "King Henry" public house. The front part of the property has been rebuilt, using old material, after a fire. All
	DESIGNATION:	Listed Building grade II	the walls have exposed timber framing with brick filling and tiled roofs. The adjacent stables are also of interest with an
	CONDITION:	Poor	early diamond mullioned window. The buildings are in poor condition, but have been secured by the owner. They have
	OCCUPANCY:	Vacant/not in use	been included in large development proposals.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080296	Contact: Alisha Lad (LPA) 01895 556000

© London Borough of Hillingdon





© Historic England Archive



	SITE NAME:	Breakspear House, Breakspear Road North, Harefield	Early to mid-C17 manor house in extensive grounds. The external skin and roof have been repaired to a high	
	DESIGNATION:	Listed Building grade I, CA	standard and internal works are partially complete.	
	CONDITION:	Good		
	OCCUPANCY:	Part occupied/part in use		
mmm	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1080262	Contact: Elizabeth Whitbourn 07889 808145	

	SITE NAME:	Langley Farm Barn, Breakspear Road North, Harefield, Northwood	C16 barn in private ownership at Langley Farm. The three bay barn is timber-framed and weatherboarded with a tiled roof. It has lost parts of the brick plinth to the north east elevation. The front area adjacent to the barn appears to have been subject to fly tipping.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
PA	OWNER TYPE:	Private	
© London Borough of Hillingdon	LIST ENTRY NUMBER:	1080261	Contact: Sarah Harper (LPA) 01895 556000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

а

HERITAGE AT RISK 2015 / LONDO			
LACT HILL	SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield	C17 red brick garden walls in need of extensive repairs. Some works have already been undertaken to a good standard.
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	
	CONDITION:	Fair	
and the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
© Historic England Archive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080272	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Wall in front of numbers 30 to 36 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
	DESIGNATION:	Listed Building grade II, CA	remainder is in poor condition.
Market Const	CONDITION:	Poor	
CHE CAN	OCCUPANCY:	N/A	
1.400000	PRIORITY CATEGORY:	С (В)	
and the second sec	OWNER TYPE:	Private	
D Historic England	LIST ENTRY NUMBER:	1080277	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Wall in front of numbers 40 to 50 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition.
A BERT	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
100000	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	С (В)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1358327	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Walls in front of numbers 52-58 (even) and along west end of property, Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired, but the quality is varied and much of the remainder is in poor condition.
	SITE NAME: DESIGNATION:	(even) and along west end of property, Church Road,	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
		(even) and along west end of property, Church Road, Hillingdon	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
	DESIGNATION:	(even) and along west end of property, Church Road, Hillingdon Listed Building grade II, CA	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
	DESIGNATION: CONDITION:	(even) and along west end of property, Church Road, Hillingdon Listed Building grade II, CA Poor	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
P Historic England	DESIGNATION: CONDITION: OCCUPANCY:	(even) and along west end of property, Church Road, Hillingdon Listed Building grade II, CA Poor N/A	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the
Ø Historic England	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	(even) and along west end of property, Church Road, Hillingdon Listed Building grade II, CA Poor N/A C (B)	create access for houses behind. Some sections have been repaired, but the quality is varied and much of the

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RIS	(2015 / LONDON	
	VZ0137 LONDON	

	SITE NAME:	Walls to east and south of garden of number 28 (Coombe House), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have beer repaired, but the quality is varied and much of the remainder is in poor condition.
	DESIGNATION:	Listed Building grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
D Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193014	Contact: Elizabeth Whitbourn 07889 808145
	SITE NAME:	Lych gate to south of Church of St Mary, Church Walk, Hayes	Circa C16 timber lych gate with tiled roof. The timber supports and base are in a very poor state of repair and
	DESIGNATION:	Listed Building grade II, CA	tiles are slipping from the roof. No repairs are planned.
the second second	CONDITION:	Poor	
	OCCUPANCY:	N/A	
E CONTRACTOR OF A CONTRACTOR			
	PRIORITY CATEGORY:	C (New entry)	
	PRIORITY CATEGORY:	C (New entry) Religious organisation	

© Historic England



OWNER TYPE: © London Borough of Hillingdon

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

1080234

Poor

A (A)

Road, Uxbridge

Vacant/not in use

Listed Building grade II

Commercial company

Cinema, RAF Uxbridge, Grays



	LIST ENTRY NUMBER:	392376	Contact: Sarah Harper (LPA) 01895 556000
1000	SITE NAME:	Front garden wall, The Beeches, High Street, Cowley	C18 red brick wall with sloped coping, located to the no of the Beeches. Repairs to the house have been complet
1	DESIGNATION:	Listed Building grade II and it has been removed from the Heritage at Register. Repairs to the wall are still outstandin	and it has been removed from the Heritage at Risk Register. Repairs to the wall are still outstanding.
	CONDITION:	Poor	
	OCCUPANCY: N/A	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	R TYPE: Private	
	LIST ENTRY NUMBER:	1194165	Contact: Sarah Harper (LPA) 01895 556000

monitored.

© London Borough of Hillingdon

1. P	SITE NAME:	The Cedars, 66, High Street, Uxbridge	C18 town house with later additions. Three storeys, central doorway with Doric pilasters, entablature and open
	DESIGNATION:	Listed Building grade II, CA	pediment. Red brick facade, with bands at first and second floors, dentil and cyma recta cornice with plain tiled roof.
	CONDITION:	Fair	The building has distinctive Dutch gables to the side elevation.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
ondon Borough of Hillingdon	LIST ENTRY NUMBER:	1358372	Contact: Sarah Harper (LPA) 01895 556000

#### PRIORITY CATEGORIES

© Lo

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Sarah Harper (LPA) 01895 556000

Designed in 1918, the building has a large auditorium used

historically as a lecture hall/cinema or concert hall and was converted to a gymnasium in the 1960s. The building is

vacant and in poor condition. The Local Authority is considering options for re-use and its condition is being

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

1	SITE NAME:	The Dower House, 393, High Street, Harlington	Two storey house with C18 brick front to an older timber- framed structure, with large rebuilt C16 chimney. The
A	DESIGNATION:	Listed Building grade II	house is four windows wide, built of brown brick with red brick quoins and window dressings. The building suffered
	CONDITION:	Very bad	severe fire damage in May 2011. It is wind and weather tight with a temporary roof. A structural survey has been
	OCCUPANCY:	Vacant/not in use	carried out and options for re-use are being considered.
	PRIORITY CATEGORY:	A (A)	
Contractory of the local division of the loc	OWNER TYPE:	Private	
don	LIST ENTRY NUMBER:	1080196	Contact: Sarah Harper (LPA) 01895 556000

|--|


© London Borough of Hillingdo

SITE NAME:	Harefield Park (annexe to Harefield Hospital), Hill End Road, Harefield	The site comprises the main building and two flanking stable buildings of early C18 date. The house is vacant and in very poor condition, with no use identified. The building
DESIGNATION:	Listed Building grade II*, CA	is propped and a temporary roof is in place. Survey work to inform repairs is underway.
CONDITION:		
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	OWNER TYPE: Health authority	
LIST ENTRY NUMBER:	1080177	Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Hillingdon





CERTER A	SITE IVALIE.	Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	building is currently being used in the short-term for clinical storage and staff accommodation. A long-term use needs to be identified.	
	LPLE	DESIGNATION:	Listed Building grade II, CA	
		CONDITION:	Poor	
		OCCUPANCY:	Part occupied/part in use	
		PRIORITY CATEGORY:	C (C)	
	© London Borough of Hillingdon	OWNER TYPE:	Health authority	
		LIST ENTRY NUMBER:	1358396	Contact: Sarah Harper (LPA) 01895 556000



Î	SITE NAME:	Nurses Home in grounds of Hillingdon Hospital, Pield Heath Road, Hillingdon	Early C19 house in the grounds of Hillingdon Hospital, currently used as offices, but generally in poor condition.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
of Hillingdon	LIST ENTRY NUMBER:	1080153	Contact: Sarah Harper (LPA) 01895 556000

#### PRIORITY CATEGORIES

© London Borough of

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

	SITE NAME:	Harefield Grove, Rickmansworth Road, Harefield	Probably early C19 country house of three storeys. Stucco with stone cornice and parapet concealing a fairly low
	DESIGNATION:	Listed Building grade II	pitched hipped slate roof. The building has a two storey modern courtyard wing for office use with atrium link. It
	CONDITION:	Fair	has been vacant for a number of years and is deteriorating.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Antonio Cruz, Comer Homes Group	LIST ENTRY NUMBER:	8  48	Contact: Sarah Harper (LPA) 01895 556000
Per l		M	1000 A hu El Marsten in Eduardian Enas Carda Duilana




SITE NAME: Mount Vernon Hospital, 1902-4 by FL Wheeler in Edwardian Free Style. Built as a Rickmansworth Road, hospital for the treatment of tuberculosis patients, and as a branch hospital of the original Mount Vernon hospital in Northwood Hampstead (built 1879-80). The building is noted for its advanced plan, including isolation wards and facilities such DESIGNATION: Listed Building grade II as an X-ray room and dental unit. It is still in use by the CONDITION: Poor hospital, but in a poor state of repair and under pressure OCCUPANCY: Occupied/in use from the redevelopment of the site. PRIORITY CATEGORY: C (C) OWNER TYPE: Health authority © London Borough of Hillingdon 1080083 LIST ENTRY NUMBER: Contact: Sarah Harper (LPA) 01895 556000



© Historic England

	SITE NAME:	Cellars of former Cranford House, Roseville Road, CranfordBrick vaulted cellars to Cranford House circa 1722 (demolished). The cellars are suffering from structu weakening and their condition is deteriorating. The		
	DESIGNATION:	Listed Building grade II, CA	Authority is working with local groups to consider optic for the future of the structure.	
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority, multiple owners		
	LIST ENTRY NUMBER:	1285115	Contact: Sarah Harper (LPA) 01895 556000	



Benlow Works, Silverdale Road, Orchestrelle Factory of 1909-11. Reinforced concrete SITE NAME: frame, with brick exterior. Four storeys with a 19 bay Hayes elevation. The entrance bay has a semi-circular stepped DESIGNATION: Listed Building grade II brick architrave to the doorway and segmental arched metal casements flanked by rusticated pilasters slightly set CONDITION: Very bad forward and breaking the parapet. Recent temporary OCCUPANCY: repairs have been undertaken by the owner, so that the Part occupied/part in use building is weathertight. Discussions have been held with PRIORITY CATEGORY: C (C) the owner, but no solution is agreed for future use as yet. OWNER TYPE: Private LIST ENTRY NUMBER: 1080121 Contact: Alisha Lad (LPA) 01895 556000 © London Borough of Hillingdon

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

## ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- WHS
  - Unitary Authority World Heritage Site



SITE NAME:	Gatehouse at Hillingdon- Uxbridge Cemetery, Uxbridge Road	Mid-C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. The gatehouse is constructed of rubble with stone dressings, tiled roof and five bays with a
DESIGNATION:	Listed Building grade II	wide central entrance under the arch. It is in detriorating condition and vacant, and the wall has partially collapsed. A
CONDITION:	DITION: Poor CC	condition survey has been completed and the extent of repairs required has been agreed.
OCCUPANCY:	Vacant/not in use	repairs required has been agreed.
PRIORITY CATEGORY:	0 (0)	
OWNER TYPE:		
LIST ENTRY NUMBER:	1358415	Contact: Sarah Harper (LPA) 01895 556000

© London Borough of Hillingdon

© London Borough of Hillingdon



SITE NAME:	Hubbard's Farm Barn and outbuildings, West Drayton Road, Colham Green, Uxbridge	Two barns dating from the CI6, both now collapsed. Historic timbers have been salvaged for reuse.
DESIGNATION:	Listed Building grade II	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1284866	Contact: Sarah Harper (LPA) 01895 556000

SITE NAME:	Manor Farm moat, Ickenham		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Moated site, west bank of River Pinn, near Ickenha	m (1/2 mile (800m)	north west of church)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002001
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Black Jacks Lock and Copper Mill Lock, Harefield		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Botwell (Thorn/EMI), Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / HILLINGDON / HOUNSLOW

SITE NAME:	Bulls Bridge, Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Cranford Park, Cranford		
DESIGNATION:	Conservation Area, 13 LBs	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Harmondsworth Village, Heathrow Village	25	
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Alisha Lad (LPA) 01895 556000
GITE NAME:	Morford Way, Eastcote, Ruislip		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	Northwood Town Centre, Green Lane, N	lorthwood	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Alisha Lad (LPA) 01895 556000
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating

## HOUNSLOW



	SITE NAME:	The Keep (Armoury) to Hounslow Cavalry Barracks, Beavers Lane, Hounslow	Built in 1875 consisting of three storeys with four storey staircase towers at each end and in the centre of the south west front. Many windows retain heavy cast iron shutters
E F	DESIGNATION:	Listed Building grade II, CA	with firing loops and massive bolts to the interior. The building has been unused for some years and the interior of
I In	CONDITION:	Poor	the top storey in particular displays evidence of deterioration. This is as a result of rainwater penetration
	OCCUPANCY: Vacant/not in use		from the rooftop parapet and blockages in the flat roof
	PRIORITY CATEGORY:	C (C)	drainage rainwater pipes. There are currently no plans for repairs.
	OWNER TYPE:	Government or agency	
w	LIST ENTRY NUMBER:	1240633	Contact: Meave Faulkner (LPA) 020 8583 4941

© London Borough of Hounslow

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / HOLINSLOW

<u>A-A-A</u>	SITE NAME:	Boston Manor House, Boston Manor Road, Boston Manor Park	Built in 1623 for Lady Mary Reade. Stabilising action to the south and west elevations has been undertaken. Repairs the south west corner are complete and reinstatement of
	DESIGNATION:	Listed Building grade I, CA	finishes awaited. An options appraisal has been undertaken grant-aided by Historic England, and discussions are
	CONDITION:	Poor	ongoing regarding future uses and funding.
fi f	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (E)	
and a second data of the second second second	OWNER TYPE:	Local authority	
listoric England	LIST ENTRY NUMBER:	1079603	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	21, Chiswick High Road W4	Stucco fronted early C19 three storey house which has
	SITE NAME: DESIGNATION:	21, Chiswick High Road W4 Listed Building grade II	
		-	Stucco fronted early C19 three storey house which has
	DESIGNATION:	Listed Building grade II	Stucco fronted early C19 three storey house which has
	designation: condition:	Listed Building grade II Poor	Stucco fronted early C19 three storey house which has
	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building grade II Poor Vacant/not in use	Stucco fronted early C19 three storey house which has
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II Poor Vacant/not in use C (New entry)	Stucco fronted early C19 three storey house which has

	SITE NAME:	Feltham House, Elmwood Avenue, Feltham	Built in the mid-C18 as a compact block in stock brick and modelled on other Palladian villas. Extended in the late C18
	DESIGNATION:	Listed Building grade II, CA	with the addition of side wings. The interior has been modernised but retains C18 decorations of interest, whi
	CONDITION:	Poor	may partly be attributable to James Wyatt who lived at Hanworth. The building has been unused for some time,
ML SAL	OCCUPANCY:	Vacant/not in use	there is extensive rot damage in the principal storey and
	PRIORITY CATEGORY:	C (C)	rainwater penetration. Some urgent repair works were carried out in 2013 to stabilise the building, but further
	OWNER TYPE:	Government or agency	work is required. There are no plans for the future use of the building.
gland	LIST ENTRY NUMBER:	1189466	Contact: Meave Faulkner (LPA) 020 8583 4941

	SITE NAME:	Westlink House, Great West Road	1928 by Wallis, Gilbert and partners in modern style. It is one of number of factories from this period that line the
	DESIGNATION:	Listed Building grade II	Great West Road. The building has been empty for a number of years and the condition is declining. There are
	CONDITION:	Poor	no known plans for re-use of the building at present.
	OCCUPANCY:	Vacant/not in use	
and the second	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
© London Borough of Hounslow	LIST ENTRY NUMBER:	1255218	Contact: Meave Faulkner (LPA) 020 8583 4941

Gunnersbury Park W5



Registered Park and Garden DESIGNATION: grade II\*, 22 LBs, CA Generally satisfactory but with CONDITION: significant localised problems VUI NERABII ITY: Medium TREND: Improving NEW ENTRY ?: No OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1000808

SITE NAME:

A landscape park developed in the C18 by Princess Amelia and in the C19 by Baron Lionel de Rothschild. It became a public park in 1925. The landscape is in variable condition. Funding of  $\pounds$ 4.1 million was received from the Heritage Lottery Fund in 2014 for improvements to the park. Works will include the restoration of parts of the historic landscape, repairs to the Round Pond and the Orangery, and the recreation of the west side of the Horseshoe Lake.

© Historic England

© Historic Engl

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### 

HERITAGE AT RISK 2015 / LONDO	ON / HOUNSLOW		
	SITE NAME:	Archway near east entrance lodge, Gunnersbury Avenue, Gunnersbury Park W3	Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park. Urgent repairs to secure the structural stability of the arch
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	were undertaken in 2012, grant-aided by Historic England. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to the
	CONDITION:	Poor	arch. Works are due to start in 2015.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
© Historic England	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1080332	Contact: Meave Faulkner (LPA) 020 8583 4941
	SITE NAME:	Boundary wall at Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Part of the boundary wall to the garden of the original Gunnersbury House, built 1658-63 by John Webb for Sir John Maynard. The wall runs north-south from the arch to
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	the south east of Princess Amelia's Bath House. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to sections of the
	CONDITION:	Poor	boundary wall. Works are due to start in 2015.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1322060	Contact: Meave Faulkner (LPA) 020 8583 4941
	SITE NAME:	East Lodge to Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Entrance lodge circa 1837. All that remains are small sections of the south and west elevations. Historic Eng awarded a grant towards urgent repairs to secure the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	structural stability of the remaining elements of the lodge, which are now complete. Funding has been secured from the Heritage Lottery Fund for the wider park, which
	CONDITION:	Poor	includes repair works to the East Lodge. Works are due to start in 2015.
	OCCUPANCY:	N/A	start in 2015.
A STATE	PRIORITY CATEGORY:	D (D)	
© Historic England Archive	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1080334	Contact: Meave Faulkner (LPA) 020 8583 4941
	SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Stable block dating from 1835, on the eastern edge of Gunnersbury Park, to the south of the Small Mansion. Works to secure the scaffold have been carried out, partly
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	funded by Historic England. Discussions regarding the future use of the stables are ongoing.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358316	Contact: Verena McCaig 020 7973 3718

## PRIORITY CATEGORIES

### Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / HOUNSLOW

HERITAGE AT RISK 2015 / LONDO	IN / HOUNSLOW		
	SITE NAME:	Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park	Mid-C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly
111	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	funded by Historic England. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to the Gothic Boathouse. Works are
	CONDITION:	Poor	due to start in 2015.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1189588	Contact: Meave Faulkner (LPA) 020 8583 4941
	SITE NAME:	Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Sham Gothic ruins on the east side of Gunnersbury Park. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Gothic ruins. Works are due to start in 2015.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
and the second sec	PRIORITY CATEGORY:	B (B)	
© Historic England	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1080335	Contact: Maeve Faulkner (LPA) 020 8583 4941
the second se	SITE NAME:	The Large Mansion, Gunnersbury Park House, Gunnersbury Avenue, Gunnersbury Park W3	Country house dating from 1801-28 by and for Alexand Copland; remodelled in 1836 by Sydney Smirke for Nat Rothschild. The building has good interiors and houses local history museum and education centre for the
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	boroughs of Hounslow and Ealing. Repairs to the roof were carried out in 2012 and the building is now weathertight. Funding has been secured from the Heritage
	CONDITION:	Poor	Lottery Fund to repair and restore the building for continued use as a local history museum. Works are due to
	OCCUPANCY:	Part occupied/part in use	start in 2015.
© Llisteria England	PRIORITY CATEGORY:	D (D)	
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358312	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	The Small Mansion, Gunnersbury House, Gunnersbury Avenue, Gunnersbury Park W3	Built circa 1810, the smaller of the two houses on the site of Gunnersbury House demolished circa 1801. Discussions are continuing with the Local Planning Authorities in order to secure the repair and re-use of the building. Urgent
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	repairs were carried out in 2012, grant-aided by Historic England.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
© Hictoris Forland	OCCUPANCY: PRIORITY CATEGORY:	Part occupied/part in use C (C)	
© Historic England			

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / HOUNSLOW

	SITE NAME:	West Lodge, Gunnersbury Avenue, Gunnersbury Park	Lodge building dating from 1875 in the manner of a gate house, partly in use for residential purposes. Historic
	DESIGNATION:	Listed Building grade II, RPG grade II*	England awarded a grant towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway, located at the south entrance of the park. Repair works
	CONDITION:	Fair	were completed in 2012.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
Historic England	LIST ENTRY NUMBER:	1389619	Contact: Meave Faulkner (LPA) 020 8583 4941



© Historic England

Citing a lat

©⊦

	SITE NAME:	West stable block in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Early C19 stables situated within Gunnersbury Park. Work to stabilise and repair the shell of the building are now complete, partly funded by Historic England. Discussions regarding the future use of the stables are ongoing.	
IT	DESIGNATION:	Listed Building grade II, RPG grade II*, CA		
CONDITIO	CONDITION:	Fair		
1	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1096950	Contact: Meave Faulkner (LPA) 020 8583 4941	

Round House, the village lock

Listed Building grade II, 2 CAs

up, High Street



SITE NAME:

DESIGNATION:

© London Borough of Hounslow



decay. CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (New entry) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1080306 Contact: Meave Faulkner (LPA) 020 8583 4941 St Lawrence's Church (former), SITE NAME: Former C15 church tower, with nave dating from 1764 by ١/: ام زر

	High Street, Brentford	I homas Hardwick and later Victorian additions. The
DESIGNATION:	Listed Building grade II*, CA	building has been empty since the 1960s and stripped of its fittings. Urgent repairs to the medieval tower were carried
CONDITION:	Poor	out. The building has since been neglected, but is weathertight. Proposals for a wider waterside
OCCUPANCY:	Vacant/not in use	development, including repair and restoration of the
PRIORITY CATEGORY:	D (C)	church and its use as a gym, were approved in December 2014.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1080302	Contact: Verena McCaig 020 7973 3718

© Historic England



1	SITE NAME:	Gate piers within Osterley Park, Jersey Road	Pair of gate piers with contemporaneous railings designed by Robert Adam. The railings are in need of repair.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1391000	Contact: Meave Faulkner (LPA) 020 8583 4941

#### PRIORITY CATEGORIES

© London Borough of Hounslow

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Built circa 1838, this circular brick building would have

been used to imprison criminals caught on Hounslow

Heath. Its condition has been deteriorating for some time

and essential repair work is necessary to prevent further

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



© Historic England

SITE NAME:	Roman Bridge, Jersey Road, Osterley Park	Bridge, dating from 1780, by Robert Adam. Rusticated stone-faced with one segmental arch. Flanking pairs of			
DESIGNATION:	Listed Building grade II*, RPG grade II*	rusticated Doric half columns. The bridge is severed from the historic park by the M4. It straddles the borough boundary between Ealing and Hounslow. The bridge is in			
CONDITION:	Very bad N/A	need of repair and consolidation; suffers from sporadic vandalism.			
OCCUPANCY:					
PRIORITY CATEGORY:	A (A)				
OWNER TYPE:	Private				
LIST ENTRY NUMBER:	189787	Contact: Verena McCaig 020 7973 3718			

	SITE NAME:	Kew Bridge Railway Station, Kew Bridge Road, Brentford	Railway station built in 1850 by Sir William Tite for the London and South Western Railway. The building is largely
	DESIGNATION:	Listed Building grade II, CA	unoccupied and boarded up at low levels. Full repair and re-roofing was undertaken in 2012 and the building is now
	CONDITION:	Good	weathertight. An application for conversion of the ground floor and basement to commercial units with a residential
KIW CLRS	OCCUPANCY:	Part occupied/part in use	unit on the first floor is being considered by the Local
	PRIORITY CATEGORY:	E (E)	Authority.
	OWNER TYPE:	Utility	
© Historic England	LIST ENTRY NUMBER:	1260672	Contact: Meave Faulkner (LPA) 020 8583 4941



© London Borough of Hounslow

1	SITE NAME:	Pair of chapels at Isleworth Cemetery, Park Road	Pair of cemetery chapels with central porte cochere built in 1879. Last used for a service in 1970 and since used as a		
	DESIGNATION:	Listed Building grade II	council store. The chapels are now boarded up and their condition is deteriorating.		
	CONDITION:	Poor	-		
	OCCUPANCY:	Vacant/not in use			
5	PRIORITY CATEGORY:	C (New entry)			
	OWNER TYPE:	Local authority			
	LIST ENTRY NUMBER:	1272433	Contact: Meave Faulkner (LPA) 020 8583 4941		

	SITE NAME:	The Hermitage, 17, Upper Sutton Lane, Heston	Late C15 timber-framed house with later additions. Badly damaged by fire in 2003. The building has suffered further
	DESIGNATION:	Listed Building grade II	deterioration following theft of the temporary protective roof. Discussions regarding future plans for this site are
	CONDITION:	Very bad	ongoing.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
nd	LIST ENTRY NUMBER:	1260544	Contact: Meave Faulkner (LPA) 020 8583 4941

© Historic England



	LIST LINTKI MORIBLIK.	1260344	Contact: Meave Faulkher (LFA) 020 6363 4941
	SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth	Country house built after 1828 with an extension c1860. Urgent works were carried out in 2002, but the building
	DESIGNATION:	Listed Building grade II	has suffered vandalism and further deterioration. Works were subsequently undertaken to stem dry rot outbreaks
	CONDITION:	Very bad	and to secure the building, but further outbreaks have occurred. Historic England and the Local Authority are in
	OCCUPANCY:	Vacant/not in use	discussion with new owners regarding the need for urgent
	PRIORITY CATEGORY:	A (B)	works, as well as future plans to bring the house back into full repair and re-use.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1240343	Contact: Maeve Faulkner (LPA) 020 8583 4941

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / HOUNSLOW / ISLINGTON

	SITE NAME:	Church of St Paul, Bath Road, Hounslow	Built in 1873, designed by WG Habershon. The tower and spire have been inspected and a scan carried out to plot
	DESIGNATION:	Listed Place of Worship grade II, CA	buried iron cramps and ties which are causing rust jacking and fracturing of stone. Some elements have been removed due to concerns over their structural integrity,
	CONDITION:	Poor	including one of the tower gargoyles, the weathervane from the spire and one of the gable crosses, along with
	PRIORITY CATEGORY:	D (C)	broken fragments of stone. The church has been award
	OWNER TYPE:	Religious organisation	a first round pass from the Heritage Lottery Fund and the development phase of a masonry repair project is
	LIST ENTRY NUMBER:	1245132	underway.
Historic England			Contact: Tracey Craig 020 7973 3756

© Hi

SITE NAME:	Romano-British site 1000yds (910m) west of East Bedfont parish church		
OWNER TYPE:	Commercial company	CONTACT:	Elizabeth Whitbourn 07889 808145
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
CONDITION:	Extensive significant problems	TREND:	Unknown
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002043
SITE NAME:	Double ditched enclosure beside A30 road 500yds (460m) west of East Bedfont parish church		

DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002042
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grand Union Canal and Boston Manor, Brentford		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maeve Faulkner (LPA) 020 8583 4941
SITE NAME:	Gunnersbury Park, Brentford W3		
DESIGNATION:	Conservation Area, 21 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown

CONTACT:

#### ISLINGTON

VULNERABILITY:



Low

SITE NAME:	Flying Scotsman public house, 2- 4, Caledonian Road, King's Cross NI va	
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1195703	Contact

house of 1900-01, by Wylson and Long. The ground in use as a public house, but the upper floors are and in poor condition with a leaking roof.

Maeve Faulkner (LPA) 020 8583 4941

© Historic England

Contact: Luciana Grave (LPA) 020 7527 2389

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
- Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

OWNER TYPE:

LIST ENTRY NUMBER:

Local authority

1246687

	SITE NAME:	Gates and railings around New Church Hawe and gates on south side of the square, Charterhouse Square EC1	C19 cast iron carriage gates, the piers of clustered columns surmounted by quatrefoiled panels with a coat of arms and scrolled finials carrying globe lanterns. There has been severe vehicle impact damage to one of the piers. Repairs are expected as part of a wider landscaping programme in the area.
A TAKE AND	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1 195529	Contact: Kristian Kaminski (LPA) 020 7527 2524
	SITE NAME:	Bevin Court, Cruickshank Street WCI	Block of 130 flats designed by Skinner, Bailey and Lubetkir built 1951-4. The entrance hall contains a mural by Peter
	DESIGNATION:	Listed Building grade II*, CA	Yates depicting elements of Finsbury's history and a staircase considered to be Lubetkin's "most idiosyncratic
	CONDITION:	Poor	post-war achievement". Redecoration to the common
	OCCUPANCY:	Occupied/in use	stairwell has been completed but works to rectify damage to the mural caused by water ingress are still outstanding.
	PRIORITY CATEGORY:	D (D)	Funding has now been secured from the Heritage Lottery Fund for the restoration of the entrance lobby and mural.

© Historic England

© Historic England

SITE NAME:	Odeon Cinema, Holloway Road N7	Cinema, built as the Gaumont 1937-8, architect C Howard Crane of Chicago. Poor general condition, with cracking
DESIGNATION:	Listed Building grade II, CA	and damage to faience. Inappropriate modern shop fronts in poor condition undermine the design aesthetic.
CONDITION:	'oor	
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	384986	Contact: Kristian Kaminski (LPA) 020 7527 2524
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	N7DESIGNATION:Listed Building grade II, CACONDITION:PoorOCCUPANCY:Occupied/in usePRIORITY CATEGORY:C (C)OWNER TYPE:Commercial company

Works will begin towards the end of 2015.

Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Studio (former Chapel), Lloyd Baker Street, Thornhill WCI	Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. Stock
	DESIGNATION:	Listed Building grade II, CA	brick with tracery windows in stone, slate roof, late Decorated Gothic style. Permission has been granted to convert the building to residential use.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
orough of Islington	LIST ENTRY NUMBER:	1195670	Contact: Andy Rayner (LPA) 020 7527 4087

© London Bor

Y	

¢,	SITE NAME:	Islington War Memorial Arch, Manor Gardens N7	Listed war memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the
1	DESIGNATION:	Listed Building grade II	archway around which the new building has been constructed. Repairs have been carried out including works
No.	CONDITION:	Fair	to the lettering and stonework. Problems remain with rising damp. A solution has been proposed and funding
Y	OCCUPANCY:	N/A	needs to be secured.
1	PRIORITY CATEGORY:	D (D)	
-	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1392555	Contact: Tanya Szendeffy (LPA) 020 7527 7733

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site


N I THAT I

© Lo

© Histor

Endon Borough of Islington	SITE NAME:	Railings and gates to Islington Tennis Centre and King George's Field, Market Road N7	Railings and gates of 1854 probably designed by J B Bunning. Cast iron with elaborate piers and finials. The fabric of some finials has failed, and several have been removed and placed into store for safety reasons. A condition survey is being carried out which will inform thei future conservation.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1195681	Contact: Kristian Kaminski (LPA) 020 7527 2524

oric England	SITE NAME:	Railings, walls, gate piers and gates to Caledonian Park, Market Road N7	Railings, walls and gates to Caledonian Market built in 1854 (market demolished). Some repairs have been carried out, part funded by Historic England, but extensive further works are required. Redevelopment of housing on an adjacent site is underway. A condition report has been prepared for the railings and Historic England will be working with the Local Authority to identify sources of funding for a phased programme of works.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1208009	Contact: Kristian Kaminski (LPA) 020 7527 2524



	SITE NAME:	Finsbury Health Centre, Pine Street ECI	Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. A conservation plan and
	DESIGNATION:	Listed Building grade I, CA	management guidelines have been produced, grant-aided by Historic England. Some urgent work has been carried
	CONDITION:	Poor	out. Its health use is to remain, but repairs are still required. A Feasibility Study has been commissioned.
	OCCUPANCY:	Occupied/in use	Works are being carried out to remove asbestos, and
	PRIORITY CATEGORY:	C (C)	discussions about further works are taking place, but no overall solution has been agreed.
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1297993	Contact: Verena McCaig 020 7973 3718

© Historic England



SITE NAME:	Finsbury Town Hall, Rosebery Avenue ECI	Town hall, built in 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style. Magnificent public
DESIGNATION:	Listed Building grade II*, CA	hall on the first floor with elaborate plasterwork in Belle Epoque manner. Now in use as dance studios with the
CONDITION:	Poor	main halls available for public use. The external fabric of the building has not yet been fully repaired. Historic England is
OCCUPANCY:	Occupied/in use	in discussion with the owners and advising them on
PRIORITY CATEGORY: C (F)		appropriate action.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1293112	Contact: Verena McCaig 020 7973 3718

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	40, Rosebery Avenue ECI	Three storey terraced house with basement and attic, circa
	DESIGNATION:	Listed Building grade II, CA	1820-30. Formerly used as offices. Damage from faulty rainwater goods has led to rot and damaged plaster in
	CONDITION:	Poor	places. Historic England is in discussion with the owner with a view to appropriate repair and securing its long-term
	OCCUPANCY:	Vacant/not in use	use.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1208473	Contact: Kristian Kaminski (LPA) 020 7527 2524

© Historic England

© Historic England

	Ch	1	1
			1
	MAN		
an france of			

SITE NAME:	The vaults to the House of Detention (part of former), Sans Walk ECI	Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. Works for conversion to office space for part of the structure have been
DESIGNATION:	Listed Building grade II, CA	approved but not yet implemented. There is a problem with water ingress from the car park above and
CONDITION:	Fair	management issues due to multiple ownership.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Private, multiple owners	
LIST ENTRY NUMBER:	1297973	Contact: Luciana Grave (LPA) 020 7527 2389



© Historic England Archive

Former church, built 1826-28 to the design of Sir Charles SITE NAME: St Paul's Church, St Paul's Road NI Barry in early Gothic Revival style. It is occupied by the Steiner Foundation and in use as a school. Repairs to the DESIGNATION: Listed Building grade II\*, CA former vestry roof were completed in summer 2012, grant-aided by Historic England. Outstanding repairs are CONDITION: Poor required to the building. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: F (F) OWNER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1208912 Contact: Verena McCaig 020 7973 3718

	A CONTRACT OF
Contract States and	Last a state of the
A STATISTICS AND A STATISTICS	Less Alter
	ALL STATES
	ALC: NO ADDRESS OF
A REAL PRIME REAL PRIME	
December 2 F. T. N. INC	428 18 18 - 1 A
A DE LA CARLE CARDON OF	
A BEALS	
212 11 2 2 2 7	
the second data and the	
Carl and the second second	
ALL THE REAL PROPERTY.	States and the second second
	and the second sec

4	SITE NAME:	Railings, Thornhill Square NI	Some repairs to the railings were completed in 2010, part
E.	DESIGNATION:	Listed Building grade II, CA	funded by Historic England. The Local Authority is proposing to apply to the Heritage Lottery Fund for a grant towards further repairs and landscaping. Discussions are
	CONDITION:	Poor	towards further repairs and landscaping. Discussions are ongoing regarding how best to repair or replace damaged
	OCCUPANCY:	N/A	railings.
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Local authority	
100	LIST ENTRY NUMBER:	1297982	Contact: Andy Rayner (LPA) 020 7527 4087

© Historic England



	SITE NAME:	Railings, Wilmington Square WCI	Cast iron railings of 1819-1841, in very poor condition. Urgent works have previously been carried out, but
	DESIGNATION:	Listed Building grade II, CA	currently no funding has been identified for a full repair programme.
100	CONDITION:	Very bad	
S.	OCCUPANCY:	N/A	
ALC: BU	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1195789	Contact: Andy Rayner (LPA) 020 7527 4087

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

Â	attached railings, Clerkenwell 1788 and 1792 for a Methodist congre Close, Islington ECI reordered in 1882 by Reginald Blomfie	The church was built by architect James Carr between 1788 and 1792 for a Methodist congregation; this was reordered in 1882 by Reginald Blomfield for an Anglican	
1	DESIGNATION:	Listed Place of Worship grade II*, CA	congregation when the altar was placed in the east and the galleries cut back. The steeple was rebuilt in 1849, and in 1900 the vaulted crypt was deepened and supported on an
	CONDITION:	Poor	iron structure. There are cracks on the west front, the windows are in need of repair and local repairs are needed
	PRIORITY CATEGORY:	C (C)	to the steeple. The church has recently been awarded a
	OWNER TYPE:	Religious organisation	grant from the Listed Places of Worship Roof Repair Fund.
© Historic England	LIST ENTRY NUMBER:	1207786	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Celestial Church of Christ, Cloudesley Square NI	Built 1826-9 to the design of Sir Charles Barry. Urgent repairs to the roof and high level stonework were carried
	DESIGNATION:	Listed Place of Worship grade II*, CA	out with Heritage Lottery Fund/Historic England funding in 2006-7. However the west turrets are still in bad condition and the finials remain clad in netting. The nave ceiling is still
	CONDITION:	Very bad	netted internally to catch plaster.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
Allistaria England	LIST ENTRY NUMBER:	1195557	Contact: Ian Harper 020 7973 3786

© Historic England



SITE NAME: Congregational chapel and related buildings of 1876-7 by Union Chapel, Compton Terrace Nİ James Cubitt with the upper part of the tower completed in 1889. Repairs to the tower and high level roofs are Listed Place of Worship grade I, complete, grant-aided by the Heritage Lottery Fund and DESIGNATION: CA Historic England. There are still concerns about the lower level masonry of the tower and the structure of the CONDITION: Fair octagon. In March 2015 the chapel was awarded a grant PRIORITY CATEGORY: C (C) from the Listed Places of Worship Roof Repair Fund. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1208365 Contact: lan Harper 020 7973 3786

MINIMIMIMIMI	SITE NAME:	Former Mecca Bingo, 161-169, Essex Road N1	Built as the Carlton Cinema in 1930 by George Coles, previously a bingo hall and now in use as a place of worship
	DESIGNATION:	Listed Place of Worship grade II*	by Resurrection Manifestations. Black, white and coloured faience to the Essex Road front, the rest of yellow brick
	CONDITION:	Poor	with slate roof. The façade to Essex Road is in Egyptian style. The church has temporary consent for their use of
	PRIORITY CATEGORY:	C (C)	the building, including the temporary division of the main
The second s	OWNER TYPE:	Religious organisation	auditorium. Some repairs and restoration have been carried out, but there is evidence of damage to the faience
_	LIST ENTRY NUMBER:	1292870	tiles. Proposals for re-use are currently being explored.
O Lintonia Fardan d			Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic England



SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19	The Passionists (Roman Catholic Religious Order) acquired the site in 1858 and built a monastery and chapel. The
DESIGNATION:	Listed Place of Worship grade II*, CA	monastery remains and is wrapped around the existing church to its eastern end. The existing church was built in 1887-9 by Albert Vicars in a Neo-Romanesque style. The
CONDITION:	Poor	roofs, parapet gutters and rainwater goods are in poor condition and an extensive programme of repairs is
PRIORITY CATEGORY:	A (A)	needed. Leaks have damaged the important wall paintings.
OWNER TYPE:	Religious organisation	The church was recently awarded a grant towards repairs from the Listed Places of Worship Roof Repair Fund.
LIST ENTRY NUMBER:	1279729	Contact: Ian Harper 020 7973 3786

© Jim Linwood

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE A	T RISK 2015 /	ISLINGTON

HERITAGE AT RISK 2015 / LONDO	on / Islington				
	SITE NAME:	NAME: Hope Church (former Church of St Mary Magdalene) and attached railings, Holloway Road, Islington N7		Church of England church re-named Hope Church in 2013 built 1812-14 by architect William Wickings as the Chapel of Ease to St Mary's Islington. London yellow stock bricks with Portland stone dressings. The east end tower has	
6-0-1	DESIGNATION:	Listed Place of Worship grade II*, CA	settled structurally against the aisles, and the north and south porches have settled and pulled away from the ai The west end and west porch have also settled. The cry		
	CONDITION:	Poor	is at risk of floo	ding; underground water levels, currently ermanent pumping, require investigation to	
	PRIORITY CATEGORY:	C (C)	achieve a sustai	nable solution to the settlement.	
© Historic England	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1195637	Contact: lan Ha	arper 020 7973 3786	
and the second second	SITE NAME:	Church of St Silas, Penton Street, Islington NI	EP Loftus Brocl	esigned by SS Teulon, completed in 1863 by and chancel added in 1884 by W White. e re-slated in 2010, the south slope with	
	DESIGNATION:	Listed Place of Worship grade II, CA	photovoltaic til Priority stone r	es to match the slates in size and colour. epairs have been carried out but more	
	CONDITION:	Poor		uired. The church has been awarded a first n the Heritage Lottery Fund for structural	
Main 1. J. N.	PRIORITY CATEGORY:	D (D)	repairs to the v	vest end, where there is significant cracking.	
	OWNER TYPE:	Religious organisation	The developme	ent phase of the project is underway.	
	LIST ENTRY NUMBER:	1208241	Contact: Trace	y Craig 020 7973 3756	
© Historic England					
	SITE NAME:	Church of St Mary, Upper Street, Islington NI	This is the fourth church on this site, having been rebuil 1955-56 by Seely and White to replace the 1751 church		
	DESIGNATION:	Listed Place of Worship grade II, CA	destroyed in the Blitz, which had replaced a C14 me church built on the site of a Norman church. Constr as with the C18 church, is in brick with stone quoins		
	CONDITION:	Poor		neoclassical tower survived, along with the y R Blomfield. The portico has settled and	
	PRIORITY CATEGORY:	C (C)	the masonry and roof are in need of repair. Possible sources of funding are currently being explored.		
THE REAL PROPERTY	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1195776	Contact: Ian Ha	arper 020 7973 3786	
© Historic England					
SITE NAME:	Bunhill Fields, Fin	sbury Square EC2			
DESIGNATION:	Conservation Are	a, 95 LBs, RPG grade I	NEW ENTRY?:	No	
CONDITION:	Fair	u u	TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	Luciana Grave (LPA) 020 7527 3000	
SITE NAME:	Chapel Market N				
DESIGNATION:	Conservation Are	ea, 5 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad		TREND:		
VULNERABILITY:	Medium		CONTACT:	Luciana Grave (LPA) 020 7527 3000	
SITE NAME:	Chiswell Street E	СІ			
DESIGNATION:	Conservation Are	ea, 3 LBs	NEW ENTRY?:	No	
CONDITION:	Fair		TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	Luciana Grave (LPA) 020 7527 3000	
SITE NAME:	Clerkenwell ECI				
DESIGNATION:	Conservation Are	ea, 92 LBs, SM	NEW ENTRY?:	No	
CONDITION:	Poor		TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	Luciana Grave (LPA) 020 7527 3000	

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hat and Feathers ECI		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	Mercers Road/Tavistock Terrace N7		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	Moorfields EC1		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	St John's Grove N19		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	St Mary Magdalene N5		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	Stroud Green N4		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 3000
SITE NAME:	Tollington Park N4		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300

## KENSINGTON AND CHELSEA



SITE NAME:	31, Brompton Square, South Kensington SW3	House dating from 1824-39, part of Brompton Square. A series of Planning Permissions and Listed Building Consents
DESIGNATION:	Listed Building grade II, CA	have been granted for internal alterations and rear extensions. Works to implement the consents came to a
CONDITION:	Poor	halt in December 2008. An Urgent Works Notice to make the building weathertight was served and complied with in
OCCUPANCY:	Vacant/not in use	December 2009.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1080723	Contact: Mark Butler (LPA) 020 7361 2465

© Royal Borough of Kensington and Chelsea

U v

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Arcade forming circle and avenue, Brompton Cemetery, Old Brompton Road SW10	Arcade, 1839-40, situated in the centre of the southern half of Brompton Cemetery, designed by Benjamin Baud. It is a united composition comprising four quadrants which form	
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	the circle and the avenue. A Heritage Lottery Fund grant was awarded in January 2014 for works to the wider cemetery. Discussions are ongoing regarding the detail of	
	CONDITION:	Poor	repair works to the arcade.	
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	D (C)		
	OWNER TYPE:	Government or agency		
	LIST ENTRY NUMBER:	1225713	Contact: Rebecca Barrett 020 7973 3716	




Xt	SITE NAME:	Campden Hill, I, Campden Hill W8	Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country
	DESIGNATION:	Listed Building grade II, CA	house in an urban setting. Permission was granted for internal alterations and extensions in July 2008. Works
a a	CONDITION:	Fair	have stalled on site and the building is now showing the initial signs of neglect with a lack of general maintenance.
	OCCUPANCY:	Vacant/not in use	
T THE	PRIORITY CATEGORY:	D (D)	
-	OWNER TYPE:	Private	
n and	LIST ENTRY NUMBER:	39  38	Contact: Mark Butler (LPA) 020 7361 2465

© Royal Borough of Kensington a Chelsea



© Historic England





	LIST ENTRY NUMBER: 1000817		Contact: Zosia Mellor 020 7973 3473	
No.	SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10	High brick boundary wall to Harrow Road, a 100 metre section of which collapsed in 2006. Further bays were	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	subsequently reduced in height due to safety concerns. Historic England has awarded a grant towards the first phase of rebuilding the collapsed section which involves	
	CONDITION:	Very bad	piling, casting a ground beam and rebuilding the wall as original. Repair works are underway, with two bays near	
	OCCUPANCY:	N/A	completion. Historic England is in discussion with the	
~	PRIORITY CATEGORY:	F (C)	owners regarding proposals for future repair.	
1	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1191000	Contact: Mark Butler (LPA) 020 7361 2465	

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB I PA
- NP
- Conservation Area Listed Building Local Planning Authority National Park RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
  - Unitary Authority World Heritage Site

	SITE NAME:	Blumberg Mausoleum, Harrow Road, Kensal Green Cemetery W10	Large mausoleum from the mid-C19 in Carrara marble, grey granite and bronze. In very bad condition with extensive vegetation growth, collapsed in parts and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	showing widespread delamination. A comprehensive condition survey was produced in 2013, funded by Histor England. This monument has been prioritised for
	CONDITION:	Very bad	conservation and funding is now being sought to carry this out.
	OCCUPANCY:	N/A	out.
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1245932	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Mausoleum of Andrew Ducrow, Harrow Road, Kensal Green Cemetery W10	Mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson, with later embellishments following Ducrow's own interment. The
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	mausoleum is in poor condition given the loss of sculptural elements and ironwork, overgrown vegetation and general erosion. A comprehensive condition survey was produced
	CONDITION:	Poor	in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being
A Long	OCCUPANCY:	N/A	sought to carry this out.
Alter Lan	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1358179	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Mausoleum of Isabella Gregory, Harrow Road, Kensal Green Cemetery NW10	Mausoleum circa 1830. Overgrown vegetation obscures the condition of much of the mausoleum but spalled stone due to corroding iron cramps is evident. A comprehensive
And the second second	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly, although some some vegetation clearance has already been
A State of the second	CONDITION:	Very bad	undertaken.
AN AN AREA	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1227650	Contact: Mark Butler (LPA) 020 7361 2465



	LIST ENTRY NUMBER:	1227650	Contact: Mark Butler (LPA) 020 7361 2465
L'ann	SITE NAME:	Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10	Large mausoleum dated 1838 designed by Robert Shout. Several of the stone roof panels are missing, part of a pediment has collapsed and there are cracks in the stone,
	Listed Building grade II, RPG		probably due to corroding iron cramps. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
aring a	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246098	Contact: Mark Butler (LPA) 020 7361 2465

## © Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2015 / LONDO		ND CHELSEA	
	SITE NAME:	Mausoleum of Joseph Hudson, Harrow Road, Kensal Green Cemetery W10	Opulent classical mausoleum of Portland stone dating from circa 1850. Invasive vegetation and saplings are damaging the roof and the joints in the stonework are separating,
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	allowing further water ingress. A condition survey and specification are required.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
N AND A STREET	PRIORITY CATEGORY:	A (New entry)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389190	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Mausoleum of Martha Ross, Harrow Road, Kensal Green Cemetery W10	Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	there is considerable damage to windows. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
	CONDITION:	Very bad	accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246097	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Monument to Joseph Allmond Cropper, Harrow Road, Kensal Green Cemetery W10	Circa 1870, tall composite monument in Portland store and pink Peterhead granite shafts. The monument is lea significantly and there is damage to the figure, canopy a
ANAL	DESIGNATION:	Listed Building grade II, RPG grade I, CA	ironwork. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (A)	
D Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389193	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Monument to Julia Slater, Harrow Road, Kensal Green Cemetery W10	Triangular monument with relief of an allegorical female figure on each side on a circular plinth, circa 1840. The monument is leaning significantly, is very unstable and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	severely damaged due largely to rusting iron cramps. There is also encroaching mature vegetation. A comprehensive condition survey was produced in 2013, funded by Historic
Service of Second	CONDITION:	Very bad	England. This monument has been prioritised for conservation and funding is now being sought to carry this
and the second sec	OCCUPANCY:	N/A	out.
A state of the sta		A (A)	
and the second se	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	A (A) Unknown	

Contact: Mark Butler (LPA) 020 7361 2465

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1389201

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### 

HERITAGE AT RISK 2015 / LONDO	on / Kensington An	ID CHELSEA	
E all of	SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10	1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco central chapel of a Greek Doric tetra style, with (now roofless) pavilions
ALL THE ALL	DESIGNATION:	Listed Building grade I, RPG grade I, CA	containing marble memorial sculpture. Large catacombs below. The building is no longer in use and is suffering from water ingress. A detailed condition survey has been
	CONDITION:	Poor	undertaken, funded by Historic England and an options appraisal is being carried out to consider its future re-use in
	OCCUPANCY:	Vacant/not in use	conjunction with key stakeholders, inluding local people.
	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1190995	Contact: Verena McCaig 020 7973 3718
1 Tallanian B	SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10	Built by John Griffith in 1833 to display tablets and monuments, with brick vaulted catacombs underneath. Currently in poor condition. The restoration of a sample
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	bay has been completed, part funded by Historic England. Discussions regarding the repair of the remainder of the colonnade are ongoing.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
1 port	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080629	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Admiral Henry Collins Deacon, Harrow Road, Kensal Green Cemetery W10	Mid-C19 sculptural monument in Portland stone with cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	monument on its base and a significant lean. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised
Contraction of the second	CONDITION:	Poor	accordingly.
	OCCUPANCY:	N/A	
ALL PROPERTY.	PRIORITY CATEGORY:	C (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	389226	Contact: Mark Butler (LPA) 020 7361 2465
No. tak	SITE NAME:	Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery W10	Marble memorial with sculpture of an anchor and cross on a tall pedestal, dating from the mid-C19. There is a significant lean to the south and risk from invasive plants. A
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Very bad	
1 1 3 m	OCCUPANCY:	N/A	
States and The Second	PRIORITY CATEGORY:	C (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389215	Contact: Mark Butler (LPA) 020 7361 2465

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Harrow Road, Kensal Green rectangular pedestal up Cemetery W10 mourning women in a t	Two stage monument dating from 1850 consisting of a rectangular pedestal upon a tomb chest with a relief of mourning women in a tropical landscape. A deep undercut
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
a server the	CONDITION:	Poor	funded by Historic England. Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
Charles and	PRIORITY CATEGORY:	C (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389188	Contact: Mark Butler (LPA) 020 7361 2465



© Historic England

© Historic

	SITE NAME:	Tomb of Alfred Cooke, Harrow Road, Kensal Green Cemetery W10	A limestone tomb by Thomas Milnes from the mid-C19 with a statue of a horse and infant on a pedestal. The sculpture is very badly damaged and railings are missing. A
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389167	Contact: Mark Butler (LPA) 020 7361 2465

	SITE NAME:	Tomb of Colonel Gideon Gorrequer, Harrow Road, Kensal Green Cemetery NW10	Elaborate military monument dating from 1841 to Colonel Gorrequer, ADC (aide-de-camp) to the Governor of St Helena during Napoleon's banishment. There is evidence
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	of erosion at foundation level and architectural elements are threatened by ivy growth. A comprehensive condition survey was produced in 2013, funded by Historic England.
	CONDITION:	Poor	Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
ic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389244	Contact: Mark Butler (LPA) 020 7361 2465



© Historic England

	LIST ENTRY NUMBER:	1389244	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10	Monument designed by William Burges in 1867. Elaborate Portland stone canopied tomb with sarcophagus decorated with naval imagery. In very poor condition with damage
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	inflicted by anti-social behaviour, invasive vegetation and general weathering. A comprehensive condition survey was produced in 2013, funded by Historic England. This
	CONDITION:	Very bad	monument has been prioritised for conservation and funding is now being sought to carry this out.
	OCCUPANCY:	N/A	funding is now being sought to early this out.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080630	Contact: Verena McCaig 020 7973 3718

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 / LONDO	on / Kensington An	ID CHELSEA		
1	SITE NAME:	Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10	Indian grave marker of red sandstone from the mid-C19. The tomb has a significant lean due to severe erosion of the base. A comprehensive condition survey was produced	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	in 2013, funded by Historic England. Works are being prioritised accordingly.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (A)		
D Historic England	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1246079	Contact: Mark Butler (LPA) 020 7361 2465	
An	SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10	Portland stone mausoleum dating from the mid-C19. There is erosion at foundation level, and spalling stone to rusting cramps. The interior is in poor condition an	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	there is evidence of anti-social activity. A comprehensive condition survey was produced in 2013, funded by Historic England and works are being prioritised accordingly. The	
	CONDITION:	Poor	entrance has been secured temporarily to minimise any risk from anti-social behaviour.	
	OCCUPANCY:	N/A	from and-social behaviour.	
and the second sec	PRIORITY CATEGORY:	C (C)		
D Historic England	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1389242	Contact: Mark Butler (LPA) 020 7361 2465	
	SITE NAME:	Tomb of Frederick Tillson, Harrow Road, Kensal Green Cemetery W10	Gothic Revival monument dating from circa 1870, consisting of a canopied tomb of Portland stone, marble and sandstone over a raised, moulded base. The	
	DESIGNATION:	Listed Building grade II, RPG grade I. CA	monument is in very poor condition with subsidence on the north elevation, deterioration of stonework, widening of joints, correction of iron, and loss of finish.	



CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

grade I, CA

Very bad

Unknown

N/A

A (A)

© Historic England

©

©



LIST ENTRY NUMBER:	1389192	Contact: Mark Butler (LPA) 020 7361 2465
SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10	Portland stone sarcophagus with effigy of a sleeping child in Carrara marble from around 1840. There is a slight lean to the north east, erosion of foundations and invasive
DESIGNATION:	Listed Building grade II, RPG grade I, CA	vegetation growth. The effigy of the child has been removed for safekeeping. A comprehensive condition survey was produced in 2013, funded by Historic England.
CONDITION:	Poor	Works are being prioritised accordingly.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	389 82	Contact: Mark Butler (LPA) 020 7361 2465

© Historic England

## PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

## NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

of joints, corrosion of iron, and loss of finials. A comprehensive condition survey was produced in 2013,

sought to carry this out.

funded by Historic England. This monument has been prioritised for conservation and funding is now being

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park
  - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site



SITE NAME:	Tomb of General James Perry and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10	Large chapel-like mausoleum from the end o very bad condition with widespread erosion, growth and extensive damage to the roof an corner. A comprehensive condition survey w
DESIGNATION:	Listed Building grade II, RPG grade I, CA	in 2013, funded by Historic England. This mo been prioritised for conservation and funding sought to carry this out.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1246096	Contact: Mark Butler (LPA) 020 7361 2465

e chapel-like mausoleum from the end of the C19. In bad condition with widespread erosion, harmful plant th and extensive damage to the roof and north west er. A comprehensive condition survey was produced 13, funded by Historic England. This monument has prioritised for conservation and funding is now being ht to carry this out.

Slate chest tomb from the mid-C18. Structural settlement

© Historic England



	SITE NAME:	Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10	A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large headstone with Masonic symbols over a raised ledger framed by Minton
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	tiles and looked over by an angel sculpture. The tomb is in a deteriorating condition due to the failure of metal supports behind the sculpture, the loss of tiles and general
	CONDITION:	Poor	erosion. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has
	OCCUPANCY:	N/A	been prioritised for conservation and funding is now being
	PRIORITY CATEGORY:	C (A)	sought to carry this out.
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246092	Contact: Mark Butler (LPA) 020 7361 2465



© Historic England



SITE NAME:

Road, Kensal Green Cemetery has led to compression/shearing of some slate elements. W10 This structural movement needs to be arrested. The tomb has also suffered from the loss of decorative features. A Listed Building grade II, RPG DESIGNATION: comprehensive condition survey was produced in 2013, grade I, CA funded by Historic England. Works are being prioritised accordingly. CONDITION: Very bad N/A OCCUPANCY: PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1271534 Contact: Mark Butler (LPA) 020 7361 2465

Tomb of James Poole, Harrow



SITE NAME:	Tomb of James Ward, Harrow Road, Kensal Green Cemetery W10	Tall upright with a relief of the Muse of Painting dating from circa 1859. The stone now lies flat and broken in two pieces, and its plinth feared lost. A comprehensive
DESIGNATION:	Listed Building grade II, RPG England.	condition survey was produced in 2013, funded by Historic England. This monument has been prioritised for conservation and funding is now being sought to carry this out.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:		
OWNER TYPE:		
LIST ENTRY NUMBER:	1389200	Contact: Mark Butler (LPA) 020 7361 2465

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Tomb of John Thompson, Harrow Road, Kensal Green Cemetery W10	Tomb of John Thompson, died 1843, of Portland stone and Carrara marble. One of the earliest monuments in the cemetery. The surface of the stone is deteriorating and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	part of the wall structure is starting to bulge. The roof is in very poor condition with vegetative growth. A condition survey and specification are required. This monument has
	CONDITION:	Poor	been prioritised for conservation and funding is now bei sought to carry this out.
をたい王山町	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246094	Contact: Mark Butler (LPA) 020 7361 2465




© Hi

	SITE NAME:	Tomb of John Gibson, Harrow Road, Kensal Green Cemetery W10	Gothic style tomb of architect John Gibson d.1859, designed by the architect himself. There is severe erosion of the upper registers and widening of joints. Tree works
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	are also required to minimise the risk of damage from overhanging branches. A comprehensive condition surve was produced in 2013, funded by Historic England. Worl
Bar Barris	CONDITION:	Poor	are being prioritised accordingly, and tree works will be undertaken imminently.
	OCCUPANCY:	N/A	under taken in innihenty.
Maria I	PRIORITY CATEGORY:	C (C)	
1	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080632	Contact: Mark Butler (LPA) 020 7361 2465



Ô	Historic	: England

© Historic England





SITE NAME:

LIST ENTRY NUMBER:

Cemetery WI0 Listed Building grade II\*, RPG survey was produced in 2013, funded by Historic England. DESIGNATION: grade I, CA This monument has been prioritised for conservation and funding is now being sought to carry this out. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown

1293515

Tomb of Major General Sir William Casement, Knight

Harrow Road, Kensal Green

Commander of the Bath,

Portland stone base supporting a coffin chest draped with Casement's cloak and topped with his bicorn and sword, all under a stone canopy supported at each corner by an Indian bearer. There has been some disruption of stone due to ivy and the corrosion of cramps has led to part of the cornice being removed. A comprehensive condition

© Historic England

D

Е

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Verena McCaig 020 7973 3718

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

		1275170	
	LIST ENTRY NUMBER:	1293490	Contact: Verena McCaig 020 7973 3718
Historic England	OWNER TYPE:	Private	
	PRIORITY CATEGORY:	C (A)	sought to carry this out.
	OCCUPANCY:	N/A	prioritised for conservation and funding is now being
	CONDITION:	Poor	comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	support a now missing central wreath. The tomb is in pc condition due to the loss of sculptural elements, sinking the west side, widespread erosion and dirt accretions. A
	SITE NAME:	Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10	Monumental tomb from 1856 comprising a carved coffin under an open aedicule with twelve Corinthian columns surmounted by four angels each with an arm held aloft to




©⊦

	SITE NAME:	Tomb of Samuel Griffith, Harrow Road, Kensal Green Cemetery W10	Portland stone altar tomb on a stepped granite base, from circa 1830. The tomb is in poor condition due to erosion and loss of detailing, corrosion of ironwork and heavy	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	overgrowth which is exacerbating the disruption of stone. Railings are missing and bollards have fallen. A comprehensive condition survey was produced in 2013,	
HL	CONDITION:	Poor	funded by Historic England. Works are being prioritised accordingly, although significant vegetation clearance has	
	OCCUPANCY:	N/A	already been undertaken.	
Contra la	PRIORITY CATEGORY:	C (A)		
	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1389237	Contact: Mark Butler (LPA) 020 7361 2465	



© Historic England

© Historic England





	LIST ERVITATION DEIX.	1307223	Contact. Hark Butler (ELA) 020 7301 2403
	SITE NAME:	Tomb of the Earl of Galloway, Harrow Road, Kensal Green Cemetery W10	Large neoclassical chest tomb by JB Papworth dating from 1838. There is damage to the kerb stone, widening of joints, invasive plant growth causing extensive disruption
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	and some collapse on the east face. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised accordingly.
	CONDITION:	Very bad	
1	OCCUPANCY:	N/A	
d'as âl	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	389 78	Contact: Mark Butler (LPA) 020 7361 2465

## © Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Tomb of Thomas Fenwick, Harrow Road, Kensal Green Cemetery NW10	Mausoleum from 1834, one of the earliest monuments in the cemetery. Several elements have collapsed and vegetation is infiltrating through the masonry. The door is	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	rusted and the bollards and chains have been lost. A comprehensive condition survey was produced in 2013, funded by Historic England. This monument has been	
	CONDITION:	Very bad	prioritised for conservation and funding is now being sought to carry this out.	
	OCCUPANCY:	N/A	sought to carry this out.	
A CONTRACTOR OF A	PRIORITY CATEGORY:	A (A)		
© Historic England	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1227649	Contact: Mark Butler (LPA) 020 7361 2465	
1 Alex	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery NW10	Carrara marble pedestal surmounted by a draped urn with a relief of a dog at its base, dating from 1874. The tomb is in poor condition due to erosion of its carving,	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	deterioration of the inscription, the heavy lean of the monument towards the west and encroaching vegetation has almost obscured the monument entirely. A	
	CONDITION:	Poor	comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised	
A state of the sta	OCCUPANCY:	N/A	accordingly.	
	PRIORITY CATEGORY:	C (A)		
© Historic England	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1389246	Contact: Mark Butler (LPA) 020 7361 2465	
	SITE NAME:	Tomb of William Price Lewis, Harrow Road, Kensal Green Cemetery W10	Portland stone obelisk with armorial and Anthemion reliefs from the mid-C19. The corrosion of iron cramps is causing spalling of the stone. The ground is eroded around the	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by Historic England. Works are being prioritised	
	CONDITION:	Poor	accordingly.	
	OCCUPANCY:	N/A		
A COMPANY	PRIORITY CATEGORY:	C (C)		
© Historic England	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1246083	Contact: Mark Butler (LPA) 020 7361 2465	
N A	SITE NAME:	Commonwealth Institute, Kensington High Street W14	The Commonwealth Institute designed by Robert Matthew, Johnson-Marshall and Partners is one of the important public buildings in Britain of the late 1950s. I	
and the second	DESIGNATION:	Listed Building grade II*, CA	been vacant since 1995. Works are underway to repair and	
	CONDITION:	Fair	convert the building to accommodate the Design Museum, due to open in late 2016.	
T DEVENT PROPERTY	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Commercial company		
© Historic England	LIST ENTRY NUMBER:	22744	Contact: Rebecca Barrett 020 7973 3716	
	SITE NAME:	Enclosing walls to Moravian Burial Ground, King's Road SW10	Brick walls enclosing the Moravian Burial Ground, mostly Tudor in origin with later additions. Historic repairs have resulted in a patchwork of bricks and mortars in places.	
	DESIGNATION:	Listed Building grade II, CA	Vegetation growth, large tree roots and the loss of brickwork are causing localised damage. A condition survey	
	CONDITION:	Poor	is required to inform repair works. Discussions are ongoing between the Local Authority, Histoirc England and the	
and the sector	OCCUPANCY:	N/A	owners to explore possible sources of funding.	
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation		
© Historic England	LIST ENTRY NUMBER:	1224734	Contact: Mark Butler (LPA) 020 7361 2465	
PRIORITY CATEGORIES			ABBREVIATIONS	
<ul> <li>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</li> <li>B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.</li> <li>B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.</li> <li>C Slow decay; no solution agreed.</li> </ul>				

SITE NAME:

DESIGNATION:

	SITE NAME:	25-26, Pembridge Square W2	Two mid-C19 stucco houses in florid classical style now
	DESIGNATION:	Listed Building grade II, CA	joined together to form a hotel. Permission was granted in June 2009 for change of use back to residential with a rear
	CONDITION:	Fair	extension and basement. The elevations have been repaired and redecorated, however other works on site
	OCCUPANCY:	Part occupied/part in use	have ceased following the submission of further Planning
	PRIORITY CATEGORY:	D (D)	and Listed Building Consent applications. The buildings are now showing signs of neglect.
	OWNER TYPE:	Private	
T	LIST ENTRY NUMBER:	1225869	Contact: Mark Butler (LPA) 020 7361 2465
sington and			

© Royal Borough of Kensington and Chelsea

	SITE NAME:	Church of St John the Baptist, Holland Road, Kensington W14	Church dating from 1874-1911 by J Brooks and JS Atkins architects. Coursed rubble walling with Bath stone
	DESIGNATION:	Listed Place of Worship grade I, CA	dressings and slate pitched roofs. Early English style with a large rose window at the west end and a highly decorated baptistery. Extensive repairs to the roofs, high level
	CONDITION:	Fair	masonry and rainwater goods were completed in early 2015, grant-aided by the Heritage Lottery Fund and
Aler Pas	PRIORITY CATEGORY:	C (F)	Historic England. The west end roofs and masonry are still
	OWNER TYPE:	Religious organisation	in need of repair.
	LIST ENTRY NUMBER:	1080593	Contact: Tracey Craig 020 7973 3756
gland			

Church of St Michael and All

Listed Place of Worship grade II,

Angels, Ladbroke Grove, Kensington WI0

CA

© Historic Engl



© Historic Engl

	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
gland	LIST ENTRY NUMBER:	1226579	Contact: Tracey Craig 020 7973 3756
. And the second second	SITE NAME:	Church of St Augustine, Queen's Gate, Kensington SW7	Large church designed by William Butterfield in the Goth style completed in 1876. Constructed in Gault brick with
	DESIGNATION:	Listed Place of Worship grade II*, CA	stone and red brick banding with areas of patterned diaper work to parapets and gables and decorative carved stone panels. Rich polychromatic decoration internally also. Re-
	CONDITION:	Poor	slating of the north slope of the nave and the north aisle was completed in 2011, grant-aided by Historic England
TAN	PRIORITY CATEGORY:	C (C)	and the Heritage Lottery Fund. The south side is in need of
ALL ALL	OWNER TYPE:	Religious organisation	similar work, along with brick and stone repairs particularly to the west elevation.
	LIST ENTRY NUMBER:	1226161	Contact: Tracey Craig 020 7973 3756
Igland			

of repair.

© Historic Engl

	SITE NAME:	St Clement's Church, Treadgold Street, Kensington W11	Designed by JP Auby an east end range of
	DESIGNATION:	Listed Place of Worship grade II	reordered in 2007 se community education
SP	CONDITION:	Poor	eastern end of the na associated rainwater
100	PRIORITY CATEGORY:	D (C)	with funding from the
	OWNER TYPE:	Religious organisation	England. The church the Heritage Lottery
	LIST ENTRY NUMBER:	1265169	south aisle roofs and

yn, built in 1867. Fellowes Pryne added f rooms c1905. The interior was eparating off the chancel to form a on suite. The chancel, transepts and the ave were re-roofed in 2014 along with goods, drainage and masonry repairs e Heritage Lottery Fund and Historic has received a first round pass from Fund for repairs to the north and the rest of the nave roof.

Designed by J and JS Edmeston, built in 1871. Rhineland

Romanesque style in London stock brick with terracotta,

red Mansfield and Forest of Dean stone dressings, with clay roof tiles. The roofs and rainwater disposal system are in

poor condition. Some stone and brickwork is also in need

Contact: Tracey Craig 020 7973 3756

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
  - Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / KENSINGTON AND CHELSEA / KINGSTON UPON THAMES / LAMBETH

SITE NAME:	Kensal Green Cemetery W10		
DESIGNATION:	Conservation Area, 153 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 020 7361 2465

	SITE NAME	Former Head Post Office 42	Post office built in 1875. Three storeys in red brick with
© Historic England	LIST ENTRY NUMBER:	1080059	Contact: Chloe Clay (LPA) 020 8547 5318
Historic England	OWNER TYPE:	Commercial company	
	PRIORITY CATEGORY:	C (E)	
	OCCUPANCY:	Vacant/not in use	
	CONDITION:	Poor	discussions with the owners regarding appropriate development for re-use.
	DESIGNATION:	Listed Building grade II	comprehensive redevelopment as set out in the K+20 Area Action Plan. Historic England and the Local Authority are in
	SITE NAME:	Kingston Telephone Exchange, Ashdown Road, Kingston upon Thames	Purpose built telephone exchange, built in 1907 and opened in 1908. Arts and Crafts style with an asymmetric plan. The building is located within an area identified for
KINGSTON UPON THA	MES		

al.	
The second se	

© Historic England

	SITE NAME:	Former Head Post Office, 42, Eden Street, Kingston upon Thames	Post office built in 1875. Three storeys in red brick with stone dressings. The re-use of the building has been delayed due to wider considerations relating to the Local
	DESIGNATION:	Listed Building grade II	Authority's aspirations for town centre renewal as set out in the K+20 Area Action Plan. However, Historic England
	CONDITION:	Fair	and the Local Authority are now in discussions with the owners regarding appropriate development for re-use.
	OCCUPANCY:	Vacant/not in use	
-	PRIORITY CATEGORY:	C (E)	
100	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080100	Contact: Chloe Clay (LPA) 020 8547 5318



Uncovered coal store with tower and attached SITE NAME: Lambeth uncovered coal store including tower and attached tunnels, Portsmouth Road, underground tunnels. Built 1851-1852 to the design of James Simpson in a Romanesque style for the Lambeth Waterworks. It has been vacant for many years. The Local Surbiton Authority has been in negotiations with the owner DESIGNATION: Listed Building grade II, CA regarding works. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (A) OWNER TYPE: Private LIST ENTRY NUMBER: Contact: Chloe Clay (LPA) 020 8547 5318 1031864

LAMBETH

© Royal Borough of Kingston upon

Thames

	SITE NAME:	Beaufoy Institute, 39, Black Prince Road, Vauxhall SEI I	Educational building of 1907 (architect FA Powell). Brick and terracotta facade with free Baroque motifs. 1930
	DESIGNATION:	Listed Building grade II, CA	laboratory wing to the side and assembly hall at the rear. The building was vacated by the Lilian Baylis Secondary
	CONDITION:	Fair	School in 1999. The building is now occupied and repair works are progressing.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1358193	Contact: Douglas Black (LPA) 020 7926 4065

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D


Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site





Early to mid-C19. The windows are boarded up and SITE NAME 136 and 138, Brixton Hill SW2 scaffolding has been erected. Planning Permission for DESIGNATION: Listed Building grade II, CA change of use to residential was granted by the Local Authority in 2013. The building is still unoccupied. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE-Unknown LIST ENTRY NUMBER: 1080539 Contact: Douglas Black (LPA) 020 7926 4065

© London Borough of Lambeth





Eight blocks with 96 flats around a central landscaped SITE NAME: Dorchester Court, Herne Hill courtyard, dating from 1933-4 by Leslie H Kemp and SE24 Frederick E Tasker. There are structural problems with the DESIGNATION: Listed Building grade II balconies and general external deterioration. Discussions are ongoing regarding a comprehensive programme of CONDITION: Poor refurbishment. OCCUPANCY: Occupied/in use PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1390780 Contact: Douglas Black (LPA) 020 7926 4065

© London Borough of Lambeth



	SITE NAME:	Off licence attached to the Old Red Lion public house, 44, Kennington Park Road SEI I	Tudorbethan style off-licence, built circa 1929. Damage includes a broken window pane. Planning Permission and Listed Building Consent for the erection of a three storey	
	DESIGNATION:	Listed Building grade II	extension were granted on appeal in 2014.	
	CONDITION:	Poor		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	D (C)		
	OWNER TYPE:	Private		
٦	LIST ENTRY NUMBER:	1061361	Contact: Douglas Black (LPA) 020 7926 4065	

© London Borough of Lambeth

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

F

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA

WHS


- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ΪA

Unitary Authority World Heritage Site

	A STREET
	AL STREET
and the second se	Contraction of the
and the second s	1.000
A CONTRACTOR	Server 1
TOTAL CO. CO. C.	
AND A PARTY OF THE REAL PROPERTY OF THE PARTY OF THE PART	and Distances
COLUMN TWO IS NOT THE OWNER.	
	COLUMN TWO IS NOT
	Contract of the second
and the second second	100 C
	100000-001
and the second se	124.50
	Contraction of
	- Frank - Frank
Sent And State	ALC: NOT A
Sale and a second	and the second second
Alter ALL ALL AND	100 B
	and the second second


© London Borough of Lambeth

SITE NAME:	Old Paradise Gardens, walls of former graveyard, Lambeth High Street SEI I	C18 walls of reddish brick enclosing a former burial ground. The brickwork and coping stones are in poor condition. The walls are cracked and bowed and, in places,
DESIGNATION:	Listed Building grade II	are in a state of collapse.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (New entry)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1080371	Contact: Douglas Black (LPA) 020 7926 4065





© Historic England



Former fire station in use as the South London Theatre for SITE NAME: Old Fire Station (South London many years, leased from the London Borough of Lambeth. Theatre), 2A, Norwood High There has been internal water damage and significant roof Street SE27 repairs are required. Funding has been secured from the DESIGNATION: Listed Building grade II, CA Heritage Lottery Fund and a Conservation Management Plan is being prepared. Planning Permission and Listed CONDITION: Poor Building Consent applications were approved by the Local Part occupied/part in use Authority in April 2014 for redevelopment of the site, OCCUPANCY: including new accessible theatre space, entrance foyer and PRIORITY CATEGORY: B (B) passenger lift. OWNER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1263240 Contact: Douglas Black (LPA) 020 7926 4065

Doric temple mortuary chapel c1872, attributed to J Oldrid SITE NAME: Augustus Ralli Mortuary Chapel, Scott, within the Greek Burial Ground and known as St Norwood Road, West Norwood Memorial Park SE27 Stephen's Chapel. Built of white and gold coloured fossiliferous limestone. The chapel is in poor condition due Listed Building grade II\*, RPG to subsidence, collapsed steps and internal water damage. DESIGNATION: grade II\*, CA A condition survey has been prepared, with funding from Historic England, and discussions are now underway to CONDITION: Poor secure the necessary repair works. OCCUPANCY: N/A PRIORITY CATEGORY C (C) © Historic England OWNER TYPE: Unknown LIST ENTRY NUMBER: 1064989 Contact: Elizabeth Whitbourn 07889 808145

#### PRIORITY CATEGORIES

© London Borough of Lambeth

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

#### ABBREVIATIONS

WHS

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA
  - Unitary Authority World Heritage Site



Catacombs circa 1837; cemetery laid out circa 1837 by Sir William Tite. A temporary roof has been erected over the SITE NAME: Catacombs beneath the Remembrance Garden, Norwood High Street, West entrance to allow the structure to dry out before agreeing repairs. Funding options are being explored. An application Norwood Memorial Park SE27 to retain the temporary roof was approved in 2011 for five Listed Building grade II, RPG years. Moisture surveys are ongoing; levels appear to be DESIGNATION: grade II\*, CA stabilising/reducing. Discussions are ongoing regarding a cemetery management plan and long-term future. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: C (D) OWNER TYPE: Local authority 1263192 LIST ENTRY NUMBER ntact: Douglas Black (LPA) 020 7926 4065



	LIST ENTRY NUMBER:	1263192	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Letts Family Tomb, West Norwood Memorial Park, Norwood Road SE27	Pedestal monument and slab above a vault circa 1850. The tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. A condition
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1263199	Contact: Douglas Black (LPA) 020 7926 4065

Mausoleum of George Dodd, Norwood Road,West

Norwood Memorial Park SE27

Listed Building grade II, RPG

grade II\*, CA

C (New entry)

Very bad

Unknown

1325944

N/A

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



SITE NAME: Tomb of Alexander Berens, 1858 chest tomb designed by EM Barry. Pink granite plinth, Norwood Road, West with marble superstructure and Portland stone sculpture. Norwood Memorial Park SE27 Conservation works, funded by the Berens family and Historic England, are underway and due for completion in Listed Building grade II\*, RPG 2015. DESIGNATION: grade II\*, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: F (F) OWNER TYPE: Private LIST ENTRY NUMBER: 1065022 Contact: Elizabeth Whitbourn 07889 808145

© Historic England

#### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

Mausoleum, circa 1865, by Thomas Allom. Built of white

plan of three bays defined by pinnacle buttresses. The mausoleum was noted as being in a poor state of repair

marble in a northern Italian Gothic style, with a rectangular

when listed in 1981 and has continued to deteriorate. The

monument is now overgrown with vegetation. A condition survey has been prepared, with funding from Historic

England, and discussions are now underway to secure the

Contact: Douglas Black (LPA) 020 7926 4065

necessary repair works.

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA Unitary Authority World Heritage Site WHS



SITE NAME: Tomb of C Auffrey and E O'Gorman, Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A)

Unknown

Tomb of Christopher Gabriel, Norwood Road, West

Norwood Memorial Park SE27

Listed Building grade II, RPG

grade II\*, CA

Poor N/A

A (A)

Unknown

1064988

OWNER TYPE:

OWNER TYPE:

LIST ENTRY NUMBER:

Pedestal tomb dating from 1893 with carved wreaths, faces and anchor. The tomb is leaning significantly. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.

Chest tomb in Portland stone dating from 1873 with

discussions are now underway to secure the necessary

the side of the tomb. A condition survey has been prepared, with funding from Historic England, and

Contact: Douglas Black (LPA) 020 7926 4065

carvings by Kelsey. There is cracking to the stone panels on

© Historic England



	LIST ENTRY NUMBER:	1250576	Contact: Douglas Black (LPA) 020 7926 4065
MARINE A. S.	SITE NAME:	Tomb of Captain John Wimble, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1851 with finely carved reliefs showing ships at sea. The stone ship surmounting the tomb is subject to movement. A condition survey has been
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.
19 19	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065020	Contact: Douglas Black (LPA) 020 7926 4065



© Historic England



© Historic England



SITE NAME: Tomb of Elizabeth King, Statue of an angel mounted against a rough headstone over rough base, dating from 1922. In the style of the 1878 Oneto Monument by Giulio Monteverge in Genoa. The Norwood Road, West Norwood Memorial Park SE27 statue and headstone are leaning significantly. A condition Listed Building grade II, RPG survey has been prepared, with funding from Historic DESIGNATION: grade II\*, CA England, and discussions are now underway to secure the necessary repair works. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: Contact: Douglas Black (LPA) 020 7926 4065 1250589

repair works.

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

## ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ

Unitary Authority World Heritage Site WHS

All and a


C

Contra In	SITE NAME:	Tomb of Israel Thomas, Norwood Road, West	Pedestal monument above a vault in the Egyptian Revival style, circa 1842. The tomb is overgrown with vegetation. The plinth is also broken and open to the elements. A
	LIST ENTRY NUMBER:	1250687	Contact: Douglas Black (LPA) 020 7926 4065
© Historic England	OWNER TYPE:	Unknown	
	PRIORITY CATEGORY:	A (A)	
	OCCUPANCY:	N/A	
	CONDITION:	Poor	repair works.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	causing further damage. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary
the t	SITE NAME:	Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on a pedestal with grave slab dating from 1904. Tiles are missing and cementitious repairs are

		1
	-	~
	-	and and
		- AL

© Historic England

1		Norwood Memorial Park SE27	The plinth is also broken and open to the elements. A
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	condition survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.
	CONDITION:	Poor	
the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1263196	Contact: Douglas Black (LPA) 020 7926 4065





	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250584	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of James Kershaw, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1864 in Gothic style with elaborate carving. Designed by Alfred Waterhouse commemorating the MP James Kershaw. The structural
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	ironwork is corroding, causing splitting of the stone. The railings are also being affected by movement to the plinth. A condition survey has been prepared, with funding from
	CONDITION:	Poor	Historic England, and discussions are now underway to secure the necessary repair works.
T	OCCUPANCY:	N/A	secure the necessary repair works.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1263197	Contact: Douglas Black (LPA) 020 7926 4065

© Historic England

PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D


Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site



Tomb of John Stevens, Norwood Road, West

grade II\*, CA

Poor N/A

A (A)

Unknown

Norwood Memorial Park SE27

Listed Building grade II, RPG



	SITE NAME:	Tomb of John and Virginia Schilizzi, Norwood Road, West Norwood Memorial Park SE27	Monument dating from 1908 within the Greek Burial Ground. Comprises a stepped granite base with sarcophagus surmounted by white marble female figure
1	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	with flowing robes and veiled head. The figure is subject to movement and is now close to the edge of the sarcophagus. A condition survey has been prepared, with
	CONDITION:	Poor	funding from Historic England, and discussions are now underway to secure the necessary repair works.
	OCCUPANCY:	N/A	anderway to secure the necessary repair works.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1064995	Contact: Douglas Black (LPA) 020 7926 4065

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY: PRIORITY CATEGORY:

OWNER TYPE:

© Historic England



LIST ENTRY NUMBER: 1064983 Contact: Douglas Black (LPA) 020 7926 4065 SITE NAME: Tomb of Michael Emmanuel Pink granite table tomb dating from circa 1899 within the Rodocanachi and Family, Greek Burial Ground. Invasive vegetation is causing damage to the stepped base and the pillars surrounding the central Norwood Road, West Norwood Memorial Park SE21 pedestal. A condition survey has been prepared, with funding from Historic England, and discussions are now Listed Building grade II, RPG underway to secure the necessary repair works. DESIGNATION: grade II\*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1064992 Contact: Douglas Black (LPA) 020 7926 4065

repair works.

© Historic England

## PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Obelisk monument dating from 1861 by Anderson and

discussions are now underway to secure the necessary

is leaning significantly. A condition survey has been prepared, with funding from Historic England, and

McKenzie of Aberdeen with incised fret pattern. The tomb

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ΪA
- Unitary Authority World Heritage Site WHS

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Poor

N/A

A (A)

Poor

N/A

C (C)

1120820

Unknown

1065021

Tomb of William Grane,

Norwood Road, West Norwood Memorial Park SE27

Listed Building grade II, RPG grade II\*, CA

	SITE NAME:	Tomb of Mrs Alice Moffatt, Norwood Road, West Norwood Memorial Park SE27	An arcaded chest tomb, circa 1847. The columns and top slab have been lost, leaving the structural rods exposed. A condition survey has been prepared, with funding from
In the second	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Historic England, and discussions are now underway to secure the necessary repair works.
All and a second	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357922	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Tomb of Thomas De La Garde Grissell, Norwood Road, West Norwood Memorial Park SE27	Chest tomb, circa 1847. Cast iron, stucco and pink granite. The plinth is broken and parts are exposed. A condition survey has been prepared, with funding from Historic
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	England, and discussions are now underway to secure the necessary repair works.

© Historic England





© Historic England



© Historic England

	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357900	Contact: Douglas Black (LPA) 020 7926 4065
I	SITE NAME:	Tomb of XE Balli Family, Norwood Road, West Norwood Memorial Park SE27	lonic temple mausoleum dating from the late C19 within the Greek Burial Ground. There is evidence of movement to the entablature and collapse of the steps. A condition
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	

Contact: Douglas Black (LPA) 020 7926 4065

Contact: Douglas Black (LPA) 020 7926 4065

necessary repair works.

Tomb dating from 1856, noted in the listing description as

having a pink granite cross with foliated arms and vine trails to stem. This cross is missing and there is clear evidence of movement to the base of the monument. A condition

survey has been prepared, with funding from Historic

England, and discussions are now underway to secure the

## PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / LAMBETH



© Historic England

Sec. Sec.	SITE NAME:	West Norwood fire station, 445, Norwood Road, Norwood SE27	Fire station with flats above, although no longer in use. Built in 1914-15 by the London County Council Architects' Department. Planning Permission was granted in 2015 for a
	DESIGNATION:	Listed Building grade II	mixed use conversion with residential uses on the upper floors.
	CONDITION:	Good	
	OCCUPANCY:	Vacant/not in use	
T.L.	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1392336	Contact: Douglas Black (LPA) 020 7926 4065




A Serve	SITE NAME:	Dyce drinking fountain, Streatham Green SW16	Drinking fountain, 1862 in Portland stone/red sandstone with a marble basin. There is water ingress and structural
	DESIGNATION:	Listed Building grade II, CA	instability. A condition survey has been prepared (spring 2015) and repairs are due to start later in 2015 with
	CONDITION:	Very bad	funding from Historic England.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	39 393	Contact: Douglas Black (LPA) 020 7926 4065

© London Borough of Lambeth

© London Borough of Lambeth







and Really 1	
	and

Coade stone chest tomb in railed enclosure, dated 1808 by Coade and Sealy. The railings are broken and in a poor state of repair. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to secure the necessary repair works. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1323732 Contact: Douglas Black (LPA) 020 7926 4065

### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / LAMBETH

HERITAGE AT RISK 2015 / LONDO	JN / LAMBETH		
	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa 1808 by Coade and Sealy. The Coade stone is in an advanced state of decay. A condition survey has been prepared, with funding from Historic England, and discussions are now underway to
	DESIGNATION:	Listed Building grade II, CA	secure the necessary repair works.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1323731	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	335-337, Wandsworth Road SW8	Pair of Regency houses, formerly undertaker's premises. The buildings are occupied and the freeholders are co- operating with the Local Authority on a phased
	DESIGNATION:	Listed Building grade II, CA	programme of repairs.
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	D (D)	
1	OWNER TYPE:	Commercial company	
© London Borough of Lambeth	LIST ENTRY NUMBER:	1081047	Contact: Douglas Black (LPA) 020 7926 4065
	SITE NAME:	Wall on the south side of St John with All Saints' churchyard, Waterloo Road SEI	Early C19 stock brick walls, spalled with cracked brickwork. The finials are broken and missing.
A LEADER COMPLETE	DESIGNATION:	Listed Building grade II, CA	
Anter the	CONDITION:	Poor	
Sale of the second	OCCUPANCY:	N/A	
12 Martin State	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1068687	Contact: Douglas Black (LPA) 020 7926 4065
-	SITE NAME:	The Clapham Orangery, Worsopp Drive SW4	Orangery built in 1793 to the design of William Burgh, in Palladian style. It stood in the grounds of Thornton Hou
	DESIGNATION:	Listed Building grade II	demolished in the 1940s. Now standing in the middle of a housing estate.
	CONDITION:	Fair	5
	OCCUPANCY:	N/A	
Enter [E]	PRIORITY CATEGORY:	C (C)	
	PRIORITY CATEGORY: OWNER TYPE:	C (C) Local authority	
© Historic England Archive			Contact: Douglas Black (LPA) 020 7926 4065
© Historic England Archive	OWNER TYPE:	Local authority	Church dating from 1849 to 1851 by William Wardell, with fittings and further extensions by JF Bentley and others. Built in Kentish ragstone with slated roofs. There are problems with the stonework of the spire. The church has been awarded a grant from the Heritage Lottery Fund and
© Historic England Archive	OWNER TYPE: LIST ENTRY NUMBER:	Local authority 1068843 Roman Catholic Church of St Mary (Church of the Redemptionist Fathers), Clapham Park Road, Clapham	Church dating from 1849 to 1851 by William Wardell, with fittings and further extensions by JF Bentley and others. Built in Kentish ragstone with slated roofs. There are problems with the stonework of the spire. The church has
© Historic England Archive	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Local authority 1068843 Roman Catholic Church of St Mary (Church of the Redemptionist Fathers), Clapham Park Road, Clapham SW4 Listed Place of Worship grade	Church dating from 1849 to 1851 by William Wardell, with fittings and further extensions by JF Bentley and others. Built in Kentish ragstone with slated roofs. There are problems with the stonework of the spire. The church has been awarded a grant from the Heritage Lottery Fund and repair works started in April 2015, with completion due in
	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Local authority 1068843 Roman Catholic Church of St Mary (Church of the Redemptionist Fathers), Clapham Park Road, Clapham SW4 Listed Place of Worship grade II*, CA	Church dating from 1849 to 1851 by William Wardell, with fittings and further extensions by JF Bentley and others. Built in Kentish ragstone with slated roofs. There are problems with the stonework of the spire. The church has been awarded a grant from the Heritage Lottery Fund and repair works started in April 2015, with completion due in
e Historic England Archive Set Historic England Archive Set Historic England	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Local authority 1068843 Roman Catholic Church of St Mary (Church of the Redemptionist Fathers), Clapham Park Road, Clapham SW4 Listed Place of Worship grade II*, CA Very bad	Church dating from 1849 to 1851 by William Wardell, with fittings and further extensions by JF Bentley and others. Built in Kentish ragstone with slated roofs. There are problems with the stonework of the spire. The church has been awarded a grant from the Heritage Lottery Fund and repair works started in April 2015, with completion due in

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / LAMBETH / LEWISHAM

	SITE NAME:	Trinity Congregational Chapel, St Matthews Road, Brixton SW2	Classical chapel built in 1828 of stock brick with stucco entablature and original pews internally. There are structural problems with the front and side elevations and
	DESIGNATION:	Listed Place of Worship grade II	the congregation has commissioned structural repairs to begin in summer 2015.
	CONDITION:	Poor	-
an 🛛 🗮	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1357942	Contact: Tracey Craig 020 7973 3756
prough of Lambeth			

© London Bord

# LEWISHAM

© Historic England

	SITE NAME:	Beckenham Place, Foxgrove Road, Beckenham Place Park	Mansion built circa 1773, situated within former park land, now a golf course. Some emergency repairs were carried	
Part	DESIGNATION:	Listed Building grade II*, CA	out in 2012 with a grant from Historic England. A Heritage Lottery Fund bid is being prepared by the Local Authority	
	CONDITION:	Fair	for repairs to Beckenham Place and a strategy for its future use.	
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1359317	Contact: Elizabeth Whitbourn 07889 808145	

Stable block and garden walls to

Beckenham Place, Beckenham

Listed Building grade II

Holland and Company's

Listed Building grade II

Vacant/not in use

Distillery, 14 and 16, Deptford

Vacant/not in use

Local authority

Hill Road

Very bad

1080027

Bridge SE8

Poor

C (C)

Private

1080000

B (B)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:

© London Borough of Lewisham



	SITE NAME:	Ramp at Deptford Railway Station, Deptford High Street SE8	Built in 1856 to the design of engineer Colonel Lordmann. A dog-leg ramp formed by a series of brick arches rising up from Deptford High Street to the level of the tracks. A
	DESIGNATION:	Listed Building grade II, CA	scheme for the redevelopment of the enclosed square, including the repair of the ramp and occupation of the
	CONDITION:	Poor	arches, is in the process of being implemented.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1079947	Contact: Regina Jaszinski (LPA) 020 8314 9112

#### PRIORITY CATEGORIES

© Historic England Archive

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

Late C18 stable block, which was severely damaged by fire

in 2011. An updated survey is being prepared to ensure

that the remaining structure is stabilised and protected.

The Heritage Lottery Fund has awarded development

funding under the Parks for People programme for the wider park, which includes funds towards restoring the

stable block and a strategy for its future use.

Contact: Regina Jaszinski (LPA) 020 8314 9112

door and a carriage entrance, framed in late C19

for a number of years and is deteriorating.

Contact: Regina Jaszinski (LPA) 020 8314 9112

Former offices of the Holland and Company's Distillery,

stonework with dentil cornice and an inscription in the

late C18. On the ground floor at the east end is a double

small pediment over: "Established 1779. Holland and Co's Distillery and Bonded Store". The building has been empty

- Conservation Area Listed Building LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2015 / LONDC	DN / LEWISHAM		
	SITE NAME:	Old Swimming Baths, Ladywell Road SE13	Public baths, consisting of first and second class swimming pools constructed in 1884. Designed in the Gothic style by
	DESIGNATION:	Listed Building grade II, CA	Wilson and Son and Thomas Aldwinkle. The building is currently unused, however urgent works to the roof and
	CONDITION:	Poor	dry rot are now complete and have stabilised the building. The Local Authority is investigating funding options for the
	OCCUPANCY:	Vacant/not in use	full repair of the building and options for its long term use.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© London Borough of Lewisham	LIST ENTRY NUMBER:	1391811	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old Churchyard SE13	A stone chest tomb from the middle of the C18 commemorates Captain Limeburner of the Royal Navy and his wife. The south side has lost its central panel and the
A SPAL	DESIGNATION:	Listed Building grade II, CA	angle balusters are displaced. A condition survey has been prepared, with funding from Historic England, and
CONTRACTOR OF	CONDITION:	Very bad	discussions are now underway to secure the necessary
	OCCUPANCY:	N/A	repair works.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392002	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard SEI3	An elaborate Rococo tomb from 1769 in Portland stone and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION:	Listed Building grade II*, CA	from vegetation growth and some collapse. A condition survey has been prepared, with funding from Historic
	CONDITION:	Very bad	England, and discussions are now underway to secure the necessary repair works.
	OCCUPANCY:	N/A	necessary repair works.
	PRIORITY CATEGORY:	A (A)	
and the second	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1391993	Contact: Elizabeth Whitbourn 07889 808145
2-57	SITE NAME:	Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE13	Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carving of garlanded cherub's head dating from 1752. The
	DESIGNATION:	Listed Building grade II, CA	monument has lost its railings, back plates and inscription panels and vegetation growth is causing further damage. A
	CONDITION:	Poor	condition survey has been prepared, with funding from Historic England, and discussions are now underway to
and All	OCCUPANCY:	N/A	secure the necessary repair works.
and the first	PRIORITY CATEGORY:	A (A)	
and the second se	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1391998	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of John Crutchley, Lee Terrace, St Margaret's Old Churchyard SEI3	Raised ledger stone from 1727. Ground subsidence has caused some sinking and movement to the ledger which is now set at an angle. A condition survey has been prepared,
and the	DESIGNATION:	Listed Building grade II, CA	with funding from Historic England, and discussions are now underway to secure the necessary repair works.
	CONDITION:	Poor	. , , ,
ALL TO THE	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392012	Contact: Regina Jaszinski (LPA) 020 8314 9112

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

93

HERITAGE AT	RISK 2015 /	LONDON /	LEWISHAM

A Ringhan	SITE NAME:	Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SEI3	Stone chest tomb erected in 1767. The tomb is badly damaged by vegetation growth through open joints. A condition survey has been prepared, with funding from
ALL REAL FOR	DESIGNATION:	Listed Building grade II, CA	Historic England, and discussions are now underway to secure the necessary repair works.
	CONDITION:	Poor	······
Contra 1	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
and the state of the	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392013	Contact: Regina Jaszinski (LPA) 020 8314 9112
		Tank (Land David La	This serves exits your recomment to Lond Deers dates from
MOX.	SITE NAME:	Tomb of Lord Dacre, Lee Terrace, St Margaret's Old Churchyard SEI3	This composite urn monument to Lord Dacre dates from 1794. All the elements now lie disassembled on the ground. The monument needs urgent attention to avoid further damage or loss of its components. A condition
- Martin	DESIGNATION:	Listed Building grade II, CA	survey has been prepared, with funding from Historic
LA CAN PERSON	CONDITION:	Very bad	England, and discussions are now underway to secure the necessary repair works.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392008	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Rev. Thomas Negus,	Chest tomb from 1765, badly damaged from vegetation which has infiltrated through open joints and cracked the
		Lee Terrace, St Margaret's Old Churchyard SE13	ledger slab. One angle baluster has been lost and there
	DESIGNATION:	Listed Building grade II, CA	risk of further collapse. A condition survey has been prepared, with funding from Historic England, and
	CONDITION:	Very bad	discussions are now underway to secure the necessar
I De la Carte	OCCUPANCY:	N/A	repair works.
the man and the	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392011	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Thomas Butler, Lee	Chest tomb from 1733. The panels on both sides and on
North .		Terrace, St Margaret's Old Churchyard SEI3	one end have collapsed exposing brickwork and making the monument vulnerable to rapid deterioration. A condition survey has been prepared, with funding from Historic
	DESIGNATION:	Listed Building grade II, CA	England, and discussions are now underway to secure the
	CONDITION:	Very bad	necessary repair works.
Lange 1	OCCUPANCY:	N/A	
Charles and and	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1392003	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Tredway, Lee Terrace,	A composite monument formed by a mid/late C18 chest
		St Margaret's Old Churchyard SEI3	tomb surmounted by an early C19 sarcophagus. The end panel of the upper part is broken. A condition survey has
- 5000	DESIGNATION:	Listed Building grade II, CA	been prepared, with funding from Historic England, and discussions are now underway to secure the necessary
CONT	CONDITION:	Poor	repair works.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
17 Jan 18 1	OWNER TYPE:	Religious organisation	
D Historic England	LIST ENTRY NUMBER:	1392010	Contact: Regina Jaszinski (LPA) 020 8314 9112
		1572010	
PRIORITY CATEGORIES			ABBREVIATIONS

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
  - use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

94

	SITE NAME:	Church of St Mary the Virgin,	This Georgian church, completed to an unusual design in 1774 by George Gibson Inc. replaced a medieval church
D Historic England			
	LIST ENTRY NUMBER:	1192516	Contact: lan Harper 020 7973 3786
	OWNER TYPE:	Religious organisation	is still some further repair work required.
	PRIORITY CATEGORY:	C (C)	west end was mostly completed in early 2014, grant-aided by the Heritage Lottery Fund and Historic England. There
	CONDITION:	Fair	Portland stone for copings, all under slated roofs. A programme of repairs to windows and masonry at the
AT L	DESIGNATION:	Listed Place of Worship grade II	brick, Bath stone is used for windows and dressings and
	SITE NAME:	Church of St Swithun, Hither Green Lane, Lewisham SE13	This church was completed in 1893 to the designs of Erne Newton, with an extension in 1905. A small mission churc of 1884 survives at the east end. Built of red Wrotham
	LIST ENTRY NUMBER:	1413050	Contact: Regina Jaszinski (LPA) 020 8314 9112
London Borough of Lewisham	OWNER TYPE:	Other not for profit group	
	PRIORITY CATEGORY:	С (С)	Heritage Lottery Fund.
TE PAR	OCCUPANCY:	Vacant/not in use	The condition is deteriorating. In spring 2015 the owner secured a major Heritage Enterprise award from the
	CONDITION:	Poor	water damage, although the roof structure appears sound
	DESIGNATION:	Listed Building grade II	been unoccupied for some time and many windows have been vandalised and parts of the hall have had fire and
	SITE NAME:	Hall attached to the rear of the Fellowship Inn public house, Randlesdown Road, Bellingham SE6	Two storey entertainment hall attached to the rear of the public house built in 1923-4 by FG Newnham for the brewery Barclay Perkins and Co. to serve the former London County Council's Bellingham Estate. The hall has
	LIST ENTRY NUMBER:	1392397	Contact: Regina Jaszinski (LPA) 020 8314 9112
London Borough of Lewisham	OWNER TYPE:	Religious organisation	
	PRIORITY CATEGORY:	C (C)	extensions have been submitted but have not yet been determined.
	OCCUPANCY:	Vacant/not in use	the change of use to a place of worship. Planning and Liste Building Consent applications for associated changes and
TANK BULL THE ARE	CONDITION:	Poor	showing signs of neglect. There is water ingress on the upper floor. Planning Permission was granted in 2012 for
	DESIGNATION:	Listed Building grade II	the past two years. It has been gutted internally and is
	SITE NAME:	Rileys (former Temperance Billiard Hall), 233-241, Lewisham High Street SE13	A temperance billiard hall built 1909-10, originally incorporating a café, lounge and shops facing Lewisham High Street. Listed as a well-surviving example of an uncommon building type. The building has been empty for
	LIST ENTRY NUMBER:	39200	Contact: Regina Jaszinski (LPA) 020 8314 9112
Historic England	OWNER TYPE:	Religious organisation	
	PRIORITY CATEGORY:	A (A)	
	OCCUPANCY:	N/A	necessary repair works.
A Designed	CONDITION:	Poor	England, and discussions are now underway to secure the necessary repair works.
	DESIGNATION:	Listed Building grade II, CA	attention to avoid serious structural damage. A condition survey has been prepared, with funding from Historic
	SITE NAME:	Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE13	Coade stone chest tomb from the late C18. The loss of ledger slab has allowed a tree to take root inside the structure and to grow from its top. The tomb is in new



	SITE NAME:	Church of St Mary the Virgin, Lewisham High Street, Lewisham SEI 3	This Georgian church, completed to an unusual design in 1774 by George Gibson Jnr, replaced a medieval church and incorporated the original tower. The chancel was
	DESIGNATION:	Listed Place of Worship grade II*, CA	added in 1882 by William Blomfield and then re-modelled in 1995-96. The whole building is raised over a crypt and the south side entrance protected by a neoclassical
	CONDITION:	Poor	portico. Despite repairs to the aisle parapet gutters, there has been continued leakage into the church. A project to
	PRIORITY CATEGORY:	B (A)	renew the nave roofs and repair the parapet gutters.
	OWNER TYPE:	Religious organisation	funded by the Heritage Lottery fund, is due to start in early 2016.
	LIST ENTRY NUMBER:	1 193297	Contact: Ian Harper 020 7973 3786

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / LEWISHAM / MERTON

SITE NAME:	Deptford High Street SE8		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Philip Ashford (LPA) 020 8314 8533

# MERTON

	SITE NAME:	Garden wall enclosing four sides of playing field, Church Lane, Merton Park SW19	Garden wall dating from the C16 to C17, with later alterations. There are many areas of eroded brick and inappropriate past repair. Damaging vegetation has been
	DESIGNATION:	Listed Building grade II	removed and a comprehensive survey and specification repair has been carried out. The Local Authority has
	CONDITION:	Poor	previously carried out rebuilding and repairs to a section around the entrance gateway which had been dismantled
	OCCUPANCY:	N/A	for safety reasons, but further works are needed, include
	PRIORITY CATEGORY:	C (C)	control of vegetation.
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1286387	Contact: Jill Tyndale (LPA) 020 8545 3041




-	SITE NAME:	Tomb of Thomas Stanly, Church Road, Mitcham, St Peter and St Paul's Churchyard	Table tomb over large podium erected in the early C18. The podium is severely damaged by vegetation.
DESIGNATION:	DESIGNATION:	Listed Building grade II	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
100	OWNER TYPE:	Religious organisation	
	LIST ENITRY NILIMBER	1000040	Contact: Iill Typdala (I PA) 020 9545 2041

© Historic England



© Historic England





and and	SITE NAME:	109-111, London Road, Mitcham	Pair of semi-detached lap boarded cottages. The property is now fully occupied but inappropriate works have been
DESIGNATION:	Listed Building grade II	carried out without permission.	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
78	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193387	Contact: Jill Tyndale (LPA) 020 8545 3041

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / MERTON

	SITE NAME:	Burn Bullock Public House, 315, London Road	Public house, formerly the Kings Head Hotel, with C16 interior and exterior features and C18 front. No longer
	DESIGNATION:	Listed Building grade II	operating as a public house, but currently illegally occupied as a House in Multiple Occupation (HMO) with associated
	CONDITION:	Poor	management problems and deterioration. Its use is subject to ongoing enforcement action. Historic England and the
	OCCUPANCY:	Part occupied/part in use	Local Authority are in discussion with the owner regarding
	PRIORITY CATEGORY:	C (C)	the need for immediate repairs and developing plans for full conservation.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	9339	Contact: Jill Tyndale (LPA) 020 8545 3041

	SITE NAME:	Dovecote adjacent to pond to south east of The Canons, Madeira Road, Mitcham	The dovecote was built in 1511, being the oldest building in Merton. It is a square structure of chalk blocks and red brick quoins with a hipped tiled roof. There are nesting
W LOG	DESIGNATION:	Listed Building grade II	boxes on the inside of the walls. Repairs to the walls and roof were carried out following damage by vandals. It
	CONDITION:	Fair	g grade II roof were carried out following damage by vandals. It remains very vulnerable to vandalism. Plans for the re-use of nearby Canons should have a positive impact on the
	OCCUPANCY:	Vacant/not in use	ongoing management and care of this building.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
toric England	LIST ENTRY NUMBER:	1080904	Contact: Jill Tyndale (LPA) 020 8545 3041

	SITE NAME:	Ravensbury Mill (North Wing), 245, Morden Road, Morden	C18 and C19 snuff mill powered by water. The North Wing is subject to a Section 106 agreement. There is slow
	DESIGNATION:	Listed Building grade II	progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the
	CONDITION:	Fair	North Wing by Wandle Industrial Museum. Discussions are ongoing to resolve these outstanding issues.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
© Historic England	LIST ENTRY NUMBER:	1080857	Contact: Jill Tyndale (LPA) 020 8545 3041



© Historic England

© Histo



	SITE NAME:	Tomb of Bankes, St Mary's Road, Wimbledon, St Mary's	Table tomb from the mid-C18 with inset panels and baluster profiled corners. Suffering from continued waste
	LIST ENTRY NUMBER:	1080887	Contact: Jill Tyndale (LPA) 020 8545 3041
	OWNER TYPE:	Religious organisation	
	PRIORITY CATEGORY:	A (A)	
	OCCUPANCY:	N/A	
	CONDITION:	Poor	
	DESIGNATION:	Listed Building grade II	
	SITE NAME:	Mausoleum of Sir Joseph William Bazalgette, St Mary's Road, St Mary's Churchyard, Wimbledon SW19	Portland stone mausoleum from the end of the C19. The ironwork has recently been repainted but the gates are missing. There is evidence that water ingress is causing collapse of the internal brickwork to the roof.

om continu oor quality	
3041	
3041	

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted). ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

N. P	SITE NAME:	Tomb of Elizabeth Johnson, St Mary's Road, Wimbledon, St Mary's Churchyard SW19	Table tomb, tapered to the base, erected around 1800. The side panels have collapsed and vegetation has rooted in the monument and on its pedestal.	
A State of the second s	DESIGNATION:	Listed Building grade II		
	CONDITION:	Very bad		
COLDER-	OCCUPANCY:	N/A		
N THE R	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Religious organisation		
) Historic England	LIST ENTRY NUMBER:	93775	Contact: Jill Tyndale (LPA) 020 8545 3041	
	SITE NAME:	Tomb of John Lawson, St Mary's Road, Wimbledon, St Mary's Churchyard SW19	Table tomb on a stepped podium, dating from circa 1704. There is evidence of joints widening and the plinth collapsing.	
	DESIGNATION:	Listed Building grade II		
- antal -	CONDITION:	Very bad		
A MARCA L	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (C)		
	OWNER TYPE:	Religious organisation		
Historic England	LIST ENTRY NUMBER:	1080886	Contact: Jill Tyndale (LPA) 020 8545 3041	
	SITE NAME:	Base of windmill at Mill House, Windmill Road	Brick with timber framing comprising the base of a hollow- post windmill. It is located within the car park of the Mill	
	DESIGNATION:	Listed Building grade II	House public house with its timber superstructure exposed to the elements. The owners have undertaken works to	
	CONDITION:	Fair	preserve the timbers which have now been reinstated. The	
	OCCUPANCY:	N/A	structure remains at risk without a protective cover. Repairs are now required to the supporting walls.	
	PRIORITY CATEGORY:	C (E)		
Statement of the local division of the local	OWNER TYPE:	Commercial company		
Historic England	LIST ENTRY NUMBER:	1194005	Contact: Jill Tyndale (LPA) 020 8545 3041	
	SITE NAME:	Wall to rear of flats, 27-33 (consecutive), Windsor Avenue, Colliers Wood SW19	Fragment of medieval and probably later precinct wall of the former Merton Priory. Constructed from flint and rubble stone, it is being damaged by vegetation growing ou	
and the second	DESIGNATION:	Listed Building grade II	of the wall structure.	
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Private		
) Historic England	LIST ENTRY NUMBER:	1080856	Contact: Jill Tyndale (LPA) 020 8545 3041	
	SITE NAME:	Wall to rear of the block of flats west of easternmost block, 9 1 1 15 17, Windsor Avenue SW19	Fragments of medieval and probably later precinct wall of the former Merton Priory. Constructed from flint and rubble stone, they are being damaged by vegetation	
		west of easternmost block, 911 1517, Windsor Avenue SW19	the former Merton Priory. Constructed from flint and	
	SITE NAME:	west of easternmost block, 9 11 15 17, Windsor Avenue SW19 Listed Building grade II	the former Merton Priory. Constructed from flint and rubble stone, they are being damaged by vegetation	
	SITE NAME: DESIGNATION:	west of easternmost block, 911 1517, Windsor Avenue SW19	the former Merton Priory. Constructed from flint and rubble stone, they are being damaged by vegetation	

Contact: Jill Tyndale (LPA) 020 8545 3041

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

A (New entry)

Private

1194014

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / MERTON / NEWHAM

SITE NAME:	Morden Park Mound		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002011
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Merton Priory (site of), Merantun Way, Colliers W	/ood SW19	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001976
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Bathgate Road SW19		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041
SITE NAME:	Drax Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Jill Tyndale (LPA) 020 8545 3041

Abbey Mills Pumping Station

# NEWHAM

© Historic England




SITE NAME:

	(Station C) with associated Valve House, Abbey Lane E15	and moulded stone dressings. The internal pumping floor sunk deep below ground level. There are no long term
DESIGNATION:	Listed Building grade II, CA	proposals for the re-use of the building at this stage, although options are being discussed.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1392550	Contact: Ben Hull (LPA) 020 3373 9574



© Historic England



### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

Pumping station 1910-14, white stock brick with terracotta

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

· is

#### HERITAGE AT RISK 2015 / LONDON / NEWHAM

	SITE NAME:	Gate lodge at Abbey Mills Pumping Station, Abbey Lane E15	Lodge to pumping station, built circa 1865. Whilst some external repairs have been carried out, more are needed and the interior is in poor condition. It has now been
	DESIGNATION:	Listed Building grade II, CA	leased to a charitable trust for use in connection with a neighbouring site.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (E)	
100	OWNER TYPE:	Charity (non-heritage)	
© Historic England	LIST ENTRY NUMBER:	1080982	Contact: Ben Hull (LPA) 020 3373 9574



	SITE NAME:	Stores Building at Abbey Mills Pumping Station, Abbey Lane E15	Storage building circa 1865 by Sir Joseph Bazalgette. The building is currently vacant. There is significant structural movement and damage due to water ingress. The building
2	DESIGNATION:	Listed Building grade II, CA	is now wind and watertight, and the extent of any ongoing structural movement is being fully assessed in order that
	CONDITION:	Very bad	Thames Water can consider options for repair.
-	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1080980	Contact: Ben Hull (LPA) 020 3373 9574



© Historic England

© Historic England

	SITE NAME:	Ancillary Pump House at Abbey Mills Pumping Station (Station B), Abbey Road E15	Pump house circa 1868, probably by Bazalgette and Cooper, built in a similar style to the main pumping station. There is some evidence of water ingress and the design of
	DESIGNATION:	Listed Building grade II, CA	the exterior downpipes makes them vulnerable to plant growth and blockages. The building is now vacant and has
d i	CONDITION:	Poor	no identified use.
*	OCCUPANCY:	Vacant/not in use	
-	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357994	Contact: Ben Hull (LPA) 020 3373 9574

-	SITE NAME:	West Ham Pumping Station Engine House, Abbey Road EI5	Engine house, built in 1897. Contains original Lilleshall Company beam engines. The building is currently in use as
	DESIGNATION:	Listed Building grade II	a training facility. There are extensive unauthorised works to the interior. The owner is engaging with the Local
	CONDITION:	Fair	Authority and Historic England to regularise works and further develop the use of the building as a training facility,
	OCCUPANCY:	Part occupied/part in use	as part of an overall package of improvements to the site
	PRIORITY CATEGORY:	D (D)	
ALL COMPANY	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357997	Contact: Ben Hull (LPA) 020 3373 9574



3	SITE NAME:	Dukes Head public house, 593, Barking Road, East Ham E6	Impressive corner public house dating from 1900. The ground and first floor function rooms are being used as
	DESIGNATION:	Listed Building grade II	halls for weddings and parties. The flats on the upper floors are vacant. Restoration works were undertaken following
	CONDITION:	Fair	fire damage. There is some unauthorised signage and repairs are needed to the cornice and string courses.
	OCCUPANCY:	Part occupied/part in use	repairs are needed to the connect and suring courses.
	PRIORITY CATEGORY:	C (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1392558	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / NEWHAM

	SITE NAME:	Coach and Horses public house, 100, High Street, Plaistow E13	Three storey C18 public house, yellow brick with red brick arches and reveals. There is extensive damage to the 1930s
and in such	DESIGNATION:	Listed Building grade II	interior. The building is in need of maintenance. It is currently for sale (spring 2015).
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
1 1 3	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080959	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

© Historic England

© Histo

Chimney dating from 1887/89, designed by Joseph SITE NAME: Chimney to Beckton Sewage Works, Jenkins Lane, Beckton Bazalgette, as part of the improvements to the northern outfall of the London drainage network. Listed Building E6 Consent has been granted for works to facilitate the Lee DESIGNATION: Listed Building grade II Tunnel and Beckton extension works. The chimney has been dismantled and is in storage, pending re-erection CONDITION: Poor following completion of the tunnelling works. Regular OCCUPANCY: N/A surveys are carried out on its condition. PRIORITY CATEGORY: D (D) OWNER TYPE: Utility LIST ENTRY NUMBER: 1393160 Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Silo D, North Woolwich Road, Canning Town E16	Grain silo, 1920, built of reinforced concrete. The building appears neglected. There is vegetation growing from
	DESIGNATION:	Listed Building grade II	various areas of the structure and broken windows in many places. Historic England has recommended that the silo's
F P	CONDITION:	Fair	repair and re-use be integrated into the proposed development scheme for the wider area.
	OCCUPANCY:	N/A	development serieme for the wider area.
	PRIORITY CATEGORY:	E (E)	
All and a second	OWNER TYPE:	Unknown	
storic England	LIST ENTRY NUMBER:	1245030	Contact: Ben Hull (LPA) 020 3373 9574



Former railway station, 1847. There are broken windows SITE NAME: North Woolwich Station at first floor level on the front elevation. Vegetation is including turntable and platform growing from the stonework and brickwork and the lamp standards, Pier Road, North Woolwich EI6 platform is overgrown. Historic England and the Local Authority have met with the owners and advised on DESIGNATION: Listed Building grade II necessary works to stabilise the building. A possible shortterm use is being considered. CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: Contact: Ben Hull (LPA) 020 3373 9574 1376229

	SITE NAME:	Earl of Essex public house, 616, Romford Road, Newham E12	Impressive Edwardian public house by Henry Poston and WE Trent, dating from 1902, on a prominent corner site.
TA .	DESIGNATION:	Listed Building grade II	The ground floor is empty and boarded up, with no future use identified. The upper floors are occupied. Repairs are
IN A	CONDITION:	Fair	needed, particularly to external architectural details. Consents have been granted for the conversion of the
	OCCUPANCY:	Part occupied/part in use	building to a banqueting facility and flats.
3	PRIORITY CATEGORY:	D (E)	
P.	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357990	Contact: Ben Hull (LPA) 020 3373 9574

© Historic England

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site


#### HERITAGE AT RISK 2015 / LONDON / NEWHAM

	SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16	Restaurant, built in 1883 to the design of Vigers and Wagstaff in a free classical style. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Good	repairs undertaken. Discussions are taking place regarding the potential refurbishment and re-use of the building as
	OCCUPANCY:	Vacant/not in use	part of wider developments in the area.
	PRIORITY CATEGORY:	E (E)	
And in the second second second	OWNER TYPE:	Government or agency	
) Historic England Archive	LIST ENTRY NUMBER:	1380201	Contact: Ben Hull (LPA) 020 3373 9574

1 .	SITE NAME:	Central offices at Custom House, Royal Albert Dock E16	Offices, built in 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Now owned by the
PIP 0	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Good	repairs undertaken. Discussions are taking place regarding the potential refurbishment and re-use of the building as
	OCCUPANCY:	Vacant/not in use	part of wider developments in the area.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Government or agency	
c England Archive	LIST ENTRY NUMBER:	1376228	Contact: Ben Hull (LPA) 020 3373 9574

Tide Mill (known as the House Mill), Three Mill Lane E3

1191297




© Historic Engla

© I

© Historic

	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Listed Building grade I, CA Fair Part occupied/part in use F (E) Charity (heritage)	needed to the undershot water wheels and surviving machinery. A Stage I Heritage Lottery Fund grant was awarded to the River Lea Tidal Mill Trust and the development work is now complete. The scope of the Stage 2 bid will be refined before submission to the Heritage Lottery Fund. Works will include the repair of machinery, interpretation throughout the building and improvements to education and community facilities.
gland	LIST ENTRY NUMBER:	1080970	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Spotted Dog public house, 212, Upton Lane E7	Weatherboarded C15 timber-framed public house. The property has remained vacant for some years. Whilst
IS REAL AND AND ADDRESS		Opton Lane L7	
	DESIGNATION:	Listed Building grade II	repairs were previously carried out following enforcement
	DESIGNATION: CONDITION:	•	
		Listed Building grade II	repairs were previously carried out following enforcement action, maintenance of the property is again needed.
	CONDITION:	Listed Building grade II Very bad	repairs were previously carried out following enforcement action, maintenance of the property is again needed.
	CONDITION: OCCUPANCY:	Listed Building grade II Very bad Vacant/not in use	repairs were previously carried out following enforcement action, maintenance of the property is again needed.

© Historic England



© Historic England

PRIORITY CATEGORIES	

D

Е

# А

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but  $\ \ F$  not yet implemented.

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Ben Hull (LPA) 020 3373 9574

# ABBREVIATIONS

Tide Mill dating from 1776 and last used in 1941. Much of

the building fabric has been repaired, but work is now needed to the undershot water wheels and surviving

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / NEWHAM / REDBRIDGE

vith triple gable in 1900-09 to
brick with th roofing
third and final age Lottery

#### © Historic England

SITE NAME:	Sugar House Lane, Stratford E15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574
SITE NAME:	Three Mills, Stratford/Bow EI5		
SITE NAME: DESIGNATION:	Three Mills, Stratford/Bow E15 Conservation Area, 12 LBs	NEW ENTRY?:	No
	,	NEW ENTRY?: TREND:	No Improving significantly
DESIGNATION:	Conservation Area, 12 LBs		

# REDBRIDGE

Acres 4	SITE NAME:	831, High Road	Shop with circa 1900 interior, featuring striking glazed
	DESIGNATION:	Listed Building grade II	decorative wall tiling and Minton floor tiling. Severely damaged by nailed studwork and plasterboard covering the
	CONDITION:	Poor	wall tiling, and cement screeding of the floor. In need of major tile repairs and replacements to restore the interior.
	OCCUPANCY:	Occupied/in use	The Local Authority is taking enforcement action.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1271968	Contact: Allan Jones (LPA) 020 8708 2926
© London Borough of Redbridge			

144	SITE NAME:	Dr Johnson public house, Longwood Gardens, llford	Moderne-style public house dating from 1937-8 by H Reginald Ross. Built to serve the large new estates in
	DESIGNATION:	Listed Building grade II	Barkingside. The building has been vacant and boarded up since 2010. The roof is in a poor state of repair and in 2011
	CONDITION:	Poor	the interior was seriously damaged following flooding. Historic England and the Local Authority are in discussion
	OCCUPANCY:	Vacant/not in use	with the owners regarding acceptable uses and associated
	PRIORITY CATEGORY:	A (A)	alterations.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1392792	Contact: Conservation Officer (LPA) 020 8708 2747

	SITE NAME:	Garden Temple in garden of Temple House, 14, The Avenue, Wanstead E11	Garden temple, 1730-40, with lonic pedimented portico. Roof, wall and column repairs have been completed, gran aided by Historic England. However, further repairs are	
	DESIGNATION:	Listed Building grade II*, CA	required. Historic England and the Local Authority are working with the owner to determine the scope of	
	CONDITION:	Very bad	necessary surveys.	
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (C)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1357974	Contact: Verena McCaig 020 7973 3718	

# PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / REDBRIDGE / RICHMOND UPON THAMES


A STATE OF STATE	SITE NAME:	Wanstead Park EI2	Remains of an important landscape dating from the late		
England	DESIGNATION:	Registered Park and Garden grade II*, 6 LBs, part in CA	C17 to the early C19, further developed in the late C19 by the City of London as a public park. The central area was converted to a private golf course in the early C20.		
	CONDITION:	Extensive significant problems	Features of the historic designed landscape survive but are in poor condition. The City of London commissioned a		
	VULNERABILITY:	High	Parkland Plan to guide future improvements to the park.		
	TREND:	Declining	The plan was completed in April 2015. A steering group of stakeholders meets regularly to promote the		
	NEW ENTRY ?:	No	implementation of the Parkland Plan and to explore possible sources of funding.		
	OWNER TYPE:	Local authority, multiple owners	possible sources of funding.		
	LIST ENTRY NUMBER:	1000194	Contact: Zosia Mellor 020 7973 3473		

© Historic Er

SITE NAME:	Mayfield, Ilford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mike Brown (LPA) 020 8708 2747
SITE NAME:	Wanstead Park EI I		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade II*	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mike Brown (LPA) 020 8708 2747
SITE NAME:	Woodford Bridge, Bridge		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mike Brown (LPA) 020 8708 2747

# **RICHMOND UPON THAMES**

NIST OF	SITE NAME:	Loggia and grotto in grounds of Thames Eyot, Cross Deep, Twickenham	Stone loggia of nine Doric columns and shellwork grotto, probably C18. Situated in the grounds of 1930s flats on the bank of the Thames. The roof has suffered partial collapse
	DESIGNATION:	Listed Building grade II*, CA	and structural movement causing distortion to the colonnade. An options appraisal was completed in 2011,
The sea has been the sea in	CONDITION:	Very bad	but no further progress has been made due to a lack of resources. Monitoring of the loggia and grotto is ongoing.
© Historic England	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080812	Contact: Verena McCaig 020 7973 3718



### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / RICHMOND UPON THAMES



© Gould and Company

© Historic England Archive

	SITE NAME:	Garrick's Villa, Hampton Court Road, Hampton	Villa by Robert Adam built in 1756 and remodelled in 1773. Converted into nine apartments in the 1960s and severely
M	DESIGNATION:	Listed Building grade I, RPG grade II, CA	damaged by fire in 2008. External works are complete and the internal fit-out is now progressing.
	CONDITION:	Fair	
1	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193477	Contact: Verena McCaig 020 7973 3718

SITE NAME:	Boat house No. 5 (easternmost 13 bays), Platts Eyot, Hampton	Alban Hamilton Scott for the Thorneycroft firm to build		
DESIGNATION:	Listed Building grade II, CA	torpedo boats for the Admiralty. A full measured survey of the remaining structure has been completed. Monitoring of		
CONDITION:	Very bad	the boat house is ongoing.		
OCCUPANCY:	Part occupied/part in use			
PRIORITY CATEGORY:	A (A)			
OWNER TYPE:	Commercial company			
LIST ENTRY NUMBER:	1254429	Contact: Nicolette Duckham (LPA) 020 8891 7335		
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	I3 bays), Platts Eyot, HamptonDESIGNATION:Listed Building grade II, CACONDITION:Very badOCCUPANCY:Part occupied/part in usePRIORITY CATEGORY:A (A)OWNER TYPE:Commercial company		

	SITE NAME:	Wick House, Richmond Hill, Richmond	Designed by Sir William Chambers circa 1772 for Sir Joshua Reynolds. Permission was granted in recent years for conversion from a nurses' home to a single residence
	DESIGNATION:	Listed Building grade II, CA	for conversion from a nurses' home to a single residence once again. However, after internal works were carried
	CONDITION:	Poor	out, construction work ceased and the building was sold to a new owner. A large crack has since appeared on the flank
	OCCUPANCY:	Vacant/not in use	wall of the building indicating significant structural
	PRIORITY CATEGORY:	D (C)	problems. Listed Building Consent has been approved for repairs. No work has taken place to date.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1263475	Contact: Nicolette Duckham (LPA) 020 8891 7335

	SITE NAME:	Doughty House, 142, Richmond Hill, Richmond	C18 house with C19 alterations made by the Cook family. Planning Permission and Listed Building Consent have beer
	DESIGNATION:	Listed Building grade II, CA	granted to retain the main property as a single dwelling and to convert the gallery to ancillary accommodation, along
	CONDITION:	Poor	with re-instating Doughty Cottage as the link between the house and gallery. No works have taken place and the
	OCCUPANCY:	Vacant/not in use	building is vacant but secure. Permission is currently being
1	PRIORITY CATEGORY:	D (C)	sought for amendments to this scheme.
	OWNER TYPE:	Private	
mond on	LIST ENTRY NUMBER:	1249955	Contact: Nicolette Duckham (LPA) 020 8891 7335

© London Borough of Richm Thames



SITE NAME:	The Gallery at Doughty House, 142, Richmond Hill, Richmond	Gallery built in 1880 for Sir Francis Cook, extended in 1915 by Brewer Smith, comprising eleven bays. Giant Ionic order
DESIGNATION:	Listed Building grade II, CA	with balustrade, the lower order containing door and window openings between Doric pilasters. Works are
CONDITION:	Poor	required to the roof, balustrade and rainwater goods. Planning Permission and Listed Building Consent have been
OCCUPANCY:	Vacant/not in use	granted to retain the main property as a single dwelling and
PRIORITY CATEGORY:	D (D)	to convert the gallery to ancillary accommodation, along with re-instating Doughty Cottage as the link between the
OWNER TYPE:	Private	house and gallery. No works have taken place and the building is vacant.
LIST ENTRY NUMBER:	1387232	Contract: Nicolatta Dualitaria (LDA) 020 0001 7225

Contact: Nicolette Duckham (LPA) 020 8891 7335

### PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / RICHMOND UPON THAMES




Thames

SITE NAME:	Temperate House, Royal Botanical Gardens, Kew	Begun in 1860 by Decimus Burton and not completed until 1897-9. The Temperate House comprises three
DESIGNATION:	Listed Building grade I, RPG grade I, CA, WHS	communicating glasshouses in iron, glass and stucco. Heritage Lottery Funding has been secured and Planning Permission and Listed Building Consent granted for major
CONDITION:	Poor	repair and refurbishment works, along with the former Evolution House. Work has commenced on site with an
OCCUPANCY:	Occupied/in use	anticipated completion date of spring 2017.
PRIORITY CATEGORY:	F (D)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1262590	Contact: Verena McCaig 020 7973 3718



	SITE NAME:	Sandycombe Lodge, 40, Sandycoombe Road, Twickenham	Early C19, built for and to the design of JMW Turner. Main central bay with gable roof and wide eaves, with lower set back flanking wings. The building is vacant but used for
	DESIGNATION:	Listed Building grade II*, CA	tours at present. The intention is to convert the former dwelling to a centre dedicated to the life and work of
	CONDITION:	Fair	Turner. Funding has now been secured from the Heritage Lottery Fund and Listed Building Consent has been
	OCCUPANCY:	Vacant/not in use	granted.
Close a	PRIORITY CATEGORY:	D (C)	
mond on	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1262429	Contact: Verena McCaig 020 7973 3718





	SITE NAME:	Church of St Michael and St George, Wilcox Road	Built in 1913 and designed by JS Adkins. Slate covered pitched roofs with walls externally and internally in red and
	DESIGNATION:	Listed Place of Worship grade II	stock brick with stone dressings. The church ceased functioning in 2000 but is now being used for worship
	CONDITION:	Poor	again, albeit it only in the former Lady Chapel as the rest of the building suffers from leaking roofs and lacks building
	PRIORITY CATEGORY:	C (New entry - re-assessed)	services.
THE COLOR OF	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1393730	Contact: Tracey Craig 020 7973 3756

© Historic England

Thames

SITE NAME:	Platt's Eyot		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Nicolette Duckham (LPA) 020 8891 7335

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### SOUTHWARK

	SITE NAME:	Number 8, Addington Square and attached railings SE5	One of a pair of early C19 houses in the Addington Square Conservation Area. The house has suffered from
	DESIGNATION:	Listed Building grade II, CA	considerable rain ingress owing to faulty rainwater goods and there are signs of some structural movement, particularly to the porch. Historic England has been working with the Local Authority to prioritise necessary repairs and advise the owner.
	CONDITION:	Very bad	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	A (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1376521	Contact: Tracy Chapman (LPA) 020 7525 2289



© Historic England

	SITE NAME:	Railings and gates to Caroline Gardens, Asylum Road SEI5	Iron railings to the Licensed Victuallers' Almshouse complex, dating largely to circa 1830-40. Sections of the ironwork are in a poor state of repair with some elements
	DESIGNATION:	Listed Building grade II, CA	cracked or missing.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1376543	Contact: Tracy Chapman (LPA) 020 7525 2289

Former almshouse chapel, dating from 1827-31. The SITE NAME: Licensed Victuallers building is leased by the London Borough of Southwark to Almshouses: Chapel, Asylum a local artists' group. The condition of the building continues to decline and extensive repairs are required. Road SEI5 DESIGNATION: Listed Building grade II, CA Work is progressing towards commissioning full condition and structural surveys in order to assess the extent of CONDITION: Very bad necessary works, jointly funded by the Local Authority and OCCUPANCY: Part occupied/part in use Historic England. PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority © Historic England LIST ENTRY NUMBER: 1376538 Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Chest tomb, Bermondsey Street, St Mary Magdalene Churchyard SEI	Chest tomb from 1815 with original railings. Overgrowth has caused damage to the stone and ironwork. Historic England has funded a condition survey and specification for
No and a local	DESIGNATION:	Listed Building grade II, SM, CA	works to the tomb. The Local Authority will be funding and commissioning works based on this survey.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1376573	Contact: Tracy Chapman (LPA) 020 7525 2289



	SITE NAME:	Table tomb, Bermondsey Street, St Mary Magdalene Churchyard SEI	Unusual C18 table tomb under a stone canopy with tapered, fluted columns. There is some deterioration to the stone elements and railings. Historic England has	
	DESIGNATION:	Listed Building grade II, CA	funded a condition survey and specification for works to the tomb. The Local Authority will be funding and	
	CONDITION:	Fair	commissioning works based on this survey.	
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	D (D)		
-atry 18	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1376578	Contact: Tracy Chapman (LPA) 020 7525 2289	

#### PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2015 /	LONDON	SOUTHWARK

No.	SITE NAME:	Tomb of John Sargeant, Bermondsey Street, St Mary Magdalene Churchyard SEI	C18 stone chest tomb. The monument has been damaged by erosion and cementitious repairs in the past. Historic England has funded a condition survey and specification for
Set NI_	DESIGNATION:	Listed Building grade II, CA	works to the tomb. The Local Authority will be funding and commissioning works based on this survey.
	CONDITION:	Fair	
The Prove A	OCCUPANCY:	N/A	
and the property of the	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
c England	LIST ENTRY NUMBER:	1376580	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Presbyterian Chapel, 109, Borough Road SEI	Former Presbyterian chapel, 1846. Consent was granted in 2006 for facade retention and the conditions discharged,
	DESIGNATION:	Listed Building grade II, CA	but works have ceased. The building has been made weatherproof and 'mothballed' while South Bank University
	CONDITION:	Poor	reviews options.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1378375	Contact: Tracy Chapman (LPA) 020 7525 2289



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

© Historic

© Historic England

© London Borough of Southwar	ark	Southw	۱ of	Borough	ondon	©
------------------------------	-----	--------	------	---------	-------	---





LIST ENTRY NUMBER: 1378387 Contact: Tracy Chapman (LPA) 020 7525 2289 Early to mid-C19 railings, gates and gate piers. Wrought iron railings and Portland stone piers and plinth. They are a SITE NAME: Gate piers and railings to the churchyard of the former Church of St John, Fair Street good example of late Georgian ironwork but have started to corrode. Proposals for repair have stalled. SEI DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER 1393615 Contact: Tracy Chapman (LPA) 020 7525 2289

Lodge, Camberwell New Cemetery, Brenchley Gardens, Honor Oak SE23

Listed Building grade II

Vacant/not in use

Local authority

Fair

F (D)



	SITE NAME:	Monument to Charles Waters, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1910 to Charles Waters. Marble group of a seated woman with book/bible in her lap embracing a small child on a battered plinth. Whilst the monument has been assessed as stable and fencing removed, the monument is listing markedly.	
	DESIGNATION:	Listed Building grade II		
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (A)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1385530	Contact: Tracy Chapman (LPA) 020 7525 2289	

#### PRIORITY CATEGORIES

© London Borough of Southwark

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Е

obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

Former cemetery lodge (1928-29) designed by Sir Aston

Webb. The building is vacant and its condition had been deteriorating. Works are now at an advanced stage to bring the building back into use by the Local Authority in

connection with cemetery management.

- CA LB
- I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2015	LONDON / SOUTHWARK
TERITAGE AT RISK 2015 /	LUNDON / SOUTHWARK

HERITAGE AT RISK 2015 / LONDO	on / <b>Southwark</b>		
	SITE NAME:	Monument to Rebekah Horniman, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1895 to Rebekah, wife of FS Horniman. Its prominent bronze tablet depicting a figure of an angel is missing, presumed stolen.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
ALL DETIRS	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1385533	Contact: Tracy Chapman (LPA) 020 7525 2289
	SITE NAME:	38, Glengall Road, Peckham SEI5	Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. The lonic entrance
	DESIGNATION:	Listed Building grade II, CA	porch is in poor condition. Discussions have been held regarding the repair of the building.
1 - HERE	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
el e The	PRIORITY CATEGORY:	C (C)	
ALL LAL TELEVICE	OWNER TYPE:	Private	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385563	Contact: Tracy Chapman (LPA) 020 7525 2289
	SITE NAME:	55, Great Suffolk Street SEI	Unaltered mid-C19 warehouse. The building is in a poor
The states	DESIGNATION:	Listed Building grade II	condition having been vacant for a number of years. Historic England and the Local Authority are in discussion with the owners regarding its future use and associated alterations.
	CONDITION:	Poor	
1 1 3 1 4 J	OCCUPANCY:	Vacant/not in use	
1	PRIORITY CATEGORY:	C (C)	
1 3 3 1 12	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	393 23	Contact: Tracy Chapman (LPA) 020 7525 2289
© Historic England			
	SITE NAME:	133, Kennington Park Road SELL	Late C18 terraced house. Planning Permission and Listed Building Consent were granted in May 2008 for conversi
	DESIGNATION:	Listed Building grade II, CA	to four flats, but not implemented. These consents have now expired and have not been renewed. The building is
	CONDITION:	Fair	partially occupied but no repairs have been undertaken and the building continues to decline.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1385634	Contact: Tracy Chapman (LPA) 020 7525 2289
	SITE NAME:	Nunhead Cemetery (All Saints) SE15	An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the cemetery skilfully exploits the undulating topography to
	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, CA	create picturesque effects and vistas. Vegetation and self- sown saplings are disrupting historic monuments and
A PART	CONDITION:	Generally unsatisfactory with major localised problems	obscuring the legibility of the landscape. The East Lodge is a building at risk, but plays a key role in the landscape due to its location at the main entrance to the cemetery. The
	VULNERABILITY:	High	Management Plan for the cemetery as a whole urgently needs updating.
	TREND:	Declining	needs updaung.
© Historic England	NEW ENTRY ?:	No	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1000824	Contact: Zosia Mellor 020 7973 3473

### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	East Lodge to Nunhead Cemetery, Linden Grove SEI5	One of a pair of gate lodges dating from 1840, by James Bunstone Bunning, adjacent to the main entrance gates.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	The lodge is in a ruinous condition, but stabilised. Histori England has advised the Local Authority on the necessary surveys required to consider options for the building's future, and is working with them and the Friends of Nunhead Cemetery to progress this as soon as possible.
A MARKE	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	runnead Cemetery to progress this as soon as possible.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1385647	Contact: Tracy Chapman (LPA) 020 7525 2289

No.	SITE NAME:	St Peter's Church Hall, 522.	Situated adjacent to St Peter's Church, the hall was
	LIST ENTRY NUMBER:	1385651	Contact: Tracy Chapman (LPA) 020 7525 2289
		,	
ic England	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	N/A	
	CONDITION:	Fair	monument due to ground subsidence nearby.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	praying figure carried on a tall column and plinth and an angel statue at its base. The railings around it are missing. There is concern over the structural stability of the
	SITE NAME:	Tomb of Maria Proom, Linden Grove, Nunhead Cemetery SEI5	Visually prominent monument from 1872 in pink and g granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure present

Lordship Lane, East Dulwich

Listed Building grade II, CA

SE22

Very bad

A (A)

1385671

Vacant/not in use

Religious organisation

Commercial company

F

1385740



© Historia

© London Borough of Southwark



Fire station (former), 306-312 (even), Old Kent Road SEI SITE NAME: DESIGNATION: Listed Building grade II CONDITION: Poor 

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



	OCCUPANCY:	Part occupied/part in use	advanced stage.		
	PRIORITY CATEGORY:	F (F)			
1	OWNER TYPE:	Commercial company			
	LIST ENTRY NUMBER:	1385738	Contact: Tracy Chapman (LPA) 020 7525 2289		
ſ	SITE NAME:	The Kentish Drovers public house, 720, Old Kent Road, Peckham SE15	Mid-C19 public house. The mural over painting has been removed. Enforcement is pending on unauthorised alterations to the building's fabric and the installation of		
	DESIGNATION:	Listed Building grade II	UPVC windows, and investigation continues into further breaches.		
	CONDITION:	Poor			
<b>H</b>	OCCUPANCY:	Part occupied/part in use			
-	PRIORITY CATEGORY:	C (C)			

Contact: Tracy Chapman (LPA) 020 7525 2289

constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is

suffering from structural movement and lack of

Contact: Tracy Chapman (LPA) 020 7525 2289

Fire station built between 1903-4 by the London County Council Architects Department. Red brick with Portland stone dressings. Shop fronts have been installed without

appropriate authorisation. Following provision of a grant from the Empty Homes Agency, works towards

conversion of the upper floors into residential units is at an

maintenance.

#### PRIORITY CATEGORIES

© London Borough of Southwark

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

D

Е

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
  - Unitary Authority World Heritage Site

	SITE NAME:	21 and 23, Park Street SE1	Pair of houses dating from circa 1820. Currently vacant and
	DESIGNATION:	Listed Building grade II, CA	suffering from significant structural problems. The northern flank wall to No. 23 is propped with scaffolding. Consents
	CONDITION:	Poor	have been granted for the conversion of the houses into two single dwellings and works are underway.
	OCCUPANCY:	Vacant/not in use	two single dwellings and works are underway.
	PRIORITY CATEGORY:	F (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1385752	Contact: Tracy Chapman (LPA) 020 7525 2289

© Historic England

GTENNUE 20 Devidence Little Course SELE One of a torrage of four bourses built	circa 1840 The		
	One of a terrace of four houses, built circa 1840. The		
DESIGNATION: Listed Building grade II building was damaged by fire in 2009 sold. Unauthorised works were carried	and subsequently ed out to mitigate fire		
CONDITION: Poor damage. No valid application has as y regularise these works.	et been received to		
OCCUPANCY: Occupied/in use			
PRIORITY CATEGORY: C (C)			
OWNER TYPE: Private			
LIST ENTRY NUMBER: 1385760 Contact: Tracy Chapman (LPA) 020	7525 2289		

© London Borough of Southwark

	SITE NAME:	112, Peckham Park Road, Peckham SE15	One of a group of four pairs of early C19 houses. Repairs have been carried out using unsuitable materials. There are
THE R.	DESIGNATION:	Listed Building grade II	currently no proposals for re-use.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385765	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Former Peckham Fire Station, 82, Peckham Road SE5	Former fire station built circa 1867 by Edward Cresy Junior which later became part of the Kennedy's sausage factory. The remainder of the factory has been demolished. The building has been vacant for some time and is in a poor state of repair, with water ingress and widespread rot.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
No. of the second s	PRIORITY CATEGORY:	C (C)	
E The Second	OWNER TYPE:	Educational (state sector)	
© London Borough of Southwark	LIST ENTRY NUMBER:	1392995	Contact: Tracy Chapman (LPA) 020 7525 2289



	SITE NAME:	40, Queens Road, Peckham SE15	Early C19 terraced building. The building is in poor condition and has suffered from extensive unauthorised	
	DESIGNATION:	Listed Building grade II	works.	
	CONDITION:	Poor		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
-	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1385796	Contact: Tracy Chapman (LPA) 020 7525 2289	

© London Borough of Southwark

### PRIORITY CATEGORIES

# Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Former Clare College Mission Church, Southwark Park SEI6	Former church. The Bermondsey Artists' Group was awarded a Big Lottery grant under the Community Assets
	DESIGNATION:	Listed Building grade II	Programme (2008) to refurbish the building as an art gallery space. Whilst Historic England and Southwark
	CONDITION:	Poor	Council have previously funded roof repairs, further repairs are required to the walls.
	OCCUPANCY:	Occupied/in use	
ALC: NO	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
England	LIST ENTRY NUMBER:	1385919	Contact: Tracy Chapman (LPA) 020 7525 2289

-	SITE NAME:	Number 1 and attached railings, 1, Stamford Street SE1	Mid-C19 red brick building that occupies a prominent position looking towards Blackfriars Bridge. The building is
	DESIGNATION:	Listed Building grade II	vacant and in a poor condition. Consents have been granted for conversion from offices to a hotel associated
	CONDITION:	Poor	with the adjacent Mad Hatter Hotel and works have begun.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Commercial company	
land	LIST ENTRY NUMBER:	1385933	Contact: Tracy Chapman (LPA) 020 7525 2289

Peckham Rye Station, Station

© Historic Engla

© Historic Er



SITE NAME:

OWNER TYPE:

LIST ENTRY NUMBER:

Private

1385937

© Historic England

DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Way, Peckham SE15 Listed Building grade II, CA Poor Part occupied/part in use D (D) Utility	Charles Henry Driver for the London, Brighton and South East Coast Railway. The northern wing has been refurbished and brought back into use. Discussions are ongoing to bring the vacant areas in the southern wing back into use. An application has been approved to refurbish parts of the south wing, but works have not yet started. Funding has been secured for restoration of the staircase from the Railway Heritage Trust, the Local Authority and Network Rail following local campaigns.
LIST ENTRY NUMBER:	1392389	Contact: Tracy Chapman (LPA) 020 7525 2289
SITE NAME:	5, Stoney Street SEI	Early C18 three storey house with a shop on the ground
DESIGNATION:	Listed Building grade II, CA	floor, formerly a potato warehouse. The upper floors are vacant and in a poor condition, with significant water
 CONDITION:	Poor	ingress, and unauthorised works have been carried out. The ground floor of the property is occupied but works
OCCUPANCY:	Part occupied/part in use	have not been carried out in line with planning consents
PRIORITY CATEGORY:	C (A)	granted in 2007. Applications have now been submitted by the leaseholder to regularise the works and carry out

© Historic England



Contact: Tracy Chapman (LPA) 020 7525 2289 Large mid-Victorian villa, possibly by Banks and Barry, SITE NAME: Beltwood House, 41, Sydenham Hill, Camberwell SE26 Dulwich College architects. The house was remodelled in the neoclassical style in circa 1895. The building contains DESIGNATION: Listed Building grade II, CA fine interiors, but is currently vacant and suffering from the effects of water ingress. The curtilage buildings (stables, CONDITION: Fair lodge, two cottages and animal store) are in a poor state of OCCUPANCY: repair. A planning application for conversion to flats and Part occupied/part in use houses has been refused. PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1385958 Contact: Tracy Chapman (LPA) 020 7525 2289

© London Borough of Southwark

D

Е

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

The station is an H-shaped building, built in 1864-65 by

further alterations to the commercial unit. The Local

bringing the upper floors back in to use.


Authority is in discussion with the freeholder regarding

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ŬA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Drinking fountain, Tanner Street Park, Bermondsey SEI	Originally a turret and the capping to the tower of the former Church of St Olave, Tooley Street. 1738-9, re-sited
	DESIGNATION:	Listed Building grade II, CA	in 1929. Now a defunct drinking fountain and in poor condition. A condition survey has been carried out, funded
	CONDITION:	Poor	by Historic England, with a view to works being carried out as part of a new landscaping scheme for the park. The
	OCCUPANCY:	N/A	Local Authority will be funding and commissioning works
	PRIORITY CATEGORY:	D (C)	based on this survey.
	OWNER TYPE:	Local authority	
storic England	LIST ENTRY NUMBER:	1385959	Contact: Tracy Chapman (LPA) 020 7525 2289
	SITE NAME:	62 and 64, Union Street SEI	Pair of terraced houses built circa 1835. Network Rail has
	DESIGNATION:	Listed Building grade II, CA	carried out works to make the properties weatherproof and structurally secure. Planning Permission has now been

1 W 11	DESIGNATION:	Listed Building grade II, CA	and structurally secure. Planning Permission has now been
•- MLE *	CONDITION:	Fair	granted for restoration and conversion for restaurant use and works have begun.
00	OCCUPANCY:	Vacant/not in use	
in the	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1386010	Contact: Tracy Chapman (LPA) 020 7525 2289

© Hist



ANE OF SUD	SITE NAME:	Kennedys sausages shop, 305, Walworth Road, Walworth SE17	Former Kennedy sausages shop, circa 1923. A well- preserved example of a 1920s shop. Considerable works have been undertaken to bring the shop back into use and
	DESIGNATION:	Listed Building grade II	it is now open as a restaurant. Further repairs are needed, particularly to architectural details.
	CONDITION:	Fair	,
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Commercial company	
storic England	LIST ENTRY NUMBER:	1392595	Contact: Tracy Chapman (LPA) 020 7525 2289



		1572575	
	SITE NAME:	Former office to Denmark Hill Station, Windsor Walk SE5	The former office to Denmark Hill Station dates from 1864-66. Consent was granted in 2007 for refurbishment
In a second	DESIGNATION:	Listed Building grade II, CA	but not implemented. The building is in a poor condition following a fire.
The other designation of the local division	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1386053	Contact: Tracy Chapman (LPA) 020 7525 2289

© Historic England

© Hist

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site
- 113

	SITE NAME:	Celestial Church of Christ and attached wall and railings, Glengall Road, Camberwell SEI5	Designed by E Bassett Keeling, built in 1865. The spire removed c1950. Formerly known as St Andrew's. Mai clay tiled pitched roofs and Kentish ragstone walling w limestone dressings and red sandstone banding. A grau from the Heritage Lottery Fund and Historic England awarded in 2012 to carry out masonry and roofing rep and to overhaul rainwater goods. Works are due to complete in summer 2015. Further repairs are require the west end of the church.	
the second	DESIGNATION:	Listed Place of Worship grade II		
	CONDITION:	Poor		
	PRIORITY CATEGORY:	F (D)		
	OWNER TYPE:	Religious organisation		
© Historic England	LIST ENTRY NUMBER:	1385564	Contact: Ian Har	per 020 7973 3786
	SITE NAME:	Church of St Augustine, Honor Oak Park, Camberwell, Southwark SE23	Constructed between 1872-73 by William Oakley in Kentish ragstone with ashlar details and slate roof. Hig level fabric and some structural defects have been remedied, and some roofs and masonry repaired. The latest phase of stonework and tower re-roofing, grant- aided by the Heritage Lottery Fund and Historic Englar was completed in 2014. Monitoring of the structure continues and may require a further phase of works.	
	DESIGNATION:	Listed Place of Worship grade II		
	CONDITION:	Fair		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1385617	Contact: Ian Harper 020 7973 3786	
© Historic England				
SITE NAME:	Roman boat at N	lew Guy's House, Bermondsey SEI		
	Scheduled Monur	nent	LIST ENTRY NUMBER:	1001979
DESIGNATION:	Scheduled Fiolidi	nent		
DESIGNATION: CONDITION:		tory but with significant localised	TREND:	Unknown

SITE NAME:	The Rose Theatre, Rose Court, Southwark SEI		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012707
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Nunhead Cemetery, Nunhead SE15		
SITE NAME: DESIGNATION:	Nunhead Cemetery, Nunhead SE15 Conservation Area, 13 LBs, RPG grade II*	NEW ENTRY?:	No
	1.	NEW ENTRY?: TREND:	No Deteriorating

CONTACT:

# SUTTON

© Historic England

OWNER TYPE:



D

Е

SITE NAME:	Boundary walls to Beddington Place along east side of churchyard and along Church Lane, Church Road
DESIGNATION:	Listed Building grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1357592

Substantial length of C16 or C17 wall of red brick with battered coping and roll moulding, with dentil course and plinth. Sections have been buttressed. The brickwork is in need of substantial repairs, including extensive repointing and in some areas replacement of brickwork and repair of buttresses. Tree growth threatens stability and vegetation is causing further damage to the coping. A structural engineer's report has been produced and the wall has been temporarily fenced off pending decisions on its future repair.

Elizabeth Whitbourn 07889 808145

Contact: Dean James (LPA) 0208 770 5000

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Health authority

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
  - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

114

#### HERITAGE AT RISK 2015 / LONDON / SUTTON / TOWER HAMLETS

	SITE NAME:	Churchyard walls, Church Road	Circa C19 walls of dressed flint with rounded tops, with
	DESIGNATION:	Listed Building grade II, CA	pilasters and brick quoins at intervals. Vegetation and mechanical damage has caused some sections to collapse,
	CONDITION:	Very bad	and mortar failure has led to the loss of flints from some sections. Extensive repair is now required.
	OCCUPANCY:	N/A	sections. Extensive repair is now required.
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065671	Contact: Dean James (LPA) 0208 770 5000

© Historic England

© Hist

	SITE NAME:	Garden walls at Beddington Place (Carew Manor Special School) to north of Orangery walls, Church Road	C17 to C18 garden walls. The east, south and part of the north walls to the east of Beddington Park Cottages are of brick with battered coping; the west wall is of a later date with plain capping. Damage has been largely caused by
Lindler VY	DESIGNATION:	Listed Building grade II, CA	vegetation, and upper brick courses have been completely dislodged in some sections. The brickwork is in need of
J. Dr	CONDITION:	Very bad	substantial repairs, including extensive repointing and rebuilding of upper sections.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (New entry)	
storic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1200792	Contact: Dean James (LPA) 0208 770 5000

Orangery wall to Beddington Place, Church Road, Beddington

Listed Building grade II, CA

Poor

N/A



© Historic England



1	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1065673	Contact: Dean James (LPA) 0208 770 5000	
	SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton	Early C18 grotto in Carshalton Park. The exterior of t grotto has symmetrical curved walls of brick, ramped	
	DESIGNATION:	Listed Building grade II, CA	gradually to a central peak. The grotto is extremely vulnerable to vandalism and graffiti.	
	CONDITION:	Poor	-	
17	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1065628	Contact: Dean James (LPA) 0208 770 5000	

to secure repairs.

© Historic England

# TOWER HAMLETS

	SITE NAME:	24, Bazely Street E14	Early C19 stock brick terraced house, three storeys with
	DESIGNATION:	Listed Building grade II, CA	basement and mansard roof. The terrace faces Montague Place with the side elevation facing Bazely Street. The
	CONDITION:	Fair	entrance door and porch are on the side elevation. The building is empty and boarded up.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1357833	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

Orangery wall of circa 1720. Previously subject to severe

Authority has completed a restoration strategy document. Historic England and the Local Authority are in discussion

vandalism. The soft brickwork is subject to erosion and there is invasive plant and shrub growth. The Local


- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Front wall, gate piers and gates at St Clements Hospital, Bow Road, Bow E3	Decorative gates and railings forming the front boundar the redundant St Clements Hospital. The freehold has been transferred to the Greater London Authority.
Pront and	DESIGNATION:	Listed Building grade II, CA	Planning Permission and Listed Building Consent have been granted for the conversion of the former hospital to
	CONDITION:	Poor	housing, and works have started on site.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (D)	
9 Historic England	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1065276	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	St Clements Hospital, Bow Road, Bow E3	Redundant hospital, formerly City of London infirmary. Impressive Italianate main block fronting Bow Road. The
	DESIGNATION:	Listed Building grade II, CA	freehold has been transferred to the Greater London Authority. Planning Permission and Listed Building Consent
	CONDITION:	Poor	have been granted for the conversion of the former hospital to housing, and works have started on site.
	OCCUPANCY:	Vacant/not in use	hospital to housing, and works have started on site.
	PRIORITY CATEGORY:	F (D)	


C



© Historic England



FIF	SITE NAME:	Gentlemen's public convenience, Bow Road, Bromley-By-Bow E3	Underground gentlemen's public convenience, constructed by the Board of Works and opened in 1899. Curved entrance steps designed to fit around the statue of WE
	DESIGNATION:	Listed Building grade II, CA	Gladstone. The decorative interior finish includes russet marble urinals. The public convenience has been disused
	CONDITION:	Very bad	for many years and the decorative iron gates have been damaged. The interior is also subject to vandalism. The Local Authority is aiming to work with strategic partners to
	OCCUPANCY:	Vacant/not in use	
terris in the second in the second	PRIORITY CATEGORY:	A (A)	find a way forward.
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1392968	Contact: Andrew Hargreaves (LPA) 020 7364 5576



# PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK	2015 / LONDON	/ TOWER HAMLETS

	SITE NAME:	How Memorial Gateway, Bromley High Street E3	Gabled stone Gothic arch with double buttresses at each side, circa 1893. Formerly an entrance to St Mary's
	DESIGNATION:	Listed Building grade II	Churchyard. The gateway is suffering from stonework decay. The Local Authority is considering options for
	CONDITION:	Poor	repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065281	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	Limehouse Commerci E14
	DESIGNATION:	Listed Build
	CONDITION:	Fair
	OCCUPANCY:	Vacant/no
	PRIORITY CATEGORY:	D (D)
	OWNER TYPE:	Private

© Historic England

© Historic England

	SITE NAME:	Limehouse District Library, Commercial Road, Limehouse E14	Former Passmore Edwards Library. Built in 1900 by Messrs Clarkson Architects. The library is closed and the building vacant and boarded up. Planning Permission and Listed
iii †	DESIGNATION:	Listed Building grade II, CA	Building Consent have been granted to convert the building to student accommodation with associated educational and
	CONDITION:	Fair	ancillary facilities, subject to a Section 106 agreement and detailed conditions.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357807	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	689, Commercial Road, Limehouse E14	Early C19 terraced house, three storeys and basement. The building was severely damaged by fire in 2012.
	DESIGNATION:	Listed Building grade II, CA	Temporary propping and protection has been erected. Planning Permission and Listed Building Consent have been
	CONDITION:	Very bad	granted for works to convert the building into flats. Material has been submitted to the Local Authority to
	OCCUPANCY:	Vacant/not in use	discharge detailed conditions, with the intention of starting
	PRIORITY CATEGORY:	B (A)	works soon.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357810	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME: Former Caird & Rayner L Warehouse, 777-783, Commercial Road E14		Former sail makers and ship chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. The building was fire damaged, resulting in the
AN	DESIGNATION:	Listed Building grade II, CA	loss of its roof covering. Urgent works were completed in April 2010. Recently much of the vegetation inside the
TILL STAT MARKET	CONDITION:	Very bad	building and on the front elevation has been removed to prevent further damage. A Section 215 Notice has been served and advertisement hoardings have been removed from the building. The Local Authority is continuing to pursue enforcement action and discussions regarding the
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	re-use of the building are ongoing.
© Historic England	LIST ENTRY NUMBER:	1385372	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	Poplar Baths, East India Dock Road E14	Former public baths, with slipper and vapour baths. Built 1932-4 for Poplar Borough Council to the designs of
	DESIGNATION:	Listed Building grade II	Harley Heckford, Borough Engineer, and RW Stanton, Chief Assistant. Planning Permission and Listed Building Consent have been granted for works associated with the re-use of the building as a leisure centre and swimming pool and works are underway, scheduled for completion in 2016.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1334939	Contact: Andrew Hargreaves (LPA) 020 7364 5576

# PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2015 / LONDO	ON / TOWER HAMLETS	5	
AT T	SITE NAME:	Wiltons Music Hall, Graces Alley El	Former music hall with fine ornamental interior built in 1858. The building is leased to an opera company and is
Sta P	DESIGNATION:	Listed Building grade II*, CA	now in regular use. The interior and exterior restoration of the auditorium is now complete. The final stages of
	CONDITION:	Good	restoration work, implementing Stage 2 of a Heritage Lottery Fund grant, are nearing completion in anticipation
	OCCUPANCY:	Occupied/in use	of a public launch in September 2015.
	PRIORITY CATEGORY:	F (F)	
95-1	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1065173	Contact: Elizabeth Whitbourn 07889 808145
hier	SITE NAME:	Drinking fountain (on pavement outside 31-74 Mile End Road), Mile End Road, Stepney E1	Late C19 polished granite drinking fountain, with a short column on a plinth. The drinking fountain has an inscription commemorating its erection by the Metropolitan Cattle
	DESIGNATION:	Listed Building grade II, CA	Trough and Drinking Fountain Association. The bowl has been removed. The Local Authority is investigating the
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CONDITION:	Very bad	reinstatement of missing elements.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (D)	
Literation Fundamente	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1065113	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	St Saviours Church, Northumbria Street, Poplar E14	Former church dating from 1873-4 to the design of Frederick J and Horace Francis. The building was severely
Non another and	DESIGNATION:	Listed Building grade II	damaged by fire in May 2007 and is currently propped by scaffolding. Following detailed negotiations, Planning
	CONDITION:	Very bad	Permission and Listed Building Consent have been granted for residential conversion.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY: OWNER TYPE:	B (A)	
		Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1242275	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	19, Princelet Street, Spitalfields El	Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. The building
	DESIGNATION:	Listed Building grade II*, CA	combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and a rare surviving
	CONDITION:	Poor	small synagogue. Listed Building Consent has been granted
	OCCUPANCY:	Part occupied/part in use	for roof repairs.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Charity (heritage)	
© Historic England	LIST ENTRY NUMBER:	1260421	Contact: Elizabeth Whitbourn 07889 808145
			Monument to prove the start have 1725 to M/illing
	SITE NAME:	113, Redchurch Street, Tower Hamlets E2	Weavers' tenement house, built circa 1735 by William Farmer, a local builder. The building is of interest as a rare and early survival of a building type that once dominated
	DESIGNATION:	Listed Building grade II, CA	Spitalfields. The building is derelict and has structural
	CONDITION:	Very bad	problems. The facade is braced to prevent further movement. Planning Permission and Listed Building
	OCCUPANCY:	Vacant/not in use	Consent have been granted, but works have yet to start.
Estate Agents Ltd.	PRIORITY CATEGORY:	B (B)	The Local Planning Authority is now considering enforcement action.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1393497	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

She -	SITE NAME:	Tomb of Joseph Westwood, Southern Grove, Tower	One of the most prominent monuments within the cemetery given its design and location, this stone cross
	DESIGNATION:	Hamlets Cemetery E3	dates from circa 1883. It is in poor condition due to genera decay and the loss of parts of its low railings, tiles, finials
		Listed Building grade II, CA	and other detailing. The Local Authority is working with the Friends Group to consider options for funding the
	CONDITION:	Poor	necessary repairs.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© Historic England	OWNER TYPE:	Local authority	
C C	LIST ENTRY NUMBER:	1378758	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	St Pauls Mission Room and Infant Nursery, Wellclose Square EI	Gothic style structure built in 1874 to designs by Reuben Greatorex. The building is of stock brick with a red brick eaves cornice and red and blue brick bands. It has stone
	DESIGNATION:	Listed Building grade II, CA	dressings to the doors and windows, a steeply pitched tiled roof with cresting, and a stone banded chimney. The
	CONDITION:	Poor	building is empty and boarded up.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1242432	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Braithwaite Viaduct, Bishopsgate Goods Yard, Wheler Street / Brick Lane EI	Early railway viaduct built in 1840 by John Braithwaite for the Eastern Counties Railway, formerly set within extensive brick vaulted goods yard circa 1880, demolished in 2003.
	DESIGNATION:	Listed Building grade II	Planning and Listed Building Consent applications have been submitted as part of a wider scheme relating to the
	CONDITION:	Poor	Goods Yard site.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
© Historic England	LIST ENTRY NUMBER:	1063895	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road EI	Drinking fountain with pink marble basin and plaque set in a Norman style arch. Erected in 1860 but moved to its present position in 1879. The Local Authority has cleaned
	DESIGNATION:	Listed Building grade II, CA	the fountain, but repairs are outstanding. The Local Authority and Historic England are working towards a
	CONDITION:	Poor	repair scheme.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Local authority	
© Historic England	LIST ENTRY NUMBER:	1357512	Contact: Andrew Hargreaves (LPA) 020 7364 5576
19	SITE NAME:	Royal London Hospital - front block, Whitechapel Road, Whitechapel El	Fine C18 yellow brick hospital building fronting Whitechapel Road. The building, which became redundant following development of new facilities to the rear, has
THEFT	DESIGNATION:	Listed Building grade II, CA	been purchased by Tower Hamlets Council. Plans to convert the building into a Civic Centre are progressing, as
	CONDITION:	Fair	part of the new masterplan for Whitechapel. Planning and
			Listed Building Consent applications will be submitted in due course.
	OCCUPANCY:	Vacant/not in use	
59999	OCCUPANCY: PRIORITY CATEGORY:	Vacant/not in use D (E)	

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
   C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / TOWER HAMLETS

	SITE NAME:	2, Wilkes Street EI	Early C18 terraced house. Three storeys with basement
	DESIGNATION:	Listed Building grade II, CA	and attic in painted brick. Some repair works have been undertaken. The Local Authority is considering
	CONDITION:	Poor	enforcement action.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1242278	Contact: Andrew Hargreaves (LPA) 020 7364 5576
1.4.1.			

© Historic England Archive

H

	SITE NAME:	Church of St Mary Stratford Bow, Bow Road, Poplar E3	St Mary's Bow is shrouded by trees on a traffic island on the AII. The tower and chancel were built circa 1490 onto
	DESIGNATION:	Listed Place of Worship grade II*, CA	an early C14 nave. The south aisle was rebuilt in 1794, th upper tower in 1829 and restorations completed in 1848 and 1898-9. The upper tower was rebuilt and railings restored in the 1950s following World War II damage. T church suffers from extensive dampness, stone decay and
	CONDITION:	Very bad	
	PRIORITY CATEGORY:	A (New entry)	leaking roofs. The congregation is currently exploring
	OWNER TYPE:	Religious organisation	options for funding and repairs are due to start in 2016.
and a second second	LIST ENTRY NUMBER:	1065273	Contact: Ian Harper 020 7973 3786

© Historic England

A Carlor	SITE NAME:	St Paul's Church, Burdett Road, Stepney E3	Designed by architect Robert Maguire, the church was consecrated on the 30th April 1960. The church is based
	DESIGNATION:	Listed Place of Worship grade II*	on a rectangular plan centred around the altar, with projections to the north west and south east for the porch
	CONDITION:	Very bad	and the baptistery. The nave was closed in 2013 due to a fall of ceiling panels. The church has been awarded a grant
	PRIORITY CATEGORY:	B (A)	from the Heritage Lottery Fund and repairs are expected
	OWNER TYPE:	Religious organisation	to start in late summer 2015.
	LIST ENTRY NUMBER:	24 88	Contact: Ian Harper 020 7973 3786

© Historic England

	SITE NAME:	St Mary's Church, Cable Street, Stepney El	This church was designed by Frederick and Horace Francis and completed c1850. It was reordered internally in 1986.
	DESIGNATION:	Listed Place of Worship grade II	The church has slate roofing, Kentish ragstone walling with Bath stone dressings. A grant from the Heritage Lottery
	CONDITION:	Poor	Fund and Historic England was awarded in 2013 for masonry repairs to the tower. Works are expected to st
	PRIORITY CATEGORY:	D (D)	in July 2015.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1096892	Contact: Ian Harper 020 7973 3786

© Historic England



0	SITE NAME:	Church of St John on Bethnal Green, Cambridge Heath Road,	Parish church of 1824 by Sir John Soane. Heavily restored and extended in the C19 by William Munday and GF
			Bodley. Stock brick with artificial stone dressings and
	DESIGNATION:	Listed Place of Worship grade I, CA	western portico. The third phase of a programme of repairs to high level stonework was funded by Historic England and the Heritage Lottery Fund, and completed in
	CONDITION:	Fair	2014. Another phase of repairs is anticipated to the church steps and the interior of the narthex.
	PRIORITY CATEGORY:	C (F)	steps and the interior of the hardness.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065245	Contact: Ian Harper 020 7973 3786

© Historic England

PRIORITY CATEGORIES	

D Е

# А

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / TOWER HAMLETS

	SITE NAME:	Calvary Charismatic Baptist Church (former Trinity Methodist Church), including attached hall and church rooms, East India Dock Road, Poplar E14	Church built in the 1950s as part of the live architectural exhibition of the 1951 Festival of Britain by Cecil Handisyde and D Rogers Stark. The roofs to the church and chancel continue to leak causing damage to the fabric and finishes. Spalling of the external concrete structure is exposing reinforcement which requires repair. The new
	DESIGNATION:	Listed Place of Worship grade II, CA	congregation has been awarded a grant from Historic England for the most urgent of the repairs and technical investigations are underway. Phase I works are due to
	CONDITION:	Poor	complete in 2016.
© Historic England	PRIORITY CATEGORY:	D (C)	
-	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1376625	Contact: Ian Harper 020 7973 3786
	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	Church constructed of London stock brick with stone dressings, designed by G Austin and built 1836-9. Repairs to the roofs and stonework have been undertaken, however the interior is now closed due to the continuing fall of ceiling plasters. The congregation is actively exploring options for funding.
	DESIGNATION:	Listed Place of Worship grade II, CA	
	CONDITION:	Very bad	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Historic England Archive	LIST ENTRY NUMBER:	1065118	Contact: Ian Harper 020 7973 3786
and the second s	SITE NAME:	Sandy's Row Synagogue, Sandys Row, Bethnal Green El	Former Huguenot chapel which was altered in the mid C19 as a synagogue. Slate roof and stock brick walling with red
	DESIGNATION:	Listed Place of Worship grade II, CA	brick dressings. Major re-roofing and high level brick repairs were completed in 2011 with funding from the Heritage Lottery Fund and Historic England. Whilst works
	CONDITION:	Fair	were underway bowing of the narrow brick piers on the

	DESIGNATION:	CA	repairs were completed in 2011 with funding from the Heritage Lottery Fund and Historic England. Whilst work
	CONDITION:	Fair	were underway bowing of the narrow brick piers on the front elevation was discovered. Emergency works were
	PRIORITY CATEGORY:	C (C)	carried out to temporarily restrain the piers until
	OWNER TYPE:	Religious organisation	permanent repair and funding can be resolved.
	LIST ENTRY NUMBER:	1260323	Contact: Tracey Craig 020 7973 3756

© Historic England

SITE NAME:	Priory and Hospital of St Mary Spital, Steward St	treet El	
DESIGNATION:	Scheduled Monument, 11 LBs, part in CA	LIST ENTRY NUMBER:	1001982
CONDITION:	Generally unsatisfactory with major localised problems		Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	WNER TYPE: Commercial company, multiple owners		Elizabeth Whitbourn 07889 808145
SITE NAME:	London Hospital, Stepney El		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	DITION: Very bad		No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Anne's Church EI4		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

#### PRIORITY CATEGORIES

#### Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

#### HERITAGE AT RISK 2015 / LONDON / TOWER HAMLETS / WALTHAM FOREST

SITE NAME:	Tower Hamlets Cemetery, Bow E3		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wentworth Street, Bethnal Green El		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Whitechapel High Street, Aldgate El		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

# WALTHAM FOREST

	SITE NAME:	Wall to south east of St Mary's Churchyard, Church End E17	C18 walls, formerly belonging to a house, now demolished, on the adjacent site. In need of repair.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A STATE	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357602	Contact: Jacinta Fisher (LPA) 020 8496 6737

	SITE NAME:	Walnut Tree House, 500, High Road E10	Mid C16 timber-framed property formerly used as the Conservative Club, but currently vacant. Unauthorised and
	DESIGNATION:	Listed Building grade II*	unsympathetic changes have been made to the property, including the removal of original floorboards and the
	CONDITION:	Fair	installation of modern skirting/architraves. Enforcement action has been initiated. Listed Building Consent and
	OCCUPANCY:	Part occupied/part in use	Planning Permission have been granted subject to
	PRIORITY CATEGORY:	F (E)	conditions. The conditions are yet to be discharged.
	OWNER TYPE:	Other not for profit group	
d	LIST ENTRY NUMBER:	1065586	Contact: Verena McCaig 020 7973 3718

© Historic England

© Historic England



LIST ENTRY NUMBER:	1065586	Contact: Verena McCaig 020 7973 3718
SITE NAME:	698a, High Road Leytonstone, Leytonstone EI I	One of a surviving terrace of three Georgian houses, probably late C18, for many years the home of the local
DESIGNATION:	Listed Building grade II	British Legion branch. The owner is in discussion with the Local Authority regarding revised plans for its conversion.
CONDITION:	Very bad	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (D)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1357632	Contact: Jacinta Fisher (LPA) 020 8496 6737

© London Borough of Waltham Forest

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / WALTHAM FOREST

	SITE NAME:	Granada Cinema, 186, Hoe Street, Walthamstow E17	Built 1929-30 as the Granada Cinema to the design of Cecil Masey with fine Art Deco and Moorish style interiors by
	DESIGNATION:	Listed Building grade II*	Theodore Komisarjevsky. Discussions are ongoing between the Local Authority, Historic England and the
	CONDITION:	Poor	owners regarding plans for its future re-use.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065590	Contact: Verena McCaig 020 7973 3718
the second se			

© Historic England


© Historic England


© Historic England



CI6/CI7 timber-framed dovecote, the last surviving SITE NAME: Pimp Hall dovecote, King's Road, Chingford E4 structure from the historic Chingford Manor of Gowers and Buckerells. The building is in a very poor condition as a DESIGNATION: Listed Building grade II result of the deteriorating timber frame and repeated vandalism. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1065591 Contact: Jacinta Fisher (LPA) 020 8496 6737

Closed chapel to hospital (formerly a workhouse), 1840. SITE NAME: Chapel to south of main Roof tiles have slipped and the building is not wind and hospital block, Langthorne Road weathertight. ELL DESIGNATION: Listed Building grade II CONDITION Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Health authority LIST ENTRY NUMBER: 1357634 Contact: Jacinta Fisher (LPA) 020 8496 6737





© London Borough of Waltham Forest

D

Е

Contact: Jacinta Fisher (LPA) 020 8496 6737

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

#### HERITAGE AT RISK 2015 / LONDON / WALTHAM FOREST



© London Borough of Waltham Fore

	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Listed Building Consent for residential use were granted in 2007
	DESIGNATION:	Listed Building grade II	and subsequently renewed, subject to a Section 106 agreement. Enforcement action for unauthorised works is
	CONDITION:	Very bad	ongoing.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
1.1	OWNER TYPE:	Commercial company	
rest	LIST ENTRY NUMBER:	1065574	Contact: Jacinta Fisher (LPA) 020 8496 6737


	SITE NAME:	133, Whipps Cross Road, Leytonstone EI I	One of six survivors from an original terrace of 12 'middle- class' three storey houses called Assembly Row. Built in
	DESIGNATION:	Listed Building grade II, CA	1767 on the high ground at the edge of the forest land and within Leytonstone Conservation Area. The building is now
	CONDITION:	Poor	vacant and deteriorating.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ough of Waltham Forest	LIST ENTRY NUMBER:	35762	Contact: Jacinta Fisher (LPA) 020 8496 6737



	h ragstone
SITE NAME: Church of St Saviour, Markhouse Road, Walthamstow EI7 Church built in 1874 of squared coursed Kentis to the design of TF Dolman, with a 1980s inter enclosure at the west end composed of glass s	nal creens and
DESIGNATION: Listed Place of Worship grade II after war damage in 1945 to a lower pitch and	finished in
CONDITION: Poor slates. The gutters, rainwater pipes and drainage need of repair. The leaking gutters have caused	es and drainage are in
PRIORITY CATEGORY: C (C) staining to the internal walls of the nave and the	e aisles.
OWNER TYPE: Religious organisation	
LIST ENTRY NUMBER: 1065595 Contact: Ian Harper 020 7973 3786	

© Historic England

© London Borc



© Historic England



Church of St Margaret of A late C19 basilica style church by architect JT Newman SITE NAME: commenced in 1892, replacing an earlier iron mission Antioch and attached railings, Woodhouse Road, Leyton El I church. The Lady Chapel was added in 1910. There are fine decorations and wall paintings internally. The church DESIGNATION: Listed Place of Worship grade II has completed projects to repair most of the roofs. Further repair is needed to the north transept and aisle roofs, CONDITION: Poor rainwater goods and drainage. The railings around the PRIORITY CATEGORY: C (C) church are contemporary and also in need of repair. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1390581 Contact: lan Harper 020 7973 3786

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

WHS

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
  - Unitary Authority World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / WANDSWORTH

#### WANDSWORTH

SITE NAME:	Battersea Park Station, Battersea Park Road SW8	Italianate style railway station built circa 1865 for the London, Brighton and South Coast Railway. Repair works
DESIGNATION:	Listed Building grade II, CA	are now complete. Alterations to the train service mean that the historically and architecturally significant platform I
 CONDITION:	Fair	is now redundant. Following a study carried out in 2014 Network Rail is now considering options in conjunction
OCCUPANCY:	Part occupied/part in use	with improvements to the station to deal with the
PRIORITY CATEGORY:	E (E)	additional passenger flows resulting from the Nine Elms regeneration.
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1357652	Contact: Barry Sellers (LPA) 020 8871 7564



	SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII	Church School of 1866-67 designed by Benjamin Ferrey. The building is currently vacant. A report on the structural
	DESIGNATION:	Listed Building grade II, CA	condition, commissioned by the owners, found the building wind and weathertight. Initial proposals for demolition
	CONDITION:	Poor	were discussed in 2012. Further discussions were held in February 2015 concerning the re-use, extension, alteration
	OCCUPANCY:	Vacant/not in use	and repair of the building. Applications are anticipated in
	PRIORITY CATEGORY:	A (A)	2015.
	OWNER TYPE:	Religious organisation	
th	LIST ENTRY NUMBER:	1389136	Contact: Barry Sellers (LPA) 020 8871 7564



SITE NAME

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

use)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© London Borough of Wandswort

© Historic England



stable condition. It is linked with the Springfield Hospital SW17 redevelopment and funding is due to be secured through a DESIGNATION: Listed Building grade II Section 106 agreement. Discussions with the owners about a strategy for use and repair are ongoing. CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C) OWNER TYPE: Educational (state sector) LIST ENTRY NUMBER: 1065554 Contact: Barry Sellers (LPA) 020 8871 7564 SITE NAME: Battersea Power Station, Power station built from 1932 onwards, closed and Cringle Street SW8 vacated in 1983. Planning and Listed Building Consent applications were approved in 2011, subject to a legal DESIGNATION: Listed Building grade II\* agreement, for restoration, extension and conversion to provide mixed use facilities. Works have commenced and

Ice house in the grounds of Burntwood Secondary School,

Beechcroft Road, Tooting

Very bad

1357620

F (F)

Vacant/not in use

Commercial company

© Historic England



SITE NAME:	Springfield Hospital (main building), Glenburnie Road SW17	Former p style as th Listed Bui and demo appeal in approved	
DESIGNATION:	Listed Building grade II, RPG grade II		
CONDITION:	Poor	the submi historic pa	
OCCUPANCY:	Part occupied/part in use	the park a	
PRIORITY CATEGORY:	D (D)		
OWNER TYPE:	Health authority		
LIST ENTRY NUMBER:	1065553	Contact:	

osychiatric hospital built in 1840 in Tudor Gothic he Surrey County Asylum. Planning Permission and uilding Consent for the redevelopment of the site olition of curtilage listed buildings were granted on 2012. Phase I of the re-development has been d, subject to a variation in the legal agreement for nission of a strategy for the listed buildings and park and garden. Discussions on the strategy for and garden have commenced.

the rebuilding of the chimneys is due for completion

towards the end of 2016. Ongoing discussion's about

repairs are being dealt with through a Conservation

Contact: Elizabeth Whitbourn 07889 808145

Circular domical ice house in brown and yellow brick

covered by an earth mound with retaining walls to the

approach. Probably C18. The ice house is in a poor but

Barry Sellers (LPA) 020 8871 7564

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Steering Group.

ABBREVIATIONS
---------------


- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site ŴĤS

#### HERITAGE AT RISK 2015 / LONDON / WANDSWORTH



SITE NAME:	Paggen table tomb, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb dating from 1769. One of five table tombs. The strategy for its conservation and repair is being discussed with the Local Authority and Historic England.
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1065536	Contact: Trisha Jean-Marie (LPA) 020 8871 6612

SITE NAME: Table tomb to Errington Ward, Stone faced table tomb, dating from 1720, with a deep moulded plinth. One of five table tombs. The strategy for Huguenot Place, Huguenot Burial Ground SW18 its conservation and repair is being discussed with the Local Authority and Historic England. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown © Historic England LIST ENTRY NUMBER: 1184219 Contact: Trisha Jean-Marie (LPA) 020 8871 6612



	SITE NAME:	Table tomb to Samuel John, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb, dating from the early to mid C18, with a deep moulded plinth. One of five table tombs. The strategy for its conservation and repair is being discussed
	DESIGNATION:	Listed Building grade II, CA	with the Local Authority and Historic England.
2	CONDITION:	Poor	
and the first	OCCUPANCY:	N/A	
And And	PRIORITY CATEGORY:	A (A)	
and the second	OWNER TYPE:	Unknown	
© Historic England	LIST ENTRY NUMBER:	1357644	Contact: Trisha Jean-Marie (LPA) 020 8871 6612



©

	SITE NAME:	Tomb of Cotterell and Allen, Huguenot Place, Huguenot Burial Ground SW18	Table tomb from 1843. The moulded top slab is cracked in the middle and vegetation is growing through it. One of five table tombs. The strategy for its conservation and repair is being discussed with the Local Authority and Historic England.
	DESIGNATION:	Listed Building grade II, CA	
R	CONDITION:	Poor	-
	OCCUPANCY:	N/A	
14	PRIORITY CATEGORY:	A (A)	
- 10 - S	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1184206	Contact: Trisha Jean-Marie (LPA) 020 8871 6612

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

#### HERITAGE AT RISK 2015 / LONDON / WANDSWORTH

auntagut gruns	SITE NAME:	The Montague Arms, 3, Medfield Street, Roehampton Village SW15	C17 house converted into a public house in the 1860s. Applications for change of use from a public house to retail or office uses at ground floor level with residential above
	DESIGNATION:	Listed Building grade II, CA	were approved in June 2010. Works to the flats are complete and they are occupied. Discussions were held in
e Arms rational files Chaffer and	CONDITION:	Fair	2015 with a prospective tenant for the ground floor commercial use.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
London Borough of Wandsworth	LIST ENTRY NUMBER:	1184425	Contact: Barry Sellers (LPA) 020 8871 7564

Former White Lion, 14-16,

Putney High Street SW15

Listed Building grade II, CA

Poor

1389413

	SITE NAME:	Temple in the grounds of Mount Clare, Minstead Gardens SW15
	DESIGNATION:	Listed Building grade II*, CA
	CONDITION:	Poor
	OCCUPANCY:	N/A
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Educational (state sector)
Dondon Borough of Wandsworth	LIST ENTRY NUMBER:	1065545

SITE NAME:

DESIGNATION:

CONDITION:

LIST ENTRY NUMBER:

© Lo

9

© London Borough of Wandsworth



	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	A (New entry)			
	OWNER TYPE:	Commercial company			
	LIST ENTRY NUMBER:	1184658	Contact: Barry Sellers (LPA) 020 8871 7564		
	SITE NAME:	Queenstown Road Station, Queenstown Road SW8	Station built in 1877. Repairs are needed to the doors, windows and floors of the disused areas of this unattended		
	DESIGNATION:	Listed Building grade II, CA	station. The former station ticket office has been re-used as a cafe and redecoration of the lobby area carried out. The		
	CONDITION:	Poor	owners have confirmed that funding is in place for repair works in 2015-16. A Listed Building Consent application		
	OCCUPANCY:	Part occupied/part in use	will be required for the works.		
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Utility			

access problems.

© London Borough of Wandsworth



	SITE NAME:	The Watchers, behind Downshire House, Roehampton Lane, Roehampton SW15	culpture of 1960 by Lynn Chadwick and installed in 1963 y the London County Council. The sculpture has been emporarily removed following vandalism and carefully
	DESIGNATION:	Listed Building grade II, CA	stored. A planning application was approved in 2013 with a condition requiring the submission of details for the
	CONDITION:	Poor	restoration of The Watchers linked to the occupancy of new student accommodation. The details of restoration
	OCCUPANCY:	N/A	are expected in 2015 following discussions.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1031600	Contact: Barry Sellers (LPA) 020 8871 7564

#### PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

# ABBREVIATIONS

Temple dating from 1762-69. Some damage was caused by vandalism following unauthorised access. The site has been

Former White Lion public house built in 1887. The building

administration. It is in poor condition, with unresolved

re-secured and minor works of repair to the roof were undertaken in 2012. The masterplan for the University's campus sites prepared in 2013 is currently being updated. Pre-application discussions were held with Roehampton

University in 2014 and these are ongoing.

Contact: Elizabeth Whitbourn 07889 808145

is unoccupied following closure and is now in

Contact: Barry Sellers (LPA) 020 8871 7564

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

### HERITAGE AT RISK 2015 / LONDON / WANDSWORTH / WESTMINSTER, CITY OF

10	SITE NAME:	100, Tooting Bec Road SW17	Early C19 stucco lodge. The building is vacant and in need
T	DESIGNATION:	Listed Building grade II	of répair. Planning and Listed Building Consent applications were approved in September 2012 to use the building for
1. 1.	CONDITION:	Poor	retail and ancillary office space, together with a separate new building for use as a café and storage facilities for cars
-	OCCUPANCY:	Vacant/not in use	in conjunction with car sales. A Repairs Notice was serv
	PRIORITY CATEGORY:	F (D)	in early 2015 and repair works are now progressing on site.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357661	Contact: Barry Sellers (LPA) 020 8871 7564
ndoworth			

© London Borough of Wandsworth

-Wi-

©W

# WESTMINSTER, CITY OF

	SITE NAME:	Bow Street Magistrates Court and Police Station, Bow Street WC2	Court and Police Station, built in 1879-80. Greco Roman style with Vanbrughian details. Planning Permission and Listed Building Consent have been granted for the
	DESIGNATION:	Listed Building grade II, CA	refurbishment of the site and re-use as a hotel, museum and interpretive centre. Works have not yet begun.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
Vestminster City Council	LIST ENTRY NUMBER:	1066393	Contact: David Clegg (LPA) 020 7641 3014

	SITE NAME:	21, Charles Street W1	Terraced town house circa 1750-53. Some unauthorised
	DESIGNATION:	Listed Building grade II, CA	works have taken place. Planning Permission and Listed Building Consent were granted in July 2008 for various
	CONDITION:	Poor	works including demolition and rebuilding of the mews building to the rear. The street elevation was cleaned and
	OCCUPANCY:	Vacant/not in use	repaired in 2011-12.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357294	Contact: Robert Ayton (LPA) 020 7641 2978
nd			

© Historic England

	SITE NAME:	39, Charles Street, Mayfair WI	The main house dates from the 1750s and includes mews
	DESIGNATION:	Listed Building grade II*, CA	buildings at the rear. Severe structural problems to the rear of the property are in the process of being rectified and
	CONDITION:	Poor	works have started to implement permissions for a phased scheme of repair and restoration.
	OCCUPANCY:	Vacant/not in use	scheme of repair and restoration.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1292197	Contact: Rebecca Barrett 020 7973 3716

© Westminster City Council



and a	SITE NAME:	I I 2, Eaton Square SWI	Grand terraced house, circa 1825. The building is suffering
	DESIGNATION:	Listed Building grade II*, CA	from neglect, water ingress and a serious outbreak of dry rot. Works to improve the building are underway.
	CONDITION:	Poor	
00	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
12	OWNER TYPE:	Private	
1	LIST ENTRY NUMBER:	1066851	Contact: Rebecca Barrett 020 7973 3716

© Westminster City Council

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

EEE	SITE NAME:	94 and 100, Gloucester Place WI	Terraced houses built circa 1800 for the Portman Estate. Listed Building Consent was granted in July 2009 for the
THEFFE	DESIGNATION:	Listed Building grade II, CA	internal refurbishment and alterations to No. 100. Works have yet to be implemented.
	CONDITION:	Poor	· ·
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
© Westminster City Council	LIST ENTRY NUMBER:	1066788	Contact: Susanna Miller (LPA) 020 7641 2459

	SITE NAME:	10-11, Lancaster Gate W2	Grand terrace of houses dating from 1865, attributed to
	DESIGNATION:	Listed Building grade II, CA	John Johnson. The building is three bays wide with four storeys plus attic and basement. It has excellent classical
	CONDITION:	Very bad	detailing. The condition of the existing building is very poor owing to water leakage and a lack of maintenance over
	OCCUPANCY:	Vacant/not in use	many years. The building has, however, been temporari secured following enforcement action, and discussions a ongoing with regards to its long-term use and repair.
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1221694	Contact: Alistair Taylor (LPA) 020 7641 2979

© Westminster City Council

	SITE NAME:	7-12, Leinster Square W2	The site comprises six terraced buildings which form part
	DESIGNATION:	Listed Building grade II, CA	of the group listing of 7–16 Leinster Square. Built in 1857 by George Wyatt, they form an integral part of the planned
	CONDITION:	Poor	layout of Leinster Square. Since ceasing to function as a hotel, the properties, which are laterally converted, have
	OCCUPANCY:	Vacant/not in use	remained empty. Planning Permission and Listed Building Consent were granted in July 2013 for various works, including repairs to the external elevations and internal
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	refurbishment. Works have yet to be implemented.
	LIST ENTRY NUMBER:	1221945	Contact: Alistair Taylor (LPA) 020 7641 2979

© Westminster City Council

	SITE NAME:	90-93, Piccadilly WI	Corner block of shops and chambers dating from 1883.
	DESIGNATION:	Listed Building grade II, CA	Red brick with stucco ornament and dressings, slate roofs in an eclectic High Victorian design. Part of the former
	CONDITION:	Poor	private club complex with 94 and 95 Piccadilly. The buildings are currently vacant. Planning Permission and
	OCCUPANCY:	Vacant/not in use	Listed Building Consent have been granted but works ha
	PRIORITY CATEGORY:	D (New entry)	yet to commence.
	OWNER TYPE:	Commercial company	
TIN	LIST ENTRY NUMBER:	1226747	Contact: Matthew Pendleton (LPA) 020 7641 5971

© Historic England

SITE NAME:	94, Piccadilly WI	Town Mansion of 1756-1760 by Matthew Brettingham for
DESIGNATION:	Listed Building grade I, CA	Lord Egremont, with 1822 and later alterations. Naval and Military Club from 1866 until 1999. Planning Permission
CONDITION:	Poor	and Listed Building Consent have been granted for alterations and extensions associated with the use of 94
OCCUPANCY:	Vacant/not in use	and 95 Piccadilly as two single dwellings. Works have yet to
PRIORITY CATEGORY:	D (D)	commence on site.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1226748	Contact: Rebecca Barrett 020 7973 3716

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
  - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	95, Piccadilly WI	Town house dating from 1886, forming part of a larger site
	DESIGNATION:	Listed Building grade II, CA	with the Former Naval and Military Club. Planning Permission and Listed Building Consent have been granted
	CONDITION:	Poor	for alterations and extensions associated with the use of 94 and 95 Piccadilly as two single dwellings. The condition of
	OCCUPANCY:	Vacant/not in use	95 is deteriorating. Works have yet to commence on sit
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1265696	Contact: Matthew Pendleton (LPA) 020 7641 5971
uncil			

© Westminster City Council

14	SITE NAME:	26, Portland Place WI	Main house circa 1770s, with some C18 interiors. Works	
	DESIGNATION:	Listed Building grade II*, CA	have commenced on site and are nearing completion.	
3	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1227024	Contact: Rebecca Barrett 020 7973 3716	

© Westminster City Council

© Historic England Archive



Wharf side shelter and store to Wharf side shelter and store circa 1840. Brick ground floor SITE NAME: with timber first floor with large slated hipped roof. Part of rear of builders' merchants, 22, the redevelopment scheme for Paddington Basin. The Praed Street W2 shelter is currently being stored off-site and will be re-DESIGNATION: Listed Building grade II erected as part of the final landscaping proposals. CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: Contact: Tom Burke (LPA) 020 7641 2357 1248366

0.0.0	SITE NAME:	21, Upper Grosvenor Street WI	Terraced town house circa 1732. The building is suffering from a general lack of maintenance and repair with water
	DESIGNATION:	Listed Building grade II, CA	ingress. Planning Permission and Listed Building Consent were granted in 2012 to extensively alter and extend the
	CONDITION:	Poor	property consistent with its use as a single family dwelling. Works are underway to implement this scheme.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
ster City Council	LIST ENTRY NUMBER:	1066191	Contact: Matthew Pendleton (LPA) 020 7641 5971

© Westminst

	SITE NAME:	140, Westbourne Terrace W2	Detached villa dating from 1843-8 in an Italianate style.
	DESIGNATION:	Listed Building grade II, CA	Occupied as a number of bedsits. Planning Permission and Listed Building Consent were refused in November 2011
	CONDITION:	Good	for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised
	OCCUPANCY:	Occupied/in use	works. This is being investigated as an enforcement matt
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1267518	Contact: John Wilman (LPA) 020 7641 2561

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	34, Wimpole Street WI	One of a terrace of houses dating from the 1770s,
	DESIGNATION:	Listed Building grade II, CA	probably designed by John White. The building is built of stock brick, with stucco rustications and slate roof. The
EF	CONDITION:	Very bad	building was severely fire damaged in December 2014. Discussions are ongoing to secure the full repair of the
	OCCUPANCY:	Vacant/not in use	building.
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1224882	Contact: Alistair Taylor (LPA) 020 7641 2979

© Westminster City Council

	SITE NAME:	Church of St Mark, Hamilton Terrace, Paddington NW8	Gothic church dating from 1846-7 by Thomas Cundy Senior with spire by Thomas Cundy Junior and chancel in
	DESIGNATION:	Listed Place of Worship grade II*, CA	1878 by EB Ferrey. Slate covered pitched roofs, Kentish ragstone walling with ashlar dressings. A Heritage Lotter Fund/Historic England grant was awarded towards re- slating the nave roof and works are now complete. A further grant has been offered towards masonry repairs the tower and spire and works are due to commence in
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	summer 2015.
	LIST ENTRY NUMBER:	1066681	Contact: Tracey Craig 020 7973 3756

© Historic England

	SITE NAME:	Church of St Augustine, Kilburn Park Road, Paddington NW6	Designed by JL Pearson, built in 1877. Slated pitched roofs and red brick walling with Bath stone dressings. Internally
	DESIGNATION:	Listed Place of Worship grade I	the walls are covered in wall paintings by Clayton & Bell. A Heritage Lottery Fund/Historic England grant was awarded
	CONDITION:	Poor	in 2010 towards repairs which included re-slating the south aisle roof. These works are now complete. Other roofs,
	PRIORITY CATEGORY:	C (C)	particularly the nave and chancel, are in poor condition
	OWNER TYPE:	Religious organisation	along with the heating system.
	LIST ENTRY NUMBER:	1221320	Contact: Tracey Craig 020 7973 3756

© Historic England

	SITE NAME:	Buddhist Temple, Margaret Street, Marylebone WI	Former Parish School and Church House dating from 1868-70 by William Butterfield. The building is in full-time
	DESIGNATION:	Listed Place of Worship grade II*, CA	occupation and used for worship, library and residential accommodation. Repairs are required to the roofs and external facades. Possible sources of funding are currently
	CONDITION:	Poor	being explored.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1273611	Contact: Tracey Craig 020 7973 3756

© Historic England



SITE NAME:	Church of St Mary Magdalene, Rowington Close, Paddington W2	Built between 1867 and 1878 by GE Street, with crypt chapel of St Sepulchre of 1895 by Sir Ninian Comper. An exceptional High Victorian Gothic church with a complete
DESIGNATION:	Listed Place of Worship grade I, CA	internal decorative scheme. Roof repairs were completed with funding from the Heritage Lottery Fund and Historic England in 2008, and further grant-aid saw the replacement
CONDITION:	Poor	of electrics and the repair of drainage in 2012. The St Sepulchre Chapel is in need of repair and conservation
PRIORITY CATEGORY:	C (C)	works.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1235288	Contact: Tracey Craig 020 7973 3756

© Historic England

# PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Gabriel, Warwick Square, Westminster SWI	Church dating from 1851-3 by the architect Thomas Cundy II with his son Thomas Cundy III. The external walling is
	DESIGNATION:	Listed Place of Worship grade II*, CA	generally Kentish ragstone with Bath stone dressings. Repairs to the tower are now complete, funded by the Heritage Lottery Fund and Historic England. However, some roofs and masonry in other areas remain in poor condition.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	condition.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1357369	Contact: Tracey Craig 020 7973 3756

© Historic England



	SITE NAME:	Church of St Stephen, Westbourne Park Road, Westminster W2	Built in 1856, designed by F & H Francis. Apse added in 1900. Externally coursed ragstone with limestone dressings and slate roofs. The spire was taken down after World
	DESIGNATION:	Listed Place of Worship grade II, CA	War II. The church became near derelict and underwent major repair in 1995. Progressive structural instability is exhibited by extensive cracking and splitting of stone in the
	CONDITION:	Very bad	nave arcading. Some holding works have been implemented to pin back split stones and steel plates fixed
	PRIORITY CATEGORY:	A (A)	to the underside of arches where the stones have slipped.
	OWNER TYPE:	Religious organisation	The congregation is actively exploring options for funding.
	LIST ENTRY NUMBER:	1267651	Contact: Tracey Craig 020 7973 3756

© Historic England

#### PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
   E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
  - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

# NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

This document is one in a series of publications produced as part of Historic England's national **Heritage at Risk** programme. More information about **Heritage at Risk** and other titles in the series can be found at **HistoricEngland.org.uk/har** 

Heritage at Risk Published October 2015 1 Waterhouse Square 138–142 Holborn London EC1N 2ST © Copyright Historic England 2015 Product code: 51993



London Register 2015